

The Taylor Review Pilot



Fabric Support Officers Suffolk, Tom Küpper Manchester, Karen Heverin



Case Study Chelsworth, All Saints (CofE)



Grade I, ca. 14th Century

Image: Historic England©






Allison Russell (Churchwarden) and Andrew Brash (Project Leader)

Image: Historic England©
Taylor Review Pilot







Walk around inspection and maintenance coaching



Image: Historic England©

Taylor Review Pilot





North porch entrance, pre-repair.

- North porch, main entrance to the building.
- Roof tiles are dangerously loose, missing rain water goods, rotting timber work.
- Real H&S concerns with the potential of slipping tiles.

Image: Historic England©

Taylor Review Pilot









North porch entrance, details pre-repair.

Images: Historic England©





North porch entrance, post-repair.

- TRP Grant of £5443.00.
- Re-roofing of the porch using the original clay tiles and carrying out timber repairs.
- Improving drainage and preventing internal damp with the addition of new rain water goods.
- The main entrance is now stable providing secure access.
- Churchwardens received a maintenance coaching and are encouraged to set up a robust and regular maintenance plan for the fabric.

Images: Historic England©

Taylor Review Pilot