

VORKSHIRE AND THE HUMBER

# Contents

3
6
9
11
11
13
16 41 41 42 44 106 117 130



The Heritage at Risk Register helps us to identify the most threatened buildings, archaeological sites and landscapes in this most distinctive of English regions. For the 60% of listed buildings on this year's Register that could have a sustainable future through commercial or residential reuse, the economic downturn has brought additional challenges to which we must now respond. This year, we undertook a pioneering 15% sample survey of England's 14,500 listed places of worship to help us understand the condition of the thousands of designated churches,

chapels, synagogues, mosques and temples and other faith buildings that are the spiritual focus for our communities. They face many different kinds of challenges and we need to ensure their future.

In response to the expansion of asset types and changed economic conditions we have developed a new strategy. From now on we will focus our resources on types of site that make a particular contribution to the region's character. This means we will target fewer places more strongly in an effort to help owners and local authorities to maintain and find new uses for their properties during this demanding period.

The textile industry of the West Riding and the metal trades of South Yorkshire placed the region on the world map. The surviving mills and workshops give a distinctive character to these areas. While many sites, such as Folly Hall Mill, Huddersfield, have been transformed to provide new homes and workplaces, the recession has brought a slow-down to this established regeneration activity. We intend to focus our efforts on these sites, including our grants where they can make the difference.

We continue to work with Natural England to help target funding on rural sites. We will also partner the national park authorities to find solutions for the industrial legacy of the Yorkshire Dales and the ancient landscapes of the North York Moors. On the Wolds, we are funding a Rural Heritage Officer with the local LEADER partnership to generate solutions for the area's high density of scheduled monuments at risk. The region boasts some of the finest designed landscapes in the country, but the magnificent pleasure grounds of South Yorkshire are less well known and have perhaps suffered as a result. We will look for ways to address this, while supporting restoration projects at Wentworth Castle, Wentworth Woodhouse and Bretton Park.

Last year we included conservation areas in the Register for the first time. This year, 46 of these, including Haworth, Holbeck and Rotherham, are known to be at risk, but the survey of nearly 800 areas is proving a challenging task and it will be some time before we get a full picture. Last year's Register also revealed that the battlefields of Stamford Bridge, Boroughbridge, Towton Moor and Adwalton Moor are at risk, as a result of which a study is underway into how to deal with the problem.

The restoration of Hellifield Peel, featured on Grand Designs, showed what can be done to give new life to decaying ruins. The recent residential conversion of an ancient brewhouse at Whitby and the restoration of Bolton Percy Gatehouse are further examples of how scheduled monuments can be brought back into productive use – precisely the kinds of imaginative approach we need to encourage in these challenging times.

Trevor Mitchell

Trevor Mitchell, Planning and Development Regional Director, Yorkshire and the Humber

Contact: Susan Daniels, Business Manager, English Heritage, Yorkshire and the Humber Region, Tanner Row, York YOI 6WP. Telephone: 01904 601979 Fax: 01904 601999 Email: susan.daniels@english-heritage.org.uk

#### **BOLTON PERCY GATEHOUSE, SELBY, NORTH YORKSHIRE**

This rare late medieval building, last used as a meeting room, had fallen into a poor condition, in spite of repairs in the 1970s. The Vivat Trust came to the rescue in 2005 and has worked hard in the current economic climate to secure a package of funding from Yorkshire Forward, Defra, The Country Houses Foundation and English Heritage. The Gatehouse is now a very desirable holiday cottage, which should sustain it for the future, enable people to stay in a medieval building and benefit the regional tourism economy.

# LISTED BUILDINGS

- I in 32 (3.1%) grade I and II\* listed buildings are at risk across the country. In Yorkshire and the Humber this increases to 4.5% (98 sites).
- 7 sites were removed from the 2009 regional Register during the year, but 4 new sites had to be added.
- Since publication of the 1999 baseline Register 55.7%, of the region's buildings at risk (98) have been removed from the regional Register as their futures have been secured, compared to the national figure of 50.7% (724).
- Nationally, £6.2m was offered to 76 sites on the Register during 2009/10. In Yorkshire and the Humber we awarded grants totalling £492k to 7 sites.

# **CONSERVATION AREAS**

- 272 local authorities (81%) have taken part in our national survey of conservation areas, 21 of which were in the Yorkshire and the Humber region.
- We now have information for 7,388 of England's 9,300 designated conservation areas, of which 834 are in Yorkshire and the Humber.
- 549 (7.4%) of the conservation areas for which we have information are at risk, 46 (5.5%) of them in our region.

# SCHEDULED MONUMENTS

- Approximately I in 6 (17.2%) of England's 19,731 scheduled monuments are at risk, compared with 28% (734 sites) in Yorkshire and the Humber.
- The total nationally has fallen by 140 (4.0%) since 2009, 10 of which (1.3%) were in this region.
- Arable ploughing and unrestricted plant, scrub or tree growth account for nearly two thirds of sites at risk. The region follows the national trend in this respect.
- Nationally, 82% of scheduled monuments at risk are in private ownership, rising to 87% in Yorkshire and the Humber.
- Of the £450k offered to owners of scheduled monuments at risk in 2009/10, £94k was to 4 sites in our region.

# REGISTERED PARKS AND GARDENS

- I in 16 of England's 1,606 registered parks and gardens are at risk, with an increase from 6.0% (96) in 2009 to 6.2% (99) this year. In Yorkshire and the Humber, 12 of the 117 of our sites are at risk (10.3%).
- Nationally, 5 sites have been added and 2 removed from the Register. In this region 2 sites have been added (Swinton Castle and Sheffield General Cemetery, both grade II\*) and I removed.

# REGISTERED BATTLEFIELDS

- Of the 43 registered battlefields in England, 6 are at risk, I less than in 2009.
- Of the 7 registered battlefields in Yorkshire and the Humber 4 are at risk, the same number as in 2009.

# PROTECTED SHIP WRECKS

- Of the 46 protected wreck sites around England's coast, 8 are at risk, a fall of I since 2009, due to the implementation of an improved management regime.
- Yorkshire and the Humber's I protected wreck is not considered to be at risk.



#### **ELLAND**

Parts of the centre of this once-prosperous West Yorkshire textile town have become rundown. In response, a partnership scheme led by the local authority and English Heritage is now planning to regenerate the conservation area.

THERE ARE

GRADE I AND II\* LISTED BUILDINGS

AT RISK
IN YORKSHIRE
AND THE HUMBER

200/0 OF THE REGION'S 734 SCHEDULED MONUMENTS ARE AT RISK

5000 OF CONSERVATION AREAS SURVEYED IN THE REGION ARE AT RISK

# CARING FOR PLACES OF WORSHIP

Places of worship make a huge contribution to our towns and villages. They sit at the heart of communities, dominating skylines and landscapes. They are the product of centuries of invested skill and philanthropy. Most remain as places of prayer and spirituality but others have acquired new social uses that benefit a much wider cross-section of urban and rural society.

Like all buildings, they require regular maintenance to keep them in good condition. They also need to adapt to the evolving needs of their congregations and the wider community. Responsibility for their care falls almost entirely on the shoulders of volunteers, and for many smaller congregations the burden can be heavy.

We have therefore undertaken a series of consultation events with congregations, user groups and local authorities to identify the biggest concerns of those who manage these very special places. Places of Worship are particularly close to the heart of local communities, but in practice it is often just a handful of dedicated individuals who maintain them. They face unique challenges, which are illustrated in an accompanying report.


#### What we know

- 45% of all grade I buildings are places of worship.
- 85% of listed places of worship belong to the Church of England.
- Up to I in IO could be at risk from leaking roofs, faulty gutters or eroding stonework.
- 1,850 repair projects at 1,567 buildings have shared £171m of English Heritage and Heritage Lottery Fund grant aid since 2002/3.

# What congregations want to understand better

- Why their building has been listed and what that means.
- How to get permission to make changes and find expert help.
- How to raise money for one-off projects and day-to-day maintenance.
- Who will look after their buildings in the future.

All of these are considered in our booklet *Caring for Places of Worship*, sent to every listed place of worship.



For more information, see www.english-heritage.org.uk/risk or contact your English Heritage regional office.

If you would like this document in a different format, please contact our customer services department on telephone: 0870 333 1181 fax: 01793 414926 textphone: 01793 414878 email: customers@english-heritage.org.uk

# Reducing the risks

English Heritage is committed to securing a year-on-year reduction in the number of heritage sites at risk. This will be challenging given the number of assets now on the register and the different kinds of risk they face. Each asset type and individual case will require its own approach and solution.

There are, however, some general approaches that are relevant to all assets at risk. Resolving cases requires working in close partnership with owners, local planning authorities and other relevant organisations and partners. Advice and understanding are essential. Historic Environment Records, maintained by local authorities, are repositories of information on local historic assets. They underpin the work of local authority historic environment services and can help improve the protection, conservation and management of heritage assets.

Maintenance of heritage assets is essential if they are not to become 'at risk', and to prevent those that are already at risk from decaying further and thereby escalating the cost of their repair and consolidation. Buildings, for instance, decay rapidly when left empty. Avoiding vacancy through short-term lets or schemes that provide protection through residential occupation are low-cost ways of maintaining buildings until permanent solutions can be found.

English Heritage provides on-line advice and guidance to local authorities, owners and managers of sites through the Historic Environment Local Management (HELM) website www.helm.org.uk.

# LISTED BUILDINGS

English Heritage's role in securing the future of buildings at risk is primarily to provide practical advice, guidance and resources to local authorities and owners. Our involvement in cases is determined by the importance of the building and the complexity of the issues. We can help with analysis of the issues, investigation of the feasibility of options and brokering solutions. Although buildings at risk will continue to be a priority for English Heritage repair grants, grant-aid is limited in relation to demand. Grants from other public sources, notably the Heritage Lottery Fund, continue to be essential in helping secure the future of buildings at risk.

In very exceptional cases, English Heritage may acquire and repair a particularly important building at risk, where it is clear that the scale and complexity of problems are such that direct involvement is the best way of securing the building's long-term future.

Local authorities have a primary role in protecting the historic environment. The creation of a local 'at risk' register is the first step in tackling neglected buildings in order to assess and monitor the scale of the problem and prioritise resources and action. Local authorities can also take action to secure the preservation of historic buildings through the use of statutory notices. Some councils have a successful track record, but generally these powers are under-used. It is essential that local authorities make best use of their powers to secure buildings at risk, to 'stop the rot' and prevent the costs escalating beyond the point where it is economic to repair.

To help local authorities make more frequent and timely use of their statutory powers, English Heritage runs a grant scheme to underwrite a significant proportion of the irrecoverable costs involved in serving Urgent Works and Repairs Notices.

Building preservation trusts can be the key to saving many buildings at risk. Some trusts cover geographical areas; others specialise in particular types of building or are formed to save just one building. Determined individuals and trusts have saved numerous buildings at risk, working in partnership with other organisations such as local and national amenity societies, including SAVE Britain's Heritage, the Society for the Protection of Ancient Buildings, The Victorian Society and the Georgian Group.

# SCHEDULED MONUMENTS

Although a significant proportion of scheduled monuments remain at risk, in many cases the problems can be reduced by either small changes to land management or better-informed decision-making. This is reinforced by the success in reducing the number of monuments at risk since the release of the interim figures in 2008, which shows how the simple act of disseminating information and advice can go a long way towards improving conditions. English Heritage provides on-line advice to the owners and managers of sites via the Historic Environment Local Management website www.helm.org.uk; through its Historic Environment Field Advisers and through the network of local authority Historic Environment Countryside Advisers that we have co-sponsored with local authority partners.

While most owners and managers of scheduled monuments address their long-term care on a regular basis, some monuments do require significant resources to stabilise their condition, to carry out repairs, or to change the way in which the land on and around them is used. English Heritage therefore works closely with Natural England who deliver the Environmental Stewardship agri-environment scheme on behalf of Defra and who are active in helping develop management regimes which include scheduled monuments. We also help the Heritage Lottery Fund to identify important sites deserving grant-aid.

The English Heritage National Monuments Record and local authority Historic Environment Records have increased the information available to land managers and we are continuing to develop their services. A new Selected Heritage Inventory for Natural England (SHINE) will soon allow owners to view online information on scheduled monuments and other archaeological features on their holdings.

In all cases — whether for rural or urban monuments — close co-operation with owners and land managers is the key to making further progress.

# REGISTERED PARKS AND GARDENS

Inclusion on the Register brings no additional statutory controls, but there is a presumption in favour of the conservation of all designated assets in the planning system. The Government's new Planning Policy Statement 5 *Planning for the Historic Environment* (PPS 5) and its supporting Practice Guide will help planning authorities to assess and mitigate the impact of development on our irreplaceable heritage of designed landscapes.

English Heritage can engage only with the proposals for change to the highest graded designed landscapes and where the impact on historic significance is greatest. We will continue to tackle the skills crisis facing historic parks and gardens through sector-wide initiatives.

English Heritage encourages the development of conservation management plans for registered historic parks and gardens, especially those in multiple ownership. We are also keen for bursars and estate teams to use management plans to help conserve important but fragile landscapes in the care of schools, hospitals, hotels and other institutional owners.

# REGISTERED BATTLEFIELDS

As with registered parks and gardens, this designation brings no additional statutory controls, but there is a presumption in favour of conservation of registered battlefields in the new PPS 5.

English Heritage will continue to work with owners to develop management plans for registered sites and, in appropriate cases, contribute towards the cost of management plans. We will develop positive landscape strategies with owners and partners such as Defra. In some circumstances, we may encourage the conversion from arable to pasture of especially sensitive locations to protect battlefield archaeology from the effects of ploughing and as part of a wider drive to prevent unauthorised or damaging metal-detecting.

English Heritage will also continue to encourage greater access to battlefields and improve their amenity value and visitors' appreciation of the impact these historic events had on our development as a nation.

Local authorities can help reduce the risk to battlefields by designating registered battlefields as conservation areas. This provides further protection and makes sure that registered battlefields are explicitly taken into account in Local Development Frameworks. Local authorities can also invite comments from the Battlefields Trust on planning applications affecting the setting of registered sites.

# PROTECTED WRECK SITES

At the strategic level, the major sources of risk to designated wreck sites have now been identified. In terms of high-priority sites, practical requirements have also been identified in conservation management plans.

Risks to protected wreck sites can often be reduced through education, provision of marker buoys, or planning policies that take full account of their national importance. However, some sites require significant resources to stabilise their condition or to carry out detailed archaeological assessments of their conservation requirements. Although English Heritage has statutory power to allocate funds to promote the preservation and maintenance of protected wreck sites, its financial resources can solve only a small proportion of the problems.

In spite of the inherent difficulties with caring for this type of site, careful management must be maintained if we are to avoid the loss of wreck sites. It is therefore close co-operation between the owners of protected wreck sites (where known), authorised divers and all organisations charged with care for the marine and coastal environment, that will make the real difference to their long-term survival.

Practical advice on the management of historic wreck sites, whether at the coast-edge or under water, is available from English Heritage's Maritime Archaeology Team (maritime@english-heritage.org.uk) and from www.helm.org.uk.

#### **CONSERVATION AREAS**

The risks to conservation areas are difficult to address as they cover large areas of land and involve many different owners. Looking after them is thus a responsibility we all share – those of us who visit them to work or for enjoyment, those of us who own homes and businesses in them, those of us whose job it is to manage the spaces between the buildings and make decisions about their future.

Overall understanding of their character, development of a robust management regime and engagement by the public are therefore the keys to providing them with sustainable long-term futures. A conservation area is more likely to improve over time if the local authority commits itself to employing a dedicated conservation officer and to appointing an elected member as a heritage champion to promote the historic environment within the council. It also depends on members of the local community engaging either individually or through some form of conservation area advisory committee.

Armed with the information provided by the survey, we and our regional partners will have the evidence to direct resources and investment much more accurately towards those conservation areas at greatest risk. We will also want to target those with the greatest potential to improve the quality of life and economic prospects of people in the villages, towns and cities of which they are such crucially important components.

# Publications and guidance

English Heritage has produced the following publications relating to heritage at risk, including:

- Buildings at Risk: a New Strategy (1998)
- Caring for Places of Worship 2010 (2010) a report on the condition of England's listed places of worship and the needs of the congregations
- Heritage at Risk: Conservation Areas (2009)
- Heritage at Risk 2010 national report and summaries for each of our nine regions: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, Yorkshire and the Humber
- Heritage at Risk Register 2010 detailed listings for each of our nine regions: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, Yorkshire and the Humber can be downloaded from our website or viewed as an interactive database: www.english-heritage.org.uk/risk
- Monuments at Risk (2008) summary of scheduled monuments at risk in each of our nine regions: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, Yorkshire and the Humber
- Protected Wreck Sites at Risk: A Risk Management Handbook (2007)
- The Monuments at Risk initiative 2003–08 (2010)

# HERITAGE AT RISK ON THE WEB

To find out more about the Heritage 'at risk' programme visit **www.english-heritage.org.uk/risk** where you will find an interactive database providing detailed information on all heritage sites 'at risk' nationally.

For further information about the different classes of designated heritage assets, including listed buildings, conservation areas, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites visit the Heritage Protection section of our website www.english-heritage.org.uk/heritageprotection

# CONSERVATION POLICIES AND GUIDANCE

The following publications are among the numerous helpful guidance documents now available on our website: www.english-heritage.org.uk/publications or www.english-heritage.org.uk/helm

Caring for Places of Worship (2010) — a practical booklet for everyone involved in caring for England's listed places of worship

Constructive Conservation in Practice (2008)

Conservation Principles, Policies and Guidance for the Sustainable Management of the Historic Environment (2008)

Creativity and Care: New Works in English Cathedrals (2009)

Enabling Development and the Conservation of Significant Places (2008)

Farming the Historic Landscape: Caring for Archaeological sites on Arable Land (2004)

Farming the Historic Landscape: Caring for Archaeological sites in Grassland (2004)

Guidance on the Management of Conservation Areas (2006)

Guidance on Conservation Area Appraisals (2006)

Guidance Notes and Application Forms for Grants to Local Authorities:

- Grants to Local Authorities to Underwrite Urgent Works Notices (1998)
- Acquisition Grants to Local Authorities to Underwrite Repairs Notices (1998)
- Grants for Historic Buildings, Monuments and Designed Landscapes (2004)

Heritage at Risk: Conservation Areas (2009) — guidance for local authorities

Managing Local Authority Heritage Assets: Some Guiding Principles for Decision Makers (2003)

New Uses for Former Places of Worship (2010)

Options for the Disposal of Redundant Churches and Other Places of Worship (2010)

Paradise Preserved: An Introduction to the Assessment, Evaluation, Conservation and Management of Historic Cemeteries (2002)

Scheduled Monument Consent: a Guide for Owners and Occupiers (2009)

Shared Interest: Celebrating Investment in the Historic Environment (2006)

Stopping the Rot: a Step by Step Guide to Serving Urgent Works and Repairs Notices (1998)

The Disposal of Historic Buildings: Guidance Note for Government Departments and Non-Departmental Public Bodies (DCMS, 1999). A new version is being prepared

If you would like further information about any of these publications, please contact:

English Heritage Customer Services Department PO Box 569, Swindon SN2 2YP Telephone: 0870 333 1181

Fax: 01793 414926

Email: customers@english-heritage.org.uk

# THE REGISTER

# Content and criteria

# **DESIGNATION**

All the historic environment matters but there are some elements which warrant extra protection through the planning system. Since 1882, when the first Act protecting ancient monuments and archaeological remains was passed, government has been developing the designation system. Listing emerged from the post-blitz 1940s Planning Acts, and is now applied to about half a million buildings ranging from palaces to street lamps. Almost 20,000 archaeological sites are scheduled, which introduces tight management controls. Some 1,606 designed landscapes are registered, as are 43 battlefields, and 46 wreck sites are protected.

English Heritage, as the government's expert adviser, is responsible for making recommendations — but it is still the Secretary of State at the Department for Culture Media and Sport who makes the decisions on whether a site is designated. Understanding and appreciation develop constantly, which makes keeping the designation base up to date a never-ending challenge. While responding to threat-driven cases, we also seek to work strategically. Recent developments have seen a greater striving for openness and transparency in the process of designating a site, and better communication of what makes something special.

Conservation areas are designated locally by local planning authorities. They are areas of special architectural or historic interest the character or appearance of which it is desirable to preserve or enhance.

# LISTED BUILDINGS Definition

A listed building is a building (or structure) that has been designated as being of 'special architectural or historic interest'. The older and rarer a building is, the more likely it is to be listed. Buildings less than 30 years old are listed only if they are of outstanding quality and under threat.

Listed buildings are graded I, II\* and II. Grade I and II\* are particularly important buildings of outstanding interest; together they amount to 8% of all listed buildings. The remaining 92% are of special interest and are listed grade II.

Entries on the statutory list of buildings of special architectural or historic interest may comprise a number of separate buildings. Formal residential terraces are the most obvious example. Entries on this register reflect how buildings are grouped and recorded on the statutory list.

Structures can occasionally be both listed as buildings and scheduled as monuments.

# Criteria for inclusion on this register

Buildings considered for inclusion on this register must be listed grade I or II\*, (or grade II in London) or be a structural scheduled monument. Buildings are assessed for inclusion on the basis of condition and, where applicable, occupancy (or use). The condition of buildings on the register ranges from 'very bad' to 'poor', 'fair' and (occasionally) 'good'. The register also includes buildings that are vulnerable to becoming at risk because they are empty, under-used or face redundancy without a new use to secure their future.

Occupancy (or use) is noted as 'vacant', 'part occupied', 'occupied', or occasionally, 'unknown'; for many structural monuments, occupancy is not applicable.

Assessing vulnerability in the case of a building in fair condition necessarily involves judgement and discretion. A few buildings on the register are in good condition, having been repaired or mothballed, but a new use or owner is still to be secured.

Buildings are removed from the 'at risk' register when they are fully repaired/consolidated, their future secured, and where appropriate, occupied.

# Priority for action

Once a building is identified as 'at risk' or vulnerable and included on the register, priority for action is assessed on a scale of A to F, where 'A' is the highest priority for a building which is deteriorating rapidly with no solution to secure its future, and 'F' is the lowest priority where a repair scheme is in progress and an end use has been secured.

# SCHEDULED MONUMENTS Definition

Scheduled monuments include archaeological sites and landscapes, and 19,731 examples have been designated because of their national importance. Scheduled monuments are not graded, and most have limited potential for beneficial use. They cover human activity from the prehistoric era, such as burial mounds, to 20th century military and industrial remains. For the millennia before written history, scheduled monuments are the only testament to innumerable generations of people of whom there is no other record.

The later 20th century saw unprecedented changes to the landscape. As a result, types of historic site that once were commonplace began to become rare. Those that survive often represent just small islands of what once characterised broad sweeps of our towns and countryside. Although protected by law, scheduled monuments are still at risk from a wide range of processes. In particular, they can frequently be exposed to intense pressures beyond the reach

of the planning system. These include damage from cultivation, forestry and — often most seriously of all — wholly natural processes such as scrub growth, animal burrowing and erosion.

# Criteria for inclusion on this register

Scheduled monuments included on this register have been identified as being 'at risk' because of their condition and vulnerability, the trend in their condition, and their likely future vulnerability. A site's condition is expressed in terms of the scale and severity of adverse effects on it, ranging from those with 'extensive significant problems' to others that have only 'minor localised problems'.

Monuments are removed from the register once sufficient progress has been made to address identified issues, demonstrating a significant reduction in the level of risk.

# REGISTERED PARKS AND GARDENS Definition

There are 1,606 designed landscapes on the current English Heritage Register of Historic Parks and Gardens of Special Historic Interest. These registered landscapes are graded I, II\* or II, and include private gardens, public parks and other green spaces, country estates and cemeteries. They are valued for their design, diversity and historical importance and in contrast to the number of listed buildings and scheduled monuments, registered parks and gardens is a very small group of assets.

Inclusion on the English Heritage Register of Historic Parks and Gardens brings no additional statutory controls, but there is a presumption in favour of conservation of the designated site. Local authorities are required to consult English Heritage on applications affecting sites registered as grade I or II\* and the Garden History Society on sites of all grades.

# Criteria for inclusion on this register

The identification of registered parks and gardens at risk begins with an appraisal of the condition and vulnerability of each registered landscape. Steps being taken by owners to address problems are also taken into consideration.

Landscapes assessed as being 'at risk' are typically affected by development and neglect. They have frequently been altered by development or are faced with major change. The original function of these landscapes has often changed; and divided ownership often results in the loss of the cohesive conservation of the historic designs.

Landscapes are removed from the register once plans are put in place to address issues and positive progress is being made.

# REGISTERED BATTLEFIELDS Definition

English Heritage's Register of Historic Battlefields has identified 43 nationally significant sites ranging in date from 991 to 1685. These are places where people risked their lives fighting for a cause and where history was made. The outcome of these battles was influenced by where they were fought and traces of the events will have been left across the landscape. Battlefields are cherished for many reasons, as a commemoration of the event and those who died, as a resource for understanding the course of the battle, and for the light they can shed on the times in which the battle was fought. They are vulnerable to insensitive development and to poorly managed investigation such as large-scale metal-detecting. While this designation introduces no additional statutory controls, one of its primary objectives is to encourage policies and other mechanisms that ensure that change and development affecting battlefields are sensitive and appropriate.

# Criteria for inclusion on this register

Battlefields deemed to be 'at risk' of loss of historic significance are included on this register. The identified risks and threats come from development pressure – for example, because they lie on urban fringes or are subject to development pressures within the site; arable cultivation, and unregulated metal-detecting. One major impact or a combination of several factors can be enough to raise the risk at a particular site.

Battlefields are removed from the register when either actual damaging activities are reversed or managed, or threats recede due to effective management planning.

# PROTECTED WRECK SITES Definition

England's 46 protected wreck sites represent a tiny proportion of the 32,476 pre-1945 wrecks and recorded casualties that are known to lie in the territorial sea. Wreck sites can be of importance for different reasons: the distinctive design or construction of a ship, the story it can tell about its past, its association with notable people or events, its cargo, flora and fauna or its role as a focus for the local community. The Protection of Wrecks Act 1973 empowers the appropriate Secretary of State to designate a restricted area around a vessel to protect it or its contents from unauthorised interference.

Local authorities are able to react to foreshore infrastructure projects through the planning process, thereby securing the preservation of important remains in this intertidal zone.

# Criteria for inclusion on this register

English Heritage has audited all designated wreck sites to identify those most at risk based on their current condition, vulnerability and the way they are being managed.

Wrecks are vulnerable to both environmental and human impacts. Risks that contribute to the inclusion on the register range from unauthorised access to erosion and fishing damage.

What needs to be done to ensure that the significance of the sites is maintained is identified as part of the monitoring process. In spite of the inherent difficulties in caring for this type of site, careful management must be maintained.

Wrecks are removed from the register once an appropriate management and monitoring regime is operational.

# CONSERVATION AREAS Definition

Conservation areas are designated by local authorities and are areas of special architectural or historic interest the character or appearance of which it is desirable to preserve or enhance. For more than 40 years conservation areas have proved a highly effective mechanism for managing change on an area-wide basis. There are currently some 9,300 conservation areas in England including town and city centres, suburbs, industrial areas, rural landscapes, cemeteries and residential areas. They form the historic backcloth to national and local life and are a crucial component of local identity and community cohesion.

# Criteria for inclusion on this register

English Heritage has asked every local authority in England to complete a survey of its conservation areas, highlighting current condition, threats and trends, identifying those that are expected to deteriorate, or are in very bad or poor condition and are not expected to change significantly in the next three years, being defined as at risk.

The methodology for assessing conservation areas at risk has been refined since the first survey in 2008/2009. The information collated this year provides a more detailed assessment of each conservation area and an overall category for condition, vulnerability and trend is included for each conservation area on this register. Conservation areas identified as 'at risk' last year, but not reassessed using the revised methodology, are included on the register but with more limited information.

Conservation areas are removed from the register once issues have been identified, plans put in place to address them and positive progress is being made.

# Key to the entries

# This register includes the following heritage assets at risk:

- grade I and II\* listed buildings and structural scheduled monuments
- scheduled monuments
- registered parks and gardens
- registered battlefields (where applicable)
- protected wreck sites (where applicable)
- conservation areas

# **ORDER**

Entries are grouped and ordered alphabetically first by county\* or unitary authority, and then by local planning authority (unitary authority/national park/district or borough).

Asset types are grouped within the relevant planning authority in the following order:

- listed buildings and structural scheduled monuments
- scheduled monuments
- · registered parks and gardens
- · registered battlefields
- protected wreck sites (are listed at the end of the county or unitary authority off which they are located)
- conservation areas

Within each asset type, sites are ordered alphabetically by parish, locality, street and site name.

\*The metropolitan counties of South Yorkshire and West Yorkshire are used to group the data. North Yorkshire is the only two tier planning authority in the Region.

#### DESIGNATION

The principal designation is noted for each entry, and includes:

- Listed Building (LB) grade I, II\* or II
- Scheduled Monument (SM)
- Registered Park and Garden (RPG) grade I, II\* or II
- Registered Battlefield
- Protected Wreck Site
- Conservation Area (CA)

Other designations that apply to buildings at risk and registered parks and gardens at risk, including their location within a World Heritage Site (WHS), are also noted where applicable.

The monument number is noted for scheduled monuments.

#### CONDITION

For buildings at risk, condition is graded as: 'very bad', 'poor', 'fair' and 'good'.

For sites that cover areas (scheduled monuments, registered parks and gardens and protected wreck sites) one overall condition category is recorded. The category may relate only to the part of the site or monument that is at risk and not the whole site:

- extensive significant problems
- generally unsatisfactory with major localised problems
- generally satisfactory but with significant localised problems
- generally satisfactory but with minor localised problems
- optimal
- unknown (is noted for a number of scheduled monuments that are below-ground and where their condition cannot be established).

For conservation areas, condition is categorised as: 'very bad', 'poor', 'fair' and 'optimal'.

# **OCCUPANCY**

For buildings that can be occupied or have a use, the main vulnerability is vacancy, or under-use. Occupancy (or use) is noted as follows:

- vacant
- part occupied
- occupied
- unknown
- not applicable

#### **VULNERABILITY**

Principal vulnerability is noted for scheduled monuments and may relate only to the part of the monument which is at risk, and include:

- · animal burrowing
- · arable ploughing
- coastal erosion
- collapse
- deterioration in need of management
- scrub / tree growth
- visitor erosion.

For registered parks and gardens, protected wreck sites and conservation areas, vulnerability is noted as high, medium or low.

#### **PRIORITY**

For buildings at risk, the following priority categories are used as an indication of trend and as a means of prioritising action:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- **B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- **D** Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

If the priority category has changed since the 2009 register, the previous category is given in brackets.

#### TREND

Trend for scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites may relate only to the part of the site that is at risk and is categorised as:

- declining
- stable
- · improving
- unknown

For conservation areas trend is categorised as:

- expected to deteriorate significantly
- · expected to deteriorate
- deteriorating
- unknown
- · no significant change expected
- expected to show some improvement

# **OWNERSHIP**

A principal ownership category is given for each entry, although many scheduled monuments, registered parks and gardens, and registered battlefields are in divided ownership. For registered parks and gardens, single or multiple ownership is noted.

# **CONTACT**

This is the member of the English Heritage regional team who acts as a first point of contact for the case, and to whom enquiries should be addressed.

For conservation areas, the contact is the conservation/planning officer at the relevant local planning authority (indicated by 'LA' on the register).

We are not in any sense agents for the owners of the sites included, but we will endeavour to put people in touch with them where appropriate.

# **ABBREVIATIONS**

CA Conservation Area EH English Heritage

HLF Heritage Lottery Fund LA/LPA Local Planning Authority

LB/LBs Listed Building/s
NP National Park

RPG Registered Park and Garden SM/SMs Scheduled Monument/s UA Unitary Authority WHS World Heritage Site

#### EAST RIDING OF YORKSHIRE (UA)



SITE NAME: Gates, gate piers and railings to Norwood House, Norwood, Beverley

DESIGNATION: Listed Building Grade I, CA

Poor CONDITION:

OCCUPANCY: Not applicable

C(C)PRIORITY-

Company OWNERSHIP-

Two pairs of stone gate piers, two pairs of gates and wrought iron railings of circa 1780. Enclosing the forecourt to Norwood House, which until 1996 was used by Beverley Girls' High School, but has since been vacant. The gates and railings are rusting and the stonework has been damaged.

Contact: Catherine Dewar 01904 601972



Norwood House, SITE NAME: Norwood.

Beverley

DESIGNATION: Listed Building Grade I, CA

CONDITION: Vacant OCCUPANCY: C(C)PRIORITY:

Company OWNERSHIP:

Circa 1765-70, probably built for the attorney Jonathan Midgley, twice Mayor of Beverley. Úsed by Beverley Girls' High School until 1996 and vacant since. The fire damaged library has been repaired, but the remainder of the building is neglected.

Contact: Catherine Dewar 01904 601972



Easington Tithe Barn, SITE NAME: High Street, Easington

DESIGNATION: Listed Building Grade II\*, SM, CA

CONDITION: Poor occupancy: Occupied PRIORITY C(C)Private OWNERSHIP:

Medieval and post medieval thatched timber-framed aisled barn associated with historic rectory farm. A unique survival for this part of the region. Fallen into disuse and disrepair.

Contact: Catherine Dewar 01904 601972



Flamborough Castle, SITE NAME: Tower Street,

Flamborough

DESIGNATION: Listed Building Grade II, SM, CA

occupancy: Not applicable

C (C) PRIORITY-OWNERSHIP: Private Mid C14 castle comprised of earthworks and upstanding remains within a pasture field in the centre of the village. The upstanding elements consist of an unconsolidated former undercroft which is made of decaying chalk blocks.

Contact: Catherine Dewar 01904 601972



Elmswell Old Hall. SITE NAME: Elmswell Lane,

Garton

DESIGNATION: Listed Building Grade II3 Very bad CONDITION:

Vacant OCCUPANCY: A(A)

OWNERSHIP: Private

House, 1634 with later alterations. Once the home of Henry Best, important C17 agricultural diarist. Isolated and abandoned. Urgent works have been carried out but these have not arrested decay. The whole building is roofless. An application to restore the house to a dwelling has been made by the Spitalfield Trust.

Contact: Catherine Dewar 01904 601972



Gates, gate piers, SITE NAME:

> flanking walls and abutments, Londesborough

DESIGNATION: Listed Building Grade I, CA, RPG II\*

CONDITION:

occupancy: Not applicable

PRIORITY: C(C)OWNERSHIP: Private of the gatepiers are deteriorating and trees are growing from the joints. The ball finials have fallen.

Gateway, 1660-70, probably by Robert Hooke, forming

the principal entrance to Londesborough Park. The caps

Contact: Neil Redfern 01904 601897

#### PRIORITY (FOR BUILDINGS)


- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# NOTE:

If the priority category has changed since the 2009 register, the previous category is given in brackets.

#### ABBREVIATIONS

Conservation Area CA LB/LBs Conservation Area Listed Building/s National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site NIP RPG SM/SMs UA WHS



Paull Holme Tower, SITE NAME: Thorngumbald Road,

Paull

DESIGNATION: Listed Building Grade I, SM, CA

Very bad CONDITION: Vacant OCCUPANCY: A(A)PRIORITY: Private OWNERSHIP:

Mid C15 three storey brick tower house in a scheduled moated site, originally part of a larger manorial complex. A unique survival for this region. Restored and re-roofed in 1871; roofless since the early C20. The building has been surveyed.

Contact: Keith Miller 01904 601990



Adlingfleet Medieval Rectory, SITE NAME: Church Lane, Adlingfleet, Twin Rivers

DESIGNATION: Listed Building Grade II\*, SM

Very bad CONDITION: OCCUPANCY: Vacant C(C)PRIORITY: Private OWNERSHIP:

Part of a C13 dwelling of the wealthy rector and King's councillor, John le Franceys. Re-used as farm buildings in the C18. A unique survival of a stone-built medieval dwelling in this area.

Contact: Catherine Dewar 01904 601972



Outbuildings to Watton Abbey, SITE NAME: Church Lane. Watton

DESIGNATION: Listed Building Grade II\*, SM

Very bad CONDITION: Vacant OCCUPANCY: D (D) PRIORITY: Private OWNERSHIP:

Gilbertine priory buildings, now outbuildings. C16 with later additions and alterations. The structure is derelict and mainly ruinous. Urgent repairs have been undertaken with the help of an English Heritage grant to stabilise the leaning gable.

Contact: Keith Miller 01904 601990



Haltemprice Priory Farmhouse, Abbey Lane, Willerby

DESIGNATION: Listed Building Grade II\*, SM

Very bad CONDITION: Vacant A(A)PRIORITY Private OWNERSHIP-

Fragmentary remains of a farmhouse dating largely from the C17-C19, incorporating sections of re-used medieval and C16 fabric. In a very advanced state of decay. Proposals for repair and residential re-use are in preparation.

Contact: Catherine Dewar 01904 601972



Wressle Castle, SITE NAME: Breighton Road,

Wressle

DESIGNATION: Listed Building Grade I, SM

CONDITION: OCCUPANCY: Vacant A(A)PRIORITY-OWNERSHIP: Private Very impressive and important surviving range of a major late C14 castle built for the Percy family and occupied by them during the period when they were at the height of their power as the leading family in northern England. Repaired and consolidated as a roofless ruin in the C19; some repairs in 1970-80s.

Contact: Catherine Dewar 01904 601972

	*

SITE NAME:

Bewick Hall moated site, Aldbrough

Scheduled Monument (No. 21206) Generally satisfactory DESIGNATION: CONDITION: but with significant localised problems

PRINCIPAL VULNERABILITY: Scrub / tree growth Declining TREND:

Private Keith Miller 01904 601990 OWNERSHIP: CONTACT

SITE NAME:	Rectilinear enclosures, Barmby Moo
DESIGNATION:	Scheduled Monument (No. ER224)

Extensive significant problems CONDITION: i.e. under plough, collapse

Arable ploughing Declining PRINCIPAL VULNERABILITY: TREND:

Keith Miller 01904 601990 Private OWNERSHIP: CONTACT:

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# NOTE:

If the priority category has changed since the 2009 register, the previous category is given in brackets.

#### ABBREVIATIONS

CA LB/LBs RPG SM/SMs UA WHS

Conservation Area Conservation Area Listed Building/s National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site

SITE NAME:	Round barrow on Metlow Hill, 300m WSV	V of Wandale Farm	ı, Bempton
DESIGNATION:	Scheduled Monument (No. 26511)	CONDITION:	Extensive significant problems
	,		i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Barf Hill moated site, Beswick		
DESIGNATION:	Scheduled Monument (No. 21173)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Beverley sanctuary limit stone, Bishop Bur	ton cross, Bishop E	Burton
DESIGNATION:	Scheduled Monument (No. 26501)	CONDITION:	Generally satisfactory
JESIGNATION:	Scheduled Floridiffett (140, 20301)	CONDITION:	but with significant localised problems
DDINICIDAL VILLA IEDA DI ITEL	Arable clipping	TRENE	
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining  Keith Miller 01904 401990
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Five round barrows 700m north east of Li	ittlewood Lodge, Bi	shop Burton
DESIGNATION:	Scheduled Monument (No. 21138)	CONDITION:	Extensive significant problems
	(12:2-1)		i.e. under plough, collapse
PRINCIPAL VI II NERARII ITV	Arable ploughing	TREVID:	Declining
PRINCIPAL VULNERABILITY: OWNERSHIP:	Arable ploughing Private	TREND: CONTACT:	Declining Keith Miller 01904 601990
OWNERSHIP: SITE NAME:	Private  Four round barrows 780m north east of L	contact: Littlewood Lodge, B	Keith Miller 01904 601990
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990  Sishop Burton  Extensive significant problems
OWNERSHIP: SITE NAME:	Private  Four round barrows 780m north east of L	contact: Littlewood Lodge, B	Keith Miller 01904 601990
OWNERSHIP: SITE NAME: DESIGNATION:	Private  Four round barrows 780m north east of L  Scheduled Monument (No. 21145)	contact:  Littlewood Lodge, E  CONDITION:	Keith Miller 01904 601990  Sishop Burton  Extensive significant problems i.e. under plough, collapse
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Private  Four round barrows 780m north east of L  Scheduled Monument (No. 21145)  Arable ploughing	CONTACT:  Littlewood Lodge, E  CONDITION:  TREND:  CONTACT:	Keith Miller 01904 601990  Sishop Burton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Private  Four round barrows 780m north east of L Scheduled Monument (No. 21145)  Arable ploughing Private  Round barrow 1000m north east of Little	CONTACT:  Littlewood Lodge, B  CONDITION:  TREND:  CONTACT:  wood Lodge, Bisho	Keith Miller 01904 601990  Sishop Burton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  P Burton
DWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  SITE NAME:	Private  Four round barrows 780m north east of L Scheduled Monument (No. 21145)  Arable ploughing Private	CONTACT:  Littlewood Lodge, E  CONDITION:  TREND:  CONTACT:	Keith Miller 01904 601990  dishop Burton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  P Burton  Extensive significant problems
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:	Private  Four round barrows 780m north east of L  Scheduled Monument (No. 21145)  Arable ploughing Private  Round barrow 1000m north east of Littler  Scheduled Monument (No. 21144)	CONTACT:  Littlewood Lodge, B  CONDITION:  TREND:  CONTACT:  wood Lodge, Bisho  CONDITION:	Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  P Burton  Extensive significant problems i.e. under plough, collapse
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Private  Four round barrows 780m north east of L Scheduled Monument (No. 21145)  Arable ploughing Private  Round barrow 1000m north east of Littlet Scheduled Monument (No. 21144)  Arable ploughing	CONTACT:  Littlewood Lodge, B  CONDITION:  TREND:  CONTACT:  wood Lodge, Bisho  CONDITION:  TREND:	Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  P Burton  Extensive significant problems i.e. under plough, collapse Declining
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Private  Four round barrows 780m north east of L  Scheduled Monument (No. 21145)  Arable ploughing Private  Round barrow 1000m north east of Littler  Scheduled Monument (No. 21144)	CONTACT:  Littlewood Lodge, B  CONDITION:  TREND:  CONTACT:  wood Lodge, Bisho  CONDITION:	Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  P Burton  Extensive significant problems i.e. under plough, collapse
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Private  Four round barrows 780m north east of L Scheduled Monument (No. 21145)  Arable ploughing Private  Round barrow 1000m north east of Littlet Scheduled Monument (No. 21144)  Arable ploughing	CONTACT:  Littlewood Lodge, E  CONDITION:  TREND:  CONTACT:  WOOD Lodge, Bisho  CONDITION:  TREND:  CONTACT:	Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  P Burton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DWNERSHIP:  SITE NAME:  DWNERSHIP:	Private  Four round barrows 780m north east of L Scheduled Monument (No. 21145)  Arable ploughing Private  Round barrow 1000m north east of Littlet Scheduled Monument (No. 21144)  Arable ploughing Private	CONTACT:  Littlewood Lodge, E  CONDITION:  TREND:  CONTACT:  WOOD Lodge, Bisho  CONDITION:  TREND:  CONTACT:	Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  P Burton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Private  Four round barrows 780m north east of L Scheduled Monument (No. 21145)  Arable ploughing Private  Round barrow 1000m north east of Littlet Scheduled Monument (No. 21144)  Arable ploughing Private  Round barrow 900m north east of Littlet Scheduled Monument (No. 21144)	CONTACT:  Littlewood Lodge, B  CONDITION:  TREND:  CONTACT:  WOOD Lodge, Bisho  CONTACT:  TREND:  CONTACT:	Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  P Burton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Burton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  DESIGNATION:  DESIGNATION:	Four round barrows 780m north east of L Scheduled Monument (No. 21145)  Arable ploughing Private  Round barrow 1000m north east of Little Scheduled Monument (No. 21144)  Arable ploughing Private  Round barrow 900m north east of Littlew	CONTACT:  Littlewood Lodge, B  CONDITION:  TREND:  CONTACT:  WOOD Lodge, Bisho  CONDITION:  TREND:  CONTACT:	Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  P Burton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Burton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:	Four round barrows 780m north east of L Scheduled Monument (No. 21145)  Arable ploughing Private  Round barrow 1000m north east of Littlet Scheduled Monument (No. 21144)  Arable ploughing Private  Round barrow 900m north east of Littlet Scheduled Monument (No. 21144)  Arable ploughing Private	CONTACT:  Littlewood Lodge, B  CONDITION:  TREND:  CONTACT:  WOOD Lodge, Bishop  CONDITION:  TREND:  CONTACT:  CONTACT:  TREND:  CONDITION:  TREND:  TREND:  TREND:  TREND:  TREND:  TREND:	Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  P Burton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Burton  Extensive significant problems i.e. under plough, collapse Declining Lettensive significant problems i.e. under plough, collapse Declining
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:	Four round barrows 780m north east of L Scheduled Monument (No. 21145)  Arable ploughing Private  Round barrow 1000m north east of Littlet Scheduled Monument (No. 21144)  Arable ploughing Private  Round barrow 900m north east of Littlet Scheduled Monument (No. 21144)  Arable ploughing Private	CONTACT:  Littlewood Lodge, B  CONDITION:  TREND:  CONTACT:  WOOD Lodge, Bisho  CONDITION:  TREND:  CONTACT:  TREND:  CONDITION:  TREND:  CONDITION:  TREND:  CONDITION:	Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  P Burton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Burton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Keith Miller 01904 601990
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  DESIGNATION:  DESIGNATION:  DESIGNATION:  DESIGNATION:  DESIGNATION:  OWNERSHIP:  DESIGNATION:  OWNERSHIP:	Four round barrows 780m north east of L Scheduled Monument (No. 21145)  Arable ploughing Private  Round barrow 1000m north east of Littlet Scheduled Monument (No. 21144)  Arable ploughing Private  Round barrow 900m north east of Littlew Scheduled Monument (No. 21143)  Arable ploughing Private	CONTACT:  Littlewood Lodge, B  CONDITION:  TREND:  CONTACT:  WOOD Lodge, Bisho  CONDITION:  TREND:  CONTACT:  TREND:  CONDITION:  TREND:  CONDITION:  TREND:  CONDITION:	Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  P Burton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Burton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Keith Miller 01904 601990
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Four round barrows 780m north east of L Scheduled Monument (No. 21145)  Arable ploughing Private  Round barrow 1000m north east of Littler Scheduled Monument (No. 21144)  Arable ploughing Private  Round barrow 900m north east of Littlew Scheduled Monument (No. 21143)  Arable ploughing Private  Three round barrows 800m north east of	CONTACT:  Littlewood Lodge, B  CONDITION:  TREND: CONTACT:  WOOD Lodge, Bishop  CONDITION:  TREND: CONTACT:  TREND: CONTACT:  Littlewood Lodge,	Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  P Burton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Burton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Burton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Bishop Burton
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Four round barrows 780m north east of L Scheduled Monument (No. 21145)  Arable ploughing Private  Round barrow 1000m north east of Littler Scheduled Monument (No. 21144)  Arable ploughing Private  Round barrow 900m north east of Littlew Scheduled Monument (No. 21143)  Arable ploughing Private  Three round barrows 800m north east of	CONTACT:  Littlewood Lodge, B  CONDITION:  TREND: CONTACT:  WOOD Lodge, Bishop  CONDITION:  TREND: CONTACT:  TREND: CONTACT:  Littlewood Lodge,	Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  P Burton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Burton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Burton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Bishop Burton  Extensive significant problems

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

CA LB/LBs NP RPG SM/SMs UA WHS

SITE NAME:	Round barrow 250m east of Wold Farm, E	Bishop Wilton Wold	, Bishop Wilton
DESIGNATION:	Scheduled Monument (No. 21095)	CONDITION:	Extensive significant problems
DDINICIDAL VILILATED A DILITY.	Arable ploughing	TDENID.	i.e. under plough, collapse  Declining
PRINCIPAL VULNERABILITY:	Private	TREND:	Keith Miller 01904 601990
DWNERSHIP:	rrivate	CONTACT:	Reiti i illier 01704 601770
SITE NAME:	Round barrow 250m south of Callis Wold	Farm, Bishop Wilto	on
DESIGNATION:	Scheduled Monument (No. 21105)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Round barrow 300m south west of Callis	Wold Farm, Bishop	Wilton
DESIGNATION:	Scheduled Monument (No. 21098)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Round barrow 300m south west of Cot N	lab Farm, Bishop W	/ilton
DESIGNATION:	Scheduled Monument (No. 21084)	CONDITION:	Extensive significant problems
	A malala and a combine a		i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Round barrow 350m west of Cot Nab Fai	rm, Bishop Wilton	
DESIGNATION:	Scheduled Monument (No. 21082)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
	Arable ploughing Private	TREND: CONTACT:	
OWNERSHIP:	, , ,	CONTACT:	Declining Keith Miller 01904 601990
OWNERSHIP: SITE NAME:	Private	CONTACT:	Declining Keith Miller 01904 601990  The Wold, Bishop Wilton Extensive significant problems
OWNERSHIP: SITE NAME: DESIGNATION:	Private  Round barrow 400m north east of Wold F  Scheduled Monument (No. 21094)	CONTACT: Farm, Bishop Wilton CONDITION:	Declining Keith Miller 01904 601990  Nold, Bishop Wilton Extensive significant problems i.e. under plough, collapse
OWNERSHIP:  ITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Private  Round barrow 400m north east of Wold F  Scheduled Monument (No. 21094)  Arable ploughing	CONTACT:  Farm, Bishop Wilton  CONDITION:  TREND:	Declining Keith Miller 01904 601990  Nold, Bishop Wilton Extensive significant problems i.e. under plough, collapse Declining
DWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Private  Round barrow 400m north east of Wold F  Scheduled Monument (No. 21094)	CONTACT: Farm, Bishop Wilton CONDITION:	Declining Keith Miller 01904 601990  Nold, Bishop Wilton Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Private  Round barrow 400m north east of Wold F  Scheduled Monument (No. 21094)  Arable ploughing	CONTACT:  Farm, Bishop Wilton  CONDITION:  TREND:  CONTACT:	Declining Keith Miller 01904 601990  n Wold, Bishop Wilton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990
DWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  SITE NAME:	Private  Round barrow 400m north east of Wold F  Scheduled Monument (No. 21094)  Arable ploughing  Private	CONTACT:  Farm, Bishop Wilton  CONDITION:  TREND:  CONTACT:	Declining Keith Miller 01904 601990  n Wold, Bishop Wilton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  SITE NAME:	Private  Round barrow 400m north east of Wold F Scheduled Monument (No. 21094)  Arable ploughing Private  Round barrow 850m north of Wold Farm,	CONTACT:  Farm, Bishop Wilton  CONDITION:  TREND:  CONTACT:	Declining Keith Miller 01904 601990  N Wold, Bishop Wilton Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Id, Bishop Wilton
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DITE NAME:  DESIGNATION:	Private  Round barrow 400m north east of Wold F Scheduled Monument (No. 21094)  Arable ploughing Private  Round barrow 850m north of Wold Farm,	CONTACT:  Farm, Bishop Wilton  CONDITION:  TREND:  CONTACT:	Declining Keith Miller 01904 601990  n Wold, Bishop Wilton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Id, Bishop Wilton  Extensive significant problems
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Private  Round barrow 400m north east of Wold F Scheduled Monument (No. 21094)  Arable ploughing Private  Round barrow 850m north of Wold Farm, Scheduled Monument (No. 21093)	CONTACT:  Farm, Bishop Wilton  CONDITION:  TREND:  CONTACT:  Bishop Wilton Wo  CONDITION:	Declining Keith Miller 01904 601990  Nold, Bishop Wilton Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Id, Bishop Wilton Extensive significant problems i.e. under plough, collapse
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Private  Round barrow 400m north east of Wold F Scheduled Monument (No. 21094)  Arable ploughing Private  Round barrow 850m north of Wold Farm, Scheduled Monument (No. 21093)  Arable ploughing	CONTACT:  Farm, Bishop Wilton  CONDITION:  TREND:  CONDITION:  TREND:  CONDITION:  TREND:  CONTACT:	Declining Keith Miller 01904 601990  The Wold, Bishop Wilton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Id, Bishop Wilton  Extensive significant problems i.e. under plough, collapse Declining
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Round barrow 400m north east of Wold F Scheduled Monument (No. 21094)  Arable ploughing Private  Round barrow 850m north of Wold Farm, Scheduled Monument (No. 21093)  Arable ploughing Private	CONTACT:  Farm, Bishop Wilton  CONDITION:  TREND:  CONDITION:  TREND:  CONDITION:  TREND:  CONTACT:	Declining Keith Miller 01904 601990  The Wold, Bishop Wilton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Id, Bishop Wilton  Extensive significant problems i.e. under plough, collapse Declining
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Round barrow 400m north east of Wold Found Scheduled Monument (No. 21094)  Arable ploughing Private  Round barrow 850m north of Wold Farm, Scheduled Monument (No. 21093)  Arable ploughing Private  Round barrow south east of Cot Nab Farm	CONTACT:  Farm, Bishop Wilton  CONDITION:  TREND:  CONDITION:  TREND:  CONDITION:  TREND:  CONTACT:	Declining Keith Miller 01904 601990  Twold, Bishop Wilton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Id, Bishop Wilton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Round barrow 400m north east of Wold Found Scheduled Monument (No. 21094)  Arable ploughing Private  Round barrow 850m north of Wold Farm, Scheduled Monument (No. 21093)  Arable ploughing Private  Round barrow south east of Cot Nab Farm	CONTACT:  Farm, Bishop Wilton  CONDITION:  TREND:  CONDITION:  TREND:  CONDITION:  TREND:  CONTACT:	Declining Keith Miller 01904 601990  n Wold, Bishop Wilton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Id, Bishop Wilton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Extensive significant problems

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Section of linear boundary dyke on Milling	gton Lings 625m no	orth east of High Callis Wold, Bishop Wil
DESIGNATION:	Scheduled Monument (No. 26590)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Site of Archbishop's moated palace and fis	hponds, Hall Garth	, Bishop Wilton
DESIGNATION:	Scheduled Monument (No. 21054)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Settlement site at Boynton Hall, Boynton		
DESIGNATION:	Scheduled Monument (No. ER218)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Romano-British villa at Cockle Pits, near E	Brantingham, Branti	ngham
DESIGNATION:	Scheduled Monument (No. 26522)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Dumping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow, 500m south of Buckton Barr	n, Bridlington	
DESIGNATION:	Scheduled Monument (No. 26518)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow, 500m SSW of Buckton Barn	, Bridlington	
DESIGNATION:	Scheduled Monument (No. 26517)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Moated site at North Park Farm, Burstwic	:k	
DESIGNATION:	Scheduled Monument (No. 21199)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Iron Age square barrow cemetery on Hais 750m WNW of Demming Farm, Burton A		
DESIGNATION:	Scheduled Monument (No. 26527)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Metal detecting	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
OVVINEIGI III .			

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

ABBREVIATIONS

SITE NAME:	Wharram Hill embankment cross, Burton	Agnes	
DESIGNATION:	Scheduled Monument (No. ER186)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
OVVINERSHIF:	TTIVALE	CONTACT:	Return liller 01701 001770
SITE NAME:	Site revealed by aerial photography north	west of Argam Co	ttages, Burton Fleming
DESIGNATION:	Scheduled Monument (No. ER153)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Willy Howe round barrow, Burton Fleming		
DESIGNATION:	Scheduled Monument (No. 21190)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow 200m west of Crest Cottage	es, Carnaby	
DESIGNATION:	Scheduled Monument (No. 21235)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
PRINCIPAL VULNERABILITI:	1 0 0		9
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
	·		
OWNERSHIP: SITE NAME:	Private		
OWNERSHIP:	Private  Moated site and two fishponds 80m south	west of Parkhouse	e Farm, Cherry Burton  Generally satisfactory
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Moated site and two fishponds 80m south Scheduled Monument (No. 21177)	west of Parkhouse	e Farm, Cherry Burton  Generally satisfactory  but with significant localised problems
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Private  Moated site and two fishponds 80m south Scheduled Monument (No. 21177)  Scrub / tree growth	west of Parkhouse  CONDITION:  TREND:  CONTACT:	e Farm, Cherry Burton  Generally satisfactory but with significant localised problems  Declining  Keith Miller 01904 601990
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:	Private  Moated site and two fishponds 80m south Scheduled Monument (No. 21177)  Scrub / tree growth Private	west of Parkhouse  CONDITION:  TREND:  CONTACT:	e Farm, Cherry Burton  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  erry Burton  Extensive significant problems
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DITE NAME:  DESIGNATION:	Private  Moated site and two fishponds 80m south Scheduled Monument (No. 21177)  Scrub / tree growth Private  Round barrow 300m south west of High C Scheduled Monument (No. 21225)	west of Parkhouse  CONDITION:  TREND:  CONTACT:  Gardham Farm, Che	e Farm, Cherry Burton  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  erry Burton  Extensive significant problems i.e. under plough, collapse
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Moated site and two fishponds 80m south Scheduled Monument (No. 21177) Scrub / tree growth Private  Round barrow 300m south west of High C	west of Parkhouse  CONDITION:  TREND:  CONTACT:  Gardham Farm, Che  CONDITION:	e Farm, Cherry Burton  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  erry Burton  Extensive significant problems
OWNERSHIP: SITE NAME: DESIGNATION:	Moated site and two fishponds 80m south Scheduled Monument (No. 21177) Scrub / tree growth Private  Round barrow 300m south west of High C Scheduled Monument (No. 21225)  Arable ploughing	west of Parkhouse  CONDITION:  TREND:  CONTACT:  Gardham Farm, Che  CONDITION:  TREND:  CONTACT:	e Farm, Cherry Burton  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  erry Burton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DWNERSHIP:  DWNERSHIP:	Moated site and two fishponds 80m south Scheduled Monument (No. 21177)  Scrub / tree growth Private  Round barrow 300m south west of High C Scheduled Monument (No. 21225)  Arable ploughing Other	west of Parkhouse  CONDITION:  TREND:  CONTACT:  Gardham Farm, Che  CONDITION:  TREND:  CONTACT:	e Farm, Cherry Burton  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  erry Burton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  erry Burton  Extensive significant problems
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  DESIGNATION:  DESIGNATION:	Moated site and two fishponds 80m south Scheduled Monument (No. 21177) Scrub / tree growth Private  Round barrow 300m south west of High ( Scheduled Monument (No. 21225)  Arable ploughing Other  Round barrow 430m north west of High ( Scheduled Monument (No. 21226)	west of Parkhouse  CONDITION:  TREND: CONTACT:  Gardham Farm, Che CONDITION:  TREND: CONTACT:  CONTACT:	e Farm, Cherry Burton  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  erry Burton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  erry Burton  Extensive significant problems i.e. under plough, collapse
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:	Moated site and two fishponds 80m south Scheduled Monument (No. 21177)  Scrub / tree growth Private  Round barrow 300m south west of High ( Scheduled Monument (No. 21225)  Arable ploughing Other  Round barrow 430m north west of High ( Scheduled Monument (No. 21226)  Arable ploughing	west of Parkhouse  CONDITION:  TREND:  CONTACT:  Gardham Farm, Che  CONDITION:  TREND:  CONTACT:  Gardham Farm, Che  CONDITION:  TREND:  TREND:  TREND:  TREND:  TREND:	e Farm, Cherry Burton  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  erry Burton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  erry Burton  Extensive significant problems i.e. under plough, collapse Declining Cerry Burton  Extensive significant problems i.e. under plough, collapse Declining
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Moated site and two fishponds 80m south Scheduled Monument (No. 21177) Scrub / tree growth Private  Round barrow 300m south west of High ( Scheduled Monument (No. 21225)  Arable ploughing Other  Round barrow 430m north west of High ( Scheduled Monument (No. 21226)	west of Parkhouse  CONDITION:  TREND: CONTACT:  Gardham Farm, Che CONDITION:  TREND: CONTACT:  CONTACT:	e Farm, Cherry Burton  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  erry Burton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  erry Burton  Extensive significant problems i.e. under plough, collapse
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Moated site and two fishponds 80m south Scheduled Monument (No. 21177)  Scrub / tree growth Private  Round barrow 300m south west of High ( Scheduled Monument (No. 21225)  Arable ploughing Other  Round barrow 430m north west of High ( Scheduled Monument (No. 21226)  Arable ploughing	west of Parkhouse  CONDITION:  TREND: CONTACT:  Gardham Farm, Che CONDITION:  TREND: CONTACT:  TREND: CONDITION:  TREND: CONDITION:  TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  erry Burton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  erry Burton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  erry Burton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  OWNERSHIP:  OWNERSHIP:	Moated site and two fishponds 80m south Scheduled Monument (No. 21177)  Scrub / tree growth Private  Round barrow 300m south west of High ( Scheduled Monument (No. 21225)  Arable ploughing Other  Round barrow 430m north west of High ( Scheduled Monument (No. 21226)  Arable ploughing Other	west of Parkhouse  CONDITION:  TREND: CONTACT:  Gardham Farm, Che CONDITION:  TREND: CONTACT:  TREND: CONDITION:  TREND: CONDITION:  TREND: CONTACT:	e Farm, Cherry Burton  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  erry Burton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  erry Burton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  erry Burton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  erry Burton  Extensive significant problems
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Moated site and two fishponds 80m south Scheduled Monument (No. 21177)  Scrub / tree growth Private  Round barrow 300m south west of High C Scheduled Monument (No. 21225)  Arable ploughing Other  Round barrow 430m north west of High C Scheduled Monument (No. 21226)  Arable ploughing Other  Round barrow 430m north west of High C Scheduled Monument (No. 21226)  Arable ploughing Other	west of Parkhouse  CONDITION:  TREND: CONTACT:  Gardham Farm, Che CONDITION:  TREND: CONDITION:  TREND: CONDITION:  TREND: CONTACT:  Gardham Farm, Che CONDITION:	e Farm, Cherry Burton  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  erry Burton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  erry Burton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  erry Burton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

CA LB/LBs NP RPG SM/SMs UA WHS

SITE NAME:	Round barrow 700m west of High Gardha	am Farm, Cherry Bo	urton
DESIGNATION:	Scheduled Monument (No. 21228)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Seven round barrows 530m west of High	Gardham Farm, Ch	erry Burton
DESIGNATION:	Scheduled Monument (No. 21230)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Two round barrows 600m north west of I	High Gardham Farn	n. Cherry Burton
		-	•
DESIGNATION:	Scheduled Monument (No. 21229)	CONDITION:	Extensive significant problems
	Avalala playedaine		i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining Keith Miller 01904 601990
OWNERSHIP:	Other	CONTACT:	Kelth Miller 01904 601990
SITE NAME:	Linear earthwork north east of Collingwo	od Farm, Cottam	
DESIGNATION:	Scheduled Monument (No. 21222)	CONDITION:	Extensive significant problems
SESSI WITTON N.	ochodalod Fioridifficite (FNO, Z1ZZZ)	CONDITION:	i.e. under plough, collapse
			artaer proagri, conapse
PRINCIPAL VI II NERARII ITY:	Arable ploughing	TRENID:	Declining
	Arable ploughing Private	TREND: CONTACT:	Declining Keith Miller 01904 601990
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Private  Round barrow 700m north east of Colling	contact:	Keith Miller 01904 601990
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990  m  Extensive significant problems
OWNERSHIP: SITE NAME:	Private  Round barrow 700m north east of Colling	contact:	Keith Miller 01904 601990
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Round barrow 700m north east of Colling Scheduled Monument (No. 21221)	contact: gwood Farm, Cotta condition:	MEXTENSIVE SIGNIFICANT PROBLEMS  i.e. under plough, collapse
OWNERSHIP: SITE NAME: DESIGNATION:	Private  Round barrow 700m north east of Colling Scheduled Monument (No. 21221)  Arable ploughing	contact:  gwood Farm, Cotta  condition:  trend:	MEXTENSIVE SIGNIFICANT PROBLEMS  i.e. under plough, collapse  Declining
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Private  Round barrow 700m north east of Colling Scheduled Monument (No. 21221)  Arable ploughing Private  Baynard Castle, Cottingham	contact:  gwood Farm, Cotta  condition:  trend:  contact:	Meith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:	Private  Round barrow 700m north east of Colling Scheduled Monument (No. 21221)  Arable ploughing Private	contact:  gwood Farm, Cotta  condition:  trend:	MExtensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Generally satisfactory
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DITE NAME:  DESIGNATION:	Private  Round barrow 700m north east of Colling Scheduled Monument (No. 21221)  Arable ploughing Private  Baynard Castle, Cottingham Scheduled Monument (No. 32633)	contact:  gwood Farm, Cotta  condition:  trend:  contact:	M  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Private  Round barrow 700m north east of Colling Scheduled Monument (No. 21221)  Arable ploughing Private  Baynard Castle, Cottingham Scheduled Monument (No. 32633)  Drainage/dewatering	CONTACT:  gwood Farm, Cotta  CONDITION:  TREND:  CONTACT:  CONDITION:  TREND:	M  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems Declining
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Private  Round barrow 700m north east of Colling Scheduled Monument (No. 21221)  Arable ploughing Private  Baynard Castle, Cottingham Scheduled Monument (No. 32633)	contact:  gwood Farm, Cotta  condition:  trend:  contact:	M  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Private  Round barrow 700m north east of Colling Scheduled Monument (No. 21221)  Arable ploughing Private  Baynard Castle, Cottingham Scheduled Monument (No. 32633)  Drainage/dewatering	CONTACT:  gwood Farm, Cotta  CONDITION:  TREND:  CONTACT:  CONDITION:  TREND:	M  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems Declining
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DWNERSHIP:  DWNERSHIP:	Private  Round barrow 700m north east of Colling Scheduled Monument (No. 21221)  Arable ploughing Private  Baynard Castle, Cottingham Scheduled Monument (No. 32633)  Drainage/dewatering Private	CONTACT:  gwood Farm, Cotta  CONDITION:  TREND:  CONTACT:  CONDITION:  TREND:	M  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Generally satisfactory
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  DESIGNATION:  DESIGNATION:	Private  Round barrow 700m north east of Colling Scheduled Monument (No. 21221)  Arable ploughing Private  Baynard Castle, Cottingham Scheduled Monument (No. 32633)  Drainage/dewatering Private  Money Hill round barrow, Dalton Holme Scheduled Monument (No. 21171)	CONTACT:  gwood Farm, Cotta  CONDITION:  TREND:  CONTACT:  CONDITION:  TREND:  CONTACT:	MExtensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:	Private  Round barrow 700m north east of Colling Scheduled Monument (No. 21221)  Arable ploughing Private  Baynard Castle, Cottingham Scheduled Monument (No. 32633)  Drainage/dewatering Private  Money Hill round barrow, Dalton Holme Scheduled Monument (No. 21171)  Arable clipping	CONTACT:  gwood Farm, Cotta  CONDITION:  TREND:  CONTACT:  CONDITION:  TREND:  CONTACT:  CONDITION:  TREND:  TREND:  TREND:  TREND:  TREND:	MExtensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:	Private  Round barrow 700m north east of Colling Scheduled Monument (No. 21221)  Arable ploughing Private  Baynard Castle, Cottingham Scheduled Monument (No. 32633)  Drainage/dewatering Private  Money Hill round barrow, Dalton Holme Scheduled Monument (No. 21171)	CONTACT:  gwood Farm, Cotta  CONDITION:  TREND:  CONTACT:  CONDITION:  TREND:  CONTACT:	MExtensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Private  Round barrow 700m north east of Colling Scheduled Monument (No. 21221)  Arable ploughing Private  Baynard Castle, Cottingham Scheduled Monument (No. 32633)  Drainage/dewatering Private  Money Hill round barrow, Dalton Holme Scheduled Monument (No. 21171)  Arable clipping	CONTACT:  gwood Farm, Cotta  CONDITION:  TREND:  CONTACT:  CONDITION:  TREND:  CONTACT:  CONDITION:  TREND:  CONDITION:	MExtensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Keith Miller 01904 601990
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  OWNERSHIP:  OWNERSHIP:	Private  Round barrow 700m north east of Colling Scheduled Monument (No. 21221)  Arable ploughing Private  Baynard Castle, Cottingham Scheduled Monument (No. 32633)  Drainage/dewatering Private  Money Hill round barrow, Dalton Holme Scheduled Monument (No. 21171)  Arable clipping Private	CONTACT:  gwood Farm, Cotta  CONDITION:  TREND:  CONTACT:  CONDITION:  TREND:  CONTACT:  CONDITION:  TREND:  CONDITION:	MExtensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Keith Miller 01904 601990
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Private  Round barrow 700m north east of Colling Scheduled Monument (No. 21221)  Arable ploughing Private  Baynard Castle, Cottingham Scheduled Monument (No. 32633)  Drainage/dewatering Private  Money Hill round barrow, Dalton Holme Scheduled Monument (No. 21171)  Arable clipping Private  Moot Hill motte and bailey castle, and site	CONTACT:  gwood Farm, Cotta  CONDITION:  TREND:  CONTACT:  CONDITION:  TREND:  CONTACT:  CONDITION:  TREND:  CONTACT:	m  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  sted manor, Driffield
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Private  Round barrow 700m north east of Colling Scheduled Monument (No. 21221)  Arable ploughing Private  Baynard Castle, Cottingham Scheduled Monument (No. 32633)  Drainage/dewatering Private  Money Hill round barrow, Dalton Holme Scheduled Monument (No. 21171)  Arable clipping Private  Moot Hill motte and bailey castle, and site	CONTACT:  gwood Farm, Cotta  CONDITION:  TREND:  CONTACT:  CONDITION:  TREND:  CONTACT:  CONDITION:  TREND:  CONTACT:	Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Atted manor, Driffield Generally unsatisfactory

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	World War I acoustic mirror 335m north	east of Kilnsea Gra	ange, Easington
DESIGNATION:	Scheduled Monument (No. 35482)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Site of deserted village of Grimston, East 0	Garton	
DESIGNATION:	Scheduled Monument (No. 35496)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Moated site at Newland Farm, Eastrington		
DESIGNATION:	Scheduled Monument (No. 26598)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Motte and bailey castle, fishpond and moa	ted site north and	east of Aughton church, Ellerton
DESIGNATION:	Scheduled Monument (No. 23828)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bolton Old Hall moated site, Fangfoss		
DESIGNATION:	Scheduled Monument (No. 21195)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow 150m NNE of Towthorpe Hi	igh Barn, Fimber	
DESIGNATION:	Scheduled Monument (No. 26539)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow, I50m south east of Towthor	pe Reservoir, Fimb	er
DESIGNATION:	Scheduled Monument (No. 26540)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Settlement at Blealands Nook, Fimber		
DESIGNATION:	Scheduled Monument (No. ER213)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
CTTIVEIOFIII.	rivate	CONTACT:	Note I micr 01701 001770

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category
has changed since the 2009
register, the previous category
is given in brackets.

# ABBREVIATIONS

SITE NAME:	Garton Slack settlement site, Garton		
DESIGNATION:	Scheduled Monument (No. ER92)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Linear earthwork running from the head of and associated settlement site, Garton	of Warren Dale tow	vards Sledmere Field Farm
DESIGNATION:	Scheduled Monument (No. 21238)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Round barrow 350m south east of Low Fa	arm, Garton	
DESIGNATION:	Scheduled Monument (No. 21210)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Round barrow 400m south west of Low F	arm, Garton	
DESIGNATION:	Scheduled Monument (No. 21216)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Round barrow 420m south west of Low F	arm, Garton	
DESIGNATION:	Scheduled Monument (No. 21217)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Round barrow 440m south west of Low F	arm, Garton	
DESIGNATION:	Scheduled Monument (No. 21214)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Round barrow 450m south west of Low F	arm, Garton	
DESIGNATION:	Scheduled Monument (No. 21213)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Round barrow 500m south east of Low Fo	arm, Garton	
DESIGNATION:	Scheduled Monument (No. 21211)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Round barrow 500m south of Low Farm, 0	Garton	
DESIGNATION:	Scheduled Monument (No. 21212)	CONDITION:	Extensive significant problems i.e. under plough, collapse
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
	Private		Keith Miller 01904 601990
DWNERSHIP:	riivate	CONTACT:	Reiti i illier 01704 601770
TITE NAME:	Round barrow 700m south of Low Farm, 0	Garton	
DESIGNATION:	Scheduled Monument (No. 21208)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Round barrow 700m south of Low Farm, 0	Garton	
DESIGNATION:	Scheduled Monument (No. 21215)	CONDITION:	Extensive significant problems
SESSIW MICHA	Schooling Floridificite (140, 21213)	CONDITION:	i.e. under plough, collapse
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
JWINERSHIP:	Titvate	CONTACT:	Return liller 01704 001770
SITE NAME:	Round barrow 750m south of Low Farm, 0	Garton	
DESIGNATION:	Scheduled Monument (No. 21209)	CONDITION:	Extensive significant problems i.e. under plough, collapse
			Declining
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
PRINCIPAL VULNERABILITY: OWNERSHIP:	Arable ploughing Private	trend: contact:	Keith Miller 01904 601990
		CONTACT:	Keith Miller 01904 601990
OWNERSHIP: SITE NAME:	Private	CONTACT:	Keith Miller 01904 601990  a, Goodmanham  Extensive significant problems
OWNERSHIP: ITE NAME: DESIGNATION:	Bowl barrow 1000m north east of Goodm Scheduled Monument (No. 21168)	contact: nanham Wold Farm condition:	Keith Miller 01904 601990  a, Goodmanham  Extensive significant problems i.e. under plough, collapse
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Private  Bowl barrow 1000m north east of Goodm	contact:	Keith Miller 01904 601990  a, Goodmanham  Extensive significant problems
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Bowl barrow 1000m north east of Goodm Scheduled Monument (No. 21168)  Arable ploughing	contact:  nanham Wold Farm  condition:  trend:  contact:	Keith Miller 01904 601990  A, Goodmanham  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990
DWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  SITE NAME:	Bowl barrow 1000m north east of Goodm Scheduled Monument (No. 21168)  Arable ploughing Private  Bowl barrow 230m south west of Enthorp	contact:  nanham Wold Farm  condition:  trend:  contact:  pe House, Goodma	Keith Miller 01904 601990  A, Goodmanham  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990
DWNERSHIP:  JITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  JITE NAME:	Bowl barrow 1000m north east of Goodm Scheduled Monument (No. 21168)  Arable ploughing Private	contact:  nanham Wold Farm  condition:  trend:  contact:	Keith Miller 01904 601990  A, Goodmanham  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Anham  Extensive significant problems
DWNERSHIP:  JESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  JITE NAME:  DESIGNATION:	Bowl barrow 1000m north east of Goodm Scheduled Monument (No. 21168)  Arable ploughing Private  Bowl barrow 230m south west of Enthorp Scheduled Monument (No. 21152)	CONTACT:  nanham Wold Farm  CONDITION:  TREND:  CONTACT:  DE House, Goodma  CONDITION:	Keith Miller 01904 601990  A, Goodmanham  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Anham  Extensive significant problems i.e. under plough, collapse
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Bowl barrow 1000m north east of Goodm Scheduled Monument (No. 21168)  Arable ploughing Private  Bowl barrow 230m south west of Enthorp Scheduled Monument (No. 21152)  Arable ploughing	CONTACT:  nanham Wold Farm  CONDITION:  TREND:  CONTACT:  De House, Goodma  CONDITION:  TREND:	Keith Miller 01904 601990  A, Goodmanham  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Anham  Extensive significant problems i.e. under plough, collapse Declining
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Bowl barrow 1000m north east of Goodm Scheduled Monument (No. 21168)  Arable ploughing Private  Bowl barrow 230m south west of Enthorp Scheduled Monument (No. 21152)	CONTACT:  nanham Wold Farm  CONDITION:  TREND:  CONTACT:  DE House, Goodma  CONDITION:	Keith Miller 01904 601990  A, Goodmanham  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Anham  Extensive significant problems i.e. under plough, collapse
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:	Bowl barrow 1000m north east of Goodm Scheduled Monument (No. 21168)  Arable ploughing Private  Bowl barrow 230m south west of Enthorp Scheduled Monument (No. 21152)  Arable ploughing	CONTACT:  nanham Wold Farm  CONDITION:  TREND:  CONTACT:  DE House, Goodma  CONDITION:  TREND:  CONTACT:	Keith Miller 01904 601990  A, Goodmanham  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Anham  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DWNERSHIP:  DWNERSHIP:	Bowl barrow 1000m north east of Goodm Scheduled Monument (No. 21168)  Arable ploughing Private  Bowl barrow 230m south west of Enthorp Scheduled Monument (No. 21152)  Arable ploughing Private	CONTACT:  nanham Wold Farm  CONDITION:  TREND:  CONTACT:  DE House, Goodma  CONDITION:  TREND:  CONTACT:	Keith Miller 01904 601990  A, Goodmanham  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Anham  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990
DWNERSHIP: DESIGNATION: DESIGNATION: DWNERSHIP: DESIGNATION: DESIGNATION: DWNERSHIP: DESIGNATION: DWNERSHIP: DWNERSHIP: DWNERSHIP:	Bowl barrow 1000m north east of Goodm Scheduled Monument (No. 21168)  Arable ploughing Private  Bowl barrow 230m south west of Enthorp Scheduled Monument (No. 21152)  Arable ploughing Private  Bowl barrow 550m north east of Goodma	CONTACT:  nanham Wold Farm  CONDITION:  TREND:  CONDITION:  TREND:  CONTACT:  TREND:  CONTACT:	Keith Miller 01904 601990  A, Goodmanham  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Anham  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Goodmanham  Extensive significant problems
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:	Bowl barrow 1000m north east of Goodm Scheduled Monument (No. 21168)  Arable ploughing Private  Bowl barrow 230m south west of Enthorp Scheduled Monument (No. 21152)  Arable ploughing Private  Bowl barrow 550m north east of Goodma Scheduled Monument (No. 21155)	CONTACT:  nanham Wold Farm  CONDITION:  TREND:  CONTACT:  De House, Goodma  CONDITION:  TREND:  CONTACT:  CONTACT:	Keith Miller 01904 601990  A, Goodmanham  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Anham  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Goodmanham  Extensive significant problems i.e. under plough, collapse
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  DESIGNATION:  DWNERSHIP:	Bowl barrow 1000m north east of Goodm Scheduled Monument (No. 21168)  Arable ploughing Private  Bowl barrow 230m south west of Enthorp Scheduled Monument (No. 21152)  Arable ploughing Private  Bowl barrow 550m north east of Goodma Scheduled Monument (No. 21155)  Arable ploughing Private	CONTACT:  nanham Wold Farm  CONDITION:  TREND:  CONTACT:  DE HOUSE, GOODMA  CONDITION:  TREND:  CONTACT:  Anham Wold Farm,  CONDITION:  TREND:  CONTACT:	Keith Miller 01904 601990  A, Goodmanham  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Anham  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Goodmanham  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Keith Miller 01904 601990
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Bowl barrow 1000m north east of Goodm Scheduled Monument (No. 21168)  Arable ploughing Private  Bowl barrow 230m south west of Enthorp Scheduled Monument (No. 21152)  Arable ploughing Private  Bowl barrow 550m north east of Goodma Scheduled Monument (No. 21155)  Arable ploughing Private  Bowl barrow 550m south west of Enthorp	CONTACT:  nanham Wold Farm  CONDITION:  TREND:  CONTACT:  De House, Goodma  CONDITION:  TREND:  CONTACT:  anham Wold Farm,  CONDITION:  TREND:  CONTACT:	Keith Miller 01904 601990  A, Goodmanham  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Anham  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Goodmanham  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Goodmanham  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990
DWNERSHIP: DESIGNATION: DESIGNATION: DWNERSHIP: DESIGNATION:	Bowl barrow 1000m north east of Goodm Scheduled Monument (No. 21168)  Arable ploughing Private  Bowl barrow 230m south west of Enthorp Scheduled Monument (No. 21152)  Arable ploughing Private  Bowl barrow 550m north east of Goodma Scheduled Monument (No. 21155)  Arable ploughing Private	CONTACT:  nanham Wold Farm  CONDITION:  TREND:  CONTACT:  DE HOUSE, GOODMA  CONDITION:  TREND:  CONTACT:  Anham Wold Farm,  CONDITION:  TREND:  CONTACT:	Keith Miller 01904 601990  A, Goodmanham  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Anham  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Goodmanham  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Anham  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  OWNERSHIP:  OWNERSHIP:	Bowl barrow 1000m north east of Goodm Scheduled Monument (No. 21168)  Arable ploughing Private  Bowl barrow 230m south west of Enthorp Scheduled Monument (No. 21152)  Arable ploughing Private  Bowl barrow 550m north east of Goodma Scheduled Monument (No. 21155)  Arable ploughing Private  Bowl barrow 550m south west of Enthorp	CONTACT:  nanham Wold Farm  CONDITION:  TREND:  CONTACT:  De House, Goodma  CONDITION:  TREND:  CONTACT:  anham Wold Farm,  CONDITION:  TREND:  CONTACT:	Keith Miller 01904 601990  A, Goodmanham  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Anham  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Goodmanham  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Goodmanham  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Bowl barrow 700m south west of Enthorp	oe House, Goodma	nham
DESIGNATION:	Scheduled Monument (No. 21153)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Round barrow 730m NNW of Goodmanh	nam Wold Farm, Go	oodmanham
DESIGNATION:	Scheduled Monument (No. 21151)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Twelve bowl barrows 800m north of Goo	dmanham Wold Fa	rm, Goodmanham
DESIGNATION:	Scheduled Monument (No. 21169)	CONDITION:	Extensive significant problems
	,		i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Romano-British villa east of Sandy Lane, 80	00m north west of	Harpham Grange, Harpham
DESIGNATION:	Scheduled Monument (No. 26523)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
	Arable ploughing	TREND:	Declining
PRINCIPAL VULNERABILITY:	7 (lable ploagrilling		
PRINCIPAL VULNERABILITY:  OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
		CONTACT:	Keith Miller 01904 601990
OWNERSHIP:	Private  Park Closes moated lodge, I 30m south we	contact: est of Park Farm, H	Keith Miller 01904 601990  Iolme upon Spalding Moor
OWNERSHIP: SITE NAME:	Private	CONTACT:	Keith Miller 01904 601990  Iolme upon Spalding Moor  Extensive significant problems
OWNERSHIP: SITE NAME:	Private  Park Closes moated lodge, I 30m south we	contact: est of Park Farm, H	Keith Miller 01904 601990  Iolme upon Spalding Moor
OWNERSHIP: SITE NAME: DESIGNATION:	Private  Park Closes moated lodge, I30m south we Scheduled Monument (No. 26611)	est of Park Farm, F	Keith Miller 01904 601990  Iolme upon Spalding Moor  Extensive significant problems i.e. under plough, collapse
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Private  Park Closes moated lodge, I30m south we Scheduled Monument (No. 26611)  Arable ploughing	est of Park Farm, H  CONDITION:  TREND:  CONTACT:	Keith Miller 01904 601990  Iolme upon Spalding Moor  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Private  Park Closes moated lodge, I30m south we Scheduled Monument (No. 26611)  Arable ploughing Private  Hall Garths moated site, immediately south	est of Park Farm, H  CONDITION:  TREND:  CONTACT:  th of St Mary's Chu	Keith Miller 01904 601990  Iolme upon Spalding Moor  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  rch, Hook
DWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  SITE NAME:	Private  Park Closes moated lodge, I30m south we Scheduled Monument (No. 26611)  Arable ploughing Private	est of Park Farm, H  CONDITION:  TREND:  CONTACT:	Keith Miller 01904 601990  Iolme upon Spalding Moor  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  rch, Hook Generally satisfactory
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  SITE NAME:  DESIGNATION:	Private  Park Closes moated lodge, I30m south we Scheduled Monument (No. 26611)  Arable ploughing Private  Hall Garths moated site, immediately sout Scheduled Monument (No. 30129)	est of Park Farm, H  CONDITION:  TREND:  CONTACT:  th of St Mary's Chu	Keith Miller 01904 601990  Iolme upon Spalding Moor  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  rch, Hook Generally satisfactory
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Private  Park Closes moated lodge, I30m south we Scheduled Monument (No. 26611)  Arable ploughing Private  Hall Garths moated site, immediately south	est of Park Farm, H  CONDITION:  TREND:  CONTACT:  Ch of St Mary's Chu  CONDITION:	Keith Miller 01904 601990  lolme upon Spalding Moor  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  rch, Hook  Generally satisfactory but with significant localised problems
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Private  Park Closes moated lodge, I30m south we Scheduled Monument (No. 26611)  Arable ploughing Private  Hall Garths moated site, immediately sout Scheduled Monument (No. 30129)  Drainage/dewatering	est of Park Farm, H  CONDITION:  TREND:  CONTACT:  CONDITION:  TREND:  CONDITION:  TREND:  CONTACT:	Keith Miller 01904 601990  Iolme upon Spalding Moor  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  rch, Hook  Generally satisfactory but with significant localised problems Declining
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  OWNERSHIP:	Private  Park Closes moated lodge, I30m south we Scheduled Monument (No. 26611)  Arable ploughing Private  Hall Garths moated site, immediately sout Scheduled Monument (No. 30129)  Drainage/dewatering Private  Bowl barrow 230m south west of High Barrow 230m south West Ontology 2	est of Park Farm, H CONDITION:  TREND: CONTACT:  Ch of St Mary's Chu CONDITION:  TREND: CONTACT:	Keith Miller 01904 601990  Iolme upon Spalding Moor  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  rch, Hook  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  DESIGNATION:  DESIGNATION:	Private  Park Closes moated lodge, I30m south we Scheduled Monument (No. 26611)  Arable ploughing Private  Hall Garths moated site, immediately sout Scheduled Monument (No. 30129)  Drainage/dewatering Private  Bowl barrow 230m south west of High Basscheduled Monument (No. 21112)	est of Park Farm, H  CONDITION:  TREND: CONTACT:  CONDITION:  TREND: CONTACT:  TREND: CONTACT:  CONTACT:	Keith Miller 01904 601990  Iolme upon Spalding Moor  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  rch, Hook  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  OWNERSHIP:	Private  Park Closes moated lodge, I30m south we Scheduled Monument (No. 26611)  Arable ploughing Private  Hall Garths moated site, immediately sout Scheduled Monument (No. 30129)  Drainage/dewatering Private  Bowl barrow 230m south west of High Base Scheduled Monument (No. 21112)  Arable ploughing	est of Park Farm, H CONDITION:  TREND: CONTACT:  Ch of St Mary's Chu CONDITION:  TREND: CONTACT:	Keith Miller 01904 601990  Iolme upon Spalding Moor  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  rch, Hook  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  DESIGNATION:  DESIGNATION:	Private  Park Closes moated lodge, I30m south we Scheduled Monument (No. 26611)  Arable ploughing Private  Hall Garths moated site, immediately sout Scheduled Monument (No. 30129)  Drainage/dewatering Private  Bowl barrow 230m south west of High Basscheduled Monument (No. 21112)	est of Park Farm, H  CONDITION:  TREND: CONTACT:  CONDITION:  TREND: CONTACT:  TREND: CONTACT:  CONTACT:	Keith Miller 01904 601990  Iolme upon Spalding Moor  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  rch, Hook  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:	Private  Park Closes moated lodge, I30m south we Scheduled Monument (No. 26611)  Arable ploughing Private  Hall Garths moated site, immediately sout Scheduled Monument (No. 30129)  Drainage/dewatering Private  Bowl barrow 230m south west of High Base Scheduled Monument (No. 21112)  Arable ploughing	est of Park Farm, H  CONDITION:  TREND: CONTACT:  CONDITION:  TREND: CONTACT:  TREND: CONDITION:  TREND: CONDITION:  TREND: CONDITION:  TREND: CONDITION:	Keith Miller 01904 601990  Iolme upon Spalding Moor  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  rch, Hook  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  DESIGNATION:  DESIGNATION:  DESIGNATION:  DESIGNATION:  DESIGNATION:  OWNERSHIP:  DESIGNATION:  OWNERSHIP:	Private  Park Closes moated lodge, I30m south we Scheduled Monument (No. 26611)  Arable ploughing Private  Hall Garths moated site, immediately sout Scheduled Monument (No. 30129)  Drainage/dewatering Private  Bowl barrow 230m south west of High Base Scheduled Monument (No. 21112)  Arable ploughing Private	est of Park Farm, H  CONDITION:  TREND: CONTACT:  CONDITION:  TREND: CONTACT:  TREND: CONDITION:  TREND: CONDITION:  TREND: CONDITION:  TREND: CONDITION:	Iolme upon Spalding Moor  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  rch, Hook  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Extensive significant problems
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Private  Park Closes moated lodge, I30m south we Scheduled Monument (No. 26611)  Arable ploughing Private  Hall Garths moated site, immediately sout Scheduled Monument (No. 30129)  Drainage/dewatering Private  Bowl barrow 230m south west of High Base Scheduled Monument (No. 21112)  Arable ploughing Private  Bowl barrow 400m NNW of East Greeny	est of Park Farm, H  CONDITION:  TREND: CONTACT:  Ch of St Mary's Chu  CONDITION:  TREND: CONTACT:  TREND: CONDITION:  TREND: CONDITION:  TREND: CONDITION:  TREND: CONTACT:	Iolme upon Spalding Moor  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  rch, Hook  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

CA LB/LBs NP RPG SM/SMs UA WHS

SITE NAME:	Bowl barrow 780m north east of Waterma	anhole Reservoir, H	Huggate		
DESIGNATION:	Scheduled Monument (No. 26552)	CONDITION:	Extensive significant problems i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
DWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990		
TITE NAME:	Bowl barrow on Huggate Pasture, 350m north east of Pasture Dale Plantation, Huggate				
DESIGNATION:	Scheduled Monument (No. 26556)	CONDITION:	Extensive significant problems i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
DWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990		
ITE NAME:	Bowl barrow on Huggate Pasture, 450m N	INE of Pasture Dal	e Plantation, Huggate		
DESIGNATION:	Scheduled Monument (No. 26555)	CONDITION:	Extensive significant problems i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
DWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990		
ZVVI 4ELOFIII.	(Tivace	CONTACT:	TOTALL MICE 01701 001770		
SITE NAME:	Bowl barrow on Huggate Pasture, 500m no	orth of Pasture Da	le Plantation, Huggate		
DESIGNATION:	Scheduled Monument (No. 26554)	CONDITION:	Extensive significant problems i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990		
SITE NAME:	Bowl barrow on Huggate Wold, 400m NN	W of Watermanho	ole Reservoir, Huggate		
DESIGNATION:	Scheduled Monument (No. 26549)	CONDITION:	Extensive significant problems		
	5611656166 / 16116116 (1 to: 255 17)	20112111011	i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
	·		Keith Miller 01904 601990		
DWNERSHIP:	Private	CONTACT:	Keith Miller 01704 601770		
OWNERSHIP:	Private	CONTACT:	Reith Miller 01704 601770		
	Bowl barrow on Huggate Wold, 460m WN				
ITE NAME:			ner of Horsedale Plantation, Huggate Extensive significant problems		
SITE NAME:	Bowl barrow on Huggate Wold, 460m WN Scheduled Monument (No. 26546)	IW of western cor	ner of Horsedale Plantation, Huggate  Extensive significant problems i.e. under plough, collapse		
ite name: Designation:	Bowl barrow on Huggate Wold, 460m WN Scheduled Monument (No. 26546) Arable ploughing	IW of western cor	ner of Horsedale Plantation, Huggate  Extensive significant problems i.e. under plough, collapse  Declining		
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Bowl barrow on Huggate Wold, 460m WN Scheduled Monument (No. 26546)	IW of western cor	ner of Horsedale Plantation, Huggate  Extensive significant problems i.e. under plough, collapse		
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Bowl barrow on Huggate Wold, 460m WN Scheduled Monument (No. 26546) Arable ploughing	ONDITION:  TREND:  CONTACT:	ner of Horsedale Plantation, Huggate  Extensive significant problems i.e. under plough, collapse  Declining  Keith Miller 01904 601990		
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  SITE NAME:	Bowl barrow on Huggate Wold, 460m WN Scheduled Monument (No. 26546)  Arable ploughing Private  Bowl barrow on Huggate Wold, 480m nor	ONDITION:  TREND:  CONTACT:	ner of Horsedale Plantation, Huggate  Extensive significant problems i.e. under plough, collapse  Declining  Keith Miller 01904 601990		
DESIGNATION: PRINCIPAL VULNERABILITY: DWNERSHIP: SITE NAME:	Bowl barrow on Huggate Wold, 460m WN Scheduled Monument (No. 26546) Arable ploughing Private	IW of western cor  CONDITION:  TREND:  CONTACT:  th of Watermanhol	ner of Horsedale Plantation, Huggate  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  de Reservoir, Huggate		
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  SITE NAME:  DESIGNATION:	Bowl barrow on Huggate Wold, 460m WN Scheduled Monument (No. 26546)  Arable ploughing Private  Bowl barrow on Huggate Wold, 480m nor	IW of western cor  CONDITION:  TREND:  CONTACT:  th of Watermanhol	ner of Horsedale Plantation, Huggate  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Reservoir, Huggate Extensive significant problems		
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Bowl barrow on Huggate Wold, 460m WN Scheduled Monument (No. 26546)  Arable ploughing Private  Bowl barrow on Huggate Wold, 480m nor Scheduled Monument (No. 26550)	IW of western cor  CONDITION:  TREND:  CONTACT:  th of Watermanhol  CONDITION:	ner of Horsedale Plantation, Huggate  Extensive significant problems i.e. under plough, collapse  Declining Keith Miller 01904 601990  Re Reservoir, Huggate  Extensive significant problems i.e. under plough, collapse		
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Bowl barrow on Huggate Wold, 460m WN Scheduled Monument (No. 26546)  Arable ploughing Private  Bowl barrow on Huggate Wold, 480m nor Scheduled Monument (No. 26550)  Arable ploughing Private	IW of western cor  CONDITION:  TREND:  CONTACT:  th of Watermanhol  CONDITION:  TREND:  CONTACT:	ner of Horsedale Plantation, Huggate  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Re Reservoir, Huggate Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990		
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Bowl barrow on Huggate Wold, 460m WN Scheduled Monument (No. 26546)  Arable ploughing Private  Bowl barrow on Huggate Wold, 480m nor Scheduled Monument (No. 26550)  Arable ploughing Private  Bowl barrow on Huggate Wold, 500m NN	IW of western cor  CONDITION:  TREND:  CONTACT:  th of Watermanhol  CONDITION:  TREND:  CONTACT:  W of Horsedale P	ner of Horsedale Plantation, Huggate  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Reservoir, Huggate Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Jantation, Huggate		
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Bowl barrow on Huggate Wold, 460m WN Scheduled Monument (No. 26546)  Arable ploughing Private  Bowl barrow on Huggate Wold, 480m nor Scheduled Monument (No. 26550)  Arable ploughing Private	IW of western cor  CONDITION:  TREND:  CONTACT:  th of Watermanhol  CONDITION:  TREND:  CONTACT:	ner of Horsedale Plantation, Huggate  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Re Reservoir, Huggate Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Plantation, Huggate Extensive significant problems		
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  OWNERSHIP:  SITE NAME:  DESIGNATION:  SITE NAME:  DESIGNATION:  DESIGNATION:	Bowl barrow on Huggate Wold, 460m WN Scheduled Monument (No. 26546)  Arable ploughing Private  Bowl barrow on Huggate Wold, 480m nor Scheduled Monument (No. 26550)  Arable ploughing Private  Bowl barrow on Huggate Wold, 500m NN Scheduled Monument (No. 26542)	IW of western cor  CONDITION:  TREND: CONTACT:  th of Watermanhol  CONDITION:  TREND: CONTACT:  W of Horsedale P  CONDITION:	ner of Horsedale Plantation, Huggate  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Reservoir, Huggate Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Jantation, Huggate Extensive significant problems i.e. under plough, collapse		
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Bowl barrow on Huggate Wold, 460m WN Scheduled Monument (No. 26546)  Arable ploughing Private  Bowl barrow on Huggate Wold, 480m nor Scheduled Monument (No. 26550)  Arable ploughing Private  Bowl barrow on Huggate Wold, 500m NN	IW of western cor  CONDITION:  TREND:  CONTACT:  th of Watermanhol  CONDITION:  TREND:  CONTACT:  W of Horsedale P	ner of Horsedale Plantation, Huggate  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Re Reservoir, Huggate Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Plantation, Huggate Extensive significant problems		

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Bowl barrow on Huggate Wold, 580m nor	th west of Horsed	ale Plantation, Huggate
DESIGNATION:	Scheduled Monument (No. 26545)	CONDITION:	Extensive significant problems
	A 11 1 1		i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
ITE NAME:	Bowl barrow on Huggate Wold, 600m NN	IW of Horsedale P	lantation, Huggate
DESIGNATION:	Scheduled Monument (No. 26541)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow on Huggate Wold, 600m wes	st of Horsedale Pla	ntation, Huggate
DESIGNATION:	Scheduled Monument (No. 26547)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
		22	
SITE NAME:	Bowl barrow on Huggate Wold, 700m NN	IW of Watermanho	ole Reservoir, Huggate
DESIGNATION:	Scheduled Monument (No. 26551)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
TRINCIPAL VULINERABILITI:			
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
	, , ,	CONTACT:	Keith Miller 01904 601990
ownership:	Private	CONTACT:	Keith Miller 01904 601990  ale Plantation, Huggate  Extensive significant problems
OWNERSHIP: SITE NAME: DESIGNATION:	Private  Bowl barrow on Huggate Wold, 700m nor	contact:	Keith Miller 01904 601990  ale Plantation, Huggate
OWNERSHIP: SITE NAME:	Bowl barrow on Huggate Wold, 700m nor Scheduled Monument (No. 26544)	contact:  th west of Horsed:  condition:	Keith Miller 01904 601990  ale Plantation, Huggate  Extensive significant problems i.e. under plough, collapse
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Bowl barrow on Huggate Wold, 700m nor Scheduled Monument (No. 26544)  Arable ploughing	contact:  th west of Horsed:  condition:  trend:  contact:	Keith Miller 01904 601990  ale Plantation, Huggate  Extensive significant problems i.e. under plough, collapse  Declining  Keith Miller 01904 601990
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:	Bowl barrow on Huggate Wold, 700m nor Scheduled Monument (No. 26544)  Arable ploughing Private	contact:  th west of Horsed:  condition:  trend:  contact:	Keith Miller 01904 601990  ale Plantation, Huggate  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Reservoir, Huggate  Extensive significant problems
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  SITE NAME:  DESIGNATION:	Bowl barrow on Huggate Wold, 700m nor Scheduled Monument (No. 26544)  Arable ploughing Private  Bowl barrow on Huggate Wold, 840m ENI Scheduled Monument (No. 26548)	CONTACT:  th west of Horsed:  CONDITION:  TREND:  CONTACT:  E of Watermanhole  CONDITION:	Keith Miller 01904 601990  ale Plantation, Huggate  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Reservoir, Huggate  Extensive significant problems i.e. under plough, collapse
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Bowl barrow on Huggate Wold, 700m nor Scheduled Monument (No. 26544)  Arable ploughing Private  Bowl barrow on Huggate Wold, 840m ENI	th west of Horsed:  CONDITION:  TREND:  CONTACT:  E of Watermanhole	Keith Miller 01904 601990  ale Plantation, Huggate  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Reservoir, Huggate  Extensive significant problems
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Bowl barrow on Huggate Wold, 700m nor Scheduled Monument (No. 26544)  Arable ploughing Private  Bowl barrow on Huggate Wold, 840m ENI Scheduled Monument (No. 26548)  Arable ploughing Private	CONTACT:  th west of Horsed:  CONDITION:  TREND:  CONTACT:  E of Watermanhole  CONDITION:  TREND:  CONTACT:	Keith Miller 01904 601990  ale Plantation, Huggate  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Reservoir, Huggate  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  OWNERSHIP:	Bowl barrow on Huggate Wold, 700m nor Scheduled Monument (No. 26544)  Arable ploughing Private  Bowl barrow on Huggate Wold, 840m ENI Scheduled Monument (No. 26548)  Arable ploughing Private  Round barrow 240m south west of High E	CONTACT:  th west of Horsed:  CONDITION:  TREND:  CONTACT:  E of Watermanhole  CONDITION:  TREND:  CONTACT:  Sarn Farm, Huggate	Keith Miller 01904 601990  ale Plantation, Huggate  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Reservoir, Huggate  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DWNERSHIP:  SITE NAME:	Bowl barrow on Huggate Wold, 700m nor Scheduled Monument (No. 26544)  Arable ploughing Private  Bowl barrow on Huggate Wold, 840m ENI Scheduled Monument (No. 26548)  Arable ploughing Private  Round barrow 240m south west of High E Scheduled Monument (No. 21111)	CONTACT:  th west of Horsed:  CONDITION:  TREND:  CONTACT:  E of Watermanhole  CONDITION:  TREND:  CONTACT:	Keith Miller 01904 601990  ale Plantation, Huggate  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Reservoir, Huggate  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Bowl barrow on Huggate Wold, 700m nor Scheduled Monument (No. 26544)  Arable ploughing Private  Bowl barrow on Huggate Wold, 840m ENI Scheduled Monument (No. 26548)  Arable ploughing Private  Round barrow 240m south west of High E Scheduled Monument (No. 21111)  Arable ploughing	CONTACT:  th west of Horsed:  CONDITION:  TREND:  CONTACT:  E of Watermanhole  CONDITION:  TREND:  CONTACT:  Sarn Farm, Huggate	Keith Miller 01904 601990  ale Plantation, Huggate  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Reservoir, Huggate  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Declining Lextensive significant problems i.e. under plough, collapse Declining
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  DESIGNATION:  DESIGNATION:	Bowl barrow on Huggate Wold, 700m nor Scheduled Monument (No. 26544)  Arable ploughing Private  Bowl barrow on Huggate Wold, 840m ENI Scheduled Monument (No. 26548)  Arable ploughing Private  Round barrow 240m south west of High E Scheduled Monument (No. 21111)	CONTACT:  th west of Horsed:  CONDITION:  TREND:  CONTACT:  E of Watermanhole  CONDITION:  TREND:  CONTACT:  CONTACT:	Keith Miller 01904 601990  ale Plantation, Huggate  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Reservoir, Huggate  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:	Bowl barrow on Huggate Wold, 700m nor Scheduled Monument (No. 26544)  Arable ploughing Private  Bowl barrow on Huggate Wold, 840m ENI Scheduled Monument (No. 26548)  Arable ploughing Private  Round barrow 240m south west of High E Scheduled Monument (No. 21111)  Arable ploughing	CONTACT:  th west of Horsed:  CONDITION:  TREND:  CONTACT:  E of Watermanhole  CONDITION:  TREND:  CONTACT:  Sarn Farm, Huggate  CONDITION:  TREND:  CONTACT:	Keith Miller 01904 601990  ale Plantation, Huggate  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Reservoir, Huggate  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Keith Miller 01904 601990
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  DESIGNATION:  DESIGNATION:  DESIGNATION:  DESIGNATION:  DESIGNATION:  OWNERSHIP:  OWNERSHIP:	Bowl barrow on Huggate Wold, 700m nor Scheduled Monument (No. 26544)  Arable ploughing Private  Bowl barrow on Huggate Wold, 840m ENI Scheduled Monument (No. 26548)  Arable ploughing Private  Round barrow 240m south west of High E Scheduled Monument (No. 21111)  Arable ploughing Private	CONTACT:  th west of Horsed:  CONDITION:  TREND:  CONTACT:  E of Watermanhole  CONDITION:  TREND:  CONTACT:  Sarn Farm, Huggate  CONDITION:  TREND:  CONTACT:	Ale Plantation, Huggate  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Reservoir, Huggate  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Bowl barrow on Huggate Wold, 700m nor Scheduled Monument (No. 26544)  Arable ploughing Private  Bowl barrow on Huggate Wold, 840m ENI Scheduled Monument (No. 26548)  Arable ploughing Private  Round barrow 240m south west of High E Scheduled Monument (No. 21111)  Arable ploughing Private  Round barrow 320m south west of High E Scheduled Monument (No. 21111)	CONTACT:  th west of Horsed:  CONDITION:  TREND:  CONTACT:  E of Watermanhole  CONDITION:  TREND:  CONTACT:  Barn Farm, Huggate  CONDITION:  TREND:  CONTACT:	Keith Miller 01904 601990  ale Plantation, Huggate  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Reservoir, Huggate  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Keith Miller 01904 601990

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

SITE NAME:	Round barrow 360m south west of High E	Barn Farm, Huggate	2
DESIGNATION:	Scheduled Monument (No. 21113)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Round barrow 380m south west of High E	Barn Farm, Huggate	}
DESIGNATION:	Scheduled Monument (No. 21114)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Round barrow 390m south west of High E	Barn Farm, Huggate	3
DESIGNATION:	Scheduled Monument (No. 21109)	CONDITION:	Extensive significant problems
	,		i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Section of a single and double linear boun and Harper Dale, north west of Northfield		e Dale, and the junctions of Holm Dale
DESIGNATION:	Scheduled Monument (No. 26581)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Section of linear boundary dyke on Cow I	Moor, Millington Da	ale, Huggate
DESIGNATION:	Scheduled Monument (No. 26586)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Section of linear boundary dyke south of l	Middleham Plantati	on and Harper Dale Plantation, Huggate
DESIGNATION:	Scheduled Monument (No. 26584)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Sections of linear boundary dyke in Cow l	Dale Plantation, Ral	bbit Dale and Oxland Plantation, Huggat
DESIGNATION:	Scheduled Monument (No. 26585)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Two bowl barrows on Huggate Wold, 600	m north west of H	orsedale Plantation, Huggate
DESIGNATION:	Scheduled Monument (No. 26543)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Shaw Fosse moated site, Humbleton		
DESIGNATION:	Scheduled Monument (No. 21205)	CONDITION:	Generally satisfactory
	, , ,		but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Nunnery Hill and adjacent earthworks, Litt	le Kelk, Kelk	
DESIGNATION:	Scheduled Monument (No. ER196)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Gallows Hill round barrow, Kilham		
DESIGNATION:	Scheduled Monument (No. 33581)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Iron Age barrow cemetery, Kilham		
DESIGNATION:	Scheduled Monument (No. ER223)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
			D I''
PRINCIPAL VULNERABILITY:	Metal detecting	TREND:	Declining
PRINCIPAL VULNERABILITY: OWNERSHIP:	Metal detecting Private	TREND: CONTACT:	Keith Miller 01904 601990
OWNERSHIP:	<u> </u>	CONTACT:	Keith Miller 01904 601990
OWNERSHIP: SITE NAME:	Private  Round barrow 250m north east of Painstho	contact:	Keith Miller 01904 601990 es, Kirby Underdale
OWNERSHIP: SITE NAME:	Private	CONTACT:	Keith Miller 01904 601990  es, Kirby Underdale  Extensive significant problems
OWNERSHIP: SITE NAME: DESIGNATION:	Private  Round barrow 250m north east of Painsthe Scheduled Monument (No. 21088)	CONTACT:  orpe Wold Cottag  CONDITION:	Keith Miller 01904 601990  es, Kirby Underdale  Extensive significant problems i.e. under plough, collapse
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Round barrow 250m north east of Painsthe Scheduled Monument (No. 21088) Arable ploughing	CONTACT:  orpe Wold Cottag  CONDITION:  TREND:	es, Kirby Underdale  Extensive significant problems i.e. under plough, collapse Declining
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Private  Round barrow 250m north east of Painsthe Scheduled Monument (No. 21088)	CONTACT:  orpe Wold Cottag  CONDITION:	Keith Miller 01904 601990  es, Kirby Underdale  Extensive significant problems i.e. under plough, collapse
	Round barrow 250m north east of Painsthe Scheduled Monument (No. 21088) Arable ploughing	CONTACT:  orpe Wold Cottag  CONDITION:  TREND:  CONTACT:	es, Kirby Underdale  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990
DWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  SITE NAME:	Round barrow 250m north east of Painsthe Scheduled Monument (No. 21088)  Arable ploughing Private	CONTACT:  orpe Wold Cottag  CONDITION:  TREND:  CONTACT:	es, Kirby Underdale  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990
DWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  SITE NAME:	Private  Round barrow 250m north east of Painstho Scheduled Monument (No. 21088)  Arable ploughing Private  Round barrow 350m south east of Fordhan	CONTACT:  orpe Wold Cottag  CONDITION:  TREND:  CONTACT:  m Farm, Kirby Unc	Keith Miller 01904 601990  es, Kirby Underdale  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Jerdale
DWNERSHIP:  JESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  JETE NAME:  DESIGNATION:	Private  Round barrow 250m north east of Painstho Scheduled Monument (No. 21088)  Arable ploughing Private  Round barrow 350m south east of Fordhan	CONTACT:  orpe Wold Cottag  CONDITION:  TREND:  CONTACT:  m Farm, Kirby Unc	es, Kirby Underdale  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  derdale  Extensive significant problems
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  ITE NAME:  DESIGNATION:	Round barrow 250m north east of Painstho Scheduled Monument (No. 21088)  Arable ploughing Private  Round barrow 350m south east of Fordhar Scheduled Monument (No. 21087)	CONTACT:  orpe Wold Cottag  CONDITION:  TREND:  CONTACT:  m Farm, Kirby Unc	es, Kirby Underdale  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Jerdale  Extensive significant problems i.e. under plough, collapse
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  ITE NAME:  DESIGNATION:	Round barrow 250m north east of Painstho Scheduled Monument (No. 21088)  Arable ploughing Private  Round barrow 350m south east of Fordhar Scheduled Monument (No. 21087)  Arable ploughing	CONTACT:  orpe Wold Cottag  CONDITION:  TREND:  CONTACT:  m Farm, Kirby Unc  CONDITION:  TREND:	es, Kirby Underdale  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Jerdale  Extensive significant problems i.e. under plough, collapse Declining
DWNERSHIP: DESIGNATION: PRINCIPAL VULNERABILITY: DWNERSHIP: DESIGNATION: PRINCIPAL VULNERABILITY: DWNERSHIP:	Round barrow 250m north east of Painstho Scheduled Monument (No. 21088)  Arable ploughing Private  Round barrow 350m south east of Fordhar Scheduled Monument (No. 21087)  Arable ploughing	CONTACT:  orpe Wold Cottag  CONDITION:  TREND:  CONTACT:  TREND:  CONTACT:	es, Kirby Underdale  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Jerdale  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DWNERSHIP:  DWNERSHIP:	Round barrow 250m north east of Painstho Scheduled Monument (No. 21088)  Arable ploughing Private  Round barrow 350m south east of Fordhar Scheduled Monument (No. 21087)  Arable ploughing Private	CONTACT:  orpe Wold Cottag  CONDITION:  TREND:  CONTACT:  TREND:  CONTACT:	es, Kirby Underdale  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Berdale  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  es, Kirby Underdale Generally unsatisfactory
DWNERSHIP: DESIGNATION: DESIGNATION: DWNERSHIP: DESIGNATION: DESIGNATION: DESIGNATION: DWNERSHIP: DESIGNATION: DWNERSHIP:	Round barrow 250m north east of Painstho Scheduled Monument (No. 21088)  Arable ploughing Private  Round barrow 350m south east of Fordhar Scheduled Monument (No. 21087)  Arable ploughing Private  Round barrow 500m south east of Painstho Scheduled Monument (No. 21099)	CONTACT:  orpe Wold Cottage  CONDITION:  TREND: CONTACT:  m Farm, Kirby Unc  CONDITION:  TREND: CONTACT:  contact:  contact:	es, Kirby Underdale  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Berdale  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  es, Kirby Underdale  Generally unsatisfactory with major localised problems
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Round barrow 250m north east of Painstho Scheduled Monument (No. 21088)  Arable ploughing Private  Round barrow 350m south east of Fordhar Scheduled Monument (No. 21087)  Arable ploughing Private  Round barrow 500m south east of Painstho Scheduled Monument (No. 21099)  Arable clipping	CONTACT:  orpe Wold Cottage  CONDITION:  TREND:  CONTACT:  TREND:  CONDITION:  TREND:  CONTACT:  Orpe Wold Cottage  CONDITION:  TREND:  TREND:  TREND:  TREND:  TREND:  TREND:	es, Kirby Underdale  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  derdale  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  es, Kirby Underdale  Generally unsatisfactory with major localised problems Declining
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:	Round barrow 250m north east of Painstho Scheduled Monument (No. 21088)  Arable ploughing Private  Round barrow 350m south east of Fordhar Scheduled Monument (No. 21087)  Arable ploughing Private  Round barrow 500m south east of Painstho Scheduled Monument (No. 21099)	CONTACT:  orpe Wold Cottage  CONDITION:  TREND: CONTACT:  m Farm, Kirby Unc  CONDITION:  TREND: CONTACT:  contact:  contact:	es, Kirby Underdale  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Berdale  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  es, Kirby Underdale  Generally unsatisfactory with major localised problems
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  DESIGNATION:  DESIGNATION:  DESIGNATION:  DESIGNATION:  DESIGNATION:  OWNERSHIP:	Round barrow 250m north east of Painstho Scheduled Monument (No. 21088)  Arable ploughing Private  Round barrow 350m south east of Fordhar Scheduled Monument (No. 21087)  Arable ploughing Private  Round barrow 500m south east of Painstho Scheduled Monument (No. 21099)  Arable clipping	CONTACT:  orpe Wold Cottage  CONDITION:  TREND: CONTACT:  m Farm, Kirby Unc  CONDITION:  TREND: CONTACT:  orpe Wold Cottage  CONDITION:  TREND: CONTACT:	es, Kirby Underdale  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Berdale  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  es, Kirby Underdale  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DWNERSHIP:	Private  Round barrow 250m north east of Painstho Scheduled Monument (No. 21088)  Arable ploughing Private  Round barrow 350m south east of Fordhar Scheduled Monument (No. 21087)  Arable ploughing Private  Round barrow 500m south east of Painstho Scheduled Monument (No. 21099)  Arable clipping Private  Round barrow 600m north east of Painstho	CONTACT:  orpe Wold Cottage  CONDITION:  TREND: CONTACT:  TREND: CONTACT:  Orpe Wold Cottage  CONDITION:  TREND: CONTACT:	es, Kirby Underdale  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Berdale  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  es, Kirby Underdale  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  es, Kirby Underdale
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DWNERSHIP:	Private  Round barrow 250m north east of Painstho Scheduled Monument (No. 21088)  Arable ploughing Private  Round barrow 350m south east of Fordhar Scheduled Monument (No. 21087)  Arable ploughing Private  Round barrow 500m south east of Painstho Scheduled Monument (No. 21099)  Arable clipping Private	CONTACT:  orpe Wold Cottage  CONDITION:  TREND: CONTACT:  TREND: CONTACT:  Orpe Wold Cottage  CONDITION:  TREND: CONTACT:  TREND: CONTACT:  TREND: CONTACT:	es, Kirby Underdale  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  derdale  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  es, Kirby Underdale  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  es, Kirby Underdale Extensive significant problems Declining Keith Miller 01904 601990
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Private  Round barrow 250m north east of Painstho Scheduled Monument (No. 21088)  Arable ploughing Private  Round barrow 350m south east of Fordhar Scheduled Monument (No. 21087)  Arable ploughing Private  Round barrow 500m south east of Painstho Scheduled Monument (No. 21099)  Arable clipping Private  Round barrow 600m north east of Painstho	CONTACT:  orpe Wold Cottage  CONDITION:  TREND: CONTACT:  TREND: CONTACT:  Orpe Wold Cottage  CONDITION:  TREND: CONTACT:  TREND: CONTACT:  TREND: CONTACT:	es, Kirby Underdale  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Berdale  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  es, Kirby Underdale  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  es, Kirby Underdale

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Round barrow 850m north east of Wayrham Farm, Kirby Underdale				
DESIGNATION:	Scheduled Monument (No. 21091)	CONDITION:	Extensive significant problems i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990		
SITE NAME:	Round barrow 900m north east of Wayrham Farm, Kirby Underdale				
DESIGNATION:	Scheduled Monument (No. 21092)	CONDITION:	Extensive significant problems i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990		
SITE NAME:	Round barrow south east of South Wold	Farm, Kirby Underd	dale		
designation:	Scheduled Monument (No. 21055)	CONDITION:	Generally satisfactory		
	Amble dinning		but with significant localised problems		
PRINCIPAL VULNERABILITY:	Arable clipping Private	TREND:	Declining Keith Miller 01904 601990		
OWNERSHIP:	rivate	CONTACT:	KEILITTIIIELUT7U <del>T</del> 00177U		
SITE NAME:	Eastern bowl barrow of a pair at crossroa Ikm NNW of Eastburn Warren Farm, Kirl		Hill,		
DESIGNATION:	Scheduled Monument (No. 26531)	CONDITION:	Extensive significant problems i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990		
SITE NAME:	Western bowl barrow of a pair east of Cr	raike Hill, Ikm NN\	W of Eastburn Warren Farm, Kirkburn		
DESIGNATION:	Scheduled Monument (No. 26530)	CONDITION:	Extensive significant problems		
			i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990		
SITE NAME:	Moated site at Metham Hall Farm, Laxton				
DESIGNATION:	Scheduled Monument (No. 23813)	CONDITION:	Generally unsatisfactory		
			with major localised problems		
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining		
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990		
SITE NAME:	Moated site 100m north of Parkhouse Fai	rm, Leconfield			
DESIGNATION:	Scheduled Monument (No. 21174)	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining		
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990		
SITE NAME:	Moated site 310m north east of Scorboro	ough church, Leconf	îeld		
DESIGNATION:	Scheduled Monument (No. 26595)	CONDITION:	Generally unsatisfactory with major localised problems		
			,		
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining		
PRINCIPAL VULNERABILITY:  OWNERSHIP:	Scrub / tree growth Private	TREND: CONTACT:	Declining Keith Miller 01904 601990		

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Moated site 550m south east of Scorboro	ugh Hall, Leconfield	ı
DESIGNATION:	Scheduled Monument (No. 26608)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Moated site of Leconfield Castle, Leconfie	ld	
DESIGNATION:	Scheduled Monument (No. 21172)	CONDITION:	Generally satisfactory
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	but with significant localised problems  Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SVVIVEI GI III .	Timace	CONT.CT.	
SITE NAME:	Hayholme moated site, Leven		
DESIGNATION:	Scheduled Monument (No. 21184)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Hall Garth motte and bailey, Lockington		
DESIGNATION:	Scheduled Monument (No. 35484)	CONDITION:	Generally satisfactory
	,		but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Cleaving Hall moated site, Londesborough		
DESIGNATION:	Scheduled Monument (No. 21194)	CONDITION:	Extensive significant problems
	Seriodalea Fronanione (Fronzi III )	20112111011	i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow 100m north east of High Wo	old Farm, Market W	/eighton
designation:	Scheduled Monument (No. 21161)	CONDITION:	Extensive significant problems
DESIGNATION.	Schodura Fioridifficite (FNO. 21101)	CONDITION:	i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow 110m east of High Wold Far	m, Market Weighto	
DESIGNATION:	Scheduled Monument (No. 21162)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow 200m south east of High Wo	old Farm. Market W	eighton
DESIGNATION:	Scheduled Monument (No. 21163)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
2011/2/04/14 14 11 12 12 12	Arabla plaustins		Doclining
PRINCIPAL VULNERABILITY:  OWNERSHIP:	Arable ploughing Private	TREND: CONTACT:	Declining Keith Miller 01904 601990

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Bowl barrow 320m north east of High Wo	old Farm, Market W	/eighton	
DESIGNATION:	Scheduled Monument (No. 21159)	CONDITION:	Extensive significant problems i.e. under plough, collapse	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Bowl barrow 400m south of High Wold Farm, Market Weighton			
DESIGNATION:	Scheduled Monument (No. 21165)	CONDITION:	Extensive significant problems i.e. under plough, collapse	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Bowl barrow 450m north east of High Wo	old Farm, Market W	/eighton	
DESIGNATION:	Scheduled Monument (No. 23827)	CONDITION:	Extensive significant problems i.e. under plough, collapse	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Bowl barrow 450m north of High Wold Fa	arm, Market Weigh	ton	
DESIGNATION:	Scheduled Monument (No. 21157)	CONDITION:	Extensive significant problems i.e. under plough, collapse	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Bowl barrow 550m north of High Wold Fa	arm, Market Weight	ton	
SITE NAME: DESIGNATION:	Bowl barrow 550m north of High Wold Fa	arm, Market Weight	Extensive significant problems	
designation:	Scheduled Monument (No. 21156)	CONDITION:	Extensive significant problems i.e. under plough, collapse	
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 21156)  Arable ploughing	CONDITION:	Extensive significant problems i.e. under plough, collapse Declining	
designation:	Scheduled Monument (No. 21156)	CONDITION:	Extensive significant problems i.e. under plough, collapse	
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 21156)  Arable ploughing	CONDITION:  TREND:  CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990	
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Scheduled Monument (No. 21156)  Arable ploughing Private	CONDITION:  TREND:  CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  rket Weighton  Extensive significant problems	
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:	Scheduled Monument (No. 21156)  Arable ploughing Private  Four bowl barrows 450m south east of H  Scheduled Monument (No. 21167)	CONDITION:  TREND:  CONTACT:  igh Wold Farm, Mail  CONDITION:	Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  rket Weighton  Extensive significant problems i.e. under plough, collapse	
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Scheduled Monument (No. 21156)  Arable ploughing Private  Four bowl barrows 450m south east of H	CONDITION:  TREND:  CONTACT:  igh Wold Farm, Mai	Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  rket Weighton  Extensive significant problems	
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Scheduled Monument (No. 21156)  Arable ploughing Private  Four bowl barrows 450m south east of H Scheduled Monument (No. 21167)  Arable ploughing Private	CONDITION:  TREND: CONTACT:  igh Wold Farm, Mail CONDITION:  TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  rket Weighton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990	
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Scheduled Monument (No. 21156)  Arable ploughing Private  Four bowl barrows 450m south east of H Scheduled Monument (No. 21167)  Arable ploughing Private  Nine round barrows south east of Arras C	CONDITION:  TREND: CONTACT:  igh Wold Farm, Mail CONDITION:  TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  rket Weighton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990	
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Scheduled Monument (No. 21156)  Arable ploughing Private  Four bowl barrows 450m south east of Historian Scheduled Monument (No. 21167)  Arable ploughing Private  Nine round barrows south east of Arras Conscience Scheduled Monument (No. ER58)	CONDITION:  TREND: CONTACT:  igh Wold Farm, Mail CONDITION:  TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  rket Weighton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  /eighton  Extensive significant problems i.e. under plough, collapse	
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Scheduled Monument (No. 21156)  Arable ploughing Private  Four bowl barrows 450m south east of H Scheduled Monument (No. 21167)  Arable ploughing Private  Nine round barrows south east of Arras C Scheduled Monument (No. ER58)  Metal detecting	CONDITION:  TREND: CONTACT:  igh Wold Farm, Mail CONDITION:  TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  rket Weighton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  /eighton  Extensive significant problems i.e. under plough, collapse Declining	
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:	Scheduled Monument (No. 21156)  Arable ploughing Private  Four bowl barrows 450m south east of Historian Scheduled Monument (No. 21167)  Arable ploughing Private  Nine round barrows south east of Arras Conscience of Arras Cons	CONDITION:  TREND: CONTACT:  igh Wold Farm, Mail CONDITION:  TREND: CONTACT:  CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  rket Weighton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  /eighton  Extensive significant problems i.e. under plough, collapse	
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:	Scheduled Monument (No. 21156)  Arable ploughing Private  Four bowl barrows 450m south east of H Scheduled Monument (No. 21167)  Arable ploughing Private  Nine round barrows south east of Arras C Scheduled Monument (No. ER58)  Metal detecting	CONDITION:  TREND: CONTACT:  igh Wold Farm, Mail CONDITION:  TREND: CONTACT:  CONDITION:  TREND: CONDITION:  TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  rket Weighton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  /eighton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990	
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  OWNERSHIP:	Scheduled Monument (No. 21156)  Arable ploughing Private  Four bowl barrows 450m south east of H. Scheduled Monument (No. 21167)  Arable ploughing Private  Nine round barrows south east of Arras C. Scheduled Monument (No. ER58)  Metal detecting Private	CONDITION:  TREND: CONTACT:  igh Wold Farm, Mail CONDITION:  TREND: CONTACT:  CONDITION:  TREND: CONDITION:  TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  rket Weighton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  /eighton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  /et Weighton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990	
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  OWNERSHIP:	Scheduled Monument (No. 21156)  Arable ploughing Private  Four bowl barrows 450m south east of H Scheduled Monument (No. 21167)  Arable ploughing Private  Nine round barrows south east of Arras C Scheduled Monument (No. ER58)  Metal detecting Private  Six bowl barrows 300m north east of High	CONDITION:  TREND: CONTACT:  igh Wold Farm, Mail CONDITION:  TREND: CONTACT:  CONDITION:  TREND: CONDITION:  TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  rket Weighton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  /eighton  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  /eight Miller 01904 601990	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Iron Age barrow group north east of Mido	lleton on the Wold	s, Middleton
DESIGNATION:	Scheduled Monument (No. ER60)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
	Private	CONTACT:	Keith Miller 01904 601990
DWNERSHIP:	Titvate	CONTACT:	Return filler 01701 001770
SITE NAME:	Bowl barrow 340m south east of Waterm	anhole Reservoir, M	1illington
DESIGNATION:	Scheduled Monument (No. 26553)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Dane's Graves, Nafferton		
arachitian.	Schodulad Manument (No. ED42)	CONTRACTOR	Caparally satisfactory
DESIGNATION:	Scheduled Monument (No. ER62)	CONDITION:	Generally satisfactory
DELL'ORDA VALLA INC.	Dumping		but with significant localised problems
PRINCIPAL VULNERABILITY:	Dumping	TREND:	Declining
DWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Five round barrows 750m south east of N	lewbald Lodge, Nev	vbald
DESIGNATION:	Scheduled Monument (No. 21150)	CONDITION:	Extensive significant problems
	(		i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
	Private	INDINU.	
OWNERSHIP:	rrivate	CONTACT:	Keith Miller 01904 601990
OWNERSHIP: SITE NAME:	Round barrow 400m south west of Newb		d
SITE NAME:	Round barrow 400m south west of Newb	ald Lodge, Newbald	Extensive significant problems i.e. under plough, collapse Declining
SITE NAME: DESIGNATION:	Round barrow 400m south west of Newb Scheduled Monument (No. 21146)	ald Lodge, Newbald	Extensive significant problems i.e. under plough, collapse
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Round barrow 400m south west of Newb Scheduled Monument (No. 21146) Arable ploughing	ald Lodge, Newbald  CONDITION:  TREND:  CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990
DESIGNATION: PRINCIPAL VULNERABILITY: DWNERSHIP: SITE NAME:	Round barrow 400m south west of Newb Scheduled Monument (No. 21146)  Arable ploughing Private	ald Lodge, Newbald  CONDITION:  TREND:  CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Extensive significant problems
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNIERSHIP:  SITE NAME:  DESIGNATION:	Round barrow 400m south west of Newb Scheduled Monument (No. 21146)  Arable ploughing Private  Round barrow 550m south east of Newbar Scheduled Monument (No. 21147)	ald Lodge, Newbald  CONDITION:  TREND:  CONTACT:  ald Lodge, Newbald  CONDITION:	Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNERSHIP: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY:	Round barrow 400m south west of Newb Scheduled Monument (No. 21146)  Arable ploughing Private  Round barrow 550m south east of Newba Scheduled Monument (No. 21147)  Arable ploughing	ald Lodge, Newbald  CONDITION:  TREND:  CONTACT:  ald Lodge, Newbald  CONDITION:  TREND:	Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:	Round barrow 400m south west of Newb Scheduled Monument (No. 21146)  Arable ploughing Private  Round barrow 550m south east of Newbar Scheduled Monument (No. 21147)	ald Lodge, Newbald  CONDITION:  TREND:  CONTACT:  ald Lodge, Newbald  CONDITION:	Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Round barrow 400m south west of Newb Scheduled Monument (No. 21146)  Arable ploughing Private  Round barrow 550m south east of Newba Scheduled Monument (No. 21147)  Arable ploughing	ald Lodge, Newbald  CONDITION:  TREND:  CONTACT:  ald Lodge, Newbald  CONDITION:  TREND:  CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:	Round barrow 400m south west of Newb Scheduled Monument (No. 21146)  Arable ploughing Private  Round barrow 550m south east of Newba Scheduled Monument (No. 21147)  Arable ploughing Private	ald Lodge, Newbald  CONDITION:  TREND:  CONTACT:  ald Lodge, Newbald  CONDITION:  TREND:  CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNIERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNIERSHIP:  DWNIERSHIP:	Round barrow 400m south west of Newb Scheduled Monument (No. 21146)  Arable ploughing Private  Round barrow 550m south east of Newba Scheduled Monument (No. 21147)  Arable ploughing Private  Round barrow 600m south east of Newba Scheduled Monument (No. 21148)	ald Lodge, Newbald  CONDITION:  TREND:  CONTACT:  ald Lodge, Newbald  CONDITION:  TREND:  CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Extensive significant problems
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  DESIGNATION:  DESIGNATION:	Round barrow 400m south west of Newb Scheduled Monument (No. 21146)  Arable ploughing Private  Round barrow 550m south east of Newba Scheduled Monument (No. 21147)  Arable ploughing Private  Round barrow 600m south east of Newba	ald Lodge, Newbald  CONDITION:  TREND:  CONTACT:  ald Lodge, Newbald  CONDITION:  TREND:  CONTACT:  CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse
DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:	Round barrow 400m south west of Newbords Scheduled Monument (No. 21146)  Arable ploughing Private  Round barrow 550m south east of Newbords Scheduled Monument (No. 21147)  Arable ploughing Private  Round barrow 600m south east of Newbords Scheduled Monument (No. 21148)  Arable ploughing	ald Lodge, Newbald  CONDITION:  TREND:  CONTACT:  ald Lodge, Newbald  CONDITION:  TREND:  CONTACT:  ald Lodge, Newbald  CONDITION:  TREND:  TREND:  TREND:  TREND:  TREND:	Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Lettensive significant problems i.e. under plough, collapse Declining
DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:	Round barrow 400m south west of Newbords Scheduled Monument (No. 21146)  Arable ploughing Private  Round barrow 550m south east of Newbords Scheduled Monument (No. 21147)  Arable ploughing Private  Round barrow 600m south east of Newbords Scheduled Monument (No. 21148)  Arable ploughing	ald Lodge, Newbald  CONDITION:  TREND:  CONTACT:  ald Lodge, Newbald  CONDITION:  TREND:  CONTACT:  ald Lodge, Newbald  CONDITION:  TREND:  CONDITION:  TREND:  CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990
DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNERSHIP:	Round barrow 400m south west of Newb Scheduled Monument (No. 21146)  Arable ploughing Private  Round barrow 550m south east of Newba Scheduled Monument (No. 21147)  Arable ploughing Private  Round barrow 600m south east of Newba Scheduled Monument (No. 21148)  Arable ploughing Private	ald Lodge, Newbald  CONDITION:  TREND:  CONTACT:  ald Lodge, Newbald  CONDITION:  TREND:  CONTACT:  ald Lodge, Newbald  CONDITION:  TREND:  CONDITION:  TREND:  CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:	Round barrow 400m south west of Newbords Scheduled Monument (No. 21146)  Arable ploughing Private  Round barrow 550m south east of Newbords Scheduled Monument (No. 21147)  Arable ploughing Private  Round barrow 600m south east of Newbords Scheduled Monument (No. 21148)  Arable ploughing Private  Round barrow 620m south east of Newbords Scheduled Monument (No. 21148)  Scheduled Monument (No. 21149)	ald Lodge, Newbald  CONDITION:  TREND:  CONTACT:  ald Lodge, Newbald  CONDITION:  TREND:  CONTACT:  ald Lodge, Newbald  CONDITION:  TREND:  CONTACT:  CONDITION:  CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990
DESIGNATION:  PRINCIPAL VULNERABILITY: DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY: DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY: DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY: DWNERSHIP:  DWNERSHIP:	Round barrow 400m south west of Newbords Scheduled Monument (No. 21146)  Arable ploughing Private  Round barrow 550m south east of Newbords Scheduled Monument (No. 21147)  Arable ploughing Private  Round barrow 600m south east of Newbords Scheduled Monument (No. 21148)  Arable ploughing Private  Round barrow 600m south east of Newbords Scheduled Monument (No. 21148)  Arable ploughing Private	ald Lodge, Newbald  CONDITION:  TREND:  CONTACT:  ald Lodge, Newbald  CONDITION:  TREND:  CONTACT:  ald Lodge, Newbald  CONDITION:  TREND:  CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Round barrow 700m north east of Littlew	ood Lodge, Newba	ld
designation:	Scheduled Monument (No. 21136)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
	·····		
SITE NAME:	Bowl barrow 600m ESE of Blanch Farm, N	lorth Dalton	
DESIGNATION:	Scheduled Monument (No. 21107)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow 610m east of Blanch Farm, N	North Dalton	
DESIGNATION:	Scheduled Monument (No. 21104)	CONDITION:	Extensive significant problems
	(		i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
		2011/1011	
SITE NAME:	Bowl barrow 620m ESE of Blanch Farm, N	lorth Dalton	
DESIGNATION:	Scheduled Monument (No. 21106)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Paull Holme moated site and tower, Paull		
DESIGNATION:	Scheduled Monument (No. 21175)	CONDITION:	Generally satisfactory
DESIGNATION:		23.1511014	· · · · · · · · · · · · · · · · · · ·
	,		but with significant localised problems
PRINCIPAL VULNERABILITY:		TREND:	but with significant localised problems  Declining
	Drainage/dewatering Private	TREND: CONTACT:	-
PRINCIPAL VULNERABILITY: OWNERSHIP:	Drainage/dewatering Private	CONTACT:	Declining Keith Miller 01904 601990
	Drainage/dewatering Private  Paull Point Battery, coastal artillery battery	CONTACT:	Declining Keith Miller 01904 601990  ining Establishment, Paull
OWNERSHIP: SITE NAME:	Drainage/dewatering Private	CONTACT:	Declining Keith Miller 01904 601990  ining Establishment, Paull Generally unsatisfactory
OWNERSHIP: SITE NAME:	Drainage/dewatering Private  Paull Point Battery, coastal artillery battery Scheduled Monument (No. 34713)	contact: y and Submarine M	Declining Keith Miller 01904 601990  ining Establishment, Paull  Generally unsatisfactory with major localised problems
OWNERSHIP:  SITE NAME:  DESIGNATION:	Drainage/dewatering Private  Paull Point Battery, coastal artillery battery Scheduled Monument (No. 34713)  Coastal erosion	contact: y and Submarine M	Declining Keith Miller 01904 601990  ining Establishment, Paull  Generally unsatisfactory with major localised problems Declining
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Drainage/dewatering Private  Paull Point Battery, coastal artillery battery Scheduled Monument (No. 34713)	y and Submarine M	Declining Keith Miller 01904 601990  ining Establishment, Paull  Generally unsatisfactory with major localised problems
OWNERSHIP:	Drainage/dewatering Private  Paull Point Battery, coastal artillery battery Scheduled Monument (No. 34713)  Coastal erosion	y and Submarine M  CONDITION:  TREND:	Declining Keith Miller 01904 601990  ining Establishment, Paull  Generally unsatisfactory with major localised problems Declining
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Drainage/dewatering Private  Paull Point Battery, coastal artillery battery Scheduled Monument (No. 34713)  Coastal erosion Private	y and Submarine M  CONDITION:  TREND:	Declining Keith Miller 01904 601990  ining Establishment, Paull Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  Generally unsatisfactory
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:	Drainage/dewatering Private  Paull Point Battery, coastal artillery battery Scheduled Monument (No. 34713)  Coastal erosion Private  Argam dykes, Rudston Scheduled Monument (No. ER87)	y and Submarine M  CONDITION:  TREND:  CONTACT:  CONDITION:	Declining Keith Miller 01904 601990  ining Establishment, Paull Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  Generally unsatisfactory with major localised problems
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Drainage/dewatering Private  Paull Point Battery, coastal artillery battery Scheduled Monument (No. 34713)  Coastal erosion Private  Argam dykes, Rudston Scheduled Monument (No. ER87)  Arable clipping	contact:  y and Submarine M  condition:  trend:  contact:  condition:	Declining Keith Miller 01904 601990  ining Establishment, Paull Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  Generally unsatisfactory with major localised problems Declining
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Drainage/dewatering Private  Paull Point Battery, coastal artillery battery Scheduled Monument (No. 34713)  Coastal erosion Private  Argam dykes, Rudston Scheduled Monument (No. ER87)	y and Submarine M  CONDITION:  TREND:  CONTACT:  CONDITION:	Declining Keith Miller 01904 601990  ining Establishment, Paull Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  Generally unsatisfactory with major localised problems
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Drainage/dewatering Private  Paull Point Battery, coastal artillery battery Scheduled Monument (No. 34713)  Coastal erosion Private  Argam dykes, Rudston Scheduled Monument (No. ER87)  Arable clipping	contact:  y and Submarine M  condition:  trend:  contact:  condition:  trend:  contact:	Declining Keith Miller 01904 601990  ining Establishment, Paull  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Drainage/dewatering Private  Paull Point Battery, coastal artillery battery Scheduled Monument (No. 34713)  Coastal erosion Private  Argam dykes, Rudston Scheduled Monument (No. ER87)  Arable clipping Private	contact:  y and Submarine M  condition:  trend:  contact:  condition:  trend:  contact:	Declining Keith Miller 01904 601990  ining Establishment, Paull Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  te for 530yds (480m), Rudston Extensive significant problems
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Drainage/dewatering Private  Paull Point Battery, coastal artillery battery Scheduled Monument (No. 34713)  Coastal erosion Private  Argam dykes, Rudston Scheduled Monument (No. ER87)  Arable clipping Private  Earthwork on the Sheepwalk stretching no	contact:  y and Submarine M  condition:  TREND:  contact:  Condition:  TREND:  contact:  contact:	Declining Keith Miller 01904 601990  ining Establishment, Paull Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  te for 530yds (480m), Rudston

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Roman villa site, Rudston		
Scheduled Monument (No. ER104)	CONDITION:	Extensive significant problems i.e. under plough, collapse
Arable ploughing	TREND:	Declining
Private	CONTACT:	Keith Miller 01904 601990
Rudston Beacon and round barrows to ea	st, Rudston	
Schodulad Manument (No ED49)	CONDITION	Extensive significant problems
· , , , , , , , , , , , , , , , , , , ,	CONDITION:	i.e. under plough, collapse
·	TREND:	Declining
Private	CONTACT:	Keith Miller 01904 601990
Bowl barrow 550m south of High Wold Fa	arm, Sancton	
Scheduled Monument (No. 21166)	CONDITION:	Extensive significant problems
		i.e. under plough, collapse
Arable ploughing	TREND:	Declining
Private	CONTACT:	Keith Miller 01904 601990
Moated monastic grange 300m south wes	t of Winsetts Farm	Skeffling
Scheduled Monument (No. 26609)	CONDITION:	Extensive significant problems
		i.e. under plough, collapse
	TREND:	Declining
Private	CONTACT:	Keith Miller 01904 601990
Hallgarth medieval hall and moat, Skipsea		
Scheduled Monument (No. 26525)	CONDITION:	Generally unsatisfactory with major localised problems
Drainage/dewatering	TREND:	Declining
Private	CONTACT:	Keith Miller 01904 601990
Royal Observer Corps underground monitoring post and World War II visual spotting post, 200m north of Southfield House, Skipsea		
Scheduled Monument (No. 35490)	CONDITION:	Generally unsatisfactory with major localised problems
Extensive animal burrowing	TREND:	Declining
Private	CONTACT:	Keith Miller 01904 601990
Skipsea Castle: 11th century motte and ba	iley castle and inla	nd harbour, Skipsea
Scheduled Monument (No. 13334)	CONDITION:	Generally satisfactory but with significant localised problems
Drainage/dewatering	TREND:	Declining
Private	CONTACT:	Keith Miller 01904 601990
Moated site, fishponds and associated eart	thworks at Manor I	House, Skirpenbeck
Scheduled Monument (No. 26602)	CONDITION:	Generally satisfactory but with significant localised problems
		out with significant localised problems
Drainage/dewatering	TRENID.	Declining
Drainage/dewatering Private	TREND: CONTACT:	Declining Keith Miller 01904 601990
	Scheduled Monument (No. ER104)  Arable ploughing Private  Rudston Beacon and round barrows to ear Scheduled Monument (No. ER68)  Arable ploughing Private  Bowl barrow 550m south of High Wold Fast Scheduled Monument (No. 21166)  Arable ploughing Private  Moated monastic grange 300m south west Scheduled Monument (No. 26609)  Arable ploughing Private  Hallgarth medieval hall and moat, Skipsea Scheduled Monument (No. 26525)  Drainage/dewatering Private  Royal Observer Corps underground monic 200m north of Southfield House, Skipsea Scheduled Monument (No. 35490)  Extensive animal burrowing Private  Skipsea Castle: 11th century motte and base Scheduled Monument (No. 13334)  Drainage/dewatering Private  Moated site, fishponds and associated earther the state of the sta	Scheduled Monument (No. ER104)  Arable ploughing Private  Rudston Beacon and round barrows to east, Rudston  Scheduled Monument (No. ER68)  Arable ploughing Private  CONTACT:  Bowl barrow 550m south of High Wold Farm, Sancton  Scheduled Monument (No. 21166)  Arable ploughing Private  CONTACT:  Moated monastic grange 300m south west of Winsetts Farm, Scheduled Monument (No. 26609)  Arable ploughing Private  CONTACT:  Hallgarth medieval hall and moat, Skipsea  Scheduled Monument (No. 26525)  Drainage/dewatering Private  CONTACT:  Royal Observer Corps underground monitoring post and Wood 200m north of Southfield House, Skipsea  Scheduled Monument (No. 35490)  Extensive animal burrowing Private  CONTACT:  Skipsea Castle: 11th century motte and bailey castle and inlant Scheduled Monument (No. 13334)  Drainage/dewatering Private  CONDITION  TREND: CONDITION  TREND: CONDITION  TREND: CONTACT:  CONTACT:  CONTACT:  Moated site, fishponds and associated earthworks at Manor I

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# ABBREVIATIONS

SITE NAME:	Round barrow 1300m east of Life Hill, Slee	dmere	
DESIGNATION:	Scheduled Monument (No. 21218)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Round barrow 1400m east of Life Hill, Slee	dmere	
DESIGNATION:	Scheduled Monument (No. 21219)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Round barrow 1650m east of Life Hill, Slee	dmere	
DESIGNATION:	Scheduled Monument (No. 21220)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Kings Manor moated site, 450m south of l	ittle London, Snait	h and Cowick
DESIGNATION:	Scheduled Monument (No. 26606)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Moated site at St Lois Farm, Sutton upon	Derwent	
	, ,		
DESIGNATION:	Scheduled Monument (No. 21193)	CONDITION:	Generally satisfactory but with significant localised problems
	·		·
PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 21193)	CONDITION:	but with significant localised problems
PRINCIPAL VULNERABILITY: OWNERSHIP:	Scheduled Monument (No. 21193)  Scrub / tree growth	CONDITION:  TREND:  CONTACT:	but with significant localised problems Declining Keith Miller 01904 601990
PRINCIPAL VULNERABILITY:  DWNERSHIP:  SITE NAME:	Scheduled Monument (No. 21193)  Scrub / tree growth  Private	CONDITION:  TREND:  CONTACT:	but with significant localised problems Declining Keith Miller 01904 601990  pond, Twin Rivers Generally satisfactory
PRINCIPAL VULNERABILITY: OWNERSHIP:  SITE NAME:  DESIGNATION:	Scheduled Monument (No. 21193)  Scrub / tree growth Private  Hall Garth moated site, associated drainag Scheduled Monument (No. 26504)	CONDITION:  TREND:  CONTACT:  e channels and fish	but with significant localised problems Declining Keith Miller 01904 601990  pond, Twin Rivers
PRINCIPAL VULNERABILITY: OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 21193)  Scrub / tree growth Private  Hall Garth moated site, associated drainage	CONDITION:  TREND:  CONTACT:  e channels and fish  CONDITION:	but with significant localised problems Declining Keith Miller 01904 601990  pond, Twin Rivers  Generally satisfactory but with significant localised problems
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Scheduled Monument (No. 21193)  Scrub / tree growth Private  Hall Garth moated site, associated drainag Scheduled Monument (No. 26504)  Drainage/dewatering	CONDITION:  TREND:  CONTACT:  e channels and fish  CONDITION:  TREND:	but with significant localised problems Declining Keith Miller 01904 601990  pond, Twin Rivers  Generally satisfactory but with significant localised problems Declining
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Scheduled Monument (No. 21193)  Scrub / tree growth Private  Hall Garth moated site, associated drainag Scheduled Monument (No. 26504)  Drainage/dewatering Private	CONDITION:  TREND:  CONTACT:  e channels and fish  CONDITION:  TREND:	but with significant localised problems Declining Keith Miller 01904 601990  pond, Twin Rivers  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Extensive significant problems
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:	Scheduled Monument (No. 21193)  Scrub / tree growth Private  Hall Garth moated site, associated drainag Scheduled Monument (No. 26504)  Drainage/dewatering Private  Ling Howe long barrow, Walkington	CONDITION:  TREND:  CONTACT:  e channels and fish  CONDITION:  TREND:  CONTACT:	but with significant localised problems Declining Keith Miller 01904 601990  pond, Twin Rivers  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 21193)  Scrub / tree growth Private  Hall Garth moated site, associated drainag Scheduled Monument (No. 26504)  Drainage/dewatering Private  Ling Howe long barrow, Walkington Scheduled Monument (No. 26605)	CONDITION:  TREND: CONTACT:  e channels and fish  CONDITION:  TREND: CONTACT:	but with significant localised problems Declining Keith Miller 01904 601990  pond, Twin Rivers Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  OWNERSHIP:	Scheduled Monument (No. 21193)  Scrub / tree growth Private  Hall Garth moated site, associated drainag Scheduled Monument (No. 26504)  Drainage/dewatering Private  Ling Howe long barrow, Walkington Scheduled Monument (No. 26605)  Arable ploughing	CONDITION:  TREND: CONTACT:  e channels and fish  CONDITION:  TREND: CONTACT:  CONDITION:  TREND: CONTACT:	but with significant localised problems Declining Keith Miller 01904 601990  pond, Twin Rivers Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  OWNERSHIP:	Scheduled Monument (No. 21193)  Scrub / tree growth Private  Hall Garth moated site, associated drainag Scheduled Monument (No. 26504)  Drainage/dewatering Private  Ling Howe long barrow, Walkington Scheduled Monument (No. 26605)  Arable ploughing Private	CONDITION:  TREND: CONTACT:  e channels and fish  CONDITION:  TREND: CONTACT:  CONDITION:  TREND: CONTACT:	but with significant localised problems Declining Keith Miller 01904 601990  pond, Twin Rivers Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  ter  Extensive significant problems
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Scheduled Monument (No. 21193)  Scrub / tree growth Private  Hall Garth moated site, associated drainag Scheduled Monument (No. 26504)  Drainage/dewatering Private  Ling Howe long barrow, Walkington Scheduled Monument (No. 26605)  Arable ploughing Private  Bowl barrow 170m north west of Farbern	CONDITION:  TREND: CONTACT:  e channels and fish  CONDITION:  TREND: CONTACT:  CONDITION:  TREND: CONTACT:	but with significant localised problems Declining Keith Miller 01904 601990  pond, Twin Rivers  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  ter

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

CA LB/LBs NP RPG SM/SMs UA WHS

SITE NAME:	Bowl barrow 210m south east of Blanch F	arm,Warter	
DESIGNATION:	Scheduled Monument (No. 21100)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
OVVINCIOI III .	Tivate	CONTACT.	Relati iller 61761 661776
SITE NAME:	Bowl barrow 290m south east of Blanch F	arm, Warter	
DESIGNATION:	Scheduled Monument (No. 21101)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow 500m east of Blanch Farm, V	Varter	
DESIGNATION:	Scheduled Monument (No. 21103)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
·		23.47/61.	
SITE NAME:	Bowl barrow 560m NNW of Farberry Ga	arth Farm,Warter	
DESIGNATION:	Scheduled Monument (No. 21132)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow 720m NNW of Farberry Ga	arth Farm, Warter	
DESIGNATION:	Scheduled Monument (No. 21131)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow 760m NNE of Farberry Gar	th Farm, Warter	
DESIGNATION:	Scheduled Monument (No. 21130)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Round barrow 100m south west of Cobd	ale Farm,Warter	
DESIGNATION:	Scheduled Monument (No. 21118)	CONDITION:	Extensive significant problems
	(10.2.1.0)		i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Round barrow 400m north west of Cobd	ale Farm,Warter	
			Extensive significant amplians
DESIGNATION:	Scheduled Monument (No. 21115)	CONDITION:	Extensive significant problems
	Arable ploughing	TREND:	i.e. under plough, collapse  Declining
PRINCIPAL VULNERABILITY:	Private		Keith Miller 01904 601990
OWNERSHIP:	1 1 IVale	CONTACT:	Neiull IIIICI 01707 001770

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Round barrow 450m north east of Blanch	Farm, Warter	
DESIGNATION:	Scheduled Monument (No. 21125)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Round barrow 520m south of Warren Far	m,Warter	
DESIGNATION:	Scheduled Monument (No. 21116)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Round barrow 915m north east of Dalton	Gates Farm, Wart	er
DESIGNATION:	Scheduled Monument (No. 21128)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Round barrow 930m north east of Dalton	Gates Farm, Wart	er
DESIGNATION:	Scheduled Monument (No. 21127)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Round barrow on Thirty Acres, Warter		
DESIGNATION:	Scheduled Monument (No. 21126)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Section of linear boundary dyke between Sylvan Dale and Warren Farm, north west of Coldwold Farm, Warter		
DESIGNATION:	Scheduled Monument (No. 26587)	CONDITION:	Generally satisfactory but with significant localised problems
	Arable clipping	TREND:	Declining
PRINCIPAL VULNERABILITY:			
	Private	CONTACT:	Keith Miller 01904 601990
OWNERSHIP:	Two bowl barrows 300m south east of Bla	CONTACT:	Keith Miller 01904 601990
OWNERSHIP: SITE NAME:		CONTACT:	Keith Miller 01904 601990  Extensive significant problems i.e. under plough, collapse
OWNERSHIP: SITE NAME: DESIGNATION:	Two bowl barrows 300m south east of Bla	contact:	Extensive significant problems
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Two bowl barrows 300m south east of Black Scheduled Monument (No. 21102)	contact: unch Farm, Warter condition:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Two bowl barrows 300m south east of Bla Scheduled Monument (No. 21102) Arable ploughing	contact:  unch Farm, Warter  condition:  trend:  contact:	Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Two bowl barrows 300m south east of Black Scheduled Monument (No. 21102)  Arable ploughing Private	contact:  unch Farm, Warter  condition:  trend:  contact:	Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Two bowl barrows 300m south east of Black Scheduled Monument (No. 21102)  Arable ploughing Private  Two bowl barrows 500m north west of Face	CONTACT:  unch Farm, Warter  CONDITION:  TREND:  CONTACT:  urberry Garth Farm	Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990  n, Warter Extensive significant problems

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Two round barrows 820m north east of Dal	ton Gates Farm,	Warter
DESIGNATION:	Scheduled Monument (No. 21129)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Site of Watton Gilbertine priory, two possible	e medieval arche	ery butts and Civil War earthworks,Watto
DESIGNATION:	Scheduled Monument (No. 23805)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Medieval moated tile kiln 250m north east o	f North Grange	Farm, Wawne
DESIGNATION:	Scheduled Monument (No. 21182)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Moated monastic grange site and fishponds in 630m north west of Carlam Hill Farm, Wawr		,
DESIGNATION:	Scheduled Monument (No. 26620)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Haltemprice Augustinian priory, Willerby		
DESIGNATION:	Scheduled Monument (No. 32639)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	i.e. under plough, collapse  Declining
OWNERSHIP:	Private Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow 580m west of High Fordon Far	m,Wold Newto	n
DESIGNATION:	Scheduled Monument (No. 21246)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow 600m west of High Fordon Far	m,Wold Newto	n
DESIGNATION:	Scheduled Monument (No. 21245)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Hall Garth moated site south of Beverley Mi	nster, Woodman	sey
SITE NAITE.			
	Scheduled Monument (No. 21176)	CONDITION:	Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 21176)  Drainage/dewatering	CONDITION: TREND:	Generally satisfactory but with significant localised problems Declining

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.



SITE NAME:	Thwaite	Hall,	Cottingham
------------	---------	-------	------------

DESIGNATION: Registered Park and Garden Grade II,

also CA

сонытюм: Generally satisfactory

but with significant localised problems

VULNERABILITY: High

Declining

Private, single owner OWNERSHIP:

Grounds of a villa developed mainly in the 1870s/80s, but modified in the mid C20 to provide accommodation for the University College of Hull. Grounds partly developed as a botanical garden. Problems with flood damage in 2007 and drainage problems are affecting mature planting and lawns around the lake.

Contact: Andy Wimble 01904 601970



SITE NAME: Battle of Stamford Bridge

DESIGNATION: Registered Battlefield

Declining TREND:

OWNERSHIP: Private

Three weeks before the Battle of Hastings (1066) King Harold defeated a Norwegian army at this crossing point on the River Derwent. The modern settlement of Stamford Bridge grew markedly in the later C20 and little of the battlefield remains undeveloped.

Contact: Susan Daniels 01904 601 979

### KINGSTON UPON HULL, CITY OF (UA)

	· /		
SITE NAME:	Beverley Road, Hull		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	No significant change expected
CONTACT:	Philip Hampel (LA) 01482 612343		
SITE NAME:	Holderness Road (West)		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	No significant change expected
CONTACT:	Philip Hampel (LA) 01482 612343		
SITE NAME:	Spring Bank		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	No significant change expected
CONTACT:	Philip Hampel (LA) 01482 612343		
SITE NAME:	St Andrew's Dock		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Expected to deteriorate significantly
CONTACT:	Philip Hampel (LA) 01482 612343		

### NORTH EAST LINCOLNSHIRE (UA)



The Grimsby Ice Factory, SITE NAME:

Gorton Street, Grimsby

DESIGNATION: Listed Building Grade II\*

condition: Very bad OCCUPANCY: Vacant PRIORITY: A(A)

OWNERSHIP: Company

1900 ice works with extension factory of 1907-8 and later alterations. Closed in 1990. It is thought that this is the earliest surviving ice factory in Britain, and the sole survivor from this period to retain its machinery.

Window damage. Roof is now deteriorating rapidly.

Contact: Catherine Dewar 01904 601972

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# NOTE: If the priority category has changed since the 2009 register, the previous category is given in brackets.

## **ABBREVIATIONS**

CA LB/LBs Conservation Area Conservation Area Listed Building/s National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site NIP NP RPG SM/SMs UA WHS



Church of Saint Margaret, SITE NAME: Barton Street, Hawerby cum Beesby

DESIGNATION: Listed Building Grade II Poor CONDITION:

Vacant OCCLIPANCY: D(D)PRIORITY: Private OWNERSHIP:

Parish church, C12, C13 and C17, with mid C19 restorations. The arcade to the former south aisle survives. The church was made redundant in 1978. It is proposed to convert the church to an artist's studio. Some holding repairs are to be carried out to the north nave roof and further work is planned.

Contact: Catherine Dewar 01904 601972

SITE NAME:	Civil War earthwork fort 350	m north east of Walk Farm, Irby

Scheduled Monument (No. 21237) Generally satisfactory DESIGNATION: CONDITION: but with significant localised problems Scrub / tree growth PRINCIPAL VUI NERABILITY TREND: Keith Miller 01904 601990 Private OWNERSHIP: CONTACT

Premonstratensian priory chapel 170m south west of Priory Farm, West Ravendale SITE NAME:

DESIGNATION Scheduled Monument (No. 34702) CONDITION: Generally unsatisfactory with major localised problems Declining PRINCIPAL VULNERABILITY: Arable clipping TREND: Keith Miller 01904 601990 OWNERSHIP: Private CONTACT

SITE NAME: Central Area, Grimsby

Conservation Area DESIGNATION CONDITION Expected to show some improvement VULNERABILITY TREND Tony Sargent (LA) 01472 324252 CONTACT:

Central Sea Front, Cleethorpes SITE NAME:

Conservation Area Very bad DESIGNATION: CONDITION: Medium Expected to deteriorate VULNERABILITY TREND Tony Sargent (LA) 01472 324252 CONTACT:

Waltham SITE NAME:

Conservation Area CONDITION: DESIGNATION: VULNERABILITY: High TREND: Expected to show some improvement Tony Sargent (LA) 01472 324252 CONTACT:

#### NORTH LINCOLNSHIRE (UA)



Hibaldstow Mill and walls to mill pond and wheel race, Ings Lane, Hibaldstow

DESIGNATION: Listed Building Grade II\*, SM

Fair CONDITION:

OCCUPANCY: Part occupied

C (C) PRIORITY

OWNERSHIP: Private

Combined wind and watermill, I 802, by James Middleton of Hibaldstow. Some repairs undertaken, but further work required to both exterior and interior.

Contact: Catherine Dewar 01904 601972



SITE NAME:

Manor Farmhouse. East Halton Road, North Killingholme

DESIGNATION: Listed Building Grade II

Very bad CONDITION: Vacant OCCUPANCY: B (B)

Medieval, C17-C19 manor house on a scheduled moated site. Exceptional multi-period survival for this region. The roof was repaired in 1980, but little has been done since and the interior is propped with scaffolding. A feasibility study has been completed.

Contact: Keith Miller 01904 601990

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Private

Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE:

If the priority category has changed since the 2009 register, the previous category is given in brackets.

#### **ABBREVIATIONS**

CA LB/LBs Conservation Area Conservation Area Listed Building/s National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site NIP RPG SM/SMs UA WHS

SITE NAME:	Heavy Anti-aircraft gunsite 220m east of We	st Marsh Cottage	e, Barrow upon Humber
DESIGNATION:	Scheduled Monument (No. 34708)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Moated site 285m east of Castlethorpe Hou	se, Broughton	
DESIGNATION:	Scheduled Monument (No. 32625)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
ITE NAME:	Yarborough Camp large univallate hillfort, Ci	roxton	
DESIGNATION:	Scheduled Monument (No. 32623)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Romano-British settlement near Staniwells F	arm, Hibaldstow	
DESIGNATION:	Scheduled Monument (No. NL102)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Roman settlement, Kirmington		
DESIGNATION:	Scheduled Monument (No. NL217)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Metal detecting	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Romano-British villa at Mount Pleasant Farm	, Kirton in Linds	ey
DESIGNATION:	Scheduled Monument (No. 26521)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
			Keith Miller 01904 601990
OWNERSHIP:	Private	CONTACT:	
	Moated site and fishpond 200m south east o		elton Ross
SITE NAME:			Generally satisfactory
SITE NAME: DESIGNATION:	Moated site and fishpond 200m south east of Scheduled Monument (No. 21250)	of Melton Hall, M	Generally satisfactory but with significant localised problems
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Moated site and fishpond 200m south east o	of Melton Hall, M	Generally satisfactory
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Moated site and fishpond 200m south east of Scheduled Monument (No. 21250)  Drainage/dewatering	of Melton Hall, M  CONDITION:  TREND:	Generally satisfactory but with significant localised problems Stable
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Moated site and fishpond 200m south east of Scheduled Monument (No. 21250)  Drainage/dewatering	of Melton Hall, M  CONDITION:  TREND:  CONTACT:	Generally satisfactory but with significant localised problems Stable Keith Miller 01904 601990
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Moated site and fishpond 200m south east of Scheduled Monument (No. 21250)  Drainage/dewatering Private	of Melton Hall, M  CONDITION:  TREND:  CONTACT:	Generally satisfactory but with significant localised problems Stable Keith Miller 01904 601990
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Moated site and fishpond 200m south east of Scheduled Monument (No. 21250)  Drainage/dewatering Private  North Garth moated site and associated end	of Melton Hall, M  CONDITION:  TREND:  CONTACT:  Closures, North 1	Generally satisfactory but with significant localised problems Stable Keith Miller 01904 601990  Killingholme Generally satisfactory

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

CA LB/LBs NP RPG SM/SMs UA WHS

SITE NAME:	Money Field Roman site, Dragonby, North	Lincolnshire	
DESIGNATION:	Scheduled Monument (No. NL106)	CONDITION:	Extensive significant problems
	, i		i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Kinaird motte and bailey castle, Owston F	erry	
DECIGNATION.	Scheduled Monument (No. 30124)	•	Caparally satisfactory
DESIGNATION:	Scrieduled Pioridifierit (190. 30124)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
JVVNERSHIP:	TTIVate	CONTACT:	Retuit tiller 01704 001770
SITE NAME:	Thornton Abbey Augustinian monastery: grafishponds, post-Dissolution college and sch		
DESIGNATION:	Scheduled Monument (No. 13377)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Old Winteringham Roman settlement, Wir	nteringham	
DESIGNATION:	Scheduled Monument (No. NL8)		E
DESIGNATION.	Scrieduled Floridifient (140.1420)	CONDITION:	Extensive significant problems
DESIGNATION.	· ,	CONDITION:	i.e. under plough, collapse
	Arable ploughing	CONDITION: TREND:	i.e. under plough, collapse Improving
PRINCIPAL VULNERABILITY:	· ,		i.e. under plough, collapse
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Arable ploughing	TREND:	i.e. under plough, collapse Improving
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Arable ploughing Private  Howe Hill bowl barrow, Wootton	TREND:	i.e. under plough, collapse Improving Keith Miller 01904 601990
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Arable ploughing Private	TREND: CONTACT:	i.e. under plough, collapse Improving Keith Miller 01904 601990  Generally unsatisfactory
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:	Arable ploughing Private  Howe Hill bowl barrow, Wootton Scheduled Monument (No. 21051)	TREND: CONTACT:	i.e. under plough, collapse Improving Keith Miller 01904 601990
PRINCIPAL VULNERABILITY: OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Arable ploughing Private  Howe Hill bowl barrow, Wootton	TREND: CONTACT:  CONDITION:	i.e. under plough, collapse Improving Keith Miller 01904 601990  Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY: OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Arable ploughing Private  Howe Hill bowl barrow, Wootton Scheduled Monument (No. 21051)  Arable clipping	TREND: CONTACT:  CONDITION:  TREND:	i.e. under plough, collapse Improving Keith Miller 01904 601990  Generally unsatisfactory with major localised problems Declining
PRINCIPAL VULNERABILITY: OWNERSHIP:	Arable ploughing Private  Howe Hill bowl barrow, Wootton Scheduled Monument (No. 21051)  Arable clipping	TREND: CONTACT:  CONDITION:  TREND: CONTACT:	i.e. under plough, collapse Improving Keith Miller 01904 601990  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Arable ploughing Private  Howe Hill bowl barrow, Wootton  Scheduled Monument (No. 21051)  Arable clipping Private	TREND: CONTACT:  CONDITION:  TREND: CONTACT:	i.e. under plough, collapse Improving Keith Miller 01904 601990  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  forlaby Extensive significant problems
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:	Arable ploughing Private  Howe Hill bowl barrow, Wootton  Scheduled Monument (No. 21051)  Arable clipping Private  Roman site 400yds (370m) north east of V  Scheduled Monument (No. NL86)	TREND: CONTACT:  CONDITION: TREND: CONTACT:  Vorlaby Church, W	i.e. under plough, collapse Improving Keith Miller 01904 601990  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  PRINCIPAL VULNERABILITY:	Arable ploughing Private  Howe Hill bowl barrow, Wootton  Scheduled Monument (No. 21051)  Arable clipping Private  Roman site 400yds (370m) north east of V	TREND: CONTACT:  CONDITION: TREND: CONTACT:  Worlaby Church, W  CONDITION:	i.e. under plough, collapse Improving Keith Miller 01904 601990  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  Yorlaby  Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  PRINCIPAL VULNERABILITY:	Arable ploughing Private  Howe Hill bowl barrow, Wootton  Scheduled Monument (No. 21051)  Arable clipping Private  Roman site 400yds (370m) north east of V  Scheduled Monument (No. NL86)  Arable ploughing	TREND: CONTACT:  CONDITION: TREND: CONTACT:  Vorlaby Church, W CONDITION: TREND:	i.e. under plough, collapse Improving Keith Miller 01904 601990  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  forlaby  Extensive significant problems i.e. under plough, collapse Declining
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  OWNERSHIP:	Arable ploughing Private  Howe Hill bowl barrow, Wootton  Scheduled Monument (No. 21051)  Arable clipping Private  Roman site 400yds (370m) north east of V  Scheduled Monument (No. NL86)  Arable ploughing	TREND: CONTACT:  CONDITION: TREND: CONTACT:  Vorlaby Church, W CONDITION: TREND:	i.e. under plough, collapse Improving Keith Miller 01904 601990  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  forlaby  Extensive significant problems i.e. under plough, collapse Declining
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Arable ploughing Private  Howe Hill bowl barrow, Wootton  Scheduled Monument (No. 21051)  Arable clipping Private  Roman site 400yds (370m) north east of V  Scheduled Monument (No. NL86)  Arable ploughing Private	TREND: CONTACT:  CONDITION: TREND: CONTACT:  Vorlaby Church, W CONDITION: TREND:	i.e. under plough, collapse Improving Keith Miller 01904 601990  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  forlaby  Extensive significant problems i.e. under plough, collapse Declining
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  OWNERSHIP:	Arable ploughing Private  Howe Hill bowl barrow, Wootton  Scheduled Monument (No. 21051)  Arable clipping Private  Roman site 400yds (370m) north east of V  Scheduled Monument (No. NL86)  Arable ploughing Private  Crowle	TREND: CONTACT:  CONDITION: TREND: CONTACT:  Worlaby Church, W  CONDITION: TREND: CONTACT:	i.e. under plough, collapse Improving Keith Miller 01904 601990  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  Forlaby  Extensive significant problems i.e. under plough, collapse Declining Keith Miller 01904 601990

### **NORTH YORKSHIRE CRAVEN**



Dale End Mills, SITE NAME: Dale End, Lothersdale

DESIGNATION: Listed Building Grade II, SM

condition: Poor

occupancy: Part occupied C(C)PRIORITY:

C19 mill, including disused waterwheel (1861), pit and enclosing building. The mill-wheel is the largest in England and is in poor condition. The base of the stack is also in need of remedial work. Discussions are underway with the owner to find a solution to the building repair.

Contact: Giles Proctor 01904 601981

### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE:

If the priority category has changed since the 2009 register, the previous category is given in brackets.

### ABBREVIATIONS

SITE NAME:	Moated site west of Paget Hall, Gargrave		
DESIGNATION:	Scheduled Monument (No. NY735)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate stock erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988

#### **HAMBLETON**



The Coach House. SITE NAME Rounton Grange, East Rounton

Coach house, built in 1875. Now used as a combined home and workshop. One range is in a fair condition, the rest is in state of collapse.

DESIGNATION: Listed Building Grade II\*

condition: Very bad Part occupied OCCUPANCY:

PRIORITY: A (A) Private OWNERSHIP:

Contact: Diane Green 01904 601973



Landmoth Hall, SITE NAME: Landmoth cum Catto

Part of the east wing of a medieval manor house. Now in an unstable condition.

DESIGNATION: Scheduled Monument Very bad OCCUPANCY: Not applicable B (B) PRIORITY: OWNERSHIP: Private

Contact: Neil Redfern 01904 601897



West Lodge, Thornton Stud, SITE NAME: Newsham Road,

Newsham with Breckenbrough

DESIGNATION: Listed Building Grade II\*

Poor CONDITION: occupancy: Vacant C(C)PRIORITY OWNERSHIP: Private Late C18 lodge and entrance gateway. Deteriorating.



SITE NAME: Snape Castle, Snape with Thorp

DESIGNATION: Listed Building Grade I, SM, CA, RPG II Very bad

Part occupied OCCUPANCY: B (B) PRIORITY:

Private OWNERSHIP:

Castle dated to circa 1430, with additions and alterations in the C16 and C18. It is comprised of extensive ruins, including some vaulted rooms and two towers. The rear ranges are in a poor condition. The upper parts of the towers are particularly unstable. Much repointing is required elsewhere. The front ranges are divided into two dwellings.

Contact: Neil Redfern 01904 601897

Contact: Neil Redfern 01904 601897



SITE NAME: West Harlsey

Stables at Harlsey Castle Farmhouse, Remains of medieval castle keep; in use as farm buildings.

DESIGNATION: Listed Building Grade II\*, SM CONDITION: Poor OCCUPANCY: Occupied D (D) PRIORITY: OWNERSHIP: Private

Contact: Neil Redfern 01904 601897

#### Medieval moated grange 160m south east of The Grange, Balk SITE NAME:

but with significant localised problems  PRINCIPAL VULNERABILITY: Drainage/dewatering TREND: Declining  OWNERSHIP: Private CONTACT: Keith Emerick 01904 601988	DESIGNATION:	Scheduled Monument (No. 28291)	CONDITION:	Generally satisfactory
N. 31 E 1 01004 (01000				but with significant localised problems
OWNERSHIP: Private CONTACT: Keith Emerick 01904 601988	PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
	OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# NOTE: If the priority category has changed since the 2009 register, the previous category is given in brackets.

#### ABBREVIATIONS CA LB/LBs NIP

SITE NAME:	Birkby medieval settlement and associated	l field system, moat	ted site and fishponds, Birkby
DESIGNATION:	Scheduled Monument (No. 31341)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Localised/limited stock erosion	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Lime kilns 400m south west of Furlands, B	Sorrowby	
DESIGNATION:	Scheduled Monument (No. 35486)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 150m south of Warren Ho	use, Brandsby cum	Stearsby
designation:	Scheduled Monument (No. 28217)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 300m east of Warren House	se, Brandsby cum S	tearsby
DESIGNATION:	Scheduled Monument (No. 28216)	CONDITION:	Generally satisfactory
	District		but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 300m west of Quarry Hou	se, Brandsby cum S	Stearsby
DESIGNATION:	Scheduled Monument (No. 28218)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 330yds (300m) south of Ba	arhouse Farm, Bran	dsby cum Stearsby
DESIGNATION:	Scheduled Monument (No. NY551)	CONDITION:	Extensive significant problems
	,		i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
	D	· D d.h	- C+
SITE NAME:	Round barrow 450m north east of Hagg F	arm, Brandsby cum	•
DESIGNATION:	Scheduled Monument (No. 28208)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Healam Bridge Roman fort and vicus, Burn	neston	
DESIGNATION:	Scheduled Monument (No. 34736)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Road construction	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Moated site immediately south of Danby \	Viske church, Dant	by Wiske with Lazenby
DESIGNATION:	Scheduled Monument (No. 31347)	CONDITION:	Generally satisfactory but with minor localised problems
			but with minor localised problems
PRINICIPAL VI II NIEDARII ITV	Gardening	TRENID.	Stable
PRINCIPAL VULNERABILITY:  OWNERSHIP:	Gardening Private	TREND: CONTACT:	Stable Keith Emerick 01904 601988

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# NOTE: NOTE: If the priority category has changed since the 2009 register, the previous category is given in brackets.

## ABBREVIATIONS

SITE NAME:	Deighton moated site, Deighton		
DESIGNATION:	Scheduled Monument (No. NY846)	CONDITION:	Generally satisfactory
			but with minor localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Earth circles, cursus, pit alignments and buincluding Centre Hill round barrow, East Ta		terfield and Thornborough,
designation:	Scheduled Monument (No. NY36)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 425m north west of Rushw	ood Hall, East Tanf	ìeld
DESIGNATION:	Scheduled Monument (No. 29509)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
		CONTACT.	
SITE NAME:	Medieval moated site, fishponds and associ 125m south of Eldmire Cottage, Eldmire w	,	
DESIGNATION:	Scheduled Monument (No. 28292)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Localised/limited stock erosion	TREND:	Stable
		TINEIND.	Stable
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
	Private  Medieval settlement of Little Broughton, as Great and Little Broughton	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Medieval settlement of Little Broughton, as	CONTACT:	Keith Emerick 01904 601988
site name: Designation:	Medieval settlement of Little Broughton, as Great and Little Broughton	contact:	Keith Emerick 01904 601988  em and site of medieval chapel,
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Medieval settlement of Little Broughton, as Great and Little Broughton  Scheduled Monument (No. 31356)	contact: ssociated field syste	Keith Emerick 01904 601988  em and site of medieval chapel,  Unknown
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Medieval settlement of Little Broughton, as Great and Little Broughton  Scheduled Monument (No. 31356)  Localised/limited stock erosion	contact:  ssociated field syste  condition:  trend:  contact:	Keith Emerick 01904 601988  em and site of medieval chapel,  Unknown  Unknown  Keith Emerick 01904 601988
DESIGNATION: PRINCIPAL VULNERABILITY: DWNERSHIP: SITE NAME:	Medieval settlement of Little Broughton, as Great and Little Broughton  Scheduled Monument (No. 31356)  Localised/limited stock erosion  Private	contact:  ssociated field syste  condition:  trend:  contact:	Keith Emerick 01904 601988  em and site of medieval chapel,  Unknown Unknown Keith Emerick 01904 601988  wle Generally unsatisfactory
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:	Medieval settlement of Little Broughton, as Great and Little Broughton  Scheduled Monument (No. 31356) Localised/limited stock erosion Private  Round barrow 180m NNE of St Wilfred's Scheduled Monument (No. 25587)	contact:  ssociated field syste  condition:  TREND:  CONTACT:  Church, Kirby Kno	Keith Emerick 01904 601988  em and site of medieval chapel,  Unknown Unknown Keith Emerick 01904 601988  wle  Generally unsatisfactory with major localised problems
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Medieval settlement of Little Broughton, as Great and Little Broughton  Scheduled Monument (No. 31356) Localised/limited stock erosion Private  Round barrow 180m NNE of St Wilfred's	CONTACT:  ssociated field system  CONDITION:  TREND:  CONTACT:  Church, Kirby Kno  CONDITION:	Keith Emerick 01904 601988  em and site of medieval chapel,  Unknown Unknown Keith Emerick 01904 601988  wle Generally unsatisfactory
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Medieval settlement of Little Broughton, as Great and Little Broughton  Scheduled Monument (No. 31356) Localised/limited stock erosion Private  Round barrow 180m NNE of St Wilfred's Scheduled Monument (No. 25587)  Arable clipping	CONTACT:  ssociated field system  CONDITION:  TREND:  CONTACT:  Church, Kirby Kno  CONDITION:  TREND:  CONTACT:	Keith Emerick 01904 601988  em and site of medieval chapel,  Unknown Unknown Keith Emerick 01904 601988  wle  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNIERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNIERSHIP:  SITE NAME:	Medieval settlement of Little Broughton, as Great and Little Broughton  Scheduled Monument (No. 31356) Localised/limited stock erosion Private  Round barrow 180m NNE of St Wilfred's Scheduled Monument (No. 25587)  Arable clipping Private	CONTACT:  ssociated field system  CONDITION:  TREND:  CONTACT:  Church, Kirby Kno  CONDITION:  TREND:  CONTACT:	Keith Emerick 01904 601988  em and site of medieval chapel,  Unknown Unknown Keith Emerick 01904 601988  wle  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  n cum Upsland Generally satisfactory
DESIGNATION:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNERSHIP:  DESIGNATION:  DESIGNATION:  DESIGNATION:	Medieval settlement of Little Broughton, as Great and Little Broughton  Scheduled Monument (No. 31356) Localised/limited stock erosion Private  Round barrow 180m NNE of St Wilfred's Scheduled Monument (No. 25587)  Arable clipping Private  Round barrow 250m north east of Comer	CONTACT:  condition: trend: contact:  Church, Kirby Kno condition: trend: contact:	Keith Emerick 01904 601988  em and site of medieval chapel,  Unknown Unknown Keith Emerick 01904 601988  wle  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:	Medieval settlement of Little Broughton, as Great and Little Broughton  Scheduled Monument (No. 31356) Localised/limited stock erosion Private  Round barrow 180m NNE of St Wilfred's Scheduled Monument (No. 25587)  Arable clipping Private  Round barrow 250m north east of Comer Scheduled Monument (No. 29526)	CONTACT:  condition:  TREND:  CONDITION:  TREND:  CONDITION:  TREND:  CONTACT:  CONTACT:	Keith Emerick 01904 601988  em and site of medieval chapel,  Unknown Unknown Keith Emerick 01904 601988  wle  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  n cum Upsland  Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP:	Medieval settlement of Little Broughton, as Great and Little Broughton  Scheduled Monument (No. 31356) Localised/limited stock erosion Private  Round barrow 180m NNE of St Wilfred's Scheduled Monument (No. 25587)  Arable clipping Private  Round barrow 250m north east of Comer Scheduled Monument (No. 29526)  Extensive visitor erosion	CONTACT:  condition:  trend:  contact:  Church, Kirby Kno  condition:  trend:  contact:  Lodge, Kirklingtor  condition:  trend:  condition:  trend:  condition:	Keith Emerick 01904 601988  em and site of medieval chapel,  Unknown Unknown Keith Emerick 01904 601988  wle  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  n cum Upsland  Generally satisfactory but with significant localised problems Improving
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  OWNERSHIP:	Medieval settlement of Little Broughton, as Great and Little Broughton  Scheduled Monument (No. 31356) Localised/limited stock erosion Private  Round barrow 180m NNE of St Wilfred's Scheduled Monument (No. 25587)  Arable clipping Private  Round barrow 250m north east of Comer Scheduled Monument (No. 29526)  Extensive visitor erosion Private	CONTACT:  condition:  trend:  contact:  Church, Kirby Kno  condition:  trend:  contact:  Lodge, Kirklingtor  condition:  trend:  condition:  trend:  condition:	Keith Emerick 01904 601988  em and site of medieval chapel,  Unknown Unknown Keith Emerick 01904 601988  wle  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  n cum Upsland  Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988  Generally satisfactory
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Medieval settlement of Little Broughton, as Great and Little Broughton  Scheduled Monument (No. 31356) Localised/limited stock erosion Private  Round barrow 180m NNE of St Wilfred's Scheduled Monument (No. 25587)  Arable clipping Private  Round barrow 250m north east of Comer Scheduled Monument (No. 29526)  Extensive visitor erosion Private  Moated site known as The Rush, Marton of	CONTACT:  condition:  TREND:  CONDITION:  TREND:  CONTACT:  Contact:  Contact:  Contact:  TREND:  CONDITION:  TREND:  CONDITION:  TREND:  CONDITION:  TREND:  CONTACT:	Em and site of medieval chapel,  Unknown Unknown Keith Emerick 01904 601988  WIE  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  In cum Upsland  Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# NOTE: NOTE: If the priority category has changed since the 2009 register, the previous category is given in brackets.

CA LB/LBs NP RPG SM/SMs UA WHS

ABBREVIATIONS Conservation Area Listed Building/s National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site

SITE NAME:	Section of cross ridge dyke and earthworl	ks in Roman Planta	tion, Oulston Moor, Oulston
DESIGNATION:	Scheduled Monument (No. 26973)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	A moated site 100m east of St Mary Mago	dalene's Church,Th	irsk
DESIGNATION:	Scheduled Monument (No. 20532)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow known as Gospel Hill, 80m	south west of Pas	ture House,Thornton Watlass
DESIGNATION:	Scheduled Monument (No. 31358)	CONDITION:	Generally satisfactory
	,		but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Maiden Bower and Cock Lodge: a motte a windmill mound and associated linear out		oated site,
DESIGNATION:	Scheduled Monument (No. 20530)	CONDITION:	Generally satisfactory
	,		but with minor localised problems
PRINCIPAL VULNERABILITY:	Moderate vehicle damage/erosion	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Medieval Park Pale, Upsall Estate, Thirsk, U	Jpsall	
DESIGNATION:	Scheduled Monument (No. 12702)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Three round barrows at Three Hills 500m	north east of Can	np House,West Tanfield
DESIGNATION:	Scheduled Monument (No. 29508)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow on Rabbit Hill, I20m north	of High Park Hou	se,Winton, Stank and Hallikeld
DESIGNATION:	Scheduled Monument (No. 31357)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Four round barrows on Yearsley Moor 20	Om south west of h	High Lions' Lodge, Yearsley
DESIGNATION:	Scheduled Monument (No. 26966)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
	Private	CONTACT:	Keith Emerick 01904 601988
OWNERSHIP:	Tivate	COITINGI.	Reith Efficiency 01701 001700

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Round barrow on Yearsley Moor 330m SS	W of High Lions' L	.odge, Yearsley
DESIGNATION:	Scheduled Monument (No. 26968)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow on Yearsley Moor 400m so	uth west of High L	ions' Lodge,Yearsley
DESIGNATION:	Scheduled Monument (No. 26967)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Two round barrows on Yearsley Moor 550	m south west of H	ligh Lions' Lodge, Yearsley
DESIGNATION:	Scheduled Monument (No. 26969)	CONDITION:	Extensive significant problems
	,		i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988

#### **HARROGATE**



SITE NAME: Chapel of St Mary attached to the mansion, Allerton Park,
Allerton Mauleverer with Hopperton

DESIGNATION: Listed Building Grade II\*, RPG II
CONDITION: POOR
OCCUPANCY: Vacant
PRIORITY: C (C)
OWNERSHIP: Trust

Roman Catholic chapel, circa 1807, attached to the grade I house. The house stands on a promontory in the eastern section of the C18 park, with mid C19 terraces to the north. Much of the interior of the chapel has been stripped out for dry rot treatment. English Heritage has funded an up-to-date condition survey.

Contact: Giles Proctor 01904 601981



STIE NAME: Syningthwaite Priory Farmhouse, Rudgate, Bilton in Ainsty with Bickerton

DESIGNATION: Listed Building Grade I

CONDITION: Fair

OCCUPANCY: Vacant

PRIORITY: F (F)

OWNERSHIP: Private

Farmhouse consists of a front range of circa 1820 and a rear wing of C12 date with C15-C16 and C19 alterations. A full historical and archaeological survey has been completed by EH. Below-ground archaeological investigations are being undertaken. The (unlisted) farm buildings have been rebuilt as luxury holiday cottages. The external repair of the farmhouse is complete. The interior should be repaired this year.



Coach house and bee hives approx
10 metres to north of Nutwith Cote,
Grewelthorpe Road, Burton on Yore

DESIGNATION: Listed Building Grade II\*

CONDITION: Poor

OCCUPANCY: Part occupied

PRIORITY: A (A)

OWNERSHIP: Private

Coach house with bee hives. Mid C18 and C16. The rear hall of the coach house is settling and the end return of the bee hives is failing. There are structural cracks to the right hand return and rear, and some of the copings are missing from the rear gable. Pointing is failing to cut stone on facades leaving some stone loose.

Contact: Neil Redfern 01904 601897

Contact: Neil Redfern 01904 601897



SITE NAME: Outbuilding approx 20m to north of Nutwith Cote,
Grewelthorpe Road, Burton on Yore

DESIGNATION: Listed Building Grade II\*

CONDITION: Fair

OCCUPANCY: Vacant

PRIORITY: C (C)

Early C18 outbuilding/store. The building has been vacant for some time. Emergency re-roofing in corrugated asbestos was carried out many years ago. Building is slowly decaying, with open joints and defective rainwater goods. The corrugated asbestos roof appears to be failing at the ridge and at one of the gables.

Contact: Neil Redfern 01904 601897

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Private

OWNERSHIP:

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE: If the priority category has changed since the 2009 register, the previous category is given in brackets.

#### ABBREVIATIONS

CA Conservation Area
LB/LBs Listed Building/s
NP National Park
RPG Registered Park and Garden
SM/SMs Scheduled Monument/s
UA unitary Authority
WHS World Heritage Site



SITE NAME: Temple of Victory with railed enclosure, Allerton Park, Flaxby

DESIGNATION: Listed Building Grade II\*, RPG II


CONDITION: Fair
OCCUPANCY: Vacant

PRIORITY: E (E)

OWNERSHIP: Trust

Summerhouse or view point, I790, situated on a knoll in the park, to the NW of the house. Re-roofed in lead, cornice repaired and building made secure over I0 years ago with grant aid from English Heritage and Harrogate Borough Council. Repairs still needed to stonework below cornice level and to the steps and railings, and interior needs reinstating. Extensive views from the Temple over the park and surrounding landscape.

Contact: Giles Proctor 01904 601981



SITE NAME: Church of St Mary, Harlow Terrace, Harrogate

DESIGNATION: Listed Building Grade II\*, CA

CONDITION: Poor
OCCUPANCY: Vacant
PRIORITY: F (C)
OWNERSHIP: Company

Church circa 1916 by Sir Walter Tapper: Deterioration of the stone has occurred from an early date. There is evidence that the mineral felt to the aisle roofs is leaking. It is now proposed to convert the church into a luxury day spa, with minimal internal subdivision. English Heritage is proposing to support the cost of repairs.

Contact: Giles Proctor 01904 601981

Contact: Neil Redfern 01904 601897



SITE NAME: The Old Hall,
Middleton Quernhow

DESIGNATION: Listed Building Grade II, SM

condition: Poor

occupancy: Not applicable

PRIORITY: C (C)

OWNERSHIP: Private

Gable wall and part of the south wall of an early C17 house. Many open joints are visible and part of chimney stack appears to be unstable.



Orangery with flanking walls, botheys and pavilion (Ripley Castle), Ripley

DESIGNATION: Listed Building Grade II\*, CA, RPG II

CONDITION: Poor

occupancy: Part occupied

PRIORITY: C (C)
OWNERSHIP: Private

Classical Orangery in walled garden with flanking pavilions, circa 1785 by William Belwood. One surviving glasshouse circa 1840, now repaired. Botheys, in poor condition, to rear. East Pavilion recently repaired and some emergency repairs to Orangery. The balustrade has been dismantled and the cornice has been temporarily supported to prevent collapse.

Contact: Neil Redfern 01904 601897



SITE NAME: Butterton Bridge, Sawley

DESIGNATION: Scheduled Monument

CONDITION: Poc

occupancy: Not applicable

PRIORITY: C (D)

OWNERSHIP: Private

Medieval bridge, now crossed by a public footpath. The structure is overgrown and decaying and there is danger of structural collapse. English Heritage grant offered but not accepted by owner.

Contact: Neil Redfern 01904 601897



SITE NAME: Dob Park Lodge, Dob Park Lane, Weston

DESIGNATION: Listed Building Grade II, SM

condition: Very bad occupancy: Not applicable

PRIORITY: C (C)

OWNERSHIP: Private

Ruins of a C17 park lodge, now roofless structure three storeys high. Scheduled as an Ancient Monument in 1997.

Contact: Keith Emerick 01904 601988

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE:

If the priority category has changed since the 2009 register, the previous category is given in brackets.

#### ABBREVIATIONS

CA Conservation Area
LB/LBs Listed Building/s
NP National Park
RPG Registered Park and Garden
SM/SMs Scheduled Monument/s
UA unitary Authority
WHS World Heritage Site

SITE NAME:	Cairnfield, enclosures, boulder walling, holl of Snowden Carr centred at 370m south 6	,	•
DESIGNATION:	Scheduled Monument (No. 28065)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Cup, ring and groove marked rock in wall	220m south of Far	High Westcliff, Bewerley
DESIGNATION:	Scheduled Monument (No. 29105)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Stable
DWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Rock with complex carving south west of	a wall junction, 265	5m SSW of Far High Westcliff, Bewerley
DESIGNATION:	Scheduled Monument (No. 28099)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Rock with complex pattern of cup, ring and	d groove marks in v	wall 250m south of Far High Westcliff, Bev
DESIGNATION:	Scheduled Monument (No. 28100)	CONDITION:	Generally satisfactory
	,		but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Unknown
PRINCIPAL VULNERABILITY:  OWNERSHIP:	Plant growth Private	trend: contact:	Keith Emerick 01904 601988
	-	CONTACT:	Keith Emerick 01904 601988
ownership:	Private  Stone alignment west of Boroughbridge kr	CONTACT:	Keith Emerick 01904 601988  Arrows, including three standing stones  Generally satisfactory
OWNERSHIP: SITE NAME:	Stone alignment west of Boroughbridge kr and the setting for a fourth, Boroughbridge Scheduled Monument (No. 28221)	contact: nown as the Devil's e	Keith Emerick 01904 601988  Arrows, including three standing stones  Generally satisfactory but with significant localised problems
OWNERSHIP:  SITE NAME:  DESIGNATION:	Stone alignment west of Boroughbridge kr and the setting for a fourth, Boroughbridge Scheduled Monument (No. 28221)	contact: nown as the Devil's e	Keith Emerick 01904 601988  Arrows, including three standing stones  Generally satisfactory but with significant localised problems Improving
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Stone alignment west of Boroughbridge kr and the setting for a fourth, Boroughbridge Scheduled Monument (No. 28221)	contact:  nown as the Devil's e  condition:	Keith Emerick 01904 601988  Arrows, including three standing stones  Generally satisfactory but with significant localised problems
OWNERSHIP: SITE NAME:	Stone alignment west of Boroughbridge kr and the setting for a fourth, Boroughbridge Scheduled Monument (No. 28221)	contact:  nown as the Devil's e  condition:  trend:  contact:	Keith Emerick 01904 601988  Arrows, including three standing stones  Generally satisfactory but with significant localised problems Improving
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:	Stone alignment west of Boroughbridge kr and the setting for a fourth, Boroughbridge Scheduled Monument (No. 28221)  Arable clipping Private	contact:  nown as the Devil's e  condition:  trend:  contact:	Keith Emerick 01904 601988  Arrows, including three standing stones  Generally satisfactory but with significant localised problems Improving
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:	Stone alignment west of Boroughbridge kr and the setting for a fourth, Boroughbridge Scheduled Monument (No. 28221)  Arable clipping Private  Henge monument 300m north of Nunwick Scheduled Monument (No. 25585)	CONTACT:  nown as the Devil's e  CONDITION:  TREND:  CONTACT:	Keith Emerick 01904 601988  Arrows, including three standing stones  Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988
DWNERSHIP: DESIGNATION: PRINCIPAL VULNERABILITY: DWNERSHIP: DESIGNATION:	Stone alignment west of Boroughbridge kr and the setting for a fourth, Boroughbridge Scheduled Monument (No. 28221)  Arable clipping Private  Henge monument 300m north of Nunwick Scheduled Monument (No. 25585)  Arable ploughing	CONTACT:  nown as the Devil's e  CONDITION:  TREND:  CONTACT:	Keith Emerick 01904 601988  Arrows, including three standing stones  Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988  Extensive significant problems i.e. under plough, collapse Declining
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Stone alignment west of Boroughbridge kr and the setting for a fourth, Boroughbridge Scheduled Monument (No. 28221)  Arable clipping Private  Henge monument 300m north of Nunwick Scheduled Monument (No. 25585)	CONTACT:  nown as the Devil's e  CONDITION:  TREND:  CONTACT:  k, Hutton Conyers  CONDITION:	Keith Emerick 01904 601988  Arrows, including three standing stones  Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988  Extensive significant problems i.e. under plough, collapse
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Stone alignment west of Boroughbridge kr and the setting for a fourth, Boroughbridge Scheduled Monument (No. 28221)  Arable clipping Private  Henge monument 300m north of Nunwick Scheduled Monument (No. 25585)  Arable ploughing	CONTACT:  nown as the Devil's e  CONDITION:  TREND:  CONTACT:  k, Hutton Conyers  CONDITION:  TREND:	Keith Emerick 01904 601988  Arrows, including three standing stones  Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988  Extensive significant problems i.e. under plough, collapse Declining
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DWNERSHIP:	Stone alignment west of Boroughbridge kr and the setting for a fourth, Boroughbridge Scheduled Monument (No. 28221)  Arable clipping Private  Henge monument 300m north of Nunwick Scheduled Monument (No. 25585)  Arable ploughing Private	CONTACT:  nown as the Devil's e  CONDITION:  TREND:  CONTACT:  k, Hutton Conyers  CONDITION:  TREND:	Arrows, including three standing stones  Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988  Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988  Generally satisfactory
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  DESIGNATION:	Stone alignment west of Boroughbridge kr and the setting for a fourth, Boroughbridge Scheduled Monument (No. 28221)  Arable clipping Private  Henge monument 300m north of Nunwick Scheduled Monument (No. 25585)  Arable ploughing Private  Hutton Hall (site of), Hutton Conyers	CONTACT:  nown as the Devil's e  CONDITION:  TREND:  CONTACT:  k, Hutton Conyers  CONDITION:  TREND:  CONTACT:	Arrows, including three standing stones  Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988  Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Stone alignment west of Boroughbridge kr and the setting for a fourth, Boroughbridge Scheduled Monument (No. 28221)  Arable clipping Private  Henge monument 300m north of Nunwick Scheduled Monument (No. 25585)  Arable ploughing Private  Hutton Hall (site of), Hutton Conyers Scheduled Monument (No. NY1002)	CONTACT:  nown as the Devil's e  CONDITION:  TREND:  CONTACT:  k, Hutton Conyers  CONDITION:  TREND:  CONTACT:	Arrows, including three standing stones  Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988  Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988  Generally satisfactory but with minor localised problems
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:	Stone alignment west of Boroughbridge kr and the setting for a fourth, Boroughbridge Scheduled Monument (No. 28221)  Arable clipping Private  Henge monument 300m north of Nunwick Scheduled Monument (No. 25585)  Arable ploughing Private  Hutton Hall (site of), Hutton Conyers  Scheduled Monument (No. NY1002)  Localised/limited stock erosion	CONTACT:  nown as the Devil's e  CONDITION:  TREND:  CONTACT:  K, Hutton Conyers  CONDITION:  TREND:  CONTACT:  CONDITION:  TREND:  CONTACT:	Arrows, including three standing stones  Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988  Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988  Generally satisfactory but with minor localised problems Stable
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:	Stone alignment west of Boroughbridge kr and the setting for a fourth, Boroughbridge Scheduled Monument (No. 28221)  Arable clipping Private  Henge monument 300m north of Nunwick Scheduled Monument (No. 25585)  Arable ploughing Private  Hutton Hall (site of), Hutton Conyers  Scheduled Monument (No. NY1002)  Localised/limited stock erosion Private  Round barrow 150m east of Burtree Hill, 1	CONTACT:  nown as the Devil's e  CONDITION:  TREND: CONTACT:  K, Hutton Conyers  CONDITION:  TREND: CONTACT:  CONDITION:  TREND: CONTACT:  Hutton Conyers	Arrows, including three standing stones  Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988  Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988  Generally satisfactory but with minor localised problems Stable Keith Emerick 01904 601988
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:	Stone alignment west of Boroughbridge kr and the setting for a fourth, Boroughbridge Scheduled Monument (No. 28221)  Arable clipping Private  Henge monument 300m north of Nunwick Scheduled Monument (No. 25585)  Arable ploughing Private  Hutton Hall (site of), Hutton Conyers  Scheduled Monument (No. NY1002)  Localised/limited stock erosion Private	CONTACT:  nown as the Devil's e  CONDITION:  TREND:  CONTACT:  K, Hutton Conyers  CONDITION:  TREND:  CONTACT:  CONDITION:  TREND:  CONTACT:	Arrows, including three standing stones  Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988  Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988  Generally satisfactory but with minor localised problems Stable Keith Emerick 01904 601988  Extensive significant problems
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  DESIGNATION:	Stone alignment west of Boroughbridge kr and the setting for a fourth, Boroughbridge Scheduled Monument (No. 28221)  Arable clipping Private  Henge monument 300m north of Nunwick Scheduled Monument (No. 25585)  Arable ploughing Private  Hutton Hall (site of), Hutton Conyers  Scheduled Monument (No. NY1002)  Localised/limited stock erosion Private  Round barrow 150m east of Burtree Hill, 1	CONTACT:  nown as the Devil's e  CONDITION:  TREND: CONTACT:  K, Hutton Conyers  CONDITION:  TREND: CONTACT:  CONDITION:  TREND: CONTACT:  Hutton Conyers	Arrows, including three standing stones  Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988  Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988  Generally satisfactory but with minor localised problems Stable Keith Emerick 01904 601988

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Round barrow 300m WNW of Low Barn,	Hutton Conyers	
DESIGNATION:	Scheduled Monument (No. 25573)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
AAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA	Timate	CONTROL.	Refut Effected 01701 001700
SITE NAME:	Round barrow at Moor House, Hutton Co	onyers	
DESIGNATION:	Scheduled Monument (No. 25572)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
ITE NAME:	Round barrow in Harland's Plantation, Hut	tton Conyers	
DESIGNATION:	Scheduled Monument (No. 25574)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
PRINCIPAL VULNERABILITY:  DWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
ZVVINERSPIIF:	ilivate	CONTACT:	NEIGH EHIGHER OFFOT OUT 700
SITE NAME:	Motte and bailey castle, known as Mowbra	ay Castle, east of K	irkby Malzeard, Kirkby Malzeard
DESIGNATION:	Scheduled Monument (No. 26935)	CONDITION:	Generally satisfactory but with significant localised problems
	Scrub / tree growth	TREND:	Declining
'RINCIPAL VULNERABILITY:	Sci db / ti cc gi owti i	TINLIND.	Dec
PRINCIPAL VULNERABILITY:  DWNERSHIP:	Private growth	CONTACT:	Keith Emerick 01904 601988
	~	CONTACT:	Keith Emerick 01904 601988
OWNERSHIP:	Private	CONTACT:	Meith Emerick 01904 601988  Inds and outwork, Kirkby Overblow  Generally unsatisfactory
OWNERSHIP: SITE NAME:	Private  Rougemont Castle ringwork and bailey an	CONTACT: d associated fishpo	Keith Emerick 01904 601988
OWNERSHIP:  SITE NAME:  DESIGNATION:	Private  Rougemont Castle ringwork and bailey an  Scheduled Monument (No. 13296)	contact:  d associated fishpo  condition:	nds and outwork, Kirkby Overblow  Generally unsatisfactory with major localised problems
DWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Private  Rougemont Castle ringwork and bailey an Scheduled Monument (No. 13296)  Moderate animal burrowing	contact:  d associated fishpo  condition:  trend:  contact:	Keith Emerick 01904 601988  Inds and outwork, Kirkby Overblow  Generally unsatisfactory  with major localised problems  Declining  Keith Emerick 01904 601988
DWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:	Private  Rougemont Castle ringwork and bailey an Scheduled Monument (No. 13296)  Moderate animal burrowing Private	contact:  d associated fishpo  condition:  trend:  contact:	Keith Emerick 01904 601988  Inds and outwork, Kirkby Overblow  Generally unsatisfactory  with major localised problems  Declining  Keith Emerick 01904 601988
DWNERSHIP:  JITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  JITE NAME:	Private  Rougemont Castle ringwork and bailey an Scheduled Monument (No. 13296)  Moderate animal burrowing Private  Medieval monastic fishponds immediately	d associated fishpo  CONDITION:  TREND:  CONTACT:  east of Park House	Keith Emerick 01904 601988  Inds and outwork, Kirkby Overblow  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  In Markington with Wallerthwaite
DWNERSHIP:  ITE NAME:  DESIGNATION:  RINCIPAL VULNERABILITY:  DWNERSHIP:  ITE NAME:  DESIGNATION:	Private  Rougemont Castle ringwork and bailey an Scheduled Monument (No. 13296)  Moderate animal burrowing Private  Medieval monastic fishponds immediately	d associated fishpo  CONDITION:  TREND:  CONTACT:  east of Park House	Keith Emerick 01904 601988  Inds and outwork, Kirkby Overblow  Generally unsatisfactory  with major localised problems  Declining  Keith Emerick 01904 601988  In Markington with Wallerthwaite  Generally unsatisfactory
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:	Private  Rougemont Castle ringwork and bailey an Scheduled Monument (No. 13296)  Moderate animal burrowing Private  Medieval monastic fishponds immediately Scheduled Monument (No. 31338)	CONTACT:  d associated fishpo  CONDITION:  TREND:  CONTACT:  east of Park House  CONDITION:	Keith Emerick 01904 601988  Inds and outwork, Kirkby Overblow  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  In Markington with Wallerthwaite Generally unsatisfactory with major localised problems
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Private  Rougemont Castle ringwork and bailey an Scheduled Monument (No. 13296)  Moderate animal burrowing Private  Medieval monastic fishponds immediately Scheduled Monument (No. 31338)  Extensive vehicle damage/erosion	CONTACT:  d associated fishpo  CONDITION:  TREND:  CONTACT:  east of Park House  CONDITION:  TREND:  CONTACT:	Reith Emerick 01904 601988  Inds and outwork, Kirkby Overblow  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  India and outwork, Kirkby Overblow  Generally unsatisfactory with major with Wallerthwaite  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:	Private  Rougemont Castle ringwork and bailey an Scheduled Monument (No. 13296)  Moderate animal burrowing Private  Medieval monastic fishponds immediately Scheduled Monument (No. 31338)  Extensive vehicle damage/erosion Private	CONTACT:  d associated fishpo  CONDITION:  TREND:  CONTACT:  east of Park House  CONDITION:  TREND:  CONTACT:	Reith Emerick 01904 601988  Inds and outwork, Kirkby Overblow  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  India and outwork, Kirkby Overblow  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DWNERSHIP:  DWNERSHIP:	Private  Rougemont Castle ringwork and bailey an Scheduled Monument (No. 13296)  Moderate animal burrowing Private  Medieval monastic fishponds immediately Scheduled Monument (No. 31338)  Extensive vehicle damage/erosion Private  Henge monument 300m north west of Cascheduled Monument (No. 25579)	CONTACT:  d associated fishpo  CONDITION:  TREND:  CONTACT:  east of Park House  CONDITION:  TREND:  CONTACT:	Keith Emerick 01904 601988  Inds and outwork, Kirkby Overblow  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  In Markington with Wallerthwaite  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  In Moor  Extensive significant problems i.e. under plough, collapse
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DWNERSHIP:  DWNERSHIP:	Private  Rougemont Castle ringwork and bailey an Scheduled Monument (No. 13296)  Moderate animal burrowing Private  Medieval monastic fishponds immediately Scheduled Monument (No. 31338)  Extensive vehicle damage/erosion Private  Henge monument 300m north west of Cascheduled Monument (No. 25579)  Arable ploughing	CONTACT:  d associated fishpo  CONDITION:  TREND:  CONTACT:  east of Park House  CONDITION:  TREND:  CONTACT:	Keith Emerick 01904 601988  Inds and outwork, Kirkby Overblow  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Indicate the major localised problems Declining With major localised problems Declining Weith Emerick 01904 601988  Indicate the major localised problems Declining Weith Emerick 01904 601988  Indicate the major localised problems Declining Weith Emerick 01904 601988  Indicate the major localised problems Declining  Indicate the major localised problems Declining
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DWNERSHIP:  DWNERSHIP:  DESIGNATION:  DESIGNATION:	Private  Rougemont Castle ringwork and bailey an Scheduled Monument (No. 13296)  Moderate animal burrowing Private  Medieval monastic fishponds immediately Scheduled Monument (No. 31338)  Extensive vehicle damage/erosion Private  Henge monument 300m north west of Cascheduled Monument (No. 25579)	CONTACT:  d associated fishpo  CONDITION:  TREND:  CONTACT:  east of Park House  CONDITION:  TREND:  CONTACT:  CONTACT:	Keith Emerick 01904 601988  Inds and outwork, Kirkby Overblow  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  In Markington with Wallerthwaite  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  In Moor  Extensive significant problems i.e. under plough, collapse
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:	Private  Rougemont Castle ringwork and bailey an Scheduled Monument (No. 13296)  Moderate animal burrowing Private  Medieval monastic fishponds immediately Scheduled Monument (No. 31338)  Extensive vehicle damage/erosion Private  Henge monument 300m north west of Cascheduled Monument (No. 25579)  Arable ploughing	CONTACT:  d associated fishpo  CONDITION:  TREND:  CONTACT:  east of Park House  CONDITION:  TREND:  CONTACT:  Ina Barn, Marton-le  CONDITION:  TREND:  CONTACT:	Keith Emerick 01904 601988  Inds and outwork, Kirkby Overblow  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Indicate the major localised problems Declining With major localised problems Declining Weith Emerick 01904 601988  Indicate the major localised problems Declining Weith Emerick 01904 601988  Indicate the major localised problems Declining Weith Emerick 01904 601988  Indicate the major localised problems Declining  Indicate the major localised problems Declining
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:	Rougemont Castle ringwork and bailey an Scheduled Monument (No. 13296)  Moderate animal burrowing Private  Medieval monastic fishponds immediately Scheduled Monument (No. 31338)  Extensive vehicle damage/erosion Private  Henge monument 300m north west of Ca Scheduled Monument (No. 25579)  Arable ploughing Private	CONTACT:  d associated fishpo  CONDITION:  TREND:  CONTACT:  east of Park House  CONDITION:  TREND:  CONTACT:  Ina Barn, Marton-le  CONDITION:  TREND:  CONTACT:	Reith Emerick 01904 601988  Inds and outwork, Kirkby Overblow  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  In Markington with Wallerthwaite  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  In Moor  Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988  Generally unsatisfactory
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DWNERSHIP:	Private  Rougemont Castle ringwork and bailey an Scheduled Monument (No. 13296)  Moderate animal burrowing Private  Medieval monastic fishponds immediately Scheduled Monument (No. 31338)  Extensive vehicle damage/erosion Private  Henge monument 300m north west of Cascheduled Monument (No. 25579)  Arable ploughing Private  Moated site 50m north west of Red House	CONTACT:  d associated fishpo  CONDITION:  TREND:  CONTACT:  east of Park House  CONDITION:  TREND:  CONTACT:  Ina Barn, Marton-le  CONDITION:  TREND:  CONTACT:	Reith Emerick 01904 601988  Inds and outwork, Kirkby Overblow  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  India Markington with Wallerthwaite  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  India Markington  Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Green Howe bowl barrow, 280m south of Bank House, North Deighton		
DESIGNATION:	Scheduled Monument (No. 26622)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Moated site 50m north east of North Rig	ton School, North	Rigton
SITE NAME:	Moated site 50m north east of North Rig	ton School, North	Rigton
	Moated site 50m north east of North Rig Scheduled Monument (No. 29538)	ton School, North	Rigton  Generally satisfactory
			•
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:			Generally satisfactory
DESIGNATION:	Scheduled Monument (No. 29538)	CONDITION:	Generally satisfactory but with significant localised problems

SITE NAME:

#### Cairn 7m in diameter north of track east of plantation on Weston Moor 450m WNW of Weston Moor Cottage, Weston

DESIGNATION:	Scheduled Monument (No. 28074)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988



Allerton Park. SITE NAME: Allerton Mauleverer with Hopperton DESIGNATION: Registered Park and Garden Grade II, also 19 LBs

CONDITION: Generally unsatisfactory with major localised problems

VULNERABILITY: Medium Declining TREND:

Private, multiple owners OWNERSHIP:

Mid C19 terraced gardens which provide the setting for a country house, surrounded by parkland which was enlarged in the 1720s and reworked in the 1770s. C20 woodland planting has significantly changed the character of the historic landscape and a number of listed structures are in poor condition.

Contact: Andy Wimble 01904 601970



Swinton Castle, SITE NAME: Swinton with Warthermarske

DESIGNATION: Registered Park and Garden Grade II\*, also 7 LBs

Generally satisfactory CONDITION: but with significant localised problems

VULNERABILITY: Medium

Declining TREND: Private, single owner OWNERSHIP:

or earlier origins. Significant proportion of the tree cover has reached maturity and beyond, some structures in poor condition and water bodies in Quarry Gill woods

Gardens and extensive pleasure grounds with grottoes,

rustic bridges and rockwork laid out from 1796 to circa

1820 under the direction of Adam Mickle the second

and others for Sir William Danby, incorporating lakes and landscaping of circa 1760. The park probably has C17

Contact: Andy Wimble 01904 601970



Battle of Boroughbridge, SITE NAME: Boroughbridge / Langthorpe / Milby

DESIGNATION: Registered Battlefield Declining TREND: OWNERSHIP: Private

Thomas Earl of Lancaster's 1322 revolt against Edward II ended with defeat as his army attempted to retreat north and cross the River Ure. Much of the battlefield lies under modern Boroughbridge; further expansion is possible north of the river.

Contact: Susan Daniels 01904 601 979

#### PRIORITY (FOR BUILDINGS)


- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# NOTE: If the priority category has changed since the 2009 register, the previous category is given in brackets.

NIP

ABBREVIATIONS CA LB/LBs Conservation Area Conservation Area Listed Building/s National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site RPG SM/SMs UA WHS

#### NORTH YORK MOORS (NP)



Ruins of Whorlton Castle Undercroft, C14 castle. Parts of two vaulted chambers remain. SITE NAME: Castle Bank, Whorlton,

Hambleton

DESIGNATION: Listed Building Grade II\*, SM, CA

Poor CONDITION:

Not applicable OCCUPANCY:

D (D) PRIORITY: Private OWNERSHIP:

Conservation plan complete. Options appraisal in progress.

Shell remains of a late C14 gatehouse, which was altered

Decorative temple, circa 1730, attributed to Vanbrugh,

situated at the north end of the approximately 800m long, grass East Terrace, approximately I 20m east of

the house. The column shafts are badly decayed.


The possibility of full repair is under discussion.

The trial repair of one column is complete.

in the C16. Conservation plan complete. Options appraisal

Contact: Keith Emerick 01904 601988

in progress.



Whorlton Castle Gatehouse, SITE NAME: Castle Bank, Whorlton,

Hambleton

DESIGNATION: Listed Building Grade I, SM, CA

CONDITION:

occupancy: Not applicable

D (D) PRIORITY: Private OWNERSHIP:

Contact: Keith Emerick 01904 601988



Ionic Temple, SITE NAME: Duncombe Park Estate, Helmsley, Ryedale

DESIGNATION: Listed Building Grade I

CONDITION: Poor

occupancy: Not applicable

PRIORITY: D (C) Private OWNERSHIP:

Contact: Giles Proctor 01904 601981



Tuscan Temple, SITE NAME: Duncombe Park Estate, Helmsley, Ryedale

DESIGNATION: Listed Building Grade I, CA

CONDITION:

occupancy: Not applicable

C (New) PRIORITY-

OWNERSHIP: Private Decorative temple circa 1730 in the Palladian style situated at the south end of the East Terrace. The column shafts are badly decayed and internal plasterwork falling.

Contact: Giles Proctor 01904 601981



Ayton Castle, SITE NAME:

Castle Rise, West Ayton,

Scarborough

DESIGNATION: Listed Building Grade I, SM

Poor CONDITION:

OCCUPANCY: Not applicable

F (F) PRIORITY:

OWNERSHIP: Local authority

Pele tower, late C14. The upper storeys are ruinous, but the undercroft still has a vaulted roof. Subject to weathering. The site has been the subject of a detailed condition survey. Conservation plan completed.

Contact: Keith Emerick 01904 601988

SITE NAME:

#### Fox Howe round barrow, Allerston

DESIGNATION:	Scheduled Monument (No. 34589)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNERSHIP:	Government or Agency	CONTACT:	Keith Emerick 01904 601988

#### Oxmoor and Givendale Dikes: prehistoric linear boundaries and associated features, Allerston SITE NAME:

DESIGNATION:	Scheduled Monument (No. 35443)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE:

If the priority category has changed since the 2009 register, the previous category is given in brackets.

#### ABBREVIATIONS

CA LB/LBs Conservation Area Conservation Area Listed Building/s National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site NIP RPG SM/SMs UA WHS

SITE NAME:	Round barrow 250m south east of the Ade	der Stone, Allersto	n
DESIGNATION:	Scheduled Monument (No. 34595)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNERSHIP:	Government or Agency	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Two round barrows on Low Common,Ap	pleton-le-Moors	
DESIGNATION:	Scheduled Monument (No. NY592)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Standing stone 470m north east of High Fa	arm, known as Wa	de's Stone, Barnby
DESIGNATION:	Scheduled Monument (No. 32481)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow on Beadlam Rigg, 490m we	st of Stone Ruckle	s round barrow, Beadlam
DESIGNATION:	Scheduled Monument (No. 32693)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Group of round barrows on Bilsdale Moor	1/2 mile (800m) I	NW of Fangdale Beck, Bilsdale Midcable
DESIGNATION:	Scheduled Monument (No. NY613)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow at Money Howe, Bilsdale Ea	ast Moor, Bilsdale 1	Midcable
DESIGNATION:	Scheduled Monument (No. 25549)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Urra Moor prehistoric linear boundary on the western edge of Urra Moor, Bilsdale Midcable		
DESIGNATION:	Scheduled Monument (No. 29506)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Pit alignment forming part of the Cleave D	yke system 1000m	n north west of Dialstone Farm, Boltby
DESIGNATION:	Scheduled Monument (No. 25565)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

CA LB/LBs NP RPG SM/SMs UA WHS

SITE NAME:	Pit alignment, part of the Cleave Dyke pre 450m south east of High Paradise, Boltby	historic boundary s	system and round barrow
DESIGNATION:	Scheduled Monument (No. 26942)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Ravensthorpe manor house (site of), Boltb	у	
DESIGNATION:	Scheduled Monument (No. NY980)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Localised/limited animal burrowing	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 200m east of High Barn, Bo	oltby	
DESIGNATION:	Scheduled Monument (No. 25584)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 400m south east of Hill Fo		
DESIGNATION:	Scheduled Monument (No. 25559)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 500m south east of Hill Fo	rt Windypit, Boltby	
DESIGNATION:	Scheduled Monument (No. 25560)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
DWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
TITE NAME:	Round barrow 600m north east of South	Woods, Boltby	
DESIGNATION:	Scheduled Monument (No. 25561)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 650m east of South Woods	s, Boltby	
DESIGNATION:	Scheduled Monument (No. 25562)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
IITE NAME:	Section of Cleave Dyke, I.4km long from Sincluding two pit alignments and round ba		on to east edge of Town's Pasture Wood
		-	
		CONDITION:	Extensive significant problems
DESIGNATION:	Scheduled Monument (No. 26927)	CONDITION.	
DESIGNATION:			i.e. under plough, collapse
DESIGNATION: PRINCIPAL VULNERABILITY: DWNERSHIP:	Scheduled Monument (No. 26927)  Arable ploughing  Private	TREND:  CONTACT:	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# NOTE: NOTE: If the priority category has changed since the 2009 register, the previous category is given in brackets.

#### ABBREVIATIONS

SITE NAME:	Section of the Cleave Dyke system known	n as Hesketh Dike a	and Silver Hill round barrow, Boltby
DESIGNATION:	Scheduled Monument (No. 24454)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Section of the Cleave Dyke system on Arc including the Steeple Cross boundary stor		own as Steeple Cross Dyke
DESIGNATION:	Scheduled Monument (No. 25597)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Two round barrows at Seta Pike, Boltby		
DESIGNATION:	Scheduled Monument (No. 25516)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
ITE NAME:	Late prehistoric enclosed settlement and		rowby Moor,
	360m south of Moor House Farm, Borrov	vby	
DESIGNATION:	Scheduled Monument (No. 32025)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Cockan Cross wayside cross 600m west o	of Fox Hole Crag, B	Bransdale
DESIGNATION:	Scheduled Monument (No. 25686)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow at Crook Staff Hill, Bransda	ale	
DESIGNATION:	Scheduled Monument (No. 25544)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Northern section of prehistoric linear bot known as Rise Dikes, in Wykeham Forest,		ecting hollow ways,
DESIGNATION:	Scheduled Monument (No. 33733)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow in Wykeham Forest, 440m	east of Jenny Thrus	h Spring, Brompton
DESIGNATION:	Scheduled Monument (No. 34164)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

## ABBREVIATIONS

Private Contract. Keith Emerick 01904 601988  Cross dyke in Cloughton Plantations, 550m and 890m north east of Gowland Farm, Cloughton  Scheduled Monument (No. 34564)  EBEGINATION  Scheduled Monument (No. 34564)  CONDITION: Generally satisfactory but with significant localised problems  Plant growth  TRIND  Declining  Other  CONTACT: Keith Emerick 01904 601988  Round barrow 150m south of Thirley Beck Farm, Cloughton  ESCHEDULAR ABBUTY  Arable ploughing  TRIND  Declining  OWNERSHIP  Private  Round barrow known as Hunter Howe, Cloughton  ESCHEDULAR ABBUTY  FIRE NAME:  Round barrow known as Hunter Howe, Cloughton  ESCHEDULAR ABBUTY  Plant growth  TRIND  Declining  OTHER  CONTACT: Keith Emerick 01904 601988  Round barrow known as Hunter Howe, Cloughton  ESCHEDULAR ABBUTY  FIRE NAME:  Round barrow known as Hunter Howe, Cloughton  DESCHANDON  Scheduled Monument (No. 34562)  CONDITION:  Generally satisfactory  with major localised problems  Plant growth  TRIND  Declining  OTHER  Stone hut circle and iron working site on Holm Slack, 300m south of The Hulleys, Cloughton  DESCHANDON  Scheduled Monument (No. 34568)  CONDITION:  Generally satisfactory  but with significant localised problems  FORESTRY  TRIND:  Declining  CONDITION:  Generally satisfactory  but with significant localised problems  FORESTRY  TRIND:  Declining  CONDITION:  Generally satisfactory  but with significant localised problems  FORESTRY  TRIND:  DESCHANDON  DESCHANDON  DESCHANDON  DESCHANDON  CONDITION:  Generally satisfactory  but with significant localised problems  FORESTRY  TRIND:  DESCHANDON  DESCHANDON  DESCHANDON  DESCHANDON  CONDITION:  Generally satisfactory  but with significant localised problems  FORESTRY  TRIND:  DESCHANDON  DESCHANDON  DESCHANDON  DESCHANDON	SITE NAME:	Round barrow on Troutsdale Brow, 165m	south east of Jenny	Thrush Spring, Brompton
Plant growth private conserve Keith Emerick 01904 601988  Round barrow, lime Idin and warrening enclosure in Wykeham Forest, S40m east of Jenny Thrush Spring, Brompton  Scheduled Monument (No. 34163)  Plant growth Thrush Spring, Brompton  Private Conserve Keith Emerick 01904 601988  Round barrow as west of Green Bank, Carlton  Scheduled Monument (No. 25524)  Conserve Conserve Keith Emerick 01904 601988  Round barrow Scheduled Monument (No. 25524)  Conserve Conserve Conserve Keith Emerick 01904 601988  Round barrow Scheduled Monument (No. 25524)  Conserve Conserve Conserve Keith Emerick 01904 601988  Round barrow Round Farm, Cloughton Plantations, 550m and 890m north east of Gowland Farm, Cloughton  Conserve Conser	DESIGNATION:	Scheduled Monument (No. 34162)	CONDITION:	Generally unsatisfactory
Government or Agency   Contact:   Keth Emerick 01904 601988				with major localised problems
Round barrow, lime kiln and warrening enclosure in Wykeham Forest, 540m east of Jenny Thrush Spring, Brompton  Scheduled Monument (No. 34163)  CONDITION  Scheduled Monument (No. 34163)  CONDITION  Plant growth  Private  Round barrow 350m west of Green Bank, Carlton  Scheduled Monument (No. 25524)  CONDITION  Private  Cross dyke in Cloughton Plantations, 550m and 890m north east of Gowland Farm, Cloughton  Scheduled Monument (No. 34564)  CONDITION  Scheduled Monument (No. 34564)  CONDITION  Scheduled Monument (No. 34564)  CONDITION  CONDITION  Scheduled Monument (No. 34564)  CONDITION  Condi	PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
Scheduled Monument (No. 34163)  Scheduled Monument (No. 25524)  Scheduled Monument (No. 34564)  Scheduled Monument (No. 34564)  Scheduled Monument (No. 34564)  Scheduled Monument (No. 34569)  Scheduled Monument (No. 34569)	OWNERSHIP:	Government or Agency	CONTACT:	Keith Emerick 01904 601988
Dut with significant localised problems Plant growth Private  Round barrow 350m west of Green Bank, Carlton  Scheduled Monument (No. 25524)  Scheduled Monumen	SITE NAME:			n Forest,
Plant growth Private  Round barrow 350m west of Green Bank, Carlton  Scheduled Monument (No. 25524)  CONDITION  Plant growth Private  Round barrow 350m west of Green Bank, Carlton  Scheduled Monument (No. 25524)  CONDITION  Plant growth Private  CONDITION  Plant growth Private  CONDITION  CONDITION  Repertally satisfactory but with significant localised problems  Private  CONDITION  CONDITION  Repertally satisfactory but with significant localised problems  Repertally satisfactory but with significant problems  Repertally satisfactory with major localised problems  Repertally satisfactory but with significant loca	DESIGNATION:	Scheduled Monument (No. 34163)	CONDITION:	· · · · · · · · · · · · · · · · · · ·
Round barrow 350m west of Green Bank, Carlton  Scheduled Monument (No. 25524)  CONDITION  Declining  Private  Cross dyke in Cloughton Plantations, 550m and 890m north east of Gowland Farm, Cloughton  SECONDATE  SECONDATE  CONTROL  CONTROL  CONTROL  Reith Emerick 01904 601988  SET NAME  Cross dyke in Cloughton Plantations, 550m and 890m north east of Gowland Farm, Cloughton  SECONDATION  Scheduled Monument (No. 34564)  CONDITION  CONDITI	PRINCIPAL VULNERABILITY:	Plant growth	TREND:	
Scheduled Monument (No. 25524)  Scheduled Monument (No. 25524)  Plant growth  TEND  Declining  Scheduled Monument (No. 34564)  SCHEDING	DWNERSHIP:	-	CONTACT:	·
Dut with significant localised problems Private Plant growth Private Constant Private Cross dyke in Cloughton Plantations, 550m and 890m north east of Gowland Farm, Cloughton Description	ITE NAME:	Round barrow 350m west of Green Bank	, Carlton	
Plant growth TREAD: Declining CONSTRUCT CONTACT Reith Emerick 01904 601988  STEINAME: Cross dyke in Cloughton Plantations, 550m and 890m north east of Gowland Farm, Cloughton DESIGNATION: Scheduled Monument (No. 34564) CONDITION Generally satisfactory but with significant localised problems Declining OWNERSHER Other CONTACT: Keith Emerick 01904 601988  Round barrow 150m south of Thirley Beck Farm, Cloughton DESIGNATION: Scheduled Monument (No. 34569) CONDITION Extensive significant problems i.e. under plough, collapse Declining OWNERSHER Private Round barrow known as Hunter Howe, Cloughton DESIGNATION: Scheduled Monument (No. 34569) CONTACT: Keith Emerick 01904 601988  RETEINAME: Round barrow known as Hunter Howe, Cloughton DESIGNATION: Scheduled Monument (No. 34562) CONDITION DESIGNATION: Scheduled Monument (No. 34562) CONDITION DESIGNATION: Scheduled Monument (No. 34562) CONDITION DESIGNATION: Declining DESIGNATION: Declining DESIGNATION: Declining DESIGNATION: Scheduled Monument (No. 34568) CONDITION D	DESIGNATION:	Scheduled Monument (No. 25524)	CONDITION:	
Cross dyke in Cloughton Plantations, 550m and 890m north east of Gowland Farm, Cloughton  Scheduled Monument (No. 34564)  Scheduled Monument (No. 34564)  CONDITION  Scheduled Monument (No. 34564)  CONDITION  Scheduled Monument (No. 34564)  CONDITION  Plant growth  TREND  Declining  OWNESSHIP  Other  CONTACT: Keith Emerick 01904 601988  Round barrow 150m south of Thirley Beck Farm, Cloughton  Scheduled Monument (No. 34569)  Scheduled Monument (No. 34569)  CONDITION  Extensive significant problems  i.e. under plough, collapse  PRINCIPAL VULNERABILITY:  Arable ploughing  TREND  Declining  OWNESSHIP  Private  CONTACT: Keith Emerick 01904 601988  Round barrow known as Hunter Howe, Cloughton  Scheduled Monument (No. 34562)  CONDITION  Scheduled Monument (No. 34562)  CONDITION  Scheduled Monument (No. 34562)  CONDITION  Scheduled Monument (No. 34562)  CONTACT: Keith Emerick 01904 601988  PRINCIPAL VULNERABILITY:  Plant growth  TREND  Declining  OWNESSHIP  Other  CONTACT: Keith Emerick 01904 601988  Steen hut circle and iron working site on Holm Slack, 300m south of The Hulleys, Cloughton  DESCRAPIONE  Scheduled Monument (No. 34568)  CONDITION:  Scheduled Monument (No. 34568)  CONDITION:  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY:  Forestry  TREND  Declining  OWNESSHIP  Other  CONTACT:  Keith Emerick 01904 601988  CONDITION:  Generally satisfactory but with significant localised problems  CONTACT:  Keith Emerick 01904 601988	PRINCIPAL VULNERABILITY:	Plant growth	TREND:	-
Scheduled Monument (No. 34564)  Scheduled Monument (No. 34564)  Scheduled Monument (No. 34564)  Stername:  Round barrow 150m south of Thirley Beck Farm, Cloughton  Designation:  Scheduled Monument (No. 34569)  Scheduled Monument (No. 34562)  Scheduled Monument (No. 34568)  Scheduled Mo	OWNERSHIP:	-	CONTACT:	~
Dut with significant localised problems Declining Devinership Other Other Contact: Keith Emerick 01904 601988  Stenance Scheduled Monument (No. 34569) Condition: Extensive significant problems Lie. under plough, collapse Declining Devinership Declining Declining Devinership Declining Declining Devinership Declining Devinership Declining Devinership Declining Devinership Declining Devinership Declining Devinership Declining Declining Devinership Declining Dev	SITE NAME:	Cross dyke in Cloughton Plantations, 550r	m and 890m north	east of Gowland Farm, Cloughton
Plant growth Other Other CONTACT: Keith Emerick 01904 601988  STEINAME: Round barrow 150m south of Thirley Beck Farm, Cloughton  DESIGNATION: Scheduled Monument (No. 34569) DESIGNATION: PRINCIPAL VULNERABILITY: Arable ploughing TREND: DESIGNATION: Private  Round barrow known as Hunter Howe, Cloughton  DESIGNATION: Scheduled Monument (No. 34562) DESIGNATION: DESIGNATION: DESIGNATION: Scheduled Monument (No. 34562) DESIGNATION: DESI	DESIGNATION:	Scheduled Monument (No. 34564)	CONDITION:	
CONTACT: Keith Emerick 01904 601988  Round barrow 150m south of Thirley Beck Farm, Cloughton  Scheduled Monument (No. 34569)  CONDITION: Extensive significant problems i.e. under plough, collapse  PRINCIPAL VULNERABILITY: Arable ploughing  TREND: Declining  CONTACT: Keith Emerick 01904 601988  Round barrow known as Hunter Howe, Cloughton  Scheduled Monument (No. 34562)  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth  TREND: Declining  CONTACT: Keith Emerick 01904 601988  STEINAME: Stone hut circle and iron working site on Holm Slack, 300m south of The Hulleys, Cloughton  DESIGNATION: Scheduled Monument (No. 34568)  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Forestry  TREND: Declining  CONTACT: Keith Emerick 01904 601988  STEINAME: Scheduled Monument (No. 34568)  CONDITION: Generally satisfactory but with significant localised problems  CONTACT: Keith Emerick 01904 601988  STEINAME: Section of the Cleave Dyke system, known as the Casten Dike, 300m ENE of Hambleton Inn, Cold Kinderschullers, Condition: Scheduled Monument (No. 26924)  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Forestry  TREND: Unknown				but with significant localised problems
Round barrow 150m south of Thirley Beck Farm, Cloughton  Scheduled Monument (No. 34569)  CONDITION: Extensive significant problems i.e. under plough, collapse  PRINCIPAL VULNERABILITY: Arable ploughing  TREND: Declining  CONTACT: Keith Emerick 01904 601988  ROUND Barrow known as Hunter Howe, Cloughton  Scheduled Monument (No. 34562)  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth  TREND: Declining  CONTACT: Keith Emerick 01904 601988  STE NAME: Stone hut circle and iron working site on Holm Slack, 300m south of The Hulleys, Cloughton  DESIGNATION: Scheduled Monument (No. 34568)  CONDITION: Generally satisfactory with significant localised problems  PRINCIPAL VULNERABILITY: Forestry  TREND: Declining  CONTACT: Keith Emerick 01904 601988  STE NAME: Section of the Cleave Dyke system, known as the Casten Dike, 300m ENE of Hambleton Inn, Cold Kinderschauture.  Scheduled Monument (No. 26924)  CONDITION: Generally satisfactory but with significant localised problems  Scheduled Monument (No. 26924)  CONDITION: Generally satisfactory but with significant localised problems  FRINCIPAL VULNERABILITY: Forestry  TREND: Unknown	PRINCIPAL VULNERABILITY:	-	TREND:	
Scheduled Monument (No. 34569)  CONDITION: Extensive significant problems i.e. under plough, collapse  PRINCIPAL VULNERABILITY: Arable ploughing  TREND: Declining  CONTACT: Keith Emerick 01904 601988  BATE NAME: Round barrow known as Hunter Howe, Cloughton  DESIGNATION: Scheduled Monument (No. 34562)  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth  TREND: Declining  CONTACT: Keith Emerick 01904 601988  BATE NAME: Stone hut circle and iron working site on Holm Slack, 300m south of The Hulleys, Cloughton  DESIGNATION: Scheduled Monument (No. 34568)  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Forestry  TREND: Declining  CONTACT: Keith Emerick 01904 601988  BATE NAME: Section of the Cleave Dyke system, known as the Casten Dike, 300m ENE of Hambleton Inn, Cold Kingershame  Section of the Cleave Dyke system, known as the Casten Dike, 300m ENE of Hambleton Inn, Cold Kingershaming  CONDITION: Generally satisfactory but with significant localised problems  Section of the Cleave Dyke system, known as the Casten Dike, 300m ENE of Hambleton Inn, Cold Kingershaming  CONDITION: Generally satisfactory but with significant localised problems  Figure Name: Section of the Cleave Dyke system, known as the Casten Dike, 300m ENE of Hambleton Inn, Cold Kingershaming  CONDITION: Generally satisfactory but with significant localised problems  Figure Name: Scheduled Monument (No. 26924)  CONDITION: Generally satisfactory but with significant localised problems  Figure Name: Forestry  TREND: Unknown	OWNERSHIP:	Other	CONTACT:	Keith Emerick 01904 601988
i.e. under plough, collapse  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  OWNERSHIP: Private CONTACT: Keith Emerick 01904 601988  STEENAME: Round barrow known as Hunter Howe, Cloughton  DESIGNATION: Scheduled Monument (No. 34562) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth TREND: Declining  OWNERSHIP: Other CONTACT: Keith Emerick 01904 601988  STEENAME: Stone hut circle and iron working site on Holm Slack, 300m south of The Hulleys, Cloughton  DESIGNATION: Scheduled Monument (No. 34568) CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Forestry TREND: Declining  OWNERSHIP: Other CONTACT: Keith Emerick 01904 601988  SETENAME: Section of the Cleave Dyke system, known as the Casten Dike, 300m ENE of Hambleton Inn, Cold Kinderschaller (No. 26924) CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Forestry TREND: ONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Forestry TREND: Unknown	SITE NAME:	Round barrow 150m south of Thirley Bec	k Farm, Cloughton	
Round barrow known as Hunter Howe, Cloughton  DESIGNATION: Scheduled Monument (No. 34562) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth Other CONTACT: Keith Emerick 01904 601988  STE NAME: Stone hut circle and iron working site on Holm Slack, 300m south of The Hulleys, Cloughton  DESIGNATION: Scheduled Monument (No. 34568) CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Forestry TREND: Declining OWNERSHIP: Other CONTACT: Keith Emerick 01904 601988  STE NAME: Section of the Cleave Dyke system, known as the Casten Dike, 300m ENE of Hambleton Inn, Cold Kinderschaller.  DESIGNATION: Scheduled Monument (No. 26924) CONDITION: Generally satisfactory but with significant localised problems  CONTACT: CONDITION: Generally satisfactory but with significant localised problems  DESIGNATION: Scheduled Monument (No. 26924) CONDITION: Generally satisfactory but with significant localised problems  TREND: Unknown	DESIGNATION:	Scheduled Monument (No. 34569)	CONDITION:	
Round barrow known as Hunter Howe, Cloughton  DESIGNATION:  Scheduled Monument (No. 34562)  CONDITION:  Generally unsatisfactory with major localised problems  Plant growth  TREND:  Declining  Declining  DWNERSHIP:  Other  CONTACT:  Keith Emerick 01904 601988  Stone hut circle and iron working site on Holm Slack, 300m south of The Hulleys, Cloughton  DESIGNATION:  Scheduled Monument (No. 34568)  CONDITION:  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY:  Forestry  TREND:  Declining  DWNERSHIP:  Other  CONTACT:  Keith Emerick 01904 601988  SETE NAME:  Section of the Cleave Dyke system, known as the Casten Dike, 300m ENE of Hambleton Inn, Cold Kir  DESIGNATION:  Scheduled Monument (No. 26924)  CONDITION:  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY:  Forestry  TREND:  Unknown	PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DESIGNATION:  Scheduled Monument (No. 34562)  CONDITION:  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Plant growth  Other  CONTACT:  Keith Emerick 01904 601988  Stone hut circle and iron working site on Holm Slack, 300m south of The Hulleys, Cloughton  DESIGNATION:  Scheduled Monument (No. 34568)  CONDITION:  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY:  Forestry  TREND:  Declining  Other  CONTACT:  Keith Emerick 01904 601988  STE NAME:  Section of the Cleave Dyke system, known as the Casten Dike, 300m ENE of Hambleton Inn, Cold Kin  DESIGNATION:  Scheduled Monument (No. 26924)  CONDITION:  Generally satisfactory but with significant localised problems  Forestry  TREND:  Unknown	OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
With major localised problems Principal Vulnerability: Plant growth Trend: Declining DWNERSHIP: Other Contact: Keith Emerick 01904 601988  Stone hut circle and iron working site on Holm Slack, 300m south of The Hulleys, Cloughton DESIGNATION: Scheduled Monument (No. 34568) CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Forestry Trend: Declining DWNERSHIP: Other Contact: Keith Emerick 01904 601988  Section of the Cleave Dyke system, known as the Casten Dike, 300m ENE of Hambleton Inn, Cold Kin DESIGNATION: Scheduled Monument (No. 26924) CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Forestry  TREND: Unknown	SITE NAME:	Round barrow known as Hunter Howe, C	Cloughton	
Other  Stone hut circle and iron working site on Holm Slack, 300m south of The Hulleys, Cloughton  DESIGNATION:  Scheduled Monument (No. 34568)  PRINCIPAL VULNERABILITY:  Forestry  Other  Section of the Cleave Dyke system, known as the Casten Dike, 300m ENE of Hambleton Inn, Cold Kinderschaften.  Scheduled Monument (No. 26924)  Section of the Cleave Dyke system, known as the Casten Dike, 300m ENE of Hambleton Inn, Cold Kinderschaften.  Scheduled Monument (No. 26924)  CONDITION:  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY:  Forestry  TREND:  Unknown	DESIGNATION:	Scheduled Monument (No. 34562)	CONDITION:	· · · · · · · · · · · · · · · · · · ·
Stone hut circle and iron working site on Holm Slack, 300m south of The Hulleys, Cloughton  Scheduled Monument (No. 34568)  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Forestry  TREND: Declining  CONTACT: Keith Emerick 01904 601988  SETE NAME: Section of the Cleave Dyke system, known as the Casten Dike, 300m ENE of Hambleton Inn, Cold Kinderschulder (No. 26924)  Scheduled Monument (No. 26924)  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Forestry  TREND: Unknown	PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
Designation:  Scheduled Monument (No. 34568)  CONDITION:  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY:  Forestry  Other  CONTACT:  Keith Emerick 01904 601988  Section of the Cleave Dyke system, known as the Casten Dike, 300m ENE of Hambleton Inn, Cold King Contact:  Scheduled Monument (No. 26924)  CONDITION:  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY:  Forestry  TREND:  Unknown	OWNERSHIP:	Other	CONTACT:	Keith Emerick 01904 601988
but with significant localised problems PRINCIPAL VULNERABILITY: Forestry  TREND: Declining CONTACT: Keith Emerick 01904 601988  Section of the Cleave Dyke system, known as the Casten Dike, 300m ENE of Hambleton Inn, Cold Kindle Contact:  Scheduled Monument (No. 26924)  CONDITION: Generally satisfactory but with significant localised problems CRINCIPAL VULNERABILITY: Forestry  TREND: Unknown	SITE NAME:	Stone hut circle and iron working site on	Holm Slack, 300m	south of The Hulleys, Cloughton
PRINCIPAL VULNERABILITY: Forestry  TREND: Declining  Other  CONTACT: Keith Emerick 01904 601988  Section of the Cleave Dyke system, known as the Casten Dike, 300m ENE of Hambleton Inn, Cold Kinderstrands:  Scheduled Monument (No. 26924)  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Forestry  TREND: Unknown	DESIGNATION:	Scheduled Monument (No. 34568)	CONDITION:	
Section of the Cleave Dyke system, known as the Casten Dike, 300m ENE of Hambleton Inn, Cold Kinderstrands:  Scheduled Monument (No. 26924)  Scheduled Monument (No. 26924)  CONDITION:  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY:  Forestry  TREND:  Unknown	PRINCIPAL VULNERABILITY:	Forestry	TREND:	-
Scheduled Monument (No. 26924)  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Forestry  TREND: Unknown	OWNERSHIP:	Other	CONTACT:	Keith Emerick 01904 601988
but with significant localised problems PRINCIPAL VULNERABILITY: Forestry TREND: Unknown	SITE NAME:	Section of the Cleave Dyke system, know	n as the Casten Dil	ke, 300m ENE of Hambleton Inn, Cold Kii
principal vulnerability: Forestry trend: Unknown	DESIGNATION:	Scheduled Monument (No. 26924)	CONDITION:	
•	PRINCIPAL VULNERABILITY:	Forestry	TREND:	= .
		•		Keith Emerick 01904 601988

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Fall Rigg cross dyke and round barrow, 71	0m north of Sycam	ore Farm, Cropton
DESIGNATION:	Scheduled Monument (No. 30151)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 410m south of Keldy Bank	s, Cropton	
DESIGNATION:	Scheduled Monument (No. 25592)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Cairnfield on The Howe, Danby Low Moo	r, 330m north west	t of Howe Farm, Danby
DESIGNATION:	Scheduled Monument (No. 32614)	CONDITION:	Generally unsatisfactory
	,		with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	One of four round barrows known as Rol 530m north east of Black Beck Swang, Da		nd adjacent enclosed Bronze Age urnfield,
DESIGNATION:	Scheduled Monument (No. 30190)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	One of four round barrows known as Rol	bin Hood's Butts, 7!	50m north east of Black Beck Swang, Dan
designation:	Scheduled Monument (No. 30192)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Cross dyke 900m west of Backleys Farm,	Darncombe cum La	angdale End
DESIGNATION:	Scheduled Monument (No. 34684)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Maw Rigg cairnfield in Langdale Forest, Da	rncombe cum Lang	gdale End
DESIGNATION:	Scheduled Monument (No. 34561)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Unknown
OWNERSHIP:	Government or Agency	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow on Maw Rigg, I.6km south	west of High Lange	dale End, Darncombe cum Langdale End
DESIGNATION:	Scheduled Monument (No. 34560)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
PRINCIPAL VULNERABILITY:	Plant growth Government or Agency	TREND: CONTACT:	Improving Keith Emerick 01904 601988

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Round barrow 520m north west of Keepe	ers Cottage, East Ay	rton
DESIGNATION:	Scheduled Monument (No. 21062)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
OWNERSHIP:	Local Authority	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow in Raincliffe Woods, 420m	north of Osborne I	Lodge, East Ayton
DESIGNATION:	Scheduled Monument (No. 35458)	CONDITION:	Generally satisfactory
525,6, (, 1,1,0,1,1,	( 10. 55 .55)	20112111011	but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Skell Dikes: a prehistoric linear boundary and an adjoining pit alignment, East Ayton	with two associated	d round barrows
DESIGNATION:	Scheduled Monument (No. 35905)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow at Blanket Head, 350m nor	th west of Broad H	lead Farm, Ebberston and Yedingham
DESIGNATION:	Scheduled Monument (No. 35432)	CONDITION:	Generally unsatisfactory
	,		with major localised problems
			,
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
PRINCIPAL VULNERABILITY: DWNERSHIP:	Plant growth Government or Agency	TREND: CONTACT:	Declining Keith Emerick 01904 601988
	-	CONTACT:	Keith Emerick 01904 601988
OWNERSHIP:	Government or Agency	CONTACT:	Keith Emerick 01904 601988  d features, Ebberston and Yedingham  Generally satisfactory
OWNERSHIP: SITE NAME:	Scamridge Dikes: prehistoric linear bounds Scheduled Monument (No. 35444)	contact:	Keith Emerick 01904 601988  If features, Ebberston and Yedingham  Generally satisfactory
OWNERSHIP: SITE NAME: DESIGNATION:	Government or Agency  Scamridge Dikes: prehistoric linear bounds	contact:  aries and associated  condition:	Keith Emerick 01904 601988  d features, Ebberston and Yedingham  Generally satisfactory but with significant localised problems
DWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Scamridge Dikes: prehistoric linear bounds Scheduled Monument (No. 35444)  Arable clipping	contact:  aries and associated  condition:  TREND:  contact:	Keith Emerick 01904 601988  d features, Ebberston and Yedingham  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988
DWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:	Scamridge Dikes: prehistoric linear bounds Scheduled Monument (No. 35444)  Arable clipping Private	contact:  aries and associated  condition:  TREND:  contact:	Keith Emerick 01904 601988  If features, Ebberston and Yedingham  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  ad Farm, Ebberston and Yedingham  Generally unsatisfactory
DWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  SITE NAME:	Scamridge Dikes: prehistoric linear bounds Scheduled Monument (No. 35444)  Arable clipping Private  Two round barrows in Dalby Forest, 70m Scheduled Monument (No. 35166)	contact:  aries and associated  condition:  TREND:  CONTACT:	Keith Emerick 01904 601988  d features, Ebberston and Yedingham  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  ad Farm, Ebberston and Yedingham
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DITE NAME:  DESIGNATION:	Scamridge Dikes: prehistoric linear bounds Scheduled Monument (No. 35444)  Arable clipping Private  Two round barrows in Dalby Forest, 70m	CONTACT:  aries and associated  CONDITION:  TREND:  CONTACT:  north of Broad He  CONDITION:	Keith Emerick 01904 601988  If features, Ebberston and Yedingham  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  ad Farm, Ebberston and Yedingham  Generally unsatisfactory with major localised problems
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Scamridge Dikes: prehistoric linear bounds Scheduled Monument (No. 35444)  Arable clipping Private  Two round barrows in Dalby Forest, 70m Scheduled Monument (No. 35166)  Plant growth	CONTACT:  aries and associated  CONDITION:  TREND:  CONTACT:  TREND:  CONDITION:  TREND:  CONTACT:	Keith Emerick 01904 601988  If features, Ebberston and Yedingham  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  ad Farm, Ebberston and Yedingham  Generally unsatisfactory with major localised problems Declining
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:	Scamridge Dikes: prehistoric linear bounds Scheduled Monument (No. 35444)  Arable clipping Private  Two round barrows in Dalby Forest, 70m Scheduled Monument (No. 35166)  Plant growth Government or Agency	CONTACT:  aries and associated  CONDITION:  TREND:  CONTACT:  TREND:  CONDITION:  TREND:  CONTACT:	Keith Emerick 01904 601988  If features, Ebberston and Yedingham  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  ad Farm, Ebberston and Yedingham  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Generally satisfactory
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DWNERSHIP:  SITE NAME:	Scamridge Dikes: prehistoric linear bounds Scheduled Monument (No. 35444)  Arable clipping Private  Two round barrows in Dalby Forest, 70m Scheduled Monument (No. 35166)  Plant growth Government or Agency  Enclosure on In Moor, Struntry Carr, Egto	CONTACT:  aries and associated  CONDITION:  TREND:  CONTACT:  north of Broad He  CONDITION:  TREND:  CONTACT:	Keith Emerick 01904 601988  If features, Ebberston and Yedingham  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  ad Farm, Ebberston and Yedingham  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  DWNERSHIP:  DESIGNATION:  DESIGNATION:	Scamridge Dikes: prehistoric linear bounds Scheduled Monument (No. 35444)  Arable clipping Private  Two round barrows in Dalby Forest, 70m Scheduled Monument (No. 35166)  Plant growth Government or Agency  Enclosure on In Moor, Struntry Carr, Egto Scheduled Monument (No. NY462)	CONTACT:  aries and associated  CONDITION:  TREND:  CONTACT:  north of Broad He  CONDITION:  TREND:  CONTACT:	Keith Emerick 01904 601988  If features, Ebberston and Yedingham  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  ad Farm, Ebberston and Yedingham  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:	Scamridge Dikes: prehistoric linear bound: Scheduled Monument (No. 35444)  Arable clipping Private  Two round barrows in Dalby Forest, 70m Scheduled Monument (No. 35166)  Plant growth Government or Agency  Enclosure on In Moor, Struntry Carr, Egto Scheduled Monument (No. NY462)  Plant growth	CONTACT:  aries and associated  CONDITION:  TREND:  CONTACT:  north of Broad He  CONDITION:  TREND:  CONTACT:  n  CONDITION:	Keith Emerick 01904 601988  If features, Ebberston and Yedingham  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  ad Farm, Ebberston and Yedingham  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:	Scamridge Dikes: prehistoric linear bound: Scheduled Monument (No. 35444)  Arable clipping Private  Two round barrows in Dalby Forest, 70m Scheduled Monument (No. 35166)  Plant growth Government or Agency  Enclosure on In Moor, Struntry Carr, Egto Scheduled Monument (No. NY462)  Plant growth Private	CONTACT:  aries and associated  CONDITION:  TREND:  CONTACT:  north of Broad He  CONDITION:  TREND:  CONTACT:  n  CONDITION:	Keith Emerick 01904 601988  If features, Ebberston and Yedingham  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  ad Farm, Ebberston and Yedingham  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Lodge, Egton  Generally unsatisfactory
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DWNERSHIP:	Scamridge Dikes: prehistoric linear bounds Scheduled Monument (No. 35444)  Arable clipping Private  Two round barrows in Dalby Forest, 70m Scheduled Monument (No. 35166)  Plant growth Government or Agency  Enclosure on In Moor, Struntry Carr, Egto Scheduled Monument (No. NY462)  Plant growth Private  Round cairn on Skivick Crag, 380m south	CONTACT:  aries and associated  CONDITION:  TREND:  CONTACT:  north of Broad He  CONDITION:  TREND:  CONTACT:  n  CONDITION:  TREND:  CONTACT:  west of Wheeldale	Keith Emerick 01904 601988  If features, Ebberston and Yedingham  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  ad Farm, Ebberston and Yedingham  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Lodge, Egton

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

ABBREVIATIONS

SITE NAME:	Two round barrows east of Coopers Quarr	ries, Egton	
DESIGNATION:	Scheduled Monument (No. NY561)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow in Newton Mulgrave Woods	, 740m south of N	lewton Brow, Ellerby
DESIGNATION:	Scheduled Monument (No. 32036)	CONDITION:	Generally satisfactory
	(		but with significant localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
DWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
ITE NAME:	Group of seventeen tumuli to the north of Eskdaleside cum Ugglebarnby	Greenlands Howe	e, on the east side of Sleights Moor,
DESIGNATION:	Scheduled Monument (No. NY200D)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	High Bride Stones, Eskdaleside cum Uggleba	arnby	
DESIGNATION:	Scheduled Monument (No. NY200E)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 300m south east of Faceby F	Plantation, Faceby	
DESIGNATION:	Scheduled Monument (No. 26914)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Blakey Howe round barrow, Farndale East		
DESIGNATION:	Scheduled Monument (No. 32642)	CONDITION:	Generally unsatisfactory
	· · · · · · · · · · · · · · · · · · ·		with major localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	with major localised problems  Declining
PRINCIPAL VULNERABILITY:	· · · · · · · · · · · · · · · · · · ·		with major localised problems
PRINCIPAL VULNERABILITY: OWNERSHIP:	Extensive visitor erosion	TREND:	with major localised problems  Declining
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Extensive visitor erosion Private	TREND:	with major localised problems Declining Keith Emerick 01904 601988  Generally satisfactory
PRINCIPAL VULNERABILITY:  DWNERSHIP:  SITE NAME:  DESIGNATION:	Extensive visitor erosion Private  Pike Howe round cairn, Farndale East	TREND: CONTACT:	with major localised problems Declining Keith Emerick 01904 601988  Generally satisfactory
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Extensive visitor erosion Private  Pike Howe round cairn, Farndale East Scheduled Monument (No. 32645)	TREND: CONTACT:  CONDITION:	with major localised problems Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Extensive visitor erosion Private  Pike Howe round cairn, Farndale East Scheduled Monument (No. 32645)  Vandalism	TREND: CONTACT:  CONDITION:  TREND: CONTACT:	with major localised problems Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Extensive visitor erosion Private  Pike Howe round cairn, Farndale East Scheduled Monument (No. 32645)  Vandalism Private	TREND: CONTACT:  CONDITION:  TREND: CONTACT:	with major localised problems Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  st of Park Farm, Farndale West Generally satisfactory
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Extensive visitor erosion Private  Pike Howe round cairn, Farndale East Scheduled Monument (No. 32645)  Vandalism Private  Stone circle and cairnfield on Harland Mood	TREND: CONTACT:  CONDITION: TREND: CONTACT:  r, 375m south wes	with major localised problems Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  st of Park Farm, Farndale West

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Plant growth Private Confict. Keith Emerick 01904 601988  Bowl barrow 300m north east of the junction of the A171 and the road leading to Fylingthorpe, Fylingdales  BENEVALE BOWL BARROW THREAT TIEND Declining  WARRINGTON THREAT TIEND Declining  BRICHE CANADAMENT: No known threat TIEND Declining  BROWLED THREAT TIEND Declining  Brownesselff Private Confict. Keith Emerick 01904 601988  BROWLED THREAT TIEND Declining  Brownesselff Private Confict. Keith Emerick 01904 601988  BROWLED THREAT TIEND DECLINING  BROWLED THREAT TIEND THREAT TIEND DECLINING  BROWLED THREAT TIEND	NAME:	Unenclosed hut circle settlement, field sys north west of Harland Beck House, Farnd		n cemetery on Harland Moor
Pent growth Private Control: Keith Ernerick 01904 601988  Bowl barrow 300m north east of the junction of the A171 and the road leading to Fylingthorpe, Fylingdales and the foliation of the Standing Stones on Standing Stones Rigg, Fylingdales and Fylingdales	SNATION:	Scheduled Monument (No. 34696)	CONDITION:	Generally satisfactory but with significant localised problems
Bowl barrow 300m north east of the junction of the A171 and the road leading to Fylingthorpe, Fylingdales  Scheduled Monument (No. 25676)  Scheduled Monument (No. 25676)  Declining  Private  CONTECT  Reth Emerick 01904 601988  Scheduled Monument (No. 25681)  CONTECT  Reth Emerick 01904 601988  Extensive significant problem is, under plough, collapse  Declining  Private  CONTECT  Arable ploughing  TRINDS  Declining  Private  CONTECT  Reth Emerick 01904 601988  Extensive significant problem is, under plough, collapse  Declining  TRINDS  TRINDS	CIPAL VULNERABILITY:	Plant growth	TREND:	
and the road leading to Fylingthorpe, Fylingdales  Scheduled Monument (No. 25676)  Scheduled Monument (No. 25676)  Scheduled Monument (No. 25676)  Scheduled Monument (No. 25676)  Scheduled Monument (No. 25677)  Bowl barrow in north corner of a field 205m south of the Standing Stones on Standing Stones Rigg, Fylingdales  Scheduled Monument (No. 25681)  Scheduled Monument (No. 25689)  Scheduled Monument (No. 2568	JERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
Dut with significant localised   Declining Contract: Keith Emerick 01904 601988    THE NAME: Bowl barrow in north corner of a field 205m south of the Standing Stones on Standing Stones Rigg, Fylingdales    Scheduled Monument (No. 25681)   Condition   Extensive significant problem i.e. under plough, collapse    Declining   Declin	NAME:	•		
Private Declining Construct. Keith Emerick 01904 601988 or Name Private Declining Stones on Standing Stones Rigg, Fylingdales  Streamed Bowl barrow in north corner of a field 205m south of the Standing Stones on Standing Stones Rigg, Fylingdales  Streamed Wilhermarit Private Scheduled Monument (No. 25681) Condition Extensive significant problem i.e. under plough, collapse Declining Trend Declining Control Reith Emerick 01904 601988 or Reith Emerick 01904 folly private Control Reith Emeri	gnation:	Scheduled Monument (No. 25676)	CONDITION:	Generally satisfactory but with significant localised problems
Bowl barrow in north corner of a field 205m south of the Standing Stones on Standing Stones Rigg, Fylingdales  Scheduled Monument (No. 25681)  CONDTION Extensive significant problem i.e. under plough, collapse i.e. under plough i.e. under plough i.e. under plough i.e. under plough, collapse i.e. under plough i.e. und	CIPAL VULNERABILITY:	No known threat	TREND:	
Of the Standing Stones on Standing Stones Rigg, Fylingdales  Descination:  Scheduled Monument (No. 25681)  Description:  Extensive significant problem i.e. under plough, collapse  Description:  Cairrifield, field system and ring cairn 610m south east of Foulsike Farm, Fylingdales  Description:  Cairrifield, field system and ring cairn 610m south east of Foulsike Farm, Fylingdales  Description:  Condition:  Scheduled Monument (No. 34411)  Description:  Descript	JERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
i.e. under plough, collapse Declining TREND Declining De	NAME:			
Arable ploughing TREND: Declining  CONTROLL Keith Emerick 01904 601988  Private Controll (No. 34411) CONDITION Generally unsatisfactory with major localised problem private Controll (No. 34411)  STENAME: Clinear earthwork south east of the junction of the A171 and the road leading to Fylingthorpe, Fylingdales  Declining Controll (No. 25669) CONDITION Generally satisfactory but with significant localised problem private Controll (No. 25669) CONDITION Generally satisfactory but with significant localised problem private Controll (No. 25669)  TREND: Declining Controll (No. 25669) CONDITION Generally satisfactory but with significant localised problem private Controll (No. 25669)  TREND: Declining Controll (No. 25669) CONDITION Generally satisfactory but with significant localised private Controll (No. 25669)  TREND: Declining Controll (No. 25669) CONDITION Generally satisfactory but with significant localised problem private Controll (No. 25677) CONDITION Generally satisfactory but with significant localised provided (No. 25677) CONDITION Generally satisfactory but with significant localised provided (No. 25677) CONDITION Generally satisfactory but with significant localised provided (No. 25677) CONDITION Generally satisfactory but with significant localised provided (No. 25677) CONDITION Generally satisfactory but with significant localised provided (No. 25677) CONDITION Generally satisfactory but with significant localised provided (No. 25677) Private CONTROLL (No. 25677) CONDITION Generally satisfactory but with significant localised provided (No. 25677) CONDITION Generally satisfactory but with significant localised provided (No. 25677) CONDITION Generally satisfactory but with significant localised provided (No. 25677) CONDITION Generally satisfactory but with significant localised provided (No. 25677) CONDITION Generally satisfactory with major localised provided (No. 25677) CONDITION Generally unsatisfactory with major localised problem (No. 25677) CONDITION Generally unsatisfactory with major localised pro	SNATION:	Scheduled Monument (No. 25681)	CONDITION:	Extensive significant problems
Cairnfield, field system and ring cairn 610m south east of Foulsike Farm, Fylingdales  Scheduled Monument (No. 34411)  CONDITION  Generally unsatisfactory with major localised problem  PRESCHALAGEMENTE.  Plant growth  Private  CONTACT:  Keith Emerick 01904 601988  STEINAME:  Linear earthwork south east of the junction of the A171 and the road leading to Fylingthorpe, Fylingdales  CONDITION  Generally satisfactory but with significant localised in Declining  CONDITION  Generally satisfactory but with significant localised in Declining  CONTACT:  Keith Emerick 01904 601988  FRENCHALAGEMENTERS  Private  CONTACT:  Keith Emerick 01904 601988  STEINAME:  Linear earthwork to the north west of the junction of the A171 and the road leading to Fylingthorpe, Fylingdales  DESIGNATION:  Scheduled Monument (No. 25677)  CONDITION  Generally satisfactory but with significant localised in Declining  CONTACT:  Keith Emerick 01904 601988  FRENCHALAGEMENTERS  Private  CONTACT:  Medieval dyke known as Green Dike, Fylingdales  Scheduled Monument (No. 34419)  CONDITION  Generally satisfactory but with significant localised in Declining  CONTACT:  Keith Emerick 01904 601988  FRENCHALAGEMENTERS  Private  CONTACT:  Keith Emerick 01904 601988  FRENCHALAGEMENTERS  FRENCHALAGEMENTERS  FRENCHALAGEMENTERS  Private  CONTACT:  Keith Emerick 01904 601988  FRENCHALAGEMENTERS  FRENCHALAGEMENTERS  FRENCHALAGEMENTERS  FRENCHALAGEMENTERS  No known threat  TREND  Declining  CONTACT:  Keith Emerick 01904 601988	CIPAL VULNERABILITY:	Arable ploughing	TREND:	
Scheduled Monument (No. 34411)  Scheduled Monument (No. 34669)  Scheduled Monument (No. 25669)  Scheduled Monument (No. 25677)  Scheduled Monument (No. 34419)  Scheduled Monument (No. 34419)				Keith Emerick 01904 601988
Scheduled Monument (No. 34411)  Scheduled Monument (No. 25669)  Scheduled Monument (No. 25677)  Scheduled Monument (No. 34419)  Scheduled Monument (No. 34419)	NAME:	Cairnfield, field system and ring cairn 610	m south east of Fou	ılsike Farm, Fylingdales
Private Plant growth TREND: Declining CONTRICT: Keith Emerick 01904 601988  STEINAME: Linear earthwork south east of the junction of the A171 and the road leading to Fylingthorpe, Fylingdales  DESIGNATION: Scheduled Monument (No. 25669) CONDITION: Generally satisfactory but with significant localised private CONTRICT: Keith Emerick 01904 601988  STEINAME: Linear earthwork to the north west of the junction of the A171 and the road leading to Fylingthorpe, Fylingdales  DESIGNATION: Scheduled Monument (No. 25677) CONDITION: Generally satisfactory but with significant localised private CONTRICT: Keith Emerick 01904 601988  DESIGNATION: Scheduled Monument (No. 25677) CONDITION: Generally satisfactory but with significant localised private CONTRICT: Keith Emerick 01904 601988  DESIGNATION: Private CONTRICT: Keith Emerick 01904 601988  DESIGNATION: Scheduled Monument (No. 34419) CONDITION: Generally satisfactory but with significant localised presidentials.  PRINCIPAL VULNERABILITY: Plant growth TREND: Declining  DESIGNATION: Scheduled Monument (No. 34419) CONDITION: Generally satisfactory but with significant localised providence and private CONTRICT: Keith Emerick 01904 601988  DESIGNATION: Scheduled Monument (No. 34419) CONDITION: Generally satisfactory with significant localised providence and private CONTRICT: Keith Emerick 01904 601988  DESIGNATION: Scheduled Monument (No. 34419) CONDITION: Generally unsatisfactory with major localised problems  DESIGNATION: Scheduled Monument (No. 34371) CONDITION: Generally unsatisfactory with major localised problems	gnation:	,		Generally unsatisfactory
Designation:    Contact:   Keith Emerick 01904 601988	CIPAL VI II NIERARII ITY:	Plant growth	TRENID:	
and the road leading to Fylingthorpe, Fylingdales  DESIGNATION:  Scheduled Monument (No. 25669)  CONDITION: DECINION: Declining  Private  CONTACT:  CONTACT:  CERT NAME:  Linear earthwork to the north west of the junction of the A171 and the road leading to Fylingthorpe, Fylingdales  DESIGNATION: DESIGNA		~		Keith Emerick 01904 601988
Designation:  Plant growth  TREND:  Declining  OWNERSHIP:  Private  CONTACT:  Keith Emerick 01904 601988  SITE NAME:  Linear earthwork to the north west of the junction of the A171 and the road leading to Fylingthorpe, Fylingdales  DESIGNATION:  Scheduled Monument (No. 25677)  Plant growth  TREND:  Declining  OWNERSHIP:  Private  Medieval dyke known as Green Dike, Fylingdales  SITE NAME:  Medieval dyke known as Green Dike, Fylingdales  Scheduled Monument (No. 34419)  DESIGNATION:  Scheduled Monument (No. 34419)  DESIGNATION:  Scheduled Monument (No. 34419)  DESIGNATION:  PRINCIPAL VULNERABILITY:  Plant growth  TREND:  Declining  OWNERSHIP:  Private  Round barrow 420m north east of Cook House, Fylingdales  DESIGNATION:  Scheduled Monument (No. 34371)  CONDITION:  Generally unsatisfactory with major localised problem  PRINCIPAL VULNERABILITY:  No known threat  TREND:  Declining  OWNERSHIP  PRIVATE  CONTACT:  Keith Emerick 01904 601988	NAME:			
DESIGNATION:  Linear earthwork to the north west of the junction of the A171 and the road leading to Fylingthorpe, Fylingdales  DESIGNATION:  Scheduled Monument (No. 25677)  CONDITION:  Generally satisfactory but with significant localised prince of the Emerick 01904 601988  PRINCIPAL VULNERABILITY:  Plant growth  TREND:  Declining  OWNERSHIP:  Medieval dyke known as Green Dike, Fylingdales  DESIGNATION:  Scheduled Monument (No. 34419)  CONDITION:  Generally satisfactory but with significant localised principal vulnerability:  Plant growth  TREND:  Declining  OWNERSHIP:  Private  CONTACT:  Keith Emerick 01904 601988  TREND:  Declining  OWNERSHIP:  Round barrow 420m north east of Cook House, Fylingdales  DESIGNATION:  Scheduled Monument (No. 34371)  CONDITION:  Generally unsatisfactory with major localised problem principal vulnerability:  No known threat  TREND:  Declining	SNATION:	Scheduled Monument (No. 25669)	CONDITION:	Generally satisfactory but with significant localised problems
Linear earthwork to the north west of the junction of the A171 and the road leading to Fylingthorpe, Fylingdales  DESIGNATION:  Scheduled Monument (No. 25677)  CONDITION:  Generally satisfactory but with significant localised provides and private  Plant growth  TREND:  Declining  Declining  Designation:  Scheduled Monument (No. 34419)  CONTACT:  Keith Emerick 01904 601988  DESIGNATION:  Scheduled Monument (No. 34419)  CONDITION:  Generally satisfactory but with significant localised provides and private  Declining  Private  Plant growth  TREND:  Declining	CIPAL VULNERABILITY:	Plant growth	TREND:	Declining
and the road leading to Fylingthorpe, Fylingdales  DESIGNATION:  Scheduled Monument (No. 25677)  Scheduled Monument (No. 25677)  CONDITION:  Generally satisfactory but with significant localised provided by the significant	JERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
but with significant localised principal vulnerability:  Plant growth  Private  Medieval dyke known as Green Dike, Fylingdales  Setename:  Medieval dyke known as Green Dike, Fylingdales  Scheduled Monument (No. 34419)  Condition:  Generally satisfactory but with significant localised perincipal vulnerability:  Plant growth  Trend:  Declining  Devinership:  Private  Round barrow 420m north east of Cook House, Fylingdales  Setename:  Round barrow 420m north east of Cook House, Fylingdales  Designation:  Generally unsatisfactory with major localised problem  Principal vulnerability:  No known threat  Trend:  Declining  Declining	NAME:			71
Medieval dyke known as Green Dike, Fylingdales  DESIGNATION:  Scheduled Monument (No. 34419)  PRINCIPAL VULNERABILITY:  Round barrow 420m north east of Cook House, Fylingdales  DESIGNATION:  Round Monument (No. 34371)  CONDITION:  Generally satisfactory but with significant localised principal vulnerability:  CONTACT:  Keith Emerick 01904 601988  CONTACT:  Keith Emerick 01904 601988  DESIGNATION:  Generally unsatisfactory with major localised problem principal vulnerability:  No known threat  TREND:  Declining	enation:	Scheduled Monument (No. 25677)	CONDITION:	Generally satisfactory but with significant localised problems
Medieval dyke known as Green Dike, Fylingdales  DESIGNATION:  Scheduled Monument (No. 34419)  CONDITION:  Generally satisfactory but with significant localised principal vulnerability:  Plant growth  TREND:  Declining  Private  CONTACT:  Keith Emerick 01904 601988  DESIGNATION:  Scheduled Monument (No. 34371)  CONDITION:  Generally unsatisfactory with major localised problem  PRINCIPAL VULNERABILITY:  No known threat  TREND:  Declining	CIPAL VULNERABILITY:	Plant growth	TREND:	•
DESIGNATION:  Scheduled Monument (No. 34419)  CONDITION:  Generally satisfactory but with significant localised principal vulnerability:  Plant growth  Private  Round barrow 420m north east of Cook House, Fylingdales  DESIGNATION:  Scheduled Monument (No. 34371)  CONDITION:  Generally unsatisfactory with major localised problem  PRINCIPAL VULNERABILITY:  No known threat  TREND:  Declining	IERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
but with significant localised principal vulnerability:  Plant growth  TREND:  Declining  CONTACT:  Keith Emerick 01904 601988  DESIGNATION:  Scheduled Monument (No. 34371)  CONDITION:  Generally unsatisfactory with major localised problem RINCIPAL VULNERABILITY:  No known threat  TREND:  Declining	NAME:	Medieval dyke known as Green Dike, Fylir	ngdales	
PRINCIPAL VULNERABILITY: Plant growth TREND: Declining  Devining  Private Contact: Keith Emerick 01904 601988  SITE NAME: Round barrow 420m north east of Cook House, Fylingdales  DESIGNATION: Scheduled Monument (No. 34371)  CONDITION: Generally unsatisfactory with major localised problem  PRINCIPAL VULNERABILITY: No known threat  TREND: Declining	SNATION:	Scheduled Monument (No. 34419)	CONDITION:	Generally satisfactory but with significant localised problems
Private CONTACT: Keith Emerick 01904 601988  Round barrow 420m north east of Cook House, Fylingdales  DESIGNATION: Scheduled Monument (No. 34371) CONDITION: Generally unsatisfactory with major localised problem  PRINCIPAL VULNERABILITY: No known threat TREND: Declining	CIPAL VULNERABILITY:	Plant growth	TREND:	-
DESIGNATION: Scheduled Monument (No. 34371) CONDITION: Generally unsatisfactory with major localised problem PRINCIPAL VULNERABILITY: No known threat TREND: Declining	VERSHIP:	-	CONTACT:	Keith Emerick 01904 601988
with major localised problem PRINCIPAL VULNERABILITY: No known threat TREND: Declining	NAME:	Round barrow 420m north east of Cook	House, Fylingdales	
PRINCIPAL VULNERABILITY: No known threat TREND: Declining	enation:	Scheduled Monument (No. 34371)	CONDITION:	•
9	CIPAL VULNERABILITY:	No known threat	TREND:	
ownership: Private contact: Keith Emerick 01904 601988		Private	CONTACT:	Keith Emerick 01904 601988

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# NOTE: NOTE: If the priority category has changed since the 2009 register, the previous category is given in brackets.

# ABBREVIATIONS

SITE NAME:	Round barrow 510m north east of Cook	House, Fylingdales	
DESIGNATION:	Scheduled Monument (No. 31378)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 720m north east of Cook	House, Fylingdales	
DESIGNATION:	Scheduled Monument (No. 31379)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Site of Stoupe Brow alum works, 210m so	outh east of Stoupe	Bank Farm, Fylingdales
DESIGNATION:	Scheduled Monument (No. 29546)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
	····	20.17.121.	Troid Emorial of 70 1 00 1700
SITE NAME:	The Latter Gate Hills tumuli; the northern of the A171 and the road leading to Fyling		•
DESIGNATION:	Scheduled Monument (No. 25671)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Allan Tofts cairnfield, field system, burial ca immediately south of Morton Close, Goat		c rock art,
DESIGNATION:	Scheduled Monument (No. 35915)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Simon Howe: a round cairn on Goathland a standing stone and a stone alignment, G		ted round barrows,
designation:	Scheduled Monument (No. 35919)	CONDITION:	Generally unsatisfactory
	F		with major localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining Keith Emerick 01904 601988
OWNERSHIP:	Other	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Two Howes: two round barrows on Goat	hland Moor, Goathl	and
DESIGNATION:	Scheduled Monument (No. 35918)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 200m south of Green Banl	k, Great Busby	
DESIGNATION:	Scheduled Monument (No. 25522)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### ABBREVIATIONS

SITE NAME:	Round barrow in Springwood Heights Plan	itation, 220m north	n west of Springwood Cottage, Hackness
DESIGNATION:	Scheduled Monument (No. 34549)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Shunner Howe round barrow, Hartoft		
DESIGNATION:	Scheduled Monument (No. 30156)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow in Harwood Dale Forest kr	nown as Penny Ho	we, Harwood Dale
DESIGNATION:	Scheduled Monument (No. 34565)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round cairn on Cowgate Rigg, 790m south	n west of Teydale F	arm, Harwood Dale
DESIGNATION:	Scheduled Monument (No. 34671)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNERSHIP:	Government or Agency	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round cairn on Cowgate Rigg, 870m north	n of Brooklands Fa	rm, Harwood Dale
DESIGNATION:	Scheduled Monument (No. 34673)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNERSHIP:	Government or Agency	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Cairnfield 200m east of Hazelshaw House	, Hawnby	
DESIGNATION:	Scheduled Monument (No. 25527)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Cairnfield 500m north east of Bumper Ca	stle, Hawnby	
DESIGNATION:	Scheduled Monument (No. 25528)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Cairnfield on the south west of Hawnby M	loor including a ro	und barrow and a standing stone, Hawnb
DESIGNATION:	Scheduled Monument (No. 25501)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Round barrow 150m north east of Silver	Hill Farm, Hawnby	
DESIGNATION:	Scheduled Monument (No. 24455)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 500m east of Silver Hill Fa	rm, Hawnby	
DESIGNATION:	Scheduled Monument (No. 24453)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 500m north west of Lowe	r Locker Farm, Hav	vnby
DESIGNATION:	Scheduled Monument (No. 25556)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 550m south east of High C	Cote Farm, Hawnby	
DESIGNATION:	Scheduled Monument (No. 25557)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Two round barrows at Sour Milk Hills, Ha	wnby	
DESIGNATION:	Scheduled Monument (No. 24449)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Moated site at Low Laithes Farm, Whitby	Laithes, Hawsker c	um Stainsacre
DESIGNATION:	Scheduled Monument (No. 34822)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Localised/limited stock erosion	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Saltwick Nab alum quarries, Hawsker cum	Stainsacre	
DESIGNATION:	Scheduled Monument (No. 29537)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow and 20th century Royal Ol known as the site of Hinderwell Beacon, H		on Beacon Hill,
DESIGNATION:	Scheduled Monument (No. 32024)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
	Private	CONITACT	Keith Emerick 01904 601988
OWNERSHIP:	TTIVALE	CONTACT:	Reith Linelick 01701 001700

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

	Round barrow immediately south of Califo	ornia Belt, 190m ea	st of Fox Head, Hutton Buscel
DESIGNATION:	Scheduled Monument (No. 33517)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow in School Belt, 1050m nort	th west of Jenny Spi	ring, Hutton Buscel
DESIGNATION:	Scheduled Monument (No. 33738)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow on Shortgate Hill, 500m so	outh east of Coomb	Slack Farm, Hutton Buscel
DESIGNATION:	Scheduled Monument (No. 32494)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNERSHIP:	Government or Agency	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	The Moor Dikes and Craddlegrip Dike proceedings in Wykeham Forest, Hutton Busco		ndaries and other prehistoric
DESIGNATION:	Scheduled Monument (No. 33734)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Three square barrows in Wykeham Forest	590m south east	of Mount Misony Hutton Bussel
		i, 370iii soudii east (	of Product Plisery, Huttori Buscer
DESIGNATION:	Scheduled Monument (No. 32512)	CONDITION:	Generally satisfactory but with significant localised problems
	·		Generally satisfactory but with significant localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP:	Scheduled Monument (No. 32512)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 32512)  Plant growth	CONDITION:  TREND:  CONTACT:  ad barrow, round ca	Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  irn, enclosed field and part
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Scheduled Monument (No. 32512)  Plant growth Private  Cairnfield, including a standing stone, roun	CONDITION:  TREND:  CONTACT:  ad barrow, round ca	Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  irn, enclosed field and part
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:	Scheduled Monument (No. 32512)  Plant growth Private  Cairnfield, including a standing stone, roun of Cucket medieval deer park boundary, 3	CONDITION:  TREND:  CONTACT:  d barrow, round ca 60m north of Eden	Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  irn, enclosed field and part House, Hutton Mulgrave  Generally satisfactory
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 32512)  Plant growth Private  Cairnfield, including a standing stone, roun of Cucket medieval deer park boundary, 3  Scheduled Monument (No. 32492)	CONDITION:  TREND:  CONTACT:  ad barrow, round ca 60m north of Eden  CONDITION:	Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  irn, enclosed field and part House, Hutton Mulgrave  Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Scheduled Monument (No. 32512)  Plant growth Private  Cairnfield, including a standing stone, roun of Cucket medieval deer park boundary, 3  Scheduled Monument (No. 32492)  Plant growth	condition:  TREND:  CONTACT:  ad barrow, round ca 60m north of Eden  CONDITION:  TREND:  CONTACT:	Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  irn, enclosed field and part House, Hutton Mulgrave  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Scheduled Monument (No. 32512)  Plant growth Private  Cairnfield, including a standing stone, roun of Cucket medieval deer park boundary, 3  Scheduled Monument (No. 32492)  Plant growth Private	condition:  TREND:  CONTACT:  ad barrow, round ca 60m north of Eden  CONDITION:  TREND:  CONTACT:	Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  irn, enclosed field and part House, Hutton Mulgrave  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:	Scheduled Monument (No. 32512)  Plant growth Private  Cairnfield, including a standing stone, roun of Cucket medieval deer park boundary, 3  Scheduled Monument (No. 32492)  Plant growth Private  Round barrow at Lady Cross, 730m south	condition:  TREND:  CONTACT:  ad barrow, round ca 60m north of Eden  CONDITION:  TREND:  CONTACT:	Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  irn, enclosed field and part House, Hutton Mulgrave  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Hutton Mulgrave  Generally satisfactory
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 32512)  Plant growth Private  Cairnfield, including a standing stone, roun of Cucket medieval deer park boundary, 3  Scheduled Monument (No. 32492)  Plant growth Private  Round barrow at Lady Cross, 730m south Scheduled Monument (No. 32489)	CONDITION:  TREND: CONTACT:  Id barrow, round ca 60m north of Eden  CONDITION:  TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  irn, enclosed field and part House, Hutton Mulgrave  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Hutton Mulgrave  Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  OWNERSHIP:	Scheduled Monument (No. 32512)  Plant growth Private  Cairnfield, including a standing stone, roun of Cucket medieval deer park boundary, 3  Scheduled Monument (No. 32492)  Plant growth Private  Round barrow at Lady Cross, 730m south Scheduled Monument (No. 32489)  Arable clipping	CONDITION:  TREND: CONTACT:  Id barrow, round ca 60m north of Eden  CONDITION:  TREND: CONTACT:  west of Dun Bogs,  CONDITION:  TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  irn, enclosed field and part House, Hutton Mulgrave  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Hutton Mulgrave  Generally satisfactory but with significant localised problems Declining
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  OWNERSHIP:	Scheduled Monument (No. 32512)  Plant growth Private  Cairnfield, including a standing stone, roun of Cucket medieval deer park boundary, 3  Scheduled Monument (No. 32492)  Plant growth Private  Round barrow at Lady Cross, 730m south Scheduled Monument (No. 32489)  Arable clipping Private	CONDITION:  TREND: CONTACT:  Id barrow, round ca 60m north of Eden  CONDITION:  TREND: CONTACT:  west of Dun Bogs,  CONDITION:  TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  irn, enclosed field and part House, Hutton Mulgrave  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Hutton Mulgrave  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 32512)  Plant growth Private  Cairnfield, including a standing stone, roun of Cucket medieval deer park boundary, 3  Scheduled Monument (No. 32492)  Plant growth Private  Round barrow at Lady Cross, 730m south Scheduled Monument (No. 32489)  Arable clipping Private  Douthwaite pillow mounds, Hutton-le-Ho	CONDITION:  TREND: CONTACT:  Id barrow, round ca 60m north of Eden  CONDITION:  TREND: CONTACT:  West of Dun Bogs,  CONDITION:  TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  irn, enclosed field and part House, Hutton Mulgrave  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Hutton Mulgrave  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Keith Emerick 01904 601988

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

ABBREVIATIONS

SITE NAME:	Four round barrows one 400m and three	540m east of Grou	use Hall, Hutton-le-Hole
DESIGNATION:	Scheduled Monument (No. 30105)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Two round barrows, 245m and 340m north	th west of Barmooi	· Lodge, Hutton-le-Hole
DESIGNATION:	Scheduled Monument (No. 30104)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 1200m north west of Beac	on Farm, Irton	
DESIGNATION:	Scheduled Monument (No. 21066)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Local Authority	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 1350m north west of Beac	on Farm, Irton	
DESIGNATION:	Scheduled Monument (No. 21065)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Hood Hill motte and bailey, Kilburn High	and Low	
DESIGNATION:	Scheduled Monument (No. 20524)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNERSHIP:	Government or Agency	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Promontory fort at Roulston Scar, Kilburr	n High and Low	
DESIGNATION:	Scheduled Monument (No. 28298)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 480m east of Yorkshire Gli	ding Club, Kilburn	High and Low
DESIGNATION:	Scheduled Monument (No. 28225)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Three medieval pillow mounds 900m nort	th of Grove House	Levisham
DESIGNATION:	Scheduled Monument (No. 35463)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Keith Emerick 01904 601988

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Ayton Banks alum works, Little Ayton		
DESIGNATION:	Scheduled Monument (No. 31343)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Cross dyke centred 480m south of Fox an	nd Rabbit Farm, Lo	kton
DESIGNATION:	Scheduled Monument (No. 35902)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Field system and cairnfield on Lockton Hig	gh Moor, Ikm NNE	of Needle Point, Lockton
DESIGNATION:	Scheduled Monument (No. 35455)	CONDITION:	Generally satisfactory
	,		but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Unknown
OWNERSHIP:	Local Authority	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Prehistoric dyke known as Horcum Dike,	Lockton	
DESIGNATION:	Scheduled Monument (No. 34814)	CONDITION:	Generally satisfactory
	,		but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Keith Emerick 01904 601988
OWNERSHIP:		CONTACT.	Reith Emerick 01701 001700
SITE NAME:	Round barrow 400m north east of Low Pa		
SITE NAME:	·		
SITE NAME:	Round barrow 400m north east of Low Pa	asture Farm, Lockto	on
	Round barrow 400m north east of Low Pa	asture Farm, Lockto	on  Extensive significant problems
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Round barrow 400m north east of Low Pa	asture Farm, Lockto	Extensive significant problems i.e. under plough, collapse
SITE NAME: DESIGNATION:	Round barrow 400m north east of Low Pa Scheduled Monument (No. 35451) Arable ploughing	condition:  TREND:  CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Round barrow 400m north east of Low Pa Scheduled Monument (No. 35451)  Arable ploughing Private	condition:  TREND:  CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Round barrow 400m north east of Low Passes Scheduled Monument (No. 35451)  Arable ploughing Private  Round barrow 430m north west of Cross	condition:  TREND:  CONTACT:  dale Head, Locktor	Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988
DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNERSHIP:  SITE NAME:  DESIGNATION:	Round barrow 400m north east of Low Passes Scheduled Monument (No. 35451)  Arable ploughing Private  Round barrow 430m north west of Cross	condition:  TREND:  CONTACT:  dale Head, Locktor	Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988  Generally unsatisfactory
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Round barrow 400m north east of Low Pascheduled Monument (No. 35451)  Arable ploughing Private  Round barrow 430m north west of Cross Scheduled Monument (No. 35452)	condition:  TREND:  CONTACT:  dale Head, Locktor  CONDITION:	Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988  Generally unsatisfactory with major localised problems
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Round barrow 400m north east of Low Pascheduled Monument (No. 35451)  Arable ploughing Private  Round barrow 430m north west of Cross Scheduled Monument (No. 35452)  Arable ploughing	asture Farm, Lockton  CONDITION:  TREND:  CONTACT:  dale Head, Lockton  CONDITION:  TREND:	Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988  Generally unsatisfactory with major localised problems Declining
DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNERSHIP:  DESIGNATION:  SITE NAME:	Round barrow 400m north east of Low Passes Scheduled Monument (No. 35451)  Arable ploughing Private  Round barrow 430m north west of Cross Scheduled Monument (No. 35452)  Arable ploughing Private  Alum works at Kettleness, Lythe	asture Farm, Lockton  CONDITION:  TREND:  CONTACT:  dale Head, Lockton  CONDITION:  TREND:	Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988
DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNERSHIP:  DESIGNATION:  SITE NAME:	Round barrow 400m north east of Low Pascheduled Monument (No. 35451)  Arable ploughing Private  Round barrow 430m north west of Cross Scheduled Monument (No. 35452)  Arable ploughing Private	asture Farm, Lockton  CONDITION:  TREND:  CONTACT:  dale Head, Lockton  CONDITION:  TREND:  CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Generally satisfactory
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  OWNERSHIP:  SITE NAME:  DESIGNATION:  SITE NAME:  DESIGNATION:  DESIGNATION:	Round barrow 400m north east of Low Passes Scheduled Monument (No. 35451)  Arable ploughing Private  Round barrow 430m north west of Cross Scheduled Monument (No. 35452)  Arable ploughing Private  Alum works at Kettleness, Lythe	asture Farm, Lockton  CONDITION:  TREND:  CONTACT:  dale Head, Lockton  CONDITION:  TREND:  CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  PRINCIPAL VULNERABILITY:	Round barrow 400m north east of Low Passes Scheduled Monument (No. 35451)  Arable ploughing Private  Round barrow 430m north west of Cross Scheduled Monument (No. 35452)  Arable ploughing Private  Alum works at Kettleness, Lythe Scheduled Monument (No. 29545)	asture Farm, Lockton  CONDITION:  TREND:  CONTACT:  dale Head, Lockton  CONDITION:  TREND:  CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Round barrow 400m north east of Low Passes Scheduled Monument (No. 35451)  Arable ploughing Private  Round barrow 430m north west of Cross Scheduled Monument (No. 35452)  Arable ploughing Private  Alum works at Kettleness, Lythe Scheduled Monument (No. 29545)  Coastal erosion	asture Farm, Lockton  CONDITION:  TREND:  CONTACT:  dale Head, Lockton  CONDITION:  TREND:  CONTACT:  TREND:  CONDITION:  TREND:  CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:	Round barrow 400m north east of Low Passender Scheduled Monument (No. 35451)  Arable ploughing Private  Round barrow 430m north west of Cross Scheduled Monument (No. 35452)  Arable ploughing Private  Alum works at Kettleness, Lythe Scheduled Monument (No. 29545)  Coastal erosion Private  Round barrow on Brockrigg, 400m east of	asture Farm, Lockton  CONDITION:  TREND:  CONTACT:  dale Head, Lockton  CONDITION:  TREND:  CONTACT:  CONDITION:  TREND:  CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:	Round barrow 400m north east of Low Passes Scheduled Monument (No. 35451)  Arable ploughing Private  Round barrow 430m north west of Cross Scheduled Monument (No. 35452)  Arable ploughing Private  Alum works at Kettleness, Lythe Scheduled Monument (No. 29545)  Coastal erosion Private	asture Farm, Lockton  CONDITION:  TREND:  CONTACT:  dale Head, Lockton  CONDITION:  TREND:  CONTACT:  TREND:  CONDITION:  TREND:  CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  SITE NAME:  DESIGNATION:  OWNERSHIP:  OWNERSHIP:  OWNERSHIP:	Round barrow 400m north east of Low Passender Scheduled Monument (No. 35451)  Arable ploughing Private  Round barrow 430m north west of Cross Scheduled Monument (No. 35452)  Arable ploughing Private  Alum works at Kettleness, Lythe Scheduled Monument (No. 29545)  Coastal erosion Private  Round barrow on Brockrigg, 400m east of	asture Farm, Lockton  CONDITION:  TREND:  CONTACT:  dale Head, Lockton  CONDITION:  TREND:  CONTACT:  CONDITION:  TREND:  CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

	Round barrow on Cow Hill, 410m south v	vest of Scratch Alle	y, Lythe
DESIGNATION:	Scheduled Monument (No. 32477)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Improving
DWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
AVINERSI III .	Tivace	CONTACT.	Reful Efficiency 01701 001700
SITE NAME:	Potato Nab round barrow 1020m south w	vest of Penny Holm	e, Nawton
DESIGNATION:	Scheduled Monument (No. 32689)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow on Dunsley Moor, 160m w	est of Skelder Cott	age, Newholm cum Dunsley
DESIGNATION:	Scheduled Monument (No. 32038)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
OVVINERSMIF:	Tilvate	CONTACT:	Reful Efficience 01701 001700
SITE NAME:	Rawcliffe Howe round barrow, Newton		
DESIGNATION:	Scheduled Monument (No. 34412)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable
OWNERSHIP:	Government or Agency	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round cairn 510m south of Lower Farm, N	Vewton	
DECICALIATION	Scheduled Monument (No. 34810)	CONDITION	Generally satisfactory
DESIGNATION:	scrieduled i londinent (140. 57010)	CONDITION:	
			but with cignificant localised problems
DDINICIDAL VILILATED A DILITY.	Plant growth	TDENID.	but with significant localised problems
	Plant growth	TREND:	Declining
PRINCIPAL VULNERABILITY: OWNERSHIP:	Plant growth Other	TREND: CONTACT:	
	-	CONTACT:	Declining
OWNERSHIP: SITE NAME:	Other	CONTACT:	Declining
OWNERSHIP:	Other  Two round cairns 450m south of Lower Fa	CONTACT:	Declining Keith Emerick 01904 601988  Generally satisfactory
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Other  Two round cairns 450m south of Lower Factorial Scheduled Monument (No. 34809)	arm, Newton  CONDITION:	Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems
OWNERSHIP: SITE NAME: DESIGNATION:	Other  Two round cairns 450m south of Lower Forms Scheduled Monument (No. 34809)  Plant growth	contact:  arm, Newton  condition:  trend:  contact:	Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Declining
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Other  Two round cairns 450m south of Lower Forms Scheduled Monument (No. 34809)  Plant growth Other	contact:  arm, Newton  condition:  trend:  contact:	Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Generally unsatisfactory
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DITE NAME:  DESIGNATION:	Other  Two round cairns 450m south of Lower Factorian Scheduled Monument (No. 34809)  Plant growth Other  Newton Mulgrave medieval settlement, Newton Mulgrave medieval settlement, Newton Mulgrave Monument (No. 32071)	CONTACT:  arm, Newton  CONDITION:  TREND:  CONTACT:  ewton Mulgrave  CONDITION:	Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Generally unsatisfactory with major localised problems
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Other  Two round cairns 450m south of Lower Factorian Scheduled Monument (No. 34809)  Plant growth Other  Newton Mulgrave medieval settlement, No. Scheduled Monument (No. 32071)  Permitted development	CONTACT:  arm, Newton  CONDITION:  TREND:  CONTACT:  ewton Mulgrave  CONDITION:  TREND:	Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Generally unsatisfactory with major localised problems Declining
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DITE NAME:  DESIGNATION:	Other  Two round cairns 450m south of Lower Factorian Scheduled Monument (No. 34809)  Plant growth Other  Newton Mulgrave medieval settlement, Newton Mulgrave medieval settlement, Newton Mulgrave Monument (No. 32071)	CONTACT:  arm, Newton  CONDITION:  TREND:  CONTACT:  ewton Mulgrave  CONDITION:	Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Generally unsatisfactory with major localised problems
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Other  Two round cairns 450m south of Lower Factorian Scheduled Monument (No. 34809)  Plant growth Other  Newton Mulgrave medieval settlement, No. Scheduled Monument (No. 32071)  Permitted development	CONTACT:  arm, Newton  CONDITION:  TREND:  CONTACT:  ewton Mulgrave  CONDITION:  TREND:  CONTACT:	Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Other  Two round cairns 450m south of Lower Factorian Scheduled Monument (No. 34809)  Plant growth Other  Newton Mulgrave medieval settlement, Newton Mulgrave medieval settlement, Newton Mulgrave Monument (No. 32071)  Permitted development Private	CONTACT:  arm, Newton  CONDITION:  TREND:  CONTACT:  ewton Mulgrave  CONDITION:  TREND:  CONTACT:	Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Mulgrave Generally unsatisfactory
OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  OWNERSHIP:	Two round cairns 450m south of Lower Factorian Scheduled Monument (No. 34809)  Plant growth Other  Newton Mulgrave medieval settlement, Newton Mulgrave medieval settlement, Newton Monument (No. 32071)  Permitted development Private  Round barrow 330m south west of Newton	CONTACT:  arm, Newton  CONDITION:  TREND:  CONTACT:  Ewton Mulgrave  CONDITION:  TREND:  CONTACT:	Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Round barrow 350m south of Long Plain F	arm, Old Byland a	nd Scawton
DESIGNATION:	Scheduled Monument (No. 25583)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow on Scawton Moor, 620m no	orth west of High I	Lodge, Old Byland and Scawton
DESIGNATION:	Scheduled Monument (No. 32679)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 200m north east of Priests	' Spar Quarry, Osn	notherley
DESIGNATION:	Scheduled Monument (No. 25538)	CONDITION:	Generally satisfactory
	Dlant man th		but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Four round barrows 875m north west of High Blansby, Pickering		
DESIGNATION:	Scheduled Monument (No. 35465)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 440m north of Blansby Par	k Farm, Pickering	
DESIGNATION:	Scheduled Monument (No. 35464)	CONDITION:	Generally satisfactory
	,		but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Two round barrows 400m south west of V	Vest Farm, Pickerin	g
DESIGNATION:	Scheduled Monument (No. 35468)	CONDITION:	Extensive significant
			problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Two sections of Roman road on Flamboro	ugh Rigg, Pickering	
DESIGNATION:	Scheduled Monument (No. NY784)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Cairn cemetery north east of Birk Nab Fa	rm, Pockley	
DESIGNATION:	Scheduled Monument (No. NY914)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

	Linear boundary earthwork 370m east of	Oscar Park Farm, I	Rievaulx
designation:	Scheduled Monument (No. 32687)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 920m south west of Silpho	Brow Farm, Silpho	
DESIGNATION:	Scheduled Monument (No. 34557)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	The Thieves' Dikes: prehistoric linear bour	ndaries and associa	ted features, Silpho
DESIGNATION:	Scheduled Monument (No. 34558)	CONDITION:	Generally satisfactory
	,		but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Prehistoric linear boundary and associated north, east and south east of Moorsome F		a medieval monastic grange,
DESIGNATION:	Scheduled Monument (No. 35445)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 740m east of Broad Head	Farm, Snainton	
DESIGNATION:	Scheduled Monument (No. 34612)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	but with significant localised problems  Declining
PRINCIPAL VULNERABILITY: OWNERSHIP:	Plant growth Government or Agency	TREND: CONTACT:	-
OWNERSHIP:		CONTACT:	Declining
OWNERSHIP: SITE NAME:	Government or Agency	CONTACT:	Declining Keith Emerick 01904 601988  Generally satisfactory
OWNERSHIP: SITE NAME: DESIGNATION:	Government or Agency  Round barrow 780m east of Broad Head	CONTACT: Farm, Snainton	Declining Keith Emerick 01904 601988
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Round barrow 780m east of Broad Head Scheduled Monument (No. 34613)	Farm, Snainton  CONDITION:	Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Round barrow 780m east of Broad Head Scheduled Monument (No. 34613)  Plant growth	Farm, Snainton  CONDITION:  TREND:  CONTACT:	Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Round barrow 780m east of Broad Head Scheduled Monument (No. 34613)  Plant growth Government or Agency	Farm, Snainton  CONDITION:  TREND:  CONTACT:	Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988  Sproxton Generally unsatisfactory
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:	Round barrow 780m east of Broad Head Scheduled Monument (No. 34613)  Plant growth Government or Agency  Linear dyke known as Double Dikes, in W Scheduled Monument (No. 32675)	CONTACT:  Farm, Snainton  CONDITION:  TREND:  CONTACT:  Caterloo Plantation,  CONDITION:	Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988  Sproxton Generally unsatisfactory with major localised problems
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Round barrow 780m east of Broad Head Scheduled Monument (No. 34613)  Plant growth Government or Agency  Linear dyke known as Double Dikes, in W Scheduled Monument (No. 32675)  Plant growth	CONTACT:  Farm, Snainton  CONDITION:  TREND:  CONTACT:  aterloo Plantation,  CONDITION:  TREND:	Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988  Sproxton  Generally unsatisfactory with major localised problems Declining
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Round barrow 780m east of Broad Head Scheduled Monument (No. 34613)  Plant growth Government or Agency  Linear dyke known as Double Dikes, in W Scheduled Monument (No. 32675)	CONTACT:  Farm, Snainton  CONDITION:  TREND:  CONTACT:  Caterloo Plantation,  CONDITION:	Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988  Sproxton Generally unsatisfactory with major localised problems
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Round barrow 780m east of Broad Head Scheduled Monument (No. 34613)  Plant growth Government or Agency  Linear dyke known as Double Dikes, in W Scheduled Monument (No. 32675)  Plant growth	CONTACT:  Farm, Snainton  CONDITION:  TREND:  CONTACT:  aterloo Plantation,  CONDITION:  TREND:	Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988  Sproxton  Generally unsatisfactory with major localised problems Declining
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Round barrow 780m east of Broad Head Scheduled Monument (No. 34613)  Plant growth Government or Agency  Linear dyke known as Double Dikes, in W Scheduled Monument (No. 32675)  Plant growth Private	CONTACT:  Farm, Snainton  CONDITION:  TREND:  CONTACT:  aterloo Plantation,  CONDITION:  TREND:	Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988  Sproxton  Generally unsatisfactory with major localised problems Declining
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Round barrow 780m east of Broad Head Scheduled Monument (No. 34613)  Plant growth Government or Agency  Linear dyke known as Double Dikes, in W Scheduled Monument (No. 32675)  Plant growth Private  Pry Rigg round barrows, Sproxton	CONTACT:  Farm, Snainton  CONDITION:  TREND: CONTACT:  CONDITION:  TREND: CONTACT:	Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988  Sproxton  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Extensive significant problems

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Round barrow 100m north of Church Roa	ad Farm, Stainton [	Dale
DESIGNATION:	Scheduled Monument (No. 34804)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 370m south east of Rudda	Cottages, Stainton	Dale
DESIGNATION:	Scheduled Monument (No. 34415)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 450m north west of Garbu	ıtt Farm, Sutton-un	der-Whitestonecliffe
DESIGNATION:	Scheduled Monument (No. 25563)	CONDITION:	Generally satisfactory
	( =)		but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 600m north west of Garbu	ıtt Farm, Sutton-un	der-Whitestonecliffe
DESIGNATION	Schodulad Manument (No. 25500)		Extensive significant problems
DESIGNATION:	Scheduled Monument (No. 25590)	CONDITION:	
DDINIGIDAL VIII A 150 A 200 TT	Amble plaughing	TDE: / T	i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing Private	TREND:	Declining Keith Emerick 01904 601988
OWNERSHIP:	TTIVALC	CONTACT:	Reith Emerick 01704 601700
OWNERSHIP: SITE NAME:	Rabbit type 570m south east of Pexton M		n le Dale
			n le Dale Generally satisfactory
SITE NAME:	Rabbit type 570m south east of Pexton M Scheduled Monument (No. 34603)	oor Farm,Thornto	n le Dale  Generally satisfactory  but with significant localised problems
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Rabbit type 570m south east of Pexton M Scheduled Monument (No. 34603) Plant growth	oor Farm, Thornto  CONDITION:  TREND:	n le Dale  Generally satisfactory  but with significant localised problems  Stable
site name: Designation:	Rabbit type 570m south east of Pexton M Scheduled Monument (No. 34603)	oor Farm,Thornto	n le Dale Generally satisfactory but with significant localised problems
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Rabbit type 570m south east of Pexton M Scheduled Monument (No. 34603) Plant growth	oor Farm, Thornto  CONDITION:  TREND:  CONTACT:	n le Dale  Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Rabbit type 570m south east of Pexton M Scheduled Monument (No. 34603)  Plant growth Government or Agency	oor Farm, Thornto  CONDITION:  TREND:  CONTACT:	n le Dale  Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Rabbit type 570m south east of Pexton M Scheduled Monument (No. 34603)  Plant growth Government or Agency  Round barrow 460m north west of the Ad	oor Farm, Thornto  CONDITION:  TREND:  CONTACT:  dder Stone, Thornto	n le Dale  Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  on le Dale
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNIERSHIP:  SITE NAME:  DESIGNATION:	Rabbit type 570m south east of Pexton M Scheduled Monument (No. 34603)  Plant growth Government or Agency  Round barrow 460m north west of the Ad	oor Farm, Thornto  CONDITION:  TREND:  CONTACT:  dder Stone, Thornto	Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  on le Dale Generally satisfactory
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Rabbit type 570m south east of Pexton M Scheduled Monument (No. 34603)  Plant growth Government or Agency  Round barrow 460m north west of the Ad Scheduled Monument (No. 34599)	oor Farm, Thornto  CONDITION:  TREND:  CONTACT:  dder Stone, Thornto  CONDITION:	n le Dale  Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  on le Dale  Generally satisfactory but with significant localised problems
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Rabbit type 570m south east of Pexton M Scheduled Monument (No. 34603)  Plant growth Government or Agency  Round barrow 460m north west of the Ad Scheduled Monument (No. 34599)  Plant growth	oor Farm, Thornto  CONDITION:  TREND:  CONTACT:  dder Stone, Thornto  CONDITION:  TREND:  CONTACT:	Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  on le Dale Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988
DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNERSHIP:  DESIGNATION:  SITE NAME:	Rabbit type 570m south east of Pexton M Scheduled Monument (No. 34603)  Plant growth Government or Agency  Round barrow 460m north west of the Ad Scheduled Monument (No. 34599)  Plant growth Government or Agency  Round barrow 520m north west of St Hile	oor Farm, Thornto  CONDITION:  TREND:  CONTACT:  dder Stone, Thornto  CONDITION:  TREND:  CONTACT:	Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  On le Dale Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Rabbit type 570m south east of Pexton M Scheduled Monument (No. 34603)  Plant growth Government or Agency  Round barrow 460m north west of the Ad Scheduled Monument (No. 34599)  Plant growth Government or Agency	oor Farm, Thornto  CONDITION:  TREND:  CONTACT:  dder Stone, Thornto  CONDITION:  TREND:  CONTACT:	Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  on le Dale Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  urn, Thornton le Dale Extensive significant problems
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  DESIGNATION:  DESIGNATION:	Rabbit type 570m south east of Pexton M Scheduled Monument (No. 34603)  Plant growth Government or Agency  Round barrow 460m north west of the Ad Scheduled Monument (No. 34599)  Plant growth Government or Agency  Round barrow 520m north west of St Hile Scheduled Monument (No. 35168)	oor Farm, Thornto  CONDITION:  TREND: CONTACT:  dder Stone, Thornto  CONDITION:  TREND: CONTACT:  da's Church, Ellerbu  CONDITION:	Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  on le Dale Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  urn, Thornton le Dale Extensive significant problems i.e. under plough, collapse
DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNERSHIP:  DESIGNATION:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:	Rabbit type 570m south east of Pexton M Scheduled Monument (No. 34603)  Plant growth Government or Agency  Round barrow 460m north west of the Ad Scheduled Monument (No. 34599)  Plant growth Government or Agency  Round barrow 520m north west of St Hild Scheduled Monument (No. 35168)  Arable ploughing	oor Farm, Thornto  CONDITION:  TREND: CONTACT:  dder Stone, Thornto  CONDITION:  TREND: CONTACT:  da's Church, Ellerbu  CONDITION:  TREND:	Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  On le Dale Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  Jurn, Thornton le Dale Extensive significant problems i.e. under plough, collapse Declining
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  DESIGNATION:  DESIGNATION:	Rabbit type 570m south east of Pexton M Scheduled Monument (No. 34603)  Plant growth Government or Agency  Round barrow 460m north west of the Ad Scheduled Monument (No. 34599)  Plant growth Government or Agency  Round barrow 520m north west of St Hile Scheduled Monument (No. 35168)	oor Farm, Thornto  CONDITION:  TREND: CONTACT:  dder Stone, Thornto  CONDITION:  TREND: CONTACT:  da's Church, Ellerbu  CONDITION:	Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  on le Dale Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  urn, Thornton le Dale Extensive significant problems i.e. under plough, collapse
DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNERSHIP:  DESIGNATION:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:	Rabbit type 570m south east of Pexton M Scheduled Monument (No. 34603)  Plant growth Government or Agency  Round barrow 460m north west of the Ad Scheduled Monument (No. 34599)  Plant growth Government or Agency  Round barrow 520m north west of St Hild Scheduled Monument (No. 35168)  Arable ploughing	oor Farm, Thornto  CONDITION:  TREND: CONTACT:  dder Stone, Thornto  CONDITION:  TREND: CONTACT:  da's Church, Ellerbu  CONDITION:  TREND: CONTACT:	Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  On le Dale Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  Jurn, Thornton le Dale Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  OWNERSHIP:  OWNERSHIP:	Rabbit type 570m south east of Pexton M Scheduled Monument (No. 34603)  Plant growth Government or Agency  Round barrow 460m north west of the Ad Scheduled Monument (No. 34599)  Plant growth Government or Agency  Round barrow 520m north west of St Hild Scheduled Monument (No. 35168)  Arable ploughing Private	oor Farm, Thornto  CONDITION:  TREND: CONTACT:  dder Stone, Thornto  CONDITION:  TREND: CONTACT:  da's Church, Ellerbu  CONDITION:  TREND: CONTACT:	Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  On le Dale Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  Jurn, Thornton le Dale Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:	Rabbit type 570m south east of Pexton M Scheduled Monument (No. 34603)  Plant growth Government or Agency  Round barrow 460m north west of the Ad Scheduled Monument (No. 34599)  Plant growth Government or Agency  Round barrow 520m north west of St Hild Scheduled Monument (No. 35168)  Arable ploughing Private  Round barrow 650m north west of St Hild	oor Farm, Thornto  CONDITION:  TREND: CONTACT:  dder Stone, Thornto  CONDITION:  TREND: CONTACT:  da's Church, Ellerbo  CONTACT:  da's Church, Ellerbo	Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  On le Dale Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  Jurn, Thornton le Dale Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:	Rabbit type 570m south east of Pexton M Scheduled Monument (No. 34603)  Plant growth Government or Agency  Round barrow 460m north west of the Ad Scheduled Monument (No. 34599)  Plant growth Government or Agency  Round barrow 520m north west of St Hild Scheduled Monument (No. 35168)  Arable ploughing Private  Round barrow 650m north west of St Hild	oor Farm, Thornto  CONDITION:  TREND: CONTACT:  dder Stone, Thornto  CONDITION:  TREND: CONTACT:  da's Church, Ellerbo  CONTACT:  da's Church, Ellerbo	Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  On le Dale Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  Jurn, Thornton le Dale Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988  Jurn, Thornton le Dale Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

	680m ESE and 880m NNE of Pexton Moo	rarm, inornton i	
DESIGNATION:	Scheduled Monument (No. 35433)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNERSHIP:	Government or Agency	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Two round barrows on Newclose Rigg, 81	0m north east of F	High Rigg Farm,Thornton le Dale
DESIGNATION:	Scheduled Monument (No. 34692)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNERSHIP:	Government or Agency	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Warrening enclosure 1.07km east of High	Rigg Farm, Thornto	on le Dale
DESIGNATION:	Scheduled Monument (No. 34604)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Warrening enclosure 975m north east of	High Paper Mill Far	rm,Thornton le Dale
DESIGNATION:	Scheduled Monument (No. 34616)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow on Ugthorpe Moor known as Loose Howe, I30m south west of Day Well House, Ugthorpe		
DESIGNATION:	Scheduled Monument (No. 32483)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Prehistoric linear boundary in Craddlegrip	Wood, 900m nort	h west of High Yedmandale, West Ayton
DESIGNATION:	Scheduled Monument (No. 33735)	соndition: with major	Generally unsatisfactory localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
	Private	CONTACT:	Keith Emerick 01904 601988
OWNERSHIP:	Round barrow on Coverdale Moor, 530m south of North Stile Cottage, West Ayton		
	Round barrow on Coverdale Moor, 530m	south of North Sti	le Cottage, West Ayton
SITE NAME:	Round barrow on Coverdale Moor, 530m Scheduled Monument (No. 33515)	south of North Sti	le Cottage, West Ayton  Extensive significant problems i.e. under plough, collapse
ITE NAME: DESIGNATION:			Extensive significant problems
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 33515)	CONDITION:	Extensive significant problems i.e. under plough, collapse
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Scheduled Monument (No. 33515)  Arable ploughing	CONDITION:  TREND:  CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:	Scheduled Monument (No. 33515)  Arable ploughing Private	CONDITION:  TREND:  CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Scheduled Monument (No. 33515)  Arable ploughing Private  Hut circle and adjacent clearance cairn 10	CONDITION:  TREND:  CONTACT:  Om north west of I	Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988  Round Hill, Whorlton Generally satisfactory

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# NOTE: NOTE: If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

SITE NAME:	Round barrow 100m NNW of Round Hill	,Whorlton		
DESIGNATION:	Scheduled Monument (No. 26910)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Round barrow 110m south west of Round	Hill,Whorlton		
DESIGNATION:	Scheduled Monument (No. 26908)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Round barrow 200m north west of Scarth	n Nick,Whorlton		
DESIGNATION:	Scheduled Monument (No. 25531)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Round barrow 250m west of Red Way Head, Whorlton			
DESIGNATION:	Scheduled Monument (No. 25537)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Round barrow 350m north west of Red Way Head, Whorlton			
DESIGNATION:	Scheduled Monument (No. 26912)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Round barrow 500m west of Red Way He	ad,Whorlton		
DESIGNATION:	Scheduled Monument (No. 26911)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Round barrow at northern edge of Snotte	erdale Plantation,W	/horlton	
DESIGNATION:	Scheduled Monument (No. 26920)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable	
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Two round barrows 275m south of Scarth	Wood, Whorlton		
DESIGNATION:	Scheduled Monument (No. 25532)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Round barrow at North Moor, I20m sout	h east of Forest Lo	odge, Wykeham
DESIGNATION:	Scheduled Monument (No. 32497)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow in Wykeham Forest, 550m	south east of the T	hree Tremblers, Wykeham
DESIGNATION:	Scheduled Monument (No. 32507)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow on East Moor, 640m north	of East Moor Farm	n, Wykeham
DESIGNATION:	Scheduled Monument (No. 34170)	CONDITION:	Extensive significant problems
	, , , , , , , , , , , , , , , , , , ,		i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining

#### **RICHMONDSHIRE**



Courthouse to east of Colburn Hall, SITE NAME: Colburn Hall, Colburn

DESIGNATION: Listed Building Grade I condition: Fair occupancy: Not applicable PRIORITY: E (D) OWNERSHIP: Private

A medieval courthouse built circa I 300, of rubble stone with sandstone dressings under a pantile roof. Now empty, although latterly used as a barn. The roof covering is in poor condition and work is required to the stonework. The owner is considering options for repair funding.

Contact: Neil Redfern 01904 601897



The Old Gatehouse, SITE NAME: Jervaulx Park, East Witton Out Parish

DESIGNATION: Listed Building Grade I, SM

CONDITION: Very bad occupancy: Part occupied C (C) PRIORITY:

Private

OWNERSHIP:

The house and gardens known as the Old Gatehouse is probably re-used medieval masonry (probably in the C19) on medieval foundations. Part of the building is occupied and being repaired but the western end is ruinous and in need of repair.

Contact: Neil Redfern 01904 601897



Ravensworth Castle and park wall, SITE NAME: The Green,

Ravensworth DESIGNATION: Listed Building Grade I, SM, CA CONDITION: Poor occupancy: Not applicable A(A)PRIORITY: Private OWNERSHIP:

Late C14, small roofless keep/gate tower and ruins of ancillary buildings together with impressive water defences later adapted to form water gardens. Much repointing and consolidation needed to all parts of the building. Significant parts of the standing remains, including the gate tower, are now at risk. A detailed recording of the standing fabric has been completed.

Contact: Neil Redfern 01904 601897



Cobscar Lead smelt mill, SITE NAME: Redmire

DESIGNATION: Scheduled Monument Poor Not applicable OCCUPANCY:

E (C) PRIORITY: Private OWNERSHIP:

The monument includes the standing, earthwork and buried remains of an ore hearth lead smelt mill, fuel store, and associated buildings, with the remains of a flue system leading to an intact chimney. Natural England taking forward repair programme.

Contact: Neil Redfern 01904 601897

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# NOTE: If the priority category has changed since the 2009 register, the previous category is given in brackets.

# **ABBREVIATIONS**

CA LB/LBs Conservation Area Conservation Area Listed Building/s National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site NIP NP RPG SM/SMs UA WHS



SITE NAME: Old Grandstand, Richmond

DESIGNATION: Listed Building Grade II\*, CA CONDITION: Poor

occupancy: Not applicable PRIORITY: C (C)
ownership: Company

The racecourse was closed in the late C19 and the Grandstand became derelict. It was partially demolished c1960. Ruins cleared and stonework sorted c1995. A conservation plan for the building has been completed with the support of English Heritage. The Racecourse is now a conservation area.

A rare example of an C18 racecourse grandstand.

Contact: Neil Redfern 01904 601897



St Martins Priory Ruins, A6136, St Martins

DESIGNATION: Listed Building Grade I, SM, CA

CONDITION: Poor

occupancy: Not applicable

PRIORITY: A (A)

OWNERSHIP: Private

The ruins of a small medieval monastic house, of C12 (possibly earlier) and C15. Part of a church, small gate tower and the ruined walls of other buildings also remain. Extensive consolidation and repointing work is required.

Contact: Neil Redfern 01904 601897



SITE NAME: Keld Heads lead smeltmill and mine complex,

Preston-under-Scar, Wensley

DESIGNATION: Scheduled Monument CONDITION: Poor

occupancy: Not applicable

PRIORITY: D (C)

OWNERSHIP: Private

RSHIP: Private

The mine complex displays a wide range of features associated with lead exploitation and processing. The site has been mined since the C12 but the present complex dates from C18 and C19. Scrub clearance was undertaken by North Yorkshire County Council volunteers in 2005 to assist with the preparation of survey documents.

Contact: Neil Redfern 01904 601897

SITE NAME:	Section of Scots Dyke linear boundary 600	0m south east of Pa	ark House,Aldbrough
DESIGNATION:	Scheduled Monument (No. 26953)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Stanwick Late Iron Age oppidum, Iron Age and sculpture and post-medieval emparkm		ement, early Christian church
DESIGNATION:	Scheduled Monument (No. 26950)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Section of Scots Dyke linear boundary 150	0m ENE of Olliver,	Aske
	Section of Scots Dyke linear boundary 150 Scheduled Monument (No. 28207)	Om ENE of Olliver,	Aske  Generally satisfactory
	, ,		
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	, ,		Generally satisfactory

#### PRIORITY (FOR BUILDINGS)

DESIGNATION:

OWNERSHIP:

PRINCIPAL VULNERABILITY:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

Private

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Scheduled Monument (No. 34733)

Extensive vehicle damage/erosion

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE:

CONDITION:

TREND:

CONTACT:

If the priority category has changed since the 2009 register, the previous category is given in brackets.

Generally satisfactory

Declining

but with significant localised problems

Keith Emerick 01904 601988

#### ABBREVIATIONS

CA Conservation Area
LB/LBs Listed Building/s
NP National Park
RPG Registered Park and Garden
SM/SMs Scheduled Monument/s
UA unitary Authority
WHS World Heritage Site

Scheduled Monument (No. 34735)  Extensive natural erosion	CONDITION:	Generally satisfactory
Extensive natural erosion		but with significant localised problems
EXECUSIVE HARMAN CHUSION	TREND:	Declining
Private	CONTACT:	Keith Emerick 01904 601988
Medieval settlement of Dalton upon Tees	and associated field	system, Dalton-on-Tees
Scheduled Monument (No. 31367)	CONDITION:	Generally satisfactory but with significant localised problems
Permitted development	TREND:	Stable
Private	CONTACT:	Keith Emerick 01904 601988
Section of Scots Dyke linear boundary and	d portion of field sy	stem 100m east of Whitefields Farm, Eas
Scheduled Monument (No. 26957)	CONDITION:	Generally satisfactory but with significant localised problems
Permitted development	TREND:	Improving
Private	CONTACT:	Keith Emerick 01904 601988
Roman fort and prehistoric enclosed settl	ement 400m west (	of Carkin Moor Farm, East Layton
Scheduled Monument (No. 28289)	CONDITION:	Extensive significant problems i.e. under plough, collapse
Arable ploughing	TREND:	Declining
Private	CONTACT:	Keith Emerick 01904 601988
and 180m north of The Old Hall, East Layt Scheduled Monument (No. 35479)	condition:	Generally satisfactory
D : // . :		but with significant localised problems
		Stable Keith Emerick 01904 601988
Private	CONTACT:	Keith Emerick 01904 601988
Medieval village of Hunton and field syster	n, Hunton	
Scheduled Monument (No. 29534)	CONDITION:	Generally satisfactory but with significant localised problems
Permitted development	TREND:	Declining
Private	CONTACT:	Keith Emerick 01904 601988
Section of Scots Dike linear boundary nor	th west of High Me	errybent, Melsonby
Scheduled Monument (No. 28254)	CONDITION:	Extensive significant problems i.e. under plough, collapse
Arable ploughing	TREND:	Declining
Private	CONTACT:	Keith Emerick 01904 601988
Section of Scots Dyke linear boundary eas	st of Langdale Rush	, Melsonby
Scheduled Monument (No. 26948)	CONDITION:	Generally satisfactory but with significant localised problems
		bat with significant localised problems
Scrub / tree growth	TREND:	Stable
	Scheduled Monument (No. 31367)  Permitted development Private  Section of Scots Dyke linear boundary and Scheduled Monument (No. 26957)  Permitted development Private  Roman fort and prehistoric enclosed settled Scheduled Monument (No. 28289)  Arable ploughing Private  Two moated sites, the site of a dovecote a and 180m north of The Old Hall, East Layth Scheduled Monument (No. 35479)  Drainage/dewatering Private  Medieval village of Hunton and field system Scheduled Monument (No. 29534)  Permitted development Private  Section of Scots Dike linear boundary nor Scheduled Monument (No. 28254)  Arable ploughing Private  Section of Scots Dyke linear boundary east	Permitted development Private  Section of Scots Dyke linear boundary and portion of field sy Scheduled Monument (No. 26957)  Permitted development Private  CONTACT:  Roman fort and prehistoric enclosed settlement 400m west of Scheduled Monument (No. 28289)  CONDITION:  Arable ploughing Private  Two moated sites, the site of a dovecote and further associate and 180m north of The Old Hall, East Layton  Scheduled Monument (No. 35479)  CONDITION:  Drainage/dewatering Private  Medieval village of Hunton and field system, Hunton  Scheduled Monument (No. 29534)  CONDITION:  Medieval village of Hunton and field system, Hunton  Scheduled Monument (No. 29534)  CONDITION:  Permitted development Private  Section of Scots Dike linear boundary north west of High Medieval Monument (No. 28254)  CONDITION:  Scheduled Monument (No. 28254)  CONDITION:  Section of Scots Dike linear boundary north west of High Medieval Monument (No. 28254)  CONDITION:  Section of Scots Dike linear boundary north west of High Medieval Monument (No. 28254)  CONDITION:  Section of Scots Dike linear boundary east of Langdale Rush, Marchaele Ploughing Private  Section of Scots Dyke linear boundary east of Langdale Rush, Marchaele Ploughing Private

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

ABBREVIATIONS CA LB/LBs NP RPG SM/SMs UA WHS

SITE NAME:	William's Hill, Middleham		
DESIGNATION:	Scheduled Monument (No. NY97)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Section of the Scots Dyke linear boundary	y 225m south of St	Martin's Priory, St Martin's
DESIGNATION:	Scheduled Monument (No. 29543)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Dumping	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Roman fort at Wensley, Wensley		
DESIGNATION:	Scheduled Monument (No. 24561)	CONDITION:	Extensive significant problems
	,		i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988

#### **RYEDALE**



SITE NAME: Lime Kilns,

A170, Allerston

DESIGNATION: Listed Building Grade II, SM, CA

condition: Poor

occupancy: Not applicable

PRIORITY: D (D)

OWNERSHIP: Private

Bank of four lime kilns circa 1800. For Sir George Osbaldeston. Situated in woodland. These are in a poor state of repair. Some parts are starting to collapse. Section 17 Management Agreement works to remove damaging trees completed.

Contact: Neil Redfern 01904 601897



SITE NAME: Yedingham Priory,
Ebberston and Yedingham

DESIGNATION: Listed Building Grade II\*, SM

condition: Poor

occupancy: Part occupied

PRIORITY: C (C)

OWNERSHIP: Private

Priory, C12-C13. Little standing structure survives except for part of the precinct wall and part of the refectory, which has been incorporated into a cottage and barn. The masonry is cracking and bulging in places.

Stepped cascade within a water garden of circa 1718, situated in the narrow valley of Kirk Dale approximately

50m to the north of the Hall by Colen Campbell.

Forms the lowest cascade of the two in the water

garden. Recently cleared of vegetation but the

Contact: Neil Redfern 01904 601897



Wall of cascade approximately
100 metres north of Ebberston Hall,
A170, Ebberston and Yedingham

DESIGNATION: Listed Building Grade II\*, RPG II\*

condition: Poor

occupancy: Not applicable

PRIORITY: C (C)

OWNERSHIP: Private

Contact: Neil Redfern 01904 601897

stonework is in need of repair.



Wall of cascade approximately
50 metres north of Ebberston Hall,
A170, Ebberston and Yedingham

DESIGNATION: Listed Building Grade II\*, RPG II\*

CONDITION: Poor

occupancy: Not applicable

PRIORITY: C (C)

OWNERSHIP: Private

Stepped cascade within a water garden of circa 1718, situated in the narrow valley of Kirk Dale c50m to the north of the Hall by Colen Campbell. Forms the upper cascade of the two in the water garden. In need of consolidation and restoration.

Contact: Neil Redfern 01904 601897

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE:

If the priority category has changed since the 2009 register, the previous category is given in brackets.

#### ABBREVIATIONS

CA Conservation Area
LB/LBs Listed Building/s
NP National Park
RPG Registered Park and Garden
SM/SMs Scheduled Monument/s
UA unitary Authority
WHS World Heritage Site



The Stray,
Castle Howard,
Henderskelfe

DESIGNATION: Listed Building Grade I

condition: Very bad occupancy: Not applicable

PRIORITY: D (A)

OWNERSHIP: Private

Castellated walls, 4 metres high, with square and round interval towers stretching for one mile to either side of the main drive, immediately south of the pyramid gate. Built to the designs of Sir John Vanbrugh c1723 as a landscape feature. With English Heritage support and advice the Estate has secured Natural England grant of £1 million to help fund repairs.

Contact: Hilary Roome 01904 601984



The Mausoleum and bastion wall with gates and railings, Kirk Hill,
Castle Howard Estate, Henderskelfe

DESIGNATION: Listed Building Grade I


CONDITION: Poor

occupancy: Not applicable

PRIORITY: C (C)

OWNERSHIP: Private

Contact: Neil Redfern 01904 601897



Commemorative monument of 1728 by Hawksmoor,

situated on a knoll and dominating views to the south from the Broad Walk and South Parterre. Decaying stone

pyramid suffering from cramp damage. Five of the eight

piers at the corners have been repaired with the support of grant. Set in late C17/early C18 park, one of the most



SITE NAME: The Pyramid, St Annes Hill, Castle Howard Estate, Henderskelfe

DESIGNATION: Listed Building Grade I

CONDITION: Poor

occupancy: Not applicable

PRIORITY: C (C)

OWNERSHIP: Private

historically significant landscapes in the country.

Contact: Neil Redfern 01904 601897



SITE NAME: Walls to walled garden
with gates and corner piers,
Castle Howard Estate, Henderskelfe

DESIGNATION: Listed Building Grade I

condition: Very bad

occupancy: Not applicable

PRIORITY: C (C)

OWNERSHIP: Private

Walls to the walled garden, early C18 by Sir John Vanburgh. The brick walls are in fair condition but the limestone piers are decaying and destabilising, partly collapsed due to lack of maintenance and repair.

Contact: Neil Redfern 01904 601897



SITE NAME: Screen wall,

north west of Malton Lodge, Old Maltongate, Malton

DESIGNATION: Listed Building Grade II\*, CA

condition: Very bad

occupancy: Not applicable

PRIORITY: A (A)

OWNERSHIP: Private

Private Co

Courtyard wall circa I 604 of 'An extraordinary relic of a great Prodigy house of considerable national importance' (list description). Very heavily decayed and potentially unstable.

Contact: Neil Redfern 01904 601897



SITE NAME:

St Leonard's Church and cross base adjacent to St Mary's Church, Sand Hutton

DESIGNATION: Listed Building Grade II, SM

CONDITION: Very bad

occupancy: Not applicable

PRIORITY: F (F)

OWNERSHIP: Religious organisation

Ruined chapel to rear of existing church. Standing and buried remains of a C12 church and base of associated medieval cross. Project development work commenced lune 2010.

Contact: Keith Emerick 01904 601988

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified, or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE:

If the priority category has changed since the 2009 register, the previous category is given in brackets.

#### ABBREVIATIONS

CA Conservation Area
LB/LBs Listed Building/s
NP National Park
RPG Registered Park and Garden
SM/SMs Scheduled Monument/s
UA Unitary Authority
WHS World Heritage Site



Sheriff Hutton Castle, SITE NAME: Main Street,

Sheriff Hutton

DESIGNATION: Listed Building Grade II\*, SM, CA

condition: Poor

OCCUPANCY: Not applicable

PRIORITY: C (C) OWNERSHIP: Private Ruinous castle begun in 1382 by John, Lord Neville, with C15 gatehouse inserted. Vulnerable to weathering. A condition survey was funded by English Heritage and Phase I repairs, also funded by English Heritage are complete. Emergency works to south west tower nearing completion.

Contact: Keith Emerick 01904 601988



Slingsby Castle, SITE NAME: Slingsby

DESIGNATION: Listed Building Grade II, SM

condition: Very bad occupancy: Not applicable

C (C) PRIORITY: Private OWNERSHIP:

C16 Great House built on the site of a medieval castle. Ruinous but surviving up to the eaves in height. In need of urgent consolidation; site is deteriorating as a result of natural erosion and some vandalism.

Contact: Neil Redfern 01904 601897

Scheduled Monument (No. 20549)  CONDITION  Extensive significant problems i.e. under plough, collapse i.e. under plough, collapse i.e. under plough, collapse Private  Arable ploughing  Private  CONTACT:  Keith Emerick 01904 601988  THE NAME:  Acklam Wold barrow group: a bowl barrow 300m north west of Acklam Wold House, Acklam Sescentation.  Scheduled Monument (No. 20548)  CONDITION:  Extensive significant problems i.e. under plough, collapse Declining  Private  Arable ploughing  THEND:  CONDITION:  Keith Emerick 01904 601988  Acklam Wold barrow group: a bowl barrow 300m south east of Acklam Wold House, Acklam Cesonation.  Scheduled Monument (No. 20554)  CONDITION:  Extensive significant problems i.e. under plough, collapse Declining  Private  CONTACT:  Keith Emerick 01904 601988  Acklam Wold barrow group: a bowl barrow 300m south west of Acklam Wold House, Acklam Cesonation.  Scheduled Monument (No. 20554)  CONDITION:  Extensive significant problems i.e. under plough, collapse Declining  Extensive significant problems i.e. under plough, collapse  Private  CONTACT:  Keith Emerick 01904 601988  Acklam Wold barrow group: a bowl barrow 300m south west of Acklam Wold House, Acklam Cesonation.  Scheduled Monument (No. 20552)  CONDITION:  Extensive significant problems i.e. under plough, collapse  Private  CONTACT:  Keith Emerick 01904 601988  Acklam Wold barrow group: a bowl barrow 450m south of Acklam Wold House, Acklam  Acklam Wold barrow group: a bowl barrow 450m south of Acklam Wold House, Acklam  Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  Exconation:  Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  Exconation:  Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wol				
i.e. under plough, collapse Private CONTACT: Keith Emerick 01904 601988  Arable ploughing TREND: Declining CONTACT: Keith Emerick 01904 601988  Acklam Wold barrow group: a bowl barrow 300m north west of Acklam Wold House, Acklam Essignation: Scheduled Monument (No. 20548)  CONDITION: Extensive significant problems i.e. under plough, collapse Declining Private CONTACT: Keith Emerick 01904 601988  Acklam Wold barrow group: a bowl barrow 300m south east of Acklam Wold House, Acklam CESIGNATION: Scheduled Monument (No. 20554)  CONDITION: Extensive significant problems i.e. under plough, collapse Perivate CONTACT: Keith Emerick 01904 601988  Arable ploughing TREND: Declining  Extensive significant problems i.e. under plough, collapse Declining  Private CONTACT: Keith Emerick 01904 601988  Acklam Wold barrow group: a bowl barrow 300m south west of Acklam Wold House, Acklam  CESIGNATION: Scheduled Monument (No. 20552)  CONDITION: Extensive significant problems i.e. under plough, collapse  RENDERS Acklam Wold barrow group: a bowl barrow 300m south west of Acklam Wold House, Acklam  CESIGNATION: Scheduled Monument (No. 20552)  CONTACT: Keith Emerick 01904 601988  THE NAME: Acklam Wold barrow group: a bowl barrow 450m south of Acklam Wold House, Acklam  CESIGNATION: Scheduled Monument (No. 20556)  CONTACT: Keith Emerick 01904 601988  THE NAME: Acklam Wold barrow group: a bowl barrow 450m south of Acklam Wold House, Acklam  CESIGNATION: Scheduled Monument (No. 20556)  CONTACT: Keith Emerick 01904 601988  THE NAME: Acklam Wold barrow group: a bowl barrow 450m south of Acklam Wold House, Acklam  CESIGNATION: Scheduled Monument (No. 20556)  CONTACT: Keith Emerick 01904 601988  THE NAME: Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  CESIGNATION: Scheduled Monument (No. 20555)  CONDITION: Extensive significant problems i.e. under plough, collapse i.e	SITE NAME:	Acklam Wold barrow group: a bowl barro	w 220m north wes	t of Acklam Wold House, Acklam
Arable ploughing TREND: Declining  MANDESHIP Private CONTACT: Keith Emerick 01904 601988  Acklam Wold barrow group: a bowl barrow 300m north west of Acklam Wold House, Acklam  Acklam Wold barrow group: a bowl barrow 300m north west of Acklam Wold House, Acklam  Acklam Wold barrow group: a bowl barrow 300m north west of Acklam Wold House, Acklam  Arable ploughing TREND: Declining  MENAME: Acklam Wold barrow group: a bowl barrow 300m south east of Acklam Wold House, Acklam  Acklam Wold barrow group: a bowl barrow 300m south east of Acklam Wold House, Acklam  Acklam Wold barrow group: a bowl barrow 300m south east of Acklam Wold House, Acklam  Acklam Wold barrow group: a bowl barrow 300m south west of Acklam Wold House, Acklam  Acklam Wold barrow group: a bowl barrow 300m south west of Acklam Wold House, Acklam  Acklam Wold barrow group: a bowl barrow 300m south west of Acklam Wold House, Acklam  Acklam Wold barrow group: a bowl barrow 300m south west of Acklam Wold House, Acklam  Acklam Wold barrow group: a bowl barrow 300m south west of Acklam Wold House, Acklam  Acklam Wold barrow group: a bowl barrow 450m south of Acklam Wold House, Acklam  Acklam Wold barrow group: a bowl barrow 450m south of Acklam Wold House, Acklam  Acklam Wold barrow group: a bowl barrow 450m south of Acklam Wold House, Acklam  Acklam Wold barrow group: a bowl barrow 450m south of Acklam Wold House, Acklam  Acklam Wold barrow group: a bowl barrow 450m south of Acklam Wold House, Acklam  Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  Acklam Wold barrow group: a bowl barrow 450m s	DESIGNATION:	Scheduled Monument (No. 20549)	CONDITION:	Extensive significant problems
Acklam Wold barrow group: a bowl barrow 300m north west of Acklam Wold House, Acklam  Scheduled Monument (No. 20548)  Extensive significant problems i.e. under plough, collapse  Declining  Private  Acklam Wold barrow group: a bowl barrow 300m south east of Acklam Wold House, Acklam  Scheduled Monument (No. 20554)  Scheduled Monument (No. 20554)  Extensive significant problems i.e. under plough, collapse  RENCELLA VULNERABILITY:  Arable ploughing  TREND:  Declining  SWARESHIP  Private  Acklam Wold barrow group: a bowl barrow 300m south west of Acklam Wold House, Acklam  Scheduled Monument (No. 20552)  CONDITION:  Extensive significant problems i.e. under plough, collapse  RENCELLA VULNERABILITY:  Arable ploughing  TREND:  Declining  Scheduled Monument (No. 20552)  CONDITION:  Extensive significant problems i.e. under plough, collapse  RENCELLA VULNERABILITY:  Arable ploughing  TREND:  Declining  CONTACT:  Keith Emerick 01904 601988  TRENDE:  Acklam Wold barrow group: a bowl barrow 450m south of Acklam Wold House, Acklam  Scheduled Monument (No. 20556)  TRENDE:  Acklam Wold barrow group: a bowl barrow 450m south of Acklam Wold House, Acklam  Scheduled Monument (No. 20556)  TRENDE:  Arable ploughing  TREND:  Declining  CONTACT:  Keith Emerick 01904 601988  TRENDE:  Acklam Wold barrow group: a bowl barrow 450m south of Acklam Wold House, Acklam  Scheduled Monument (No. 20556)  Extensive significant problems i.e. under plough, collapse  TRENDE:  Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  Scheduled Monument (No. 20555)  Extensive significant problems i.e. under plough, collapse  Lessonation  Extensive significant problems i.e. under plough, collapse  Declining  TRENDE:  De				i.e. under plough, collapse
Acklam Wold barrow group: a bowl barrow 300m north west of Acklam Wold House, Acklam  Scheduled Monument (No. 20548)  Extensive significant problems i.e. under plough, collapse  Declining  Private  Acklam Wold barrow group: a bowl barrow 300m south east of Acklam Wold House, Acklam  Scheduled Monument (No. 20554)  Scheduled Monument (No. 20554)  Extensive significant problems i.e. under plough, collapse  RENCELLA VULNERABILITY:  Arable ploughing  TREND:  Declining  SWARESHIP  Private  Acklam Wold barrow group: a bowl barrow 300m south west of Acklam Wold House, Acklam  Scheduled Monument (No. 20552)  CONDITION:  Extensive significant problems i.e. under plough, collapse  RENCELLA VULNERABILITY:  Arable ploughing  TREND:  Declining  Scheduled Monument (No. 20552)  CONDITION:  Extensive significant problems i.e. under plough, collapse  RENCELLA VULNERABILITY:  Arable ploughing  TREND:  Declining  CONTACT:  Keith Emerick 01904 601988  TRENDE:  Acklam Wold barrow group: a bowl barrow 450m south of Acklam Wold House, Acklam  Scheduled Monument (No. 20556)  TRENDE:  Acklam Wold barrow group: a bowl barrow 450m south of Acklam Wold House, Acklam  Scheduled Monument (No. 20556)  TRENDE:  Arable ploughing  TREND:  Declining  CONTACT:  Keith Emerick 01904 601988  TRENDE:  Acklam Wold barrow group: a bowl barrow 450m south of Acklam Wold House, Acklam  Scheduled Monument (No. 20556)  Extensive significant problems i.e. under plough, collapse  TRENDE:  Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  Scheduled Monument (No. 20555)  Extensive significant problems i.e. under plough, collapse  Lessonation  Extensive significant problems i.e. under plough, collapse  Declining  TRENDE:  De	PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
Scheduled Monument (No. 20548)  CONDITION: Extensive significant problems i.e. under plough, collapse private  Arable ploughing  TREND: Declining  CONTACT: Keith Emerick 01904 601988  Acklam Wold barrow group: a bowl barrow 300m south east of Acklam Wold House, Acklam Sesonation:  Scheduled Monument (No. 20554)  CONDITION: Extensive significant problems i.e. under plough, collapse plough, collapse private  Arable ploughing  TREND: Declining  WARRISHIP: Arable ploughing  TREND: Declining  WARRISHIP: Acklam Wold barrow group: a bowl barrow 300m south west of Acklam Wold House, Acklam Contact: Keith Emerick 01904 601988  TREND: Declining  WARRISHIP: Arable ploughing  TREND: Declining  WARRISHIP: Private  CONTACT: Keith Emerick 01904 601988  TREND: Declining  WARRISHIP: Private  Acklam Wold barrow group: a bowl barrow 450m south of Acklam Wold House, Acklam  DESIGNATION: Scheduled Monument (No. 20556)  CONDITION: Extensive significant problems i.e. under plough, collapse  DECLINING  Extensive significant problems i.e. under plough, collapse  DESIGNATION: Scheduled Monument (No. 20556)  CONDITION: Extensive significant problems i.e. under plough, collapse  BRINGIPM, VULNERABLITY: Arable ploughing  TREND: Declining  WARRISHIP: Acklam Wold barrow group: a bowl barrow 450m south of Acklam Wold House, Acklam  DESIGNATION: Scheduled Monument (No. 20556)  CONDITION: Extensive significant problems i.e. under plough, collapse  BRINGIPM, VULNERABLITY: Arable ploughing  TREND: Declining  WARRISHIPM: Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  DESIGNATION: Scheduled Monument (No. 20555)  CONDITION: Extensive significant problems i.e. under plough, collapse  BRINGIPM, VULNERABLITY: Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  DESIGNATION: Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  DESIGNATION: Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  DESIGNATION: Acklam Wold b	OWNERSHIP:		CONTACT:	Keith Emerick 01904 601988
Scheduled Monument (No. 20548)  CONDITION: Extensive significant problems i.e. under plough, collapse private  Arable ploughing  TREND: Declining  CONTACT: Keith Emerick 01904 601988  Acklam Wold barrow group: a bowl barrow 300m south east of Acklam Wold House, Acklam Sesonation:  Scheduled Monument (No. 20554)  CONDITION: Extensive significant problems i.e. under plough, collapse plough, collapse private  Arable ploughing  TREND: Declining  WARRISHIP: Arable ploughing  TREND: Declining  WARRISHIP: Acklam Wold barrow group: a bowl barrow 300m south west of Acklam Wold House, Acklam Contact: Keith Emerick 01904 601988  TREND: Declining  WARRISHIP: Arable ploughing  TREND: Declining  WARRISHIP: Private  CONTACT: Keith Emerick 01904 601988  TREND: Declining  WARRISHIP: Private  Acklam Wold barrow group: a bowl barrow 450m south of Acklam Wold House, Acklam  DESIGNATION: Scheduled Monument (No. 20556)  CONDITION: Extensive significant problems i.e. under plough, collapse  DECLINING  Extensive significant problems i.e. under plough, collapse  DESIGNATION: Scheduled Monument (No. 20556)  CONDITION: Extensive significant problems i.e. under plough, collapse  BRINGIPM, VULNERABLITY: Arable ploughing  TREND: Declining  WARRISHIP: Acklam Wold barrow group: a bowl barrow 450m south of Acklam Wold House, Acklam  DESIGNATION: Scheduled Monument (No. 20556)  CONDITION: Extensive significant problems i.e. under plough, collapse  BRINGIPM, VULNERABLITY: Arable ploughing  TREND: Declining  WARRISHIPM: Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  DESIGNATION: Scheduled Monument (No. 20555)  CONDITION: Extensive significant problems i.e. under plough, collapse  BRINGIPM, VULNERABLITY: Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  DESIGNATION: Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  DESIGNATION: Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  DESIGNATION: Acklam Wold b				
i.e. under plough, collapse  RINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  Development of Acklam Wold barrow group: a bowl barrow 300m south east of Acklam Wold House, Acklam  Acklam Wold barrow group: a bowl barrow 300m south east of Acklam Wold House, Acklam  Scheduled Monument (No. 20554) CONDITION: Extensive significant problems i.e. under plough, collapse  RINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  Declining  MARIE Acklam Wold barrow group: a bowl barrow 300m south west of Acklam Wold House, Acklam  DESIGNATION: Scheduled Monument (No. 20552) CONDITION: Extensive significant problems i.e. under plough, collapse  RINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  Declining  DEVELOPMENT OF Acklam Wold barrow group: a bowl barrow 450m south of Acklam Wold House, Acklam  DESIGNATION: Scheduled Monument (No. 20556) CONDITION: Extensive significant problems i.e. under plough, collapse  RINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  DECLINION: Extensive significant problems i.e. under plough, collapse  RINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  DECLINION: Extensive significant problems i.e. under plough, collapse  RINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  DECLINION: Extensive significant problems i.e. under plough, collapse  TRENAME: Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  DESIGNATION: Scheduled Monument (No. 20555) CONDITION: Extensive significant problems i.e. under plough, collapse  TRENAME: Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  DESIGNATION: Scheduled Monument (No. 20555) CONDITION: Extensive significant problems i.e. under plough, collapse  DECLINION: Extensive significant problems i.e. under plough, collapse  DECLINION: DECLINION: DECLINION: Extensive significant problems i.e. under plough, collapse	SITE NAME:	Acklam Wold barrow group: a bowl barro	w 300m north wes	t of Acklam Wold House, Acklam
Arable ploughing Private CONTACT: Keith Emerick 01904 601988  THE NAME: Acklam Wold barrow group: a bowl barrow 300m south east of Acklam Wold House, Acklam Pesignation: Scheduled Monument (No. 20554) CONDITION: Extensive significant problems i.e. under plough, collapse Private CONTACT: Keith Emerick 01904 601988  THE NAME: Acklam Wold barrow group: a bowl barrow 300m south west of Acklam Wold House, Acklam Private CONTACT: Keith Emerick 01904 601988  THE NAME: Acklam Wold barrow group: a bowl barrow 300m south west of Acklam Wold House, Acklam Pesignation: Scheduled Monument (No. 20552) CONDITION: Extensive significant problems i.e. under plough, collapse RINCIPAL VILLEBABILITY: Arable ploughing TREND: Declining Declining Private CONTACT: Keith Emerick 01904 601988  THE NAME: Acklam Wold barrow group: a bowl barrow 450m south of Acklam Wold House, Acklam Pesignation: Scheduled Monument (No. 20556) CONDITION: Extensive significant problems i.e. under plough, collapse RINCIPAL VILLEBABILITY: Arable ploughing TREND: Declining Declining Private CONTACT: Keith Emerick 01904 601988  THE NAME: Acklam Wold barrow group: a bowl barrow 450m south of Acklam Wold House, Acklam Private CONTACT: Keith Emerick 01904 601988  THE NAME: Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam Private CONTACT: Keith Emerick 01904 601988  THE NAME: Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam Private CONTACT: Keith Emerick 01904 601988  THE NAME: Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam Private Acklam Wold Barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam Private Acklam Wold Barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam Private Acklam Wold Barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam Private Acklam Wold Barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam Private Acklam Wold Barrow group: a bowl barrow 450m south west of Ac	DESIGNATION:	Scheduled Monument (No. 20548)	CONDITION:	Extensive significant problems
Private CONTACT: Keith Emerick 01904 601988  Acklam Wold barrow group: a bowl barrow 300m south east of Acklam Wold House, Acklam  Scheduled Monument (No. 20554)  Scheduled Monument (No. 20554)  CONDITION: Extensive significant problems i.e. under plough, collapse  RINCIPAL VULNERABILITY: Arable ploughing  TREND: Declining  WONDERSHIP: Private  Acklam Wold barrow group: a bowl barrow 300m south west of Acklam Wold House, Acklam  SESIGNATION: Scheduled Monument (No. 20552)  CONDITION: Extensive significant problems i.e. under plough, collapse  RINCIPAL VULNERABILITY: Arable ploughing  TREND: Declining  WONDERSHIP: Private  Acklam Wold barrow group: a bowl barrow 450m south of Acklam Wold House, Acklam  DESIGNATION: Scheduled Monument (No. 20556)  CONDITION: Extensive significant problems i.e. under plough, collapse  RINCIPAL VULNERABILITY: Arable ploughing  TREND: Declining  CONTACT: Keith Emerick 01904 601988  TREND: Declining  CONT				i.e. under plough, collapse
Acklam Wold barrow group: a bowl barrow 300m south east of Acklam Wold House, Acklam Besignation:  Scheduled Monument (No. 20554)  CONDITION: Extensive significant problems i.e. under plough, collapse RINGIPAL VULNERABILITY: Arable ploughing  TREND: Declining Private  CONTACT: Keith Emerick 01904 601988  THE NAME: Acklam Wold barrow group: a bowl barrow 300m south west of Acklam Wold House, Acklam Besignation: Scheduled Monument (No. 20552) CONDITION: Extensive significant problems i.e. under plough, collapse RINGIPAL VULNERABILITY: Arable ploughing  TREND: Declining Private  Acklam Wold barrow group: a bowl barrow 450m south of Acklam Wold House, Acklam Designation: Scheduled Monument (No. 20556) CONDITION: Extensive significant problems i.e. under plough, collapse RINGIPAL VULNERABILITY: Arable ploughing  TREND: Declining	PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
Scheduled Monument (No. 20554)  Scheduled Monument (No. 20554)  Scheduled Monument (No. 20554)  Scheduled Monument (No. 20554)  TREND: Declining	OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
I.e. under plough, collapse RINCIPAL VULNERABILITY: Arable ploughing TREND: Declining Devivership: Private CONTACT: Keith Emerick 01904 601988  THE NAME: Acklam Wold barrow group: a bowl barrow 300m south west of Acklam Wold House, Acklam  Designation: Scheduled Monument (No. 20552) CONDITION: Extensive significant problems i.e. under plough, collapse  RINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  Designation: CONTACT: Keith Emerick 01904 601988  THE NAME: Acklam Wold barrow group: a bowl barrow 450m south of Acklam Wold House, Acklam  DESIGNATION: Scheduled Monument (No. 20556) CONDITION: Extensive significant problems i.e. under plough, collapse  RINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  DEVINERSHIP: Private CONTACT: Keith Emerick 01904 601988  THE NAME: Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  DESIGNATION: Scheduled Monument (No. 20555) CONDITION: Extensive significant problems i.e. under plough, collapse  THE NAME: Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  DESIGNATION: Scheduled Monument (No. 20555) CONDITION: Extensive significant problems i.e. under plough, collapse  RINCIPAL VULNERABILITY: Arable ploughing TREND: Declining	SITE NAME:	Acklam Wold barrow group: a bowl barro	w 300m south east	of Acklam Wold House, Acklam
I.e. under plough, collapse RINCIPAL VULNERABILITY: Arable ploughing TREND: Declining Devivership: Private CONTACT: Keith Emerick 01904 601988  THE NAME: Acklam Wold barrow group: a bowl barrow 300m south west of Acklam Wold House, Acklam  Designation: Scheduled Monument (No. 20552) CONDITION: Extensive significant problems i.e. under plough, collapse  RINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  Designation: CONTACT: Keith Emerick 01904 601988  THE NAME: Acklam Wold barrow group: a bowl barrow 450m south of Acklam Wold House, Acklam  DESIGNATION: Scheduled Monument (No. 20556) CONDITION: Extensive significant problems i.e. under plough, collapse  RINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  DEVINERSHIP: Private CONTACT: Keith Emerick 01904 601988  THE NAME: Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  DESIGNATION: Scheduled Monument (No. 20555) CONDITION: Extensive significant problems i.e. under plough, collapse  THE NAME: Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  DESIGNATION: Scheduled Monument (No. 20555) CONDITION: Extensive significant problems i.e. under plough, collapse  RINCIPAL VULNERABILITY: Arable ploughing TREND: Declining	DESIGNATION:	Scheduled Monument (No. 20554)	CONDITION:	Extensive significant problems
RINCIPAL VULNERABILITY: Arable ploughing TREND: Declining Device Contact: Keith Emerick 01904 601988  Acklam Wold barrow group: a bowl barrow 300m south west of Acklam Wold House, Acklam Designation: Scheduled Monument (No. 20552) CONDITION: Extensive significant problems i.e. under plough, collapse RINCIPAL VULNERABILITY: Arable ploughing TREND: Declining Designation: Acklam Wold barrow group: a bowl barrow 450m south of Acklam Wold House, Acklam Designation: Scheduled Monument (No. 20556) CONDITION: Extensive significant problems i.e. under plough, collapse RINCIPAL VULNERABILITY: Arable ploughing TREND: Declining Devices In the plough of the provided Contact: Keith Emerick 01904 601988  Acklam Wold barrow group: a bowl barrow 450m south of Acklam Wold House, Acklam Designation: Contact: Keith Emerick 01904 601988  Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam Designation: Scheduled Monument (No. 20555) Condition: Extensive significant problems i.e. under plough, collapse Designation: Scheduled Monument (No. 20555) Condition: Extensive significant problems i.e. under plough, collapse Designation: Arable ploughing TREND: Declining	SESIGIV (IIOI V.	Scheduled Floriament (Fig. 2000 1)	CONDITION.	• '
Acklam Wold barrow group: a bowl barrow 300m south west of Acklam Wold House, Acklam Sesignation:  Scheduled Monument (No. 20552)  CONDITION: Extensive significant problems i.e. under plough, collapse Declining  Private  Arable ploughing  TREND: Declining  CONTACT: Keith Emerick 01904 601988  TREND: Declining  TREND: Declining  TREND: Declining  TREND: Extensive significant problems i.e. under plough, collapse  TREND: Declining	PRINCIPAL VI II NIERARII ITY	Arable ploughing	TRENID:	
Acklam Wold barrow group: a bowl barrow 300m south west of Acklam Wold House, Acklam  DESIGNATION:  Scheduled Monument (No. 20552)  CONDITION: Extensive significant problems i.e. under plough, collapse  Declining  TE NAME:  Acklam Wold barrow group: a bowl barrow 450m south of Acklam Wold House, Acklam  DESIGNATION: DESIGNATION: DECLINING				0
Scheduled Monument (No. 20552)  CONDITION: Extensive significant problems i.e. under plough, collapse  RINCIPAL VULNERABILITY: Arable ploughing  TREND: Declining  CONTACT: Keith Emerick 01904 601988  THE NAME: Acklam Wold barrow group: a bowl barrow 450m south of Acklam Wold House, Acklam  DESIGNATION: Scheduled Monument (No. 20556)  CONDITION: Extensive significant problems i.e. under plough, collapse  RINCIPAL VULNERABILITY: Arable ploughing  TREND: Declining  Declining  TREND: Keith Emerick 01904 601988  THE NAME: Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  DESIGNATION: Scheduled Monument (No. 20555)  CONDITION: Extensive significant problems i.e. under plough, collapse  RINCIPAL VULNERABILITY: Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  DESIGNATION: Scheduled Monument (No. 20555)  CONDITION: Extensive significant problems i.e. under plough, collapse  RINCIPAL VULNERABILITY: Arable ploughing  TREND: Declining	SWINEIGH III .	Tivace	CONTACT.	Reidi Emerick 01701 001700
i.e. under plough, collapse RINCIPAL VULNERABILITY: Arable ploughing TREND: Declining DWNERSHIP: Private CONTACT: Keith Emerick 01904 601988  Acklam Wold barrow group: a bowl barrow 450m south of Acklam Wold House, Acklam  Scheduled Monument (No. 20556) CONDITION: Extensive significant problems i.e. under plough, collapse  RINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  DWNERSHIP: Private CONTACT: Keith Emerick 01904 601988  Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  DESIGNATION: Scheduled Monument (No. 20555) CONDITION: Extensive significant problems i.e. under plough, collapse  RINCIPAL VULNERABILITY: Arable ploughing TREND: Declining	SITE NAME:	Acklam Wold barrow group: a bowl barro	w 300m south wes	t of Acklam Wold House, Acklam
RINCIPAL VULNERABILITY: Arable ploughing TREND: Declining Dwnership: Private Contact: Keith Emerick 01904 601988  Acklam Wold barrow group: a bowl barrow 450m south of Acklam Wold House, Acklam Designation: Scheduled Monument (No. 20556) Condition: Extensive significant problems i.e. under plough, collapse RINCIPAL VULNERABILITY: Arable ploughing TREND: Declining Dwnership: Private Contact: Keith Emerick 01904 601988  Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam Designation: Scheduled Monument (No. 20555) Condition: Extensive significant problems i.e. under plough, collapse RINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  TREND: Declining	DESIGNATION:	Scheduled Monument (No. 20552)	CONDITION:	Extensive significant problems
Acklam Wold barrow group: a bowl barrow 450m south of Acklam Wold House, Acklam  Scheduled Monument (No. 20556)  Scheduled Monument (No. 20556)  CONDITION:  Extensive significant problems i.e. under plough, collapse  RINCIPAL VULNERABILITY:  Arable ploughing  TREND:  Declining  CONTACT:  Keith Emerick 01904 601988  TREND:  Declining  TREND:  CONTACT:  TREND:  Declining  CONTACT:  TREND:  Declining  CONTACT:  TREND:  Declining  CONTACT:  TREND:  Declining  CONDITION:  Extensive significant problems i.e. under plough, collapse  RINCIPAL VULNERABILITY:  Arable ploughing  TREND:  Declining				i.e. under plough, collapse
Acklam Wold barrow group: a bowl barrow 450m south of Acklam Wold House, Acklam  Scheduled Monument (No. 20556)  CONDITION: Extensive significant problems i.e. under plough, collapse  RINCIPAL VULNERABILITY: Arable ploughing  TREND: Declining  CONTACT: Keith Emerick 01904 601988  THE NAME: Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  Designation: Scheduled Monument (No. 20555)  CONDITION: Extensive significant problems i.e. under plough, collapse  RINCIPAL VULNERABILITY: Arable ploughing  TREND: Declining	PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
Scheduled Monument (No. 20556)  CONDITION: Extensive significant problems i.e. under plough, collapse  RINCIPAL VULNERABILITY: Arable ploughing  TREND: Declining  CONTACT: Keith Emerick 01904 601988  Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  Designation: Scheduled Monument (No. 20555)  CONDITION: Extensive significant problems i.e. under plough, collapse  RINCIPAL VULNERABILITY: Arable ploughing  TREND: Declining	OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
i.e. under plough, collapse  RINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  Declining  CONTACT: Keith Emerick 01904 601988  Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  Designation: Scheduled Monument (No. 20555)  CONDITION: Extensive significant problems i.e. under plough, collapse  RINCIPAL VULNERABILITY: Arable ploughing TREND: Declining	SITE NAME:	Acklam Wold barrow group: a bowl barro	w 450m south of A	.cklam Wold House, Acklam
i.e. under plough, collapse  RINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  Declining  CONTACT: Keith Emerick 01904 601988  Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  Designation: Scheduled Monument (No. 20555)  CONDITION: Extensive significant problems i.e. under plough, collapse  RINCIPAL VULNERABILITY: Arable ploughing TREND: Declining	DESIGNATION:	Scheduled Monument (No. 20556)	CONDITION:	Extensive significant problems
Arable ploughing TREND: Declining  WINDERSHIP: Private CONTACT: Keith Emerick 01904 601988  THE NAME: Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  Designation: Extensive significant problems i.e. under plough, collapse  RINCIPAL VULNERABILITY: Arable ploughing TREND: Declining		,		
Private CONTACT: Keith Emerick 01904 601988  Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  Scheduled Monument (No. 20555) CONDITION: Extensive significant problems i.e. under plough, collapse  RINCIPAL VULNERABILITY: Arable ploughing  TREND: Declining	PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	
Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam  Scheduled Monument (No. 20555)  CONDITION: Extensive significant problems i.e. under plough, collapse  RINCIPAL VULNERABILITY: Arable ploughing  TREND: Declining	OWNERSHIP:			0
Scheduled Monument (No. 20555)  CONDITION: Extensive significant problems i.e. under plough, collapse  RINCIPAL VULNERABILITY: Arable ploughing  TREND: Declining				
i.e. under plough, collapse  RINCIPAL VULNERABILITY: Arable ploughing TREND: Declining	SITE NAME:	Acklam Wold barrow group: a bowl barro	w 450m south wes	t of Acklam Wold House, Acklam
rincipal vulnerability: Arable ploughing trend: Declining	DESIGNATION:	Scheduled Monument (No. 20555)	CONDITION:	Extensive significant problems
				i.e. under plough, collapse
DWNERSHIP: Private CONTACT: Keith Emerick 01904 601988	PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
	OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Claracteristics

  C Claracteristics

  C Claracteristics

  C Claracteristics

  C Claracteristics

  C Claracteristics
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: If the priority category has changed since the 2009 register, the previous category is given in brackets.

#### **ABBREVIATIONS**

SITE NAME:	Acklam Wold barrow group: a bowl barro	w on Wooing Nab,	Acklam
DESIGNATION:	Scheduled Monument (No. 20547)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Acklam Wold barrow group: a pair of bell 200m south west of Acklam Wold House,		vl barrow
DESIGNATION:	Scheduled Monument (No. 20551)	CONDITION:	Extensive significant problems i.e. under plough, collapse
DDINICIDAL VILILNIED A DILITY.	Arable ploughing	TREND.	Declining
PRINCIPAL VULNERABILITY:  OWNERSHIP:	Private	TREND: CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Acklam Wold barrow group: two bowl bar	rows on Wooing N	Nab. Acklam
	<u> </u>	•	
DESIGNATION:	Scheduled Monument (No. 20546)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Aldro earthworks: a linear boundary, two	cross-dykes and ni	ne round barrows on Birdsall Wold, Acklar
DESIGNATION:	Scheduled Monument (No. 20463)	CONDITION:	Generally unsatisfactory
	,		with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Long barrow 530m north of Keeper's Cot	tage, Allerston	
DESIGNATION:	Scheduled Monument (No. 35152)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNERSHIP:	Government or Agency	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Long barrow 630m north west of Scamric	lge Farm, Allerston	
DESIGNATION:	Scheduled Monument (No. 35440)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Prehistoric linear boundary on Stonygate	Moor, 550m west o	of Warren House Farm, Allerston
DESIGNATION:	Scheduled Monument (No. 35170)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 470m north of Keeper's Co	ottage,Allerston	
DESIGNATION:	Scheduled Monument (No. 35153)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNERSHIP:	Government or Agency	CONTACT:	Keith Emerick 01904 601988
	0 - /		

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Round barrow 600m west of Scamridge Fa	rm, Allerston	
DESIGNATION:	Scheduled Monument (No. 35164)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Improving
DWNERSHIP:	Government or Agency	CONTACT:	Keith Emerick 01904 601988
WINEIOI III .	Government of 7 gency	CONTACT.	Refut Efficiency 01701 001700
TE NAME:	Round barrow 250m NNE of Easthorpe Co	ottages, Amotherb	у
DESIGNATION:	Scheduled Monument (No. 28236)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
ITE NAME:	Round barrow 310m NNE of Easthorpe Lo	odge, Amotherby	
DESIGNATION:	Scheduled Monument (No. 28235)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
WINEIOF III .	TTIVACC	CONTACT:	Refut Effection 01701 001700
ITE NAME:	Round barrow 330m north of Easthorpe L	odge,Amotherby	
DESIGNATION:	Scheduled Monument (No. 28237)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
WNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
ITE NAME:	Round barrow 360m north of Easthorpe L	odge,Amotherby	
	Round barrow 360m north of Easthorpe L Scheduled Monument (No. 28238)	odge, Amotherby	Extensive significant problems
DESIGNATION:	Scheduled Monument (No. 28238)	CONDITION:	i.e. under plough, collapse
DESIGNATION: RINCIPAL VULNERABILITY:	Scheduled Monument (No. 28238)  Arable ploughing	CONDITION:	i.e. under plough, collapse Declining
DESIGNATION: RINCIPAL VULNERABILITY:	Scheduled Monument (No. 28238)	CONDITION:	i.e. under plough, collapse
DESIGNATION: PRINCIPAL VULNERABILITY: DWNERSHIP:	Scheduled Monument (No. 28238)  Arable ploughing	CONDITION:  TREND:  CONTACT:	i.e. under plough, collapse Declining
DESIGNATION:  RINCIPAL VULNERABILITY:  DWNERSHIP:  ITE NAME:	Scheduled Monument (No. 28238)  Arable ploughing  Private	CONDITION:  TREND:  CONTACT:	i.e. under plough, collapse Declining Keith Emerick 01904 601988  Extensive significant problems
DESIGNATION:  RINCIPAL VULNERABILITY:  DWNERSHIP:  ITE NAME:  DESIGNATION:	Scheduled Monument (No. 28238)  Arable ploughing Private  Round barrow 380m NNW of Easthorpe I  Scheduled Monument (No. 28241)	CONDITION:  TREND:  CONTACT:  Lodge, Amotherby	i.e. under plough, collapse Declining Keith Emerick 01904 601988  Extensive significant problems i.e. under plough, collapse
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 28238)  Arable ploughing Private  Round barrow 380m NNW of Easthorpe I	CONDITION:  TREND: CONTACT:  Lodge, Amotherby  CONDITION:	i.e. under plough, collapse Declining Keith Emerick 01904 601988  Extensive significant problems
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  SITE NAME:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  OWNERSHIP:	Scheduled Monument (No. 28238)  Arable ploughing Private  Round barrow 380m NNW of Easthorpe I Scheduled Monument (No. 28241)  Arable ploughing	CONDITION:  TREND: CONTACT:  Lodge, Amotherby  CONDITION:  TREND:	i.e. under plough, collapse Declining Keith Emerick 01904 601988  Extensive significant problems i.e. under plough, collapse Declining
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  ITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  ITE NAME:	Scheduled Monument (No. 28238)  Arable ploughing Private  Round barrow 380m NNW of Easthorpe I Scheduled Monument (No. 28241)  Arable ploughing Private  Iron Age settlement, Barton-le-Street	CONDITION:  TREND: CONTACT:  Lodge, Amotherby  CONDITION:  TREND: CONTACT:	i.e. under plough, collapse Declining Keith Emerick 01904 601988  Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  ITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  ITE NAME:	Scheduled Monument (No. 28238)  Arable ploughing Private  Round barrow 380m NNW of Easthorpe I  Scheduled Monument (No. 28241)  Arable ploughing Private	CONDITION:  TREND: CONTACT:  Lodge, Amotherby  CONDITION:  TREND:	i.e. under plough, collapse Declining Keith Emerick 01904 601988  Extensive significant problems i.e. under plough, collapse Declining
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  SITE NAME:  DESIGNATION:	Scheduled Monument (No. 28238)  Arable ploughing Private  Round barrow 380m NNW of Easthorpe I Scheduled Monument (No. 28241)  Arable ploughing Private  Iron Age settlement, Barton-le-Street	CONDITION:  TREND: CONTACT:  Lodge, Amotherby  CONDITION:  TREND: CONTACT:	i.e. under plough, collapse Declining Keith Emerick 01904 601988  Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988  Extensive significant problems i.e. under plough, collapse Declining
DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:	Scheduled Monument (No. 28238)  Arable ploughing Private  Round barrow 380m NNW of Easthorpe I Scheduled Monument (No. 28241)  Arable ploughing Private  Iron Age settlement, Barton-le-Street Scheduled Monument (No. NY1233)	CONDITION:  TREND: CONTACT:  Lodge, Amotherby  CONDITION:  TREND: CONTACT:	i.e. under plough, collapse Declining Keith Emerick 01904 601988  Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988  Extensive significant problems i.e. under plough, collapse
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Scheduled Monument (No. 28238)  Arable ploughing Private  Round barrow 380m NNW of Easthorpe I Scheduled Monument (No. 28241)  Arable ploughing Private  Iron Age settlement, Barton-le-Street Scheduled Monument (No. NY1233)  Arable ploughing	CONDITION:  TREND: CONTACT:  CONDITION:  TREND: CONTACT:  CONDITION:  TREND: CONTACT:	i.e. under plough, collapse Declining Keith Emerick 01904 601988  Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988  Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988
DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Scheduled Monument (No. 28238)  Arable ploughing Private  Round barrow 380m NNW of Easthorpe I Scheduled Monument (No. 28241)  Arable ploughing Private  Iron Age settlement, Barton-le-Street Scheduled Monument (No. NY1233)  Arable ploughing Private  Pockley Gates round barrow 600m west or	CONDITION:  TREND: CONTACT:  CONDITION:  TREND: CONTACT:  CONDITION:  TREND: CONTACT:	i.e. under plough, collapse Declining Keith Emerick 01904 601988  Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988  Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988  Beadlam
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:	Scheduled Monument (No. 28238)  Arable ploughing Private  Round barrow 380m NNW of Easthorpe I Scheduled Monument (No. 28241)  Arable ploughing Private  Iron Age settlement, Barton-le-Street Scheduled Monument (No. NY1233)  Arable ploughing Private	CONDITION:  TREND: CONTACT:  Lodge, Amotherby CONDITION: TREND: CONTACT:  CONDITION: TREND: CONTACT:	i.e. under plough, collapse Declining Keith Emerick 01904 601988  Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988  Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DWNERSHIP:  DWNERSHIP:  DWNERSHIP:	Scheduled Monument (No. 28238)  Arable ploughing Private  Round barrow 380m NNW of Easthorpe I Scheduled Monument (No. 28241)  Arable ploughing Private  Iron Age settlement, Barton-le-Street Scheduled Monument (No. NY1233)  Arable ploughing Private  Pockley Gates round barrow 600m west or	CONDITION:  TREND: CONTACT:  Lodge, Amotherby CONDITION: TREND: CONTACT:  CONDITION: TREND: CONTACT:	i.e. under plough, collapse Declining Keith Emerick 01904 601988  Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988  Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988  Beadlam Extensive significant problems

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	A bowl barrow on Birdsall Wold, 250m north west of Vessey Pasture Farm, Birdsall				
DESIGNATION:	Scheduled Monument (No. 20488)	CONDITION:	Extensive significant problems i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
WNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988		
TE NAME:	A bowl barrow on Birdsall Wold, 250m south east of Vessey Pasture Farm, Birdsall				
DESIGNATION:	Scheduled Monument (No. 20490)	CONDITION:	Extensive significant problems		
25.6.4.4.10.14.	00.1000.100 1 .0.101.101.10 (1 to: 20 1 / 0)	23.13.1161.1	i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
WNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988		
ITE NAME:	A bowl barrow on Birdsall Wold, 300m no	orth east of Vessey	Pasture Farm, Birdsall		
designation:	Scheduled Monument (No. 20489)	CONDITION:	Extensive significant problems		
	,		i.e. under plough, collapse		
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
WNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988		
ITE NAME:	A bowl barrow on Birdsall Wold, 425m east of Aldro Farm, Birdsall				
DESIGNATION:	Scheduled Monument (No. 20485)	CONDITION:	Extensive significant problems		
PESIGIVATION.	531634164 FIGHAMORE (140, 20 105)	CONDITION.	i.e. under plough, collapse		
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
WNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988		
TE NAME:	A bowl barrow on Birdsall Wold, 475m no incorporating part of a linear boundary, Bi		Pasture Farm,		
	incorporating part of a linear boundary, bi	rusan			
DESIGNATION:	Scheduled Monument (No. 20486)	CONDITION:	Extensive significant problems i.e. under plough, collapse		
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
WNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988		
ITE NAME:	A bowl barrow on Birdsall Wold, 580m ea	st of Aldro Farm, B	irdsall		
DESIGNATION:	Scheduled Monument (No. 20483)	CONDITION:	Extensive significant problems		
	( 1 1 1 )		i.e. under plough, collapse		
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
WNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	A bowl barrow on Birdsall Wold, 750m ea	st of Aldro Farm, B	irdsall		
DESIGNATION:	Scheduled Monument (No. 20481)	CONDITION:	Extensive significant problems		
	55.555.55 . Torrament (1 vo. 20 101)	CONDITION.	i.e. under plough, collapse		
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining Declining		
WNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	A bowl barrow on Birdsall Wold, between	Birdsall Dale and V	essey Pasture Dale, Birdsall		
DESIGNATION:	Scheduled Monument (No. 20475)	CONDITION:	Extensive significant problems i.e. under plough, collapse		
SINCIPAL VI II NEPARII ITV	Arable ploughing	TRENID:	Declining		
RINCIPAL VULNERABILITY:	Arable ploughing Private	TREND: CONTACT:	Declining Keith Emerick 01904 601988		

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	A bowl barrow on Birdsall Wold, between	Birdsall Dale and \	essey Pasture Dale, Birdsall	
DESIGNATION:	Scheduled Monument (No. 20476)	CONDITION:	Generally satisfactory but with minor localised problems	
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining	
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	A bowl barrow on Birdsall Wold, between	Birdsall Dale and \	essey Pasture Dale, Birdsall	
DESIGNATION:	Scheduled Monument (No. 20478)	CONDITION:	Extensive significant problems i.e. under plough, collapse	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988	
ITE NAME:	Three bowl barrows on Birdsall Wold, 400	m north west of V	essey Pasture Farm, Birdsall	
DESIGNATION:	Scheduled Monument (No. 20487)	CONDITION:	Extensive significant problems i.e. under plough, collapse	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Two bowl barrows on Birdsall Wold, 850m east of Aldro Farm, Birdsall			
DESIGNATION:	Scheduled Monument (No. 20479)	CONDITION:	Extensive significant problems i.e. under plough, collapse	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Two bowl barrows on Birdsall Wold, between	en Birdsall Dale a	nd Vessey Pasture Dale, Birdsall	
DESIGNATION:	Scheduled Monument (No. 20477)	CONDITION:	Extensive significant problems i.e. under plough, collapse	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Hedon Howe tumulus, Burythorpe			
DESIGNATION:	Scheduled Monument (No. NY29)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988	
	Roman site south west of Kennythorpe, Burythorpe			
SITE NAME:	Roman site south west of Kennythorpe, Bu	ırythorpe		
	Roman site south west of Kennythorpe, Bu Scheduled Monument (No. NY1094)	rythorpe	Extensive significant problems i.e. under plough, collapse	
DESIGNATION:	, ,	· ·	Extensive significant problems i.e. under plough, collapse Declining	
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. NY1094)	CONDITION:	i.e. under plough, collapse	
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Scheduled Monument (No. NY1094)  Metal detecting	CONDITION:  TREND:  CONTACT:	i.e. under plough, collapse Declining Keith Emerick 01904 601988	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP:	Scheduled Monument (No. NY1094)  Metal detecting  Private	CONDITION:  TREND:  CONTACT:	i.e. under plough, collapse Declining Keith Emerick 01904 601988  Generally satisfactory	
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Scheduled Monument (No. NY1094)  Metal detecting Private  Bossall Hall: a quadrangular castle, Buttercr Scheduled Monument (No. 20525)	CONDITION:  TREND:  CONTACT:  rambe with Bossall	i.e. under plough, collapse Declining Keith Emerick 01904 601988	
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:	Scheduled Monument (No. NY1094)  Metal detecting Private  Bossall Hall: a quadrangular castle, Buttercr	CONDITION:  TREND:  CONTACT:  rambe with Bossall  CONDITION:	i.e. under plough, collapse Declining Keith Emerick 01904 601988  Generally satisfactory but with minor localised problem	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

SITE NAME:	Cawthorne medieval settlement remains 15	eval settlement remains 150m north east of West Cawthorne, Cropton			
DESIGNATION:	Scheduled Monument (No. 32632)	CONDITION:	Generally satisfactory but with minor localised problems		
PRINCIPAL VULNERABILITY:	Localised/limited stock erosion	TREND:	Stable		
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Round barrow 350m north west of Hen Fl	atts, Cropton			
DESIGNATION:	Scheduled Monument (No. 30148)	CONDITION:	Extensive significant problems i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Round barrow 550m north of High Nova F	arm, Cropton			
DESIGNATION:	Scheduled Monument (No. 28293)	CONDITION:	Extensive significant problems i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988		
CITE NAME.	Forton medicual cottlement and mosted	onastic grange Fa	ston		
SITE NAME:	Foston medieval settlement and moated m	onasuc grange, Fo			
DESIGNATION:	Scheduled Monument (No. 32641)	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY:	Localised/limited stock erosion	TREND:	Declining		
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Boythorpe settlement site, Foxholes				
DESIGNATION:	Scheduled Monument (No. NY 1144)	CONDITION:	Extensive significant problems i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Romano-British settlement, Foxholes				
DESIGNATION:	Scheduled Monument (No. NY1236)	CONDITION:	Extensive significant problems i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Settlement site at Butterwick, Foxholes				
DESIGNATION:	Scheduled Monument (No. NY1237)	CONDITION:	Extensive significant problems		
			i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Round barrow 250m ENE of High Baxtonh	owe, Fryton			
DESIGNATION:	Scheduled Monument (No. 26987)	CONDITION:	Extensive significant problems i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988		

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Round barrow 700yds (640m) north east	of Brompton Wold	Farm, Ganton	
DESIGNATION:	Scheduled Monument (No. NY811)	CONDITION:	Extensive significant problems i.e. under plough, collapse	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
DWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988	
TITE NAME:	Three round barrows north east of Ganton Wold Farm, Ganton			
DESIGNATION:	Scheduled Monument (No. NY805)	CONDITION:	Extensive significant problems i.e. under plough, collapse	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988	
TITE NAME:	Round barrow 450m south west of Coney Hill Farm, Gilling East			
DESIGNATION:	Scheduled Monument (No. 28223)	CONDITION:	Extensive significant problems i.e. under plough, collapse	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Round barrow 500m SSW of Coney Hill F	arm, Gilling East		
DESIGNATION:	Scheduled Monument (No. 28224)	CONDITION:	Extensive significant problems i.e. under plough, collapse	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Round barrow 530m NNW of Maidenswo	orth Farm, Grimsto	ne	
DESIGNATION:	Scheduled Monument (No. 28215)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Round barrow on Grimston Moor 350m north east of Black Gill Plantation, Grimstone			
DESIGNATION:	Scheduled Monument (No. 26964)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving	
OWNERSHIP:	Government or Agency	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Round barrow 300m north of Rye House	Farm, Helmsley		
DESIGNATION:	Scheduled Monument (No. 32709)	CONDITION:	Extensive significant problems i.e. under plough, collapse	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Round barrow 420m north of Rye House	Farm, Helmsley		
DESIGNATION:	Scheduled Monument (No. 32708)	CONDITION:	Extensive significant problems	
			i.e. under plough, collapse	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	East Heslerton Brow barrow group: a bow	vl barrow 1.1km ea	st of Manor Wold Farm, Heslerton		
DESIGNATION:	Scheduled Monument (No. 20559)	CONDITION:	Extensive significant problems i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
)WNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988		
ITE NAME:	East Heslerton Brow barrow group: a bowl barrow 1.3km east of Manor Wold Farm, Heslerton				
DESIGNATION:	Scheduled Monument (No. 20560)	CONDITION:	Extensive significant problems i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988		
ITE NAME:	East Heslerton Brow barrow group: a bow	vl barrow 750m eas	st of Manor Wold Farm, Heslerton		
DESIGNATION:	Scheduled Monument (No. 20562)	CONDITION:	Extensive significant problems i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	East Heslerton Brow barrow group: a long	g barrow 1000m ea	st of Manor Wold Farm, Heslerton		
DESIGNATION:	Scheduled Monument (No. 20561)	CONDITION:	Extensive significant problems i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Heslerton Brow barrow group: a bowl barrow 230m north east of Wold Barn, Heslerton				
	C				
DESIGNATION:	Scheduled Monument (No. 20564)	CONDITION:	Extensive significant problems i.e. under plough, collapse		
DESIGNATION: PRINCIPAL VULNERABILITY:	Arable ploughing	CONDITION: TREND:	Extensive significant problems i.e. under plough, collapse Declining		
PRINCIPAL VULNERABILITY:	·		i.e. under plough, collapse		
	Arable ploughing	TREND: CONTACT:	i.e. under plough, collapse Declining Keith Emerick 01904 601988		
PRINCIPAL VULNERABILITY: OWNERSHIP:	Arable ploughing Private	TREND: CONTACT:	i.e. under plough, collapse Declining Keith Emerick 01904 601988  vest of Wold Barn, Heslerton Extensive significant problems		
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:	Arable ploughing Private  Heslerton Brow barrow group: a bowl bar	TREND: CONTACT: Prow 250m north v	i.e. under plough, collapse Declining Keith Emerick 01904 601988  vest of Wold Barn, Heslerton		
PRINCIPAL VULNERABILITY:  DWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Arable ploughing Private  Heslerton Brow barrow group: a bowl bar Scheduled Monument (No. 20563)	TREND: CONTACT:  row 250m north v  CONDITION:	i.e. under plough, collapse Declining Keith Emerick 01904 601988  vest of Wold Barn, Heslerton Extensive significant problems i.e. under plough, collapse		
PRINCIPAL VULNERABILITY: OWNERSHIP: SITE NAME:	Arable ploughing Private  Heslerton Brow barrow group: a bowl bar Scheduled Monument (No. 20563)  Arable ploughing	TREND: CONTACT:  CONDITION:  TREND: CONTACT:	i.e. under plough, collapse Declining Keith Emerick 01904 601988  vest of Wold Barn, Heslerton Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988		
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Arable ploughing Private  Heslerton Brow barrow group: a bowl bar Scheduled Monument (No. 20563)  Arable ploughing Private	TREND: CONTACT:  CONDITION:  TREND: CONTACT:	i.e. under plough, collapse Declining Keith Emerick 01904 601988  vest of Wold Barn, Heslerton  Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988		
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Arable ploughing Private  Heslerton Brow barrow group: a bowl bar Scheduled Monument (No. 20563)  Arable ploughing Private  Heslerton Brow barrow group: three bow	TREND: CONTACT:  CONDITION: TREND: CONTACT:	i.e. under plough, collapse Declining Keith Emerick 01904 601988  Vest of Wold Barn, Heslerton Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988  Orth east of Wold Barn, Heslerton Extensive significant problems		
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:	Arable ploughing Private  Heslerton Brow barrow group: a bowl bar Scheduled Monument (No. 20563)  Arable ploughing Private  Heslerton Brow barrow group: three bow Scheduled Monument (No. 20565)	TREND: CONTACT:  CONDITION:  TREND: CONTACT:  I barrows 300m no	i.e. under plough, collapse Declining Keith Emerick 01904 601988  vest of Wold Barn, Heslerton Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988  orth east of Wold Barn, Heslerton Extensive significant problems i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  PRINCIPAL VULNERABILITY:	Arable ploughing Private  Heslerton Brow barrow group: a bowl bar Scheduled Monument (No. 20563)  Arable ploughing Private  Heslerton Brow barrow group: three bow Scheduled Monument (No. 20565)  Arable ploughing	TREND: CONTACT:  Trow 250m north v  CONDITION:  TREND: CONTACT:  I barrows 300m no  CONDITION:  TREND: CONTACT:	i.e. under plough, collapse Declining Keith Emerick 01904 601988  Vest of Wold Barn, Heslerton Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988  Orth east of Wold Barn, Heslerton Extensive significant problems i.e. under plough, collapse Declining		
PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  OWNERSHIP:  OWNERSHIP:	Arable ploughing Private  Heslerton Brow barrow group: a bowl bar Scheduled Monument (No. 20563)  Arable ploughing Private  Heslerton Brow barrow group: three bow Scheduled Monument (No. 20565)  Arable ploughing Private	TREND: CONTACT:  Trow 250m north v  CONDITION:  TREND: CONTACT:  I barrows 300m no  CONDITION:  TREND: CONTACT:	i.e. under plough, collapse Declining Keith Emerick 01904 601988  Vest of Wold Barn, Heslerton Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988  Orth east of Wold Barn, Heslerton Extensive significant problems i.e. under plough, collapse Declining		
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  OWNERSHIP:	Arable ploughing Private  Heslerton Brow barrow group: a bowl bar Scheduled Monument (No. 20563)  Arable ploughing Private  Heslerton Brow barrow group: three bow Scheduled Monument (No. 20565)  Arable ploughing Private  New Bield round barrow and ringwork, H	TREND: CONTACT:  TOW 250m north v  CONDITION:  TREND: CONTACT:  I barrows 300m no  CONDITION:  TREND: CONTACT:	i.e. under plough, collapse Declining Keith Emerick 01904 601988  Vest of Wold Barn, Heslerton Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988  Orth east of Wold Barn, Heslerton Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988  Extensive significant problems		

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Round barrow 100m north west of Moor	House Farm, Hovi	ngham
DESIGNATION:	Scheduled Monument (No. 26976)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 250m west of Calf Close \	Vood, Hovingham	
DESIGNATION:	Scheduled Monument (No. 26984)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 350m south west of Moor	House Farm, Hovi	ngham
DESIGNATION:	Scheduled Monument (No. 26977)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 400m ESE of Theaker Waster's Spring, Hovingham		
DESIGNATION:	Scheduled Monument (No. 26985)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 500m NNW of Moor Hou	se Farm, Hovingha	n
DESIGNATION:	Scheduled Monument (No. 26979)	CONDITION:	Generally satisfactory
	,		but with significant localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	but with significant localised problems  Declining
PRINCIPAL VULNERABILITY:	Forestry	TREND: CONTACT:	Declining Keith Emerick 01904 601988
PRINCIPAL VULNERABILITY: OWNERSHIP:	Forestry Private	TREND: CONTACT:	Declining Keith Emerick 01904 601988  Generally satisfactory
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:	Forestry Private  Round barrow 700m north of Moor House Scheduled Monument (No. 26978)	TREND: CONTACT:  e Farm, Hovinghan  CONDITION:	Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Forestry Private  Round barrow 700m north of Moor House Scheduled Monument (No. 26978)  Forestry	trend: contact:  e Farm, Hovinghan condition: trend:	Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Declining
PRINCIPAL VULNERABILITY:  DWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Forestry Private  Round barrow 700m north of Moor House Scheduled Monument (No. 26978)	TREND: CONTACT:  e Farm, Hovinghan  CONDITION:	Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY: OWNERSHIP: SITE NAME:	Forestry Private  Round barrow 700m north of Moor House Scheduled Monument (No. 26978)  Forestry	TREND: CONTACT:  e Farm, Hovinghan CONDITION: TREND: CONTACT:	Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Forestry Private  Round barrow 700m north of Moor House Scheduled Monument (No. 26978)  Forestry Private	TREND: CONTACT:  e Farm, Hovinghan CONDITION: TREND: CONTACT:	Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:	Forestry Private  Round barrow 700m north of Moor House Scheduled Monument (No. 26978)  Forestry Private  Medieval moated site 150m south east of	TREND: CONTACT:  e Farm, Hovinghan CONDITION: TREND: CONTACT:	Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Office, Huttons Ambo Generally satisfactory
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Forestry Private  Round barrow 700m north of Moor House Scheduled Monument (No. 26978)  Forestry Private  Medieval moated site 150m south east of Scheduled Monument (No. 28229)	TREND: CONTACT:  e Farm, Hovinghan CONDITION:  TREND: CONTACT:  Low Hutton Post (  CONDITION:	Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Office, Huttons Ambo Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  PRINCIPAL VULNERABILITY:	Forestry Private  Round barrow 700m north of Moor House Scheduled Monument (No. 26978)  Forestry Private  Medieval moated site 150m south east of Scheduled Monument (No. 28229)  Moderate stock erosion	TREND: CONTACT:  e Farm, Hovinghan CONDITION:  TREND: CONTACT:  Low Hutton Post (  CONDITION:  TREND: CONTACT:	Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Office, Huttons Ambo Generally satisfactory but with minor localised problems Improving Keith Emerick 01904 601988
PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  OWNERSHIP:  OWNERSHIP:	Forestry Private  Round barrow 700m north of Moor House Scheduled Monument (No. 26978)  Forestry Private  Medieval moated site 150m south east of Scheduled Monument (No. 28229)  Moderate stock erosion Private	TREND: CONTACT:  e Farm, Hovinghan CONDITION:  TREND: CONTACT:  Low Hutton Post (  CONDITION:  TREND: CONTACT:	Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Office, Huttons Ambo Generally satisfactory but with minor localised problems Improving Keith Emerick 01904 601988  High Barn, Kirby Grindalythe Extensive significant problems
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  OWNERSHIP:	Forestry Private  Round barrow 700m north of Moor House Scheduled Monument (No. 26978)  Forestry Private  Medieval moated site 150m south east of Scheduled Monument (No. 28229)  Moderate stock erosion Private  Two round barrows 1/2 mile (800m) north	TREND: CONTACT:  e Farm, Hovinghan CONDITION:  TREND: CONTACT:  Low Hutton Post (  CONDITION:  TREND: CONTACT:	Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Office, Huttons Ambo Generally satisfactory but with minor localised problems Improving Keith Emerick 01904 601988  High Barn, Kirby Grindalythe

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

	Moated site known as Vivers Hill Castle, 30	00m north east of	the parish church, Kirkbymoorside
DESIGNATION:	Scheduled Monument (No. 30103)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate stock erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Starfits round barrow, 450m north east of	Starfits House, Kir	kbymoorside
DESIGNATION:	Scheduled Monument (No. 30102)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Roman villa, Langton		
DESIGNATION:	Scheduled Monument (No. NY280)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Esh's round barrow: a long barrow and late	er bowl barrow 40	
DESIGNATION:	Scheduled Monument (No. 20558)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Long barrow 650m south east of Cross Th	orns Barn, Luttons	;
DESIGNATION:	Scheduled Monument (No. 20557)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 1/4 mile (400m) north west of Broom House, Luttons		
DESIGNATION:	Scheduled Monument (No. NY810)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Three bowl barrows 200m west of Belle Vi	ue Farm, Luttons	
DESIGNATION:	Scheduled Monument (No. 20583)	CONDITION:	Extensive significant problems
DESIGNATION.			i.e. under plough, collapse
		TREND:	Declining
	Arable ploughing		0
	Arable ploughing Private	CONTACT:	Keith Emerick 01904 601988
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:			0
OWNERSHIP: SITE NAME:	Private		Keith Emerick 01904 601988  Generally satisfactory
OWNERSHIP:	Private  Roman fort, Malton	CONTACT:	Keith Emerick 01904 601988

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Middleton Heights round barrow, Middleto	on	
DESIGNATION:	Scheduled Monument (No. NY792)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Black Howe round barrow, Newton		
DESIGNATION:	Scheduled Monument (No. 34413)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Beacon Hill ringwork siege castle and Roy	al Observer Corps	post, Pickering
DESIGNATION:	Scheduled Monument (No. 32662)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 140m west of Haugh Rigg,	Pickering	
DESIGNATION:	Scheduled Monument (No. 34811)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 280m south west of Haugh	Rigg, Pickering	
DESIGNATION:	Scheduled Monument (No. 34812)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 400m north east of Haugh Rigg, Pickering		
DESIGNATION:	Scheduled Monument (No. 34414)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 570m south of Saintoft Gra	ange, Pickering	
DESIGNATION:	Scheduled Monument (No. 34820)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 600m SSW of Saintoft Gra	nge, Pickering	
DESIGNATION:	Scheduled Monument (No. 34819)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Iron Age barrow cemetery, East Field, Rillin	ngton	
DESIGNATION:	Scheduled Monument (No. NY1117)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Moated site and ridge and furrow cultivation	on 230m south eas	st of Manor Farm, Scackleton
DESIGNATION:	Scheduled Monument (No. 28220)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate stock erosion	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow on Knapton Brow, Scampst	on	
DESIGNATION:	Scheduled Monument (No. NY801)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Part of Leppington medieval village, a moated site and site of the former parish	church of St Helen,	Scrayingham
DESIGNATION:	Scheduled Monument (No. 20542)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate vehicle damage/erosion	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 1/2 mile (800m) NNE of Se	ettrington House, S	Settrington
DESIGNATION:	Scheduled Monument (No. NY568)	CONDITION:	Extensive significant problems
DESIGNATION.	scheduled Fiorialiteite (F40.141300)	CONDITION.	i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 1/4 mile (400m) south west	t of Many Thorns F	arm, Settrington
DESIGNATION:	Scheduled Monument (No. NY569)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow north east of Lawson's Wol	d Barn, Sherburn	
DESIGNATION:	Scheduled Monument (No. NY812)	CONDITION:	Extensive significant problems
DDINICIDAL VIII A IED A DII IEG	Arable ploughing	TOENIS	i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Private	TREND: CONTACT:	Declining Keith Emerick 01904 601988
OWNERSHIP:	Tivate	CONTACT:	Neith Efficiency 01701 001700
SITE NAME:	Three round barrows south of Prodham's	Wold Farm, Sherbu	urn
DESIGNATION:	Scheduled Monument (No. NY813)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category
has changed since the 2009
register, the previous category
is given in brackets.

# ABBREVIATIONS

SITE NAME:	Aldro earthworks: a bowl barrow and par 500m north west of Brown Moor Farm, T		n Birdsall Wold,
DESIGNATION:	Scheduled Monument (No. 20493)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Aldro earthworks: a bowl barrow on Bird	sall Wold, 500m no	rth west of Brown Moor Farm, Thixendal
DESIGNATION:	Scheduled Monument (No. 20494)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Aldro earthworks: a bowl barrow on Han, 400m north west of Stone Sleights Farm,		d
DESIGNATION:	Scheduled Monument (No. 20503)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Aldro earthworks: a cross-dyke on Birdsal	ll Wold, 200m west	of Brown Moor Farm,Thixendale
DESIGNATION:	Scheduled Monument (No. 20496)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Barrow near Middle Plantation, Thixendale	·	
DESIGNATION:	Scheduled Monument (No. NY510)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Barrow west of Bradeham Farm, Thixenda	le	
DESIGNATION:	Scheduled Monument (No. NY509)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Hanging Grimston barrow group: a bowl b	parrow 200m west	of Wold Farm,Thixendale
DESIGNATION:	Scheduled Monument (No. 20567)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Hanging Grimston barrow group: a bowl b	parrow 300m east o	of Stone Sleights Farm,Thixendale
DESIGNATION:	Scheduled Monument (No. 20572)	CONDITION:	Extensive significant problems i.e. under plough, collapse
			, 0
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Grimston barrow group: a bowl b	parrow 400m south	west of Wold Farm, Thixendale
d Monument (No. 20566)	CONDITION:	Extensive significant problems
		i.e. under plough, collapse
loughing	TREND:	Declining
	CONTACT:	Keith Emerick 01904 601988
Grimston barrow group: a bowl b	parrow 450m north	east of Wold Farm, Thixendale
d Monument (No. 20571)	CONDITION:	Extensive significant problems i.e. under plough, collapse
loughing	TREND:	Declining
	CONTACT:	Keith Emerick 01904 601988
Grimston barrow group: a bowl b	parrow 650m south	west of Thixendale Grange, Thixendale
d Monument (No. 20573)	CONDITION:	Extensive significant problems i.e. under plough, collapse
loughing	TREND:	Declining
- 5	CONTACT:	Keith Emerick 01904 601988
0 1		
d Monument (No. 20569)	CONDITION:	Extensive significant problems i.e. under plough, collapse
loughing	TREND:	Declining
	CONTACT:	Keith Emerick 01904 601988
		t of a cross dyke
d Monument (No. 20575)	CONDITION:	Extensive significant problems i.e. under plough, collapse
loughing	TREND:	Declining
	CONTACT:	Keith Emerick 01904 601988
Grimston barrow group: four bov	wl barrows on Uncl	eby Stoop, Thixendale
d Monument (No. 20579)	CONDITION:	Extensive significant problems i.e. under plough, collapse
loughing	TREND:	Declining
	CONTACT:	Keith Emerick 01904 601988
Grimston barrow group: three bo		Keith Emerick 01904 601988  north east of Wold Farm, Thixendale
Grimston barrow group: three bo		
	owl barrows 350m i	north east of Wold Farm, Thixendale Extensive significant problems
d Monument (No. 20570)	owl barrows 350m i	north east of Wold Farm, Thixendale  Extensive significant problems i.e. under plough, collapse
d Monument (No. 20570) loughing	condition:  TREND:  CONTACT:	north east of Wold Farm, Thixendale  Extensive significant problems i.e. under plough, collapse  Declining
d Monument (No. 20570) loughing	condition:  TREND:  CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988
d Monument (No. 20570) loughing Grimston barrow group: three bo	condition:  TREND:  CONTACT:  owl barrows 600m s	north east of Wold Farm, Thixendale  Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988  south west of Thixendale Grange, Thixend Extensive significant problems
	d Monument (No. 20571)  loughing  Grimston barrow group: a bowl by the description of the	Grimston barrow group: a bowl barrow 450m north d Monument (No. 20571)  CONDITION:  CONDITION:  CONTACT:  Grimston barrow group: a bowl barrow 650m south d Monument (No. 20573)  CONDITION:  CONTACT:  Grimston barrow group: a long barrow 400m east of ating part of a prehistoric linear boundary, Thixendal d Monument (No. 20569)  CONTACT:  CONTACT:  Grimston barrow group: four bowl barrows and part W of Thixendale Grange, Thixendale  d Monument (No. 20575)  CONDITION:  CONTACT:  CONTACT:  CONTACT:  CONTACT:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Round barrow north of manor house, This	kendale	
DESIGNATION:	Scheduled Monument (No. NY749)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow south east of Gill's Farm,Th	nixendale	
DESIGNATION:	Scheduled Monument (No. NY748)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrows south of Gill's Farm, Thixe	ndale	
DESIGNATION:	Scheduled Monument (No. NY642)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrows south west of Riggs Farm,	Thixendale	
DESIGNATION:	Scheduled Monument (No. NY643)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	The Queen Dike: part of a cross-dyke 600	m east of Wold Fa	rm, Thixendale
DESIGNATION:	Scheduled Monument (No. 20582)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow east of Weaverthorpe Ling, Weaverthorpe		
DESIGNATION:	Scheduled Monument (No. NY825)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow north west of Mount Spani	el,Weaverthorpe	
DESIGNATION:	Scheduled Monument (No. NY823)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Section of linear earthwork in Pasture Plan	ntation,Weavertho	rpe
	Scheduled Monument (No. 23831)	CONDITION:	Generally unsatisfactory
DESIGNATION:	scriedaled Florialiteit (Fto: 23031)		with major localised problems
DESIGNATION: PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	·

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Two round barrows on Weaverthorpe Pass	ture, Weaverthorpe	2	
DESIGNATION:	Scheduled Monument (No. NY824)	CONDITION:	Extensive significant problems i.e. under plough, collapse	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Two round barrows south east of Pasture Farm, Weaverthorpe			
DESIGNATION:	Scheduled Monument (No. NY579)	CONDITION:	Extensive significant problems i.e. under plough, collapse	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Round barrows on Wharram Percy Wold, V	Wharram		
DESIGNATION:	Scheduled Monument (No. NY745)	CONDITION:	Extensive significant problems i.e. under plough, collapse	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Bowl barrow 1100m west of High Fordon	Farm, Willerby		
DESIGNATION:	Scheduled Monument (No. 21248)	CONDITION:	Extensive significant problems i.e. under plough, collapse	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Bowl barrow 700m north west of High Fordon Farm, Willerby			
DESIGNATION:	Scheduled Monument (No. 21249)	CONDITION:	Extensive significant problems i.e. under plough, collapse	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Bowl barrow 800m west of High Fordon Farm, Willerby			
DESIGNATION:	Scheduled Monument (No. 21247)	CONDITION:	Extensive significant problems i.e. under plough, collapse	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Prior Moor round barrow, Willerby			
DESIGNATION:	Scheduled Monument (No. NY787)	CONDITION:	Extensive significant problems i.e. under plough, collapse	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Round barrow south east of Willerby Wol	d House,Willerby		
DESIGNATION:	Scheduled Monument (No. NY807)	CONDITION:	Extensive significant problems i.e. under plough, collapse	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
	1 0 0		Keith Emerick 01904 601988	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Round barrow west of Willerby Wold Hou	ıse,Willerby	
DESIGNATION:	Scheduled Monument (No. NY788)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Two round barrows north east of Ganton	Dale, Willerby	
DESIGNATION:	Scheduled Monument (No. NY806)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Two round barrows, Staxton Brow, Willerb	ру	
DESIGNATION:	Scheduled Monument (No. NY814)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Wilton Hall moated site 250m south of M	anor Farm,Wilton	
DESIGNATION:	Scheduled Monument (No. 35565)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 1/4 mile (400m) south east	of Newton South	Wold Farm, Wintringham
DESIGNATION:	Scheduled Monument (No. NY575)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 330yds (300m) NNW of La	adyhills,Wintringha	ım
DESIGNATION:	Scheduled Monument (No. NY554)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow north east of Wintringham	South Wold Farm,	Wintringham
DESIGNATION:	Scheduled Monument (No. NY573)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow west of Newlands Lane, Wi	intringham	
DESIGNATION:	Scheduled Monument (No. NY809)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
CNA/NIEDEL IID.	Private	CONTACT:	Keith Emerick 01904 601988
OWNERSHIP:			

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Three round barrows on West Heslerton Wold,	Wintringham	
DESIGNATION:	Scheduled Monument (No. NY803)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988



SITE NAME:	${\bf Ebberston\ Hall, Ebberston\ and\ Yedingham}$
DESIGNATION:	Registered Park and Garden Grade II*, also 5 LBs, 2 SMs
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY	:Low
TREND:	Declining
OWN IEBSHIP	Private single owner

Gardens with water features c1718 integral to the design of Ebberston Hall and views of the wider landscape from it. Stepped cascade water features (listed grade II\*) in need of consolidation and repair, trees in parkland to south over-mature.



SITE NAME:	Castle Howard, Henderskelfe
DESIGNATION:	Registered Park and Garden Grade I, also 65 LBs, 2 SMs
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY	:Low
TREND:	Declining
OWNERSHIP:	Private, single owner

Gardens, pleasure grounds and park with a mixture of geometric and less formal features developed c1698-1738 by Charles Howard, third Earl of Carlisle and Sir John Vanbrugh (1664-1726) possibly with some advice from Stephen Switzer (1682-1745). Key buildings and structures in the landscape are in need of consolidation and repair; sections of the grand approach avenues have over-mature trees in need of replacement.

Contact: Andy Wimble 01904 601970

Contact: Andy Wimble 01904 601970

#### RYEDALE / HAMBLETON




SITE NAME:	Gilling Castle, Gilling East
DESIGNATION:	Registered Park and Garden Grade II,
	also 3 LBs, I SM
CONDITION:	Generally satisfactory
	but with significant localised problems
VULNERABILITY:	Medium
TREND:	Unknown

Corporate, single owner

The castle a C14 tower house, park with medieval origins, and gardens probably of the early C18 possibly with earlier origins. Now owned by Ampleforth College. Significant parts of the parkland lie under forestry and include fishponds in need of conservation and repair works. English Heritage is working with key stakeholders to commission a Conservation Management Plan. Part of the park is also in the district of Hambleton.

Contact: Andy Wimble 01904 601970

#### **SCARBOROUGH**



SITE NAME:

SITE NAME: Wykeham Priory, Back Lane, Wykeham

DESIGNATION: Listed Building Grade II, SM

condition: Poor

OWNERSHIP:

occupancy: Not applicable

D(D) PRIORITY:

ownership: Private

C12 Cistercian priory. Little remains of the priory except some sections of walling, part of the old parish church and a transplanted moorland cross. It is situated in the private grounds of a large country house.

Contact: Neil Redfern 01904 601897

# Bowl barrow 700m north of Betton Farm, East Ayton

DESIGNATION:	Scheduled Monument (No. 23806)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988

Bowl barrow 920m north of Betton Farm, East Ayton SITE NAME

DESIGNATION:	Scheduled Monument (No. 23807)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# NOTE: If the priority category has changed since the 2009 register, the previous category is given in brackets.

# ABBREVIATIONS

CA LB/LBs Conservation Area Conservation Area Listed Building/s National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site NIP RPG SM/SMs UA WHS

SITE NAME:	Bowl barrow 950m north of Betton Farm, East	Ayton	
DESIGNATION:	Scheduled Monument (No. 23808)	CONDITION:	Extensive significant problems
	Amble plaughing	TDE 15	i.e. under plough, collapse Declining
PRINCIPAL VULNERABILITY:	Arable ploughing Private	TREND:	Keith Emerick 01904 601988
OWNERSHIP:	Titvate	CONTACT:	Reith Linerick 01704 001700
SITE NAME:	Roman signal station, Carr Naze, Filey		
DESIGNATION:	Scheduled Monument (No. NY478)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Elf Howe round barrow, Folkton		
DESIGNATION:	Scheduled Monument (No. NY815)	CONDITION:	Extensive significant problems
	,		i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow on Flixton Wold, Folkton		
DESIGNATION:	Scheduled Monument (No. NY808)	CONDITION:	Extensive significant problems
	(		i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow on Flotmanby Brow, Folkton		
DESIGNATION:	Scheduled Monument (No. NY822)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow on Flotmanby Wold, Folkton		
DESIGNATION:	Scheduled Monument (No. NY821)	CONDITION:	Extensive significant problems
	(10.11.02.)		i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow south of Long Plantation, Folkto	on	
DESIGNATION:	Scheduled Monument (No. NY818)	CONDITION:	Extensive significant problems
DESIGNATION.	scheduled Floridificate (110.11110)	CONDITION:	i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Sharpe Howes, round barrows, Folkton		
DESIGNATION:	Scheduled Monument (No. NY405)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
	Private	CONTACT:	Keith Emerick 01904 601988

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

SITE NAME:	Two round barrows north west of Danebu	ry Manor, Folkton	
DESIGNATION:	Scheduled Monument (No. NY816)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Group of circular and rectangular enclosur	es, near Cansdale	Whin, Hunmanby
DESIGNATION:	Scheduled Monument (No. NYI 177)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow south of Grange Farm, Hun	manby	
DESIGNATION:	Scheduled Monument (No. NY817)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 60m west of Beacon Farm,	Irton	
DESIGNATION:	Scheduled Monument (No. 21064)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
	, a doic cupping	HILLIND.	2 3000 00 76
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
OWNERSHIP: SITE NAME:	Bowl barrow 450m north east of Moor Ho	ouse Farm, Scarboi	rough
OWNERSHIP: SITE NAME:			rough Generally unsatisfactory
OWNERSHIP: SITE NAME: DESIGNATION:	Bowl barrow 450m north east of Moor Ho Scheduled Monument (No. 23839)	ouse Farm, Scarboi	rough  Generally unsatisfactory  with major localised problems
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Bowl barrow 450m north east of Moor Ho	ouse Farm, Scarboi	rough Generally unsatisfactory
OWNERSHIP:	Bowl barrow 450m north east of Moor Ho Scheduled Monument (No. 23839) Arable ploughing	condition:  trend:  contact:	Generally unsatisfactory with major localised problems Unknown Keith Emerick 01904 601988
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Bowl barrow 450m north east of Moor Ho Scheduled Monument (No. 23839)  Arable ploughing Private  Bowl barrow 600m north of Moor House	condition:  TREND:  CONTACT:  Farm, Scarborough	Generally unsatisfactory with major localised problems Unknown Keith Emerick 01904 601988
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Bowl barrow 450m north east of Moor Ho Scheduled Monument (No. 23839) Arable ploughing Private	condition:  trend:  contact:	Generally unsatisfactory with major localised problems Unknown Keith Emerick 01904 601988  Generally unsatisfactory
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:	Bowl barrow 450m north east of Moor Ho Scheduled Monument (No. 23839)  Arable ploughing Private  Bowl barrow 600m north of Moor House	condition:  TREND:  CONTACT:  Farm, Scarborough	Generally unsatisfactory with major localised problems Unknown Keith Emerick 01904 601988
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Bowl barrow 450m north east of Moor Ho Scheduled Monument (No. 23839)  Arable ploughing Private  Bowl barrow 600m north of Moor House Scheduled Monument (No. 23838)	condition:  TREND: CONTACT:  Farm, Scarborough	Generally unsatisfactory with major localised problems Unknown Keith Emerick 01904 601988  Generally unsatisfactory with major localised problems
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Bowl barrow 450m north east of Moor Ho Scheduled Monument (No. 23839)  Arable ploughing Private  Bowl barrow 600m north of Moor House Scheduled Monument (No. 23838)  Arable ploughing	condition:  TREND: CONTACT:  Farm, Scarborough  CONDITION:  TREND: CONTACT:	Generally unsatisfactory with major localised problems Unknown Keith Emerick 01904 601988  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Bowl barrow 450m north east of Moor Ho Scheduled Monument (No. 23839)  Arable ploughing Private  Bowl barrow 600m north of Moor House Scheduled Monument (No. 23838)  Arable ploughing Private	condition:  TREND: CONTACT:  Farm, Scarborough  CONDITION:  TREND: CONTACT:	Generally unsatisfactory with major localised problems Unknown Keith Emerick 01904 601988  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  SITE NAME:  DESIGNATION:	Bowl barrow 450m north east of Moor Ho Scheduled Monument (No. 23839)  Arable ploughing Private  Bowl barrow 600m north of Moor House Scheduled Monument (No. 23838)  Arable ploughing Private  Round barrow 460m south of Oliver's Mou	CONDITION:  TREND: CONTACT:  Farm, Scarborough  CONDITION:  TREND: CONTACT:	Generally unsatisfactory with major localised problems Unknown Keith Emerick 01904 601988  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Dugh Extensive significant problems
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Bowl barrow 450m north east of Moor Ho Scheduled Monument (No. 23839)  Arable ploughing Private  Bowl barrow 600m north of Moor House Scheduled Monument (No. 23838)  Arable ploughing Private  Round barrow 460m south of Oliver's Mou Scheduled Monument (No. 35449)	CONDITION:  TREND: CONTACT:  Farm, Scarborough  CONDITION:  TREND: CONTACT:  CONTACT:  LINE FARM, Scarborough  CONDITION:  CONTACT:  CONDITION:	Generally unsatisfactory with major localised problems Unknown Keith Emerick 01904 601988  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  bugh  Extensive significant problems i.e. under plough, collapse
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  OWNERSHIP:  OWNERSHIP:	Bowl barrow 450m north east of Moor Ho Scheduled Monument (No. 23839)  Arable ploughing Private  Bowl barrow 600m north of Moor House Scheduled Monument (No. 23838)  Arable ploughing Private  Round barrow 460m south of Oliver's Mou Scheduled Monument (No. 35449)  Arable ploughing	condition:  TREND: CONTACT:  Farm, Scarborough  CONTACT:  TREND: CONTACT:  LINT Farm, Scarboro  CONDITION:  TREND: CONTACT:	Generally unsatisfactory with major localised problems Unknown Keith Emerick 01904 601988  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Dugh Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  SITE NAME:	Bowl barrow 450m north east of Moor Ho Scheduled Monument (No. 23839)  Arable ploughing Private  Bowl barrow 600m north of Moor House Scheduled Monument (No. 23838)  Arable ploughing Private  Round barrow 460m south of Oliver's Mou Scheduled Monument (No. 35449)  Arable ploughing Private	condition:  TREND: CONTACT:  Farm, Scarborough  CONTACT:  TREND: CONTACT:  LINT Farm, Scarboro  CONDITION:  TREND: CONTACT:	Generally unsatisfactory with major localised problems Unknown Keith Emerick 01904 601988  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Dugh Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  PRINCIPAL VULNERABILITY:	Bowl barrow 450m north east of Moor Ho Scheduled Monument (No. 23839)  Arable ploughing Private  Bowl barrow 600m north of Moor House Scheduled Monument (No. 23838)  Arable ploughing Private  Round barrow 460m south of Oliver's Mou Scheduled Monument (No. 35449)  Arable ploughing Private  Section of linear earthwork on Seamer Mo	CONDITION:  TREND: CONTACT:  Farm, Scarborough  CONDITION:  TREND: CONTACT:  Unt Farm, Scarboro  CONDITION:  TREND: CONTACT:  TREND: CONTACT:	Generally unsatisfactory with major localised problems Unknown Keith Emerick 01904 601988  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Extensive significant problems i.e. under plough, collapse Declining Keith Emerick 01904 601988

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Three barrows at Seamer Beacon and the	ruins of Baron Alb	ert's Tower, Scarborough
DESIGNATION:	Scheduled Monument (No. 21069)	CONDITION:	Generally satisfactory
			but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Bowl barrow 150m north of Moor House	Farm, Seamer	
DESIGNATION:	Scheduled Monument (No. 23833)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Bowl barrow 450m north west of Moor H	House Farm, Seame	r
DESIGNATION:	Scheduled Monument (No. 24463)	CONDITION:	Extensive significant problems
	,		i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Bowl barrow 550m NNW of Moor House	e Farm, Seamer	
DESIGNATION:	Scheduled Monument (No. 23836)	CONDITION:	Extensive significant problems
DESIGN (TION)	Scheduled Floridifient (Fto: 25050)	CONDITION.	i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
	D 11 000 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
SITE NAME:	Bowl barrow 800m north west of Moor F	nouse rarm, seame	
DESIGNATION:	Scheduled Monument (No. 23837)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Cayton		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating

#### **SELBY**



SITE NAME:

Chapel to Huddleston Hall (now barn), Chapel with C15 origins, C16 rebuilding west of house, Laith Staid Lane, Huddleston with Newthorpe

to the east and later alterations.

DESIGNATION: Listed Building Grade II\*

condition: Fair

occupancy: Part occupied

C(C)PRIORITY:

Private OWNERSHIP:

Contact: Neil Redfern 01904 601897



SITE NAME:

Huddleston Hall, Laith Staid Lane,

Huddleston with Newthorpe

DESIGNATION: Listed Building Grade II\*

condition: Fair

Part occupied OCCUPANCY:

PRIORITY: C(C)

OWNERSHIP: Private

Late C16 manor house, now used as a farmhouse. A full repairs programme has been prepared but work has not yet been carried out.

Contact: Neil Redfern 01904 601897

# PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE:

If the priority category has changed since the 2009 register, the previous category is given in brackets.

#### **ABBREVIATIONS**



Stables to Huddleston Hall, SITE NAME:

south east of house, Laith Staid Lane, Huddleston with Newthorpe

DESIGNATION: Listed Building Grade II\*

condition: Fair

occupancy: Part occupied PRIORITY: C(C)

OWNERSHIP: Private Stables of the late C16 with C19 additions and alterations.

Contact: Neil Redfern 01904 601897



Abbot's Staith Buildings, SITE NAME:

Water Lane, Selby

DESIGNATION: Listed Building Grade II\*, SM, CA

Poor CONDITION:

occupancy: Part occupied

C(C)PRIORITY:

OWNERSHIP: Company C15 or early C16, two storey, 'H' shaped plan warehouse built for Selby Abbey. Mainly of magnesium limestone ashlar with some brick. The roof is modern, the building is in poor condition and the roof is deteriorating.

Contact: Keith Emerick 01904 601988

SITE NAME:	St Andrew's College and moat, 440m north east of College Farm, Acaster Selby			
DESIGNATION:	Scheduled Monument (No. 30110)	CONDITION:	Generally satisfactory	
			but with minor localised problems	
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Stable	
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Brocket Hall moated site, Appleton Roebu	ick		
DESIGNATION:	Scheduled Monument (No. 20522)	CONDITION:	Generally satisfactory	
			but with minor localised problems	
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining	
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Mote Hill: a moated site, two fishponds an 500m west of Nun Appleton Hall, Appleto	'	ent field system	
DESIGNATION:	Scheduled Monument (No. 20521)	CONDITION:	Generally satisfactory	
			but with significant localised problems	
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Unknown	
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Parkshaw moated site, 170m north west o	of Wood Farm, Baln	e	
DESIGNATION:	Scheduled Monument (No. 30107)	CONDITION:	Generally satisfactory	
	,		but with significant localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Catterton Hall moated site and adjacent b	ouilding platform, C	atterton	
DESIGNATION:	Scheduled Monument (No. 30109)	CONDITION:	Generally satisfactory	
DESIGNATION.	Scheduled Fromatheric (Feb. 50107)	CONDITION.	but with significant localised problems	
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining	
OWNERSHIP:	Private Private	CONTACT:	Keith Emerick 01904 601988	
OWNERSHIII.	· · · · · · · ·	CONTACT.	Telar Emerick 61701 661766	
SITE NAME:	Castle Hill moated site, 350m south of St	Peter and St Paul's	Church, Drax	
DESIGNATION:	Scheduled Monument (No. 30108)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Stable	

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Claracteristics

  C Claracteristics

  C Claracteristics

  C Claracteristics

  C Claracteristics

  C Claracteristics
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.
- NOTE: If the priority category has changed since the 2009 register, the previous category is given in brackets.

#### **ABBREVIATIONS**

SITE NAME:	Scurff Hall moated site, Drax		
DESIGNATION:	Scheduled Monument (No. 30117)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	No known threat	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Kelfield moated site and fishpond, 180m n	orth of Kelfield Ch	
DESIGNATION:	Scheduled Monument (No. 30112)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Toulston medieval village, manor house sit	e and early garden	earthworks, Newton Kyme cum Toulston
DESIGNATION:	Scheduled Monument (No. 30122)	CONDITION:	Generally satisfactory
	,		but with minor localised problems
PRINCIPAL VULNERABILITY:	Permitted development	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Two Roman forts, two Roman camps, vicu monument west of Newton Kyme, Newto		re, Bronze Age barrows and Neolithic hengton
DESIGNATION:	Scheduled Monument (No. 26907)	CONDITION:	Extensive significant problems
	A 11 1 1 1		i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing Private	TREND:	Declining Keith Emerick 01904 601988
OWNERSHIP:	Tilvate	CONTACT:	Retti Effect 01701 001700
SITE NAME:	Danes Hills square barrow cemetery, 300	n south of Adamso	n Farm, Riccall
DESIGNATION:	Scheduled Monument (No. 30179)	CONDITION:	Generally unsatisfactory
	DI ( )		with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth Private	TREND:	Stable Keith Emerick 01904 601988
OWNERSHIP:	rnvate	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	York prebendary manor moated site, 300r	n north west of Ha	awthorn Farm, Riccall
DESIGNATION:	Scheduled Monument (No. 30121)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Stable
DWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Paradise Lodge moated site and grange of	the Prior of Bolton	n, Ryther cum Ossendyke
DESIGNATION:	Scheduled Monument (No. 20517)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Thorpe Hall moated monastic grange, Selb	ру	
DESIGNATION:	Scheduled Monument (No. 30113)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Unknown
PRINCIPAL VULNERABILITY:  OWNERSHIP:	Drainage/dewatering Private	TREND: CONTACT:	Unknown Keith Emerick 01904 601988

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

ABBREVIATIONS CA LB/LBs NP RPG SM/SMs UA WHS

SITE NAME:	Danes Hills square barrow cemetery on C	Crook Moor, Skipwi	th
DESIGNATION:	Scheduled Monument (No. 30176)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Moated site and fishpond 140m south of S	St Helen's Church,	Skipwith
DESIGNATION:	Scheduled Monument (No. 28250)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
ITE NAME:	Round barrow on Skipwith Common, 800	m south east of Ad	amson Farm, Skipwith
DESIGNATION:	Scheduled Monument (No. 30180)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow on Skipwith Common, 810	m south of Skipwit	h Church, Skipwith
DESIGNATION:	Scheduled Monument (No. 30177)	CONDITION:	Generally unsatisfactory
			with major localised problems
RINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
	D ' (		=
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
OWNERSHIP: SITE NAME:	Round barrow on Skipwith Common, 830		
SITE NAME:			amson Farm, Skipwith  Generally unsatisfactory
site name: Designation:	Round barrow on Skipwith Common, 830 Scheduled Monument (No. 30181)	m south east of Ad	amson Farm, Skipwith  Generally unsatisfactory  with major localised problems
DESIGNATION: PRINCIPAL VULNERABILITY:	Round barrow on Skipwith Common, 830	m south east of Ad	amson Farm, Skipwith  Generally unsatisfactory
DESIGNATION: PRINCIPAL VULNERABILITY:	Round barrow on Skipwith Common, 830 Scheduled Monument (No. 30181) Plant growth	m south east of Ad CONDITION: TREND:	amson Farm, Skipwith  Generally unsatisfactory with major localised problems Declining
	Round barrow on Skipwith Common, 830 Scheduled Monument (No. 30181) Plant growth	m south east of Ad CONDITION: TREND: CONTACT:	Amson Farm, Skipwith  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  SITE NAME:	Round barrow on Skipwith Common, 830 Scheduled Monument (No. 30181)  Plant growth Private	m south east of Ad CONDITION: TREND: CONTACT:	amson Farm, Skipwith  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Tee, South Milford Generally satisfactory
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  SITE NAME:	Round barrow on Skipwith Common, 830 Scheduled Monument (No. 30181)  Plant growth Private  Steeton Hall medieval magnate's residence Scheduled Monument (No. 28240)	m south east of Ad  CONDITION:  TREND:  CONTACT:	amson Farm, Skipwith  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Tre, South Milford  Generally satisfactory but with significant localised problems
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  SITE NAME:  DESIGNATION:	Round barrow on Skipwith Common, 830  Scheduled Monument (No. 30181)  Plant growth Private  Steeton Hall medieval magnate's residence Scheduled Monument (No. 28240)  Permitted development	m south east of Ad  CONDITION:  TREND:  CONTACT:	lamson Farm, Skipwith  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Tre, South Milford  Generally satisfactory but with significant localised problems Declining
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Round barrow on Skipwith Common, 830 Scheduled Monument (No. 30181)  Plant growth Private  Steeton Hall medieval magnate's residence Scheduled Monument (No. 28240)	m south east of Ad  CONDITION:  TREND:  CONTACT:  and manorial cent  CONDITION:	amson Farm, Skipwith  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Tre, South Milford  Generally satisfactory but with significant localised problems
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Round barrow on Skipwith Common, 830  Scheduled Monument (No. 30181)  Plant growth Private  Steeton Hall medieval magnate's residence Scheduled Monument (No. 28240)  Permitted development	m south east of Ad  CONDITION:  TREND:  CONTACT:  cand manorial cent  CONDITION:  TREND:  CONTACT:	lamson Farm, Skipwith  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Tre, South Milford  Generally satisfactory but with significant localised problems Declining
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DWNERSHIP:	Round barrow on Skipwith Common, 830 Scheduled Monument (No. 30181)  Plant growth Private  Steeton Hall medieval magnate's residence Scheduled Monument (No. 28240)  Permitted development Private  Steeton medieval village, moated site and form	m south east of Ad  CONDITION:  TREND:  CONTACT:  cand manorial cent  CONDITION:  TREND:  CONTACT:	amson Farm, Skipwith  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Tre, South Milford  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  DWNERSHIP:	Round barrow on Skipwith Common, 830  Scheduled Monument (No. 30181)  Plant growth Private  Steeton Hall medieval magnate's residence Scheduled Monument (No. 28240)  Permitted development Private	m south east of Ad  CONDITION:  TREND: CONTACT:  cand manorial cent CONDITION:  TREND: CONTACT:	amson Farm, Skipwith  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Tre, South Milford  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Generally satisfactory
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Round barrow on Skipwith Common, 830 Scheduled Monument (No. 30181)  Plant growth Private  Steeton Hall medieval magnate's residence Scheduled Monument (No. 28240)  Permitted development Private  Steeton medieval village, moated site and form	m south east of Ad  CONDITION:  TREND: CONTACT:  cand manorial cent CONDITION:  TREND: CONTACT:	amson Farm, Skipwith  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Tre, South Milford  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Generally satisfactory
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  OWNERSHIP:  SITE NAME:  DESIGNATION:  SITE NAME:  DESIGNATION:  SITE NAME:  DESIGNATION:	Round barrow on Skipwith Common, 830  Scheduled Monument (No. 30181)  Plant growth Private  Steeton Hall medieval magnate's residence Scheduled Monument (No. 28240)  Permitted development Private  Steeton medieval village, moated site and steep scheduled Monument (No. 30123)	m south east of Ad  CONDITION:  TREND: CONTACT:  e and manorial cent  CONDITION:  TREND: CONTACT:	amson Farm, Skipwith  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Tre, South Milford  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:	Round barrow on Skipwith Common, 830  Scheduled Monument (No. 30181)  Plant growth Private  Steeton Hall medieval magnate's residence Scheduled Monument (No. 28240)  Permitted development Private  Steeton medieval village, moated site and some scheduled Monument (No. 30123)  Arable ploughing	m south east of Ad  CONDITION:  TREND: CONTACT:  and manorial cent  CONDITION:  TREND: CONTACT:  fishponds, Steeton  CONDITION:  TREND: CONTACT:	amson Farm, Skipwith  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Tre, South Milford  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Keith Emerick 01904 601988
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:	Round barrow on Skipwith Common, 830  Scheduled Monument (No. 30181)  Plant growth Private  Steeton Hall medieval magnate's residence Scheduled Monument (No. 28240)  Permitted development Private  Steeton medieval village, moated site and scheduled Monument (No. 30123)  Arable ploughing Private	m south east of Ad  CONDITION:  TREND: CONTACT:  and manorial cent  CONDITION:  TREND: CONTACT:  fishponds, Steeton  CONDITION:  TREND: CONTACT:	amson Farm, Skipwith  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Tre, South Milford  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Keith Emerick 01904 601988
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Round barrow on Skipwith Common, 830 Scheduled Monument (No. 30181)  Plant growth Private  Steeton Hall medieval magnate's residence Scheduled Monument (No. 28240)  Permitted development Private  Steeton medieval village, moated site and steep site of the steep si	m south east of Ad  CONDITION:  TREND: CONTACT:  e and manorial cent  CONDITION:  TREND: CONTACT:  fishponds, Steeton  CONDITION:  TREND: CONTACT:  te, 600m north we	amson Farm, Skipwith  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Tre, South Milford  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  st of Fulham House, Whitley
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Round barrow on Skipwith Common, 830 Scheduled Monument (No. 30181)  Plant growth Private  Steeton Hall medieval magnate's residence Scheduled Monument (No. 28240)  Permitted development Private  Steeton medieval village, moated site and steep site of the steep si	m south east of Ad  CONDITION:  TREND: CONTACT:  e and manorial cent  CONDITION:  TREND: CONTACT:  fishponds, Steeton  CONDITION:  TREND: CONTACT:  te, 600m north we	amson Farm, Skipwith  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Tre, South Milford  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  st of Fulham House, Whitley Generally satisfactory

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

OWNERSHIP-



Battle of Towton, SITE NAME: Lead / Saxton with

Scarthingwell / Towton

DESIGNATION: Registered Battlefield Declining TREND: Private

High, bleak, arable land near Tadcaster was the scene of a ten-hour battle in March 1461 during the Wars of the Roses. 28,000 were said to have been killed. Still actively farmed and under the plough, the below-ground battlefield archaeology – artefacts and arrowheads from the battle has been consistently targeted by metal detectorists, some unauthorised and working independently of any agreed archaeological survey. At least one episode of deep ploughing may have disturbed a possible mass grave.

Contact: Susan Daniels 01904 601 979

#### YORKSHIRE DALES (NP)



Barden Church, B6160, Barden,

Craven

DESIGNATION: Listed Building Grade I

CONDITION: Fair Vacant OCCUPANCY: C(C)PRIORITY: Private OWNERSHIP:

C16 chapel. The interior is derelict but the chapel has been re-roofed. Although the church building itself is not scheduled, the ground beneath it, and much of the surrounding manorial complex is.

Contact: Diane Green 01904 601973



Lead cupola, SITE NAME: flue and chimney, Grassington, Craven

**DESIGNATION: Scheduled Monument** 

CONDITION: Poor

occupancy: Not applicable

PRIORITY: D (C) Private OWNERSHIP:

Smelt mills, flues and chimney of a lead processing complex. Built in 1792. Some consolidation has been undertaken but the flue system is still in urgent need of repair.

Contact: Neil Redfern 01904 601897



Lodge Hall, Ingman Lodge Road, SITE NAME: Selside, Horton in Ribblesdale,

Craven

DESIGNATION: Listed Building Grade II\*

Poor OCCUPANCY: Occupied

C (C) PRIORITY OWNERSHIP: Private Farmhouse dated 1687. Structural cracks to main (east) front and bulge on north side. Roof reported to leak badly with attendant decay. Integral part of a working fárm.

Contact: Neil Redfern 01904 601897



Nappa Hall, SITE NAME: Askrigg, Richmondshire

DESIGNATION: Listed Building Grade I

Poor CONDITION:

OCCUPANCY: Part occupied

PRIORITY: F (C) Private OWNERSHIP:

A fortified Manor House built in 1459 for James Metcalf. A wing was added in C17. Most of the medieval portion has not been occupied for some years. There has recently been a change in ownership and some repairs are underway.

Contact: Neil Redfern 01904 601897

# SITE NAME:

#### Bolton Parks Lead Mine and ore works, Castle Bolton with East and West Bolton

DESIGNATION:	Scheduled Monument (No. 31344)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988

#### SITE NAME:

#### Large univallate hillfort on Ingleborough Hill, Clapham cum Newby

PRINCIPAL VULNERABILITY: Extensive visitor erosion trend: Declining  OWNERSHIP: Private contact: Keith Emerick 01904 601988	DESIGNATION:	Scheduled Monument (No. 24479)	CONDITION:	Generally unsatisfactory
N. 1. F. 1. 1. 0.1004 (0.1000)				with major localised problems
OWNERSHIP: Private CONTACT: Keith Emerick 01904 601988	PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
	OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE:

If the priority category has changed since the 2009 register, the previous category is given in brackets.

#### ABBREVIATIONS

CA LB/LBs Conservation Area Conservation Area Listed Building/s National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site RPG SM/SMs UA WHS

SITE NAME:	Kinsey Cave, Giggleswick Scar, Giggleswick		
designation:	Scheduled Monument (No. 13248)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Multi-period lead mines and processing wo on Grassington Moor, Grassington	orks and 20th cent	ury barytes mill
DESIGNATION:	Scheduled Monument (No. 31331)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Dumping	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Sargill ore hearth lead smelt mill, on Nort	h Rigg, 340m south	east of Sargill Lead Mine, High Abbotside
DESIGNATION:	Scheduled Monument (No. 31334)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Meal Bank Quarry Hoffmann kiln, quarry a	and lime works, Ing	leton
DESIGNATION:	Scheduled Monument (No. 35474)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Marrick ore hearth lead smeltmill, Marrick		
DESIGNATION:	Scheduled Monument (No. 29006)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Dumping	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Gunnerside Gill lead mines and ore works, Melbecks		
DESIGNATION:	Scheduled Monument (No. 29007)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
	Collapse Private	TREND: CONTACT:	Declining Keith Emerick 01904 601988
ownership:		CONTACT:	
OWNERSHIP: SITE NAME:	Private	CONTACT:	
OWNERSHIP: SITE NAME: DESIGNATION:	Private  Beldi Hill Low Level lead mine and ore wo	contact: orks, Muker	Keith Emerick 01904 601988  Generally unsatisfactory
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Beldi Hill Low Level lead mine and ore wo Scheduled Monument (No. 28248)	contact:  orks, Muker  condition:	Keith Emerick 01904 601988  Generally unsatisfactory with major localised problems
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Beldi Hill Low Level lead mine and ore wo Scheduled Monument (No. 28248)	contact:  orks, Muker  condition:  trend:  contact:	Keith Emerick 01904 601988  Generally unsatisfactory with major localised problems Declining
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Beldi Hill Low Level lead mine and ore wo Scheduled Monument (No. 28248)  Plant growth Private	contact:  orks, Muker  condition:  trend:  contact:	Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Extensive significant problems
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  PRINCIPAL VULNERABILITY:	Beldi Hill Low Level lead mine and ore wo Scheduled Monument (No. 28248)  Plant growth Private  West Stonesdale lead mine and ore works	contact:  orks, Muker  condition:  trend: contact:	Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Swaledale and Arkengarthdale barns and walls		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Don McIellan (LA) 01969 650456		

# **SOUTH YORKSHIRE**

# **BARNSLEY**



Grimethorpe Hall, SITE NAME: Brierley Road, **Brierley** 

DESIGNATION: Listed Building Grade II\*

Poor CONDITION: Vacant OCCUPANCY: C(C)PRIORITY: Company OWNERSHIP:

House, circa 1670, altered in C18, C19 and C20, which requires extensive repairs. Although standing in an amply sized site, the surrounding area is residential. The setting has been eroded by construction of housing to the west. Consent was granted for conversion to a restaurant in

2005, but the scheme has failed.

Contact: Catherine Dewar 01904 601972



Conservatory and linking bridge SITE NAME: at north west corner of Wentworth Castle, Stainborough

DESIGNATION: Listed Building Grade II\*, CA CONDITION: Very bad occupancy: Vacant D (D) PRIORITY:

OWNERSHIP:

Conservatory built in 1877, probably by Crompton and Fawkes, located immediately west of the house. The conservatory is situated in the early C18 formal gardens on the west side of the house. A support scaffold has been erected to prevent collapse. English Heritage grant has been offered towards the full repair of the conservatory.

Contact: Hilary Roome 01904 601984



Gun Room, SITE NAME: Wentworth Castle, Stainborough

DESIGNATION: Listed Building Grade II\*, CA

CONDITION: Fair OCCUPANCY: Vacant E (F) PRIORITY-Trust OWNERSHIP:

Probably built as a banqueting house or a bath-house, it was used as a gun room in the CI9. The interior has exceptionally fine plasterwork. Repairs to the walls and roof were carried out in 2006-07, but a further phase of conservation is required to the interior.

Contact: Catherine Dewar 01904 601972



Dovecote at Glebe Farm, SITE NAME: **Tankersley** 

DESIGNATION: Listed Building Grade II, SM

CONDITION: Very bad occupancy: Vacant A (D) PRIORITY-Private OWNERSHIP:

Stone built dovecote and cart shed, built in 1735 as part of the Glebe Farm for Richard Goodwin, Rector 1715-52. A particularly good example, complete with full interior and a rare set of spiked protective grilles over the dove holes.

Contact: Catherine Dewar 01904 601972



SITE NAME: Low Forge, Wortley

ownership: Private

Roofless remains of an early C18 water-powered iron forge, including waterwheel and tilt-hammer, associated wheelraces, forge and bloomery building; in need of repair.

**DESIGNATION: Scheduled Monument** CONDITION: Poor occupancy: Not applicable PRIORITY: C(C)

Contact: Catherine Dewar 01904 601972

#### SITE NAME:

#### East Gawber Hall colliery fanhouse, 800m north east of Croft Farm, Barnsley

DESIGNATION:	Scheduled Monument (No. 30951)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE:

If the priority category has changed since the 2009 register, the previous category is given in brackets.

#### ABBREVIATIONS

CA LB/LBs Conservation Area Conservation Area Listed Building/s National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site NIP RPG SM/SMs UA WHS

SITE NAME:	Elsecar Colliery Newcomen engine, Barnsle	ey	
DESIGNATION:	Scheduled Monument (No. SY1146)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Heavy Anti-aircraft gunsite 330m south east	t of Lowfield Farm	n, Barnsley
DESIGNATION:	Scheduled Monument (No. 29993)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Monk Bretton standing cross, Barnsley		
DESIGNATION:	Scheduled Monument (No. 23395)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Romano-British settlements at Finkle Street	t,Wortley	
DESIGNATION:	Scheduled Monument (No. SY1252)	CONDITION:	Generally unsatisfactory
5151G1 V 11161 1.	( 1 to 1 to 1 2 2 2 )	20110111	with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Water powered bloomery, iron forge and r	olling mill at Low	Forge, Wortley
DESIGNATION:	Scheduled Monument (No. 34714)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Elsecar, Barnsley		
	Conservation Area	CONDITION:	Very bad
DESIGNATION:			
DESIGNATION:  VULNERABILITY:	Low	TREND:	Expected to deteriorate

#### **DONCASTER**



SITE NAME: Moat Hall ruins,
Braithwell

Ruins of medieval monastic grange and post-medieval dwelling, consisting of arched doorway and low walls, in poor repair.

DESIGNATION: Scheduled Monument

CONDITION: Very bad

OCCUPANCY: Not applicable

PRIORITY: A (New)

OWNERSHIP: Private

Contact: Keith Miller 01904 601990



Stable to Hickleton Hall including the Stable Cottage and attached walls and gate piers, Hickleton Hall, Hickleton

DESIGNATION: Listed Building Grade II\*, CA, RPG II

CONDITION: Fair

OCCUPANCY: Vacant

PRIORITY: E (A)

PRIORITY: E (A)

OWNERSHIP: Charity

Contact

Mid C18 stable block, now store and house with attached walls and gatepiers. Possibly by James Paine, who designed Hickleton Hall, 1745-48, for Godfrey Wentworth. The stable block stands to the north of the Hall, which occupies an elevated position towards the north end of the registered site. Repairs have recently been carried out to the roofs and the building is now in fair condition, but disused.

Contact: Kathryn Gibson 01904 601939

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE:

If the priority category has changed since the 2009 register, the previous category is given in brackets.

#### ABBREVIATIONS

CA Conservation Area
LB/LBs Listed Building/s
NP National Park
RPG Registered Park and Garden
SM/SMs Scheduled Monument/s
UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Site of St Helen's Chapel, Barnburgh and H	larlington	
DESIGNATION:	Scheduled Monument (No. SY1229)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Manor Holt moated site, Bawtry		
DESIGNATION:	Scheduled Monument (No. 13228)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Moat Hall moated site and site of external	ancillary buildings	, Braithwell
DESIGNATION:	Scheduled Monument (No. 13234)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Roman Ridge, Roman road, north west of Doncaster, Brodsworth		
DESIGNATION:	Scheduled Monument (No. SYI 179)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Dumping	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Roman fort at Robin Hood's Well, Burghwa	allis	
DESIGNATION:	Scheduled Monument (No. SY1222)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Roman potteries 300yds (270m) north east of Rossington Bridge, Cantley		
DESIGNATION:	Scheduled Monument (No. SYI 108)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Castle Hills motte and bailey castle, Langthwaite, Adwick le Street, Doncaster		
DESIGNATION:	Scheduled Monument (No. 13211)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Moat Hills moated site, Bentley, Doncaster		
DESIGNATION:	Scheduled Monument (No. 13216)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
			Keith Miller 01904 601990

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Edlington Wood Roman settlement, Edlingt	on	
DESIGNATION:	Scheduled Monument (No. SY1096)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Metal detecting	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SVVINERGI III .	Tivace	CONTACT.	Return liner 01701 001770
SITE NAME:	Moat Hill moated site, Fenwick		
DESIGNATION:	Scheduled Monument (No. 13221)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Castle Hill, Hampole		
DESIGNATION:	Scheduled Monument (No. SYI 175)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Icehouse 720m south east of Bath House F	arm, High Melton	
DESIGNATION:	Scheduled Monument (No. 29995)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Earthworks on Sutton Common, Norton		
DESIGNATION:	Scheduled Monument (No. SY291)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Rossington Roman fort, Rossington		
DESIGNATION:	Scheduled Monument (No. SY1044)	CONDITION:	Extensive significant problems i.e. under plough, collapse
			Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	
	Arable ploughing Private	TREND: CONTACT:	Keith Miller 01904 601990
OWNERSHIP:		CONTACT:	Keith Miller 01904 601990
OWNERSHIP: SITE NAME:	Private	CONTACT:	Keith Miller 01904 601990
OWNERSHIP: SITE NAME: DESIGNATION:	Thorpe in Balne moated site, chapel and fis Scheduled Monument (No. 13220)	contact: shpond, Thorpe in condition:	Keith Miller 01904 601990  Balne  Generally satisfactory but with significant localised problems
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Private  Thorpe in Balne moated site, chapel and fis Scheduled Monument (No. 13220)  Drainage/dewatering	contact: shpond, Thorpe in condition: trend:	Keith Miller 01904 601990  Balne  Generally satisfactory but with significant localised problems Declining
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Thorpe in Balne moated site, chapel and fis Scheduled Monument (No. 13220)	contact: shpond, Thorpe in condition:	Keith Miller 01904 601990  Balne  Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Private  Thorpe in Balne moated site, chapel and fis Scheduled Monument (No. 13220)  Drainage/dewatering	contact: shpond, Thorpe in condition: trend:	Keith Miller 01904 601990  Balne  Generally satisfactory but with significant localised problems Declining
DWNERSHIP:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNERSHIP:  SITE NAME:	Private  Thorpe in Balne moated site, chapel and fis Scheduled Monument (No. 13220)  Drainage/dewatering Private	contact: shpond, Thorpe in condition: trend:	Keith Miller 01904 601990  Balne  Generally satisfactory but with significant localised problems Declining
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Thorpe in Balne moated site, chapel and fis Scheduled Monument (No. 13220)  Drainage/dewatering Private  Stancil Roman villa, Tickhill	contact:  shpond, Thorpe in  condition:  trend:  contact:	Keith Miller 01904 601990  Balne  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Extensive significant problems

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Tickhill Castle, Tickhill		
DESIGNATION:	Scheduled Monument (No. SY125)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Hatfield High Street		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Malcolm Thomas (LA) 01302 735199		
SITE NAME:	Mexborough		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	High	TREND:	No significant change expected
CONTACT:	Malcolm Thomas (LA) 01302 735199		
SITE NAME:	St George's		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Malcolm Thomas (LA) 01302 735199		
SITE NAME:	Thorne		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	High	TREND:	Expected to show some improvement
CONTACT:	Malcolm Thomas (LA) 01302 735199		
SITE NAME:	Thorne Road		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Malcolm Thomas (LA) 01302 735199		g The state of the
SITE NAME:	Town Field		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Malcolm Thomas (LA) 01302 735199		
SITE NAME:	Woodlands		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Malcolm Thomas (LA) 01302 735199		-
PEAK DISTRICT (N	NP)		
SITE NAME:	Bailey Hill motte and bailey castle, High Bra	adfield, Bradfield	
DESIGNATION:	Scheduled Monument (No. 13212)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
	D : .		K-#- Mill 01004 (01000

OWNERSHIP:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

Private

- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### NOTE:

CONTACT:

NOTE:
If the priority category
has changed since the 2009
register, the previous category
is given in brackets.

#### ABBREVIATIONS

Keith Miller 01904 601990

SITE NAME:	Castle Hill motte and bailey castle, High B	Bradfield, Bradfield	
DESIGNATION:	Scheduled Monument (No. 13244)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Cowell Flat prehistoric field system, 350m	south east of Mor	timer House, Bradfield
DESIGNATION:	Scheduled Monument (No. 29820)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Round cairn 200m west of Margery Hill to	riangulation pillar, B	radfield
DESIGNATION:	Scheduled Monument (No. 31311)	CONDITION:	Generally unsatisfactory
	,		with major localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
DWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990

#### **ROTHERHAM**



SITE NAME: 25 and 27 High Street, Rotherham

DESIGNATION: Listed Building Grade II\*, CA
CONDITION: Poor
OCCUPANCY: Vacant
PRIORITY: C (C)
OWNERSHIP: Company

Known as The Three Cranes. Late medieval house. Signs of structural decay, faulty rainwater goods. Proposal in place to take into Council ownership.

Contact: Alison Fisher 01904 601975



SITE NAME: Keppels Column, Admirals Crest,

Thorpe Common, Rotherham

DESIGNATION: Listed Building Grade II\*

condition: Poor

occupancy: Not applicable

PRIORITY: C (C)

OWNERSHIP: Local authority

Monumental column built 1773-80. Now on the edge of Wentworth Woodhouse Estate. The building is closed to the public, although emergency repairs have been carried out to the viewing platform and stairwell. There are significant structural cracks and stonework erosion. The internal staircase is unsafe.

Contact: Hilary Roome 01904 601984



SITE NAME: Thorpe Salvin Old Hall (Ruins of), Ladyfield Road,

Thorpe Salvin

DESIGNATION: Listed Building Grade II\*, SM, CA

condition: Poor

occupancy: Not applicable

PRIORITY: C (D)

ownership: Private

Gatehouse and imposing 3 storey south facade of mid C16 stone-built mansion built by Henry Sanford (died 1582) standing in an open courtyard. Grant has been offered for a condition survey.

Contact: Catherine Dewar 01904 601972



SITE NAME: Stable Block and Riding School,

Wentworth Woodhouse,

Wentworth

DESIGNATION: Listed Building Grade I, RPG II\*

CONDITION: Fair
OCCUPANCY: Vacant

priority: E (E)

OWNERSHIP: Private

Stable block and riding school, 1760s, situated approx 300 metres north-west of the house. Vacant and vulnerable due to under-maintenance and vandalism.

Contact: Kathryn Gibson 01904 601939

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE:

If the priority category has changed since the 2009 register, the previous category is given in brackets.

#### ABBREVIATIONS

CA Conservation Area
LB/LBs Listed Building/s
NP National Park
RPG Registered Park and Garden
SM/SMs Scheduled Monument/s
UA unitary Authority
WHS World Heritage Site

	Roman Ridge (Roman road): section 135yd	s (120m) long, eas	t of Hoober House, Brampton Bierlow
DESIGNATION:	Scheduled Monument (No. SY155A)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Roman Ridge (Roman road): section south	of Hoober House	, Brampton Bierlow
DESIGNATION:	Scheduled Monument (No. SY155B)	CONDITION:	Generally unsatisfactory
SESIGI VITTO I V.	scribadica Fioriament (Fio. 3 Fi335)	CONDITION.	with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Roman Ridge: section 300yds (270m) long of	on Birchcliff Bank,	Brampton Bierlow
DESIGNATION:	Scheduled Monument (No. SY231G)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Roman Ridge: section 400yds (370m) long s	south of Abdy Fari	m, Brampton Bierlow
DESIGNATION:	Scheduled Monument (No. SY231H)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
DWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Dead Man's Cave, Anston, North and South	Anston	
DESIGNATION:	Scheduled Monument (No. 13251)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Kimberworth motte and bailey castle, Roth	erham	
DESIGNATION:	Scheduled Monument (No. 13224)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Dumping	TREND:	,
	Dumping Private	TREND: CONTACT:	Declining Keith Miller 01904 601990
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:		CONTACT:	Declining Keith Miller 01904 601990
OWNERSHIP: SITE NAME:	Private  Roman Ridge: section 110yds (100m) long,	CONTACT:	Declining Keith Miller 01904 601990  NE  Generally satisfactory
OWNERSHIP: SITE NAME: DESIGNATION:	Roman Ridge: section 110yds (100m) long, of Kimberworth Park Farm, Rotherham  Scheduled Monument (No. SY231A)	CONTACT: 450yds (410m) NI	Declining Keith Miller 01904 601990  NE  Generally satisfactory but with minor localised problems
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Roman Ridge: section 110yds (100m) long, of Kimberworth Park Farm, Rotherham	CONTACT: 450yds (410m) NI CONDITION:	Declining Keith Miller 01904 601990  NE  Generally satisfactory
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Roman Ridge: section 110yds (100m) long, of Kimberworth Park Farm, Rotherham  Scheduled Monument (No. SY231A)  Scrub / tree growth Private	CONTACT:  450yds (410m) NI  CONDITION:  TREND:  CONTACT:	Declining Keith Miller 01904 601990  NE  Generally satisfactory but with minor localised problems Declining Keith Miller 01904 601990
OWNERSHIP:	Roman Ridge: section 110yds (100m) long, of Kimberworth Park Farm, Rotherham  Scheduled Monument (No. SY231A)  Scrub / tree growth	CONTACT:  450yds (410m) NI  CONDITION:  TREND:  CONTACT:	Declining Keith Miller 01904 601990  NE  Generally satisfactory but with minor localised problems Declining Keith Miller 01904 601990
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Private  Roman Ridge: section 110yds (100m) long, of Kimberworth Park Farm, Rotherham  Scheduled Monument (No. SY231A)  Scrub / tree growth Private  Roman Ridge: section 300yds (270m) long in the section 300yds	CONTACT:  450yds (410m) NI  CONDITION:  TREND:  CONTACT:	Declining Keith Miller 01904 601990  NE  Generally satisfactory but with minor localised problems Declining Keith Miller 01904 601990  od  Generally satisfactory
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Roman Ridge: section 110yds (100m) long, of Kimberworth Park Farm, Rotherham  Scheduled Monument (No. SY231A)  Scrub / tree growth Private  Roman Ridge: section 300yds (270m) long (east of Chemical Cottages), Rotherham	CONTACT:  450yds (410m) NI  CONDITION:  TREND:  CONTACT:	Declining Keith Miller 01904 601990  NE  Generally satisfactory but with minor localised problems Declining Keith Miller 01904 601990

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

ABBREVIATIONS Conservation Area Listed Building/s National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site

SITE NAME:	Roman Ridge: section 400yds (370m) long fr	om Hill Top Lane	e to Little Common Lane, Rotherham
DESIGNATION:	Scheduled Monument (No. SY231F)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate visitor erosion	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Roman Ridge: section 400yds (370m) long in	Wath Wood, Ro	therham
DESIGNATION:	Scheduled Monument (No. SY2311)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate vehicle damage/erosion	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Roman Ridge: section 520yds (480m) east of	Dyson's Cottag	e to Long Plantation, Rotherham
DESIGNATION:	Scheduled Monument (No. SY231L)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Digging	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Roman Ridge: south east of Hill Top (section Meadowhall Road to Hill Top), Rotherham	700yds (660m)	long,
DESIGNATION:	Scheduled Monument (No. SY231E)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Swinton Pottery (The Rockingham Works), 3	310m and 120m	north west of Keeper's Cottage, Rotherh
DESIGNATION:	Scheduled Monument (No. 29957)	CONDITION:	Generally unsatisfactory
525/G/W/110/W	(. vo. 27707)	201121110111	with major localised problems
PRINCIPAL VULNERABILITY:	Moderate natural erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Hood Hill shaft mounds, 480m east of Hood	Hill Farm, Went	worth
DESIGNATION:	Scheduled Monument (No. 30949)	CONDITION:	Extensive significant problems
	(,		i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Roman Ridge: section 330yds (300m) long, so	outh of Dog Ken	nel Pond, Wentworth Park, Wentworth
DESIGNATION:	Scheduled Monument (No. SYI55D)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Roman Ridge: section 500yds (460m) long, n	orth of Dog Ken	nel Pond,Wentworth Park,Wentworth
DESIGNATION:	Scheduled Monument (No. SY155C)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
OVVIVEI OF III .			

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Brampton-en-le Morthen, Rotherham, Thurcro	ft	
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	No significant change expected
CONTACT:	Jonathan Bell (LA) 01709 823811		
SITE NAME:	Doncaster Road, Rotherham Urban		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Expected to show some improvement
CONTACT:	Jonathan Bell (LA) 01709 823811		
SITE NAME:	Gildingwells, Rotherham South		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Expected to deteriorate
CONTACT:	Jonathan Bell (LA) 01709 823811		
SITE NAME:	Greasborough, Rotherham Urban		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Expected to show some improvement
CONTACT:	Jonathan Bell (LA) 01709 823811		
SITE NAME:	Rotherham Town Centre, Rotherham Urban		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Expected to show some improvement
CONTACT:	Jonathan Bell (LA) 01709 823811		·
SITE NAME:	Wales, Rotherham South		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Expected to deteriorate

#### **SHEFFIELD**



Loxley United Reformed Church, SITE NAME: Loxley Road, Bradfield

DESIGNATION: Listed Building Grade II\*

CONDITION: Fair Vacant OCCUPANCY: PRIORITY: C(C)OWNERSHIP: Private Church, 1787. Closed in 1994. The building is adequately maintained. The possibility of community use is under consideration.

Contact: Giles Proctor 01904 601981



Leah's Yard, SITE NAME:

> 20-22 Cambridge Street, Sheffield

DESIGNATION: Listed Building Grade II\*, CA

Poor CONDITION: occupancy: Vacant PRIORITY: D (D) OWNERSHIP: Company Mid C19 cutlery/silversmithing works, with late C19 alterations. General decay, some fire damage. Use for shops and food/drink agreed and included in "New Retail Quarter" proposals. Some patch repairs to the roof have been carried out.

Contact: Catherine Dewar 01904 601972

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

## NOTE: If the priority category has changed since the 2009 register, the previous category is given in brackets.

## **ABBREVIATIONS**



Nonconformist Chapel, SITE NAME: General Cemetery, Cemetery Road, Sheffield

DESIGNATION: Listed Building Grade II\*, CA, RPG II\*

Poor CONDITION: Vacant OCCUPANCY: A(A)Trust OWNERSHIP:

Cemetery chapel built in circa 1836. Lead has been stolen from the roof and not reinstated, risking further structural deterioration.

Contact: Tammy Whitaker 01904 601880



Crucible Steel Shop in south corner SITE NAME: of former Sanderson Kaysers Darnall Works, Darnall Road, Sheffield

DESIGNATION: Listed Building Grade II\*, SM

Very bad CONDITION: Vacant OCCUPANCY: E (C) PRIORITY: Company OWNERSHIP:

Crucible steel works, 1872, now disused. Of international significance as a unique survival of its type. A major English Heritage grant-aided repair scheme started in 2009 and is due for completion late in 2010.

Contact: Keith Miller 01904 601990



Crucible Steel Shop on south east side Crucible steel works, single storey range dated to 1871 SITE NAME: of former Sanderson Kaysers Darnall Works, Darnall Road, Sheffield

DESIGNATION: Listed Building Grade II\*, SM

Poor CONDITION:

occupancy: Part occupied

PRIORITY: E (C) OWNERSHIP: Company now disused. Of international significance as a unique survival of its type. A major English Heritage grant-aided repair scheme started in 2009 and is due for completion late in 2010.

Contact: Keith Miller 01904 601990



Wicker Arch and adjoining viaduct, The Wicker,

Sheffield

DESIGNATION: Listed Building Grade II\*

CONDITION: Fair

Part occupied

C(C)PRIORITY Company OWNERSHIP:

Railway viaduct, I 848. Main arch II\* has been cleared and overhauled but the remaining arches are suffering from stone theft (parapets) and general lack of maintenance. Many of the adjacent (grade II listed) viaduct arches are in use for workshops but remain in poor repair.

Contact: Catherine Dewar 01904 601972



Workshop ranges and crucible SITE NAME: furnace, attached to No.35,

Well Meadow Street, Sheffield

DESIGNATION: Listed Building Grade II\*

CONDITION: Poor Vacant OCCUPANCY: F (C) PRIORITY-

OWNERSHIP: Private Workshops and a crucible furnace, circa 1840. The buildings are suffering from general decay. The gutters are failing in places and some slates have slipped. Site is generally secure and weathertight. Consents are in place and some repair underway. English Heritage is considering supporting the cost of further repair.

Contact: Giles Proctor 01904 601981



Gateway and adjoining walls SITE NAME: at garden entrance to Oakes Park, Norton, Sheffield

DESIGNATION: Listed Building Grade II\*, CA, RPG II

CONDITION: Poor

occupancy: Not applicable

C(C)PRIORITY: ownership: Private

Early C18 and early C19 gateway with ornamental iron gates leading to C18 gardens. The gates are rusty and the gate piers are in poor condition. The park is also at risk.

Contact: Catherine Dewar 01904 601972

#### SITE NAME:

#### Handlands Romano-British settlement, 460m south west of Woodseats Farm, Ecclesfield

DESIGNATION:	Scheduled Monument (No. 29822)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented

#### NOTE:

If the priority category has changed since the 2009 register, the previous category is given in brackets

#### ABBREVIATIONS

Conservation Area CA LB/LBs Conservation Area Listed Building/s National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site NIP RPG SM/SMs WHS

SITE NAME:	Willow Garth moated site and fishpond, Ecclesfield		
DESIGNATION:	Scheduled Monument (No. 13223)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Roman Ridge: section 600yds (550m) long between	een Jenkin La	ne (now Road) and Tylers Street, Sheffield
DESIGNATION:	Scheduled Monument (No. SY231D)	CONDITION:	Generally unsatisfactory
	,		with major localised problems
PRINCIPAL VULNERABILITY:	Moderate visitor erosion	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Keith Miller 01904 601990
SITE NAME:	The Shepherd Wheel, Sheffield		
DESIGNATION:	Scheduled Monument (No. SY1291)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Iron Age and Roman quern workings on Wharno	cliffe Rocks, S	Stocksbridge
DESIGNATION:	Scheduled Monument (No. SY1253)	CONDITION:	Generally unsatisfactory
	()		with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Keith Miller 01904 601990
	SITE NAME: Oakes Park, Sheffield	origins, an e	nd pleasure grounds with early to mid C18 early C19 terrace and parkland probably 9 date. Park and gardens compromised
	DESIGNATION: Registered Park and Garden Grade II, also CA, 9 LBs	by multiple	use, condition of park is poor and listed in very poor condition.
	condition: Extensive significant problems		
	VULNERABILITY: High		
	TREND: Declining		
	ownership: Mixed, multiple owners	Contact: Ar	ndy Wimble 01904 601970
	SITE NAME: Sheffield General Cemetery, Sheffield	Cemetery	of 1836 designed by Sheffield architect Sam
	•	\M/orth (fil	830) with a chapel, catacombs and a ceme
	DESIGNATION: Registered Park and Garden Grade II*,	office, and	a layout which makes dramatic use of a qua
	also CA, 9 LBs		. An extension of 1846 for Anglican burials,
THE PARTY OF THE P	CONDITION Conorally uncatisfactory	out by Rob	pert Marnock (1800-89). The cemetery reta



CONDITION: Generally unsatisfactory with major localised problems VULNERABILITY: High Declining TREND:

OWNERSHIP: Local Authority, multiple owners

out by Robert Marnock (1800-89). The cemetery retains both its Anglican and Non-Conformist Chapels (listed grade II\*) the latter a building at risk. Site managed by The Friends of Sheffield General Cemetery.

Contact: Andy Wimble 01904 601970

SITE NAME:	General Cemetery		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Craig Broadwith (LA) 0114 2734472		
SITE NAME:	Well Meadow		
SITE NAME: DESIGNATION:	Well Meadow  Conservation Area	CONDITION:	At risk
		CONDITION: TREND:	At risk Deteriorating

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

## NOTE: If the priority category has changed since the 2009 register, the previous category is given in brackets.

#### WEST YORKSHIRE

#### **BRADFORD**



SITE NAME Manningham Mill, Heaton Street,

Heaton, Bradford

DESIGNATION: Listed Building Grade II\*, CA

Fair Vacant OCCUPANCY: F (F) PRIORITY: Company OWNERSHIP:

Silk mill, with boiler house, chimney and warehouse. Built in 1873. Scheme of residential and office conversion agreed. Conversion of warehouse completed. Works to

mill block underway.

Contact: Catherine Dewar 01904 601972



SITE NAME: Leventhorpe Hall,

1289 and 1291 Thornton Road, Lower Grange, Bradford

DESIGNATION: Listed Building Grade II\*

Poor CONDITION: occupancy: Vacant PRIORITY: D(D)Private OWNERSHIP:

Late C17 house with C19 additions. Windows are broken, the roof is sagging with missing slates. The east wall is failing. The site in general has substantially deteriorated but not the Hall. Residential scheme has consent for the whole site.

Contact: Catherine Dewar 01904 601972



Mill Building at Low Mills, SITE NAME:

> Low Mill Lane, Keighley

DESIGNATION: Listed Building Grade II\*

Poor Vacant OCCUPANCY: D(D)PRIORITY: OWNERSHIP: Company Late C18. Early cotton mill, adjacent to supermarket and car park. Application approved for residential use. English Heritage grant offered towards repair works.

Contact: Catherine Dewar 01904 601972



Waterloo Mill. SITE NAME:

Howden Road, Silsden

DESIGNATION: Listed Building Grade II\*, CA

CONDITION: Fair

Part occupied OCCUPANCY: F (F)

OWNERSHIP: Company

Main four storey spinning mill block, parts of roof deteriorating and allowing water ingress although extensive repairs to windows and roof covering recently completed. The middle section, which contains the engine, is deteriorating. Part converted to residential use. The Chimney was extensively repaired in 2005.

Contact: Catherine Dewar 01904 601972

THE STATE OF THE S	H
TWO TOL	N HV

SITE NAME:

SITE NAME

### Late prehistoric enclosed settlement known as Round Dykes Camp on Addingham Low Moor, Addingham

DESIGNATION:	Scheduled Monument (No. 31498)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Moderate vehicle damage/erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990

#### Cup and ring marked rock north of Pennythorn Hill, Baildon SITE NAME

DESIGNATION:	Scheduled Monument (No. 25408)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Keith Miller 01904 601990

#### Cup-marked rock on slight bank north east of Glovershaw quarry, Baildon

DESIGNATION:	Scheduled Monument (No. 25273)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Keith Miller 01904 601990

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE:

If the priority category has changed since the 2009 register, the previous category is given in brackets.

#### **ABBREVIATIONS**

CA LB/LBs Conservation Area Conservation Area Listed Building/s National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site NIP RPG SM/SMs UA WHS

SITE NAME:	Enclosed settlement known as 'Soldier's Tr	ench' including a co	ıp-marked rock, Baildon
DESIGNATION:	Scheduled Monument (No. 25257)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Northernmost of two cairns east of Glove	ershaw quarry, inclu	ıding adjacent cup-marked rock, Baildon
DESIGNATION:	Scheduled Monument (No. 25275)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNERSHIP:	Local Authority	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Round cairn and curving bank on Pennyth	orn Hill, Baildon	
DESIGNATION:	Scheduled Monument (No. 25407)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Round cairn on east flank of Baildon Hill,	Baildon	
DESIGNATION:	Scheduled Monument (No. 25400)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Small cup-marked rock 30m east of Glove	rshaw quarry, Baild	on
DESIGNATION:	Scheduled Monument (No. 25271)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Southernmost of two cairns east of Glove	rshaw quarry, Baild	on
DESIGNATION:	Scheduled Monument (No. 25276)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Cairn 330m north of Woodhead on Hard	en Moor, Bradford	
DESIGNATION:	Scheduled Monument (No. 31489)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Twelve Apostles stone circle, Burley Moor	, Burley	
DESIGNATION:	Scheduled Monument (No. 25313)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
TRINCIPAL VOENEIVABIETT.			-
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Late prehistoric enclosed settlement know	vn as Castle Stead	Ring, Cullingworth
DESIGNATION:	Scheduled Monument (No. 31497)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Late prehistoric enclosed settlement know	vn as Catstones Rii	ng on Catstones Hill, Cullingworth
DESIGNATION:	Scheduled Monument (No. 31490)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Cairn at Rombalds Moor triangulation pilla	ar, Ilkley	
DESIGNATION:	Scheduled Monument (No. 25293)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Cairnfield, carved rocks and associated cureast of Gill Head Reservoir, llkley	rved bank at north	west end of Green Crag Slack,
DESIGNATION:	Scheduled Monument (No. 25342)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Cup and Ring marked rock known as the l	Hanging Stone Roc	k, likley
DESIGNATION:	Scheduled Monument (No. 25362)	CONDITION:	Generally satisfactory
	,		but with significant localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Enclosure with carved rocks and disturbed	d cairn known as G	reen Crag Enclosure, llkley
DESIGNATION:	Scheduled Monument (No. 25344)	CONDITION:	Generally satisfactory but with significant localised problems
	Plant growth		Declining
PRINCIPAL VULNERABILITY:	Traine growth	TREND:	8
	Local Authority	TREND: CONTACT:	Keith Miller 01904 601990
OWNERSHIP:	~	CONTACT:	Keith Miller 01904 601990
OWNERSHIP: SITE NAME:	Local Authority	CONTACT:	Keith Miller 01904 601990
OWNERSHIP:  SITE NAME:  DESIGNATION:	Local Authority  Two cup marked rocks in path south east	contact:	Keith Miller 01904 601990  and Calf Rocks, Ilkley  Generally unsatisfactory
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Two cup marked rocks in path south east Scheduled Monument (No. 25341)	of quarry at Cow a	Keith Miller 01904 601990  and Calf Rocks, Ilkley  Generally unsatisfactory with major localised problems
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:	Two cup marked rocks in path south east Scheduled Monument (No. 25341) Extensive visitor erosion	of quarry at Cow a condition:  TREND:  CONTACT:	Keith Miller 01904 601990  and Calf Rocks, Ilkley  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990
OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:	Two cup marked rocks in path south east Scheduled Monument (No. 25341)  Extensive visitor erosion Local Authority	of quarry at Cow a condition:  TREND:  CONTACT:	Keith Miller 01904 601990  and Calf Rocks, Ilkley  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  Farm, Wilsden  Generally unsatisfactory
PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNERSHIP:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Two cup marked rocks in path south east Scheduled Monument (No. 25341)  Extensive visitor erosion Local Authority  Late prehistoric enclosed settlement 150m	of quarry at Cow a condition:  TREND:  CONTACT:	Keith Miller 01904 601990  and Calf Rocks, Ilkley  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  Farm, Wilsden

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.



Whinburn, Keighley SITE NAME:

DESIGNATION: Registered Park and Garden Grade II,

also 3 LBs

сонытюм: Generally satisfactory

but with minor localised problems

vulnerability: Low Stable

OWNERSHIP: Private, single owner

Gardens and pleasure grounds partly laid out c1897 with additional formal landscaping and features dating from 1912 to 1938, with some design work in the latter period by T.H. Mawson and Son. Formerly owned by Bradford City Council, now in private ownership and lay vacant for a number of years suffering decay and vandalism. New owners in process of repairing house and grounds.

Contact: Andy Wimble 01904 601970

SITE NAME:	Devonshire Park and Cliffe Castle, Keighley		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Expected to deteriorate
CONTACT:	Christine Kerrin (LA) 01274 434554		
SITE NAME:	Great Horton		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Expected to deteriorate
CONTACT:	Christine Kerrin (LA) 01274 434554		
SITE NAME:	Haworth, Keighley		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Expected to show some improvement
CONTACT:	Christine Kerrin (LA) 01274 434554		
SITE NAME:	Idle and The Green		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Expected to deteriorate
CONTACT:	Christine Kerrin (LA) 01274 434554		
SITE NAME:	Keighley Town Centre		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Expected to show some improvement
		TIALIAD.	Expected to show some improvement
CONTACT:	Christine Kerrin (LA) 01274 434554	THEND.	Expected to show some improvement
	Christine Kerrin (LA) 01274 434554  North Park Road	TINE VIS.	Expected to show some improvement
SITE NAME:	·	CONDITION:	Very bad
site name: Designation:	North Park Road		
CONTACT:  SITE NAME:  DESIGNATION:  VULNERABILITY:  CONTACT:	North Park Road  Conservation Area	CONDITION:	Very bad
SITE NAME:  DESIGNATION:  VULNERABILITY:  CONTACT:	North Park Road  Conservation Area Low	CONDITION:	Very bad
SITE NAME:  DESIGNATION:  VULNERABILITY:  CONTACT:  SITE NAME:	North Park Road  Conservation Area Low Christine Kerrin (LA) 01274 434554	CONDITION:	Very bad Expected to deteriorate
SITE NAME:  DESIGNATION:  VULNERABILITY:	North Park Road  Conservation Area Low Christine Kerrin (LA) 01274 434554  Thornton	CONDITION: TREND:	Very bad

#### BRADFORD / KIRKLEES / LEEDS



Battle of Adwalton Moor SITE NAME:

The I 643 battle during the English Civil War on moorland outside Bradford in which some 14,000 men fought, gave control of the north of England to the Royalists. The battlefield faces various development pressures, notably from an industrial zone at its west end.

DESIGNATION: Registered Battlefield

TREND: Declining OWNERSHIP: Private

Contact: Susan Daniels 01904 601 979

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

## NOTE:

If the priority category has changed since the 2009 register, the previous category is given in brackets.

#### **ABBREVIATIONS**

#### **CALDERDALE**



SITE NAME: Double aisled barn to north west of Kirklees Priory Gatehouse, Kirklees Park, Brighouse

DESIGNATION: Listed Building Grade I

CONDITION: Fair

OCCUPANCY: Part occupied

PRIORITY: C(C)OWNERSHIP-Private Aisled barn. One of the farm buildings of the Priory (now gone), with a CI5 timber frame, which was later stone-clad. Whole complex continuing to decay. North east corner of stables and north threshing porch appear unstable. A report on development options is under consideration by the owners.

Contact: Giles Proctor 01904 601981



Home Farm Building No. 6, SITE NAME: Kirklees Park, Brighouse

DESIGNATION: Listed Building Grade II\*

CONDITION: Very bad Vacant OCCUPANCY: A(A)PRIORITY: Private OWNERSHIP:

Early C17 cowhouse, two cell house, possibly slaughter house. Gable wall partially collapsed and unstable. A report on development options is under consideration by the owners.

Contact: Giles Proctor 01904 601981



SITE NAME: Kirklees Priory Gatehouse, Kirklees Park,

DESIGNATION: Listed Building Grade II\*

**Brighouse** 

Poor CONDITION: occupancy: Vacant PRIORITY: A (B) Private OWNERSHIP:

Gatehouse to the Priory (now gone). Early C16, part timber-framed. Holding repairs in place, but beginning to fail. Feasibility and consent for office or dwelling recently obtained. Grant offered for repair but not taken up. Timber decay ongoing, so that work is becoming urgently necessary. A report on development options is under consideration by the owners.

Contact: Giles Proctor 01904 601981



L-shaped Aisled Barn, SITE NAME: Kirklees Park,

**Brighouse** 

DESIGNATION: Listed Building Grade II

Fair occupancy: Vacant C (C) PRIORITY-Private

OWNERSHIP:

Aisled barn, early C16, encased in stone during the early to mid C17. Part of a little used farm complex. Area of roof missing to north and some timber decay to frame. A report on development options is under consideration by the owners.

Contact: Giles Proctor 01904 601981



Malthouse. SITE NAME: Kirklees Park, Brighouse

DESIGNATION: Listed Building Grade I

CONDITION: Fair Vacant OCCUPANCY: C(C)OWNERSHIP: Private Malthouse, late C17. It forms part of a little used farm complex. Building appears to be in a stable condition. A report on development options is under consideration by the owners.

Contact: Giles Proctor 01904 601981



Scout Hall, SITE NAME:

Lee Lane, Halifax

DESIGNATION: Listed Building Grade II\*

Poor CONDITION: OCCUPANCY: Vacant PRIORITY: B (B) OWNERSHIP: Private Late C17 house. Part repaired with English Heritage grant, part derelict. Repair and reuse under discussion.

Contact: Catherine Dewar 01904 601972

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE:

If the priority category has changed since the 2009 register, the previous category is given in brackets.

#### ABBREVIATIONS

Conservation Area CA LB/LBs Conservation Area Listed Building/s National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site NIP RPG SM/SMs UA WHS



Former lock-up, SITE NAME: 121 Keighley Road, Illingworth, Halifax

DESIGNATION: Listed Building Grade II\*

Very bad CONDITION: Vacant OCCUPANCY:

PRIORITY: A (New) Local authority OWNERSHIP:

Located on the north side of the A629 Halifax – Keighley Road, the lock-up is a small two storey building of coursed sandstone walls and stone slate roof dated 1823. The dated tablet over the arched door opening and lunette is inscribed 'Let him that stole steal no more but rather let him labour with his hands the thing which is good that he may have to give to him that needeth'.

Contact: Richard Jaques 01904 601986



Broad Bottom Old Hall, SITE NAME: Mytholmroyd. Hebden Royd

DESIGNATION: Listed Building Grade II\*

Fair CONDITION: Vacant C(C)PRIORITY: Private OWNERSHIP:

Late medieval timber-framed open hall encased in stone in the mid C16. Watertight but vacant for some years. Vulnerable to decay without a sustaining use.

Contact: Catherine Dewar 01904 601972



Birchen Lee Carr and attached barn, SITE NAME: Raw Lane, Mytholmroyd, Hebden Royd

DESIGNATION: Listed Building Grade II\*

CONDITION: Fair

PRIORITY:

occupancy: Part occupied

F (A) Private OWNERSHIP:

House of mid C17 date, with added barn, 1886. Partly re-roofed 30 years ago, rear wing dismantled. Roof and interior renewed following major collapse. A restoration scheme has been agreed and repair works are underway.

Contact: Catherine Dewar 01904 601972



Barn to north west SITE NAME: of Greenwood Lee, Widdop Road, Heptonstall

DESIGNATION: Listed Building Grade II\*

Very bad CONDITION: occupancy: Vacant C(C)PRIORITY-

OWNERSHIP:

Private

Late C16 aisled barn. Major failure of roof structure and loss of roof covering. Residential conversion of the barn and nearby outbuildings has been approved.

Contact: Catherine Dewar 01904 601972



Wainsgate Baptist Church, SITE NAME: Wainsgate Lane, Hebden Bridge, Wadsworth

DESIGNATION: Listed Building Grade II\*

occupancy: Part occupied

Chapel with attached Sunday School and former Minister's house dating from 1859. The Chapel is redundant and in poor condition: the school is currently used as a workshop and the former Minister's house is used as a store.

Contact: Richard Jaques 01904 601986

SITE NAME:	Camp at	Kirklees Park, C
	OWNERSHIP:	Trust
	PRIORITY:	E (E)
A PROPERTY OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COL		

SITE NAME:	Camp at Kirklees Park, Calderdale		
DESIGNATION:	Scheduled Monument (No.WY253)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990

SITE NAME:	Mill gas plant, Shaw Lodge Mills, Calderdale		
DESIGNATION:	Scheduled Monument (No.WY1288)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

## NOTE: If the priority category has changed since the 2009 register, the previous category is given in brackets.

## ABBREVIATIONS

Conservation Area CA LB/LBs Conservation Area Listed Building/s National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site NIP RPG SM/SMs UA WHS

SITE NAME:	Ventilation chimney and furnace house 260	Jili Soudii Oi I alk I	arrii, Caidei dale
DESIGNATION:	Scheduled Monument (No. 30960)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Blackstone Edge Roman road, Ripponden		
DESIGNATION:	Scheduled Monument (No.WY32)	CONDITION:	Generally satisfactory
	` '		but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Cairnfield on Ringstone Edge Moor, 240m	south west of Clay	· House, Ripponden
DESIGNATION:	Scheduled Monument (No. 31509)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Oxygrains packhorse bridge, Rishworth, Ri	ipponden	
DESIGNATION:	Scheduled Monument (No.WY142)	CONDITION:	Generally unsatisfactory
	` ,		with major localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Elland		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Expected to deteriorate
CONTACT:	Kate Peach (LA) 01422 392267		
SITE NAME:	Todmorden		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Expected to deteriorate
	Kate Peach (LA) 01422 392267		

## KIRKLEES



Milnsbridge House, SITE NAME: 2-6 Dowker Street, Huddersfield

DESIGNATION: Listed Building Grade II\*, CA

CONDITION: Fair occupancy: Part occupied E(D) PRIORITY:

Private OWNERSHIP:

Mid C18 house now in engineering use. Pediments conceal modern flat roof. Scheme approved for residential conversion. Repair works commenced.

Contact: Catherine Dewar 01904 601972



18-20 St George's Square, SITE NAME: Huddersfield

DESIGNATION: Listed Building Grade II\*, CA condition: Poor occupancy: Part occupied

C(C)PRIORITY: ownership: Company Part of Tite's Building. Built as offices and warehousing (Sir William Tite, 1852). Planning permission and listed building consent granted for conversion to student accommodation.

Contact: Kathryn Gibson 01904 601939

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE:

If the priority category has changed since the 2009 register, the previous category is given in brackets.

#### **ABBREVIATIONS**



Westwood Mills, SITE NAME: Lowestwood Lane, Linthwaite, Huddersfield

DESIGNATION: Listed Building Grade II\*, CA CONDITION: Very bad

occupancy: Vacant PRIORITY: A(A)

An early C19 mill complex, with some later C19 alterations. Buildings include former scribbling, carding and fulling mill, office, warehouse, workshops, boiler and engine house. Interiors and roofs stripped for refurbishment. Part lacks roof covering. Consents for conversion to residential use and new build residential development approved October 2005. Scheme revisions discussed but no application made.

Contact: Catherine Dewar 01904 601972



SITE NAME: Hopton Congregational Church, Calder Road. Mirfield

DESIGNATION: Listed Building Grade II\*

Company

Poor CONDITION: OCCUPANCY: Vacant C(C)PRIORITY: Private OWNERSHIP:

Church and attached school buildings to rear dated 1829. Largely unaltered and retaining box pews in the body of the church and original windows throughout. Water penetration has resulted in patches of timber decay and a falling roof truss. No longer used for worship.

Contact: Catherine Dewar 01904 601972

SITE NAME:	Late prehistoric enclosed settlement on Castl	e Hill, 550m no	rth of Broadstone Lodge, Denby Dale
DESIGNATION:	Scheduled Monument (No. 31503)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Thornhill Hall moat and sites of formal garder and remnant of pre-seventeenth century oper		
DESIGNATION:	Scheduled Monument (No. 13289)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Crosland Lower Hall moated site, Meltham		
DESIGNATION:	Scheduled Monument (No. 13286)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Castle Hall Hill motte and bailey castle, Mirfie	ld	
DESIGNATION:	Scheduled Monument (No. 13295)	CONDITION:	Generally unsatisfactory
	,		with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Birkby		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	High	TREND:	Expected to deteriorate
CONTACT:	Anne Ross (LA) 01484 222066		
SITE NAME:	Dewsbury		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Expected to deteriorate
	Anne Ross (LA) 01484 222066		

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.
- NOTE: If the priority category has changed since the 2009 register, the previous category is given in brackets.

#### **ABBREVIATIONS**

CA LB/LBs NP RPG SM/SMs UA WHS

Conservation Area Conservation Area Listed Building/s National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site

SITE NAME:	Edgerton, Huddersfield		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Expected to deteriorate
CONTACT:	Anne Ross (LA) 01484 222066		
SITE NAME:	Holmfirth		
SITE NAME:  DESIGNATION:	Holmfirth  Conservation Area	CONDITION:	At risk
		Condition: trend:	At risk Deteriorating

#### **LEEDS**



SITE NAME: Stank Hall quasi-manorial site, Dewsbury Road,

Beeston

DESIGNATION: Listed Building Grade II\*, SM, CA

Very bad CONDITION: occupancy: Vacant A(A)PRIORITY:

Local authority OWNERSHIP:

Remains of a major yeoman farm of sub-manorial type, with surviving barn of C15 of eight bays. Southern-most bays rebuilt in stone mid C17.

Contact: Richard Jaques 01904 601986



Church of St Margaret, SITE NAME: Cardigan Road, Burley

DESIGNATION: Listed Building Grade II

condition: Fair Vacant OCCUPANCY: F(D)

OWNERSHIP: Religious organisation

Anglican church 1908-9. Designed by TL Moore. West end finished by GG Pace in 1964. Plan to reuse as a church and community centre. English Heritage/Heritage Lottery Fund grants offered December 2006, 2007 and 2008.

Repair works have commenced.

Contact: Richard Jaques 01904 601986



Temple Works gate lodge, SITE NAME: Marshall Street,

Holbeck

DESIGNATION: Listed Building Grade II\*, CA

Poor CONDITION:

occupancy: Not applicable

C(C)PRIORITY: OWNERSHIP: Company Small derelict gate lodge to spinning, water, steam and flax mill of 1836-40 designed by Bonomi in the Egyptian style. Walls stable, but lacks a roof.

Contact: Kathryn Gibson 01904 601939



Ledston Hall. SITE NAME Hall Lane,

Ledston

DESIGNATION: Listed Building Grade I, RPG II

Fair CONDITION:

occupancy: Part occupied

E (E) PRIORITY: OWNERSHIP:

Private

Country house now partly subdivided into flats, situated in late C17/C18 walled gardens with terraces to south and west, grass terraces to the east and an early C18 park to the north. Five periods of building starting in c1200 with chapel and kitchen. Landscape condition is generally fair to good. Long term future under consideration through preparation of a conservation plan and feasibility study.

Contact: Catherine Dewar 01904 601972



First Leeds White Cloth Hall, SITE NAME: 98-101 (consec) Kirkgate,

DESIGNATION: Listed Building Grade II\*, CA

Very bad Vacant OCCUPANCY: C (C)

OWNERSHIP: Company

PRIORITY:

Cloth hall built in 1711. Derelict and deteriorating. An exceptionally rare example of an early C18 arcaded cloth hall. Total rebuild likely to be necessary, as structure is very decayed. Part of generally dilapidated block along Kirkgate, which is being proposed for the Heritage Lottery Fund Townscape Heritage Initiative programme.

Contact: Kathryn Gibson 01904 601939

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE:

If the priority category has changed since the 2009 register, the previous category is given in brackets.

#### ABBREVIATIONS

CA LB/LBs Conservation Area Conservation Area Listed Building/s National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site NIP RPG SM/SMs UA WHS



Temple Mill, SITE NAME: Marshall Street, Holbeck, Leeds

DESIGNATION: Listed Building Grade I, CA

Very bad CONDITION: Vacant OCCUPANCY: F (B) PRIORITY:

Brick-vaulted former spinning shed by Bonomi, Egyptian facade, 1836-40. Brick-vaulted roof with circular rooflights. Failure of tie bar has caused collapse of two front bays. Other bays vulnerable to similar failure. Remedial scheme agreed and underway.

Contact: Kathryn Gibson 01904 601939



SITE NAME: Hunslet Mill. Goodman Street. Hunslet, Leeds

Company

DESIGNATION: Listed Building Grade II\*

Poor CONDITION: Vacant OCCUPANCY: D (D) PRIORITY: Company OWNERSHIP:

Flax mill of 1838 with later infill in south block. Housing development agreed, but not yet underway. A permanent roof has recently been erected.

Contact: Catherine Dewar 01904 601972



St Marys Convent Church SITE NAME: (Mount Saint Mary), Church Road, Richmond Hill, Leeds

DESIGNATION: Listed Building Grade II\*

Poor CONDITION: Vacant OCCUPANCY: D (D) PRIORITY: Company OWNERSHIP:

Redundant Roman Catholic Church, 1852, by Joseph Hansom. Chancel and transepts by EW Pugin, 1866. Gothic style. Presbytery roof slates are partly missing, the windows are boarded and broken and the interior of the church has been stripped. Surveyed following concern of the Council for public safety. Holding works have been undertaken. Housing development has received consent.

Contact: Catherine Dewar 01904 601972



SITE NAME: Memorial to Queen Victoria, Woodhouse Lane, Woodhouse Moor, Leeds

DESIGNATION: Listed Building Grade II\*, CA

CONDITION: Poor

occupancy: Not applicable

C(C)PRIORITY-

Local authority OWNERSHIP:

1903 by Sir George Frampton. Portland stone base supporting an enthroned bronze statue of Queen Victoria. The base is flanked by bronzes of "Peace" and "Industry". The figure of Industry is severely damaged and now in store. The remaining bronzes are corroding. Formerly located in front of the Town Hall.

Contact: Catherine Dewar 01904 601972



Rothwell Castle, SITE NAME: Church Street (off),

Rothwell DESIGNATION: Scheduled Monument, CA

CONDITION:

occupancy: Not applicable

C(C)PRIORITY-

OWNERSHIP: Trust of an active Local Heritage Initiative scheme to investigate its surroundings.

Ruined chapel to medieval manor complex. C14.

Masonry needs to be consolidated. The site is part

Contact: Richard Jaques 01904 601986



Gazebo north of Clumpcliffe SITE NAME: Farmhouse, Methley Lane, Methley, Rothwell

DESIGNATION: Listed Building Grade II\*

Very bad CONDITION: Vacant OCCUPANCY: PRIORITY: B (B) OWNERSHIP: Private

Hunting lodge dated 1708 on rainwater heads. Total collapse of the front elevation. Temporary cover on the flanking roofs has failed. Residential conversion agreed. Work still not implemented other than removal of debris. Site fenced.

Contact: Catherine Dewar 01904 601972

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

## NOTE:

If the priority category has changed since the 2009 register, the previous category is given in brackets.

#### ABBREVIATIONS

Conservation Area CA LB/LBs Conservation Area Listed Building/s National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site NIP RPG SM/SMs UA WHS



Thorpe Hall, SITE NAME: Middleton Lane, Thorpe on the Hill

DESIGNATION: Listed Building Grade II\*

condition: Very bad occupancy: Vacant PRIORITY:

A(A)Private OWNERSHIP:

Former farmhouse, 1735. Unitary Development Plan proposes employment land use allocation (offices). Some windows broken and gutters failed. Ceiling collapsed in one room. Roof holed.

Contact: Catherine Dewar 01904 601972

Length of linear earthworks known as Becca Banks and The Ridge, part of the Aberford Dyke system,

	between Aberford and a quarry 590m nor	th of Ass Bridge, A	berford
DESIGNATION:	Scheduled Monument (No. 31516)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Linear earthwork, part of the Aberford Dy 770m east from Humphrey Dale Cottage,		ng
DESIGNATION:	Scheduled Monument (No. 31519)	CONDITION:	Extensive significant problems
	,		i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Dalton Parlours Roman villa and Iron Age	settlement, Bramha	am cum Oglethorpe
DESIGNATION:	Scheduled Monument (No. 29898)	CONDITION:	Extensive significant problems
	,		i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Cairn west of Craven Hall Hill, Leeds		
DESIGNATION:	Scheduled Monument (No. 25283)	CONDITION:	Generally unsatisfactory
	,		with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Medieval farmstead in Ireland Wood, 150m	n north east of Coo	okridge Hospital, Leeds
DESIGNATION:	Scheduled Monument (No. 31502)	CONDITION:	Generally unsatisfactory with major localised problems
	E	TREND:	Declining
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREIND:	Decilining

#### PRIORITY (FOR BUILDINGS)

PRINCIPAL VULNERABILITY:

DESIGNATION:

OWNERSHIP:

SITE NAME:

DESIGNATION:

OWNERSHIP:

PRINCIPAL VULNERABILITY:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

Extensive visitor erosion

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Scheduled Monument (No. 31527)

Scheduled Monument (No. 31528)

Stone hut circle settlement in Iveson Wood, Leeds

Extensive visitor erosion

Local Authority

Local Authority

F Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE:

CONDITION:

TREND:

CONTACT:

CONDITION:

TREND:

CONTACT:

If the priority category has changed since the 2009 register, the previous category is given in brackets.

Generally unsatisfactory

Declining

Declining

with major localised problems

Keith Miller 01904 601990

Generally unsatisfactory

with major localised problems

Keith Miller 01904 601990

#### **ABBREVIATIONS**

SITE NAME:	Linear earthworks known as Woodhouse Moor part of the Aberford Dyke system, Lotherton cur		uth Dyke,	
DESIGNATION:	Scheduled Monument (No. 31520)	CONDITION:	Generally unsatisfactory	
	,		with major localised problems	
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining	
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Howley Hall: a 16th century country house and gardens, Morley			
DESIGNATION:	Scheduled Monument (No. 29897)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining	
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Roman period native settlement in Danefield Wo	ood, 490m sc	outh west of Stubbings Farm, Otley	
DESIGNATION:	Scheduled Monument (No. 31500)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
OWNERSHIP:	Local Authority	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Roman period native settlement in Poolscar Woo	od, 350m sou	uth of Stubbings Farm, Otley	
DECICA IATION I.	Scheduled Monument (No. 31501)		Generally satisfactory	
DESIGNATION:	scheduled Monarhent (140, 31301)	CONDITION:	but with significant localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
OWNERSHIP:	Local Authority	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Settlement site revealed by aerial photography n	ear Moat Ho	ouse. Walton	
DESIGNATION:	Scheduled Monument (No. WY1195)	CONDITION:	Extensive significant problems i.e. under plough, collapse	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990	
	SITE NAME: Oulton Hall		leasure grounds laid out in part to designs by	
	DESIGNATION: Registered Park and Garden Grade II, also CA, 2 LBs	WA Nesfie hotel and g	Repton of 1809-10 with mid C19 additions by ld. Chequered C20 history and now split as a golf course. De Vere hotel group restored the	
	condition: Generally satisfactory but with significant localised problems	main buildir	ng.The garden layout survives in part but golf new development predominate.	
	VULNERABILITY: LOW			
	trend: Unknown			
Z S	ownership: Mixed, multiple owners	Contact: Ar	ndy Wimble 01904 601970	
	SITE NAME: High Royds Hospital, Aireborough	The ground	ds of an echelon-style psychiatric hospital, 1888, including airing courts, sports grounds,	
	DESIGNATION: Registered Park and Garden Grade II, also I LB	woodland and parkland. Hospital under conversion t residential use including extensive new build within the grounds. Historic landscape now significantly compro		
	condition: Extensive significant problems		eral areas neglected.	
	VULNERABILITY: High			
	TREND: Declining			
	OWNERSHIP: Mixed, multiple owners	Contact: Ar	ndy Wimble 01904 601970	
SITE NAME:	Buslingthorpe, Leeds			
DESIGNATION:	Conservation Area	CONDITION:	Poor	
VULNERABILITY:	High	TREND:	Expected to deteriorate	
	Richard Taylor (LA) 0113 247 8145		•	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# NOTE: If the priority category has changed since the 2009 register, the previous category is given in brackets.

SITE NAME:	Chapeltown, Leeds		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Expected to show some improvement
CONTACT:	Richard Taylor (LA) 0113 247 8145		
SITE NAME:	Holbeck, Leeds		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	No significant change expected
CONTACT:	Richard Taylor (LA) 0113 247 8145		
SITE NAME:	Stank Hall, Leeds		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Expected to deteriorate
CONTACT:	Richard Taylor (LA) 0113 247 8145		



Malt House approx 15 metres south west of Blacker Hall Farmhouse, Crigglestone Branch Road, Chevet

DESIGNATION: Listed Building Grade II\*

CONDITION: Very bad
OCCUPANCY: Vacant
PRIORITY: A (New)
OWNERSHIP: Private

Rare early-mid C17 malt-house located approx 15m south west of Blacker Hall Farmhouse. Impressive group value. Recent partial collapse of front wall, roof covering missing, roof timbers collapsing. Imminent danger of total collapse. Local Authority working closely with owner to find a sustainable future use.



SITE NAME: Pontefract Castle,
Pontefract

DESIGNATION: Scheduled Monument

CONDITION: Poor

OCCUPANCY: Not applicable

PRIORITY: B (B)

OWNERSHIP: Local authority

Substantial ruins comprising motte, bailey and Saxon cemetery. The fabric of the ruins needs substantial consolidation. A condition survey and Conservation Management Plan have been completed and discussions on future works are underway.

Contact: Richard Jaques 01904 601986

Contact: Kathryn Gibson 01904 601939



SITE NAME: Dovecote approximately
100 metres south of Sharlston Hall,
The Green, Sharlston

DESIGNATION: Listed Building Grade II, SM

CONDITION: Very bad

OCCUPANCY: Not applicable

PRIORITY: B (C)

OWNERSHIP: Private

Stone dovecote with pyramidal roof of uncertain date. Roof covering missing in part: much of the masonry is decayed and in dangerous condition.

Contact: Richard Jaques 01904 601986

SITE NAME:	Newland Preceptory, Newland with Woodhouse Moor		
DESIGNATION:	Scheduled Monument (No. 21052)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Digging	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990

SITE NAME:	Sharlston Common coal and ironstone workings, Sharlston		
DESIGNATION:	Scheduled Monument (No. 30962)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate vehicle damage/erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE: If the priority category has changed since the 2009 register, the previous category is given in brackets.

## gory R

ABBREVIATIONS
CA Conservation Area
LB/LBs Listed Building/s
NP National Park
RPG Registered Park and Garden
SM/SMs Scheduled Monument/s
UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Site of post-medieval tannery, Felkirk, South Hiendley		
DESIGNATION:	Scheduled Monument (No.WY1217)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Prehistoric enclosed settlement known as	South Kirkby Cam	p, South Kirkby and Moorthorpe
DESIGNATION:	Scheduled Monument (No. 31532)	CONDITION:	Generally unsatisfactory
	·		with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Keith Miller 01904 601990
SITE NAME:  DESIGNATION:	Earthwork west of Ferrybridge, Knottingley, Wakefield  Scheduled Monument (No. WY720)   CONDITION: Extensive significant problems		
DESIGNATION.	Scheduled Floriditient (140.441720)	CONDITION.	i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Ferrybridge near Knottingley,Wakefield		
DESIGNATION:	Scheduled Monument (No.WY75)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Keith Miller 01904 601990

#### WAKEFIELD / BARNSLEY / KIRKLEES



SITE NAME:	Bretton Hall, West Bretton
DESIGNATION:	Registered Park and Garden Grade II,
	also CA, 23 LBs
CONDITION:	Generally unsatisfactory
	with major localised problems
VULNERABILITY	Medium
TREND:	Declining
OWNERSHIP:	Mixed, multiple owners

Pleasure grounds of late C18 and early C19, parkland of C18 with earlier origins. Associations with Richard Woods and Robert Marnock. Part of parkland accommodates Yorkshire Sculpture Park, part country park. Hall is owned by Wakefield Council. Core of landscape significantly compromised by incremental development. Historic character of outer areas are suffering neglect. Part of park is in Kirklees and Barnsley. Conservation Management Plan for whole park nearing completion and will form basis for a unified management regime.

Contact: Andy Wimble 01904 601970

YORK (UA)			
SITE NAME:	Strensall		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Leigh Weston (LA) 01904 551329		
SITE NAME:	The Racecourse and Terry's Factory		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Leigh Weston (LA) 01904 551329		
SITE NAME:	Towthorpe		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Leigh Weston (LA) 01904 551329		

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### NOTE:

If the priority category has changed since the 2009 register, the previous category is given in brackets.

#### **ABBREVIATIONS**



This document is one in a series of publications produced as part of English Heritage's national Heritage at Risk campaign programme. More information about Heritage at Risk and other titles in the series can be found at www.english-heritage.org.uk/risk

HERITAGE AT RISK

Published July 2010 by English Heritage I Waterhouse Square, 138-142 Holborn, London ECIN 2ST