



NORTH EAST

Contents

HERITAGE AT RISK 3 Reducing the risks 7 Publications and guidance 10 THE REGISTER 12 12 Content and assessment criteria Key to the entries 15 North East heritage assets at risk 17 County Durham (UA) 18 26 Northumberland (UA) 49 Tees Valley Tyne and Wear 54



In its fourth year, the Heritage at Risk Register now includes grade I and II* listed buildings, listed places of worship, scheduled monuments, registered parks and gardens, registered battlefields, protected wreck sites and conservation areas known to be at risk as a result of neglect, decay or inappropriate development. This year, for the first time, we have published a list of 'priority sites': important heritage at risk sites where we will focus our resources to secure their futures.

"Information is not knowledge" mused Albert Einstein; meanwhile, in similarly thoughtful mode, Anton Chekhov stroked his beard and averred "knowledge is of no value unless you put it into practice". So whither the latest version of the Heritage at Risk Register in light of these caveats and what is English Heritage doing to avoid data collection without purpose?

Since 1998, the Register has grown from identifying grade I and grade II* buildings at risk to become a universal resource covering a range of heritage assets overground, underground and even under the sea. The 2011 version introduces listed places of worship known to be at risk. The Register is an ongoing work; the art is to weave in refinement whilst employing it as a tool to protect cherished historic fabric. That fabric could be rusting ironwork, as at Tynemouth Railway Station or vegetation-ravaged stonework on Overgrass Tower House, a reminder of the North East's border battleground past. These are two very different sites in scale, individual history and type of urgent work required to conserve them, yet they share a common factor in being included on the Register; a vital criterion in the decision-making process used when allocating English Heritage funding.

The concept of "partnership working" is fundamental. In the cases at Tynemouth, Overgrass and others, such as repairs to houses on the Ralph Erskine-designed Byker Estate, the ability of English Heritage to liaise with a wide array of individuals and organisations is imperative to the ignition, maintenance and ultimate success of a project. More co-operative working is embodied in the Heritage Partnership Agreement between English Heritage and the owner of a sizeable collection of scheduled monuments situated within a large swathe of Ingram Valley, Northumberland. Discussion and co-operation has produced a cohesive plan for the repair and future maintenance of the very different assets at Byker and Ingram Valley. The £233,933 of English Heritage grant aid it has taken to support these schemes is excellent value for money considering the gains in long-term protection and use of our heritage.

Despite these successes, warning bells are sounding. Over the past four years, the percentage of designated heritage assets at risk in the North East has fallen steadily from 7.4% in 2008 to 6.3% in 2011. Warning bells? Good news, surely? Well, the fact remains that, at 6.3% (compared to the national average of 3.0%), the North East still has the biggest percentage of its grade I and II* buildings at risk. And, whilst a recent survey showed that the region's stock of places of worship is in generally good repair, fifteen have been assessed as being in poor or very bad condition with an estimated $\pounds 2.9m$ required to repair them.

A total of \pounds 1.6m in grant aid was offered to sites in the North East during 2010/11; positive news derived from persistent, constructive liaison with many stakeholders. The very real danger is that the current squeeze on public and private sector resources, both human and monetary, will, in time, undermine this effort and see a reversal of many of the recent positive trends. It is at this point that the caveats expounded by Chekhov and Einstein will be very stark: we will have information but increasingly limited means to convert this into applied knowledge. Good news for rust and tree roots; bad news for iron and stone.

Carol Pyrah, Planning Director NORTH EAST

BUILDINGS AT RISK

- Nationally, 3.0% of grade I and II* listed buildings are at risk. In the North East this rises to 6.3%, representing 72 sites.
- 8 sites have been removed from the 2010 Register, but 4 have been added.
- 56% of entries (64 buildings) on the baseline 1999 Register for the North East have been removed as their futures have been secured, compared to the national figure of 53% (757 buildings).
- Nationally, £5.2m was offered to 71 sites on the Register during 2010/11. In the North East we awarded grants totalling £691k to 13 sites.
- 15 listed places of worship have been added to our Register this year. We estimate the cost of repairing these buildings is £2.9m.

SCHEDULED MONUMENTS

- 16.9% (3,339) of England's 19,748 scheduled monuments are at risk, compared to 13.4% (184 sites) in the North East.
- In the North East, 16 sites have been removed from the 2010 Register, but 6 sites have been added.
- 11.8% of entries (20 sites) on the baseline 2009 Register for the North East have been removed due to positive reasons, compared to the national figure of 11.9% (399 sites).
- Arable ploughing and unrestricted plant, scrub or tree growth account for nearly two thirds of sites at risk nationally. In the North East, the latter is responsible for 41% of sites at risk.
- Nationally, 82% of scheduled monuments at risk are in private ownership, this rises to 85% in the North East.
- Of the £357k offered by English Heritage to owners of scheduled monuments at risk in 2010/11, £55k was to 6 sites in the North East.

REGISTERED PARKS AND GARDENS

- 103 of England's 1,610 registered parks and gardens are at risk, an increase from 6.2% (99) in 2010 to 6.4% this year. In the North East, 3 of our 54 sites are at risk (5.6%).
- Nationally, 6 sites have been added and 2 removed from the 2010 Register. In the North East, 1 site has been added.

REGISTERED BATTLEFIELDS

- Of the 43 registered battlefields in England, 6 are at risk, 2 less than the 2008 baseline.
- Of the 6 registered battlefields in the North East, I is at risk.

PROTECTED WRECK SITES

• Of the 46 protected wreck sites off England's coast, 7 are at risk, 3 less than the 2008 baseline. There are no protected wreck sites off the coast of the North East.

CONSERVATION AREAS

- 288 local planning authorities (86%) have taken part in the national survey of conservation areas, of which I 3 are in the North East. This is all our local planning authorities.
- We now have information on the condition of 7,841 of England's 9,600 designated conservation areas and 516 (6.6%) are at risk.
- Of the 265 conservation areas surveyed in the North East, 16 (6%) are at risk.



DOVECOTE AT BARFORTH HALL, COUNTY DURHAM The Art of Consolidation – the dovecote pictured after repair works were completed.

IN THE NORTH EAST:









INDUSTRIAL HERITAGE

Britain was the world's first industrial nation and has a wealth of industrial heritage but many industrial sites have been lost or are at risk due to functional redundancy. Our survey has shown that the percentage of listed industrial buildings at risk is three times greater than the national average for listed buildings at risk.

The conservation of industrial sites can pose considerable challenges. However, industrial sites often have great potential for re-use. Our research shows that the best way of saving industrial buildings is, where possible, to find an adaptive new use. We know this isn't easy, and is not always possible, but we hope those who own or are thinking of developing an industrial building will find our new web pages an invaluable source of information.

Voluntary groups and owners have saved a number of key industrial sites, often sites which contain working machinery. However, research has shown that many of these groups need support to encourage more and younger members to achieve the rescue of the site.

Building preservation trusts can provide the answer for industrial buildings where there is no apparent commercial solution by repairing the site and then selling it, or retaining and letting the space.

What we know

- 4% of listed buildings and scheduled monuments are industrial
- Nationally there are proportionally more grade II* industrial listed buildings than grade II (4.6% compared to 4.4%)
- 10.6% of industrial grade I and II* listed buildings are at risk, making industrial buildings over three times more likely to be at risk than the national average for grade I and II* listed buildings
- The average estimated conservation deficit (cost of repair in excess of the end value) of industrial buildings at risk is twice that of non-industrial buildings at risk
- About 10% of industrial buildings at risk are economic to repair, compared to 13% of non-industrial buildings at risk
- Approximately 40% of industrial buildings at risk are capable of beneficial use, compared to 44% of non-industrial buildings at risk
- 10.9% of industrial scheduled monument are at risk, making industrial scheduled monuments less likely to be at risk than the national average for scheduled monuments
- 3% of conservation areas were designated because of their industrial significance
- Industrial conservation areas in the North West and West Midlands are over twice are likely to be at risk than the national average
- In the last 10 years, English Heritage has offered grants totalling $\pounds 25m$ to industrial sites



HYDRAULIC SILO, CRAGEND FARM, NORTHUMBERLAND Abandoned Experiment – this hydraulic silo is the legacy of a rare failed experiment by the great industrialist Lord Armstrong.

What are we doing?

- Providing new guidance for owners on maintaining vacant historic buildings.
- Publishing a developers' portal on the English Heritage website where advice for all types of heritage asset including industrial sites can be found.
- Funding a new Industrial Heritage Support Officer, who will build capacity for industrial museums.
- Publishing an industrial themed issue of Conservation Bulletin in October 2011.
- Supporting a new Architectural Heritage Fund grant scheme which aims to encourage local groups to take on industrial buildings.
- Publishing an updated Stopping the Rot: a guide to enforcement action to save historic buildings.
- Using the National Heritage Protection Programme (2011-2015) to shape an industrial designation programme.


If you are a developer, member of a building preservation trust, work in a local authority, own a visitor attraction or have an interest in England's industrial heritage, visit our website for more information:

www.english-heritage.org.uk/industrial-heritage-at-risk

PRIORITY SITES

- Bowes Railway Incline, Birtley, Gateshead
- Greenhouse east of Felton Park with potting shed, Felton Park, Felton, Northumberland
- Harperley Working Camp, WWII POW Camp at Craigside, Wolsingham, County Durham
- Kirkleatham Hall Stables and Landscape (Kirkleatham Hall Stables, Bastion and ha-ha wall north of Kirkleatham Hall Stables, Bastion north west of Kirkleatham Hall Stables, Gate piers at entrance of Kirkleatham Hall School and the, Gatehouse, north east of Kirkleatham Hall), Redcar, Tees Valley
- Monastic cell and medieval tower, Coquet Island, Hauxley, Northumberland
- Prebends' Bridge, Durham and Framwellgate, Durham, County Durham
- Ravensworth Castle, Lamesley (Ravensworth Castle and Nash House), Gateshead
- Sockburn Hall and Church (Sockburn Hall, and the Church of All Saints) Sockburn Lane, Sockburn, Darlington
- Tynemouth Station, Tynemouth, North Tyneside
- Ushaw College, Esh (Chapel of St Michael at College of St Cuthbert, Former Junior Seminary Chapel of St. Aloysius and Bounds Wall), County Durham

CONTACT: Stephen Allott, Business Manager, English Heritage North East, Bessie Surtees House, 41-44 Sandhill, Newcastle upon Tyne, NEI 3JF. Telephone: 0191 269 1235 Fax: 0191 261 1130 Email: **stephen.allott@english-heritage.org.uk**



For more information on Heritage at Risk visit **www.english-heritage.org.uk/risk**

If you would like this document in a different format, please contact our customer services department on telephone: 0870 333 1 181 fax: 01793 414926 textphone: 01793 414878 email: customers@english-heritage.org.uk



Vhen you have finished with this report please recycle it



COVER IMAGE: Bowes Railway, Gateshead, Building at Risk and Priority Site

Reducing the risks

English Heritage is committed to securing a year-on-year reduction in the number of heritage sites at risk as part of our national plan for the protection of England's historic environment (National Heritage Protection Plan 2011-2015). This will be challenging given the number of assets now on the Register and the different kinds of risk they face. Each asset type and individual case will require its own approach and solution.

There are, however, some general approaches that are relevant to all assets at risk. Resolving cases requires working in close partnership with owners, local planning authorities and other relevant organisations and partners. Advice and understanding are essential. Historic Environment Records, maintained by local authorities, are repositories of information on local historic assets. They underpin the work of local authority historic environment services and can help improve the protection, conservation and management of heritage assets.

Maintenance of heritage assets is essential if they are not to become at risk, and to prevent those that are already at risk from decaying further and thereby escalating the cost of their repair and consolidation. Buildings, for instance, decay rapidly when left empty. Avoiding vacancy through short-term lets or schemes that provide protection through residential occupation are low-cost ways of maintaining buildings until permanent solutions can be found. English Heritage has published guidance for owners on options for maintaining vacant buildings (*Vacant Historic Buildings: An Owner's Guide to Temporary Uses, Maintenance and Mothballing*).

English Heritage provides on-line advice and guidance to local authorities, owners and managers of sites through the Historic Environment Local Management (HELM) website **www.helm.org.uk**.

LISTED BUILDINGS Buildings at risk

English Heritage's role in securing the future of buildings at risk is primarily to provide practical advice, guidance and resources to local authorities, owners and developers. Our involvement in cases is determined by the importance of the building and the complexity of the issues. We can help with analysis of the issues, investigation of the feasibility of options and brokering solutions. Although buildings at risk will continue to be a priority for English Heritage repair grants, grant aid is limited in relation to demand. Grants from other public sources, notably the Heritage Lottery Fund, continue to be essential in helping secure the future of buildings at risk. In very exceptional cases, English Heritage may acquire and repair a particularly important building at risk, where it is clear that the scale and complexity of problems are such that direct involvement is the best way of securing the building's long-term future.

Local authorities have a primary role in protecting the historic environment. The creation of a local heritage at risk register is the first step in tackling neglected buildings in order to assess and monitor the scale of the problem and prioritise resources and action. Local authorities can also take action to secure the preservation of historic buildings through the use of statutory notices. Some local authorities have a successful track record, but generally these powers are under-used. It is essential that local authorities make best use of their powers to secure buildings at risk, to 'stop the rot' and prevent the costs escalating beyond the point where it is economic to repair. For this reason, English Heritage has published revised guidance (Stopping the Rot) for local planning authorities on taking action to save historic buildings.

To help local authorities make more frequent and timely use of their statutory powers, English Heritage runs grant schemes to underwrite a significant proportion of the irrecoverable costs involved in serving Urgent Works Notices and Repairs Notices.

Building preservation trusts can be the key to saving many buildings at risk. Some trusts cover geographical areas; others specialise in particular types of building or are formed to save just one building. Determined individuals and trusts have saved numerous buildings at risk, working in partnership with other organisations such as local and national amenity societies, including SAVE Britain's Heritage, the Society for the Protection of Ancient Buildings, the Georgian Group, The Victorian Society and the Twentieth Century Society.

Places of worship at risk

Regular maintenance helps to keep buildings and places of worship in good condition but those that are in poor or very bad condition need help to minimise the risks to both the structure and the contents. Keeping drains and gutters clear so that water is taken away from the building efficiently is the most important thing that congregations can do as it stops small problems in the building fabric developing into unnecessary crises. English Heritage supports the Society for the Protection of Ancient Buildings's Faith in Maintenance scheme, giving volunteers practical local training and on-going support. It also encourages the establishment of gutter-clearance projects, enabling congregations to get good quality work done at reasonable prices by reputable contractors.

Where major structural repairs are required, the Repair Grants for Places of Worship scheme helps under resourced buildings in urgent need. The Listed Places of Worship scheme is another source of funding for repairs and maintenance that is available more widely, while local and national charities can offer small grants.

Many congregations wish to adapt and change their places of worship to encourage wider community use alongside worship and faith-focussed events. English Heritage supports the efforts of congregations to keep their places of worship in use wherever possible and welcomes proposals for appropriate new facilities such as kitchens and toilets that are sensitive to the building's special character.

English Heritage is aware of the need for practical, hands-on help to be given to individual congregations and is working with partner organisations to enable this. Support Officers are employed by local denominational groups but part-funded by English Heritage. They give advice and encouragement to congregations so that they can achieve repair projects, develop necessary new facilities or re-engage with the wider community, depending on local circumstances and needs.

SCHEDULED MONUMENTS

The continuing success in reducing the number of monuments at risk, even in difficult economic times, demonstrates the value of the dialogue that the initiative has fostered between English Heritage, owners, managers and other partners. More and more owners and managers of scheduled monuments are addressing their long-term care on a regular basis. Over half of all scheduled monuments are now on land subject to an agreement under Natural England's Environmental Stewardship agri-environment scheme, administered on behalf of Defra. Work in the coming years with Defra and Natural England will concentrate upon ensuring that the right options are being used in the correct way, maximising the conservation benefits whilst at the same time delivering value for money. We will also work closely with the Heritage Lottery Fund to help identify those important monuments deserving of grant aid for major stabilisation or repair work.

Progress is also reliant upon better understanding. As a result, as part of the National Heritage Protection Plan – which sets out English Heritage's commitment to safeguarding heritage up to 2015 – the Conservation of Scheduled Monuments in Cultivation project will be rolled out nationally from 2011 onwards. The project, already successfully trialled amongst farmers in the East Midlands, will address what is still the biggest threat by far to monuments – their gradual degradation and loss through arable cultivation. Some causes of risk are neither so obvious nor dramatic in their effects however. Heritage at risk shows that unmanaged tree, scrub and bracken growth is the most widespread cause of long term damage to both urban and rural monuments, even if the effects are not as visible or immediately destructive as other processes. Further work will therefore be needed to better understand how these effects can be minimised.

In all cases, however – whether for rural or urban monuments – close co-operation with owners and land managers is still key to making further progress in ever more challenging circumstances.

REGISTERED PARKS AND GARDENS

Inclusion on the Register of Historic Parks and Gardens of Special Historic Interest brings no additional statutory controls, but there is a presumption in favour of the conservation of all designated assets in the planning system. The Government's Planning Policy Statement 5 *Planning for the Historic Environment* (PPS 5) and its supporting Practice Guide helps planning authorities to assess and mitigate the impact of development on our irreplaceable heritage of designed landscapes.

English Heritage can engage only with the proposals for change to the highest graded designed landscapes and where the impact on historic significance is greatest. Our landscape architects can help tailor plans and funding packages for individual landscape features as well as strategies for the whole site. We will continue to tackle the skills crisis facing historic parks and gardens through sector-wide initiatives.

English Heritage encourages the development of conservation management plans for registered historic parks and gardens, especially those in multiple ownership. We are keen for bursars and estate teams to use management plans to help conserve important but fragile landscapes in the care of schools, hospitals, hotels and other institutional owners.

REGISTERED BATTLEFIELDS

As with registered parks and gardens, this designation brings no additional statutory controls, but there is a presumption in favour of conservation of registered battlefields in Planning Policy Statement 5.

English Heritage will continue to work with owners to develop management plans for registered sites and, in appropriate cases, contribute towards the cost of management plans. We will develop positive landscape strategies with owners and partners such as Defra. In some circumstances, we may encourage the conversion from arable to pasture of especially sensitive locations to protect battlefield archaeology from the effects of ploughing and as part of a wider drive to prevent unauthorised or damaging metal-detecting.

English Heritage will also continue to encourage greater access to battlefields and improve their amenity value and visitors' appreciation of the impact these historic events had on our development as a nation.

Local authorities can also invite comments from the Battlefields Trust on planning applications affecting the setting of registered sites.

PROTECTED WRECK SITES

At the strategic level, the major sources of risk to designated wreck sites have been identified. In terms of high-priority sites, practical requirements have also been implemented through conservation management plans.

Risks to protected wreck sites can often be reduced through education, provision of marker buoys, or planning policies that take full account of their national importance. However, some sites require significant resources to stabilise their condition or to carry out detailed archaeological assessments of their conservation requirements. Although English Heritage has statutory power to allocate funds to promote the preservation and maintenance of protected wreck sites, its financial resources can solve only a small proportion of the problems.

In spite of the inherent difficulties with caring for this type of site, careful management must be maintained if we are to avoid the loss of wreck sites. It is therefore close co-operation between the owners of protected wreck sites (where known), authorised divers and all organisations charged with care for the marine and coastal environment, that will make the real difference to their long-term survival.

Practical advice on the management of historic wreck sites, whether at the coast-edge or under water, is available from English Heritage (maritime@english-heritage.org.uk) and from www.helm.org.uk

CONSERVATION AREAS

The risks to conservation areas are difficult to address as they cover large areas of land: they include the spaces between buildings and trees as well as buildings and structures and therefore involve many different owners. Looking after them is a responsibility shared by those of us who own homes and businesses in them and those of us whose job it is to manage the spaces between the buildings or make decisions about their future.

The conservation area survey provides us with an understanding of what is particularly affecting the character and appearance of our conservation areas: what is working well or what is putting them at risk. Strong planning policies, guidance and a clear management strategy for individual conservation areas are critical in managing change in these areas. This is difficult at a time when local authorities across the country are reducing the number of staff managing changes in conservation areas. There are, of course, opportunities for members of the local community to engage, either individually or through groups such as civic societies or conservation area advisory committees which are proven to help achieve positive action.

Armed with the information provided by the surveys, we, local authorities and other partners will have the evidence to direct resources much more accurately towards those conservation areas at greatest risk. We will also want to target those with the greatest potential to improve the quality of life and economic prospects of people in the villages, towns and cities of which they are such crucially important components.

Publications and guidance

English Heritage has produced the following publications relating to heritage at risk, including:

Buildings at Risk: a New Strategy (1998)

Caring for Places of Worship 2010 (2010) – a report on the condition of England's listed places of worship and the needs of the congregations

Heritage at Risk 2010

Heritage at Risk: Conservation Areas (2009)

Heritage at Risk 2011 – national report and summaries for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, Yorkshire and the Humber

Heritage at Risk Register 2011 – detailed listings for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, Yorkshire and the Humber can be downloaded from our website or viewed as an interactive database: www.english-heritage.org.uk/risk

Monuments at Risk (2008) – summary of scheduled monuments at risk for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, Yorkshire and the Humber

Protected Wreck Sites at Risk: A Risk Management Handbook (2007)

Saving London: 20 Years of Heritage at Risk in the Capital (2010)

Stopping the Rot: A Guide to Saving Historic Buildings Through Enforcement Action (2011)

The Monuments at Risk initiative 2003–08 (2010)

Vacant Historic Buildings: An Owner's Guide to Temporary Uses, Maintenance and Mothballing (2011)

HERITAGE AT RISK ON THE WEB

To find out more about the Heritage at Risk programme visit **www.english-heritage.org.uk/risk** where you will find an interactive database providing detailed information on all heritage sites at risk nationally.

For further information about the different classes of designated heritage assets, including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites visit the Heritage Protection section of our website **www.english-heritage.org.uk/heritageprotection**. Details of all nationally designated historic places in England are now available in one place on the National Heritage List for England online database: **http://list.english-heritage.org.uk**

CONSERVATION POLICIES AND GUIDANCE

The following publications are among the numerous helpful guidance documents now available on our website: www.english-heritage.org.uk/publications or www.english-heritage.org.uk/helm

Caring for Places of Worship (2010) – a practical booklet for everyone involved in caring for England's listed places of worship

Constructive Conservation in Practice (2008)

Conservation Principles, Policies and Guidance for the Sustainable Management of the Historic Environment (2008)

Creativity and Care: New Works in English Cathedrals (2009)

Enabling Development and the Conservation of Significant Places (2008)

Farming the Historic Landscape: Caring for Archaeological sites on Arable Land (2004)

Farming the Historic Landscape: Caring for Archaeological Sites in Grassland (2004)

Guidance on the Management of Conservation Areas (2006)

Guidance on Conservation Area Appraisals (2006)

Guidance Notes and Application Forms for Grants to Local Authorities:

- Grants to Local Authorities to Underwrite Urgent Works Notices (1998)
- Acquisition Grants to Local Authorities to Underwrite Repairs Notices (1998)
- Grants for Historic Buildings, Monuments and Designed Landscapes (2004)

Heritage at Risk: Conservation Areas (2009) – guidance for local authorities

Managing Local Authority Heritage Assets: Some Guiding Principles for Decision Makers (2003)

New Uses for Former Places of Worship (2010)

Options for the Disposal of Redundant Churches and Other Places of Worship (2010)

Paradise Preserved: An Introduction to the Assessment, Evaluation, Conservation and Management of Historic Cemeteries (2002)

Scheduled Monument Consent: a Guide for Owners and Occupiers (2009)

Shared Interest: Celebrating Investment in the Historic Environment (2006)

The Disposal of Historic Buildings: Guidance Note for Government Departments and Non-Departmental Public Bodies (2010).

Valuing Places: Good Practice in Conservation Areas (2011)

If you would like further information about any of these publications, please contact:

English Heritage Customer Services Department PO Box 569, Swindon SN2 2YP Telephone: 0870 333 1181 Fax: 01793 414926 Email: customers@english-heritage.org.uk

THE REGISTER Content and criteria

DESIGNATION

All the historic environment matters but there are some elements which warrant extra protection through the planning system. Since 1882, when the first Act protecting ancient monuments and archaeological remains was passed, government has been developing the designation system. Listing emerged from the post-blitz 1940s Planning Acts, and is now applied to about half a million buildings ranging from palaces to street lamps. Almost 20,000 archaeological sites are scheduled, which introduces tight management controls. Some 1,610 designed landscapes are registered, as are 43 battlefields, and 46 wreck sites are protected.

English Heritage, as the government's expert adviser, is responsible for making recommendations – but it is still the Secretary of State at the Department for Culture Media and Sport who makes the decisions on whether a site is designated. Understanding and appreciation develop constantly, which makes keeping the designation base up-to-date a never-ending challenge. While responding to threat-driven cases, we also seek to work strategically. Recent developments have seen a greater striving for openness and transparency in the process of designating a site, and better communication of what makes something special.

Conservation areas are designated locally by local planning authorities. They are areas of special architectural or historic interest the character or appearance of which it is desirable to preserve or enhance.

LISTED BUILDINGS Definition

A listed building is a building (or structure) that has been designated as being of 'special architectural or historic interest'. The older and rarer a building is, the more likely it is to be listed. Buildings less than 30 years old are listed only if they are of outstanding quality and under threat.

Listed buildings are graded I, II* and II. Grade I and II* are particularly important buildings of outstanding interest; together they amount to 8% of all listed buildings. The remaining 92% are of special interest and are listed grade II. Entries on the statutory list of buildings of special architectural or historic interest may comprise a number of separate buildings. Formal residential terraces are the most obvious example. Entries on this Register reflect how buildings are grouped and recorded on the statutory list.

Structures can occasionally be both listed as buildings and scheduled as monuments.

Criteria for inclusion on this Register

Buildings (not in use as a public place of worship) considered for inclusion on this Register must be listed grade I or II*, (or grade II in London) or be a structural scheduled monument. Buildings are assessed for inclusion on the basis of condition and, where applicable, occupancy (or use). The condition of buildings on the Register ranges from 'very bad' to 'poor', 'fair' and (occasionally) 'good'. The Register also includes buildings that are vulnerable to becoming at risk because they are empty, under-used or face redundancy without a new use to secure their future.

Occupancy (or use) is noted as 'vacant', 'part occupied', 'occupied', or occasionally, 'unknown'; for many structural monuments, occupancy is not applicable.

Assessing vulnerability in the case of a building in fair condition necessarily involves judgement and discretion. A few buildings on the Register are in good condition, having been repaired or mothballed, but a new use or owner is still to be secured.

Buildings are removed from the Register when they are fully repaired/consolidated, their future secured, and where appropriate, occupied or in use.

Listed places of worship

Places of worship are the largest single group of non-domestic historic buildings still in use primarily for the purpose for which they were built. Their complex development over centuries is a testament to the changes in social, political and liturgical attitudes over time. This reflects the developing mission of congregations and means that they protect a wide range of fittings and furnishings of national and international, importance. Their architectural, archaeological, aesthetic and historic significance is outstanding but so too is their value as the record of the endeavours and experiences of individuals and communities.

To date English Heritage has assessed only a small proportion of the 14,500 listed places of worship so the number identified so far as 'at risk' and included on this year's Register is small. In the coming years an increasing number of places of worship will be assessed to identify those that are at risk. Future registers will provide stronger evidence and build up our understanding of the challenges.

Criteria for inclusion on this Register

Places of worship considered for inclusion on this Register must be listed grade I, II* or II and be used as a public place of worship at least six times a year.

Places of worship are assessed on the basis of condition only. If the place of worship is in 'very bad' or 'poor' condition it is added to the Register. Places of worship previously included on the Register may be in any condition category.

Once on the Register, all places of worship can move through the condition categories (e.g. from very bad to poor, to fair, even good) as repairs are implemented and the condition improves, until they are fully repaired and can be removed from the Register.

Priority for action

Once a building is identified as at risk or vulnerable and included on the Register, priority for action is assessed on a scale of A to F, where 'A' is the highest priority for a building which is deteriorating rapidly with no solution to secure its future, and 'F' is the lowest priority where a repair scheme is in progress and an end use has been secured.

SCHEDULED MONUMENTS Definition

Scheduled monuments include archaeological sites and landscapes, and 19,731 examples have been designated because of their national importance. Scheduled monuments are not graded, and most have limited potential for beneficial use. They cover human activity from the prehistoric era, such as burial mounds, to 20th century military and industrial remains. For the millennia before written history, archaeology is the only testament to innumerable generations of people of whom there is no other record.

The later 20th century saw unprecedented changes to the landscape. As a result, types of historic site that once were commonplace began to become rare. Those that survive often represent just small islands of what once characterised broad sweeps of our towns and countryside. Although protected by law, scheduled monuments are still at risk from a wide range of processes. In particular, they can frequently be exposed to intense pressures beyond the reach of the planning system. These include damage from cultivation, forestry and – often most seriously of all – wholly natural processes such as scrub growth, animal burrowing and erosion.

Criteria for inclusion on this Register

Scheduled monuments included on this Register have been identified as being at risk because of their condition and vulnerability, the trend in their condition, and their likely future vulnerability. A site's condition is expressed in terms of the scale and severity of adverse effects on it, ranging from those with 'extensive significant problems' to others that have only 'minor localised problems'.

Monuments are removed from the Register once sufficient progress has been made to address identified issues, demonstrating a significant reduction in the level of risk.

REGISTERED PARKS AND GARDENS Definition

There are 1,610 designed landscapes on the current English Heritage *Register of Historic Parks and Gardens of Special Historic Interest*. These registered landscapes are graded I, II* or II, and include private gardens, public parks and other green spaces, country estates and cemeteries. They are valued for their design, diversity and historical importance and in contrast to the number of listed buildings and scheduled monuments, registered parks and gardens is a very small group of assets.

Inclusion on the English Heritage Register of Historic Parks and Gardens brings no additional statutory controls, but there is a presumption in favour of conservation of the designated site. Local authorities are required to consult English Heritage on applications affecting sites registered as grade I or II* and the Garden History Society on sites of all grades.

Criteria for inclusion on this Register

The identification of registered parks and gardens at risk begins with an appraisal of the condition and vulnerability of each registered landscape. Steps being taken by owners to address problems are also taken into consideration.

Landscapes assessed as being at risk are typically affected by development and neglect. They have frequently been altered by development or are faced with major change. The original function of these landscapes has often changed; and divided ownership often results in the loss of the cohesive conservation of the historic designs.

Landscapes are removed from the Register once plans are put in place to address issues and positive progress is being made.

REGISTERED BATTLEFIELDS Definition

English Heritage's Register of Historic Battlefields has identified 43 nationally significant sites ranging in date from 991 to 1685. These are places where people risked their lives fighting for a cause and where history was made. The outcome of these battles was influenced by where they were fought and traces of the events will have been left across the landscape. Battlefields are cherished for many reasons, as a commemoration of the event and those who died, as a resource for understanding the course of the battle, and for the light they can shed on the times in which the battle was fought. They are vulnerable to insensitive development and to poorly managed investigation such as large-scale metal-detecting. While this designation introduces no additional statutory controls, one of its primary objectives is to encourage policies and other mechanisms that ensure that change and development affecting battlefields is sensitive and appropriate.

Criteria for inclusion on this Register

Battlefields deemed to be at risk of loss of historic significance are included on this Register.

The identified risks and threats come from development pressure – for example, because they lie on urban fringes or are subject to development pressures within the site; arable cultivation, and unregulated metal-detecting. One major impact or a combination of several factors can be enough to raise the risk at a particular site.

Battlefields are removed from the Register when either actual damaging activities are reversed or managed, or threats recede due to effective management planning.

PROTECTED WRECK SITES Definition

England's 46 protected wreck sites represent a tiny proportion of the 32,476 pre-1945 wrecks and recorded casualties that are known to lie in the territorial sea. Wreck sites can be of importance for different reasons: the distinctive design or construction of a ship, the story it can tell about its past, its association with notable people or events, its cargo, flora and fauna or its role as a focus for the local community. The Protection of Wrecks Act 1973 empowers the appropriate Secretary of State to designate a restricted area around a vessel to protect it or its contents from unauthorised interference.

Local authorities are able to react to foreshore infrastructure projects through the planning process, thereby securing the preservation of important remains in this intertidal zone.

Criteria for inclusion on this Register

English Heritage has audited all designated wreck sites to identify those most at risk based on their current condition, vulnerability and the way they are being managed. Wrecks are vulnerable to both environmental and human impacts. Risks that contribute to the inclusion on the Register range from unauthorised access to erosion and fishing damage.

The monitoring process ensures that the significance of the site is identified and maintained.

In spite of the inherent difficulties in caring for this type of site, careful management must be maintained.

Wrecks are removed from the Register once an appropriate management and monitoring regime is operational.

CONSERVATION AREAS Definition

Conservation areas are designated by local authorities and are areas of special architectural or historic interest the character or appearance of which it is desirable to preserve or enhance. For more than 40 years conservation areas have proved a highly effective mechanism for managing change on an area-wide basis. There are currently some 9,300 conservation areas in England including town and city centres, suburbs, industrial areas, rural landscapes, cemeteries and residential areas. They form the historic backcloth to national and local life and are a crucial component of local identity and community cohesion.

Criteria for inclusion on this Register

English Heritage has asked every local authority in England to complete (and update as appropriate) a survey of its conservation areas, highlighting current condition, threats and trends, identifying those that are deteriorating, or are in very bad or poor condition and are not expected to change significantly in the next three years, as being defined as at risk.

The methodology for assessing conservation areas at risk has been refined since the first survey in 2008/2009. The information collated provides a detailed assessment of each conservation area and an overall category for condition, vulnerability and trend is included for each conservation area on this Register. Conservation areas identified as at risk in 2009, but not reassessed since using the revised methodology, are included on the Register but with more limited information.

Conservation areas are removed from the Register once plans have been put in place to address the issues that led to the conservation area being at risk, and once positive progress is being made.

Key to the entries

This register includes the following heritage assets at risk:

- grade I and II* listed buildings and structural scheduled monuments
- grade I, II* and II listed places of worship
- scheduled monuments
- registered parks and gardens
- registered battlefields (where applicable)
- protected wreck sites (where applicable)
- conservation areas

ORDER

Entries are grouped and ordered alphabetically first by County* or Unitary Authority, and then by Local Planning Authority (Unitary Authority/National Park/District or Borough).

Asset types are grouped within the relevant planning authority in the following order:

- listed buildings and structural scheduled monuments
- places of worship
- scheduled monuments
- registered parks and gardens
- registered battlefields
- conservation areas

Within each asset type, sites are ordered alphabetically by parish, locality, street/site name.

*The sub-region Tees Valley is included to group the following unitary authorities: Darlington, Hartlepool, Middlesbrough, Redcar and Cleveland, Stockton-on-Tees.

DESIGNATION

The principal designation is noted for each entry, and includes:

- Listed Building (LB) grade I, II* or II
- Listed Place of Worship grade I, II* or II
- Scheduled Monument (SM)
- Registered Park and Garden (RPG) grade I, II* or II
- Registered Battlefield
- Conservation Area (CA)

Other designations that apply to buildings at risk and registered parks and gardens at risk, including their location within a World Heritage Site (WHS), are also noted where applicable.

The National Heritage List for England reference number is noted for scheduled monuments.

CONDITION

For buildings (including places of worship) at risk, condition is graded as: 'very bad', 'poor', 'fair' and 'good'.

For sites that cover areas (scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites) one overall condition category is recorded. The category may relate only to the part of the site or monument that is at risk and not the whole site:

- extensive significant problems
- generally unsatisfactory with major localised problems
- generally satisfactory but with significant localised problems
- generally satisfactory but with minor localised problems
- optimal
- unknown (is noted for a number of scheduled monuments that are below-ground and where their condition cannot be established).

For conservation areas, condition is categorised as: 'very bad', 'poor', 'fair' and 'optimal'.

OCCUPANCY / USE

For buildings (excluding places of worship) that can be occupied or have a use, the main vulnerability is vacancy, or under-use. Occupancy (or use) is noted as follows:

- vacant
- part occupied
- occupied
- unknown
- not applicable

VULNERABILITY

Principal vulnerability is noted for scheduled monuments and may relate only to the part of the monument which is at risk, and include:

- animal burrowing
- arable ploughing
- coastal erosion
- collapse
- deterioration in need of management
- scrub / tree growth
- visitor erosion.

For registered parks and gardens, registered battlefields, protected wreck sites and conservation areas, vulnerability is noted as high, medium or low.

PRIORITY

For buildings at risk, the following priority categories are used as an indication of trend and as a means of prioritising action:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- **B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

If the priority category has changed since the 2010 Register, the previous category is given in brackets.

TREND

Trend for scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites may relate only to the part of the site that is at risk and is categorised as:

- declining
- stable
- improving
- unknown

For conservation areas trend is categorised as:

- deteriorating
- deteriorating significantly
- no significant change
- improving
- improving significantly
- unknown

OWNERSHIP

A principal ownership category is given for each entry, although many scheduled monuments, registered parks and gardens, and registered battlefields are in divided ownership. For registered parks and gardens, single or multiple ownership is noted.

CONTACT

This is the member of the English Heritage regional team who acts as a first point of contact for the case, and to whom enquiries should be addressed.

For conservation areas, the contact is the conservation/planning officer at the relevant local planning authority (indicated by 'LPA' on the Register).

We are not in any sense agents for the owners of the sites included, but we will endeavour to put people in touch with them where appropriate.

ABBREVIATIONS

CA	Conservation Area
EH	English Heritage
HLF	Heritage Lottery Fund
LA/LPA	Local Planning Authority
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

North East heritage assets at risk

	Buildings at risk	Places of worship at risk	Scheduled monuments at risk	Registered parks and gardens at risk	Registered battlefields at risk	Protected wreck sites at risk	Conservation areas at risk
COUNTY DURHAM (UA	N)						
County Durham (UA)	28	2	22		0	0	6
NORTHUMBERLAND (U	A)						
Northumberland (UA)	42	3	57	2	0	0	0
NORTHUMBERLAND (N	IP)						
Northumberland (NP)	2	0	61	0	0	0	0
TEES VALLEY							
Darlington (UA)	4	4	2	0	0	0	3
Hartlepool (UA)	0		2	0	0	0	0
Middlesbrough (UA)	L	0	0	0	0	0	0
Redcar and Cleveland (UA)	8	0	2	0	0	0	3
Redcar and Cleveland (UA) / North York Moors (NP)*	0	0	I	0	0	0	0
Stockton-on-Tees (UA)	2	0	0	0	0	0	0
TYNE AND WEAR							
Gateshead	6	0	3	0	0	0	0
Newcastle upon Tyne	6	3	I	0	0	0	0
Newcastle upon Tyne / Gateshead*	0	0	0	0	I	0	0
North Tyneside	2	0	0	0	0	0	1
South Tyneside	2		0	0	0	0	1
Sunderland	5		2	0	0	0	2
TOTAL	108	15	153	3	I	0	16

The sub-region Tees Valley is included to group the following unitary authorities: Darlington, Hartlepool, Middlesbrough, Redcar and Cleveland, Stockton-on-Tees *Sites that cross LPA boundaries

COUNTY DURHAM (UA)		
4	SITE NAME:	West Mural Tower at Auckland Castle, Auckland Castle Park, Bishop Auckland	Two-storey viewing tower in the grounds of Auckland Castle. C13, with later alterations. The building requires urgent consolidation works as there is immediate risk of loss of historic fabric.
Contraction of the second	DESIGNATION:	Listed Building Grade I, CA, RPG II*	
A STATE	CONDITION:	Very bad	
the seal of the	OCCUPANCY:	Vacant	
	PRIORITY:	A (A)	
	OWNER TYPE:	Charity	Contact: Carol Pyrah 0191 2691 202
	SITE NAME:	Brancepeth Castle, Brancepeth	Brancepeth Castle is a medieval fortress that was greatly enlarged in the C19 by architects John Paterson and, later, Anthony Salvin. It was occupied by the army during World War II and then by glassware makers JA Joblings.
	DESIGNATION:	Listed Building Grade I, CA, RPG II	Parts of the building are currently lived in and some areas
	CONDITION:	Poor	are used as workshops and offices. There is a need for
	OCCUPANCY:	Part occupied	some urgent repairs as well as longer term maintenance.
	PRIORITY:	C (C)	
	OWNER TYPE:	Private	Contact: Kate Wilson 0191 269 1221
	SITE NAME:	Hedleyhill Colliery Coke Works, 500m south west of Hazlet House, Brandon and Byshottles	C18-C19 lines of brick-built coke ovens. Many bricks have been dislodged by livestock sheltering within them. Livestock have also eroded the grassy banks between each oven and established tree growth can be found
	DESIGNATION:	Scheduled Monument	along the entire structure.
Children is	CONDITION:	Very bad	0
	OCCUPANCY:	N/A	
	PRIORITY:	A (A)	
	OWNER TYPE:	Private	Contact: Rob Young 0191 269 1239
	SITE NAME:	Langley Old Hall, Burnhope	C15 ruin and moated earthwork in mature deciduous woodland. At risk from vandalism. Mature trees grow close by (saplings growing on walls). There is general
	DESIGNATION:	Scheduled Monument	deterioration so removal of undergrowth and recording are needed urgently. A metric survey of the Old Hall is being
	CONDITION:	Very bad	prepared as the first stage in a conservation programme.
A CONTRACTOR OF THE OWNER	OCCUPANCY:	N/A	
Det de la	PRIORITY:	A (A)	
	OWNER TYPE:	Private	Contact: Rob Young 0191 269 1239
10			
THE PARTY	SITE NAME:	Hamsterley Hall, Hamsterley, Consett	Mid C18 Gothic country house, possibly with older core. The house also has C19 and C20 additions. The building was saved from dereliction by the previous owners, who also part-restored the front range. However, further
IT I A	DESIGNATION:	Listed Building Grade II*	deterioration has occurred since then, resulting in the
	CONDITION:	Very bad	new owners developing a fully costed plan for restoration
	OCCUPANCY:	Vacant	of the entire building.
	PRIORITY:	B (B)	
	OWNER TYPE:	Private	Contact: David Farrington 0191 269 1230
	SITE NAME:	Church, 50m north-east of Croxdale Hall, Croxdale Hall, Croxdale and Hett	Redundant medieval church with nave dating back to late CII and chancel to late CI2. Altered in later centuries but Norman south doorway contains the original door with iron hinges. On the Croxdale Estate and rarely opened
	DESIGNATION:	Listed Building Grade I, SM, RPG II*	up. There is severe damp in the building, both rising damp
	CONDITION:	Poor	in the floors and walls and penetrating damp over the
	OCCUPANCY:		chancel arch.
	PRIORITY:	C (C)	
	OWNER TYPE:	Private	Contact: John Edwards 0191 269 1231

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

	SITE NAME:	Durham Prison Officers' Club, "The Tithe Barn", Hallgarth Street, Durham	This C15 granary building, erroneously known as The Tithe Barn, forms part of an important group of medieval farm buildings. The building lies outside the secure perimeter
	DESIGNATION:	Listed Building Grade II*, CA	of the adjoining prison and is used as part of the Prison Officers' Club. The roof, stonework and close-studded
	CONDITION:	Poor	upper floor are in poor condition. Repointing of the barn
AND THE TAXABLE AND	OCCUPANCY:	Occupied	has begun but further works are required, particularly
The Panel of Manual States	PRIORITY:	D (D)	to the granary.
		Government	Contact: Rob Young 0191 269 1239
			0
	SITE NAME:	Castle Wall, behind, 3 North Bailey, Durham & Framwellgate, Durham	C12 castle wall with base of angle tower. Consists of coursed squared sandstone. Suffering from progressive collapse of wall face and the core requires urgent
	DESIGNATION:	Listed Building Grade I, CA	attention to avoid further substantial failure.
	CONDITION:	Very bad	
	OCCUPANCY:	,	
	PRIORITY:	A (A)	
A START REAL	OWNER TYPE:		Contact: Rob Young 0191 269 1239
	OWNER TIPE.	Charty	Contact, nob roung of 21 202 1252
and a	SITE NAME:	Prebends' Bridge, Durham and Framwellgate, Durham	Bridge over the River Wear designed in 1772-8 by George Nicholson for the Dean and Chapter of Durham Cathedral. Despite several repair campaigns down the
	DESIGNATION:	Listed Building Grade I, SM, CA, WHS	years, the masonry of the arches continues to deteriorate and cause concern. Investigations are in progress to inform
10º	CONDITION:	Poor	a repair programme with the aim of bringing the bridge
	OCCUPANCY:	N/A	back into full use.
	PRIORITY:	С (С)	
		Religious organisation	Contact: Kate Wilson 0191 269 1221
	SITE NAME:	Bounds Wall, Ushaw College, Ushaw, Esh	Playing field boundary wall, incorporating racquet and handball courts and houses. Designed circa 1850 by Joseph Hansom for the Catholic seminary at Ushaw
	DESIGNATION:	Listed Building Grade II*	College. A section of one court is progressively collapsing and is a dangerous structure. The remainder is at risk
	CONDITION:	Very bad	due to the difficulty of maintenance and repair. EH is
		N 1/ A	grant-aiding a series of surveys and trial repairs to inform
	OCCUPANCY:	IN/A	
A	OCCUPANCY:		a full repair programme.
- ALARTICAL	OCCUPANCY: PRIORITY: OWNERTYPE:	A (B)	
	PRIORITY:	A (B)	a full repair programme.
	PRIORITY: OWNER TYPE: SITE NAME:	A (B) Charity Chapel of St Michael at College of St Cuthbert, Ushaw, Esh	a full repair programme. Contact: Kate Wilson 0191 269 1221 Memorial mortuary chapel, of 1858/9, designed by EW Pugin. The chapel is part of the Ushaw College complex; a seminary for the training of Catholic priests that has
	PRIORITY: OWNER TYPE: SITE NAME:	A (B) Charity Chapel of St Michael at College of St Cuthbert, Ushaw, Esh Listed Building Grade I	a full repair programme. Contact: Kate Wilson 0191 269 1221 Memorial mortuary chapel, of 1858/9, designed by EW Pugin. The chapel is part of the Ushaw College complex; a seminary for the training of Catholic priests that has occupied the Ushaw site since 1808. Moisture is causing damage to the high relief carving on the altar and the
	PRIORITY: OWNER TYPE: SITE NAME:	A (B) Charity Chapel of St Michael at College of St Cuthbert, Ushaw, Esh	a full repair programme. Contact: Kate Wilson 0191 269 1221 Memorial mortuary chapel, of 1858/9, designed by EW Pugin. The chapel is part of the Ushaw College complex; a seminary for the training of Catholic priests that has occupied the Ushaw site since 1808. Moisture is causing damage to the high relief carving on the altar and the reredos and to adjoining masonry. English Heritage has
	PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	A (B) Charity Chapel of St Michael at College of St Cuthbert, Ushaw, Esh Listed Building Grade I Poor	a full repair programme. Contact: Kate Wilson 0191 269 1221 Memorial mortuary chapel, of 1858/9, designed by EW Pugin. The chapel is part of the Ushaw College complex; a seminary for the training of Catholic priests that has occupied the Ushaw site since 1808. Moisture is causing damage to the high relief carving on the altar and the reredos and to adjoining masonry. English Heritage has offered a grant towards repair works and these are
	PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	A (B) Charity Chapel of St Michael at College of St Cuthbert, Ushaw, Esh Listed Building Grade I Poor	a full repair programme. Contact: Kate Wilson 0191 269 1221 Memorial mortuary chapel, of 1858/9, designed by EW Pugin. The chapel is part of the Ushaw College complex; a seminary for the training of Catholic priests that has occupied the Ushaw site since 1808. Moisture is causing damage to the high relief carving on the altar and the reredos and to adjoining masonry. English Heritage has
	PRIORITY: OWNER TYPE SITE NAME: DESIGNATION: CONDITION: OCCUPANCY:	A (B) Charity Chapel of St Michael at College of St Cuthbert, Ushaw, Esh Listed Building Grade I Poor Vacant D (B)	a full repair programme. Contact: Kate Wilson 0191 269 1221 Memorial mortuary chapel, of 1858/9, designed by EW Pugin. The chapel is part of the Ushaw College complex; a seminary for the training of Catholic priests that has occupied the Ushaw site since 1808. Moisture is causing damage to the high relief carving on the altar and the reredos and to adjoining masonry. English Heritage has offered a grant towards repair works and these are
	PRIORITY: OWNER TYPE SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	A (B) Charity Chapel of St Michael at College of St Cuthbert, Ushaw, Esh Listed Building Grade I Poor Vacant D (B)	 a full repair programme. Contact: Kate Wilson 0191 269 1221 Memorial mortuary chapel, of 1858/9, designed by EW Pugin. The chapel is part of the Ushaw College complex; a seminary for the training of Catholic priests that has occupied the Ushaw site since 1808. Moisture is causing damage to the high relief carving on the altar and the reredos and to adjoining masonry. English Heritage has offered a grant towards repair works and these are expected to be undertaken in 2011. Contact: Kate Wilson 0191 269 1221 Former Junior Roman Catholic seminary chapel of 1857-59 by Edward W Pugin in the Gothic Revival style. The roofs have been maintained in good condition but
	PRIORITY: OWNER TYPE SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	A (B) Charity Chapel of St Michael at College of St Cuthbert, Ushaw, Esh Listed Building Grade I Poor Vacant D (B) Charity Former Junior Seminary Chapel of St Aloysius, Ushaw College, Ushaw, Esh	 a full repair programme. Contact: Kate Wilson 0191 269 1221 Memorial mortuary chapel, of 1858/9, designed by EW Pugin. The chapel is part of the Ushaw College complex; a seminary for the training of Catholic priests that has occupied the Ushaw site since 1808. Moisture is causing damage to the high relief carving on the altar and the reredos and to adjoining masonry. English Heritage has offered a grant towards repair works and these are expected to be undertaken in 2011. Contact: Kate Wilson 0191 269 1221 Former Junior Roman Catholic seminary chapel of 1857-59 by Edward W Pugin in the Gothic Revival style.
	PRIORITY: OWNER TYPE SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	A (B) Charity Chapel of St Michael at College of St Cuthbert, Ushaw, Esh Listed Building Grade 1 Poor Vacant D (B) Charity Former Junior Seminary Chapel of St Aloysius, Ushaw College,	 a full repair programme. Contact: Kate Wilson 0191 269 1221 Memorial mortuary chapel, of 1858/9, designed by EW Pugin. The chapel is part of the Ushaw College complex; a seminary for the training of Catholic priests that has occupied the Ushaw site since 1808. Moisture is causing damage to the high relief carving on the altar and the reredos and to adjoining masonry. English Heritage has offered a grant towards repair works and these are expected to be undertaken in 2011. Contact: Kate Wilson 0191 269 1221 Former Junior Roman Catholic seminary chapel of 1857-59 by Edward W Pugin in the Gothic Revival style. The roofs have been maintained in good condition but
	PRIORITY: OWNERTYPE SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION:	A (B) Charity Chapel of St Michael at College of St Cuthbert, Ushaw, Esh Listed Building Grade I Poor Vacant D (B) Charity Former Junior Seminary Chapel of St Aloysius, Ushaw College, Ushaw, Esh Listed Building Grade II* Poor	 a full repair programme. Contact: Kate Wilson 0191 269 1221 Memorial mortuary chapel, of 1858/9, designed by EW Pugin. The chapel is part of the Ushaw College complex; a seminary for the training of Catholic priests that has occupied the Ushaw site since 1808. Moisture is causing damage to the high relief carving on the altar and the reredos and to adjoining masonry. English Heritage has offered a grant towards repair works and these are expected to be undertaken in 2011. Contact: Kate Wilson 0191 269 1221 Former Junior Roman Catholic seminary chapel of 1857-59 by Edward W Pugin in the Gothic Revival style. The roofs have been maintained in good condition but
	PRIORITY: OWNERTYPE SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNERTYPE SITE NAME: DESIGNATION: CONDITION: CONDITION:	A (B) Charity Chapel of St Michael at College of St Cuthbert, Ushaw, Esh Listed Building Grade 1 Poor Vacant D (B) Charity Former Junior Seminary Chapel of St Aloysius, Ushaw College, Ushaw, Esh Listed Building Grade II* Poor Vacant	 a full repair programme. Contact: Kate Wilson 0191 269 1221 Memorial mortuary chapel, of 1858/9, designed by EW Pugin. The chapel is part of the Ushaw College complex; a seminary for the training of Catholic priests that has occupied the Ushaw site since 1808. Moisture is causing damage to the high relief carving on the altar and the reredos and to adjoining masonry. English Heritage has offered a grant towards repair works and these are expected to be undertaken in 2011. Contact: Kate Wilson 0191 269 1221 Former Junior Roman Catholic seminary chapel of 1857-59 by Edward W Pugin in the Gothic Revival style. The roofs have been maintained in good condition but
	PRIORITY: OWNERTYPE SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION:	A (B) Charity Chapel of St Michael at College of St Cuthbert, Ushaw, Esh Listed Building Grade I Poor Vacant D (B) Charity Former Junior Seminary Chapel of St Aloysius, Ushaw College, Ushaw, Esh Listed Building Grade II* Poor Vacant C (New entry)	 a full repair programme. Contact: Kate Wilson 0191 269 1221 Memorial mortuary chapel, of 1858/9, designed by EW Pugin. The chapel is part of the Ushaw College complex; a seminary for the training of Catholic priests that has occupied the Ushaw site since 1808. Moisture is causing damage to the high relief carving on the altar and the reredos and to adjoining masonry. English Heritage has offered a grant towards repair works and these are expected to be undertaken in 2011. Contact: Kate Wilson 0191 269 1221 Former Junior Roman Catholic seminary chapel of 1857-59 by Edward W Pugin in the Gothic Revival style. The roofs have been maintained in good condition but

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Concentration
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

19

ALL ALL	SITE NAME:	Remains of the Stockton and Darlington Railway, Etherley	The site comprises embankments, cuttings, revetments and abutments. Some sections are in very good condition, such as Brusselton Bridge and incline, others are slowly
	DESIGNATION:	Scheduled Monument	deteriorating, such as the Gaunless Bridge abutments, or overgrown, such as the cutting with a stone revetment
	CONDITION:	Very bad	between North Leazes and St Helen Auckland.
No. In C. Martin	OCCUPANCY:	N/A	
	PRIORITY:	С (С)	
	OWNER TYPE:	Local authority	Contact: Jenny Lee 0191 384 0114
Man Man	SITE NAME:	Dovecote 45m south of Gainford Hall, Gainford	Dovecote, CI7, within the grounds of Gainford Hall. Stone repairs, roof renewal and repointing required.
	DESIGNATION:	Listed Building Grade II*, CA	
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY:	D (D)	
The Real Property of the Prope	OWNER TYPE:	Private	Contact: Rob Young 0191 269 1239
			U U U U U U U U U U U U U U U U U U U
	SITE NAME:	Gainford Hall, Low Road, Gainford	Impressive manor house circa 1600-1603. Occupied but part of upper floor never completed. The building has a defective roof valley and localised structural deformation
	DESIGNATION:	Listed Building Grade I, CA	of walling.
	CONDITION:	Poor	
	OCCUPANCY:	Occupied	
	PRIORITY:	D (D)	
	OWNER TYPE:	Private	Contact: Rob Young 0191 269 1239
	SITE NAME:	Medieval Chapel at Harbour House Farm, Plawsworth, Kimblesworth and Plawsworth	Redundant chapel. A rare survival of a private manorial chapel dating to the CI3-CI4. A buttress was built in 2008 to support the leaning southern wall; however, further consolidation and repointing work is required.
		Listed Building Grade II, SM	iai a lei consolidation and repointing work is required.
	DESIGNATION:		
	CONDITION:	Fair	
		Fair	
	CONDITION:	Fair	
	CONDITION: OCCUPANCY:	Fair N/A F (F)	Contact: Jenny Lee 0191 384 0114
	CONDITION: OCCUPANCY: PRIORITY:	Fair N/A F (F)	Posts, gates and railings at north west drive to Lambton Castle forming a large and elaborate wrought iron gateway. Certain details are missing and the gateway is
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE SITE NAME:	Fair N/A F (F) Private Iron gates and railings, Lambton Castle, Lambton Park, Little Lumley	Posts, gates and railings at north west drive to Lambton Castle forming a large and elaborate wrought iron gateway. Certain details are missing and the gateway is slowly decaying. In 2010, English Heritage grant-aided a
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE SITE NAME:	Fair N/A F (F) Private	Posts, gates and railings at north west drive to Lambton Castle forming a large and elaborate wrought iron gateway. Certain details are missing and the gateway is slowly decaying. In 2010, English Heritage grant-aided a Condition Survey with costed priorities for repair works;
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION:	Fair N/A F (F) Private Iron gates and railings, Lambton Castle, Lambton Park, Little Lumley Listed Building Grade II*, RPG II Poor	Posts, gates and railings at north west drive to Lambton Castle forming a large and elaborate wrought iron gateway. Certain details are missing and the gateway is slowly decaying. In 2010, English Heritage grant-aided a
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION:	Fair N/A F (F) Private Iron gates and railings, Lambton Castle, Lambton Park, Little Lumley Listed Building Grade II*, RPG II Poor N/A	Posts, gates and railings at north west drive to Lambton Castle forming a large and elaborate wrought iron gateway. Certain details are missing and the gateway is slowly decaying. In 2010, English Heritage grant-aided a Condition Survey with costed priorities for repair works; it is hoped these essential repairs will be undertaken
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE SITE NAME: SITE NAME: CONDITION: CONDITION:	Fair N/A F (F) Private Iron gates and railings, Lambton Castle, Lambton Park, Little Lumley Listed Building Grade II*, RPG II Poor N/A D (C)	Posts, gates and railings at north west drive to Lambton Castle forming a large and elaborate wrought iron gateway. Certain details are missing and the gateway is slowly decaying. In 2010, English Heritage grant-aided a Condition Survey with costed priorities for repair works; it is hoped these essential repairs will be undertaken
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE SITE NAME: SITE NAME: CONDITION: CONDITION: CONDITION: PRIORITY:	Fair N/A F (F) Private Iron gates and railings, Lambton Castle, Lambton Park, Little Lumley Listed Building Grade II*, RPG II Poor N/A D (C)	Posts, gates and railings at north west drive to Lambton Castle forming a large and elaborate wrought iron gateway. Certain details are missing and the gateway is slowly decaying. In 2010, English Heritage grant-aided a Condition Survey with costed priorities for repair works; it is hoped these essential repairs will be undertaken within the next three to five years. Contact: Kate Wilson 0191 269 1221 Ashlar sandstone bridge over the River Wear. Built in 1819 by Ignatius Bonomi for John Lambton, 1st Earl of Durham. The bridge has structural distortions that are causing
	CONDITION: OCCUPANCY: PRORITY: OWNERTYPE SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE SITE NAME:	Fair N/A F (F) Private Iron gates and railings, Lambton Castle, Lambton Park, Little Lumley Listed Building Grade II*, RPG II Poor N/A D (C) Private Lamb Bridge, Lambton Park,	Posts, gates and railings at north west drive to Lambton Castle forming a large and elaborate wrought iron gateway. Certain details are missing and the gateway is slowly decaying. In 2010, English Heritage grant-aided a Condition Survey with costed priorities for repair works; it is hoped these essential repairs will be undertaken within the next three to five years. Contact: Kate Wilson 0191 269 1221 Ashlar sandstone bridge over the River Wear. Built in 1819 by Ignatius Bonomi for John Lambton, 1st Earl of Durham. The bridge has structural distortions that are causing concern about its stability. Work has been undertaken to
	CONDITION: OCCUPANCY: PRORITY: OWNERTYPE SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE SITE NAME:	Fair N/A F (F) Private Iron gates and railings, Lambton Castle, Lambton Park, Little Lumley Listed Building Grade II*, RPG II Poor N/A D (C) Private Lamb Bridge, Lambton Park, Little Lumley	Posts, gates and railings at north west drive to Lambton Castle forming a large and elaborate wrought iron gateway. Certain details are missing and the gateway is slowly decaying. In 2010, English Heritage grant-aided a Condition Survey with costed priorities for repair works; it is hoped these essential repairs will be undertaken within the next three to five years. Contact: Kate Wilson 0191 269 1221 Ashlar sandstone bridge over the River Wear. Built in 1819 by Ignatius Bonomi for John Lambton, 1st Earl of Durham. The bridge has structural distortions that are causing concern about its stability. Work has been undertaken to the foundations and further upstream. The outcome of
	CONDITION: PRIORITY: OWNERTYPE: OWNERTYPE: SITE NAME: CONDITION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION:	Fair N/A F (F) Private Iron gates and railings, Lambton Castle, Lambton Park, Little Lumley Listed Building Grade II*, RPG II Poor N/A D (C) Private Lamb Bridge, Lambton Park, Little Lumley Listed Building Grade II*, RPG II Poor	Posts, gates and railings at north west drive to Lambton Castle forming a large and elaborate wrought iron gateway. Certain details are missing and the gateway is slowly decaying. In 2010, English Heritage grant-aided a Condition Survey with costed priorities for repair works; it is hoped these essential repairs will be undertaken within the next three to five years. Contact: Kate Wilson 0191 269 1221 Ashlar sandstone bridge over the River Wear. Built in 1819 by Ignatius Bonomi for John Lambton, 1st Earl of Durham. The bridge has structural distortions that are causing concern about its stability. Work has been undertaken to
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: CONDITION: CONDITION: OCCUPANCY: OWNERTYPE: SITE NAME: SITE NAME:	Fair N/A F (F) Private Iron gates and railings, Lambton Castle, Lambton Park, Little Lumley Listed Building Grade II*, RPG II Poor N/A D (C) Private Lamb Bridge, Lambton Park, Little Lumley Listed Building Grade II*, RPG II Poor	Posts, gates and railings at north west drive to Lambton Castle forming a large and elaborate wrought iron gateway. Certain details are missing and the gateway is slowly decaying. In 2010, English Heritage grant-aided a Condition Survey with costed priorities for repair works; it is hoped these essential repairs will be undertaken within the next three to five years. Contact: Kate Wilson 0191 269 1221 Ashlar sandstone bridge over the River Wear. Built in 1819 by Ignatius Bonomi for John Lambton, 1st Earl of Durham. The bridge has structural distortions that are causing concern about its stability. Work has been undertaken to the foundations and further upstream. The outcome of these works will be monitored prior to a further repair

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Concentration
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

20

	SITE NAME:	Monastic Grange at Priory Farm (formerly Hunting Lodge), Muggleswick	C13 hunting lodge ruin, with the rubble core eroding from the north and south walls. English Heritage offered a grant in 2009 towards selected urgent repairs and some
	DESIGNATION:	Listed Building Grade I, SM	interpretation. These works were completed in 2010 but further repairs are required on other areas of the site.
n Lall	CONDITION:	Poor	in the repairs are required on other areas of the site.
	OCCUPANCY:	N/A	
A DECK	PRIORITY:	F (F)	
	OWNER TYPE:	Private	Contact: Jenny Lee 0191 384 0114
	SITE NAME:	Gateway, Mortham Tower, Rokeby	Late medieval gateway to Grade I medieval fortified manor house, set within landscaped Rokeby Park (Grade II* registered). An inspection has revealed structural movement in the gateway.
	DESIGNATION:	Listed Building Grade I, RPG II*	sti detdi ai movement in the gateway.
	CONDITION:	Poor	
	OCCUPANCY:		
	PRIORITY:	C (C)	
	OWNER TYPE:	Private	Contact: Kate Wilson 0191 269 1221
	SITE NAME:	Sherburn House Bridge, Sherburn	Mid-medieval stone bridge, dating from 1335 but upper part rebuilt at unknown later date. Tree growth and water ingress has started to push out masonry, as evidenced
	DESIGNATION:	Scheduled Monument	by pronounced gaps running throughout the structure. Drainage channels empty adjacent to the bridge
	CONDITION:	Very bad	abutments and this compounds the ongoing erosion.
	OCCUPANCY:	N/A	
	PRIORITY:	A (A)	
	OWNER TYPE:	Private	Contact: Rob Young 0191 269 1239
	SITE NAME:	Brandon Walls Lead Mine, Stanhope	Recently scheduled mid C19 lead mining complex with some elements in need of conservation action.
The state of the state			
	DESIGNATION:	Scheduled Monument	
	DESIGNATION: CONDITION:	Scheduled Monument Poor	
		Poor Vacant	
	CONDITION: OCCUPANCY: PRIORITY:	Poor Vacant C (C)	
	CONDITION: OCCUPANCY:	Poor Vacant C (C)	Contact: Rob Young 0191 269 1239
	CONDITION: OCCUPANCY: PRIORITY:	Poor Vacant C (C) Private Middle Level Lead Mine,	C18 and C19 lead mine suffering from extensive flood
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Poor Vacant C (C) Private Middle Level Lead Mine, Greenlaws, Daddry Shield,	C18 and C19 lead mine suffering from extensive flood damage and erosion problems. Discussions have been held with the owners and potential funding partners
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Poor Vacant C (C) Private Middle Level Lead Mine, Greenlaws, Daddry Shield, Stanhope	C18 and C19 lead mine suffering from extensive flood damage and erosion problems. Discussions have been
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Poor Vacant C (C) Private Middle Level Lead Mine, Greenlaws, Daddry Shield, Stanhope Listed Building Grade II, SM	C18 and C19 lead mine suffering from extensive flood damage and erosion problems. Discussions have been held with the owners and potential funding partners
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION:	Poor Vacant C (C) Private Middle Level Lead Mine, Greenlaws, Daddry Shield, Stanhope Listed Building Grade II, SM Very bad	C18 and C19 lead mine suffering from extensive flood damage and erosion problems. Discussions have been held with the owners and potential funding partners
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Poor Vacant C (C) Private Middle Level Lead Mine, Greenlaws, Daddry Shield, Stanhope Listed Building Grade II, SM Very bad	C18 and C19 lead mine suffering from extensive flood damage and erosion problems. Discussions have been held with the owners and potential funding partners
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY:	Poor Vacant C (C) Private Middle Level Lead Mine, Greenlaws, Daddry Shield, Stanhope Listed Building Grade II, SM Very bad N/A A (A)	C18 and C19 lead mine suffering from extensive flood damage and erosion problems. Discussions have been held with the owners and potential funding partners
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Poor Vacant C (C) Private Middle Level Lead Mine, Greenlaws, Daddry Shield, Stanhope Listed Building Grade II, SM Very bad N/A A (A)	C18 and C19 lead mine suffering from extensive flood damage and erosion problems. Discussions have been held with the owners and potential funding partners over a suitable conservation programme.
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Poor Vacant C (C) Private Middle Level Lead Mine, Greenlaws, Daddry Shield, Stanhope Listed Building Grade II, SM Very bad N/A A (A) Private Westgate Primitive Methodist Chapel, Westgate,	C18 and C19 lead mine suffering from extensive flood damage and erosion problems. Discussions have been held with the owners and potential funding partners over a suitable conservation programme. Contact: Jenny Lee 0191 384 0114 Redundant Primitive Methodist chapel, with attached schoolroom, constructed in 1871 to the design of George Race Junior and Atkinson and incorporating
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Poor Vacant C (C) Private Middle Level Lead Mine, Greenlaws, Daddry Shield, Stanhope Listed Building Grade II, SM Very bad N/A A (A) Private Westgate Primitive Methodist Chapel, Westgate, Stanhope	C18 and C19 lead mine suffering from extensive flood damage and erosion problems. Discussions have been held with the owners and potential funding partners over a suitable conservation programme. Contact: Jenny Lee 0191 384 0114 Redundant Primitive Methodist chapel, with attached schoolroom, constructed in 1871 to the design of George Race Junior and Atkinson and incorporating parts of an earlier C19 chapel. Roof leaks are causing
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Poor Vacant C (C) Private Middle Level Lead Mine, Greenlaws, Daddry Shield, Stanhope Listed Building Grade II, SM Very bad N/A A (A) Private Westgate Primitive Methodist Chapel, Westgate,	C18 and C19 lead mine suffering from extensive flood damage and erosion problems. Discussions have been held with the owners and potential funding partners over a suitable conservation programme. Contact: Jenny Lee 0191 384 0114 Redundant Primitive Methodist chapel, with attached schoolroom, constructed in 1871 to the design of George Race Junior and Atkinson and incorporating parts of an earlier C19 chapel. Roof leaks are causing localised internal damage. English Heritage offered a
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME:	Poor Vacant C (C) Private Middle Level Lead Mine, Greenlaws, Daddry Shield, Stanhope Listed Building Grade II, SM Very bad N/A A (A) Private Westgate Primitive Methodist Chapel, Westgate, Stanhope Listed Building Grade II*, CA Poor	C18 and C19 lead mine suffering from extensive flood damage and erosion problems. Discussions have been held with the owners and potential funding partners over a suitable conservation programme. Contact: Jenny Lee 0191 384 0114 Redundant Primitive Methodist chapel, with attached schoolroom, constructed in 1871 to the design of George Race Junior and Atkinson and incorporating parts of an earlier C19 chapel. Roof leaks are causing
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: CONDITION:	Poor Vacant C (C) Private Middle Level Lead Mine, Greenlaws, Daddry Shield, Stanhope Listed Building Grade II, SM Very bad N/A A (A) Private Westgate Primitive Methodist Chapel, Westgate, Stanhope Listed Building Grade II*, CA Poor Vacant	C18 and C19 lead mine suffering from extensive flood damage and erosion problems. Discussions have been held with the owners and potential funding partners over a suitable conservation programme. Contact: Jenny Lee 0191 384 0114 Redundant Primitive Methodist chapel, with attached schoolroom, constructed in 1871 to the design of George Race Junior and Atkinson and incorporating parts of an earlier C19 chapel. Roof leaks are causing localised internal damage. English Heritage offered a grant in March 2011 towards a package of investigative
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	Poor Vacant C (C) Private Middle Level Lead Mine, Greenlaws, Daddry Shield, Stanhope Listed Building Grade II, SM Very bad N/A A (A) Private Westgate Primitive Methodist Chapel, Westgate, Stanhope Listed Building Grade II*, CA Poor Vacant E (C)	C18 and C19 lead mine suffering from extensive flood damage and erosion problems. Discussions have been held with the owners and potential funding partners over a suitable conservation programme. Contact: Jenny Lee 0191 384 0114 Redundant Primitive Methodist chapel, with attached schoolroom, constructed in 1871 to the design of George Race Junior and Atkinson and incorporating parts of an earlier C19 chapel. Roof leaks are causing localised internal damage. English Heritage offered a grant in March 2011 towards a package of investigative

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

	SITE NAME:	Coke ovens at Inkerman Farm, Tow Law	Post-medieval beehive coke ovens. The management of the site was reviewed in 1998 with the involvement of Tow Law Town Council, which had a local heritage
	DESIGNATION:	Scheduled Monument	initiative. English Heritage grant-aided the consolidation works, excavation and recording of finds. The initial repair
ALL STAN	CONDITION:	Poor	programme is complete and half of the site is now open
	OCCUPANCY:	N/A	to the public. However, consolidation of the rest of the
	PRIORITY:	С (С)	site is still required.
	OWNER TYPE:	Private	Contact: Rob Young 0191 269 1239
	SITE NAME:	Clock Tower, Windlestone Hall, Windlestone	Early C19 clock tower and stables gateway by Ignatius Bonomi. Cupola repaired with an English Heritage grant in 1989, but stonework repairs now needed. The Hall was used as a school but was put on the market in 2006.
	DESIGNATION:	Listed Building Grade II*, CA, RPG II	The clock faces have been stolen.
	CONDITION:	Poor	
	OCCUPANCY:		
	PRIORITY:	C (C)	
	OWNER TYPE:	Local authority	Contact: Catherine Dewar 0191 269 1232
	SITE NAME:	Windlestone Hall, Windlestone Park, Windlestone	Large house, circa 1835, by Ignatius Bonomi for Sir Robert Johnson Eden. Incorporates an earlier C16 house. Surrounded by gardens and parkland and a cluster of Estate buildings, including stables.
THE REPORT OF TH	DESIGNATION:	Listed Building Grade II*, CA, RPG II	Last occupied as a residential school but now vacant.
	CONDITION:	Poor	The Hall is showing signs of a lack of maintenance,
	OCCUPANCY:		with some internal water ingress.
	PRIORITY:	C (C)	
	OWNER TYPE:	Local authority	Contact: Catherine Dewar 0191 269 1232
	SITE NAME:	Harperley Working Camp, WWII POW Camp at Craigside, Wolsingham	Very rare surviving example of a WWII POW Camp. Used by both German and Italian Prisoners of War. 85% of original buildings in roofed condition. Wall paintings and internal fittings have survivided too. Following a painting
		WWII POW Camp at Craigside,	Used by both German and Italian Prisoners of War. 85% of original buildings in roofed condition. Wall paintings and internal fittings have survived too. Following a series
ANEI		WWII POW Camp at Craigside, Wolsingham	Used by both German and Italian Prisoners of War. 85% of original buildings in roofed condition. Wall paintings
	DESIGNATION:	WWII POW Camp at Craigside, Wolsingham Scheduled Monument Very bad Part occupied	Used by both German and Italian Prisoners of War. 85% of original buildings in roofed condition. Wall paintings and internal fittings have survived too. Following a series of investigative surveys, a programme of conservation
	DESIGNATION:	WWII POW Camp at Craigside, Wolsingham Scheduled Monument Very bad Part occupied B (A)	Used by both German and Italian Prisoners of War. 85% of original buildings in roofed condition. Wall paintings and internal fittings have survived too. Following a series of investigative surveys, a programme of conservation works, funded by English Heritage, will commence in 2011.
	DESIGNATION: CONDITION: OCCUPANCY:	WWII POW Camp at Craigside, Wolsingham Scheduled Monument Very bad Part occupied	Used by both German and Italian Prisoners of War. 85% of original buildings in roofed condition. Wall paintings and internal fittings have survived too. Following a series of investigative surveys, a programme of conservation
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	WWII POW Camp at Craigside, Wolsingham Scheduled Monument Very bad Part occupied B (A)	Used by both German and Italian Prisoners of War. 85% of original buildings in roofed condition. Wall paintings and internal fittings have survived too. Following a series of investigative surveys, a programme of conservation works, funded by English Heritage, will commence in 2011. Contact: Rob Young 0191 269 1239 Roman Catholic church and presbytery built 1826-27 in Church Perpendicular style. West tower and Lady Chapel were added in 1869 to the designs of Bonomi. Signs of cracking in the tower masonry and pockets of erosion; the
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	WWII POW Camp at Craigside, Wolsingham Scheduled Monument Very bad Part occupied B (A) Private Church of St Cuthbert and presbytery attached, Old Elvet, Durham	Used by both German and Italian Prisoners of War. 85% of original buildings in roofed condition. Wall paintings and internal fittings have survived too. Following a series of investigative surveys, a programme of conservation works, funded by English Heritage, will commence in 2011. Contact: Rob Young 0191 269 1239 Roman Catholic church and presbytery built 1826-27 in Church Perpendicular style. West tower and Lady Chapel were added in 1869 to the designs of Bonomi. Signs of cracking in the tower masonry and pockets of erosion; the latter probably due to an earlier repair using cementitious
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	WWII POW Camp at Craigside, Wolsingham Scheduled Monument Very bad Part occupied B (A) Private Church of St Cuthbert and presbytery attached,	Used by both German and Italian Prisoners of War. 85% of original buildings in roofed condition. Wall paintings and internal fittings have survived too. Following a series of investigative surveys, a programme of conservation works, funded by English Heritage, will commence in 2011. Contact: Rob Young 0191 269 1239 Roman Catholic church and presbytery built 1826-27 in Church Perpendicular style. West tower and Lady Chapel were added in 1869 to the designs of Bonomi. Signs of cracking in the tower masonry and pockets of erosion; the latter probably due to an earlier repair using cementitious repointing mortar. Some repairs are underway on the north elevation of the nave but a wider programme
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	WWII POW Camp at Craigside, Wolsingham Scheduled Monument Very bad Part occupied B (A) Private Church of St Cuthbert and presbytery attached, Old Elvet, Durham Listed Place of Worship Grade II, CA Poor	Used by both German and Italian Prisoners of War. 85% of original buildings in roofed condition. Wall paintings and internal fittings have survived too. Following a series of investigative surveys, a programme of conservation works, funded by English Heritage, will commence in 2011. Contact: Rob Young 0191 269 1239 Roman Catholic church and presbytery built 1826-27 in Church Perpendicular style. West tower and Lady Chapel were added in 1869 to the designs of Bonomi. Signs of cracking in the tower masonry and pockets of erosion; the latter probably due to an earlier repair using cementitious repointing mortar. Some repairs are underway on the
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	WWII POW Camp at Craigside, Wolsingham Scheduled Monument Very bad Part occupied B (A) Private Church of St Cuthbert and presbytery attached, Old Elvet, Durham Listed Place of Worship Grade II, CA	Used by both German and Italian Prisoners of War. 85% of original buildings in roofed condition. Wall paintings and internal fittings have survived too. Following a series of investigative surveys, a programme of conservation works, funded by English Heritage, will commence in 2011. Contact: Rob Young 0191 269 1239 Roman Catholic church and presbytery built 1826-27 in Church Perpendicular style. West tower and Lady Chapel were added in 1869 to the designs of Bonomi. Signs of cracking in the tower masonry and pockets of erosion; the latter probably due to an earlier repair using cementitious repointing mortar. Some repairs are underway on the north elevation of the nave but a wider programme
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME:	WWII POW Camp at Craigside, Wolsingham Scheduled Monument Very bad Part occupied B (A) Private Church of St Cuthbert and presbytery attached, Old Elvet, Durham Listed Place of Worship Grade II, CA Poor C (New entry) Religious organisation Church of St John the Baptist, St John's Chapel, Stanhope	Used by both German and Italian Prisoners of War. 85% of original buildings in roofed condition. Wall paintings and internal fittings have survived too. Following a series of investigative surveys, a programme of conservation works, funded by English Heritage, will commence in 2011. Contact: Rob Young 0191 269 1239 Roman Catholic church and presbytery built 1826-27 in Church Perpendicular style. West tower and Lady Chapel were added in 1869 to the designs of Bonomi. Signs of cracking in the tower masonry and pockets of erosion; the latter probably due to an earlier repair using cementitious repointing mortar. Some repairs are underway on the north elevation of the nave but a wider programme is required to address all of the structural issues. Contact: Kate Wilson 0191 269 1221 Church built in 1752 on the site of a medieval chapel and extended in 1881-83 by Ewan Christian. Contains an elegant Georgian interior but is suffering from water ingress due to blocked gutters and fall pipes. The roof coverings also need replacing. Structural movement in the tower
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME:	WWII POW Camp at Craigside, Wolsingham Scheduled Monument Very bad Part occupied B (A) Private Church of St Cuthbert and presbytery attached, Old Elvet, Durham Listed Place of Worship Grade II, CA Poor C (New entry) Religious organisation Church of St John the Baptist, St John's Chapel,	Used by both German and Italian Prisoners of War. 85% of original buildings in roofed condition. Wall paintings and internal fittings have survived too. Following a series of investigative surveys, a programme of conservation works, funded by English Heritage, will commence in 2011. Contact: Rob Young 0191 269 1239 Roman Catholic church and presbytery built 1826-27 in Church Perpendicular style. West tower and Lady Chapel were added in 1869 to the designs of Bonomi. Signs of cracking in the tower masonry and pockets of erosion; the latter probably due to an earlier repair using cementitious repointing mortar. Some repairs are underway on the north elevation of the nave but a wider programme is required to address all of the structural issues. Contact: Kate Wilson 0191 269 1221 Church built in 1752 on the site of a medieval chapel and extended in 1881-83 by Ewan Christian. Contains an elegant Georgian interior but is suffering from water ingress due to blocked gutters and fall pipes. The roof coverings also need replacing. Structural movement in the tower will be arrested when surface water drainage is repaired.
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME:	WWII POW Camp at Craigside, Wolsingham Scheduled Monument Very bad Part occupied B (A) Private Church of St Cuthbert and presbytery attached, Old Elvet, Durham Listed Place of Worship Grade II, CA Poor C (New entry) Religious organisation Church of St John the Baptist, St John's Chapel, Stanhope	Used by both German and Italian Prisoners of War. 85% of original buildings in roofed condition. Wall paintings and internal fittings have survived too. Following a series of investigative surveys, a programme of conservation works, funded by English Heritage, will commence in 2011. Contact: Rob Young 0191 269 1239 Roman Catholic church and presbytery built 1826-27 in Church Perpendicular style. West tower and Lady Chapel were added in 1869 to the designs of Bonomi. Signs of cracking in the tower masonry and pockets of erosion; the latter probably due to an earlier repair using cementitious repointing mortar. Some repairs are underway on the north elevation of the nave but a wider programme is required to address all of the structural issues. Contact: Kate Wilson 0191 269 1221 Church built in 1752 on the site of a medieval chapel and extended in 1881-83 by Ewan Christian. Contains an elegant Georgian interior but is suffering from water ingress due to blocked gutters and fall pipes. The roof coverings also need replacing. Structural movement in the tower will be arrested when surface water drainage is repaired. A Heritage Lottery Fund grant of £92k was offered in
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME:	WWII POW Camp at Craigside, Wolsingham Scheduled Monument Very bad Part occupied B (A) Private Church of St Cuthbert and presbytery attached, Old Elvet, Durham Listed Place of Worship Grade II, CA Poor C (New entry) Religious organisation Church of St John the Baptist, St John's Chapel, Stanhope Listed Place of Worship Grade II, CA Poor D (New entry)	Used by both German and Italian Prisoners of War 85% of original buildings in roofed condition. Wall paintings and internal fittings have survived too. Following a series of investigative surveys, a programme of conservation works, funded by English Heritage, will commence in 2011. Contact: Rob Young 0191 269 1239 Roman Catholic church and presbytery built 1826-27 in Church Perpendicular style. West tower and Lady Chapel were added in 1869 to the designs of Bonomi. Signs of cracking in the tower masonry and pockets of erosion; the latter probably due to an earlier repair using cementitious repointing mortar. Some repairs are underway on the north elevation of the nave but a wider programme is required to address all of the structural issues. Contact: Kate Wilson 0191 269 1221 Church built in 1752 on the site of a medieval chapel and extended in 1881-83 by Ewan Christian. Contains an elegant Georgian interior but is suffering from water ingress due to blocked gutters and fall pipes. The roof coverings also need replacing. Structural movement in the tower will be arrested when surface water drainage is repaired. A Heritage Lottery Fund grant of £92k was offered in March 2011 towards repair programme.
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME:	WWII POW Camp at Craigside, Wolsingham Scheduled Monument Very bad Part occupied B (A) Private Church of St Cuthbert and presbytery attached, Old Elvet, Durham Listed Place of Worship Grade II, CA Poor C (New entry) Religious organisation Church of St John the Baptist, St John's Chapel, Stanhope	Used by both German and Italian Prisoners of War. 85% of original buildings in roofed condition. Wall paintings and internal fittings have survived too. Following a series of investigative surveys, a programme of conservation works, funded by English Heritage, will commence in 2011. Contact: Rob Young 0191 269 1239 Roman Catholic church and presbytery built 1826-27 in Church Perpendicular style. West tower and Lady Chapel were added in 1869 to the designs of Bonomi. Signs of cracking in the tower masonry and pockets of erosion; the latter probably due to an earlier repair using cementitious repointing mortar. Some repairs are underway on the north elevation of the nave but a wider programme is required to address all of the structural issues. Contact: Kate Wilson 0191 269 1221 Church built in 1752 on the site of a medieval chapel and extended in 1881-83 by Ewan Christian. Contains an elegant Georgian interior but is suffering from water ingress due to blocked gutters and fall pipes. The roof coverings also need replacing. Structural movement in the tower will be arrested when surface water drainage is repaired. A Heritage Lottery Fund grant of £92k was offered in

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

	A cairn and a carved rock west of Cowclose Gill, in Scale Knoll Allotment, 460m west of Haythwaite, Barningham Moor, Barningham					
DESIGNATION:	Scheduled Monument (No. 1017434)	CONDITION:	Generally unsatisfactory			
			with major localised problems			
RINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining			
DWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235			
TE NAME:	A cairn, a carved rock, and a rubble bank, in 800m south east of Far East Hope, Barningh					
DESIGNATION:	Scheduled Monument (No. 1017431)	CONDITION:	Generally unsatisfactory with major localised problems			
RINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining			
DWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235			
ITE NAME:	A carved rock and boulder walling, near the south wall of Scale Knoll Allotment, 500m north east of Black Hill Gate, Barningham					
DESIGNATION:	Scheduled Monument (No. 1017430)	CONDITION:	Generally unsatisfactory with major localised problems			
RINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining			
DWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235			
ite name:	Carved rock and cairn in Rowley Intake, 410m south east of Cowclose House, Barningham Moor, Barningham					
DESIGNATION:	Scheduled Monument (No. 1017422)	CONDITION:	Generally unsatisfactory with major localised problems			
RINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining			
	Private	CONTACT:	Stephen Allott 0191 269 1235			
	Carved rock and prehistoric enclosure on w	vest side of Scale	Knoll Gill,			
ITE NAME:		vest side of Scale	Knoll Gill, am Generally satisfactory			
ITE NAME: DESIGNATION:	Carved rock and prehistoric enclosure on w 410m south west of Haythwaite, Barninghan Scheduled Monument (No. 1017440)	vest side of Scale n Moor, Barningha condition:	Knoll Gill, am Generally satisfactory but with significant localised problems			
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY:	Carved rock and prehistoric enclosure on w 410m south west of Haythwaite, Barninghan	vest side of Scale n Moor, Barningha	Knoll Gill, am Generally satisfactory but with significant localised problems Declining			
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY:	Carved rock and prehistoric enclosure on v 410m south west of Haythwaite, Barninghan Scheduled Monument (No. 1017440) Plant growth Private	vest side of Scale n Moor, Barningha condition: trend: contact:	Knoll Gill, am Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235			
ITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:	Carved rock and prehistoric enclosure on v 410m south west of Haythwaite, Barninghan Scheduled Monument (No. 1017440) Plant growth Private Prehistoric enclosure 530m and a rubble bar Barningham Moor, Barningham	vest side of Scale n Moor, Barningha condition: trend: contact:	Knoll Gill, am Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235			
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME:	Carved rock and prehistoric enclosure on w 410m south west of Haythwaite, Barninghan Scheduled Monument (No. 1017440) Plant growth Private Prehistoric enclosure 530m and a rubble ba	vest side of Scale n Moor, Barningha condition: trend: contact:	Knoll Gill, am Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 Haythwaite in Scale Knoll Allotment, Generally unsatisfactory			
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DVVNER TYPE: ITE NAME: DESIGNATION:	Carved rock and prehistoric enclosure on w 410m south west of Haythwaite, Barninghan Scheduled Monument (No. 1017440) Plant growth Private Prehistoric enclosure 530m and a rubble bar Barningham Moor, Barningham Scheduled Monument (No. 1017436)	vest side of Scale n Moor, Barningha condition: Trend: contact: nk 500m east of condition:	Knoll Gill, am Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 Haythwaite in Scale Knoll Allotment, Generally unsatisfactory with major localised problems			
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY:	Carved rock and prehistoric enclosure on w 410m south west of Haythwaite, Barninghan Scheduled Monument (No. 1017440) Plant growth Private Prehistoric enclosure 530m and a rubble bar Barningham Moor, Barningham Scheduled Monument (No. 1017436) Plant growth	vest side of Scale n Moor, Barningha condition: trend: contact: nk 500m east of condition: trend:	Knoll Gill, am Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 Haythwaite in Scale Knoll Allotment, Generally unsatisfactory with major localised problems Declining			
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY:	Carved rock and prehistoric enclosure on w 410m south west of Haythwaite, Barninghan Scheduled Monument (No. 1017440) Plant growth Private Prehistoric enclosure 530m and a rubble bar Barningham Moor, Barningham Scheduled Monument (No. 1017436)	vest side of Scale n Moor, Barningha condition: Trend: contact: nk 500m east of condition:	Knoll Gill, am Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 Haythwaite in Scale Knoll Allotment, Generally unsatisfactory with major localised problems			
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE:	Carved rock and prehistoric enclosure on w 410m south west of Haythwaite, Barninghan Scheduled Monument (No. 1017440) Plant growth Private Prehistoric enclosure 530m and a rubble bar Barningham Moor, Barningham Scheduled Monument (No. 1017436) Plant growth Private Prehistoric enclosure on the west side of Sc 400m WSW of Haythwaite, Barningham Moor	vest side of Scale n Moor, Barningha condition: Trend: contact: nk 500m east of condition: Trend: contact: contact:	Knoll Gill, am Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 Haythwaite in Scale Knoll Allotment, Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235			
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DWNER TYPE: DWNER TYPE: DWNER TYPE:	Carved rock and prehistoric enclosure on w 410m south west of Haythwaite, Barninghan Scheduled Monument (No. 1017440) Plant growth Private Prehistoric enclosure 530m and a rubble bar Barningham Moor, Barningham Scheduled Monument (No. 1017436) Plant growth Private Prehistoric enclosure on the west side of Sc	vest side of Scale n Moor, Barningha condition: Trend: contact: nk 500m east of condition: Trend: contact: contact:	Knoll Gill, am Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 Haythwaite in Scale Knoll Allotment, Generally unsatisfactory with major localised problems Declining			
TE NAME: ESIGNATION: RINCIPAL VULNERABILITY: WINER TYPE: TE NAME: ESIGNATION: TE NAME: ESIGNATION:	Carved rock and prehistoric enclosure on w 410m south west of Haythwaite, Barninghan Scheduled Monument (No. 1017440) Plant growth Private Prehistoric enclosure 530m and a rubble bar Barningham Moor, Barningham Scheduled Monument (No. 1017436) Plant growth Private Prehistoric enclosure on the west side of Sc 400m VVSW of Haythwaite, Barningham Moo Scheduled Monument (No. 1017437) Plant growth	vest side of Scale n Moor, Barningha CONDITION: TREND: CONTACT: nk 500m east of CONDITION: TREND: CONTACT: contact: cale Knoll Gill, or, Barningham	Knoll Gill, am Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 Haythwaite in Scale Knoll Allotment, Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems Declining			
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY:	Carved rock and prehistoric enclosure on w 410m south west of Haythwaite, Barninghan Scheduled Monument (No. 1017440) Plant growth Private Prehistoric enclosure 530m and a rubble bat Barningham Moor, Barningham Scheduled Monument (No. 1017436) Plant growth Private Prehistoric enclosure on the west side of Sc 400m WSW of Haythwaite, Barningham Moor Scheduled Monument (No. 1017437)	vest side of Scale n Moor, Barningha CONDITION: TREND: CONTACT: nk 500m east of CONDITION: TREND: CONDITION: contact: cale Knoll Gill, or, Barningham	Knoll Gill, am Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 Haythwaite in Scale Knoll Allotment, Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235			
SITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE:	Carved rock and prehistoric enclosure on w 410m south west of Haythwaite, Barninghan Scheduled Monument (No. 1017440) Plant growth Private Prehistoric enclosure 530m and a rubble bar Barningham Moor, Barningham Scheduled Monument (No. 1017436) Plant growth Private Prehistoric enclosure on the west side of Sc 400m VVSW of Haythwaite, Barningham Moo Scheduled Monument (No. 1017437) Plant growth	vest side of Scale n Moor, Barningha condition: trend: contact: nk 500m east of condition: trend: contact: contact: condition: trend: condition: trend: condition:	Knoll Gill, am Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 Haythwaite in Scale Knoll Allotment, Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235			
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: DWNER TYPE:	Carved rock and prehistoric enclosure on v 410m south west of Haythwaite, Barninghan Scheduled Monument (No. 1017440) Plant growth Private Prehistoric enclosure 530m and a rubble bar Barningham Moor, Barningham Scheduled Monument (No. 1017436) Plant growth Private Prehistoric enclosure on the west side of Sc 400m WSW of Haythwaite, Barningham Moo Scheduled Monument (No. 1017437) Plant growth Private	vest side of Scale n Moor, Barningha condition: trend: contact: nk 500m east of condition: trend: contact: contact: condition: trend: condition: trend: condition:	Knoll Gill, Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 Haythwaite in Scale Knoll Allotment, Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235			
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: PRINCIPAL VU	Carved rock and prehistoric enclosure on w 410m south west of Haythwaite, Barninghan Scheduled Monument (No. 1017440) Plant growth Private Prehistoric enclosure 530m and a rubble bar Barningham Moor, Barningham Scheduled Monument (No. 1017436) Plant growth Private Prehistoric enclosure on the west side of Sc 400m WSW of Haythwaite, Barningham Moo Scheduled Monument (No. 1017437) Plant growth Private Ring cairn 350m east of Haythwaite, Barning Scheduled Monument (No. 1017424)	vest side of Scale n Moor, Barningha CONDITION: TREND: CONTACT: nk 500m east of CONDITION: TREND: CONTACT: cale Knoll Gill, or, Barningham CONDITION: TREND: CONTACT:	Knoll Gill, Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 Haythwaite in Scale Knoll Allotment, Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 with major localised problems Declining Stephen Allott 0191 269 1235			
DWNER TYPE:	Carved rock and prehistoric enclosure on w 410m south west of Haythwaite, Barninghan Scheduled Monument (No. 1017440) Plant growth Private Prehistoric enclosure 530m and a rubble bar Barningham Moor, Barningham Scheduled Monument (No. 1017436) Plant growth Private Prehistoric enclosure on the west side of Sc 400m WSW of Haythwaite, Barningham Moo Scheduled Monument (No. 1017437) Plant growth Private Ring cairn 350m east of Haythwaite, Barning	vest side of Scale n Moor, Barningha condition: trend: contact: nk 500m east of condition: trend: contact: cale Knoll Gill, or, Barningham condition: trend: contact: gham Moor, Barni	Knoll Gill, Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 Haythwaite in Scale Knoll Allotment, Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235			

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Unenclosed settlement, 260m south east of	Cowclose House	e, Barningham Moor, Barningham
DESIGNATION:	Scheduled Monument (No. 1017423)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Grange and Chapel, Bear Park, Bearpark		
DESIGNATION:	Scheduled Monument (No. 1002346)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Cup marked rock 100m north of West Lou	ps's, Cotherstone	Moor, Cotherstone
DESIGNATION:	Scheduled Monument (No. 1018326)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Stable
OWNER TYPE:	Government or Agency	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Cup, ring and groove marked rock 310m w	est of East Loups'	s, Cotherstone Moor, Cotherstone
DESIGNATION:	Scheduled Monument (No. 1018324)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate natural erosion	TREND:	Stable
OWNER TYPE:	Government or Agency	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Derwentcote steel cementation furnace, irc	on finery forge an	d drift coal mine, Derwentside
SITE NAME: DESIGNATION:	Derwentcote steel cementation furnace, iro Scheduled Monument (No. 1015522)	on finery forge an	d drift coal mine, Derwentside Generally unsatisfactory with major localised problems
			Generally unsatisfactory
DESIGNATION:	Scheduled Monument (No. 1015522)	CONDITION:	Generally unsatisfactory with major localised problems
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1015522) Plant growth	CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1015522) Plant growth Government or Agency	CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: 5ITE NAME:	Scheduled Monument (No. 1015522) Plant growth Government or Agency Pike Law lead hushes and mines, Forest and Scheduled Monument (No. 1015835) Extensive animal burrowing	CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 Generally satisfactory but with significant localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1015522) Plant growth Government or Agency Pike Law lead hushes and mines, Forest and Scheduled Monument (No. 1015835)	Frith CONDITION:	Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: 5ITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1015522) Plant growth Government or Agency Pike Law lead hushes and mines, Forest and Scheduled Monument (No. 1015835) Extensive animal burrowing	CONDITION: TREND: CONTACT: Frith CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1015522) Plant growth Government or Agency Pike Law lead hushes and mines, Forest and Scheduled Monument (No. 1015835) Extensive animal burrowing Private	CONDITION: TREND: CONTACT: Frith CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: SITE NAME:	Scheduled Monument (No. 1015522) Plant growth Government or Agency Pike Law lead hushes and mines, Forest and Scheduled Monument (No. 1015835) Extensive animal burrowing Private Roman period native settlement at Calf Homes	CONDITION: TREND: CONTACT: Frith CONDITION: TREND: CONTACT: Im, immediately v	Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 vest of Dine Holm Scar, Forest and Frith Generally satisfactory but with significant localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1015522) Plant growth Government or Agency Pike Law lead hushes and mines, Forest and Scheduled Monument (No. 1015835) Extensive animal burrowing Private Roman period native settlement at Calf Ho Scheduled Monument (No. 1019162)	CONDITION: CONDITION: CONTACT: CONDITION: TREND: CONTACT: Im, immediately we CONDITION:	Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 vest of Dine Holm Scar, Forest and Frith Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1015522) Plant growth Government or Agency Pike Law lead hushes and mines, Forest and Scheduled Monument (No. 1015835) Extensive animal burrowing Private Roman period native settlement at Calf Ho Scheduled Monument (No. 1019162) Scrub / tree growth	CONDITION: TREND: CONTACT: Frith CONDITION: TREND: CONTACT: Im, immediately w CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 vest of Dine Holm Scar, Forest and Frith Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: OWNER TYPE: OWNER TYPE:	Scheduled Monument (No. 1015522) Plant growth Government or Agency Pike Law lead hushes and mines, Forest and Scheduled Monument (No. 1015835) Extensive animal burrowing Private Roman period native settlement at Calf Ho Scheduled Monument (No. 1019162) Scrub / tree growth Private	CONDITION: TREND: CONTACT: Frith CONDITION: TREND: CONTACT: Im, immediately w CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 vest of Dine Holm Scar, Forest and Frith Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION:	Scheduled Monument (No. 1015522) Plant growth Government or Agency Pike Law lead hushes and mines, Forest and Scheduled Monument (No. 1015835) Extensive animal burrowing Private Roman period native settlement at Calf Ho Scheduled Monument (No. 1019162) Scrub / tree growth Private Enclosed hilltop settlement on Pig Hill, 6000	CONDITION: TREND: CONTACT: Frith CONDITION: TREND: CONTACT: Im, immediately w CONDITION: TREND: CONTACT: m south west of h	Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 vest of Dine Holm Scar, Forest and Frith Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 High Fallowfield, Haswell

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

SITE NAME:	Packhorse bridge, Headlam		
DESIGNATION:	Scheduled Monument (No. 1002359)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Two Romano-British hut circles and three shieling	gs on Holwig	ck Scars 250m south of Hungry Hall, Holv
DESIGNATION:	Scheduled Monument (No. 1019455)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Area of carved bedrock I 20m south of The Rigg,	Lartington	
DESIGNATION:	Scheduled Monument (No. 1018253)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive natural erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Carved bedrock with cups and grooves 170m sou	ith east of T	he Rigg, Lartington
DESIGNATION:	Scheduled Monument (No. 1018251)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive natural erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT: Stephen Allott 0191 269 1235	
SITE NAME:	Cup, ring and groove marked rock 170m south w	est of West	Loups's, Cotherstone Moor, Lartington
DESIGNATION:	Scheduled Monument (No. 1016595)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate natural erosion	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
	Four areas of carving on a rock outcrop 200m sc	west of	The Rigg, Lartington
SITE NAME:	Tour areas of carving on a rock outer op 200m se		00, 0
	Scheduled Monument (No. 1018250)	CONDITION:	Generally unsatisfactory with major localised problems
DESIGNATION:			Generally unsatisfactory
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1018250)	CONDITION:	Generally unsatisfactory with major localised problems
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1018250) Extensive natural erosion	CONDITION: TREND:	Generally unsatisfactory with major localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1018250) Extensive natural erosion Private SITE NAME: Croxdale Hall, Croxdale and Hett	CONDITION: TREND: CONTACT: A late CI8	Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 walled garden accompanying a country
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1018250) Extensive natural erosion Private	CONDITION: TREND: CONTACT: A late C18 house and s The walled Lewis Kenn	Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 walled garden accompanying a country set in parkland of early to mid C18 origin. garden and lakes are by the designer edy. Croxdale Hall has been the seat
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1018250) Extensive natural erosion Private SITE NAME: Croxdale Hall, Croxdale and Hett DESIGNATION: Registered Park and Garden Grade II*,	CONDITION: TREND: CONTACT: A late C18 house and s The walled Lewis Kenn of the Salvin Maintenanc	Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 walled garden accompanying a country set in parkland of early to mid C18 origin. garden and lakes are by the designer edy. Croxdale Hall has been the seat n family since the beginning of the C15. e of the gardens has fallen back in recent
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1018250) Extensive natural erosion Private SITE NAME: Croxdale Hall, Croxdale and Hett DESIGNATION: Registered Park and Garden Grade II*, also CA, 17 LBs, 2 SMs CONDITION: Generally satisfactory but with significant localised problems VULNERABILITY: Medium	CONDITION: TREND: CONTACT: A late C18 house and s The walled Lewis Kenn of the Salvir Maintenanc years and th deterioratin	Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 walled garden accompanying a country set in parkland of early to mid C18 origin. garden and lakes are by the designer edy. Croxdale Hall has been the seat n family since the beginning of the C15. e of the gardens has fallen back in recent ne water bodies are in a poor and g state. The notable "cranked" walls flanking
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1018250) Extensive natural erosion Private SITE NAME: Croxdale Hall, Croxdale and Hett DESIGNATION: Registered Park and Garden Grade II*, also CA, 17 LBs, 2 SMs CONDITION: Generally satisfactory but with significant localised problems	CONDITION: TREND: CONTACT: A late C18 house and s The walled Lewis Kenn of the Salvin Maintenanc years and th deterioratin the Orange	Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 walled garden accompanying a country set in parkland of early to mid C18 origin. garden and lakes are by the designer edy. Croxdale Hall has been the seat n family since the beginning of the C15. e of the gardens has fallen back in recent ne water bodies are in a poor and
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1018250) Extensive natural erosion Private SITE NAME: Croxdale Hall, Croxdale and Hett DESIGNATION: Registered Park and Garden Grade II*, also CA, 17 LBs, 2 SMs CONDITION: Generally satisfactory but with significant localised problems VULNERABILITY: Medium TREND: Declining OWNER TYPE Private, single owner	CONDITION: TREND: CONTACT: A late C18 house and s The walled Lewis Kenn of the Salvin Maintenanc years and th deterioratin the Orange	Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 walled garden accompanying a country set in parkland of early to mid C18 origin. garden and lakes are by the designer edy. Croxdale Hall has been the seat in family since the beginning of the C15. e of the gardens has fallen back in recent he water bodies are in a poor and g state. The notable "cranked" walls flanking ry are in an advanced state of decay.
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1018250) Extensive natural erosion Private SITE NAME: Croxdale Hall, Croxdale and Hett DESIGNATION: Registered Park and Garden Grade II*, also CA, 17 LBs, 2 SMs CONDITION: Generally satisfactory but with significant localised problems VULNERABILITY: Medium TREND: Declining OWNERTYPE: Private, single owner	CONDITION: TREND: CONTACT: A late C18 house and s The walled Lewis Kenn of the Salvir Maintenanc years and th deterioratin the Orange Contact: Ar	Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 walled garden accompanying a country set in parkland of early to mid C18 origin. garden and lakes are by the designer edy. Croxdale Hall has been the seat n family since the beginning of the C15. e of the gardens has fallen back in recent ne water bodies are in a poor and g state. The notable "cranked" walls flanking ry are in an advanced state of decay. ady Wimble 01904 601970
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1018250) Extensive natural erosion Private SITE NAME: Croxdale Hall, Croxdale and Hett DESIGNATION: Registered Park and Garden Grade II*, also CA, 17 LBs, 2 SMs CONDITION: Generally satisfactory but with significant localised problems VULNERABILITY: Medium TREND: Declining OWNER TYPE Private, single owner	CONDITION: TREND: CONTACT: A late C18 house and s The walled Lewis Kenn of the Salvin Maintenanc years and th deterioratin the Orange	Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 walled garden accompanying a country set in parkland of early to mid C18 origin. garden and lakes are by the designer edy. Croxdale Hall has been the seat in family since the beginning of the C15. e of the gardens has fallen back in recent he water bodies are in a poor and g state. The notable "cranked" walls flanking ry are in an advanced state of decay.

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

HERITAGE AT RISK 2011 / NORTH EAST / COUNTY DURHAM (UA) / NORTHUMBERLAND (UA)

SITE NAME:	Bowburn		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Sandra Robertson (LPA) 0191 383 4196	NEW ENTRY?:	No
SITE NAME:	Bishop Auckland		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Improving
CONTACT:	Sandra Robertson (LPA) 0191 383 4196	NEW ENTRY?:	Yes
SITE NAME:	Kirk Merrington		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Sandra Robertson (LPA) 0191 383 4196	NEW ENTRY?:	No
SITE NAME:	Mordon		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Sandra Robertson (LPA) 0191 383 4196	NEW ENTRY?:	No
SITE NAME:	Windlestone Park		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	High	TREND:	Improving
CONTACT:	Sandra Robertson (LPA) 0191 383 4196	NEW ENTRY?:	No

NORTHUMBERLAND (UA)

	(0, 1)		
-	SITE NAME:	Allenheads Lead Ore Works, Allendale	Built in the C19, the Allenheads mine was the largest single lead mine in the North Pennines. Much of the complex is well cared for, but some buildings are not weathertight and are becoming increasingly endangered.
ALIA	DESIGNATION:	Scheduled Monument	A report on the required scope of works has been
	CONDITION:	Fair	prepared by English Heritage.
	OCCUPANCY:	Vacant	
	PRIORITY:	C (C)	
The second second	OWNER TYPE:	Private	Contact: Kate Wilson 0191 269 1221
	SITE NAME:	Holmslinn Lead Mine, 200m south east of Holmes, Sinderhope, Allendale	A series of standing and buried remains of one of four mine shafts in the East Allen valley. The shaft, 70m deep, was dug in 1855. The tower base enclosing the shaft,
I & I A A A	DESIGNATION:	Scheduled Monument	the engine bed and wheel pit (Grade II listed) is being damaged by tree roots. Parts of the wheel pit collapsed
the second second	CONDITION:	Very bad	in 2011. A broad repair solution has been agreed but
	OCCUPANCY:	N/A	the requisite funding has yet to be found.
	PRIORITY:	D (D)	
A AND	OWNER TYPE:	Private	Contact: Jenny Lee 0191 384 0114
	SITE NAME:	Bondgate Tower, Bondgate Within, Alnwick	The east gate of the former town wall, built circa 1450 by the 2nd Earl of Northumberland. Consists of a recessed central portal between two projecting semi-octagonal
	DESIGNATION:	Listed Building Grade I, SM, CA	towers. The main defects relate to damage from high-sided vehicles passing through the central portal. Further impact

Contact: John Edwards 0191 269 1231

of a similar nature could cause a serious collapse.

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Compared for the sound of the sound
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

OWNER TYPE: Private

CONDITION:

OCCUPANCY:

PRIORITY:

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Very bad

Vacant A (A)

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

	A (A)	Early C19 townhouse in plain ashlar, with three storeys and a basement. Most of the original interior detailing is still present. The building is vacant and deteriorating due to a lack of maintenance. Dry rot is now present in the main body of the building. Contact: David Farrington 0191 269 1230
SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Coastal artillery battery on Blyth Links, Links Road, Blyth Listed Building Grade II, SM	Artillery battery built in 1916 to defend the submarine base in Blyth Harbour. An observation post was added and the gun emplacements altered during World War II. The buildings are constructed of concrete and steel and were designed to withstand shelling but were not intended to stand in the long term. EH has part-funded a programme that has repaired several structures on the site but further works are required. Contact: John Edwards 0191 269 1231
	C (C)	Experimental hydraulic silo (circa 1895) by Lord Armstrong. Linear plan: rectangular silage bay on each side of a taller cross-gabled centre. Interior contains a twin-cylinder hydraulic engine in the basement and turbine on the entrance level. The process proved to be inefficient in terms of manpower and was soon abandoned. The roof and rainwater goods are in a poor condition, leaving the building vulnerable. Contact: John Edwards 0191 269 1231
	B (B)	Fine fortified manor house. C14 in origin, extensively altered C16 and C17. The ruins were modified in 1887-9 with a partial reconstruction of the south wall of the north tower. The site is in a ruinous condition and in severe risk of collapse, with tree roots a major problem. Needs urgent repairs, although some vegetation was cleared in 2003 and some emergency stabilisation works have been completed. Contact: Kate Wilson 0191 269 1221
SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	A (A)	Remote C15 tower house in a poor state of repair. Part of Little Swinburne shrunken medieval village. Surrounded by fallen masonry and in need of urgent attention to prevent further falls. Contact: Kate Wilson 0191 269 1221
SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	C (C)	Early C19 bottle kiln. In poor condition, although deterioration is slow and controlled. Contact: Kate Wilson 0191 269 1221



- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

-	SITE NAME:	Twizel Medieval Tower House and Folly, Twizel, Duddo	The present building incorporates the remains of a medieval tower house that was later developed into an C18 folly by Sir Francis Blake. Originally five storeys high,
	DESIGNATION:	Listed Building Grade II*, SM, RPG II*	it now stands to three storeys. The site is unmanaged and
	CONDITION:	Very bad	shows signs of structural instability, including substantial vertical cracks around many of the arches and window
	OCCUPANCY:		openings. Some vegetation removed from site in 2004.
	PRIORITY:	C (C)	
and the second s	OWNER TYPE:		Contact: John Edwards 0191 269 1231
	OWNER THE	in doc	
	SITE NAME:	Greenhouse east of Felton Park with potting shed, Felton Park, Felton	Unoccupied greenhouse of circa 1830. In very bad condition. English Heritage has grant-aided repairs to a section of brick wall and parapet above the glasshouse.
	DESIGNATION:	Listed Building Grade II*	
and the Rear and a talk of	CONDITION:	Very bad	
	OCCUPANCY:	Vacant	
	PRIORITY:	С (С)	
	OWNER TYPE:		Contact: John Edwards 0191 269 1231
Helle	SITE NAME:	Ford Castle, Ford	Originally a C14 quadrilateral castle with four corner towers, converted to a mansion in 1694 and further altered in 1761 (for John Hussey Delaval) and 1862
	DESIGNATION:	Listed Building Grade I	(for the Marchioness of Waterford). Now used for residential courses and as a venue for functions.
THE REAL PROPERTY AND A	CONDITION:	Poor	The building is suffering from dry rot, defective
	OCCUPANCY:	Part occupied	masonry, leaking roofs and damaged rainwater goods.
	PRIORITY:	C (New entry)	
	OWNER TYPE:	Private	Contact: John Edwards 0191 269 1231
AL 199	SITE NAME:	Ford Colliery, Ford	Monument including above and below ground remains of Ford Colliery. Situated on moorland partly on and
		Ford	adjacent to Ford Moss. Colliery worked from at least
	DESIGNATION:	Scheduled Monument	adjacent to Ford Moss. Colliery worked from at least middle of C17 through to 1914. Site includes the engine
	DESIGNATION: CONDITION:		adjacent to Ford Moss. Colliery worked from at least middle of C17 through to 1914. Site includes the engine house chimney, which requires repairs to its stone base
		Scheduled Monument Poor	adjacent to Ford Moss. Colliery worked from at least middle of C17 through to 1914. Site includes the engine house chimney, which requires repairs to its stone base and to loose masonry, and the engine house itself, which has suffered a roof collapse. The walls of the engine
	CONDITION: OCCUPANCY:	Scheduled Monument Poor Vacant	adjacent to Ford Moss. Colliery worked from at least middle of C17 through to 1914. Site includes the engine house chimney, which requires repairs to its stone base and to loose masonry, and the engine house itself, which
	CONDITION:	Scheduled Monument Poor Vacant C (D)	adjacent to Ford Moss. Colliery worked from at least middle of C17 through to 1914. Site includes the engine house chimney, which requires repairs to its stone base and to loose masonry, and the engine house itself, which has suffered a roof collapse. The walls of the engine
	CONDITION: OCCUPANCY: PRIORITY:	Scheduled Monument Poor Vacant C (D)	adjacent to Ford Moss. Colliery worked from at least middle of C17 through to 1914. Site includes the engine house chimney, which requires repairs to its stone base and to loose masonry, and the engine house itself, which has suffered a roof collapse. The walls of the engine house are also starting to collapse.
	CONDITION: OCCUPANCY: PRIORITY:	Scheduled Monument Poor Vacant C (D)	adjacent to Ford Moss. Colliery worked from at least middle of C17 through to 1914. Site includes the engine house chimney, which requires repairs to its stone base and to loose masonry, and the engine house itself, which has suffered a roof collapse. The walls of the engine house are also starting to collapse. Contact: Kate Wilson 0191 269 1221 Gates made by the Coalbrookdale Company and exhibited at the Vienna Exhibition of 1873. English Heritage offered grant-aid towards the repair of the gates and the
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Scheduled Monument Poor Vacant C (D) Private Entrance gates to Hartford Hall, Hartford Bridge, Hartford	adjacent to Ford Moss. Colliery worked from at least middle of C17 through to 1914. Site includes the engine house chimney, which requires repairs to its stone base and to loose masonry, and the engine house itself, which has suffered a roof collapse. The walls of the engine house are also starting to collapse. Contact: Kate Wilson 0191 269 1221 Gates made by the Coalbrookdale Company and exhibited at the Vienna Exhibition of 1873. English Heritage offered grant-aid towards the repair of the gates and the works duly started. However, the project is currently on
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Scheduled Monument Poor Vacant C (D) Private Entrance gates to Hartford Hall, Hartford Bridge, Hartford	adjacent to Ford Moss. Colliery worked from at least middle of C17 through to 1914. Site includes the engine house chimney, which requires repairs to its stone base and to loose masonry, and the engine house itself, which has suffered a roof collapse. The walls of the engine house are also starting to collapse. Contact: Kate Wilson 0191 269 1221 Gates made by the Coalbrookdale Company and exhibited at the Vienna Exhibition of 1873. English Heritage offered grant-aid towards the repair of the gates and the
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument Poor Vacant C (D) Private Entrance gates to Hartford Hall, Hartford Bridge, Hartford Listed Building Grade II* Very bad	adjacent to Ford Moss. Colliery worked from at least middle of C17 through to 1914. Site includes the engine house chimney, which requires repairs to its stone base and to loose masonry, and the engine house itself, which has suffered a roof collapse. The walls of the engine house are also starting to collapse. Contact: Kate Wilson 0191 269 1221 Gates made by the Coalbrookdale Company and exhibited at the Vienna Exhibition of 1873. English Heritage offered grant-aid towards the repair of the gates and the works duly started. However, the project is currently on
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Scheduled Monument Poor Vacant C (D) Private Entrance gates to Hartford Hall, Hartford Bridge, Hartford Listed Building Grade II* Very bad	adjacent to Ford Moss. Colliery worked from at least middle of C17 through to 1914. Site includes the engine house chimney, which requires repairs to its stone base and to loose masonry, and the engine house itself, which has suffered a roof collapse. The walls of the engine house are also starting to collapse. Contact: Kate Wilson 0191 269 1221 Gates made by the Coalbrookdale Company and exhibited at the Vienna Exhibition of 1873. English Heritage offered grant-aid towards the repair of the gates and the works duly started. However, the project is currently on
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Scheduled Monument Poor Vacant C (D) Private Entrance gates to Hartford Hall, Hartford Bridge, Hartford Listed Building Grade II* Very bad N/A	adjacent to Ford Moss. Colliery worked from at least middle of C17 through to 1914. Site includes the engine house chimney, which requires repairs to its stone base and to loose masonry, and the engine house itself, which has suffered a roof collapse. The walls of the engine house are also starting to collapse. Contact: Kate Wilson 0191 269 1221 Gates made by the Coalbrookdale Company and exhibited at the Vienna Exhibition of 1873. English Heritage offered grant-aid towards the repair of the gates and the works duly started. However, the project is currently on
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Scheduled Monument Poor Vacant C (D) Private Entrance gates to Hartford Hall, Hartford Bridge, Hartford Listed Building Grade II* Very bad N/A A (A)	adjacent to Ford Moss. Colliery worked from at least middle of C17 through to 1914. Site includes the engine house chimney, which requires repairs to its stone base and to loose masonry, and the engine house itself, which has suffered a roof collapse. The walls of the engine house are also starting to collapse. Contact: Kate Wilson 0191 269 1221 Gates made by the Coalbrookdale Company and exhibited at the Vienna Exhibition of 1873. English Heritage offered grant-aid towards the repair of the gates and the works duly started. However, the project is currently on hold whilst complex contractual issues are resolved.
<image/>	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Scheduled Monument Poor Vacant C (D) Private Entrance gates to Hartford Hall, Hartford Bridge, Hartford Bridge, Hartford Bridge, Hartford Bridge, Hartford Bridge, Hartford Hall, Company Monastic cell and medieval tower, Coquet Island, Hauxley	adjacent to Ford Moss. Colliery worked from at least middle of C17 through to 1914. Site includes the engine house chimney, which requires repairs to its stone base and to loose masonry, and the engine house itself, which has suffered a roof collapse. The walls of the engine house are also starting to collapse. Contact: Kate Wilson 0191 269 1221 Gates made by the Coalbrookdale Company and exhibited at the Vienna Exhibition of 1873. English Heritage offered grant-aid towards the repair of the gates and the works duly started. However, the project is currently on hold whilst complex contractual issues are resolved. Contact: John Edwards 0191 269 1231 Site of a monastic cell founded AD684 comprising a domestic range and chapel. It survives as an east-west range of medieval stone buildings incorporated into C19
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Scheduled Monument Poor Vacant C (D) Private Entrance gates to Hartford Hall, Hartford Bridge, Hartford Bridge, Hartford Bridge, Hartford Bridge, Hartford Bridge, Hartford Bridge, Hartford Bridge, Hartford Bridge, Hartford Bridge, Hartford Bridge, Company Monastic cell and medieval tower, Coquet Island, Hauxley Listed Building Grade II*, SM	adjacent to Ford Moss. Colliery worked from at least middle of C17 through to 1914. Site includes the engine house chimney, which requires repairs to its stone base and to loose masonry, and the engine house itself, which has suffered a roof collapse. The walls of the engine house are also starting to collapse. Contact: Kate Wilson 0191 269 1221 Gates made by the Coalbrookdale Company and exhibited at the Vienna Exhibition of 1873. English Heritage offered grant-aid towards the repair of the gates and the works duly started. However, the project is currently on hold whilst complex contractual issues are resolved. Contact: John Edwards 0191 269 1231 Site of a monastic cell founded AD684 comprising a domestic range and chapel. It survives as an east-west range of medieval stone buildings incorporated into C19 buildings associated with the island's lighthouse. The site is also an important seabird habitat. English Heritage has
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Scheduled Monument Poor Vacant C (D) Private Entrance gates to Hartford Hall, Hartford Bridge, Hartford Bridge, Hartford Bridge, Hartford Bridge, Hartford Bridge, Hartford Hall, Company Monastic cell and medieval tower, Coquet Island, Hauxley	adjacent to Ford Moss. Colliery worked from at least middle of C17 through to 1914. Site includes the engine house chimney, which requires repairs to its stone base and to loose masonry, and the engine house itself, which has suffered a roof collapse. The walls of the engine house are also starting to collapse. Contact: Kate Wilson 0191 269 1221 Gates made by the Coalbrookdale Company and exhibited at the Vienna Exhibition of 1873. English Heritage offered grant-aid towards the repair of the gates and the works duly started. However, the project is currently on hold whilst complex contractual issues are resolved. Contact: John Edwards 0191 269 1231 Site of a monastic cell founded AD684 comprising a domestic range and chapel. It survives as an east-west range of medieval stone buildings incorporated into C19 buildings associated with the island's lighthouse. The site is also an important seabird habitat. English Heritage has offered a grant towards a package of urgent repairs that
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME:	Scheduled Monument Poor Vacant C (D) Private Entrance gates to Hartford Hall, Hartford Bridge, Hartford Bridge,	adjacent to Ford Moss. Colliery worked from at least middle of C17 through to 1914. Site includes the engine house chimney, which requires repairs to its stone base and to loose masonry, and the engine house itself, which has suffered a roof collapse. The walls of the engine house are also starting to collapse. Contact: Kate Wilson 0191 269 1221 Gates made by the Coalbrookdale Company and exhibited at the Vienna Exhibition of 1873. English Heritage offered grant-aid towards the repair of the gates and the works duly started. However, the project is currently on hold whilst complex contractual issues are resolved. Contact: John Edwards 0191 269 1231 Site of a monastic cell founded AD684 comprising a domestic range and chapel. It survives as an east-west range of medieval stone buildings incorporated into C19 buildings associated with the island's lighthouse. The site is also an important seabird habitat. English Heritage has offered a grant towards a package of urgent repairs that will commence in late 2011 after the conclusion of the
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION:	Scheduled Monument Poor Vacant C (D) Private Entrance gates to Hartford Hall, Hartford Bridge, Hartford Bridge,	adjacent to Ford Moss. Colliery worked from at least middle of C17 through to 1914. Site includes the engine house chimney, which requires repairs to its stone base and to loose masonry, and the engine house itself, which has suffered a roof collapse. The walls of the engine house are also starting to collapse. Contact: Kate Wilson 0191 269 1221 Gates made by the Coalbrookdale Company and exhibited at the Vienna Exhibition of 1873. English Heritage offered grant-aid towards the repair of the gates and the works duly started. However, the project is currently on hold whilst complex contractual issues are resolved. Contact: John Edwards 0191 269 1231 Site of a monastic cell founded AD684 comprising a domestic range and chapel. It survives as an east-west range of medieval stone buildings incorporated into C19 buildings associated with the island's lighthouse. The site is also an important seabird habitat. English Heritage has offered a grant towards a package of urgent repairs that
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION: CONDITION:	Scheduled Monument Poor Vacant C (D) Private Entrance gates to Hartford Hall, Hartford Bridge, Hartford Bridge, Hartford Bilding Grade II* Very bad N/A A (A) Company Monastic cell and medieval tower, Coquet Island, Hauxley Listed Building Grade II*, SM Poor Vacant B (B)	adjacent to Ford Moss. Colliery worked from at least middle of C17 through to 1914. Site includes the engine house chimney, which requires repairs to its stone base and to loose masonry, and the engine house itself, which has suffered a roof collapse. The walls of the engine house are also starting to collapse. Contact: Kate Wilson 0191 269 1221 Gates made by the Coalbrookdale Company and exhibited at the Vienna Exhibition of 1873. English Heritage offered grant-aid towards the repair of the gates and the works duly started. However, the project is currently on hold whilst complex contractual issues are resolved. Contact: John Edwards 0191 269 1231 Site of a monastic cell founded AD684 comprising a domestic range and chapel. It survives as an east-west range of medieval stone buildings incorporated into C19 buildings associated with the island's lighthouse. The site is also an important seabird habitat. English Heritage has offered a grant towards a package of urgent repairs that will commence in late 2011 after the conclusion of the

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.


E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

	SITE NAME:	Bastles at Chesterwood, Haydon Bridge, Haydon	Two defended farmhouses dating from between 1575-1650 in the hamlet of Chesterwood. Both buildings are currently used for general storage but are suffering from major
	DESIGNATION:	Scheduled Monument	structural problems.
	CONDITION:	Poor	
The state of the	OCCUPANCY:	N/A	
	PRIORITY:	С (С)	
the second s	OWNER TYPE:	Private	Contact: Jenny Lee 0191 384 0114
	SITE NAME:	Langley Barony Mines, Haydon Bridge, Haydon	Unusual steam-powered lead mine complex including, inter alia, an engine house with chimney, smithy, arched adits, bridge, buddle pits, stone-lined stream reservoirs and waste tips. Dates to C19 but was reworked in the
	DESIGNATION:	Scheduled Monument, WHS	1950s. Deteriorating owing to neglect, tree and shrub
A North Contraction	CONDITION:	Very bad	growth and rabbit activity.
	OCCUPANCY:	N/A	
	PRIORITY:	C (C)	
and the second second	OWNER TYPE:	Private	Contact: Jenny Lee 0191 384 0114
	SITE NAME:	Stublick Colliery Beam Engine House, Langley on Tyne, Haydon	The beam engine house is part of the Stublick Colliery site – the finest early C19 group of colliery buildings in the region. Although other grade II* buildings on the site are in fair condition, the engine house is in urgent need
	DESIGNATION:	Listed Building Grade II*, SM	of repair. The ground around the colliery buildings was
	CONDITION:	Poor	scheduled in November 2003.
The second second second second	OCCUPANCY:	N/A	
AND DAY OF A STATE OF	PRIORITY:	C (C)	
South and the state of the	OWNER TYPE:	Private	Contact: John Edwards 0191 269 1231
-	SITE NAME:	Cockle Park Tower, Cockle Park, Hebron	Tower house built early C16, altered C17 and re-fenestrated circa 1790.Vacant and in very bad condition. A condition survey and architectural report
1 1 1 1		Cockle Park,	re-fenestrated circa 1790.Vacant and in very bad condition. A condition survey and architectural report were produced in 2006. A comprehensive package of
		Cockle Park, Hebron	re-fenestrated circa 1790.Vacant and in very bad condition. A condition survey and architectural report
	DESIGNATION:	Cockle Park, Hebron Listed Building Grade I Very bad	re-fenestrated circa 1790.Vacant and in very bad condition. A condition survey and architectural report were produced in 2006. A comprehensive package of repairs to the tower, part-funded by English Heritage,
	DESIGNATION: CONDITION:	Cockle Park, Hebron Listed Building Grade I Very bad	re-fenestrated circa 1790.Vacant and in very bad condition. A condition survey and architectural report were produced in 2006. A comprehensive package of repairs to the tower, part-funded by English Heritage,
	DESIGNATION: CONDITION: OCCUPANCY:	Cockle Park, Hebron Listed Building Grade I Very bad Vacant E (B)	re-fenestrated circa 1790.Vacant and in very bad condition. A condition survey and architectural report were produced in 2006. A comprehensive package of repairs to the tower, part-funded by English Heritage,
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Cockle Park, Hebron Listed Building Grade I Very bad Vacant E (B)	re-fenestrated circa 1790.Vacant and in very bad condition. A condition survey and architectural report were produced in 2006. A comprehensive package of repairs to the tower, part-funded by English Heritage, commenced in 2011.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Cockle Park, Hebron Listed Building Grade I Very bad Vacant E (B)	re-fenestrated circa 1790. Vacant and in very bad condition. A condition survey and architectural report were produced in 2006. A comprehensive package of repairs to the tower, part-funded by English Heritage, commenced in 2011. Contact: John Edwards 0191 269 1231 An extremely rare example in the county of a heather-thatched cruck barn. Probably C18 but restored in 1989. Rear pitch of barn roof now heavily
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Cockle Park, Hebron Listed Building Grade I Very bad Vacant E (B) Educational Body Barn north west of Burncliffe, Tow House, Bardon Mill, Henshaw	re-fenestrated circa 1790.Vacant and in very bad condition. A condition survey and architectural report were produced in 2006. A comprehensive package of repairs to the tower, part-funded by English Heritage, commenced in 2011. Contact: John Edwards 0191 269 1231 An extremely rare example in the county of a heather-thatched cruck barn. Probably C18 but restored in 1989. Rear pitch of barn roof now heavily decayed and this is affecting structural timbers.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Cockle Park, Hebron Listed Building Grade I Very bad Vacant E (B) Educational Body Barn north west of Burncliffe, Tow House, Bardon Mill, Henshaw	re-fenestrated circa 1790. Vacant and in very bad condition. A condition survey and architectural report were produced in 2006. A comprehensive package of repairs to the tower, part-funded by English Heritage, commenced in 2011. Contact: John Edwards 0191 269 1231 An extremely rare example in the county of a heather-thatched cruck barn. Probably C18 but restored in 1989. Rear pitch of barn roof now heavily decayed and this is affecting structural timbers. English Heritage offered a grant in 2010 towards
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Cockle Park, Hebron Listed Building Grade I Very bad Vacant E (B) Educational Body Barn north west of Burncliffe, Tow House, Bardon Mill, Henshaw Listed Building Grade II*	re-fenestrated circa 1790. Vacant and in very bad condition. A condition survey and architectural report were produced in 2006. A comprehensive package of repairs to the tower, part-funded by English Heritage, commenced in 2011. Contact: John Edwards 0191 269 1231 An extremely rare example in the county of a heather-thatched cruck barn. Probably C18 but restored in 1989. Rear pitch of barn roof now heavily decayed and this is affecting structural timbers. English Heritage offered a grant in 2010 towards a package of project development works designed to inform a full repair programme. These works started
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	Cockle Park, Hebron Listed Building Grade I Very bad Vacant E (B) Educational Body Barn north west of Burncliffe, Tow House, Bardon Mill, Henshaw Listed Building Grade II* Very bad	re-fenestrated circa 1790. Vacant and in very bad condition. A condition survey and architectural report were produced in 2006. A comprehensive package of repairs to the tower, part-funded by English Heritage, commenced in 2011. Contact: John Edwards 0191 269 1231 An extremely rare example in the county of a heather-thatched cruck barn. Probably C18 but restored in 1989. Rear pitch of barn roof now heavily decayed and this is affecting structural timbers. English Heritage offered a grant in 2010 towards a package of project development works designed
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	Cockle Park, Hebron Listed Building Grade I Very bad Vacant E (B) Educational Body Barn north west of Burncliffe, Tow House, Bardon Mill, Henshaw Listed Building Grade II* Very bad Part occupied E (A)	re-fenestrated circa 1790. Vacant and in very bad condition. A condition survey and architectural report were produced in 2006. A comprehensive package of repairs to the tower, part-funded by English Heritage, commenced in 2011. Contact: John Edwards 0191 269 1231 An extremely rare example in the county of a heather-thatched cruck barn. Probably C18 but restored in 1989. Rear pitch of barn roof now heavily decayed and this is affecting structural timbers. English Heritage offered a grant in 2010 towards a package of project development works designed to inform a full repair programme. These works started
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY:	Cockle Park, Hebron Listed Building Grade I Very bad Vacant E (B) Educational Body Barn north west of Burncliffe, Tow House, Bardon Mill, Henshaw Listed Building Grade II* Very bad Part occupied E (A)	re-fenestrated circa 1790. Vacant and in very bad condition. A condition survey and architectural report were produced in 2006. A comprehensive package of repairs to the tower, part-funded by English Heritage, commenced in 2011. Contact: John Edwards 0191 269 1231 An extremely rare example in the county of a heather-thatched cruck barn. Probably C18 but restored in 1989. Rear pitch of barn roof now heavily decayed and this is affecting structural timbers. English Heritage offered a grant in 2010 towards a package of project development works designed to inform a full repair programme. These works started in 2011 and should be completed during 2011/12.
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY:	Cockle Park, Hebron Listed Building Grade I Very bad Vacant E (B) Educational Body Barn north west of Burncliffe, Tow House, Bardon Mill, Henshaw Listed Building Grade II* Very bad Part occupied E (A)	re-fenestrated circa 1790. Vacant and in very bad condition. A condition survey and architectural report were produced in 2006. A comprehensive package of repairs to the tower, part-funded by English Heritage, commenced in 2011. Contact: John Edwards 0191 269 1231 An extremely rare example in the county of a heather-thatched cruck barn. Probably C18 but restored in 1989. Rear pitch of barn roof now heavily decayed and this is affecting structural timbers. English Heritage offered a grant in 2010 towards a package of project development works designed to inform a full repair programme. These works started in 2011 and should be completed during 2011/12. Contact: John Edwards 0191 269 1231 C14 ruined tower. The south wall stands to almost 40 feet but the eastern wall collapsed many years ago. The interior walls are around eight feet thick and most
	DESIGNATION: CONDITION: PRIORITY: OWNERTYPE SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE SITE NAME:	Cockle Park, Hebron Listed Building Grade I Very bad Vacant E (B) Educational Body Barn north west of Burncliffe, Tow House, Bardon Mill, Henshaw Listed Building Grade II* Very bad Part occupied E (A) Private Hepple Tower,	re-fenestrated circa 1790. Vacant and in very bad condition. A condition survey and architectural report were produced in 2006. A comprehensive package of repairs to the tower, part-funded by English Heritage, commenced in 2011. Contact: John Edwards 0191 269 1231 An extremely rare example in the county of a heather-thatched cruck barn. Probably C18 but restored in 1989. Rear pitch of barn roof now heavily decayed and this is affecting structural timbers. English Heritage offered a grant in 2010 towards a package of project development works designed to inform a full repair programme. These works started in 2011 and should be completed during 2011/12. Contact: John Edwards 0191 269 1231
	DESIGNATION: CONDITION: PRIORITY: OWNERTYPE SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE SITE NAME:	Cockle Park, Hebron Listed Building Grade I Very bad Vacant E (B) Educational Body Barn north west of Burncliffe, Tow House, Bardon Mill, Henshaw Listed Building Grade II* Very bad Part occupied E (A) Private Hepple Tower, Hepple	re-fenestrated circa 1790. Vacant and in very bad condition. A condition survey and architectural report were produced in 2006. A comprehensive package of repairs to the tower, part-funded by English Heritage, commenced in 2011. Contact: John Edwards 0191 269 1231 An extremely rare example in the county of a heather-thatched cruck barn. Probably C18 but restored in 1989. Rear pitch of barn roof now heavily decayed and this is affecting structural timbers. English Heritage offered a grant in 2010 towards a package of project development works designed to inform a full repair programme. These works started in 2011 and should be completed during 2011/12. Contact: John Edwards 0191 269 1231 C14 ruined tower. The south wall stands to almost 40 feet but the eastern wall collapsed many years ago. The interior walls are around eight feet thick and most
	DESIGNATION: CONDITION: PRIORITY: OWNERTYPE: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME:	Cockle Park, Hebron Listed Building Grade I Very bad Vacant E (B) Educational Body Barn north west of Burncliffe, Tow House, Bardon Mill, Henshaw Listed Building Grade II* Very bad Part occupied E (A) Private Hepple Tower, Hepple	re-fenestrated circa 1790. Vacant and in very bad condition. A condition survey and architectural report were produced in 2006. A comprehensive package of repairs to the tower, part-funded by English Heritage, commenced in 2011. Contact: John Edwards 0191 269 1231 An extremely rare example in the county of a heather-thatched cruck barn. Probably C18 but restored in 1989. Rear pitch of barn roof now heavily decayed and this is affecting structural timbers. English Heritage offered a grant in 2010 towards a package of project development works designed to inform a full repair programme. These works started in 2011 and should be completed during 2011/12. Contact: John Edwards 0191 269 1231 C14 ruined tower. The south wall stands to almost 40 feet but the eastern wall collapsed many years ago. The interior walls are around eight feet thick and most of the tunnel vault remains. Now under threat from encroachment by vegetation and there are signs of
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION:	Cockle Park, Hebron Listed Building Grade I Very bad Vacant E (B) Educational Body Barn north west of Burncliffe, Tow House, Bardon Mill, Henshaw Listed Building Grade II* Very bad Part occupied E (A) Private Hepple Tower, Hepple Tower, Hepple State II* Poor	re-fenestrated circa 1790. Vacant and in very bad condition. A condition survey and architectural report were produced in 2006. A comprehensive package of repairs to the tower, part-funded by English Heritage, commenced in 2011. Contact: John Edwards 0191 269 1231 An extremely rare example in the county of a heather-thatched cruck barn. Probably C18 but restored in 1989. Rear pitch of barn roof now heavily decayed and this is affecting structural timbers. English Heritage offered a grant in 2010 towards a package of project development works designed to inform a full repair programme. These works started in 2011 and should be completed during 2011/12. Contact: John Edwards 0191 269 1231 C14 ruined tower. The south wall stands to almost 40 feet but the eastern wall collapsed many years ago. The interior walls are around eight feet thick and most of the tunnel vault remains. Now under threat from encroachment by vegetation and there are signs of
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: COUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION: CONDITION:	Cockle Park, Hebron Listed Building Grade I Very bad Vacant E (B) Educational Body Barn north west of Burncliffe, Tow House, Bardon Mill, Henshaw Listed Building Grade II* Very bad Part occupied E (A) Private Hepple Tower, Hepple Tower, Poor N/A C (C)	re-fenestrated circa 1790. Vacant and in very bad condition. A condition survey and architectural report were produced in 2006. A comprehensive package of repairs to the tower, part-funded by English Heritage, commenced in 2011. Contact: John Edwards 0191 269 1231 An extremely rare example in the county of a heather-thatched cruck barn. Probably C18 but restored in 1989. Rear pitch of barn roof now heavily decayed and this is affecting structural timbers. English Heritage offered a grant in 2010 towards a package of project development works designed to inform a full repair programme. These works started in 2011 and should be completed during 2011/12. Contact: John Edwards 0191 269 1231 C14 ruined tower. The south wall stands to almost 40 feet but the eastern wall collapsed many years ago. The interior walls are around eight feet thick and most of the tunnel vault remains. Now under threat from encroachment by vegetation and there are signs of



- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

1 . 60 . AL			Material and outbuilding sizes 1700
all and a	SITE NAME:	Old Mill 30m south west of Linnels Bridge, Linnels, Hexhamshire Low Quarter	Watermill and outbuilding circa 1700, enlarged and remodelled circa 1800. The interior has a complete set of machinery and an early C20 water turbine.
	DESIGNATION:	Listed Building Grade II*	Structural repairs, re-roofing and reinstatement of missing windows are needed.
	CONDITION:	Poor	Thissing windows are needed.
The search of the second se	OCCUPANCY:	Vacant	
Marcall All The -	PRIORITY:	C (C)	
	OWNER TYPE:		Contact: Mike Collins 0191 269 1212
	OWNERTH L.	Thvate	
	SITE NAME:	The Palace, medieval house and Tudor supply base, Holy Island	Courtyard arrangement with entire ground floor surviving beneath internal ground surface. Exterior north wall is suffering from localised areas of collapse; limited action could secure its long term future. In an AONB and on the
The could be interest	DESIGNATION:	Scheduled Monument, CA	Heritage Coast. Site is used as a paddock and as a dump.
100 Sector and	CONDITION:	Very bad	There is much archaeological information. English Heritage
	OCCUPANCY:	Vacant	grant-aided recording of site but a proposed repair
	PRIORITY:	С (С)	programme stalled.
A AND AND AND AND AND AND AND AND AND AN	OWNER TYPE:		Contact: Kate Wilson 0191 269 1221
	SITE NAME:	Bastle, 100m south west of Ray Cottages, Kirkwhelpington	Ruined C16/17 defended farmhouse, situated in the gardens of Ray Castle, with 1.4m thick stone walls standing to a maximum height of 2.2m.Very little mortar remains in the joints between the squared stonework. English Heritage
	DESIGNATION:	Scheduled Monument	offered a Management Agreement grant in 2005 and this
	CONDITION:	Poor	has led to the clearance of mature vegetation that was
A CONTRACTOR OF THE OWNER	OCCUPANCY:	N/A	dislodging masonry.
	PRIORITY:	С (С)	
	OWNER TYPE:		Contact: Kate Wilson 0191 269 1221
	SITE NAME:	Capheaton Tilery, Mirlaw House, Kirkwhelpington	Tilery built for Kirkharle Estate in circa 1800. Masonry and brick vaults are in a poor condition due to invasive vegetation and loss of fabric.
		Mirlaw House,	Masonry and brick vaults are in a poor condition due to invasive vegetation and loss of fabric. Vegetation control would help secure its
		Mirlaw House, Kirkwhelpington	Masonry and brick vaults are in a poor condition due to invasive vegetation and loss of fabric.
	DESIGNATION:	Mirlaw House, Kirkwhelpington Scheduled Monument, CA Poor	Masonry and brick vaults are in a poor condition due to invasive vegetation and loss of fabric. Vegetation control would help secure its
	DESIGNATION: CONDITION: OCCUPANCY:	Mirlaw House, Kirkwhelpington Scheduled Monument, CA Poor N/A	Masonry and brick vaults are in a poor condition due to invasive vegetation and loss of fabric. Vegetation control would help secure its
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Mirlaw House, Kirkwhelpington Scheduled Monument, CA Poor N/A C (C)	Masonry and brick vaults are in a poor condition due to invasive vegetation and loss of fabric. Vegetation control would help secure its long-term future.
	DESIGNATION: CONDITION: OCCUPANCY:	Mirlaw House, Kirkwhelpington Scheduled Monument, CA Poor N/A C (C)	Masonry and brick vaults are in a poor condition due to invasive vegetation and loss of fabric. Vegetation control would help secure its
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Mirlaw House, Kirkwhelpington Scheduled Monument, CA Poor N/A C (C)	Masonry and brick vaults are in a poor condition due to invasive vegetation and loss of fabric. Vegetation control would help secure its long-term future. Contact: Kate Wilson 0191 269 1221 Roman bridge abutment, probably associated with Whitley Castle Roman fort 600 metres to the north east. Years of neglect has seen the fabric of the abutment
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Mirlaw House, Kirkwhelpington Scheduled Monument, CA Poor N/A C (C) Private Kirkhaugh Bridge Abutment,	Masonry and brick vaults are in a poor condition due to invasive vegetation and loss of fabric. Vegetation control would help secure its long-term future. Contact: Kate Wilson 0191 269 1221 Roman bridge abutment, probably associated with Whitley Castle Roman fort 600 metres to the north east. Years of neglect has seen the fabric of the abutment undermined by tree growth. In urgent need of recording,
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Mirlaw House, Kirkwhelpington Scheduled Monument, CA Poor N/A C (C) Private Kirkhaugh Bridge Abutment, Knaresdale with Kirkhaugh	Masonry and brick vaults are in a poor condition due to invasive vegetation and loss of fabric. Vegetation control would help secure its long-term future. Contact: Kate Wilson 0191 269 1221 Roman bridge abutment, probably associated with Whitley Castle Roman fort 600 metres to the north east. Years of neglect has seen the fabric of the abutment
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Mirlaw House, Kirkwhelpington Scheduled Monument, CA Poor N/A C (C) Private Kirkhaugh Bridge Abutment, Knaresdale with Kirkhaugh Scheduled Monument Very bad	Masonry and brick vaults are in a poor condition due to invasive vegetation and loss of fabric. Vegetation control would help secure its long-term future. Contact: Kate Wilson 0191 269 1221 Roman bridge abutment, probably associated with Whitley Castle Roman fort 600 metres to the north east. Years of neglect has seen the fabric of the abutment undermined by tree growth. In urgent need of recording,
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	Mirlaw House, Kirkwhelpington Scheduled Monument, CA Poor N/A C (C) Private Kirkhaugh Bridge Abutment, Knaresdale with Kirkhaugh Scheduled Monument Very bad N/A	Masonry and brick vaults are in a poor condition due to invasive vegetation and loss of fabric. Vegetation control would help secure its long-term future. Contact: Kate Wilson 0191 269 1221 Roman bridge abutment, probably associated with Whitley Castle Roman fort 600 metres to the north east. Years of neglect has seen the fabric of the abutment undermined by tree growth. In urgent need of recording,
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	Mirlaw House, Kirkwhelpington Scheduled Monument, CA Poor N/A C (C) Private Kirkhaugh Bridge Abutment, Knaresdale with Kirkhaugh Scheduled Monument Very bad N/A C (C)	Masonry and brick vaults are in a poor condition due to invasive vegetation and loss of fabric. Vegetation control would help secure its long-term future. Contact: Kate Wilson 0191 269 1221 Roman bridge abutment, probably associated with Whitley Castle Roman fort 600 metres to the north east. Years of neglect has seen the fabric of the abutment undermined by tree growth. In urgent need of recording,
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: OCCUPANCY: PRIORITY:	Mirlaw House, Kirkwhelpington Scheduled Monument, CA Poor N/A C (C) Private Kirkhaugh Bridge Abutment, Knaresdale with Kirkhaugh Scheduled Monument Very bad N/A C (C)	Masonry and brick vaults are in a poor condition due to invasive vegetation and loss of fabric. Vegetation control would help secure its long-term future. Contact: Kate Wilson 0191 269 1221 Roman bridge abutment, probably associated with Whitley Castle Roman fort 600 metres to the north east. Years of neglect has seen the fabric of the abutment undermined by tree growth. In urgent need of recording, repointing and consolidation.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: OCCUPANCY: PRIORITY:	Mirlaw House, Kirkwhelpington Scheduled Monument, CA Poor N/A C (C) Private Kirkhaugh Bridge Abutment, Knaresdale with Kirkhaugh Scheduled Monument Very bad N/A C (C)	Masonry and brick vaults are in a poor condition due to invasive vegetation and loss of fabric. Vegetation control would help secure its long-term future. Contact: Kate Wilson 0191 269 1221 Roman bridge abutment, probably associated with Whitley Castle Roman fort 600 metres to the north east. Years of neglect has seen the fabric of the abutment undermined by tree growth. In urgent need of recording, repointing and consolidation. Contact: Jenny Lee 0191 384 0114 Early C19 limekiln, 30 x 18 metres with charing ramp. One of the largest C19 limekilns in the country. The building is redundant and is suffering from exposure
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Mirlaw House, Kirkwhelpington Scheduled Monument, CA Poor N/A C (C) Private Kirkhaugh Bridge Abutment, Knaresdale with Kirkhaugh Scheduled Monument Very bad N/A C (C) Private Limekiln to east of the Limery, Little Mill,	Masonry and brick vaults are in a poor condition due to invasive vegetation and loss of fabric. Vegetation control would help secure its long-term future. Contact: Kate Wilson 0191 269 1221 Roman bridge abutment, probably associated with Whitley Castle Roman fort 600 metres to the north east. Years of neglect has seen the fabric of the abutment undermined by tree growth. In urgent need of recording, repointing and consolidation. Contact: Jenny Lee 0191 384 0114 Early C19 limekiln, 30 x 18 metres with charing ramp. One of the largest C19 limekilns in the country. The building is redundant and is suffering from exposure to the elements and the encroachment of the natural
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Mirlaw House, Kirkwhelpington Scheduled Monument, CA Poor N/A C (C) Private Kirkhaugh Bridge Abutment, Knaresdale with Kirkhaugh Scheduled Monument Very bad N/A C (C) Private Limekiln to east of the Limery, Little Mill, Longhoughton	Masonry and brick vaults are in a poor condition due to invasive vegetation and loss of fabric. Vegetation control would help secure its long-term future. Contact: Kate Wilson 0191 269 1221 Roman bridge abutment, probably associated with Whitley Castle Roman fort 600 metres to the north east. Years of neglect has seen the fabric of the abutment undermined by tree growth. In urgent need of recording, repointing and consolidation. Contact: Jenny Lee 0191 384 0114 Early C19 limekiln, 30 x 18 metres with charing ramp. One of the largest C19 limekilns in the country. The building is redundant and is suffering from exposure to the elements and the encroachment of the natural environment. A detailed survey of the building was
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Mirlaw House, Kirkwhelpington Scheduled Monument, CA Poor N/A C (C) Private Kirkhaugh Bridge Abutment, Knaresdale with Kirkhaugh Scheduled Monument Very bad N/A C (C) Private Limekiln to east of the Limery, Little Mill, Longhoughton Listed Building Grade II*	Masonry and brick vaults are in a poor condition due to invasive vegetation and loss of fabric. Vegetation control would help secure its long-term future. Contact: Kate Wilson 0191 269 1221 Roman bridge abutment, probably associated with Whitley Castle Roman fort 600 metres to the north east. Years of neglect has seen the fabric of the abutment undermined by tree growth. In urgent need of recording, repointing and consolidation. Contact: Jenny Lee 0191 384 0114 Early C19 limekiln, 30 x 18 metres with charing ramp. One of the largest C19 limekilns in the country. The building is redundant and is suffering from exposure to the elements and the encroachment of the natural
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Mirlaw House, Kirkwhelpington Scheduled Monument, CA Poor N/A C (C) Private Kirkhaugh Bridge Abutment, Knaresdale with Kirkhaugh Scheduled Monument Very bad N/A C (C) Private Limekiln to east of the Limery, Little Mill, Longhoughton Listed Building Grade II* Very bad Vacant	Masonry and brick vaults are in a poor condition due to invasive vegetation and loss of fabric. Vegetation control would help secure its long-term future. Contact: Kate Wilson 0191 269 1221 Roman bridge abutment, probably associated with Whitley Castle Roman fort 600 metres to the north east. Years of neglect has seen the fabric of the abutment undermined by tree growth. In urgent need of recording, repointing and consolidation. Contact: Jenny Lee 0191 384 0114 Early C19 limekiln, 30 x 18 metres with charing ramp. One of the largest C19 limekilns in the country. The building is redundant and is suffering from exposure to the elements and the encroachment of the natural environment. A detailed survey of the building was carried out in 2010 and plans are now being made
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME:	Mirlaw House, Kirkwhelpington Scheduled Monument, CA Poor N/A C (C) Private Kirkhaugh Bridge Abutment, Knaresdale with Kirkhaugh Scheduled Monument Very bad N/A C (C) Private Limekiln to east of the Limery, Little Mill, Longhoughton Listed Building Grade II* Very bad Vacant B (B)	Masonry and brick vaults are in a poor condition due to invasive vegetation and loss of fabric. Vegetation control would help secure its long-term future. Contact: Kate Wilson 0191 269 1221 Roman bridge abutment, probably associated with Whitley Castle Roman fort 600 metres to the north east. Years of neglect has seen the fabric of the abutment undermined by tree growth. In urgent need of recording, repointing and consolidation. Contact: Jenny Lee 0191 384 0114 Early C19 limekiln, 30 x 18 metres with charing ramp. One of the largest C19 limekilns in the country. The building is redundant and is suffering from exposure to the elements and the encroachment of the natural environment. A detailed survey of the building was carried out in 2010 and plans are now being made

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

	SITE NAME:	Barmoor Castle, Barmoor, Lowick	Country House of 1801. The building received grant aid towards repairs in 1986 but has deteriorated since these works were completed.
FT Internation	DESIGNATION:	Listed Building Grade II*	
	CONDITION:	Very bad	
	OCCUPANCY:	Vacant	
	PRIORITY:	A (A)	
	OWNER TYPE:	Private	Contact: John Edwards 0191 269 1231
	SITE NAME:	Pithead Baths at Lynemouth Colliery, Lynemouth	Pithead baths of 1938 by FG Frizzell in Modern Movement style. Vacant for over twenty years and subject to vandalism. The future of the overall site continues to be in doubt, participated the closure of the associated Ellington
1-2 623	DESIGNATION:	Listed Building Grade II*	particularly since the closure of the associated Ellington Colliery in January 2005.
4 Marin	CONDITION:	Very bad	
	OCCUPANCY:		
	PRIORITY:	C (C)	
	OWNER TYPE:	Company	Contact: John Edwards 0191 269 1231
	SITE NAME:	Mitford Castle, Mitford	Late CI I motte and bailey castle converted to shell keep in CI2. Five-sided keep of CI3 includes CI2 curtain wall, curtain wall structures and mid CI2 chapel. It is
	DESIGNATION:	Listed Building Grade I, SM	now a roofless ruin but capable of consolidation. Grant offered for photographic recording (now complete).
and the star	CONDITION:	Poor	English Heritage offered grants towards three phases
	OCCUPANCY:	N/A	of the repair programme, the first two of which are now complete.
A STATE OF	PRIORITY:	D (D)	now complete.
	OWNER TYPE:	Company	Contact: John Edwards 0191 269 1231
	SITE NAME:	Newminster Abbey, Mitford Road, Morpeth	Cistercian abbey founded circa I 137. In a ruined condition but with some C19 reconstruction. Parts of the structure are suffering badly from vegetation growth, unconsolidated
		Mitford Road,	but with some C19 reconstruction. Parts of the structure are suffering badly from vegetation growth, unconsolidated masonry and vandalism. English Heritage offered a grant in
		Mitford Road, Morpeth	but with some C19 reconstruction. Parts of the structure are suffering badly from vegetation growth, unconsolidated masonry and vandalism. English Heritage offered a grant in 2011 towards a package of development works, including vegetation clearance and topographic surveys, that will
	DESIGNATION:	Mitford Road, Morpeth Listed Building Grade II, SM Very bad	but with some C19 reconstruction. Parts of the structure are suffering badly from vegetation growth, unconsolidated masonry and vandalism. English Heritage offered a grant in 2011 towards a package of development works, including
	DESIGNATION:	Mitford Road, Morpeth Listed Building Grade II, SM Very bad	but with some C19 reconstruction. Parts of the structure are suffering badly from vegetation growth, unconsolidated masonry and vandalism. English Heritage offered a grant in 2011 towards a package of development works, including vegetation clearance and topographic surveys, that will
	DESIGNATION: CONDITION: OCCUPANCY:	Mitford Road, Morpeth Listed Building Grade II, SM Very bad N/A A (A)	but with some C19 reconstruction. Parts of the structure are suffering badly from vegetation growth, unconsolidated masonry and vandalism. English Heritage offered a grant in 2011 towards a package of development works, including vegetation clearance and topographic surveys, that will
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Mitford Road, Morpeth Listed Building Grade II, SM Very bad N/A A (A)	but with some C19 reconstruction. Parts of the structure are suffering badly from vegetation growth, unconsolidated masonry and vandalism. English Heritage offered a grant in 2011 towards a package of development works, including vegetation clearance and topographic surveys, that will inform a wider programme of repairs in the future.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Mitford Road, Morpeth Listed Building Grade II, SM Very bad N/A A (A) Private Mausoleum east of Seaton Delaval Hall, Seaton Delaval	but with some C19 reconstruction. Parts of the structure are suffering badly from vegetation growth, unconsolidated masonry and vandalism. English Heritage offered a grant in 2011 towards a package of development works, including vegetation clearance and topographic surveys, that will inform a wider programme of repairs in the future. Contact: Sara Rushton 01661 881 363 Mausoleum of 1766; the focal point of a walk to the east of the Hall, overlooking parkland to the south. The Hall was built 1718-29 by Vanbrugh, with early C18 landscaping incorporating earlier and later features. The landscape was
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Mitford Road, Morpeth Listed Building Grade II, SM Very bad N/A A (A) Private Mausoleum east of Seaton Delaval Hall,	but with some C19 reconstruction. Parts of the structure are suffering badly from vegetation growth, unconsolidated masonry and vandalism. English Heritage offered a grant in 2011 towards a package of development works, including vegetation clearance and topographic surveys, that will inform a wider programme of repairs in the future. Contact: Sara Rushton 01661 881 363 Mausoleum of 1766; the focal point of a walk to the east of the Hall, overlooking parkland to the south. The Hall was built 1718-29 by Vanbrugh, with early C18 landscaping incorporating earlier and later features. The landscape was restored in the 1950s-1960s. The mausoleum is roofless but
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Mitford Road, Morpeth Listed Building Grade II, SM Very bad N/A A (A) Private Mausoleum east of Seaton Delaval Hall, Seaton Delaval Listed Building Grade II*, RPG II* Fair	but with some C19 reconstruction. Parts of the structure are suffering badly from vegetation growth, unconsolidated masonry and vandalism. English Heritage offered a grant in 2011 towards a package of development works, including vegetation clearance and topographic surveys, that will inform a wider programme of repairs in the future. Contact: Sara Rushton 01661 881 363 Mausoleum of 1766; the focal point of a walk to the east of the Hall, overlooking parkland to the south. The Hall was built 1718-29 by Vanbrugh, with early C18 landscaping incorporating earlier and later features. The landscape was
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Mitford Road, Morpeth Listed Building Grade II, SM Very bad N/A A (A) Private Mausoleum east of Seaton Delaval Hall, Seaton Delaval Listed Building Grade II*, RPG II* Fair	but with some C19 reconstruction. Parts of the structure are suffering badly from vegetation growth, unconsolidated masonry and vandalism. English Heritage offered a grant in 2011 towards a package of development works, including vegetation clearance and topographic surveys, that will inform a wider programme of repairs in the future. Contact: Sara Rushton 01661 881 363 Mausoleum of 1766; the focal point of a walk to the east of the Hall, overlooking parkland to the south. The Hall was built 1718-29 by Vanbrugh, with early C18 landscaping incorporating earlier and later features. The landscape was restored in the 1950s-1960s. The mausoleum is roofless but stable following works grant-aided by English Heritage in
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY:	Mitford Road, Morpeth Listed Building Grade II, SM Very bad N/A A (A) Private Mausoleum east of Seaton Delaval Hall, Seaton Delaval Listed Building Grade II*, RPG II* Fair N/A	but with some C19 reconstruction. Parts of the structure are suffering badly from vegetation growth, unconsolidated masonry and vandalism. English Heritage offered a grant in 2011 towards a package of development works, including vegetation clearance and topographic surveys, that will inform a wider programme of repairs in the future. Contact: Sara Rushton 01661 881 363 Mausoleum of 1766; the focal point of a walk to the east of the Hall, overlooking parkland to the south. The Hall was built 1718-29 by Vanbrugh, with early C18 landscaping incorporating earlier and later features. The landscape was restored in the 1950s-1960s. The mausoleum is roofless but stable following works grant-aided by English Heritage in
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Mitford Road, Morpeth Listed Building Grade II, SM Very bad N/A A (A) Private Mausoleum east of Seaton Delaval Hall, Seaton Delaval Listed Building Grade II*, RPG II* Fair N/A C (C) Trust North West Pillbox, Fort House, A193 (east side off), Hartley, Seaton Sluice	but with some C19 reconstruction. Parts of the structure are suffering badly from vegetation growth, unconsolidated masonry and vandalism. English Heritage offered a grant in 2011 towards a package of development works, including vegetation clearance and topographic surveys, that will inform a wider programme of repairs in the future. Contact: Sara Rushton 01661 881 363 Mausoleum of 1766; the focal point of a walk to the east of the Hall, overlooking parkland to the south. The Hall was built 1718-29 by Vanbrugh, with early C18 landscaping incorporating earlier and later features. The landscape was restored in the 1950s-1960s. The mausoleum is roofless but stable following works grant-aided by English Heritage in 1994. The site was acquired by the National Trust in 2009.
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Mitford Road, Morpeth Listed Building Grade II, SM Very bad N/A A (A) Private Mausoleum east of Seaton Delaval Hall, Seaton Delaval Listed Building Grade II*, RPG II* Fair N/A C (C) Trust North West Pillbox, Fort House, A193 (east side off),	but with some C19 reconstruction. Parts of the structure are suffering badly from vegetation growth, unconsolidated masonry and vandalism. English Heritage offered a grant in 2011 towards a package of development works, including vegetation clearance and topographic surveys, that will inform a wider programme of repairs in the future. Contact: Sara Rushton 01661 881 363 Mausoleum of 1766; the focal point of a walk to the east of the Hall, overlooking parkland to the south. The Hall was built 1718-29 by Vanbrugh, with early C18 landscaping incorporating earlier and later features. The landscape was restored in the 1950s-1960s. The mausoleum is roofless but stable following works grant-aided by English Heritage in 1994. The site was acquired by the National Trust in 2009. Contact: John Edwards 0191 269 1231 Pillbox or defensible latrine, circa 1917. Rare survival as part of World War I fort. Suffering from structural
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Mitford Road, Morpeth Listed Building Grade II, SM Very bad N/A A (A) Private Mausoleum east of Seaton Delaval Hall, Seaton Delaval Listed Building Grade II*, RPG II* Fair N/A C (C) Trust North West Pillbox, Fort House, A193 (east side off), Hartley, Seaton Sluice	but with some C19 reconstruction. Parts of the structure are suffering badly from vegetation growth, unconsolidated masonry and vandalism. English Heritage offered a grant in 2011 towards a package of development works, including vegetation clearance and topographic surveys, that will inform a wider programme of repairs in the future. Contact: Sara Rushton 01661 881 363 Mausoleum of 1766; the focal point of a walk to the east of the Hall, overlooking parkland to the south. The Hall was built 1718-29 by Vanbrugh, with early C18 landscaping incorporating earlier and later features. The landscape was restored in the 1950s-1960s. The mausoleum is roofless but stable following works grant-aided by English Heritage in 1994. The site was acquired by the National Trust in 2009. Contact: John Edwards 0191 269 1231 Pillbox or defensible latrine, circa 1917. Rare survival as part of World War I fort. Suffering from structural
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Mitford Road, Morpeth Listed Building Grade II, SM Very bad N/A A (A) Private Mausoleum east of Seaton Delaval Hall, Seaton Delaval Listed Building Grade II*, RPG II* Fair N/A C (C) Trust North West Pillbox, Fort House, A193 (east side off), Hartley, Seaton Sluice Listed Building Grade II* Poor N/A	but with some C19 reconstruction. Parts of the structure are suffering badly from vegetation growth, unconsolidated masonry and vandalism. English Heritage offered a grant in 2011 towards a package of development works, including vegetation clearance and topographic surveys, that will inform a wider programme of repairs in the future. Contact: Sara Rushton 01661 881 363 Mausoleum of 1766; the focal point of a walk to the east of the Hall, overlooking parkland to the south. The Hall was built 1718-29 by Vanbrugh, with early C18 landscaping incorporating earlier and later features. The landscape was restored in the 1950s-1960s. The mausoleum is roofless but stable following works grant-aided by English Heritage in 1994. The site was acquired by the National Trust in 2009. Contact: John Edwards 0191 269 1231 Pillbox or defensible latrine, circa 1917. Rare survival as part of World War I fort. Suffering from structural
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	Mitford Road, Morpeth Listed Building Grade II, SM Very bad N/A A (A) Private Mausoleum east of Seaton Delaval Hall, Seaton Delaval Listed Building Grade II*, RPG II* Fair N/A C (C) Trust North West Pillbox, Fort House, A193 (east side off), Hartley, Seaton Sluice Listed Building Grade II* Poor N/A C (C)	but with some C19 reconstruction. Parts of the structure are suffering badly from vegetation growth, unconsolidated masonry and vandalism. English Heritage offered a grant in 2011 towards a package of development works, including vegetation clearance and topographic surveys, that will inform a wider programme of repairs in the future. Contact: Sara Rushton 01661 881 363 Mausoleum of 1766; the focal point of a walk to the east of the Hall, overlooking parkland to the south. The Hall was built 1718-29 by Vanbrugh, with early C18 landscaping incorporating earlier and later features. The landscape was restored in the 1950s-1960s. The mausoleum is roofless but stable following works grant-aided by English Heritage in 1994. The site was acquired by the National Trust in 2009. Contact: John Edwards 0191 269 1231 Pillbox or defensible latrine, circa 1917. Rare survival as part of World War I fort. Suffering from structural problems and lack of maintenance.
	DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	Mitford Road, Morpeth Listed Building Grade II, SM Very bad N/A A (A) Private Mausoleum east of Seaton Delaval Hall, Seaton Delaval Listed Building Grade II*, RPG II* Fair N/A C (C) Trust North West Pillbox, Fort House, A193 (east side off), Hartley, Seaton Sluice Listed Building Grade II* Poor N/A C (C)	but with some C19 reconstruction. Parts of the structure are suffering badly from vegetation growth, unconsolidated masonry and vandalism. English Heritage offered a grant in 2011 towards a package of development works, including vegetation clearance and topographic surveys, that will inform a wider programme of repairs in the future. Contact: Sara Rushton 01661 881 363 Mausoleum of 1766; the focal point of a walk to the east of the Hall, overlooking parkland to the south. The Hall was built 1718-29 by Vanbrugh, with early C18 landscaping incorporating earlier and later features. The landscape was restored in the 1950s-1960s. The mausoleum is roofless but stable following works grant-aided by English Heritage in 1994. The site was acquired by the National Trust in 2009. Contact: John Edwards 0191 269 1231 Pillbox or defensible latrine, circa 1917. Rare survival as part of World War I fort. Suffering from structural

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

	SITE NAME:	Water Tank, Fort House, A193 (east side), Hartley, Seaton Sluice	Water tank incorporating former ablutions building – a rare survival of part of a World War I fort. Circa 1917. Suffering from structural problems and lack of maintenance
	DESIGNATION:	Listed Building Grade II*	
	CONDITION:	Poor	
THE REAL PROPERTY AND A DESCRIPTION OF A	OCCUPANCY:	Part occupied	
	PRIORITY:	C (C)	
	OWNER TYPE:	Private	Contact: Catherine Dewar 0191 269 1232
	SITE NAME:	Simonburn Castle, Castle Lane, Simonburn	C13 tower house with C18 Gothick style additions to create a folly. Basement vault has suffered some collapse and there is damaging vegetation growth. In need of
	DESIGNATION:	Listed Building Grade II, SM	urgent repair. Management Agreement established with owner in 2005 to clear some of the vegetation.
THE COURSE	CONDITION:	Very bad	owner in 2005 to clear some of the vegetation.
a.e.理	OCCUPANCY:	Vacant	
	PRIORITY:	A (A)	
and the second	OWNER TYPE:		Contact: Kate Wilson 0191 269 1221
	SITE NAME:	Shilla Hill Bastle, west of Comb, Tarset	C16/C17 bastle standing on the summit of Shilla Hill. English Heritage offered a grant in 2006 towards rectified photography work plus production of a specification and
	DESIGNATION:	Scheduled Monument	schedule for repair works. A further grant was offered in 2008 towards consolidation works and vegetation
	CONDITION:	Good	clearance. The repair programme commenced in 2009
Construction of the state	OCCUPANCY:	N/A	and will be completed in 2011.
ALL AND ALL AN	PRIORITY:	F (E)	
	OWNER TYPE-	Government	Contact: Kate Wilson 0191 269 1221
	officient in a	Government	Contact. Nate Wilson 0171 207 1221
	SITE NAME: DESIGNATION: CONDITION:	Bastle and associated buildings northwest of Comb, Comb, Tarset Listed Building Grade II, SM Good	Ruins of C16 or early C17 bastle surviving to first floor level. Vault has mostly collapsed but a number of interesting features survive. English Heritage offered a grant in 2006 towards rectified photography work plus production of a specification and schedule for repairs. A further grant offer was made in 2008 towards consolidation works. The repair
	SITE NAME: DESIGNATION:	Bastle and associated buildings northwest of Comb, Comb, Tarset Listed Building Grade II, SM Good	Ruins of CI6 or early CI7 bastle surviving to first floor level. Vault has mostly collapsed but a number of interestin features survive. English Heritage offered a grant in 2006 towards rectified photography work plus production of a specification and schedule for repairs. A further grant offer was made in 2008 towards consolidation works. The repai
	SITE NAME: DESIGNATION: CONDITION:	Bastle and associated buildings northwest of Comb, Comb, Tarset Listed Building Grade II, SM Good	Ruins of C16 or early C17 bastle surviving to first floor level. Vault has mostly collapsed but a number of interesting features survive. English Heritage offered a grant in 2006 towards rectified photography work plus production of a specification and schedule for repairs. A further grant offer was made in 2008 towards consolidation works. The repair
	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Bastle and associated buildings northwest of Comb, Comb, Tarset Listed Building Grade II, SM Good N/A	Ruins of C16 or early C17 bastle surviving to first floor level. Vault has mostly collapsed but a number of interesting features survive. English Heritage offered a grant in 2006 towards rectified photography work plus production of a specification and schedule for repairs. A further grant offer was made in 2008 towards consolidation works. The repair
	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Bastle and associated buildings northwest of Comb, Comb, Tarset Listed Building Grade II, SM Good N/A F (E)	Ruins of C16 or early C17 bastle surviving to first floor level. Vault has mostly collapsed but a number of interesting features survive. English Heritage offered a grant in 2006 towards rectified photography work plus production of a specification and schedule for repairs. A further grant offer was made in 2008 towards consolidation works. The repair works commenced in 2009 and will be completed in 2011 Contact: Kate Wilson 0191 269 1221 Folly, probably 1720s, by Archdeacon Sharpe, Rector of Rothbury. Ashlar round tower c30 ft high. Probably the earliest folly in the county, said to have been built partly
	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Bastle and associated buildings northwest of Comb, Comb, Tarset Listed Building Grade II, SM Good N/A F (E) Government Sharpe's Folly, Rothbury,	Ruins of C16 or early C17 bastle surviving to first floor level. Vault has mostly collapsed but a number of interesting features survive. English Heritage offered a grant in 2006 towards rectified photography work plus production of a specification and schedule for repairs. A further grant offer was made in 2008 towards consolidation works. The repair works commenced in 2009 and will be completed in 2011 Contact: Kate Wilson 0191 269 1221 Folly, probably 1720s, by Archdeacon Sharpe, Rector of Rothbury. Ashlar round tower c30 ft high. Probably the
	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Bastle and associated buildings northwest of Comb, Comb, TarsetListed Building Grade II, SMGoodN/AF (E)GovernmentSharpe's Folly, Rothbury, Tosson	Ruins of C16 or early C17 bastle surviving to first floor level. Vault has mostly collapsed but a number of interesting features survive. English Heritage offered a grant in 2006 towards rectified photography work plus production of a specification and schedule for repairs. A further grant offer was made in 2008 towards consolidation works. The repain works commenced in 2009 and will be completed in 2011 Contact: Kate Wilson 0191 269 1221 Folly, probably 1720s, by Archdeacon Sharpe, Rector of Rothbury. Ashlar round tower c30 ft high. Probably the earliest folly in the county, said to have been built partly to alleviate local unemployment and partly to satisfy the Archdeacon's taste for astronomy. Local authority in negotiation with owner to secure emergency repairs and
	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Bastle and associated buildings northwest of Comb, Comb, Tarset Listed Building Grade II, SM Good N/A F (E) Government Sharpe's Folly, Rothbury, Tosson Listed Building Grade II*, CA Fair Vacant	Ruins of C16 or early C17 bastle surviving to first floor level. Vault has mostly collapsed but a number of interesting features survive. English Heritage offered a grant in 2006 towards rectified photography work plus production of a specification and schedule for repairs. A further grant offer was made in 2008 towards consolidation works. The repair works commenced in 2009 and will be completed in 2011 Contact: Kate Wilson 0191 269 1221 Folly, probably 1720s, by Archdeacon Sharpe, Rector of Rothbury. Ashlar round tower c30 ft high. Probably the earliest folly in the county, said to have been built partly to alleviate local unemployment and partly to satisfy the Archdeacon's taste for astronomy. Local authority in
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION:	Bastle and associated buildings northwest of Comb, Comb, Tarset Listed Building Grade II, SM Good N/A F (E) Government Sharpe's Folly, Rothbury, Tosson Listed Building Grade II*, CA Fair	Ruins of C16 or early C17 bastle surviving to first floor level. Vault has mostly collapsed but a number of interesting features survive. English Heritage offered a grant in 2006 towards rectified photography work plus production of a specification and schedule for repairs. A further grant offer was made in 2008 towards consolidation works. The repair works commenced in 2009 and will be completed in 2011 Contact: Kate Wilson 0191 269 1221 Folly, probably 1720s, by Archdeacon Sharpe, Rector of Rothbury. Ashlar round tower c30 ft high. Probably the earliest folly in the county, said to have been built partly to alleviate local unemployment and partly to satisfy the Archdeacon's taste for astronomy. Local authority in negotiation with owner to secure emergency repairs and
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Bastle and associated buildings northwest of Comb, Comb, Tarset Listed Building Grade II, SM Good N/A F (E) Government Sharpe's Folly, Rothbury, Tosson Listed Building Grade II*, CA Fair Vacant	Ruins of C16 or early C17 bastle surviving to first floor level. Vault has mostly collapsed but a number of interesting features survive. English Heritage offered a grant in 2006 towards rectified photography work plus production of a specification and schedule for repairs. A further grant offer was made in 2008 towards consolidation works. The repain works commenced in 2009 and will be completed in 2011 Contact: Kate Wilson 0191 269 1221 Folly, probably 1720s, by Archdeacon Sharpe, Rector of Rothbury. Ashlar round tower c30 ft high. Probably the earliest folly in the county, said to have been built partly to alleviate local unemployment and partly to satisfy the Archdeacon's taste for astronomy. Local authority in negotiation with owner to secure emergency repairs and
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Bastle and associated buildings northwest of Comb, Comb, Tarset Listed Building Grade II, SM Good N/A F (E) Government Sharpe's Folly, Rothbury, Tosson Listed Building Grade II*, CA Fair Vacant C (C)	Ruins of C16 or early C17 bastle surviving to first floor level. Vault has mostly collapsed but a number of interesting features survive. English Heritage offered a grant in 2006 towards rectified photography work plus production of a specification and schedule for repairs. A further grant offer was made in 2008 towards consolidation works. The repair works commenced in 2009 and will be completed in 2011 Contact: Kate Wilson 0191 269 1221 Folly, probably 1720s, by Archdeacon Sharpe, Rector of Rothbury. Ashlar round tower c30 ft high. Probably the earliest folly in the county, said to have been built partly to alleviate local unemployment and partly to satisfy the Archdeacon's taste for astronomy. Local authority in negotiation with owner to secure emergency repairs and English Heritage has advised on the schedule of works. Contact: John Edwards 0191 269 1231 Tower of early C14 containing wall paintings of probable C16 date. The tower is roofless, with self-seeded shrubs in the wall tops and over the first-floor barrel-vaulting.
	SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Bastle and associated buildings northwest of Comb, Comb, Tarset Listed Building Grade II, SM Good N/A F (E) Government Sharpe's Folly, Rothbury, Tosson Listed Building Grade II*, CA Fair Vacant C (C) Company Cocklaw Tower, East Cocklaw, Wall	Ruins of C16 or early C17 bastle surviving to first floor level.Vault has mostly collapsed but a number of interesting features survive. English Heritage offered a grant in 2006 towards rectified photography work plus production of a specification and schedule for repairs. A further grant offer was made in 2008 towards consolidation works. The repair works commenced in 2009 and will be completed in 2011 Contact: Kate Wilson 0191 269 1221 Folly, probably 1720s, by Archdeacon Sharpe, Rector of Rothbury. Ashlar round tower c30 ft high. Probably the earliest folly in the county, said to have been built partly to alleviate local unemployment and partly to satisfy the Archdeacon's taste for astronomy. Local authority in negotiation with owner to secure emergency repairs and English Heritage has advised on the schedule of works. Contact: John Edwards 0191 269 1231 Tower of early C14 containing wall paintings of probable C16 date. The tower is roofless, with self-seeded shrubs in the wall tops and over the first-floor barrel-vaulting. The wall tops are perilous and there has been a partial
	SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Bastle and associated buildings northwest of Comb, Comb, Tarset Listed Building Grade II, SM Good N/A F (E) Government Sharpe's Folly, Rothbury, Tosson Listed Building Grade II*, CA Fair Vacant C (C) Company	Ruins of C16 or early C17 bastle surviving to first floor level. Vault has mostly collapsed but a number of interesting features survive. English Heritage offered a grant in 2006 towards rectified photography work plus production of a specification and schedule for repairs. A further grant offer was made in 2008 towards consolidation works. The repair works commenced in 2009 and will be completed in 2011 Contact: Kate Wilson 0191 269 1221 Folly, probably 1720s, by Archdeacon Sharpe, Rector of Rothbury. Ashlar round tower c30 ft high. Probably the earliest folly in the county, said to have been built partly to alleviate local unemployment and partly to satisfy the Archdeacon's taste for astronomy. Local authority in negotiation with owner to secure emergency repairs and English Heritage has advised on the schedule of works. Contact: John Edwards 0191 269 1231 Tower of early C14 containing wall paintings of probable C16 date. The tower is roofless, with self-seeded shrubs in the wall tops and over the first-floor barrel-vaulting. The wall tops are perilous and there has been a partial collapse of the vaulting. The wall paintings show recent loss and are highly vulnerable. Recent decay in the vaulting
	SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Bastle and associated buildings northwest of Comb, Comb, Tarset Listed Building Grade II, SM Good N/A F (E) Government Sharpe's Folly, Rothbury, Tosson Listed Building Grade II*, CA Fair Vacant C (C) Company Cocklaw Tower, East Cocklaw, Wall Listed Building Grade I, SM	Ruins of C16 or early C17 bastle surviving to first floor level. Vault has mostly collapsed but a number of interesting features survive. English Heritage offered a grant in 2006 towards rectified photography work plus production of a specification and schedule for repairs. A further grant offer was made in 2008 towards consolidation works. The repair works commenced in 2009 and will be completed in 2011 Contact: Kate Wilson 0191 269 1221 Folly, probably 1720s, by Archdeacon Sharpe, Rector of Rothbury. Ashlar round tower c30 ft high. Probably the earliest folly in the county, said to have been built partly to alleviate local unemployment and partly to satisfy the Archdeacon's taste for astronomy. Local authority in negotiation with owner to secure emergency repairs and English Heritage has advised on the schedule of works. Contact: John Edwards 0191 269 1231 Tower of early C14 containing wall paintings of probable C16 date. The tower is roofless, with self-seeded shrubs in the wall tops and over the first-floor barrel-vaulting. The wall tops are perilous and there has been a partial collapse of the vaulting. The wall paintings show recent
	SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME:	Bastle and associated buildings northwest of Comb, Comb, Tarset Listed Building Grade II, SM Good N/A F (E) Government Sharpe's Folly, Rothbury, Tosson Listed Building Grade II*, CA Fair Vacant C (C) Company Cocklaw Tower, East Cocklaw, Wall Listed Building Grade I, SM	Ruins of C16 or early C17 bastle surviving to first floor level. Vault has mostly collapsed but a number of interesting features survive. English Heritage offered a grant in 2006 towards rectified photography work plus production of a specification and schedule for repairs. A further grant offer was made in 2008 towards consolidation works. The repair works commenced in 2009 and will be completed in 2011 Contact: Kate Wilson 0191 269 1221 Folly, probably 1720s, by Archdeacon Sharpe, Rector of Rothbury. Ashlar round tower c30 ft high. Probably the earliest folly in the county, said to have been built partly to alleviate local unemployment and partly to satisfy the Archdeacon's taste for astronomy. Local authority in negotiation with owner to secure emergency repairs and English Heritage has advised on the schedule of works. Contact: John Edwards 0191 269 1231 Tower of early C14 containing wall paintings of probable C16 date. The tower is roofless, with self-seeded shrubs in the wall tops and over the first-floor barrel-vaulting. The wall tops are perilous and there has been a partial collapse of the vaulting. The wall paintings show recent loss and are highly vulnerable. Recent decay in the vaulting

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

		· · ·	
Sile	SITE NAME:	Bastle at Horneystead, 400m south west of The Ash, Wark	A defensive farmhouse of the type found only in the northern border counties of England. The walls stand up to 4.5 metres high but the first floor has collapsed
	DESIGNATION:	Scheduled Monument	on a barrel vault. The main cause for concern was a large tree growing out of the upper courses of the north wall,
	CONDITION:	Very bad	whose roots were displacing and dislodging original fabric.
	OCCUPANCY:		The tree was removed during 2009 but further
	PRIORITY:	B (B)	consolidation works are required.
	OWNER TYPE:	Private	Contact: Jenny Lee 0191 384 0114
	SITE NAME:	Carrshield Lead Mines and Ore Works, Carrshield, West Allen	The remains of two lead mines and an ore works on the base and lower slopes of the West Allen valley at Carrshield. The site was used over three centuries,
	DESIGNATION:	Scheduled Monument	leaving a complex assortment of remains. The grade II lodging shop is the largest of its kind in the North Pennines
	CONDITION:	Very bad	but has severe structural damage and parts of the stone
	OCCUPANCY:	N/A	wall revetment have collapsed into the river.
	PRIORITY:	A (A)	
The second second	OWNER TYPE:		Contact: Jenny Lee 0191 384 0114
	SITE NAME:	Mohopehead Lead Mine and Ore Works, Mohope, West Allen	Scheduled lead mine of C18/C19.The mineshop is in a very dangerous condition, with the roof and rear wall collapsing recently.The bouse team is slowly deteriorating
A CONTRACT OF	DESIGNATION:	Listed Building Grade II, SM	and trees are encroaching. Site included within North
and Stoppen	CONDITION:	Very bad	Pennines AONB management plan and lead mining strategy.
And Committee	OCCUPANCY:		
A A A A A A A A A A A A A A A A A A A	PRIORITY:	A (A)	
and the second sec	OWNER TYPE:		Contact: Kate Wilson 0191 269 1221
	SITE NAME:	Haydon Old Church, Old Haydon, Haydon	Former parish church with C12 chancel and C14 south chapel. Some Roman material has been used amongst the squared stonework and the font is a re-cut Roman altar. Building is in an isolated rural location and used very experdically The PCC is considering a case for redundancy
		Old Haydon, Haydon	chapel. Some Roman material has been used amongst the squared stonework and the font is a re-cut Roman altar. Building is in an isolated rural location and used very sporadically. The PCC is considering a case for redundancy.
	DESIGNATION:	Old Haydon, Haydon Listed Place of Worship Grade I	chapel. Some Roman material has been used amongst the squared stonework and the font is a re-cut Roman altar. Building is in an isolated rural location and used very sporadically. The PCC is considering a case for redundancy. The roof has serious problems, with a heavy build-up of moss holding water and exacerbating the problems caused
	DESIGNATION:	Old Haydon, Haydon Listed Place of Worship Grade I Very bad	chapel. Some Roman material has been used amongst the squared stonework and the font is a re-cut Roman altar. Building is in an isolated rural location and used very sporadically. The PCC is considering a case for redundancy. The roof has serious problems, with a heavy build-up of
	DESIGNATION: CONDITION: PRIORITY:	Old Haydon, Haydon Listed Place of Worship Grade I Very bad A (New entry)	chapel. Some Roman material has been used amongst the squared stonework and the font is a re-cut Roman altar. Building is in an isolated rural location and used very sporadically. The PCC is considering a case for redundancy. The roof has serious problems, with a heavy build-up of moss holding water and exacerbating the problems caused by water penetration through holes in the roof.
	DESIGNATION:	Old Haydon, Haydon Listed Place of Worship Grade I Very bad	chapel. Some Roman material has been used amongst the squared stonework and the font is a re-cut Roman altar. Building is in an isolated rural location and used very sporadically. The PCC is considering a case for redundancy. The roof has serious problems, with a heavy build-up of moss holding water and exacerbating the problems caused
	DESIGNATION: CONDITION: PRIORITY:	Old Haydon, Haydon Listed Place of Worship Grade I Very bad A (New entry)	chapel. Some Roman material has been used amongst the squared stonework and the font is a re-cut Roman altar. Building is in an isolated rural location and used very sporadically. The PCC is considering a case for redundancy. The roof has serious problems, with a heavy build-up of moss holding water and exacerbating the problems caused by water penetration through holes in the roof. Contact: John Edwards 0191 2691231 Parish church built in 1897, in Late Perpendicular style, to the designs of C Hodgson Fowler. Font has a C12 bowl on a C19 stem and there are medieval grave markers within the nave. Slate roof coverings have almost reached the end
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME:	Old Haydon, Haydon Listed Place of Worship Grade I Very bad A (New entry) Religious organisation Christ Church, Hepple	chapel. Some Roman material has been used amongst the squared stonework and the font is a re-cut Roman altar. Building is in an isolated rural location and used very sporadically. The PCC is considering a case for redundancy. The roof has serious problems, with a heavy build-up of moss holding water and exacerbating the problems caused by water penetration through holes in the roof. Contact: John Edwards 0191 2691231 Parish church built in 1897, in Late Perpendicular style, to the designs of C Hodgson Fowler. Font has a C12 bowl on a C19 stem and there are medieval grave markers within the nave. Slate roof coverings have almost reached the end of their useful life, particularly on the north slope, causing
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME:	Old Haydon, Haydon Listed Place of Worship Grade I Very bad A (New entry) Religious organisation Christ Church,	chapel. Some Roman material has been used amongst the squared stonework and the font is a re-cut Roman altar. Building is in an isolated rural location and used very sporadically. The PCC is considering a case for redundancy. The roof has serious problems, with a heavy build-up of moss holding water and exacerbating the problems caused by water penetration through holes in the roof. Contact: John Edwards 0191 2691231 Parish church built in 1897, in Late Perpendicular style, to the designs of C Hodgson Fowler. Font has a C12 bowl on a C19 stem and there are medieval grave markers within the nave. Slate roof coverings have almost reached the end of their useful life, particularly on the north slope, causing leaks. An outline repair programme has been drawn up and the church is building up funding to allow implementation
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Old Haydon, Haydon Listed Place of Worship Grade I Very bad A (New entry) Religious organisation Christ Church, Hepple Listed Place of Worship Grade II Poor	chapel. Some Roman material has been used amongst the squared stonework and the font is a re-cut Roman altar. Building is in an isolated rural location and used very sporadically. The PCC is considering a case for redundancy. The roof has serious problems, with a heavy build-up of moss holding water and exacerbating the problems caused by water penetration through holes in the roof. Contact: John Edwards 0191 2691231 Parish church built in 1897, in Late Perpendicular style, to the designs of C Hodgson Fowler. Font has a C12 bowl on a C19 stem and there are medieval grave markers within the nave. Slate roof coverings have almost reached the end of their useful life, particularly on the north slope, causing leaks. An outline repair programme has been drawn up and
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Old Haydon, Haydon Listed Place of Worship Grade I Very bad A (New entry) Religious organisation Christ Church, Hepple Listed Place of Worship Grade II	chapel. Some Roman material has been used amongst the squared stonework and the font is a re-cut Roman altar. Building is in an isolated rural location and used very sporadically. The PCC is considering a case for redundancy. The roof has serious problems, with a heavy build-up of moss holding water and exacerbating the problems caused by water penetration through holes in the roof. Contact: John Edwards 0191 2691231 Parish church built in 1897, in Late Perpendicular style, to the designs of C Hodgson Fowler. Font has a C12 bowl on a C19 stem and there are medieval grave markers within the nave. Slate roof coverings have almost reached the end of their useful life, particularly on the north slope, causing leaks. An outline repair programme has been drawn up and the church is building up funding to allow implementation
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: PRIORITY:	Old Haydon, Haydon Listed Place of Worship Grade I Very bad A (New entry) Religious organisation Christ Church, Hepple Listed Place of Worship Grade II Poor D (New entry)	chapel. Some Roman material has been used amongst the squared stonework and the font is a re-cut Roman altar. Building is in an isolated rural location and used very sporadically. The PCC is considering a case for redundancy. The roof has serious problems, with a heavy build-up of moss holding water and exacerbating the problems caused by water penetration through holes in the roof. Contact: John Edwards 0191 2691231 Parish church built in 1897, in Late Perpendicular style, to the designs of C Hodgson Fowler. Font has a C12 bowl on a C19 stem and there are medieval grave markers within the nave. Slate roof coverings have almost reached the end of their useful life, particularly on the north slope, causing leaks. An outline repair programme has been drawn up and the church is building up funding to allow implementation of the repair scheme.
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: PRIORITY:	Old Haydon, Haydon Listed Place of Worship Grade I Very bad A (New entry) Religious organisation Christ Church, Hepple Listed Place of Worship Grade II Poor D (New entry)	chapel. Some Roman material has been used amongst the squared stonework and the font is a re-cut Roman altar. Building is in an isolated rural location and used very sporadically. The PCC is considering a case for redundancy. The roof has serious problems, with a heavy build-up of moss holding water and exacerbating the problems caused by water penetration through holes in the roof. Contact: John Edwards 0191 2691231 Parish church built in 1897, in Late Perpendicular style, to the designs of C Hodgson Fowler. Font has a C12 bowl on a C19 stem and there are medieval grave markers within the nave. Slate roof coverings have almost reached the end of their useful life, particularly on the north slope, causing leaks. An outline repair programme has been drawn up and the church is building up funding to allow implementation of the repair scheme. Contact: John Edwards 0191 2691231
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME:	Old Haydon, Haydon Listed Place of Worship Grade I Very bad A (New entry) Religious organisation Christ Church, Hepple Listed Place of Worship Grade II Poor D (New entry) Religious organisation Church of St Cuthbert, Church Lane,	chapel. Some Roman material has been used amongst the squared stonework and the font is a re-cut Roman altar. Building is in an isolated rural location and used very sporadically. The PCC is considering a case for redundancy. The roof has serious problems, with a heavy build-up of moss holding water and exacerbating the problems caused by water penetration through holes in the roof. Contact: John Edwards 0191 2691231 Parish church built in 1897, in Late Perpendicular style, to the designs of C Hodgson Fowler. Font has a C12 bowl on a C19 stem and there are medieval grave markers within the nave. Slate roof coverings have almost reached the end of their useful life, particularly on the north slope, causing leaks. An outline repair programme has been drawn up and the church is building up funding to allow implementation of the repair scheme. Contact: John Edwards 0191 2691231
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME:	Old Haydon, Haydon Listed Place of Worship Grade I Very bad A (New entry) Religious organisation Christ Church, Hepple Listed Place of Worship Grade II Poor D (New entry) Religious organisation Church of St Cuthbert, Church Lane, Norham	chapel. Some Roman material has been used amongst the squared stonework and the font is a re-cut Roman altar. Building is in an isolated rural location and used very sporadically. The PCC is considering a case for redundancy. The roof has serious problems, with a heavy build-up of moss holding water and exacerbating the problems caused by water penetration through holes in the roof. Contact: John Edwards 0191 2691231 Parish church built in 1897, in Late Perpendicular style, to the designs of C Hodgson Fowler. Font has a C12 bowl on a C19 stem and there are medieval grave markers within the nave. Slate roof coverings have almost reached the end of their useful life, particularly on the north slope, causing leaks. An outline repair programme has been drawn up and the church is building up funding to allow implementation of the repair scheme. Contact: John Edwards 0191 2691231 Parish church built in the late C12, probably by Richard of Wolviston for Bishop Puiset. Eastern bay was added to chancel in early C14, with tower built in 1837 and south porch and aisle by Bonomi erected in 1846. The church is generally in a fair condition but the south aisle and porch roofs are leaking. Heritage Lottery Fund grant of £83,000 was offered in December 2010 towards
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME:	Old Haydon, Haydon Listed Place of Worship Grade I Very bad A (New entry) Religious organisation Christ Church, Hepple Listed Place of Worship Grade II Poor D (New entry) Religious organisation Church of St Cuthbert, Church Lane, Norham	chapel. Some Roman material has been used amongst the squared stonework and the font is a re-cut Roman altar. Building is in an isolated rural location and used very sporadically. The PCC is considering a case for redundancy. The roof has serious problems, with a heavy build-up of moss holding water and exacerbating the problems caused by water penetration through holes in the roof. Contact: John Edwards 0191 2691231 Parish church built in 1897, in Late Perpendicular style, to the designs of C Hodgson Fowler. Font has a C12 bowl on a C19 stem and there are medieval grave markers within the nave. Slate roof coverings have almost reached the end of their useful life, particularly on the north slope, causing leaks. An outline repair programme has been drawn up and the church is building up funding to allow implementation of the repair scheme. Contact: John Edwards 0191 2691231
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	Old Haydon, Haydon Listed Place of Worship Grade I Very bad A (New entry) Religious organisation Christ Church, Hepple Listed Place of Worship Grade II Poor D (New entry) Religious organisation Church of St Cuthbert, Church Lane, Norham	chapel. Some Roman material has been used amongst the squared stonework and the font is a re-cut Roman altar. Building is in an isolated rural location and used very sporadically. The PCC is considering a case for redundancy. The roof has serious problems, with a heavy build-up of moss holding water and exacerbating the problems caused by water penetration through holes in the roof. Contact: John Edwards 0191 2691231 Parish church built in 1897, in Late Perpendicular style, to the designs of C Hodgson Fowler. Font has a C12 bowl on a C19 stem and there are medieval grave markers within the nave. Slate roof coverings have almost reached the end of their useful life, particularly on the north slope, causing leaks. An outline repair programme has been drawn up and the church is building up funding to allow implementation of the repair scheme. Contact: John Edwards 0191 2691231 Parish church built in the late C12, probably by Richard of Wolviston for Bishop Puiset. Eastern bay was added to chancel in early C14, with tower built in 1837 and south porch and aisle by Bonomi erected in 1846. The church is generally in a fair condition but the south aisle and porch roofs are leaking. Heritage Lottery Fund grant of £83,000 was offered in December 2010 towards

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

33

SITE NAME:	Hadrian's Wall and vallum between the track and the field boundary east of milecastle 24		
DESIGNATION:	Scheduled Monument (No. 1010626)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Lucker camp, Adderstone with Lucker		
DESIGNATION:	Scheduled Monument (No. 1006478)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Iron Age defended settlement and cultivation	n terraces 600m	north east of Brown's Law Cottage, Akeld
DESIGNATION:	Scheduled Monument (No. 1019139)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Camp on Alnwick Moor, Alnwick		
DESIGNATION:	Scheduled Monument (No. 1006474)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Haggerston dovecote, Ancroft		
DESIGNATION:	Scheduled Monument (No. 1006570)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Round barrow 520m WNW of Quarry Cott	age, Bamburgh	
DESIGNATION:	Scheduled Monument (No. 1014503)	CONDITION:	Generally unsatisfactory
PRINCIPAL VULNERABILITY:	Public utilities	TREND:	with major localised problems Stable
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Defended settlement and Roman signal stati	on 410m south c	of West Crindledikes, Bardon Mill
DESIGNATION:	Scheduled Monument (No. 1018536)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Benthall round cairn, Beadnell		
DESIGNATION:	Scheduled Monument (No. 1008430)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

SITE NAME:	St Ebba's chapel and monastic site, Beadnell		
DESIGNATION:	Scheduled Monument (No. 1008563)	CONDITION:	Generally unsatisfactory
	``````````````````````````````````````		with major localised problems
PRINCIPAL VULNERABILITY:	Moderate visitor erosion	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Chester's Hill camps, Belford		
DESIGNATION:	Scheduled Monument (No. 1006513)	CONDITION:	Generally unsatisfactory
JESIGNATION:	Scheduled Fiohument (No. 1000515)	CONDITION:	with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Huckhoe palisaded enclosure, defended sett 550m north east of Bolam West Houses, Be	lement and Roma	ano-British settlement,
DESIGNATION:	Scheduled Monument (No. 1011838)	CONDITION:	Generally satisfactory
		CONDITION:	but with significant localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Springhill Roman camp, Berwick upon Tweed	ł	
DESIGNATION:	Scheduled Monument (No. 1003655)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Bewick Hill camp, Bewick		
DESIGNATION:	Scheduled Monument (No. 1006580)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Bewick Hill Moor camp, Old Bewick, Bewick	ζ	
DESIGNATION:	Scheduled Monument (No. 1006582)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Romano-British farmstead, 520m north east	of Birtley Shields	s, Birtley
DESIGNATION:	Scheduled Monument (No. 1009676)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
		CONTACT.	
SITE NAME:	Romano-British settlement, 300m north of T	The Heugh, Birtle	у
DESIGNATION:	Scheduled Monument (No. 1010045)	CONDITION:	Generally satisfactory
			but with significant localised problems
	F		
PRINCIPAL VULNERABILITY: OWNER TYPE:	Forestry Private	TREND: CONTACT:	Declining Stephen Allott 0191 269 1235

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

## ABBREVIATIONS

IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

35

SITE NAME:	Hut circle settlement and field system, Ron 750m north east of Burntshield Haugh, Blar		ment, hush and lead ore works,
DESIGNATION:	Scheduled Monument (No. 1017959)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
GITE NAME:	Defended settlement, 450m NNW of Fern	ey Chesters, Caph	eaton
designation:	Scheduled Monument (No. 1011835)	CONDITION:	Generally unsatisfactory
	Scheduled Hondment (140. 1011055)	CONDITION.	with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Romano-British settlement and Iron Age de 550m north east of Shaftoe Grange, Caphe		t,
DESIGNATION:	Scheduled Monument (No. 1013757)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Double ditched enclosure south west of Br	oomhouse, Chatt	on
DESIGNATION:	Scheduled Monument (No. 1006410)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Simonside camp, Chatton		
DESIGNATION:	Scheduled Monument (No. 1002907)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate stock erosion	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Two cairn cemeteries west of Willie Law, C	Chatton	
DESIGNATION:	Scheduled Monument (No. 1006451)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Hepburn Crags camp, Chillingham		
DESIGNATION:	Scheduled Monument (No. 1006547)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Corbridge (Corstopitum) Roman station, C	Corbridge	
DESIGNATION:	Scheduled Monument (No. 1006611)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Concentration
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

## ABBREVIATIONS

SITE NAME:	Hadrian's Wall and vallum between the Fen in wall miles 21 and 22, Corbridge	ce Burn and the t	rack to Portgate Cottage
DESIGNATION:	Scheduled Monument (No. 1010625)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
DWNER TYPE:	Other	CONTACT:	Stephen Allott 0191 269 1235
ITE NAME:	Cornhill Castle, Cornhill-on-Tweed		
DESIGNATION:	Scheduled Monument (No. 1006508)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
WNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
ITE NAME:	Ridsdale ironworks, Corsenside		
DESIGNATION:	Scheduled Monument (No. 1006420)	CONDITION:	Generally satisfactory but with significant localised problems
RINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
ITE NAME:	Cresswell tower house, Cresswell		
DESIGNATION:	Scheduled Monument (No. 1014509)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
DWNER TYPE:	Private Heiferlaw defended settlement, I 00m north		
ITE NAME:			
ITE NAME: DESIGNATION:	Heiferlaw defended settlement, 100m north	of Holywell, Den	wick Generally unsatisfactory
	Heiferlaw defended settlement, 100m north Scheduled Monument (No. 1014080)		wick Generally unsatisfactory with major localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	<b>Heiferlaw defended settlement, 100m north</b> Scheduled Monument (No. 1014080) Forestry	CONDITION: TREND: CONTACT:	wick Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME:	Heiferlaw defended settlement, 100m north Scheduled Monument (No. 1014080) Forestry Private Incised rocks 550yds (500m) north west of	of Holywell, Den CONDITION: TREND: CONTACT:	wick Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235
TE NAME: ESIGNATION: RINCIPAL VULNERABILITY: WNER TYPE: TE NAME: ESIGNATION:	Heiferlaw defended settlement, 100m north Scheduled Monument (No. 1014080) Forestry Private Incised rocks 550yds (500m) north west of	of Holywell, Den CONDITION: TREND: CONTACT:	wick Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235
	Heiferlaw defended settlement, 100m north Scheduled Monument (No. 1014080) Forestry Private Incised rocks 550yds (500m) north west of Scheduled Monument (No. 1006555)	of Holywell, Den CONDITION: TREND: CONTACT: Doddington Dear CONDITION:	wick Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 NWood, Doddington Generally satisfactory but with significant localised problems
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE:	Heiferlaw defended settlement, 100m north         Scheduled Monument (No. 1014080)         Forestry         Private         Incised rocks 550yds (500m) north west of         Scheduled Monument (No. 1006555)         Extensive natural erosion	of Holywell, Den CONDITION: TREND: CONTACT: Doddington Deal CONDITION: TREND:	wick Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 NWood, Doddington Generally satisfactory but with significant localised problems Declining
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME:	Heiferlaw defended settlement, 100m north         Scheduled Monument (No. 1014080)         Forestry         Private         Incised rocks 550yds (500m) north west of         Scheduled Monument (No. 1006555)         Extensive natural erosion         Private	of Holywell, Den CONDITION: TREND: CONTACT: Doddington Deal CONDITION: TREND:	wick Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 NWood, Doddington Generally satisfactory but with significant localised problems Declining
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: ITE NAME: DESIGNATION: DESIGNATION: DESIGNATION:	Heiferlaw defended settlement, 100m north         Scheduled Monument (No. 1014080)         Forestry         Private         Incised rocks 550yds (500m) north west of         Scheduled Monument (No. 1006555)         Extensive natural erosion         Private         Roughting Linn camp, Doddington	of Holywell, Den CONDITION: TREND: CONTACT: Doddington Deat CONDITION: TREND: CONTACT:	wick Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 NWood, Doddington Wood, Doddington Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 Generally unsatisfactory
ITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWINER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWINER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY:	Heiferlaw defended settlement, 100m north         Scheduled Monument (No. 1014080)         Forestry         Private         Incised rocks 550yds (500m) north west of         Scheduled Monument (No. 1006555)         Extensive natural erosion         Private         Roughting Linn camp, Doddington         Scheduled Monument (No. 1006601)	of Holywell, Den CONDITION: TREND: CONTACT: Doddington Deal CONDITION: TREND: CONDITION:	wick Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 NWood, Doddington Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems
NTE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE:	Heiferlaw defended settlement, 100m north         Scheduled Monument (No. 1014080)         Forestry         Private         Incised rocks 550yds (500m) north west of         Scheduled Monument (No. 1006555)         Extensive natural erosion         Private         Roughting Linn camp, Doddington         Scheduled Monument (No. 1006601)         Scrub / tree growth	of Holywell, Den CONDITION: TREND: CONTACT: Doddirgton Deal CONDITION: CONDITION: CONTACT: TREND: CONDITION:	wick Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 NWood, Doddington Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION:	Heiferlaw defended settlement, 100m north         Scheduled Monument (No. 1014080)         Forestry         Private         Incised rocks 550yds (500m) north west of         Scheduled Monument (No. 1006555)         Extensive natural erosion         Private         Roughting Linn camp, Doddington         Scheduled Monument (No. 1006601)         Scrub / tree growth         Private	of Holywell, Den CONDITION: TREND: CONTACT: Doddirgton Deal CONDITION: CONDITION: CONTACT: TREND: CONDITION:	wick Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 NWood, Doddington Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:	Heiferlaw defended settlement, 100m north         Scheduled Monument (No. 1014080)         Forestry         Private         Incised rocks 550yds (500m) north west of         Scheduled Monument (No. 1006555)         Extensive natural erosion         Private         Roughting Linn camp, Doddington         Scheduled Monument (No. 1006601)         Scrub / tree growth         Private         Two camps and cup and ring marked rocks	of Holywell, Den CONDITION: TREND: CONTACT: DOddIngton Dead CONDITION: CONDITION: CONTACT: CONTACT: TREND: CONTACT:	wick Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 NWood, Doddington NWood, Doddington Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 Mington Generally unsatisfactory

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS CA LB/LBs LPA NP RPG SM/SMs UA WHS

IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site

SITE NAME:	Iron Age defended settlement in Camp Plan	tation, 350m nort	h west of North Charlton Mill, Eglingham
DESIGNATION:	Scheduled Monument (No. 1017955)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Unknown
DWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
ITE NAME:	Site south west of Thirlings, Ewart		
DESIGNATION:	Scheduled Monument (No. 1006436)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
DWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
ITE NAME:	Haw Hill camp, Falstone		
DESIGNATION:	Scheduled Monument (No. 1006491)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Flooding	TREND:	Unknown
DWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
ITE NAME:	Camp 400yds (370m) NNE of Flodden, For	d	
DESIGNATION:	Scheduled Monument (No. 1006445)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
ITE NAME:	Circular enclosure west of Second Linthaug	h, Ford	
DESIGNATION:	Scheduled Monument (No. 1006430)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Flodden camp, Ford		
DESIGNATION:	Scheduled Monument (No. 1006481)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing Private	TREND:	Unknown Stephen Allott 0191 269 1235
DWNER TYPE:	rnvate	CONTACT:	
ITE NAME:	Flodden Edge camp, Ford		
DESIGNATION:	Scheduled Monument (No. 1006449)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
DWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
ITE NAME:	Ford Westfield settlement, Ford		
	Scheduled Monument (No. 1006423)	CONDITION:	Extensive significant problems
JESIGINATION:	Arable ploughing	TREND:	Unknown
		CONITACT	
RINCIPAL VULNERABILITY:	Private	CONTACT:	Stephen Allott 0191 269 1235
PESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME:			Stephen Allott 0171 267 1235
RINCIPAL VULNERABILITY: OWNER TYPE:	Private		Generally unsatisfactory
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Private Two incised rocks on Broom Ridge, Hunter	's Moor, Ford	

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the solution of the solution

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Hadrian's Wall and vallum from Throckley to East Town House, Heddon-on-the-Wall in wall mile I I, Heddon-on-the-Wall				
DESIGNATION:	Scheduled Monument (No. 1010616)		Unknown		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown		
OWNER TYPE:	Other	CONTACT:	Stephen Allott 0191 269 1235		
SITE NAME:	Romano-British enclosed settlement, 800m r	north west of Ea	st Bolton, Hedgeley		
DESIGNATION:	Scheduled Monument (No. 1007446)	CONDITION:	Generally satisfactory		
			but with significant localised problems		
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Unknown		
DWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235		
SITE NAME:	'The Palace' medieval house and Tudor suppl	y base, Holy Isla	nd village, Holy Island		
DESIGNATION:	Scheduled Monument (No. 1014571)	CONDITION:	Generally satisfactory		
			but with significant localised problems		
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235		
SITE NAME:	Medieval chapel and associated building on S	t Cuthbert's Isle	Holy Island		
DESIGNATION:	Scheduled Monument (No. 1014485)	CONDITION:	Generally satisfactory		
			but with significant localised problems		
RINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235		
OWNER TYPE:	Private Nafferton castle and tower house, 750m eas				
SITE NAME:	Nafferton castle and tower house, 750m eas	t of Nafferton Fa	arm, Horsley		
			arm, Horsley Generally satisfactory		
SITE NAME: DESIGNATION:	Nafferton castle and tower house, 750m eas Scheduled Monument (No. 1018369)	t of Nafferton Fa	Generally satisfactory but with significant localised problems		
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Nafferton castle and tower house, 750m eas Scheduled Monument (No. 1018369) Deterioration – in need of management	t of Nafferton Fa condition: trend:	arm, Horsley Generally satisfactory but with significant localised problems Declining		
SITE NAME:	Nafferton castle and tower house, 750m eas Scheduled Monument (No. 1018369)	t of Nafferton Fa	Generally satisfactory but with significant localised problems		
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Nafferton castle and tower house, 750m eas Scheduled Monument (No. 1018369) Deterioration – in need of management	t of Nafferton Fa CONDITION: TREND: CONTACT:	<b>arm, Horsley</b> Generally satisfactory but with significant localised problems Declining		
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:	Nafferton castle and tower house, 750m eas Scheduled Monument (No. 1018369) Deterioration – in need of management Private	t of Nafferton Fa CONDITION: TREND: CONTACT:	arm, Horsley Generally satisfactory but with significant localised problems Declining		
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWINER TYPE:	Nafferton castle and tower house, 750m eas Scheduled Monument (No. 1018369) Deterioration – in need of management Private Remains of medieval bridge, Chollerford, Hu	t of Nafferton F condition: trend: contact: mshaugh	Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235		
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Nafferton castle and tower house, 750m eas         Scheduled Monument (No. 1018369)         Deterioration – in need of management         Private         Remains of medieval bridge, Chollerford, Hu         Scheduled Monument (No. 1006567)	t of Nafferton Fa CONDITION: TREND: CONTACT: mshaugh CONDITION:	Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 Extensive significant problems		
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWINER TYPE: SITE NAME: DESIGNATION:	Nafferton castle and tower house, 750m eas         Scheduled Monument (No. 1018369)         Deterioration – in need of management         Private         Remains of medieval bridge, Chollerford, Hu         Scheduled Monument (No. 1006567)         Other	t of Nafferton Fa CONDITION: TREND: CONTACT: mshaugh CONDITION: TREND: CONTACT:	Arm, Horsley Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 Extensive significant problems Unknown		
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:	Nafferton castle and tower house, 750m eas         Scheduled Monument (No. 1018369)         Deterioration – in need of management         Private         Remains of medieval bridge, Chollerford, Hu         Scheduled Monument (No. 1006567)         Other         Private	t of Nafferton Fa CONDITION: TREND: CONTACT: mshaugh CONDITION: TREND: CONTACT:	Arm, Horsley Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 Extensive significant problems Unknown Stephen Allott 0191 269 1235 Generally unsatisfactory		
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION:	Nafferton castle and tower house, 750m eas         Scheduled Monument (No. 1018369)         Deterioration – in need of management         Private         Remains of medieval bridge, Chollerford, Hu         Scheduled Monument (No. 1006567)         Other         Private         Round cairn 790m west of Smithy Strip, Ilder         Scheduled Monument (No. 1016248)	t of Nafferton Fa CONDITION: TREND: CONTACT: CONDITION: TREND: CONDITION: TREND: CONDITION:	Arm, Horsley Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 Extensive significant problems Unknown Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems		
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY:	Nafferton castle and tower house, 750m ease         Scheduled Monument (No. 1018369)         Deterioration – in need of management         Private         Remains of medieval bridge, Chollerford, Hu         Scheduled Monument (No. 1006567)         Other         Private         Round cairn 790m west of Smithy Strip, Ilder         Scheduled Monument (No. 1016248)         Forestry	t of Nafferton Fa CONDITION: TREND: CONTACT: mshaugh CONDITION: TREND: CONDITION: TREND: CONDITION:	Arm, Horsley Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 Extensive significant problems Unknown Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems Unknown		
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Nafferton castle and tower house, 750m eas         Scheduled Monument (No. 1018369)         Deterioration – in need of management         Private         Remains of medieval bridge, Chollerford, Hu         Scheduled Monument (No. 1006567)         Other         Private         Round cairn 790m west of Smithy Strip, Ilder         Scheduled Monument (No. 1016248)	t of Nafferton Fa CONDITION: TREND: CONTACT: CONDITION: TREND: CONDITION: TREND: CONDITION:	Arm, Horsley Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 Extensive significant problems Unknown Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems		
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION:	Nafferton castle and tower house, 750m ease         Scheduled Monument (No. 1018369)         Deterioration – in need of management         Private         Remains of medieval bridge, Chollerford, Hu         Scheduled Monument (No. 1006567)         Other         Private         Round cairn 790m west of Smithy Strip, Ilder         Scheduled Monument (No. 1016248)         Forestry	t of Nafferton Fa CONDITION: TREND: CONTACT: mshaugh CONDITION: TREND: CONDITION: TREND: CONDITION:	Arm, Horsley Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 Extensive significant problems Unknown Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems Unknown		
ATE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWINER TYPE: ATE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWINER TYPE: ATE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWINER TYPE: ATE NAME: DESIGNATION:	Nafferton castle and tower house, 750m ease         Scheduled Monument (No. 1018369)         Deterioration – in need of management         Private         Remains of medieval bridge, Chollerford, Hu         Scheduled Monument (No. 1006567)         Other         Private         Round cairn 790m west of Smithy Strip, Ilder         Scheduled Monument (No. 1016248)         Forestry         Private	t of Nafferton Fa CONDITION: TREND: CONTACT: mshaugh CONDITION: TREND: CONDITION: TREND: CONDITION:	Arm, Horsley Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 Extensive significant problems Unknown Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems Unknown		
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWINER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWINER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWINER TYPE: SITE NAME:	Nafferton castle and tower house, 750m ease         Scheduled Monument (No. 1018369)         Deterioration – in need of management         Private         Remains of medieval bridge, Chollerford, Hu         Scheduled Monument (No. 1006567)         Other         Private         Round cairn 790m west of Smithy Strip, Ilder         Scheduled Monument (No. 1016248)         Forestry         Private         Castle Hill camp, Kilham	t of Nafferton Fa CONDITION: TREND: CONTACT: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION:	Arm, Horsley Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 Extensive significant problems Unknown Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235		
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:	Nafferton castle and tower house, 750m ease         Scheduled Monument (No. 1018369)         Deterioration – in need of management         Private         Remains of medieval bridge, Chollerford, Hu         Scheduled Monument (No. 1006567)         Other         Private         Round cairn 790m west of Smithy Strip, Ilder         Scheduled Monument (No. 1016248)         Forestry         Private         Castle Hill camp, Kilham	t of Nafferton Fa CONDITION: TREND: CONTACT: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION:	Arm, Horsley Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 Extensive significant problems Unknown Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235		

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Red House Roman camp, Newbrough		
DESIGNATION:	Scheduled Monument (No. 1006492)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Overgrass tower house 150m south east of	Newmoor Hall, N	Newton-on-the-Moor and Swarland
DESIGNATION:	Scheduled Monument (No. 1016711)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Camp in Oakwood south east of Plenmeller	r village, Plenmelle	er with Whitfield
DESIGNATION:	Scheduled Monument (No. 1006484)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SWINER TIFE.		CONTACT:	
SITE NAME:	Ellsnook tumulus, Rock, Rennington		
DESIGNATION:	Scheduled Monument (No. 1006564)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Cairn 900m north east of Old Rothbury hil		
DESIGNATION:	Scheduled Monument (No. 1008757)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Old Rothbury multivallate hillfort and cairm	field, Rothbury	
DESIGNATION:	Scheduled Monument (No. 1011616)	CONDITION:	Generally unsatisfactory with major localised problems
	Scheduled Monument (No. 1011616) Plant growth	CONDITION: TREND:	, ,
PRINCIPAL VULNERABILITY:			with major localised problems
PRINCIPAL VULNERABILITY: OWNER TYPE:	Plant growth	TREND: CONTACT:	with major localised problems Unknown Stephen Allott 0191 269 1235
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Plant growth Private The vallum between Oatens Bank,	TREND: CONTACT:	with major localised problems Unknown Stephen Allott 0191 269 1235
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Plant growth Private The vallum between Oatens Bank, Harlow Hill, and Whittle Dene Watercourse	trend: contact: e in wall mile 16, S	with major localised problems Unknown Stephen Allott 0191 269 1235 tamfordham
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Plant growth Private The vallum between Oatens Bank, Harlow Hill, and Whittle Dene Watercourse Scheduled Monument (No. 1010621)	TREND: CONTACT: e in wall mile 16, S CONDITION:	with major localised problems Unknown Stephen Allott 0191 269 1235 tamfordham Extensive significant problems
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Plant growth Private The vallum between Oatens Bank, Harlow Hill, and Whittle Dene Watercourse Scheduled Monument (No. 1010621) Arable ploughing	TREND: CONTACT: e in wall mile 16, S CONDITION: TREND: CONTACT:	with major localised problems Unknown Stephen Allott 0191 269 1235 tamfordham Extensive significant problems Unknown
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Plant growth Private The vallum between Oatens Bank, Harlow Hill, and Whittle Dene Watercourse Scheduled Monument (No. 1010621) Arable ploughing Private	TREND: CONTACT: e in wall mile 16, S CONDITION: TREND: CONTACT:	with major localised problems Unknown Stephen Allott 0191 269 1235 tamfordham Extensive significant problems Unknown Stephen Allott 0191 269 1235 Generally satisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Plant growth Private The vallum between Oatens Bank, Harlow Hill, and Whittle Dene Watercourse Scheduled Monument (No. 1010621) Arable ploughing Private Two round cairns 590m and 610m east of B	TREND: CONTACT: CONTACT: CONDITION: TREND: CONTACT: Burn Brae, Tosson	with major localised problems Unknown Stephen Allott 0191 269 1235 tamfordham Extensive significant problems Unknown Stephen Allott 0191 269 1235

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

# HERITAGE AT RISK 2011 / NORTH EAST / NORTHUMBERLAND (UA) / NORTHUMBERLAND (NP)

and the states of	SITE NAME:	Tillmouth Park, Cornhill-on-Tweed		ate C19 picturesque pleasure grounds and dens. The trust-owned Twizel medieval tower
C MARTIN	DESIGNATION:	Registered Park and Garden Grade II*, also I I LBs, 2 SMs	house and eye-catcher is on the H Picturesque walk alongside River Ti	
A CAR	CONDITION:	Generally satisfactory but with significant localised problems	undertaker	n, some woodland management work below the castle. Grade II listed bridge Burn and adjacent tunnel both at risk.
THE PARTY OF	VULNERABILITY	High	over Dearr	burn and adjacent turner both at risk.
St. Barbar	TREND: OWNER TYPE:	Declining Mixed, multiple owners	Contact: Ar	ndy Wimble 01904 601970
			Devesting	
	SITE NAME: DESIGNATION:	Seaton Delaval Registered Park and Garden Grade II*,	1950s-60s,	an early C18 garden, partially restored in the the setting for the house designed by Sir John
		also 18 LBs	regeneratio	n 1719. Approach avenue deteriorating, natural on concealing some key landscape features
	CONDITION:	Generally satisfactory but with significant localised problems	acquired by	e Mausoleum. The Hall and its landscape were / the National Trust in December 2009 and visitors in May 2010.
Net an	VULNERABILITY	Medium	opened to	VISICOLS IIT FIAY 2010.
	TREND: OWNER TYPE:	Improving Corporate, single owner	Contact: Ar	ndy Wimble 01904 601970
		Corporate, single owner	Contact. Ai	
NORTHUMBERLAND	(NP)			
	SITE NAME:	Hadrian's Wall from Cockmount Hill to Walltown, Greenhead, Tynedale	track to Co Wall Miles	unconsolidated Hadrian's Wall (between the ockmount Hill and Walltown Quarry East in 43, 44 and 45). Many of the issues have been through a Higher Level Stewardship (HLS)
	DESIGNATION:	Scheduled Monument, WHS	scheme inv	olving the owner, Natural England and EH.
	CONDITION:	Poor		tions of the Wall are under different ownershi ots will be made during 2011/12 to bring these
	OCCUPANCY:			ther HLS agreement.
and the second of the	PRIORITY:	B (B)		
	OWNER TYPE:	Irust	Contact: Mike Collins 0191 269 1212	
	SITE NAME:	Evistones Deserted Village, Rochester, Tynedale	bastles. On basement. S	a deserted settlement containing three e survives to first floor level with a vaulted Small scale consolidation work would stabilise
and the state of the state	DESIGNATION:	Scheduled Monument		gs. Included in Northumberland National Park's pastles. A programme of repair and recording is
	CONDITION:	Poor	under discu	
Star Sta	OCCUPANCY:	N/A		
States and	PRIORITY:	C (C)		
	OWNER TYPE:	Private	Contact: Ka	ate Wilson 0191 269 1221
SITE NAME:	Hut circle	770m south east of White Gables, Ake	eld	
DESIGNATION:	Scheduled	Monument (No. 1017380)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant grow	th	TREND:	Unknown
DWNER TYPE:	Private		CONTACT:	Stephen Allott 0191 269 1235
ITE NAME:	Prehistori	c enclosed settlement, Iron Age hillfort	and mediev	al shielings on Humbleton Hill, Akeld
DESIGNATION:		Monument (No. 1016714)	CONDITION:	Generally satisfactory
	Extensive	visitor erosion		but with significant localised problems Declining
PRINCIPAL VULNERABILITY: DWNER TYPE:	Private		TREND: CONTACT:	Stephen Allott 0191 269 1235
JITE NAME:	Romano	British farmstead 630m south west of V	Vhite Gable	s Akeld
DESIGNATION:		Monument (No. 1017379)	CONDITION:	Generally unsatisfactory
			CC. NDITION.	with major localised problems
			TOOLO	Unknown
PRINCIPAL VULNERABILITY:	Plant grow Private		TREND:	Stephen Allott 0191 269 1235

#### PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the solution of the solution

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Romano-British farmstead 900m north east of triangulation point on Gains Law, Akeld				
DESIGNATION:	Scheduled Monument (No. 1017381)	CONDITION:	Generally unsatisfactory with major localised problems		
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Unknown		
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235		
SITE NAME:	Romano-British farmstead and part of an as	sociated field sys	tem 630m south west of White Gables, A		
DESIGNATION:	Scheduled Monument (No. 1019311)	CONDITION:	Generally unsatisfactory		
	Di la la la		with major localised problems		
PRINCIPAL VULNERABILITY:	Plant growth	TREND:			
DWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235		
SITE NAME:	Romano-British native farmstead 970m nor	th east of triangu	lation point on Gains Law, Akeld		
DESIGNATION:	Scheduled Monument (No. 1017382)	CONDITION:	Generally unsatisfactory		
	· · · /		with major localised problems		
RINCIPAL VULNERABILITY:	Plant growth	TREND:	Unknown		
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235		
SITE NAME:	Two Roman period native settlements and a	associated field su	stem on Coldberry Hill Akeld		
DESIGNATION:	Scheduled Monument (No. 1017043)	CONDITION:	Generally unsatisfactory		
JESIGINATION:	Scheddied Hondment (140. 1017015)	CONDITION:	with major localised problems		
RINCIPAL VULNERABILITY:	Plant growth	TREND:	Unknown		
RINCIPAL VOLNERABILI I Y: DWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235		
		CONTACT.	Stephen / 10tt 0171 207 1255		
SITE NAME:	Unenclosed scooped settlement on the eas	t slope of Hareho			
SITE NAME:	750m south east of High Akeld Cottages, A	t slope of Hareho	ppe Hill,		
		t slope of Hareho	Generally unsatisfactory		
	<b>750m south east of High Akeld Cottages, A</b> Scheduled Monument (No. 1014932)	t slope of Harehc keld	Generally unsatisfactory with major localised problems		
DESIGNATION: PRINCIPAL VULNERABILITY:	<b>750m south east of High Akeld Cottages, A</b> Scheduled Monument (No. 1014932) Plant growth	t slope of Harehc keld CONDITION: TREND:	Generally unsatisfactory with major localised problems Unknown		
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	<b>750m south east of High Akeld Cottages, A</b> Scheduled Monument (No. 1014932)	t slope of Harehc keld condition:	Generally unsatisfactory with major localised problems		
DESIGNATION: PRINCIPAL VULNERABILITY:	<b>750m south east of High Akeld Cottages, A</b> Scheduled Monument (No. 1014932) Plant growth	t slope of Hareho keld CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235		
DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME:	<b>750m south east of High Akeld Cottages, A</b> Scheduled Monument (No. 1014932) Plant growth Private	t slope of Hareho keld CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235		
DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME:	750m south east of High Akeld Cottages, A Scheduled Monument (No. 1014932) Plant growth Private Unenclosed stone hut circle settlement 120	t slope of Hareho keld CONDITION: TREND: CONTACT: m north west of	ope Hill, Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 Gleadscleugh, Akeld		
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION:	750m south east of High Akeld Cottages, A Scheduled Monument (No. 1014932) Plant growth Private Unenclosed stone hut circle settlement 120	t slope of Hareho keld CONDITION: TREND: CONTACT: m north west of	ppe Hill, Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 Gleadscleugh, Akeld Generally unsatisfactory		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	750m south east of High Akeld Cottages, A Scheduled Monument (No. 1014932) Plant growth Private Unenclosed stone hut circle settlement 120 Scheduled Monument (No. 1014929)	t slope of Hareho keld CONDITION: TREND: CONTACT: m north west of CONDITION:	ppe Hill, Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 Gleadscleugh, Akeld Generally unsatisfactory with major localised problems		
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	750m south east of High Akeld Cottages, A         Scheduled Monument (No. 1014932)         Plant growth         Private         Unenclosed stone hut circle settlement 120         Scheduled Monument (No. 1014929)         Plant growth         Private	t slope of Hareho keld CONDITION: TREND: CONTACT: m north west of CONDITION: TREND:	ppe Hill, Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 Gleadscleugh, Akeld Generally unsatisfactory with major localised problems Unknown		
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DW	750m south east of High Akeld Cottages, A         Scheduled Monument (No. 1014932)         Plant growth         Private         Unenclosed stone hut circle settlement 120         Scheduled Monument (No. 1014929)         Plant growth         Private         Crigdon Hill round cairn, Alwinton	t slope of Hareho keld CONDITION: TREND: CONTACT: m north west of CONDITION: TREND: CONTACT:	ope Hill,         Generally unsatisfactory         with major localised problems         Unknown         Stephen Allott 0191 269 1235    Gleadscleugh, Akeld          Generally unsatisfactory         with major localised problems         Unknown         Stephen Allott 0191 269 1235		
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: PRINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME:	750m south east of High Akeld Cottages, A         Scheduled Monument (No. 1014932)         Plant growth         Private         Unenclosed stone hut circle settlement 120         Scheduled Monument (No. 1014929)         Plant growth         Private	t slope of Hareho keld CONDITION: TREND: CONTACT: m north west of CONDITION: TREND:	ppe Hill, Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 Gleadscleugh, Akeld Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 Generally unsatisfactory		
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION:	750m south east of High Akeld Cottages, A         Scheduled Monument (No. 1014932)         Plant growth         Private         Unenclosed stone hut circle settlement 120         Scheduled Monument (No. 1014929)         Plant growth         Private         Crigdon Hill round cairn, Alwinton         Scheduled Monument (No. 1008567)	t slope of Hareho keld CONDITION: TREND: CONTACT: m north west of CONDITION: TREND: CONTACT:	Generally unsatisfactory         with major localised problems         Unknown         Stephen Allott 0191 269 1235    Gleadscleugh, Akeld  Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235  Generally unsatisfactory with major localised problems		
DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: RINCIPAL VULNERABILITY: RINCIPAL VULNERABILITY: DWNER TYPE: RINCIPAL VULNERABILITY: DESIGNATION: RINCIPAL VULNERABILITY: RINCIPAL VULNERABILITY: RINCIPAL VULNERABILITY:	750m south east of High Akeld Cottages, A         Scheduled Monument (No. 1014932)         Plant growth         Private         Unenclosed stone hut circle settlement 120         Scheduled Monument (No. 1014929)         Plant growth         Private         Crigdon Hill round cairn, Alwinton         Scheduled Monument (No. 1008567)         Other	t slope of Hareho keld CONDITION: TREND: CONTACT: CONDITION: TREND: CONDITION: CONDITION:	generally unsatisfactory         with major localised problems         Unknown         Stephen Allott 0191 269 1235    Gleadscleugh, Akeld  Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235  Generally unsatisfactory with major localised problems Stephen Allott 0191 269 1235		
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY:	750m south east of High Akeld Cottages, A         Scheduled Monument (No. 1014932)         Plant growth         Private         Unenclosed stone hut circle settlement 120         Scheduled Monument (No. 1014929)         Plant growth         Private         Crigdon Hill round cairn, Alwinton         Scheduled Monument (No. 1008567)	t slope of Hareho keld CONDITION: TREND: CONTACT: m north west of CONDITION: TREND: CONTACT:	Generally unsatisfactory         with major localised problems         Unknown         Stephen Allott 0191 269 1235    Gleadscleugh, Akeld  Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235  Generally unsatisfactory with major localised problems		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DITE	750m south east of High Akeld Cottages, A         Scheduled Monument (No. 1014932)         Plant growth         Private         Unenclosed stone hut circle settlement 120         Scheduled Monument (No. 1014929)         Plant growth         Private         Crigdon Hill round cairn, Alwinton         Scheduled Monument (No. 1008567)         Other	t slope of Harehor keld CONDITION: TREND: CONTACT: m north west of CONDITION: TREND: CONTACT: CONTACT: TREND: CONDITION:	Generally unsatisfactory         with major localised problems         Unknown         Stephen Allott 0191 269 1235    Gleadscleugh, Akeld          Generally unsatisfactory         with major localised problems         Unknown         Stephen Allott 0191 269 1235    Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235          Generally unsatisfactory         with major localised problems         Stephen Allott 0191 269 1235		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: DESIGNATION	750m south east of High Akeld Cottages, A         Scheduled Monument (No. 1014932)         Plant growth         Private         Unenclosed stone hut circle settlement 120         Scheduled Monument (No. 1014929)         Plant growth         Private         Crigdon Hill round cairn, Alwinton         Scheduled Monument (No. 1008567)         Other         Government or Agency	t slope of Harehor keld CONDITION: TREND: CONTACT: m north west of CONDITION: TREND: CONTACT: CONTACT: TREND: CONDITION:	Generally unsatisfactory         with major localised problems         Unknown         Stephen Allott 0191 269 1235    Gleadscleugh, Akeld          Generally unsatisfactory         with major localised problems         Unknown         Stephen Allott 0191 269 1235    Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235          Generally unsatisfactory         with major localised problems         Stephen Allott 0191 269 1235		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: DESIGNATION	750m south east of High Akeld Cottages, A         Scheduled Monument (No. 1014932)         Plant growth         Private         Unenclosed stone hut circle settlement 120         Scheduled Monument (No. 1014929)         Plant growth         Private         Crigdon Hill round cairn, Alwinton         Scheduled Monument (No. 1008567)         Other         Government or Agency         Cross dyke and two building foundations at         Scheduled Monument (No. 1017736)	t slope of Harehor keld CONDITION: TREND: CONTACT: m north west of CONDITION: TREND: CONTACT: CONTACT: TREND: CONTACT:	ppe Hill,         Generally unsatisfactory         with major localised problems         Unknown         Stephen Allott 0191 269 1235         Gleadscleugh, Akeld         Generally unsatisfactory         with major localised problems         Unknown         Stephen Allott 0191 269 1235         Generally unsatisfactory         with major localised problems         Unknown         Stephen Allott 0191 269 1235         Generally unsatisfactory         with major localised problems         Stephen Allott 0191 269 1235		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DOWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DOWNER TYPE:	750m south east of High Akeld Cottages, A         Scheduled Monument (No. 1014932)         Plant growth         Private         Unenclosed stone hut circle settlement 120         Scheduled Monument (No. 1014929)         Plant growth         Private         Crigdon Hill round cairn, Alwinton         Scheduled Monument (No. 1008567)         Other         Government or Agency         Cross dyke and two building foundations at	t slope of Harehor keld CONDITION: TREND: CONTACT: m north west of CONDITION: TREND: CONTACT: CONTACT: TREND: CONTACT:	gee Hill,         Generally unsatisfactory         with major localised problems         Unknown         Stephen Allott 0191 269 1235         Gleadscleugh, Akeld         Generally unsatisfactory         with major localised problems         Unknown         Stephen Allott 0191 269 1235         Generally unsatisfactory         with major localised problems         Unknown         Stephen Allott 0191 269 1235		

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Three cross dykes on Middle Hill, Alwinton				
DESIGNATION:	Scheduled Monument (No. 1007525)	CONDITION:	Generally satisfactory		
			but with significant localised problems		
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining		
OWNER TYPE:	Government or Agency	CONTACT:	Stephen Allott 0191 269 1235		
SITE NAME:	Hadrian's Wall and associated features betw and the field boundary west of milecastle 3	,			
DESIGNATION:	Scheduled Monument (No. 1010964)	CONDITION:	Unknown		
PRINCIPAL VULNERABILITY:	No known threat	TREND:	Unknown		
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235		
SITE NAME:	Hadrian's Wall and associated features between the field boundary west of turret 37a and the road to Steel Rigg car park in wall miles 37, 38 and 39, Bardon Mill				
DESIGNATION:	Scheduled Monument (No. 1010966)	CONDITION:	Unknown		
PRINCIPAL VULNERABILITY:	No known threat	TREND:	Unknown		
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235		
SITE NAME:	Roman period native enclosed settlement 3	60m south east c	f Broadstruther, Earle		
DESIGNATION:	Scheduled Monument (No. 1016249)	CONDITION:	Generally unsatisfactory		
Besidi Wittork.		Condition.	with major localised problems		
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Unknown		
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235		
SITE NAME:	Roman period native settlement on south eastern slope of Hart Heugh, 490m north west of Carey Burn Bridge, Earle				
DESIGNATION:	Scheduled Monument (No. 1016237)	CONDITION:	Generally unsatisfactory		
			with major localised problems		
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Unknown		
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235		
SITE NAME:	Hadrian's Wall and vallum between the field and the west side of the B6318 road in wal				
DESIGNATION:	Scheduled Monument (No. 1010992)	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining		
DWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235		
SITE NAME:	Haltwhistle Burn Roman temporary camps	2 and 3 and area	of cord rig cultivation, Haltwhistle		
DESIGNATION:	Scheduled Monument (No. 1010946)	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY:	Moderate stock erosion	TREND:	Declining		
	Private	CONTACT:	Stephen Allott 0191 269 1235		
OWNER TYPE:					
OWNER TYPE:					
SITE NAME:	Barrow Burn unenclosed hut circle settlem				
SITE NAME:	<b>Barrow Burn unenclosed hut circle settlem</b> Scheduled Monument (No. 1017727)	ent, 300m north c	of Yearning Crag, Harbottle Generally unsatisfactory with major localised problems		
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:			Generally unsatisfactory		

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Round cairn 340m west of The Beacon, Ha	rbottle			
DESIGNATION:	Scheduled Monument (No. 1021032)	CONDITION:	Generally unsatisfactory		
			with major localised problems		
PRINCIPAL VULNERABILITY:	Digging	TREND:	Declining		
OWNER TYPE:	Government or Agency	CONTACT:	Stephen Allott 0191 269 1235		
SITE NAME:	Hadrian's Wall and vallum between the field east of turret 34a in wall miles 32, 33 and 3		wn Dikes and the field boundary		
DESIGNATION:	Scheduled Monument (No. 1010963)	CONDITION:	Unknown		
PRINCIPAL VULNERABILITY:	Localised/limited stock erosion	TREND:	Unknown		
OWNER TYPE:	Other	CONTACT:	Stephen Allott 0191 269 1235		
SITE NAME:	Seatsides I Roman temporary camp and section of the Stanegate Roman road from the west side of the road from Once Brewed to the south side of the B6318, Henshaw				
DESIGNATION:	Scheduled Monument (No. 1010940)	CONDITION:	Generally satisfactory		
	```		but with significant localised problems		
PRINCIPAL VULNERABILITY:	Moderate stock erosion	TREND:	Unknown		
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235		
SITE NAME:	18th century water mill at Grasslees, Hepp	le			
DESIGNATION:	Scheduled Monument (No. 1006404)	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining		
DWNER TYPE:	Government or Agency	CONTACT:	Stephen Allott 0191 269 1235		
	Soldions Fold univellate killfort 200m ocuth	unet of Suindan			
SITE NAME: DESIGNATION:	Soldiers Fold univallate hillfort, 300m south Scheduled Monument (No. 1008886)	west of Swindon,	Hepple Generally unsatisfactory		
DESIGNATION:	Scheduled Monument (No. 1008886)	CONDITION:	Hepple Generally unsatisfactory with major localised problems		
			Hepple Generally unsatisfactory		
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1008886) Plant growth	CONDITION: TREND: CONTACT:	Hepple Generally unsatisfactory with major localised problems Unknown		
DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE:	Scheduled Monument (No. 1008886) Plant growth Private	CONDITION: TREND: CONTACT:	Hepple Generally unsatisfactory with major localised problems Unknown		
DESIGNATION: PRINCIPAL VULNERABILITY: DWINER TYPE: SITE NAME:	Scheduled Monument (No. 1008886) Plant growth Private Bastle 150m south west of Morrelhirst, Hol	CONDITION: TREND: CONTACT:	Hepple Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235		
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1008886) Plant growth Private Bastle 150m south west of Morrelhirst, Hol Scheduled Monument (No. 1018994)	CONDITION: TREND: CONTACT: Ilinghill CONDITION:	Hepple Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 Generally satisfactory but with significant localised problems		
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1008886) Plant growth Private Bastle 150m south west of Morrelhirst, Hol Scheduled Monument (No. 1018994) Moderate natural erosion	CONDITION: TREND: CONTACT: CONDITION: CONDITION: TREND: CONTACT:	Hepple Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235		
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DWNER TYPE:	Scheduled Monument (No. 1008886) Plant growth Private Bastle 150m south west of Morrelhirst, Hol Scheduled Monument (No. 1018994) Moderate natural erosion Private	CONDITION: TREND: CONTACT: CONDITION: CONDITION: TREND: CONTACT:	Hepple Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235		
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DW	Scheduled Monument (No. 1008886) Plant growth Private Bastle 150m south west of Morrelhirst, Hold Scheduled Monument (No. 1018994) Moderate natural erosion Private Long cairn on the south western slope of D	CONDITION: TREND: CONTACT: Ilinghill CONDITION: TREND: CONTACT: CONTACT:	Hepple Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 h east of The Dod, Ilderton Generally satisfactory		
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DWNER TYPE: DESIGNATION: DESIGNATION: DESIGNATION:	Scheduled Monument (No. 1008886) Plant growth Private Bastle 150m south west of Morrelhirst, Hold Scheduled Monument (No. 1018994) Moderate natural erosion Private Long cairn on the south western slope of I Scheduled Monument (No. 1019417)	CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT: CONTACT:	Hepple Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 h east of The Dod, Ilderton Generally satisfactory but with significant localised problems		
DESIGNATION: PRINCIPAL VULNERABILITY: DITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DITE NAME: DISTE NAME: DIST	Scheduled Monument (No. 1008886) Plant growth Private Bastle 150m south west of Morrelhirst, Hold Scheduled Monument (No. 1018994) Moderate natural erosion Private Long cairn on the south western slope of I Scheduled Monument (No. 1019417) Plant growth Private	CONDITION: TREND: CONTACT: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION:	Hepple Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 h east of The Dod, Ilderton Generally satisfactory but with significant localised problems Unknown Stephen Allott 0191 269 1235		
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION:	Scheduled Monument (No. 1008886) Plant growth Private Bastle 150m south west of Morrelhirst, Hold Scheduled Monument (No. 1018994) Moderate natural erosion Private Long cairn on the south western slope of D Scheduled Monument (No. 1019417) Plant growth Private Romano-British farmstead on the eastern slope	CONDITION: TREND: CONTACT: CONDITION: TREND: CONDITION: CONDITION: TREND: CONDITION: CONDITION: CONDITION:	Hepple Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 H east of The Dod, Ilderton Generally satisfactory but with significant localised problems Unknown Stephen Allott 0191 269 1235 Km north of The Dod, Ilderton		
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DWNER TYPE	Scheduled Monument (No. 1008886) Plant growth Private Bastle 150m south west of Morrelhirst, Hold Scheduled Monument (No. 1018994) Moderate natural erosion Private Long cairn on the south western slope of I Scheduled Monument (No. 1019417) Plant growth Private	CONDITION: TREND: CONTACT: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION:	Hepple Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 h east of The Dod, Ilderton Generally satisfactory but with significant localised problems Unknown Stephen Allott 0191 269 1235		
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION:	Scheduled Monument (No. 1008886) Plant growth Private Bastle 150m south west of Morrelhirst, Hold Scheduled Monument (No. 1018994) Moderate natural erosion Private Long cairn on the south western slope of D Scheduled Monument (No. 1019417) Plant growth Private Romano-British farmstead on the eastern slope	CONDITION: TREND: CONTACT: CONDITION: TREND: CONDITION: CONDITION: TREND: CONDITION: CONDITION: CONDITION:	Hepple Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 Generally satisfactory but with significant localised problems Declining Stephen Allott 0191 269 1235 h east of The Dod, Ilderton Generally satisfactory but with significant localised problems Unknown Stephen Allott 0191 269 1235 km north of The Dod, Ilderton Generally satisfactory		

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Round cairn cemetery 1000m north west o	f Heddon Hill, Ilde	erton
DESIGNATION:	Scheduled Monument (No. 1019920)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Unknown
DWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Round cairn on the southern slope of Dod	Hill, 800m NNE d	of The Dod, Ilderton
DESIGNATION:	Scheduled Monument (No. 1019868)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Settlements south east of Heddon Hill, Ilde	rton	
DESIGNATION:	Scheduled Monument (No. 1006443)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Greaves Ash camp, Ingram		
DESIGNATION:	Scheduled Monument (No. 1006588)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
OWNER TYPE:	Private Ingram Farm: prehistoric to post-medieval s		·
OWNER TYPE:			·
OWNER TYPE:	Ingram Farm: prehistoric to post-medieval s	settlement, agricul	tural and funerary remains, Ingram Generally unsatisfactory
OWNER TYPE:	Ingram Farm: prehistoric to post-medieval s Scheduled Monument (No. 1021382)	settlement, agricul	tural and funerary remains, Ingram Generally unsatisfactory with major localised problems
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Ingram Farm: prehistoric to post-medieval s Scheduled Monument (No. 1021382) Plant growth	Settlement, agricul CONDITION: TREND: CONTACT: em, cairnfield and	tural and funerary remains, Ingram Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Ingram Farm: prehistoric to post-medieval s Scheduled Monument (No. 1021382) Plant growth Private Unenclosed hut circle settlement, field syste	Settlement, agricul CONDITION: TREND: CONTACT: em, cairnfield and	tural and funerary remains, Ingram Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235
DWNER TYPE:	Ingram Farm: prehistoric to post-medieval s Scheduled Monument (No. 1021382) Plant growth Private Unenclosed hut circle settlement, field syste immediately north west of Linhope Spout, I	Settlement, agricul CONDITION: TREND: CONTACT: em, cairnfield and ngram	tural and funerary remains, Ingram Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 cord rig cultivation Generally unsatisfactory
OWNER TYPE:	Ingram Farm: prehistoric to post-medieval s Scheduled Monument (No. 1021382) Plant growth Private Unenclosed hut circle settlement, field syste immediately north west of Linhope Spout, I Scheduled Monument (No. 1020247)	Settlement, agricul CONDITION: TREND: CONTACT: em, cairnfield and ngram CONDITION:	tural and funerary remains, Ingram Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 cord rig cultivation Generally unsatisfactory with major localised problems
OWNER TYPE:	Ingram Farm: prehistoric to post-medieval s Scheduled Monument (No. 1021382) Plant growth Private Unenclosed hut circle settlement, field syste immediately north west of Linhope Spout, I Scheduled Monument (No. 1020247) Plant growth	Settlement, agricul CONDITION: TREND: CONTACT: em, cairnfield and ngram CONDITION: TREND: CONTACT:	tural and funerary remains, Ingram Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 cord rig cultivation Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235
OWNER TYPE:	Ingram Farm: prehistoric to post-medieval s Scheduled Monument (No. 1021382) Plant growth Private Unenclosed hut circle settlement, field syste immediately north west of Linhope Spout, I Scheduled Monument (No. 1020247) Plant growth Private	Settlement, agricul CONDITION: TREND: CONTACT: em, cairnfield and ngram CONDITION: TREND: CONTACT:	tural and funerary remains, Ingram Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 cord rig cultivation Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235
	Ingram Farm: prehistoric to post-medieval s Scheduled Monument (No. 1021382) Plant growth Private Unenclosed hut circle settlement, field system Immediately north west of Linhope Spout, I Scheduled Monument (No. 1020247) Plant growth Private Elsdonburn Roman period native settlement	Settlement, agricul CONDITION: TREND: CONTACT: em, cairnfield and ngram CONDITION: TREND: CONTACT: ts and medieval sl	tural and funerary remains, Ingram Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 cord rig cultivation Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 nieling, Kilham Generally unsatisfactory
OWNER TYPE:	Ingram Farm: prehistoric to post-medieval s Scheduled Monument (No. 1021382) Plant growth Private Unenclosed hut circle settlement, field system immediately north west of Linhope Spout, I Scheduled Monument (No. 1020247) Plant growth Private Elsdonburn Roman period native settlement Scheduled Monument (No. 1014505)	Settlement, agricul CONDITION: TREND: CONTACT: em, cairnfield and ngram CONDITION: TREND: CONTACT: ts and medieval si	tural and funerary remains, Ingram Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 Cord rig cultivation Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 Thieling, Kilham Generally unsatisfactory with major localised problems
OWNER TYPE:	Ingram Farm: prehistoric to post-medieval s Scheduled Monument (No. 1021382) Plant growth Private Unenclosed hut circle settlement, field syste immediately north west of Linhope Spout, I Scheduled Monument (No. 1020247) Plant growth Private Elsdonburn Roman period native settlement Scheduled Monument (No. 1014505) Plant growth	Settlement, agricul CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONTACT: CONTACT: TREND: CONTACT: TREND: CONDITION: TREND: CONDITION:	tural and funerary remains, Ingram Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 Cord rig cultivation Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 hieling, Kilham Generally unsatisfactory with major localised problems Unknown
OWNER TYPE:	Ingram Farm: prehistoric to post-medieval s Scheduled Monument (No. 1021382) Plant growth Private Unenclosed hut circle settlement, field syste immediately north west of Linhope Spout, I Scheduled Monument (No. 1020247) Plant growth Private Elsdonburn Roman period native settlement Scheduled Monument (No. 1014505) Plant growth Private	Settlement, agricul CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONTACT: CONTACT: TREND: CONTACT: TREND: CONDITION: TREND: CONDITION:	tural and funerary remains, Ingram Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 cord rig cultivation Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 hieling, Kilham Generally unsatisfactory with major localised problems Unknown
OWNER TYPE:	Ingram Farm: prehistoric to post-medieval s Scheduled Monument (No. 1021382) Plant growth Private Unenclosed hut circle settlement, field system immediately north west of Linhope Spout, I Scheduled Monument (No. 1020247) Plant growth Private Elsdonburn Roman period native settlement Scheduled Monument (No. 1014505) Plant growth Private Northern ring cairn on Coldsmouth Hill, K	Settlement, agricul CONDITION: TREND: CONTACT: CONDITION: CONDITION: CONDITION: TREND: CONTACT: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: CONDITION:	tural and funerary remains, Ingram Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 Cord rig cultivation Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 hieling, Kilham Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 Generally satisfactory

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

ITE NAME:	Roman period native enclosed settlement 6	600m north east c	of Elsdonburn Shank, Kilham
DESIGNATION:	Scheduled Monument (No. 1015195)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Roman period native enclosed settlement 7	700m south of Rin	g Chesters defended settlement. Kilham
			-
DESIGNATION:	Scheduled Monument (No. 1014678)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Southern ring cairn on Coldsmouth Hill, Ki	lham	
DESIGNATION:	Scheduled Monument (No. 1009530)	CONDITION:	Generally satisfactory
		CONDITION.	but with minor localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Ell's Knowe defended settlement and earlie	r palisaded site, K	
DESIGNATION:	Scheduled Monument (No. 1009040)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Unknown
	Private	~~~~~	Stophon Allott 0101 2/0 1225
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
OWNER TYPE:	Private Enclosed native settlements, cultivation terr		
OWNER TYPE:			
OWNER TYPE: SITE NAME: DESIGNATION:	Enclosed native settlements, cultivation terr	races and cairn fie	Id south west of Mounthooly, Kirknewton Generally unsatisfactory
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Enclosed native settlements, cultivation terr Scheduled Monument (No. 1015647)	races and cairn fie	Id south west of Mounthooly, Kirknewton Generally unsatisfactory with major localised problems
	Enclosed native settlements, cultivation terr Scheduled Monument (No. 1015647) Plant growth	races and cairn fie condition: trend:	Id south west of Mounthooly, Kirknewton Generally unsatisfactory with major localised problems Unknown
OWNER TYPE:	Enclosed native settlements, cultivation terr Scheduled Monument (No. 1015647) Plant growth Private Hethpool tower house, Kirknewton	races and cairn fie condition: trend:	Id south west of Mounthooly, Kirknewton Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235
OWNER TYPE:	Enclosed native settlements, cultivation terr Scheduled Monument (No. 1015647) Plant growth Private	races and cairn fie Condition: TREND: CONTACT:	Id south west of Mounthooly, Kirknewton Generally unsatisfactory with major localised problems Unknown
OWNER TYPE:	Enclosed native settlements, cultivation terr Scheduled Monument (No. 1015647) Plant growth Private Hethpool tower house, Kirknewton	races and cairn fie Condition: TREND: CONTACT:	Id south west of Mounthooly, Kirknewton Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems Declining
OWNER TYPE:	Enclosed native settlements, cultivation terr Scheduled Monument (No. 1015647) Plant growth Private Hethpool tower house, Kirknewton Scheduled Monument (No. 1018439)	CONDITION: CONTACT: CONDITION:	Id south west of Mounthooly, Kirknewton Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Enclosed native settlements, cultivation term Scheduled Monument (No. 1015647) Plant growth Private Hethpool tower house, Kirknewton Scheduled Monument (No. 1018439) Collapse	races and cairn fie CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT:	Id south west of Mounthooly, Kirknewton Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235
OWNER TYPE:	Enclosed native settlements, cultivation term Scheduled Monument (No. 1015647) Plant growth Private Hethpool tower house, Kirknewton Scheduled Monument (No. 1018439) Collapse Private	races and cairn fie CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT:	Id south west of Mounthooly, Kirknewton Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235
OWNER TYPE:	Enclosed native settlements, cultivation terr Scheduled Monument (No. 1015647) Plant growth Private Hethpool tower house, Kirknewton Scheduled Monument (No. 1018439) Collapse Private Roman period native enclosed settlement 2	races and cairn fie CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT: 270m ESE of Fleeh	Id south west of Mounthooly, Kirknewton Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 Ope, Kirknewton Generally satisfactory
OWNER TYPE:	Enclosed native settlements, cultivation term Scheduled Monument (No. 1015647) Plant growth Private Hethpool tower house, Kirknewton Scheduled Monument (No. 1018439) Collapse Private Roman period native enclosed settlement 2 Scheduled Monument (No. 1014501)	races and cairn fie CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT: 270m ESE of Fleeh	Id south west of Mounthooly, Kirknewton Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 Ope, Kirknewton Generally satisfactory but with significant localised problems
OWNER TYPE:	Enclosed native settlements, cultivation term Scheduled Monument (No. 1015647) Plant growth Private Hethpool tower house, Kirknewton Scheduled Monument (No. 1018439) Collapse Private Roman period native enclosed settlement 2 Scheduled Monument (No. 1014501) Dumping	races and cairn fie CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT: 270m ESE of Fleeh	Id south west of Mounthooly, Kirknewton Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 Ope, Kirknewton Generally satisfactory but with significant localised problems Unknown
OWNER TYPE:	Enclosed native settlements, cultivation term Scheduled Monument (No. 1015647) Plant growth Private Hethpool tower house, Kirknewton Scheduled Monument (No. 1018439) Collapse Private Roman period native enclosed settlement 2 Scheduled Monument (No. 1014501) Dumping	races and cairn fie CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT: CONDITION: TREND: CONDITION: TREND: CONDITION:	Id south west of Mounthooly, Kirknewton Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 Ope, Kirknewton Generally satisfactory but with significant localised problems Unknown Stephen Allott 0191 269 1235
OWNER TYPE:	Enclosed native settlements, cultivation term Scheduled Monument (No. 1015647) Plant growth Private Hethpool tower house, Kirknewton Scheduled Monument (No. 1018439) Collapse Private Roman period native enclosed settlement 2 Scheduled Monument (No. 1014501) Dumping Private	races and cairn fie CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT: CONDITION: TREND: CONDITION: TREND: CONDITION:	Id south west of Mounthooly, Kirknewton Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 Ope, Kirknewton Generally satisfactory but with significant localised problems Unknown Stephen Allott 0191 269 1235
OWNER TYPE:	Enclosed native settlements, cultivation terr Scheduled Monument (No. 1015647) Plant growth Private Hethpool tower house, Kirknewton Scheduled Monument (No. 1018439) Collapse Private Roman period native enclosed settlement 2 Scheduled Monument (No. 1014501) Dumping Private Roman period native enclosed settlement a	races and cairn fie CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT: 270m ESE of Fleeh CONDITION: TREND: CONDITION: TREND: CONTACT: CONTACT:	Id south west of Mounthooly, Kirknewton Generally unsatisfactory with major localised problems Unknown Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 Ope, Kirknewton Generally satisfactory but with significant localised problems Unknown Stephen Allott 0191 269 1235

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Romano-British farmstead 760m north of Whitehall, Kirknewton				
DESIGNATION:	Scheduled Monument (No. 1019925)	CONDITION:	Generally unsatisfactory		
			with major localised problems		
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Unknown		
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235		
SITE NAME:	Romano-British settlement 810m south eas	t of Whitehall, Ki	rknewton		
DESIGNATION:	Scheduled Monument (No. 1019927)	CONDITION:	Generally unsatisfactory		
	``````````````````````````````````````		with major localised problems		
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Unknown		
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235		
SITE NAME:	Settlement north of White Law, Kirknewto	n			
DESIGNATION:	Scheduled Monument (No. 1006456)	CONDITION:	Generally satisfactory		
			but with significant localised problems		
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Unknown		
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235		
SITE NAME:	Settlement north west of Ell's Knowe, Kirkı	newton			
DESIGNATION:	Scheduled Monument (No. 1008478)	CONDITION:	Generally satisfactory		
DESIGNATION:		CONDITION:	but with significant localised problems		
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Unknown		
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235		
	Settlement on north east slope of Yeavering	Bell Kirknewtor			
SITE NAME:	Settlement on north east slope of Yeavering	g Bell, Kirknewtor			
	Settlement on north east slope of Yeavering Scheduled Monument (No. 1006459)	g Bell, Kirknewtor	Generally satisfactory		
DESIGNATION:	Scheduled Monument (No. 1006459)	CONDITION:	Generally satisfactory but with significant localised problems		
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1006459) Plant growth	CONDITION: TREND:	Generally satisfactory but with significant localised problems Unknown		
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1006459)	CONDITION:	Generally satisfactory but with significant localised problems		
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1006459) Plant growth	CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Unknown		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1006459) Plant growth Private	CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Unknown Stephen Allott 0191 269 1235 Generally satisfactory		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1006459) Plant growth Private Settlement on north slope of Yeavering Bell Scheduled Monument (No. 1006466)	CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Unknown Stephen Allott 0191 269 1235 Generally satisfactory but with significant localised problems		
DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1006459) Plant growth Private Settlement on north slope of Yeavering Bell Scheduled Monument (No. 1006466) Plant growth	CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Unknown Stephen Allott 0191 269 1235 Generally satisfactory but with significant localised problems Unknown		
designation: Principal Vulnerability: Owner Type:	Scheduled Monument (No. 1006459) Plant growth Private Settlement on north slope of Yeavering Bell Scheduled Monument (No. 1006466)	CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Unknown Stephen Allott 0191 269 1235 Generally satisfactory but with significant localised problems		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1006459) Plant growth Private Settlement on north slope of Yeavering Bell Scheduled Monument (No. 1006466) Plant growth	CONDITION: TREND: CONTACT: Kirkrewton CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Unknown Stephen Allott 0191 269 1235 Generally satisfactory but with significant localised problems Unknown		
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DW	Scheduled Monument (No. 1006459) Plant growth Private Settlement on north slope of Yeavering Bell Scheduled Monument (No. 1006466) Plant growth Private	CONDITION: TREND: CONTACT: Kirkrewton CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Unknown Stephen Allott 0191 269 1235 Generally satisfactory but with significant localised problems Unknown		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: DESIGNATION:	Scheduled Monument (No. 1006459)         Plant growth         Private         Settlement on north slope of Yeavering Bell         Scheduled Monument (No. 1006466)         Plant growth         Private         Settlement on the east slope of The Bell, K         Scheduled Monument (No. 1006465)	CONDITION: TREND: CONTACT: , Kirknewton CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Unknown Stephen Allott 0191 269 1235 Generally satisfactory but with significant localised problems Unknown Stephen Allott 0191 269 1235 Generally satisfactory		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1006459) Plant growth Private Settlement on north slope of Yeavering Bell Scheduled Monument (No. 1006466) Plant growth Private Settlement on the east slope of The Bell, K	CONDITION: TREND: CONTACT: CONDITION: CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Unknown Stephen Allott 0191 269 1235 Generally satisfactory but with significant localised problems Unknown Stephen Allott 0191 269 1235 Generally satisfactory but with significant localised problems		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1006459)         Plant growth         Private         Settlement on north slope of Yeavering Bell         Scheduled Monument (No. 1006466)         Plant growth         Private         Settlement on the east slope of The Bell, K         Scheduled Monument (No. 1006465)         Plant growth	CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONDITION: CONDITION: CONDITION:	Generally satisfactory but with significant localised problems Unknown Stephen Allott 0191 269 1235 Generally satisfactory but with significant localised problems Unknown Stephen Allott 0191 269 1235 Generally satisfactory but with significant localised problems Unknown		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: OWNER TYPE:	Scheduled Monument (No. 1006459)         Plant growth         Private         Settlement on north slope of Yeavering Bell         Scheduled Monument (No. 1006466)         Plant growth         Private         Settlement on the east slope of The Bell, K         Scheduled Monument (No. 1006465)         Plant growth         Private         Settlement on the east slope of The Bell, K         Scheduled Monument (No. 1006465)         Plant growth         Private         Roman camp and prehistoric round cairn 7	CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONDITION: CONDITION: TREND: CONDITION:	Generally satisfactory but with significant localised problems Unknown Stephen Allott 0191 269 1235 Generally satisfactory but with significant localised problems Unknown Stephen Allott 0191 269 1235 Generally satisfactory but with significant localised problems Unknown Stephen Allott 0191 269 1235		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNERTYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNERTYPE: SITE NAME: DESIGNATION: SITE NAME: SITE NAME: SITE NAME: SITE NAME:	Scheduled Monument (No. 1006459)         Plant growth         Private         Settlement on north slope of Yeavering Bell         Scheduled Monument (No. 1006466)         Plant growth         Private         Settlement on the east slope of The Bell, K         Scheduled Monument (No. 1006465)         Plant growth         Private	CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONDITION: CONDITION: TREND: CONDITION:	Generally satisfactory but with significant localised problems Unknown Stephen Allott 0191 269 1235 Generally satisfactory but with significant localised problems Unknown Stephen Allott 0191 269 1235 Generally satisfactory but with significant localised problems Unknown Stephen Allott 0191 269 1235 Generally satisfactory but with significant localised problems Unknown Stephen Allott 0191 269 1235		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1006459)         Plant growth         Private         Settlement on north slope of Yeavering Bell         Scheduled Monument (No. 1006466)         Plant growth         Private         Settlement on the east slope of The Bell, K         Scheduled Monument (No. 1006465)         Plant growth         Private         Settlement on the east slope of The Bell, K         Scheduled Monument (No. 1006465)         Plant growth         Private         Roman camp and prehistoric round cairn 7	CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONTACT: TREND: CONDITION: TREND: CONTACT: 000m north east o	Generally satisfactory but with significant localised problems Unknown Stephen Allott 0191 269 1235 Generally satisfactory but with significant localised problems Unknown Stephen Allott 0191 269 1235 Generally satisfactory but with significant localised problems Unknown Stephen Allott 0191 269 1235		

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Round cairn 230m west of Ridlees Cairn, R	ochester	
DESIGNATION:	Scheduled Monument (No. 1021030)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Digging	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Round cairn, 800m east of Mally's Crag, Roo	chester	
DESIGNATION:	Scheduled Monument (No. 1014077)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Reaveley Hill cairn cemetery, Roddam		
DESIGNATION:	Scheduled Monument (No. 1006469)	CONDITION:	Generally satisfactory
	. , , ,		but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Reaveley Hill settlement, Roddam		
DESIGNATION:	Scheduled Monument (No. 1006468)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Settlement on south east slope of Ewe Hill,	, Roddam	
DESIGNATION:	Scheduled Monument (No. 1002916)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Fishponds, 450m north east of Sewingshield	ls, Simonburn	
DESIGNATION:	Scheduled Monument (No. 1011081)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Moderate stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Tarset fortified house, 180m east of Tarset	Hall, Tarset	
DESIGNATION:	Scheduled Monument (No. 1015528)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Extensive natural erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Romano-British farmstead, 175m south of C	Cockpit Well, Tosso	on
DESIGNATION:	Scheduled Monument (No. 1009582)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
OVVINER I YPE:	IIIvate	CONTACT:	Stephen Anoli 0171 207 1255

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.


# ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

### HERITAGE AT RISK 2011 / NORTH EAST / NORTHUMBERLAND (NP) / DARLINGTON (UA)


SITE NAME:	Walwick Fell Roman temporary camp, Warder	n	
DESIGNATION:	Scheduled Monument (No. 1010935)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Blacka Burn shieling, Wark		
SITE NAME: DESIGNATION:	<b>Blacka Burn shieling, Wark</b> Scheduled Monument (No. 1010038)	CONDITION:	Generally satisfactory but with significant localised problems
	5	CONDITION: TREND:	, , ,
DESIGNATION:	Scheduled Monument (No. 1010038)		but with significant localised problems

# TEES VALLEY DARLINGTON (UA)

	SITE NAME:	Middridge Grange Farmhouse, Shildon Road, Heighington	Farmhouse c1600 with C17, C18 and C19 alterations and extensions. English Heritage offered a significant grant towards a first phase of repairs to the roof and general structural work to make the building stable and
HARTHAL	DESIGNATION:	Listed Building Grade II*	weathertight. These works were successfully completed in
	CONDITION:	Good	2006. A further grant was offered towards internal repairs,
	OCCUPANCY:	Vacant	which will lead to the building being secured in 2011.
	PRIORITY:	F (F)	
	OWNER TYPE:	Private	Contact: Kate Wilson 0191 269 1221
	SITE NAME:	Dovecote 45m east of Manor House, Houghton Bank Lane, Houghton le Side	Dovecote, probably medieval. Disused and requires roof repairs, repointing and removal of vegetation from walls.



	SITE NAME:	Church of All Saints, Sockburn Lane, Sockburn	An important site containing the remains of the church (C13-C15) and a major collection of pre-Conquest stone effigies housed in the nearby Conyers Chapel. The church was abandoned in 1838
	DESIGNATION:	Listed Building Grade I, SM	and allowed to fall into ruin. Urgent repair works were
社工业工-以下外	CONDITION:	Fair	completed in 2006 with English Heritage grant aid. A second phase of consolidation works was undertaken
A PLANE AND ANALY	OCCUPANCY:	Vacant	A second phase of consolidation works was undertaken in 2010, again grant-aided by English Heritage.
N. Contraction of the second	PRIORITY:	E (D)	in 2010, again grant-aided by English Heritage.
	OWNER TYPE:	Religious organisation	Contact: Rob Young 0191 269 1239





PRIORITY:	C (D)	development work is now in progress.
OWNER TYPE:	Private	Contact: Kate Wilson 0191 269 1221
SITE NAME:	Church of Holy Trinity, Woodland Road, Darlington	Built in 1836-38 by Anthony Salvin, with a chancel and vestry by J Ross added in 1867. The church has historical importance as an early example of the Early English Gothic Revival and its building reflects Darlington's rapid growth at that time. Defective parapet gutters have led to an
DESIGNATION:	Listed Place of Worship Grade II*, CA	outbreak of dry-rot and repairs are required urgently.
CONDITION:	Very bad	Roof coverings also need attention.
PRIORITY:	C (New entry)	
OWNER TYPE:	Religious organisation	Contact: Kate Wilson 0191 269 1221

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. В
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

Site NAME       Church of St Hilds, Park Gate, Darlington       Built (1887-88) in red brains in the Early English eminent. C19 Aburch archites [], Parkonan The and interior fittings were removed soon after: 1986. The Goreen removed soon after the removed soon after 1986. The Goreen removed soon after the removed soon after 1986. The Goreen removed soon after the removed soon after 1986. The Goreen removed soon	arson. The stained glas oon after redundancy fire before being y the Life and Light the end of their life	9 ćhurch architect JL Pearson		,	SITE NAME:	
Descurrence worder         Existed Place of Worship Grade II construct worder         Mission. Roof coverings are reaching the end of and low level brickwork is in need of repair.           worder         C (New entry) worder. The Religious organisation         Contact: Kate Wilson 0191 269 1221           worder         C (New entry) worder. The Religious organisation         Contact: Kate Wilson 0191 269 1221           worder         Part MARE         Church of St Andrew, Haughton Teren, Haughton Ic Skerne         An ancient church dating to around 1100 and on the site of an earlier Saxon church. The buil restored in the CI 5 and extraded in 1795. The mostor Poor moerne         An ancient church dating to around 1100 and on the site of an earlier Saxon church. The buil restored in the CI 5 and extraded in 1795. The mostorne Poor moerne         An ancient church of 1871 by JP Pritchett. Contact: Kate Wilson 0191 269 1221           worder         B (New entry) worder. B (New entry)         Contact: Kate Wilson 0191 269 1221           worder         B (New entry) worder. B (Medleton One Row, Middleton St George         A small parish church of 1871 by JP Pritchett. Contaris a stained glass window of 1957 by LG Structural defects in the nave and vestry were repairs have not been carried out. Recently, the has been found to be colling for worships of the structural defects in the nave and vestry were repairs have not been carried out. Recently, the has been found to be colling for worships of and the church is now closed.           structural defects in the nave and the church is now closed.         Contact: Catherine Dewar 0191 2691232           structure <td< td=""><td>, the end of their life</td><td>church then suffered a fire b</td><td>and interior in 1986.The</td><td></td><td></td><td></td></td<>	, the end of their life	church then suffered a fire b	and interior in 1986.The			
Priority:       C (New entry)         OWNERTIME:       Religious organisation       Contact: Kate Wilson 0191 269 1221         Image: Contact:       Strenwer:       Haughton Green, Haughton Green, Haughton Is Skerne       An ancient church dating to around 1100 and on the site of an earlier. Saxon church. The built of an assonry regains are required. Heritag to dresson regains are required. Heritag for an assonry regains are required. Heritag for an assonry regains are required. Heritag for an assonry regains are required. Heritag for a massonry regains are required. Heritag for the control is the Contact Kate Wilson 0191 269 1221         Immediate       Stret. Meritage for the contage for the mouter of the contage for the contage for the contage fo	of repair.	of coverings are reaching the	Mission. Roo	Listed Place of Worship Grade II	DESIGNATION:	-0.0. 0.1.0.0.0.0.0.0.0.0.0.0.0.0.0.0.0.0
ownext three     Religious organisation     Contact: Kate Wilson 0191 269 1221       Image: Streme     Streme     Haughton Green, Haughton Is Skerne     An ancient church dating to around 1100 and on the site of an earlier Saxon church. The buil restored in the C15 and extended in 1795. The full gate to 1620 and strended in 299. The full gate to 1620 and strended		el brickwork is in need of rep	and low leve		CONDITION:	
STE NAME:     Church of St Andrew, Haughton Ie Skerne     An ancient durch dating to around 1100 and the site of an earlier Saxon durch. The bui restored in the Ste of an earlier Saxon durch. The bui restored in the Ste of an earlier Saxon durch. The bui restored in the Ste of an earlier Saxon durch. The bui restored in the Ste of an earlier Saxon durch. The bui restored in the Ste of an earlier Saxon durch. The bui restored in the Ste of an earlier Saxon durch. The bui restored in the Ste of an earlier Saxon durch. The bui restored in the Ste of an earlier Saxon durch. The bui restored in the Ste of an earlier Saxon durch. The bui restored in the Ste of an earlier Saxon durch. The bui restored in the Ste of an earlier Saxon durch. The bui restored in the Ste of an earlier Saxon durch. The built fund grant of 2146,000 was offered in Decem to an masonry repairs are required. Heritag Fund grant of 2146,000 was offered in Decem to and masonry repairs are required. Heritag Fund grant of 2146,000 was offered in Decem to and masonry repairs are required. Heritag Fund grant of 2146,000 was offered in Decem to and masonry repairs are required. Heritag Fund grant of 2146,000 was offered in Decem to and masonry repairs are required. Heritag Fund grant of 2146,000 was offered in Decem to and the church of 1871 by JP Pritchett. Contaris a statined glass window of 1957 by LC Contaris a statined building for worship se repairs have not been carried out. Recently the and the church is now closed.       stre NAME:     Small multi-valate hillfort and tower mill on Shacker Prince Prince growth     Contaric Stephen Allott 0191 269 12				. ,,	PRIORITY:	The second
Provide the set of the s	I	e Wilson 0191 269 1221	Contact: Kat	Religious organisation	OWNER TYPE:	A good service of the
Descontrione:       Poor       Fund grant of £146,000 was offered in Decem towards repair programme.         Winderstring:       B (New entry)       Contact: Kate Wilson 0191 269 1221         Winderstring:       Church of St Lawrence, Church of St Lawrence, Middleton St George       A small parish church of 1871 by JP Pritchett.         Contact:       Site NAME       Church lane, Middleton One Row, Middleton St George       A small parish church of 1871 by JP Pritchett.         Contact:       Site NAME       Listed Place of Worship Grade II, CA       Contact: Kate Wilson 0191 269 1221         Winderton:       Listed Place of Worship Grade II, CA       Contact: Kate Wilson 0191 269 1232       Structural defects in the nave and vestry were repaired using grant aid but the PCC has also exploring using another building for worship so exploring using another building for worship	ch. The building was n 1795. The interior an in style. High level	of an earlier Saxon church.Th the C15 and extended in 179 to 1662 and are Jacobean in	on the site restored in fittings date	Haughton Green,	SITE NAME:	
Implementation       B (New entry)       Contact: Kate Wilson 0191 269 1221         Implementation       Site NAME       Church of St Lawrence, Church Lane, Middleton One Row, Middleton St George       A small parish church of 1871 by JP Pritchett. Contains a stained glass window of 1957 by LC Structural defects in the nave and vestry were repaired duils grant all but the PCC has also composing using another building for worship so repairs have not been carried out. Recently the Rece	in December 2010	of £146,000 was offered in D	Fund grant (	Listed Place of Worship Grade I, CA	DESIGNATION:	
OWNERTIME       Religious organisation       Contact: Kate Wilson 0191 269 1221         Image: Stream of the		air programme.	towards rep		CONDITION:	
STE NAME       Church of St Lawrence, Church Lane, Middleton One Row, Middleton St George       A small parish church of 1871 by JP Pritchett. Church Lane, Middleton One Row, Middleton St George         DESIGNATION:       Listed Place of Worship Grade II, CA Robit Very bad Robit Very bad Robit Very bad Robit Very bad       A small parish church of 1871 by JP Pritchett. Controm Very bad Robit Very bad Robit Very bad         Stre NAME       Small multivallate Place of Worship Grade II, CA Robit Very bad       Contact: Catherine Dewar 0191 2691232         Stre NAME       Small multivallate hillfort and tower mill on Shack/eton Beacon Hill, Heighington       Contact: Catherine Dewar 0191 2691232         Stre NAME       Scheduled Monument (No. 1016867)       Contact: Catherine Dewar 0191 2691235         Stre NAME       Scheduled Monument (No. 1016867)       Contact: Stephen Allott 0191 269 1235         Stre NAME       Medieval moated manorial site of Low Dinsdale at the Manor House, Low Dinsdale         Stre NAME       Scheduled Monument (No. 1007715)       ConDITION:         Stre NAME       Scheduled Monument (No. 1007715)       ConDITION:         Stre NAME       Scheduled Monument (No. 1007715)       ConDITION:         Stre NAME       Northgate       Scheduled Monument (No. 1007715)       ConDITION:         Stre NAME       Northgate       Scheduled Monument (No. 1007715)       ConDITION:       Stre NAME         Stre NAME       Northgate <td></td> <td></td> <td></td> <td></td> <td>PRIORITY:</td> <td></td>					PRIORITY:	
Functional problem in the problem i	1	e Wilson 0191 269 1221	Contact: Kat	Religious organisation	OWNER TYPE:	
DESIGNATION:       Listed Place of Worship Grade II, CA CONDITION:       repairs have not been carried out. Recently, the has been found to be collapsing beneath the conditions:         VEY bad       and the church is now closed.         PRIORITY:       C (New entry)         OWNERTYPE       Religious organisation         Stre NAME:       Small multivallate hillfort and tower mill on Shacktory but with significant localised proteins but with significant localised proteins         PRINCIPAL VULNERABILITY:       Scheduled Monument (No. 1016867)       CONDITION:       Generally satisfactory but with significant localised proteins         OWNERTYPE       Other       conditions       Conditions       Stephen Allott 0191 269 1235         Stre NAME:       Medieval moted manorial site of Low Dinsdale at the Manor House, Low Dinsdale       Descining         Stre NAME:       Other       conditions       Generally satisfactory but with significant localised prote but with sign	1957 by LC Evetts. estry were to be C has also been	stained glass window of 1957 efects in the nave and vestry ng grant aid but the PCC has	Contains a s Structural d repaired usi	Church Lane, Middleton One Row,	SITE NAME:	,
PRIORITY:       C (New entry)       and the church is now closed.         OWNERTYPE       Religious organisation       Contact: Catherine Dewar 0191 2691232         SITE NAME:       Small multivallate hillfort and tower mill on Shackton Beacon Hill, Heighington         DESIGNATION:       Scheduled Monument (No. 1016867)       Condition:         Generally satisfactory but with significant localised prote       but with significant localised prote         PRINCIPAL VULNERABILITY:       Scrub / tree growth       TREND:       Declining         OWNERTYPE:       Other       Contact:       Stephen Allott 0191 269 1235         STE NAME:       Medieval moated manorial site of Low Dinsdale at the Manor House, Low Dinsdale         DESIGNATION:       Cother       Contact:       Stephen Allott 0191 269 1235         VILUNERABILITY:       Other       TREND:       Unknown         OWNERTYPE:       Other       TREND:       Unknown         Stre NAME:       Northgate       VULNERABILITY:       Stephen Allott 0191 269 1235         Stre NAME:       Northgate       VILNERABILITY:       VILNERABILITY:	Recently, the ceiling	not been carried out. Recen	repairs have	Listed Place of Worship Grade II, CA	DESIGNATION:	
PRIORITY:       C (New entry)         OWNER TYPE:       Religious organisation       Contact: Catherine Dewar 0191 2691232         SITE NAME:       Small multivallate hillfort and tower mill on Shack/eton Beacon       Hill, Heighington         DESIGNATION:       Scheduled Monument (No. 1016867)       CONDITION:       Generally satisfactory but with significant localised prote but with significant localised prote         PRINCIPAL VULNERABILITY:       Scrub / tree growth       TREND:       Declining         OWNER TYPE:       Other       CONDITION:       Generally satisfactory but with significant localised prote         SITE NAME:       Medieval moated manorial site of Low Dinsdale       THEND:       Generally satisfactory but with significant localised prote         PRINCIPAL VULNERABILITY:       Other       CONDITION:       Generally satisfactory but with significant localised prote         PRINCIPAL VULNERABILITY:       Other       TREND:       Unknown         OWNER TYPE:       Private       CONTACT:       Stephen Allott 0191 269 1235         STE NAME:       Morthgate       CONTACT:       Stephen Allott 0191 269 1235         PRINCIPAL VULNERABILITY:       Other       TREND:       Unknown         OWNER TYPE:       Private       CONTACT:       Stephen Allott 0191 269 1235         STE NAME:       Northgate       CONDITION:<	eath the overboarding			Very bad	CONDITION:	
STIE NAME:       Small multivallate hillfort and tower mill on Shackleton Beacon Hill, Heighington         DESIGNATION:       Scheduled Monument (No. 1016867)       CONDITION:       Generally satisfactory but with significant localised proteout with significant		rch is now closed.	and the chu	C (New entry)	PRIORITY:	
Design Antion:Scheduled Monument (No. 1016867)CONDITION:Generally satisfactory but with significant localised prote but with significant localised protePRINCIPAL VULNERABILITY:Scrub / tree growthTREND:DecliningOwner TYPE:OtherCONTACT:Stephen Allott 01912691235SITE NAME:Medieval moated manorial site of Low Dinsdale at the ManorGenerally satisfactory but with significant localised proteDesign Anton:Scheduled Monument (No. 1007715)CONDITION:Generally satisfactory but with significant localised protePRINCIPAL VULNERABILITY:OtherTREND:UnknownOwner TYPE:OtherCONDITION:Stephen Allott 01912691235PRINCIPAL VULNERABILITY:OtherTREND:UnknownSTE NAME:NorthgateSconservation AreaCONDITION:Very badVULNERABILITY:MediumTREND:Very bad	91232	therine Dewar 0191 2691232	Contact: Ca	Religious organisation	OWNER TYPE:	49
PRINCIPAL VULNERABILITY:Scrub / tree growthTREND:DecliningOWNER TYPE:Othercontact:Stephen Allott 0191 269 1235SITE NAME:Medieval moated manorial site of Low Dinsdalethe Manor House, Low DinsdaleDesignation:Scheduled Monument (No. 1007715)contact:Generally satisfactory but with significant localised protPRINCIPAL VULNERABILITY:OtherTREND:UnknownOWNER TYPE:Othercontact:Stephen Allott 0191 269 1235PRINCIPAL VULNERABILITY:OtherTREND:UnknownSTE NAME:Northgatecontact:Stephen Allott 0191 269 1235SITE NAME:Northgatecontact:Stephen Allott 0191 269 1235SITE NAME:Mediumcontact:Stephen Allott 0191 269 1235		n Hill, Heighington	kleton Beaco	ivallate hillfort and tower mill on Shac	Small mult	SITE NAME:
OWNERTYPE:       Other       CONTACT:       Stephen Allott 0191 269 1235         SITE NAME:       Medieval moated manorial site of Low Dinsdale at the Manor House, Low Dinsdale         DESIGNATION:       Scheduled Monument (No. 1007715)       CONDITION:       Generally satisfactory but with significant localised prob         PRINCIPAL VULNERABILITY:       Other       TREND:       Unknown         OWNERTYPE:       Private       CONTACT:       Stephen Allott 0191 269 1235         SITE NAME:       Northgate       TREND:       Unknown         SITE NAME:       Northgate       CONSTRATION:       Very bad         UNINERABILITY:       Medium       TREND:       Very bad	alised problems	, , ,	CONDITION:	Monument (No. 1016867)	Scheduled	DESIGNATION:
SITE NAME:       Medieval moated manorial site of Low Dinsdale at the Manor House, Low Dinsdale         DESIGNATION:       Scheduled Monument (No. 1007715)       CONDITION:       Generally satisfactory but with significant localised proteout with significant lo			TREND:	e growth	Scrub / tre	PRINCIPAL VULNERABILITY:
DESIGNATION:       Scheduled Monument (No. 1007715)       CONDITION:       Generally satisfactory but with significant localised proter but with significant localised protei but with significant localis	69 1235	Stephen Allott 0191 269 12	CONTACT:		Other	OWNER TYPE:
PRINCIPAL VULNERABILITY:       Other       TREND:       Unknown         OWNER TYPE:       Private       CONTACT:       Stephen Allott 0191 269 1235         SITE NAME:       Northgate       CONServation Area       CONDITION:       Very bad         VULNERABILITY:       Medium       TREND:       No significant localised proteins		House, Low Dinsdale	at the Manor	noated manorial site of Low Dinsdale	Medieval r	site name:
PRINCIPAL VULNERABILITY:     Other     TREND:     Unknown       OWNER TYPE:     Private     CONTACT:     Stephen Allott 0191 269 1235       SITE NAME:     Northgate     VULNERABILITY:     Conservation Area       VULNERABILITY:     Medium     TREND:     Very bad       No significant change     VERD:     No significant change	alised problems		CONDITION:	Monument (No. 1007715)	Scheduled	DESIGNATION:
OWNER TYPE:     Private     CONTACT:     Stephen Allott 0191 269 1235       SITE NAME:     Northgate	F	-	TREND:		Other	PRINCIPAL VULNERABILITY:
DESIGNATION:     Conservation Area     condition:     Very bad       vulnerability:     Medium     Trend:     No significant change	69 1235	Stephen Allott 0191 269 12	CONTACT:		Private	
DESIGNATION:     Conservation Area     condition:     Very bad       vulnerability:     Medium     TREND:     No significant change					Northgate	SITE NAME:
VULNERABILITY: Medium TREND: No significant change		Very bad			-	
				irimshaw (LPA) 01325 388604		
site NAME: Victoria Embankment				mbankment	Victoria Ei	SITE NAME:
DESIGNATION: Conservation Area CONDITION: Very bad		Very bad		ion Area	Conservat	DESIGNATION
VULNERABILITY:     Medium     TREND:     No significant change		,				
CONTACT: Heather Grimshaw (LPA) 01325 388604 NEW ENTRY: NO				irimshaw (LPA) 01325 388604		
site NAME: West End (formerly Stanhope / Grange Road)				(formerly Stanhope / Grange Road)	West End	SITE NAME:
DESIGNATION: Conservation Area CONDITION: Fair		<b>F</b> '	CONDITION:	ion Area	Conservat	DESIGNATION:
		Fair				
VULNERABILITY: IMEDIUM TREND: Deteriorating		Fair Deteriorating	TREND:		Medium	VULNERABILITY:

### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS

HERITAGE AT RISK 2011 / NORTH EAST / HARTLEPOOL (UA) / MIDDLESBROUGH (UA) / REDCAR AND CLEVELAND (UA)

HARTLEPOOL (UA)						
	SITE NAME:	High Street, Hartlepool Headland		Built around 1200 on the site of a C7 monastery, incorporating the remains of an early C12 church. Many Saxon and medieval architectural fragments throughout the church, which has undergone several re-designs and was fully restored between 1925-32.		
	DESIGNATION:	Listed Place of Worship Grade I, CA		is on an exposed site near the sea and		
TRACK-	CONDITION:	Poor	the parapets (and other masonry) are open-jointed. In addition to having a spalling roof, the tower has structural issues that are currently under investigation.			
	PRIORITY:	C (New entry)				
	OWNER TYPE:	D III		te Wilson 0191 269 1221		
SITE NAME:	Medieval f	armstead and irregular open field syst	em at High B	urntoft Farm, Elwick		
DESIGNATION:	Scheduled	Monument (No. 1015207)	CONDITION:	Generally unsatisfactory		
				with major localised problems		
PRINCIPAL VULNERABILITY:	Extensive	vehicle damage/erosion	TREND:	Declining		
OWNER TYPE:	Private		CONTACT:	Stephen Allott 0191 269 1235		
site name:	Low Thro	ston deserted medieval village, Hartle	bool			
DESIGNATION:	Scheduled	Monument (No. 1006765)	CONDITION:	Generally satisfactory		
				but with significant localised problems		
PRINCIPAL VULNERABILITY:	Deteriorat	ion – in need of management	TREND:	Declining		
OWNER TYPE:	Private		CONTACT:	Stephen Allott 0191 269 1235		
MIDDLESBROUGH (U	JA)					
11.10	SITE NAME:	Acklam Hall, Hall Drive, Acklam	Situated in landscape.	nanor house with C19 and C20 additions. the remnants of a historic designed The building was last occupied by Middlesbroug		
		Listed Building Grade I, CA	deterioratio	t became vacant in 2008. There is progressive on to the fabric of the building and it is		
	CONDITION:	Poor	vulnerable	to anti-social behaviour. Discussions are		
	OCCUPANCY:			about a scheme to secure the future of		
	PRIORITY:	C (New entry)	the site.			
the Sur		Educational Body	Contact [,] D	avid Farrington 0191 269 1230		
		,	Contact D			
REDCAR AND CLEV	eland (l	JA)				
LAN AV	SITE NAME:	Remains of Kilton Castle, Kilton Thorpe Lane, Kilton, Lockwood	The buildin in its walls	astle ruin occupying a rocky outcrop. g is in a very bad condition, with vertical cracks and there is some regeneration of vegetation. nly limited management by the Estate.		
	DESIGNATION:	Listed Building Grade I, SM		,		
	CONDITION:	Very bad				
	OCCUPANCY:	,				
	PRIORITY:	A (A)				

	SITE NAME:	Bastion and ha-ha wall north of Kirkleatham Hall Stables, Kirkleatham, Redcar	Early-mid C18 bastion and adjoining ha-ha. Bastion badly vandalised and robbed of much stonework. A Conservation Plan for structures on the Kirkleatham Hall estate was
	DESIGNATION:	Listed Building Grade II*, CA	completed in 2008. English Heritage has offered two grants; one towards the production of an Options Appraisal for
	CONDITION:	Very bad	the garden buildings on the Estate and the other towards urgent repair works that will start in 2011.
The A Martin	OCCUPANCY:	N/A	urgent repair works that will start in 2011.
	PRIORITY:	B (B)	
A CARLES OF A CARLES OF	OWNER TYPE:	Local authority	Contact: Catherine Dewar 0191 269 1232

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the solution of the solution

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

OWNER TYPE: Private

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

Contact: Rob Young 0191 269 1239

# ABBREVIATIONS

## HERITAGE AT RISK 2011 / NORTH EAST / REDCAR AND CLEVELAND (UA)

	SITE NAME:	Bastion north west of Kirkleatham Hall Stables, Kirkleatham, Redcar	much stone on the Kirkle	stion. Badly vandalised and robbed of work. A Conservation Plan for structures eatham Hall estate was completed in 2008.
	DESIGNATION: CONDITION:	Listed Building Grade II*, CA Very bad	towards the	tage offered two grants in 2009; the first production of an Options Appraisal for the ings on the Estate and the second towards
	OCCUPANCY:		urgent repai	r works that will start in 2011.
		B (B)	0.000	
	PRIORITY:		Contact: Cat	therine Dewar 0191 269 1232
	OWNER I TPE:	Local authority	Contact. Ca	Liferine Dewar 0191 269 1232
	SITE NAME:	Gate piers at entrance of Kirkleatham Hall School, Kirkleatham, Redcar	cramps and structures o	ers. In poor condition, with rusting of iron general decay. A Conservation Plan for n the Kirkleatham Hall estate was completed lish Heritage offered two grants in 2009; the
	DESIGNATION:	Listed Building Grade I, CA		the production of an Options Appraisal for
h f C	CONDITION:	Poor	the garden b	buildings on the Estate and the second towards
	OCCUPANCY:	N/A	urgent repai	r works that will commence in 2011.
	PRIORITY:	B (B)		
	OWNER TYPE:	Local authority	Contact: Cat	therine Dewar 0191 269 1232
	SITE NAME:	Gatehouse, north east of Kirkleatham Hall Stables, Kirkleatham, Redcar	stonework r on the Kirkle	circa 1780. Roofless and upper levels of obbed. A Conservation Plan for structures eatham Hall estate was completed in 2008.
	DESIGNATION:	Listed Building Grade II*, CA		tage offered two grants in 2009; the first
		Very bad	garden build	production of an Options Appraisal for the ings on the Estate and the second towards
	OCCUPANCY:			r works that will commence in 2011.
	PRIORITY:	B (B)		
		Local authority	Contact: Cat	therine Dewar 0191 269 1232
	OWNERTH L		Contact. Ca	
	SITE NAME:	Kirkleatham Hall Stables, Kirkleatham, Redcar	and restore Plan for stru	able block. EU grants used to repair fabric structural integrity in 1985. A Conservation ctures on the Kirkleatham Hall estate was n 2008. English Heritage offered two grants
-	DESIGNATION:	Listed Building Grade II*, CA		towards the production of an Options
	CONDITION:	Poor	Appraisal fo	r the garden buildings on the Estate and
	OCCUPANCY:	Vacant		wards urgent repair works that will
	PRIORITY:	B (B)	commence i	M 2011.
	OWNER TYPE:	Local authority	Contact: Cat	therine Dewar 0191 269 1232
	SITE NAME:	Turner Mausoleum, Church of St Cuthbert, Kirkleatham Lane, Kirkleatham, Redcar	attached to Gibbs.The ir	in memory of Marwood William Turner, Church of St Cuthbert. 1739-40 by James Interior contains a number of monuments.
	DESIGNATION:	Listed Building Grade I, CA	rising damp.	has suffered from water penetration and causing damage to the internal plasterwork
CONKING READ	CONDITION:	Poor	and monum	ents. A joint EH / HLF grant was offered in
The second second	OCCUPANCY:	Part occupied	2010 toward	ds a package of urgent repairs; these works
1 TOTAL	PRIORITY:	F (C)	are due to b	be completed in 2011.
TAL	OWNER TYPE:	Religious organisation	Contact: Cat	therine Dewar 0191 269 1232
READ	SITE NAME:	War Memorial, Saltburn by Sea, Glenside, Saltburn, Marske and New Marske	Great War I Reynolds-Ste	afts style memorial to the dead of the 914-18 with bronze sculpture by Sir William ephens. Unveiled on 14 November 1920.
	DESIGNATION:	Listed Building Grade II*, CA, RPG II		as open joints and cracking in its west arm.
	CONDITION:	Poor	suffered from	Iding paved area and retaining walls have n subsidence and corrosion is affecting
	OCCUPANCY:		the heavily p	patinated bronze sculpture.
	PRIORITY:	A (A)		
NAME OF A DESCRIPTION O		Local authority	Contact: Cat	therine Dewar 0191 269 1232
SITE NAME:	Eston Nab	hill fort, palisaded settlement and bea	con, Guisboro	bugh
DESIGNATION:		Monument (No. 1011273)	CONDITION:	Generally unsatisfactory
				with major localised problems
PRINCIPAL VULNERABILITY:	Vandalism		TREND:	Stable
OWNER TYPE:	Local Auth	ority	CONTACT:	Stephen Allott 0191 269 1235

#### PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

HERITAGE AT RISK 2011 / NORTH EAST / REDCAR AND CLEVELAND (UA) / STOCKTON-ON-TEES (UA)

SITE NAME:		ettlement, dovecote and fragment of 1arske and New Marske	field system, i	mmediately north of Marske Inn Farm,
DESIGNATION:	Scheduled	Monument (No. 1018948)	CONDITION:	Generally satisfactory
				but with significant localised problems
RINCIPAL VULNERABILITY:	Moderate	stock erosion	TREND:	Declining
DWNER TYPE:	Private		CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Brotton			
DESIGNATION:	Conservat	ion Area	CONDITION:	Poor
/ULNERABILITY:	Medium		TREND:	Deteriorating
CONTACT:	Stewart Ra	amsdale (LPA) 01287 612349	NEW ENTRY?:	Yes
ITE NAME:	Guisborou	ıgh		
DESIGNATION:	Conservat	ion Area	CONDITION:	Poor
/ULNERABILITY:	Low		TREND:	Deteriorating
CONTACT:		amsdale (LPA) 01287 612349	NEW ENTRY?:	No
		< /		
SITE NAME:	Kirkleatha	m, Redcar		
DESIGNATION:	Conservat	ion Area	CONDITION:	Very bad
/ULNERABILITY:	Medium		TREND:	Improving
CONTACT:	Stewart Ra	amsdale (LPA) 01287 612349	NEW ENTRY?:	No
REDCAR AND CLEVE		IA) / NORTH YORK MOORS (		
	ELAND (U Pinchintho	IA) / NORTH YORK MOORS ( orpe Hall moated site and post medie	NP)	
SITE NAME:	ELAND (U Pinchintho	A) / NORTH YORK MOORS (	NP)	
SITE NAME: DESIGNATION:	ELAND (U Pinchintho	<b>IA) / NORTH YORK MOORS (</b> orpe Hall moated site and post medie Monument (No. 1013215)	NP) val gardens, G	<b>uisborough</b> Generally unsatisfactory
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY:	ELAND (U Pinchintho Scheduled	<b>IA) / NORTH YORK MOORS (</b> orpe Hall moated site and post medie Monument (No. 1013215)	NP) val gardens, G condition:	uisborough Generally unsatisfactory with major localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:	ELAND (U Pinchintho Scheduled Gardening Private	<b>IA) / NORTH YORK MOORS (</b> orpe Hall moated site and post medie Monument (No. 1013215)	NP) val gardens, G condition: trend:	uisborough Generally unsatisfactory with major localised problems Stable
ITE NAME: DESIGNATION: 'RINCIPAL VULNERABILITY: DWNER TYPE:	ELAND (U Pinchintho Scheduled Gardening Private	<b>IA) / NORTH YORK MOORS (</b> orpe Hall moated site and post medie Monument (No. 1013215)	NP) val gardens, G condition: TREND: contact: Reinforced with reinfor Designed b	uisborough Generally unsatisfactory with major localised problems Stable Stephen Allott 0191 269 1235 concrete silo of 1928/29. Parabolic cross-section reed concrete arches, with ribs at the ends. y Monnoyer British Construction Ltd, for the
ITE NAME: ESIGNATION: RINCIPAL VULNERABILITY: WWNER TYPE:	ELAND (U Pinchintho Scheduled Gardening Private S (UA) SITE NAME:	Phosphate Rock Silo (No. 15), Haverton Hill, Former ICI,	NP) val gardens, G condition: TREND: contact: Reinforced with reinfor Designed b storage of p of fertilizer:	uisborough Generally unsatisfactory with major localised problems Stable Stephen Allott 0191 269 1235 concrete silo of 1928/29. Parabolic cross-secti- rced concrete arches, with ribs at the ends. y Monnoyer British Construction Ltd, for the phosphate rock imported for the production This is the earliest surviving example of this
ITE NAME: ESIGNATION: RINCIPAL VULNERABILITY: WWNER TYPE:	ELAND (U Pinchintho Scheduled Gardening Private S (UA) SITE NAME: DESIGNATION:	Phosphate Rock Silo (No. 15), Haverton Hill, Former ICI, Billingham	NP) val gardens, G condition: TREND: contact: Reinforced with reinfor Designed b storage of p of fertilizer: type of silo	uisborough Generally unsatisfactory with major localised problems Stable Stephen Allott 0191 269 1235 concrete silo of 1928/29. Parabolic cross-secti- rced concrete arches, with ribs at the ends. y Monnoyer British Construction Ltd, for the phosphate rock imported for the production This is the earliest surviving example of this in England. The owner is considering options
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE:	ELAND (U Pinchintho Scheduled Gardening Private S (UA) SITE NAME: DESIGNATION:	A) / NORTH YORK MOORS ( prpe Hall moated site and post medie Monument (No. 1013215) Phosphate Rock Silo (No. 15), Haverton Hill, Former ICI, Billingham Listed Building Grade II* Poor	NP) val gardens, G condition: TREND: contact: Reinforced with reinfor Designed b storage of p of fertilizer:	uisborough Generally unsatisfactory with major localised problems Stable Stephen Allott 0191 269 1235 concrete silo of 1928/29. Parabolic cross-secti- rced concrete arches, with ribs at the ends. y Monnoyer British Construction Ltd, for the phosphate rock imported for the production This is the earliest surviving example of this in England. The owner is considering options
ITE NAME: DESIGNATION: 'RINCIPAL VULNERABILITY: DWNER TYPE:	ELAND (U Pinchintho Scheduled Gardening Private S (UA) SITE NAME: DESIGNATION: CONDITION:	A) / NORTH YORK MOORS ( prpe Hall moated site and post medie Monument (No. 1013215) Phosphate Rock Silo (No. 15), Haverton Hill, Former ICI, Billingham Listed Building Grade II* Poor	NP) val gardens, G condition: TREND: contact: Reinforced with reinfor Designed b storage of p of fertilizer: type of silo	uisborough Generally unsatisfactory with major localised problems Stable Stephen Allott 0191 269 1235 concrete silo of 1928/29. Parabolic cross-secti rced concrete arches, with ribs at the ends. y Monnoyer British Construction Ltd, for the phosphate rock imported for the production This is the earliest surviving example of this in England. The owner is considering options
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE:	ELAND (U Pinchintho Scheduled Gardening Private S (UA) SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY:	A) / NORTH YORK MOORS ( prpe Hall moated site and post medie Monument (No. 1013215) Phosphate Rock Silo (No. 15), Haverton Hill, Former ICI, Billingham Listed Building Grade II* Poor Vacant	NP) val gardens, G condition: TREND: contact: Reinforced with reinfor Designed b storage of p of fertilizer: type of silo for repair a	uisborough Generally unsatisfactory with major localised problems Stable Stephen Allott 0191 269 1235 concrete silo of 1928/29. Parabolic cross-secti rced concrete arches, with ribs at the ends. y Monnoyer British Construction Ltd, for the ohosphate rock imported for the production This is the earliest surviving example of this in England. The owner is considering options
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE:	ELAND (U Pinchintho Scheduled Gardening Private S (UA) SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY:	A) / NORTH YORK MOORS ( brpe Hall moated site and post medie Monument (No. 1013215) Phosphate Rock Silo (No. 15), Haverton Hill, Former ICI, Billingham Listed Building Grade II* Poor Vacant C (C) Company	NP) val gardens, G CONDITION: TREND: CONTACT: Reinforced with reinfor Designed b storage of p of fertilizer. type of silo for repair a Contact: Ka t, Ruins of lat in 1789. No	uisborough Generally unsatisfactory with major localised problems Stable Stephen Allott 0191 269 1235 concrete silo of 1928/29. Parabolic cross-secti reed concrete arches, with ribs at the ends. y Monnoyer British Construction Ltd, for the shosphate rock imported for the production This is the earliest surviving example of this in England. The owner is considering options nd re-use.
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:	ELAND (U Pinchintho Scheduled Gardening Private S (UA) SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	A) / NORTH YORK MOORS ( prpe Hall moated site and post medie Monument (No. 1013215) Phosphate Rock Silo (No. 15), Haverton Hill, Former ICl, Billingham Listed Building Grade II* Poor Vacant C (C) Company Ruins of Church of St Thomas a Becke Durham Road,	NP) val gardens, G CONDITION: TREND: CONTACT: Reinforced with reinfor Designed b storage of p of fertilizer. type of silo for repair a Contact: Ka t, Ruins of lat in 1789. No	uisborough Generally unsatisfactory with major localised problems Stable Stephen Allott 0191 269 1235 concrete silo of 1928/29. Parabolic cross-secti reed concrete arches, with ribs at the ends. y Monnoyer British Construction Ltd, for the phosphate rock imported for the production This is the earliest surviving example of this in England. The owner is considering options nd re-use. te Wilson 0191 269 1221 e C12 church that was altered significantly w a roofless, part-collapsed ruin and
ITE NAME: DESIGNATION: 'RINCIPAL VULNERABILITY: DWNER TYPE:	ELAND (U Pinchintho Scheduled Gardening Private S (UA) SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	A) / NORTH YORK MOORS ( prpe Hall moated site and post medie Monument (No. 1013215) Phosphate Rock Silo (No. 15), Haverton Hill, Former ICI, Billingham Listed Building Grade II* Poor Vacant C (C) Company Ruins of Church of St Thomas a Becker Durham Road, Grindon	NP) val gardens, G CONDITION: TREND: CONTACT: Reinforced with reinfor Designed b storage of p of fertilizer. type of silo for repair a Contact: Ka t, Ruins of lat in 1789. No	uisborough Generally unsatisfactory with major localised problems Stable Stephen Allott 0191 269 1235 concrete silo of 1928/29. Parabolic cross-secti reed concrete arches, with ribs at the ends. y Monnoyer British Construction Ltd, for the phosphate rock imported for the production This is the earliest surviving example of this in England. The owner is considering options nd re-use. te Wilson 0191 269 1221 e C12 church that was altered significantly w a roofless, part-collapsed ruin and
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:	ELAND (U Pinchintho Scheduled Gardening Private S (UA) SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	A) / NORTH YORK MOORS ( prpe Hall moated site and post medie Monument (No. 1013215) Phosphate Rock Silo (No. 15), Haverton Hill, Former ICI, Billingham Listed Building Grade II* Poor Vacant C (C) Company Ruins of Church of St Thomas a Becker Durham Road, Grindon Listed Building Grade I, SM Very bad	NP) val gardens, G CONDITION: TREND: CONTACT: Reinforced with reinfor Designed b storage of p of fertilizer. type of silo for repair a Contact: Ka t, Ruins of lat in 1789. No	uisborough Generally unsatisfactory with major localised problems Stable Stephen Allott 0191 269 1235 concrete silo of 1928/29. Parabolic cross-secti reed concrete arches, with ribs at the ends. y Monnoyer British Construction Ltd, for the phosphate rock imported for the production This is the earliest surviving example of this in England. The owner is considering options nd re-use. te Wilson 0191 269 1221 e C12 church that was altered significantly w a roofless, part-collapsed ruin and
REDCAR AND CLEVE	ELAND (U Pinchintho Scheduled Gardening Private S (UA) SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	A) / NORTH YORK MOORS ( prpe Hall moated site and post medie Monument (No. 1013215) Phosphate Rock Silo (No. 15), Haverton Hill, Former ICI, Billingham Listed Building Grade II* Poor Vacant C (C) Company Ruins of Church of St Thomas a Becker Durham Road, Grindon Listed Building Grade I, SM Very bad	NP) val gardens, G condition: TREND: contact: Reinforced with reinfor Designed b storage of p of fertilizer. type of silo for repair a Contact: Ka t, Ruins of lat in 1789. No	uisborough Generally unsatisfactory with major localised problems Stable Stephen Allott 0191 269 1235 concrete silo of 1928/29. Parabolic cross-section reed concrete arches, with ribs at the ends. y Monnoyer British Construction Ltd, for the phosphate rock imported for the production This is the earliest surviving example of this in England. The owner is considering options nd re-use. te Wilson 0191 269 1221 e C12 church that was altered significantly we a roofless, part-collapsed ruin and

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the solution of the solution
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS

	SITE NAME:	Bowes Railway Incline, Birtley	Part of rope-hauled colliery railway designed by George Stephenson. Opened in 1826. Suffering from severe erosion and loss of track bed. The site also suffers from extensive vandalism. The Wardley Locomotive Shed
Harris Contract	DESIGNATION:	Scheduled Monument	suffered storm-damage in 2005 and emergency repairs
	CONDITION:	Very bad	were completed in 2006 but it remains vulnerable, along with many other sections of the site.
	OCCUPANCY:		
	PRIORITY:	C (C)	
	OWNER TYPE:	Local authority	Contact: Kate Wilson 0191 269 1221
	SITE NAME:	Dunston Staiths, Dunston	Built by the North Eastern Railway Company and opened in 1893. Closed in the 1970s after being the last working staiths on the River Tyne. Fire damage in November 2003
AND ALL	DESIGNATION:	Listed Building Grade II, SM	resulted in 8% of the monument being lost and there was a further fire in July 2010. A Conservation Plan and
A AND A	CONDITION:	Poor	Feasibility Study to identify a future for the structure have
March AT	OCCUPANCY:	N/A	been produced and work continues to try and raise funding for repair works.
	PRIORITY:	C (C)	
A THURSDAY	OWNER TYPE:	Trust	Contact: Kate Wilson 0191 269 1221
	SITE NAME:	Ravensworth Castle (Nash House), Lamesley	Nash house of 1808 for SirThomas Liddell. House completed in 1846 but now a ruin with only one remainin upstanding tower at the north end. A Conservation Plan
The second se	DESIGNATION:	Listed Building Grade II*, CA	was completed in 2008 for the entire site, followed in 200 by a Viability Study and Planning Brief. Discussions are
	CONDITION:	Very bad	underway about a scheme to secure the tower and its
	OCCUPANCY:		neighbouring historic structures.
	PRIORITY:	A (A)	
	OWNER TYPE:	Private	Contact: David Farrington 0191 269 1230
	SITE NAME:	Ravensworth Castle, Cross Lane, Lamesley	Medieval castle of which two C14 corner towers and part of the curtain wall survive, in poor condition. The towers are propped to prevent further collapse.
	DESIGNATION:	Listed Building Grade II*, SM, CA	A Conservation Plan was completed in 2008 and there is now a Viability Study and Planning Brief for the site.
	CONDITION:	Very bad	An English Heritage grant was offered in 2010 to help
	OCCUPANCY:	N/A	fund project development work that will bring forward a phased repair scheme.
	PRIORITY:	A (A)	
m	OWNER TYPE:	Private	Contact: David Farrington 0191 269 1230
And Andrews	SITE NAME:	Gibside Hall, B6314, Gibside Estate, Rowlands Gill, Whickham	Large house/hall of 1603-20, enlarged C18 and altered early C19. Fell into disrepair in early C20 and now a roofless shell in poor condition. Set in early/mid C18 park
	DESIGNATION:	Listed Building Grade II*, SM, CA, RPG I	The house requires major stabilisation and consolidation works. The National Trust has undertaken works to
	CONDITION:	Very bad	improve public access to the immediate setting of the building but there remains a burge amount of remedial
	OCCUPANCY:	Vacant	building but there remains a huge amount of remedial work to do on the actual house.
	PRIORITY: OWNER TYPE:	A (A) Trust	Contact: David Farrington 0191 269 1230
	OWNER TIPE.	ii ust	
	SITE NAME:	Whinfield Coking Ovens, south east of Low Spen Farm, Whickham	Remains of what was originally a bank of 193 bee-hive coke ovens dating back to the mid-C19. Part of an extensive former mining landscape that is now largely cleared and landscaped. The remaining ovens
and the second s		Scheduled Monument	represent a rare example of intact bee-hive coke ovens.
	CONDITION:	Poor	Currently under severe attack by vandals. Initial repairs carried out in 2003 but further works are required.
	OCCUPANCY:		
	PRIORITY:	A (A)	
	OWNER TYPE:	Trust	Contact: Kate Wilson 0191 269 1221

# PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS


#### HERITAGE AT RISK 2011 / NORTH EAST / GATESHEAD / NEWCASTLE UPON TYNE

SITE NAME:	Coal mining remains at Dunston Hill, Gateshead		
DESIGNATION:	Scheduled Monument (No. 1018227)	Generally satisfactory	
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Road construction	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Site of Ravensworth coalmill, 600m north east o	f Ravenswort	h Castle, Gateshead
DESIGNATION:	Scheduled Monument (No. 1015922)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Washingwells Roman fort, Whickham, Gateshead	1	
DESIGNATION:	Scheduled Monument (No. 1018645)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235

# NEWCASTLE UPON TYNE

- 20	SITE NAME:	The Keelmen's Hospital, City Road, Newcastle upon Tyne	Almshouses constructed in 1701 for keelmen and keelmen's widows. The building was last used as student accommodation but is now vacant and disused. There are signs of water ingress and the building is a
	DESIGNATION:	Listed Building Grade II*	target for vandalism.
	CONDITION:	Poor	
A CONTRACTOR OF THE PARTY	OCCUPANCY:	Vacant	
The Art A start	PRIORITY:	C (C)	
	OWNER TYPE:	Local authority	Contact: David Farrington 0191 269 1230

<b>.</b> .	SITE NAME:	4 Eldon Square, Newcastle upon Tyne	Four-storey town house built 1825-31 by Thomas Oliver and John Dobson Frichard Grainger (one of his earliest enterprises and preludes his
	DESIGNATION	Listed Building Grade II*	ambitious remodelling of Newcastle's town centre, which began in 1834). Last occupied as shops but now largely
	CONDITION:	Poor	disused. The vacant nature of the building makes it highly
	OCCUPANCY:	Part occupied	vulnerable and there are signs of a lack of maintenance.
NH AND	PRIORITY:	C (C)	
I the second party of the second second	OWNER TYPE:	Local authority	Contact: David Farrington 0191 269 1230





	OCCUPANCY:	Part occupied	repair and conversion scheme.
id.	PRIORITY:	C (C)	
-	OWNER TYPE:	Private	Contact: David Farrington 0191 269 1230
HE HAND	SITE NAME:	55 and 57 Westgate Road, Newcastle upon Tyne	House of circa 1750 that was an art shop before becoming vacant. The interior, which contains high-quality plasterwork, needed restoration and repair after some vandalism and
	DESIGNATION:	Listed Building Grade II*, CA	neglect. English Heritage offered a grant towards a package of urgent repair works that commenced in 2008 and were
1 and 1	CONDITION:	Good	completed in 2009. However, no end use has been
RO	OCCUPANCY:	Vacant	identified for the building, which remains vacant.
	PRIORITY:	E (E)	
×	OWNER TYPE:	Private	Contact: John Edwards 0191 269 1231

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C for durant determented.
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS CA LB/LBs LPA NP RPG SM/SMs

## HERITAGE AT RISK 2011 / NORTH EAST / NEWCASTLE UPON TYNE

	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	I-17 Bolam Coyne, Byker, Newcastle upon Tyne Listed Building Grade II* Poor Vacant F (A)	Block of flats and houses built 1976-78 to a design by Ralph Erskine and widely regarded as one of the most imaginative and remarkable single developments within the Byker Estate. The complex has been vacant for many years and is a consistent target for vandalism. A repair and re-use scheme, part-funded by English Heritage, is in progress and is due to be completed during 2011/12.
A Carlos and	OWNER TYPE:	Housing Association	Contact: David Farrington 0191 269 1230
<u>,</u>	SITE NAME:	Woolsington Hall, Woolsington	A compact late C17 country house, with later additions. It has service buildings, all set in fine gardens and parkland. The house is vacant and showing signs of roof failure. The building was made weathertight during 2008 in
	DESIGNATION:	Listed Building Grade II*, RPG II	advance of proposed further repairs and restoration
and the second second	CONDITION:	Poor	designed to bring the house back into beneficial use.
	OCCUPANCY:		
	PRIORITY:	C (C)	
	OWNER TYPE:	Company	Contact: John Edwards 0191 269 1231
	SITE NAME:	Church of St James, Benwell Lane, Benwell	Built as a chapel of ease in 1832, St James became a parish church in 1843. Re-designed in 1864 in a mostly Norman style by John Dobson. Spire, choir vestry and porch were added by Hicks and Charlewood in 1895. Roof coverings are in a bad condition, as are lead valley
	DESIGNATION:	Listed Place of Worship Grade II	gutters which run the full length of the building. Heritage
	CONDITION:	Poor	Lottery Fund grant of £129,000 was offered in March
	PRIORITY:	D (New entry)	2011 towards repair programme.
	OWNER TYPE:	Religious organisation	Contact: John Edwards 0191 2691231
	SITE NAME:	Church of St Michael with St Lawrence, Avondale Road, Byker	Parish church built 1862-63 by WL Moffat. North aisle and vestry added in 1936. Repair of roofs and gutters grant-aided in past, but windows now require urgent attention and some areas of flooring are unsound. A repair scheme will form part of a wider programme of reordering
	DESIGNATION:	Listed Place of Worship Grade II	to allow greater community use as well as being a place of
	CONDITION:	Poor	worship. A £40,000 Heritage Lottery Fund grant was
	PRIORITY:	D (New entry)	offered in March 2011 towards repair programme.
	OWNER TYPE:	Religious organisation	Contact: John Edwards 0191 2691231
	SITE NAME:	Church of All Saints, Pilgrim Street	Built between 1786-96 by David Stephenson to replace a medieval church on same site. Classical style, with baroque tower, All Saints was made redundant by the Church of England in 1961. Building was used as urban studies centre and concert hall but has been reused for worship in recent
	DESIGNATION:	Listed Place of Worship Grade I, CA	years by the Church of St Wilibrord. Staining to stonework
	CONDITION:	Poor	around rainwater goods indicates leaks and there is
The second second second second		$C(N_{1})$	evidence of spalling of high level stonework.
	PRIORITY:	C (New entry)	

SITE NAME:	Dewley Hill round barrow and associated leatur	es, 550m nor	in west of Dewley Farm, Newcastle upon Tyne
DESIGNATION:	Scheduled Monument (No. 1018678)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS

NEWCASTLE UPON	TYNE / G	ATESHEAD		
	site name:	Battle of Newburn Ford, Ryton / Newburn	Second Bisho	Newburn Ford (1640) was the only battle of the ps War.The Scottish Army took Newcastle by
Ton State Salar and	DESIGNATION:	Registered Battlefield	northern def	English at this river crossing rather than attacking the ences of the city. The effect of the Scottish campaig
A MARTINE AND	CONDITION:	Generally satisfactory but with	was to force	Charles I to raise an army against them and after t
La se and a set		significant localised problems		astle, to pay them off. This expense spelt the end fo
A A Decommentation	VULNERABILIT	-		od of rule without Parliament and proved to be a owards the English Civil War. The battlefield has bee
	TREND:	Stable	subject to pie	ecemeal, peripheral development.
	OWNER TYPE:	Private	Contact: Ste	phen Allott 0191 2691 235
NORTH TYNESIDE				
	SITE NAME:	Tynemouth Station, Tynemouth	is sound and to house a	ion of 1882 by William Bell. The central section d is used operationally as a Metro station and weekend market. However, the flanking areas and in disrepair. The canopies are of ironwork
	DESIGNATION:	Listed Building Grade II*, CA	with ornam	ental spandrels. A scheme to repair the outlyin
VAN PROVINCE		Very bad	canopies co	mmenced in 2011 following a successful fundi
		Part occupied	award from	the "Sea Change" programme.
- A A A A A A A A A A A A A A A A A A A	PRIORITY:	F (D)		
		Company	Contact: Da	vid Farrington 0191 269 1230
	Owner The	company	Contact Du	
and the second	SITE NAME:	Clifford's Fort, Union Road, North Shields, Tynemouth	survives but	2, altered in C18 and C20.The curtain wall is masked by later buildings. A Conservation mpleted in 2003. Part-funded by English
and the second second		Listed Building Grade II*, SM, CA	Heritage, a s	significant programme of consolidation work
And And And And And	CONDITION:	- -	in 2008 and	terpretation of the fort walls) commenced I this scheme will continue until 2012.
		Part occupied		This scheme will continue until 2012.
	PRIORITY:	F (F)		
		Local authority	Contact: Ca	therine Dewar 0191 269 1232
SITE NAME:	St Peter's,	Wallsend		
DESIGNATION:	Conservat	ion Area	CONDITION:	Very bad
VULNERABILITY:	Medium		TREND:	Improving
CONTACT:	lan McCaf	fery (LPA) 0191 6436334	NEW ENTRY?:	Yes
SOUTH TYNESIDE				
	SITE NAME:	Cleadon Chimney, Cleadon Mill, Sunniside Lane, Cleadon, Boldon	Built in 1860 A prominen	e chimney, detached from boiler house. )-62 in Italianate style by Thomas Hawksley. It local landmark and one of a series of Itions along the North East coast.
		Cleadon Mill, Sunniside Lane,	Built in 1860 A prominen	0-62 in Italianate style by Thomas Hawksley. It local landmark and one of a series of
		Cleadon Mill, Sunniside Lane, Cleadon, Boldon Listed Building Grade II*, CA	Built in 1860 A prominen	0-62 in Italianate style by Thomas Hawksley. It local landmark and one of a series of
	DESIGNATION:	Cleadon Mill, Sunniside Lane, Cleadon, Boldon Listed Building Grade II*, CA Poor	Built in 1860 A prominen	0-62 in Italianate style by Thomas Hawksley. It local landmark and one of a series of
	DESIGNATION: CONDITION:	Cleadon Mill, Sunniside Lane, Cleadon, Boldon Listed Building Grade II*, CA Poor	Built in 1860 A prominen	0-62 in Italianate style by Thomas Hawksley. It local landmark and one of a series of
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Cleadon Mill, Sunniside Lane, Cleadon, Boldon Listed Building Grade II*, CA Poor N/A	Built in 1860 A prominer pumping sta	0-62 in Italianate style by Thomas Hawksley. It local landmark and one of a series of
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Cleadon Mill, Sunniside Lane, Cleadon, Boldon Listed Building Grade II*, CA Poor N/A C (C)	Built in 1860 A prominen pumping sta	2-62 in Italianate style by Thomas Hawksley. It local landmark and one of a series of Itions along the North East coast. In Edwards 0191 269 1231 In industrial kilns of two types. In poor Ind in urgent need of repair. A recording has been completed and a programme
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Cleadon Mill, Sunniside Lane, Cleadon, Boldon Listed Building Grade II*, CA Poor N/A C (C) Company Marsden Lime Kilns,	Built in 1860 A prominen pumping sta Contact: Joh Massive C19 condition ar programme of conserva	D-62 in Italianate style by Thomas Hawksley. It local landmark and one of a series of Itions along the North East coast. In Edwards 0191 269 1231 Dindustrial kilns of two types. In poor and in urgent need of repair. A recording
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Cleadon Mill, Sunniside Lane, Cleadon, Boldon Listed Building Grade II*, CA Poor N/A C (C) Company Marsden Lime Kilns, South Shields	Built in 1860 A prominen pumping sta	2-62 in Italianate style by Thomas Hawksley. It local landmark and one of a series of Itions along the North East coast. In Edwards 0191 269 1231 In industrial kilns of two types. In poor Ind in urgent need of repair: A recording has been completed and a programme
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Cleadon Mill, Sunniside Lane, Cleadon, Boldon Listed Building Grade II*, CA Poor N/A C (C) Company Marsden Lime Kilns, South Shields Scheduled Monument Poor	Built in 1860 A prominen pumping sta Contact: Joh Massive C19 condition ar programme of conserva	2-62 in Italianate style by Thomas Hawksley. It local landmark and one of a series of Itions along the North East coast. In Edwards 0191 269 1231 In industrial kilns of two types. In poor Ind in urgent need of repair: A recording has been completed and a programme
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Cleadon Mill, Sunniside Lane, Cleadon, Boldon Listed Building Grade II*, CA Poor N/A C (C) Company Marsden Lime Kilns, South Shields Scheduled Monument Poor	Built in 1860 A prominen pumping sta Contact: Joh Massive C19 condition ar programme of conserva	2-62 in Italianate style by Thomas Hawksley. It local landmark and one of a series of Itions along the North East coast. In Edwards 0191 269 1231 In industrial kilns of two types. In poor Ind in urgent need of repair: A recording has been completed and a programme

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS

HERITAGE AT RISK 2011 / NOR	IH EAST / SU	OTH TTNESIDE / SUNDERLAND		
	SITE NAME: DESIGNATION: CONDITION:	Christ Church, Grange Road West, Jarrow Listed Place of Worship Grade II Very bad	English style of Frosterle high quality a dangerous	ch of 1868 by Johnson and Hicks in the Early a. Interior contains a Norman-style font made y marble and a Gothic-style altar composed of woodwork. The tip of the tall broach spire is in s condition and is scheduled to be taken down during 2011. There is also a need for other pairs.
	PRIORITY:	B (New entry)		
	OWNER TYPE:	Religious organisation	Contact: Joh	nn Edwards 0191 2691231
SITE NAME:	Mill Dam,	South Shields		
DESIGNATION:	Conservat	ion Area	CONDITION:	Poor
VULNERABILITY:	Low		TREND:	Deteriorating
CONTACT:	Lucy Rout	ledge (LPA) 0191 424 7592	NEW ENTRY?:	No
SUNDERLAND				
	SITE NAME:	Screen Wall at Monkwearmouth Museum of Land Transport, Sunderland	Monkwearn on a north/ for the York	ashlar high screen wall flanking the former nouth Railway Station (North Bridge Street) south axis. Built in 1848 as a branch terminus , Newcastle & Berwick Railway Co.The station
	DESIGNATION:	Listed Building Grade II*		81 and is now a museum. The central
	CONDITION:	Poor	museum bu	ilding was recently repaired as part of a ramme of works but the screen wall was
	OCCUPANCY:	N/A	not included and remains in a poor condition.	
	PRIORITY:	С (С)		
	OWNER TYPE:	Local authority	Contact: Joł	nn Edwards 0191 269 1231
	CONDITION: OCCUPANCY:	N/A	sound of ap to the surro shallow dish short ramp	irror built during World War I to listen for the opproaching enemy airships and give warning bunding area. Made of concrete, comprising a n measuring I5 feet in diameter either side of ed walls. The structure is slowly deteriorating, se of the concrete dish beginning to fall away.
	PRIORITY:	C (New entry) Local authority	Contact: Ka	te Wilson 0191 269 1221
	OWNER TIPE:	Local autionty	Contact. Na	
	SITE NAME:	Doxford House, Warden Law Lane, Silksworth, Sunderland	formerly us the early C	e (previously known as Silksworth House), ed as a students' hall of residence. Mostly of 19 but with some earlier features. The property d is highly vulnerable to theft and arson
	DESIGNATION:	Listed Building Grade II*, CA		cent fire has caused extensive damage to
	CONDITION:	Very bad	the conserv	atory. A re-use scheme has been agreed
FAIL STREET	OCCUPANCY:	Vacant	but has stall	
	PRIORITY:	A (D)		
1	OWNER TYPE:	Private	Contact: Da	avid Farrington 0191 269 1230
	SITE NAME:	'F' Pit Museum – Colliery Engine House, Albany Way (East side), Washington	opened in I House was	House was built in 1926, although the pit 777. The pit closed in 1968 and the Engine presented as a monument. It opened as a 1976, being leased to Tyne & Wear Museums
Fe - 1 - THE	DESIGNATION:	Listed Building Grade II, SM		wever, operational and maintenance costs,
	CONDITION:	Poor	coupled wit	h low visitor figures, caused TWMS to cease its
	OCCUPANCY:	Part occupied	operations	and the future of the building remains uncertair
	PRIORITY:	C (C)		
		l a anti-acate a star :	Carata at Va	

Contact: Kate Wilson 0191 269 1221

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Concentration
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

OWNER TYPE: Local authority

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS

### HERITAGE AT RISK 2011 / NORTH EAST / SUNDERLAND

	CONDITION: OCCUPANCY: PRIORITY:	Track, Wagon Shop and associated sheds and structures, Bowes Railway, WashingtonScheduled MonumentVery badPart occupiedB (A)Local authority	opened in workshops vulnerable restoration. part-funded EH offered to the Wag	track, part of the Bowes Railway, which 1826. The Blacksmiths, Engineering and Fitting were repaired in 2003/04 but the site remains to vandalism and the track bed requires general . Blackham's Hill Hauler House was repaired, d by English Heritage grant aid, in 2009/10 and another grant in 2011 towards urgent repairs fon Shop.
	SITE NAME: DESIGNATION: CONDITION: PRIORITY:	Guru Gobind Singh Gurdwara Sikh Centre (Formerly Christ Church), Ryhope Road Listed Place of Worship Grade II, CA Very bad C (New entry)	of Coventr including ea redundant by the Sikh Spire is in r temporary	parish church built in 1862-64 by James Murray y. The building contains high quality glasswork, ast window by Morris and Co. Church was made by the Church of England but has been acquired community and continues as a place of worship. need of urgent repair and currently has protection attached to it. Repairs are also proof, rainwater goods and windows.
	OWNER TYPE:	Religious organisation	Contact: Jol	hn Edwards 0191 2691231
SITE NAME: DESIGNATION:	17th and 1	stle: a medieval fortified house, chapel 8th century country houses and assoc Monument (No. 1017223)		s, Sunderland Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Vandalism		TREND:	Stable
PRINCIPAL VULNERABILITY: OWNER TYPE:	Vandalism Local Auth	ority	TREND: CONTACT:	<b>.</b> .
	Local Auth World Wa 570m nor	nority ar I early warning acoustic mirror on N th of Carley Hill Cricket Ground, Sunc Monument (No. 1020325)	CONTACT:	Stable
OWNER TYPE:	Local Auth World Wa 570m nor	r I early warning acoustic mirror on N th of Carley Hill Cricket Ground, Sunc	CONTACT: Namey Hill, derland	Stable Stephen Allott 0191 269 1235 Generally unsatisfactory
OWNER TYPE: SITE NAME: DESIGNATION:	Local Auth World Wa 570m nor	r I early warning acoustic mirror on N th of Carley Hill Cricket Ground, Sunc Monument (No. 1020325)	CONTACT: Jamey Hill, Jerland CONDITION:	Stable Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Vorld Wa 570m nor Scheduled Collapse Local Auth	r I early warning acoustic mirror on N th of Carley Hill Cricket Ground, Sunc Monument (No. 1020325)	CONTACT: Jamey Hill, Jerland CONDITION: TREND:	Stable Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems Declining
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Vorld Wa 570m nor Scheduled Collapse Local Auth	ar I early warning acoustic mirror on N th of Carley Hill Cricket Ground, Sund Monument (No. 1020325) nority erland Riverside	CONTACT: Jamey Hill, Jerland CONDITION: TREND:	Stable Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems Declining
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Vorld Wa 570m nor Scheduled Collapse Local Auth Old Sunde Conservat Low	ar I early warning acoustic mirror on N th of Carley Hill Cricket Ground, Sund Monument (No. 1020325) nority erland Riverside	CONTACT: Aamey Hill, derland CONDITION: TREND: CONTACT:	Stable Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Vorld Wa 570m nor Scheduled Collapse Local Auth Old Sunde Conservat Low	ar I early warning acoustic mirror on N th of Carley Hill Cricket Ground, Sund Monument (No. 1020325) nority erland Riverside	CONTACT: Aamey Hill, derland CONDITION: TREND: CONTACT: CONDITION:	Stable Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: VULNERABILITY:	Local Auth World Wa 570m nor Scheduled Collapse Local Auth Old Sunde Conservat Low Michael Lo	ar I early warning acoustic mirror on N th of Carley Hill Cricket Ground, Sund Monument (No. 1020325) nority erland Riverside	CONTACT: Jamey Hill, Jerland CONDITION: TREND: CONDITION: CONDITION:	Stable Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 Very bad Deteriorating significantly
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT:	Local Auth World Wa 570m nor Scheduled Collapse Local Auth Old Sunde Conservat Low Michael Lo	ar I early warning acoustic mirror on N th of Carley Hill Cricket Ground, Sund Monument (No. 1020325) nority erland Riverside ion Area wwe (LPA) 0191 5612546 erland, East End of City	CONTACT: Jamey Hill, Jerland CONDITION: TREND: CONDITION: CONDITION:	Stable Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 Very bad Deteriorating significantly No
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME:	Vorld Wa 570m nor Scheduled Collapse Local Auth Old Sunde Conservat Low Michael Lo	ar I early warning acoustic mirror on N th of Carley Hill Cricket Ground, Sund Monument (No. 1020325) nority erland Riverside ion Area wwe (LPA) 0191 5612546 erland, East End of City	CONTACT: CONDITION: CONDITION: CONTACT: CONTACT: CONDITION: CONDITION: NEW ENTRY?:	Stable Stephen Allott 0191 269 1235 Generally unsatisfactory with major localised problems Declining Stephen Allott 0191 269 1235 Very bad Deteriorating significantly

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS



This document is one in a series of publications produced as part of English Heritage's national Heritage at Risk programme. More information about Heritage at Risk and other titles in the series can be found at **www.english-heritage.org.uk/risk** 

HERITAGE AT RISK

Published October 2011 by English Heritage 1 Waterhouse Square, 138-142 Holborn, London ECIN 2ST

© Copyright English Heritage 2011