



ENGLISH HERITAGE

HERITAGE AT
RISK
REGISTER
2010

SOUTH EAST

Contents

HERITAGE AT RISK	3
Reducing the risks	6
Publications and guidance	9
THE REGISTER	11
Content and assessment criteria	11
Key to the entries	13
Bracknell Forest (UA)	16
Brighton and Hove, City of (UA)	16
Buckinghamshire	18
East Sussex	22
Hampshire	26
Isle of Wight (UA)	40
Kent	43
Medway (UA)	57
Milton Keynes (UA)	59
Oxfordshire	60
Portsmouth, City of (UA)	68
Reading (UA)	69
Southampton, City of (UA)	70
Surrey	70
West Berkshire (UA)	75
West Sussex	77
Windsor and Maidenhead (UA)	85
Wokingham (UA)	85

HERITAGE AT RISK

2010 marks the publication of the third edition of our Heritage at Risk Register. It identifies which of this country's most important grade I and II* listed buildings, scheduled monuments, registered parks and gardens, registered battlefields, protected wreck sites and conservation areas are threatened by development pressures, neglect or decay. The Heritage at Risk Register also monitors the changing condition of assets to help prioritise where resources and expertise can best be deployed. This year, we undertook a pioneering 15% sample survey of England's 14,500 listed places of worship to help us understand the condition of the thousands of designated churches, chapels, synagogues, mosques and temples and other faith buildings that are the spiritual focus for our communities. They face many different kinds of challenges and we need to ensure their future.


The expansion of the Heritage at Risk Register in the South East has presented both opportunities and challenges. Complex and problematic defence buildings still feature strongly in the Register. The threats to conservation areas and landscapes are also challenging because the problems are more difficult to address; they are often related to development pressures and multiple ownership rather than to neglect and decay of individual structures.

However, the past year has seen successes on all fronts too. We have seen some of our longest-standing buildings at risk conserved and removed from the Register, including the magnificent barn at Westenhanger Castle in Kent and the ruined church of St Mary at Treyford in West Sussex. As well as working to understand better the data provided by the Register, we have been sowing the seeds of what we hope will turn out to be a number of positive future solutions. For example, we have improved liaison with owners and have provided advice and guidance to partners on Environmental Stewardship schemes that improve site management within the agricultural landscape. Several of the region's registered parks and gardens at risk have had conservation management plans commissioned to help owners understand and better manage their sites.

The global financial recession and its consequences are having an impact on progress in dealing with Heritage at Risk. Funding is becoming ever more difficult to obtain and competition is increasing for scarce public grants and subsidies. Many sites have no obvious commercial value, which discourages owners from investing in them.

It is also becoming harder to find developers with the will and the resources to take on the most difficult cases. At some sites, even though plans have been agreed, work will not start until the economy recovers. Elsewhere, improvement or repair works have been partially completed when contractors have gone into receivership and projects have stalled – as at Swaylands, a grade II registered park and garden in Kent, and the Smithery at Chatham Dockyard, although happily the hiatus was short-lived at both these sites.

Safeguarding our heritage will remain very challenging, even as we emerge from the recession. Strong partnership working and positive engagement with owners and local authorities on sustainable solutions will remain at the heart of future success in managing Heritage at Risk in the region.



Andrew Brown, Planning and Development Regional Director, South East

Contact: Simon Goodhugh, Business Manager, English Heritage South East Region, Eastgate Court, 195-205 High Street, Guildford, GU1 3EH. Telephone: 01483 252037 Fax: 01483 252021 Email: simon.goodhugh@english-heritage.org.uk

HADLOW TOWER, KENT

This grade I listed folly once belonged to a demolished early 19th century country house; it has been on the Buildings at Risk Register since its inception in 1998. Plans for the tower to be restored for use as a holiday property by the Vivat Trust have been developed. The Heritage Lottery Fund and English Heritage have both agreed to provide grants but the project has been delayed because of difficulties in securing partnership funding in the wake of the global economic downturn. The Trust is now looking at a reduced scope of works that can be achieved with the budget available.

LISTED BUILDINGS

- 1 in 32 (3.1%) grade I and II* listed buildings are at risk across the country. In the South East this falls to 1.8% (102 sites).
- 7 sites were removed from the 2009 Register in the region during the year, but 3 new sites have been added.
- Since publication of the 1999 baseline Register 49.4% of the region's buildings at risk (115 sites) have been removed from the regional Register as their futures have been secured, compared to the national figure of 50.7% (724).
- Nationally, £6.2m was offered to 76 sites on the Register during 2009/10. In the South East we awarded grants totalling £450k to 8 sites.

CONSERVATION AREAS

- 272 local authorities (81%) have taken part in our national survey of conservation areas, 52 of which were in the South East region.
- We now have information for 7,388 of England's 9,300 designated conservation areas, of which 1,423 are in the South East.
- 549 (7.4%) of the conservation areas for which we have information are at risk, 101 (6.6%) of them in our region.

SCHEDULED MONUMENTS

- Approximately 1 in 6 (17.2%) of England's 19,731 scheduled monuments are at risk, compared with 9.4% (246 sites) in the South East.
- The total at risk has fallen by 142 (4.0%) since 2009, 24 of which (8.9%) were in this region.
- Arable ploughing and unrestricted plant, scrub or tree growth account for nearly two thirds of sites at risk nationally. This increases to three quarters in our region.
- Nationally, 82% of scheduled monuments at risk are in private ownership, rising to 89% in the South East.
- Of the £450k offered to owners of scheduled monuments at risk in 2009/10, £64k was awarded to 11 sites in our region.

REGISTERED PARKS AND GARDENS

- 1 in 16 of England's 1,606 registered parks and gardens are at risk, with an increase from 6.0% (96) in 2009 to 6.2% (99) this year. In the South East, 24 of our 368 sites are at risk (6.5%).
- Nationally, 5 sites have been added and 2 removed from the Register. There has been no change in the South East.

REGISTERED BATTLEFIELDS

- Of the 43 registered battlefields in England, 6 are at risk, 1 fewer than in 2009.
- Of the 6 registered battlefields in the South East, 1 (Newbury) is at risk.

PROTECTED SHIP WRECKS

- Of the 46 protected wreck sites around England's coast, 8 are at risk, a fall of 1 since 2009, due to the implementation of an improved management regime.
- 7 of the South East's 20 protected wreck sites are at risk, 4 of them on the Goodwin Sands.



BROOKWOOD CEMETERY, SURREY

Brookwood's huge size, wealth of monuments and multiple ownership have combined to put its future at risk. Woking Borough Council and English Heritage are encouraging development of a Conservation Management Plan to guide this unique landscape to long-term safety.

THERE ARE

5,574

GRADE I AND II*
LISTED
BUILDINGS
IN THE SOUTH EAST

9.4%

OF THE
REGION'S
SCHEDULED
MONUMENTS
ARE AT RISK

7.1%

OF
CONSERVATION
AREAS SURVEYED
IN THE REGION ARE
AT RISK

6.5%

OF THE REGIONS
368 REGISTERED
PARKS AND
GARDENS
ARE AT RISK

CARING FOR PLACES OF WORSHIP

Places of worship make a huge contribution to our towns and villages. They sit at the heart of communities, dominating skylines and landscapes. They are the product of centuries of invested skill and philanthropy. Most remain as places of prayer and spirituality but others have acquired new social uses that benefit a much wider cross-section of urban and rural society.

Like all buildings, they require regular maintenance to keep them in good condition. They also need to adapt to the evolving needs of their congregations and the wider community. Responsibility for their care falls almost entirely on the shoulders of volunteers, and for many smaller congregations the burden can be heavy.

We have therefore undertaken a series of consultation events with congregations, user groups and local authorities to identify the biggest concerns of those who manage these very special places. Places of Worship are particularly close to the heart of local communities, but in practice it is often just a handful of dedicated individuals who maintain them. They face unique challenges, which are illustrated in an accompanying report.


What we know

- 45% of all grade I buildings are places of worship.
- 85% of listed places of worship belong to the Church of England.
- Up to 1 in 10 could be at risk from leaking roofs, faulty gutters or eroding stonework.
- 1,850 repair projects at 1,567 buildings have shared £171m of English Heritage and Heritage Lottery Fund grant aid since 2002/3.

What congregations want to understand better

- Why their building has been listed and what that means.
- How to get permission to make changes and find expert help.
- How to raise money for one-off projects and day-to-day maintenance.
- Who will look after their buildings in the future.

All of these are considered in our booklet *Caring for Places of Worship*, sent to every listed place of worship.



For more information, see
www.english-heritage.org.uk/risk
or contact your English Heritage regional office.

If you would like this document in a different format, please contact our customer services department on telephone: 0870 333 1181 fax: 01793 414926 textphone: 01793 414878 email: customers@english-heritage.org.uk

Reducing the risks

English Heritage is committed to securing a year-on-year reduction in the number of heritage sites at risk. This will be challenging given the number of assets now on the register and the different kinds of risk they face. Each asset type and individual case will require its own approach and solution.

There are, however, some general approaches that are relevant to all assets at risk. Resolving cases requires working in close partnership with owners, local planning authorities and other relevant organisations and partners. Advice and understanding are essential. Historic Environment Records, maintained by local authorities, are repositories of information on local historic assets. They underpin the work of local authority historic environment services and can help improve the protection, conservation and management of heritage assets.

Maintenance of heritage assets is essential if they are not to become 'at risk', and to prevent those that are already at risk from decaying further and thereby escalating the cost of their repair and consolidation. Buildings, for instance, decay rapidly when left empty. Avoiding vacancy through short-term lets or schemes that provide protection through residential occupation are low-cost ways of maintaining buildings until permanent solutions can be found.

English Heritage provides on-line advice and guidance to local authorities, owners and managers of sites through the Historic Environment Local Management (HELM) website www.helm.org.uk.

LISTED BUILDINGS

English Heritage's role in securing the future of buildings at risk is primarily to provide practical advice, guidance and resources to local authorities and owners. Our involvement in cases is determined by the importance of the building and the complexity of the issues. We can help with analysis of the issues, investigation of the feasibility of options and brokering solutions. Although buildings at risk will continue to be a priority for English Heritage repair grants, grant-aid is limited in relation to demand. Grants from other public sources, notably the Heritage Lottery Fund, continue to be essential in helping secure the future of buildings at risk.

In very exceptional cases, English Heritage may acquire and repair a particularly important building at risk, where it is clear that the scale and complexity of problems are such that direct involvement is the best way of securing the building's long-term future.

Local authorities have a primary role in protecting the historic environment. The creation of a local 'at risk' register is the first step in tackling neglected buildings in order to assess and monitor the scale of the problem and prioritise resources and action. Local authorities can also take action to secure the preservation of historic buildings through the use of statutory notices. Some councils have a successful track record, but generally these powers are under-used. It is essential that local authorities make best use of their powers to secure buildings at risk, to 'stop the rot' and prevent the costs escalating beyond the point where it is economic to repair.

To help local authorities make more frequent and timely use of their statutory powers, English Heritage runs a grant scheme to underwrite a significant proportion of the irrecoverable costs involved in serving Urgent Works and Repairs Notices.

Building preservation trusts can be the key to saving many buildings at risk. Some trusts cover geographical areas; others specialise in particular types of building or are formed to save just one building. Determined individuals and trusts have saved numerous buildings at risk, working in partnership with other organisations such as local and national amenity societies, including SAVE Britain's Heritage, the Society for the Protection of Ancient Buildings, The Victorian Society and the Georgian Group.

SCHEDULED MONUMENTS

Although a significant proportion of scheduled monuments remain at risk, in many cases the problems can be reduced by either small changes to land management or better-informed decision-making. This is reinforced by the success in reducing the number of monuments at risk since the release of the interim figures in 2008, which shows how the simple act of disseminating information and advice can go a long way towards improving conditions. English Heritage provides on-line advice to the owners and managers of sites via the Historic Environment Local Management website www.helm.org.uk; through its Historic Environment Field Advisers and through the network of local authority Historic Environment Countryside Advisers that we have co-sponsored with local authority partners.

While most owners and managers of scheduled monuments address their long-term care on a regular basis, some monuments do require significant resources to stabilise their condition, to carry out repairs, or to change the way in which the land on and around them is used. English Heritage therefore works closely with Natural England who deliver the Environmental Stewardship agri-environment scheme on behalf of Defra and who are active in helping develop management regimes which include scheduled monuments. We also help the Heritage Lottery Fund to identify important sites deserving grant-aid.

The English Heritage National Monuments Record and local authority Historic Environment Records have increased the information available to land managers and we are continuing to develop their services. A new Selected Heritage Inventory for Natural England (SHINE) will soon allow owners to view online information on scheduled monuments and other archaeological features on their holdings.

In all cases – whether for rural or urban monuments – close co-operation with owners and land managers is the key to making further progress.

REGISTERED PARKS AND GARDENS

Inclusion on the Register brings no additional statutory controls, but there is a presumption in favour of the conservation of all designated assets in the planning system. The Government's new Planning Policy Statement 5 *Planning for the Historic Environment* (PPS 5) and its supporting Practice Guide will help planning authorities to assess and mitigate the impact of development on our irreplaceable heritage of designed landscapes.

English Heritage can engage only with the proposals for change to the highest graded designed landscapes and where the impact on historic significance is greatest. We will continue to tackle the skills crisis facing historic parks and gardens through sector-wide initiatives.

English Heritage encourages the development of conservation management plans for registered historic parks and gardens, especially those in multiple ownership. We are also keen for bursars and estate teams to use management plans to help conserve important but fragile landscapes in the care of schools, hospitals, hotels and other institutional owners.

REGISTERED BATTLEFIELDS

As with registered parks and gardens, this designation brings no additional statutory controls, but there is a presumption in favour of conservation of registered battlefields in the new PPS 5.

English Heritage will continue to work with owners to develop management plans for registered sites and, in appropriate cases, contribute towards the cost of management plans. We will develop positive landscape strategies with owners and partners such as Defra. In some circumstances, we may encourage the conversion from arable to pasture of especially sensitive locations to protect battlefield archaeology from the effects of ploughing and as part of a wider drive to prevent unauthorised or damaging metal-detecting.

English Heritage will also continue to encourage greater access to battlefields and improve their amenity value and visitors' appreciation of the impact these historic events had on our development as a nation.

Local authorities can help reduce the risk to battlefields by designating registered battlefields as conservation areas. This provides further protection and makes sure that registered battlefields are explicitly taken into account in Local Development Frameworks. Local authorities can also invite comments from the Battlefields Trust on planning applications affecting the setting of registered sites.

PROTECTED WRECK SITES

At the strategic level, the major sources of risk to designated wreck sites have now been identified. In terms of high-priority sites, practical requirements have also been identified in conservation management plans.

Risks to protected wreck sites can often be reduced through education, provision of marker buoys, or planning policies that take full account of their national importance. However, some sites require significant resources to stabilise their condition or to carry out detailed archaeological assessments of their conservation requirements. Although English Heritage has statutory power to allocate funds to promote the preservation and maintenance of protected wreck sites, its financial resources can solve only a small proportion of the problems.

In spite of the inherent difficulties with caring for this type of site, careful management must be maintained if we are to avoid the loss of wreck sites. It is therefore close co-operation between the owners of protected wreck sites (where known), authorised divers and all organisations charged with care for the marine and coastal environment, that will make the real difference to their long-term survival.

Practical advice on the management of historic wreck sites, whether at the coast-edge or under water, is available from English Heritage's Maritime Archaeology Team (maritime@english-heritage.org.uk) and from www.helm.org.uk.

CONSERVATION AREAS

The risks to conservation areas are difficult to address as they cover large areas of land and involve many different owners. Looking after them is thus a responsibility we all share – those of us who visit them to work or for enjoyment, those of us who own homes and businesses in them, those of us whose job it is to manage the spaces between the buildings and make decisions about their future.

Overall understanding of their character, development of a robust management regime and engagement by the public are therefore the keys to providing them with sustainable long-term futures. A conservation area is more likely to improve over time if the local authority commits itself to employing a dedicated conservation officer and to appointing an elected member as a heritage champion to promote the historic environment within the council. It also depends on members of the local community engaging either individually or through some form of conservation area advisory committee.

Armed with the information provided by the survey, we and our regional partners will have the evidence to direct resources and investment much more accurately towards those conservation areas at greatest risk. We will also want to target those with the greatest potential to improve the quality of life and economic prospects of people in the villages, towns and cities of which they are such crucially important components.

Publications and guidance

English Heritage has produced the following publications relating to heritage at risk, including:

- *Buildings at Risk: a New Strategy* (1998)
- *Caring for Places of Worship 2010* (2010) – a report on the condition of England's listed places of worship and the needs of the congregations
- *Heritage at Risk: Conservation Areas* (2009)
- *Heritage at Risk 2010* – national report and summaries for each of our nine regions: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, Yorkshire and the Humber
- *Heritage at Risk Register 2010* – detailed listings for each of our nine regions: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, Yorkshire and the Humber can be downloaded from our website or viewed as an interactive database: www.english-heritage.org.uk/risk
- *Monuments at Risk* (2008) – summary of scheduled monuments at risk in each of our nine regions: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, Yorkshire and the Humber
- *Protected Wreck Sites at Risk: A Risk Management Handbook* (2007)
- *The Monuments at Risk initiative 2003–08* (2010)

HERITAGE AT RISK ON THE WEB

To find out more about the Heritage 'at risk' programme visit www.english-heritage.org.uk/risk where you will find an interactive database providing detailed information on all heritage sites 'at risk' nationally.

For further information about the different classes of designated heritage assets, including listed buildings, conservation areas, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites visit the Heritage Protection section of our website www.english-heritage.org.uk/heritageprotection

CONSERVATION POLICIES AND GUIDANCE

The following publications are among the numerous helpful guidance documents now available on our website: www.english-heritage.org.uk/publications or www.english-heritage.org.uk/helm

Caring for Places of Worship (2010) – a practical booklet for everyone involved in caring for England's listed places of worship

Constructive Conservation in Practice (2008)

Conservation Principles, Policies and Guidance for the Sustainable Management of the Historic Environment (2008)

Creativity and Care: New Works in English Cathedrals (2009)

Enabling Development and the Conservation of Significant Places (2008)

Farming the Historic Landscape: Caring for Archaeological sites on Arable Land (2004)

Farming the Historic Landscape: Caring for Archaeological sites in Grassland (2004)

Guidance on the Management of Conservation Areas (2006)

Guidance on Conservation Area Appraisals (2006)

Guidance Notes and Application Forms for Grants to Local Authorities:

– *Grants to Local Authorities to Underwrite Urgent Works Notices* (1998)

– *Acquisition Grants to Local Authorities to Underwrite Repairs Notices* (1998)

– *Grants for Historic Buildings, Monuments and Designed Landscapes* (2004)

Heritage at Risk: Conservation Areas (2009) – guidance for local authorities

Managing Local Authority Heritage Assets: Some Guiding Principles for Decision Makers (2003)

New Uses for Former Places of Worship (2010)

Options for the Disposal of Redundant Churches and Other Places of Worship (2010)

Paradise Preserved: An Introduction to the Assessment, Evaluation, Conservation and Management of Historic Cemeteries (2002)

Scheduled Monument Consent: a Guide for Owners and Occupiers (2009)

Shared Interest: Celebrating Investment in the Historic Environment (2006)

Stopping the Rot: a Step by Step Guide to Serving Urgent Works and Repairs Notices (1998)

The Disposal of Historic Buildings: Guidance Note for Government Departments and Non-Departmental Public Bodies (DCMS, 1999). A new version is being prepared

If you would like further information about any of these publications, please contact:

English Heritage Customer Services Department
PO Box 569, Swindon SN2 2YP
Telephone: 0870 333 1181
Fax: 01793 414926
Email: customers@english-heritage.org.uk

THE REGISTER

Content and criteria

DESIGNATION

All the historic environment matters but there are some elements which warrant extra protection through the planning system. Since 1882, when the first Act protecting ancient monuments and archaeological remains was passed, government has been developing the designation system. Listing emerged from the post-blitz 1940s Planning Acts, and is now applied to about half a million buildings ranging from palaces to street lamps. Almost 20,000 archaeological sites are scheduled, which introduces tight management controls. Some 1,606 designed landscapes are registered, as are 43 battlefields, and 46 wreck sites are protected.

English Heritage, as the government's expert adviser, is responsible for making recommendations – but it is still the Secretary of State at the Department for Culture Media and Sport who makes the decisions on whether a site is designated. Understanding and appreciation develop constantly, which makes keeping the designation base up to date a never-ending challenge. While responding to threat-driven cases, we also seek to work strategically. Recent developments have seen a greater striving for openness and transparency in the process of designating a site, and better communication of what makes something special.

Conservation areas are designated locally by local planning authorities. They are areas of special architectural or historic interest the character or appearance of which it is desirable to preserve or enhance.

LISTED BUILDINGS

Definition

A listed building is a building (or structure) that has been designated as being of 'special architectural or historic interest'. The older and rarer a building is, the more likely it is to be listed. Buildings less than 30 years old are listed only if they are of outstanding quality and under threat.

Listed buildings are graded I, II* and II. Grade I and II* are particularly important buildings of outstanding interest; together they amount to 8% of all listed buildings. The remaining 92% are of special interest and are listed grade II.

Entries on the statutory list of buildings of special architectural or historic interest may comprise a number of separate buildings. Formal residential terraces are the most obvious example. Entries on this register reflect how buildings are grouped and recorded on the statutory list.

Structures can occasionally be both listed as buildings and scheduled as monuments.

Criteria for inclusion on this register

Buildings considered for inclusion on this register must be listed grade I or II*, (or grade II in London) or be a structural scheduled monument. Buildings are assessed for inclusion on the basis of condition and, where applicable, occupancy (or use). The condition of buildings on the register ranges from 'very bad' to 'poor', 'fair' and (occasionally) 'good'. The register also includes buildings that are vulnerable to becoming at risk because they are empty, under-used or face redundancy without a new use to secure their future.

Occupancy (or use) is noted as 'vacant', 'part occupied', 'occupied', or occasionally, 'unknown'; for many structural monuments, occupancy is not applicable.

Assessing vulnerability in the case of a building in fair condition necessarily involves judgement and discretion. A few buildings on the register are in good condition, having been repaired or mothballed, but a new use or owner is still to be secured.

Buildings are removed from the 'at risk' register when they are fully repaired/consolidated, their future secured, and where appropriate, occupied.

Priority for action

Once a building is identified as 'at risk' or vulnerable and included on the register, priority for action is assessed on a scale of A to F, where 'A' is the highest priority for a building which is deteriorating rapidly with no solution to secure its future, and 'F' is the lowest priority where a repair scheme is in progress and an end use has been secured.

SCHEDULED MONUMENTS

Definition

Scheduled monuments include archaeological sites and landscapes, and 19,731 examples have been designated because of their national importance. Scheduled monuments are not graded, and most have limited potential for beneficial use. They cover human activity from the prehistoric era, such as burial mounds, to 20th century military and industrial remains. For the millennia before written history, scheduled monuments are the only testament to innumerable generations of people of whom there is no other record.

The later 20th century saw unprecedented changes to the landscape. As a result, types of historic site that once were commonplace began to become rare. Those that survive often represent just small islands of what once characterised broad sweeps of our towns and countryside. Although protected by law, scheduled monuments are still at risk from a wide range of processes. In particular, they can frequently be exposed to intense pressures beyond the reach

of the planning system. These include damage from cultivation, forestry and – often most seriously of all – wholly natural processes such as scrub growth, animal burrowing and erosion.

Criteria for inclusion on this register

Scheduled monuments included on this register have been identified as being 'at risk' because of their condition and vulnerability, the trend in their condition, and their likely future vulnerability. A site's condition is expressed in terms of the scale and severity of adverse effects on it, ranging from those with 'extensive significant problems' to others that have only 'minor localised problems'.

Monuments are removed from the register once sufficient progress has been made to address identified issues, demonstrating a significant reduction in the level of risk.

REGISTERED PARKS AND GARDENS

Definition

There are 1,606 designed landscapes on the current English Heritage Register of Historic Parks and Gardens of Special Historic Interest. These registered landscapes are graded I, II* or II, and include private gardens, public parks and other green spaces, country estates and cemeteries. They are valued for their design, diversity and historical importance and in contrast to the number of listed buildings and scheduled monuments, registered parks and gardens is a very small group of assets.

Inclusion on the English Heritage Register of Historic Parks and Gardens brings no additional statutory controls, but there is a presumption in favour of conservation of the designated site. Local authorities are required to consult English Heritage on applications affecting sites registered as grade I or II* and the Garden History Society on sites of all grades.

Criteria for inclusion on this register

The identification of registered parks and gardens at risk begins with an appraisal of the condition and vulnerability of each registered landscape. Steps being taken by owners to address problems are also taken into consideration.

Landscapes assessed as being 'at risk' are typically affected by development and neglect. They have frequently been altered by development or are faced with major change. The original function of these landscapes has often changed; and divided ownership often results in the loss of the cohesive conservation of the historic designs.

Landscapes are removed from the register once plans are put in place to address issues and positive progress is being made.

REGISTERED BATTLEFIELDS

Definition

English Heritage's Register of Historic Battlefields has identified 43 nationally significant sites ranging in date from 991 to 1685. These are places where people risked their lives fighting for a cause and where history was made. The outcome of these battles was influenced by where they were fought and traces of the events will have been left across the landscape. Battlefields are cherished for many reasons, as a commemoration of the event and those who died, as a resource for understanding the course of the battle, and for the light they can shed on the times in which the battle was fought. They are vulnerable to insensitive development and to poorly managed investigation such as large-scale metal-detecting. While this designation introduces no additional statutory controls, one of its primary objectives is to encourage policies and other mechanisms that ensure that change and development affecting battlefields are sensitive and appropriate.

Criteria for inclusion on this register

Battlefields deemed to be 'at risk' of loss of historic significance are included on this register. The identified risks and threats come from development pressure – for example, because they lie on urban fringes or are subject to development pressures within the site; arable cultivation, and unregulated metal-detecting. One major impact or a combination of several factors can be enough to raise the risk at a particular site.

Battlefields are removed from the register when either actual damaging activities are reversed or managed, or threats recede due to effective management planning.

PROTECTED WRECK SITES

Definition

England's 46 protected wreck sites represent a tiny proportion of the 32,476 pre-1945 wrecks and recorded casualties that are known to lie in the territorial sea. Wreck sites can be of importance for different reasons: the distinctive design or construction of a ship, the story it can tell about its past, its association with notable people or events, its cargo, flora and fauna or its role as a focus for the local community. The Protection of Wrecks Act 1973 empowers the appropriate Secretary of State to designate a restricted area around a vessel to protect it or its contents from unauthorised interference.

Local authorities are able to react to foreshore infrastructure projects through the planning process, thereby securing the preservation of important remains in this intertidal zone.

Criteria for inclusion on this register

English Heritage has audited all designated wreck sites to identify those most at risk based on their current condition, vulnerability and the way they are being managed.

Wrecks are vulnerable to both environmental and human impacts. Risks that contribute to the inclusion on the register range from unauthorised access to erosion and fishing damage.

What needs to be done to ensure that the significance of the sites is maintained is identified as part of the monitoring process. In spite of the inherent difficulties in caring for this type of site, careful management must be maintained.

Wrecks are removed from the register once an appropriate management and monitoring regime is operational.

CONSERVATION AREAS

Definition

Conservation areas are designated by local authorities and are areas of special architectural or historic interest the character or appearance of which it is desirable to preserve or enhance. For more than 40 years conservation areas have proved a highly effective mechanism for managing change on an area-wide basis. There are currently some 9,300 conservation areas in England including town and city centres, suburbs, industrial areas, rural landscapes, cemeteries and residential areas. They form the historic backcloth to national and local life and are a crucial component of local identity and community cohesion.

Criteria for inclusion on this register

English Heritage has asked every local authority in England to complete a survey of its conservation areas, highlighting current condition, threats and trends, identifying those that are expected to deteriorate, or are in very bad or poor condition and are not expected to change significantly in the next three years, being defined as at risk.

The methodology for assessing conservation areas at risk has been refined since the first survey in 2008/2009. The information collated this year provides a more detailed assessment of each conservation area and an overall category for condition, vulnerability and trend is included for each conservation area on this register. Conservation areas identified as 'at risk' last year, but not reassessed using the revised methodology, are included on the register but with more limited information.

Conservation areas are removed from the register once issues have been identified, plans put in place to address them and positive progress is being made.

Key to the entries

This register includes the following heritage assets at risk:

- grade I, II* and II listed buildings and structural scheduled monuments
- scheduled monuments
- registered parks and gardens
- registered battlefields (where applicable)
- protected wreck sites (where applicable)
- conservation areas

ORDER

Entries are grouped and ordered alphabetically first by county or unitary authority, and then by local planning authority (unitary authority/national park/district or borough).

Asset types are grouped within the relevant planning authority in the following order:

- listed buildings and structural scheduled monuments
- scheduled monuments
- registered parks and gardens
- registered battlefields
- protected wreck sites (listed at the end of the county or unitary authority off which they are located)
- conservation areas

Within each asset type, sites are ordered alphabetically by parish, locality, street and site name.

DESIGNATION

The principal designation is noted for each entry, and includes:

- Listed Building (LB) grade I, II* or II
- Scheduled Monument (SM)
- Registered Park and Garden (RPG) grade I, II* or II
- Registered Battlefield
- Protected Wreck Site
- Conservation Area (CA)

Other designations that apply to buildings at risk and registered parks and gardens at risk, including their location within a World Heritage Site (WHS), are also noted where applicable.

The monument number is noted for scheduled monuments.

CONDITION

For buildings at risk, condition is graded as: 'very bad', 'poor', 'fair' and 'good'.

For sites that cover areas (scheduled monuments, registered parks and gardens and protected wreck sites) one overall condition category is recorded. The category may relate only to the part of the site or monument that is at risk and not the whole site:

- extensive significant problems
- generally unsatisfactory with major localised problems
- generally satisfactory but with significant localised problems
- generally satisfactory but with minor localised problems
- optimal
- unknown (is noted for a number of scheduled monuments that are below-ground and where their condition cannot be established).

For conservation areas, condition is categorised as: 'very bad', 'poor', 'fair' and 'optimal'.

OCCUPANCY

For buildings that can be occupied or have a use, the main vulnerability is vacancy, or under-use.

Occupancy (or use) is noted as follows:

- vacant
- part occupied
- occupied
- unknown
- not applicable

VULNERABILITY

Principal vulnerability is noted for scheduled monuments and may relate only to the part of the monument which is at risk, and include:

- animal burrowing
- arable ploughing
- coastal erosion
- collapse
- deterioration – in need of management
- scrub / tree growth
- visitor erosion.

For registered parks and gardens, protected wreck sites and conservation areas, vulnerability is noted as high, medium or low.

PRIORITY

For buildings at risk, the following priority categories are used as an indication of trend and as a means of prioritising action:

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

If the priority category has changed since the 2009 register, the previous category is given in brackets.

TREND

Trend for scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites may relate only to the part of the site that is at risk and is categorised as:

- declining
- stable
- improving
- unknown

For conservation areas trend is categorised as:

- expected to deteriorate significantly
- expected to deteriorate
- deteriorating
- unknown
- no significant change expected
- expected to show some improvement

OWNERSHIP

A principal ownership category is given for each entry, although many scheduled monuments, registered parks and gardens, and registered battlefields are in divided ownership. For registered parks and gardens, single or multiple ownership is noted.

CONTACT

This is the member of the English Heritage regional team who acts as a first point of contact for the case, and to whom enquiries should be addressed.

For conservation areas, the contact is the conservation/planning officer at the relevant local planning authority (indicated by 'LA' on the register).

We are not in any sense agents for the owners of the sites included, but we will endeavour to put people in touch with them where appropriate.

ABBREVIATIONS

CA	Conservation Area
EH	English Heritage
HLF	Heritage Lottery Fund
LA/LPA	Local Planning Authority
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

BRACKNELL FOREST (UA)



SITE NAME:	Newbold College (formerly Moor Close), Binfield ‘
DESIGNATION:	Registered Park and Garden Grade II*, also 7 LBs
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Declining
OWNERSHIP:	Corporate, single owner

Moor Close estate, now the home of Newbold College, was Oliver Hill's first house and garden design in an early C20 Arts & Crafts style. The hard landscape features are deteriorating and in urgent need of renovation. A condition survey was completed with a grant from English Heritage but an ensuing application to the Heritage Lottery Fund was unsuccessful. Further resources and action are urgently needed. The garden and park setting is also threatened by a cluster housing development currently under consideration. Contact: Charlotte McLean 01483 252043



SITE NAME:	Broadmoor Hospital, Crowthorne ‘
DESIGNATION:	Registered Park and Garden Grade II, also 1 LB
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Declining
OWNERSHIP:	Corporate, single owner

A mid C19 asylum, built for the criminally insane to designs by Joshua Jebb. The site is undergoing major redevelopment. The secure psychiatric hospital is to be relocated and the main building converted to an hotel. The extensive walled garden is to be developed for housing. The ornamented farmland has survived but needs managing. Close liaison with the owner and local authority is necessary to ensure what remains in terms of historic significance can be salvaged. Contact: Charlotte McLean 01483 252043

BRIGHTON AND HOVE, CITY OF (UA)



SITE NAME:	The West Pier, Kings Road, Brighton
DESIGNATION:	Listed Building Grade I, CA
CONDITION:	Very bad
OCCUPANCY:	Not applicable
PRIORITY:	A (A)
OWNERSHIP:	Trust

Pier, 1864-66 by Eugenius Birch. Closed in 1975. English Heritage has declared its view that the combination of significant recent damage and cost of repair make restoration from public funds uneconomic. Contact: Tom Foxall 01483 252035



SITE NAME:	14 Montpelier Crescent, Brighton
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	C (New)
OWNERSHIP:	Private

Terraced house (1843-47) with three storeys over a basement. Last in use as a house in multiple occupation. Roof not watertight, ceilings damaged by water ingress and no long-term solution agreed. Contact: Tom Foxall 01483 252035



SITE NAME:	Marlborough House, 54 Old Steine, Brighton and Hove, Brighton
DESIGNATION:	Listed Building Grade I, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied
PRIORITY:	C (C)
OWNERSHIP:	Private

House, now office. Built 1765, remodelled in 1786 by Robert Adam. Not structurally sound, secure or weathertight. Contact: Tom Foxall 01483 252035



SITE NAME:	The stables at Stanmer House, Stanmer Park, Brighton
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied
PRIORITY:	D (D)
OWNERSHIP:	Private

Stables probably C18. Much altered and largely empty for some years. Contact: Tom Foxall 01483 252035

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME: **53 Brunswick Square, Hove**

DESIGNATION: Listed Building Grade I, CA

CONDITION: Poor

OCCUPANCY: Part occupied

PRIORITY: C (New)

OWNERSHIP: Private

Terraced house by A Wids and CA Busby, 1825-27. Used for multiple occupancy but now largely vacant. The rear elevation and outbuildings are in poor condition and parts of the building are not habitable. Made temporarily weathertight but no long-term solution in place.'

Contact: Tom Foxall 01483 252035



SITE NAME: **Mews building to the rear of No. 14, 14 Brunswick Square, East Sussex, Hove**

DESIGNATION: Listed Building Grade I, CA

CONDITION: Poor

OCCUPANCY: Part occupied

PRIORITY: F (B)

OWNERSHIP: Private

Terraced house, 1825-7. Mews to the rear of 14 Brunswick Square circa 1825. Repair works underway, but not complete.

Contact: Tom Foxall 01483 252035

SITE NAME:

Earthworks and lynchets near Eastwick Barn, Patcham, Brighton and Hove

DESIGNATION:

Scheduled Monument (No. BH10)

CONDITION:

Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY:

Arable ploughing

TREND:

Declining

OWNERSHIP:

Local Authority

CONTACT:

Paul Roberts 01483 252032

BRIGHTON AND HOVE, CITY OF (UA) / LEWES



SITE NAME: **Stanmer Park, Stanmer**

DESIGNATION: Registered Park and Garden Grade II, also part in CA, 19 LBs, 3 SMs

CONDITION: Extensive significant problems

VULNERABILITY: High

TREND: Stable

OWNERSHIP: Mixed, multiple owners

C18 estate village set in a landscape park with informal pleasure grounds. Brighton Borough bought it in 1947 as a public amenity but the park was left to decline. There are multiple ownership issues and implementation of the landscape restoration management plan (2003) progresses as opportunities arise. A road widening scheme is about to slice through the southern boundary wall, however; a recent recommendation to extend the Conservation Area should increase protection for the park and garden in the future.

Contact: Charlotte McLean 01483 252043

BRIGHTON AND HOVE, CITY OF (UA)

SITE NAME:

Benfield Barn

DESIGNATION:

Conservation Area

CONDITION:

Very bad

VULNERABILITY:

Low

TREND:

Expected to deteriorate

CONTACT:

Tim Jefferies (LA) 01273 293152

SITE NAME:

East Cliff

DESIGNATION:

Conservation Area

CONDITION:

Poor

VULNERABILITY:

Low

TREND:

Expected to deteriorate

CONTACT:

Tim Jefferies (LA) 01273 293152

SITE NAME:

Queen's Park

DESIGNATION:

Conservation Area

CONDITION:

Poor

VULNERABILITY:

Medium

TREND:

Expected to deteriorate

CONTACT:

Tim Jefferies (LA) 01273 293152

SITE NAME:

Sackville Gardens

DESIGNATION:

Conservation Area

CONDITION:

Very bad

VULNERABILITY:

Low

TREND:

Expected to deteriorate

CONTACT:

Tim Jefferies (LA) 01273 293152

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Stanmer		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Expected to deteriorate
CONTACT:	Tim Jefferies (LA) 01273 293152		

SITE NAME:	Valley Gardens		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Expected to deteriorate
CONTACT:	Tim Jefferies (LA) 01273 293152		

BUCKINGHAMSHIRE

AYLESBURY VALE



SITE NAME: **Barn at New Manor Farm, Broughton Lane, Berton with Broughton**

DESIGNATION: Listed Building Grade II*
 CONDITION: Very bad
 OCCUPANCY: Vacant
 PRIORITY: A (C)
 OWNERSHIP: Private

Barn, late C12 and later. Propped with scaffolding and with a temporary roof covering. Urgent works have been carried out. Slow decay: no solution; up-rated to immediate risk of deterioration or loss. 'A historic building analysis has been carried out with English Heritage grant aid.

Contact: Richard Peats 01483 252026



SITE NAME: **Ashfold School (Dorton House), Dorton**

DESIGNATION: Listed Building Grade I
 CONDITION: Poor
 OCCUPANCY: Occupied
 PRIORITY: C (C)
 OWNERSHIP: Private

Early C17, dated 1626 on staircase soffit, altered 1784. Contains extremely elaborate C17 plaster ceilings in several rooms and under staircase soffits. The building has been occupied for many years as a school. The roofs, stonework and the condition of the lintels all give cause for concern. The fine plaster ceilings are vulnerable to water damage and this is already occurring.

Contact: Richard Peats 01483 252026



SITE NAME: **Mentmore Towers, Mentmore**

DESIGNATION: Listed Building Grade I, RPG II*
 CONDITION: Poor
 OCCUPANCY: Vacant
 PRIORITY: A (A)
 OWNERSHIP: Company

Building vacant for a number of years. Listed building consent and planning permission granted for conversion to a hotel together with a major extension. Planning for the implementation of these consents has stopped 2009. 'Emergency works undertaken to central roof lantern, works in hand to make these permanent and renew tower roofs. The service wing roof remains in very poor condition.

Contact: Richard Peats 01483 252026



SITE NAME: **New Inn Farmhouse with outbuildings behind, Stowe**

DESIGNATION: Listed Building Grade II*, CA
 CONDITION: Very bad
 OCCUPANCY: Vacant
 PRIORITY: F (F)
 OWNERSHIP: Trust

Former coaching inn, now farmhouse, 1717-19 and later. Built for visitors to Stowe House and garden. Acquired by the National Trust. Urgent work carried out but building still precarious. Works in progress on repair, conversion and new building for visitor centre.

Contact: Richard Peats 01483 252026



SITE NAME: **Grotto, Stowe Landscape Garden, Stowe**

DESIGNATION: Listed Building Grade II*, CA
 CONDITION: Fair
 OCCUPANCY: Not applicable
 PRIORITY: F (D)
 OWNERSHIP: Trust

Grotto, 1739, altered extensively mid C18. Situated at the northern end of the Elysian Fields, views to the south over Elysian Fields and serpentine rivers. Some work done on flanking tunnels, security gates installed, but water ingress through the roof. Pleasure grounds are in process of restoration. Conservation cleaning and stabilisation has taken place. Restoration work in progress March 2010.

Contact: Richard Peats 01483 252026

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.
 E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
 If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	Stowe House, Stowe Landscape Garden, Stowe
DESIGNATION:	Listed Building Grade I, CA
CONDITION:	Good
OCCUPANCY:	Occupied
PRIORITY:	F (F)
OWNERSHIP:	Private

Country house, 1680, situated in extensive and immensely influential C17 to C19 pleasure grounds and landscaped park of circa 500 hectares. Extensive repairs have been carried out on the house but further work is needed. Repair of north colonnades, north portico and roof complete. Repair works to library roof in progress.

Contact: Richard Peats 01483 252026



SITE NAME:	Temple of Friendship, Stowe Landscape Garden, Stowe
DESIGNATION:	Listed Building Grade I, CA
CONDITION:	Very bad
OCCUPANCY:	Not applicable
PRIORITY:	C (D)
OWNERSHIP:	Trust

Garden temple, 1739, situated in the south-east corner of the pleasure gardens, close to the Palladian Bridge and with views to the north over the lake and Hawkwell Field beyond. The Tuscan portico has been consolidated and has a new roof, however the cellar and two flanking loggias remain roofless. The pleasure grounds are in the process of restoration.

Contact: Richard Peats 01483 252026



SITE NAME:	The Boycott Pavilions, Stowe Landscape Garden, Stowe
DESIGNATION:	Listed Building Grade I, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied
PRIORITY:	C (D)
OWNERSHIP:	Trust

One of pair of large stone pavilions, circa 1728, by James Gibbs, incorporating domestic accommodation. Situated on one side of the Oxford Avenue, at the south-west of The Course which is the main approach to the house. Work is needed to masonry. Work also needed to lead roof covering and cupola needs reinstating at east pavilion. The pleasure grounds are in the process of restoration.

Contact: Richard Peats 01483 252026



SITE NAME:	The Palladian Bridge, Stowe Landscape Garden, Stowe
DESIGNATION:	Listed Building Grade I, CA
CONDITION:	Fair
OCCUPANCY:	Not applicable
PRIORITY:	D (D)
OWNERSHIP:	Trust

Covered bridge built in 1738; attributed to James Gibbs, situated in the south-east corner of the pleasure grounds. Bridge is viewed from the west across the Octagon Lake, and from the north-west and north across Hawkwell Fields. Steady decay of the roof covering, ceiling plaster and masonry. Holding repairs have been carried out, but more work needed. Pleasure grounds are in the process of restoration.

Contact: Kathryn Davies 01483 252028



SITE NAME:	The Queens Temple, Stowe Landscape Garden, Stowe
DESIGNATION:	Listed Building Grade I, CA
CONDITION:	Fair
OCCUPANCY:	Occupied
PRIORITY:	F (F)
OWNERSHIP:	Trust

Pavilion of 1740, attributed to James Gibbs, remodelled 1770. Sited c300m to east of house in pleasure grounds. Main views from the temple to the south, over fields to the Gothic temple, Palladian Bridge and Temple of Friendship. Overflow detection recently installed in roof, including a new chute. Masonry repairs done. Works to interior and roofs to be done. Structural monitoring of portico being carried out.

Contact: Richard Peats 01483 252026

SITE NAME: **A small multivallate hillfort on Southend Hill, Cheddington**

DESIGNATION:	Scheduled Monument (No. 29410)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME: **A slight univallate hillfort 600m south east of Home Farm, Maids Moreton**

DESIGNATION:	Scheduled Monument (No. 29420)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	Halton House, Halton / Aston Clinton
DESIGNATION:	Registered Park and Garden Grade II, also part in CA, 5 LBs
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Stable
OWNERSHIP:	Corporate, single owner

A Rothschild country house with late C19 formal gardens and park with woodland rides. The estate was sold to the RAF in 1918 and Halton House is now the Officers' Mess. The Forestry Commission manage the woodland rides. Some of the ornamental features of the garden are in poor condition, however; work to restore the pavilion in the Italian garden has begun. A landscape Conservation Management Plan is in draft form and will be used for assessing options for a proposed accommodation block.

Contact: Charlotte McLean 01483 252043

BUCKINGHAMSHIRE / HERTFORDSHIRE



SITE NAME:	Mentmore Towers, Mentmore / Tring Rural / Cheddington
DESIGNATION:	Registered Park and Garden Grade II*, also CA, 10 LBs
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Stable
OWNERSHIP:	Mixed, multiple owners

Sir Joseph Paxton designed both the house, and the park and gardens. The house and gardens were sold in 2000 and permission granted in 2005 to convert to an hotel. The adjacent golf course was recently bought by the developer thus reuniting most of the site. The permission has not yet been implemented. The current intention is to begin works to the house in the near future. Hopefully the conditioned landscape works will follow however at the moment Mentmore's future is still uncertain.

Contact: Charlotte McLean 01483 252043

BUCKINGHAMSHIRE CHILTERN

SITE NAME:	Old Town and town centre Chesham	
DESIGNATION:	Conservation Area	CONDITION: At risk
VULNERABILITY:	Unknown	TREND: Deteriorating
CONTACT:	Planning Department (LA) 01494 732950	

SOUTH BUCKS



SITE NAME:	Aviary at Dropmore House, Heathfield Road, Taplow
DESIGNATION:	Listed Building Grade I, RPG II
CONDITION:	Very bad
OCCUPANCY:	Not applicable
PRIORITY:	B (B)
OWNERSHIP:	Private

Aviary, early C19, situated on south side of the range of buildings to west of the house. Vandalised and neglected for some years. Situated within late C18 to early C19 gardens in a ruinous condition. The woodland to the north and west in a poor condition. The park to south and east is in good condition. Mansion has been repaired and converted to residential use. LBC granted for repair of aviary – not started.

Contact: Richard Peats 01483 252026

SITE NAME:	Burnham	
DESIGNATION:	Conservation Area	CONDITION: At risk
VULNERABILITY:	Unknown	TREND: Deteriorating
CONTACT:	Conservation & Design Team (LA) 01895 837374	

SITE NAME:	Gerrards Cross Common	
DESIGNATION:	Conservation Area	CONDITION: At risk
VULNERABILITY:	Unknown	TREND: Deteriorating
CONTACT:	Conservation & Design Team (LA) 01895 837374	

SITE NAME:	Iver	
DESIGNATION:	Conservation Area	CONDITION: At risk
VULNERABILITY:	Unknown	TREND: Deteriorating
CONTACT:	Conservation & Design Team (LA) 01895 837374	

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Stoke Green		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Conservation & Design Team (LA) 01895 837375		

SITE NAME:	Taplow Riverside		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Conservation & Design Team (LA) 01895 837376		

SITE NAME:	Uxbridge Lock		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Conservation & Design Team (LA) 01895 837377		

WYCOMBE

SITE NAME:	Bell barrow 260m WNW of Slough Glebe Farm, part of the Saunderton Lee barrow cemetery, Bledlow cum Saunderton		
DESIGNATION:	Scheduled Monument (No. 27120)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Bledlow Cross, Bledlow cum Saunderton		
DESIGNATION:	Scheduled Monument (No. BU2)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Bowl barrow 140m WNW of Slough Glebe Farm, part of the Saunderton Lee round barrow cemetery, Bledlow cum Saunderton		
DESIGNATION:	Scheduled Monument (No. 27121)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Roman villa east of Lodge Hill Farm, Bledlow cum Saunderton		
DESIGNATION:	Scheduled Monument (No. 27149)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Two bowl barrows 450m north west of Slough Glebe Farm, part of the Saunderton Lee barrow cemetery, Bledlow cum Saunderton		
DESIGNATION:	Scheduled Monument (No. 27119)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Roman villa north of Yewden Lodge, Hambleden		
DESIGNATION:	Scheduled Monument (No. 27160)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

BUCKINGHAMSHIRE / OXFORDSHIRE

WYCOMBE / SOUTH OXFORDSHIRE / WOKINGHAM (UA)



SITE NAME:	Fawley Court and Temple Island, Fawley / Henley-on-Thames / Remenham
DESIGNATION:	Registered Park and Garden Grade II*, also CA, 18 LBs
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	High
TREND:	Declining
OWNERSHIP:	Private, multiple owners

Early C18 garden and pleasure grounds surrounding a 1680s house set within a park landscaped by Lancelot Brown. Most of the estate and park are in separate ownership. Discussions with the new owner of the house and pleasure grounds are underway. English Heritage agreed to works to improve the vegetation structure within the gardens but requested a landscape Conservation Management Plan that engages with the other key owners, before agreeing to any further major works. A joined up approach to management is essential.

Contact: Charlotte McLean 01483 252043

EAST SUSSEX

EASTBOURNE



SITE NAME:	Eastbourne Redoubt, Eastbourne
DESIGNATION:	Listed Building Grade II, SM, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied
PRIORITY:	C (C)
OWNERSHIP:	Local authority

A redoubt built as part of the Martello system, 1806. Main parts are in use as a museum. The aquarium building, which occupies casemates and the mast on the south west side, is in very poor condition. The surviving caponieres suffer from water ingress. Moat walls are decaying.

Contact: Paul Roberts 01483 252032



SITE NAME:	Martello Tower No. 64, Eastbourne
DESIGNATION:	Listed Building Grade II, SM
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	C (C)
OWNERSHIP:	Company

Martello tower, 1806. On the beach with a housing development nearby. The preservation of archaeological and historical significance will be the main consideration in assessing the suitability of proposals to convert Martello towers for residential use.

Contact: Paul Roberts 01483 252032



SITE NAME:	Martello Tower No. 66, Langney Point, Eastbourne
DESIGNATION:	Listed Building Grade II, SM
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	C (C)
OWNERSHIP:	Company

Martello tower, 1806. On the beach near the harbour entrance. The preservation of archaeological and historical significance will be the main consideration in assessing the suitability of proposals to convert Martello towers for residential use.

Contact: Paul Roberts 01483 252032

HASTINGS



SITE NAME:	Statue of Queen Anne south east of Holmhurst St Mary's School, The Ridge, Baldslow, Hastings
DESIGNATION:	Listed Building Grade II*
CONDITION:	Very bad
OCCUPANCY:	Not applicable
PRIORITY:	A (C)
OWNERSHIP:	Trust

Statue, 1711-12 in grounds of former convent (now sold separately). The statue is not being maintained and deteriorating more rapidly through rainwater off overhanging trees and saline rain off the sea.'

Contact: Tom Foxall 01483 252035

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME: **Remains of Manor House, Ore Place, Ore, Hastings**

Ruins of late medieval manor house surrounded by new housing development, close to Old St. Helens Church.

DESIGNATION: Scheduled Monument

CONDITION: Poor

OCCUPANCY: Not applicable

PRIORITY: D (D)

OWNERSHIP: Local authority

Contact: Paul Roberts 01483 252032



SITE NAME: **Church of St Helen, Elphinstone Road, St Helens, Hastings**

Ruined church with associated manor. English Heritage grant given in past for repair of the tower. English Heritage funded a feasibility study, which has resulted in an application to Heritage Lottery Fund for a conservation, learning and access project.

DESIGNATION: Listed Building Grade II, SM

CONDITION: Very bad

OCCUPANCY: Not applicable

PRIORITY: D (C)

OWNERSHIP: Trust

Contact: Paul Roberts 01483 252032

LEWES



SITE NAME: **Lewes Priory Ruins, Cockshut Road, Lewes**

Cluniac Priory founded after 1077. Much of the ruin is in the care of a Trust and open to the public, but the ruins are fenced off because of a risk to public safety. Applications for grant funding to English Heritage and Heritage Lottery Fund were granted and a project to conserve the ruins and improve access and interpretation is being developed. "Work expected to start in 2010.

DESIGNATION: Listed Building Grade I, SM, CA

CONDITION: Poor

OCCUPANCY: Not applicable

PRIORITY: F (D)

OWNERSHIP: Local authority

Contact: Paul Roberts 01483 252032



SITE NAME: **Newhaven Fort; Caponier, Fort Road, Newhaven**

Caponier of Newhaven Fort. Victorian caponier is in poor condition in places, but conservation is proposed by owners. Lunette battery was repaired with English Heritage grant by Lewes District Council in 2009.

DESIGNATION: Scheduled Monument

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: F (F)

OWNERSHIP: Local authority

Contact: Paul Roberts 01483 252032

SITE NAME:

Anglo-Saxon cemetery 275m north of Comps Farm, Beddingham

DESIGNATION: Scheduled Monument (No. 28891)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Metal detecting

TREND: Declining

OWNERSHIP: Private

CONTACT: Paul Roberts 01483 252032

SITE NAME:

Fore Hill round barrow, Beddingham

DESIGNATION: Scheduled Monument (No. ES269)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Paul Roberts 01483 252032

SITE NAME:

Round barrow south of Ditchling Beacon, Ditchling

DESIGNATION: Scheduled Monument (No. ES285)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Paul Roberts 01483 252032

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA Conservation Area
LB/LBs Listed Building/s
NP National Park
RPG Registered Park and Garden
SM/SMs Scheduled Monument/s
UA Unitary Authority
WHS World Heritage Site

SITE NAME: Bowl barrow on Front Hill, Iford			
DESIGNATION:	Scheduled Monument (No. 25483)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Paul Roberts 01483 252032

SITE NAME: Multiple ring-ditch at Mount Pleasant, Denton, Newhaven			
DESIGNATION:	Scheduled Monument (No. 12800)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Paul Roberts 01483 252032

SITE NAME: Bowl barrow forming part of a linear round barrow cemetery on Rookery Hill, Seaford			
DESIGNATION:	Scheduled Monument (No. 25486)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Paul Roberts 01483 252032

SITE NAME: Two bowl barrows, the south easternmost pair of a group of six bowl barrows, forming part of a linear round barrow cemetery on Rookery Hill, Seaford			
DESIGNATION:	Scheduled Monument (No. 25484)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Paul Roberts 01483 252032

SITE NAME: Seaford Town Centre, Seaford			
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Expected to deteriorate
CONTACT:	Chris Morris (LA) 01273 471600		

ROTHER



SITE NAME: **Martello Tower No. 55, Normans Bay, Bexhill**

DESIGNATION: Listed Building Grade II, SM

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: F (D)

OWNERSHIP: Private

Martello tower built 1806. The preservation of archaeological and historical significance will be the main consideration in assessing the suitability of proposals to convert Martello towers for residential use.

Contact: Paul Roberts 01483 252032



SITE NAME: **Martello Tower No. 28, Rye Harbour, Icklesham**

DESIGNATION: Listed Building Grade II, SM

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNERSHIP: Private

A derelict martello tower built 1806. Situated on the edge of a caravan park. The preservation of archaeological and historical significance will be the main consideration in assessing the suitability of proposals to convert Martello towers for residential use.

Contact: Paul Roberts 01483 252032

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME: **Grey Friars (Winchelsea Priory), Friars Road, Winchelsea, Icklesham**

Ruins of a monastic church circa 1310-20, in the grounds of a C19 mansion.

DESIGNATION: Listed Building Grade I, SM, CA

CONDITION: Poor

OCCUPANCY: Not applicable

PRIORITY: D (D)

OWNERSHIP: Private

Contact: Paul Roberts 01483 252032



SITE NAME: **Grey Friars boundary wall, Friars Road, Winchelsea, Icklesham**

The C19 boundary wall to the Grey Friars mansion has suffered from multiple collapses and further collapses are likely.

DESIGNATION: Scheduled Monument, CA

CONDITION: Very bad

OCCUPANCY: Not applicable

PRIORITY: B (B)

OWNERSHIP: Private

Contact: Paul Roberts 01483 252032



SITE NAME: **Austin Friars Chapel, Conduit Hill, Rye**

Remains of a friary chapel dating from about 1380. Vacant at present, but a new use is being sought. The window tracery is suffering from decay.

DESIGNATION: Listed Building Grade II, SM, CA

CONDITION: Poor

OCCUPANCY: Occupied

PRIORITY: C (C)

OWNERSHIP: Private

Contact: Paul Roberts 01483 252032



SITE NAME: **Martello Tower No. 30, Winchelsea Road, Rye**

Martello tower built 1806. Now nearly derelict and the moat and glacis on the east side lost. Unconnected with destruction of the moat and glacis, a small housing development was built adjacent to the east. The preservation of archaeological and historical significance will be the main consideration in assessing the suitability of proposals to convert Martello towers for residential use.'

DESIGNATION: Listed Building Grade II, SM

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNERSHIP: Private

Contact: Paul Roberts 01483 252032

SITE NAME:

Romano-British iron working site in Beauport Park, Battle

DESIGNATION:

Scheduled Monument (No. ES383)

CONDITION:

Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY:

Deterioration – in need of management

TREND:

Declining

OWNERSHIP:

Private

CONTACT:

Paul Roberts 01483 252032

WEALDEN



SITE NAME: **Argos Hill Windmill, Argos Hill, Mayfield**

Post mill suffering from lack of maintenance and scaffolded.

DESIGNATION: Listed Building Grade II*

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: D (D)

OWNERSHIP: Local authority

Contact: Tom Foxall 01483 252035

SITE NAME:

A barrow field, a bowl barrow and a dewpond on Bostal Hill, Alciston

DESIGNATION:

Scheduled Monument (No. 27042)

CONDITION:

Generally satisfactory
but with significant localised problems

PRINCIPAL VULNERABILITY:

Metal detecting

TREND:

Declining

OWNERSHIP:

Private

CONTACT:

Paul Roberts 01483 252032

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA Conservation Area
 LB/LBs Listed Building/s
 NP National Park
 RPG Registered Park and Garden
 SM/SMs Scheduled Monument/s
 UA Unitary Authority
 WHS World Heritage Site

SITE NAME: Bowl barrow 545m east of Jerry's Pond, forming part of a round barrow cemetery south east of Bostal Hill, Alciston	
DESIGNATION: Scheduled Monument (No. 27045)	CONDITION: Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY: Metal detecting	TREND: Declining
OWNERSHIP: Private	CONTACT: Paul Roberts 01483 252032

SITE NAME: Round barrow south west of Bopeep Bostal, Alciston	
DESIGNATION: Scheduled Monument (No. ES275)	CONDITION: Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY: Metal detecting	TREND: Declining
OWNERSHIP: Private	CONTACT: Paul Roberts 01483 252032

SITE NAME: Two groups of round barrows south east of Firlle Beacon, Alciston	
DESIGNATION: Scheduled Monument (No. ES273)	CONDITION: Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY: Metal detecting	TREND: Declining
OWNERSHIP: Private	CONTACT: Paul Roberts 01483 252032

SITE NAME: Far Blacklands iron bloomery, Forest Row	
DESIGNATION: Scheduled Monument (No. ES403)	CONDITION: Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY: Arable ploughing	TREND: Declining
OWNERSHIP: Private	CONTACT: Paul Roberts 01483 252032

SITE NAME: High Rocks Camp, Frant (part in Kent)	
DESIGNATION: Scheduled Monument (No. ES196)	CONDITION: Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY: Arable ploughing	TREND: Declining
OWNERSHIP: Private	CONTACT: Paul Roberts 01483 252032



SITE NAME: Kidbrooke Park, Forest Row
DESIGNATION: Registered Park and Garden Grade II, also 2 LBs
CONDITION: Extensive significant problems
VULNERABILITY: Medium
TREND: Declining
OWNERSHIP: Mixed, multiple owners

C18 park with extensive C19 landscape features attributed to Humphry Repton and later formal and woodland gardens. The estate was sold in 1938 then further subdivided. The house became a Steiner school which has since sold perimeter land for development and built school facilities in the grounds. It is vulnerable to development. The Environment Agency is currently investigating the possibility of using the lower lake as a flood storage facility which has highlighted the need for an up-to-date Conservation Management Plan. Contact: Charlotte McLean 01483 252043

HAMPSHIRE

BASINGSTOKE AND DEANE



SITE NAME: Barn at Manor Farm, Old Burghclere, Burghclere
DESIGNATION: Listed Building Grade I
CONDITION: Poor
OCCUPANCY: Not applicable
PRIORITY: C (C)
OWNERSHIP: Private

Manorial barn, 1451, built for the Bishop of Winchester. Suffering from water ingress and failure of joints, the building needs comprehensive repair. Emergency repairs have been carried out. Contact: David Brock 01483 252044

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
 If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME: **London Lodge,
Highclere Park,
Highclere**

Ceremonial archway and attached accommodation, 1793.
Only emergency repairs have been carried out and negotiations continue to allow it to be occupied.

DESIGNATION: Listed Building Grade II*

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNERSHIP: Private

Contact: David Brock 01483 252044

SITE NAME:

A cross dyke and bowl barrow on the northern spur of Beacon Hill, Burghclere

DESIGNATION: Scheduled Monument (No. 25611)

CONDITION: Generally unsatisfactory
with major localised problems

PRINCIPAL VULNERABILITY: Extensive animal burrowing

TREND: Declining

OWNERSHIP: Private

CONTACT: Richard Massey 01483 252046

SITE NAME:

Long barrow 600m south of Preston Grange, Candovers

DESIGNATION: Scheduled Monument (No. 12106)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Richard Massey 01483 252046

SITE NAME:

**A bell barrow and a saucer barrow 315m ESE of the unfinished hillfort on Ladle Hill,
Echinswell and Sydmonton**

DESIGNATION: Scheduled Monument (No. 25613)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Richard Massey 01483 252046

SITE NAME:

**The western of two rectangular enclosures on Great Litchfield Down,
SSW of Ladle Hill, Litchfield and Woodcott**

DESIGNATION: Scheduled Monument (No. 25615)

CONDITION: Generally unsatisfactory
with major localised problems

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Richard Massey 01483 252046

SITE NAME:

Long barrow 250m south east of Willesley Warren Farm, Overton

DESIGNATION: Scheduled Monument (No. 12108)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Richard Massey 01483 252046

SITE NAME:

Round barrow south west of Lower Farm, Preston Candover

DESIGNATION: Scheduled Monument (No. HA322)

CONDITION: Generally unsatisfactory
with major localised problems

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Richard Massey 01483 252046

EAST HAMPSHIRE

SITE NAME:

Bowl barrow on Chalton Down, 350m south east of Manor Farm, Clanfield

DESIGNATION: Scheduled Monument (No. 34155)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Richard Massey 01483 252046

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHs	World Heritage Site

SITE NAME: Bowl barrow 620m north east of Warhill Cottage, East Meon			
DESIGNATION:	Scheduled Monument (No. 32558)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME: Group of four bowl barrows 660m north of Warhill Cottage, East Meon			
DESIGNATION:	Scheduled Monument (No. 32557)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME: Bowl barrow 60m south east of the junction of the A32 and Fawley Lane, part of The Jumps round barrow cemetery, Froxfield			
DESIGNATION:	Scheduled Monument (No. 32556)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME: Bowl barrow 100m south east of Lower Bordean Farm, Langrish			
DESIGNATION:	Scheduled Monument (No. 30260)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME: Three bowl barrows on Chalton Down, 860m east of Netherley Farm, Rowlands Castle			
DESIGNATION:	Scheduled Monument (No. 34156)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME: Bowl barrow 250m west of the junction of the A32 and Fawley Lane, part of The Jumps round barrow cemetery, West Tisted			
DESIGNATION:	Scheduled Monument (No. 32554)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME: Bowl barrow 330m south west of the junction of the A32 and Fawley Lane, part of The Jumps round barrow cemetery, West Tisted			
DESIGNATION:	Scheduled Monument (No. 32555)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME: Round barrow cemetery, Roman road and hollow ways 200m south west of Woolmer Cottages, Whitehill			
DESIGNATION:	Scheduled Monument (No. 34144)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Three disc barrows on Longmoor Common, 250m north west of the church, Whitehill		
DESIGNATION:	Scheduled Monument (No. 30280)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Walldown enclosures, Whitehill		
DESIGNATION:	Scheduled Monument (No. 30287)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Richard Massey 01483 252046

FAREHAM



SITE NAME:	Fort Fareham, Newgate Lane, Fareham	Mid C19 fort forming part of a series of fortifications built to defend Portsmouth Harbour. Unoccupied parts suffering from decay and vandalism. Site now owned by various private companies.
DESIGNATION:	Listed Building Grade II, SM	
CONDITION:	Poor	
OCCUPANCY:	Part occupied	
PRIORITY:	A (A)	
OWNERSHIP:	Company	Contact: Richard Massey 01483 252046



SITE NAME:	Barn at Fernhill Farm, Mill Lane, Titchfield, Fareham	Tithe barn, probably C15, formally part of Titchfield Abbey. Has been damaged by casual vandalism and needs repair and a new use.
DESIGNATION:	Listed Building Grade I, SM, CA	
CONDITION:	Fair	
OCCUPANCY:	Vacant	
PRIORITY:	C (C)	
OWNERSHIP:	Unknown	Contact: Richard Massey 01483 252046



SITE NAME:	Titchfield Abbey and fishponds – stables, Mill Street, Titchfield, Fareham	Stables to Titchfield Abbey. The Abbey was founded in 1232 and converted to a private residence in 1537. The stables are overgrown with vegetation and have some structural problems. Investigations leading to a repair programme are underway.
DESIGNATION:	Scheduled Monument, CA	
CONDITION:	Fair	
OCCUPANCY:	Not applicable	
PRIORITY:	D (D)	
OWNERSHIP:	Private	Contact: Richard Massey 01483 252046

SITE NAME:	Titchfield Abbey		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Mike Maude-Roxby (LA) 01329 236100		

GOSPORT



SITE NAME:	Fort Elson, RNAD, Military Road, Gosport	Polygonal artillery fort of 1853-60. Damaging vegetation has taken hold of the site. Programmes of vegetation removal are intermittent. A management plan has been drafted but not agreed or implemented. The building cannot be occupied because it lies within a munitions storage area.
DESIGNATION:	Scheduled Monument	
CONDITION:	Poor	
OCCUPANCY:	Vacant	
PRIORITY:	A (C)	
OWNERSHIP:	Government	Contact: Alan Johnson 020 7973 3174

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

	<p>SITE NAME: Fortifications north of Mumby Road, Mumby Road, Gosport</p> <p>DESIGNATION: Scheduled Monument, CA</p> <p>CONDITION: Fair</p> <p>OCCUPANCY: Not applicable</p> <p>PRIORITY: C (C)</p> <p>OWNERSHIP: Government</p>	<p>A 600 metre length of the western fortifications of Gosport, now cut off from the adjacent barracks site. The site is a fuel store, and so was excluded from the redevelopment scheme at the barracks.</p> <p>Contact: Rory O'Donnell 020 7973 3775</p>
	<p>SITE NAME: Railway Station Old Terminal, Spring Garden Lane, Gosport</p> <p>DESIGNATION: Listed Building Grade II*, CA</p> <p>CONDITION: Good</p> <p>OCCUPANCY: Vacant</p> <p>PRIORITY: F (D)</p> <p>OWNERSHIP: Housing Association</p>	<p>Railway station circa 1842, by Sir William Tite, for the London and South Western Railway Company. Damaged by bombing. Stable but unexploited ruin, now with consent for a housing scheme, on which works should start shortly.</p> <p>Contact: David Brock 01483 252044</p>
	<p>SITE NAME: Gilkicker Fort, Fort Road, Gilkicker Point, Gosport</p> <p>DESIGNATION: Listed Building Grade II*, SM</p> <p>CONDITION: Poor</p> <p>OCCUPANCY: Vacant</p> <p>PRIORITY: D (D)</p> <p>OWNERSHIP: Local authority</p>	<p>Artillery fort 1865-71. Owner has put barrack block into good order; but casemates and magazines are threatened by water penetration. Repair and conversion to residential development being considered.</p> <p>Contact: Richard Massey 01483 252046</p>
	<p>SITE NAME: Workshops, boilerhouse and engine room, Haslar Gunboat Yard, HMS Dolphin, Gosport</p> <p>DESIGNATION: Scheduled Monument, CA</p> <p>CONDITION: Poor</p> <p>OCCUPANCY: Vacant</p> <p>PRIORITY: A (A)</p> <p>OWNERSHIP: Company</p>	<p>Workshop, boiler house and offices, mid C19, cause concern. The buildings are already in a poor state of repair and are deteriorating. Parts are no longer stable (including sections of the workshops roof). There is no current use.</p> <p>Contact: Richard Massey 01483 252046</p>
	<p>SITE NAME: Guardrooms to Haslar Gunboat Yard, Haslar Road, HMS Dolphin, Dolphin 3, Gosport</p> <p>DESIGNATION: Scheduled Monument, CA</p> <p>CONDITION: Poor</p> <p>OCCUPANCY: Vacant</p> <p>PRIORITY: C (C)</p> <p>OWNERSHIP: Government</p>	<p>The buildings have been unoccupied for many years and are derelict. In 1999 basic repairs were carried out to make the buildings weathertight but there has been no progress since then. An options study has been undertaken.</p> <p>Contact: Alan Johnson 020 7973 3174</p>
HART		
	<p>SITE NAME: Garden walls and associated structures, Bramshill House, Bramshill</p> <p>DESIGNATION: Listed Building Grade I, RPG II*</p> <p>CONDITION: Fair</p> <p>OCCUPANCY: Not applicable</p> <p>PRIORITY: E (D)</p> <p>OWNERSHIP: Government</p>	<p>Walls to early C17 and C18 formal walled gardens, surrounding the house, which is situated within a park of medieval origin, landscaped in the C17, C18 and C19. Some sections of the walls are in a poor condition and a section of the wall to west of the house collapsed in 2003. A scheme for repair is in preparation for all the walls.</p> <p>Contact: Elizabeth Moore 020 7973 3803</p>

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	High Bridge, Bramshill House, Bramshill
DESIGNATION:	Listed Building Grade I, RPG II*
CONDITION:	Poor
OCCUPANCY:	Not applicable
PRIORITY:	D (D)
OWNERSHIP:	Government

The bridge is in poor condition, requiring repairs to structure and fabric. Some repairs were carried out in 2000-03 but further works are required.

Contact: Elizabeth Moore 020 7973 3803

SITE NAME: **Round barrow cemetery at Heath Brow, Ewshot, Crowthorne**

DESIGNATION:	Scheduled Monument (No. 31177)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Richard Massey 01483 252046



SITE NAME:	Bramshill Park, Bramshill / Eversley
DESIGNATION:	Registered Park and Garden Grade II*, also part in CA, 8 LBs
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Stable
OWNERSHIP:	Corporate, multiple owners

Early C17 formal walled gardens within a park of medieval origin which was landscaped in the C17 and mid C18 and later deformalised and enlarged. The site became the Police Staff College in 1952, the farmland being sold and put under commercial forestry. The historic significance is vulnerable to the College's requirement for future building. An up-to-date landscape Conservation Management Plan is required which should also address the college's future development requirements.'

Contact: Charlotte McLean 01483 252043



SITE NAME:	Warbrook House, Eversley
DESIGNATION:	Registered Park and Garden Grade II*, also 1 LB
CONDITION:	Extensive significant problems
VULNERABILITY:	Medium
TREND:	Declining
OWNERSHIP:	Corporate, single owner

The gardens were designed c1724 by the architect John James whose home it was. Major change occurred in the mid C20 with the conversion of the house to business use and the addition of new buildings and service areas. James' axes extend beyond the gardens but these, and the parkland, are perceived as without beneficial use and have deteriorated. A seminal site in garden history terms, this landscape needs an up-to-date Conservation Management Plan and the necessary resources and commitment to implement it.

Contact: Charlotte McLean 01483 252043

NEW FOREST

SITE NAME: **Giant's Grave: a long barrow 400m north west of Down Farm, Breamore**

DESIGNATION:	Scheduled Monument (No. 12085)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME: **Bowl barrow 630m north of Hardley Bridge, Hythe and Dibden**

DESIGNATION:	Scheduled Monument (No. 20267)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Richard Massey 01483 252046

SITE NAME: **Bowl barrow 330m north of Grim's Ditch, near Tidpit Common, Martin**

DESIGNATION:	Scheduled Monument (No. 24342)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Richard Massey 01483 252046

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Long Barrow 800m north west of Paradise, Martin	
DESIGNATION: Scheduled Monument (No. 12103)	CONDITION: Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY: Arable ploughing	TREND: Declining
OWNERSHIP: Private	CONTACT: Richard Massey 01483 252046

SITE NAME: Duck's Nest: a long barrow on Rockbourne Down, Rockbourne	
DESIGNATION: Scheduled Monument (No. 12088)	CONDITION: Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY: Extensive animal burrowing	TREND: Declining
OWNERSHIP: Private	CONTACT: Richard Massey 01483 252046

SITE NAME: Grans barrow: a long barrow 880m west of Down Farm, Rockbourne	
DESIGNATION: Scheduled Monument (No. 12089)	CONDITION: Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY: Moderate animal burrowing	TREND: Improving
OWNERSHIP: Private	CONTACT: Richard Massey 01483 252046

SITE NAME: Long barrow 700m north west of Tenantry Farm, Rockbourne	
DESIGNATION: Scheduled Monument (No. 12096)	CONDITION: Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY: Arable ploughing	TREND: Declining
OWNERSHIP: Private	CONTACT: Richard Massey 01483 252046

NEW FOREST (NP)



SITE NAME: **Beaulieu Abbey,
Beaulieu**

Arcade of Chapter House and associated walls, part of C13 Abbey. Arcade in danger of collapse and wall suffering from vegetation growth. Condition report completed.

DESIGNATION: Scheduled Monument, CA

CONDITION: Very bad

OCCUPANCY: Not applicable

PRIORITY: C (B)

OWNERSHIP: Company

Contact: Richard Massey 01483 252046



SITE NAME: **Tide Mill,
High Street,
Beaulieu**

Early C18, one of the few remaining tide mills. Repairs were largely complete before a fire (March 2006) which destroyed much of the roof.

DESIGNATION: Listed Building Grade II*, CA

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNERSHIP: Trust

Contact: David Brock 01483 252044

SITE NAME: Bell barrow and two bowl barrows 180m south west of Stagbury Hill, Furzley Common, Bramshaw	
DESIGNATION: Scheduled Monument (No. 31172)	CONDITION: Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY: Moderate stock erosion	TREND: Declining
OWNERSHIP: Private	CONTACT: Richard Massey 01483 252046

SITE NAME: Rabbit warren and four bowl barrows on Stagbury Hill, Furzley Common, Bramshaw	
DESIGNATION: Scheduled Monument (No. 31171)	CONDITION: Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY: Extensive visitor erosion	TREND: Declining
OWNERSHIP: Private	CONTACT: Richard Massey 01483 252046

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Studley Castle royal hunting lodge, Bramshaw			
DESIGNATION:	Scheduled Monument (No. 32542)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Richard Massey 01483 252046

SITE NAME: Twin bowl barrow on Furzley Common, 810m SSW of Stagbury Hill, Bramshaw			
DESIGNATION:	Scheduled Monument (No. 31173)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME: Bowl barrow 320m west of Ober House, Brockenhurst			
DESIGNATION:	Scheduled Monument (No. 20287)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Richard Massey 01483 252046

SITE NAME: Hillfort 400m south of Home Farm, Denny Lodge			
DESIGNATION:	Scheduled Monument (No. 30272)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Richard Massey 01483 252046

SITE NAME: Medieval hunting lodge in Churchplace Inclosure, Denny Lodge			
DESIGNATION:	Scheduled Monument (No. 30270)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Richard Massey 01483 252046

SITE NAME: Three bowl barrows 420m south west of Pitts Copse Farm forming part of the Beaulieu Heath round barrow cemetery, Denny Lodge			
DESIGNATION:	Scheduled Monument (No. 20236)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME: Bowl barrow 360m west of Pitts Copse farm forming part of Beaulieu Heath round barrow cemetery, Fawley			
DESIGNATION:	Scheduled Monument (No. 20314)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME: Frankenbury hillfort, Godshill			
DESIGNATION:	Scheduled Monument (No. 34133)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Bowl barrow 400m south west of Robin Hood Farm, Minstead		
DESIGNATION:	Scheduled Monument (No. 12159)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Bowl barrow 550m north west of Avon Tyrrell, Ringwood		
DESIGNATION:	Scheduled Monument (No. 12161)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

RUSHMOOR



SITE NAME:	Building Q121 at Royal Defence Agency (24 foot wind tunnel), Hall Road, Farnborough	Wind tunnel built 1934-35. The future use of the building is currently uncertain, but the owner is exploring imaginative solutions for re-use. Repairs are complete.
DESIGNATION:	Listed Building Grade I	
CONDITION:	Fair	
OCCUPANCY:	Vacant	
PRIORITY:	F (F)	
OWNERSHIP:	Company	Contact: David Brock 01483 252044



SITE NAME:	Building R133 at Royal Defence Agency (Transonic Tunnel), O'Gorman Avenue, Farnborough	Wind tunnel built 1939 and modified in 1956. The future use of the building is currently uncertain, but being actively explored by the owners. Repairs are now complete.
DESIGNATION:	Listed Building Grade I	
CONDITION:	Fair	
OCCUPANCY:	Vacant	
PRIORITY:	E (F)	
OWNERSHIP:	Company	Contact: David Brock 01483 252044

TEST VALLEY

SITE NAME:	Ashley Wood camp, Ashley		
DESIGNATION:	Scheduled Monument (No. 26741)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Long barrow 400m south east of Moody's Down Farm, Barton Stacey		
DESIGNATION:	Scheduled Monument (No. 12110)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Long barrow 400m west of Moody's Down Farm, Barton Stacey		
DESIGNATION:	Scheduled Monument (No. 12094)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Long barrow and two bowl barrows, 400m north of Chattis Hill House, Broughton		
DESIGNATION:	Scheduled Monument (No. 12116)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Two bowl barrows 90m south of Hill Lodge: part of a group of round barrows on Broughton Hill, Broughton		
DESIGNATION:	Scheduled Monument (No. 26781)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Long barrow 300m south east of Middlebarn Farm, Chilbolton		
DESIGNATION:	Scheduled Monument (No. 12115)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Castle Hill, Chilworth		
DESIGNATION:	Scheduled Monument (No. HA235)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Barrow cemetery 730m north of Hampshire Gap, Grately		
DESIGNATION:	Scheduled Monument (No. 26746)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Bowl barrow 780m NNE of Hampshire Gap, Grately		
DESIGNATION:	Scheduled Monument (No. 26745)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Andover-Redbridge canal, Chalk Hill Lock, Horsebridge, Kings Somborne		
DESIGNATION:	Scheduled Monument (No. HA532)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Long barrow 50m north east of Down Farm, Nether Wallop		
DESIGNATION:	Scheduled Monument (No. 12102)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site


SITE NAME: Bowl barrow 250m south of Martin's Clump, Over Wallop	
DESIGNATION: Scheduled Monument (No. 12136)	CONDITION: Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY: Extensive animal burrowing	TREND: Declining
OWNERSHIP: Government or Agency	CONTACT: Richard Massey 01483 252046

SITE NAME: Flint mines, linear boundary and two bowl barrows at Martin's Clump, Porton Down, Over Wallop	
DESIGNATION: Scheduled Monument (No. 26787)	CONDITION: Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY: Moderate animal burrowing	TREND: Stable
OWNERSHIP: Government or Agency	CONTACT: Richard Massey 01483 252046

SITE NAME: Long barrow and adjoining bowl barrow, 250m south of Martin's Clump, Over Wallop	
DESIGNATION: Scheduled Monument (No. 12086)	CONDITION: Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY: Extensive animal burrowing	TREND: Declining
OWNERSHIP: Government or Agency	CONTACT: Richard Massey 01483 252046

SITE NAME: Long Barrow 350m south east of Nutbane, Penton Grafton	
DESIGNATION: Scheduled Monument (No. 12098)	CONDITION: Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY: Arable ploughing	TREND: Declining
OWNERSHIP: Private	CONTACT: Richard Massey 01483 252046

SITE NAME: Roman villa 500yds (460m) south west of Clanville House, Penton Grafton	
DESIGNATION: Scheduled Monument (No. HA496)	CONDITION: Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY: Arable ploughing	TREND: Declining
OWNERSHIP: Private	CONTACT: Richard Massey 01483 252046



SITE NAME: Embley Park, Wellow
DESIGNATION: Registered Park and Garden Grade II, also 8 LBs
CONDITION: Extensive significant problems
VULNERABILITY: High
TREND: Stable
OWNERSHIP: Mixed, multiple owners

C19 and early C20 woodland and shrub garden of late C18 origin, once the home of Florence Nightingale. After WWII the estate was divided, the house becoming a school. The school has reunited the historic core but the wider park is divided between multiple owners. The site suffers from development pressures in all directions. Unfortunately, the school's recently updated Conservation Management Plan only addressed land within their ownership. The issue of how to co-ordinate management of the whole designed landscape remains.

Contact: Charlotte McLean 01483 252043

WINCHESTER



SITE NAME: Brambridge House, Kiln Lane, Colden Common
DESIGNATION: Listed Building Grade II*
CONDITION: Poor
OCCUPANCY: Occupied
PRIORITY: D (D)
OWNERSHIP: Company

Country house, 1762 and 1872, suffering from deferred maintenance. Some repairs have been carried out but more are needed.

Contact: David Brock 01483 252044

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
 If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME: **Merdon Castle,
Hursley**

Norman ringwork with a standing gatehouse surviving as core work. Overgrown and in need of consolidation. Discussions need to be held with new owners.

DESIGNATION: Scheduled Monument

CONDITION: Poor

OCCUPANCY: Not applicable

PRIORITY: C (D)

OWNERSHIP: Unknown

Contact: Richard Massey 01483 252046



SITE NAME: **St Peter's Church (ruin),
Lainston House, Lainston Park,
Sparsholt**

C12 ruinous chapel, located circa 150m south-west of Lainston House. The ruin was used as a romantic folly in C18 pleasure grounds in which it stands. Requires consolidation. Discussions have taken place and some masonry repairs were carried out in 2005 but further work is needed.

DESIGNATION: Listed Building Grade II, SM, RPG II*

CONDITION: Fair

OCCUPANCY: Not applicable

PRIORITY: C (F)

OWNERSHIP: Company

Contact: Richard Massey 01483 252046



SITE NAME: **Walled garden to Lainston House,
Lainston Park,
Sparsholt**

Hexagonal walled fruit or kitchen garden, c5.3ha, c100m west of the house. Probably C18. Striking polygonal layout. Axial vista from main entrance of house, across forecourt and into walled garden. In use as hotel car park around the sides and planted in the centre. Some fruit trees remain on the walls. In need of repair. The gardens around the house are in good condition, but the park is in arable use.

DESIGNATION: Listed Building Grade II*, RPG II*

CONDITION: Fair

OCCUPANCY: Not applicable

PRIORITY: D (D)

OWNERSHIP: Company

Contact: David Brock 01483 252044



SITE NAME: **King Johns House,
Warnford Park,
Warnford**

Ruinous C13 hall house. A feature within the C18 pleasure grounds of Warnford Park, within which it is situated. Stop gap repairs have been carried out. Requires further consolidation and discussions taking place.

DESIGNATION: Listed Building Grade I, SM, RPG II

CONDITION: Poor

OCCUPANCY: Not applicable

PRIORITY: B (B)

OWNERSHIP: Company

Contact: Richard Massey 01483 252046

SITE NAME:

Two bowl barrows north of Hoe Farm, Bishops Waltham

DESIGNATION: Scheduled Monument (No. 12142)

CONDITION: Generally unsatisfactory with major localised problems

PRINCIPAL VULNERABILITY: Scrub / tree growth

TREND: Declining

OWNERSHIP: Private

CONTACT: Richard Massey 01483 252046

SITE NAME:

Four round barrows in 'Hump Field' south of Stakes Lane, Corhampton and Meonstoke

DESIGNATION: Scheduled Monument (No. HA238)

CONDITION: Extensive significant problems i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Richard Massey 01483 252046

SITE NAME:

Long barrow 640m south east of Stock's Farm, Corhampton and Meonstoke

DESIGNATION: Scheduled Monument (No. 12090)

CONDITION: Generally unsatisfactory with major localised problems

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Richard Massey 01483 252046

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA Conservation Area
LB/LBs Listed Building/s
NP National Park
RPG Registered Park and Garden
SM/SMs Scheduled Monument/s
UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Iron Age field system, banjo enclosure and Romano-British villa, 500m east of Woodham Farm, Kings Worthy		
DESIGNATION:	Scheduled Monument (No. 12049)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Norsebury Ring hillfort, Micheldever		
DESIGNATION:	Scheduled Monument (No. 34140)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Long barrow and bowl barrow 440m north west of Sanctuary Farm, Wonston		
DESIGNATION:	Scheduled Monument (No. 12112)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Abbots Worthy		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Department (LA) 01962 848177		

SITE NAME:	Avington		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Department (LA) 01962 848177		

SITE NAME:	Bishops Waltham		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Department (LA) 01962 848177		

SITE NAME:	Cheriton		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Department (LA) 01962 848177		

SITE NAME:	Compton Street		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Department (LA) 01962 848177		

SITE NAME:	Corhampton and Meonstoke		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Department (LA) 01962 848177		

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Droxford		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Department (LA) 01962 848177		

SITE NAME:	Easton		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Department (LA) 01962 848177		

SITE NAME:	Exton		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Department (LA) 01962 848177		

SITE NAME:	Hambledon		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Department (LA) 01962 848177		

SITE NAME:	Hursley		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Department (LA) 01962 848177		

SITE NAME:	Itchen Stoke		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Department (LA) 01962 848177		

SITE NAME:	Kings Worthy		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Department (LA) 01962 848177		

SITE NAME:	Littleton		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Department (LA) 01962 848177		

SITE NAME:	Martyr Worthy		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Department (LA) 01962 848177		

SITE NAME:	New Alresford		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Department (LA) 01962 848177		

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Southwick		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Department (LA) 01962 848177		

SITE NAME:	Sparsholt		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Department (LA) 01962 848177		

SITE NAME:	Sutton Scotney		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Department (LA) 01962 848177		

SITE NAME:	Twyford		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Department (LA) 01962 848177		

SITE NAME:	West Meon		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Department (LA) 01962 848177		

SITE NAME:	Wickham		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Department (LA) 01962 848177		

SITE NAME:	Winchester		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Department (LA) 01962 848177		

SITE NAME:	Wonston		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Department (LA) 01962 848177		

ISLE OF WIGHT (UA)



SITE NAME:	Northwood House, Ward Avenue, Cowes
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Part occupied
PRIORITY:	C (C)
OWNERSHIP:	Trust

Large house, 1837, with spectacular interiors. The long-term future of this partly-used building is unresolved and maintenance needs to be addressed in the short term. The cost of full repair is very high.

Contact: David Brock 01483 252044

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME: **Hammerhead crane,
Thetis Road, West Cowes,
Cowes**

DESIGNATION: Listed Building Grade II*

CONDITION: Poor

OCCUPANCY: Not applicable

PRIORITY: C (C)

OWNERSHIP: Trust

Giant cantilever crane, also called 'hammerhead' crane, built 1911. One of a handful of this type of crane now surviving, and witness to a major local industry. Now disused and surrounded by a potential development site.

Contact: David Brock 01483 252044



SITE NAME: **Golden Hill Fort,
Military Road,
Freshwater**

DESIGNATION: Listed Building Grade I

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: F (F)

OWNERSHIP: Company

Infantry fort of 1863 built as a hexagon around a courtyard. The former use as industrial units has ceased and domestic conversion is now being carried out.

Contact: David Brock 01483 252044



SITE NAME: **Remains of Old Quarr Abbey,
Fishbourne Park Road,
Binstead, Ryde**

DESIGNATION: Listed Building Grade II, SM

CONDITION: Poor

OCCUPANCY: Not applicable

PRIORITY: A (A)

OWNERSHIP: Religious organisation

Cistercian foundation of 1131. In an advanced state of decline due to neglect and vegetation growth. English Heritage has carried out a photographic survey and a condition survey. Stage I Heritage Lottery Fund grant approved for works including repairs to this monument.

Contact: Richard Massey 01483 252046

SITE NAME: **Medieval settlement 100m south east and 350m north east of East Ashey Manor Farm, Brading**

DESIGNATION:	Scheduled Monument (No. 22066)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME: **Bowl barrow on Newbarn Down: 1.1km south west of Rowridge, Brighstone**

DESIGNATION:	Scheduled Monument (No. 21988)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Moderate stock erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME: **A Bronze Age barrow and Anglo-Saxon cemetery on Bowcombe Down, 575m south east of Apesdown, Isle of Wight**

DESIGNATION:	Scheduled Monument (No. 22068)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME: **Carisbrooke Romano-British villa, Isle of Wight**

DESIGNATION:	Scheduled Monument (No. 22039)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).


- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Two bowl barrows 180m WNW of Puck House, Fishbourne, Isle of Wight		
DESIGNATION:	Scheduled Monument (No. 22036)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046



SITE NAME:	Swainston, Calbourne	Mid/late C18 woodland pleasure grounds, set in parkland, with intersecting avenues, pools and a stream incorporating earlier fishponds. The reconstructed house and refurbished gardens are now a hotel, but some key features lie in the remainder of the estate and in private ownership. This includes a temple which is further isolated by a public road and some inappropriate light industrial units. Perceived low value of landscape features and levels of repair make holistic conservation and management difficult. Contact: Charlotte McLean 01483 252043
DESIGNATION:	Registered Park and Garden Grade II, also 3 LBs	
CONDITION:	Generally unsatisfactory with major localised problems	
VULNERABILITY:	High	
TREND:	Declining	
OWNERSHIP:	Mixed, multiple owners	

SITE NAME:	Brading		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Conservation & Design Team (LA) 01983 823552		

SITE NAME:	Carisbrooke		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Conservation & Design Team (LA) 01983 823552		

SITE NAME:	Cowes		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Conservation & Design Team (LA) 01983 823552		

SITE NAME:	Godshill		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Conservation & Design Team (LA) 01983 823552		

SITE NAME:	Newport		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Conservation & Design Team (LA) 01983 823552		

SITE NAME:	Ryde St John		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Conservation & Design Team (LA) 01983 823552		

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
 If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

KENT

ASHFORD



SITE NAME: **Remains of Archbishop's Palace, Market Place, Charing**

DESIGNATION: Listed Building Grade I, SM, CA
 CONDITION: Very bad
 OCCUPANCY: Not applicable
 PRIORITY: A (A)
 OWNERSHIP: Private

Remains of palace built in C13 and C14. Farm complex converted from remains includes gatehouse, barn (east range of palace courtyard), outhouse (west range) and Palace Farmhouse (north range). Temporary support has been given to the structurally unsound barn with English Heritage grant aid. Survey carried out by the Royal Commission on the Historic Monuments of England.

Contact: Judith Roebuck 01483 252048



SITE NAME: **Ruins of Church of St Mary, Pluckley Road, Little Chart**

DESIGNATION: Listed Building Grade II, SM
 CONDITION: Poor
 OCCUPANCY: Not applicable
 PRIORITY: D (D)
 OWNERSHIP: Local authority

War damaged church, circa 1500, now ruinous with tower still standing. Local authority has repaired ruined walls of nave and chancel with English Heritage grant.

Contact: Judith Roebuck 01483 252048



SITE NAME: **Wye Undercroft, Bridge Street, Wye with Hinxhill**

DESIGNATION: Listed Building Grade II, SM, CA
 CONDITION: Poor
 OCCUPANCY: Not applicable
 PRIORITY: E (D)
 OWNERSHIP: Private

C13 undercroft in front garden of new house; of virtually no beneficial use. Repair scheme now underway after detailed technical investigation.

Contact: Judith Roebuck 01483 252048

SITE NAME:

Castle Toll Saxon burgh and medieval fort, Newenden

DESIGNATION:

Scheduled Monument (No. 12841)

CONDITION:

Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY:

Arable ploughing

TREND:

Declining

OWNERSHIP:

Private

CONTACT:

Judith Roebuck 01483 252048

CANTERBURY



SITE NAME: **Greyfriars Monastery, Stour Street, Canterbury**

DESIGNATION: Listed Building Grade I, SM, CA
 CONDITION: Very bad
 OCCUPANCY: Not applicable
 PRIORITY: A (A)
 OWNERSHIP: Housing Association

Boundary walls from Tudor house built on site of the friary and one part of the friary church. Friary built in 1267.

Contact: Judith Roebuck 01483 252048



SITE NAME: **Monuments in the precinct of Canterbury Cathedral, The Precinct, Canterbury**

DESIGNATION: Listed Building Grade I, WHS, SM, CA
 CONDITION: Very bad
 OCCUPANCY: Not applicable
 PRIORITY: B (B)
 OWNERSHIP: Religious organisation

Very important medieval ruinous structures of Christchurch Priory, which have suffered from years of decline. Major backlog of repairs; work has started with English Heritage grant to Llanfrancs dormitory and the city wall. Slow progress is being made.

Contact: Judith Roebuck 01483 252048

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.
 E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME: **Horton Manor Chapel,
Horton,
Chartham**

Two cell medieval (C14) chapel now roofless.
Located on a farm. Repair schedule prepared.

DESIGNATION: Listed Building Grade II, SM

CONDITION: Very bad

OCCUPANCY: Not applicable

PRIORITY: C (C)

OWNERSHIP: Private

Contact: Judith Roebuck 01483 252048



SITE NAME: **Barn at Hardres Court,
Upper Hardres**

Late C15 to early C16 aisled timber barn.
Damaged by fire in 1993.

DESIGNATION: Listed Building Grade II*, CA

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNERSHIP: Private

Contact: Tom Foxall 01483 252035

SITE NAME:

Bowl barrow 350m south west of Upper Digges Farm, Adisham

DESIGNATION:

Scheduled Monument (No. 12810)

CONDITION:

Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY:

Arable ploughing

TREND:

Declining

OWNERSHIP:

Private

CONTACT:

Judith Roebuck 01483 252048

SITE NAME:

Enclosures west of Woodlands, Adisham

DESIGNATION:

Scheduled Monument (No. KE317)

CONDITION:

Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY:

Arable ploughing

TREND:

Declining

OWNERSHIP:

Private

CONTACT:

Judith Roebuck 01483 252048

DARTFORD

SITE NAME:

Roman enclosure south east of Vagniacae, Southfleet

DESIGNATION:

Scheduled Monument (No. KE198)

CONDITION:

Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY:

Arable ploughing

TREND:

Declining

OWNERSHIP:

Private

CONTACT:

Judith Roebuck 01483 252048

SITE NAME:

Springhead Roman site, Southfleet

DESIGNATION:

Scheduled Monument (No. KE158)

CONDITION:

Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY:

Arable ploughing

TREND:

Declining

OWNERSHIP:

Private

CONTACT:

Judith Roebuck 01483 252048

SITE NAME:

Dartford Town Centre

DESIGNATION:

Conservation Area

CONDITION:

At risk

VULNERABILITY:

Unknown

TREND:

Deteriorating

CONTACT:

Tony Phillips (LA) 01322 343434

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

DOVER



SITE NAME:	The Western Heights fortifications, Castle Hill, Dover
DESIGNATION:	Scheduled Monument, CA,
CONDITION:	Poor
OCCUPANCY:	Part occupied
PRIORITY:	C (C)
OWNERSHIP:	Government

An Immigration Removal Centre, managed by the Home Office, occupies the Citadel on the Western Heights. The surrounding moats and western outworks are in poor condition and there is no programme for their maintenance. Funding for a quadrennial inspection report has not been secured. There has been no progress since the previous report in 2007

Contact: Alan Johnson 020 7973 3174



SITE NAME:	Fort Burgoyne, Connaught Barracks, Guston
DESIGNATION:	Scheduled Monument
CONDITION:	Fair
OCCUPANCY:	Vacant
PRIORITY:	C (C)
OWNERSHIP:	Housing Association

1860s polygonal-plan fort now part of a later barracks. The earth-covered terraced casemates are vacant. Structures on the ramparts (the brick-built Haxo casemates) are at risk from lack of maintenance and invasive ivy growth. The site is now owned by Homes and Community Agency.

Contact: Judith Roebuck 01483 252048



SITE NAME:	St Radegunds Abbey, Abbey Road, Hougham Without
DESIGNATION:	Listed Building Grade II*, SM
CONDITION:	Very bad
OCCUPANCY:	Not applicable
PRIORITY:	A (A)
OWNERSHIP:	Private

A significant C13 monastic site with standing remains of the church and claustral buildings. Heavily overgrown and fabric in a ruinous state. The site is now a farm with buildings used as barns and a farmhouse. These are in fair condition.

Contact: Judith Roebuck 01483 252048



SITE NAME:	The Belvedere, Waldershare Park, Shepherdswell with Coldred
DESIGNATION:	Listed Building Grade I, RPG II
CONDITION:	Very bad
OCCUPANCY:	Vacant
PRIORITY:	C (C)
OWNERSHIP:	Private

Belvedere: 1725-7 by Lord Burlington or Colen Campbell for Sir Henry Furnese located at the southern end of the western side of an early C18 Wilderness, overlooking the park to the north and south. Derelict for many years and now in a ruinous state. The Wilderness lies to the south of the house; mostly cleared and planted with larch in the 1950s. The rides and scattered mature oaks and sweet chestnuts survive.

Contact: Tom Foxall 01483 252035

SITE NAME:	Great Mongeham Anglo-Saxon cemetery, Great Mongeham	
DESIGNATION:	Scheduled Monument (No. KE324)	CONDITION: Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND: Declining
OWNERSHIP:	Private	CONTACT: Judith Roebuck 01483 252048

SITE NAME:	St Radegund's Abbey, Poulton, Hougham Without	
DESIGNATION:	Scheduled Monument (No. KE8)	CONDITION: Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Collapse	TREND: Declining
OWNERSHIP:	Private	CONTACT: Judith Roebuck 01483 252048

SITE NAME:	Ring ditch and enclosure 200yds (180m) east of Parsonage Farm, Preston	
DESIGNATION:	Scheduled Monument (No. KE260)	CONDITION: Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND: Declining
OWNERSHIP:	Private	CONTACT: Judith Roebuck 01483 252048

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Four ring ditches on ridge of Sutton Hill, Sutton		
DESIGNATION:	Scheduled Monument (No. KE263)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Judith Roebuck 01483 252048

SITE NAME:	Romano-Celtic temple and Iron Age site south of Worth, Worth		
DESIGNATION:	Scheduled Monument (No. KE197)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Judith Roebuck 01483 252048

GRAVESHAM



SITE NAME:	The Dairy, Cobham Hall, Cobham	Unusual Georgian model dairy, part repaired several years ago and awaiting completion of works.
DESIGNATION:	Listed Building Grade II*, RPG II*	
CONDITION:	Fair	
OCCUPANCY:	Vacant	
PRIORITY:	E (E)	
OWNERSHIP:	Trust	Contact: Tom Foxall 01483 252035

MAIDSTONE



SITE NAME:	Boxley Abbey Barn, Boxley Abbey, Boxley	Cistercian abbey founded in 1146. Main threat is to a medieval roofed range used formerly as a barn, but which is now vacant. Agricultural use now no longer feasible.
DESIGNATION:	Listed Building Grade I, SM, CA	
CONDITION:	Poor	
OCCUPANCY:	Vacant	
PRIORITY:	E (E)	
OWNERSHIP:	Private	Contact: Judith Roebuck 01483 252048



SITE NAME:	St Andrews Chapel, Boarley Lane, Boxley Abbey, Boxley	Late C15 chapel. Currently unoccupied and subject to vandalism. Location affected by proximity of motorway.
DESIGNATION:	Listed Building Grade II*	
CONDITION:	Fair	
OCCUPANCY:	Vacant	
PRIORITY:	E (E)	
OWNERSHIP:	Private	Contact: Tom Foxall 01483 252035



SITE NAME:	Dovecotes at Leeds Priory, Lower Street, Leeds	Mid C16 overgrown and roofless dovecotes from a post-dissolution mansion. Site purchased for possible new houses.
DESIGNATION:	Listed Building Grade II, SM	
CONDITION:	Very bad	
OCCUPANCY:	Vacant	
PRIORITY:	B (B)	
OWNERSHIP:	Trust	Contact: Judith Roebuck 01483 252048

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME: **Slype and associated remains at Leeds Priory, Lower Street, Leeds**

A slype (covered passage) and associated remains of medieval priory. Site purchased for possible new houses.

DESIGNATION: Listed Building Grade II, SM

CONDITION: Very bad

OCCUPANCY: Not applicable

PRIORITY: C (C)

OWNERSHIP: Trust

Contact: Judith Roebuck 01483 252048



SITE NAME: **I I Lower Stone Street, Maidstone**

Early C18 house. Vacant for some years.

DESIGNATION: Listed Building Grade II*, CA

CONDITION: Fair

OCCUPANCY: Vacant

PRIORITY: E (E)

OWNERSHIP: Company

Contact: Tom Foxall 01483 252035



SITE NAME: **Ruined gateway, College of All Saints, Mill Street, Maidstone**

Ruined gatehouse to medieval college. Structural cracking evident. Monitoring by structural engineer will inform application for English Heritage grant consideration.

DESIGNATION: Listed Building Grade II, SM, CA

CONDITION: Poor

OCCUPANCY: Not applicable

PRIORITY: D (D)

OWNERSHIP: Local authority

Contact: Judith Roebuck 01483 252048



SITE NAME: **The Dungeons at the Archbishop's Palace, Mill Street, Maidstone**

Partially ruined stone building of medieval date. Previous alterations and lack of repair are contributing to structural problems.

DESIGNATION: Listed Building Grade II*, CA

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNERSHIP: Local authority

Contact: Tom Foxall 01483 252035



SITE NAME: **Mote House, Mote Park, Maidstone**

House, 1793-1801. Recently used as an old people's home. Currently under repair for conversion to retirement housing.

DESIGNATION: Listed Building Grade II*, RPG II

CONDITION: Fair

OCCUPANCY: Vacant

PRIORITY: F (F)

OWNERSHIP: Local authority

Contact: Tom Foxall 01483 252035

SITE NAME:

Leeds Priory: Augustinian Priory of St Mary and St Nicholas with associated dovecotes and slype, and the site of the 18th century Meredith mansion, Leeds

DESIGNATION:

Scheduled Monument (No. 24346)

CONDITION:

Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY:

Collapse

TREND:

Declining

OWNERSHIP:

Private

CONTACT:

Judith Roebuck 01483 252048

SITE NAME:

Binbury motte and bailey castle, Thurnham

DESIGNATION:

Scheduled Monument (No. 23033)

CONDITION:

Generally unsatisfactory
with major localised problems

PRINCIPAL VULNERABILITY:

Scrub / tree growth

TREND:

Declining

OWNERSHIP:

Private

CONTACT:

Judith Roebuck 01483 252048

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA Conservation Area
LB/LBs Listed Building/s
NP National Park
RPG Registered Park and Garden
SM/SMs Scheduled Monument/s
UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Boxley Abbey		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Expected to deteriorate
CONTACT:	Michelle Sadlier (LA) 01622 602816		

SITE NAME:	Elmstone Hole, Grafty Green, Boughton Malherbe		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Expected to deteriorate
CONTACT:	Michelle Sadlier (LA) 01622 602816		

SEVENOAKS

SITE NAME:	Chapel, Maplescombe, West Kingsdown		
DESIGNATION:	Scheduled Monument (No. KE362)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Judith Roebuck 01483 252048



SITE NAME:	Combe Bank, Sundridge with Ide Hill / Brasted
DESIGNATION:	Registered Park and Garden Grade II*, also part in CA, 17 LBs
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Declining
OWNERSHIP:	Mixed, multiple owners

Combe Bank's gardens and pleasure grounds date from the 1720s and 1740s. After WWI the estate was sold and divided up. The house and gardens became a school in 1924. The north park became derelict after construction of the M25; recent attempts to develop it as a burial ground remain unresolved. The gardens suffered considerable storm damage in 1987. A joined up conservation led management approach, in conjunction with sufficient resources, is still required.

Contact: Charlotte McLean 01483 252043

SEVENOAKS / TUNBRIDGE WELLS



SITE NAME:	Swaylands, Penshurst / Bidborough / Chiddingstone
DESIGNATION:	Registered Park and Garden Grade II, also part in CA, 3 LBs
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	High
TREND:	Improving
OWNERSHIP:	Private, multiple owners

Important for its terraced gardens and pleasure grounds, including extensive rockwork developed in the late C19. Work began in 2006 to convert the house into 28 apartments, including the addition of two new wings, and works to the gardens as well. The project stalled last year due to financial difficulties but thankfully work has recommenced. The park is diminutive but in need of management. The lower lake, farm and kitchen garden are in separate ownership and much neglected – here the future remains less certain.

Contact: Charlotte McLean 01483 252043

SEVENOAKS

SITE NAME:	Brasted High Street		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Team (LA) 01732 227000		

SITE NAME:	Chiddingstone		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Team (LA) 01732 227000		

SITE NAME:	Edenbridge		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Team (LA) 01732 227000		

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Halstead		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Team (LA) 01732 227000		

SITE NAME:	Kippington and Oakhill Road, Sevenoaks		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Team (LA) 01732 227000		

SITE NAME:	Otford		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Team (LA) 01732 227000		

SITE NAME:	Riverhead		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Team (LA) 01732 227000		

SITE NAME:	Seal		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Team (LA) 01732 227000		

SITE NAME:	Sevenoaks High Street		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Team (LA) 01732 227000		

SITE NAME:	Shoreham High Street		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Team (LA) 01732 227000		

SITE NAME:	South Darenth		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Team (LA) 01732 227000		

SITE NAME:	Sundridge		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Team (LA) 01732 227000		

SITE NAME:	The Vine, Sevenoaks		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Team (LA) 01732 227000		

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Vine Court, Sevenoaks		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Planning Team (LA) 01732 227000		


SHEPWAY

	SITE NAME:	Martello Tower No.5, Folkestone	A very good example of a Martello tower. Situated in the grounds of a school and vacant but with potential for re-use by the school. The preservation of archaeological and historical significance will be the main consideration in assessing the suitability of proposals to convert Martello towers for residential use.
	DESIGNATION:	Scheduled Monument	
	CONDITION:	Fair	
	OCCUPANCY:	Vacant	
	PRIORITY:	E (E)	
	OWNERSHIP:	Local authority	

	SITE NAME:	Martello Tower No. 4, The Leas, Folkestone	A good example of a Martello tower built 1806. Derelict and situated in the grounds of a private house. The preservation of archaeological and historical significance will be the main consideration in assessing the suitability of proposals to convert Martello towers for residential use.
	DESIGNATION:	Scheduled Monument, CA	
	CONDITION:	Very bad	
	OCCUPANCY:	Vacant	
	PRIORITY:	C (C)	
	OWNERSHIP:	Private	

	SITE NAME:	Martello Towers Nos. 6 and 7, Shorncliffe Camp, Folkestone	Martello towers, 1806. Derelict recently sold by Ministry of Defence to private owner. (Photograph shows tower 6). The preservation of archaeological and historical significance will be the main consideration in assessing the suitability of proposals to convert Martello towers for residential or other use.
	DESIGNATION:	Listed Building Grade II, SM	
	CONDITION:	Poor	
	OCCUPANCY:	Vacant	
	PRIORITY:	C (C)	
	OWNERSHIP:	Private	

	SITE NAME:	Martello Tower No. 9, Shorncliffe Camp, Sandgate, Folkestone	Martello tower, 1806. Derelict, disposed by Ministry Of Defence to private owner. The preservation of archaeological and historical significance will be the main consideration in assessing the suitability of proposals to convert Martello towers for residential use.
	DESIGNATION:	Listed Building Grade II, SM	
	CONDITION:	Very bad	
	OCCUPANCY:	Vacant	
	PRIORITY:	C (C)	
	OWNERSHIP:	Private	

	SITE NAME:	Dymchurch Redoubt, Hythe Ranges, Hythe	Currently used as a military training facility. The original fort of 1806 is a massive brick circular structure within a dry moat, and has C20 additions. Located on MoD ranges, some parts have been brought back into use. There is brickwork deterioration to both the original fort and later additions. A conservation plan was prepared in 2005. Phased repairs are in progress.
	DESIGNATION:	Scheduled Monument	
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied	
	PRIORITY:	D (D)	
	OWNERSHIP:	Government	

SITE NAME:	Romano-British building south of Burch's Rough, Lympe		
DESIGNATION:	Scheduled Monument (No. KE307)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Judith Roebuck 01483 252048

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Motte and Bailey Castle 200m north west of Stowting Church, Stowting		
DESIGNATION:	Scheduled Monument (No. 12825)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Judith Roebuck 01483 252048

SITE NAME:	Bowl barrow 150m north east of Red House Farm, Swingfield		
DESIGNATION:	Scheduled Monument (No. 25466)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Judith Roebuck 01483 252048

SITE NAME:	Bowl barrow at Minnis Beeches, Swingfield		
DESIGNATION:	Scheduled Monument (No. 25467)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Judith Roebuck 01483 252048

SITE NAME:	Dungeness		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Roger Sapsford (LA) 01303 852381		

SITE NAME:	Lydd		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Roger Sapsford (LA) 01303 852381		

SITE NAME:	Sandgate High Street		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Roger Sapsford (LA) 01303 852381		

SWALE



SITE NAME: **The ruins of Shurland Hall, Leysdown Road, Eastchurch**

DESIGNATION: Listed Building Grade II*, SM

CONDITION: Fair

OCCUPANCY: Vacant

PRIORITY: F (F)

OWNERSHIP: Trust

Tudor courtier house with long history of neglect. Gatehouse built during reign of Henry VIII. English Heritage has negotiated with the Spitalfield Trust a rescue project to which an English Heritage grant was offered. Works are well advanced and attention is turning to the other ruins.

Contact: Peter Kendall 01483 252038



SITE NAME: **Medieval Stables at Abbey Farm, Abbey Fields, Faversham**

DESIGNATION: Listed Building Grade II*, CA

CONDITION: Very bad

OCCUPANCY: Vacant

PRIORITY: F (D)

OWNERSHIP: Private

Very small medieval farm building in a very poor state of repair. Consent has been granted to use as an outbuilding to an adjacent stable conversion and repairs are underway.'

Contact: Tom Foxall 01483 252035

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
 If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHs	World Heritage Site

	<p>SITE NAME: Provender, Provender Lane, Norton</p> <p>DESIGNATION: Listed Building Grade II*</p> <p>CONDITION: Poor</p> <p>OCCUPANCY: Occupied</p> <p>PRIORITY: F (D)</p> <p>OWNERSHIP: Private</p>	<p>Fine medieval and later house, for which a programme of substantial repairs is well underway.</p> <p>Contact: Tom Foxall 01483 252035</p>
	<p>SITE NAME: Former Medway Ports Authority Offices (Dockyard House), Sheerness Docks, Sheerness</p> <p>DESIGNATION: Listed Building Grade II*, CA</p> <p>CONDITION: Fair</p> <p>OCCUPANCY: Vacant</p> <p>PRIORITY: C (C)</p> <p>OWNERSHIP: Company</p>	<p>House, 1830. Vacant with a growing maintenance problem. Applications for a flat conversion have been submitted and are under consideration.'</p> <p>Contact: Tom Foxall 01483 252035</p>
	<p>SITE NAME: Coach Houses, Naval Terrace, Sheerness Docks, Sheerness</p> <p>DESIGNATION: Listed Building Grade II*, CA</p> <p>CONDITION: Very bad</p> <p>OCCUPANCY: Part occupied</p> <p>PRIORITY: B (B)</p> <p>OWNERSHIP: Private</p>	<p>Coach houses ancillary to Nos 1-8 Naval Terrace, 1830. Some are now restored, but others continue to suffer from a lack of repairs and maintenance.</p> <p>Contact: Tom Foxall 01483 252035</p>
	<p>SITE NAME: I-15 (consec) Regency Close, Sheerness Docks, Sheerness</p> <p>DESIGNATION: Listed Building Grade II*, CA</p> <p>CONDITION: Fair</p> <p>OCCUPANCY: Part occupied</p> <p>PRIORITY: C (C)</p> <p>OWNERSHIP: Company</p>	<p>Row of houses built 1830. Largely vacant. Applications have been made to restore the houses to residential use, along with new development in their gardens.'</p> <p>Contact: Tom Foxall 01483 252035</p>
	<p>SITE NAME: Former Royal Dockyard Church and attached wall and railings, Sheerness Dockyard, Sheerness</p> <p>DESIGNATION: Listed Building Grade II*, CA</p> <p>CONDITION: Very bad</p> <p>OCCUPANCY: Vacant</p> <p>PRIORITY: B (B)</p> <p>OWNERSHIP: Private</p>	<p>Former St Paul's Parish Dockyard Church. Built originally in 1828, Architect George Taylor; but destroyed by fire and rebuilt in 1884 incorporating the old clock tower. Empty since 1970 and damaged by fire in 2001, now scaffolded. Consent received for conversion to apartments.</p> <p>Contact: Tom Foxall 01483 252035</p>
	<p>SITE NAME: The Boat Store (No. 78), Sheerness Dockyard, Sheerness</p> <p>DESIGNATION: Listed Building Grade I</p> <p>CONDITION: Fair</p> <p>OCCUPANCY: Part occupied</p> <p>PRIORITY: C (C)</p> <p>OWNERSHIP: Company</p>	<p>Boat store. Built 1859. Since the destruction of the Crystal Palace and the first South Kensington Museum this is the earliest surviving example of a multi-storey iron-frame and panel structure. In minor use for storage. Discussions with Local Planning Authority and port company continuing.</p> <p>Contact: Tom Foxall 01483 252035</p>

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME: **Former Working Mast House,
26 Jetty Road, Sheerness Dockyard,
Sheerness**

Large C19 industrial building.

DESIGNATION: Listed Building Grade II*

CONDITION: Poor

OCCUPANCY: Part occupied

PRIORITY: C (C)

OWNERSHIP: Company

Contact: Tom Foxall 01483 252035

SITE NAME: **Murston Old Church,
Sittingbourne**

Originally a large church with three aisles and three chancels with a square tower and wooden turret, built between 1375 and 1550; only the southern chapel remains. The rest of the church survives as buried archaeological remains.

DESIGNATION: Scheduled Monument

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: A (A)

OWNERSHIP: Trust

Contact: Judith Roebuck 01483 252048



SITE NAME: **51 High Street,
Sittingbourne**

A Regency front to a probable C18 house. Vacant and suffering from vandalism and a lack of maintenance. 'Potentially for sale.'

DESIGNATION: Listed Building Grade II*, CA

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: D (D)

OWNERSHIP: Company

Contact: Tom Foxall 01483 252035



SITE NAME: **Sheerness Defences,
Swale**

Moated artillery fortifications from C17-C20. A major complex defending the dockyard.

DESIGNATION: Scheduled Monument, CA

CONDITION: Very bad

OCCUPANCY: Not applicable

PRIORITY: C (C)

OWNERSHIP: Company

Contact: Peter Kendall 01483 252038

THANET



SITE NAME: **The Shell Grotto,
Grotto Hill,
Margate**

Early C19 grotto. Extensive shell designs to walls and ceilings, some of which are loose or have detached completely.

DESIGNATION: Listed Building Grade I

CONDITION: Poor

OCCUPANCY: Not applicable

PRIORITY: D (D)

OWNERSHIP: Private

Contact: Tom Foxall 01483 252035



SITE NAME: **Dreamland Cinema,
Marine Terrace,
Margate**

Cinema, 1935. The first English cinema in the style based on the Titania Palast of Berlin, a style subsequently used extensively by Odeon. Vacant and with a backlog of repairs.

DESIGNATION: Listed Building Grade II*

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNERSHIP: Company

Contact: Tom Foxall 01483 252035

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: **Barn about 50 metres east of Ozengell Grange, Haine Road, Ramsgate**

Derelict late medieval grain barn, on land formerly owned by St Augustine's Abbey, Canterbury.

DESIGNATION: Listed Building Grade II*

CONDITION: Very bad

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNERSHIP: Private

Contact: Tom Foxall 01483 252035

SITE NAME: **Ring ditches and enclosures 500yds (450m) ESE of College Farm, Acol**

DESIGNATION: Scheduled Monument (No. KE259)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Judith Roebuck 01483 252048

SITE NAME: **Group of ring ditches 400yds (360m) north west of Great Brooks End Farm, Birchington**

DESIGNATION: Scheduled Monument (No. KE270)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Judith Roebuck 01483 252048

SITE NAME: **Anglo-Saxon cemetery, Dane Valley Road, Broadstairs and St Peters**

DESIGNATION: Scheduled Monument (No. KE316)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Judith Roebuck 01483 252048

SITE NAME: **Double ring ditch and two enclosures 400yds (360m) north west of Danes Court, Broadstairs and St Peters**

DESIGNATION: Scheduled Monument (No. KE261)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Judith Roebuck 01483 252048

SITE NAME: **Anglo-Saxon cemetery south of Ozengell Grange, Margate and Ramsgate**

DESIGNATION: Scheduled Monument (No. KE250)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Judith Roebuck 01483 252048

SITE NAME: **Quex Park settlements, Margate and Ramsgate**

DESIGNATION: Scheduled Monument (No. KE367)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Judith Roebuck 01483 252048

SITE NAME: **Settlement one mile (1610m) east of village, Margate and Ramsgate**

DESIGNATION: Scheduled Monument (No. KE365)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Judith Roebuck 01483 252048

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA Conservation Area
LB/LBs Listed Building/s
NP National Park
RPG Registered Park and Garden
SM/SMs Scheduled Monument/s
UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Enclosure and ring ditches 200yds (180m) ENE of Minster Laundry, Minster		
DESIGNATION:	Scheduled Monument (No. KE262)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Judith Roebuck 01483 252048

TONBRIDGE AND MALLING



SITE NAME:	Hadlow Tower, High Street, Hadlow	Tower of an otherwise demolished late C18/early C19 country house. The service buildings around base have been converted into housing.
DESIGNATION:	Listed Building Grade I, CA	
CONDITION:	Poor	
OCCUPANCY:	Occupied	
PRIORITY:	C (C)	
OWNERSHIP:	Private	Contact: Tom Foxall 01483 252035

SITE NAME:	Romano-British villa, Anglo-Saxon cemetery and associated remains at Eccles, Aylesford		
DESIGNATION:	Scheduled Monument (No. 25471)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Judith Roebuck 01483 252048

SITE NAME:	Chapel of St Blaise, Offham		
DESIGNATION:	Scheduled Monument (No. KE205)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Judith Roebuck 01483 252048

SITE NAME:	Town banks, Tonbridge		
DESIGNATION:	Scheduled Monument (No. KE136)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Judith Roebuck 01483 252048

TUNBRIDGE WELLS



SITE NAME:	Providence Chapel, Stone Street, Cranbrook	Strict Baptist chapel. 1795 with early to mid C19 alterations.
DESIGNATION:	Listed Building Grade II*, CA	
CONDITION:	Poor	
OCCUPANCY:	Vacant	
PRIORITY:	C (C)	
OWNERSHIP:	Private	Contact: Tom Foxall 01483 252035

SITE NAME:	High Rocks Camp, Tunbridge Wells (part in East Sussex)		
DESIGNATION:	Scheduled Monument (No. KE399)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Judith Roebuck 01483 252048

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

TUNBRIDGE WELLS / TONBRIDGE AND MALLING



SITE NAME:	Somerhill, Capel
DESIGNATION:	Registered Park and Garden Grade II, also 4 LBs
CONDITION:	Extensive significant problems
VULNERABILITY:	Medium
TREND:	Declining
OWNERSHIP:	Mixed, multiple owners

Early C19 terraced garden probably laid out by William Sawrey Gilpin, with surrounding, later C19, ornamental gardens, all set within parkland. The site is now divided between a school, an estate and several smaller, private owners all operating diverse management regimes. The school is interested in commissioning a Conservation Management Plan if grant aid is available. This could form the basis of a coordinated management approach for the whole site. Discussions with Natural England are underway. Contact: Charlotte McLean 01483 252043

TUNBRIDGE WELLS / WEALDEN




SITE NAME:	Bayham Abbey, Lamberhurst / Frant
DESIGNATION:	Registered Park and Garden Grade II, also 7 LBs, 1 SM
CONDITION:	Unknown
VULNERABILITY:	Medium
TREND:	Declining
OWNERSHIP:	Mixed, multiple owners

Late C19 mansion gardens with formal terraces and informal pleasure ground all set within a Humphry Repton park focussed on the abbey ruins. The property was divided and sold in the 1970s and further fragmented since then. English Heritage looks after the abbey ruins but fragmentation of ownership has severely compromised this significant picturesque landscape. Co-ordinated action is needed to conserve the historic landscape – part of which lies in East Sussex and part in Kent. Contact: Charlotte McLean 01483 252043

TUNBRIDGE WELLS

SITE NAME:	Royal Tunbridge Wells	CONDITION:	At risk
DESIGNATION:	Conservation Area	TREND:	Deteriorating
VULNERABILITY:	Unknown		
CONTACT:	Alan Legg (LA) 01892 554069		

OFF KENT




SITE NAME:	London, Thames Estuary
DESIGNATION:	Protected Wreck Site
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Natural decline
OWNERSHIP:	Government
PHOTO:	© Wessex Archaeology and the Port of London Authority

The London was a Second Rate 'Large Ship' built in Chatham in 1654 during the Interregnum. She is known to have participated in the First Dutch War (1652-4) and later formed part of an English Squadron sent to collect Charles II from the Netherlands and restore him to his throne. The London blew up on passage from Chatham in March 1665. A series of artefacts have been identified on the river bed and recovered to the surface. In addition, an abundance of loose material on the bottom has been noted in a remarkably well preserved state. This suggests that the site has been recently disturbed. Contact: Simon Goodhugh 01483 252037



SITE NAME:	Northumberland, Goodwin Sands
DESIGNATION:	Protected Wreck Site
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Significant decline
OWNERSHIP:	Government
PHOTO:	© Wessex Archaeology

Third Rate 70-gun warship built 1678 as part of Samuel Pepys' regeneration of the English navy. The first third rate ship to be built under contract, after it was realised that the naval dockyards could not cope with the construction of the number of ships requested. She foundered on Goodwin Sands during the 'Great Storm' of 1703. The Goodwin Sands change morphology on a seasonal basis leading to periodic exposure of the vessel's wooden hulls. Exposed timbers are weakened by biological attack and may be subject to detachment and dispersal by tide and wave surge during winter storms. Contact: Simon Goodhugh 01483 252037



SITE NAME:	Restoration, Goodwin Sands
DESIGNATION:	Protected Wreck Site
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Significant decline
OWNERSHIP:	Government
PHOTO:	© University of St Andrews and Wessex Archaeology

Although there is no definite evidence, this wreck of a wooden warship is thought to be the remains of the Restoration, a Third Rate 70-gun warship built 1678 as part of Samuel Pepys' regeneration of the English navy. Along with the Northumberland and Stirling Castle, she foundered on Goodwin Sands during the 'Great Storm' of 1703. The Goodwin Sands change morphology on a seasonal basis leading to periodic exposure of the vessel's wooden hulls. Exposed timbers are weakened by biological attack and may be subject to detachment and dispersal by tide and wave surge during winter storms. Contact: Simon Goodhugh 01483 252037

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	Rooswijk, Goodwin Sands
DESIGNATION:	Protected Wreck Site
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	High
TREND:	Natural decline
OWNERSHIP:	Private
PHOTO:	© Private

The VOC (Dutch East Company) ship Rooswijk was built in Amsterdam in 1737 but stranded on the Goodwin Sands in 1739 while en route from the Texel to the East Indies. The site represents archaeological evidence for the practice of large-scale overseas commerce between the Netherlands and Asia during the C18. As with other sites in the Goodwins, archaeological material is at risk owing to mobile sediments causing periodic exposure.

Contact: Simon Goodhugh 01483 252037



SITE NAME:	Stirling Castle, Goodwin Sands
DESIGNATION:	Protected Wreck Site
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Significant decline
OWNERSHIP:	Trust
PHOTO:	© Seadive

One of twenty Third Rate 70-gun warships built 1678 at Deptford as part of Samuel Pepys' regeneration of the English navy. Like the Northumberland and the Restoration she was rebuilt at Chatham in 1699. All three ships foundered on the Goodwin Sands during the 'Great Storm' of 1703.

Contact: Simon Goodhugh 01483 252037

MEDWAY (UA)



SITE NAME:	The Chapel of St Bartholomew, High Street, Chatham
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Vacant
PRIORITY:	D (D)
OWNERSHIP:	Private

Hospital Chapel since C12. Now vacant, but potentially for sale.

Contact: Tom Foxall 01483 252035



SITE NAME:	Cliffe Fort, Cliffe
DESIGNATION:	Scheduled Monument
CONDITION:	Very bad
OCCUPANCY:	Vacant
PRIORITY:	C (C)
OWNERSHIP:	Company

Fort circa 1860. Fabric is derelict but stable due to massive construction. Remains of Brennan Torpedo Rail, said to be the best surviving example, are vulnerable. Surrounded by gravel pits.

Contact: Peter Kendall 01483 252038



SITE NAME:	Cooling Castle, Cooling
DESIGNATION:	Listed Building Grade I, SM
CONDITION:	Very bad
OCCUPANCY:	Part occupied
PRIORITY:	A (A)
OWNERSHIP:	Private

A quadrangular castle with ruined fabric and in need of major repair. Includes C14 gatehouse repaired with English Heritage grant.

Contact: Peter Kendall 01483 252038



SITE NAME:	Barn 30 yards south east of the manor, Upnor Road (south side), Frindsbury Extra
DESIGNATION:	Listed Building Grade I, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant
PRIORITY:	A (A)
OWNERSHIP:	Private

Very fine medieval barn, more or less redundant for agricultural use. Subject to fire damage.

Contact: Tom Foxall 01483 252035

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME: **Brompton Lines, Gillingham**

DESIGNATION: ,Scheduled Monument, CA,

CONDITION: Poor

OCCUPANCY: Not applicable

PRIORITY: D (D)

OWNERSHIP: Government

Landward defences to dockyard at Chatham, subsequently used in part as a pleasure ground for officers. Now cross Ministry of Defence owned land, housing and Brompton Barracks. Lower lines site now released to new owner. Discussions continue about management of retained MOD parts.

Contact: Peter Kendall 01483 252038



SITE NAME: **Fort Darnet, Gillingham**

DESIGNATION: Scheduled Monument

CONDITION: Very bad

OCCUPANCY: Vacant

PRIORITY: A (A)

OWNERSHIP: Private

A Royal Commission fort circa 1860, in the Medway Estuary, washed by high tides.

Contact: Peter Kendall 01483 252038



SITE NAME: **No. 8 machine shop, Dock Head Road, Chatham Dockyard, Gillingham**

DESIGNATION: Listed Building Grade II*

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNERSHIP: Quango

1840 former dry dock cover; later used as Machine Shop, now disused. Cladding removed and awaiting solution.

Contact: Tom Foxall 01483 252035



SITE NAME: **Cockham Wood Fort, Hoo St Werburgh**

DESIGNATION: Scheduled Monument

CONDITION: Very bad

OCCUPANCY: Vacant

PRIORITY: A (A)

OWNERSHIP: Private

A rare C17 artillery fort. The brick lower battery is very decayed as it is washed by the tidal Medway. The higher earthwork batteries survive but in woodland, with the remains of a redoubt and commander's house.

Contact: Peter Kendall 01483 252038



SITE NAME: **Fort Hoo, Hoo St Werburgh**

DESIGNATION: Scheduled Monument

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNERSHIP: Company

Sister fort to Fort Darnet circa 1860. Fort lies abandoned on an island in the Medway.

Contact: Peter Kendall 01483 252038



SITE NAME: **Artillery Tower (Grain Tower), Isle of Grain**

DESIGNATION: Listed Building Grade II, SM

CONDITION: Very bad

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNERSHIP: Private

Artillery tower. Late 1840s to early 1850s. Forms part of the defences to Sheerness dockyard. Abandoned and surrounded by the sea at high tide.

Contact: Peter Kendall 01483 252038

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

- CA Conservation Area
- LB/LBs Listed Building/s
- NP National Park
- RPG Registered Park and Garden
- SM/SMs Scheduled Monument/s
- UA Unitary Authority
- WHS World Heritage Site



SITE NAME:	Brompton Lines (Fort Amherst), Rochester
DESIGNATION:	Scheduled Monument, CA,
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	B (B)
OWNERSHIP:	Trust

Part of the major C18 landward defence to the dockyard at Chatham. Open periodically to the public. Grants from English Heritage and local authority have conserved main part but significant areas still derelict.

Contact: Peter Kendall 01483 252038



SITE NAME:	351 High Street, Rochester
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	E (E)
OWNERSHIP:	Company

Early C18 town house, last used as a shop in 1980s. Empty since then, but a programme of repairs is currently under discussion.

Contact: Tom Foxall 01483 252035



SITE NAME:	Priors Gate, The Precinct, Rochester
DESIGNATION:	Listed Building Grade I, SM, CA
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	F (C)
OWNERSHIP:	Trust

Medieval gatehouse, 1344, forming the south entrance to the precincts of the Cathedral. Signs of structural movement. Recording undertaken and repairs are now underway.

Contact: Peter Kendall 01483 252038

MILTON KEYNES (UA)



SITE NAME:	Orchard House, 67 and 69 High Street, Olney
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	A (New)
OWNERSHIP:	Private

Pair of C18 houses converted into a single dwelling in 1904 by Ellis Anderson for Joseph William Mann. Impressive and exceptionally complete Edwardian interior: Flat roofs, parapet gutters and hip and valley soakers are all failing and both stonework and interior plasterwork are being damaged by water ingress.

Contact: Richard Peats 01483 252026

SITE NAME:

Roman town of Magiovinium and Roman fort, Bletchley and Fenny Stratford

DESIGNATION:	Scheduled Monument (No. MK82)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:

Wood Farm moat, Clifton Reynes

DESIGNATION:	Scheduled Monument (No. MK128)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:

St Martin's Church (site of), Emberton

DESIGNATION:	Scheduled Monument (No. 35359)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Roman villa 300m south east of Newton Lodge Farm, Newton Blossomville		
DESIGNATION:	Scheduled Monument (No. 27158)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Roman site at Olney, Olney		
DESIGNATION:	Scheduled Monument (No. MK127)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Group of ring ditches and enclosures at Tyringham, Tyringham and Filgrave		
DESIGNATION:	Scheduled Monument (No. MK142)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

OXFORDSHIRE

CHERWELL



SITE NAME: **Hampton Gay Manor House,
Hampton Gay,
Hampton Gay and Poyle**

Manor house, late C16. Burnt down in 1887.
Now a roofless ruin.

DESIGNATION: Listed Building Grade II, SM

CONDITION: Very bad

OCCUPANCY: Not applicable

PRIORITY: A (A)

OWNERSHIP: Private

Contact: Chris Welch 01483 252027

SITE NAME:	Ilbury Camp hillfort, Deddington		
DESIGNATION:	Scheduled Monument (No. 28139)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Islip Roman villa, 300m east of Hillside Farm, Islip		
DESIGNATION:	Scheduled Monument (No. 28136)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	RAF Bicester: World War II airfield, Laughton		
DESIGNATION:	Scheduled Monument (No. 30907)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Chris Welch 01483 252027

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Castle Bank Enclosure		
DESIGNATION:	Scheduled Monument (No. 30875)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Blenheim Villa, a Roman villa and associated field system 200m north east of Little Cote, Shipton-on-Cherwell and Thrupp		
DESIGNATION:	Scheduled Monument (No. 35545)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Long barrow 730m south west of Enslow Bridge, Shipton-on-Cherwell and Thrupp		
DESIGNATION:	Scheduled Monument (No. 30873)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

OXFORD



SITE NAME: **Osney Abbey,
Mill Street,
Oxford**

Only surviving building of Augustinian Priory, founded 1129. Rubble and timber framed building, probably C15, with C16 roof. Attached wall with C15 archway. Currently included in discussions over the wider Osney Mill site.

DESIGNATION: Listed Building Grade II, SM
CONDITION: Fair
OCCUPANCY: Part occupied
PRIORITY: C (C)
OWNERSHIP: Company

Contact: Chris Welch 01483 252027

SOUTH OXFORDSHIRE



SITE NAME: **Bix Old Church,
Bix,
Bix and Assendon**

Ruins of church of St James. Norman chancel with later additions. Very overgrown. Roofless, with considerable collapse at west end. Further collapse likely. English Heritage Section 17 management agreement with PCC to control vegetation (2010).

DESIGNATION: Listed Building Grade II, SM
CONDITION: Very bad
OCCUPANCY: Not applicable
PRIORITY: A (A)
OWNERSHIP: Religious organisation

Contact: Chris Welch 01483 252027

SITE NAME: **Gothic Temple,
Shotover Park,
Forest Hill with Shotover**

Gothic Temple within the grade I Shotover Park, designed as a garden temple or boathouse c1740, by William Townsend of Oxford (?) for General James Tyrrell in Gothick style. The temple lies at the eastern end of the main axis of the early C18 layout of the formal garden. Front repaired 10 years ago but rear structure in need of repairs to roof and rainwater goods. Conservation Management Plan completed 2009.

DESIGNATION: Listed Building Grade II*
CONDITION: Poor
OCCUPANCY: Not applicable
PRIORITY: C (C)
OWNERSHIP: Private

Contact: Richard Peats 01483 252026



SITE NAME: **Walled garden approximately
30 metres west of manor,
North Weston, Great Haseley**

Walled garden with loggia dating from early C18. Built of brick with limestone ashlar details and a plain tile roof to the loggia. The wall has a moulded brick coping. It was formerly part of the North Weston Manor which was largely demolished in early C19. The wall tops are disintegrating; there are structural cracks and the loggia is propped to prevent collapse.

DESIGNATION: Listed Building Grade II*
CONDITION: Very bad
OCCUPANCY: Not applicable
PRIORITY: A (A)
OWNERSHIP: Private

Contact: Richard Peats 01483 252026

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHs	World Heritage Site



SITE NAME: **Fernhouse, archway, gateway and walls, The Street, Mapledurham**

Fernhouse, archway, gateway and walls. C17 and C18. The Fernhouse is roofless, although recent consolidation has taken place to the parapet.

DESIGNATION: Listed Building Grade II*, CA

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNERSHIP: Private

Contact: Richard Peats 01483 252026

SITE NAME: **North Stoke henge and ring ditch site, Crowmarsh**

DESIGNATION: Scheduled Monument (No. OX121)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Chris Welch 01483 252027

SITE NAME: **Dike Hills, Dorchester**

DESIGNATION: Scheduled Monument (No. OX17)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Extensive animal burrowing

TREND: Declining

OWNERSHIP: Private

CONTACT: Chris Welch 01483 252027

SITE NAME: **Ring ditches, cursus, enclosures and settlement site, Dorchester**

DESIGNATION: Scheduled Monument (No. OX144)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Chris Welch 01483 252027

SITE NAME: **Settlement site at Northfield Farm, Long Wittenham**

DESIGNATION: Scheduled Monument (No. OX180)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Chris Welch 01483 252027

SITE NAME: **Site of Roman kilns, Marsh Baldon**

DESIGNATION: Scheduled Monument (No. OX132)

CONDITION: Generally satisfactory
but with significant localised problems

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Chris Welch 01483 252027

SITE NAME: **Church Piece cemetery site, Warborough**

DESIGNATION: Scheduled Monument (No. OX186)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Chris Welch 01483 252027

SITE NAME: **Long barrow 140m north west of Cooks Cottages, Warborough**

DESIGNATION: Scheduled Monument (No. 31431)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Chris Welch 01483 252027

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Long barrow 340m north west of Cooks Cottages, Warborough		
DESIGNATION:	Scheduled Monument (No. 31435)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Romano-British settlement 520m north west of Cooks Cottages, Warborough		
DESIGNATION:	Scheduled Monument (No. 31432)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Thomley deserted medieval village, Waterperry with Thomley		
DESIGNATION:	Scheduled Monument (No. OX237)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Camp on Bozedown, Whitchurch on Thames		
DESIGNATION:	Scheduled Monument (No. OX130)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

VALE OF WHITE HORSE

SITE NAME:	Castle mound at Fitzharris, Abingdon		
DESIGNATION:	Scheduled Monument (No. OX222)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Sutton Wick settlement site, Abingdon		
DESIGNATION:	Scheduled Monument (No. OX242)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Settlement site south east of church, Appleford-on-Thames		
DESIGNATION:	Scheduled Monument (No. OX243)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Settlement site, Drayton		
DESIGNATION:	Scheduled Monument (No. OX248)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	East Hendred Down bowl barrow, East Hendred		
DESIGNATION:	Scheduled Monument (No. 28193)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Yew Down round barrow 950m south west of Butterbush Reservoir, Lockinge		
DESIGNATION:	Scheduled Monument (No. 28194)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Settlement site north of Cow Lane, Marcham		
DESIGNATION:	Scheduled Monument (No. OX245)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Disc barrow 700m north east of Sevenbarrows House: part of the Seven Barrows cemetery, Sparsholt		
DESIGNATION:	Scheduled Monument (No. 12352)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Roman villa east of Cornhill Farm, West Challow		
DESIGNATION:	Scheduled Monument (No. OX251)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

WEST OXFORDSHIRE

SITE NAME:	Iron Age settlement centring 500m south west of Black Bourton, Alvescot		
DESIGNATION:	Scheduled Monument (No. OX157)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Asthall Barrow: an Anglo-Saxon burial mound 100m SSW of Barrow Farm, Asthal		
DESIGNATION:	Scheduled Monument (No. 21797)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Pair of confluent bowl barrows 200m SSW of Bockett's Corner on Leigh Hale Plain, Asthal		
DESIGNATION:	Scheduled Monument (No. 21788)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Ring ditches, Aston, Cote, Shifford and Chimney		
DESIGNATION:	Scheduled Monument (No. OX137)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Interrupted ditch system, Broadwell		
DESIGNATION:	Scheduled Monument (No. OX136)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Bowl barrow 525m north of Barter's Hill Farm, Chadlington		
DESIGNATION:	Scheduled Monument (No. 28118)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Besbury Lane bowl barrow, 450m north east of Conduit Farm, Churchill		
DESIGNATION:	Scheduled Monument (No. 28151)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	One of a pair of bowl barrows 370m north west of High Lodge, Cornbury and Wychwood		
DESIGNATION:	Scheduled Monument (No. 21771)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	One of a pair of bowl barrows 370m north west of High Lodge, Cornbury and Wychwood		
DESIGNATION:	Scheduled Monument (No. 21789)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Sites discovered by aerial photography, near Foxley Farm, Eynsham		
DESIGNATION:	Scheduled Monument (No. OX119)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Oaklands Farm Roman villa, Fawler		
DESIGNATION:	Scheduled Monument (No. 21818)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:		Linear earthworks east of Callow Hill Roman villa forming part of the north Oxfordshire Grim's Ditch, Glympton	
DESIGNATION:	Scheduled Monument (No. 28127)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027
SITE NAME:		Ring ditches, Grafton and Radcot	
DESIGNATION:	Scheduled Monument (No. OX135)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027
SITE NAME:		Beaconsfield Farm Roman villa, Great Tew	
DESIGNATION:	Scheduled Monument (No. OX96)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027
SITE NAME:		145m section of the north Oxfordshire Grim's Ditch situated 200m west of Grimsdyke Farm, Kiddington with Asterleigh	
DESIGNATION:	Scheduled Monument (No. 21849)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027
SITE NAME:		Medieval settlement and church of Asterleigh, Kiddington with Asterleigh	
DESIGNATION:	Scheduled Monument (No. 30837)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027
SITE NAME:		Pump Copse earthwork, Kiddington with Asterleigh	
DESIGNATION:	Scheduled Monument (No. OX57)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027
SITE NAME:		Enclosures and trackways, Langford	
DESIGNATION:	Scheduled Monument (No. OX179)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027
SITE NAME:		Rectangular enclosures 1100yds (1010m) north west of Mount Owen Farm, Lew	
DESIGNATION:	Scheduled Monument (No. OX77)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Enclosures 1500m south east of Little Faringdon, Little Faringdon		
DESIGNATION:	Scheduled Monument (No. OX156)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Skew Plantation bowl barrow, Sarsden		
DESIGNATION:	Scheduled Monument (No. 28149)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Complex of rectangular enclosures, ring ditches and tracks, Standlake		
DESIGNATION:	Scheduled Monument (No. OX140)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Callow Hill Roman villa, Stonesfield		
DESIGNATION:	Scheduled Monument (No. 28126)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	90m section of the north Oxfordshire Grim's Ditch 350m south of Grim's Dyke Farm, Wootton		
DESIGNATION:	Scheduled Monument (No. 21853)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Aston		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Richard Wheeler (LA) 01993 770247		

SITE NAME:	Bampton		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Richard Wheeler (LA) 01993 770247		

SITE NAME:	Great Tew		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Richard Wheeler (LA) 01993 770247		

SITE NAME:	Stonesfield		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Richard Wheeler (LA) 01993 770247		

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Taynton		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Richard Wheeler (LA) 01993 770247		

SITE NAME:	Witney and Cogges		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Richard Wheeler (LA) 01993 770247		

PORTSMOUTH, CITY OF (UA)



SITE NAME: **The Beneficial School,
Kent Street, Portsea,
Portsmouth**

Charity school, 1784 and 1836. Now being converted to a dance-drama school.

DESIGNATION: Listed Building Grade II*, CA

CONDITION: Fair

OCCUPANCY: Occupied

PRIORITY: D (C)

OWNERSHIP: Company

Contact: David Brock 01483 252044



SITE NAME: **Fort Southwick,
moat and ramparts,
Portsdown Hill, Portsmouth**

Fort circa 1860s. Part of Palmerston's Portsmouth defences. In poor condition in parts. Fort is now in private ownership following disposal by Defence Estate, and has benefited from a recent programme of repair and consolidation.

DESIGNATION: Listed Building Grade I, SM

CONDITION: Fair

OCCUPANCY: Part occupied

PRIORITY: F (F)

OWNERSHIP: Trust

Contact: Richard Massey 01483 252046



SITE NAME: **Fort Cumberland,
Fort Cumberland Road,
Eastney, Portsmouth**

Coastal fort of 1746-1812 with later buildings and features. Some repairs have been carried out, and the number of buildings being used by the Centre for Archaeology and others has increased. The Guardhouse, a stand-alone structure with the Fort Cumberland complex and the only surviving element of the 1747 Demarets Fort, is suffering from water ingress and associated decay.

DESIGNATION: Listed Building Grade II*, SM

CONDITION: Poor

OCCUPANCY: Part occupied

PRIORITY: F (F)

OWNERSHIP: English Heritage

Contact: Richard Massey 01483 252046



SITE NAME: **Hilsea Lines – Bastion No. 5,
Hilsea, Portsmouth**

Earthwork defence dating from 1858-1869, with batteries, magazines and barracks. Bastion No. 5 is continuing to suffer from vandalism and neglect.

DESIGNATION: Scheduled Monument, CA

CONDITION: Poor

OCCUPANCY: Not applicable

PRIORITY: A (A)

OWNERSHIP: Local authority

Contact: Richard Massey 01483 252046



SITE NAME: **No. 25 Store, Yard Services Manager's
Office, 1/118 Jago Road,
HM Naval Base, Portsmouth**

Two storey storehouse of 1782, with internal courtyard. In fair condition but vacant. Future use uncertain.

DESIGNATION: Listed Building Grade II*, CA

CONDITION: Fair

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNERSHIP: Government

Contact: Alan Johnson 020 7973 3174

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	2-8 The Parade, HM Naval Base, Portsmouth
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	A (C)
OWNERSHIP:	Government

Terrace of dockyard officers' lodgings, 1715-19. Partially converted to office use c1995, but now empty. Prone to wet rot and some structural movement. An options report is said to have been drawn up. A repairs schedule promised by May 2009 has not been circulated, so the risk category has been raised from C to A.

Contact: Rory O'Donnell 020 7973 3775



SITE NAME:	Iron and Brass Foundry, 1/140 Victoria Road, HM Naval Base, Portsmouth
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Part occupied
PRIORITY:	C (C)
OWNERSHIP:	Government

The main part of the building was converted to office use in 2003. The east wing (Building 1/136) remains unused and at risk. There are concerns over water ingress.

Contact: Alan Johnson 020 7973 3174



SITE NAME:	No. 6 Dock, Basin No. 1, Portsmouth Dockyard, Portsmouth
DESIGNATION:	Listed Building Grade I, SM, CA
CONDITION:	Poor
OCCUPANCY:	Not applicable
PRIORITY:	C (C)
OWNERSHIP:	Government

Naval dock c1690 rebuilt 1737, immediately adjacent to the Block Mills. The dock is suffering from rotation and mortar joints on the stonework altars on the north side have opened up.

Contact: Rory O'Donnell 020 7973 3775



SITE NAME:	Horse Sand Fort, Solent, Portsmouth
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	C (C)
OWNERSHIP:	Company

C19 sea fort in state of dereliction. Owned by private company which is looking to convert the property.

Contact: Richard Massey 01483 252046



SITE NAME:	Spitbank Fort, Solent, Portsmouth
DESIGNATION:	Scheduled Monument
CONDITION:	Fair
OCCUPANCY:	Occupied
PRIORITY:	C (C)
OWNERSHIP:	Company

C19 Solent sea fort. Used as a tourist attraction. In need of repair.

Contact: Richard Massey 01483 252046

READING (UA)



SITE NAME:	Chazey Farm barn, The Warren, Reading
DESIGNATION:	Listed Building Grade I
CONDITION:	Very bad
OCCUPANCY:	Vacant
PRIORITY:	A (A)
OWNERSHIP:	Company

A very large seven bay red brick barn C17 or earlier. Structural cracking and gable currently has temporary shoring. The building forms part of a larger site proposal for a healthcare development. Ground works for new development undertaken spring 2010. No works to barn.

Contact: Richard Peats 01483 252026

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Reading Abbey: a Cluniac and Benedictine monastery and Civil War earthwork, Reading		
DESIGNATION:	Scheduled Monument (No. 19019)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Chris Welch 01483 252027

SOUTHAMPTON, CITY OF (UA)



SITE NAME: **Chapel Mills,
American Wharf,
Elm Street, Southampton**

Former steam mill, 1781 and 1800, built to produce ship's biscuits for the Navy. Now used as storage and suffering from lack of maintenance. An application for domestic use is being tested at Inquiry: flood risk is an issue.

DESIGNATION: Listed Building Grade II*

CONDITION: Poor

OCCUPANCY: Occupied

PRIORITY: C (C)

OWNERSHIP: Company

Contact: David Brock 01483 252044



SITE NAME: **Red Lion Public House,
55 High Street,
Southampton**

C15 hall house now commercial premises, suffering from water ingress and deferred maintenance.

DESIGNATION: Listed Building Grade II*

CONDITION: Poor

OCCUPANCY: Part occupied

PRIORITY: C (C)

OWNERSHIP: Private

Contact: David Brock 01483 252044

SURREY

ELMBRIDGE



SITE NAME: **Former kitchen garden walls
to Claremont House,
Claremont Park Road, Esher**

Garden walls, 1717 by Vanbrugh. Unusually monumental. Suffering from vegetation and mortar loss and in need of general repair.

DESIGNATION: Listed Building Grade II*

CONDITION: Poor

OCCUPANCY: Not applicable

PRIORITY: C (C)

OWNERSHIP: Private

Contact: Andy White 01483 252047



SITE NAME: **The Belvedere,
Claremont Park,
Esher**

Eye-catcher and viewpoint in the form of a mock castle, 1717 by Sir John Vanbrugh. In need of repair to bring it back into use as a focal point of the grade I landscape of Claremont Park.

DESIGNATION: Listed Building Grade II*, SM

CONDITION: Fair

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNERSHIP: Charity

Contact: David Brock 01483 252044

SITE NAME:	Brooklands		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Clare Smith (LA) 01372 474828		

SITE NAME:	Thames Ditton		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Clare Smith (LA) 01372 474828		

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

EPSOM AND EWELL



SITE NAME: **Riding School at The Durdans,
Chalk Lane,
Epsom**

Covered riding school of 1881, designed by George Devey for Lord Rosebery. Last used as part of a stable. The yard is now tenanted and to be repaired.

DESIGNATION: Listed Building Grade II*, CA

CONDITION: Fair

OCCUPANCY: Not applicable

PRIORITY: C (C)

OWNERSHIP: Private

Contact: David Brock 01483 252044

SITE NAME: **Adelphi Road, Linton**

DESIGNATION: Conservation Area

CONDITION: At risk

VULNERABILITY: Unknown

TREND: Deteriorating

CONTACT: Anthony Evans (LA) 01372 732394

SITE NAME: **Church Stree, Worple Road**

DESIGNATION: Conservation Area

CONDITION: At risk

VULNERABILITY: Unknown

TREND: Deteriorating

CONTACT: Anthony Evans (LA) 01372 732394

SITE NAME: **Epsom Town Centre**

DESIGNATION: Conservation Area

CONDITION: At risk

VULNERABILITY: Unknown

TREND: Deteriorating

CONTACT: Anthony Evans (LA) 01372 732394

SITE NAME: **Ewell Village**

DESIGNATION: Conservation Area

CONDITION: At risk

VULNERABILITY: Unknown

TREND: Deteriorating

CONTACT: Anthony Evans (LA) 01372 732394

SITE NAME: **Stamford Green**

DESIGNATION: Conservation Area

CONDITION: At risk

VULNERABILITY: Unknown

TREND: Deteriorating

CONTACT: Anthony Evans (LA) 01372 732394

SITE NAME: **The Manor, Horton Hospital, Long Grove Hospital, St.Ebba**

DESIGNATION: Conservation Area

CONDITION: At risk

VULNERABILITY: Unknown

TREND: Deteriorating

CONTACT: Anthony Evans (LA) 01372 732394

SITE NAME: **Woodcote, Chalk Lane**

DESIGNATION: Conservation Area

CONDITION: At risk

VULNERABILITY: Unknown

TREND: Deteriorating

CONTACT: Anthony Evans (LA) 01372 732394

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
 If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

GUILDFORD



SITE NAME: **The Watts Gallery,
Down Lane,
Compton**

Gallery built in 1904 as a memorial to the painter GF Watts. Major renovation is now proceeding.

DESIGNATION: Listed Building Grade II*

CONDITION: Poor

OCCUPANCY: Occupied

PRIORITY: F (D)

OWNERSHIP: Trust

Contact: David Brock 01483 252044

SITE NAME: **Hillbury hillfort, Puttenham**

DESIGNATION: Scheduled Monument (No. 29296)

CONDITION: Generally unsatisfactory
with major localised problems

PRINCIPAL VULNERABILITY: Scrub / tree growth

TREND: Declining

OWNERSHIP: Private

CONTACT: Richard Massey 01483 252046

SITE NAME: **Large univallate hillfort at Felday, Shere**

DESIGNATION: Scheduled Monument (No. 23014)

CONDITION: Generally unsatisfactory
with major localised problems

PRINCIPAL VULNERABILITY: Scrub / tree growth

TREND: Declining

OWNERSHIP: Private

CONTACT: Richard Massey 01483 252046



SITE NAME: **Clandon Park,
West Clandon**

DESIGNATION: Registered Park and Garden Grade II,
also part in CA, 8 LBs

CONDITION: Extensive significant problems

VULNERABILITY: High

TREND: Declining

OWNERSHIP: Mixed, multiple owners

Lancelot Brown designed Clandon's landscape park c1776-81. The house and garden are now owned by the National Trust but the park is privately owned. It is currently unsympathetically managed thus affecting the overall integrity of the design and the setting of the house. Discussions regarding a proposed business park development and a future landscape Conservation Management Plan, part funded by Natural England, are ongoing but successful resolution of these issues will hopefully reverse the current trajectory.

Contact: Charlotte McLean 01483 252043

MOLE VALLEY



SITE NAME: **Ruins of Betchworth Castle,
Reigate Road,
Betchworth**

Late C17 ruined house built on site of medieval castle. Consolidation required. Emergency works required urgently. Some areas are in danger of imminent collapse.

DESIGNATION: Listed Building Grade II, SM

CONDITION: Poor

OCCUPANCY: Not applicable

PRIORITY: B (B)

OWNERSHIP: Local authority

Contact: Richard Massey 01483 252046



SITE NAME: **Brockham Lime Works,
Brockham**

The remains include an eastern battery of eight kilns and a western battery of two. The eastern battery, originally built in 1870, comprises four pairs of linked flare kilns. The northern two pairs were modified to the Brockham patent, as was the western battery, and comprises the type site for this type of kiln. Parts of the kilns are in a very poor condition but some repairs are planned this summer.

DESIGNATION: Listed Building Grade II, SM

CONDITION: Very bad

OCCUPANCY: Not applicable

PRIORITY: B (A)

OWNERSHIP: Trust

Contact: Richard Massey 01483 252046

SITE NAME: **Lime kilns at Betchworth Quarry, Betchworth**

DESIGNATION: Scheduled Monument (No. 22781)

CONDITION: Generally unsatisfactory
with major localised problems

PRINCIPAL VULNERABILITY: Deterioration – in need of management

TREND: Declining

OWNERSHIP: Private

CONTACT: Richard Massey 01483 252046

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Betchworth Castle, Brockham		
DESIGNATION:	Scheduled Monument (No. 31388)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Anstiebury Camp: a large multivallate hillfort south east of Crockers Farm, Capel		
DESIGNATION:	Scheduled Monument (No. 20186)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Bell barrow in Deerleap Wood, Wotton		
DESIGNATION:	Scheduled Monument (No. 20192)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046



SITE NAME:	Ashted Park, Ashted
DESIGNATION:	Registered Park and Garden Grade II, also part in CA, 19 LBs, 1 SM
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Stable
OWNERSHIP:	Mixed, multiple owners

Begun as a C17 park, Ashted was developed during the C18 and C19 by successive owners. Although the estate was sold as 51 lots in the 1920s, the historic landscape is largely in two ownerships. The main house and surrounds are a school which is preparing a new master plan that, it is hoped, will be informed by an almost complete landscape Conservation Management Plan. The northern park is managed as public open space by Surrey Wildlife Trust who are willing to acknowledge the site's history in management decisions. '

Contact: Charlotte McLean 01483 252043

SITE NAME:	Buckland		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Conservation Team (LA) 01306 879247		

SITE NAME:	Coldharbour		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Conservation Team (LA) 01306 879247		

SITE NAME:	Dorking		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Conservation Team (LA) 01306 879247		

SITE NAME:	Leatherhead		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Conservation Team (LA) 01306 879247		

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
 If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

REIGATE AND BANSTEAD



SITE NAME: **Alderstead (Merstham) Fort, Shepherd's Hill, Reigate**

C19 mobilisation centre, one of 13 constructed on the North Downs for the defence of London. The scheduling comprises the infantry fort and detached tool store. Tree growth and poor drainage are causing problems and the fort has no current use.

DESIGNATION: Scheduled Monument

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNERSHIP: Private

Contact: Richard Massey 01483 252046

SITE NAME:

Walton on the Hill

DESIGNATION: Conservation Area

CONDITION: At risk

VULNERABILITY: Unknown

TREND: Deteriorating

CONTACT: John McNally (LA) 01737 276204

RUNNYMEDE

SITE NAME:

Bronze Age settlement, west of Runnymede Bridge, Runnymede

DESIGNATION: Scheduled Monument (No. SUI79)

CONDITION: Generally satisfactory but with significant localised problems

PRINCIPAL VULNERABILITY: Scrub / tree growth

TREND: Declining

OWNERSHIP: Government or Agency

CONTACT: Richard Massey 01483 252046



SITE NAME: **Woburn Farm, Addlestone**

An Arcadian landscaped 'ferme ornée' designed by Philip Southcote from 1734/5, it was highly influential in the history of garden design but rather ephemeral in nature. The site is now in divided public and private ownership, including a school with intrusive sports facilities, some private residences and an area owned by the local planning authority but leased for various inappropriate uses. A member of the Surrey garden history trust is currently assessing and recording the survival of historic features on site.

DESIGNATION: Registered Park and Garden Grade II, also 5 LBs

CONDITION: Extensive significant problems

VULNERABILITY: Medium

TREND: Declining

OWNERSHIP: Mixed, multiple owners

Contact: Charlotte McLean 01483 252043

TANDRIDGE



SITE NAME: **Bletchingly Castle, Bletchingly**

Norman ringwork and bailey. Some trees are growing too close to the fragile masonry which is in need of consolidation. Owners have previously had plans for development approved. A Conservation Management Plan has also been approved and work now needs to start.

DESIGNATION: Scheduled Monument

CONDITION: Very bad

OCCUPANCY: Not applicable

PRIORITY: D (D)

OWNERSHIP: Private

Contact: Richard Massey 01483 252046

WAVERLEY

SITE NAME:

Four bowl barrows 30m south east of Tilford Barrows: part of The Barrows round barrow cemetery, Tilford

DESIGNATION: Scheduled Monument (No. 20174)

CONDITION: Extensive significant problems i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Scrub / tree growth

TREND: Declining

OWNERSHIP: Private

CONTACT: Richard Massey 01483 252046

SITE NAME:

Peperharow

DESIGNATION: Conservation Area

CONDITION: At risk

VULNERABILITY: Unknown

TREND: Deteriorating

CONTACT: Geraldine Molony (LA) 01483 523308

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

WOKING



SITE NAME:	Brookwood Cemetery, Brookwood
DESIGNATION:	Registered Park and Garden Grade I, also CA, 18 LBs
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Declining
OWNERSHIP:	Mixed, multiple owners

The largest cemetery in England, founded in 1852 to house London's dead. Part remains a working cemetery and is owned by a limited company. The scale of maintenance and restoration work required is immense. With the help of Woking Borough Council, the company is about to commission a landscape conservation management plan, partly funded by English Heritage. This will help the company to prioritise work, engage with other owners, and fulfil their ambitions to restore this historic site.'

Contact: Charlotte McLean 01483 252043

WEST BERKSHIRE (UA)



SITE NAME:	Chapel of St Leonard, east of Manor Farmhouse, Brimpton Road, Brimpton
DESIGNATION:	Listed Building Grade II*, SM
CONDITION:	Good
OCCUPANCY:	Vacant
PRIORITY:	E (E)
OWNERSHIP:	Private

Chapel. C12 and later. Structure is generally sound, with repair programme completed. Planning permission and scheduled monument consent granted for sympathetic conversion to office use.

Contact: Chris Welch 01483 252027



SITE NAME:	Pair of gate piers 103 metres south of east end of church, Park Lane, Hamstead Marshall
DESIGNATION:	Listed Building Grade I, RPG II
CONDITION:	Very bad
OCCUPANCY:	Not applicable
PRIORITY:	A (A)
OWNERSHIP:	Private

Gate piers (built before 1718) to C17 house, burnt down in 1718. The gate piers remain in the north west corner of the park. Stone cornice eroded in places with open joints and weed growth. The landscape is generally in good condition, but other pairs of gate piers and C17 walled gardens are also at risk.

Contact: Richard Peats 01483 252026



SITE NAME:	Pair of gate piers 204 metres east of entrance to Home Farm, Park Lane, Hamstead Marshall
DESIGNATION:	Listed Building Grade I, RPG II
CONDITION:	Poor
OCCUPANCY:	Not applicable
PRIORITY:	C (C)
OWNERSHIP:	Private

Gate piers (built before 1718) to C17 house, burnt down in 1718. The gate piers remain in the north west corner of the park. Some of the bricks have eroded. The landscape is generally in good condition, but three other pairs of gate piers and the C17 walled garden are also at risk.

Contact: Richard Peats 01483 252026



SITE NAME:	Pair of gate piers 210 metres south of church tower, Park Lane, Hamstead Marshall
DESIGNATION:	Listed Building Grade I, RPG II
CONDITION:	Poor
OCCUPANCY:	Not applicable
PRIORITY:	C (C)
OWNERSHIP:	Private

Gate piers (built before 1718) to C17 house, burnt down in 1718. The gate piers remain in the north west corner of the park. The landscape is generally in good condition, but five other pairs of gate piers and the C17 walled gardens are also at risk. The stonework is in poor condition and a section of cornice has fallen away.

Contact: Richard Peats 01483 252026



SITE NAME:	Pair of gate piers 30 metres south of east end of church, Park Lane, Hamstead Marshall
DESIGNATION:	Listed Building Grade I, RPG II
CONDITION:	Very bad
OCCUPANCY:	Not applicable
PRIORITY:	A (A)
OWNERSHIP:	Private

Gate piers (built before 1718) to C17 house, burnt down in 1718. The gate piers remain in the north west corner of the park. Bricks and pointing have eroded and the stone cornices are damaged. Shrubs are growing from the joints. A section of the base and the pier corner has fallen away. The landscape is generally in good condition, but other pairs of gate piers and the C17 walled gardens are also at risk.

Contact: Richard Peats 01483 252026

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME: **Three pairs of gate piers and walls around gardens and terrace at Home Farm, Park Lane, Hamstead Marshall**

DESIGNATION: Listed Building Grade I, RPG II

CONDITION: Very bad

OCCUPANCY: Not applicable

PRIORITY: C (C)

OWNERSHIP: Private

Two late C17 walled gardens (one with raised terrace) and three pairs of gate piers located in the north west corner of the park. Formerly the gardens to the C17 house, burnt down in 1718. Used by the C19 as kitchen gardens for Hamstead Lodge. The walls are in joint ownership. Some sections have open joints. One of the gate piers has weed growth to the cornice. Parts are being repaired.

Contact: Richard Peats 01483 252026

SITE NAME: **Round barrow cemetery at Brimpton Common, Brimpton**

DESIGNATION: Scheduled Monument (No. 12074)

CONDITION: Generally satisfactory but with significant localised problems

PRINCIPAL VULNERABILITY: Moderate visitor erosion

TREND: Declining

OWNERSHIP: Private

CONTACT: Chris Welch 01483 252027

SITE NAME: **Long barrow at Combe Gibbet, Gallows Down, Combe**

DESIGNATION: Scheduled Monument (No. 12001)

CONDITION: Generally satisfactory but with significant localised problems

PRINCIPAL VULNERABILITY: Extensive vehicle damage/erosion

TREND: Declining

OWNERSHIP: Private

CONTACT: Chris Welch 01483 252027

SITE NAME: **East Ilsley Down round barrows, East Ilsley**

DESIGNATION: Scheduled Monument (No. WB111)

CONDITION: Extensive significant problems i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Chris Welch 01483 252027

SITE NAME: **Long barrow on Sheep Down, 1km north of East Ilsley, East Ilsley**

DESIGNATION: Scheduled Monument (No. 12016)

CONDITION: Generally unsatisfactory with major localised problems

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Chris Welch 01483 252027

SITE NAME: **Bowl barrow 30m north of Bitham Lane, Inkpen**

DESIGNATION: Scheduled Monument (No. 19026)

CONDITION: Extensive significant problems i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Chris Welch 01483 252027

SITE NAME: **Membury Camp, Lambourn (part in Wiltshire (UA))**

DESIGNATION: Scheduled Monument (No. WB199)

CONDITION: Extensive significant problems i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Chris Welch 01483 252027

SITE NAME: **Two bowl barrows 500m north east of Stancombe Farm, Lambourn**

DESIGNATION: Scheduled Monument (No. 12069)

CONDITION: Generally unsatisfactory with major localised problems

PRINCIPAL VULNERABILITY: Extensive animal burrowing

TREND: Declining

OWNERSHIP: Private

CONTACT: Chris Welch 01483 252027

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	Aldermaston Court, Aldermaston
DESIGNATION:	Registered Park and Garden Grade II, also part in CA, 11 LBs
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	Medium
TREND:	Declining
OWNERSHIP:	Corporate, single owner

An important mid/late C19 landscape with remains of C17/C18 pleasure grounds relating to an earlier manor house. Following WWII, the Victorian mansion house was sold for corporate use then converted into a hotel and conference centre. The registered area is a fragment of an extensive park. It is owned by one owner but leased to two tenants. A perceived lack of beneficial use and resources threaten this landscape. A conservation led approach to management is required.

Contact: Charlotte McLean 01483 252043



SITE NAME:	Sandleford Priory, Greenham
DESIGNATION:	Registered Park and Garden Grade II, also 2 LBs
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Declining
OWNERSHIP:	Mixed, multiple owners

A mid/late C18 landscape laid out to designs by Lancelot Brown, surrounding a Gothick house remodelled by James Wyatt. In 1947 the estate was sold into divided ownership, the house, gardens and core of the park being used as a school. Other ownerships have fallen prey to development (housing, waste disposal) leaving the core compromised as a design fragment which in turn is under-resourced in its management. The setting of the house and park and garden is extremely vulnerable to development.

Contact: Charlotte McLean 01483 252043



SITE NAME:	Shaw House, Shaw cum Donnington
DESIGNATION:	Registered Park and Garden Grade II, also CA, 6 LBs
CONDITION:	Extensive significant problems
VULNERABILITY:	Medium
TREND:	Declining
OWNERSHIP:	Local Authority, single owner

This site consists of rare earthworks of a late C16 or early C17 garden laid out by the Dolman family and a complex of early C18 water gardens by the Duke of Chandos. Shaw House is now restored, with Heritage Lottery Fund and English Heritage grant aid, as a conference centre and heritage attraction. The local authority need help and additional funding to restore all the garden areas and to integrate the proposed new facilities within them.'

Contact: Charlotte McLean 01483 252043



SITE NAME:	First Battle of Newbury, Enborne / Newbury / Speen
DESIGNATION:	Registered Battlefield
TREND:	Stable
OWNERSHIP:	Private

Site of the 164 First Battle of Newbury (English Civil War) between Parliamentary and Royalist forces. This battle probably represented the best chance King Charles ever had of winning the Civil War. It marked the turning point of the whole war and is accordingly an important place in English history. Already some of the south eastern periphery of the battlefield is built over and the A34 Newbury bypass clips a corner of it. The battlefield is principally at risk from development pressures for housing; strategic locations elsewhere are limited by risk of flooding and AONB and other environmental designation.

Contact: Simon Goodhugh 01483 252037

WEST SUSSEX

ADUR



SITE NAME:	Shoreham Old Fort, Old Fort Road, Shoreham by Sea
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	D (C)
OWNERSHIP:	Company

C19 fort, with later coastguards' observation post. Fort is vulnerable to vandalism and the elements. Parts are beginning to deteriorate badly. Proposals for repair being agreed.

Contact: Richard Massey 01483 252046

ARUN



SITE NAME:	Maison Dieu, Mill Road, Arundel
DESIGNATION:	Listed Building Grade II, SM, CA
CONDITION:	Very bad
OCCUPANCY:	Not applicable
PRIORITY:	B (A)
OWNERSHIP:	Private

C14 remains of the former hospital of the Holy Trinity. The monument is in two distinct parts, with different owners, divided by a road. One part is in a fair condition and not deemed to be at risk, whilst the other is in very bad condition but grant has been offered to investigate what repairs are needed.

Contact: Richard Massey 01483 252046

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
 If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME: **Littlehampton Fort,
Littlehampton**

Fort C19. The fort is partly covered in ivy which poses the main threat to the building. Part of the fort is engulfed by sand dunes which have Site of Special Scientific Interest status.

DESIGNATION: Scheduled Monument

CONDITION: Poor

OCCUPANCY: Not applicable

PRIORITY: C (C)

OWNERSHIP: Private

Contact: Richard Massey 01483 252046

SITE NAME: **Romano-British villa and traces of Iron Age occupation 500m WSW of New Barn, Angmering**

DESIGNATION: Scheduled Monument (No. 29240)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Richard Massey 01483 252046

SITE NAME: **Flint mine and a bowl barrow on Church Hill, 400m south west of Findon Place, Findon**

DESIGNATION: Scheduled Monument (No. 29245)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Richard Massey 01483 252046

SITE NAME: **Itford Hill style settlement on Cock Hill, Patching**

DESIGNATION: Scheduled Monument (No. 29272)

CONDITION: Generally satisfactory
but with significant localised problems

PRINCIPAL VULNERABILITY: Extensive animal burrowing

TREND: Declining

OWNERSHIP: Private

CONTACT: Richard Massey 01483 252046

CHICHESTER



SITE NAME: **The chapel at the former
King Edward VII Hospital,
Easebourne**

Remarkable L-shaped chapel for tuberculosis patients by Charles Holden, 1903-6. In need of roof repairs as part of scheme to convert the hospital.

DESIGNATION: Listed Building Grade II*, RPG II

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: B (B)

OWNERSHIP: Company

Contact: David Brock 01483 252044



SITE NAME: **Former Church of the Assumption,
Church Farm Lane,
East Wittering**

Medieval church, restored 1875-6. Redundant for some years. Repairs have now been made but future use is not yet agreed.

DESIGNATION: Listed Building Grade II*

CONDITION: Fair

OCCUPANCY: Vacant

PRIORITY: E (C)

OWNERSHIP: Private

Contact: David Brock 01483 252044



SITE NAME: **North Park Furnace,
Linchmere**

The furnace is one of the most complete charcoal fired blast furnaces surviving from the Wealden iron industry but is in need of urgent repairs. Heritage Lottery Fund has now offered a Stage 2 grant and works should start soon.

DESIGNATION: Scheduled Monument

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: D (C)

OWNERSHIP: Trust

Contact: Richard Massey 01483 252046

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Bowl barrow 480m south of Irongates Lodge, Compton			
DESIGNATION:	Scheduled Monument (No. 20015)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME: Duncton Common round barrow cemetery, Duncton			
DESIGNATION:	Scheduled Monument (No. 20031)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME: Field system in Lamb Lea, East Dean			
DESIGNATION:	Scheduled Monument (No. WS365)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME: Harting Beacon: a hilltop enclosure, Anglo-Saxon burial mound and telegraph station on Beacon and Pen Hills, Elsted and Treyford			
DESIGNATION:	Scheduled Monument (No. 29278)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME: A Romano-Celtic temple, Iron Age shrine and associated remains 250m north west of Ratham Mill, Funtington			
DESIGNATION:	Scheduled Monument (No. 31391)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME: Devil's Ditch, section extending 200yds (180m) east from Chapel Lane, Funtington			
DESIGNATION:	Scheduled Monument (No. WS84)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME: Devil's Ditch, section extending 400yds (370m) west from Chapel Lane, Funtington			
DESIGNATION:	Scheduled Monument (No. WS85)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME: Devil's Ditch, section extending 900yds (820m), Lye Wood, West Stoke, Funtington			
DESIGNATION:	Scheduled Monument (No. WS86)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Flint mine on Stoke Down, immediately north of Stoke Clump, Funtington		
DESIGNATION:	Scheduled Monument (No. 31212)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Linear boundary on Stoke Down, 800m north of West Stoke House, Funtington		
DESIGNATION:	Scheduled Monument (No. 31213)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Bowl barrow 350m WNW of Barnett's Bridge, Graffham		
DESIGNATION:	Scheduled Monument (No. 20052)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Bowl barrow 500m WNW of Barnett's Bridge, Graffham		
DESIGNATION:	Scheduled Monument (No. 20055)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Bowl barrow on Gallows Hill, 150m east of Millborough House, Graffham		
DESIGNATION:	Scheduled Monument (No. 20058)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Two bowl barrows on Gallows Hill, 200m east of Millborough House, Graffham		
DESIGNATION:	Scheduled Monument (No. 20057)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Bexley Bushes earthworks, Lavant		
DESIGNATION:	Scheduled Monument (No. WS42)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Devil's Ditch, section 230yds (210m) long from Chichester main road to Pook Lane, Lavant		
DESIGNATION:	Scheduled Monument (No. WS81)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Richard Massey 01483 252046

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Devil's Ditch, section extending 530yds (480m) west from Lavant Lodge, Lavant		
DESIGNATION:	Scheduled Monument (No. WS82)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Devil's Ditch, section extending 960yds (870m) south of Lavant House, Lavant		
DESIGNATION:	Scheduled Monument (No. WS80)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Bowl barrow on Gallows Hill, 300m east of Millborough House, Lodsworth		
DESIGNATION:	Scheduled Monument (No. 20056)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Bowl barrow on Fitzhall Rough, 330m ENE of Fitzhall: part of Fitzhall Rough round barrow cemetery, Stedham with Iping		
DESIGNATION:	Scheduled Monument (No. 20037)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046



SITE NAME:	Lavington Park, East Lavington / Duncton
DESIGNATION:	Registered Park and Garden Grade II, also 7 LBs
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Stable
OWNERSHIP:	Corporate, single owner

Late C18 and C19 garden, laid out on the site of a former late C16 house and garden and further altered in the C20, set within a park largely planted in the C19 but of C18 origin. The property is now a school. Two relatively substantial developments were granted planning permission earlier this year. The opportunity to rationalise development within the park was considered to outweigh the negative impacts. There is now a conservation plan for the landscape, but no management commitment for areas unaffected by development. Contact: Charlotte McLean 01483 252043

SITE NAME:	East Marden		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Lone Le Vay (LA) 01243 534688		

SITE NAME:	Graylingwell		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Lone Le Vay (LA) 01243 534688		

SITE NAME:	Kirdford		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Lone Le Vay (LA) 01243 534688		

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
 If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Selsey		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Lone Le Vay (LA) 01243 534688		

SITE NAME:	Tangmere		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Lone Le Vay (LA) 01243 534688		

SITE NAME:	Walderton		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Lone Le Vay (LA) 01243 534688		

SITE NAME:	West Itchenor		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Lone Le Vay (LA) 01243 534688		

SITE NAME:	West Wittering		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Lone Le Vay (LA) 01243 534688		

HORSHAM



SITE NAME: **Amberley Limeworks, Houghton Bridge, Amberley**

C19 Limeworks including kilns and associated buildings. The ingress of rain and inadequate maintenance in the past have led to structural weaknesses. Site owned by West Sussex County Council but leased to Amberley Museum Trust.

DESIGNATION: Scheduled Monument

CONDITION: Poor

OCCUPANCY: Not applicable

PRIORITY: D (C)

OWNERSHIP: Trust

Contact: Richard Massey 01483 252046



SITE NAME: **St Marys House, The Street, Bramber**

Built in the C15 as a home for the Wardens of the Bridge, who were the monks of Sele Priory at Upper Beeding. Repairs are necessary in the medium term but funding from either private or public sources remains uncertain.

DESIGNATION: Listed Building Grade I, CA

CONDITION: Fair

OCCUPANCY: Occupied

PRIORITY: C (C)

OWNERSHIP: Private

Contact: David Brock 01483 252044



SITE NAME: **Chapter house and remains of kitchen, Hardham Priory, Coldwaltham**

Remains of an Augustinian monastery founded during mid C13 by Sir William Dawtry. The Chapter House is in need of urgent repair. The upstanding remains of the kitchen have been supported to prevent collapse. First stage of repair project nearing completion.

DESIGNATION: Listed Building Grade I, SM

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: D (B)

OWNERSHIP: Private

Contact: Richard Massey 01483 252046

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME: **Sedgwick Castle,
Moated site,
Nuthurst**

DESIGNATION: Scheduled Monument

CONDITION: Poor

OCCUPANCY: Not applicable

PRIORITY: A (B)

OWNERSHIP: Private

Moated medieval castle. Ruinous. The exposed parts of this structure are in a very poor state of repair. Discussions needed with new owners. A conservation strategy has previously been prepared but will need to be updated.

Contact: Richard Massey 01483 252046

SITE NAME: **Bowl barrow on Black Hill, Colgate**

DESIGNATION: Scheduled Monument (No. 20008)

CONDITION: Generally unsatisfactory
with major localised problems

PRINCIPAL VULNERABILITY: Other

TREND: Declining

OWNERSHIP: Private

CONTACT: Richard Massey 01483 252046

SITE NAME: **Motte and bailey castle in Pulborough Park, Pulborough**

DESIGNATION: Scheduled Monument (No. 12864)

CONDITION: Generally unsatisfactory
with major localised problems

PRINCIPAL VULNERABILITY: Plant growth

TREND: Declining

OWNERSHIP: Private

CONTACT: Richard Massey 01483 252046

SITE NAME: **Alfoldean Roman site, Slinfold**

DESIGNATION: Scheduled Monument (No. WS222)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Richard Massey 01483 252046

SITE NAME: **Bowl barrow 950m south west of Grey Friars Farm: part of a dispersed round barrow cemetery on Kithurst Hill, Storrington and Sullington**

DESIGNATION: Scheduled Monument (No. 29263)

CONDITION: Generally unsatisfactory
with major localised problems

PRINCIPAL VULNERABILITY: Scrub / tree growth

TREND: Declining

OWNERSHIP: Private

CONTACT: Richard Massey 01483 252046

SITE NAME: **Greatham**

DESIGNATION: Conservation Area

CONDITION: Very bad

VULNERABILITY: Medium

TREND: Expected to deteriorate

CONTACT: Catherine Jeater (LA) 01403 215528

SITE NAME: **Pulborough Church Place**

DESIGNATION: Conservation Area

CONDITION: Very bad

VULNERABILITY: Medium

TREND: No significant change expected

CONTACT: Catherine Jeater (LA) 01403 215528

SITE NAME: **Pulborough Lower Street, Pulborough**

DESIGNATION: Conservation Area

CONDITION: Very bad

VULNERABILITY: Medium

TREND: Expected to deteriorate

CONTACT: Catherine Jeater (LA) 01403 215528

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.


ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

MID SUSSEX

SITE NAME:	Motte and bailey castle 240m east of Dean's Mill, Lindfield Rural		
DESIGNATION:	Scheduled Monument (No. 12865)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Richard Massey 01483 252046

WORTHING



SITE NAME:	Castle Goring, Arundel Road, Worthing	Large house. Built by Shelley's grandfather, Sir Bysshe Shelley, about 1797-8. Currently let to a language school. The condition is very grave, and enforcement action for repairs must now be considered.
DESIGNATION:	Listed Building Grade I	
CONDITION:	Very bad	
OCCUPANCY:	Part occupied	
PRIORITY:	A (A)	
OWNERSHIP:	Private	Contact: David Brock 01483 252044



SITE NAME:	The Dome Cinema, Marine Parade, Worthing	Early example of leisure complex, built 1911 as a roller skating rink and developed as a cinema in 1923. In need of extensive repair. The Worthing Dome and Regeneration Trust has secured Heritage Lottery Fund and English Heritage funding for repair and enhancement as a cinema, which is now nearly complete.
DESIGNATION:	Listed Building Grade II*, CA	
CONDITION:	Good	
OCCUPANCY:	Occupied	
PRIORITY:	F (F)	
OWNERSHIP:	Trust	Contact: David Brock 01483 252044

SITE NAME:	Goring	
DESIGNATION:	Conservation Area	CONDITION: At risk
VULNERABILITY:	Unknown	TREND: Deteriorating
CONTACT:	Planning Section (LA) 01903 221065	

OFF WEST SUSSEX



SITE NAME:	Hazardous, Bracklesham Bay,	A 54-gun Fourth Rate Ship of the Line, captured from the French in 1703 and refitted for the Royal Navy. Grounded on a reef in Bracklesham Bay during a storm in 1706 while acting as escort for a convoy en route from Chesapeake Bay, Virginia, to the Thames Estuary. Urgent investigation occurred after seabed levels dropped in 1984. Subsequent accretion and erosion have been recorded, including loss of exposed timbers in early 1990s. In 2006, changes to sediment patterns caused new areas of scouring. Recent studies have quantified environmental threats which we are using to mitigate further loss.
DESIGNATION:	Protected Wreck Site	
CONDITION:	Extensive significant problems	
VULNERABILITY:	Medium	
TREND:	Significant decline	
OWNERSHIP:	Government	
PHOTO:	© Hazardous Project	Contact: Simon Goodhugh 01483 252037



SITE NAME:	Submarine HMS/m A1, Eastern Solent	Built by Vickers in 1903, the A1 is the first British designed and built submarine used by the Royal Navy. She sank for the second time in 1911 while operating under automatic pilot as a submerged target. The site has been subject to unauthorised access and a chain of shellfish pots was fixed by an unknown diver to the vessel's pressure hull causing abrasive damage.
DESIGNATION:	Protected Wreck Site	
CONDITION:	Extensive significant problems	
VULNERABILITY:	High	
TREND:	Significant decline	
OWNERSHIP:	Private	
PHOTO:	© Private	Contact: Simon Goodhugh 01483 252037

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

WINDSOR AND MAIDENHEAD (UA)



SITE NAME: **Noahs Boathouse,
Stonehouse Lane (Off),
Cookham**

1930, by Colin Lucas for his father; constructed of monolithic reinforced concrete with a flat roof. An early and pioneering example of Modern Movement architecture by one of the major figures in the movement. The building floods regularly and is derelict. The roof is leaking and the concrete is spalling.

DESIGNATION: Listed Building Grade II*

CONDITION: Poor

OCCUPANCY: Not applicable

PRIORITY: A (A)

OWNERSHIP: Private

Contact: Richard Peats 01483 252026

SITE NAME: **Royal Mausoleum,
The Home Park,
Windsor**

Mausoleum of Queen Victoria and Prince Albert, 1862-71. Damp problems are placing external and internal historic fabric at risk, including the internal frescoes. The original rainwater drainage is inadequate and poorly designed, running within the wall fabric, and is difficult to maintain. Environmental monitoring is now being carried out.

DESIGNATION: Listed Building Grade I

CONDITION: Fair

OCCUPANCY: Not applicable

PRIORITY: C (C)

OWNERSHIP: Crown

Contact: Elizabeth Moore 020 7973 3803

SITE NAME:

Beenham's Heath

DESIGNATION: Conservation Area

CONDITION: At risk

VULNERABILITY: Unknown

TREND: Deteriorating

CONTACT: Conservation Team (LA) 01628 685687

SITE NAME:

Maidenhead Town Centre

DESIGNATION: Conservation Area

CONDITION: At risk

VULNERABILITY: Unknown

TREND: Deteriorating

CONTACT: Conservation Team (LA) 01628 685687

WOKINGHAM (UA)



SITE NAME: **Site of St Bartholomews Church,
Arborfield,
Arborfield and Newland**

Old parish church, now a roofless ruin. Originally C13 in flint and stone, with substantial probable C18 brick rebuilding. One wall partially standing, with fragments of later brick segments. Very overgrown. Risk of further collapse.

DESIGNATION: Listed Building Grade II, SM

CONDITION: Very bad

OCCUPANCY: Not applicable

PRIORITY: A (A)

OWNERSHIP: Religious organisation

Contact: Chris Welch 01483 252027



SITE NAME: **Infirmary Stables,
Arborfield Garrison,
Arborfield, Finchampstead**

A specialised 'horse hospital' built 1911-12. The building is redundant by virtue of changes in army practices (i.e. reduced cavalry activity).

DESIGNATION: Scheduled Monument

CONDITION: Very bad

OCCUPANCY: Vacant

PRIORITY: A (A)

OWNERSHIP: Government

Contact: Chris Welch 01483 252027

SITE NAME:

Cropmark complex south west of St Patrick's Avenue, Charvil

DESIGNATION: Scheduled Monument (No. WO180)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Chris Welch 01483 252027

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Cropmark enclosure and pits north east of St Patrick's Avenue, Charvil			
DESIGNATION:	Scheduled Monument (No.WO182)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME: Ring ditch cropmark east of St Patrick's Avenue, Charvil			
DESIGNATION:	Scheduled Monument (No.WO181)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME: Cropmark site east of Broadmoor Lane, Sonning			
DESIGNATION:	Scheduled Monument (No.WO179)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Chris Welch 01483 252027



SITE NAME: Bearwood College, Arborfield and Newland / Barkham	
DESIGNATION:	Registered Park and Garden Grade II*, also part in CA, 5 LBs
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	High
TREND:	Declining
OWNERSHIP:	Corporate, multiple owners

This C19 landscape park and woodland surrounds a Victorian country house standing on formal terraces, with gardens by William Sawrey Gilpin and Pulham. The school, who now occupy the house, helped secure its future after WWI. The landscape park is now subdivided into two golf courses. Subsequent and current development and management of the gardens and woodland, plus a lack of specialist guidance and resources, challenge the integrity and survival of the historic landscape.'

Contact: Charlotte McLean 01483 252043

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



ENGLISH HERITAGE

This document is one in a series of publications produced as part of English Heritage's national Heritage at Risk campaign programme. More information about Heritage at Risk and other titles in the series can be found at www.english-heritage.org.uk/risk

HERITAGE AT RISK

Published July 2010 by English Heritage
1 Waterhouse Square, 138-142 Holborn,
London EC1N 2ST

© Copyright English Heritage 2010