



ENGLISH HERITAGE

HERITAGE AT
RISK
REGISTER
2010

SOUTH WEST

Contents

HERITAGE AT RISK	3
Reducing the risks	6
Publications and guidance	9
THE REGISTER	11
Content and assessment criteria	11
Key to the entries	13
Bath and North East Somerset (UA)	16
Bournemouth (UA)	19
Bristol, City of (UA)	19
Cornwall (UA)	22
Devon	53
Dorset	113
Gloucestershire	155
Isles of Scilly (UA)	169
North Somerset (UA)	173
Plymouth, City of (UA)	174
Poole (UA)	177
Somerset	178
South Gloucestershire (UA)	191
Swindon (UA)	193
Torbay (UA)	194
Wiltshire (UA)	196

HERITAGE AT RISK

2010 marks the publication of the third edition of our Heritage at Risk Register. It identifies which of this country's most important grade I and II* listed buildings, scheduled monuments, registered parks and gardens, registered battlefields, protected wreck sites and conservation areas are threatened by development pressures, neglect or decay. The Heritage at Risk Register also monitors the changing condition of assets to help us prioritise where our resources and expertise can best be deployed. This year, we undertook a pioneering 15% sample survey of England's 14,500 listed places of worship to help us understand the condition of the thousands of designated churches, chapels, synagogues, mosques and temples and other faith buildings that are the spiritual focus for our communities. They face many different kinds of challenges and we need to help congregations ensure their future.


The expansion of the Heritage at Risk Register in the South West means our understanding of the threats facing our most important historic assets is improving year on year. However, finding solutions for so many, and such a diverse range of historic structures and places remains a challenge for us and our partners, not least in the current economic climate.

The global financial recession and its consequences are having an impact on progress in dealing with Heritage at Risk. Funding is becoming ever more difficult to obtain and competition is increasing for scarce public grants and subsidies. It is clear that capital spending, particularly by public sector bodies, will be squeezed for some time to come, which may mean significantly reduced investment in the repair and adaptation of publicly owned buildings and assets. Developers with the will and resources to take on 'at risk' buildings are becoming harder to find, and agreed development schemes may not now be implemented until the economy recovers. As a result, it may be that charitable and voluntary organisations such as building preservation trusts and friends groups have a greater role to play in saving vulnerable heritage assets.

A number of important buildings that have been at risk for several years have suffered further as a direct consequence of the economic downturn. Repair schemes at Tonedale Mills in Somerset, and the historic World War Two aerodrome at Yatesbury in Wiltshire both ceased when developers abandoned the site. The future of these buildings is particularly uncertain; their condition is once again deteriorating, their repair costs are rising, and it could take many years to find another suitable solution for them.

However, we have made progress in other areas over the last year. Devonport Guildhall and 81 Montpelier Terrace, Cheltenham, are among the buildings at risk that have been removed from the Register following the completion of repairs. We also have a strong partnership with Natural England that allows vulnerable scheduled monuments to be included in Higher Level Environmental Stewardship schemes. We are grateful to a number of local authorities for helping us to improve our shared understanding of the condition of the Region's conservation areas.

Tackling the most vulnerable historic assets is always challenging, and becomes even more so in a recession. We will use this time to target the most urgent repairs to ensure the most vulnerable sites are not lost.



Andrew Vines, Planning and Development Regional Director, South West

Contact: Kara Fitzhugh, Business Manager, English Heritage South West Region, 29/30 Queen Square, Bristol, BS1 4ND
Telephone: 0117 9750700 Fax: 0117 9750706 Email: kara.fitzhugh@english-heritage.org.uk

TONEDALE MILLS, WELLINGTON, SOMERSET

The Tonedale woollen mill complex closed in the late 1990s after nearly two hundred years of operation. It is recognised as one of the best-preserved historic textile sites in the country, but its grade II* buildings became progressively more derelict and were placed on the Buildings at Risk Register in 2001. Conversion work began in 2008, but the development was abandoned a few months later with the start of the economic downturn. Several government agencies are discussing possible solutions for the site, which is now in the hands of the official receiver.

LISTED BUILDINGS

- 1 in 32 (3.1%) grade I and II* listed buildings are at risk nationally. In the South West this falls to 2.2% (155 sites).
- 9 sites were removed from the 2009 regional Register during the year, but 17 new sites were added.
- Since publication of the 1999 baseline Register 55.4% of the region's buildings at risk (102) have been removed from the regional Register as their futures have been secured, compared to the national figure of 50.7% (724).
- Nationally, £6.2m was offered to 76 sites on the Register during 2009/10. In the South West we awarded grants totalling £594k to 8 sites.

CONSERVATION AREAS

- 272 local authorities (81%) have taken part in our national survey of conservation areas, 28 of which were in the South West region.
- We now have information for 7,388 of England's 9,300 designated conservation areas, of which 920 are in the South West.
- 549 (7.4%) of the conservation areas for which we have information are at risk, 107 (11.6%) of them in our region.

SCHEDULED MONUMENTS

- Approximately 1 in 6 (17.2%) of England's 19,731 scheduled monuments are at risk, this rises to 20.2% (1409 sites) in the South West region.
- The total at risk has reduced by 140 (4.0%) since 2009, of which 32 (2.2%) were in this region.
- Arable ploughing and unrestricted plant, scrub or tree growth account for nearly two thirds of sites at risk. The South West follows the national trend in this respect.
- Nationally, 82% of scheduled monuments at risk are in private ownership, falling to 75% in the South West.
- Of the £450k offered to owners of scheduled monuments at risk in 2009/10, £31k was awarded to 24 sites in our region.

REGISTERED PARKS AND GARDENS

- 1 in 16 of England's 1,606 registered parks and gardens are at risk, with an increase from 6.0% (96) in 2009 to 6.2% (99) this year. In the South West, 16 of our 293 sites are at risk (5.5%).
- Nationally, 5 sites have been added and 2 removed from the Register but no change in the South West.

REGISTERED BATTLEFIELDS

- Of the 43 registered battlefields in England, 6 are at risk, 1 less than in 2009.
- None of the 8 registered battlefields in the South West is at risk following the removal of Langport from the Register during the year.

PROTECTED SHIP WRECKS

- Of the 46 protected wreck sites around England's coast, 8 are at risk, a fall of 1 since 2009.
- 1 of the 23 protected wreck sites off the coast of the South West is at risk, a reduction of 1 since last year – the *Royal Anne* has been removed following the implementation of an improved management regime.



LELANT, CORNWALL

More than one hundred and fifty of Cornwall's most vulnerable wayside crosses have recently been fitted with microchips to discourage their theft.

© Ann Preston-Jones, Cornwall Historic Environment Services

THERE ARE

7,093

GRADE I AND II*
LISTED
BUILDINGS
IN THE SOUTH WEST

20.2% OF

THE REGION'S 6,974
SCHEDULED
MONUMENTS
ARE AT RISK

11.6% OF

CONSERVATION
AREAS SURVEYED
IN THE REGION ARE
AT RISK

32 SITES
ON THE

2009 REGISTER
RECEIVED
GRANT AID

CARING FOR PLACES OF WORSHIP

Places of worship make a huge contribution to our towns and villages. They sit at the heart of communities, dominating skylines and landscapes. They are the product of centuries of invested skill and philanthropy. Most remain as places of prayer and spirituality but others have acquired new social uses that benefit a much wider cross-section of urban and rural society.

Like all buildings, they require regular maintenance to keep them in good condition. They also need to adapt to the evolving needs of their congregations and the wider community. Responsibility for their care falls almost entirely on the shoulders of volunteers, and for many smaller congregations the burden can be heavy.

We have therefore undertaken a series of consultation events with congregations, user groups and local authorities to identify the biggest concerns of those who manage these very special places. Places of Worship are particularly close to the heart of local communities, but in practice it is often just a handful of dedicated individuals who maintain them. They face unique challenges, which are illustrated in an accompanying report.


What we know

- 45% of all grade I buildings are places of worship.
- 85% of listed places of worship belong to the Church of England.
- Up to 1 in 10 could be at risk from leaking roofs, faulty gutters or eroding stonework.
- 1,850 repair projects at 1,567 buildings have shared £171m of English Heritage and Heritage Lottery Fund grant aid since 2002/3.

What congregations want to understand better

- Why their building has been listed and what that means.
- How to get permission to make changes and find expert help.
- How to raise money for one-off projects and day-to-day maintenance.
- Who will look after their buildings in the future.

All of these are considered in our booklet *Caring for Places of Worship*, sent to every listed place of worship.



For more information, see
www.english-heritage.org.uk/risk
or contact your English Heritage regional office.

If you would like this document in a different format, please contact our customer services department on telephone: 0870 333 1181 fax: 01793 414926 textphone: 01793 414878 email: customers@english-heritage.org.uk

Reducing the risks

English Heritage is committed to securing a year-on-year reduction in the number of heritage sites at risk. This will be challenging given the number of assets now on the register and the different kinds of risk they face. Each asset type and individual case will require its own approach and solution.

There are, however, some general approaches that are relevant to all assets at risk. Resolving cases requires working in close partnership with owners, local planning authorities and other relevant organisations and partners. Advice and understanding are essential. Historic Environment Records, maintained by local authorities, are repositories of information on local historic assets. They underpin the work of local authority historic environment services and can help improve the protection, conservation and management of heritage assets.

Maintenance of heritage assets is essential if they are not to become 'at risk', and to prevent those that are already at risk from decaying further and thereby escalating the cost of their repair and consolidation. Buildings, for instance, decay rapidly when left empty. Avoiding vacancy through short-term lets or schemes that provide protection through residential occupation are low-cost ways of maintaining buildings until permanent solutions can be found.

English Heritage provides on-line advice and guidance to local authorities, owners and managers of sites through the Historic Environment Local Management (HELM) website www.helm.org.uk.

LISTED BUILDINGS

English Heritage's role in securing the future of buildings at risk is primarily to provide practical advice, guidance and resources to local authorities and owners. Our involvement in cases is determined by the importance of the building and the complexity of the issues. We can help with analysis of the issues, investigation of the feasibility of options and brokering solutions. Although buildings at risk will continue to be a priority for English Heritage repair grants, grant-aid is limited in relation to demand. Grants from other public sources, notably the Heritage Lottery Fund, continue to be essential in helping secure the future of buildings at risk.

In very exceptional cases, English Heritage may acquire and repair a particularly important building at risk, where it is clear that the scale and complexity of problems are such that direct involvement is the best way of securing the building's long-term future.

Local authorities have a primary role in protecting the historic environment. The creation of a local 'at risk' register is the first step in tackling neglected buildings in order to assess and monitor the scale of the problem and prioritise resources and action. Local authorities can also take action to secure the preservation of historic buildings through the use of statutory notices. Some councils have a successful track record, but generally these powers are under-used. It is essential that local authorities make best use of their powers to secure buildings at risk, to 'stop the rot' and prevent the costs escalating beyond the point where it is economic to repair.

To help local authorities make more frequent and timely use of their statutory powers, English Heritage runs a grant scheme to underwrite a significant proportion of the irrecoverable costs involved in serving Urgent Works and Repairs Notices.

Building preservation trusts can be the key to saving many buildings at risk. Some trusts cover geographical areas; others specialise in particular types of building or are formed to save just one building. Determined individuals and trusts have saved numerous buildings at risk, working in partnership with other organisations such as local and national amenity societies, including SAVE Britain's Heritage, the Society for the Protection of Ancient Buildings, The Victorian Society and the Georgian Group.

SCHEDULED MONUMENTS

Although a significant proportion of scheduled monuments remain at risk, in many cases the problems can be reduced by either small changes to land management or better-informed decision-making. This is reinforced by the success in reducing the number of monuments at risk since the release of the interim figures in 2008, which shows how the simple act of disseminating information and advice can go a long way towards improving conditions. English Heritage provides on-line advice to the owners and managers of sites via the Historic Environment Local Management website www.helm.org.uk; through its Historic Environment Field Advisers and through the network of local authority Historic Environment Countryside Advisers that we have co-sponsored with local authority partners.

While most owners and managers of scheduled monuments address their long-term care on a regular basis, some monuments do require significant resources to stabilise their condition, to carry out repairs, or to change the way in which the land on and around them is used. English Heritage therefore works closely with Natural England who deliver the Environmental Stewardship agri-environment scheme on behalf of Defra and who are active in helping develop management regimes which include scheduled monuments. We also help the Heritage Lottery Fund to identify important sites deserving grant-aid.

The English Heritage National Monuments Record and local authority Historic Environment Records have increased the information available to land managers and we are continuing to develop their services. A new Selected Heritage Inventory for Natural England (SHINE) will soon allow owners to view online information on scheduled monuments and other archaeological features on their holdings.

In all cases – whether for rural or urban monuments – close co-operation with owners and land managers is the key to making further progress.

REGISTERED PARKS AND GARDENS

Inclusion on the Register brings no additional statutory controls, but there is a presumption in favour of the conservation of all designated assets in the planning system. The Government's new Planning Policy Statement 5 *Planning for the Historic Environment* (PPS 5) and its supporting Practice Guide will help planning authorities to assess and mitigate the impact of development on our irreplaceable heritage of designed landscapes.

English Heritage can engage only with the proposals for change to the highest graded designed landscapes and where the impact on historic significance is greatest. We will continue to tackle the skills crisis facing historic parks and gardens through sector-wide initiatives.

English Heritage encourages the development of conservation management plans for registered historic parks and gardens, especially those in multiple ownership. We are also keen for bursars and estate teams to use management plans to help conserve important but fragile landscapes in the care of schools, hospitals, hotels and other institutional owners.

REGISTERED BATTLEFIELDS

As with registered parks and gardens, this designation brings no additional statutory controls, but there is a presumption in favour of conservation of registered battlefields in the new PPS 5.

English Heritage will continue to work with owners to develop management plans for registered sites and, in appropriate cases, contribute towards the cost of management plans. We will develop positive landscape strategies with owners and partners such as Defra. In some circumstances, we may encourage the conversion from arable to pasture of especially sensitive locations to protect battlefield archaeology from the effects of ploughing and as part of a wider drive to prevent unauthorised or damaging metal-detecting.

English Heritage will also continue to encourage greater access to battlefields and improve their amenity value and visitors' appreciation of the impact these historic events had on our development as a nation.

Local authorities can help reduce the risk to battlefields by designating registered battlefields as conservation areas. This provides further protection and makes sure that registered battlefields are explicitly taken into account in Local Development Frameworks. Local authorities can also invite comments from the Battlefields Trust on planning applications affecting the setting of registered sites.

PROTECTED WRECK SITES

At the strategic level, the major sources of risk to designated wreck sites have now been identified. In terms of high-priority sites, practical requirements have also been identified in conservation management plans.

Risks to protected wreck sites can often be reduced through education, provision of marker buoys, or planning policies that take full account of their national importance. However, some sites require significant resources to stabilise their condition or to carry out detailed archaeological assessments of their conservation requirements. Although English Heritage has statutory power to allocate funds to promote the preservation and maintenance of protected wreck sites, its financial resources can solve only a small proportion of the problems.

In spite of the inherent difficulties with caring for this type of site, careful management must be maintained if we are to avoid the loss of wreck sites. It is therefore close co-operation between the owners of protected wreck sites (where known), authorised divers and all organisations charged with care for the marine and coastal environment, that will make the real difference to their long-term survival.

Practical advice on the management of historic wreck sites, whether at the coast-edge or under water, is available from English Heritage's Maritime Archaeology Team (maritime@english-heritage.org.uk) and from www.helm.org.uk.

CONSERVATION AREAS

The risks to conservation areas are difficult to address as they cover large areas of land and involve many different owners. Looking after them is thus a responsibility we all share – those of us who visit them to work or for enjoyment, those of us who own homes and businesses in them, those of us whose job it is to manage the spaces between the buildings and make decisions about their future.

Overall understanding of their character, development of a robust management regime and engagement by the public are therefore the keys to providing them with sustainable long-term futures. A conservation area is more likely to improve over time if the local authority commits itself to employing a dedicated conservation officer and to appointing an elected member as a heritage champion to promote the historic environment within the council. It also depends on members of the local community engaging either individually or through some form of conservation area advisory committee.

Armed with the information provided by the survey, we and our regional partners will have the evidence to direct resources and investment much more accurately towards those conservation areas at greatest risk. We will also want to target those with the greatest potential to improve the quality of life and economic prospects of people in the villages, towns and cities of which they are such crucially important components.

Publications and guidance

English Heritage has produced the following publications relating to heritage at risk, including:

- *Buildings at Risk: a New Strategy* (1998)
- *Caring for Places of Worship 2010* (2010) – a report on the condition of England's listed places of worship and the needs of the congregations
- *Heritage at Risk: Conservation Areas* (2009)
- *Heritage at Risk 2010* – national report and summaries for each of our nine regions: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, Yorkshire and the Humber
- *Heritage at Risk Register 2010* – detailed listings for each of our nine regions: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, Yorkshire and the Humber can be downloaded from our website or viewed as an interactive database: www.english-heritage.org.uk/risk
- *Monuments at Risk* (2008) – summary of scheduled monuments at risk in each of our nine regions: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, Yorkshire and the Humber
- *Protected Wreck Sites at Risk: A Risk Management Handbook* (2007)
- *The Monuments at Risk initiative 2003–08* (2010)

HERITAGE AT RISK ON THE WEB

To find out more about the Heritage 'at risk' programme visit www.english-heritage.org.uk/risk where you will find an interactive database providing detailed information on all heritage sites 'at risk' nationally.

For further information about the different classes of designated heritage assets, including listed buildings, conservation areas, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites visit the Heritage Protection section of our website www.english-heritage.org.uk/heritageprotection

CONSERVATION POLICIES AND GUIDANCE

The following publications are among the numerous helpful guidance documents now available on our website: www.english-heritage.org.uk/publications or www.english-heritage.org.uk/helm

Caring for Places of Worship (2010) – a practical booklet for everyone involved in caring for England's listed places of worship

Constructive Conservation in Practice (2008)

Conservation Principles, Policies and Guidance for the Sustainable Management of the Historic Environment (2008)

Creativity and Care: New Works in English Cathedrals (2009)

Enabling Development and the Conservation of Significant Places (2008)

Farming the Historic Landscape: Caring for Archaeological sites on Arable Land (2004)

Farming the Historic Landscape: Caring for Archaeological sites in Grassland (2004)

Guidance on the Management of Conservation Areas (2006)

Guidance on Conservation Area Appraisals (2006)

Guidance Notes and Application Forms for Grants to Local Authorities:

– *Grants to Local Authorities to Underwrite Urgent Works Notices* (1998)

– *Acquisition Grants to Local Authorities to Underwrite Repairs Notices* (1998)

– *Grants for Historic Buildings, Monuments and Designed Landscapes* (2004)

Heritage at Risk: Conservation Areas (2009) – guidance for local authorities

Managing Local Authority Heritage Assets: Some Guiding Principles for Decision Makers (2003)

New Uses for Former Places of Worship (2010)

Options for the Disposal of Redundant Churches and Other Places of Worship (2010)

Paradise Preserved: An Introduction to the Assessment, Evaluation, Conservation and Management of Historic Cemeteries (2002)

Scheduled Monument Consent: a Guide for Owners and Occupiers (2009)

Shared Interest: Celebrating Investment in the Historic Environment (2006)

Stopping the Rot: a Step by Step Guide to Serving Urgent Works and Repairs Notices (1998)

The Disposal of Historic Buildings: Guidance Note for Government Departments and Non-Departmental Public Bodies (DCMS, 1999). A new version is being prepared

If you would like further information about any of these publications, please contact:

English Heritage Customer Services Department
PO Box 569, Swindon SN2 2YP
Telephone: 0870 333 1181
Fax: 01793 414926
Email: customers@english-heritage.org.uk

THE REGISTER

Content and criteria

DESIGNATION

All the historic environment matters but there are some elements which warrant extra protection through the planning system. Since 1882, when the first Act protecting ancient monuments and archaeological remains was passed, government has been developing the designation system. Listing emerged from the post-blitz 1940s Planning Acts, and is now applied to about half a million buildings ranging from palaces to street lamps. Almost 20,000 archaeological sites are scheduled, which introduces tight management controls. Some 1,606 designed landscapes are registered, as are 43 battlefields, and 46 wreck sites are protected.

English Heritage, as the government's expert adviser, is responsible for making recommendations – but it is still the Secretary of State at the Department for Culture Media and Sport who makes the decisions on whether a site is designated. Understanding and appreciation develop constantly, which makes keeping the designation base up to date a never-ending challenge. While responding to threat-driven cases, we also seek to work strategically. Recent developments have seen a greater striving for openness and transparency in the process of designating a site, and better communication of what makes something special.

Conservation areas are designated locally by local planning authorities. They are areas of special architectural or historic interest the character or appearance of which it is desirable to preserve or enhance.

LISTED BUILDINGS

Definition

A listed building is a building (or structure) that has been designated as being of 'special architectural or historic interest'. The older and rarer a building is, the more likely it is to be listed. Buildings less than 30 years old are listed only if they are of outstanding quality and under threat.

Listed buildings are graded I, II* and II. Grade I and II* are particularly important buildings of outstanding interest; together they amount to 8% of all listed buildings. The remaining 92% are of special interest and are listed grade II.

Entries on the statutory list of buildings of special architectural or historic interest may comprise a number of separate buildings. Formal residential terraces are the most obvious example. Entries on this register reflect how buildings are grouped and recorded on the statutory list.

Structures can occasionally be both listed as buildings and scheduled as monuments.

Criteria for inclusion on this register

Buildings considered for inclusion on this register must be listed grade I or II*, (or grade II in London) or be a structural scheduled monument. Buildings are assessed for inclusion on the basis of condition and, where applicable, occupancy (or use). The condition of buildings on the register ranges from 'very bad' to 'poor', 'fair' and (occasionally) 'good'. The register also includes buildings that are vulnerable to becoming at risk because they are empty, under-used or face redundancy without a new use to secure their future.

Occupancy (or use) is noted as 'vacant', 'part occupied', 'occupied', or occasionally, 'unknown'; for many structural monuments, occupancy is not applicable.

Assessing vulnerability in the case of a building in fair condition necessarily involves judgement and discretion. A few buildings on the register are in good condition, having been repaired or mothballed, but a new use or owner is still to be secured.

Buildings are removed from the 'at risk' register when they are fully repaired/consolidated, their future secured, and where appropriate, occupied.

Priority for action

Once a building is identified as 'at risk' or vulnerable and included on the register, priority for action is assessed on a scale of A to F, where 'A' is the highest priority for a building which is deteriorating rapidly with no solution to secure its future, and 'F' is the lowest priority where a repair scheme is in progress and an end use has been secured.

SCHEDULED MONUMENTS

Definition

Scheduled monuments include archaeological sites and landscapes, and 19,731 examples have been designated because of their national importance. Scheduled monuments are not graded, and most have limited potential for beneficial use. They cover human activity from the prehistoric era, such as burial mounds, to 20th century military and industrial remains. For the millennia before written history, scheduled monuments are the only testament to innumerable generations of people of whom there is no other record.

The later 20th century saw unprecedented changes to the landscape. As a result, types of historic site that once were commonplace began to become rare. Those that survive often represent just small islands of what once characterised broad sweeps of our towns and countryside. Although protected by law, scheduled monuments are still at risk from a wide range of processes. In particular, they can frequently be exposed to intense pressures beyond the reach

of the planning system. These include damage from cultivation, forestry and – often most seriously of all – wholly natural processes such as scrub growth, animal burrowing and erosion.

Criteria for inclusion on this register

Scheduled monuments included on this register have been identified as being 'at risk' because of their condition and vulnerability, the trend in their condition, and their likely future vulnerability. A site's condition is expressed in terms of the scale and severity of adverse effects on it, ranging from those with 'extensive significant problems' to others that have only 'minor localised problems'.

Monuments are removed from the register once sufficient progress has been made to address identified issues, demonstrating a significant reduction in the level of risk.

REGISTERED PARKS AND GARDENS

Definition

There are 1,606 designed landscapes on the current English Heritage Register of Historic Parks and Gardens of Special Historic Interest. These registered landscapes are graded I, II* or II, and include private gardens, public parks and other green spaces, country estates and cemeteries. They are valued for their design, diversity and historical importance and in contrast to the number of listed buildings and scheduled monuments, registered parks and gardens is a very small group of assets.

Inclusion on the English Heritage Register of Historic Parks and Gardens brings no additional statutory controls, but there is a presumption in favour of conservation of the designated site. Local authorities are required to consult English Heritage on applications affecting sites registered as grade I or II* and the Garden History Society on sites of all grades.

Criteria for inclusion on this register

The identification of registered parks and gardens at risk begins with an appraisal of the condition and vulnerability of each registered landscape. Steps being taken by owners to address problems are also taken into consideration.

Landscapes assessed as being 'at risk' are typically affected by development and neglect. They have frequently been altered by development or are faced with major change. The original function of these landscapes has often changed; and divided ownership often results in the loss of the cohesive conservation of the historic designs.

Landscapes are removed from the register once plans are put in place to address issues and positive progress is being made.

REGISTERED BATTLEFIELDS

Definition

English Heritage's Register of Historic Battlefields has identified 43 nationally significant sites ranging in date from 991 to 1685. These are places where people risked their lives fighting for a cause and where history was made. The outcome of these battles was influenced by where they were fought and traces of the events will have been left across the landscape. Battlefields are cherished for many reasons, as a commemoration of the event and those who died, as a resource for understanding the course of the battle, and for the light they can shed on the times in which the battle was fought. They are vulnerable to insensitive development and to poorly managed investigation such as large-scale metal-detecting. While this designation introduces no additional statutory controls, one of its primary objectives is to encourage policies and other mechanisms that ensure that change and development affecting battlefields are sensitive and appropriate.

Criteria for inclusion on this register

Battlefields deemed to be 'at risk' of loss of historic significance are included on this register. The identified risks and threats come from development pressure – for example, because they lie on urban fringes or are subject to development pressures within the site; arable cultivation, and unregulated metal-detecting. One major impact or a combination of several factors can be enough to raise the risk at a particular site.

Battlefields are removed from the register when either actual damaging activities are reversed or managed, or threats recede due to effective management planning.

PROTECTED WRECK SITES

Definition

England's 46 protected wreck sites represent a tiny proportion of the 32,476 pre-1945 wrecks and recorded casualties that are known to lie in the territorial sea. Wreck sites can be of importance for different reasons: the distinctive design or construction of a ship, the story it can tell about its past, its association with notable people or events, its cargo, flora and fauna or its role as a focus for the local community. The Protection of Wrecks Act 1973 empowers the appropriate Secretary of State to designate a restricted area around a vessel to protect it or its contents from unauthorised interference.

Local authorities are able to react to foreshore infrastructure projects through the planning process, thereby securing the preservation of important remains in this intertidal zone.

Criteria for inclusion on this register

English Heritage has audited all designated wreck sites to identify those most at risk based on their current condition, vulnerability and the way they are being managed.

Wrecks are vulnerable to both environmental and human impacts. Risks that contribute to the inclusion on the register range from unauthorised access to erosion and fishing damage.

What needs to be done to ensure that the significance of the sites is maintained is identified as part of the monitoring process. In spite of the inherent difficulties in caring for this type of site, careful management must be maintained.

Wrecks are removed from the register once an appropriate management and monitoring regime is operational.

CONSERVATION AREAS

Definition

Conservation areas are designated by local authorities and are areas of special architectural or historic interest the character or appearance of which it is desirable to preserve or enhance. For more than 40 years conservation areas have proved a highly effective mechanism for managing change on an area-wide basis. There are currently some 9,300 conservation areas in England including town and city centres, suburbs, industrial areas, rural landscapes, cemeteries and residential areas. They form the historic backcloth to national and local life and are a crucial component of local identity and community cohesion.

Criteria for inclusion on this register

English Heritage has asked every local authority in England to complete a survey of its conservation areas, highlighting current condition, threats and trends, identifying those that are expected to deteriorate, or are in very bad or poor condition and are not expected to change significantly in the next three years, being defined as at risk.

The methodology for assessing conservation areas at risk has been refined since the first survey in 2008/2009. The information collated this year provides a more detailed assessment of each conservation area and an overall category for condition, vulnerability and trend is included for each conservation area on this register. Conservation areas identified as 'at risk' last year, but not reassessed using the revised methodology, are included on the register but with more limited information.

Conservation areas are removed from the register once issues have been identified, plans put in place to address them and positive progress is being made.

Key to the entries

This register includes the following heritage assets at risk:

- grade I and II* listed buildings and structural scheduled monuments
- scheduled monuments
- registered parks and gardens
- registered battlefields (where applicable)
- protected wreck sites (where applicable)
- conservation areas

ORDER

Entries are grouped and ordered alphabetically first by county or unitary authority, and then by local planning authority (unitary authority/national park/district or borough).

Asset types are grouped within the relevant planning authority in the following order:

- listed buildings and structural scheduled monuments
- scheduled monuments
- registered parks and gardens
- registered battlefields
- protected wreck sites (listed at the end of the county or unitary authority off which they are located)
- conservation areas

Within each asset type, sites are ordered alphabetically by parish, locality, street and site name.

DESIGNATION

The principal designation is noted for each entry, and includes:

- Listed Building (LB) grade I, II* or II
- Scheduled Monument (SM)
- Registered Park and Garden (RPG) grade I, II* or II
- Registered Battlefield
- Protected Wreck Site
- Conservation Area (CA)

Other designations that apply to buildings at risk and registered parks and gardens at risk, including their location within a World Heritage Site (WHS), are also noted where applicable.

The monument number is noted for scheduled monuments.

CONDITION

For buildings at risk, condition is graded as: 'very bad', 'poor', 'fair' and 'good'.

For sites that cover areas (scheduled monuments, registered parks and gardens and protected wreck sites) one overall condition category is recorded. The category may relate only to the part of the site or monument that is at risk and not the whole site:

- extensive significant problems
- generally unsatisfactory with major localised problems
- generally satisfactory but with significant localised problems
- generally satisfactory but with minor localised problems
- optimal
- unknown (is noted for a number of scheduled monuments that are below-ground and where their condition cannot be established).

For conservation areas, condition is categorised as: 'very bad', 'poor', 'fair' and 'optimal'.

OCCUPANCY

For buildings that can be occupied or have a use, the main vulnerability is vacancy, or under-use.

Occupancy (or use) is noted as follows:

- vacant
- part occupied
- occupied
- unknown
- not applicable

VULNERABILITY

Principal vulnerability is noted for scheduled monuments and may relate only to the part of the monument which is at risk, and include:

- animal burrowing
- arable ploughing
- coastal erosion
- collapse
- deterioration – in need of management
- scrub / tree growth
- visitor erosion.

For registered parks and gardens, protected wreck sites and conservation areas, vulnerability is noted as high, medium or low.

PRIORITY

For buildings at risk, the following priority categories are used as an indication of trend and as a means of prioritising action:

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

If the priority category has changed since the 2009 register, the previous category is given in brackets.

TREND

Trend for scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites may relate only to the part of the site that is at risk and is categorised as:

- declining
- stable
- improving
- unknown

For conservation areas trend is categorised as:

- expected to deteriorate significantly
- expected to deteriorate
- deteriorating
- unknown
- no significant change expected
- expected to show some improvement

OWNERSHIP

A principal ownership category is given for each entry, although many scheduled monuments, registered parks and gardens, and registered battlefields are in divided ownership. For registered parks and gardens, single or multiple ownership is noted.

CONTACT

This is the member of the English Heritage regional team who acts as a first point of contact for the case, and to whom enquiries should be addressed.

For conservation areas, the contact is the conservation/planning officer at the relevant local planning authority (indicated by 'LA' on the register).

We are not in any sense agents for the owners of the sites included, but we will endeavour to put people in touch with them where appropriate.

ABBREVIATIONS

CA	Conservation Area
EH	English Heritage
HLF	Heritage Lottery Fund
LA/LPA	Local Planning Authority
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

BATH AND NORTH EAST SOMERSET (UA)



SITE NAME:	King Edwards School, Broad Street, Bath
DESIGNATION:	Listed Building Grade II*, WHS, CA
CONDITION:	Fair
OCCUPANCY:	Vacant
PRIORITY:	E (E)
OWNERSHIP:	Company


School, 1752. A scheme for use as a hotel was submitted but withdrawn in 2006. Works to repair the roof have been successfully completed. The threat of decay has therefore diminished but the building remains vacant. The owner has initiated discussions regarding reuse and a new application for hotel use has been submitted and is under consideration.

Contact: Isla Macneal 0117 975 0742

SITE NAME:	Cleveland Baths, Hampton Row, Bath
DESIGNATION:	Listed Building Grade II*, WHS, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant
PRIORITY:	C (A)
OWNERSHIP:	Local authority

Dating from 1815, Cleveland Baths are believed to be the oldest surviving public outdoor swimming pools in England. A diminutive Georgian crescent houses the changing rooms and Caretakers Cottage. The Cleveland Pool Trust carried out a feasibility study in 2006 and are currently undertaking a business plan, condition survey and scheme design with English Heritage grant aid.

Contact: Sarah Ball 0117 975 0666



SITE NAME:	Hinton Priory, Hinton Charterhouse
DESIGNATION:	Listed Building Grade I, SM
CONDITION:	Poor
OCCUPANCY:	Not applicable
PRIORITY:	C (C)
OWNERSHIP:	Private

Early C13 Carthusian monastery, chapter house and refectory still standing. Later stables, coachhouse and garden buildings incorporate earlier material and follow original complex layout of cloister and cells. All structures in use except chapterhouse. Decay and subsidence across site causing structural damage.

Contact: Veryan Heal 0117 975 0717



SITE NAME:	St Thomas a Beckett Church, Pensford, Publow
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Not applicable
PRIORITY:	F (C)
OWNERSHIP:	Private

Parish church. Late C14 tower. The remainder of the church was rebuilt 1869. The tower and nave of this redundant church are in separate ownership. The tower is owned by the Churches Conservation Trust which repairs and opens the tower to the public. Planning permission and listed building consent were granted for conversion to a single family dwelling in October 2008 and some work has been carried out on site.

Contact: Isla Macneal 0117 975 0742

SITE NAME:	Wansdyke: section 1230yds (1120m) eastwards from Burnt House Inn, Odd Down	
DESIGNATION:	Scheduled Monument (No. BA93)	CONDITION: Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Gardening	TREND: Declining
OWNERSHIP:	Private	CONTACT: Veryan Heal 0117 975 0717

SITE NAME:	Camerton Romano-British town and associated Prehistoric and early medieval monuments, Camerton	
DESIGNATION:	Scheduled Monument (No. 11509)	CONDITION: Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND: Stable
OWNERSHIP:	Private	CONTACT: Veryan Heal 0117 975 0717

SITE NAME:	Richmont Castle, East Harptree	
DESIGNATION:	Scheduled Monument (No. BA120)	CONDITION: Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND: Declining
OWNERSHIP:	Private	CONTACT: Veryan Heal 0117 975 0717

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Roman road 720yds (660m) long, north of Abbey Farm, Hinton Charterhouse		
DESIGNATION:	Scheduled Monument (No. BA20)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Veryan Heal 0117 975 0717

SITE NAME:	Stantonbury camp and adjacent sections of Wansdyke, Marksbury		
DESIGNATION:	Scheduled Monument (No. BA72)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Veryan Heal 0117 975 0717

SITE NAME:	Lansdown Roman camp, North Stoke		
DESIGNATION:	Scheduled Monument (No. BA21)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Veryan Heal 0117 975 0717

SITE NAME:	Little Down camp, North Stoke		
DESIGNATION:	Scheduled Monument (No. BA73)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Veryan Heal 0117 975 0717

SITE NAME:	Wansdyke: south east of Newbarn Farm, Norton Malreward		
DESIGNATION:	Scheduled Monument (No. BA168)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Veryan Heal 0117 975 0717

SITE NAME:	Roman villa at Upper Hayes, Wellow		
DESIGNATION:	Scheduled Monument (No. BA91)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Veryan Heal 0117 975 0717

SITE NAME:	Bathampton		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Ian Lund (LA) 01225 477 687		

SITE NAME:	Batheaston		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Ian Lund (LA) 01225 477 687		

SITE NAME:	Chew Magna		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Ian Lund (LA) 01225 477 687		

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Chew Stoke		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Ian Lund (LA) 01225 477 687		

SITE NAME:	Compton Martin		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Ian Lund (LA) 01225 477 687		

SITE NAME:	Corston		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Ian Lund (LA) 01225 477 687		

SITE NAME:	Englishcombe		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Ian Lund (LA) 01225 477 687		

SITE NAME:	Hinton Blewett		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Ian Lund (LA) 01225 477 687		

SITE NAME:	Hinton Charterhouse (including The Green)		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Ian Lund (LA) 01225 477 687		

SITE NAME:	Keynsham Dapps Hill, Keynsham		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Ian Lund (LA) 01225 477 687		

SITE NAME:	Keynsham High Street, Keynsham		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Ian Lund (LA) 01225 477 687		

SITE NAME:	Midsomer Norton and Welton, Norton-Radstock		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Ian Lund (LA) 01225 477 687		

SITE NAME:	Newton St Loe		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Ian Lund (LA) 01225 477 687		

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	North Stoke		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Ian Lund (LA) 01225 477 687		

SITE NAME:	Paulton (including Paulton Basin)		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Ian Lund (LA) 01225 477 687		

SITE NAME:	Radstock (including Braysdown and Clandown)		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Ian Lund (LA) 01225 477 687		

SITE NAME:	South Stoke		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Ian Lund (LA) 01225 477 687		

SITE NAME:	Timsbury		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Ian Lund (LA) 01225 477 687		

SITE NAME:	Wellow		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Ian Lund (LA) 01225 477 687		

BOURNEMOUTH (UA)

SITE NAME:	Two round barrows 300yds (270m) north west of Double Dykes, Hengistbury Head, Bournemouth		
DESIGNATION:	Scheduled Monument (No. BO820)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Veryan Heal 0117 975 0717

SITE NAME:	Holdenhurst Village East, Hurn		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Andy Williams (LA) 01202 451169		

BRISTOL, CITY OF (UA)



SITE NAME:	Lower Lodge to Ashton Court, Ashton Road, Bristol
DESIGNATION:	Listed Building Grade II*, CA, RPG II
CONDITION:	Very bad
OCCUPANCY:	Vacant
PRIORITY:	A (A)
OWNERSHIP:	Local authority

Picturesque Gothic style entrance lodge built 1805 by Henry Wood. Limestone ashlar, two storeys with wrought iron gates. Vacant with hole in main roof and signs of structural distress in ashlar. Doors and windows blocked on ground floor but upper storey open to weather. A scheme for grant-aided restoration is under negotiation.

Contact: Justin Ayton 0117 975 0687

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	Mortimer House, Clifton Down Road, Bristol
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	C (New)
OWNERSHIP:	Private

Imposing mid C18 palladian suburban villa, until recently in hospital use, now vacant. Roofs are deteriorating and there is significant water ingress. The building has recently changed ownership and negotiations have commenced.

Contact: Justin Ayton 0117 975 0687



SITE NAME:	Clifton Observatory, Clifton, Bristol
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Part occupied
PRIORITY:	F (F)
OWNERSHIP:	Private

Former windmill, now camera obscura. Built C18, camera obscura early C19. Interior winding stair leads up to obscura and down to a tunnel leading to Ghyston's Cave on the side of the Avon Gorge. Following extensive negotiations, a scheme of repair and conversion is advanced and consent has been given to restore the observatory dome in conjunction with restaurant use.

Contact: Justin Ayton 0117 975 0687



SITE NAME:	Stair turret (Holy Cross) Inns Court Vicarage, Inns Court Green, Knowle, Bristol
DESIGNATION:	Listed Building Grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant
PRIORITY:	D (C)
OWNERSHIP:	Religious organisation

C15 stair turret attached to C20 building. Situated in middle of a housing estate. The roof has recently been repaired but a long term use is still being sought for the building.

Contact: Business Manager 0117 975 0700



SITE NAME:	Church of St Michael and attached railings, St Michaels Hill, Bristol
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	B (B)
OWNERSHIP:	Religious organisation

Church, rebuilt in 1775-77 in a Gothick style, but retaining the mid C15 tower; the interior is divided in three aisles by classical colonnades and has some late C19 fittings. The church is now redundant, and has been vacant for over six years. Scheme proposed for new denominational church use.

Contact: Justin Ayton 0117 975 0687



SITE NAME:	28 Portland Square, St Paul, Bristol
DESIGNATION:	Listed Building Grade I, CA
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	C (C)
OWNERSHIP:	Company

One of a terrace of seven houses located in a largely complete Georgian square, designed by Daniel Hague and built 1789-1820. Limestone ashlar, brick stacks, slate mansard roofs, double-depth plan. Late Georgian style, four storeys with attic and basement. Unoccupied with broken windows and leaking roof. Consent for conversion to mixed use granted 2009.

Contact: Justin Ayton 0117 975 0687



SITE NAME:	31 and 32 Portland Square, St Paul, Bristol
DESIGNATION:	Listed Building Grade I, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant
PRIORITY:	D (D)
OWNERSHIP:	Private

Terraced houses, 1789-1820. Emergency repairs carried out with English Heritage grant aid. Wind and weathertight, but masonry continues to decay. There has been a partial collapse of the facade. Consent has been given for repair and residential conversion.

Contact: Justin Ayton 0117 975 0687

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	Carriage Works, 104 Stokes Croft, Bristol
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant
PRIORITY:	A (A)
OWNERSHIP:	Private

Carriage works, 1862. A notable building in a manner recognised as particular to the city. Large and complex site including 4 Ashley Road (grade II) also in very bad condition. A planning application for mixed use development has been refused and is subject to appeal.

Contact: Justin Ayton 0117 975 0687



SITE NAME:	St James Priory, Whitson Street, Horsefair, Bristol
DESIGNATION:	Listed Building Grade I
CONDITION:	Very bad
OCCUPANCY:	Part occupied
PRIORITY:	F (C)
OWNERSHIP:	Religious organisation

Redundant former parish church, an important medieval priory site in Bristol city centre. The church, which was the former nave of the priory church, retains a surprising amount of Romanesque fabric. A substantial HLF grant has been awarded and EH has also offered grant towards major repairs. Work is progressing well with main scaffolding and a temporary roof in place. Works to be completed May 2011.

Contact: Business Manager 0117 975 0700



SITE NAME:	Timber Lodge, Blaise Castle Estate, Henbury Road, Henbury
DESIGNATION:	Listed Building Grade II*, CA, RPG II*
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	C (C)
OWNERSHIP:	Local authority

Early C19 cottage ornée, finely detailed and of uncommon design. Repairs were grant-aided by English Heritage but the building has subsequently been vandalised. Roof now covered with metal sheeting. Options for use are being explored by Bristol City Council.

Contact: Business Manager 0117 975 0700

SITE NAME:	Anti-aircraft gun site, Purdown, Bristol	
DESIGNATION:	Scheduled Monument (No. BS184)	CONDITION: Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND: Declining
OWNERSHIP:	Private	CONTACT: Robert Iles 0117 9750662

SITE NAME:	Civil War earthworks on Brandon Hill, Bristol	
DESIGNATION:	Scheduled Monument (No. BS118)	CONDITION: Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND: Declining
OWNERSHIP:	Local Authority	CONTACT: Robert Iles 0117 9750662

SITE NAME:	Heavy Anti-aircraft battery 520m east of Holes Mouth, Bristol	
DESIGNATION:	Scheduled Monument (No. 28885)	CONDITION: Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND: Declining
OWNERSHIP:	Local Authority	CONTACT: Robert Iles 0117 9750662

BRISTOL, CITY OF (UA) / BATH AND NORTH EAST SOMERSET (UA)



SITE NAME:	Brislington House, Bristol
DESIGNATION:	Registered Park and Garden Grade II*, also CA, 5 LBs
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Declining
OWNERSHIP:	

One of the first and most influential asylum landscapes in Britain. Now subdivided between a Sixth Form College, private residential development in the former asylum building, extensive commercial sports facilities, industrial units and a management training centre. Nevertheless some components of the designed landscape survive. Currently its designation is being re-evaluated by English Heritage. Part of the park is in Bath and North East Somerset Unitary Authority.

Contact: Kim Auston 0117 975 0696

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

BRISTOL, CITY OF (UA)

SITE NAME:	Stokes Croft, Bristol		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Kingsley Fulbrook (LA) 0117 9222966		

CORNWALL (UA)

	SITE NAME:	Codda Farmhouse, Bolventor, Altarnun	Farmhouse. C17 or earlier. Partly collapsed. Although some repairs to the habitable part of the house have been undertaken, the shippon and ancillary buildings are in poor condition. The temporary roof has recently been renewed and listed building consent granted for repair of the collapsing gable end.
	DESIGNATION:	Listed Building Grade II*	
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied	
	PRIORITY:	C (C)	
	OWNERSHIP:	Private	Contact: Francis Kelly 0117 975 0725

	SITE NAME:	Scaresdon Fort, Antony	Built 1868, used for military training purposes. A programme of works to remove vegetation and rotting timber has been carried out, the main gates have been repaired and there is a commitment to renew the bridge. The blocked drains in the south moat have been cleared. Further works are required to stop water ingress west of the entrance. A conservation plan has been prepared for the site.
	DESIGNATION:	Listed Building Grade II, SM	
	CONDITION:	Poor	
	OCCUPANCY:	Vacant	
	PRIORITY:	F (F)	
	OWNERSHIP:	Government	Contact: Michael Turner 020 7973 3808

	SITE NAME:	Tregantle Fort, Antony	Fort, built 1858-1865. The Keep is vacant, with no end use identified. A phased programme of repairs to the roof is complete. The interior is still in poor condition, but now drying out. Replacement windows and doors have been agreed and partially carried out.
	DESIGNATION:	Listed Building Grade II, SM	
	CONDITION:	Fair	
	OCCUPANCY:	Vacant	
	PRIORITY:	F (F)	
	OWNERSHIP:	Government	Contact: Michael Turner 020 7973 3808

	SITE NAME:	Barn about 40 metres south east of Tremaer, Maer, Bude Stratton	Rare example of late medieval barn in Cornwall in a hamlet now dominated by a popular caravan site not far from Bude. Approximately one third of the historic roof of cruck type (rare in Cornwall) survived late C20 fire. Historic element not in use and in poor condition. Small cob-built rear wing roofless and collapsing. Remainder re-roofed in corrugated iron and last used as riding stables.
	DESIGNATION:	Listed Building Grade II*	
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied	
	PRIORITY:	C (C)	
	OWNERSHIP:	Private	Contact: Francis Kelly 0117 975 0725

	SITE NAME:	Boiler House to Robinson's Shaft at South Crofty Mine, Station Road, Pool, Carn Brea	Boiler house to pump engine, built 1903. Relates to an outstanding group of early C20 buildings around Robinson's Shaft, the most complete surviving part of South Crofty mine. Remarkable for its degree of preservation. Boiler house is unroofed and internal machinery at risk. Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed summer 2011.
	DESIGNATION:	Listed Building Grade II*, WHS	
	CONDITION:	Poor	
	OCCUPANCY:	Vacant	
	PRIORITY:	F (D)	
	OWNERSHIP:	Local authority	Contact: Simon Ramsden 0117 975 0676

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	Carpenters' shop, workshops and forge at Robinson's Shaft, South Crofty, Station Road, Pool, Carn Brea
DESIGNATION:	Listed Building Grade II*, WHS
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	F (D)
OWNERSHIP:	Local authority

Carpenters' shop, sawmill, workshop and forge, built 1903-10. Building not secure or weather tight and the missing and deteriorating timber boarding is a concern. Part of the Robinson's complex, the most complete surviving part of the South Crofty mine, remarkable for its degree of preservation. Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed summer 2011.

Contact: Simon Ramsden 0117 975 0676



SITE NAME:	Compressor House and associated buildings at Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carn Brea
DESIGNATION:	Listed Building Grade II*, WHS
CONDITION:	Poor
OCCUPANCY:	Part occupied
PRIORITY:	F (D)
OWNERSHIP:	Local authority

Whim engine house and compressor house, chimney and electricity sub-station (1908-09). Part of the Robinson's Shaft complex, the most complete surviving part of South Crofty workings, the last working tin mine in Europe. Site is under constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed summer 2011.

Contact: Simon Ramsden 0117 975 0676



SITE NAME:	Pump Engine House at Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carn Brea
DESIGNATION:	Listed Building Grade II*, WHS
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	F (D)
OWNERSHIP:	Local authority

Pump engine house to tin mine, built in 1903. Part of the Robinson's Shaft complex, which is the most complete surviving part of South Crofty workings, the last working tin mine in Europe. Remarkable for its degree of preservation. Site faces constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed summer 2011.

Contact: Simon Ramsden 0117 975 0676



SITE NAME:	13 High Street, Launceston
DESIGNATION:	Listed Building Grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied
PRIORITY:	A (A)
OWNERSHIP:	Company

Jettied and timber framed corner house, prominent on town's market square. Roof structure is in very poor condition with partial collapse, valley plate propped. Lintels of principal first floor window propped. Listed building consent for structural repairs was submitted 2009. Building has new tenant and some of the structural work begun but condition of building remains serious.

Contact: Francis Kelly 0117 975 0725



SITE NAME:	Freemasons Hall, Quay Street, Lostwithiel
DESIGNATION:	Listed Building Grade I, CA
CONDITION:	Fair
OCCUPANCY:	Vacant
PRIORITY:	E (E)
OWNERSHIP:	Trust

C13 former hall of the Duchy Palace, a masonic hall since 1878. A building preservation trust has acquired the building; an options appraisal has been carried out and proposals for its re-use are being developed. English Heritage has offered grant for investigation and repair.

Contact: Francis Kelly 0117 975 0725



SITE NAME:	Dry sand and green sand shop, Perran Foundry, Perran Wharf, Mylor
DESIGNATION:	Listed Building Grade II*
CONDITION:	Very bad
OCCUPANCY:	Not applicable
PRIORITY:	B (B)
OWNERSHIP:	Private

Early to mid C19 mould and casting buildings, subsequently used for storage. This is the main furnace building. Impressive and surprisingly intact but very vulnerable because of its deteriorating condition. Urgent repairs carried out early 2005. Listed building consent and planning permission for repair and conversion granted 2008.

Contact: Business Manager 0117 975 0700

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME: **Engineers Shop,
Perran Foundry,
Perran Wharf, Mylor**

DESIGNATION: Listed Building Grade II*
CONDITION: Very bad
OCCUPANCY: Not applicable
PRIORITY: B (B)
OWNERSHIP: Private

Engineers shop, boring mill and pattern shop circa early/mid C18. This building's machinery was driven by two waterwheels turned by water from the leat passing parallel to the south and discharged into the river running parallel on the north side. The machinery has since been removed but many of the original openings survive. Listed building consent and planning permission for repair and conversion granted 2008.

Contact: Business Manager 0117 975 0700



SITE NAME: **New Pattern Shop,
Perran Foundry,
Perran Wharf, Mylor**

DESIGNATION: Listed Building Grade II*
CONDITION: Very bad
OCCUPANCY: Not applicable
PRIORITY: B (B)
OWNERSHIP: Private

Early C19 pattern shop. It is one of the most visually exciting buildings on site and despite serious problems retains most of its original structural fabric. A loading doorway at the southwest end of the building is spanned by an arched iron lintel dated 1865. Urgent repairs carried out early 2005. Listed building consent and planning permission for repair and conversion granted 2008.

Contact: Business Manager 0117 975 0700




SITE NAME: **Warehouse
(formerly listed as office),
Perran Foundry, Perran Wharf, Mylor**

DESIGNATION: Listed Building Grade II*
CONDITION: Very bad
OCCUPANCY: Not applicable
PRIORITY: B (B)
OWNERSHIP: Private

Mid C19 warehouse serving the former iron foundry, subsequently used as offices. It forms part of the Perran Foundry site which was established in 1791 and was the second major iron foundry to be established in Cornwall. Urgent repairs were carried out early 2005. Listed building consent and planning permission for repair and conversion granted 2008.

Contact: Business Manager 0117 975 0700



SITE NAME: **Trinity Methodist Chapel,
Chywoone Hill, Newlyn,
Penzance**

DESIGNATION: Listed Building Grade II*, CA
CONDITION: Poor
OCCUPANCY: Not applicable
PRIORITY: C (C)
OWNERSHIP: Religious organisation

Nonconformist Wesleyan chapel circa 1834, enlarged 1866. One of the best and most complete early C19 chapels in Cornwall. No longer used for religious worship. English Heritage grant for investigation and repaired offered 2010.

Contact: Francis Kelly 0117 975 0725



SITE NAME: **Sara's Foundry,
Tolgus Place,
Redruth**

DESIGNATION: Listed Building Grade II*
CONDITION: Very bad
OCCUPANCY: Not applicable
PRIORITY: A (A)
OWNERSHIP: Private

C19 and C20 iron foundry and engineering works, containing a large quantity of tools and associated machinery. Buildings continue to deteriorate and are now in a very vulnerable condition. Discussions are taking place about the possibility of the Princes Trust taking on the building.

Contact: Phil McMahon 0117 975 0699



SITE NAME: **Charlestown Methodist Church,
Charlestown Road,
St Austell**

DESIGNATION: Listed Building Grade II*, WHS, CA
CONDITION: Very bad
OCCUPANCY: Vacant
PRIORITY: B (A)
OWNERSHIP: Private

Wesleyan chapel (1827) and attached schoolroom (mid C19). No longer used for worship. Building weathertight following Urgent Works Notice but condition is very bad with collapse of organ floor imminent and rear building gutted. Conversion of rear school block and stabilisation of chapel agreed.

Contact: Francis Kelly 0117 975 0725

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	Hockings House Bible Christian Chapel, St Cleer
DESIGNATION:	Listed Building Grade II*
CONDITION:	Very bad
OCCUPANCY:	Not applicable
PRIORITY:	A (A)
OWNERSHIP:	Private

Chapel dated 1846. Exceptionally well-preserved interior with gallery and good quality original fittings including leaders' pew. Now separated from the small Sunday school. Gig House attached provides scope for modest conversion. The new owner has submitted plans for modern conversion.

Contact: Francis Kelly 0117 975 0725



SITE NAME:	Calf House at Lithiack and stable adjacent to North, Port Eliot Estate, St Germans
DESIGNATION:	Listed Building Grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	C (New)
OWNERSHIP:	Private

Late C18/early C19 Estate agricultural building. Attributed to Sloane for the Port Eliot Estate. Owner is in discussion with the Local Authority regarding future use of the building.

Contact: Francis Kelly 0117 975 0725



SITE NAME:	Porthmeor Pilchard Cellars and Studios, 13, 15 and 17 Back Road West, St Ives
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Occupied
PRIORITY:	B (New)
OWNERSHIP:	Trust

Built in the C19 and extended around 1900, the Studios were home to many important artists of the internationally known St Ives School. The net lofts below retain rare pilchard processing tanks. The building is still in use today, but requires extensive repair. A scheme has been agreed and the Trust is seeking to raise funds from charitable sources. English Heritage grant for investigation and repairs offered.

Contact: Simon Ramsden 0117 975 0676



SITE NAME:	Gatehouse to Trenethick Barton Farmhouse, Wendron
DESIGNATION:	Listed Building Grade I
CONDITION:	Very bad
OCCUPANCY:	Vacant
PRIORITY:	B (B)
OWNERSHIP:	Private

Gatehouse or barbican, C16. Granite ashlar gatehouse with scantle slate roof. Now in a precarious condition with protective roof.

Contact: Francis Kelly 0117 975 0725



SITE NAME:	Wesleyan Chapel, Porkellis, Wendron
DESIGNATION:	Listed Building Grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied
PRIORITY:	C (C)
OWNERSHIP:	Private

1866 Wesleyan Methodist chapel. The congregation has moved into the Sunday school and the chapel was sold to a private buyer. Owner has addressed the most serious roof leaks and is assessing potential for conversion to residential use.

Contact: Francis Kelly 0117 975 0725

SITE NAME:	Two hut circles 400m WSW of Furhouse, Advent	
DESIGNATION:	Scheduled Monument (No. CO888)	CONDITION: Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND: Declining
OWNERSHIP:	Private	CONTACT: Phil McMahon 0117 975 0699

SITE NAME:	Co-axial field system, hut circle settlements, cairnfield and land boundaries on Carne Down, Altarnun	
DESIGNATION:	Scheduled Monument (No. I5037)	CONDITION: Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Moderate stock erosion	TREND: Declining
OWNERSHIP:	Private	CONTACT: Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

- CA Conservation Area
- LB/LBs Listed Building/s
- NP National Park
- RPG Registered Park and Garden
- SM/SMs Scheduled Monument/s
- UA Unitary Authority
- WHS World Heritage Site

SITE NAME: Cross on Halvana Moor, Altarnun			
DESIGNATION:	Scheduled Monument (No. CO535)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Unknown
OWNERSHIP:	Government or Agency	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Deserted medieval settlement and field system with incorporated prehistoric settlement and field system and post-medieval farmhouse north west of Tresibbet Farm, Altarnun			
DESIGNATION:	Scheduled Monument (No. I5272)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Nine Stones stone circle 1.03km NNW of Bowhayland Farm, Altarnun			
DESIGNATION:	Scheduled Monument (No. I5194)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Platform cairn with rim bank and central cairn, and a secondary cairn, on the summit of Carne Down, Altarnun			
DESIGNATION:	Scheduled Monument (No. I5036)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Moderate stock erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Prehistoric coaxial field system, incorporated and adjacent hut circles, stone setting, linear boundaries and medieval settlement on Fox Tor and Treburland Farm, Altarnun			
DESIGNATION:	Scheduled Monument (No. I5230)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Prehistoric irregular field system and hut circle settlement with adjacent medieval regular field system and deserted settlement south east of Tresibbet Farm, Altarnun			
DESIGNATION:	Scheduled Monument (No. I5273)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Prehistoric stone alignment 1km SSE of Eastmoorgate, Altarnun			
DESIGNATION:	Scheduled Monument (No. I5193)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Moderate stock erosion	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Two adjacent prehistoric coaxial field systems incorporating regular field systems, stone hut circles, cairns and medieval fields on East Moor and Ridge, Altarnun			
DESIGNATION:	Scheduled Monument (No. I5220)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Hut circle group and enclosure north east of Carwen, Blisland			
DESIGNATION:	Scheduled Monument (No. CO917)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Castle Pencaire hillfort, two rounds and a field system, Tregonning Hill, Breage			
DESIGNATION:	Scheduled Monument (No. CO1073)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Group of round barrows south east of Middle Taphouse, Broadoak			
DESIGNATION:	Scheduled Monument (No. CO441)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Group of round barrows south of Penadlake, Broadoak			
DESIGNATION:	Scheduled Monument (No. CO444)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Round barrow 310yds (280m) south of Kilmansag, Broadoak			
DESIGNATION:	Scheduled Monument (No. CO442)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Round barrow south of Middle Taphouse, Broadoak			
DESIGNATION:	Scheduled Monument (No. CO443)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Round barrows west of West Taphouse, Broadoak			
DESIGNATION:	Scheduled Monument (No. CO422)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Two round barrows NW of Middle Taphouse, Broadoak			
DESIGNATION:	Scheduled Monument (No. CO421)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Okeltor 19th century arsenic, copper and tin mine, Calstock		
DESIGNATION:	Scheduled Monument (No. I5549)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Permitted development	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Tamar Canal, Gunnislake, Calstock		
DESIGNATION:	Scheduled Monument (No. CO984)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Carvannel cliff castle, Camborne		
DESIGNATION:	Scheduled Monument (No. CO519)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Group of round barrows north of Grey Mare Lodge, Cardinham		
DESIGNATION:	Scheduled Monument (No. CO445)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	St Bellarmin's Chapel, Cardinham		
DESIGNATION:	Scheduled Monument (No. CO453)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Treznace Holy Well and chapel enclosure, Cardinham		
DESIGNATION:	Scheduled Monument (No. 31826)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Carn Brea Castle, Carn Brea		
DESIGNATION:	Scheduled Monument (No. CO79)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Stable
OWNERSHIP:	Local Authority	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Great Wheal Busy engine house and mine buildings, Chacewater		
DESIGNATION:	Scheduled Monument (No. CO938)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Melangoose camp, Colan		
DESIGNATION:	Scheduled Monument (No. CO431)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Round 300yds (270m) WSW of High Cross, Constantine		
DESIGNATION:	Scheduled Monument (No. CO788)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Killibury Castle later Prehistoric hillfort, Egloshayle		
DESIGNATION:	Scheduled Monument (No. I5011)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Tregeare camp, Egloskerry		
DESIGNATION:	Scheduled Monument (No. CO87)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Jewish and Congregationalist cemeteries at Ponsharden, Falmouth		
DESIGNATION:	Scheduled Monument (No. I5581)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Cliff castle west of Gunwalloe Church, Gunwalloe		
DESIGNATION:	Scheduled Monument (No. CO781)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Rectangular camp south west of Trevarnon Round, Gwinear-Gwithian		
DESIGNATION:	Scheduled Monument (No. CO417)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Round near Lower Nanterrow, Gwinear-Gwithian		
DESIGNATION:	Scheduled Monument (No. CO985)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Trevarnon Round, Gwithian, Gwinear-Gwithian			
DESIGNATION:	Scheduled Monument (No. CO131)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Castle Kayle (earthwork), Phillack, Hayle			
DESIGNATION:	Scheduled Monument (No. CO117)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Permitted development	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: 'Headon Barrow' near Headon Cross, Jacobstow			
DESIGNATION:	Scheduled Monument (No. CO944)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Round 200m north west of Penventinnie, Kenwyn			
DESIGNATION:	Scheduled Monument (No. 29614)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Camp north east of Northcott Park Quarry, Kilkhampton			
DESIGNATION:	Scheduled Monument (No. CO571)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Group of four round barrows east of Bottaborough, Kilkhampton			
DESIGNATION:	Scheduled Monument (No. CO469)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Five bowl barrows 480m and 510m north of Hendra Farm, Ladock			
DESIGNATION:	Scheduled Monument (No. 32906)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Round and annexe 720m WSW of Tregear, Ladock			
DESIGNATION:	Scheduled Monument (No. 32950)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Neolithic settlement and hut circle on Helman Tor, Lanlivery			
DESIGNATION:	Scheduled Monument (No. CO991)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Giants Hedge, Lerryn to Lanreath, Lanreath			
DESIGNATION:	Scheduled Monument (No. CO104)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Mabel Barrow, Lansallos			
DESIGNATION:	Scheduled Monument (No. CO106)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: St Saviour's Chapel, Polruan, Lanteglos			
DESIGNATION:	Scheduled Monument (No. 31862)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Earlier Prehistoric hillfort, two cairns, medieval pound and adjacent Prehistoric field systems, hut circles and transhumance huts on Stowe's Hill, Linkinhorne			
DESIGNATION:	Scheduled Monument (No. I5071)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Early medieval transhumance hut 740m west of Blackcoombe Farm, Linkinhorne			
DESIGNATION:	Scheduled Monument (No. I5162)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Medieval and post-medieval tin and copper mines with medieval field system on the middle and lower northern slopes of Caradon Hill, Linkinhorne			
DESIGNATION:	Scheduled Monument (No. I5585)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Neolithic long cairn, Prehistoric regular and irregular aggregate field systems, linear boundaries and medieval enclosure 625m west of Blackcoombe Farm, Linkinhorne			
DESIGNATION:	Scheduled Monument (No. I5145)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Prehistoric enclosure with adjacent stone hut circle 780m NNE of Minions, Linkinhorne			
DESIGNATION:	Scheduled Monument (No. 15082)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Prehistoric enclosure with three adjacent hut circles 700m NNE of Minions, Linkinhorne			
DESIGNATION:	Scheduled Monument (No. 15081)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Prehistoric funerary cist 1.275km north west of Wardbrook Farm, Linkinhorne			
DESIGNATION:	Scheduled Monument (No. 15175)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Flooding	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Prehistoric linear boundaries, cairn and enclosure 1.225km north west of Wardbrook Farm, Linkinhorne			
DESIGNATION:	Scheduled Monument (No. 15135)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate stock erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Prehistoric linear boundary and field system, medieval enclosure and tin miners' caches 1.06km north west of Wardbrook Farm, Linkinhorne			
DESIGNATION:	Scheduled Monument (No. 15134)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Prehistoric round cairn on Caradon Hill, 310m west of Heather House, Linkinhorne			
DESIGNATION:	Scheduled Monument (No. 15582)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Prehistoric unenclosed hut circle settlement incorporating a medieval tin miners' cache and medieval shelter 1.285km north west of Wardbrook Farm, Linkinhorne			
DESIGNATION:	Scheduled Monument (No. 15130)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Round cairn 580m north west of Wardbrook Farm, Linkinhorne			
DESIGNATION:	Scheduled Monument (No. 15089)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Round cairn 775m north west of Wardbrook Farm, Linkinhorne			
DESIGNATION:	Scheduled Monument (No. 15087)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Round cairn with central cist on Bearah Common, 1.106km north of Wardbrook Farm, Linkinhorne			
DESIGNATION:	Scheduled Monument (No. 15157)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Stone hut circle 812m north west of Wardbrook Farm, Linkinhorne			
DESIGNATION:	Scheduled Monument (No. 15092)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Two adjacent transhumance huts on Caradon Hill, 450m north of East Caradon Farm, Linkinhorne			
DESIGNATION:	Scheduled Monument (No. 15163)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Round 450yds (405m) north west of Lower Chellew Farm, Ludgvan			
DESIGNATION:	Scheduled Monument (No. CO777)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Ancient village and fields at Boswarva Carn, Madron			
DESIGNATION:	Scheduled Monument (No. CO411)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Barrow 800yds (730m) WNW of Boswens Farm, Madron			
DESIGNATION:	Scheduled Monument (No. CO748)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate visitor erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Chun Downs prehistoric landscape complex, incorporating Chun Cromlech, Chun Castle, and barrow 200yds (180m) south west of Chun Farm, Madron			
DESIGNATION:	Scheduled Monument (No. CO1088)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Courtyard house 200yds (180m) NNE of Try Farm, Madron			
DESIGNATION:	Scheduled Monument (No. CO657)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Courtyard house 300yds (270m) north west of Middle Carnaquidden, Madron			
DESIGNATION:	Scheduled Monument (No. CO659)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Courtyard houses north east of Newmill, Madron			
DESIGNATION:	Scheduled Monument (No. CO662)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Hut circles with associated field system 400yds (360m) south west of Little Higher Bosullow, Madron			
DESIGNATION:	Scheduled Monument (No. CO730)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Round 300yds (270m) north east of Newmill, Madron			
DESIGNATION:	Scheduled Monument (No. CO663)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Round barrow 530yds (480m) north west of Nancothan Cottages, Madron			
DESIGNATION:	Scheduled Monument (No. CO724)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Settlement 450yds (400m) north west of Middle Carnaquidden, Madron			
DESIGNATION:	Scheduled Monument (No. CO658)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Cawsand Fort, Maker-with-Rame			
DESIGNATION:	Scheduled Monument (No. 29617)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Earthwork redoubts Nos 1, 2 and 3, Maker-with-Rame			
DESIGNATION:	Scheduled Monument (No. CO832)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Incomplete Palmerstonian fort 650yds (600m) west of Forder, Maker-with-Rame			
DESIGNATION:	Scheduled Monument (No. CO979)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Localised/limited stock erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Mount Edgcumbe round barrow, Maker-with-Rame			
DESIGNATION:	Scheduled Monument (No. CO314)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Round barrow 500yds (460m) west of Trevassack, Mawgan-in-Meneage			
DESIGNATION:	Scheduled Monument (No. CO324)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Permitted development	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Hillfort at Blacketon Farm, Menheniot			
DESIGNATION:	Scheduled Monument (No. CO1038)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Inswork Chapel, Millbrook			
DESIGNATION:	Scheduled Monument (No. CO623)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Croftoe British village, Morvah			
DESIGNATION:	Scheduled Monument (No. CO54)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Round barrow on Bin Down, Morval			
DESIGNATION:	Scheduled Monument (No. CO231)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Trevelgue promontory camp and two barrows, Newquay		
DESIGNATION:	Scheduled Monument (No. CO88)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Improving
OWNERSHIP:	Local Authority	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Hut circle settlement 975m north east of Trewortha Farm, North Hill		
DESIGNATION:	Scheduled Monument (No. 15119)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Platform cairn 667m ENE of Trewortha Farm, North Hill		
DESIGNATION:	Scheduled Monument (No. 15102)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Prehistoric irregular aggregate field system with incorporated stone hut circle 1.125km south west of East Castick Farm, North Hill		
DESIGNATION:	Scheduled Monument (No. 15112)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Round cairn 1.175km WSW of East Castick Farm, North Hill		
DESIGNATION:	Scheduled Monument (No. 15156)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Round cairn 617m ENE of Trewortha Farm, North Hill		
DESIGNATION:	Scheduled Monument (No. 15104)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Round cairn 750m ENE of Trewortha Farm, North Hill		
DESIGNATION:	Scheduled Monument (No. 15100)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Round cairn 800m WSW of Tolcarne Farm, North Hill		
DESIGNATION:	Scheduled Monument (No. 15203)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Round cairn 910m WSW of Tolcarne Farm, North Hill			
DESIGNATION:	Scheduled Monument (No. 15204)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Round cairn with central cist 1.05km east of Trewortha Farm, North Hill			
DESIGNATION:	Scheduled Monument (No. 15099)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Round cairn with central cist 1km ENE of Trewortha Farm, North Hill			
DESIGNATION:	Scheduled Monument (No. 15097)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Round cairn with central cist 970m ENE of Trewortha Farm, North Hill			
DESIGNATION:	Scheduled Monument (No. 15098)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Round cairn with double orthostatic kerb and cist 497m south east of Trewortha Farm, North Hill			
DESIGNATION:	Scheduled Monument (No. 15110)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Stone hut circle 1.225km WSW of East Castick Farm, North Hill			
DESIGNATION:	Scheduled Monument (No. 15154)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Stone hut circle 1.34km south west of East Castick Farm, North Hill			
DESIGNATION:	Scheduled Monument (No. 15116)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Stone hut circle 1.35km south west of East Castick Farm, North Hill			
DESIGNATION:	Scheduled Monument (No. 15113)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Stone hut circle 1.365km south west of East Castick Farm, North Hill			
DESIGNATION:	Scheduled Monument (No. 15114)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Stone hut circle 1.37km south west of East Castick Farm, North Hill			
DESIGNATION:	Scheduled Monument (No. 15117)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Stone hut circle 758m north east of Trewortha Farm, North Hill			
DESIGNATION:	Scheduled Monument (No. 15219)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Stone hut circle with concentric annexe 1.4km south west of East Castick Farm, North Hill			
DESIGNATION:	Scheduled Monument (No. 15115)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Three adjoining Prehistoric linear boundaries on Bearah Tor, 687m south west of Nodmans Bowda Farm, North Hill			
DESIGNATION:	Scheduled Monument (No. 15144)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Three round cairns 578m ENE of Trewortha Farm, North Hill			
DESIGNATION:	Scheduled Monument (No. 15106)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Three stone hut circles 1.055km ENE of Trewortha Farm, North Hill			
DESIGNATION:	Scheduled Monument (No. 15217)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Three stone hut circles 1.06km north east of Trewortha Farm, North Hill			
DESIGNATION:	Scheduled Monument (No. 15120)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Two round cairns 557m ENE of Trewortha Farm, North Hill			
DESIGNATION:	Scheduled Monument (No. 15107)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Two stone hut circles 1.035km ENE of Trewortha Farm, North Hill			
DESIGNATION:	Scheduled Monument (No. 15218)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Two stone hut circles and adjacent Prehistoric boundary wall 575m west of West Berriow Farm, North Hill			
DESIGNATION:	Scheduled Monument (No. 15143)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Unenclosed hut circle settlement and adjacent Prehistoric linear boundary 800m SSE of Trewortha Farm, North Hill			
DESIGNATION:	Scheduled Monument (No. 15133)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Unenclosed hut circle settlement incorporating a small cairn 875m ENE of Trewortha Farm, North Hill			
DESIGNATION:	Scheduled Monument (No. 15108)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Unenclosed hut circle settlement with adjacent enclosure and linear boundary 1.41km south west of East Castick Farm, North Hill			
DESIGNATION:	Scheduled Monument (No. 15118)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Unenclosed hut circle settlement with incorporated enclosure 1.5km north west of Wardbrook Farm, North Hill			
DESIGNATION:	Scheduled Monument (No. 15132)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Three barrows 550m ENE of Cansford, Otterham			
DESIGNATION:	Scheduled Monument (No. CO922)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Roundago, hut circle and field system on Castallack Carn, Paul			
DESIGNATION:	Scheduled Monument (No. CO807)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Bake Rings later prehistoric-Roman round with attached enclosure and outwork, Pelynt			
DESIGNATION:	Scheduled Monument (No. I5008)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Group of three round barrows north of Hendra, Pelynt			
DESIGNATION:	Scheduled Monument (No. CO559)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Hall Rings, Pelynt			
DESIGNATION:	Scheduled Monument (No. CO105)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Ten barrows south of Wilton Mill, Pelynt			
DESIGNATION:	Scheduled Monument (No. CO409)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Clapper Bridge, Quethiock			
DESIGNATION:	Scheduled Monument (No. CO368)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: D-Day landing craft maintenance site, 170m north of Saltash Pier, Saltash			
DESIGNATION:	Scheduled Monument (No. I5557)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate visitor erosion	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Caer Bran, Sancreed			
DESIGNATION:	Scheduled Monument (No. CO98)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Field system on Boswens Common, Sancreed		
DESIGNATION:	Scheduled Monument (No. CO1092)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Goldherring British village, Sancreed		
DESIGNATION:	Scheduled Monument (No. CO263)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Hut circle north of Botrea, Sancreed		
DESIGNATION:	Scheduled Monument (No. CO365)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Hut circles and field system on north west edge of Boswens Common, Sancreed		
DESIGNATION:	Scheduled Monument (No. CO1091)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Bolster Bank, St Agnes		
DESIGNATION:	Scheduled Monument (No. 29669)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Wheal Kitty 20th century tin processing works, St Agnes		
DESIGNATION:	Scheduled Monument (No. 35823)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Promontory fort and Civil War battery, Little Dennis Head, St Anthony-in-Meneage		
DESIGNATION:	Scheduled Monument (No. CO437)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Black Head promontory fort, St Austell Bay		
DESIGNATION:	Scheduled Monument (No. CO520)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Deserted Village of Garrow, St Breward			
DESIGNATION:	Scheduled Monument (No. 36059)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Camp 900yds (820m) south east of St Buryan village, St Buryan			
DESIGNATION:	Scheduled Monument (No. CO373)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Round barrow 200yds (180m) north of the Merry Maidens, St Buryan			
DESIGNATION:	Scheduled Monument (No. CO669)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Earlier Prehistoric hillfort, adjacent round cairn with incorporated shelter, and tor cairn on Tregarrick Tor, St Cleer			
DESIGNATION:	Scheduled Monument (No. I5088)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Embanked platform cairn with central mound 375m north west of Trewalla Farm, St Cleer			
DESIGNATION:	Scheduled Monument (No. I5063)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Kerbed platform cairn with kerbed central mound and outer bank 600m east of Trewalla Farm, St Cleer			
DESIGNATION:	Scheduled Monument (No. I5054)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Platform cairn with central mound 760m ESE of Lambadla Farm, St Cleer			
DESIGNATION:	Scheduled Monument (No. I5059)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Platform cairn with central mound 900m ESE of Lambadla Farm, St Cleer			
DESIGNATION:	Scheduled Monument (No. I5058)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:		Prehistoric cist, cairns and cairnfield on north east Smallacoombe Downs, 570m north west of Smallacoombe Tor, St Cleer	
DESIGNATION:	Scheduled Monument (No. 15539)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Prehistoric enclosure 325m west of Trewalla Farm, St Cleer	
DESIGNATION:	Scheduled Monument (No. 15090)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Prehistoric enclosure and field system, two hut circles and parts of a medieval field system 350m south east of Sparretts Farm, St Cleer	
DESIGNATION:	Scheduled Monument (No. 15077)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Prehistoric enclosure containing a stone hut circle and parts of a medieval field system, 500m south east of Sparretts Farm, St Cleer	
DESIGNATION:	Scheduled Monument (No. 15072)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Prehistoric irregular aggregate field system with incorporated stone hut circles 375m SSE of Sparretts Farm, St Cleer	
DESIGNATION:	Scheduled Monument (No. 15122)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Prehistoric irregular and regular aggregate field systems with incorporated stone hut circles 750m ENE of Siblyback Farm, St Cleer	
DESIGNATION:	Scheduled Monument (No. 15243)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Prehistoric irregular and regular aggregate field systems, enclosure, stone hut circles, cairnfield and kerbed boulder 750m ESE of Siblyback Farm, St Cleer	
DESIGNATION:	Scheduled Monument (No. 15083)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Prehistoric regular aggregate field system with incorporated and adjacent stone hut circles and an adjacent enclosure 550m WSW of Trewalla Farm, St Cleer			
DESIGNATION:	Scheduled Monument (No. 15095)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME: Prehistoric to medieval settlements, field systems, enclosures and cairns, with post-medieval boundary and railway on north east Smallacoombe Down, St Cleer			
DESIGNATION:	Scheduled Monument (No. 15538)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME: Prehistoric to post-medieval field systems, boundaries, settlements and railway at Smallacoombe Parks and north eastern Sibbyback Moor, St Cleer			
DESIGNATION:	Scheduled Monument (No. 15540)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME: Round cairn 450m east of Sparretts Farm, St Cleer			
DESIGNATION:	Scheduled Monument (No. 15076)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME: Round cairn 472m SSW of Caradon Hill summit, St Cleer			
DESIGNATION:	Scheduled Monument (No. 15046)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Moderate vehicle damage/erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME: Round cairn 480m SSW of Caradon Hill summit, St Cleer			
DESIGNATION:	Scheduled Monument (No. 15047)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME: Round cairn 525m east of Trewalla Farm, St Cleer			
DESIGNATION:	Scheduled Monument (No. 15174)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME: Round cairn 527m SSW of Caradon Hill summit, St Cleer			
DESIGNATION:	Scheduled Monument (No. 15048)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Round cairn 557m SSW of Caradon Hill summit, St Cleer			
DESIGNATION:	Scheduled Monument (No. 15049)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate vehicle damage/erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Round cairn 725m ESE of Trewalla Farm, St Cleer			
DESIGNATION:	Scheduled Monument (No. 15169)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Round cairn 740m SSW of Caradon Hill summit, St Cleer			
DESIGNATION:	Scheduled Monument (No. 15052)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Round cairn 800m ESE of Lambadla Farm, St Cleer			
DESIGNATION:	Scheduled Monument (No. 15060)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Round cairn 812m ESE of Trewalla Farm, St Cleer			
DESIGNATION:	Scheduled Monument (No. 15168)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Round cairn 840m south east of Trewalla Farm, St Cleer			
DESIGNATION:	Scheduled Monument (No. 15170)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Round cairn and shelters 812m SSW of Caradon Hill summit, St Cleer			
DESIGNATION:	Scheduled Monument (No. 15051)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Public utilities	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Round cairn with peripheral berm 402m SSW of Caradon Hill summit, St Cleer			
DESIGNATION:	Scheduled Monument (No. 15045)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate vehicle damage/erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: South Caradon 19th century copper mine, St Cleer			
DESIGNATION:	Scheduled Monument (No. I5556)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Stone hut circle 425m south east of Sparretts Farm, St Cleer			
DESIGNATION:	Scheduled Monument (No. I5074)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Stone hut circle 685m south east of Trewalla Farm, St Cleer			
DESIGNATION:	Scheduled Monument (No. I5165)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Stone hut circle 750m ESE of Trewalla Farm, St Cleer			
DESIGNATION:	Scheduled Monument (No. I5166)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Stone hut circle 800m ESE of Trewalla Farm, St Cleer			
DESIGNATION:	Scheduled Monument (No. I5167)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Stone hut circle centred 460m ESE of Sparretts Farm, St Cleer			
DESIGNATION:	Scheduled Monument (No. I5073)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: The Tinnors' Dyke 160yds (150m) in length south of Hendergrove Wood, St Cleer			
DESIGNATION:	Scheduled Monument (No. CO605)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Tor cairn with adjacent sub-rectangular hut 650m SSW of Caradon Hill summit, St Cleer			
DESIGNATION:	Scheduled Monument (No. I5050)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Two adjacent stone hut circles 265m WNW of Trewalla Farm, St Cleer			
DESIGNATION:	Scheduled Monument (No. 15091)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Two adjacent stone hut circles 290m west of Trewalla Farm, St Cleer			
DESIGNATION:	Scheduled Monument (No. 15093)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Two cairns 550m and 587m ENE of Trewalla Farm and two adjacent small clearance cairns, St Cleer			
DESIGNATION:	Scheduled Monument (No. 15055)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Two platform cairns 750m and 785m east of Sparretts Farm, St Cleer			
DESIGNATION:	Scheduled Monument (No. 15061)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate vehicle damage/erosion	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Two round cairns 455m and 475m north west of Trewalla Farm, St Cleer			
DESIGNATION:	Scheduled Monument (No. 15062)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Two stone hut circles and an adjoining Prehistoric boundary wall 470m east of Trewalla Farm, St Cleer			
DESIGNATION:	Scheduled Monument (No. 15173)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Round 340m north west of Tresawle Farm, St Columb Major			
DESIGNATION:	Scheduled Monument (No. 32969)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Bury camp, St Dominick			
DESIGNATION:	Scheduled Monument (No. CO522)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Localised/limited stock erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Warren's Barrow, St Erme		
DESIGNATION:	Scheduled Monument (No. 29681)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Enclosures east of Gurlyn, St Erth		
DESIGNATION:	Scheduled Monument (No. CO1052)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Promontory fort north of village, St Gennys		
DESIGNATION:	Scheduled Monument (No. CO637)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Gunpowder storage complex at Kennall Vale, St Gluvias		
DESIGNATION:	Scheduled Monument (No. 15544)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Gunpowder works at Kennall Vale, St Gluvias		
DESIGNATION:	Scheduled Monument (No. 15541)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Camp 500yds (460m) west of Trenance, St Issey		
DESIGNATION:	Scheduled Monument (No. CO845)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Permitted development	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Tokenbury camp, St Ive		
DESIGNATION:	Scheduled Monument (No. CO419)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Hut circles, Higher Bussow, St Ives		
DESIGNATION:	Scheduled Monument (No. CO118)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Whitesand Bay (or Tregonhawke) battery, St John			
DESIGNATION:	Scheduled Monument (No. CO978)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Permitted development	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Chambered barrow 100yds (90m) east of Kerrow Farm, St Just			
DESIGNATION:	Scheduled Monument (No. CO786)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Hut circles 50yds (45m) west of Carnyorth Farm, St Just			
DESIGNATION:	Scheduled Monument (No. CO734)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Round barrow 550yds (500m) north of Chycarne, St Just			
DESIGNATION:	Scheduled Monument (No. CO872)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Standing stone 200yds (180m) west of Chycarne, St Just			
DESIGNATION:	Scheduled Monument (No. CO856)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Two barrows on Carn Bean 300yds (270m) NNE of Higher Botallack, St Just			
DESIGNATION:	Scheduled Monument (No. CO737)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Two barrows on Woon Gumpus Common 700yds (640m) NNW of Boslow Farm, St Just			
DESIGNATION:	Scheduled Monument (No. CO749)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Chapel enclosure 150yds (140m) south of Trelease Farm, St Keverne			
DESIGNATION:	Scheduled Monument (No. CO693)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Round barrow east of Trelan Plantation, St Keverne			
DESIGNATION:	Scheduled Monument (No. CO569)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Cliff castle at Winecove Point, St Merryn			
DESIGNATION:	Scheduled Monument (No. CO844)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Hut circle village 330yds (300m) west of West Northwood Farm, St Neot			
DESIGNATION:	Scheduled Monument (No. CO956)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Medieval homestead and fields on Redhill Downs, St Neot			
DESIGNATION:	Scheduled Monument (No. CO401)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Prehistoric field systems, enclosure, hut circles and rounds, with adjacent medieval settlement, longhouse and field system on Higher Langdon Farm, St Neot			
DESIGNATION:	Scheduled Monument (No. I5259)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Prehistoric settlements and field system with adjacent medieval settlement, field systems, boundaries and tin streamworks on the Brown Gelly Downs, St Neot			
DESIGNATION:	Scheduled Monument (No. I5267)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Round barrow on Goonzion Down, St Neot			
DESIGNATION:	Scheduled Monument (No. CO672)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Round cairn 1.062km south west of Higher Langdon Farm, St Neot			
DESIGNATION:	Scheduled Monument (No. I5260)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Round cairn 1.17km south west of Higher Langdon Farm, St Neot			
DESIGNATION:	Scheduled Monument (No. 15261)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME: Wayside cross and cross base in St Stephen's churchyard, 6m south of the church, St Stephen-in-Brannel			
DESIGNATION:	Scheduled Monument (No. 31838)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME: Bofarnel Downs round barrows, St Winnow			
DESIGNATION:	Scheduled Monument (No. CO446)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME: Respryn Bridge, St Winnow			
DESIGNATION:	Scheduled Monument (No. CO63)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Limited/ localised vehicle damage/erosion	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME: Two round barrows north east of Fairy Cross, St Winnow			
DESIGNATION:	Scheduled Monument (No. CO448)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME: Condolden Barrow, Tintagel			
DESIGNATION:	Scheduled Monument (No. CO299)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Localised/limited stock erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME: The Ballast Pond, Torpoint			
DESIGNATION:	Scheduled Monument (No. CO1085)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME: Ancient village south of Carburrow Tor, Warleggan			
DESIGNATION:	Scheduled Monument (No. CO394)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Treen Common barrows, Zennor		
DESIGNATION:	Scheduled Monument (No. CO333)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Carclew, Mylor	Mid C18 formal terraced and water gardens, together with an C18 landscape park. The main house burnt down in 1934 and the site is now in divided ownership. Infill residential development in the park belts, substantial areas of woodland have been cleared and many individual parkland trees have been lost.
DESIGNATION:	Registered Park and Garden Grade II, also CA, 5 LBs	
CONDITION:	Extensive significant problems	
VULNERABILITY:	Medium	
TREND:	Declining	
OWNERSHIP:	Private, multiple owners	Contact: Kim Auston 0117 975 0696

SITE NAME:	Blisland		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Alyson Cooper (LA) 01872 224242		

SITE NAME:	Bodmin		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Alyson Cooper (LA) 01872 224242		

SITE NAME:	Boscastle, Forrabury and Minster		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Alyson Cooper (LA) 01872 224242		

SITE NAME:	Bude, Bude-Stratton		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Alyson Cooper (LA) 01872 224242		

SITE NAME:	Kilhampton		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Alyson Cooper (LA) 01872 224242		

SITE NAME:	Little Petherick, St Issey		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Alyson Cooper (LA) 01872 224242		

SITE NAME:	Old Cemetery, Bodmin		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Alyson Cooper (LA) 01872 224242		

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHs	World Heritage Site

SITE NAME:	Stratton, Bude-Stratton		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Alyson Cooper (LA) 01872 224242		

SITE NAME:	Wadebridge		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Alyson Cooper (LA) 01872 224242		

SITE NAME:	Week St Mary		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Alyson Cooper (LA) 01872 224242		

DEVON**DARTMOOR (NP)**

SITE NAME:	Higher Sigford, Sweet's Sigford, Ilsington, Teignbridge
DESIGNATION:	Listed Building Grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	D (D)
OWNERSHIP:	Private

A rare example of a longhouse in a farmstead context which has been used for agricultural storage in more recent years. Some internal and external stabilisation works have been carried out though further works are needed. Conditional consents for re-occupation of the house have been granted. The property is currently for sale.

Contact: Francis Kelly 0117 975 0725

SITE NAME:	Medieval farmstead 340m south east of Cold East Cross, Ashburton		
DESIGNATION:	Scheduled Monument (No. 34424)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Taw River tin blowing mill, 840m south of Tawcroft, Belstone		
DESIGNATION:	Scheduled Monument (No. 28751)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Enclosure, two stone hut circles and an alignment of upright stones 780m north west of Little Links Tor, Bridestowe		
DESIGNATION:	Scheduled Monument (No. 22333)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Hut circles and a length of enclosure wall, forming part of a stone hut circle settlement 600m east of Nodden Gate, Bridestowe		
DESIGNATION:	Scheduled Monument (No. 24075)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Hut circles and fields on Buckland Common, Buckland in the Moor			
DESIGNATION:	Scheduled Monument (No. DV511)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Lizwell Bridge, Buckland in the Moor			
DESIGNATION:	Scheduled Monument (No. DV614)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive natural erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Hut circles west of Higher Shapley, Chagford			
DESIGNATION:	Scheduled Monument (No. DV983)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Agglomerated enclosure on the west side of the Erme Valley below Stalldown, Cornwall			
DESIGNATION:	Scheduled Monument (No. I0515)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Blowing house north of Yealm Steps, Cornwall			
DESIGNATION:	Scheduled Monument (No. DV900)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Enclosure on the west side of the Erme valley below Stalldown, Cornwall			
DESIGNATION:	Scheduled Monument (No. I0516)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Medieval settlement on Ford Waste, Cornwall			
DESIGNATION:	Scheduled Monument (No. DV898)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: The southern of three enclosures north of Ford Waste, Cornwall			
DESIGNATION:	Scheduled Monument (No. I0765)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Three unenclosed stone hut circles on the west side of the Erme Valley, north of Lower Piles, Cornwood		
DESIGNATION:	Scheduled Monument (No. 10517)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Two hut circles on the south east slope of Stalldown, Cornwood		
DESIGNATION:	Scheduled Monument (No. 10514)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Unenclosed stone hut settlement north east of Yadsworthy, Cornwood		
DESIGNATION:	Scheduled Monument (No. 10518)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	A double stone hut circle and enclosure 280m south of Deadlake Foot, Dartmoor Forest		
DESIGNATION:	Scheduled Monument (No. 20395)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Camp 325yds (300m) south east of Archerton, Dartmoor Forest		
DESIGNATION:	Scheduled Monument (No. DV919)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Hut circle and field system north west of Saddle Bridge, Dartmoor Forest		
DESIGNATION:	Scheduled Monument (No. DV795)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Two irregular aggregate field systems with associated settlements, part of a coaxial field system, boundary stones and historic fields on Riddon Ridge, Dartmoor Forest		
DESIGNATION:	Scheduled Monument (No. 28733)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Enclosure and hut circles east of Huntingdon Ford, Dean Prior		
DESIGNATION:	Scheduled Monument (No. DV466)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Hut circles and two enclosures on Dean Moor, near River Avon, Dean Prior		
DESIGNATION:	Scheduled Monument (No. DV282)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Prestonbury Castle (hillfort), Drewsteignton		
DESIGNATION:	Scheduled Monument (No. DV151)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Farway Castle earthwork enclosure, Farway		
DESIGNATION:	Scheduled Monument (No. 24851)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Chambered cairn 430m south of Buttern, Gidleigh		
DESIGNATION:	Scheduled Monument (No. 34481)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Chambered cairn 830m south of Buttern, Gidleigh		
DESIGNATION:	Scheduled Monument (No. 34480)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Coaxial field system, associated and later remains at Throwleigh Common and Kennon Hill, Gidleigh		
DESIGNATION:	Scheduled Monument (No. 28694)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Part of a coaxial field system, prehistoric settlements and cairns on Buttern Hill, Gidleigh		
DESIGNATION:	Scheduled Monument (No. 34479)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Stone hut circle 380m north west of North Creaber, Gidleigh		
DESIGNATION:	Scheduled Monument (No. 34484)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Stone hut circle and field system 580m north west of North Creaber, forming part of a coaxial field system on Buttern Hill, Gidleigh			
DESIGNATION:	Scheduled Monument (No. 34483)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Two stone hut circles and field system, 590m south of Buttern, forming part of a coaxial field system on Buttern Hill, Gidleigh			
DESIGNATION:	Scheduled Monument (No. 34482)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Agglomerated enclosure with hut circles, south of Lower Piles, Harford			
DESIGNATION:	Scheduled Monument (No. 10522)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Blowing house at junction of Hook Lake and River Erme, Harford			
DESIGNATION:	Scheduled Monument (No. DV805)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Blowing house north of Dry Lake, Harford			
DESIGNATION:	Scheduled Monument (No. DV811)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Cairn in north east corner of Lower Piles, Harford			
DESIGNATION:	Scheduled Monument (No. 10526)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Cairn to the west of Tristis Rock, Burford Down, Harford			
DESIGNATION:	Scheduled Monument (No. 10528)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Enclosure and hut circles at Piles Corner, Harford			
DESIGNATION:	Scheduled Monument (No. 10530)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Enclosure with hut circles east of Addicombe, Harford			
DESIGNATION:	Scheduled Monument (No. 10556)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Enclosure with hut circles east of Addicombe, Harford			
DESIGNATION:	Scheduled Monument (No. 10617)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Enclosure with hut circles in Higher Piles newtake, Harford			
DESIGNATION:	Scheduled Monument (No. 10531)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Enclosure with hut circles to the north east of Piles Copse, Harford			
DESIGNATION:	Scheduled Monument (No. 10529)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Hut circles and enclosure to south of Left Lake, Harford			
DESIGNATION:	Scheduled Monument (No. DV812)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Hut circles in Erme Pound east of River Erme, Harford			
DESIGNATION:	Scheduled Monument (No. DV804)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Stone row, cairn and enclosures near Hook Lane, Erme Valley, Harford			
DESIGNATION:	Scheduled Monument (No. DV319)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Unenclosed stone hut settlement on the east side of the Erme Valley, north Harford Moor, Harford			
DESIGNATION:	Scheduled Monument (No. 10519)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Unenclosed stone hut settlement with enclosures north of Piles Copse, Harford		
DESIGNATION:	Scheduled Monument (No. 10521)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Eight cairns forming part of a cairn cemetery on Holne Ridge and a stone alignment immediately west of Horn's Cross, Holne		
DESIGNATION:	Scheduled Monument (No. 28770)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Enclosed prehistoric settlement and round cairn 880m south west of Venford Reservoir dam, Holne		
DESIGNATION:	Scheduled Monument (No. 22373)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Enclosed prehistoric settlement and three round cairns 870m south east of Horn's Cross, Holne		
DESIGNATION:	Scheduled Monument (No. 22374)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Four cairns 310m south of Horn's Cross forming part of a cairn cemetery on Holne Ridge, Holne		
DESIGNATION:	Scheduled Monument (No. 28769)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Four cairns on Holne Lee 1140m north west of Greatcombe, Holne		
DESIGNATION:	Scheduled Monument (No. 28764)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Holne Chase Castle, Holne		
DESIGNATION:	Scheduled Monument (No. DV251)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Medieval farmstead and field system, post-medieval tinworks, prehistoric settlements and cairns north and west of Gibby Coombe, Holne		
DESIGNATION:	Scheduled Monument (No. 34427)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Part of the Dartmeet coaxial field system and other archaeological remains on Holne Moor west and north west of Venford Reservoir, Holne		
DESIGNATION:	Scheduled Monument (No. 22368)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:	Partially enclosed stone hut circle settlement 350m south west of Horn's Cross, Holne		
DESIGNATION:	Scheduled Monument (No. 28771)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:	Partially enclosed stone hut circle settlement 420m north west and 440m west of Horn's Cross, Holne		
DESIGNATION:	Scheduled Monument (No. 28772)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:	Partially enclosed stone hut circle settlement 560m west of Horn's Cross, Holne		
DESIGNATION:	Scheduled Monument (No. 28773)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:	Prehistoric fields and settlements north east of Venford Reservoir forming part of the Dartmeet coaxial field system, Holne		
DESIGNATION:	Scheduled Monument (No. 22369)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:	Prehistoric fields, settlements and cairn south east of Venford Reservoir forming part of the Dartmeet coaxial field system, Holne		
DESIGNATION:	Scheduled Monument (No. 22370)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:	Ringleshutes tinwork, Holne		
DESIGNATION:	Scheduled Monument (No. 24091)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:	Stone hut circle and length of boundary walling 860m south west of Venford Reservoir dam, Holne		
DESIGNATION:	Scheduled Monument (No. 22372)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Three stone hut circles 780m SSW of Venford Reservoir dam, Holne		
DESIGNATION:	Scheduled Monument (No. 22371)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Cairn 240m north of Crownley Parks, Ilington		
DESIGNATION:	Scheduled Monument (No. 34423)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Hut circles east of the Saddle Tor, Ilington		
DESIGNATION:	Scheduled Monument (No. DV929)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Pound north east of Holwell Tor, Ilington		
DESIGNATION:	Scheduled Monument (No. DV451)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Settlement on Smallacombe Rocks, Ilington		
DESIGNATION:	Scheduled Monument (No. DV452)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Settlement west of Holwell Tor, Ilington		
DESIGNATION:	Scheduled Monument (No. DV450)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Two ring cairns 330m south east of Coldharbour Cross, Loddiswell		
DESIGNATION:	Scheduled Monument (No. 24852)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Dumping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Stone hut circle 530m ESE of Nodden Gate forming an outlying part of a stone hut circle settlement, Lydford		
DESIGNATION:	Scheduled Monument (No. 24076)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:		Stone hut circle 610m ESE of Nodden Gate forming an outlying part of a stone hut circle settlement, Lydford	
DESIGNATION:	Scheduled Monument (No. 24074)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Site of deserted village and field system at Challacombe, Manaton	
DESIGNATION:	Scheduled Monument (No. DV518)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Three hut circles at north end of Vogwell Down, Manaton	
DESIGNATION:	Scheduled Monument (No. DV757)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Four round barrows on Wigford Down, Meavy	
DESIGNATION:	Scheduled Monument (No. DV435)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Greenwell Girt socket stone 600m SSW of Lovaton hamlet, Meavy	
DESIGNATION:	Scheduled Monument (No. 24814)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Other	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Hut circle on Wigford Down, Meavy	
DESIGNATION:	Scheduled Monument (No. DV564)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Hut circles south east of Brisworthy, Meavy	
DESIGNATION:	Scheduled Monument (No. DV432)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Prehistoric enclosures on Dewerstone Hill, 500m south east of Dewerstone Cottage, Meavy	
DESIGNATION:	Scheduled Monument (No. 34436)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHs	World Heritage Site

SITE NAME: Round barrow north of Cadworthy Wood, Meavy			
DESIGNATION:	Scheduled Monument (No. DV565)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Settlement on Wigford Down south of Durance, Meavy			
DESIGNATION:	Scheduled Monument (No. DV436)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Settlement on Wigford Down, Meavy			
DESIGNATION:	Scheduled Monument (No. DV563)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Three hut circles north west of Cadworthy, Meavy			
DESIGNATION:	Scheduled Monument (No. DV566)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Three hut circles on south part of Wigford Down, Meavy			
DESIGNATION:	Scheduled Monument (No. DV562)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Two hut circles south of Catstor Down, Meavy			
DESIGNATION:	Scheduled Monument (No. DV561)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Enclosure south west of Hingston Rocks, Moretonhampstead			
DESIGNATION:	Scheduled Monument (No. DV330)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Wooston Castle, Moretonhampstead			
DESIGNATION:	Scheduled Monument (No. DV265)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Four hut circles north of Bush Down, North Bovey			
DESIGNATION:	Scheduled Monument (No. DV971)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Prehistoric settlement and field system 240m east of Challacombe Cross, North Bovey			
DESIGNATION:	Scheduled Monument (No. 22376)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Two hut circles north west of Bush Down, North Bovey			
DESIGNATION:	Scheduled Monument (No. DV970)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Cairnfield 460m south east of Cox Tor, Peter Tavy			
DESIGNATION:	Scheduled Monument (No. 22365)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Cairnfield and two stone hut circles 490m and 550m south west of Cox Tor, Peter Tavy			
DESIGNATION:	Scheduled Monument (No. 22364)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Coaxial field system and prehistoric settlement 410m west of Cox Tor, Peter Tavy			
DESIGNATION:	Scheduled Monument (No. 22361)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Eluvial tin streamworks and prehistoric coaxial field system together with other archaeological remains on Whitchurch Common, Peter Tavy			
DESIGNATION:	Scheduled Monument (No. 22234)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Enclosed settlement 420m south of Doetor Farm, Peter Tavy			
DESIGNATION:	Scheduled Monument (No. 20353)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Prehistoric settlement 610m south west of Cox Tor, Peter Tavy		
DESIGNATION:	Scheduled Monument (No. 22362)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Stone hut circle and a short length of boundary wall forming part of an unenclosed stone hut circle settlement on the north east slope of Cox Tor, Peter Tavy		
DESIGNATION:	Scheduled Monument (No. 20397)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Stone hut circle and field-plots 100m east of Ger Tor, Peter Tavy		
DESIGNATION:	Scheduled Monument (No. 22245)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Two stone hut circles 450m SSE of Ger Tor, Peter Tavy		
DESIGNATION:	Scheduled Monument (No. 22316)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	A stone alignment, kerbed cairn, prehistoric settlement, four pillow mounds, a vermin trap and animal runs 720m south west of Great Trowlesworthy Tor, Shaugh Prior		
DESIGNATION:	Scheduled Monument (No. 24229)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Agglomerated enclosure with hut circles south west of Ditsworthy Clam, Shaugh Prior		
DESIGNATION:	Scheduled Monument (No. 10693)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	An enclosed settlement, length of reave, two vermin traps and a pillow mound 770m east of Trowlesworthy Warren House, Shaugh Prior		
DESIGNATION:	Scheduled Monument (No. 28654)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	An unenclosed stone hut circle settlement 760m north east of Trowlesworthy Warren House, Shaugh Prior		
DESIGNATION:	Scheduled Monument (No. 24240)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Barrow near Shaugh Cross, Shaugh Prior		
DESIGNATION:	Scheduled Monument (No. DV275)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Cairn south of Mill Corner, Shaugh Prior		
DESIGNATION:	Scheduled Monument (No. 10679)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Cairn with a cist east of Willings Walls Reave, Shaugh Prior		
DESIGNATION:	Scheduled Monument (No. 10649)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Cairn with a cist, one of several on the western edge of Lee Moor, Shaugh Prior		
DESIGNATION:	Scheduled Monument (No. 10641)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Cross Dyke reave, Shaugh Prior		
DESIGNATION:	Scheduled Monument (No. 10611)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Double stone alignment with a terminal stone setting south of Great Trowlesworthy Tor, Shaugh Prior		
DESIGNATION:	Scheduled Monument (No. 10664)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate stock erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Eight pillow mounds and a vermin trap on the northern slope of Little Trowlesworthy Tor forming part of Trowlesworthy Warren, Shaugh Prior		
DESIGNATION:	Scheduled Monument (No. 28798)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Enclosed stone hut circle settlement and three round cairns on Giant's Hill, Shaugh Prior		
DESIGNATION:	Scheduled Monument (No. 24190)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Enclosure with hut circles west of Plym Steps, Shaugh Prior		
DESIGNATION:	Scheduled Monument (No. 10687)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Hut circles west of Saddlesborough, Shaugh Prior		
DESIGNATION:	Scheduled Monument (No. DV431)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Medieval farmstead and field system, length of Willings Walls Reave, four round cairns, a ring cairn and pillow mounds at Willings Walls Warren, Shaugh Prior		
DESIGNATION:	Scheduled Monument (No. 24231)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Multi-period remains at Hentor Warren, Shaugh Prior		
DESIGNATION:	Scheduled Monument (No. 24230)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	One of a number of cairns with cists south of Shavercombe Brook, Shaugh Prior		
DESIGNATION:	Scheduled Monument (No. 10653)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	One of a number of cairns with cists south of Shavercombe Brook, Shaugh Prior		
DESIGNATION:	Scheduled Monument (No. 10654)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	One of three stone hut circles 500m SSE of Legis Tor, Shaugh Prior		
DESIGNATION:	Scheduled Monument (No. 10832)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Pillow mound 100m south east of Great Trowlesworthy Tor, forming part of Trowlesworthy Warren, Shaugh Prior		
DESIGNATION:	Scheduled Monument (No. 24251)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:		Pillow mound 160m south west of Great Trowlesworthy Tor, forming part of Trowlesworthy Warren, Shaugh Prior	
DESIGNATION:	Scheduled Monument (No. 24250)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:		Pillow mound 270m south east of Ditsworthy Warren House forming part of Hentor Warren, Shaugh Prior	
DESIGNATION:	Scheduled Monument (No. 24078)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:		Pillow mound 530m ENE of Trowlesworthy Warren House forming part of Trowlesworthy Warren, Shaugh Prior	
DESIGNATION:	Scheduled Monument (No. 24213)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:		Pillow mound 610m SSW of Ditsworthy Warren House forming part of Willings Walls Warren, Shaugh Prior	
DESIGNATION:	Scheduled Monument (No. 24221)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:		Pillow mound 620m ESE of Legis Tor forming part of Willings Walls Warren, Shaugh Prior	
DESIGNATION:	Scheduled Monument (No. 24223)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:		Pillow mound 630m east of Legis Tor forming part of Willings Walls Warren, Shaugh Prior	
DESIGNATION:	Scheduled Monument (No. 24224)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:		Pillow mound 760m ENE of Trowlesworthy Warren House, forming part of Trowlesworthy Warren, Shaugh Prior	
DESIGNATION:	Scheduled Monument (No. 24235)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:		Pillow mound 790m NNE of Blackaton Cross, forming part of Trowlesworthy Warren, Shaugh Prior	
DESIGNATION:	Scheduled Monument (No. 24247)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:		Pillow mound 840m north east of Trowlesworthy Warren House, forming part of Trowlesworthy Warren, Shaugh Prior	
DESIGNATION:	Scheduled Monument (No. 24242)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Pillow mound 860m NNW of Blackaton Cross, forming part of Trowlesworthy Warren, Shaugh Prior	
DESIGNATION:	Scheduled Monument (No. 24249)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Pillow mound 860m SSE of Trowlesworthy Warren House, forming part of Trowlesworthy Warren, Shaugh Prior	
DESIGNATION:	Scheduled Monument (No. 24246)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Pillow mound and animal run 830m north east of Trowlesworthy Warren House, forming part of Trowlesworthy Warren, Shaugh Prior	
DESIGNATION:	Scheduled Monument (No. 24241)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Pound and hut circles north of Hawk's Tor, Shaugh Prior	
DESIGNATION:	Scheduled Monument (No. DV422)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Pounds and hut circles north of Saddlesborough, Shaugh Prior	
DESIGNATION:	Scheduled Monument (No. DV428)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Rectangular building 420m north west of Hen Tor, forming an outlying part of Hentor Farm, Shaugh Prior	
DESIGNATION:	Scheduled Monument (No. 24222)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Round barrow north west of Saddlesborough, Shaugh Prior	
DESIGNATION:	Scheduled Monument (No. DV430)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Round cairn on Lee Moor 950m south east of Great Trowlesworthy Tor, Shaugh Prior		
DESIGNATION:	Scheduled Monument (No. 28793)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Stone hut circle north east of Hentor Brook, Shaugh Prior		
DESIGNATION:	Scheduled Monument (No. 10659)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Stone hut circle north of Hentor Brook, Shaugh Prior		
DESIGNATION:	Scheduled Monument (No. 10660)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Stone hut circle settlement 600m ENE of Great Trowlesworthy Tor, Shaugh Prior		
DESIGNATION:	Scheduled Monument (No. 24119)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Stone row north west of Saddlesborough, Shaugh Prior		
DESIGNATION:	Scheduled Monument (No. DV429)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Three pillow mounds and a linear gully 200m north of Great Trowlesworthy Tor forming part of Trowlesworthy Warren, Shaugh Prior		
DESIGNATION:	Scheduled Monument (No. 24118)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Two pillow mounds 640m ENE of Trowlesworthy Warren House forming part of Trowlesworthy Warren, Shaugh Prior		
DESIGNATION:	Scheduled Monument (No. 28653)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Two pillow mounds and a small area of tin streamwork 510m south west of Ditsworthy Warren House forming part of Willings Walls Warren, Shaugh Prior		
DESIGNATION:	Scheduled Monument (No. 24218)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:		Two pillow mounds and a small area of tin streamwork earthworks 770m north of Blackaton Cross, forming part of Trowlesworthy Warren, Shaugh Prior	
DESIGNATION:	Scheduled Monument (No. 24248)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Two round cairns 600m ENE of Great Trowlesworthy Tor, Shaugh Prior	
DESIGNATION:	Scheduled Monument (No. 10638)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Two stone hut circles and an enclosure 680m ENE of Trowlesworthy Warren House, Shaugh Prior	
DESIGNATION:	Scheduled Monument (No. 24239)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Two stone hut circles north of Spanish Lake, Lee Moor, Shaugh Prior	
DESIGNATION:	Scheduled Monument (No. 10695)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Unenclosed stone hut circle settlement on the western edge of Lee Moor, Shaugh Prior	
DESIGNATION:	Scheduled Monument (No. 10692)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Vermin trap 350m south west of Great Trowlesworthy Tor forming part of Trowlesworthy Warren, Shaugh Prior	
DESIGNATION:	Scheduled Monument (No. 22378)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Vermin trap 520m SSW of Trowlesworthy Warren House forming part of Trowlesworthy Warren, Shaugh Prior	
DESIGNATION:	Scheduled Monument (No. 24217)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Vermin trap 700m ENE of Trowlesworthy Warren House, forming part of Trowlesworthy Warren, Shaugh Prior	
DESIGNATION:	Scheduled Monument (No. 24236)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:		Vermin trap 730m ENE of Trowlesworthy Warren House, forming part of Trowlesworthy Warren, Shaugh Prior	
DESIGNATION:	Scheduled Monument (No. 24237)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Vermin trap 800m south east of Trowlesworthy Warren House forming part of Trowlesworthy Warren, Shaugh Prior	
DESIGNATION:	Scheduled Monument (No. 24215)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Agglomerated enclosure with hut circles and later farmstead at Whittenknowles Rocks, Sheepstor	
DESIGNATION:	Scheduled Monument (No. 10710)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Brisworthy stone circle, Sheepstor	
DESIGNATION:	Scheduled Monument (No. 10594)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Cairn east of Scout Hut, Sheepstor	
DESIGNATION:	Scheduled Monument (No. 10713)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Cairn south west of Lower Hartor Tor, Sheepstor	
DESIGNATION:	Scheduled Monument (No. 10680)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Cairn with a cist north of Drizzlecombe stone alignments, Sheepstor	
DESIGNATION:	Scheduled Monument (No. 10715)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Cairn with cist north of Gutter Tor, Sheepstor	
DESIGNATION:	Scheduled Monument (No. 10581)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Enclosed stone hut settlement south west of Gutter Tor, Sheepstor			
DESIGNATION:	Scheduled Monument (No. 10597)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Enclosure north west of Gutter Tor, Sheepstor			
DESIGNATION:	Scheduled Monument (No. 10630)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Enclosure with hut circles on Eastern Tor, Sheepstor			
DESIGNATION:	Scheduled Monument (No. 10712)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Enclosure with hut circles on Gutter Tor, Sheepstor			
DESIGNATION:	Scheduled Monument (No. 10595)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Enclosure with hut circles south east of Eastern Tor, Sheepstor			
DESIGNATION:	Scheduled Monument (No. 10711)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Part of Eylesbarrow Reave, Sheepstor			
DESIGNATION:	Scheduled Monument (No. 10626)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Part of Eylesbarrow watershed reave, Sheepstor			
DESIGNATION:	Scheduled Monument (No. 10741)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Pillow mound 180m west of Legis Tor forming part of Legistor Warren, Sheepstor			
DESIGNATION:	Scheduled Monument (No. 24128)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Pillow mound 220m south west of Legis Tor forming part of Legistor Warren, Sheepstor			
DESIGNATION:	Scheduled Monument (No. 24127)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Pillow mound 40m east of Legis Tor forming part of Legistor Warren, Sheepstor			
DESIGNATION:	Scheduled Monument (No. 24129)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Prehistoric enclosed settlement 950m north east of Ditsworthy Warren House, Sheepstor			
DESIGNATION:	Scheduled Monument (No. 34470)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Prehistoric settlement, three round cairns and a post-medieval rabbit warren at Legis Tor, Sheepstor			
DESIGNATION:	Scheduled Monument (No. 22289)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Round cairn east of Whittenknowles Rocks, 960m ENE of Gutter Tor, Sheepstor			
DESIGNATION:	Scheduled Monument (No. 34464)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Three stone alignments, 15 cairns, a cist, a partially enclosed stone hut circle settlement and a small clapper bridge at Drizzle Combe, Sheepstor			
DESIGNATION:	Scheduled Monument (No. 24104)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Two enclosures and a length of the Eylesbarrow watershed reave 800m WSW of Eylesbarrow, Sheepstor			
DESIGNATION:	Scheduled Monument (No. 10742)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Unenclosed stone hut settlement south west of Gutter Tor, Sheepstor			
DESIGNATION:	Scheduled Monument (No. 10598)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Vermin trap immediately south west of Legis Tor forming part of Legistor Warren, Sheepstor		
DESIGNATION:	Scheduled Monument (No. 24130)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Cairn near Ball Gate, Corringdon Ball, South Brent		
DESIGNATION:	Scheduled Monument (No. 10571)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Cist with a retaining kerb north west of Corringdon Ball, South Brent		
DESIGNATION:	Scheduled Monument (No. 10780)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Enclosure and hut circle north of Old Hill, South Brent		
DESIGNATION:	Scheduled Monument (No. DV1013)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Enclosure with hut circles and rectangular pens, south of Bala Brook, South Brent		
DESIGNATION:	Scheduled Monument (No. 10578)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Enclosure with hut circles north of Bala Brook intake, South Brent		
DESIGNATION:	Scheduled Monument (No. 10579)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Enclosure with hut circles north of Bala Brook intake, South Brent		
DESIGNATION:	Scheduled Monument (No. 10623)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Enclosures and hut circles at Petre's Pits Bottom, South Brent		
DESIGNATION:	Scheduled Monument (No. DV1015)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Hut circle and fields, Bishop's Mead, South Brent		
DESIGNATION:	Scheduled Monument (No. DV467)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Hut enclosure north of Old Hill, South Brent		
DESIGNATION:	Scheduled Monument (No. DV1014)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	One of several stone hut circles north of Corringdon Ball, South Brent		
DESIGNATION:	Scheduled Monument (No. I0854)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Riders Rings (The Rings), South Brent		
DESIGNATION:	Scheduled Monument (No. DV374)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Stone alignment north of Glasscombe Upper Plantation, South Brent		
DESIGNATION:	Scheduled Monument (No. I0570)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	The northern of three stone hut circles south west of Corringdon Leat, Corringdon Ball, South Brent		
DESIGNATION:	Scheduled Monument (No. I0864)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	No known threat	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Three enclosed hut groups, Black Tor, Shipley Bridge, South Brent		
DESIGNATION:	Scheduled Monument (No. DV384)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Two conjoined huts between two enclosures north of Bala Brook intake, South Brent		
DESIGNATION:	Scheduled Monument (No. I0622)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Two hut circles on the right bank of Red Brook, South Brent		
DESIGNATION:	Scheduled Monument (No. 10577)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	A prehistoric settlement complex, length of reave, tin streamwork and stamping mill on the western slopes of Cosdon Hill, South Tawton		
DESIGNATION:	Scheduled Monument (No. 28800)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	A warren, two stone hut circle settlements, cairnfields and cairns at Ivy Tor, ESE of Belstone, South Tawton		
DESIGNATION:	Scheduled Monument (No. 28727)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Agglomerate enclosure and 15 stone hut circles 560m west of Cawsand Beacon, South Tawton		
DESIGNATION:	Scheduled Monument (No. 24141)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Agglomerate enclosure and ten stone hut circles 500m west of Cawsand Beacon, South Tawton		
DESIGNATION:	Scheduled Monument (No. 24140)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	An agglomerated enclosed settlement 480m west of Stoneyhurst, South Tawton		
DESIGNATION:	Scheduled Monument (No. 28705)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Cairn cemetery and earthwork bank 340m south west of Blackaton Brook Ford, South Tawton		
DESIGNATION:	Scheduled Monument (No. 28700)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Cairnfield 760m west of Stoneyhurst, South Tawton		
DESIGNATION:	Scheduled Monument (No. 28707)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Cairfield 790m north west of Stoneyhurst, South Tawton		
DESIGNATION:	Scheduled Monument (No. 28704)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Partially enclosed stone hut circle settlement 650m south east of Tawcroft, South Tawton		
DESIGNATION:	Scheduled Monument (No. 28799)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Round cairn 570m west of Stoneyhurst, South Tawton		
DESIGNATION:	Scheduled Monument (No. 28706)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Two hut circles east of Foxes Holt, South Tawton		
DESIGNATION:	Scheduled Monument (No. DV776)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Stone hut circle 140m north west of Higher Shilstone, Throwleigh		
DESIGNATION:	Scheduled Monument (No. 28716)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Chambered cairn in Cuckoo Ball newtake, Ugborough		
DESIGNATION:	Scheduled Monument (No. 10548)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Enclosure with hut circles north of Scad Brook, Ugborough		
DESIGNATION:	Scheduled Monument (No. 10553)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Long cairn east of Butterdon Hill, Ugborough		
DESIGNATION:	Scheduled Monument (No. 10547)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Multiple stone alignment and associated cairns west of Glasscombe Upper Plantation, Ugborough		
DESIGNATION:	Scheduled Monument (No. 10569)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	One of a number of cairns at Black Pool, Ugborough		
DESIGNATION:	Scheduled Monument (No. 10545)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	One of a number of cairns at Black Pool, Ugborough		
DESIGNATION:	Scheduled Monument (No. 10608)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Stone alignment and cairn south east of Western Beacon, Ugborough		
DESIGNATION:	Scheduled Monument (No. 10550)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	A length of the Great Western Reave, a prehistoric settlement, three cairns and two field systems on Walkhampton Common, Walkhampton		
DESIGNATION:	Scheduled Monument (No. 34425)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	An agglomerate enclosure and seven stone hut circles 460m WSW of Raddick Hill summit, Walkhampton		
DESIGNATION:	Scheduled Monument (No. 22293)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	An enclosed stone hut circle settlement and later tin working earthworks, 540m south east of Down Tor, Walkhampton		
DESIGNATION:	Scheduled Monument (No. 24080)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	An enclosure containing one stone hut circle 460m west of Cross Gate, Walkhampton		
DESIGNATION:	Scheduled Monument (No. 24110)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	An enclosure, attached stone hut circle and length of reave 180m NNE of Leather Tor, Walkhampton		
DESIGNATION:	Scheduled Monument (No. 20295)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	An enclosure, six stone hut circles, a length of reave and several prospecting pits 170m north east of Leather Tor, Walkhampton		
DESIGNATION:	Scheduled Monument (No. 20294)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	An unenclosed stone hut circle settlement, an irregular aggregate field system, a length of reave and an enclosure on the south east slope of Leeden Tor, Walkhampton		
DESIGNATION:	Scheduled Monument (No. 22265)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Cairn 550m south west of Raddick Hill summit forming part of a cairnfield, Walkhampton		
DESIGNATION:	Scheduled Monument (No. 22309)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Cairn 560m south west of Raddick Hill summit forming part of a cairnfield, Walkhampton		
DESIGNATION:	Scheduled Monument (No. 22308)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Eight stone hut circles and two enclosures forming part of an unenclosed settlement 580m south of Leeden Tor, Walkhampton		
DESIGNATION:	Scheduled Monument (No. 22263)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Eleven stone hut circles, a length of boundary wall and a field system forming part of an unenclosed settlement on the north east slope of Sharpitor, Walkhampton		
DESIGNATION:	Scheduled Monument (No. 22272)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Enclosed settlement 380m south west of Raddick Hill summit, Walkhampton		
DESIGNATION:	Scheduled Monument (No. 22299)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Enclosed settlement 400m west of Raddick Hill summit, Walkhampton			
DESIGNATION:	Scheduled Monument (No. 22294)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Enclosure and stone hut circle 320m north east of Sharpitor forming part of a stone hut circle settlement, Walkhampton			
DESIGNATION:	Scheduled Monument (No. 22271)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Enclosure and stone hut circle 700m west of Sharpitor, Walkhampton			
DESIGNATION:	Scheduled Monument (No. 34426)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Four stone hut circles and an enclosure 100m north east of Sharpitor summit, Walkhampton			
DESIGNATION:	Scheduled Monument (No. 22279)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Medieval settlement on Peek Hill, 240m and 280m north east of Lowery Tor, Walkhampton			
DESIGNATION:	Scheduled Monument (No. 24089)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Prehistoric coaxial field system and cairns, an historic enclosure and part of RAF Sharpitor, situated on and around Peek Hill, Walkhampton			
DESIGNATION:	Scheduled Monument (No. 24090)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Round cairn 340m ESE of Norsworthy Bridge, Walkhampton			
DESIGNATION:	Scheduled Monument (No. 22395)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Round cairn 650m WSW of Raddick Hill summit, Walkhampton			
DESIGNATION:	Scheduled Monument (No. 22291)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Routrundle Pound, Walkhampton		
DESIGNATION:	Scheduled Monument (No. DV325)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Stone alignment, two round cairns and a length of Walkhampton Common reave lying in a valley between Sharpitor and Leeden Tor, Walkhampton		
DESIGNATION:	Scheduled Monument (No. 22270)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Stone hut circle 155m east of Sharpitor, Walkhampton		
DESIGNATION:	Scheduled Monument (No. 22281)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Stone hut circle 240m south of Down Tor, Walkhampton		
DESIGNATION:	Scheduled Monument (No. 24086)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Stone hut circle 315m north east of Sharpitor forming part of a stone hut circle settlement, Walkhampton		
DESIGNATION:	Scheduled Monument (No. 22276)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Stone hut circle 350m north east of Sharpitor forming part of a stone hut circle settlement, Walkhampton		
DESIGNATION:	Scheduled Monument (No. 22277)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Stone hut circle 370m north east of Sharpitor forming part of a stone hut circle settlement, Walkhampton		
DESIGNATION:	Scheduled Monument (No. 22278)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Stone hut circle settlement 250m east of Cuckoo Rock, Walkhampton		
DESIGNATION:	Scheduled Monument (No. 34469)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Stone hut circle settlement, irregular aggregate field system, two long houses and a medieval and post-medieval field system 700m SSW of Black Tor, Walkhampton			
DESIGNATION:	Scheduled Monument (No. 22288)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Tinworks and other archaeological remains in the Meavy valley at Stanlake, Black Tor, Hart Tor and Cramber Tor, Walkhampton			
DESIGNATION:	Scheduled Monument (No. 24106)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Twelve cairns, a lynchet and a boundary bank forming part of a cairnfield 440m south west of Raddick Hill summit, Walkhampton			
DESIGNATION:	Scheduled Monument (No. 22292)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Two cairns and a boundary bank forming part of a cairnfield 440m south west of Raddick Hill summit, Walkhampton			
DESIGNATION:	Scheduled Monument (No. 22295)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Two stone hut circles 570m south west of Down Tor, Walkhampton			
DESIGNATION:	Scheduled Monument (No. 24111)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Two stone hut circles, a reave, round cairn and shelter south east of Sharpitor, Walkhampton			
DESIGNATION:	Scheduled Monument (No. 22282)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Unenclosed stone hut circle settlement 370m south west of Routrundle, Walkhampton			
DESIGNATION:	Scheduled Monument (No. 28781)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Hembury Castle, West Buckfastleigh			
DESIGNATION:	Scheduled Monument (No. DV141)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Enclosure and stone hut circle 770m south of Cox Tor,Whitchurch		
DESIGNATION:	Scheduled Monument (No. 22366)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Deserted medieval settlement at Blackaton, 340m and 400m north east of Lower Blackaton, Widecombe-in-the-Moor		
DESIGNATION:	Scheduled Monument (No. 36025)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Enclosure and fields north of Yar Tor,Widecombe-in-the-Moor		
DESIGNATION:	Scheduled Monument (No. DV533)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Foale's Arrishes, huts and fields, Blackslade Down,Widecombe-in-the-Moor		
DESIGNATION:	Scheduled Monument (No. DV262)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Hut 700yds (640m) north west of Sharp Tor,Widecombe-in-the-Moor		
DESIGNATION:	Scheduled Monument (No. DV337)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Hut circles east of Pritton,Widecombe-in-the-Moor		
DESIGNATION:	Scheduled Monument (No. DV855)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Hut circles east of Southway,Widecombe-in-the-Moor		
DESIGNATION:	Scheduled Monument (No. DV858)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Hut circles on Bonehill Down,Widecombe-in-the-Moor		
DESIGNATION:	Scheduled Monument (No. DV856)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Hut circles on Hedge Down, Widecombe-in-the-Moor		
DESIGNATION:	Scheduled Monument (No. DV857)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Hut circles south east of Yar Tor, Widecombe-in-the-Moor		
DESIGNATION:	Scheduled Monument (No. DV532)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Pound at Newbridge, Widecombe-in-the-Moor		
DESIGNATION:	Scheduled Monument (No. DV149)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Two cairns on Cator Common, Widecombe-in-the-Moor		
DESIGNATION:	Scheduled Monument (No. DV1007)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Yar Tor stone row and adjacent cist, Widecombe-in-the-Moor		
DESIGNATION:	Scheduled Monument (No. DV529)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Horrabridge		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Expected to deteriorate
CONTACT:	Keith McKay (LA) 01626 832093		

EAST DEVON



SITE NAME: **Poltmore House, Poltmore**

DESIGNATION: Listed Building Grade II*
 CONDITION: Very bad
 OCCUPANCY: Vacant
 PRIORITY: A (A)
 OWNERSHIP: Trust

C16 country house with later additions. Acquired by a trust with funding from English Heritage and the Local Planning Authority in 1997. Urgent works carried out in 1998 to make the building wind/weathertight. Emergency roof cover erected 2006. A feasibility study was undertaken with grant from Architectural Heritage Fund and English Heritage. EH grant offered 2008 for investigation and emergency repairs.

Contact: Business Manager 0117 975 0700



SITE NAME: **Tithe barn and stable block at Bishop's Court, Clyst St Mary, Sowton**

DESIGNATION: Listed Building Grade I
 CONDITION: Very bad
 OCCUPANCY: Vacant
 PRIORITY: C (C)
 OWNERSHIP: Private

Large mid C14 barn with arch-braced base-crucc roof of seven bays, and long early C16 range of stables. Currently unused and with a temporary corrugated roof. Owners are undertaking a feasibility study into potential uses, grant-aided by English Heritage.

Contact: Simon Ramsden 0117 975 0676

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
 If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Hembury Fort, Awliscombe			
DESIGNATION:	Scheduled Monument (No. 29660)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Newenham Abbey, Axminster			
DESIGNATION:	Scheduled Monument (No. 24843)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Hawkesdown Camp and associated outwork, Axmouth			
DESIGNATION:	Scheduled Monument (No. 29640)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Bowl barrow 400m north east of Common Farm, Aylesbeare			
DESIGNATION:	Scheduled Monument (No. 29635)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Bowl barrow 210m north east of Starved Oak Cross, Brampford Speke			
DESIGNATION:	Scheduled Monument (No. 15018)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Bowl barrow 320m north east of Starved Oak Cross, Brampford Speke			
DESIGNATION:	Scheduled Monument (No. 15017)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Bowl barrow in Long Plantation, 610m north east of Starved Oak Cross, Brampford Speke			
DESIGNATION:	Scheduled Monument (No. 15020)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Bowl barrow in Long Plantation, 680m north east of Starved Oak Cross, Brampford Speke			
DESIGNATION:	Scheduled Monument (No. 15019)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Cross ridge dyke extending north and south of The Three Horse Shoes Inn, Branscombe			
DESIGNATION:	Scheduled Monument (No. 29636)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Prehistoric field system on the cliffs above Littlecombe Shoot, Branscombe			
DESIGNATION:	Scheduled Monument (No. 33049)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Bowl barrow 100m south west of the B3174, forming part of a dispersed barrow group on Farway Hill, Farway			
DESIGNATION:	Scheduled Monument (No. 24959)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Bowl barrow 230m north west of Farway Castle, forming part of a dispersed barrow group on Farway Hill, Farway			
DESIGNATION:	Scheduled Monument (No. 24966)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Bowl barrow 340m north west of Farway Castle, forming part of a dispersed barrow group on Farway Hill, Farway			
DESIGNATION:	Scheduled Monument (No. 24968)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Bowl barrow 60m south west of the B3174, forming part of a dispersed barrow group on Farway Hill, Farway			
DESIGNATION:	Scheduled Monument (No. 24960)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Round barrow cemetery on Broad Down, Farway			
DESIGNATION:	Scheduled Monument (No. 29634)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Three bowl barrows to the south west of the B3174, forming part of a round barrow cemetery on Farway Hill, Farway			
DESIGNATION:	Scheduled Monument (No. 24962)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Two bowl barrows on the parish boundary to the south west of the B3174, forming part of a dispersed barrow group on Farway Hill, Farway		
DESIGNATION:	Scheduled Monument (No. 24958)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:	A bowl barrow 370m WNW of Ring-in-the-Mire, forming part of a round barrow cemetery on Gittisham Hill, Gittisham		
DESIGNATION:	Scheduled Monument (No. 27404)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:	A bowl barrow 500m WNW of Ring-in-the-Mire, forming part of a round barrow cemetery on Gittisham Hill, Gittisham		
DESIGNATION:	Scheduled Monument (No. 27405)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:	Dumpdon Camp, Luppitt		
DESIGNATION:	Scheduled Monument (No. 29661)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:	Three bowl barrows on Lypstone Common, 500m west of Fryingpans, Lypstone		
DESIGNATION:	Scheduled Monument (No. 33032)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Localised/limited animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:	Membury Castle, Membury		
DESIGNATION:	Scheduled Monument (No. 29645)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:	Musbury Castle, Musbury		
DESIGNATION:	Scheduled Monument (No. 29659)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:	Cursus, long mortuary enclosure, ring ditch and other associated cropmarks 700m east of Netherexe Barton, Nether Exe		
DESIGNATION:	Scheduled Monument (No. 22340)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Two bowl barrows north of Green Lane, 430m and 330m west of Rewe Cross, Nether Exe		
DESIGNATION:	Scheduled Monument (No. 29676)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Round barrow cemetery on Venn Ottery Hill, 660m south east of Happy Valley, Newton Poppleford and Harford		
DESIGNATION:	Scheduled Monument (No. 29632)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	High Peak camp, Sidmouth, Otterton		
DESIGNATION:	Scheduled Monument (No. DV55)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Sidbury Castle, Sidmouth		
DESIGNATION:	Scheduled Monument (No. 29658)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Two bowl barrows to the north west of Roncombe Gate Farm, forming part of a dispersed barrow group on Farway Hill, Sidmouth		
DESIGNATION:	Scheduled Monument (No. 24957)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Stockland Great Castle, Stockland		
DESIGNATION:	Scheduled Monument (No. 29646)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Bowl barrow 470m east of Fortescue, Stoke Canon		
DESIGNATION:	Scheduled Monument (No. 29675)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Roman villa 300yds (270m) SSW of Holcombe Farm, Uplyme		
DESIGNATION:	Scheduled Monument (No. DV613)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Bowl barrow 220m WSW of Starved Oak Cross, Upton Pyne			
DESIGNATION:	Scheduled Monument (No. 15024)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Bowl barrow 280m NNE of Starved Oak Cross, Upton Pyne			
DESIGNATION:	Scheduled Monument (No. 15021)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Bowl barrow 300m SSE of Stevenstone Farm, Upton Pyne			
DESIGNATION:	Scheduled Monument (No. 15016)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Bowl barrow 350m NNE of Starved Oak Cross, Upton Pyne			
DESIGNATION:	Scheduled Monument (No. 15022)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Bowl barrow 400m WSW of Starved Oak Cross, Upton Pyne			
DESIGNATION:	Scheduled Monument (No. 15025)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Bowl barrow 450m SSE of Stevenstone Farm, Upton Pyne			
DESIGNATION:	Scheduled Monument (No. 15023)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Bowl barrow 500m west of Starved Oak Cross, Upton Pyne			
DESIGNATION:	Scheduled Monument (No. 15026)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Bowl barrow 600m west of Starved Oak Cross, Upton Pyne			
DESIGNATION:	Scheduled Monument (No. 15027)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Earthwork enclosure 330yds (300m) south west of Three Horse Shoes Inn, Upton Pyne		
DESIGNATION:	Scheduled Monument (No. DV954)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Two bowl barrows, 350m south of Stevenstone Farm, Upton Pyne		
DESIGNATION:	Scheduled Monument (No. I5014)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Castle Hill, Widworthy		
DESIGNATION:	Scheduled Monument (No. 29633)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

EXETER

SITE NAME:	Alphin Brook, Exeter		
DESIGNATION:	Conservation Area	CONDITION:	Optimal
VULNERABILITY:	Low	TREND:	Expected to deteriorate significantly
CONTACT:	Katharine Metcalfe (LA) 01392 265227		

SITE NAME:	Belmont, Exeter		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	No significant change expected
CONTACT:	Katharine Metcalfe (LA) 01392 265227		

SITE NAME:	Princes Square, Exeter		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	No significant change expected
CONTACT:	Katharine Metcalfe (LA) 01392 265227		

SITE NAME:	St David's, Exeter		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Expected to deteriorate
CONTACT:	Katharine Metcalfe (LA) 01392 265227		

SITE NAME:	St Sidwells, Exeter		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	No significant change expected
CONTACT:	Katharine Metcalfe (LA) 01392 265227		

EXMOOR (NP)

SITE NAME:	Doone's Houses, Brendon		
DESIGNATION:	Scheduled Monument (No. DV51)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Two round barrows on Cheriton Ridge, Brendon			
DESIGNATION:	Scheduled Monument (No. DV715)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Five barrows and an enclosure on Challacombe Common, Challacombe			
DESIGNATION:	Scheduled Monument (No. DV913)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Round barrow on East Anstey Common, East Anstey			
DESIGNATION:	Scheduled Monument (No. DV647)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Earthwork defences of Countisbury Castle promontory fort, Lynton and Lynmouth			
DESIGNATION:	Scheduled Monument (No. 33056)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Roborough Castle, Lynton and Lynmouth			
DESIGNATION:	Scheduled Monument (No. DV242)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Localised/limited natural erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Round barrow south east of Down Linhay, Lynton and Lynmouth			
DESIGNATION:	Scheduled Monument (No. DV520)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Two round barrows and cairn cemetery, Ikkerton Ridge, Lynton and Lynmouth			
DESIGNATION:	Scheduled Monument (No. DV636)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Two round barrows near Warcombe Water, Lynton and Lynmouth			
DESIGNATION:	Scheduled Monument (No. DV716)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Beacon Castle, South Down, Martinhoe		
DESIGNATION:	Scheduled Monument (No. DV471)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Voley Castle, Parracombe		
DESIGNATION:	Scheduled Monument (No. DV50)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Trentishoe barrows, round cairns, Trentishoe		
DESIGNATION:	Scheduled Monument (No. DV608)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Two round barrows on West Anstey Common, West Anstey		
DESIGNATION:	Scheduled Monument (No. DV648)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

MID DEVON



SITE NAME: **The Walronds,
6 Fore Street,
Cullompton**

DESIGNATION: Listed Building Grade I, CA

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: B (B)

OWNERSHIP: Trust

A large early C17 mansion in the centre of Cullompton. The owner, Cullompton Walronds Preservation Trust, has obtained Stage 1 Heritage Lottery Fund funding and grant aid for project development has been provided by English Heritage and the Local Authority. Emergency repairs have also been undertaken and further grant applications are being made for the full repair of the building.

Contact: Jenny Chesher 0117 975 0686

SITE NAME:	Bowl barrow 220m south west of Hampson Cottage, Bow		
DESIGNATION:	Scheduled Monument (No. 28635)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Bowl barrow 80m south west of Hampson Cottage, Bow		
DESIGNATION:	Scheduled Monument (No. 28637)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Ring ditch 150m north of Natson Farm, Bow		
DESIGNATION:	Scheduled Monument (No. 28639)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA Conservation Area
 LB/LBs Listed Building/s
 NP National Park
 RPG Registered Park and Garden
 SM/SMs Scheduled Monument/s
 UA Unitary Authority
 WHS World Heritage Site

SITE NAME:	Two bowl barrows 180m south west of Hampson Cottage, Bow		
DESIGNATION:	Scheduled Monument (No. 28636)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Two bowl barrows 250m north of Natson Farm, Bow		
DESIGNATION:	Scheduled Monument (No. 28638)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Canonsleigh Abbey, Burescombe		
DESIGNATION:	Scheduled Monument (No. DV296)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Copplestone Cross, Crediton Hamlets		
DESIGNATION:	Scheduled Monument (No. 27329)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Stable
OWNERSHIP:	Local Authority	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Posbury camp, Castle Down, Crediton Hamlets		
DESIGNATION:	Scheduled Monument (No. DV278)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Romano-British villa, Downes, near Crediton, Crediton Hamlets		
DESIGNATION:	Scheduled Monument (No. DV1032)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Two Roman forts and two Roman camps at St Andrew's Hill, Cullompton		
DESIGNATION:	Scheduled Monument (No. 34260)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Three bowl barrows 250m south east of Gibbet Moor Cross, Templeton		
DESIGNATION:	Scheduled Monument (No. 32232)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Three bowl barrows 620m south east of Fordy Bridge, Thorverton		
DESIGNATION:	Scheduled Monument (No. 32231)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Bowl barrow 260m north west of Putson Cross, Tiverton		
DESIGNATION:	Scheduled Monument (No. 32229)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Roman Fort, Bolham Hill, Tiverton		
DESIGNATION:	Scheduled Monument (No. 10502)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Eggesford Castle, 640m north east of Eggesford House, Wembworthy		
DESIGNATION:	Scheduled Monument (No. 30311)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Bowl barrow 130m north east of Burston Cross, Zeal Monachorum		
DESIGNATION:	Scheduled Monument (No. 28611)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Bickleigh		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Expected to deteriorate
CONTACT:	Sue Warren (LA) 01884 234264		

SITE NAME:	Bradninch, Cullompton		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Expected to deteriorate
CONTACT:	Sue Warren (LA) 01884 234264		

SITE NAME:	Cullompton		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Expected to show some improvement
CONTACT:	Sue Warren (LA) 01884 234264		

SITE NAME:	Tiverton		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Expected to deteriorate
CONTACT:	Sue Warren (LA) 01884 234264		

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

NORTH DEVON



SITE NAME: **Hall House,
Bishops Tawton**

Built circa 1846-50 by Philip Hardwick, with a rear range by RD Gould. The house lies within an estate containing several other listed structures within the vicinity. The main range is generally fair, but the rear range is in very poor condition.

DESIGNATION: Listed Building Grade II*

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNERSHIP: Trust

Contact: Francis Kelly 0117 975 0725



SITE NAME: **Broomham Farmhouse,
Kings Nympton**

Early C16 Longhouse with later additions. The roof has been re-thatched with English Heritage grant aid. Further structural work still required.

DESIGNATION: Listed Building Grade II*

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNERSHIP: Private

Contact: Francis Kelly 0117 975 0725

SITE NAME:

**Two bowl barrows 170m west and 200m south west of Berry Down Cross,
forming part of a round barrow cemetery on Berry Down, Berrynarbor**

DESIGNATION: Scheduled Monument (No. 34250)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Phil McMahon 0117 975 0699

SITE NAME:

Round barrow cemetery 210m south west of Hillcrest, Centery Lane, Bittadon

DESIGNATION: Scheduled Monument (No. 34252)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Phil McMahon 0117 975 0699

SITE NAME:

Four bowl barrows on Burrington Moor lying 210m south west of Burrington Moor Cross, Burrington

DESIGNATION: Scheduled Monument (No. 28615)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Other

TREND: Declining

OWNERSHIP: Private

CONTACT: Phil McMahon 0117 975 0699

SITE NAME:

Bowl barrow 280m north east of Beacon Moor Cross, forming part of a round barrow cemetery, Chulmleigh

DESIGNATION: Scheduled Monument (No. 28612)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Phil McMahon 0117 975 0699

SITE NAME:

Bowl barrow 330m east of Beacon Moor Cross, forming part of a round barrow cemetery, Chulmleigh

DESIGNATION: Scheduled Monument (No. 28613)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Phil McMahon 0117 975 0699

SITE NAME:

Camp in East Kidland Wood, Knowstone

DESIGNATION: Scheduled Monument (No. DV473)

CONDITION: Unknown

PRINCIPAL VULNERABILITY: Plant growth

TREND: Declining

OWNERSHIP: Private

CONTACT: Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA Conservation Area
LB/LBs Listed Building/s
NP National Park
RPG Registered Park and Garden
SM/SMs Scheduled Monument/s
UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Saucer barrow 100m south west of Knowstone Moor Cross, Knowstone		
DESIGNATION:	Scheduled Monument (No. 32220)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Castle Roborough, Loxhore		
DESIGNATION:	Scheduled Monument (No. DV514)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Bowl barrow 320m east of New Moor Cross, Molland		
DESIGNATION:	Scheduled Monument (No. 32234)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Hillfort 400m north west of Woodhouse, Queen's Nympton		
DESIGNATION:	Scheduled Monument (No. 28623)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Two bowl barrows 100m east of Catkill Cross, Rose Ash		
DESIGNATION:	Scheduled Monument (No. 28604)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Camp south of Birch Ham Wood, Stoke Rivers		
DESIGNATION:	Scheduled Monument (No. DV458)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Bowl barrow 300m north west of Witheridge Moor Cross (west), Witheridge		
DESIGNATION:	Scheduled Monument (No. 32211)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Bowl barrow 610m south east of Elworthy Cross, Witheridge		
DESIGNATION:	Scheduled Monument (No. 32210)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Ilfracombe		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Expected to deteriorate
CONTACT:	James Bate (LA) 01271 388352		

SOUTH HAMS

	<p>SITE NAME: Warleigh House, Tamerton Foliot, Bickleigh</p> <p>DESIGNATION: Listed Building Grade II*</p> <p>CONDITION: Poor</p> <p>OCCUPANCY: Vacant</p> <p>PRIORITY: B (B)</p> <p>OWNERSHIP: Company</p>	<p>Medieval site. The present C16 house incorporates late medieval roof structures and was remodelled in the mid C18 and again, importantly, by John Foulston of Plymouth from 1825-31.</p> <p>Contact: Francis Kelly 0117 975 0725</p>
	<p>SITE NAME: Yarde Farmhouse, Malborough</p> <p>DESIGNATION: Listed Building Grade I</p> <p>CONDITION: Fair</p> <p>OCCUPANCY: Part occupied</p> <p>PRIORITY: F (F)</p> <p>OWNERSHIP: Private</p>	<p>Late C16 manor house. Repairs previously grant-aided by English Heritage. Work to stabilise, repair and rehabilitate this sub-medieval house is largely complete. The early C18 chamber block is now wind and weathertight and repairs and upgrading have begun inside. The greatest area of uncertainty is now confined to the important painted hangings whose conservation and future display are being negotiated.</p> <p>Contact: Francis Kelly 0117 975 0725</p>
	<p>SITE NAME: Pridhamsleigh Farmhouse, Ashburton, Staverton</p> <p>DESIGNATION: Listed Building Grade II*</p> <p>CONDITION: Very bad</p> <p>OCCUPANCY: Vacant</p> <p>PRIORITY: A (A)</p> <p>OWNERSHIP: Private</p>	<p>C16 and C17 Farmhouse. Subdivided into Pridhamsleigh Manor and Pridhamsleigh Farmhouse. Farmhouse only is at risk. North side of the Farmhouse has planning approval for conversion to two cottages. Part of the Farmhouse has suffered collapse. At risk from exposure and neglect. An Urgent Works Notice has been served.</p> <p>Contact: Francis Kelly 0117 975 0725</p>
	<p>SITE NAME: 39 The High Street, Totnes</p> <p>DESIGNATION: Listed Building Grade II*, CA</p> <p>CONDITION: Poor</p> <p>OCCUPANCY: Part occupied</p> <p>PRIORITY: C (C)</p> <p>OWNERSHIP: Private</p>	<p>Fine C17 plasterwork and interior threatened by poor condition of roof. Ground floor is a shop. Upper floors are unoccupied and in need of repair and new services. Owner is discussing proposals for repair and alteration with the Local Planning Authority and English Heritage.</p> <p>Contact: Francis Kelly 0117 975 0725</p>
	<p>SITE NAME: Garden wall, steps and gatepiers south of Langdon Court Hotel, Langdon, Wembury</p> <p>DESIGNATION: Listed Building Grade II*, RPG II</p> <p>CONDITION: Very bad</p> <p>OCCUPANCY: Not applicable</p> <p>PRIORITY: C (C)</p> <p>OWNERSHIP: Private</p>	<p>Late C17 to early C18 formal terraced garden, the layout little altered since the early C18. Terraces extend south from the house on rising ground, with central axial path and connecting steps. Enclosed by walls to the east, south and west. The northern (larger) terrace has C17 gate piers and gates in the east and west walls and a central path.</p> <p>Contact: Francis Kelly 0117 975 0725</p>
	<p>SITE NAME: Pair of garden houses south of Langdon Court Hotel, Langdon, Wembury</p> <p>DESIGNATION: Listed Building Grade II*, RPG II</p> <p>CONDITION: Very bad</p> <p>OCCUPANCY: Not applicable</p> <p>PRIORITY: C (C)</p>	<p>Early C18 gazebos standing at the junction of the northern and southern terraces in the late C17 to early C18 formal terraced garden to the south of the house. The walls, steps and gate piers of the terraced garden are also at risk. Roofless. Negotiations are underway to restore them as annexes of the hotel.</p> <p>Contact: Francis Kelly 0117 975 0725</p>

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Hilltop enclosure known as Maristow Camp, 240m east of Middle Park House, Bickleigh			
DESIGNATION:	Scheduled Monument (No. 33770)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Long barrow and two bowl barrows, 200m south east of Chapelcombe, Bigbury			
DESIGNATION:	Scheduled Monument (No. 33748)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Iron Age hillfort known as Wasteberry Camp, medieval deer park and post-medieval warren, 800m north west of Lyneham House, Brixton			
DESIGNATION:	Scheduled Monument (No. 33794)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Bowl barrow 530m south east of Duncombe Court, forming an outlying part of a barrow cemetery, Charleton			
DESIGNATION:	Scheduled Monument (No. 33777)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Three bowl barrows 310m west of Home Farm, forming part of a round barrow cemetery, Charleton			
DESIGNATION:	Scheduled Monument (No. 33776)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Two bowl barrows 440m south east of Duncombe Court, forming part of a round barrow cemetery, Charleton			
DESIGNATION:	Scheduled Monument (No. 33779)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Cholwich Town Cross: a wayside cross between Quick Bridge and Tolchmoor Gate, Cornwall			
DESIGNATION:	Scheduled Monument (No. 24816)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Two round barrows on Ridding Down, Cornwall			
DESIGNATION:	Scheduled Monument (No. DV721)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Deer park north and north west of Dartington Hall, Dartington			
DESIGNATION:	Scheduled Monument (No. 33785)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Hilltop enclosure and woodbanks in Chacegrove Wood, 540m north west of Dartington Hall, Dartington			
DESIGNATION:	Scheduled Monument (No. 33786)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Hilltop enclosures in North Wood, 780m NNW of Old Parsonage Farm, Dartington			
DESIGNATION:	Scheduled Monument (No. 33787)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Hillfort and two bowl barrows at Halwell Camp, Halwell and Moreleigh			
DESIGNATION:	Scheduled Monument (No. 33745)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Dumping	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Stanborough Camp Iron Age hillfort and bowl barrow, Halwell and Moreleigh			
DESIGNATION:	Scheduled Monument (No. 33746)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Medieval churchyard cross, 6m south east of the porch of St Andrew's Church, Harberton			
DESIGNATION:	Scheduled Monument (No. 33742)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Bowl barrow 470m south of Borough Farm, Holbeton			
DESIGNATION:	Scheduled Monument (No. 33753)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Three bowl barrows 140m west of Borough Farm, Holbeton			
DESIGNATION:	Scheduled Monument (No. 33754)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:		D-Day landing craft maintenance site on the River Dart immediately to the south of Lower Noss Point, Kingswear	
DESIGNATION:	Scheduled Monument (No. 33059)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Gomerock Tower, Kingswear	
DESIGNATION:	Scheduled Monument (No. DV185)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Coaxial field system, hut circles and medieval farm buildings at Starehole Bottom, Malborough	
DESIGNATION:	Scheduled Monument (No. 34887)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Field systems, hut circles and four beacons, 510m south of Middle Soar, Malborough	
DESIGNATION:	Scheduled Monument (No. 34884)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Hilltop enclosure 380m east of Middle Soar, Malborough	
DESIGNATION:	Scheduled Monument (No. 33781)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Medieval farmstead, boundary work and earthwork enclosures 350m south east of Middle Soar, Malborough	
DESIGNATION:	Scheduled Monument (No. 34885)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Medieval settlement, site of quadrangular castle and relict garden between Ilton Farm and Ilton Castle Farm, Malborough	
DESIGNATION:	Scheduled Monument (No. 33788)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:		Two hut circles and associated field systems and enclosure at Mousehill Brake, Malborough	
DESIGNATION:	Scheduled Monument (No. 34883)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Two bowl barrows at Beacon Hill, 120m south of The Beacon, Marlton		
DESIGNATION:	Scheduled Monument (No. 33798)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Digging	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Two prehistoric hilltop enclosures, a ditch system and four bowl barrows, 300m north of Barton Pines Inn, Marlton		
DESIGNATION:	Scheduled Monument (No. 33796)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Iron Age promontory fort known as Oldaport Camp, Modbury		
DESIGNATION:	Scheduled Monument (No. 33759)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Localised/limited stock erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Fort Charles, Salcombe		
DESIGNATION:	Scheduled Monument (No. 33799)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Barrow cemetery on western slope of Crownhill Down, Shaugh Prior		
DESIGNATION:	Scheduled Monument (No. DV1027)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Hentor Warren boundary stone standing 200m south east of Hen Tor, Shaugh Prior		
DESIGNATION:	Scheduled Monument (No. 24226)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Iron Age cliff castle known as Bolt Tail Camp, South Huish		
DESIGNATION:	Scheduled Monument (No. 33761)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Hut circle 1000yds (915m) east of Coleland Bridge, Sparkwell		
DESIGNATION:	Scheduled Monument (No. DV760)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Post-medieval deer park, medieval fishpond, 18th century triumphal arch and a 19th century lead mine, ore works and smelt mill at Boringdon Park, Sparkwell		
DESIGNATION:	Scheduled Monument (No. 33780)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:	Woodbury Camp, Stoke Fleming		
DESIGNATION:	Scheduled Monument (No. 33769)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:	Hillfort known as Slapton Castle, Stokenham		
DESIGNATION:	Scheduled Monument (No. 33744)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:	Roman settlement site at Bantham Ham, Thurlestone		
DESIGNATION:	Scheduled Monument (No. 33760)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate visitor erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:	Hilltop enclosure at Yellowberries Copse, 430m west of Higher Turtley, Ugborough		
DESIGNATION:	Scheduled Monument (No. 33763)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:	Fort Bovisand, Wembury		
DESIGNATION:	Scheduled Monument (No. DV719)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Unknown
OWNERSHIP:	Government or Agency	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:	Watch House battery and ditch, Wembury		
DESIGNATION:	Scheduled Monument (No. DV720)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Subsidence	TREND:	Improving
OWNERSHIP:	Government or Agency	CONTACT:	Phil McMahon 0117 975 0699
SITE NAME:	World War II Heavy Anti-aircraft gunsite, 100m west of Princes Cottages, Wembury		
DESIGNATION:	Scheduled Monument (No. 33070)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

TEIGNBRIDGE



SITE NAME: **The Belvedere,
Powderham**

Gothick Belvedere, 1771-1774, situated 600 metres north west of Powderham Castle on the north east fringe of Powderham Old Plantation within the C18 park. Damaged by fire after the war and now a roofless shell. English Heritage grant aid has been offered towards repairs and a first phase of repairs has been completed. Further works are still necessary.

DESIGNATION: Listed Building Grade II*, RPG II*

CONDITION: Poor

OCCUPANCY: Not applicable

PRIORITY: C (D)

OWNERSHIP: Private

Contact: Francis Kelly 0117 975 0725

SITE NAME: **Earthwork (possibly civil war) on Bovey Heath, Bovey Tracey**

DESIGNATION: Scheduled Monument (No. DV997)

CONDITION: Generally satisfactory
but with significant localised problems

PRINCIPAL VULNERABILITY: Extensive vehicle damage/erosion

TREND: Declining

OWNERSHIP: Local Authority

CONTACT: Phil McMahon 0117 975 0699

SITE NAME: **Bishop's Palace, Chudleigh**

DESIGNATION: Scheduled Monument (No. 24838)

CONDITION: Generally satisfactory
but with significant localised problems

PRINCIPAL VULNERABILITY: Scrub / tree growth

TREND: Declining

OWNERSHIP: Private

CONTACT: Phil McMahon 0117 975 0699

SITE NAME: **Cow Cave, Chudleigh Rocks, Chudleigh**

DESIGNATION: Scheduled Monument (No. 10720)

CONDITION: Generally satisfactory
but with significant localised problems

PRINCIPAL VULNERABILITY: Vandalism

TREND: Declining

OWNERSHIP: Private

CONTACT: Phil McMahon 0117 975 0699

SITE NAME: **Milber Down camp, Coffinswell**

DESIGNATION: Scheduled Monument (No. DV115)

CONDITION: Generally satisfactory
but with significant localised problems

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Phil McMahon 0117 975 0699

SITE NAME: **Cotley Castle, Dunsford**

DESIGNATION: Scheduled Monument (No. DV250)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Forestry

TREND: Declining

OWNERSHIP: Private

CONTACT: Phil McMahon 0117 975 0699

SITE NAME: **Earthwork enclosure south of Blackall's Copse, Exminster**

DESIGNATION: Scheduled Monument (No. DV952)

CONDITION: Generally unsatisfactory
with major localised problems

PRINCIPAL VULNERABILITY: Arable clipping

TREND: Declining

OWNERSHIP: Private

CONTACT: Phil McMahon 0117 975 0699

SITE NAME: **Linear round barrow cemetery at Castle Park, Alphington, Exminster**

DESIGNATION: Scheduled Monument (No. 10625)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Kingskerswell Manor House, Kingskerswell		
DESIGNATION:	Scheduled Monument (No. 34450)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Castle Dyke, Newton Abbot		
DESIGNATION:	Scheduled Monument (No. DV313)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Gardening	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699



SITE NAME:	Oxton House, Kenton
DESIGNATION:	Registered Park and Garden Grade II*, also 7 LBs
CONDITION:	Extensive significant problems
VULNERABILITY:	Medium
TREND:	Declining
OWNERSHIP:	Private, multiple owners

In the mid C19 the picturesque grounds comprised lawns, parterres, shrubberies, parkland and a lake. In the C20 the property was firstly a school and then divided into apartments. The pleasure grounds are neglected and much of the park is ploughed up, with considerable loss of parkland planting.

Contact: Kim Auston 0117 975 0696

SITE NAME:	Mamhead Park, Mamhead
DESIGNATION:	Registered Park and Garden Grade II*, also 16 LBs
CONDITION:	Extensive significant problems
VULNERABILITY:	Medium
TREND:	Stable
OWNERSHIP:	Private, multiple owners

Mamhead contains the remnants of a 'Capability' Brown park overlooking the Exe estuary. Extensive loss of parkland trees, inappropriate land management and subdivision with new boundaries. Recent pressure for residential development. Historic mixed plantations now largely converted to conifer.

Contact: Kim Auston 0117 975 0696

SITE NAME:	Stover Park, Teignrace
DESIGNATION:	Registered Park and Garden Grade II*, also 7 LBs
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	High
TREND:	Stable
OWNERSHIP:	Mixed, multiple owners

Formerly a seat of the dukes of Somerset. Late C18 gardens, pleasure grounds and park. Now in divided ownership. Large area of park now run by county council as country park, the remainder a school with ongoing expansion of school facilities. Much altered setting with pressure for hotel, retail, residential and industrial development associated with A38 trunk road.

Contact: Kim Auston 0117 975 0696

TORRIDGE



SITE NAME:	Richmond Dock, Appledore
DESIGNATION:	Listed Building Grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant
PRIORITY:	C (C)
OWNERSHIP:	Company

Dry dock, 1856. It is said to be the largest dry dock in the Bristol Channel at the time it was built. Now vacant and in fair to poor condition, the dock has not seen significant maintenance in recent years. Its condition is being monitored. Redevelopment proposals under consideration for adjacent site will entail its repair.

Contact: Francis Kelly 0117 975 0725

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME: **Winsford Hospital,
Halwill Junction,
Halwill**

DESIGNATION: Listed Building Grade II*

CONDITION: Fair

OCCUPANCY: Part occupied

PRIORITY: C (C)

OWNERSHIP: Trust

Winsford centre built as a cottage hospital in 1899, designed by Charles Voysey and founded by a local landowner. The NHS closed the hospital in 1998 when it was bought by the Winsford Trust. Since then, it has been run as a day centre and community resource. The future of the building is threatened by the urgent need for major repairs. English Heritage grant has been given towards a condition survey.

Contact: Francis Kelly 0117 975 0725

SITE NAME: **Iron Age enclosure and Roman marching camp, Alverdiscott**

DESIGNATION: Scheduled Monument (No. DV1035)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Other

TREND: Declining

OWNERSHIP: Private

CONTACT: Phil McMahon 0117 975 0699

SITE NAME: **Bowl barrow 250m north east of Oak Cottage, forming part of a round barrow cemetery, Ashwater**

DESIGNATION: Scheduled Monument (No. 34268)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Phil McMahon 0117 975 0699

SITE NAME: **Bowl barrow 540m south east of Sandymoor Cross, forming part of a round barrow cemetery, Ashwater**

DESIGNATION: Scheduled Monument (No. 34269)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Other

TREND: Declining

OWNERSHIP: Private

CONTACT: Phil McMahon 0117 975 0699

SITE NAME: **Bowl barrow 770m south east of Sandymoor Cross, forming part of a round barrow cemetery, Ashwater**

DESIGNATION: Scheduled Monument (No. 34270)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Other

TREND: Declining

OWNERSHIP: Private

CONTACT: Phil McMahon 0117 975 0699

SITE NAME: **Bowl barrow 420m north west of Dural Cross, Bradworthy**

DESIGNATION: Scheduled Monument (No. 32200)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Other

TREND: Declining

OWNERSHIP: Private

CONTACT: Phil McMahon 0117 975 0699

SITE NAME: **Thorn Barrow 520m south east of Coop, in Highermoor Plantations, Broadwoodwider**

DESIGNATION: Scheduled Monument (No. 32224)

CONDITION: Generally satisfactory
but with significant localised problems

PRINCIPAL VULNERABILITY: Extensive animal burrowing

TREND: Declining

OWNERSHIP: Government or Agency

CONTACT: Phil McMahon 0117 975 0699

SITE NAME: **Bowl barrow 130m north of Wrangworthy Cross,
forming part of a round barrow cemetery, Buckland Brewer**

DESIGNATION: Scheduled Monument (No. 32199)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Other

TREND: Declining

OWNERSHIP: Private

CONTACT: Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Three bowl barrows 250m west of Bower, Bulkworthy			
DESIGNATION:	Scheduled Monument (No. 30347)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Two bowl barrows 690m and 760m south west of Leworthy, Clawton			
DESIGNATION:	Scheduled Monument (No. 30336)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Three bowl barrows 160m north west of Venn Cottages forming part of a round barrow cemetery, East Putford			
DESIGNATION:	Scheduled Monument (No. 30343)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Two bowl barrows 600m and 750m west of Wrangworthy cross forming part of a round barrow cemetery, East Putford			
DESIGNATION:	Scheduled Monument (No. 30344)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Two bowl barrows one immediately north and one 100m south of Commonmoor Cottage forming part of a round barrow cemetery, East Putford			
DESIGNATION:	Scheduled Monument (No. 30345)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Round barrow on Darracott Moor, Great Torrington			
DESIGNATION:	Scheduled Monument (No. 13604)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Other	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Round barrow on south east of Darracott Moor, Great Torrington			
DESIGNATION:	Scheduled Monument (No. 13603)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Other	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Round barrow to the east of Darracott Moor, crossed by the B3232, Great Torrington			
DESIGNATION:	Scheduled Monument (No. 13601)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Other	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHs	World Heritage Site

SITE NAME:	Bowl barrow 220m east of Rectory Farm, Halwill		
DESIGNATION:	Scheduled Monument (No. 30324)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Bowl barrow 300m south east of Gorvin, Hartland		
DESIGNATION:	Scheduled Monument (No. 32202)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Bowl barrow 520m west of Higher Welsford, Hartland		
DESIGNATION:	Scheduled Monument (No. 32236)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Bowl barrow 580m north west of Gorvin, Hartland		
DESIGNATION:	Scheduled Monument (No. 32206)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Embury Beacon camp, Hartland		
DESIGNATION:	Scheduled Monument (No. DVI69)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Round barrow cemetery 920m south west of Higher Welsford, Hartland		
DESIGNATION:	Scheduled Monument (No. 32238)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Two bowl barrows 400m north west of Gorvin, Hartland		
DESIGNATION:	Scheduled Monument (No. 32204)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Bowl barrow on Ugworthy Moor 510m south of West Ugworthy House, Holsworthy Hamlets		
DESIGNATION:	Scheduled Monument (No. 30339)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Two bowl barrows south of Haycroft, Huntshaw			
DESIGNATION:	Scheduled Monument (No. 10501)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Bowl barrow 60m west of St James's Church, Luffincott			
DESIGNATION:	Scheduled Monument (No. 34275)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Moated site at Grange Farm, Merton			
DESIGNATION:	Scheduled Monument (No. 30317)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Cross ridge dyke on Godborough Castle earthwork north west of Turner's Wood, Northam			
DESIGNATION:	Scheduled Monument (No. DV927)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Stable
OWNERSHIP:	Other	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Bowl barrow 685m NNE of Moorfield, Peters Marland			
DESIGNATION:	Scheduled Monument (No. 30323)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Bowl barrow in Heathermoor Plantation, 50m north east of Petrockstow Station, Petrockstow			
DESIGNATION:	Scheduled Monument (No. 30313)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Cairn 20m east of Tibbett's Lookout, Lundy			
DESIGNATION:	Scheduled Monument (No. 27634)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Chapel remains, cemetery and prehistoric settlement on Beacon Hill, Lundy			
DESIGNATION:	Scheduled Monument (No. 30351)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Granite quarry on East Sidelands, Lundy		
DESIGNATION:	Scheduled Monument (No. 30352)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Hut circle and small enclosure 270m north west of The Old Lighthouse, Lundy		
DESIGNATION:	Scheduled Monument (No. 27633)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Long house and enclosure 160m north of Widow's Tenement, Lundy		
DESIGNATION:	Scheduled Monument (No. 27639)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Quarry infirmary and surgery, 220m north west of Quarterwall Cottages, Lundy		
DESIGNATION:	Scheduled Monument (No. 30353)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Ruined cottages and well 190m north west of Quarterwall Cottages, Lundy		
DESIGNATION:	Scheduled Monument (No. 30354)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Standing stone 100m north east of The Old Lighthouse, Lundy		
DESIGNATION:	Scheduled Monument (No. 27621)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	The Widow's Tenement medieval settlement and prehistoric settlement sites, Lundy		
DESIGNATION:	Scheduled Monument (No. 30357)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

WEST DEVON



SITE NAME: **Kelly House, Kelly**

C18 house. Serious maintenance issues. Roof in need of renewal, rear medieval wing partly propped.

DESIGNATION: Listed Building Grade I

CONDITION: Poor

OCCUPANCY: Part occupied

PRIORITY: C (C)

OWNERSHIP: Private

Contact: Francis Kelly 0117 975 0725

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	Stable block north of Kelly House, Kelly	Stables, 1740. Partly used, part collapsed.
DESIGNATION:	Listed Building Grade II*	
CONDITION:	Very bad	
OCCUPANCY:	Part occupied	
PRIORITY:	A (A)	
OWNERSHIP:	Private	Contact: Francis Kelly 0117 975 0725



SITE NAME:	Lower Sessland Farm including cob walls adjoining to north west and south west, Sessland Lane, South Tawton	Late medieval thatched farmhouse with later additions including C17 hall bay and parlour wing. Further C17 addition to north west has been used as a separate cottage and is now vacant and in very poor condition with severe water penetration and decay of thatch and roof timbers. Temporary protection was erected in 2006 following an Urgent Works Notice, but further repairs are necessary.
DESIGNATION:	Listed Building Grade II*	
CONDITION:	Very bad	
OCCUPANCY:	Part occupied	
PRIORITY:	A (A)	
OWNERSHIP:	Private	Contact: Francis Kelly 0117 975 0725



SITE NAME:	Church of Our Lady and St Mary Magdalene, Callington Road, Tavistock	Built 1825-67 by Henry Clutton for the Duke of Bedford. Some structural problems of uncertain significance are being analysed. Very poor condition due to maintenance problems. English Heritage has grant-aided feasibility study.
DESIGNATION:	Listed Building Grade II*, CA	
CONDITION:	Poor	
OCCUPANCY:	Occupied	
PRIORITY:	B (B)	
OWNERSHIP:	Religious organisation	Contact: Francis Kelly 0117 975 0725

SITE NAME:	Round barrow cemetery and beacon at Heathfield, 650m west of Moorlands, Brentor	
DESIGNATION:	Scheduled Monument (No. 34284)	CONDITION: Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND: Declining
OWNERSHIP:	Private	CONTACT: Phil McMahon 0117 975 0699

SITE NAME:	Motte with two baileys and a multivallate hillfort at Burley Wood, Bridestowe	
DESIGNATION:	Scheduled Monument (No. 30350)	CONDITION: Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND: Stable
OWNERSHIP:	Private	CONTACT: Phil McMahon 0117 975 0699

SITE NAME:	Iron Age defended settlement in Dunterue Wood, 570m south of Castle Head, Dunterton	
DESIGNATION:	Scheduled Monument (No. 35251)	CONDITION: Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND: Stable
OWNERSHIP:	Private	CONTACT: Phil McMahon 0117 975 0699

SITE NAME:	Bowl barrow 620m north of Higher Eworthy, Germansweek	
DESIGNATION:	Scheduled Monument (No. 30333)	CONDITION: Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND: Declining
OWNERSHIP:	Private	CONTACT: Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Gawton arsenic mine and flue, Gulworthy		
DESIGNATION:	Scheduled Monument (No. DV1024)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Roman forts, marching camps and associated monuments, North Tawton		
DESIGNATION:	Scheduled Monument (No. 10384)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Guide post at Place Cross, Okehampton Hamlets		
DESIGNATION:	Scheduled Monument (No. 34278)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Bere Alston		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	High	TREND:	Expected to deteriorate
CONTACT:	Laura Batham (LA) 01822 813549		

SITE NAME:	Exbourne		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	High	TREND:	Expected to deteriorate
CONTACT:	Laura Batham (LA) 01822 813549		

SITE NAME:	Hatherleigh		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	High	TREND:	Expected to deteriorate
CONTACT:	Laura Batham (LA) 01822 813549		

SITE NAME:	North Tawton		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Expected to deteriorate
CONTACT:	Laura Batham (LA) 01822 813549		

SITE NAME:	Okehampton		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	High	TREND:	Expected to deteriorate
CONTACT:	Laura Batham (LA) 01822 813549		

SITE NAME:	Tavistock		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	High	TREND:	Unknown
CONTACT:	Laura Batham (LA) 01822 813549		

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

DORSET

CHRISTCHURCH

SITE NAME:	Bowl barrow on East Parley Common 610m south west of Fir Grove Farm, Hurn		
DESIGNATION:	Scheduled Monument (No. 29564)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 01 17 9750726

SITE NAME:	Two bowl barrows at Gibbet Firs, 950m south west and 1080m south west of Palmers Ford Works, Hurn		
DESIGNATION:	Scheduled Monument (No. 29563)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 01 17 9750726

EAST DORSET



SITE NAME:	Grotto 250 metres south west of St Giles House, Wimborne St Giles	Grotto, circa 1751-53, located 250 metres to the south-east of the house, at the east end of a winding channel of water running westwards for 300 metres to the northern extremity of the lake (which lies 150 metres to the south of the house). One of several garden buildings situated in the C17 and C18 landscape.
DESIGNATION:	Listed Building Grade II*, RPG II*	
CONDITION:	Very bad	
OCCUPANCY:	Not applicable	
PRIORITY:	C (C)	
OWNERSHIP:	Private	Contact: Jenny Chesher 01 17 975 0686



SITE NAME:	St Giles House, Wimborne St Giles	Country house. C17, C18 and C19, situated in a C17 and C18 park. Owner's family have lived in the Dower House since the Second World War when the main house was requisitioned and subsequently used as a school. House now largely unoccupied apart from one wing used as estate office. Discussions regarding future uses of the house and their funding are being resumed following inheritance by a new owner.
DESIGNATION:	Listed Building Grade I, RPG II*	
CONDITION:	Very bad	
OCCUPANCY:	Part occupied	
PRIORITY:	C (C)	
OWNERSHIP:	Private	Contact: Jenny Chesher 01 17 975 0686

SITE NAME:	Remains of medieval buildings, Witchampton	On the southern side of the village of Witchampton lie the ruins of a substantial domestic medieval building. It was used as an agricultural building in C19 but has since fallen into a state of disrepair. Scrub/vegetation clearance work has taken place in the past, but is now regenerating.
DESIGNATION:	Scheduled Monument	
CONDITION:	Poor	
OCCUPANCY:	Not applicable	
PRIORITY:	C (C)	
OWNERSHIP:	Private	Contact: Shane Gould 01 17 975 0671

SITE NAME:	Length of deer park bank and ditch at Alderholt, Alderholt		
DESIGNATION:	Scheduled Monument (No. DO812)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 01 17 9750726

SITE NAME:	Section of Roman Road 150m south of Park Farm Cottages, Colehill		
DESIGNATION:	Scheduled Monument (No. 29586)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 01 17 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Castle mound (or Castle Hill), Cranborne			
DESIGNATION:	Scheduled Monument (No. DO17)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Barrows in and near St Giles Park, Edmondsham			
DESIGNATION:	Scheduled Monument (No. DO292)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Bell barrow 500m north east of Beacon Farm, Ferndown Town			
DESIGNATION:	Scheduled Monument (No. 29552)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Bell barrow known as Belle Vue Barrow, and a bowl barrow 250m north east of Hillamsland, Ferndown Town			
DESIGNATION:	Scheduled Monument (No. 29551)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Bowl barrow 250m west of Ferndown Upper School, Ferndown Town			
DESIGNATION:	Scheduled Monument (No. 27477)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNERSHIP:	Utility	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Barrow near Burtts Harley, Gussage All Saints			
DESIGNATION:	Scheduled Monument (No. DO297)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Barrows at junction of parish boundaries, Gussage All Saints			
DESIGNATION:	Scheduled Monument (No. DO301)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Barrows in and near The Drive Plantation, Gussage All Saints			
DESIGNATION:	Scheduled Monument (No. DO298)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Barrows on Wyke Down, Gussage All Saints			
DESIGNATION:	Scheduled Monument (No. DO299)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Part of Ackling Dyke (Roman road), including Roman road on Oakley Down, Gussage All Saints			
DESIGNATION:	Scheduled Monument (No. DO311)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Barrow on Parsonage Hill, Gussage St Michael			
DESIGNATION:	Scheduled Monument (No. DO293)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Earthworks on Gussage Down, Gussage St Michael			
DESIGNATION:	Scheduled Monument (No. DO192)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Long mound 1500yds (1370m) east of Higher Farm, Gussage St Michael			
DESIGNATION:	Scheduled Monument (No. DO294)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Round barrows near Thickthorn Farm, Gussage St Michael			
DESIGNATION:	Scheduled Monument (No. DO356)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Two barrows near Ackling Dyke, Gussage St Michael			
DESIGNATION:	Scheduled Monument (No. DO296)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Two long barrows on Gussage Hill, Gussage St Michael			
DESIGNATION:	Scheduled Monument (No. DO7778)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Two round barrows on Gussage Down, Gussage St Michael		
DESIGNATION:	Scheduled Monument (No. DO193)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Round barrow north west of High Lea Farm, Hinton Martell		
DESIGNATION:	Scheduled Monument (No. DO606)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow on Summerlug Hill 250m south of Mannington Farm, Holt		
DESIGNATION:	Scheduled Monument (No. 29596)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bull Barrow on Holt Heath, Holt		
DESIGNATION:	Scheduled Monument (No. 29595)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow cemetery and a cross dyke on Horton Common 800m south of Bridge Farm, Horton		
DESIGNATION:	Scheduled Monument (No. 29597)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 250m north west of Veiny Cheese Pond, Long Crichel		
DESIGNATION:	Scheduled Monument (No. 27468)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Disc barrow and a bowl barrow 640m south west of Veiny Cheese Pond, Long Crichel		
DESIGNATION:	Scheduled Monument (No. 33555)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Two bowl barrows 165m west of Veiny Cheese Pond, Long Crichel		
DESIGNATION:	Scheduled Monument (No. 27471)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Bradford Barrow, Pamphill		
DESIGNATION:	Scheduled Monument (No. DO103)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	A linear earthwork north east of West Woodyates Manor: part of the 'Bokerley Line', Pentridge		
DESIGNATION:	Scheduled Monument (No. 25620)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Barrow west of village, Pentridge		
DESIGNATION:	Scheduled Monument (No. DO305)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Barrows in Salisbury Plantation, Pentridge		
DESIGNATION:	Scheduled Monument (No. DO359)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Celtic fields on Pentridge Down, Pentridge		
DESIGNATION:	Scheduled Monument (No. DO307)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Long barrows and group of round barrows on Bokerly Down, Pentridge		
DESIGNATION:	Scheduled Monument (No. DO144)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Part of Dorset Cursus, Pentridge		
DESIGNATION:	Scheduled Monument (No. DO303)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Roman fort at Crab Farm, Shapwick		
DESIGNATION:	Scheduled Monument (No. DO833)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Camp in Mistlebury Wood, Sixpenny Handley			
DESIGNATION:	Scheduled Monument (No. DO668)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

SITE NAME: Enclosure south of Humby's Stock Coppice, Sixpenny Handley			
DESIGNATION:	Scheduled Monument (No. DO785)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

SITE NAME: Three bowl barrows in Avon Heath Country Park, two 620m and one 700m north west of Matcham's House, St Leonards and St Ives			
DESIGNATION:	Scheduled Monument (No. 29567)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Shane Gould 01 17 9750726

SITE NAME: Stephen's Castle, a bowl barrow 720m east of Eastworth Farm, Verwood			
DESIGNATION:	Scheduled Monument (No. 35388)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Shane Gould 01 17 9750726

SITE NAME: Mag's Barrow, West Parley			
DESIGNATION:	Scheduled Monument (No. 27480)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Shane Gould 01 17 9750726

SITE NAME: Parley Barrow, a bowl barrow on the corner of Ellesfield Drive and Druid's Close, West Parley			
DESIGNATION:	Scheduled Monument (No. 27478)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 01 17 9750726

SITE NAME: Barrow 30yds (27m) east of Dorset Cursus, Wimborne St Giles			
DESIGNATION:	Scheduled Monument (No. DO304)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

SITE NAME: Barrows near Dorset Cursus, Wimborne St Giles			
DESIGNATION:	Scheduled Monument (No. DO302)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Barrows north of St Giles Park, Wimborne St Giles			
DESIGNATION:	Scheduled Monument (No. DO290)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Camp at Nine Yews, Wimborne St Giles			
DESIGNATION:	Scheduled Monument (No. DO672)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Parts of Dorset Cursus on Bottlebush Down, Wimborne St Giles			
DESIGNATION:	Scheduled Monument (No. DO310)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Round barrow cemetery and two associated enclosures, 550m west of Wimborne Lodge, associated with the Knowlton Circles, Wimborne St Giles			
DESIGNATION:	Scheduled Monument (No. 35210)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Two round barrows south of Cranborne Farm, Wimborne St Giles			
DESIGNATION:	Scheduled Monument (No. DO673)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Bowl barrow 250m north east of Monmouth's Ash Farm, Woodlands			
DESIGNATION:	Scheduled Monument (No. 29565)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Mineral extraction / related subsidence	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Group of henge monuments, an associated group of round barrows, a Saxon cemetery, and a Norman church at Knowlton, Woodlands			
DESIGNATION:	Scheduled Monument (No. 35209)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Round barrow cemetery south of New Barn Farm, associated with the Knowlton Circles, Woodlands			
DESIGNATION:	Scheduled Monument (No. 35211)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	St Giles' House, Wimborne St Giles
DESIGNATION:	Registered Park and Garden Grade II*, also CA, 7 LBs , 12 SMs
CONDITION:	Extensive significant problems
VULNERABILITY:	Medium
TREND:	Declining
OWNERSHIP:	Private, single owner

Extensive C18 landscape park and pleasure grounds with follies, a grotto, a serpentine lake and a striking beech avenue. The main house and the shell grotto are at risk. The structural elements of the park design survive in moderate condition but the majority of the park is in arable cultivation.

Contact: Kim Auston 0117 975 0696

SITE NAME:	Brog Street/Sleight Lane, Corfe Mullen	
DESIGNATION:	Conservation Area	CONDITION: At risk
VULNERABILITY:	Unknown	TREND: Deteriorating
CONTACT:	Ray Bird (LA) 01202 886201	

SITE NAME:	Wimborne Minster	
DESIGNATION:	Conservation Area	CONDITION: At risk
VULNERABILITY:	Unknown	TREND: Deteriorating
CONTACT:	Ray Bird (LA) 01202 886201	

NORTH DORSET



SITE NAME:	Sturminster Newton Castle, Sturminster Newton
DESIGNATION:	Scheduled Monument
CONDITION:	Very bad
OCCUPANCY:	Not applicable
PRIORITY:	C (C)
OWNERSHIP:	Private

The ruins of C14 stone built manor house stand within Sturminster Newton Castle, a probable Iron Age promontory fort overlooking the River Stour. Upstanding remains in very precarious position and considerable amount of consolidation work is urgently required to avoid significant areas of collapse. EH architectural survey team has recorded the structure. EH is in discussion with owner over condition of monument.

Contact: Shane Gould 0117 975 0671



SITE NAME:	Barn and outbuilding range, Tarrant Abbey Farm, Tarrant Crawford
DESIGNATION:	Listed Building Grade II*, SM
CONDITION:	Very bad
OCCUPANCY:	Not applicable
PRIORITY:	C (C)
OWNERSHIP:	Private

C15 barn with C18 outbuildings and alterations. No longer in agricultural use. The northernmost two bays of the roof have now wholly collapsed, there is scaffolding supporting the structure and the fallen debris appear to have been cleared. The wall tops exposed by the collapse appear to have been capped within the recent past.

Contact: Shane Gould 0117 975 0671



SITE NAME:	Manor Farm barn, Winterborne Clenston
DESIGNATION:	Listed Building Grade I, SM
CONDITION:	Very bad
OCCUPANCY:	Not applicable
PRIORITY:	C (C)
OWNERSHIP:	Private

Huge late C16 tithe barn part used for storage. In a poor to fair condition. The hammer beam roof may have been reused from a monastic building at Milton Abbey. Partial roof collapse has resulted in English Heritage funding the erection of scaffolding as a temporary roof support.

Contact: Shane Gould 0117 975 0671

SITE NAME:	Linear boundary 870m south west of Spring Farm, Ashmore	
DESIGNATION:	Scheduled Monument (No. 33567)	CONDITION: Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND: Declining
OWNERSHIP:	Private	CONTACT: Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Linear boundary and section of Roman road, 550m south east of Ashmore Farm, Ashmore		
DESIGNATION:	Scheduled Monument (No. 33566)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	St Leonard's Chapel, Blandford Forum		
DESIGNATION:	Scheduled Monument (No. DO152)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Field system in Old Park, Bryanston		
DESIGNATION:	Scheduled Monument (No. DO757)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 1020m south east of Charisworth Cottages, Charlton Marshall		
DESIGNATION:	Scheduled Monument (No. 27387)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 350m south of Gorcombe Farm, Charlton Marshall		
DESIGNATION:	Scheduled Monument (No. 27389)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 500m south west of Gorcombe Farm, Charlton Marshall		
DESIGNATION:	Scheduled Monument (No. 27388)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 650m south west of Gorcombe Farm, Charlton Marshall		
DESIGNATION:	Scheduled Monument (No. 27390)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Long barrow 360m SSW of Chettle House, Chettle		
DESIGNATION:	Scheduled Monument (No. 27367)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Causewayed camp on Hambledon Hill, Child Okeford			
DESIGNATION:	Scheduled Monument (No. DO269)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Longbury long barrow 600m north west of Slaughtergate Farm, Gillingham			
DESIGNATION:	Scheduled Monument (No. 27431)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Bowl barrow known as Folly Barrow, Iwerne Minster			
DESIGNATION:	Scheduled Monument (No. 33558)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Bowl barrow 480m south east of West End Barn, Milborne St Andrew			
DESIGNATION:	Scheduled Monument (No. 27398)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Bowl barrow 70m south east of West End Barn, Milborne St Andrew			
DESIGNATION:	Scheduled Monument (No. 27397)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Stable Barrow 230m NNE of Frogmore Farm, Milborne St Andrew			
DESIGNATION:	Scheduled Monument (No. 27384)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Three bowl barrows 380m west of West End Barn, Milborne St Andrew			
DESIGNATION:	Scheduled Monument (No. 27399)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Three bowl barrows on Milborne Down 520m and 585m north east of obelisk on Weatherby Castle hillfort, Milborne St Andrew			
DESIGNATION:	Scheduled Monument (No. 33546)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Two bowl barrows and two ring ditches 450m north west of Haywards Farm, Milborne St Andrew		
DESIGNATION:	Scheduled Monument (No. 33547)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Weatherby Castle, an Iron Age hillfort 1020m north west of Ashley Barn Farm, Milborne St Andrew		
DESIGNATION:	Scheduled Monument (No. 33541)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Enclosure south of Pimperne Down, Pimperne		
DESIGNATION:	Scheduled Monument (No. DO482)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Site of St John's Church, Shaftesbury		
DESIGNATION:	Scheduled Monument (No. DO840)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Two bowl barrows west of Bonsley Common, 900m NNE of Turnworth House, Shillingstone		
DESIGNATION:	Scheduled Monument (No. 27354)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Crawford Castle (or Spetisbury Rings), Spetisbury		
DESIGNATION:	Scheduled Monument (No. DO99)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Chapel west of Manor Farm, Stourton Caundle		
DESIGNATION:	Scheduled Monument (No. DO476)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Slight univallate hillfort 850m north east of Busseys Stool Farm, Tarrant Gunville		
DESIGNATION:	Scheduled Monument (No. 33569)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Bowl barrow 200m south east of Pimperne Long Barrow, Tarrant Hinton			
DESIGNATION:	Scheduled Monument (No. 27370)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Prehistoric habitation site between north and south Hinton Downs, Tarrant Hinton			
DESIGNATION:	Scheduled Monument (No. DO481)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Roman villa on Little Barton Hill, Tarrant Hinton			
DESIGNATION:	Scheduled Monument (No. DO748)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Bowl barrow 350m south west of Buzbury Rings, Tarrant Keyneston			
DESIGNATION:	Scheduled Monument (No. 27362)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Buzbury Rings, Tarrant Keyneston			
DESIGNATION:	Scheduled Monument (No. DO127)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Roman enclosure on Keyneston Down, Tarrant Keyneston			
DESIGNATION:	Scheduled Monument (No. DO834)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Bowl barrow 600m south of Plantation Farm, Tarrant Launceston			
DESIGNATION:	Scheduled Monument (No. 27467)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Bowl barrow 700m south of Old Turnpike, Tarrant Launceston			
DESIGNATION:	Scheduled Monument (No. 27469)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Bowl barrow on The Cliff 680m east of Luton Farm, Tarrant Rawston			
DESIGNATION:	Scheduled Monument (No. 27464)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

SITE NAME: Bowl barrow on The Cliff 680m NNW of Smith's Cottages, Tarrant Rawston			
DESIGNATION:	Scheduled Monument (No. 27463)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

SITE NAME: Bowl barrow 850m ESE of Hill Farm, Tarrant Rushton			
DESIGNATION:	Scheduled Monument (No. 27459)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 01 17 9750726

SITE NAME: Bowl barrow 150m north east of Dunbury, Winterborne Houghton			
DESIGNATION:	Scheduled Monument (No. 27381)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

SITE NAME: Bowl barrow 800m north west of North Barn Farm on Houghton North Down, Winterborne Houghton			
DESIGNATION:	Scheduled Monument (No. 27357)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

SITE NAME: Bowl barrow 500m south of West Down Barn, Winterborne Kingston			
DESIGNATION:	Scheduled Monument (No. 27392)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 01 17 9750726

SITE NAME: Bowl barrow 900m north west of Pond Down Buildings, Winterborne Stickland			
DESIGNATION:	Scheduled Monument (No. 27358)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

SITE NAME: Rowbarrow, 500m north west of Hedge End Farm, Winterborne Stickland			
DESIGNATION:	Scheduled Monument (No. 27356)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Bowl barrow 120m south of the southern extent of Horse Close Plantation, Winterborne Whitechurch		
DESIGNATION:	Scheduled Monument (No. 28363)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 25m south of Whitechurch Hill Barn, Winterborne Whitechurch		
DESIGNATION:	Scheduled Monument (No. 27361)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Milling House, West Farm, Winterborne Whitechurch		
DESIGNATION:	Scheduled Monument (No. DO818)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 550m north west of Bulbarrow Farm, Woolland		
DESIGNATION:	Scheduled Monument (No. 27355)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

PURBECK



SITE NAME: **North Lodges, Lulworth Castle, Coombe Keynes**

Gate lodges and gateway to Lulworth Castle, 1785. Repairs have been undertaken by the estate, but a longer term plan for the buildings needs to be conceived.

DESIGNATION: Listed Building Grade II*, SM

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: E (E)

OWNERSHIP: Private

Contact: Isla Macneal 0117 975 0742

SITE NAME:	Bowl barrow in Throop Clump, 450m west of Heatherdown, Affpuddle		
DESIGNATION:	Scheduled Monument (No. 35237)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	The Double Barrow, a bowl barrow in Kite Hill Plantation 250m south east of Roger's Hill Cottages, Affpuddle		
DESIGNATION:	Scheduled Monument (No. 29054)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow on Worgret Heath, 320m north west of High Tor, Arne		
DESIGNATION:	Scheduled Monument (No. 29079)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Bell barrow on Blackhill Clump 470m north of Mintern's Ferry, Bere Regis		
DESIGNATION:	Scheduled Monument (No. 29052)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 01 17 9750726

SITE NAME:	Bowl barrow 190m north west of Bere Down Farm, Bere Regis		
DESIGNATION:	Scheduled Monument (No. 28345)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 01 17 9750726

SITE NAME:	Bowl barrow 515m south of the southern extent of Horse Close Plantation, Bere Regis		
DESIGNATION:	Scheduled Monument (No. 28362)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 01 17 9750726

SITE NAME:	Bowl barrow 590m north east of Bere Down Farm, Bere Regis		
DESIGNATION:	Scheduled Monument (No. 28347)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 01 17 9750726

SITE NAME:	Bowl barrow 610m east of Bere Heath Farm, Bere Regis		
DESIGNATION:	Scheduled Monument (No. 28376)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 01 17 9750726

SITE NAME:	Bowl barrow 790m north east of Haywards Farm, Bere Regis		
DESIGNATION:	Scheduled Monument (No. 28394)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

SITE NAME:	Bowl barrow on Warren Heath, 350m south west of Warren House, Bere Regis		
DESIGNATION:	Scheduled Monument (No. 33161)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 01 17 9750726

SITE NAME:	Four bowl barrows 240m east of Oak Cottage, Bere Regis		
DESIGNATION:	Scheduled Monument (No. 28367)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 01 17 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Four bowl barrows 600m east and 650m north east of Haywards Farm, Bere Regis			
DESIGNATION:	Scheduled Monument (No. 28395)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Group of six bowl barrows, forming a round barrow cemetery on Black Hill, Bere Regis			
DESIGNATION:	Scheduled Monument (No. 29050)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Long barrow on Bere Down, 1100m north east of Roke Barn, Bere Regis			
DESIGNATION:	Scheduled Monument (No. 28393)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: The End Barrow, a bowl barrow 320m south west of White House, Bere Regis			
DESIGNATION:	Scheduled Monument (No. 29053)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Three bowl barrows 230m south west of Haywards Farm, Bere Regis			
DESIGNATION:	Scheduled Monument (No. 28397)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Three bowl barrows 650m south west of Bere Down Farm, Bere Regis			
DESIGNATION:	Scheduled Monument (No. 29082)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Two bell barrows and a bowl barrow, 200m north east of Haywards Farm, Bere Regis			
DESIGNATION:	Scheduled Monument (No. 28396)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Two bowl barrows on South Heath, 900m SSE of The Bungalow, Bere Regis			
DESIGNATION:	Scheduled Monument (No. 28335)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Bowl barrow 800m NNW of West Morden Farm, Bloxworth		
DESIGNATION:	Scheduled Monument (No. 28365)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow on Bloxworth Down, 740m south of Marsh Farm, Bloxworth		
DESIGNATION:	Scheduled Monument (No. 29073)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Round barrow cemetery on Bloxworth Down, Bloxworth		
DESIGNATION:	Scheduled Monument (No. 29071)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Three bowl barrows on Bloxworth Down, 800m west of Botany Bay Barn, Bloxworth		
DESIGNATION:	Scheduled Monument (No. 29072)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 200m south east of Hill Barn: one of a group of three barrows, Chaldon Herring		
DESIGNATION:	Scheduled Monument (No. 21954)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 470m south east of Down Barn: an outlier of the Chaldon Down barrow group, Chaldon Herring		
DESIGNATION:	Scheduled Monument (No. 21951)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 550m south of Chaldon Down Buildings: part of the Chaldon Down round barrow cemetery, Chaldon Herring		
DESIGNATION:	Scheduled Monument (No. 21955)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 650m south of Chaldon Down Buildings: part of the Chaldon Down round barrow cemetery, Chaldon Herring		
DESIGNATION:	Scheduled Monument (No. 21956)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:		Bowl barrow 660m south of Chaldon Down Buildings: part of the Chaldon Down round barrow cemetery, Chaldon Herring	
DESIGNATION:	Scheduled Monument (No. 21957)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME:		Bowl barrow to the west of Five Marys: an outlier to the Five Marys round barrow cemetery, Chaldon Herring	
DESIGNATION:	Scheduled Monument (No. 21907)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME:		The Round Pound, an enclosure on Chaldon Down, Chaldon Herring	
DESIGNATION:	Scheduled Monument (No. 29084)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME:		Two bowl barrows 200m south east of Hill Barn: two of a group of three barrows, Chaldon Herring	
DESIGNATION:	Scheduled Monument (No. 21953)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME:		Wardstone Barrow: a bowl barrow on the Dorset coastal ridge 300m south of Chideock Farm, Chaldon Herring	
DESIGNATION:	Scheduled Monument (No. 21913)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME:		Bowl barrow on Creech Barrow hill, Church Knowle	
DESIGNATION:	Scheduled Monument (No. 28308)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME:		Bowl barrow 760m south west of Afflington Barn, Corfe Castle	
DESIGNATION:	Scheduled Monument (No. 33207)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726
SITE NAME:		Bowl barrow on Swyre Head, Corfe Castle	
DESIGNATION:	Scheduled Monument (No. 33180)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	The Rings: a ringwork and bailey and a Civil War battery 400m south west of Corfe Castle, Corfe Castle		
DESIGNATION:	Scheduled Monument (No. 21968)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Three bowl barrows in Holme Lane Plantation, 200m south west of Squirrel's Cottages, East Holme		
DESIGNATION:	Scheduled Monument (No. 29095)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Flower's Barrow: a small multivallate hillfort and associated outwork on Rings Hill, East Lulworth		
DESIGNATION:	Scheduled Monument (No. 21942)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Two barrows known as 'Water Barrows' 650m WNW of Whiteway Farm: part of a round barrow cemetery to the south east of East Lulworth, East Lulworth		
DESIGNATION:	Scheduled Monument (No. 21939)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 60m north east of Hethfelton Farm, East Stoke		
DESIGNATION:	Scheduled Monument (No. 29081)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow on Farm Heath, 470m south east of Hill Cottages, East Stoke		
DESIGNATION:	Scheduled Monument (No. 29058)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow on Farm Heath, 480m south east of Hill Cottages, East Stoke		
DESIGNATION:	Scheduled Monument (No. 29057)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Round barrow cemetery on West Holme Heath, 850m north west of Hurst Mill, East Stoke		
DESIGNATION:	Scheduled Monument (No. 21923)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Section of Battery Bank on Binnegar Plain, 830m north east of Stokeford Farm, East Stoke			
DESIGNATION:	Scheduled Monument (No. 29078)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Section of Battery Bank on South Heath, East Stoke			
DESIGNATION:	Scheduled Monument (No. 29059)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Two bowl barrows on South Heath, 290m and 370m east of Binnegar Hall, East Stoke			
DESIGNATION:	Scheduled Monument (No. 29062)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Alum works, other multi-period industrial remains and an associated group of jetties and breakwaters, Kimmeridge Bay, Kimmeridge			
DESIGNATION:	Scheduled Monument (No. 29096)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Bowl barrow in Morden Park 350m south west of Hunting Bridge, Morden			
DESIGNATION:	Scheduled Monument (No. 29068)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Two bowl barrows 760m north east of Miller's Farm, Morden			
DESIGNATION:	Scheduled Monument (No. 29070)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Obelisk on Fir Hill, Moreton			
DESIGNATION:	Scheduled Monument (No. DO749)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Group of three bell barrows and a bowl barrow on Godlingston Heath, Studland			
DESIGNATION:	Scheduled Monument (No. 22993)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Bowl barrow in Piddle Wood, 530m north east of Gate Barn, Turners Puddle		
DESIGNATION:	Scheduled Monument (No. 29055)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Round barrow cemetery on Povington Heath 550m north east of Whiteway Farm, Tyneham		
DESIGNATION:	Scheduled Monument (No. 21934)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Digging	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Thorn Barrow: a bowl barrow on East Holme Range, 650m north east of Whiteway Farm, Tyneham		
DESIGNATION:	Scheduled Monument (No. 21936)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Light Anti-aircraft battery on Holton Heath, 210m west of Sandford House, Wareham St Martin		
DESIGNATION:	Scheduled Monument (No. 33183)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Royal Naval Cordite Factory at Holton Heath, Wareham St Martin		
DESIGNATION:	Scheduled Monument (No. 33181)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bindon Hill camp, West Lulworth		
DESIGNATION:	Scheduled Monument (No. DO68)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 370m east of Belhuish Farm: one of a group of barrows to the west of Burngate Wood, West Lulworth		
DESIGNATION:	Scheduled Monument (No. 21948)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 400m ENE of Belhuish Farm: one of a group of barrows to the west of Burngate Wood, West Lulworth		
DESIGNATION:	Scheduled Monument (No. 21947)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:		Bowl barrow 650m south east of Belhuish Farm: one of a group of barrows to the west of Burngate Wood, West Lulworth	
DESIGNATION:	Scheduled Monument (No. 21949)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 01 17 9750726
SITE NAME:		Drove Hill round barrows, Winfrith Newburgh	
DESIGNATION:	Scheduled Monument (No. DO256)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 01 17 9750726
SITE NAME:		Bindon Abbey (site), Wool	
DESIGNATION:	Scheduled Monument (No. DO58)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 01 17 9750726
SITE NAME:		Bowl barrow 300m south east of Hyford Cottage, Wool	
DESIGNATION:	Scheduled Monument (No. 28339)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Shane Gould 01 17 9750726
SITE NAME:		Bowl barrow 380m north west of Hyford Cottage, Wool	
DESIGNATION:	Scheduled Monument (No. 28340)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Shane Gould 01 17 9750726
SITE NAME:		Two bowl barrows 85m and 130m south west of Cambrai House, Wool	
DESIGNATION:	Scheduled Monument (No. 35241)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 01 17 9750726
SITE NAME:		Bowl barrow on Emmett's Hill, Worth Matravers	
DESIGNATION:	Scheduled Monument (No. 33177)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726
SITE NAME:		Bowl barrow on St Aldhelm's Head, 470m north east of St Aldhelm's Chapel, Worth Matravers	
DESIGNATION:	Scheduled Monument (No. 33176)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Stable
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Early Christian enclosure on St Aldhelm's Head, Worth Matravers		
DESIGNATION:	Scheduled Monument (No. 33165)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Shane Gould 01 17 9750726

SITE NAME:	Acton		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Benjamin Webb (LA) 01929 556561		

SITE NAME:	Chaldon Herring		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Benjamin Webb (LA) 01929 556561		


SITE NAME:	East Lulworth		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Benjamin Webb (LA) 01929 556561		

SITE NAME:	Kimmeridge		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Benjamin Webb (LA) 01929 556561		

SITE NAME:	Wareham and Stoborough		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Benjamin Webb (LA) 01929 556561		

SITE NAME:	West Lulworth		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Benjamin Webb (LA) 01929 556561		

WEST DORSET



SITE NAME: **Literary and Scientific Institute, East Street, Bridport**

DESIGNATION: Listed Building Grade II*, CA

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNERSHIP: Local authority

Founded in 1835 as a Mechanics Institute by Henry Warburton MP. Reconstituted in 1855 as a Literary and Scientific Institute. Dorset County Council has a long lease on the building but has instituted legal proceedings to establish whether the building can be disposed of. A court hearing has been adjourned for six months to establish the feasibility of a local trust taking the building on for community purposes.

Contact: Jenny Chesher 01 17 975 0686

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

	<p>SITE NAME: Messrs Norman goods warehouse, Station Road, West Bay, Bridport</p> <p>DESIGNATION: Listed Building Grade II*</p> <p>CONDITION: Fair</p> <p>OCCUPANCY: Vacant</p> <p>PRIORITY: E (New)</p> <p>OWNERSHIP: Private</p>	<p>C18, possibly older. Former bonded stores. Vacant with no user identified.</p> <p>Contact: Jenny Chesher 01 17 975 0686</p>
	<p>SITE NAME: The Riding School, Wolfeton Manor, Wolfeton, Charmminster</p> <p>DESIGNATION: Listed Building Grade II*, CA</p> <p>CONDITION: Very bad</p> <p>OCCUPANCY: Part occupied</p> <p>PRIORITY: D (C)</p> <p>OWNERSHIP: Trust</p>	<p>One of the oldest surviving riding schools in England, late C16. Currently used as a barn. In Trust ownership awaiting major repairs. Temporary roof repairs have been undertaken with English Heritage grant aid. Specification for repair and some alteration is being prepared with grant aid from English Heritage and Natural England. Works due to start 2010-11.</p> <p>Contact: Sarah Ball 01 17 975 0666</p>
	<p>SITE NAME: Marshwood Castle, Marshwood</p> <p>DESIGNATION: Listed Building Grade I, SM</p> <p>CONDITION: Poor</p> <p>OCCUPANCY: Not applicable</p> <p>PRIORITY: C (C)</p> <p>OWNERSHIP: Private</p>	<p>The site comprises a rectangular earthwork enclosure with a moat (partly filled). There are substantial remains of the internal ramparts and the motte. These masonry structures require consolidation and careful ongoing management.</p> <p>Contact: Shane Gould 01 17 975 0671</p>
	<p>SITE NAME: Remains of Old Parish Church of St Mary Magdalene, North Wootton</p> <p>DESIGNATION: Listed Building Grade II*, SM</p> <p>CONDITION: Poor</p> <p>OCCUPANCY: Not applicable</p> <p>PRIORITY: D (D)</p> <p>OWNERSHIP: Private</p>	<p>West tower of former parish church. Early C15. The nave and chancel were demolished circa 1883 when the C19 church was built. The tower is completely encased with ivy and in a ruinous condition. In need of repairs, particularly to the roof. Negotiations are being undertaken for a schedule of works.</p> <p>Contact: Shane Gould 01 17 975 0671</p>
	<p>SITE NAME: Cart shed and stables 10 metres south of Waddon House, Portesham</p> <p>DESIGNATION: Listed Building Grade II*</p> <p>CONDITION: Poor</p> <p>OCCUPANCY: Vacant</p> <p>PRIORITY: C (New)</p> <p>OWNERSHIP: Private</p>	<p>Former stables and cart shed, dated 1702. Currently disused with thatched roof in a poor condition. Discussion about future re-use of the building currently underway with the owner.</p> <p>Contact: Jenny Chesher 01 17 975 0686</p>
	<p>SITE NAME: Sherborne House, Newland, Sherborne</p> <p>DESIGNATION: Listed Building Grade I, CA</p> <p>CONDITION: Fair</p> <p>OCCUPANCY: Part occupied</p> <p>PRIORITY: E (E)</p> <p>OWNERSHIP: Local authority</p>	<p>House circa 1720. Former girls' school. Low-key arts use. English Heritage and West Dorset Council are discussing future proposals with a prospective purchaser and an application for planning permission and listed building consent are expected shortly. The building has been scaffolded and provided with a temporary roof structure whilst full repairs are awaited.</p> <p>Contact: Jenny Chesher 01 17 975 0686</p>

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME: **Former Methodist Chapel,
Dorchester Road,
Tolpuddle**

DESIGNATION: Listed Building Grade II*, CA

CONDITION: Poor

OCCUPANCY: Not applicable

PRIORITY: C (D)

OWNERSHIP: Private

Methodist church, circa 1818, and the meeting place of the Tolpuddle Martyrs. Discussions are ongoing between West Dorset District Council and the owner, who has indicated a willingness to sell the site, to find an appropriate use for the building. The possibility of re-instating a religious/community use is being investigated.

Contact: Jenny Chesher 0117 975 0686

SITE NAME:

Abbotsbury Castle (camp), Abbotsbury

DESIGNATION:

Scheduled Monument (No. DO88)

CONDITION:

Generally unsatisfactory
with major localised problems

PRINCIPAL VULNERABILITY:

Extensive visitor erosion

TREND:

Declining

OWNERSHIP:

Private

CONTACT:

Shane Gould 0117 9750726

SITE NAME:

Barrow east of Burnt House Bottom, Alton Pancras

DESIGNATION:

Scheduled Monument (No. DO491)

CONDITION:

Generally unsatisfactory
with major localised problems

PRINCIPAL VULNERABILITY:

Arable clipping

TREND:

Declining

OWNERSHIP:

Private

CONTACT:

Shane Gould 0117 9750726

SITE NAME:

Dyke on Haydon Down, Askerswell

DESIGNATION:

Scheduled Monument (No. DO174)

CONDITION:

Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY:

Arable ploughing

TREND:

Declining

OWNERSHIP:

Private

CONTACT:

Shane Gould 0117 9750726

SITE NAME:

Earthwork 80yds (70m) long north west of Coombe Bottom, Askerswell

DESIGNATION:

Scheduled Monument (No. DO173)

CONDITION:

Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY:

Arable ploughing

TREND:

Declining

OWNERSHIP:

Private

CONTACT:

Shane Gould 0117 9750726

SITE NAME:

Group of three round barrows west of Two Gates, Askerswell

DESIGNATION:

Scheduled Monument (No. DO179)

CONDITION:

Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY:

Arable ploughing

TREND:

Declining

OWNERSHIP:

Private

CONTACT:

Shane Gould 0117 9750726

SITE NAME:

Round barrow north west of Coombe Bottom, Askerswell

DESIGNATION:

Scheduled Monument (No. DO176)

CONDITION:

Generally unsatisfactory
with major localised problems

PRINCIPAL VULNERABILITY:

Extensive vehicle damage/erosion

TREND:

Declining

OWNERSHIP:

Private

CONTACT:

Shane Gould 0117 9750726

SITE NAME:

Bowl barrow on Beaminster Down 530m south east of East Axnoller Farm, Beaminster

DESIGNATION:

Scheduled Monument (No. 27449)

CONDITION:

Generally unsatisfactory
with major localised problems

PRINCIPAL VULNERABILITY:

Arable clipping

TREND:

Declining

OWNERSHIP:

Private

CONTACT:

Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA Conservation Area
LB/LBs Listed Building/s
NP National Park
RPG Registered Park and Garden
SM/SMs Scheduled Monument/s
UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Bowl barrow on Beaminster Down 770m north east of Higher Meerhay Farm, Beaminster		
DESIGNATION:	Scheduled Monument (No. 27450)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Barrow east of Red Barn, Bradford Peverell		
DESIGNATION:	Scheduled Monument (No. DO353)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Barrow near Higher Skippet Farm, Bradford Peverell		
DESIGNATION:	Scheduled Monument (No. DO361)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bell barrow in Highfield Plantation and two bowl barrows immediately north west of Forty Acre Plantation, Bradford Peverell		
DESIGNATION:	Scheduled Monument (No. 33190)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 380m west of Whitfield Farm, Bradford Peverell		
DESIGNATION:	Scheduled Monument (No. 33189)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Discontinuous surviving sections of Roman aqueduct, Bradford Peverell		
DESIGNATION:	Scheduled Monument (No. DO166)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Group of barrows in Seven Barrow Plantation, Bradford Peverell		
DESIGNATION:	Scheduled Monument (No. DO349)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Long barrow and four bowl barrows 500m north west of Whitfield Farm, Bradford Peverell		
DESIGNATION:	Scheduled Monument (No. 33191)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Three barrows north of Penn Hill, Bradford Peverell		
DESIGNATION:	Scheduled Monument (No. DO354)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 01 17 9750726

SITE NAME:	Culliford Tree long barrow and group of round barrows, Broadmayne		
DESIGNATION:	Scheduled Monument (No. DO55)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

SITE NAME:	Oval barrow and three bowl barrows 250m and 330m south of Whitcombe Barn, Broadmayne		
DESIGNATION:	Scheduled Monument (No. 33188)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 01 17 9750726

SITE NAME:	Two bowl barrows on Lord's Down 580m south east of Crawthorne Farm, Burleston		
DESIGNATION:	Scheduled Monument (No. 33533)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

SITE NAME:	Bowl barrow on Wood Hill 310m north east of Cowden, Charminster		
DESIGNATION:	Scheduled Monument (No. 33548)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 01 17 9750726

SITE NAME:	Round barrow east of Forston Farm, Charminster		
DESIGNATION:	Scheduled Monument (No. DO458)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

SITE NAME:	Earthwork and ancient fields south east of Lyscombe Bottom, Cheselbourne		
DESIGNATION:	Scheduled Monument (No. DO670)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

SITE NAME:	Group of round barrows north east of Hog Leaze, Cheselbourne		
DESIGNATION:	Scheduled Monument (No. DO523)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Round barrow on Cheselbourne West Down, Cheselbourne		
DESIGNATION:	Scheduled Monument (No. DO525)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

SITE NAME:	Bowl barrow 360m south of Compton Barn, Compton Valence		
DESIGNATION:	Scheduled Monument (No. 33545)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 01 17 9750726

SITE NAME:	Settlement south east of Soaper's Hill Plantation, Compton Valence		
DESIGNATION:	Scheduled Monument (No. DO464)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

SITE NAME:	Bowl barrow 450m east of Dennet's Bottom Barn, Dewlish		
DESIGNATION:	Scheduled Monument (No. 27396)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

SITE NAME:	Bowl barrow 550m WNW of West End Barn, Dewlish		
DESIGNATION:	Scheduled Monument (No. 27400)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

SITE NAME:	Earthwork east of Stake Farm, East Chelborough		
DESIGNATION:	Scheduled Monument (No. DO450)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 01 17 9750726

SITE NAME:	Bell barrow and five bowl barrows 1000m south east of Kingston Russell Farm, part of the Black Down round barrow cemetery, Kingston Russell		
DESIGNATION:	Scheduled Monument (No. 22932)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

SITE NAME:	Bowl barrow 550m north east of Pitcombe Farm, part of the Black Down round barrow cemetery, Kingston Russell		
DESIGNATION:	Scheduled Monument (No. 22933)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:		Bowl barrow 810m NNE of Whatcombe House, forming part of the round barrow cemetery on the south western part of Black Down, Kingston Russell	
DESIGNATION:	Scheduled Monument (No. 22983)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726
SITE NAME:		Lime kiln 800ft (245m) north west of Langton Cross, Langton Herring	
DESIGNATION:	Scheduled Monument (No. DO802)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 01 17 9750726
SITE NAME:		Bowl barrow 165m NNW of White Hill Barn, forming part of the White Hill round barrow cemetery, Littlebredy	
DESIGNATION:	Scheduled Monument (No. 22950)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726
SITE NAME:		Bowl barrow 200m south of Winterbourne Poor Lot forming part of the Winterbourne Poor Lot round barrow cemetery, Littlebredy	
DESIGNATION:	Scheduled Monument (No. 22970)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726
SITE NAME:		Bowl barrow 265m north west of White Hill Barn, forming part of the White Hill round barrow cemetery, Littlebredy	
DESIGNATION:	Scheduled Monument (No. 22951)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726
SITE NAME:		Bowl barrow 300m WNW of White Hill Barn, forming part of the White Hill round barrow cemetery, Littlebredy	
DESIGNATION:	Scheduled Monument (No. 22952)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726
SITE NAME:		Bowl barrow 340m north west of White Hill Barn, forming part of the White Hill round barrow cemetery, Littlebredy	
DESIGNATION:	Scheduled Monument (No. 22954)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:		Bowl barrow 355m north west of White Hill Barn, forming part of the White Hill round barrow cemetery, Littlebredy	
DESIGNATION:	Scheduled Monument (No. 22953)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726
SITE NAME:		Bowl barrow 500m west of Well Bottom Wood, forming part of the Pitcombe Down round barrow cemetery, Littlebredy	
DESIGNATION:	Scheduled Monument (No. 22966)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726
SITE NAME:		Bowl barrow 600m west of Well Bottom Wood, forming part of the Pitcombe Down round barrow cemetery, Littlebredy	
DESIGNATION:	Scheduled Monument (No. 22965)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726
SITE NAME:		Bowl barrow 600m west of Well Bottom Wood, forming part of the Pitcombe Down round barrow cemetery, Littlebredy	
DESIGNATION:	Scheduled Monument (No. 22969)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726
SITE NAME:		Bowl barrow on Black Down, 870m north west of the Hardy Monument, Littlebredy	
DESIGNATION:	Scheduled Monument (No. 33209)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726
SITE NAME:		Four bowl barrows 500m west of Well Bottom Wood, forming part of the Pitcombe Down round barrow cemetery, Littlebredy	
DESIGNATION:	Scheduled Monument (No. 22968)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726
SITE NAME:		Three bowl barrows 300m south west of Well Bottom Wood, forming part of the Pitcombe Down round barrow cemetery, Littlebredy	
DESIGNATION:	Scheduled Monument (No. 22967)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHs	World Heritage Site

SITE NAME: Barrow 650yds (600m) north of North Barn Farm, Long Bredy			
DESIGNATION:	Scheduled Monument (No. DO309)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 01 17 9750726

SITE NAME: Barrow 700yds (640m) south west of North Barn Farm, Long Bredy			
DESIGNATION:	Scheduled Monument (No. DO312)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

SITE NAME: Bowl barrow on Farm Hill 620m west of Minterne Parva Farm, Minterne Magna			
DESIGNATION:	Scheduled Monument (No. 27445)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

SITE NAME: Ancient settlement south west of Incombe Wood, Nether Cerne			
DESIGNATION:	Scheduled Monument (No. DO722)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 01 17 9750726

SITE NAME: Bowl barrow 230m north east of Great Strode House, Netherbury			
DESIGNATION:	Scheduled Monument (No. 29577)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 01 17 9750726

SITE NAME: George III, chalk-cut hill side figure, Osmington			
DESIGNATION:	Scheduled Monument (No. DO746)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive natural erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 01 17 9750726

SITE NAME: Medieval settlement at West Ringstead, Osmington			
DESIGNATION:	Scheduled Monument (No. 29091)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 01 17 9750726

SITE NAME: Four barrows on Moigns Down, Owermoigne			
DESIGNATION:	Scheduled Monument (No. DO278)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 01 17 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Round barrow south west of Bourne Farm, Piddlehinton		
DESIGNATION:	Scheduled Monument (No. DO516)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Two barrows on Little Puddle Hill, Piddlehinton		
DESIGNATION:	Scheduled Monument (No. DO340)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Two barrows west of Little Piddle Down, Piddlehinton		
DESIGNATION:	Scheduled Monument (No. DO341)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Barrow on College Down, Piddletrenthide		
DESIGNATION:	Scheduled Monument (No. DO437)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow on Plush Hill 600m ESE of Lower Farm, Plush, Piddletrenthide		
DESIGNATION:	Scheduled Monument (No. 27437)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow on Plush Hill 740m ESE of Lower Farm, Plush, Piddletrenthide		
DESIGNATION:	Scheduled Monument (No. 27438)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow on Pond Eweleaze 500m north east of Dole's Ash Farm, Piddletrenthide		
DESIGNATION:	Scheduled Monument (No. 27435)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Round barrow on Hog Leaze, Piddletrenthide		
DESIGNATION:	Scheduled Monument (No. DO520)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Bowl barrow on Black Down, 80m south east of the Hardy Monument, Portesham			
DESIGNATION:	Scheduled Monument (No. 31918)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Group of round barrows on Shorn Hill and Bronkham Hill, Portesham			
DESIGNATION:	Scheduled Monument (No. DO52)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Dumping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Round barrow north east of Friar Waddon, Portesham			
DESIGNATION:	Scheduled Monument (No. DO546)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Two bowl barrows on Black Down immediately east of the Hardy Monument, Portesham			
DESIGNATION:	Scheduled Monument (No. 31914)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Two round barrows on Ridgeway, Portesham			
DESIGNATION:	Scheduled Monument (No. DO229)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Barrow near east boundary of parish, Powerstock			
DESIGNATION:	Scheduled Monument (No. DO346)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Group of barrows east of Northdown Barn, Poxwell			
DESIGNATION:	Scheduled Monument (No. DO272)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Round barrow north of Boswell's Plantation, Puddletown			
DESIGNATION:	Scheduled Monument (No. DO494)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Round barrow west of Druce Higher Barn, Puddletown		
DESIGNATION:	Scheduled Monument (No. DO518)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Three round barrows on Puddletown Down, Puddletown		
DESIGNATION:	Scheduled Monument (No. DO655)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Two round barrows south west of Well House Cottage, Puddletown		
DESIGNATION:	Scheduled Monument (No. DO519)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 400m north east of Look Farm, Puncknowle		
DESIGNATION:	Scheduled Monument (No. 29575)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bell barrow 70m west of Fidler's Green, Stinsford		
DESIGNATION:	Scheduled Monument (No. 33167)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Round barrow north east of Hog Hill Barn, Stratton		
DESIGNATION:	Scheduled Monument (No. DO513)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Dumping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Round barrow north west of Jackman's Cross, Stratton		
DESIGNATION:	Scheduled Monument (No. DO584)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Round barrow on Stratton Down, Stratton		
DESIGNATION:	Scheduled Monument (No. DO514)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Tithe barn at Court Farm, Sydling St Nicholas		
DESIGNATION:	Scheduled Monument (No. DO105)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow on Eype Down 275m east of Frogmore Farm, Symondsburry		
DESIGNATION:	Scheduled Monument (No. 29573)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Holditch Court Tower, Thorncombe		
DESIGNATION:	Scheduled Monument (No. DO426)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Four bowl barrows 710m north, 750m north west and 950m north west of Clyffe House, Tolpuddle		
DESIGNATION:	Scheduled Monument (No. 29583)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Barrow near Eggardon, West Compton		
DESIGNATION:	Scheduled Monument (No. DO343)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Dyke south east of Eggardon Hill camp, West Compton		
DESIGNATION:	Scheduled Monument (No. DO770)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow on Whitcombe Hill 500m north of Whitcombe Farm, West Stafford		
DESIGNATION:	Scheduled Monument (No. 33539)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow on Whitcombe Hill, 600m west of Stafford Farm, West Stafford		
DESIGNATION:	Scheduled Monument (No. 33538)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Enclosure on Mount Pleasant Hill, West Stafford			
DESIGNATION:	Scheduled Monument (No. DO624)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Two bowl barrows on Frome Hill 520m west of Frome Farm, West Stafford			
DESIGNATION:	Scheduled Monument (No. 33536)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Three bowl barrows 530m and 350m north east of Whitcombe Barn, Whitcombe			
DESIGNATION:	Scheduled Monument (No. 33187)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Medieval settlement of Winterborne Farringdon and associated remains, Winterborne Came			
DESIGNATION:	Scheduled Monument (No. 33196)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Two round barrows north of Came Farm, Winterborne Came			
DESIGNATION:	Scheduled Monument (No. DO402)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Long barrow immediately north west of Maiden Castle, Winterborne Monkton			
DESIGNATION:	Scheduled Monument (No. 28338)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Long barrow, three bell barrows, fancy barrow and a linear earthwork 800m north of Maiden Castle, Winterborne Monkton			
DESIGNATION:	Scheduled Monument (No. 28392)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Round barrow cemetery immediately south east of Maiden Castle, Winterborne Monkton			
DESIGNATION:	Scheduled Monument (No. 28337)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Settlement remains north of Maiden Castle, Winterborne Monkton			
DESIGNATION:	Scheduled Monument (No. DO778)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

SITE NAME: Group of barrows south of Goldsmith's Plantation, Winterborne St Martin			
DESIGNATION:	Scheduled Monument (No. DO347)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

SITE NAME: Group of round barrows near Eweleaze Barn, Winterborne St Martin			
DESIGNATION:	Scheduled Monument (No. DO226)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Localised/limited animal burrowing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

SITE NAME: Group of round barrows on and to east of Great Hill, Winterborne St Martin			
DESIGNATION:	Scheduled Monument (No. DO228)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

SITE NAME: Round barrow north of Ballarat House, Winterborne St Martin			
DESIGNATION:	Scheduled Monument (No. DO505)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

SITE NAME: Round barrow north of Ridgeway, Winterborne St Martin			
DESIGNATION:	Scheduled Monument (No. DO230)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

SITE NAME: Round barrows on Four Barrow Hill, Winterborne St Martin			
DESIGNATION:	Scheduled Monument (No. DO225)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

SITE NAME: Round barrows on Grove Hill, Winterborne St Martin			
DESIGNATION:	Scheduled Monument (No. DO227)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Three barrows south of Hart Hill Plantation, Winterborne St Martin			
DESIGNATION:	Scheduled Monument (No. DO352)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 01 17 9750726

SITE NAME: Two barrows at Rew, Winterborne St Martin			
DESIGNATION:	Scheduled Monument (No. DO348)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

SITE NAME: Bell barrow 100m south of Winterbourne Poor Lot, part of the Winterbourne Poor Lot round barrow cemetery, Winterbourne Abbas			
DESIGNATION:	Scheduled Monument (No. 22939)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

SITE NAME: Bowl barrow 400m north east of Manor Farm, part of the Pound Hill round barrow cemetery, Winterbourne Abbas			
DESIGNATION:	Scheduled Monument (No. 22931)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

SITE NAME: Bowl barrow 450m north east of Manor Farm, part of the Pound Hill round barrow cemetery, Winterbourne Abbas			
DESIGNATION:	Scheduled Monument (No. 22930)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

SITE NAME: Broad Stone, Winterbourne Abbas			
DESIGNATION:	Scheduled Monument (No. DO34)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Shane Gould 01 17 9750726

SITE NAME: Group of barrows near Big Wood, Winterbourne Abbas			
DESIGNATION:	Scheduled Monument (No. DO48)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 01 17 9750726

SITE NAME: Triple barrow and bowl barrow forming part of a barrow cemetery and part of an associated field system 250m north east of Winterbourne Poor Lot, Winterbourne Abbas			
DESIGNATION:	Scheduled Monument (No. 22942)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 01 17 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Four round barrows north west of Blagdon Barn, Winterbourne Steepleton			
DESIGNATION:	Scheduled Monument (No. DO213)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Long barrow on Pound Hill, Winterbourne Steepleton			
DESIGNATION:	Scheduled Monument (No. DO36)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Round barrow on Pound Hill, Winterbourne Steepleton			
DESIGNATION:	Scheduled Monument (No. DO512)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Round barrow south west of village, Winterbourne Steepleton			
DESIGNATION:	Scheduled Monument (No. DO218)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Round barrows on Sheep Down, Winterbourne Steepleton			
DESIGNATION:	Scheduled Monument (No. DO212)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Round barrows west of Blagdon Barn, Winterbourne Steepleton			
DESIGNATION:	Scheduled Monument (No. DO237)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Three round barrows east of Smitten Corner, Winterbourne Steepleton			
DESIGNATION:	Scheduled Monument (No. DO239)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Two round barrows on North Hill, Winterbourne Steepleton			
DESIGNATION:	Scheduled Monument (No. DO499)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Bowl barrow 1km south west of Manor Farm, Wraxall		
DESIGNATION:	Scheduled Monument (No. 27451)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Kingston Maurward, Stinsford	Designed landscape surrounding early C18 house. Later landscape phases include formal Edwardian gardens, now open to the public. House forms nucleus of expanding college. Many post-war and more recent buildings with impacts on view lines and appreciation of designed landscape.
DESIGNATION:	Registered Park and Garden Grade II*, also part in CA, 8 LBs , 1 SM	
CONDITION:	Generally satisfactory but with minor localised problems	
VULNERABILITY:	High	
TREND:	Stable	
OWNERSHIP:	Corporate, single owner	
		Contact: Kim Auston 0117 975 0696

SITE NAME:	Bothenhampton		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Kim Sankey (LA) 01305 251010		

SITE NAME:	Bradford Abbas		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Kim Sankey (LA) 01305 251010		

SITE NAME:	Bradpole		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Kim Sankey (LA) 01305 251010		

SITE NAME:	Broadwindsor		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Kim Sankey (LA) 01305 251010		

SITE NAME:	Cattistock		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Kim Sankey (LA) 01305 251010		

SITE NAME:	Charminster		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Kim Sankey (LA) 01305 251010		

SITE NAME:	Charmouth		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Kim Sankey (LA) 01305 251010		

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Chickerell		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Kim Sankey (LA) 01305 251010		

SITE NAME:	Chideock and Seatown		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Kim Sankey (LA) 01305 251010		

SITE NAME:	Dorchester		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Kim Sankey (LA) 01305 251010		

SITE NAME:	Frampton		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Kim Sankey (LA) 01305 251010		

SITE NAME:	Herrison, Charminster		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Kim Sankey (LA) 01305 251010		

SITE NAME:	Litton Cheney		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Kim Sankey (LA) 01305 251010		

SITE NAME:	Maiden Newton and Higher Frome Vauchurch		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Kim Sankey (LA) 01305 251010		

SITE NAME:	Owermoigne		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Kim Sankey (LA) 01305 251010		

SITE NAME:	Piddletrenthide		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Kim Sankey (LA) 01305 251010		

SITE NAME:	Portesham		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Kim Sankey (LA) 01305 251010		

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Puddletown		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Kim Sankey (LA) 01305 251010		

SITE NAME:	Shipton Gorge		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Kim Sankey (LA) 01305 251010		

SITE NAME:	Symondsburry		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Kim Sankey (LA) 01305 251010		

SITE NAME:	West Knighton		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Kim Sankey (LA) 01305 251010		

SITE NAME:	Whitchurch Canonicorum		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Kim Sankey (LA) 01305 251010		

SITE NAME:	Winterbourne Abbas		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Kim Sankey (LA) 01305 251010		

WEYMOUTH AND PORTLAND



SITE NAME: **Rufus Castle,
Church Ope Road,
Easton, Portland**

DESIGNATION: Listed Building Grade I, SM
CONDITION: Very bad
OCCUPANCY: Not applicable
PRIORITY: B (C)
OWNERSHIP: Private

Present structure probably late C15, on site of earlier building captured in 1142 by Earl Robert of Gloucester. Ruinous and in need of conservative repair and consolidation. Owner has retained architects to work up a repair scheme. Emergency repairs have been completed to stabilise collapsing masonry. English Heritage grant has been offered for main repair scheme. Works are due to start 2010.

Contact: Sarah Ball 0117 975 0666



SITE NAME: **Church of St Peter,
Grove Road, Grove,
Portland**

DESIGNATION: Listed Building Grade II*
CONDITION: Poor
OCCUPANCY: Vacant
PRIORITY: C (C)
OWNERSHIP: Private

Robust Romanesque church, 1872. Built by convict labour from Portland's prison and later transferred to the parish. Now redundant and in poor condition. The new owner has been in touch with the Council, English Heritage and other interested parties, regarding use of the building for functions and community activities, and these proposals are currently being developed.

Contact: Jenny Chesher 0117 975 0686

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME: **Sandsfoot Castle, Weymouth**

DESIGNATION: Listed Building Grade I, SM

CONDITION: Poor

OCCUPANCY: Not applicable

PRIORITY: C (C)

OWNERSHIP: Local authority

The castle is one of a pair built by Henry VIII to protect the Portland Anchorage, the other being Portland Castle. It is a scheduled monument and grade I listed building. The castle is built on soft clays that even with the protection of the Portland Breakwaters suffer from ongoing erosion and instability. A Stage I grant has been offered by the Heritage Lottery Fund.

Contact: Veryan Heal 0117 975 0717



SITE NAME: **Maiden Street Methodist Church, Maiden Street, Weymouth**

DESIGNATION: Listed Building Grade II*, CA

CONDITION: Very bad

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNERSHIP: Religious organisation

Fire in January 2002 left the church a gutted, roofless ruin. Subsequent health and safety works completely cleared the interior. Consent has been granted for conversion/reconstruction to a mixed residential and commercial use but works have not yet started.

Contact: Jenny Chesher 0117 975 0686

SITE NAME:

Group of round barrows on Ridgeway

DESIGNATION:

Scheduled Monument (No. DO232)

CONDITION:

Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY:

Arable ploughing

TREND:

Declining

OWNERSHIP:

Private

CONTACT:

Shane Gould 0117 9750726

OFF DORSET



SITE NAME: **Swash Channel, Poole Harbour**

DESIGNATION: Protected Wreck Site

CONDITION: Extensive significant problems

VULNERABILITY: High

TREND: Significant decline

OWNERSHIP: Private

PHOTO: © Dave Parham,
Bournemouth University

Following archaeological assessment in 2004, this wreck is thought to represent the remains of an early C17 armed vessel. Since the site first came to attention it has proven to be unstable and subject to dramatic shifts in exposure levels. In 2006 sediment monitoring stakes were positioned on site. In 2008 these stakes have revealed up to 300mm loss in sediment across the site, resulting in new exposure. This exposure and the rapid degradation of archaeological material has resulted in the site becoming at risk.

Contact: Kate Difford 0117 975 0700

GLOUCESTERSHIRE

COTSWOLD



SITE NAME: **Barrington Park, Barrington**

DESIGNATION: Listed Building Grade I, CA, RPG II

CONDITION: Poor

OCCUPANCY: Part occupied

PRIORITY: F (F)

OWNERSHIP: Private

Country house built circa 1736-38, extended late C19. Major repairs of the fabric, starting with the roof, have commenced.

Contact: Nick Molyneux 0121 625 6857



SITE NAME: **Dovecote, Barrington Park, Barrington**

DESIGNATION: Listed Building Grade II*, CA, RPG II

CONDITION: Poor

OCCUPANCY: Not applicable

PRIORITY: F (F)

OWNERSHIP: Private

C18 domed dovecote with Ionic portico on east side, located approx 500 metres north west of the house in open parkland. Emergency works to arrest further decay have been undertaken and full repairs will start when the house repairs are further advanced.

Contact: Nick Molyneux 0121 625 6857

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	Gothick Seat (Temple), Barrington Park, Barrington
DESIGNATION:	Listed Building Grade II*, CA, RPG II
CONDITION:	Very bad
OCCUPANCY:	Not applicable
PRIORITY:	F (F)
OWNERSHIP:	Private

Mid C18 garden temple, situated 100 metres to south west of the house in the gardens. Emergency works to arrest further decay have been undertaken and full repairs will start when the house repairs are further advanced.

Contact: Nick Molyneux 0121 625 6857



SITE NAME:	Roman Doric Temple, Barrington Park, Barrington
DESIGNATION:	Listed Building Grade II*, CA, RPG II
CONDITION:	Poor
OCCUPANCY:	Not applicable
PRIORITY:	F (F)
OWNERSHIP:	Private

Mid C18 garden temple located in the C18 gardens of Barrington Park. Emergency works to arrest further decay have been undertaken and full repairs will start when the house repairs are further advanced.

Contact: Nick Molyneux 0121 625 6857



SITE NAME:	Elizabeth Pengree Memorial, The Square, Blockley
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Not applicable
PRIORITY:	C (C)
OWNERSHIP:	Unknown

Commemorative monument (1770s) decaying on one side and the railings are in poor condition.

Contact: Justin Ayton 0117 975 0687



SITE NAME:	The Old Silk Mill, Chipping Campden
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Occupied
PRIORITY:	C (C)
OWNERSHIP:	Private

Former silk mill, C18. The mill became the workshops for CR Ashbee and the Guild of Handicrafts – one of the foremost Arts and Crafts workshops of its period.

Contact: Justin Ayton 0117 975 0687



SITE NAME:	Alfreds Hall, Cirencester Park, Cirencester
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Not applicable
PRIORITY:	C (C)
OWNERSHIP:	Private

Folly, begun 1721, designed by Lord Bathurst with Alexander Pope's advice, completed 1732. Probably the earliest C18 mock Gothic castle; part former house, part banqueting house and part mock ruin. Located in Oakley Wood, with rides radiating from it through the wood.

Contact: Business Manager 0117 975 0700

SITE NAME:	Two bowl barrows 690m and 790m north of The Manor Farm, Avening		
DESIGNATION:	Scheduled Monument (No. 32350)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME:	Perrott's Brook dykes, Bagendon		
DESIGNATION:	Scheduled Monument (No. GC428)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Bowl barrow 800m north east of Beverston Castle Farm, Beverstone			
DESIGNATION:	Scheduled Monument (No. 22866)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME: Long barrow 800m north east of Oldwalls Farm, Bibury			
DESIGNATION:	Scheduled Monument (No. 29786)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME: Wayside cross socket stone 125m NNW of Kilkenny Cottages, Bibury			
DESIGNATION:	Scheduled Monument (No. 22097)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Melanie Barge 0117 9751300

SITE NAME: West Barrow: a long barrow 200m west of Leighterton School, Boxwell with Leighterton			
DESIGNATION:	Scheduled Monument (No. 22885)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Localised/limited animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME: Round barrow north of Chedworth Roman villa, Chedworth			
DESIGNATION:	Scheduled Monument (No. GC201)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Digging	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME: Settlement south east of Chesterton Farm, Cirencester			
DESIGNATION:	Scheduled Monument (No. GC464)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME: Two bowl barrows, known as Crippet's Wood round barrows, 560m and 590m north east of Dryhill Farm, Coberley			
DESIGNATION:	Scheduled Monument (No. 32372)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME: Norbury Camp hillfort, Colesbourne			
DESIGNATION:	Scheduled Monument (No. 29790)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Round barrow 250yds (230m) north of Colnpen Barn, Coln St Dennis		
DESIGNATION:	Scheduled Monument (No. GC442)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME:	Condicote bowl barrow, Condicote		
DESIGNATION:	Scheduled Monument (No. 28848)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME:	Tump Barn bowl barrow, Didmarton		
DESIGNATION:	Scheduled Monument (No. 28844)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME:	Bowl barrow known as St Paul's Epistle Mound, Dowdeswell		
DESIGNATION:	Scheduled Monument (No. 32349)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME:	Camp at Upper Dowdeswell, Dowdeswell		
DESIGNATION:	Scheduled Monument (No. GC41B)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME:	Hillfort 320m north east of Castle Barn Farm, Dowdeswell		
DESIGNATION:	Scheduled Monument (No. 31183)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME:	Lineover long barrow, 530m south west of Castle Barn Farm, Dowdeswell		
DESIGNATION:	Scheduled Monument (No. 29789)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME:	Round barrow 750m north east of Eastleachdowns Farm, Eastleach		
DESIGNATION:	Scheduled Monument (No. 31938)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Bowl barrow in Three Ash Belt, 460m north east of Westwood Farm, Edgeworth			
DESIGNATION:	Scheduled Monument (No. 32345)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME: Settlement site south of Claydon Cottages, Fairford			
DESIGNATION:	Scheduled Monument (No. GC459)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Mineral extraction / related subsidence	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME: Settlement site, Great Rissington			
DESIGNATION:	Scheduled Monument (No. GC455)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME: Round barrow 300m west of Church Farm, Guiting Power			
DESIGNATION:	Scheduled Monument (No. 32354)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME: Icomb camp, Icomb			
DESIGNATION:	Scheduled Monument (No. GC181)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME: Sites near Manor Ham Barn, Kempford			
DESIGNATION:	Scheduled Monument (No. GC349)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME: Bowl barrow 450m west of Lasborough, Kingscote			
DESIGNATION:	Scheduled Monument (No. 22907)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME: The Chessalls Roman town, Kingscote			
DESIGNATION:	Scheduled Monument (No. 31929)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Metal detecting	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Roman villa 600yds (550m) north east of Great Lemhill Farm, Lechlade		
DESIGNATION:	Scheduled Monument (No. GC271)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME:	New Court Ground Roman villa (south of new buildings), Naunton		
DESIGNATION:	Scheduled Monument (No. GC176)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME:	Summerhill prehistoric site, Naunton		
DESIGNATION:	Scheduled Monument (No. GC174)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME:	Bowl barrow in Inlands Plantation, 650m south of Hazleton Manor Farm, Rodmarton		
DESIGNATION:	Scheduled Monument (No. 22890)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME:	Two bowl barrows 180m south east of Haresdown Barn, Rodmarton		
DESIGNATION:	Scheduled Monument (No. 22897)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME:	Bowl barrow 120m north of Home Farm, Sherborne		
DESIGNATION:	Scheduled Monument (No. 32386)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME:	Bowl barrow 250m west of Woeful Lake Farm, Sherborne		
DESIGNATION:	Scheduled Monument (No. 31933)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME:	Two bowl barrows 260m north of Chalk Hill Cottage; part of the Cow Common round barrow cemetery, Swell		
DESIGNATION:	Scheduled Monument (No. 22879)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Bowl barrow 990m south east of Bemborough Farm: part of the Bemborough Farm round barrow cemetery, Temple Guiting			
DESIGNATION:	Scheduled Monument (No. 22905)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME: Earthwork north of Lyne's Barn, Temple Guiting			
DESIGNATION:	Scheduled Monument (No. GC129)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	No known threat	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME: Bowl barrow 335m south east of Broadfield Farm, Tetbury Upton			
DESIGNATION:	Scheduled Monument (No. 32343)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Melanie Barge 0117 9751300

SITE NAME: Four bowl barrows forming part of a round barrow cemetery, and a long barrow 550m NNE of Eyford Hill Farm, Upper Slaughter			
DESIGNATION:	Scheduled Monument (No. 22900)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME: Syreford Farm bowl barrow, 450m south west of Oxpens, Whittington			
DESIGNATION:	Scheduled Monument (No. 28860)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300



SITE NAME:	Hatherop Castle, Hatherop
DESIGNATION:	Registered Park and Garden Grade II, also part in CA, 2 LBs , 1 SM
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	Medium
TREND:	Stable
OWNERSHIP:	Mixed, multiple owners

Hatherop, possibly landscaped by 'Capability' Brown's contemporary Richard Woods, and reworked extensively in the C19. The main house is occupied by a school with an adjacent area of new build. The wider parkland, in separate ownership, is neglected: many parkland trees have gone, clumps and ornamental woodland are over-mature and decaying, and sections of park wall and estate railings are in very poor condition.

Contact: Kim Auston 0117 975 0696

FOREST OF DEAN



SITE NAME:	Blakeney United Reformed Church, Cinderford Road, Blakeney, Awre
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Not applicable
PRIORITY:	F (F)
OWNERSHIP:	Private

Non-conformist chapel, dated 1849. Remarkably complete and architecturally distinctive example of its type. Stonework repairs required. Owner has undertaken repairs and continues to do so in consultation with the Local Planning Authority, which has offered grant aid towards new windows and roof covering.

Contact: Justin Ayton 0117 975 0687

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	Guns Mill Barn, Littledean
DESIGNATION:	Listed Building Grade II*, SM
CONDITION:	Very bad
OCCUPANCY:	Vacant
PRIORITY:	A (A)
OWNERSHIP:	Private

Formerly a blast furnace and later a paper mill, built 1682. Now unused and in perilous condition, despite some emergency holding repairs. There have been discussions about the site's future ownership and a comprehensive repair scheme.

Contact: Mel Barge 0117 975 1300



SITE NAME:	Lydney Docks and Harbour, Naas Lane, Lydney
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	Not applicable
PRIORITY:	F (F)
OWNERSHIP:	Government

The docks and harbour date from about 1810 to 1821 and were once the main commercial port serving industry in the district. Outer basin now repaired with surrounding area used for recreation, however the Inner Basin is still in poor condition.

Contact: Mel Barge 0117 975 1300



SITE NAME:	Tithe Barn, Highleadon Court, Rudford and Highleadon
DESIGNATION:	Listed Building Grade II*
CONDITION:	Poor
OCCUPANCY:	Not applicable
PRIORITY:	C (C)
OWNERSHIP:	Private

C15 or early C16 Tithe barn built for the Abbey of St Peter, Gloucester. The roof is sound, but the framing and infill panels are deteriorating. Used for agricultural storage. Some maintenance undertaken. The Local Authority is in discussion with the owner.

Contact: Justin Ayton 0117 975 0687



SITE NAME:	St James Church, Lancaut, Tidenham
DESIGNATION:	Listed Building Grade II, SM
CONDITION:	Fair
OCCUPANCY:	Vacant
PRIORITY:	F (F)
OWNERSHIP:	Trust

Small C12 chapel with later medieval extension to west. Unroofed rubble-built structure with slow deterioration of stonework and internal plasterwork. A condition survey funded by English Heritage highlighted the works needed to halt further deterioration and with a recommendation for the wall heads to be soft-capped. Repairs to the wall are due to be completed by end of 2010.

Contact: Mel Barge 0117 975 1300

SITE NAME:	Symonds Yat promontory fort, English Bicknor	
DESIGNATION:	Scheduled Monument (No. 28861)	CONDITION: Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND: Declining
OWNERSHIP:	Other	CONTACT: Melanie Barge 0117 9751300

SITE NAME:	Soudley camp, Lower Soudley, Ruspidge and Soudley	
DESIGNATION:	Scheduled Monument (No. GC59)	CONDITION: Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND: Declining
OWNERSHIP:	Government or Agency	CONTACT: Melanie Barge 0117 9751300

SITE NAME:	Offa's Dyke: section 240m north east of Buttington Farm, Tidenham	
DESIGNATION:	Scheduled Monument (No. 34859)	CONDITION: Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND: Declining
OWNERSHIP:	Private	CONTACT: Melanie Barge 0117 9751300

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Offa's Dyke: section in Boatwood Plantation, 320m south west of Chase Farm, Tidenham		
DESIGNATION:	Scheduled Monument (No. 34852)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Melanie Barge 0117 9751300

SITE NAME:	Offa's Dyke: section in Caswell Wood, 280m west of Beeches Farm, Tidenham		
DESIGNATION:	Scheduled Monument (No. 33477)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Melanie Barge 0117 9751300

SITE NAME:	Offa's Dyke: section in Chapelhouse Wood, 240m west of the Recreation Ground, Tidenham		
DESIGNATION:	Scheduled Monument (No. 34854)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME:	Offa's Dyke: section in Passage Grove, 660m west of Sheepcot, Tidenham		
DESIGNATION:	Scheduled Monument (No. 33479)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Melanie Barge 0117 9751300

SITE NAME:	Offa's Dyke: section in Shorncliff Wood including the Devil's Pulpit, 790m south west of Sheepcot, Tidenham		
DESIGNATION:	Scheduled Monument (No. 33480)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Melanie Barge 0117 9751300

SITE NAME:	Offa's Dyke: section in Worgan's Wood, 800m west of Chase Farm, Tidenham		
DESIGNATION:	Scheduled Monument (No. 34851)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Melanie Barge 0117 9751300

SITE NAME:	Roman site 150yds (140m) east of Palace Cottage, Boughspring, Tidenham		
DESIGNATION:	Scheduled Monument (No. GC437)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME:	Roman villa 600yds (550m) south west of Woolaston station, Woolaston		
DESIGNATION:	Scheduled Monument (No. GC102)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

GLOUCESTER

	<p>SITE NAME: Tanner's Hall, north of city centre, Gouda Way, Gloucester</p> <p>DESIGNATION: Scheduled Monument</p> <p>CONDITION: Very bad</p> <p>OCCUPANCY: Not applicable</p> <p>PRIORITY: A (A)</p> <p>OWNERSHIP: Private</p>	<p>This is a rare survival of a C13 merchant's house, later converted to a tannery and Tanner's Hall. Surrounding buildings have been removed for the inner relief road. English Heritage has commissioned a feasibility study which is now complete. The owner has plans for the site which are under discussion.</p> <p>Contact: Mel Barge 0117 975 1300</p>
	<p>SITE NAME: Llanthony Priory, range between Outer and Inner Courts, Llanthony Road, Gloucester</p> <p>DESIGNATION: Listed Building Grade I, SM</p> <p>CONDITION: Very bad</p> <p>OCCUPANCY: Vacant</p> <p>PRIORITY: B (B)</p> <p>OWNERSHIP: Trust</p>	<p>Remains of the range between the Outer and Inner Courts of the Augustinian Priory of Llanthony Secunda. Late C14 and early C16. Vacant buildings subject to vandalism. Timber frame decaying; brick and stonework eroded. The Llanthony Priory Trust is looking to raise funds and investigate suitable future uses for the site.</p> <p>Contact: Justin Ayton 0117 975 0687</p>
	<p>SITE NAME: Llanthony Priory, remains of outer gatehouse, Llanthony Road, Gloucester</p> <p>DESIGNATION: Listed Building Grade I, SM</p> <p>CONDITION: Poor</p> <p>OCCUPANCY: Not applicable</p> <p>PRIORITY: C (New)</p> <p>OWNERSHIP: Trust</p>	<p>Remains of the outer Gatehouse of the former Augustinian Priory of Llanthony Secunda. Only southern part of the front wall survives to full height. The Llanthony Priory Trust is looking to raise funds and investigate suitable future uses for the site.</p> <p>Contact: Justin Ayton 0117 975 0687</p>
	<p>SITE NAME: Llanthony Priory, remains of precinct wall north of Inner Gatehouse, Llanthony Road, Gloucester</p> <p>DESIGNATION: Listed Building Grade I, SM</p> <p>CONDITION: Poor</p> <p>OCCUPANCY: Not applicable</p> <p>PRIORITY: C (New)</p> <p>OWNERSHIP: Trust</p>	<p>Stone and brick wall on the west and north sides of the Outer Court of the former Augustinian Priory. Built in the C15, it was rebuilt or extended in the C17 and C18. The Llanthony Priory Trust is looking to raise funds and investigate suitable future uses for the site.</p> <p>Contact: Justin Ayton 0117 975 0687</p>
	<p>SITE NAME: Llanthony Priory, remains of precinct wall south of Outer Gatehouse, Llanthony Road, Gloucester</p> <p>DESIGNATION: Listed Building Grade I, SM</p> <p>CONDITION: Very bad</p> <p>OCCUPANCY: Not applicable</p> <p>PRIORITY: C (New)</p> <p>OWNERSHIP: Trust</p>	<p>Early C16 brick wall. Badly eroded especially at low level. Two brick piers constructed 1995 to support wall to provide support in event that condition of wall deteriorates, but these have now rotated away from back of wall. The Llanthony Priory Trust is looking to raise funds and investigate suitable future uses for the site.</p> <p>Contact: Justin Ayton 0117 975 0687</p>
	<p>SITE NAME: Llanthony Priory, remains of range on south side of Inner Court, Llanthony Road, Gloucester</p> <p>DESIGNATION: Listed Building Grade I, SM</p> <p>CONDITION: Very bad</p> <p>OCCUPANCY: Not applicable</p> <p>PRIORITY: B (B)</p> <p>OWNERSHIP: Trust</p>	<p>Remains of the range on the south side of the Inner Court of the Augustinian Priory of Llanthony Secunda. Early C16. Subject to vandalism. The Llanthony Priory Trust is looking to raise funds and investigate suitable future uses for the site.</p> <p>Contact: Justin Ayton 0117 975 0687</p>

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME: **The Fleece Hotel,
19 Westgate Street,
Gloucester**

C15 timber-framed range most recently occupied as the Fleece Hotel. The building has been vacant for sometime. It is in poor repair, with some internal decay.

DESIGNATION: Listed Building Grade I, CA

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: C (New)

OWNERSHIP: Quango

Contact: Justin Ayton 0117 975 0687

SITE NAME:

Southgate Street

DESIGNATION: Conservation Area

CONDITION: Very bad

VULNERABILITY: Low

TREND: Expected to deteriorate

CONTACT: Charlotte Lewis (LA) 01452 396855

STROUD



SITE NAME: **St Marys House,
London Road,
Chalford**

Former mill owner's house and weavers' cottages, late C16 and late C17. Roof in exceptionally poor condition and is covered with tarpaulin.

DESIGNATION: Listed Building Grade II*, CA

CONDITION: Poor

OCCUPANCY: Part occupied

PRIORITY: A (A)

OWNERSHIP: Private

Contact: Justin Ayton 0117 975 0687



SITE NAME: **Main building at Stanley Mills,
Ryeford,
Kings Stanley**

Woollen mill, 1813. Ancillary building (grade II) is in poor condition and part occupied. Roof repaired with English Heritage grant. The owners are in discussion with English Heritage about the future of the entire complex.

DESIGNATION: Listed Building Grade I, CA

CONDITION: Fair

OCCUPANCY: Part occupied

PRIORITY: E (E)

OWNERSHIP: Company

Contact: Business Manager 0117 975 0700



SITE NAME: **Former Saxon church
to west of Priory House,
Leonard Stanley**

Former Saxon and medieval chapel within core of former priory of St Leonard. Later converted to agricultural use including dovecotes and forge. Threshing floor in situ. Currently used for vehicle/equipment storage. Condition survey, funded by English Heritage, will inform an application for repair under the farms Higher Level Stewardship scheme with Natural England.

DESIGNATION: Listed Building Grade II*, SM, CA

CONDITION: Poor

OCCUPANCY: Part occupied

PRIORITY: C (C)

OWNERSHIP: Private

Contact: Mel Barge 0117 975 1300



SITE NAME: **The Red House,
Painswick Rococo Garden,
Painswick**

A mid C18 garden pavilion within Painswick Rococo Garden. The principle elevation is in elaborate gothic style. The main room has a flat vaulted ceiling which is in poor condition. Repairs with English Heritage grant aid are underway and are due to be completed end 2010.

DESIGNATION: Listed Building Grade II*, RPG II*

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: F (B)

OWNERSHIP: Trust

Contact: Business Manager 0117 975 0700



SITE NAME: **Brownhill Court,
Wick Street,
Painswick**

Early to mid C18 country house converted into flats, which are now vacant. The house has been the subject of a closing order and parts are now in a dangerous condition. Negotiations are in progress.

DESIGNATION: Listed Building Grade II*

CONDITION: Very bad

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNERSHIP: Private

Contact: Justin Ayton 0117 975 0687

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA Conservation Area
LB/LBs Listed Building/s
NP National Park
RPG Registered Park and Garden
SM/SMs Scheduled Monument/s
UA Unitary Authority
WHS World Heritage Site



SITE NAME: **Railway Goods Shed,
Station Road,
Stroud**

Railway goods shed built 1845. Shell repaired by local preservation trust with English Heritage grant aid and leased to Stroud Building Preservation Trust. Listed building consent and planning permission have been given and further discussions are ongoing

DESIGNATION: Listed Building Grade II*, CA

CONDITION: Good

OCCUPANCY: Vacant

PRIORITY: F (F)

OWNERSHIP: Former utility

Contact: Justin Ayton 0117 975 0687

SITE NAME: **Two bowl barrows, known as Climperwell round barrows, 310m south west of Climperwell Farm, Cranham**

DESIGNATION: Scheduled Monument (No. 32376) CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining

OWNERSHIP: Private CONTACT: Melanie Barge 0117 9751300

SITE NAME: **The Mount moated site, Haresfield**

DESIGNATION: Scheduled Monument (No. 32365) CONDITION: Generally satisfactory
but with significant localised problems

PRINCIPAL VULNERABILITY: Extensive animal burrowing TREND: Declining

OWNERSHIP: Private CONTACT: Melanie Barge 0117 9751300

SITE NAME: **Tresham Farbarrow round barrows, Hillesley and Tresham**

DESIGNATION: Scheduled Monument (No. GC295) CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining

OWNERSHIP: Private CONTACT: Melanie Barge 0117 9751300

SITE NAME: **Bowl barrow 450m south east of Upper Hyde Farm, Minchinhampton**

DESIGNATION: Scheduled Monument (No. 22888) CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining

OWNERSHIP: Other CONTACT: Melanie Barge 0117 9751300

SITE NAME: **Gatcombe long barrow, 400m east of Gatcombe Farm, Minchinhampton**

DESIGNATION: Scheduled Monument (No. 22884) CONDITION: Generally unsatisfactory
with major localised problems

PRINCIPAL VULNERABILITY: Extensive animal burrowing TREND: Declining

OWNERSHIP: Other CONTACT: Melanie Barge 0117 9751300

SITE NAME: **Painswick Roman villa (west of High Fold), Painswick**

DESIGNATION: Scheduled Monument (No. GC234) CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining

OWNERSHIP: Private CONTACT: Melanie Barge 0117 9751300

SITE NAME: **West Hill Romano-Celtic temple, Uley**

DESIGNATION: Scheduled Monument (No. GC471) CONDITION: Generally satisfactory
but with minor localised problems

PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining

OWNERSHIP: Private CONTACT: Melanie Barge 0117 9751300

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA Conservation Area
LB/LBs Listed Building/s
NP National Park
RPG Registered Park and Garden
SM/SMs Scheduled Monument/s
UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Bowl barrow 720m south east of Longwood Farm, Woodchester		
DESIGNATION:	Scheduled Monument (No. 32388)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300


SITE NAME:	Bowl barrow 330m north of Symonds' Hall Farm, Wotton-under-Edge		
DESIGNATION:	Scheduled Monument (No. 32387)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

TEWKESBURY

SITE NAME:	Dovecote approx 75 metres south east of Manor Farm, Fiddington, Ashchurch	Dovecote, I637. Pointing eroded particularly on the north face. Occasional missing roof tiles, although some roofing works have commenced.
DESIGNATION:	Listed Building Grade II*	
CONDITION:	Poor	
OCCUPANCY:	Not applicable	
PRIORITY:	C (C)	
OWNERSHIP:	Private	Contact: Justin Ayton 0117 975 0687



SITE NAME:	Dovecote 3 metres north of Bridge House, Bentham, Badgeworth	Dovecote, C17. Movement of structural timbers on south east and north east walls has caused joints to pull apart, leading to brick panels falling out. Wattle and daub panels are also fragmenting. Some timber decay on west side. Cement repairs to roof.
DESIGNATION:	Listed Building Grade II*	
CONDITION:	Poor	
OCCUPANCY:	Not applicable	
PRIORITY:	C (C)	
OWNERSHIP:	Private	Contact: Justin Ayton 0117 975 0687



SITE NAME:	Former gatehouse to Toddington House, Church Lane, Toddington	Ancient Jacobean ruin, a remnant of the old manor house, of which the ruined fragments remain 300 metres south west of Toddington House.
DESIGNATION:	Listed Building Grade II*, SM, RPG II	
CONDITION:	Poor	
OCCUPANCY:	Not applicable	
PRIORITY:	A (A)	
OWNERSHIP:	Private	Contact: Mel Barge 0117 975 1300



SITE NAME:	Toddington House, Church Lane, Toddington	Manor house, 1820-35, set in C19 formal gardens, on the east side of a late C18 landscape park. The house has been mothballed for more than 15 years, but has recently been purchased by a new owner who has installed a temporary roof and is currently engaging in an extensive programme of urgent works and repairs in consultation with the Local Planning Authority and English Heritage.
DESIGNATION:	Listed Building Grade I, RPG II	
CONDITION:	Fair	
OCCUPANCY:	Vacant	
PRIORITY:	E (E)	
OWNERSHIP:	Private	Contact: Justin Ayton 0117 975 0687

SITE NAME:	Nottingham Hill camp, Gotherington		
DESIGNATION:	Scheduled Monument (No. GC50)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Great Witcombe Romano-British villa, Great Witcombe			
DESIGNATION:	Scheduled Monument (No. 28521)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Melanie Barge 0117 9751300

SITE NAME: Bowl barrow 690m south west of Roel Farm, Hawling			
DESIGNATION:	Scheduled Monument (No. 32378)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME: Bowl barrow 760m south of Roel Farm, Hawling			
DESIGNATION:	Scheduled Monument (No. 32379)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME: Two bowl barrows known as Hawling Downs round barrows, 610m north east of Slade Barn Farm, Hawling			
DESIGNATION:	Scheduled Monument (No. 32368)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME: Hailes Abbey and ringwork, Stanway			
DESIGNATION:	Scheduled Monument (No. 28850)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME: Hailes Wood camp, Hailes, Stanway			
DESIGNATION:	Scheduled Monument (No. GC121)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME: Milhampost Roman site, Stanway			
DESIGNATION:	Scheduled Monument (No. GC123)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME: Wadfield Roman villa, Sudeley			
DESIGNATION:	Scheduled Monument (No. GC127)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Moat House moated site, Uckington		
DESIGNATION:	Scheduled Monument (No. 32340)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME:	Deserted medieval village, Walton Cardiff		
DESIGNATION:	Scheduled Monument (No. GC460)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

ISLES OF SCILLY (UA)

SITE NAME:	Post medieval cottages, Samson	Fossilised C18/C19 landscape. The remains of the buildings are at risk from natural weathering, vegetation and erosion caused by visitors. A management plan has been devised and initial phase of consolidation grant-aided by English Heritage is now complete. The result of the consolidation trials are being studied to inform a wider programme of repair.
DESIGNATION:	Scheduled Monument, CA	
CONDITION:	Poor	
OCCUPANCY:	Not applicable	
PRIORITY:	C (C)	
OWNERSHIP:	Trust	Contact: Phil McMahon 0117 975 0699

SITE NAME:	Civil War battery on The Green, Bryher		
DESIGNATION:	Scheduled Monument (No. 15399)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Moderate vehicle damage/erosion	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Gig shed on the north coast of Great Porth, Bryher		
DESIGNATION:	Scheduled Monument (No. 15494)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Dumping	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Prehistoric enclosure south east of The Brow, Bryher		
DESIGNATION:	Scheduled Monument (No. 15464)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Prehistoric field system and post-medieval quay in Great Porth, Bryher		
DESIGNATION:	Scheduled Monument (No. 15461)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Prehistoric field system and Romano-British cist in Green Bay, Bryher		
DESIGNATION:	Scheduled Monument (No. 15463)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Prehistoric hut circle south of The Brow, Bryher		
DESIGNATION:	Scheduled Monument (No. 15465)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Prehistoric linear boundary and cairns south west of The Bar, Bryher		
DESIGNATION:	Scheduled Monument (No. 15491)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Prehistoric linear boundary SSE of The Island, Bryher		
DESIGNATION:	Scheduled Monument (No. 15466)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Prehistoric field system and post-medieval breastwork and maze on Castella Down, St Agnes		
DESIGNATION:	Scheduled Monument (No. 15453)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Platform cairn on Cruther's Neck, St Martin's		
DESIGNATION:	Scheduled Monument (No. 15419)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Prehistoric cairn cemetery and field system on Tinkler's Hill, St Martin's		
DESIGNATION:	Scheduled Monument (No. 15517)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Prehistoric house platform settlement south west of English Island Carn, St Martin's		
DESIGNATION:	Scheduled Monument (No. 15523)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Prehistoric settlement and Romano-British shrine on Nornour, St Martin's		
DESIGNATION:	Scheduled Monument (No. 15490)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Prehistoric to Romano-British ritual, funerary and settlement remains on Par Beach, St Martin's		
DESIGNATION:	Scheduled Monument (No. 15524)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Ennor Castle, Old Town, St Mary's		
DESIGNATION:	Scheduled Monument (No. 15469)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Hut circle settlement in Pendrathen, St Mary's		
DESIGNATION:	Scheduled Monument (No. 15478)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Iron Age to Romano-British fogou on northern Peninnis Head, 170m south of Carn Gwavel Farm, St Mary's		
DESIGNATION:	Scheduled Monument (No. 15560)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Unknown
OWNERSHIP:	Other	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Kerbed platform cairn on Helvear Hill, 210m ENE of Helvear Farm, St Mary's		
DESIGNATION:	Scheduled Monument (No. 15377)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Post-medieval breastwork, curtain wall and associated defensive structures on the periphery of The Garrison, St Mary's		
DESIGNATION:	Scheduled Monument (No. 15434)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Prehistoric settlement, Romano-British cist cemetery and Civil War battery in northern Toll's Porth, St Mary's		
DESIGNATION:	Scheduled Monument (No. 15479)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Round cairn 137m east of Helvear Farm, St Mary's		
DESIGNATION:	Scheduled Monument (No. 15376)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	The Giant's Castle cliff castle, St Mary's		
DESIGNATION:	Scheduled Monument (No. 15354)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	The Old Quay, Old Town Bay, St Mary's		
DESIGNATION:	Scheduled Monument (No. 15470)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	World War II pillbox between Thomas' Porth and Porthaloo, St Mary's		
DESIGNATION:	Scheduled Monument (No. 15534)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	World War II pillbox west of Porth Hellick, 90m north of Drum Rock, St Mary's		
DESIGNATION:	Scheduled Monument (No. 15533)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Post-medieval animal-driven crushing mill 270m south west of Blockhouse Cottage, Tresco		
DESIGNATION:	Scheduled Monument (No. 15510)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Prehistoric field system and settlement in Bathinghouse Porth, Tresco		
DESIGNATION:	Scheduled Monument (No. 15502)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Prehistoric field system and settlement north of Appletree Point, Tresco		
DESIGNATION:	Scheduled Monument (No. 15505)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME:	Prehistoric round cairn 255m south west of Blockhouse Cottages, Tresco		
DESIGNATION:	Scheduled Monument (No. 15511)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	St Nicholas' Priory, Tresco		
DESIGNATION:	Scheduled Monument (No. 15507)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNERSHIP:	Other	CONTACT:	Phil McMahon 0117 975 0699

NORTH SOMERSET (UA)



SITE NAME: **Elms Colliery, Nailsea**

DESIGNATION: Scheduled Monument
CONDITION: Poor
OCCUPANCY: Vacant
PRIORITY: B (B)
OWNERSHIP: Local authority

One of the most complete examples of a late C18 colliery remaining in England. There are three standing structures and further exposed archaeological remains. All buildings are unroofed, derelict and subject to neglect and vandalism. Discussions are taking place for the colliery to be handed over to the Nailsea Historic Monuments Trust.

Contact: Rob Iles 0117 975 0662



SITE NAME: **Birnbeck Pier, Weston Super Mare**

DESIGNATION: Listed Building Grade II*, CA
CONDITION: Very bad
OCCUPANCY: Part occupied
PRIORITY: A (A)
OWNERSHIP: Company

Main pier which connects Birnbeck Island to the mainland below the Prince Consort Gardens. Dated 1862, opened 1867. Disused apart from the lifeboat station on the island. Negotiations are ongoing between local planning authority, owner, English Heritage and other interested parties about repair of pier and development of island. Trial repairs have been grant-aided by English Heritage and are pending.

Contact: Business Manager 0117 975 0700



SITE NAME: **Orangery at Tyntesfield, Tyntesfield, Wraxall**

DESIGNATION: Listed Building Grade II*, RPG II*
CONDITION: Very bad
OCCUPANCY: Not applicable
PRIORITY: A (A)
OWNERSHIP: Trust

Orangery (1897). Tyntesfield House and estate was acquired in 2002 by the National Trust with funding from the Heritage Lottery Fund. The Trust is in the process of drawing up a strategy for the various elements. A temporary roof has been installed. Investigation work has been undertaken and discussions regarding repair are ongoing. An application for listed building consent is to be submitted in 2010.

Contact: Justin Ayton 0117 975 0687

SITE NAME:	Beach Lawns, Weston-Super-Mare		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Nina Paternoster (LA) 01934 426753		

SITE NAME:	Birnbeck, Weston-Super-Mare		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Nina Paternoster (LA) 01934 426753		

SITE NAME:	Boulevard/Montpelier, Weston-Super-Mare		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Nina Paternoster (LA) 01934 426753		

SITE NAME:	Clevedon Triangle, Clevedon		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Nina Paternoster (LA) 01934 426753		

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Melrose/Grove Park, Weston-Super-Mare		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Nina Paternoster (LA) 01934 426753		

PLYMOUTH, CITY OF (UA)

SITE NAME: **Agaton Fort, Plymouth**

Heavy Goods Vehicle testing centre is located within a modern building in the Fort. Some ancillary buildings are vacant but have been subject to remedial repairs.

DESIGNATION: Scheduled Monument

CONDITION: Fair

OCCUPANCY: Part occupied

PRIORITY: D (D)

OWNERSHIP: Government

Contact: Phil McMahon 01 17 975 0699



SITE NAME: **The coastal fortifications of Drakes Island, Plymouth**

The Island incorporates numerous defences/military monuments dating from 1549-C20. It was held for Parliament during the Civil War and was used for defence purposes until 1958. More recently it has been used as an outdoor pursuits centre. All buildings and structures are thought to be in a poor state. The island is mainly scheduled, with four grade II listed buildings. No long-term solution has been identified.

DESIGNATION: Listed Building Grade II, SM

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNERSHIP: Private

Contact: Phil McMahon 01 17 975 0699



SITE NAME: **Boringdon Arch, Plymbridge Road, Plymouth**

Designed by Robert Adam and built in 1783, it is believed the arch was built as a triumphal arch and eye-catcher to be viewed from Saltram House. Its repair was included in a Section 106 agreement associated with consent for adjacent golf course, but work is yet to start.

DESIGNATION: Listed Building Grade II*, SM

CONDITION: Poor

OCCUPANCY: Not applicable

PRIORITY: D (D)

OWNERSHIP: Private

Contact: Simon Ramsden 01 17 975 0676



SITE NAME: **Woodland Fort, Crownhill Road, Crownhill, Plymouth**

Palmerston Fort, built 1863-1869. Part of barrack block in use as social club, but the rest is empty. Remedial repairs have been undertaken and some of the heavy vegetation has recently been cleared. Site is prone to vandalism and rubbish dumping. On-going discussions with English Heritage to find long term solution.

DESIGNATION: Scheduled Monument

CONDITION: Very bad

OCCUPANCY: Part occupied

PRIORITY: C (C)

OWNERSHIP: Local authority

Contact: Phil McMahon 01 17 975 0699



SITE NAME: **Oddfellows Hall, Ker Street, Devonport, Plymouth**

Hall by John Foulston, 1823, in the Egyptian style. Part of a group with the Guildhall and Devonport Column. Egyptian columns flank a central, recessed porch. Currently used as a social club and in poor repair. English Heritage has grant-aided a feasibility study and emergency repairs to the roof.

DESIGNATION: Listed Building Grade I

CONDITION: Poor

OCCUPANCY: Occupied

PRIORITY: C (C)

OWNERSHIP: Private

Contact: Simon Ramsden 01 17 975 0676



SITE NAME: **Efford Fort and Emplacement, Military Road, Efford, Plymouth**

Palmerston Fort built 1863-1869. Partially occupied as parade ground is used for storage, but all buildings are vacant. Buildings are suffering from extreme neglect and decay and heavy vegetation growth. Extensive water penetration and structural problems are apparent. No solution agreed at present.

DESIGNATION: Scheduled Monument

CONDITION: Very bad

OCCUPANCY: Part occupied

PRIORITY: A (A)

OWNERSHIP: Private

Contact: Phil McMahon 01 17 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

	<p>SITE NAME: South Saw Mills, South Yard, HM Naval Base, Plymouth</p> <p>DESIGNATION: Listed Building Grade II*</p> <p>CONDITION: Fair</p> <p>OCCUPANCY: Vacant</p> <p>PRIORITY: E (E)</p> <p>OWNERSHIP: Government</p>	<p>Sawmill of 1856-59. The saw mills ceased to be used as such in 1987 but the ground floor remained in light industrial use and for storage until 1997. It remains vacant with no identifiable use.</p> <p>Contact: Michael Turner 020 7973 3808</p>
	<p>SITE NAME: South Smithery, South Yard, HM Naval Base, Plymouth</p> <p>DESIGNATION: Listed Building Grade II*</p> <p>CONDITION: Very bad</p> <p>OCCUPANCY: Vacant</p> <p>PRIORITY: A (A)</p> <p>OWNERSHIP: Government</p>	<p>Dockyard smithery built 1771, modified in the C19 and reconstructed circa 1897. Remained in use until 1987 when structural faults were discovered. Doors and windows were made weathertight in 2007, but much of the roof remains exposed; there is continued deterioration of masonry and internal joinery.</p> <p>Contact: Michael Turner 020 7973 3808</p>
	<p>SITE NAME: Amphitheatre in grounds of Saltram House, Merafield Road, Plympton, Plymouth</p> <p>DESIGNATION: Listed Building Grade II*, RPG II*</p> <p>CONDITION: Fair</p> <p>OCCUPANCY: Not applicable</p> <p>PRIORITY: C (New)</p> <p>OWNERSHIP: Charity</p>	<p>Late C18 Screen Wall fronting rock-cut grottos overlooking the River Plym. Surrounding rock faces have become unstable and are subject to collapse.</p> <p>Contact: Simon Ramsden 01 17 975 0676</p>
	<p>SITE NAME: Belmont House, Belmont Place, Stoke, Plymouth</p> <p>DESIGNATION: Listed Building Grade II*, CA</p> <p>CONDITION: Poor</p> <p>OCCUPANCY: Occupied</p> <p>PRIORITY: D (D)</p> <p>OWNERSHIP: Private</p>	<p>Large detached stucco villa, circa 1820. Former Youth Hostel Association youth hostel. Owner has consent for modest conversion and is seeking permission for enabling development in the grounds.</p> <p>Contact: Simon Ramsden 01 17 975 0676</p>
	<p>SITE NAME: Academy Theatre and Great Western Hotel (Palace Theatre), Union Street, Stonehouse, Plymouth</p> <p>DESIGNATION: Listed Building Grade II*, CA</p> <p>CONDITION: Very bad</p> <p>OCCUPANCY: Vacant</p> <p>PRIORITY: A (C)</p> <p>OWNERSHIP: Private</p>	<p>Former variety theatre and hotel, 1898. Building gradually deteriorating. A significant building in a major regeneration area. English Heritage has offered grant aid in the past, which was not taken up. Temporary repairs undertaken in 1997. Currently in very bad condition with water penetration causing internal floors to become dangerous.</p> <p>Contact: Simon Ramsden 01 17 975 0676</p>

SITE NAME:	Austin Fort and section of military road, Plymouth	
DESIGNATION:	Scheduled Monument (No. 33067)	CONDITION: Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND: Stable
OWNERSHIP:	Local Authority	CONTACT: Phil McMahon 01 17 975 0699

SITE NAME:	Efford Fort and Efford Emplacement, Plymouth	
DESIGNATION:	Scheduled Monument (No. 33066)	CONDITION: Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND: Declining
OWNERSHIP:	Private	CONTACT: Phil McMahon 01 17 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Egg Buckland keep, Plymouth			
DESIGNATION:	Scheduled Monument (No. 33047)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Fort Stamford, Plymouth			
DESIGNATION:	Scheduled Monument (No. PY517)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Permitted development	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Knowle battery, Plymouth			
DESIGNATION:	Scheduled Monument (No. PY842)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Rain entry	TREND:	Unknown
OWNERSHIP:	Local Authority	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Laira Battery, Plymouth			
DESIGNATION:	Scheduled Monument (No. 33065)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Laira Emplacement, immediately south west of Laira Battery, Plymouth			
DESIGNATION:	Scheduled Monument (No. 33052)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Plympton Priory, Plymouth			
DESIGNATION:	Scheduled Monument (No. 24847)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: Stonehouse Manor wall, Plymouth			
DESIGNATION:	Scheduled Monument (No. PY180)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Improving
OWNERSHIP:	Local Authority	CONTACT:	Phil McMahon 0117 975 0699

SITE NAME: The coastal fortifications of Drake's Island, Plymouth			
DESIGNATION:	Scheduled Monument (No. 12614)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Woodland fort, Plymouth		
DESIGNATION:	Scheduled Monument (No. PY843)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Improving
OWNERSHIP:	Local Authority	CONTACT:	Phil McMahon 0117 975 0699

POOLE (UA)

SITE NAME:	Fern Barrow: a bowl barrow on Talbot Heath, Poole		
DESIGNATION:	Scheduled Monument (No. 29594)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Veryan Heal 0117 975 0717

SITE NAME:	Round barrow cemetery on Barrow Hill 150m south west of Brookvale Farm, Poole		
DESIGNATION:	Scheduled Monument (No. 29588)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Veryan Heal 0117 975 0717

SITE NAME:	Evening Hill, Canford Heath, Poole		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Expected to deteriorate
CONTACT:	Warren Lever (LA) 01202 633 331		

SITE NAME:	Haven Road, Canford Cliffs, Poole		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	No significant change expected
CONTACT:	Warren Lever (LA) 01202 633 331		

SITE NAME:	High Street, Town Centre, Poole		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Expected to deteriorate
CONTACT:	Warren Lever (LA) 01202 633 331		

SITE NAME:	Sandbanks, Canford Cliffs, Poole		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Expected to deteriorate
CONTACT:	Warren Lever (LA) 01202 633 331		

SITE NAME:	The Quay, Town Centre, Poole		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	High	TREND:	Expected to show some improvement
CONTACT:	Warren Lever (LA) 01202 633 331		

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SOMERSET

MENDIP



SITE NAME: **Kilmersdon Lodges,
Kilmersdon**

DESIGNATION: Listed Building Grade II*, RPG II*

CONDITION: Very bad

OCCUPANCY: Vacant

PRIORITY: A (A)

OWNERSHIP: Private

Pair of lodges, gate piers and gates, associated with Ammerdown House, 1788-94, and situated on the edge of late C18 to early C19 park. The lodges were ruinous when listed in the 1960s and their potential for reuse is limited by their size. A feasibility study has been undertaken but the scale of the project indicated was prohibitive. Discussions have commenced with estate owners but no solution yet agreed.

Contact: Jenny Chesher 01 17 975 0686



SITE NAME: **Boat House,
Orchardleigh Estate,
Orchardleigh Park, Lullington**

DESIGNATION: Listed Building Grade II*, RPG II*

CONDITION: Very bad


OCCUPANCY: Not applicable

PRIORITY: A (A)

OWNERSHIP: Private

Mid C18 temple boathouse located in the north-east corner of the lake, which is situated to the south of the house within the park. The principle of conversion to ancillary residential use to Orchardleigh House has been agreed but discussions are ongoing with the owner regarding the need for a more flexible use.

Contact: Jenny Chesher 01 17 975 0686



SITE NAME: **Former Anglo-Bavarian Brewery,
Commercial Road,
Shepton Mallet**

DESIGNATION: Listed Building Grade II*

CONDITION: Poor

OCCUPANCY: Part occupied

PRIORITY: C (C)

OWNERSHIP: Company

Brewery, now warehouses, built 1864. Whilst partly occupied at ground floor level, most of the building has been vacant for many years. The condition of the building is deteriorating and suffering from water penetration in places. A feasibility study has been financed through the Shepton Mallet Historic Environment Record scheme and discussions about the beneficial use of the site are ongoing with the owners.

Contact: Jenny Chesher 01 17 975 0686



SITE NAME: **Outbuilding about 30 metres
west of Higher Southtown Farm,
Southtown Lane, West Pennard**

DESIGNATION: Listed Building Grade II*

CONDITION: Very bad

OCCUPANCY: Vacant

PRIORITY: A (New)

OWNERSHIP: Private

Originally early C17 timber framed cottage, now part calf shed/hay store. In very bad condition due to lack of maintenance and beneficial use for many years. Wattle and daub deteriorating, lime render coming away revealing daub and large gaps are appearing in walls. Vegetation causing significant problems to building structure.

Contact: Jenny Chesher 01 17 975 0686

SITE NAME:

Round barrows south west of Cleeve's Plantation, Chewton Mendip

DESIGNATION:

Scheduled Monument (No. SO82)

CONDITION:

Generally satisfactory but with significant localised problems

PRINCIPAL VULNERABILITY:

Forestry

TREND:

Unknown

OWNERSHIP:

Private

CONTACT:

Robert Iles 01 17 9750662

SITE NAME:

Bowl barrow 300m north east of Whitnell Corner, Emborough

DESIGNATION:

Scheduled Monument (No. 22916)

CONDITION:

Extensive significant problems i.e. under plough, collapse

PRINCIPAL VULNERABILITY:

Arable ploughing

TREND:

Declining

OWNERSHIP:

Private

CONTACT:

Robert Iles 01 17 9750662

SITE NAME:

Drying house at The Coach House, Willow Vale, Frome

DESIGNATION:

Scheduled Monument (No. 29684)

CONDITION:

Extensive significant problems i.e. under plough, collapse

PRINCIPAL VULNERABILITY:

Deterioration – in need of management

TREND:

Declining

OWNERSHIP:

Private

CONTACT:

Robert Iles 01 17 9750662

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Glastonbury lake village, Godney			
DESIGNATION:	Scheduled Monument (No. SO406)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

SITE NAME: Vobster Breach colliery, 890m ENE of Tweed Farm, Leigh-on-Mendip			
DESIGNATION:	Scheduled Monument (No. 21659)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

SITE NAME: Lake villages north west of Oxenpill, Meare			
DESIGNATION:	Scheduled Monument (No. SO349)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

SITE NAME: Section of the Abbot's Way trackway, 500m WSW of Honeygar Farm, Meare			
DESIGNATION:	Scheduled Monument (No. 27990)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Robert Iles 0117 9750662

SITE NAME: Sections of the Sweet Track and Post Track, 240m south west of Sunnyside Farm, Meare			
DESIGNATION:	Scheduled Monument (No. 27981)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

SITE NAME: Sections of the Sweet Track and Post Track, 250m ESE of Station House, Meare			
DESIGNATION:	Scheduled Monument (No. 27980)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

SITE NAME: Timber trackway site, 700m west of Honeygar Farm, Meare			
DESIGNATION:	Scheduled Monument (No. 27992)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

SITE NAME: Fussell's Lower Works: an iron edge tool works, 210m south east of Wadbury, Mells			
DESIGNATION:	Scheduled Monument (No. 21695)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

SITE NAME: Whately Combe Roman villa, Nunney			
DESIGNATION:	Scheduled Monument (No. SO282)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Bowl barrow 180m south west of Yoxter Farm, Priddy			
DESIGNATION:	Scheduled Monument (No. 13931)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

SITE NAME: Bowl barrow 250m north east of King Down Farm, Priddy			
DESIGNATION:	Scheduled Monument (No. 13929)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

SITE NAME: Bowl barrow 260m east of Templedown Farm, Priddy			
DESIGNATION:	Scheduled Monument (No. 13936)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

SITE NAME: Bowl barrow 300m south west of Moor View, Priddy			
DESIGNATION:	Scheduled Monument (No. 13830)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

SITE NAME: Bowl barrow 70m north east of King Down Farm, Priddy			
DESIGNATION:	Scheduled Monument (No. 13930)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

SITE NAME: Bowl barrow 800m south of Townsend Farm, Priddy			
DESIGNATION:	Scheduled Monument (No. 13846)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

SITE NAME: Linear barrow cemetery comprising six bowl barrows 510m south west of Townsend Farm, Priddy			
DESIGNATION:	Scheduled Monument (No. 13844)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

SITE NAME: World War II bombing decoy complex, anti-aircraft obstructions and Beacon Batch round barrow cemetery on Black Down, Priddy			
DESIGNATION:	Scheduled Monument (No. 33064)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Bowl barrow 900m south west of Bristol Plain Farm: part of a group of round barrows south and south west of Bristol Plain Farm, Rodney Stoke		
DESIGNATION:	Scheduled Monument (No. 22915)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

SITE NAME:	Romano-British settlement on Stoke Moor, Rodney Stoke		
DESIGNATION:	Scheduled Monument (No. 22809)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

SITE NAME:	Hillfort on Roddenbury Hill, Selwood		
DESIGNATION:	Scheduled Monument (No. 24020)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

SITE NAME:	Group of round barrows 750m north west of Ivy Cottage, St Cuthbert Out		
DESIGNATION:	Scheduled Monument (No. 34870)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

SITE NAME:	Marston Moat, Trudoxhill		
DESIGNATION:	Scheduled Monument (No. 29779)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

SITE NAME:	Babington House, Kilmersdon
DESIGNATION:	Registered Park and Garden Grade II, also 7 LBs
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	High
TREND:	Stable
OWNERSHIP:	Mixed, multiple owners

Landscape of lakes, gardens and parkland surrounding Regency villa. Much recent development in association with use of main house as club-hotel. New build and ancillary development including car park and conversion of kitchen garden ranges. However, encouraging signs of good maintenance e.g. cultivation of walled garden along traditional principles.

Contact: Kim Auston 0117 975 0696

SEDGEMOOR



SITE NAME:	Castle House, Queen Street, Bridgwater
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant
PRIORITY:	A (A)
OWNERSHIP:	Trust

House in early Tudor Revival style, built for William Ackerman in 1851. The building is in a precarious condition. Owned by SAVE Building Preservation Trust. English Heritage has grant-aided scaffolding and project development work. Further discussions regarding grant aid are underway and a potential end use for cultural purposes is under discussion.

Contact: Jenny Chesher 0117 975 0686

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: **Westonzoyland Pumping Station, Westonzoyland**

A former pumping station (early C19) now preserved by the Westonzoyland Engine Trust. The first pumping station to be built to lift floodwater from the Somerset Levels and moors, and the only one to survive with the steam engine still working and the buildings intact. Much work has been done but some of the buildings still require attention.

DESIGNATION: Listed Building Grade II*

CONDITION: Poor

OCCUPANCY: Not applicable

PRIORITY: C (C)

OWNERSHIP: Trust

Contact: Business Manager 01 17 975 0700

SITE NAME: **Bronze Age and Iron Age trackways 600m north east of Northbrook Farm, Ashcott**

DESIGNATION: Scheduled Monument (No. 27986) CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Drainage/dewatering TREND: Declining

OWNERSHIP: Private CONTACT: Robert Iles 01 17 9750662

SITE NAME: **Horsely medieval settlement immediately north of Board's Farm, Bridgwater Without**

DESIGNATION: Scheduled Monument (No. 33729) CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining

OWNERSHIP: Private CONTACT: Robert Iles 01 17 9750662

SITE NAME: **Timber trackways 850m east of Catcott Burtle Farm, Burtle**

DESIGNATION: Scheduled Monument (No. 27991) CONDITION: Unknown

PRINCIPAL VULNERABILITY: Drainage/dewatering TREND: Unknown

OWNERSHIP: Private CONTACT: Robert Iles 01 17 9750662

SITE NAME: **Bowl barrow 300m north east of Tynning's Farm, Cheddar**

DESIGNATION: Scheduled Monument (No. 13876) CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining

OWNERSHIP: Private CONTACT: Robert Iles 01 17 9750662

SITE NAME: **World War II anti-aircraft rocket battery and bombing decoy control building
265m north east of Ashridge Farm, Cheddar**

DESIGNATION: Scheduled Monument (No. 33063) CONDITION: Generally unsatisfactory
with major localised problems

PRINCIPAL VULNERABILITY: Permitted development TREND: Declining

OWNERSHIP: Private CONTACT: Robert Iles 01 17 9750662

SITE NAME: **Bronze Age and Iron Age timber trackways, 700m north west of Coppice Gate Farm, Shapwick**

DESIGNATION: Scheduled Monument (No. 27989) CONDITION: Unknown

PRINCIPAL VULNERABILITY: Drainage/dewatering TREND: Unknown

OWNERSHIP: Private CONTACT: Robert Iles 01 17 9750662

SITE NAME: **Sections of the Sweet Track, the Post Track and associated remains
500m north east of Moorgate Farm, Shapwick**

DESIGNATION: Scheduled Monument (No. 27978) CONDITION: Generally satisfactory
but with minor localised problems

PRINCIPAL VULNERABILITY: Drainage/dewatering TREND: Declining

OWNERSHIP: Private CONTACT: Robert Iles 01 17 9750662

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA Conservation Area
LB/LBs Listed Building/s
NP National Park
RPG Registered Park and Garden
SM/SMs Scheduled Monument/s
UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Prehistoric timber trackways, 670m SSE of Parchey Bridge, Stawell		
DESIGNATION:	Scheduled Monument (No. 27987)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Unknown
OWNERSHIP:	Government or Agency	CONTACT:	Robert Iles 01 17 9750662

SITE NAME:	Alstone lake settlement site, West Huntspill		
DESIGNATION:	Scheduled Monument (No. 10504)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Robert Iles 01 17 9750662



SITE NAME:	Halswell Park, Goathurst
DESIGNATION:	Registered Park and Garden Grade II, also 17 LBs
CONDITION:	Extensive significant problems
VULNERABILITY:	Medium
TREND:	Stable
OWNERSHIP:	Mixed, multiple owners

An C18 landscape park. Local preservation trusts have instigated the restoration and maintenance of two important garden buildings. Other structures are still at risk. The main house is run as a commercial venue. The majority of the park is under intensive cultivation. The centrepiece of the design, Mill Wood, is largely denuded of trees and the structures within it are in a very poor state of repair.

Contact: Kim Auston 01 17 975 0696

SOUTH SOMERSET



SITE NAME:	The Grotto at Jordans, NGR ST 3388 1601, Ashill
DESIGNATION:	Listed Building Grade II*
CONDITION:	Poor
OCCUPANCY:	Not applicable
PRIORITY:	C (New)
OWNERSHIP:	Private

Early C19 grotto within a designed landscape whose principle house was demolished in the mid C20. The thatched roof is in a poor state of repair and the building has been subject to vandalism. The owners are currently in discussion regarding possible sources of grant aid.

Contact: Jenny Chesher 01 17 975 0686



SITE NAME:	Manning chest tomb, churchyard of St John the Baptist, Charcroft Hill, Brewham
DESIGNATION:	Listed Building Grade II*
CONDITION:	Very bad
OCCUPANCY:	Not applicable
PRIORITY:	A (A)
OWNERSHIP:	Religious organisation

Chest tomb dated 1618 commemorating William and Margaret Manning. Partially collapsed, surface decay of Douling Stone carving, invasive vegetation growth.

Contact: Jenny Chesher 01 17 975 0686



SITE NAME:	Dovecote about 370 metres south of Bruton Church, Park Wall, Bruton
DESIGNATION:	Listed Building Grade II*, SM, CA
CONDITION:	Poor
OCCUPANCY:	Not applicable
PRIORITY:	C (New)
OWNERSHIP:	Charity

This three storey square tower is situated just south of Bruton, probably within precinct of Bruton Priory. It may have been a late priory structure or a prospect tower of the Berkeley family who lived at the Bruton Priory. It was later crudely converted for use as a dovecote and survives as a roofless ruin. In need of repair, consolidation and protection from vandalism.

Contact: Rob Iles 01 17 975 0662



SITE NAME:	The Towers, Redlynch, Bruton
DESIGNATION:	Listed Building Grade II*
CONDITION:	Poor
OCCUPANCY:	Not applicable
PRIORITY:	C (C)
OWNERSHIP:	Private

Late C18 monumental gateway in Gothic style. This gateway is now 'redundant' as the main farm access has been diverted via a new entrance. Underpinning has been carried out but comprehensive repairs to the building are still awaited.

Contact: Jenny Chesher 01 17 975 0686

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

	<p>SITE NAME: Cosenes monument, Church of All Saints, Church Street, Castle Cary</p> <p>DESIGNATION: Listed Building Grade II*, CA</p> <p>CONDITION: Very bad</p> <p>OCCUPANCY: Not applicable</p> <p>PRIORITY: A (B)</p> <p>OWNERSHIP: Religious organisation</p>	<p>Late C16 monument. Rusting iron cramps have caused serious damage and threaten further loss of stone.</p> <p>Contact: Jenny Chesher 01 17 975 0686</p>
	<p>SITE NAME: Top mill building, Higher Flax Mills, Torbay Road, Castle Cary</p> <p>DESIGNATION: Listed Building Grade II*, CA</p> <p>CONDITION: Poor</p> <p>OCCUPANCY: Vacant</p> <p>PRIORITY: B (B)</p> <p>OWNERSHIP: Private</p>	<p>This mid C19 former mill has been empty for several years. Planning permission and listed building consent have been granted for two live-work units. The building has been on the market for over a year and there have been a number of prospective purchasers in discussion with the planning authority.</p> <p>Contact: Jenny Chesher 01 17 975 0686</p>
	<p>SITE NAME: Waterloo House and Manor Court House, 7A, 7B, 9, 11, 13 and 13A Fore Street, Chard, Chard Town</p> <p>DESIGNATION: Listed Building Grade I</p> <p>CONDITION: Poor</p> <p>OCCUPANCY: Part occupied</p> <p>PRIORITY: C (New)</p> <p>OWNERSHIP: Company</p>	<p>Late C16/early C17 group of shops/offices, houses and flats with two prominent projecting two and three storey porches. Partly occupied with consent for conversion to part of building granted but not yet implemented. No solution agreed to some other upper floor areas or first floor Courtroom. Retail premises part is un-let.</p> <p>Contact: Jenny Chesher 01 17 975 0686</p>
	<p>SITE NAME: Thorne chest tomb, churchyard of Church of St Lawrence, Cucklington</p> <p>DESIGNATION: Listed Building Grade II*</p> <p>CONDITION: Poor</p> <p>OCCUPANCY: Not applicable</p> <p>PRIORITY: C (B)</p> <p>OWNERSHIP: Religious organisation</p>	<p>Early C17 chest tomb, partially collapsed and heavily overgrown by ivy.</p> <p>Contact: Jenny Chesher 01 17 975 0686</p>
	<p>SITE NAME: Madey Mill, East Street, Martock</p> <p>DESIGNATION: Listed Building Grade II*</p> <p>CONDITION: Poor</p> <p>OCCUPANCY: Part occupied</p> <p>PRIORITY: C (C)</p> <p>OWNERSHIP: Private</p>	<p>Water mill with medieval origins, although current buildings are largely C17. The building is situated on a working farm, is under-used and is suffering from lack of maintenance. Viable new uses and/or funding opportunities need to be investigated to obtain adequate funding for repairs. English Heritage is currently funding a condition survey to establish the likely extent and cost of repairs.</p> <p>Contact: Jenny Chesher 01 17 975 0686</p>
	<p>SITE NAME: Prankerd chest tomb in churchyard 7m south east of south door, St John the Evangelist, Bathwell Lane, Milborne Port</p> <p>DESIGNATION: Listed Building Grade II*, CA</p> <p>CONDITION: Poor</p> <p>OCCUPANCY: Not applicable</p> <p>PRIORITY: B (B)</p> <p>OWNERSHIP: Religious organisation</p>	<p>Early C17 chest tomb. Subsidence at the northern end is causing structural instability. Rusting iron cramps threaten further damage. Surface deterioration of the south panel threatens further loss of the inscription.</p> <p>Contact: Jenny Chesher 01 17 975 0686</p>

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME: **Secular college at Parsonage Farm, Stoke Sub Hamdon**

Attached to this chantry college is a group of medieval and C16 farm buildings most of which are in poor condition and unroofed.

DESIGNATION: Listed Building Grade II, SM, CA

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: C (New)

OWNERSHIP: Charity

Contact: Rob Iles 0117 975 0662



SITE NAME: **Two monuments in churchyard, approx 6 and 8 metres S of S transept, St Mary the Virgin, East Stoke, Stoke Sub Hamdon**

Mid C17 monument. Subsidence has resulted in rising damp threatening the inscriptions, through increased salt crystallisation in the ledger slabs.

DESIGNATION: Listed Building Grade II*, CA

CONDITION: Poor

OCCUPANCY: Not applicable

PRIORITY: A (B)

OWNERSHIP: Religious organisation

Contact: Jenny Chesher 0117 975 0686



SITE NAME: **The former Ropewalk, 75 metres north east of Millbrook House, High Street, West Coker**

Former twine works, now store and workshop. Late C19, with C20 alterations and extensions. Following compulsory purchase of the site by the District Council a lease has been taken on the building by the Industrial Building Preservation Trust. A grant has been given by English Heritage for urgent repairs and supporting scaffolding has been erected whilst funding applications for its long-term use are prepared.

DESIGNATION: Listed Building Grade II*

CONDITION: Very bad

OCCUPANCY: Vacant

PRIORITY: A (A)

OWNERSHIP: Trust

Contact: Jenny Chesher 0117 975 0686



SITE NAME: **Balsam House, Common Road, Wincanton**

House dating from late C16 or early C17. Following refusal of permission for subdivision of the house at appeal, it has been sold to new owners who have commenced renovations and intend to occupy it as a family home.

DESIGNATION: Listed Building Grade II*

CONDITION: Poor

OCCUPANCY: Occupied

PRIORITY: F (C)

OWNERSHIP: Private

Contact: Jenny Chesher 0117 975 0686

SITE NAME: **Roman house south of Fair View House, Curry Rivel**

DESIGNATION:	Scheduled Monument (No. SO278)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

SITE NAME: **Roman villa north of Dunnock's Lane, East Coker**

DESIGNATION:	Scheduled Monument (No. SO279)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

SITE NAME: **Low Ham Roman villa, High Ham**

DESIGNATION:	Scheduled Monument (No. SO213)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Pill Bridge, Ilchester		
DESIGNATION:	Scheduled Monument (No. SO186)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Robert Iles 0117 9750662

SITE NAME:	Roman villa north of Stowey Hill, Pitney		
DESIGNATION:	Scheduled Monument (No. SO275)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

SITE NAME:	Melbury Roman villa, Somerton		
DESIGNATION:	Scheduled Monument (No. SO232)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

SITE NAME:	Large multivallate hillfort and associated earthworks at South Cadbury, South Cadbury		
DESIGNATION:	Scheduled Monument (No. 22904)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

SITE NAME:	Chessels Roman villa, West Coker		
DESIGNATION:	Scheduled Monument (No. SO280)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662



SITE NAME:	Redlynch Park, Bruton
DESIGNATION:	Registered Park and Garden Grade II*, also 9 LBs
CONDITION:	Extensive significant problems
VULNERABILITY:	Medium
TREND:	Stable
OWNERSHIP:	Private, multiple owners

Formerly the principal seat of the earls of Ilchester, Redlynch is a large landscape park near Wincanton. The main house has gone and the stables and ancillary buildings are now in multiple ownership. The majority of the parkland planting has disappeared, boundary walls and estate railings are in a poor state and there are ongoing development pressures. A surviving gatehouse is a building at risk.

Contact: Kim Auston 0117 975 0696



SITE NAME:	Cricket House, Cricket St Thomas
DESIGNATION:	Registered Park and Garden Grade II*, also 8 LBs
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	High
TREND:	Stable
OWNERSHIP:	Mixed, multiple owners

C18 landscape park and pleasure grounds surrounding listed mansion, partly by Soane. Heavy pressure for development from safari park, large hotel and farm diversification. However, parts of the park restored through the Environmental Stewardship Scheme.

Contact: Kim Auston 0117 975 0696

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	Hazlegrove House, Queen Camel
DESIGNATION:	Registered Park and Garden Grade II, also 3 LBs
CONDITION:	Generally satisfactory but with minor localised problems
VULNERABILITY:	Medium
TREND:	Stable
OWNERSHIP:	Mixed, multiple owners

C18 landscape park with formal garden in front of house. Avenues and veteran parkland trees survive, with some replanting. Area close to house subject to development for a range of school facilities. Sports pitches encroaching into parkland. Park bisected by main road in 1980s, severing lodge and drive.

Contact: Kim Auston 0117 975 0696

SITE NAME:	Donyatt	CONDITION:	Very bad
DESIGNATION:	Conservation Area	TREND:	No significant change expected
VULNERABILITY:	Medium	CONTACT:	Adron Duckworth (LA) 01935 462595

SITE NAME:	Henstridge	CONDITION:	Very bad
DESIGNATION:	Conservation Area	TREND:	No significant change expected
VULNERABILITY:	Medium	CONTACT:	Adron Duckworth (LA) 01935 462595

SITE NAME:	Ilchester	CONDITION:	Very bad
DESIGNATION:	Conservation Area	TREND:	No significant change expected
VULNERABILITY:	Medium	CONTACT:	Adron Duckworth (LA) 01935 462595

SITE NAME:	Misterton	CONDITION:	At risk
DESIGNATION:	Conservation Area	TREND:	Deteriorating
VULNERABILITY:	Unknown	CONTACT:	Greg Venn (LA) 01935 462595

TAUNTON DEANE



SITE NAME:	Sandhill Park, Bishops Lydeard
DESIGNATION:	Listed Building Grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant
PRIORITY:	D (D)
OWNERSHIP:	Private

Country house, circa 1720. Later used as a hospital, now unoccupied. A new use is required for the house and associated outbuildings. A revised application for conversion of the house to apartments and the construction of enabling development in its grounds has now been approved but work has not yet commenced. The property is now being marketed by Knight Frank.

Contact: Jenny Chesher 0117 975 0686

SITE NAME:	Gatehouse at Cothelstone Manor, Cothelstone
DESIGNATION:	Listed Building Grade I, CA, RPG II
CONDITION:	Poor
OCCUPANCY:	Not applicable
PRIORITY:	D (D)
OWNERSHIP:	Private

A mid C16 gatehouse. Part of a much larger estate. Urgent holding repairs undertaken. Consent has been granted for use as holiday let with associated repairs, but this has not yet been implemented. The owners have contacted English Heritage regarding potential grant aid.

Contact: Jenny Chesher 0117 975 0686

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	Cloth finishing works at Tone Mills, north range, Langford Budville
DESIGNATION:	Listed Building Grade II*
CONDITION:	Poor
OCCUPANCY:	Not applicable
PRIORITY:	A (C)
OWNERSHIP:	Private

A near-complete example of a C19 cloth dyeing and finishing works which developed between c1830 and c1920. An application for new development is being prepared for adjoining grease works site with the intention of facilitating the transfer of ownership to a dedicated building preservation trust which is currently investigating options. The LPA has recently served an UWN on part of the building with EH grant aid.

Contact: Jenny Chesher 0117 975 0686



SITE NAME:	Tonedale Mills (west complex), Wellington
DESIGNATION:	Listed Building Grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied
PRIORITY:	A (C)
OWNERSHIP:	Private

Western complex of an integrated multi-component wool textile factory, now in partial use as small industrial estate. Consent granted for mixed use redevelopment of the complex. Works halted on site in 2008 leaving some buildings in a very vulnerable condition. The site was taken into receivership and a meeting has been held between the Administrator, TDBC and EH to establish way forward but no solution agreed.

Contact: Jenny Chesher 0117 975 0686

SITE NAME: **Two groups of World War II pillboxes in the north eastern and north western sectors of the former airfield of RAF Culmhead, Trickey Warren, Churchstanton**

DESIGNATION:	Scheduled Monument (No. 33030)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

SITE NAME: **Two World War II air traffic control buildings, 620m west and 560m WSW of Whitewall Corner, on the former airfield of RAF Culmhead, Trickey Warren, Churchstanton**

DESIGNATION:	Scheduled Monument (No. 33029)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

SITE NAME: **World War II fighter pens and other airfield remains and defences of the former airfield of RAF Culmhead, at Trickey Warren Farm, Churchstanton**

DESIGNATION:	Scheduled Monument (No. 33028)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

SITE NAME: **Norton Camp large univallate hillfort, Norton Fitzwarren**

DESIGNATION:	Scheduled Monument (No. 24022)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

SITE NAME: **Camp south of Manor Farm, Wiveliscombe**

DESIGNATION:	Scheduled Monument (No. SO329)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

WEST SOMERSET



SITE NAME: **Remains of Chantry at Kilve, Sea Lane, Kilve**

Early C14, with later medieval additions. Formerly believed to be the remains of collegiate dwelling of chantry priests, a recent English Heritage survey has shown that the ruins are part of an important manorial complex. Emergency repairs are still awaited.

DESIGNATION: Listed Building Grade II*, SM

CONDITION: Very bad

OCCUPANCY: Not applicable

PRIORITY: A (A)

OWNERSHIP: Private

Contact: Rob Iles 0117 975 0662

SITE NAME: **Clatworthy hillfort, Clatworthy**

DESIGNATION: Scheduled Monument (No. SO435)

CONDITION: Generally satisfactory but with significant localised problems

PRINCIPAL VULNERABILITY: Scrub / tree growth

TREND: Declining

OWNERSHIP: Private

CONTACT: Robert Iles 0117 9750662

SITE NAME: **Four cairns on Hurley Beacon, Crowcombe**

DESIGNATION: Scheduled Monument (No. 32184)

CONDITION: Generally satisfactory but with significant localised problems

PRINCIPAL VULNERABILITY: Other

TREND: Declining

OWNERSHIP: Private

CONTACT: Robert Iles 0117 9750662

SITE NAME: **Cow Castle, Exmoor**

DESIGNATION: Scheduled Monument (No. SO341)

CONDITION: Generally satisfactory but with significant localised problems

PRINCIPAL VULNERABILITY: Scrub / tree growth

TREND: Declining

OWNERSHIP: Private

CONTACT: Robert Iles 0117 9750662

SITE NAME: **Entrenchment on Heydon Hill, Huish Champflower**

DESIGNATION: Scheduled Monument (No. SO254)

CONDITION: Generally satisfactory but with significant localised problems

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNERSHIP: Private

CONTACT: Robert Iles 0117 9750662

SITE NAME: **Iron Age defended settlement above Sweetworthy (eastern of two), Luccombe**

DESIGNATION: Scheduled Monument (No. 24029)

CONDITION: Generally unsatisfactory with major localised problems

PRINCIPAL VULNERABILITY: Scrub / tree growth

TREND: Declining

OWNERSHIP: Private

CONTACT: Robert Iles 0117 9750662

SITE NAME: **Iron Age defended settlement above Sweetworthy (western of two), Luccombe**

DESIGNATION: Scheduled Monument (No. 24030)

CONDITION: Generally unsatisfactory with major localised problems

PRINCIPAL VULNERABILITY: Scrub / tree growth

TREND: Declining

OWNERSHIP: Private

CONTACT: Robert Iles 0117 9750662

SITE NAME: **Sweetworthy deserted medieval settlement, Luccombe**

DESIGNATION: Scheduled Monument (No. 24027)

CONDITION: Generally satisfactory but with significant localised problems

PRINCIPAL VULNERABILITY: Moderate animal burrowing

TREND: Declining

OWNERSHIP: Private

CONTACT: Robert Iles 0117 9750662

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
 If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	West Luccombe packhorse bridge, Luccombe		
DESIGNATION:	Scheduled Monument (No. SO29)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

SITE NAME:	Four medieval fish weirs 500m east of the Harbour, Minehead		
DESIGNATION:	Scheduled Monument (No. 33730)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

SITE NAME:	Iron Age defended settlement, Furzebury Brake, Minehead Without		
DESIGNATION:	Scheduled Monument (No. 24031)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

SITE NAME:	Stone circle, Porlock Common, Porlock		
DESIGNATION:	Scheduled Monument (No. SO201)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

SITE NAME:	Allerford New Bridge, Selworthy		
DESIGNATION:	Scheduled Monument (No. SO230)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate vehicle damage/erosion	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Robert Iles 0117 9750662

SITE NAME:	Stringston churchyard cross, Stringston		
DESIGNATION:	Scheduled Monument (No. SO250)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

SITE NAME:	Staddon Hill camp, Winsford		
DESIGNATION:	Scheduled Monument (No. 35977)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

SITE NAME:	Brightworthy Barrows on Withypool Common, Withypool and Hawkridge		
DESIGNATION:	Scheduled Monument (No. 35973)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Robert Iles 0117 9750662

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	St Audries (House), West Quantoxhead	C19 gardens and pleasure grounds, surrounding a C19 mansion, together with parkland developed from the mid C18 and improved in the mid C19. St Audries has had a succession of institutional uses and there are derelict former school buildings in the walled garden. The parkland is mostly cultivated and few parkland trees survive. Currently St Audries house and gardens are used as a wedding venue.
DESIGNATION:	Registered Park and Garden Grade II, also 16 LBs	
CONDITION:	Generally unsatisfactory with major localised problems	
VULNERABILITY:	Medium	
TREND:	Stable	
OWNERSHIP:	Mixed, multiple owners	

SOUTH GLOUCESTERSHIRE (UA)



SITE NAME:	Monument to Lord Robert Edward Somerset, Hawkesbury	A tall tapering stone tower ashlar monument by Lewis Vulliamy dated 1846. Repairs needed at high-level to cast iron balcony and stonework. The council is continuing discussions with the owners to secure repairs to the monument.
DESIGNATION:	Listed Building Grade II*, CA	
CONDITION:	Poor	
OCCUPANCY:	Not applicable	
PRIORITY:	C (C)	
OWNERSHIP:	Private	



SITE NAME:	Ragged Castle or Keeper's Lodge, Badminton Park, Hawkesbury	Folly Castle. Set on motte at end of a main drive from Badminton House. Circa 1750 by Thomas Wright of Durham. Largely hidden by trees, ruinous and dilapidated. No roof and the floors have collapsed. The council is in discussion with the owners regarding the repair and stabilisation of the walls.
DESIGNATION:	Listed Building Grade II*	
CONDITION:	Poor	
OCCUPANCY:	Vacant	
PRIORITY:	C (C)	
OWNERSHIP:	Private	



SITE NAME:	Whitfields Tabernacle, Park Road, Kingswood	Chapel built in 1741. The building has been redundant for many years and a fire has placed the building in an even more vulnerable position. The owners have recently withdrawn their application for redevelopment of the site and a revised application is likely to be submitted mid 2010.
DESIGNATION:	Listed Building Grade I, CA	
CONDITION:	Very bad	
OCCUPANCY:	Vacant	
PRIORITY:	A (A)	
OWNERSHIP:	Private	



SITE NAME:	Brandy Bottom Colliery, Pucklechurch	A former C19 steam-powered colliery built on the site of an C18 colliery. The above-ground remains include a weighbridge, chimney, engine house, workshop, heapstead, boiler house and a Cornish beam engine house, fan house and a horizontal-winding engine house. The Avon Industrial Buildings Trust now have a licence from the owner to work on the site and a condition survey and conservation plan is underway.
DESIGNATION:	Scheduled Monument	
CONDITION:	Very bad	
OCCUPANCY:	Not applicable	
PRIORITY:	C (C)	
OWNERSHIP:	Company	



SITE NAME:	Coach House and stables north east of Oxwick Farmhouse, Oxwick Lane, Yate, Wickwar	Coach house and stables, built 1722 in a mannered provincial baroque. Roof sections/tiles are missing and the stairs in the main section have almost totally collapsed; flooring missing in parts. The farm has recently changed hands and negotiations have begun with a new owner.
DESIGNATION:	Listed Building Grade II*	
CONDITION:	Very bad	
OCCUPANCY:	Not applicable	
PRIORITY:	A (A)	
OWNERSHIP:	Private	

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	Oxwick Farmhouse, Oxwick Lane, Yate, Wickwar
DESIGNATION:	Listed Building Grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied
PRIORITY:	C (C)
OWNERSHIP:	Private

Farmhouse dated 1722, in flamboyant artisan mannerist/baroque style. Part Occupied. Vacant part has serious decay of floor structures and in areas is unsafe, but emergency repairs have commenced. The farm has recently changed hands and negotiations have begun with the new owner.

Contact: Justin Ayton 0117 975 0687

SITE NAME: **Round barrow on Barrow Hill, Bitton**

DESIGNATION:	Scheduled Monument (No. SG165)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME: **Roman villa at Cromhall north west of Tapwell Bridge, Cromhall**

DESIGNATION:	Scheduled Monument (No. SG178)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME: **Starveall long barrow, Hawkesbury**

DESIGNATION:	Scheduled Monument (No. SG42)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300

SITE NAME: **Hillfort and associated Romano-British occupation at Little Abbey, Alveston, Thornbury**

DESIGNATION:	Scheduled Monument (No. I2007)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Melanie Barge 0117 9751300



SITE NAME:	Stoke Park, Stoke Gifford
DESIGNATION:	Registered Park and Garden Grade II, also CA, 11 LBs, 1 SM
CONDITION:	Extensive significant problems
VULNERABILITY:	Medium
TREND:	Stable
OWNERSHIP:	Mixed, multiple owners

Dramatic location on a hill on the north side of Bristol. Mid C18 park laid out around crenellated Dower House. Park embellished by monuments and eye catchers. Now bisected by the M32 motorway. Setting compromised by dense residential development. Park under pressure from heavy and occasionally anti-social use.

Contact: Kim Auston 0117 975 0696

SITE NAME: **Warmley, Siston**

DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	No significant change expected
CONTACT:	Rebecca Anthony (LA) 01454 863465		

SITE NAME: **Whitfield Tabernacle, Kingswood**

DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Unknown
CONTACT:	Rebecca Anthony (LA) 01454 863465		

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SWINDON (UA)



SITE NAME: **The Mechanics Institute,
Emlyn Square,
Swindon**

DESIGNATION: Listed Building Grade II*, CA

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: A (A)

OWNERSHIP: Company

Mechanics Institute, 1853-1855; now vacant. Outstanding example at heart of railway village. End use limited by fine internal features, including a large lecture theatre. Sold in 2003 and discussions are continuing regarding the future of the building. Repairs to the southern part of the roof have been undertaken. The council served an Urgent Works Notice on the owner in 2009.

Contact: Isla Macneal 0117 975 0742



SITE NAME: **Chain Test House,
Rodbourne Road,
Swindon**

DESIGNATION: Listed Building Grade II*, CA

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: D (C)

OWNERSHIP: Company

A rare example of a railway chain testing house, 1873. Building currently vacant and in poor condition. Now part of application for mixed use development.

Contact: Isla Macneal 0117 975 0742

SITE NAME:	Bowl barrow 280m north of Downs Barn, Bishopstone		
DESIGNATION:	Scheduled Monument (No. 12329)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Veryan Heal 0117 975 0717

SITE NAME:	Bowl barrow on Hinton Downs, Bishopstone		
DESIGNATION:	Scheduled Monument (No. 12318)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Veryan Heal 0117 975 0717

SITE NAME:	Roman villa 630m south west of Starveall Farm, Bishopstone		
DESIGNATION:	Scheduled Monument (No. 28957)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Veryan Heal 0117 975 0717

SITE NAME:	Site of Roman town, west of Wanborough House, Covingham		
DESIGNATION:	Scheduled Monument (No. SW888)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Veryan Heal 0117 975 0717

SITE NAME:	Four Highworth circles 150m north east of Pickett's Copse, Highworth		
DESIGNATION:	Scheduled Monument (No. 28969)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Veryan Heal 0117 975 0717

SITE NAME:	Highworth circle 520m north west of North Leaze Farm, Highworth		
DESIGNATION:	Scheduled Monument (No. 28953)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Veryan Heal 0117 975 0717

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Three Highworth circles 600m east of North Leaze Farm, Highworth		
DESIGNATION:	Scheduled Monument (No. 28973)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Veryan Heal 0117 975 0717

SITE NAME:	Liddington Castle, Liddington		
DESIGNATION:	Scheduled Monument (No. 28964)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Veryan Heal 0117 975 0717

SITE NAME:	Long barrow 700m north of Liddington Warren Farm, Liddington		
DESIGNATION:	Scheduled Monument (No. 12281)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Veryan Heal 0117 975 0717

SITE NAME:	Remains of Holy Rood Church, The Lawn, Old Town, Swindon		
DESIGNATION:	Scheduled Monument (No. 28952)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Veryan Heal 0117 975 0717

SITE NAME:	Bowl barrow 150m north of Half Moon Wood, Wanborough		
DESIGNATION:	Scheduled Monument (No. 12284)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Veryan Heal 0117 975 0717

SITE NAME:	Bowl barrow 850m north west of North Farm, Wanborough		
DESIGNATION:	Scheduled Monument (No. 28947)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Veryan Heal 0117 975 0717

TORBAY (UA)



SITE NAME:	Lupton House (Gramercy Hall School), Brixham
DESIGNATION:	Listed Building Grade II*, RPG II*
CONDITION:	Poor
OCCUPANCY:	Part occupied
PRIORITY:	D (New)
OWNERSHIP:	Trust

C18 and C19 country house remodelled by G Wightwick c1840, with extensive ancillary buildings and fine Italianate Garden. Altered after a fire in 1928. In use as school from mid C20 to 2004. The house was empty and its condition deteriorating until 2009 when it was acquired by a charitable trust with the aim of using it for a wide range of community activities. Much of the roof is in poor condition and leaking.

Contact: Business Manager 0117 975 0700

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
 If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME: **Torbay Cinema,
Torbay Road,
Paignton**

DESIGNATION: Listed Building Grade II*
CONDITION: Fair
OCCUPANCY: Vacant
PRIORITY: C (C)
OWNERSHIP: Company

Cinema, licensed in 1912. An extremely well preserved example of an early purpose-built cinema. The building has been vacant for 10 years. Torbay Council has served a repairs notice, much of which was implemented in March 2007. Owner seeking to adapt interior for ticketing and restaurant.

Contact: Simon Ramsden 01 17 975 0676



SITE NAME: **Ilisham Manor Oratory,
Ilisham Road,
Ilisham, Torquay**

DESIGNATION: Listed Building Grade II*
CONDITION: Poor
OCCUPANCY: Vacant
PRIORITY: A (A)
OWNERSHIP: Educational Body

Oratory, part of the demolished medieval Ilisham Manor. Neglected and in poor condition, the chapel has no current use.

Contact: Simon Ramsden 01 17 975 0676

SITE NAME: Ashhole Cavern, Torbay	
DESIGNATION: Scheduled Monument (No. 33026)	CONDITION: Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY: Vandalism	TREND: Declining
OWNERSHIP: Private	CONTACT: Phil McMahon 01 17 975 0699

SITE NAME: Prehistoric field system at Walls Hill, Torbay	
DESIGNATION: Scheduled Monument (No. 33027)	CONDITION: Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY: Moderate visitor erosion	TREND: Declining
OWNERSHIP: Local Authority	CONTACT: Phil McMahon 01 17 975 0699

SITE NAME: St Michael's Chapel, Chapel Hill, Torbay	
DESIGNATION: Scheduled Monument (No. 33024)	CONDITION: Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY: Collapse	TREND: Stable
OWNERSHIP: Local Authority	CONTACT: Phil McMahon 01 17 975 0699

SITE NAME: The Bishop's Palace, Tower Road, Torbay	
DESIGNATION: Scheduled Monument (No. 33048)	CONDITION: Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY: Plant growth	TREND: Improving
OWNERSHIP: Local Authority	CONTACT: Phil McMahon 01 17 975 0699

SITE NAME: Brixham Town, Berry Head with Furzeham, Brixham	
DESIGNATION: Conservation Area	CONDITION: Very bad
VULNERABILITY: Low	TREND: No significant change expected
CONTACT: Hal Bishop (LA) 01803 207787	

SITE NAME: Torquay Harbour, Torquay	
DESIGNATION: Conservation Area	CONDITION: Very bad
VULNERABILITY: Low	TREND: Expected to show some improvement
CONTACT: Hal Bishop (LA) 01803 207787	

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Torre, Torquay		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Expected to show some improvement
CONTACT:	Hal Bishop (LA) 01803 207787		

WILTSHIRE (UA)

SITE NAME: **Gay's Cave and Diamond (Amesbury Abbey), Amesbury**

DESIGNATION: Listed Building Grade II*, WHS, CA, RPG II*

CONDITION: Fair

OCCUPANCY: Not applicable

PRIORITY: C (C)

OWNERSHIP: Private

Gay's Cave or Seat, circa 1734-38, with gateway and wrought iron gates, attributed to Henry Flitcroft, and situated on the axis of Amesbury Abbey and tumulus beyond the River Avon. Some of the shrubbery has been cleared; however, the Diamond pattern paths are overgrown and unrecognisable. One gate has been removed from the Grotto and it is suffering from vandalism and neglect.

Contact: Isla Macneal 0117 975 0742



SITE NAME: **Rudloe Manor, Box**

DESIGNATION: Listed Building Grade II*, CA

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: B (New)

OWNERSHIP: Company

Late C17 manor house surrounded by ancillary buildings including a grade II listed barn. The house was part of a larger MOD site which was vacated in 1998. The house has remained vacant. The current owners have drawn up a residential scheme with enabling development and the proposals are awaiting planning approval.

Contact: Isla Macneal 0117 975 0742



SITE NAME: **Buildings to the rear of the Lansdowne Hotel, The Strand, Calne**

DESIGNATION: Listed Building Grade II*, CA

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNERSHIP: Private

Former coach house, stable and brewhouse to rear of Lansdowne Arms Hotel. Buildings range from mid C17 to mid C19. Condition of roofs and coverings are continuing to degenerate leading to further internal decay. Urgent works notices have previously been complied with; however, the condition of these buildings continues to decline. The property has new owners who have indicated an intent to use the buildings.

Contact: Isla Macneal 0117 975 0742



SITE NAME: **Clarendon House, Clarendon Park**

DESIGNATION: Listed Building Grade I

CONDITION: Fair

OCCUPANCY: Vacant

PRIORITY: F (D)

OWNERSHIP: Private

Large house dating from 1717-37; later wings demolished. House has been vacant for some time. Work is underway to repair and convert to a single family house. It is anticipated that works will be complete by December 2010.

Contact: Isla Macneal 0117 975 0742



SITE NAME: **Former hangar at Yatesbury Airfield, Cherhill, Compton Bassett**

DESIGNATION: Listed Building Grade II*, CA

CONDITION: Very bad

OCCUPANCY: Vacant

PRIORITY: A (A)

OWNERSHIP: Private

Former aircraft hangar, built circa 1917 as part of a training centre. One of a group of three hangars at Yatesbury which are among the earliest surviving hangars from the first years of military flying. Repair of the hangars was progressing in association with enabling development proposals. However, work has stopped on site. This hangar has deteriorated dramatically in the last year.

Contact: Isla Macneal 0117 975 0742



SITE NAME: **Two former hangars at Yatesbury Airfield, Cherhill, Compton Bassett**

DESIGNATION: Listed Building Grade II*, CA

CONDITION: Very bad

OCCUPANCY: Part occupied

PRIORITY: A (A)

OWNERSHIP: Private

Two aircraft hangars, built circa 1917 as part of a training centre. Two of a group of three hangars from the first years of military flying. One hangar has been partially repaired and the owner has been served with an Urgent Works Notice to arrest further decline of the condition of the other hangar.

Contact: Isla Macneal 0117 975 0742

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA Conservation Area
LB/LBs Listed Building/s
NP National Park
RPG Registered Park and Garden
SM/SMs Scheduled Monument/s
UA Unitary Authority
WHS World Heritage Site



SITE NAME: **Devizes Castle,
Devizes**

DESIGNATION: Listed Building Grade I, SM

CONDITION: Very bad

OCCUPANCY: Not applicable

PRIORITY: A (A)

OWNERSHIP: Private

Grade I house, 1842, sited on top of a Norman motte and encircling moat. Site included on the register because of the precarious condition of the motte, though the Victorian house is occupied and in fair condition. Failure of the motte has resulted in cracking of the upper Victorian wall and could have a deleterious effect on the remains of the Orangery of Devizes Castle.

Contact: Shane Gould 0117 975 0671



SITE NAME: **Garden pavilion to the south east
of Hillworth House,
Hillworth Road, Devizes**

DESIGNATION: Listed Building Grade II*

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: D (D)

OWNERSHIP: Local authority

Attractive brick structure located in what is now a public park. External sheeting applied to windows has reduced breathability and windows are beginning to rot. Minor stone defects are apparent and external ground conditions are poor due to absence of rainwater disposal system. The Town Council has drawn up a scheme for repair in association with works to the park and £1.2m of funding has been offered by HLF.

Contact: Isla Macneal 0117 975 0742



SITE NAME: **Former Law Courts
and County Police Station,
Northgate Street, Devizes**

DESIGNATION: Listed Building Grade II*, CA

CONDITION: Very bad

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNERSHIP: Company

Law courts and police station, 1835. Wind and weathertight. Interior has been gutted. Several schemes have been granted consent, including residential use and a nightclub, but none have ever been implemented. Temporary repairs carried out as a consequence of Urgent Works Notice. Further Urgent Works Notice served 2003 but vandalism remains a constant threat. A feasibility study has been undertaken.

Contact: Isla Macneal 0117 975 0742



SITE NAME: **Stable block to Tottenham House,
Great Bedwyn**

DESIGNATION: Listed Building Grade II*, RPG II*

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: B (B)

OWNERSHIP: Private

Impressive stable block of 1818, by Thomas Cundy, located 150 metres north-north-west of Tottenham House. Consent for conversion to residential use granted early 1990s but not implemented. Consent has been granted for conversion into a spa, in association with a hotel in the main house. The condition of the building is declining.

Contact: Isla Macneal 0117 975 0742



SITE NAME: **Tottenham House,
Great Bedwyn**

DESIGNATION: Listed Building Grade I, RPG II*

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: B (D)

OWNERSHIP: Private

Country house, 1825, by Thomas Cundy, situated in park, developed from C15 to C17 and landscaped by Lancelot 'Capability' Brown in the 1760s. Previously used as a preparatory school (from the 1950s). The consent for conversion to a hotel has yet to be implemented but the website for the hotel states opening 2011. However, the fabric is vulnerable to the elements and continues to decline.

Contact: Isla Macneal 0117 975 0742



SITE NAME: **Early wing at Brook Hall,
Brokerswood,
Heywood**

DESIGNATION: Listed Building Grade I

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: A (A)

OWNERSHIP: Private

An important C15 lodging range, attached to the grade II listed house which contains some medieval remnants. Following the issuing of an Urgent Works Notice by the LPA a supporting scaffold was erected in Spring 2002. Discussions for reuse ongoing. English Heritage has grant-aided condition survey and is continuing to monitor structural movement. LPA actively considering serving a Repairs Notice.

Contact: Sarah Ball 0117 975 0666

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.


- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

	<p>SITE NAME: Chapel at Knowle House, Little Bedwyn</p> <p>DESIGNATION: Scheduled Monument</p> <p>CONDITION: Poor</p> <p>OCCUPANCY: Not applicable</p> <p>PRIORITY: C (C)</p> <p>OWNERSHIP: Private</p>	<p>Early C15 chapel in curtilage of a listed house. In poor condition and needs some work and repair.</p> <p>Contact: Shane Gould 0117 975 0671</p>
	<p>SITE NAME: 93 and 94 Bradenstoke, Lyneham</p> <p>DESIGNATION: Listed Building Grade II*, CA</p> <p>CONDITION: Fair</p> <p>OCCUPANCY: Vacant</p> <p>PRIORITY: E (E)</p> <p>OWNERSHIP: Private</p>	<p>Timber framed building, C15 to C16, upgraded to II* in 2002. Last known use as a private residence but is now unoccupied. The council is monitoring the condition.</p> <p>Contact: Isla Macneal 0117 975 0742</p>
	<p>SITE NAME: Medieval undercroft at Bradenstoke Priory, Bradenstoke, Lyneham</p> <p>DESIGNATION: Scheduled Monument</p> <p>CONDITION: Poor</p> <p>OCCUPANCY: Not applicable</p> <p>PRIORITY: C (C)</p> <p>OWNERSHIP: Private</p>	<p>C14 undercroft to priory. The building above removed in 1920s to the United States of America by Randolph Hearst. The undercroft has been propped with grant aid from English Heritage, to prevent collapse. There has been recent clearance of scrub and some survey work is being undertaken, which will help advise a specification for long term consolidation. Some work being undertaken at a slow rate.</p> <p>Contact: Vryan Heal 0117 975 0717</p>
	<p>SITE NAME: The Red House at Eastwell Manor, Eastwell Road, Potterne</p> <p>DESIGNATION: Listed Building Grade II*</p> <p>CONDITION: Poor</p> <p>OCCUPANCY: Not applicable</p> <p>PRIORITY: C (C)</p> <p>OWNERSHIP: Private</p>	<p>Red brick garden building, built circa 1700. One of several buildings on this site that are presently disused and in a decaying condition. An Enforcement Notice has been served in respect of unauthorised alterations. An appeal was lodged by the owner but was rejected by the planning inspector.</p> <p>Contact: Isla Macneal 0117 975 0742</p>
	<p>SITE NAME: Littlecote Roman Villa, Ramsbury</p> <p>DESIGNATION: Scheduled Monument</p> <p>CONDITION: Poor</p> <p>OCCUPANCY: Not applicable</p> <p>PRIORITY: C (C)</p> <p>OWNERSHIP: Company</p>	<p>Roman Villa, C1 to C4 AD. The owners have erected a new permanent cover over the mosaic. English Heritage is working with the owners over a long term management plan for the site including its future repair.</p> <p>Contact: Shane Gould 0117 975 0671</p>
	<p>SITE NAME: Chapel, immediately north of Pythouse, Pythouse Park, West Tisbury</p> <p>DESIGNATION: Listed Building Grade II*</p> <p>CONDITION: Very bad</p> <p>OCCUPANCY: Vacant</p> <p>PRIORITY: A (A)</p> <p>OWNERSHIP: Private</p>	<p>Private chapel to country house circa 1827. Built by John Bennett of Pythouse for his wife nee Lucy Lambert of Boyton. The chapel is derelict and overgrown and the stonework has been vandalised. The building is now scaffolded. Some of the vegetation has been removed and a repair schedule is being prepared.</p> <p>Contact: Isla Macneal 0117 975 0742</p>

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME: **Phipps Mausoleum,
Westbury Cemetery,
Bratton Road, Westbury**

Late C19 privately owned mausoleum, within a local authority municipal cemetery. The local authority is in discussion with English Heritage and the owners regarding a possible programme of repairs.

DESIGNATION: Listed Building Grade II*

CONDITION: Poor

OCCUPANCY: Not applicable

PRIORITY: C (C)

OWNERSHIP: Private

Contact: Isla Macneal 0117 975 0742

SITE NAME: **Banjo enclosure 480m south west of Cheldene, Aldbourne**

DESIGNATION: Scheduled Monument (No. 30285)

CONDITION: Extensive significant problems
i.e. under plough, collapse

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Unknown

OWNERSHIP: Private

CONTACT: Shane Gould 0117 9750726

SITE NAME: **Lewisham Castle, Aldbourne**

DESIGNATION: Scheduled Monument (No. 30286)

CONDITION: Generally satisfactory
but with significant localised problems

PRINCIPAL VULNERABILITY: Arable clipping

TREND: Unknown

OWNERSHIP: Private

CONTACT: Shane Gould 0117 9750726

SITE NAME: **Bowl barrow 800m south east of Tanhill Penning, All Cannings**

DESIGNATION: Scheduled Monument (No. 12185)

CONDITION: Generally unsatisfactory
with major localised problems

PRINCIPAL VULNERABILITY: Arable clipping

TREND: Unknown

OWNERSHIP: Private

CONTACT: Shane Gould 0117 9750726

SITE NAME: **Two bowl barrows 400m south of Tanhill Penning, All Cannings**

DESIGNATION: Scheduled Monument (No. 12184)

CONDITION: Generally satisfactory
but with significant localised problems

PRINCIPAL VULNERABILITY: Arable clipping

TREND: Unknown

OWNERSHIP: Government or Agency

CONTACT: Shane Gould 0117 9750726

SITE NAME: **Earth Burgh (or Eorth Burh) north west of New Town Farm, Alton**

DESIGNATION: Scheduled Monument (No. W1680)

CONDITION: Generally satisfactory
but with significant localised problems

PRINCIPAL VULNERABILITY: Extensive animal burrowing

TREND: Declining

OWNERSHIP: Private

CONTACT: Shane Gould 0117 9750726

SITE NAME: **Two Saxon boundary stones 450yds (410m) west of New Town, Alton**

DESIGNATION: Scheduled Monument (No. W1282)

CONDITION: Unknown

PRINCIPAL VULNERABILITY: Other

TREND: Unknown

OWNERSHIP: Private

CONTACT: Shane Gould 0117 9750726

SITE NAME: **Wermere pond, Alvediston**

DESIGNATION: Scheduled Monument (No. W1494)

CONDITION: Generally unsatisfactory
with major localised problems

PRINCIPAL VULNERABILITY: Arable clipping

TREND: Declining

OWNERSHIP: Private

CONTACT: Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:		A bell barrow and two bowl barrows east of The Avenue on Countess Farm: part of a linear round barrow cemetery, Amesbury	
DESIGNATION:	Scheduled Monument (No. 10441)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME:		Bell barrow 550m east of New Barn, Earl's Farm Down, Amesbury	
DESIGNATION:	Scheduled Monument (No. 12197)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME:		Bowl barrow 170m south east of Strangways on Countess Farm, Amesbury	
DESIGNATION:	Scheduled Monument (No. 10424)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME:		Bowl barrow 400m SSE of Strangways on Countess Farm, Amesbury	
DESIGNATION:	Scheduled Monument (No. 10425)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME:		Bowl barrow 60m west of A345 on Countess Farm, Amesbury	
DESIGNATION:	Scheduled Monument (No. 10418)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME:		Bowl barrow 70m west of A345 on Countess Farm, Amesbury	
DESIGNATION:	Scheduled Monument (No. 10434)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME:		Henge monument 400m south of Stonehenge Cottages, Amesbury	
DESIGNATION:	Scheduled Monument (No. 10323)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME:		Linear boundary earthwork 250m west of Stockport, Amesbury	
DESIGNATION:	Scheduled Monument (No. 28940)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Linear boundary earthwork on Amesbury Down west of Stock Bottom, Amesbury			
DESIGNATION:	Scheduled Monument (No. 28935)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME: Pond barrow 400m south east of Strangways, Amesbury			
DESIGNATION:	Scheduled Monument (No. 10412)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME: Pond barrow 480m west of Olddown Barn on Amesbury Down, Amesbury			
DESIGNATION:	Scheduled Monument (No. 28934)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME: Three bell barrows 300m north east of New Barn, Earl's Farm Down, Amesbury			
DESIGNATION:	Scheduled Monument (No. 12202)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME: Settlement east of Ashtonfield (Cotswold Community), Ashton Keynes			
DESIGNATION:	Scheduled Monument (No. W1902)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Local Authority	CONTACT:	Shane Gould 0117 9750726
SITE NAME: A henge, four Bronze Age barrows and part of a Roman road 500m south west of Fox Covert, Avebury			
DESIGNATION:	Scheduled Monument (No. 21765)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726
SITE NAME: Beckhampton round barrow cemetery 150m north east of the 'Waggon and Horses', Avebury			
DESIGNATION:	Scheduled Monument (No. 21751)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME: Bell barrow forming part of a round barrow cemetery 400m north east of West Kennett Farm on Overton Hill, Avebury			
DESIGNATION:	Scheduled Monument (No. 21726)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:		Bowl barrow 200m south of Green Street and 1100m east of the Avebury henge monument, forming part of a round barrow cemetery on Avebury Down, Avebury	
DESIGNATION:	Scheduled Monument (No. 21743)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME:		Bowl barrow 50m south of The Sanctuary on Overton Hill, forming part of the Seven Barrow Hill round barrow cemetery, Avebury	
DESIGNATION:	Scheduled Monument (No. 21762)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME:		Bowl barrow 770m south west of the junction of the Ridgeway and Green Street, forming part of a round barrow cemetery on Avebury Down, Avebury	
DESIGNATION:	Scheduled Monument (No. 21745)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME:		Bowl barrow 900m SSE of Green Bank, Avebury	
DESIGNATION:	Scheduled Monument (No. 21895)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME:		Bowl barrow forming part of a Bronze Age cemetery 400m north east of West Kennett Farm on Overton Hill, Avebury	
DESIGNATION:	Scheduled Monument (No. 21724)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME:		Bowl barrow immediately west of the Ridgeway, 400m north east of its junction with Green Street, Avebury	
DESIGNATION:	Scheduled Monument (No. 21740)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME:		Earthwork enclosure 950m SSE of Manor Farm, Avebury	
DESIGNATION:	Scheduled Monument (No. 21897)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME:		Group of six round barrows forming part of a Bronze Age cemetery 400m north-east of West Kennett Farm, Avebury	
DESIGNATION:	Scheduled Monument (No. 21723)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Pair of round barrows 400m west of the Ridgeway, forming part of a round barrow cemetery situated on Avebury Down, Avebury			
DESIGNATION:	Scheduled Monument (No. 21730)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME: Pair of round barrows forming part of the Bronze Age round barrow cemetery 400m north east of West Kennett Farm, Avebury			
DESIGNATION:	Scheduled Monument (No. 21725)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME: Remains of 'Falkner's Circle', a Neolithic stone circle 180m east of the West Kennet Avenue, Avebury			
DESIGNATION:	Scheduled Monument (No. 21737)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME: Round barrow cemetery 400m south of Avebury henge monument on Waden Hill, Avebury			
DESIGNATION:	Scheduled Monument (No. 21750)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME: Ten barrows forming part of Fox Covert round barrow cemetery, West Down, Avebury			
DESIGNATION:	Scheduled Monument (No. 21752)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME: West Kennet Avenue and an earthwork bank east of West Kennett Farm, Avebury			
DESIGNATION:	Scheduled Monument (No. 28131)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME: West Kennett Farm palisaded enclosures, Avebury			
DESIGNATION:	Scheduled Monument (No. 10380)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME: Grovely Ditch, Barford St Martin			
DESIGNATION:	Scheduled Monument (No. W1456)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Berwick Coombe ditch, Berwick St John			
DESIGNATION:	Scheduled Monument (No. W1472)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Bowl barrow west of Rotherley Wood, 750m WNW of Park Cottage, Berwick St John			
DESIGNATION:	Scheduled Monument (No. 33561)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Winkelbury Hill earthworks, Berwick St John			
DESIGNATION:	Scheduled Monument (No. W1469)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Winkelbury Hill round barrows, Berwick St John			
DESIGNATION:	Scheduled Monument (No. W1470)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Bell barrow situated between Bishop's Cannings Down and Easton Down, Bishops Cannings			
DESIGNATION:	Scheduled Monument (No. 21866)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Bowl barrow 1070m NNW of Baltic Farm forming part of a barrow cemetery on North Down, Bishops Cannings			
DESIGNATION:	Scheduled Monument (No. 21885)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Bowl barrow 150m east of the wireless station on Morgan's Hill, Bishops Cannings			
DESIGNATION:	Scheduled Monument (No. 28107)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Bowl barrow 300m east of Furze Knoll, Bishops Cannings			
DESIGNATION:	Scheduled Monument (No. 12170)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Bowl barrow 550m north east of Baltic Farm, Bishops Cannings			
DESIGNATION:	Scheduled Monument (No. 12162)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726
SITE NAME: Bowl barrow 840m north east of Baltic Farm, Bishops Cannings			
DESIGNATION:	Scheduled Monument (No. 12173)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726
SITE NAME: Bowl barrow 950m SSW of Beckhampton Plantation, forming part of a round barrow cemetery on Horton Down, Bishops Cannings			
DESIGNATION:	Scheduled Monument (No. 21873)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726
SITE NAME: Bowl barrow at east end of Morgan's Hill, Bishops Cannings			
DESIGNATION:	Scheduled Monument (No. 12174)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726
SITE NAME: Bowl barrow situated 500m SSW of Shepherds' Shore, Bishops Cannings			
DESIGNATION:	Scheduled Monument (No. 21883)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726
SITE NAME: Eleven round barrows 1000m north of Baltic Farm forming part of a barrow cemetery, and a probable enclosed Iron Age farmstead on North Down, Bishops Cannings			
DESIGNATION:	Scheduled Monument (No. 21886)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726
SITE NAME: Enclosed Iron Age farmstead 450m south of Down Barn on Bishop's Cannings Down, Bishops Cannings			
DESIGNATION:	Scheduled Monument (No. 21867)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726
SITE NAME: Four bowl barrows forming part of a cemetery 270m east of long barrow on Roughridge Hill, Bishops Cannings			
DESIGNATION:	Scheduled Monument (No. 21893)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Group of small enclosures on Horton Down, 910m north east of Easton Down long barrow, Bishops Cannings		
DESIGNATION:	Scheduled Monument (No. 28117)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Group of three bowl barrows 250m north east of Shepherds' Shore, Bishops Cannings		
DESIGNATION:	Scheduled Monument (No. 21869)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Linear earthworks forming part of a field system on Bishop's Cannings Down, Bishops Cannings		
DESIGNATION:	Scheduled Monument (No. 21870)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Long barrow 650m WSW of Shepherds' Shore, Bishops Cannings		
DESIGNATION:	Scheduled Monument (No. 21896)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Long barrow on Easton Down, Bishops Cannings		
DESIGNATION:	Scheduled Monument (No. 12190)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Long barrow on Horton Down, Bishops Cannings		
DESIGNATION:	Scheduled Monument (No. 12189)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Roundway Hill Farm round barrows, Bishops Cannings		
DESIGNATION:	Scheduled Monument (No. W1492)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Saucer barrow 600m west of Beckhampton Buildings, Bishops Cannings		
DESIGNATION:	Scheduled Monument (No. 12203)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Saucer barrow on North Down, Bishops Cannings			
DESIGNATION:	Scheduled Monument (No. 12163)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Square enclosure 350m north of Wansdyke on Bishop's Cannings Down, Bishops Cannings			
DESIGNATION:	Scheduled Monument (No. 21868)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Two saucer barrows and a pair of bowl barrows 750m SSW of Beckhampton Plantation, forming part of a round barrow cemetery on Horton Down, Bishops Cannings			
DESIGNATION:	Scheduled Monument (No. 21872)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Crouchston Down Barn round barrow, Bishopstone			
DESIGNATION:	Scheduled Monument (No. W1488)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Knighton Roman road (stretching from Reddish Gore to reservoir), Bishopstone			
DESIGNATION:	Scheduled Monument (No. W1480)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Bowl barrow 85m north of Bishopstrow House, Bishopstrow			
DESIGNATION:	Scheduled Monument (No. 34188)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Enclosure and linear earthworks between Bishopstrow Down and South Down Sleight, Bishopstrow			
DESIGNATION:	Scheduled Monument (No. 10088)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Woodminton Down round barrow, Bower Chalke			
DESIGNATION:	Scheduled Monument (No. W1482)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Corton long barrow, Boyton			
DESIGNATION:	Scheduled Monument (No. 12341)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Long barrow 250m east of Boyton Field Barn, Boyton			
DESIGNATION:	Scheduled Monument (No. 12339)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Scrubbed Oak enclosure and linear boundary earthwork, Boyton			
DESIGNATION:	Scheduled Monument (No. 26851)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Bowl barrow on Cold Kitchen Hill, 740m north east of Seagram's Barn, Brixton Deverill			
DESIGNATION:	Scheduled Monument (No. 31678)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Bowl barrow on Cold Kitchen Hill, 910m north east of Seagram's Barn, Brixton Deverill			
DESIGNATION:	Scheduled Monument (No. 31679)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Long barrow on Pertwood Down, 1400m north west of Lower Pertwood, Brixton Deverill			
DESIGNATION:	Scheduled Monument (No. 12313)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Knowle Hill round barrow, Broad Chalke			
DESIGNATION:	Scheduled Monument (No. W1501)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Round barrow 860yds (786m) south east of Knighton Hill Buildings, Broad Chalke			
DESIGNATION:	Scheduled Monument (No. W1481)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Roman road in Spye Park, Bromham		
DESIGNATION:	Scheduled Monument (No. W1663)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	A group of five bowl barrows south of Bulford Camp, Bulford		
DESIGNATION:	Scheduled Monument (No. 10257)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bell barrow 770m north west of New Barn, Bulford		
DESIGNATION:	Scheduled Monument (No. 28924)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow: one of a group of round barrows south of Bulford, Bulford		
DESIGNATION:	Scheduled Monument (No. 10249)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow: one of a group of round barrows south of Bulford, Bulford		
DESIGNATION:	Scheduled Monument (No. 10250)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow: one of a group of round barrows south of Bulford, Bulford		
DESIGNATION:	Scheduled Monument (No. 10251)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow: one of a group of round barrows south of Bulford, Bulford		
DESIGNATION:	Scheduled Monument (No. 10252)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow: one of a group of round barrows south of Bulford, Bulford		
DESIGNATION:	Scheduled Monument (No. 10253)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Nuthills Roman villa, Calne Without		
DESIGNATION:	Scheduled Monument (No. W1658)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Long barrow 240m south west of Green Barrow Farm, Castle Combe		
DESIGNATION:	Scheduled Monument (No. 31643)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 190m north east of Nolands Farm, Yatesbury, Cherhill		
DESIGNATION:	Scheduled Monument (No. 30457)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 350m north east of White Horse Plantation, Cherhill		
DESIGNATION:	Scheduled Monument (No. 19036)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 700m south east of Field Barn, Chicklade		
DESIGNATION:	Scheduled Monument (No. 26818)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow on Berril Down, Chitterne		
DESIGNATION:	Scheduled Monument (No. 10108)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Fussell's long barrow, Clarendon Park		
DESIGNATION:	Scheduled Monument (No. W1387)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl Barrow, part of the round barrow cemetery south of Codford Down, Codford		
DESIGNATION:	Scheduled Monument (No. 31666)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Three bowl barrows in Colerne Park, 450m north of Keeper's Cottage, Colerne		
DESIGNATION:	Scheduled Monument (No. 12316)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow on Wick Down, Collingbourne Ducis		
DESIGNATION:	Scheduled Monument (No. 12164)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 650m east of Summer Down Farm, Collingbourne Kingston		
DESIGNATION:	Scheduled Monument (No. 12166)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Crowdown Clump earthwork (Godsbury), Collingbourne Kingston		
DESIGNATION:	Scheduled Monument (No. W1532)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Two bowl barrows 400m south of Summer Down Farm, Collingbourne Kingston		
DESIGNATION:	Scheduled Monument (No. 12167)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 430m north west of Northdown Barn, Coombe Bissett		
DESIGNATION:	Scheduled Monument (No. 26835)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow on Little Toyd Down, 650m south west of Grims Lodge Farm, Coombe Bissett		
DESIGNATION:	Scheduled Monument (No. 26816)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Moated site and surrounding earthwork enclosure, 100m south of Chelworth Farm, Cricklade		
DESIGNATION:	Scheduled Monument (No. 12037)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Dumping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Long barrow on Ashmore Down, 775m north of Ashgrove Cottages, Donhead St Mary		
DESIGNATION:	Scheduled Monument (No. 26819)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Clearbury Down round barrow, Downton		
DESIGNATION:	Scheduled Monument (No. W1499)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Long barrow 600yds (550m) south east of Vanity, Downton		
DESIGNATION:	Scheduled Monument (No. W1506)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Wick Down round barrow, Downton		
DESIGNATION:	Scheduled Monument (No. W1500)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Ogbury camp, Durnford		
DESIGNATION:	Scheduled Monument (No. W1186)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Nine round barrows forming a round barrow cemetery 400m north of the eastern end of The Cursus, Durrington		
DESIGNATION:	Scheduled Monument (No. 10246)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Improving
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 120m west of East Kennett long barrow forming part of a cemetery, East Kennett		
DESIGNATION:	Scheduled Monument (No. 28102)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 200m east of East Kennett long barrow forming part of a barrow cemetery, East Kennett		
DESIGNATION:	Scheduled Monument (No. 28103)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Bowl barrow 200m north of East Kennett long barrow forming part of a cemetery, East Kennett		
DESIGNATION:	Scheduled Monument (No. 28105)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 40m north west of East Kennett long barrow forming part of a cemetery, East Kennett		
DESIGNATION:	Scheduled Monument (No. 28104)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 50m north east of East Kennett long barrow forming part of a cemetery, East Kennett		
DESIGNATION:	Scheduled Monument (No. 28106)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Easton Clump settlement, Easton		
DESIGNATION:	Scheduled Monument (No. W1536)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Round barrow on Easton Down, Easton		
DESIGNATION:	Scheduled Monument (No. W190)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Medieval moated site and Romano-British settlement at White Walls Wood, Easton Grey		
DESIGNATION:	Scheduled Monument (No. 12046)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Barrow on Fifield Down 700yds (640m) ESE of North Barn, Ebbesborne Wake		
DESIGNATION:	Scheduled Monument (No. W1222)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Edington Priory (site of), Edington		
DESIGNATION:	Scheduled Monument (No. W1828)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Long barrow, Tinhead Hill, Edington		
DESIGNATION:	Scheduled Monument (No. 10016)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive natural erosion	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Round barrow south west of Compton Farm, Enford		
DESIGNATION:	Scheduled Monument (No. 10039)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow north east of Everleigh Ashes, Everleigh		
DESIGNATION:	Scheduled Monument (No. 10006)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Barrow Clump, bowl barrow, east of Ablington, Figheldean		
DESIGNATION:	Scheduled Monument (No. 10137)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Three round barrows west of Netheravon Aerodrome, Fittleton		
DESIGNATION:	Scheduled Monument (No. 10133)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 540m north of Woodbine Barn, Fonthill Bishop		
DESIGNATION:	Scheduled Monument (No. 26830)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 100m north of Great Botley Copse, Grafton		
DESIGNATION:	Scheduled Monument (No. 12219)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Great Botley Copse long barrow, and disc barrow near it, Grafton		
DESIGNATION:	Scheduled Monument (No. W188)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	North Hill round barrows, Grafton		
DESIGNATION:	Scheduled Monument (No. W1573)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Romano-British kilns 150yds (135m) SSW of Tottenham House, Great Bedwyn		
DESIGNATION:	Scheduled Monument (No. W1869)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Grovely Castle and earthworks north of Grovely Wood, Great Wishford		
DESIGNATION:	Scheduled Monument (No. W1453)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 340m east of Holly Bush Farm, Grittleton		
DESIGNATION:	Scheduled Monument (No. 31642)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Medieval settlement immediately north west of Upper Littlecott Farm, Hilmarton		
DESIGNATION:	Scheduled Monument (No. 31647)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bell barrow, bowl barrow and section of hollow way 600m NNW of Long Orchard, Idmiston		
DESIGNATION:	Scheduled Monument (No. 26759)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bell barrow, three bowl barrows and gas testing trenches on Idmiston Down, Idmiston		
DESIGNATION:	Scheduled Monument (No. 26784)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 260m SSE of the southern corner of Moll Harris's Clump: one of a group of round barrows on Porton Down, Idmiston		
DESIGNATION:	Scheduled Monument (No. 26758)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Bowl barrow 440m SSW of the southern corner of Moll Harris's Clump: one of a group of round barrows on Porton Down, Idmiston			
DESIGNATION:	Scheduled Monument (No. 26756)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 01 17 9750726
SITE NAME: Bowl barrow 530m SSW of the southern corner of Moll Harris's Clump: one of a group of round barrows on Porton Down, Idmiston			
DESIGNATION:	Scheduled Monument (No. 26754)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 01 17 9750726
SITE NAME: Bowl barrow 535m SSW of the southern corner of Moll Harris's Clump: one of a group of round barrows on Porton Down, Idmiston			
DESIGNATION:	Scheduled Monument (No. 26755)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 01 17 9750726
SITE NAME: Bowl barrow 680m SSE of the southern corner of Moll Harris's Clump: one of a group of round barrows on Porton Down, Idmiston			
DESIGNATION:	Scheduled Monument (No. 26753)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 01 17 9750726
SITE NAME: Bronze Age enclosure and two bowl barrows 520m north east of Moll Harris's Clump on Idmiston Down, Idmiston			
DESIGNATION:	Scheduled Monument (No. 26785)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 01 17 9750726
SITE NAME: Long barrow 140m WSW of the Battery Hill triangulation point, Idmiston			
DESIGNATION:	Scheduled Monument (No. 26751)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 01 17 9750726
SITE NAME: Two bowl barrows 265m south of the southern corner of Moll Harris's Clump: part of a group of round barrows on Porton Down, Idmiston			
DESIGNATION:	Scheduled Monument (No. 26757)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 01 17 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:		Two disc barrows and two bowl barrows 900m north of Moll Harris's Clump on Idmiston Down, Idmiston	
DESIGNATION:	Scheduled Monument (No. 26783)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726
SITE NAME:		Barrow north east of Mere Down Farm, Kingston Deverill	
DESIGNATION:	Scheduled Monument (No. W1520)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME:		Bowl barrow 125m south of Dairy Farm, Kingston Deverill	
DESIGNATION:	Scheduled Monument (No. 12296)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME:		Bowl barrow 140m west of Cleeve, Kingston Deverill	
DESIGNATION:	Scheduled Monument (No. 30456)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME:		Bowl barrow 1480m east of Keysley Farm, Kingston Deverill	
DESIGNATION:	Scheduled Monument (No. 34211)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME:		Bowl barrow 200m south west of Keysley Farm, Kingston Deverill	
DESIGNATION:	Scheduled Monument (No. 12301)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME:		Bowl barrow 670m SSE of Kingston Dairy, Kingston Deverill	
DESIGNATION:	Scheduled Monument (No. 31684)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726
SITE NAME:		Bowl barrow 700m south west of Keysley Farm, Kingston Deverill	
DESIGNATION:	Scheduled Monument (No. 12302)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Bowl barrow 735m SSE of Kingston Dairy, Kingston Deverill			
DESIGNATION:	Scheduled Monument (No. 31683)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Bowl barrow east of Court Hill Plantation, Kingston Deverill			
DESIGNATION:	Scheduled Monument (No. 12298)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Bowl barrow on Keysley Down, 250m west of the A350 Warminster-Shaftesbury Road, Kingston Deverill			
DESIGNATION:	Scheduled Monument (No. 12305)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Romano-Celtic temple 300m south west of Keysley Farm, Kingston Deverill			
DESIGNATION:	Scheduled Monument (No. 31673)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: The Park round barrow, Kingston Deverill			
DESIGNATION:	Scheduled Monument (No. W1441)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Moated site and fishponds south east of Rowden Farm, Lacock			
DESIGNATION:	Scheduled Monument (No. 12036)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Settlement south east of Latton, Latton			
DESIGNATION:	Scheduled Monument (No. W1900)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Settlement west of Latton, Latton			
DESIGNATION:	Scheduled Monument (No. W1899)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Mineral extraction / related subsidence	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Medieval pottery kilns, Milford Farm, Laverstock		
DESIGNATION:	Scheduled Monument (No. W1740)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bell barrow on Rook Hill, 200m west of Pertwood Wood, Longbridge Deverill		
DESIGNATION:	Scheduled Monument (No. 12311)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Round barrow south west of Parsonage Down, Longbridge Deverill		
DESIGNATION:	Scheduled Monument (No. W1421)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Long barrow 600m north of Hebden Farm, Luckington		
DESIGNATION:	Scheduled Monument (No. 12287)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Enclosure on the summit of Rodmead Hill, Maiden Bradley with Yarnfield		
DESIGNATION:	Scheduled Monument (No. 26832)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Two saucer barrows 775m south east of Rodmead Farm, Maiden Bradley with Yarnfield		
DESIGNATION:	Scheduled Monument (No. 26823)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bohune Down round barrow, Manningford		
DESIGNATION:	Scheduled Monument (No. W1568)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Two bowl barrows north of Rowbury Lane, Market Lavington		
DESIGNATION:	Scheduled Monument (No. 12215)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Bowl barrow 190m north east of Burton Farm, Mere			
DESIGNATION:	Scheduled Monument (No. 26866)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Bowl barrow 760m north west of The Down House, Mere			
DESIGNATION:	Scheduled Monument (No. 29777)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Pond Bottom round barrow, Mere			
DESIGNATION:	Scheduled Monument (No. W1413)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Two round barrows in Chaddenwick Furze, Mere			
DESIGNATION:	Scheduled Monument (No. 26836)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Black Field Roman site, Mildenhall			
DESIGNATION:	Scheduled Monument (No. W1666)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Bowl barrow 800m south east of Ogbourne St. Andrew Farm, Mildenhall			
DESIGNATION:	Scheduled Monument (No. 12224)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Camp on Forest Hill, Mildenhall			
DESIGNATION:	Scheduled Monument (No. W1850)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Bowl barrow: one of three round barrows west of The Belt, Milston			
DESIGNATION:	Scheduled Monument (No. 10195)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Bowl barrow 200m north east of Everleigh Ashes, Milton Lilbourne		
DESIGNATION:	Scheduled Monument (No. 12195)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Roman tile and brick kiln site 1000yds (900m) west of Tidling Corner, Minety		
DESIGNATION:	Scheduled Monument (No. W1861)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 900m north of Down Farm, Nettleton		
DESIGNATION:	Scheduled Monument (No. 31655)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Long barrow 400m north west of Fox Covert, Nettleton		
DESIGNATION:	Scheduled Monument (No. 12288)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Long barrow 500m north of Lugbury Farm, Nettleton		
DESIGNATION:	Scheduled Monument (No. 12290)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Early medieval settlement, palace, church and Bronze Age ring ditches 340m east of Cowage Farm, Norton		
DESIGNATION:	Scheduled Monument (No. 31645)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow: one of a group of dispersed barrows south east of Norton Plantation, Norton Bavant		
DESIGNATION:	Scheduled Monument (No. 10219)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Round barrow on the south side of Cotley Hill, Norton Bavant		
DESIGNATION:	Scheduled Monument (No. 10220)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Barrow on Coombe Down, 1070yds (980m) north east of Upper Poughcombe, Ogbourne St Andrew		
DESIGNATION:	Scheduled Monument (No. W1224)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Barrow on Smeathe's Ridge, Ogbourne St Andrew		
DESIGNATION:	Scheduled Monument (No. W1194)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bell barrow 200m north of Rockley Plantation, Ogbourne St Andrew		
DESIGNATION:	Scheduled Monument (No. 12206)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 375m east of Wick Bottom Barn, Ogbourne St Andrew		
DESIGNATION:	Scheduled Monument (No. 30454)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 630m north east of Wick Bottom Barn, Ogbourne St Andrew		
DESIGNATION:	Scheduled Monument (No. 30453)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow and a saucer barrow 200m north of Rockley Plantation, Ogbourne St Andrew		
DESIGNATION:	Scheduled Monument (No. 12208)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Ogbourne Maizey Down round barrow, Ogbourne St Andrew		
DESIGNATION:	Scheduled Monument (No. W1537)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Round barrow 750yds (690m) south east of Smeathe's Plantation, Ogbourne St Andrew		
DESIGNATION:	Scheduled Monument (No. W1618)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Round barrow SSE of Greenland Camp, Orcheston		
DESIGNATION:	Scheduled Monument (No. 10116)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Round barrow cemetery 320m south east of Down Farm, Pewsey		
DESIGNATION:	Scheduled Monument (No. 31192)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	The Spectacles, Pewsey		
DESIGNATION:	Scheduled Monument (No. W1332)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Long barrow, Winterbourne, Pitton and Farley		
DESIGNATION:	Scheduled Monument (No. W1354)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bell barrow 350m south west of Barbury Barn, Preshute		
DESIGNATION:	Scheduled Monument (No. 12213)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 300m east of Ivy House Farm, Preshute		
DESIGNATION:	Scheduled Monument (No. 12225)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Group of round barrows on Rough Hill, Preshute		
DESIGNATION:	Scheduled Monument (No. W1541)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Preshute Down field system, Preshute		
DESIGNATION:	Scheduled Monument (No. W1539)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Sharpridge field system, Preshute			
DESIGNATION:	Scheduled Monument (No. W1540)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Membury Camp, Ramsbury (part in West Berkshire (UA))			
DESIGNATION:	Scheduled Monument (No. W1286)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Barrows in Bath Hole and Bury Hill Plantations, Redlynch			
DESIGNATION:	Scheduled Monument (No. W1507)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Bowl barrow 450m north of Cross Drovers, Shalbourne			
DESIGNATION:	Scheduled Monument (No. 12253)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Long barrow on Smay Down, 300m east of The Hassock, Shalbourne			
DESIGNATION:	Scheduled Monument (No. 12308)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Wansdyke: Daniel's Lane section, Shalbourne			
DESIGNATION:	Scheduled Monument (No. W1433)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Newton Barrow, South Newton			
DESIGNATION:	Scheduled Monument (No. W1148)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Earthwork enclosure on Milk Hill, Stanton St Bernard			
DESIGNATION:	Scheduled Monument (No. W1624)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Stapleford Castle, Stapleford		
DESIGNATION:	Scheduled Monument (No. W1141)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Barrow north of 'The Spectacles', Steeple Langford		
DESIGNATION:	Scheduled Monument (No. W1560)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 240m east of The Penning, Steeple Langford		
DESIGNATION:	Scheduled Monument (No. 28932)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Deptford Down round barrow, Steeple Langford		
DESIGNATION:	Scheduled Monument (No. W1397)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	East Castle, Steeple Langford		
DESIGNATION:	Scheduled Monument (No. W1446)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Little Langford round barrow, north of Upper Farm Down, Steeple Langford		
DESIGNATION:	Scheduled Monument (No. W1454)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Round barrow 230yds (210m) north west of New Field Plantation, Steeple Langford		
DESIGNATION:	Scheduled Monument (No. W1665)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Orchard Castle, Stourton with Gasper		
DESIGNATION:	Scheduled Monument (No. W1333)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Bell barrow 350m north of Haydon Farm, Sutton Veny			
DESIGNATION:	Scheduled Monument (No. 12347)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Bell barrow on Parsonage Down, 1.3km south east of Lord's Hill Farm, Sutton Veny			
DESIGNATION:	Scheduled Monument (No. 31677)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Bowl barrow on Littlecombe Down, Sutton Veny			
DESIGNATION:	Scheduled Monument (No. W1174B)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Improving
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Pair of bowl barrows 1050m NNW of Pertwood Wood, Sutton Veny			
DESIGNATION:	Scheduled Monument (No. 34212)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Fosbury camp, Tidcombe and Fosbury			
DESIGNATION:	Scheduled Monument (No. W1162)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Localised/limited stock erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Bowl barrow south east of Sidbury Hill, Tidworth			
DESIGNATION:	Scheduled Monument (No. 10204)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Castle Ditches camp, Tisbury			
DESIGNATION:	Scheduled Monument (No. W111)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Romano-British villa complex 330m north west of Queen Court Farm, Tockenham			
DESIGNATION:	Scheduled Monument (No. 31660)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Bowl barrow on Woodley Down 675m NNE of Ashmore Farm, Tollard Royal		
DESIGNATION:	Scheduled Monument (No. 33562)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Casterley Camp and associated monuments, Upavon		
DESIGNATION:	Scheduled Monument (No. 10037)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Two saucer barrows 250m west of John's Planting, Upton Lovell		
DESIGNATION:	Scheduled Monument (No. 12303)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 500m south of Upton Scudamore, Upton Scudamore		
DESIGNATION:	Scheduled Monument (No. 12293)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Barrow 1/4 mile (400m) north west of Willoughby Hedge, West Knoyle		
DESIGNATION:	Scheduled Monument (No. W1216)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow in The Belt, 350m north east of Hill Barn, West Overton		
DESIGNATION:	Scheduled Monument (No. 33958)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 100m north of Rox Hill Clump, Wilsford cum Lake		
DESIGNATION:	Scheduled Monument (No. 10488)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 250m south of Westfield Farm buildings, Wilsford cum Lake		
DESIGNATION:	Scheduled Monument (No. 10485)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Bowl barrow 350m south west of Normanton Gorse, Wilsford cum Lake		
DESIGNATION:	Scheduled Monument (No. 10479)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 400m west of Normanton Gorse, Wilsford cum Lake		
DESIGNATION:	Scheduled Monument (No. 10355)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 450m east of The Diamond south of the A303, Wilsford cum Lake		
DESIGNATION:	Scheduled Monument (No. 26263)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow 50m south west of Rox Hill Clump, Wilsford cum Lake		
DESIGNATION:	Scheduled Monument (No. 10487)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Bowl barrow south of the A303 and north west of Normanton Gorse, Wilsford cum Lake		
DESIGNATION:	Scheduled Monument (No. 10477)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Pond barrow south of the A303 and 400m west of Normanton Gorse containing the 'Wilsford Shaft', Wilsford cum Lake		
DESIGNATION:	Scheduled Monument (No. 10478)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Seven bowl barrows and a pond barrow forming a round barrow cemetery 200m north of The Diamond on Wilsford Down, Wilsford cum Lake		
DESIGNATION:	Scheduled Monument (No. 10480)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME:	Horse Barrow, Winterbourne		
DESIGNATION:	Scheduled Monument (No. WI386)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Bowl barrow 350m north west of Greenland Farm, Winterbourne Stoke			
DESIGNATION:	Scheduled Monument (No. 10459)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Bowl barrow 830m south west of Greenlands Bungalow, east of Shrewton, Winterbourne Stoke			
DESIGNATION:	Scheduled Monument (No. 28928)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Bronze Age enclosure and bowl barrow 100m west of Longbarrow Cross Roads on Winterbourne Stoke Down, Winterbourne Stoke			
DESIGNATION:	Scheduled Monument (No. 10484)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Disc barrow and pond barrow 350m NNW of Greenland Farm, Winterbourne Stoke			
DESIGNATION:	Scheduled Monument (No. 10458)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Bell barrow and bowl barrow 500m NNW of Long Orchard, Winterslow			
DESIGNATION:	Scheduled Monument (No. 26760)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Bowl barrow 375m WNW of Easton Down Farm: part of a group of round barrows south of Easton Down, Winterslow			
DESIGNATION:	Scheduled Monument (No. 26767)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Bowl barrow 750m NNE of Easton Down Farm, Winterslow			
DESIGNATION:	Scheduled Monument (No. 26768)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 0117 9750726

SITE NAME: Roman earthwork, Winterslow			
DESIGNATION:	Scheduled Monument (No. W1404)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Shane Gould 0117 9750726

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Two bowl barrows 400m west of Easton Down Farm: part of a group of round barrows south of Easton Down, Winterslow		
DESIGNATION:	Scheduled Monument (No. 26766)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 01 17 9750726

SITE NAME:	Heale Hill round barrows and earthworks, Woodford		
DESIGNATION:	Scheduled Monument (No. W1384)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Shane Gould 01 17 9750726

SITE NAME:	Bowl barrow 175m west of Square Copse: part of the Square Copse barrow cemetery, Wootton Rivers		
DESIGNATION:	Scheduled Monument (No. 12251)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 01 17 9750726

SITE NAME:	Bowl barrow 275m west of Square Copse: part of the Square Copse barrow cemetery, Wootton Rivers		
DESIGNATION:	Scheduled Monument (No. 12252)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Shane Gould 01 17 9750726



SITE NAME:	Tottenham House and Savernake Forest, Burbage and Savernake	Extensive landscape of rides linking Savernake Forest with ornamental parkland and pleasure grounds around the house. Exemplifies the work of Burlington, Brown, Cundy and others. Main house has planning permission for hotel development, including building over Brown's walled garden and laying out a golf course in the park. Forestry Commission manages Savernake Forest on a long lease.
DESIGNATION:	Registered Park and Garden Grade II*, also 20 LBs, 7 SMs	
CONDITION:	Extensive significant problems	
VULNERABILITY:	High	
TREND:	Declining	
OWNERSHIP:	Mixed, multiple owners	Contact: Kim Auston 01 17 975 0696

SITE NAME:	Atworth		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Judy Enticknap (LA) 01225 713000		

SITE NAME:	Hilperton		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Judy Enticknap (LA) 01225 713000		

SITE NAME:	Hilperton Road, Trowbridge		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Judy Enticknap (LA) 01225 713000		

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Melksham		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Judy Enticknap (LA) 01225 713000		
SITE NAME:	Newtown, Trowbridge		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Judy Enticknap (LA) 01225 713000		
SITE NAME:	Warminster		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Judy Enticknap (LA) 01225 713000		
SITE NAME:	Westbury		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Judy Enticknap (LA) 01225 713000		
SITE NAME:	Wilcot Road, Pewsey		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Judy Enticknap (LA) 01225 713000		

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2009 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



ENGLISH HERITAGE

This document is one in a series of publications produced as part of English Heritage's national Heritage at Risk campaign programme. More information about Heritage at Risk and other titles in the series can be found at www.english-heritage.org.uk/risk

HERITAGE AT RISK

Published July 2010 by English Heritage
1 Waterhouse Square, 138-142 Holborn,
London EC1N 2ST

© Copyright English Heritage 2010