



ENGLISH HERITAGE


HERITAGE AT
RISK
REGISTER
2011

SOUTH EAST

Contents

HERITAGE AT RISK	3
Reducing the risks	7
Publications and guidance	10
THE REGISTER	12
Content and assessment criteria	12
Key to the entries	15
South East heritage assets at risk	17
Bracknell Forest (UA)	20
Brighton and Hove, City of (UA)	20
South Downs (NP)*	21
Buckinghamshire	22
East Sussex	26
Hampshire	31
Isle of Wight (UA)	44
Kent	46
Medway (UA)	60
Milton Keynes (UA)	63
Oxfordshire	64
Portsmouth, City of (UA)	73
Reading (UA)	75
Southampton, City of (UA)	75
Surrey	76
West Berkshire (UA)	80
West Sussex	83
Windsor and Maidenhead (UA)	89
Wokingham (UA)	90

*Entries in the South Downs also appear in the following counties:
East Sussex, Hampshire and West Sussex



In its fourth year, the Heritage at Risk Register now includes grade I and II* listed buildings, listed places of worship, scheduled monuments, registered parks and gardens, registered battlefields, protected wreck sites and conservation areas known to be at risk as a result of neglect, decay or inappropriate development. This year, for the first time, we have published a list of 'priority sites': important heritage at risk sites where we will focus our resources to secure their futures.

This year the number of entries on the South East Register has changed little. However this masks some notable successes and some major new entries for us to tackle.

One of the biggest achievements this year was the successful completion of repairs to the beautiful Arts and Crafts style Watts Gallery in Surrey, following an £11 million restoration project. The success is particularly notable because the original contractors went into administration half way through the project, delaying its completion by almost a year. Progress is evident at some of our other long-standing cases so that we may soon see their removal from the Register: Conversion of both Hadlow Tower in Kent into holiday accommodation and the New Inn at Stowe into a new visitor centre are also exemplary schemes that illustrate high quality traditional skills and workmanship in action.

We continue to face huge challenges in the South East as we struggle to resolve new and existing heritage at risk. Whilst only a sample of the thousands of listed places of worship in the South East has been surveyed to date, 36 listed places of worship have already been added to the Register. 13 buildings at risk have been removed from the Register, but unfortunately 10 have been added. One such case is the highly publicised Saltdean Lido near Brighton. The local community is hoping to secure the lido's future by restoring it to community facilities and amenities.

Last year we highlighted the negative impact the recession was having on resolving heritage at risk sites. Although the continued slow recovery and the reduction in publicly available funding continue to have an impact on finding solutions, we remain both determined and optimistic. It is timely to remember that grant

aid is not the only way of making progress. Solutions can also be secured by local authorities' use of powers available through the planning system. We appreciate that this is challenging given the reduced numbers of specialist historic environment staff within local authorities, but we will increase the support and guidance we can offer to encourage use of these powers. This can often be the stimulus for owners to undertake maintenance and repairs before high cost solutions and rescue packages have to be found. For example, Waverley Borough Council recovered the costs of urgent works they undertook to secure Undershaw, the home of Arthur Conan Doyle, before serving a repairs notice on the owner.

We have also been particularly encouraged this year by the number of individuals, local groups and trusts that have mobilised themselves to save the heritage they care about. An example is Argos Hill Windmill, where the Argos Hill Windmill Trust has secured a long term lease from the local council to take on and restore the windmill. In the current climate, local people and groups will play an ever greater role in saving vulnerable heritage. We applaud these endeavours and where we can match such efforts with expertise or financial help we will. Our new Angel Awards Scheme, supported by the Andrew Lloyd Webber Foundation raises the profile of heritage at risk by celebrating the efforts of people who have saved significant historic places that might otherwise have been lost forever.

Andrew Brown, Planning Director
SOUTH EAST

BUILDINGS AT RISK

- Nationally, 3.0% of grade I and II* listed buildings are at risk. In the South East this falls to 1.8%, representing 100 sites.
- 13 sites have been removed from the 2010 Register, but 10 have been added.
- 52% of entries (121 buildings) on the baseline 1999 Register for the South East have been removed as their futures have been secured, compared to the national figure of 53% (757 buildings).
- Nationally, £5.2m was offered to 71 sites on the Register during 2010/11. In the South East we awarded grants totalling £505k to 8 sites.
- 36 listed places of worship have been added to our Register this year. We estimate the cost of repairing these buildings is £8.8m.

SCHEDULED MONUMENTS

- 16.9% (3,339) of England's 19,748 scheduled monuments are at risk, compared to 9.5% (249 sites) in the South East.
- In the South East, 6 sites have been removed from the 2010 Register, but 8 sites have been added.
- 15.6% of entries (38 sites) on the baseline 2009 Register for the South East have been removed due to positive reasons, compared to the national figure of 11.9% (399 sites).
- Arable ploughing and unrestricted plant, scrub or tree growth account for nearly two thirds of sites at risk nationally. This increases to almost three quarters in the South East.
- Nationally, 82% of scheduled monuments at risk are in private ownership, this rises to 89% in the South East.

REGISTERED PARKS AND GARDENS

- 103 of England's 1,610 registered parks and gardens are at risk, an increase from 6.2% (99) in 2010 to 6.4% this year. In the South East, 24 of our 368 sites are at risk (6.5%).
- Nationally, 6 sites have been added and 2 removed from the 2010 Register. There has been no change in the South East.

REGISTERED BATTLEFIELDS

- Of the 43 registered battlefields in England, 6 are at risk, 2 less than the 2008 baseline.
- Of the 6 registered battlefields in the South East, 1 is at risk.

PROTECTED WRECK SITES

- Of the 46 protected wreck sites off England's coast, 7 are at risk, 3 less than the 2008 baseline.
- 7 of the South East's 20 protected wreck sites are at risk.

CONSERVATION AREAS

- 288 local planning authorities (86%) have taken part in the national survey of conservation areas, of which 55 are in the South East. This is 80% of our local planning authorities.
- We now have information on the condition of 7,841 of England's 9,600 designated conservation areas and 516 (6.6%) are at risk.
- Of the 1,526 conservation areas surveyed in the South East, 66 (4.3%) are at risk.



WATTS GALLERY, COMPTON, SURREY

The Watts Gallery was on the Heritage at Risk Register from 2006-2010, and reopened to the public in 2011 after an £11 million restoration project.

IN THE SOUTH EAST:

52% OF
BUILDINGS
AT RISK
ON THE 1999 REGISTER
HAVE BEEN SAVED

9.9% OF
SCHEDULED
MONUMENTS
ARE AT RISK

80% OF
OUR LOCAL
AUTHORITIES
HAVE SURVEYED THEIR
CONSERVATION AREAS

£505k
IN GRANTS WAS
OFFERED
TO SITES ON THE
2010 REGISTER

INDUSTRIAL HERITAGE

Britain was the world's first industrial nation and has a wealth of industrial heritage but many industrial sites have been lost or are at risk due to functional redundancy. Our survey has shown that the percentage of listed industrial buildings at risk is three times greater than the national average for listed buildings at risk.


The conservation of industrial sites can pose considerable challenges. However, industrial sites often have great potential for re-use. Our research shows that the best way of saving industrial buildings is, where possible, to find an adaptive new use. We know this isn't easy, and is not always possible, but we hope those who own or are thinking of developing an industrial building will find our new web pages an invaluable source of information.

Voluntary groups and owners have saved a number of key industrial sites, often sites which contain working machinery. However, research has shown that many of these groups need support to encourage more and younger members to achieve the rescue of the site.

Building preservation trusts can provide the answer for industrial buildings where there is no apparent commercial solution by repairing the site and then selling it, or retaining and letting the space.

What we know

- 4% of listed buildings and scheduled monuments are industrial
- Nationally there are proportionally more grade II* industrial listed buildings than grade II (4.6% compared to 4.4%)
- 10.6% of industrial grade I and II* listed buildings are at risk, making industrial buildings over three times more likely to be at risk than the national average for grade I and II* listed buildings
- The average estimated conservation deficit (cost of repair in excess of the end value) of industrial buildings at risk is twice that of non-industrial buildings at risk
- About 10% of industrial buildings at risk are economic to repair, compared to 13% of non-industrial buildings at risk
- Approximately 40% of industrial buildings at risk are capable of beneficial use, compared to 44% of non-industrial buildings at risk
- 10.9% of industrial scheduled monuments are at risk, making industrial scheduled monuments less likely to be at risk than the national average for scheduled monuments
- 3% of conservation areas were designated because of their industrial significance
- Industrial conservation areas in the North West and West Midlands are over twice as likely to be at risk than the national average
- In the last 10 years, English Heritage has offered grants totalling £25m to industrial sites



HAMMERHEAD CRANE, COWES, ISLE OF WIGHT

On the Heritage at Risk Register since 2008, this giant cantilever dockyard crane of 1912 is seriously at risk from decay and neglect. English Heritage is supporting the council by offering to underwrite the costs of serving an Urgent Works Notice on the owners to immediately address the most rapidly deteriorating elements of the structure.

What are we doing?

- Providing new guidance for owners on maintaining vacant historic buildings.
- Publishing a developers' portal on the English Heritage website where advice for all types of heritage asset including industrial sites can be found.
- Funding a new Industrial Heritage Support Officer, who will build capacity for industrial museums.
- Publishing an industrial themed issue of Conservation Bulletin in October 2011.
- Supporting a new Architectural Heritage Fund grant scheme which aims to encourage local groups to take on industrial buildings.
- Publishing an updated Stopping the Rot: a guide to enforcement action to save historic buildings.
- Using the National Heritage Protection Programme (2011-2015) to shape an industrial designation programme.

If you are a developer, member of a building preservation trust, work in a local authority, own a visitor attraction or have an interest in England's industrial heritage, visit our website for more information:

www.english-heritage.org.uk/industrial-heritage-at-risk


PRIORITY SITES

- Brookwood Cemetery, Brookwood, Woking, Surrey
- Castle Goring, Arundel Road, Worthing, West Sussex
- Hammerhead Crane, Thetis Road, West Cowes, Cowes, Isle of Wight
- RAF Bicester: World War II airfield, Laughton, Cherwell, Oxfordshire
- Roman Catholic Church of St Augustine of England with Cloisters attached, St Augustine's Road, Ramsgate, Thanet, Kent
- Sheerness Dockyard (incl. The Boat Store (No. 78), Former Medway Ports Authority Offices (Dockyard House), Coach Houses (Naval Terrace), 1-15 (consec) Regency Close, Former Royal Dockyard Church and attached wall and railings, Former Working Mast House, 26 Jetty Road), Sheerness, Kent
- Stowe Landscape Garden (incl. The Palladian Bridge, Temple of Friendship, The East Boycott Pavilion and The Queens Temple), Stowe, Buckinghamshire
- The Belvedere, Waldershare Park, Shepherdswell with Coldred, Dover, Kent
- The chapel at the former King Edward VII Hospital, Easebourne, Chichester, West Sussex
- The Western Heights fortifications, Castle Hill, Dover, Kent

COVER IMAGE:

The Western Heights fortifications, Dover, Kent, Building at Risk and Priority Site

CONTACT: Simon Goodhugh, Business Manager, English Heritage South East, Eastgate Court, 195-205 High Street, Guildford, GU1 3EH. Telephone: 01483 252037 Fax: 01483 252021 Email: simon.goodhugh@english-heritage.org.uk



For more information on Heritage at Risk visit www.english-heritage.org.uk/risk

If you would like this document in a different format, please contact our customer services department on telephone: 0870 333 1181 fax: 01793 414926 textphone: 01793 414878 email: customers@english-heritage.org.uk

Reducing the risks

English Heritage is committed to securing a year-on-year reduction in the number of heritage sites at risk as part of our national plan for the protection of England's historic environment (National Heritage Protection Plan 2011-2015). This will be challenging given the number of assets now on the Register and the different kinds of risk they face. Each asset type and individual case will require its own approach and solution.

There are, however, some general approaches that are relevant to all assets at risk. Resolving cases requires working in close partnership with owners, local planning authorities and other relevant organisations and partners. Advice and understanding are essential. Historic Environment Records, maintained by local authorities, are repositories of information on local historic assets. They underpin the work of local authority historic environment services and can help improve the protection, conservation and management of heritage assets.

Maintenance of heritage assets is essential if they are not to become at risk, and to prevent those that are already at risk from decaying further and thereby escalating the cost of their repair and consolidation. Buildings, for instance, decay rapidly when left empty. Avoiding vacancy through short-term lets or schemes that provide protection through residential occupation are low-cost ways of maintaining buildings until permanent solutions can be found. English Heritage has published guidance for owners on options for maintaining vacant buildings (*Vacant Historic Buildings: An Owner's Guide to Temporary Uses, Maintenance and Mothballing*).

English Heritage provides on-line advice and guidance to local authorities, owners and managers of sites through the Historic Environment Local Management (HELM) website www.helm.org.uk.

LISTED BUILDINGS

Buildings at risk

English Heritage's role in securing the future of buildings at risk is primarily to provide practical advice, guidance and resources to local authorities, owners and developers. Our involvement in cases is determined by the importance of the building and the complexity of the issues. We can help with analysis of the issues, investigation of the feasibility of options and brokering solutions. Although buildings at risk will continue to be a priority for English Heritage repair grants, grant aid is limited in relation to demand. Grants from other public sources, notably the Heritage Lottery Fund, continue to be essential in helping secure the future of buildings at risk.

In very exceptional cases, English Heritage may acquire and repair a particularly important building at risk, where it is clear that the scale and complexity of problems are such that direct involvement is the best way of securing the building's long-term future.

Local authorities have a primary role in protecting the historic environment. The creation of a local heritage at risk register is the first step in tackling neglected buildings in order to assess and monitor the scale of the problem and prioritise resources and action. Local authorities can also take action to secure the preservation of historic buildings through the use of statutory notices. Some local authorities have a successful track record, but generally these powers are under-used. It is essential that local authorities make best use of their powers to secure buildings at risk, to 'stop the rot' and prevent the costs escalating beyond the point where it is economic to repair. For this reason, English Heritage has published revised guidance (*Stopping the Rot*) for local planning authorities on taking action to save historic buildings.

To help local authorities make more frequent and timely use of their statutory powers, English Heritage runs grant schemes to underwrite a significant proportion of the irrecoverable costs involved in serving Urgent Works Notices and Repairs Notices.

Building preservation trusts can be the key to saving many buildings at risk. Some trusts cover geographical areas; others specialise in particular types of building or are formed to save just one building. Determined individuals and trusts have saved numerous buildings at risk, working in partnership with other organisations such as local and national amenity societies, including SAVE Britain's Heritage, the Society for the Protection of Ancient Buildings, the Georgian Group, The Victorian Society and the Twentieth Century Society.

Places of worship at risk

Regular maintenance helps to keep buildings and places of worship in good condition but those that are in poor or very bad condition need help to minimise the risks to both the structure and the contents. Keeping drains and gutters clear so that water is taken away from the building efficiently is the most important thing that congregations can do as it stops small problems in the building fabric developing into unnecessary crises. English Heritage supports the Society for the Protection of Ancient Buildings's *Faith in Maintenance* scheme, giving volunteers practical local training and on-going support. It also encourages the establishment of gutter-clearance projects, enabling congregations to get good quality work done at reasonable prices by reputable contractors.

Where major structural repairs are required, the Repair Grants for Places of Worship scheme helps under resourced buildings in urgent need. The Listed Places of Worship scheme is another source of funding for repairs and maintenance that is available more widely, while local and national charities can offer small grants.

Many congregations wish to adapt and change their places of worship to encourage wider community use alongside worship and faith-focussed events. English Heritage supports the efforts of congregations to keep their places of worship in use wherever possible and welcomes proposals for appropriate new facilities such as kitchens and toilets that are sensitive to the building's special character.

English Heritage is aware of the need for practical, hands-on help to be given to individual congregations and is working with partner organisations to enable this. Support Officers are employed by local denominational groups but part-funded by English Heritage. They give advice and encouragement to congregations so that they can achieve repair projects, develop necessary new facilities or re-engage with the wider community, depending on local circumstances and needs.

SCHEDULED MONUMENTS

The continuing success in reducing the number of monuments at risk, even in difficult economic times, demonstrates the value of the dialogue that the initiative has fostered between English Heritage, owners, managers and other partners. More and more owners and managers of scheduled monuments are addressing their long-term care on a regular basis. Over half of all scheduled monuments are now on land subject to an agreement under Natural England's Environmental Stewardship agri-environment scheme, administered on behalf of Defra. Work in the coming years with Defra and Natural England will concentrate upon ensuring that the right options are being used in

the correct way, maximising the conservation benefits whilst at the same time delivering value for money. We will also work closely with the Heritage Lottery Fund to help identify those important monuments deserving of grant aid for major stabilisation or repair work.

Progress is also reliant upon better understanding. As a result, as part of the National Heritage Protection Plan – which sets out English Heritage's commitment to safeguarding heritage up to 2015 – the Conservation of Scheduled Monuments in Cultivation project will be rolled out nationally from 2011 onwards. The project, already successfully trialled amongst farmers in the East Midlands, will address what is still the biggest threat by far to monuments – their gradual degradation and loss through arable cultivation. Some causes of risk are neither so obvious nor dramatic in their effects however. Heritage at risk shows that unmanaged tree, scrub and bracken growth is the most widespread cause of long term damage to both urban and rural monuments, even if the effects are not as visible or immediately destructive as other processes. Further work will therefore be needed to better understand how these effects can be minimised.

In all cases, however – whether for rural or urban monuments – close co-operation with owners and land managers is still key to making further progress in ever more challenging circumstances.

REGISTERED PARKS AND GARDENS

Inclusion on the *Register of Historic Parks and Gardens of Special Historic Interest* brings no additional statutory controls, but there is a presumption in favour of the conservation of all designated assets in the planning system. The Government's Planning Policy Statement 5 *Planning for the Historic Environment* (PPS 5) and its supporting Practice Guide helps planning authorities to assess and mitigate the impact of development on our irreplaceable heritage of designed landscapes.

English Heritage can engage only with the proposals for change to the highest graded designed landscapes and where the impact on historic significance is greatest. Our landscape architects can help tailor plans and funding packages for individual landscape features as well as strategies for the whole site. We will continue to tackle the skills crisis facing historic parks and gardens through sector-wide initiatives.

English Heritage encourages the development of conservation management plans for registered historic parks and gardens, especially those in multiple ownership. We are keen for bursars and estate teams to use management plans to help conserve important but fragile landscapes in the care of schools, hospitals, hotels and other institutional owners.

REGISTERED BATTLEFIELDS

As with registered parks and gardens, this designation brings no additional statutory controls, but there is a presumption in favour of conservation of registered battlefields in Planning Policy Statement 5.

English Heritage will continue to work with owners to develop management plans for registered sites and, in appropriate cases, contribute towards the cost of management plans. We will develop positive landscape strategies with owners and partners such as Defra. In some circumstances, we may encourage the conversion from arable to pasture of especially sensitive locations to protect battlefield archaeology from the effects of ploughing and as part of a wider drive to prevent unauthorised or damaging metal-detecting.

English Heritage will also continue to encourage greater access to battlefields and improve their amenity value and visitors' appreciation of the impact these historic events had on our development as a nation.

Local authorities can also invite comments from the Battlefields Trust on planning applications affecting the setting of registered sites.

PROTECTED WRECK SITES

At the strategic level, the major sources of risk to designated wreck sites have been identified. In terms of high-priority sites, practical requirements have also been implemented through conservation management plans.

Risks to protected wreck sites can often be reduced through education, provision of marker buoys, or planning policies that take full account of their national importance. However, some sites require significant resources to stabilise their condition or to carry out detailed archaeological assessments of their conservation requirements. Although English Heritage has statutory power to allocate funds to promote the preservation and maintenance of protected wreck sites, its financial resources can solve only a small proportion of the problems.

In spite of the inherent difficulties with caring for this type of site, careful management must be maintained if we are to avoid the loss of wreck sites. It is therefore close co-operation between the owners of protected wreck sites (where known), authorised divers and all organisations charged with care for the marine and coastal environment, that will make the real difference to their long-term survival.

Practical advice on the management of historic wreck sites, whether at the coast-edge or under water, is available from English Heritage (maritime@english-heritage.org.uk) and from www.helm.org.uk

CONSERVATION AREAS

The risks to conservation areas are difficult to address as they cover large areas of land: they include the spaces between buildings and trees as well as buildings and structures and therefore involve many different owners. Looking after them is a responsibility shared by those of us who own homes and businesses in them and those of us whose job it is to manage the spaces between the buildings or make decisions about their future.

The conservation area survey provides us with an understanding of what is particularly affecting the character and appearance of our conservation areas: what is working well or what is putting them at risk. Strong planning policies, guidance and a clear management strategy for individual conservation areas are critical in managing change in these areas. This is difficult at a time when local authorities across the country are reducing the number of staff managing changes in conservation areas. There are, of course, opportunities for members of the local community to engage, either individually or through groups such as civic societies or conservation area advisory committees which are proven to help achieve positive action.

Armed with the information provided by the surveys, we, local authorities and other partners will have the evidence to direct resources much more accurately towards those conservation areas at greatest risk. We will also want to target those with the greatest potential to improve the quality of life and economic prospects of people in the villages, towns and cities of which they are such crucially important components.

Publications and guidance

English Heritage has produced the following publications relating to heritage at risk, including:

Buildings at Risk: a New Strategy (1998)

Caring for Places of Worship 2010 (2010) – a report on the condition of England's listed places of worship and the needs of the congregations

Heritage at Risk 2010

Heritage at Risk: Conservation Areas (2009)

Heritage at Risk 2011 – national report and summaries for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, Yorkshire and the Humber

Heritage at Risk Register 2011 – detailed listings for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, Yorkshire and the Humber can be downloaded from our website or viewed as an interactive database: www.english-heritage.org.uk/risk

Monuments at Risk (2008) – summary of scheduled monuments at risk for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, Yorkshire and the Humber

Protected Wreck Sites at Risk: A Risk Management Handbook (2007)

Saving London: 20 Years of Heritage at Risk in the Capital (2010)

Stopping the Rot: A Guide to Saving Historic Buildings Through Enforcement Action (2011)

The Monuments at Risk initiative 2003–08 (2010)

Vacant Historic Buildings: An Owner's Guide to Temporary Uses, Maintenance and Mothballing (2011)

HERITAGE AT RISK ON THE WEB

To find out more about the Heritage at Risk programme visit www.english-heritage.org.uk/risk where you will find an interactive database providing detailed information on all heritage sites at risk nationally.

For further information about the different classes of designated heritage assets, including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites visit the Heritage Protection section of our website www.english-heritage.org.uk/heritageprotection. Details of all nationally designated historic places in England are now available in one place on the National Heritage List for England online database: <http://list.english-heritage.org.uk>

CONSERVATION POLICIES AND GUIDANCE

The following publications are among the numerous helpful guidance documents now available on our website: www.english-heritage.org.uk/publications or www.english-heritage.org.uk/helm

Caring for Places of Worship (2010) – a practical booklet for everyone involved in caring for England's listed places of worship

Constructive Conservation in Practice (2008)

Conservation Principles, Policies and Guidance for the Sustainable Management of the Historic Environment (2008)

Creativity and Care: New Works in English Cathedrals (2009)

Enabling Development and the Conservation of Significant Places (2008)

Farming the Historic Landscape: Caring for Archaeological sites on Arable Land (2004)

Farming the Historic Landscape: Caring for Archaeological Sites in Grassland (2004)

Guidance on the Management of Conservation Areas (2006)

Guidance on Conservation Area Appraisals (2006)

Guidance Notes and Application Forms for Grants to Local Authorities:

- *Grants to Local Authorities to Underwrite Urgent Works Notices* (1998)
- *Acquisition Grants to Local Authorities to Underwrite Repairs Notices* (1998)
- *Grants for Historic Buildings, Monuments and Designed Landscapes* (2004)

Heritage at Risk: Conservation Areas (2009)

– guidance for local authorities

*Managing Local Authority Heritage Assets:
Some Guiding Principles for Decision Makers* (2003)

New Uses for Former Places of Worship (2010)

*Options for the Disposal of Redundant Churches
and Other Places of Worship* (2010)

*Paradise Preserved: An Introduction to the Assessment,
Evaluation, Conservation and Management of Historic
Cemeteries* (2002)

*Scheduled Monument Consent: a Guide for Owners
and Occupiers* (2009)

*Shared Interest: Celebrating Investment in the Historic
Environment* (2006)

*The Disposal of Historic Buildings: Guidance Note for
Government Departments and Non-Departmental
Public Bodies* (2010).

*Valuing Places: Good Practice in Conservation
Areas* (2011)

If you would like further information about
any of these publications, please contact:

English Heritage Customer Services Department

PO Box 569, Swindon SN2 2YP

Telephone: 0870 333 1181

Fax: 01793 414926

Email: customers@english-heritage.org.uk

THE REGISTER

Content and criteria

DESIGNATION

All the historic environment matters but there are some elements which warrant extra protection through the planning system. Since 1882, when the first Act protecting ancient monuments and archaeological remains was passed, government has been developing the designation system. Listing emerged from the post-blitz 1940s Planning Acts, and is now applied to about half a million buildings ranging from palaces to street lamps. Almost 20,000 archaeological sites are scheduled, which introduces tight management controls. Some 1,610 designed landscapes are registered, as are 43 battlefields, and 46 wreck sites are protected.

English Heritage, as the government's expert adviser, is responsible for making recommendations – but it is still the Secretary of State at the Department for Culture Media and Sport who makes the decisions on whether a site is designated. Understanding and appreciation develop constantly, which makes keeping the designation base up-to-date a never-ending challenge. While responding to threat-driven cases, we also seek to work strategically. Recent developments have seen a greater striving for openness and transparency in the process of designating a site, and better communication of what makes something special.

Conservation areas are designated locally by local planning authorities. They are areas of special architectural or historic interest the character or appearance of which it is desirable to preserve or enhance.

LISTED BUILDINGS

Definition

A listed building is a building (or structure) that has been designated as being of 'special architectural or historic interest'. The older and rarer a building is, the more likely it is to be listed. Buildings less than 30 years old are listed only if they are of outstanding quality and under threat.

Listed buildings are graded I, II* and II. Grade I and II* are particularly important buildings of outstanding interest; together they amount to 8% of all listed buildings. The remaining 92% are of special interest and are listed grade II.

Entries on the statutory list of buildings of special architectural or historic interest may comprise a number of separate buildings. Formal residential terraces are the most obvious example. Entries on this Register reflect how buildings are grouped and recorded on the statutory list.

Structures can occasionally be both listed as buildings and scheduled as monuments.

Criteria for inclusion on this Register

Buildings (not in use as a public place of worship) considered for inclusion on this Register must be listed grade I or II*, (or grade II in London) or be a structural scheduled monument. Buildings are assessed for inclusion on the basis of condition and, where applicable, occupancy (or use). The condition of buildings on the Register ranges from 'very bad' to 'poor', 'fair' and (occasionally) 'good'. The Register also includes buildings that are vulnerable to becoming at risk because they are empty, under-used or face redundancy without a new use to secure their future.

Occupancy (or use) is noted as 'vacant', 'part occupied', 'occupied', or occasionally, 'unknown'; for many structural monuments, occupancy is not applicable.

Assessing vulnerability in the case of a building in fair condition necessarily involves judgement and discretion. A few buildings on the Register are in good condition, having been repaired or mothballed, but a new use or owner is still to be secured.

Buildings are removed from the Register when they are fully repaired/consolidated, their future secured, and where appropriate, occupied or in use.

Listed places of worship

Places of worship are the largest single group of non-domestic historic buildings still in use primarily for the purpose for which they were built. Their complex development over centuries is a testament to the changes in social, political and liturgical attitudes over time. This reflects the developing mission of congregations and means that they protect a wide range of fittings and furnishings of national and international importance. Their architectural, archaeological, aesthetic and historic significance is outstanding but so too is their value as the record of the endeavours and experiences of individuals and communities.

To date English Heritage has assessed only a small proportion of the 14,500 listed places of worship so the number identified so far as 'at risk' and included on this year's Register is small. In the coming years an increasing number of places of worship will be assessed to identify those that are at risk. Future registers will provide stronger evidence and build up our understanding of the challenges.

Criteria for inclusion on this Register

Places of worship considered for inclusion on this Register must be listed grade I, II* or II and be used as a public place of worship at least six times a year.

Places of worship are assessed on the basis of condition only. If the place of worship is in 'very bad' or 'poor' condition it is added to the Register. Places of worship previously included on the Register may be in any condition category.

Once on the Register, all places of worship can move through the condition categories (e.g. from very bad to poor; to fair; even good) as repairs are implemented and the condition improves, until they are fully repaired and can be removed from the Register.

Priority for action

Once a building is identified as at risk or vulnerable and included on the Register, priority for action is assessed on a scale of A to F, where 'A' is the highest priority for a building which is deteriorating rapidly with no solution to secure its future, and 'F' is the lowest priority where a repair scheme is in progress and an end use has been secured.

SCHEDULED MONUMENTS

Definition

Scheduled monuments include archaeological sites and landscapes, and 19,731 examples have been designated because of their national importance. Scheduled monuments are not graded, and most have limited potential for beneficial use. They cover human activity from the prehistoric era, such as burial mounds, to 20th century military and industrial remains. For the millennia before written history, archaeology is the only testament to innumerable generations of people of whom there is no other record.

The later 20th century saw unprecedented changes to the landscape. As a result, types of historic site that once were commonplace began to become rare. Those that survive often represent just small islands of what once characterised broad sweeps of our towns and countryside. Although protected by law, scheduled monuments are still at risk from a wide range of processes. In particular, they can frequently be exposed to intense pressures beyond the reach of the planning system. These include damage from cultivation, forestry and – often most seriously of all – wholly natural processes such as scrub growth, animal burrowing and erosion.

Criteria for inclusion on this Register

Scheduled monuments included on this Register have been identified as being at risk because of their condition and vulnerability, the trend in their condition, and their likely future vulnerability. A site's condition is expressed in terms of the scale and severity of adverse effects on it, ranging from those with 'extensive significant problems' to others that have only 'minor localised problems'.

Monuments are removed from the Register once sufficient progress has been made to address identified issues, demonstrating a significant reduction in the level of risk.

REGISTERED PARKS AND GARDENS

Definition

There are 1,610 designed landscapes on the current English Heritage *Register of Historic Parks and Gardens of Special Historic Interest*. These registered landscapes are graded I, II* or II, and include private gardens, public parks and other green spaces, country estates and cemeteries. They are valued for their design, diversity and historical importance and in contrast to the number of listed buildings and scheduled monuments, registered parks and gardens is a very small group of assets.

Inclusion on the English Heritage Register of Historic Parks and Gardens brings no additional statutory controls, but there is a presumption in favour of conservation of the designated site. Local authorities are required to consult English Heritage on applications affecting sites registered as grade I or II* and the Garden History Society on sites of all grades.

Criteria for inclusion on this Register

The identification of registered parks and gardens at risk begins with an appraisal of the condition and vulnerability of each registered landscape. Steps being taken by owners to address problems are also taken into consideration.

Landscapes assessed as being at risk are typically affected by development and neglect. They have frequently been altered by development or are faced with major change. The original function of these landscapes has often changed; and divided ownership often results in the loss of the cohesive conservation of the historic designs.

Landscapes are removed from the Register once plans are put in place to address issues and positive progress is being made.

REGISTERED BATTLEFIELDS

Definition

English Heritage's *Register of Historic Battlefields* has identified 43 nationally significant sites ranging in date from 991 to 1685. These are places where people risked their lives fighting for a cause and where history was made. The outcome of these battles was influenced by where they were fought and traces of the events will have been left across the landscape. Battlefields are cherished for many reasons, as a commemoration of the event and those who died, as a resource for understanding the course of the battle, and for the light they can shed on the times in which the battle was fought. They are vulnerable to insensitive development and to poorly managed investigation such as large-scale metal-detecting. While this designation introduces no additional statutory controls, one of its primary objectives is to encourage policies and other mechanisms that ensure that change and development affecting battlefields is sensitive and appropriate.

Criteria for inclusion on this Register

Battlefields deemed to be at risk of loss of historic significance are included on this Register:

The identified risks and threats come from development pressure – for example, because they lie on urban fringes or are subject to development pressures within the site; arable cultivation, and unregulated metal-detecting. One major impact or a combination of several factors can be enough to raise the risk at a particular site.

Battlefields are removed from the Register when either actual damaging activities are reversed or managed, or threats recede due to effective management planning.

PROTECTED WRECK SITES

Definition

England's 46 protected wreck sites represent a tiny proportion of the 32,476 pre-1945 wrecks and recorded casualties that are known to lie in the territorial sea. Wreck sites can be of importance for different reasons: the distinctive design or construction of a ship, the story it can tell about its past, its association with notable people or events, its cargo, flora and fauna or its role as a focus for the local community. The Protection of Wrecks Act 1973 empowers the appropriate Secretary of State to designate a restricted area around a vessel to protect it or its contents from unauthorised interference.

Local authorities are able to react to foreshore infrastructure projects through the planning process, thereby securing the preservation of important remains in this intertidal zone.

Criteria for inclusion on this Register

English Heritage has audited all designated wreck sites to identify those most at risk based on their current condition, vulnerability and the way they are being managed. Wrecks are vulnerable to both environmental and human impacts. Risks that contribute to the inclusion on the Register range from unauthorised access to erosion and fishing damage.

The monitoring process ensures that the significance of the site is identified and maintained.

In spite of the inherent difficulties in caring for this type of site, careful management must be maintained.

Wrecks are removed from the Register once an appropriate management and monitoring regime is operational.

CONSERVATION AREAS

Definition

Conservation areas are designated by local authorities and are areas of special architectural or historic interest the character or appearance of which it is desirable to preserve or enhance. For more than 40 years conservation areas have proved a highly effective mechanism for managing change on an area-wide basis. There are currently some 9,300 conservation areas in England including town and city centres, suburbs, industrial areas, rural landscapes, cemeteries and residential areas. They form the historic backcloth to national and local life and are a crucial component of local identity and community cohesion.

Criteria for inclusion on this Register

English Heritage has asked every local authority in England to complete (and update as appropriate) a survey of its conservation areas, highlighting current condition, threats and trends, identifying those that are deteriorating, or are in very bad or poor condition and are not expected to change significantly in the next three years, as being defined as at risk.

The methodology for assessing conservation areas at risk has been refined since the first survey in 2008/2009. The information collated provides a detailed assessment of each conservation area and an overall category for condition, vulnerability and trend is included for each conservation area on this Register. Conservation areas identified as at risk in 2009, but not reassessed since using the revised methodology, are included on the Register but with more limited information.

Conservation areas are removed from the Register once plans have been put in place to address the issues that led to the conservation area being at risk, and once positive progress is being made.

Key to the entries

This register includes the following heritage assets at risk:

- grade I and II* listed buildings and structural scheduled monuments
- grade I, II* and II listed places of worship
- scheduled monuments
- registered parks and gardens
- registered battlefields
- protected wreck sites
- conservation areas

ORDER

Entries are grouped and ordered alphabetically first by County or Unitary Authority, and then by Local Planning Authority (Unitary Authority/National Park/District or Borough).

Asset types are grouped within the relevant planning authority in the following order:

- listed buildings and structural scheduled monuments
- places of worship
- scheduled monuments
- registered parks and gardens
- registered battlefields
- protected wreck sites (listed at the end of the County off which they are located)
- conservation areas

Within each asset type, sites are ordered alphabetically by district (for sites in national parks), parish, locality, street/site name.

DESIGNATION

The principal designation is noted for each entry, and includes:

- Listed Building (LB) grade I, II* or II
- Listed Place of Worship grade I, II* or II
- Scheduled Monument (SM)
- Registered Park and Garden (RPG) grade I, II* or II
- Registered Battlefield
- Protected Wreck Site
- Conservation Area (CA)

Other designations that apply to buildings at risk and registered parks and gardens at risk, including their location within a World Heritage Site (WHS), are also noted where applicable.

The National Heritage List for England reference number is noted for scheduled monuments.

CONDITION

For buildings (including places of worship) at risk, condition is graded as: 'very bad', 'poor', 'fair' and 'good'.

For sites that cover areas (scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites) one overall condition category is recorded. The category may relate only to the part of the site or monument that is at risk and not the whole site:

- extensive significant problems
- generally unsatisfactory with major localised problems
- generally satisfactory but with significant localised problems
- generally satisfactory but with minor localised problems
- optimal
- unknown (is noted for a number of scheduled monuments that are below-ground and where their condition cannot be established).

For conservation areas, condition is categorised as: 'very bad', 'poor', 'fair' and 'optimal'.

OCCUPANCY / USE

For buildings (excluding places of worship) that can be occupied or have a use, the main vulnerability is vacancy, or under-use. Occupancy (or use) is noted as follows:

- vacant
- part occupied
- occupied
- unknown
- not applicable

VULNERABILITY

Principal vulnerability is noted for scheduled monuments and may relate only to the part of the monument which is at risk, and include:

- animal burrowing
- arable ploughing
- coastal erosion
- collapse
- deterioration – in need of management
- scrub / tree growth
- visitor erosion.

For registered parks and gardens, registered battlefields, protected wreck sites and conservation areas, vulnerability is noted as high, medium or low.

PRIORITY

For buildings at risk, the following priority categories are used as an indication of trend and as a means of prioritising action:

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

If the priority category has changed since the 2010 Register, the previous category is given in brackets.

TREND

Trend for scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites may relate only to the part of the site that is at risk and is categorised as:

- declining
- stable
- improving
- unknown

For conservation areas trend is categorised as:

- deteriorating
- deteriorating significantly
- no significant change
- improving
- improving significantly
- unknown

OWNERSHIP

A principal ownership category is given for each entry, although many scheduled monuments, registered parks and gardens, and registered battlefields are in divided ownership. For registered parks and gardens, single or multiple ownership is noted.

CONTACT

This is the member of the English Heritage regional team who acts as a first point of contact for the case, and to whom enquiries should be addressed.

For conservation areas, the contact is the conservation/planning officer at the relevant local planning authority (indicated by 'LPA' on the Register).

We are not in any sense agents for the owners of the sites included, but we will endeavour to put people in touch with them where appropriate.

ABBREVIATIONS

CA	Conservation Area
EH	English Heritage
HLF	Heritage Lottery Fund
LA/LPA	Local Planning Authority
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

South East heritage assets at risk

	Buildings at risk	Places of worship at risk	Scheduled monuments at risk	Registered parks and gardens at risk	Registered battlefields at risk	Protected wreck sites at risk	Conservation areas at risk
BRACKNELL FOREST (UA)							
Bracknell Forest (UA)	0	0	0	2	0	0	0
BRIGHTON AND HOVE, CITY OF (UA)							
Brighton and Hove, City of (UA)	5	0	0	0	0	0	5
SOUTH DOWNS (NP)							
South Downs (NP)	1	0	1	0	0	0	1
South Downs (NP) / Brighton and Hove, City of (UA) / Lewes*	0	0	0	1	0	0	0
BUCKINGHAMSHIRE							
Aylesbury Vale	7	1	2	1	0	0	0
Aylesbury Vale / Dacorum*	0	0	0	1	0	0	0
Chiltern	0	0	0	0	0	0	0
South Bucks	1	0	0	0	0	0	6
Wycombe	0	2	7	0	0	0	0
Wycombe / South Oxfordshire / Wokingham (UA)*	0	0	0	1	0	0	0
EAST SUSSEX							
Eastbourne	3	0	0	0	0	0	0
Hastings	4	1	1	0	0	0	0
Lewes	1	0	0	0	0	0	1
Rother	6	0	1	0	0	0	0
South Downs (NP)	0	1	10	0	0	0	0
Wealden	2	0	2	1	0	0	0
OFF EAST SUSSEX							
	0	0	0	0	0	1	0
HAMPSHIRE							
Basingstoke and Deane	2	0	6	0	0	0	0
East Hampshire	0	0	1	0	0	0	0
Eastleigh	0	0	0	0	0	0	0
Fareham	3	1	0	0	0	0	0
Gosport	4	0	0	0	0	0	0
Hart	2	0	1	2	0	0	0
Havant	0	0	0	0	0	0	0
New Forest	0	0	7	0	0	0	0
New Forest (NP)	2	0	12	0	0	0	0
Rushmoor	2	0	0	0	0	0	0
South Downs (NP)	3	1	13	0	0	0	8
Test Valley	0	0	16	1	0	0	0
Winchester	3	0	3	0	0	0	11
ISLE OF WIGHT (UA)							
Isle of Wight (UA)	4	2	5	1	0	0	5

KENT								
Ashford	3	1	1	0	0	0	0	0
Canterbury	4	1	1	0	0	0	0	0
Dartford	0	0	2	0	0	0	0	0
Dover	4	0	5	0	0	0	0	0
Gravesham	1	2	0	0	0	0	0	0
Maidstone	7	1	2	0	0	0	0	2
Sevenoaks	0	1	1	1	0	0	0	7
Sevenoaks / Tunbridge Wells*	0	0	0	1	0	0	0	0
Shepway	5	1	4	0	0	0	0	0
Swale	11	2	0	0	0	0	0	0
Thanet	3	1	8	0	0	0	0	0
Tonbridge and Malling	1	0	3	0	0	0	0	0
Tunbridge Wells	1	0	1	0	0	0	0	1
Tunbridge Wells / Tonbridge and Malling*	0	0	0	1	0	0	0	0
Tunbridge Wells / Wealden*	0	0	0	1	0	0	0	0
OFF KENT								
Off Kent	0	0	0	0	0	0	5	0
MEDWAY (UA)								
Medway (UA)	12	0	0	0	0	0	0	3
MILTON KEYNES (UA)								
Milton Keynes (UA)	1	0	6	0	0	0	0	0
OXFORDSHIRE								
Cherwell	1	2	6	0	0	0	0	6
Oxford	1	1	1	0	0	0	0	0
South Oxfordshire	5	3	11	0	0	0	0	0
Vale of White Horse	0	0	9	0	0	0	0	0
West Oxfordshire	0	2	26	0	0	0	0	0
PORTSMOUTH, CITY OF (UA)								
Portsmouth, City of (UA)	11	1	0	0	0	0	0	0
READING (UA)								
Reading (UA)	1	0	1	0	0	0	0	0
SLOUGH (UA)								
Slough (UA)	0	0	0	0	0	0	0	0
SOUTHAMPTON, CITY OF (UA)								
Southampton, City of (UA)	3	1	0	0	0	0	0	0
SURREY								
Elmbridge	3	0	0	0	0	0	0	1
Epsom and Ewell	1	0	0	0	0	0	0	5
Guildford	0	1	2	1	0	0	0	0
Mole Valley	2	0	4	1	0	0	0	0
Reigate and Banstead	1	0	0	0	0	0	0	0
Runnymede	0	0	1	1	0	0	0	0
Spelthorne	0	1	0	0	0	0	0	0
Surrey Heath	0	0	0	0	0	0	0	0
Tandridge	1	0	0	0	0	0	0	0
Waverley	0	0	1	0	0	0	0	0
Woking	0	0	0	1	0	0	0	0
WEST BERKSHIRE (UA)								
West Berkshire (UA)	6	2	7	3	1	0	0	0

WEST SUSSEX							
Adur	1	0	0	0	0	0	1
Arun	2	0	0	0	0	0	0
Chichester	1	0	0	0	0	0	1
Crawley	0	0	0	0	0	0	0
Horsham	2	1	2	0	0	0	1
Mid Sussex	0	0	1	0	0	0	0
South Downs (NP)	5	1	24	1	0	0	0
Worthing	1	1	0	0	0	0	0
OFF WEST SUSSEX							
Off West Sussex	0	0	0	0	0	1	0
WINDSOR AND MAIDENHEAD (UA)							
Windsor and Maidenhead (UA)	2	0	0	0	0	0	1
WOKINGHAM (UA)							
Wokingham (UA)	2	0	4	1	0	0	0
TOTAL	160	36	222	24	1	7	66

*Sites that cross LPA boundaries

BRACKNELL FOREST (UA)



SITE NAME:	Newbold College (formerly Moor Close), Binfield
DESIGNATION:	Registered Park and Garden Grade II*, also 7 LBs
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Declining
OWNER TYPE:	Corporate, single owner

Moor Close estate, now the home of Newbold College, was Oliver Hill's first house and garden design in an early C20 Arts & Crafts style. The hard landscape features are deteriorating and in urgent need of renovation. A condition survey was completed with a grant from English Heritage but an ensuing application to the Heritage Lottery Fund was unsuccessful. Further resources and action are urgently needed. The garden and park setting is also threatened by a cluster of housing development under consideration. Contact: Kathryn Davies 01483 252028



SITE NAME:	Broadmoor Hospital, Crowthorne
DESIGNATION:	Registered Park and Garden Grade II, also 1 LB
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Declining
OWNER TYPE:	Corporate, single owner

A mid C19 asylum, built for the criminally insane to designs by Joshua Jebb. The site is undergoing major redevelopment. The secure psychiatric hospital is to be relocated and the main building converted to an hotel. The extensive walled garden is to be developed for housing. The ornamented farmland has survived but needs managing. Close liaison with the owner and local authority is necessary to ensure what remains in terms of historic significance can be salvaged.

Contact: Kathryn Davies 01483 252028

BRIGHTON AND HOVE, CITY OF (UA)



SITE NAME:	Saltdean Lido, Marine Drive, Saltdean
DESIGNATION:	Listed Building Grade II*
CONDITION:	Poor
OCCUPANCY:	Occupied
PRIORITY:	C (New entry)
OWNER TYPE:	Local authority

Lido of 1938 by RWH Jones in Moderne style. It is suffering from a maintenance backlog and there is a particular deterioration of its reinforced concrete.

Contact: Tom Foxall 01483 252035



SITE NAME:	The West Pier, Kings Road, Brighton
DESIGNATION:	Listed Building Grade I, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY:	A (A)
OWNER TYPE:	Trust

Pier, 1864-66 by Eugenius Birch. Closed in 1975. English Heritage has declared its view that the combination of significant damage and cost of repair make restoration from public funds uneconomic.

Contact: Tom Foxall 01483 252035



SITE NAME:	Marlborough House, 54 Old Steine, Brighton and Hove, Brighton
DESIGNATION:	Listed Building Grade I, CA
CONDITION:	Fair
OCCUPANCY:	Vacant
PRIORITY:	E (C)
OWNER TYPE:	Private

House, now office. Built 1765, remodelled in 1786 by Robert Adam. Some holding repairs have recently been carried out, but the building is currently vacant.

Contact: Tom Foxall 01483 252035



SITE NAME:	53 Brunswick Square, Hove
DESIGNATION:	Listed Building Grade I, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied
PRIORITY:	C (C)
OWNER TYPE:	Private

Terraced house by A Wids and C A Busby, 1825-27. Used for multiple occupancy but now largely vacant. The rear elevation and outbuildings are in poor condition and parts of the building are not habitable. Made temporarily weathertight but no long-term solution in place.

Contact: Tom Foxall 01483 252035

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	Mews building to the rear of No. 14, 14 Brunswick Square, East Sussex, Hove	Terraced house, 1825-7. Mews to the rear of 14 Brunswick Square circa 1825. Repair works underway, but not complete.
DESIGNATION:	Listed Building Grade I, CA	
CONDITION:	Poor	
OCCUPANCY:	Part occupied	
PRIORITY:	F (F)	
OWNER TYPE:	Private	Contact: Tom Foxall 01483 252035

SITE NAME:	Benfield Barn	
DESIGNATION:	Conservation Area	CONDITION: Poor
VULNERABILITY:	Low	TREND: Deteriorating
CONTACT:	Tim Jefferies (LPA) 01273 293152	NEW ENTRY?: No

SITE NAME:	East Cliff	
DESIGNATION:	Conservation Area	CONDITION: Poor
VULNERABILITY:	Low	TREND: Deteriorating
CONTACT:	Tim Jefferies (LPA) 01273 293152	NEW ENTRY?: No

SITE NAME:	Queen's Park	
DESIGNATION:	Conservation Area	CONDITION: Poor
VULNERABILITY:	Medium	TREND: Deteriorating
CONTACT:	Tim Jefferies (LPA) 01273 293152	NEW ENTRY?: No

SITE NAME:	Sackville Gardens	
DESIGNATION:	Conservation Area	CONDITION: Poor
VULNERABILITY:	Low	TREND: Deteriorating
CONTACT:	Tim Jefferies (LPA) 01273 293152	NEW ENTRY?: No

SITE NAME:	Valley Gardens	
DESIGNATION:	Conservation Area	CONDITION: Very bad
VULNERABILITY:	Low	TREND: Deteriorating
CONTACT:	Tim Jefferies (LPA) 01273 293152	NEW ENTRY?: No

SOUTH DOWNS (NP)



SITE NAME:	The stables at Stanmer House, Stanmer Park, Brighton	Stables probably C18. Much altered and largely empty for some years.
DESIGNATION:	Listed Building Grade II*, CA	
CONDITION:	Poor	
OCCUPANCY:	Part occupied	
PRIORITY:	D (D)	
OWNER TYPE:	Private	Contact: Tom Foxall 01483 252035

SITE NAME:	Earthworks and lynchets near Eastwick Barn, Patcham, Brighton and Hove	
DESIGNATION:	Scheduled Monument (No. 1002303)	CONDITION: Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND: Declining
OWNER TYPE:	Local Authority	CONTACT: Paul Roberts 01483 252032

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SOUTH DOWNS (NP)

SITE NAME: **Stanmer, Brighton and Hove**

DESIGNATION: Conservation Area

CONDITION: Very bad

VULNERABILITY: Low

TREND: No significant change

CONTACT: Tim Jefferies (LPA) 01273 293152

NEW ENTRY: No

SOUTH DOWNS (NP) / BRIGHTON AND HOVE, CITY OF (UA) / LEWES

SITE NAME: **Stanmer Park, Stanmer, Ditching / Falmer / Westmeston**

DESIGNATION: Registered Park and Garden Grade II, also part in CA, 19 LBs, 3 SMs

CONDITION: Extensive significant problems

VULNERABILITY: High

TREND: Stable

OWNER TYPE: Mixed, multiple owners

C18 estate village set in a landscape park with informal pleasure grounds. Brighton Borough bought it in 1947 as a public amenity but the park was left to decline. There are multiple ownership issues and implementation of the landscape restoration management plan (2003) progresses as opportunities arise. A road widening scheme is to slice through the southern boundary wall. However, the 2010 extension of the Conservation Area should increase protection for that part of the park and garden.

Contact: Peter Kendall 01483 252038

BUCKINGHAMSHIRE

AYLESBURY VALE

SITE NAME: **Barn at New Manor Farm, Broughton Lane, Bierton with Broughton**

DESIGNATION: Listed Building Grade II*

CONDITION: Very bad

OCCUPANCY: Vacant

PRIORITY: A (A)

OWNER TYPE: Private

Barn, late C12 and later. Propped with scaffolding and with a temporary roof covering. Urgent works have been carried out. A historic building analysis has been carried out with English Heritage grant aid.

Contact: Richard Peats 01483 252026

SITE NAME: **Mentmore Towers, Mentmore**

DESIGNATION: Listed Building Grade I, RPG II*

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: A (A)

OWNER TYPE: Company

Building vacant for a number of years. Listed building consent and planning permission granted for conversion to a hotel together with a major extension. Planning for the implementation of these consents has stopped 2009. Emergency works undertaken to central roof lantern. The service wing roof remains in very poor condition.

Contact: Richard Peats 01483 252026

SITE NAME: **New Inn Farmhouse with outbuildings behind, Stowe**

DESIGNATION: Listed Building Grade II*, CA, RPG I

CONDITION: Good

OCCUPANCY: Vacant

PRIORITY: F (F)

OWNER TYPE: Trust

Former coaching inn, now farmhouse, 1717-19 and later. Built for visitors to Stowe House and garden. Acquired by the National Trust. Works in progress on repair; conversion and new building for visitor centre due for completion Autumn 2011.

Contact: Richard Peats 01483 252026

SITE NAME: **Temple of Friendship, Stowe Landscape Garden, Stowe**

DESIGNATION: Listed Building Grade I, CA, RPG I

CONDITION: Very bad

OCCUPANCY: N/A

PRIORITY: C (C)

OWNER TYPE: Trust

Garden temple, 1739, situated in the south-east corner of the pleasure gardens, close to the Palladian Bridge and with views to the north over the lake and Hawkwell Field beyond. The Tuscan portico has been consolidated and has a new roof, however the cellar and two flanking loggias remain roofless.

Contact: Richard Peats 01483 252026

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	The East Boycott Pavilion, Stowe Landscape Garden, Stowe
DESIGNATION:	Listed Building Grade I, CA, RPG I
CONDITION:	Poor
OCCUPANCY:	Part occupied
PRIORITY:	C (C)
OWNER TYPE:	Trust

One of a pair of large stone pavilions, circa 1728, by James Gibbs, incorporating domestic accommodation. Situated either side of the Oxford Avenue, at the south-west of The Course which is the main approach to the house. Roof repairs needed and cupola needs reinstating.

Contact: Richard Peats 01483 252026



SITE NAME:	The Palladian Bridge, Stowe Landscape Garden, Stowe
DESIGNATION:	Listed Building Grade I, CA, RPG I
CONDITION:	Fair
OCCUPANCY:	N/A
PRIORITY:	D (D)
OWNER TYPE:	Trust

Covered bridge built in 1738; attributed to James Gibbs, situated in the south-east corner of the pleasure grounds. Bridge is viewed from the west across the Octagon Lake, and from the north-west and north across Hawkwell Fields. Steady decay of the roof covering, ceiling plaster and masonry. Holding repairs have been carried out, but more work needed.

Contact: Kathryn Davies 01483 252028



SITE NAME:	The Queens Temple, Stowe Landscape Garden, Stowe
DESIGNATION:	Listed Building Grade I, CA, RPG I
CONDITION:	Fair
OCCUPANCY:	Occupied
PRIORITY:	F (F)
OWNER TYPE:	Trust

Pavilion of 1740, attributed to James Gibbs, remodelled 1770. Sited c300m to east of house in pleasure grounds. Main views from the temple to the south, over fields to the Gothic temple, Palladian Bridge and Temple of Friendship. Overflow detection installed in roof, including a new chute. Masonry repairs completed. Works to interior and roofs to be carried out. Structural monitoring of portico being carried out.

Contact: Richard Peats 01483 252026



SITE NAME:	Church of St Mary the Virgin, Church Lane, Ludgershall
DESIGNATION:	Listed Place of Worship Grade I, CA
CONDITION:	Poor
PRIORITY:	D (New entry)
OWNER TYPE:	Religious organisation

Largely C14 church with C19 restorations. In March 2010 vandals stole much of the lead from the roof of the nave, leaving the timber work open to the elements. Repairs required to decaying roof timbers and lead roof covering. Renewal of rainwater disposal systems on tower; nave aisles and porch and stonework repairs and repointing. Deathwatch beetle infestation to damp timbers evident. A Repair Grant for Places of Worship has been offered to support these remedial works.

Contact: Jane Wilkinson 01483 252029

SITE NAME:

A small multivallate hillfort on Southend Hill, Cheddington

DESIGNATION:	Scheduled Monument (No. 1017517)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:

A slight univallate hillfort 600m south east of Home Farm, Maids Moreton

DESIGNATION:	Scheduled Monument (No. 1018453)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027



SITE NAME:	Halton House, Halton / Aston Clinton
DESIGNATION:	Registered Park and Garden Grade II, also part in CA, 5 LBs
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Stable
OWNER TYPE:	Mixed, multiple owners

A Rothschild country house with late C19 formal gardens and park with woodland rides. The estate was sold to the RAF in 1918 and Halton House is now the Officers' Mess. The Forestry Commission manage the woodland rides. Some of the ornamental features of the garden are in poor condition. A landscape Conservation Management Plan has been written and will be used for assessing options for a proposed accommodation block.

Contact: Kathryn Davies 01483 252028

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

BUCKINGHAMSHIRE / HERTFORDSHIRE

AYLESBURY VALE / DACORUM



SITE NAME:	Mentmore Towers, Mentmore / Cheddington / Tring Rural
DESIGNATION:	Registered Park and Garden Grade II*, also CA, 10 LBs
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Declining
OWNER TYPE:	Mixed, multiple owners

Sir Joseph Paxton designed both the house and the park and gardens. The house and gardens were sold in 2000 and permission granted in 2005 to convert to an hotel. The adjacent golf course was recently bought by the developer thus reuniting most of the site. The permission has not yet been implemented and at the moment Mentmore's future is still uncertain.

Contact: Kathryn Davies 01483 252028

BUCKINGHAMSHIRE

SOUTH BUCKS



SITE NAME:	Aviary at Dropmore House, Heathfield Road, Taplow
DESIGNATION:	Listed Building Grade I, RPG II
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY:	B (B)
OWNER TYPE:	Private

Aviary, early C19, situated on south side of the range of buildings to west of the house. Vandalised and neglected for some years. Situated within late C18 to early C19 gardens in a ruinous condition. The woodland to the north and west in a poor condition. The park to south and east is in good condition. Mansion has been repaired and converted to residential use. LBC granted for repair of aviary – not started.

Contact: Richard Peats 01483 252026

SITE NAME:	Burnham	
DESIGNATION:	Conservation Area	CONDITION: At risk
VULNERABILITY:	Unknown	TREND: Deteriorating
CONTACT:	Conservation & Design Team (LPA) 01895 837374	NEW ENTRY: No

SITE NAME:	Gerrards Cross Common	
DESIGNATION:	Conservation Area	CONDITION: At risk
VULNERABILITY:	Unknown	TREND: No significant change
CONTACT:	Conservation & Design Team (LPA) 01895 837374	NEW ENTRY: No

SITE NAME:	Iver	
DESIGNATION:	Conservation Area	CONDITION: At risk
VULNERABILITY:	Unknown	TREND: Deteriorating
CONTACT:	Conservation & Design Team (LPA) 01895 837374	NEW ENTRY: No

SITE NAME:	Stoke Green	
DESIGNATION:	Conservation Area	CONDITION: At risk
VULNERABILITY:	Unknown	TREND: No significant change
CONTACT:	Conservation & Design Team (LPA) 01895 837374	NEW ENTRY: No

SITE NAME:	Taplow Riverside	
DESIGNATION:	Conservation Area	CONDITION: At risk
VULNERABILITY:	Unknown	TREND: Unknown
CONTACT:	Conservation & Design Team (LPA) 01895 837374	NEW ENTRY: No

SITE NAME:	Uxbridge Lock	
DESIGNATION:	Conservation Area	CONDITION: At risk
VULNERABILITY:	Unknown	TREND: Unknown
CONTACT:	Conservation & Design Team (LPA) 01895 837374	NEW ENTRY: No

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

WYCOMBE



SITE NAME:	Church of St Mary the Virgin, Well Hill Road, Fawley Green, Fawley
DESIGNATION:	Listed Place of Worship Grade II*, CA
CONDITION:	Poor
PRIORITY:	D (New entry)
OWNER TYPE:	Religious organisation

Village church of medieval origins with extensive remodelling in the mid eighteenth century and major restoration in 1882-3. At risk due to stone decay to tower, including string courses and openings, roof tiling uneven, especially to south transept and defective leadwork to valley gutter, north of the chancel. A Repair Grant for Places of Worship has been offered to support the cost of repair work.

Contact: Andy White 01483 252047



SITE NAME:	Church of St Francis, Terriers, High Wycombe
DESIGNATION:	Listed Place of Worship Grade II*
CONDITION:	Poor
PRIORITY:	D (New entry)
OWNER TYPE:	Religious organisation

Skilfully planned and detailed suburban church set well back from the main road to the north east of the town centre. Has poor rainwater disposal system which has led to internal damage to plasterwork. A Repair Grant for Places of Worship has been offered to assist with the cost of repairs.

Contact: Andy White 01483 252047

SITE NAME:	Bledlow Cross, Bledlow cum Sauderton	
DESIGNATION:	Scheduled Monument (No. 1006950)	CONDITION: Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND: Declining
OWNER TYPE:	Private	CONTACT: Chris Welch 01483 252027

SITE NAME:	Two bowl barrows 450m north west of Slough Glebe Farm, part of the Sauderton Lee barrow cemetery, Bledlow cum Sauderton	
DESIGNATION:	Scheduled Monument (No. 1013952)	CONDITION: Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND: Declining
OWNER TYPE:	Private	CONTACT: Chris Welch 01483 252027

SITE NAME:	Bell barrow 260m WNW of Slough Glebe Farm, part of the Sauderton Lee barrow cemetery, Bledlow cum Sauderton	
DESIGNATION:	Scheduled Monument (No. 1013953)	CONDITION: Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND: Declining
OWNER TYPE:	Private	CONTACT: Chris Welch 01483 252027

SITE NAME:	Bowl barrow 140m WNW of Slough Glebe Farm, part of the Sauderton Lee round barrow cemetery, Bledlow cum Sauderton	
DESIGNATION:	Scheduled Monument (No. 1013954)	CONDITION: Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND: Declining
OWNER TYPE:	Private	CONTACT: Chris Welch 01483 252027

SITE NAME:	Roman villa east of Lodge Hill Farm, Bledlow cum Sauderton	
DESIGNATION:	Scheduled Monument (No. 1014599)	CONDITION: Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND: Declining
OWNER TYPE:	Private	CONTACT: Chris Welch 01483 252027

SITE NAME:	Motte and bailey castle, moated site and Roman villa immediately east of All Saint's Church, Great and Little Kimble	
DESIGNATION:	Scheduled Monument (No. 1018007)	CONDITION: Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND: Declining
OWNER TYPE:	Private	CONTACT: Chris Welch 01483 252027

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Roman villa north of Yewden Lodge, Hambleton		
DESIGNATION:	Scheduled Monument (No. 1014606)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

BUCKINGHAMSHIRE / OXFORDSHIRE**WYCOMBE / SOUTH OXFORDSHIRE / WOKINGHAM (UA)**

SITE NAME:	Fawley Court and Temple Island, Fawley / Henley-on-Thames / Remenham
DESIGNATION:	Registered Park and Garden Grade II*, also CA, 18 LBs
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	High
TREND:	Stable
OWNER TYPE:	Private, multiple owners

Early C18 garden and pleasure grounds surrounding a 1680s house set within a park landscaped by Lancelot Brown. Most of the estate and park are in separate ownership. Discussions with the new owner of the house and pleasure grounds are underway. English Heritage agreed to works to improve the vegetation structure within the gardens but requested a landscape Conservation Management Plan that engages with the other key owners, before agreeing to any further major works. A joined up approach to management is essential.


Contact: Kathryn Davies 01483 252028

EAST SUSSEX**EASTBOURNE**

SITE NAME:	Eastbourne Redoubt, Eastbourne
DESIGNATION:	Listed Building Grade II, SM, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied
PRIORITY:	C (C)
OWNER TYPE:	Local authority

A redoubt built as part of the Martello system, 1806. Main parts are in use as a museum. The aquarium building, which occupies casemates and the mast on the south west side, is in very poor condition. The surviving caponiers suffer from water ingress. Moat walls are decaying.

Contact: Paul Roberts 01483 252032



SITE NAME:	Martello Tower No. 64, Eastbourne
DESIGNATION:	Listed Building Grade II, SM
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	C (C)
OWNER TYPE:	Company

Martello tower, 1806. On the beach with a housing development nearby. The preservation of archaeological and historical significance will be the main consideration in assessing the suitability of proposals to convert Martello towers for residential use.

Contact: Paul Roberts 01483 252032



SITE NAME:	Martello Tower No. 66, Langney Point, Eastbourne
DESIGNATION:	Listed Building Grade II, SM
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	C (C)
OWNER TYPE:	Company

Martello tower, 1806. On the beach near the harbour entrance. The preservation of archaeological and historical significance will be the main consideration in assessing the suitability of proposals to convert Martello towers for residential use.

Contact: Paul Roberts 01483 252032

HASTINGS

SITE NAME:	Pelham Arcade, 1-12 & 12A Hastings
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied
PRIORITY:	A (New entry)
OWNER TYPE:	Private

Semi-subterranean arcade of shops, developed as the first part of the Pelham scheme by Joseph Kay in 1823-5. Poor drainage from the carriage drive above the Arcade and structural failures in its formerly glazed lantern have resulted in problems of damp, particularly to the rear.

Contact: Tom Foxall 01483 252035

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME: **Statue of Queen Anne south east of Holmhurst St Mary's School, The Ridge, Baldslow, Hastings**

DESIGNATION: Listed Building Grade II*

CONDITION: Very bad

OCCUPANCY: N/A

PRIORITY: A (A)

OWNER TYPE: Trust

Statue, 1711-12 in grounds of former convent (now sold separately). The statue is not being maintained and is deteriorating more rapidly through rainwater off overhanging trees and saline rain off the sea.

Contact: Tom Foxall 01483 252035



SITE NAME: **Remains of Manor House, Ore Place, Ore, Hastings**

DESIGNATION: Scheduled Monument, CA

CONDITION: Very bad

OCCUPANCY: N/A

PRIORITY: A (D)

OWNER TYPE: Local authority

Ruins of late medieval manor house surrounded by new housing development, close to Old St Helens Church. The ruins are being damaged by heavy vegetation growth.

Contact: Paul Roberts 01483 252032



SITE NAME: **Church of St Helen, Elphinstone Road, St Helens, Hastings**

DESIGNATION: Listed Building Grade II, SM

CONDITION: Very bad

OCCUPANCY: N/A

PRIORITY: D (D)

OWNER TYPE: Trust

Ruined church and burial ground. English Heritage grant given for repair of the tower and feasibility study, which has resulted in an application to Heritage Lottery Fund for a conservation, learning and access project.

Contact: Paul Roberts 01483 252032



SITE NAME: **Church of St Mary Magdalen, St Margaret's Road**

DESIGNATION: Listed Place of Worship Grade II, CA

CONDITION: Very bad

PRIORITY: A (New entry)

OWNER TYPE: Religious organisation

Decorated-style church in prominent position in St Leonards, with four-stage south west tower. Facing stonework and roofs in a fair condition but the tracery stonework is in a very poor condition.

Contact: Tom Foxall 01483 252035

SITE NAME:

Old St Helen's Church, Ore, Hastings

DESIGNATION:

Scheduled Monument (No. 1011845)

CONDITION:

Generally unsatisfactory with major localised problems

PRINCIPAL VULNERABILITY:

Collapse

TREND:

Declining

OWNER TYPE:

Private

CONTACT:

Paul Roberts 01483 252032

LEWES



SITE NAME: **Newhaven Fort; Caponier, Fort Road, Newhaven**

DESIGNATION: Scheduled Monument

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: C (F)

OWNER TYPE: Local authority

Caponier of Newhaven Fort. Victorian caponier is in very poor condition in places. Lunette battery was repaired with English Heritage grant by Lewes District Council in 2009.

Contact: Paul Roberts 01483 252032

SITE NAME:

Seaford Town Centre

DESIGNATION:

Conservation Area

CONDITION:

Poor

VULNERABILITY:

Medium

TREND:

Deteriorating

CONTACT:

Chris Morris (LPA) 01273 471600

NEW ENTRY:

No

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA Conservation Area
LB/LBs Listed Building/s
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM/SMs Scheduled Monument/s
UA Unitary Authority
WHS World Heritage Site

ROTHER



SITE NAME: **Martello Tower No. 55,
Normans Bay,
Bexhill**

DESIGNATION: Listed Building Grade II, SM

CONDITION: Fair

OCCUPANCY: Vacant

PRIORITY: F (F)

OWNER TYPE: Private

Martello tower built 1806. Work is underway to convert the tower for occasional residential use. This tower has been substantially altered in the past and the new work has been designed to have limited additional impact on its heritage significance and character.

Contact: Paul Roberts 01483 252032



SITE NAME: **Martello Tower No. 28,
Rye Harbour,
Icklesham**

DESIGNATION: Listed Building Grade II, SM

CONDITION: Very bad

OCCUPANCY: Vacant

PRIORITY: A (C)

OWNER TYPE: Private

A derelict martello tower built 1806. Situated on the edge of a caravan park. The preservation of archaeological and historical significance will be the main consideration in assessing the suitability of proposals to convert Martello towers for residential use.

Contact: Paul Roberts 01483 252032



SITE NAME: **Grey Friars (Winchelsea Priory),
Friars Road, Winchelsea,
Icklesham**

DESIGNATION: Listed Building Grade I, SM, CA

CONDITION: Poor

OCCUPANCY: N/A

PRIORITY: D (D)

OWNER TYPE: Private

Ruins of a monastic church circa 1310-20, in the grounds of a C19 mansion.

Contact: Paul Roberts 01483 252032



SITE NAME: **Grey Friars boundary wall,
Friars Road, Winchelsea,
Icklesham**

DESIGNATION: Scheduled Monument, CA

CONDITION: Very bad

OCCUPANCY: N/A

PRIORITY: A (B)

OWNER TYPE: Private

The C19 boundary wall to the Grey Friars mansion has suffered from multiple collapses and further collapses are likely.

Contact: Paul Roberts 01483 252032



SITE NAME: **Austin Friars Chapel,
Conduit Hill,
Rye**

DESIGNATION: Listed Building Grade II, SM, CA

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNER TYPE: Private

Remains of a friary chapel dating from about 1380. Vacant at present, but a new use is being sought. The window tracery is suffering from decay.

Contact: Paul Roberts 01483 252032



SITE NAME: **Martello Tower No. 30,
Winchelsea Road,
Rye**

DESIGNATION: Listed Building Grade II, SM

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNER TYPE: Private

Martello tower built 1806. Now nearly derelict and the moat and glacis on the east side lost. Unconnected with destruction of the moat and glacis, a small housing development was built adjacent to the east. The preservation of archaeological and historical significance will be the main consideration in assessing the suitability of proposals to convert Martello towers for residential use.

Contact: Paul Roberts 01483 252032

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Romano-British iron working site in Beauport Park, Battle		
DESIGNATION:	Scheduled Monument (No. 1002250)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Paul Roberts 01483 252032

SOUTH DOWNS (NP)

SITE NAME:	Parish Church of St Michael and All Angels, Plumpton, Lewes	Small parish church with large square tower to the west. Dates to the C12 with a C13 chancel. The church is located within Plumpton Agricultural College, but is in regular use for worship. The building is not well maintained and is suffering with slipped tiles to the north, blocked guttering, cement renders and dense ivy causing structural problems to the tower and internal damp. Plans for repairs are being prepared.	
DESIGNATION:	Listed Place of Worship Grade II*		
CONDITION:	Poor		
PRIORITY:	D (New entry)		
OWNER TYPE:	Religious organisation	Contact: Tom Foxall 01483 252035	

SITE NAME:	Anglo-Saxon cemetery 275m north of Comps Farm, Beddingham, Lewes		
DESIGNATION:	Scheduled Monument (No. 1021436)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Metal detecting	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Paul Roberts 01483 252032

SITE NAME:	Round barrow south of Ditchling Beacon, Ditchling, Lewes		
DESIGNATION:	Scheduled Monument (No. 1002254)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Paul Roberts 01483 252032

SITE NAME:	Bowl barrow 180m south west of Glydebourne Pit, Glyde, Lewes		
DESIGNATION:	Scheduled Monument (No. 1013355)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Metal detecting	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Paul Roberts 01483 252032

SITE NAME:	Bowl barrow 300m SSW of Glydebourne Pit, Glyde, Lewes		
DESIGNATION:	Scheduled Monument (No. 1013357)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Metal detecting	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Paul Roberts 01483 252032

SITE NAME:	Hillfort, bowl barrow and associated remains on The Caburn, Glyde, Lewes		
DESIGNATION:	Scheduled Monument (No. 1014527)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Metal detecting	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Paul Roberts 01483 252032

SITE NAME:	Bowl barrow on Front Hill, Iford, Lewes		
DESIGNATION:	Scheduled Monument (No. 1009950)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Paul Roberts 01483 252032

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHs	World Heritage Site

SITE NAME:	Multiple ring-ditch at Mount Pleasant, Denton, Newhaven, Lewes		
DESIGNATION:	Scheduled Monument (No. 1012144)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Paul Roberts 01483 252032

SITE NAME:	Bowl barrow forming part of a linear round barrow cemetery on Rookery Hill, Seaford, Lewes		
DESIGNATION:	Scheduled Monument (No. 1009953)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Paul Roberts 01483 252032

SITE NAME:	Two bowl barrows, the south easternmost pair of a group of six bowl barrows, forming part of a linear round barrow cemetery on Rookery Hill, Seaford, Lewes		
DESIGNATION:	Scheduled Monument (No. 1009951)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Paul Roberts 01483 252032

SITE NAME:	Round barrow south west of Bopeep Bostal, Alciston, Wealden		
DESIGNATION:	Scheduled Monument (No. 1002269)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Metal detecting	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Paul Roberts 01483 252032

WEALDEN



SITE NAME: **Ruins of Brambletye House, Forest Row**

DESIGNATION: Listed Building Grade I, SM
 CONDITION: Poor
 OCCUPANCY: N/A
 PRIORITY: A (New entry)
 OWNER TYPE: Private

The monument comprises the ruins and buried remains of an early 17th century country house, which was built by Sir Henry Compton in 1631 but slighted during the Civil War by Cromwellian troops. The upstanding remains include much of the north front, containing the main entrance and three towers, the remains of an undercroft and remains of a guardhouse. Parts of the structure are currently supported by scaffold.

Contact: Paul Roberts 01483 252032



SITE NAME: **Argos Hill Windmill, Argos Hill, Mayfield**

DESIGNATION: Listed Building Grade II*
 CONDITION: Poor
 OCCUPANCY: Vacant
 PRIORITY: D (D)
 OWNER TYPE: Local authority

Post mill suffering from lack of maintenance and scaffolded. The Argos Hill Windmill Trust have leased the windmill and have launched a fundraising campaign for its restoration.

Contact: Tom Foxall 01483 252035

SITE NAME:	Far Blacklands iron bloomery, Forest Row		
DESIGNATION:	Scheduled Monument (No. 1002231)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Paul Roberts 01483 252032

SITE NAME:	High Rocks Camp (part in Kent), Frant		
DESIGNATION:	Scheduled Monument (No. 1002280)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Paul Roberts 01483 252032

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
 If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	Kidbrooke Park, Forest Row
DESIGNATION:	Registered Park and Garden Grade II, also 2 LBs
CONDITION:	Extensive significant problems
VULNERABILITY:	Medium
TREND:	Declining
OWNER TYPE:	Mixed, multiple owners

C18 park with extensive C19 landscape features attributed to Humphry Repton and later formal and woodland gardens. The estate was sold in 1938 then further subdivided. The house became a Steiner school which has since sold perimeter land for development and built school facilities in the grounds. It is vulnerable to development. The Environment Agency is investigating the possibility of using the lower lake as a flood storage facility which has highlighted the need for an up-to-date Conservation Management Plan.

Contact: Peter Kendall 01483 252038

OFF EAST SUSSEX



SITE NAME:	Holland No. 5
DESIGNATION:	Protected Wreck Site
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Declining
OWNER TYPE:	Private
PHOTO:	© Crown Copyright, Wessex Archaeology

The Holland No.5 was designed and built by the Holland Torpedo Boat Company at Barrow-in-Furness and was launched in May 1902. She foundered on 8th August 1912 whilst under tow to the breakers yard. The site has been subject to unauthorised access and the removal of the bow torpedo hatch as well as fishing damage.

Contact: Simon Goodhugh 01483 252037

HAMPSHIRE

BASINGSTOKE AND DEANE



SITE NAME:	Barn at Manor Farm, Old Burghclere, Burghclere
DESIGNATION:	Listed Building Grade I
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY:	C (C)
OWNER TYPE:	Private

Manorial barn, 1451, built for the Bishop of Winchester. Suffering from water ingress and failure of joints, the building needs comprehensive repair. Emergency repairs have been carried out.

Contact: David Brock 01483 252044



SITE NAME:	London Lodge, Highclere Park, Highclere
DESIGNATION:	Listed Building Grade II*, RPG I
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	C (C)
OWNER TYPE:	Private

Ceremonial archway and attached accommodation, 1793. Only emergency repairs have been carried out and negotiations continue to allow it to be occupied.

Contact: David Brock 01483 252044

SITE NAME:

A cross dyke and bowl barrow on the northern spur of Beacon Hill, Burghclere

DESIGNATION:	Scheduled Monument (No. 1012033)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:

Long barrow 600m south of Preston Grange, Candovers

DESIGNATION:	Scheduled Monument (No. 1013009)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:

A bell barrow and a saucer barrow 315m ESE of the unfinished hillfort on Ladle Hill, Ecchinswell and Sydmonton

DESIGNATION:	Scheduled Monument (No. 1012035)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	The western of two rectangular enclosures on Great Litchfield Down, SSW of Ladle Hill, Litchfield and Woodcott		
DESIGNATION:	Scheduled Monument (No. 1012037)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Long barrow 250m south east of Willesley Warren Farm, Overton		
DESIGNATION:	Scheduled Monument (No. 1013006)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Round barrow south west of Lower Farm, Preston Candover		
DESIGNATION:	Scheduled Monument (No. 1005541)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

EAST HAMPSHIRE

SITE NAME:	Walldown enclosures, Whitehill		
DESIGNATION:	Scheduled Monument (No. 1017368)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Richard Massey 01483 252046

FAREHAM

SITE NAME:	Fort Fareham, Newgate Lane, Fareham
DESIGNATION:	Listed Building Grade II, SM
CONDITION:	Poor
OCCUPANCY:	Part occupied
PRIORITY:	A (A)
OWNER TYPE:	Company

Mid C19 fort forming part of a series of fortifications built to defend Portsmouth Harbour. Unoccupied parts suffering from decay and vandalism. Site now owned by various private companies.

Contact: Richard Massey 01483 252046



SITE NAME:	Barn at Fernhill Farm, Mill Lane, Titchfield, Fareham
DESIGNATION:	Listed Building Grade I, CA
CONDITION:	Fair
OCCUPANCY:	Vacant
PRIORITY:	C (C)
OWNER TYPE:	Private

Tithe barn, probably C15, formally part of Titchfield Abbey. Has been damaged by casual vandalism and needs repair and a new use.

Contact: David Brock 01483 252044



SITE NAME:	Titchfield Abbey and fishponds – “stables”, Mill Street, Titchfield, Fareham
DESIGNATION:	Scheduled Monument, CA
CONDITION:	Fair
OCCUPANCY:	N/A
PRIORITY:	D (D)
OWNER TYPE:	Private

Remains of possible stables to Titchfield Abbey. The Abbey was founded in 1232 and converted to a private residence in 1537. The “stables” are overgrown with vegetation and have some structural problems. Investigations leading to a repair programme are underway.

Contact: Richard Massey 01483 252046

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHs	World Heritage Site



SITE NAME: **St Marys Church, Portchester Castle, Castle Street, Portchester**

DESIGNATION: Listed Place of Worship Grade I, CA
 CONDITION: Poor
 PRIORITY: C (New entry)
 OWNER TYPE: Religious organisation

Romanesque church standing within the outer bailey of Portchester Castle. Flint and rendered walls with plain tiled roofs. At risk due to slipped and missing tiles to roofs, especially on the south slope of the nave. Rainwater disposal system to south and east slopes of the tower appears broken and defective. Open joints and vegetation growth to flint rubble walls, especially to tower. Water penetration internally to south west corner of chancel.

Contact: Andy White 01483 252047

GOSPORT



SITE NAME: **Fort Elson, RNAD, Military Road, Gosport**

DESIGNATION: Scheduled Monument
 CONDITION: Poor
 OCCUPANCY: Vacant
 PRIORITY: A (A)
 OWNER TYPE: Government

Polygonal artillery fort of 1853-60. Damaging vegetation has taken hold of the site. Programmes of vegetation removal are intermittent. A management plan has been drafted but not agreed or implemented. The building cannot be occupied because it lies within a munitions storage area.

Contact: Alan Johnson 020 7973 3174



SITE NAME: **Gilkicker Fort, Fort Road, Gilkicker Point, Gosport**

DESIGNATION: Listed Building Grade II*, SM
 CONDITION: Poor
 OCCUPANCY: Vacant
 PRIORITY: D (D)
 OWNER TYPE: Local authority

Artillery fort 1865-71. Owner has put barrack block into good order; but casemates and magazines are threatened by water penetration. Repair and conversion to residential units approved.

Contact: Richard Massey 01483 252046



SITE NAME: **Workshops, boilerhouse and engine room, Haslar Gunboat Yard, HMS Dolphin, Gosport**

DESIGNATION: Scheduled Monument, CA
 CONDITION: Poor
 OCCUPANCY: Vacant
 PRIORITY: A (A)
 OWNER TYPE: Company

Workshops, boiler house and offices, mid C19, cause concern. The buildings are already in a poor state of repair and are deteriorating. Parts are no longer stable (including sections of the workshops' roofs). There is no current use.

Contact: Richard Massey 01483 252046



SITE NAME: **Guardrooms to Haslar Gunboat Yard, Haslar Road, HMS Dolphin, Dolphin 3, Gosport**

DESIGNATION: Scheduled Monument, CA
 CONDITION: Poor
 OCCUPANCY: Vacant
 PRIORITY: A (C)
 OWNER TYPE: Government

The buildings have been unoccupied for many years and are derelict. In 1999 basic repairs were carried out to make the buildings weathertight but there has been no progress since then. An options study has been undertaken.

Contact: Alan Johnson 020 7973 3174

HART



SITE NAME: **Garden walls and associated structures, Bramshill House, Bramshill**

DESIGNATION: Listed Building Grade I, RPG II*
 CONDITION: Fair
 OCCUPANCY: N/A
 PRIORITY: E (E)
 OWNER TYPE: Government

Walls to early C17 and C18 formal walled gardens, surrounding the house, which is situated within a park of medieval origin, landscaped in the C17, C18 and C19. Some sections of the walls are in a poor condition, but the south-east turret and some parts of the garden walls have been repaired.

Contact: Elizabeth Moore 020 7973 3803

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
 If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

- CA** Conservation Area
LB/LBs Listed Building/s
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM/SMs Scheduled Monument/s
UA Unitary Authority
WHS World Heritage Site



SITE NAME:	High Bridge, Bramshill House, Bramshill
DESIGNATION:	Listed Building Grade I, RPG II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY:	D (D)
OWNER TYPE:	Government

The bridge is in poor condition, requiring repairs to structure and fabric. Some repairs were carried out in 2000-03 but further works are required.

Contact: Elizabeth Moore 020 7973 3803

SITE NAME: **Round barrow cemetery at Heath Brow, Ewshot, Crondall**

DESIGNATION:	Scheduled Monument (No. 1016891)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Richard Massey 01483 252046



SITE NAME:	Bramshill Park, Bramshill / Eversley
DESIGNATION:	Registered Park and Garden Grade II*, also part in CA, 8 LBs
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Stable
OWNER TYPE:	Corporate, multiple owners

Early C17 formal walled gardens within a park of medieval origin which was landscaped in the C17 and mid C18 and later deformed and enlarged. The site became the Police Staff College in 1952, the farmland being sold and put under commercial forestry. An up-to-date landscape Conservation Management Plan is required. Repairs have been carried out to some of the buildings at risk on the estate but further work is required.

Contact: David Brock 01483 252044



SITE NAME:	Warbrook House, Eversley
DESIGNATION:	Registered Park and Garden Grade II*, also 1 LB
CONDITION:	Extensive significant problems
VULNERABILITY:	Medium
TREND:	Declining
OWNER TYPE:	Mixed, multiple owners

The gardens were designed c1724 by the architect John James whose home it was. Major change occurred in the mid C20 with the conversion of the house to business use and the addition of new buildings and service areas. James' axes extend beyond the gardens but these, and the parkland, are perceived as without beneficial use and have deteriorated. A seminal site in garden history terms, this landscape needs an up-to-date Conservation Management Plan and the necessary resources and commitment to implement it.

Contact: David Brock 01483 252044

NEW FOREST

SITE NAME: **Giant's Grave: a long barrow 400m north west of Down Farm, Breamore**

DESIGNATION:	Scheduled Monument (No. 1015980)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME: **Bowl barrow 630m north of Hardley Bridge, Hythe and Dibden**

DESIGNATION:	Scheduled Monument (No. 1013136)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Richard Massey 01483 252046

SITE NAME: **Bowl barrow 330m north of Grim's Ditch, near Tidpit Common, Martin**

DESIGNATION:	Scheduled Monument (No. 1011000)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Richard Massey 01483 252046

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
 If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Long Barrow 800m north west of Paradise, Martin		
DESIGNATION:	Scheduled Monument (No. 1012512)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Duck's Nest: a long barrow on Rockbourne Down, Rockbourne		
DESIGNATION:	Scheduled Monument (No. 1012920)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Grans barrow: a long barrow 880m west of Down Farm, Rockbourne		
DESIGNATION:	Scheduled Monument (No. 1020740)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Long barrow 700m north west of Tenantry Farm, Rockbourne		
DESIGNATION:	Scheduled Monument (No. 1013002)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

NEW FOREST (NP)



SITE NAME:	Beaulieu Abbey, Beaulieu	Arcade of Chapter House and associated walls, part of C13 Abbey. Parts of arcade deteriorating and wall suffering from vegetation growth. Condition report completed.
DESIGNATION:	Scheduled Monument, CA	
CONDITION:	Very bad	
OCCUPANCY:	N/A	
PRIORITY:	C (C)	
OWNER TYPE:	Company	Contact: Richard Massey 01483 252046



SITE NAME:	Tide Mill, High Street, Beaulieu	Early C18, one of the few remaining tide mills. Repairs were largely complete before a fire (March 2006) which destroyed much of the roof.
DESIGNATION:	Listed Building Grade II*, CA	
CONDITION:	Poor	
OCCUPANCY:	Vacant	
PRIORITY:	C (C)	
OWNER TYPE:	Trust	Contact: David Brock 01483 252044

SITE NAME:	Bell barrow and two bowl barrows 180m south west of Stagbury Hill, Furzley Common, Bramshaw, New Forest		
DESIGNATION:	Scheduled Monument (No. 1016491)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Rabbit warren and four bowl barrows on Stagbury Hill, Furzley Common, Bramshaw, New Forest		
DESIGNATION:	Scheduled Monument (No. 1016490)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: Studley Castle royal hunting lodge, Bramshaw, New Forest			
DESIGNATION:	Scheduled Monument (No. 1016494)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Richard Massey 01483 252046

SITE NAME: Twin bowl barrow on Furzley Common, 810m SSW of Stagbury Hill, Bramshaw, New Forest			
DESIGNATION:	Scheduled Monument (No. 1016492)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME: Bowl barrow 320m west of Ober House, Brockenhurst, New Forest			
DESIGNATION:	Scheduled Monument (No. 1009888)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Richard Massey 01483 252046

SITE NAME: Hillfort 400m south of Home Farm, Denny Lodge, New Forest			
DESIGNATION:	Scheduled Monument (No. 1017019)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Richard Massey 01483 252046

SITE NAME: Medieval hunting lodge in Churchplace Inclosure, Denny Lodge, New Forest			
DESIGNATION:	Scheduled Monument (No. 1016715)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Richard Massey 01483 252046

SITE NAME: Three bowl barrows 420m south west of Pitts Copse Farm forming part of the Beaulieu Heath round barrow cemetery, Denny Lodge, New Forest			
DESIGNATION:	Scheduled Monument (No. 1013206)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME: Bowl barrow 360m west of Pitts Copse farm forming part of Beaulieu Heath round barrow cemetery, Fawley, New Forest			
DESIGNATION:	Scheduled Monument (No. 1017578)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME: Frankenbury hillfort, Godshill, New Forest			
DESIGNATION:	Scheduled Monument (No. 1019125)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Bowl barrow 400m south west of Robin Hood Farm, Minstead, New Forest		
DESIGNATION:	Scheduled Monument (No. 1012640)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Bowl barrow 550m north west of Avon Tyrrell, Ringwood, New Forest		
DESIGNATION:	Scheduled Monument (No. 1012637)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

RUSHMOOR



SITE NAME: **Building Q121 at Royal Defence Agency (24 foot wind tunnel), Hall Road, Farnborough**

Wind tunnel built 1934-35. The future use of the building is currently uncertain, but the owner is exploring imaginative solutions for re-use. Repairs are complete.

DESIGNATION: Listed Building Grade I

CONDITION: Fair

OCCUPANCY: Vacant

PRIORITY: E (F)

OWNER TYPE: Company

Contact: David Brock 01483 252044



SITE NAME: **Building R133 at Royal Defence Agency (Transonic Tunnel), O'Gorman Avenue, Farnborough**

Wind tunnel built 1939 and modified in 1956. The future use of the building is currently uncertain, but being actively explored by the owners. Repairs are complete.

DESIGNATION: Listed Building Grade I

CONDITION: Fair

OCCUPANCY: Vacant

PRIORITY: E (E)

OWNER TYPE: Company

Contact: David Brock 01483 252044

SOUTH DOWNS (NP)



SITE NAME: **Ruins of St Nicholas Chapel, Westbury, East Meon, East Hampshire**

Small ruined medieval church of possibly C13 date and later. Designated with associated earthwork remains of contemporary settlement. Ruins are suffering from vegetation growth.

DESIGNATION: Listed Building Grade II, SM

CONDITION: Very bad

OCCUPANCY: N/A

PRIORITY: A (New entry)

OWNER TYPE: Private

Contact: Richard Massey 01483 252046



SITE NAME: **Brambridge House, Kiln Lane, Colden Common, Winchester**

Country house, 1762 and 1872, suffering from deferred maintenance. Some repairs have been carried out but more are needed.

DESIGNATION: Listed Building Grade II*

CONDITION: Poor

OCCUPANCY: Occupied

PRIORITY: C (D)

OWNER TYPE: Company

Contact: David Brock 01483 252044

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	King Johns House, Warnford Park, Warnford, Winchester
DESIGNATION:	Listed Building Grade I, SM, RPG II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY:	B (B)
OWNER TYPE:	Company

Ruinous C13 hall house. A feature within the C18 pleasure grounds of Warnford Park, within which it is situated. Stop gap repairs have been carried out. Requires further consolidation and discussions taking place.

Contact: Richard Massey 01483 252046



SITE NAME:	Church of St Leonard, Hartley Mauditt, Worldham, East Hampshire
DESIGNATION:	Listed Place of Worship Grade II*, CA
CONDITION:	Poor
PRIORITY:	C (New entry)
OWNER TYPE:	Religious organisation

Isolated small rural church of Norman origins with C14 chancel. Collection of C17 and early C18 wall monuments to chancel. Major restoration work undertaken in 1854. It has rendered walls and a tiled roof. Sunday services are held during the summer months only. Some slippage of tiles to the south slope of the nave indicating failure of fixings, defective rainwater goods and drainage, with internal dampness and algal growth.

Contact: Andy White 01483 252047

SITE NAME:	Bowl barrow on Chalton Down, 350m south east of Manor Farm, Clanfield, East Hampshire		
DESIGNATION:	Scheduled Monument (No. 1020511)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Bowl barrow 620m north east of Warhill Cottage, East Meon, East Hampshire		
DESIGNATION:	Scheduled Monument (No. 1019116)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Group of four bowl barrows 660m north of Warhill Cottage, East Meon, East Hampshire		
DESIGNATION:	Scheduled Monument (No. 1019115)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Bowl barrow 60m south east of the junction of the A32 and Fawley Lane, part of The Jumps round barrow cemetery, Froxfield, East Hampshire		
DESIGNATION:	Scheduled Monument (No. 1019120)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Bowl barrow 100m south east of Lower Bordean Farm, Langrish, East Hampshire		
DESIGNATION:	Scheduled Monument (No. 1017051)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Three bowl barrows on Chalton Down, 860m east of Netherley Farm, Rowlands Castle, East Hampshire		
DESIGNATION:	Scheduled Monument (No. 1020512)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Bowl barrow 250m west of the junction of the A32 and Fawley Lane, part of The Jumps round barrow cemetery, West Tisted, East Hampshire		
DESIGNATION:	Scheduled Monument (No. 1019118)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Bowl barrow 330m south west of the junction of the A32 and Fawley Lane, part of The Jumps round barrow cemetery, West Tisted, East Hampshire		
DESIGNATION:	Scheduled Monument (No. 1019119)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Round barrow cemetery, Roman road and hollow ways 200m south west of Woolmer Cottages, Whitehill, East Hampshire		
DESIGNATION:	Scheduled Monument (No. 1020502)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Three disc barrows on Longmoor Common, 250m north west of the church, Whitehill, East Hampshire		
DESIGNATION:	Scheduled Monument (No. 1016843)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Two bowl barrows north of Hoe Farm, Bishops Waltham, Winchester		
DESIGNATION:	Scheduled Monument (No. 1013078)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Four round barrows in 'Hump Field' south of Stakes Lane, Corhampton and Meonstoke, Winchester		
DESIGNATION:	Scheduled Monument (No. 1001886)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Long barrow 640m south east of Stock's Farm, Corhampton and Meonstoke, Winchester		
DESIGNATION:	Scheduled Monument (No. 1012946)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Droxford, Winchester		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Historic Environment Team (LPA) 01962 848481	NEW ENTRY?:	No

SITE NAME:	Easton, Winchester		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Historic Environment Team (LPA) 01962 848481	NEW ENTRY?:	No

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Exton, Winchester		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Improving
CONTACT:	Historic Environment Team (LPA) 01962 848481	NEW ENTRY?:	No

SITE NAME:	Hambledon, Winchester		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Historic Environment Team (LPA) 01962 848481	NEW ENTRY?:	No

SITE NAME:	Itchen Stoke, Winchester		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Historic Environment Team (LPA) 01962 848481	NEW ENTRY?:	No

SITE NAME:	Martyr Worthy, Winchester		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Historic Environment Team (LPA) 01962 848481	NEW ENTRY?:	No

SITE NAME:	Twyford, Winchester		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Historic Environment Team (LPA) 01962 848481	NEW ENTRY?:	No

SITE NAME:	West Meon, Winchester		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Historic Environment Team (LPA) 01962 848481	NEW ENTRY?:	No

TEST VALLEY

SITE NAME:	Ashley Wood camp, Ashley		
DESIGNATION:	Scheduled Monument (No. 1014815)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Long barrow 400m south east of Moody's Down Farm, Barton Stacey		
DESIGNATION:	Scheduled Monument (No. 1012515)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Long barrow 400m west of Moody's Down Farm, Barton Stacey		
DESIGNATION:	Scheduled Monument (No. 1013201)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Long barrow and two bowl barrows, 400m north of Chattis Hill House, Broughton		
DESIGNATION:	Scheduled Monument (No. 1012998)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Two bowl barrows 90m south of Hill Lodge: part of a group of round barrows on Broughton Hill, Broughton		
DESIGNATION:	Scheduled Monument (No. 1014844)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046
SITE NAME:	Long barrow 300m south east of Middlebarn Farm, Chilbolton		
DESIGNATION:	Scheduled Monument (No. 1012517)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046
SITE NAME:	Castle Hill, Chilworth		
DESIGNATION:	Scheduled Monument (No. 1001885)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Richard Massey 01483 252046
SITE NAME:	Barrow cemetery 730m north of Hampshire Gap, Grately		
DESIGNATION:	Scheduled Monument (No. 1014817)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046
SITE NAME:	Bowl barrow 780m NNE of Hampshire Gap, Grately		
DESIGNATION:	Scheduled Monument (No. 1014816)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046
SITE NAME:	Andover-Redbridge canal, Chalk Hill Lock, Horsebridge, Kings Somborne		
DESIGNATION:	Scheduled Monument (No. 1001794)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046
SITE NAME:	Long barrow 50m north east of Down Farm, Nether Wallop		
DESIGNATION:	Scheduled Monument (No. 1012511)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046
SITE NAME:	Bowl barrow 250m south of Martin's Clump, Over Wallop		
DESIGNATION:	Scheduled Monument (No. 1013063)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Richard Massey 01483 252046
SITE NAME:	Flint mines, linear boundary and two bowl barrows at Martin's Clump, Porton Down, Over Wallop		
DESIGNATION:	Scheduled Monument (No. 1017168)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Stable
OWNER TYPE:	Government or Agency	CONTACT:	Richard Massey 01483 252046

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Long barrow and adjoining bowl barrow, 250m south of Martin's Clump, Over Wallop		
DESIGNATION:	Scheduled Monument (No. 1015981)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Long Barrow 350m south east of Nutbane, Penton Grafton		
DESIGNATION:	Scheduled Monument (No. 1013202)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Roman villa 500yds (460m) south west of Clanville House, Penton Grafton		
DESIGNATION:	Scheduled Monument (No. 1001839)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046



SITE NAME:	Embley Park, Wellow
DESIGNATION:	Registered Park and Garden Grade II, also 8 LBs
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Stable
OWNER TYPE:	Mixed, multiple owners

C19 and early C20 woodland and shrub garden of late C18 origin, once the home of Florence Nightingale. After WWII the estate was divided, the house becoming a school. The school has reunited the historic core but the wider park is divided between multiple owners. The site suffers from development pressures in all directions. Unfortunately, the school's recently updated Conservation Management Plan only addressed land within their ownership. The issue of how to co-ordinate management of the whole designed landscape remains.

Contact: David Brock 01483 252044

WINCHESTER



SITE NAME:	Merton Castle, Hursley
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY:	C (C)
OWNER TYPE:	Company

Norman ringwork with a standing gatehouse surviving as core work. Overgrown and in need of consolidation. Discussions need to be held with new owners.

Contact: Richard Massey 01483 252046



SITE NAME:	St Peters Church (ruin), Lainston House, Lainston Park, Sparsholt
DESIGNATION:	Listed Building Grade II, SM, RPG II*
CONDITION:	Fair
OCCUPANCY:	N/A
PRIORITY:	C (C)
OWNER TYPE:	Company

C12 ruinous chapel, located circa 150m south-west of Lainston House. The ruin was used as a romantic folly in C18 pleasure grounds in which it stands. Requires consolidation. Discussions have taken place and some masonry repairs were carried out in 2005 but further work is needed.

Contact: Richard Massey 01483 252046



SITE NAME:	Walled garden to Lainston House, Lainston Park, Sparsholt
DESIGNATION:	Listed Building Grade II*, RPG II*
CONDITION:	Fair
OCCUPANCY:	N/A
PRIORITY:	D (D)
OWNER TYPE:	Company

Hexagonal walled fruit or kitchen garden, c5.3ha, c100m west of the house. Probably C18. Striking polygonal layout. Axial vista from main entrance of house, across forecourt and into walled garden. In use as hotel car park around the sides and planted in the centre. Some fruit trees remain on the walls. In need of repair. The gardens around the house are in good condition, but the park is in arable use.

Contact: David Brock 01483 252044

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Iron Age field system, banjo enclosure and Romano-British villa, 500m east of Woodham Farm, Kings Worthy		
DESIGNATION:	Scheduled Monument (No. 1013269)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Norsebury Ring hillfort, Micheldever		
DESIGNATION:	Scheduled Monument (No. 1020317)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Long barrow and bowl barrow 440m north west of Sanctuary Farm, Wonston		
DESIGNATION:	Scheduled Monument (No. 1021109)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Compton Street		
DESIGNATION:	Conservation Area	CONDITION:	Fair
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Historic Environment Team (LPA) 01962 848481	NEW ENTRY:	No

SITE NAME:	Hursley		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Historic Environment Team (LPA) 01962 848481	NEW ENTRY:	No

SITE NAME:	Kings Worthy		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Historic Environment Team (LPA) 01962 848481	NEW ENTRY:	No

SITE NAME:	Littleton		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Historic Environment Team (LPA) 01962 848481	NEW ENTRY:	No

SITE NAME:	New Alresford		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Improving
CONTACT:	Historic Environment Team (LPA) 01962 848481	NEW ENTRY:	No

SITE NAME:	Southwick		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Historic Environment Team (LPA) 01962 848481	NEW ENTRY:	No

SITE NAME:	Sparsholt		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Historic Environment Team (LPA) 01962 848481	NEW ENTRY:	No

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Sutton Scotney		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Historic Environment Team (LPA) 01962 848481	NEW ENTRY?:	No
SITE NAME:	Wickham		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Improving
CONTACT:	Historic Environment Team (LPA) 01962 848481	NEW ENTRY?:	No
SITE NAME:	Winchester		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Historic Environment Team (LPA) 01962 848481	NEW ENTRY?:	No
SITE NAME:	Wonston		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Historic Environment Team (LPA) 01962 848481	NEW ENTRY?:	No

ISLE OF WIGHT (UA)



SITE NAME: **Northwood House,
Ward Avenue,
Cowes**

Large house, 1837, with spectacular interiors. The long-term future of this partly-used building is unresolved and maintenance needs to be addressed in the short term. The cost of full repair is very high.

DESIGNATION: Listed Building Grade II*, CA
CONDITION: Fair
OCCUPANCY: Part occupied
PRIORITY: C (C)
OWNER TYPE: Trust

Contact: David Brock 01483 252044



SITE NAME: **Hammerhead crane,
Thetis Road,
West Cowes, Cowes**

Giant cantilever crane, also called 'hammerhead' crane, built 1911. One of a handful of this type of crane now surviving, and witness to a major local industry. Now disused and surrounded by a potential development site.

DESIGNATION: Listed Building Grade II*
CONDITION: Poor
OCCUPANCY: N/A
PRIORITY: A (C)
OWNER TYPE: Private

Contact: David Brock 01483 252044



SITE NAME: **Norris Castle,
Newbarn Road,
East Cowes**

Mock castle of 1799 by James Wyatt. A recent failure in the external walling is being addressed but more work may be needed.

DESIGNATION: Listed Building Grade I, RPG II
CONDITION: Poor
OCCUPANCY: Occupied
PRIORITY: D (New entry)
OWNER TYPE: Private

Contact: David Brock 01483 252044



SITE NAME: **Remains of Old Quarr Abbey,
Fishbourne Park Road, Binstead,
Ryde**

Cistercian foundation of 1131. In an advanced state of decline due to neglect and vegetation growth. English Heritage has carried out a photographic survey and a condition survey. Stage I Heritage Lottery Fund grant approved for works including repairs to this monument.

DESIGNATION: Listed Building Grade II, SM
CONDITION: Poor
OCCUPANCY: N/A
PRIORITY: A (A)
OWNER TYPE: Religious organisation

Contact: Richard Massey 01483 252046

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME: **Holy Trinity Church,
Dover Street,
Ryde**

Large town church with prominent tower and spire, designed 1841 by Thomas Hellyer. At risk due to leaking rainwater goods, decaying stonework, water penetration and timber decay, including to the transept floors.

DESIGNATION: Listed Place of Worship Grade II, CA

CONDITION: Poor

PRIORITY: C (New entry)

OWNER TYPE: Religious organisation

Contact: Andy White 01483 252047



SITE NAME: **St Boniface (Old Church),
Bonchurch,
Ventnor**

Small church of Norman origin with nave, chancel and south porch. Romanesque wall paintings to south wall of nave. At risk due to structural cracking to chancel, decaying stonework and defective rainwater goods and drainage.

DESIGNATION: Listed Place of Worship Grade II*, CA

CONDITION: Poor

PRIORITY: C (New entry)

OWNER TYPE: Religious organisation

Contact: Andy White 01483 252047

SITE NAME: **Medieval settlement 100m south east and 350m north east of East Ashley Manor Farm, Brading**

DESIGNATION:	Scheduled Monument (No. 1015622)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME: **Bowl barrow on Newbarn Down: 1.1km south west of Rowridge, Brighstone**

DESIGNATION:	Scheduled Monument (No. 1007782)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Moderate stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME: **A Bronze Age barrow and Anglo-Saxon cemetery on Bowcombe Down, 575m south east of Apesdown, Isle of Wight**

DESIGNATION:	Scheduled Monument (No. 1015624)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME: **Carisbrooke Romano-British villa, Isle of Wight**

DESIGNATION:	Scheduled Monument (No. 1012718)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME: **Two bowl barrows 180m WNW of Puck House, Fishbourne, Isle of Wight**

DESIGNATION:	Scheduled Monument (No. 1012715)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	Swainston, Calbourne
DESIGNATION:	Registered Park and Garden Grade II, also 3 LBs
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	High
TREND:	Declining
OWNER TYPE:	Mixed, multiple owners

Mid-late C18 woodland pleasure grounds, set in parkland, with intersecting avenues, pools and a stream incorporating earlier fishponds. The reconstructed house and refurbished gardens are now a hotel, but some key features lie in the remainder of the estate and in private ownership. This includes a temple which is further isolated by a public road and some inappropriate light industrial units. Perceived low value of landscape features and levels of repair make holistic conservation and management difficult.

Contact: David Brock 01483 252044

SITE NAME:	Brading	
DESIGNATION:	Conservation Area	CONDITION: Fair
VULNERABILITY:	Medium	TREND: Deteriorating
CONTACT:	Oliver Boulter (LPA) 01983 823552	NEW ENTRY?: No

SITE NAME:	Carisbrooke	
DESIGNATION:	Conservation Area	CONDITION: Poor
VULNERABILITY:	Medium	TREND: Deteriorating
CONTACT:	Oliver Boulter (LPA) 01983 823552	NEW ENTRY?: No

SITE NAME:	Cowes	
DESIGNATION:	Conservation Area	CONDITION: Poor
VULNERABILITY:	Medium	TREND: Deteriorating
CONTACT:	Oliver Boulter (LPA) 01983 823552	NEW ENTRY?: No

SITE NAME:	Godshill	
DESIGNATION:	Conservation Area	CONDITION: Fair
VULNERABILITY:	High	TREND: Deteriorating
CONTACT:	Oliver Boulter (LPA) 01983 823552	NEW ENTRY?: No

SITE NAME:	Newport	
DESIGNATION:	Conservation Area	CONDITION: Poor
VULNERABILITY:	Medium	TREND: Deteriorating
CONTACT:	Oliver Boulter (LPA) 01983 823552	NEW ENTRY?: No

KENT

ASHFORD



SITE NAME:	Remains of Archbishop's Palace, Market Place, Charing
DESIGNATION:	Listed Building Grade I, SM, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY:	A (A)
OWNER TYPE:	Private

Remains of palace built in C13 and C14. Farm complex converted from remains includes gatehouse, barn (east range of palace courtyard), outhouse (west range) and Palace Farmhouse (north range). Temporary support has been given to the structurally unsound barn with English Heritage grant aid. Survey carried out by the Royal Commission on the Historic Monuments of England.

Contact: Judith Roebuck 01483 252048



SITE NAME:	Ruins of Church of St Mary, Pluckley Road, Little Chart
DESIGNATION:	Listed Building Grade II, SM
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY:	D (D)
OWNER TYPE:	Local authority

War damaged church, circa 1500, now ruinous with tower still standing. Local authority has repaired ruined walls of nave and chancel with English Heritage grant.

Contact: Judith Roebuck 01483 252048

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	Wye Undercroft, Bridge Street, Wye with Hinxhill
DESIGNATION:	Listed Building Grade II, SM, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY:	E (E)
OWNER TYPE:	Private

C13 undercroft in front garden of new house; of virtually no beneficial use. Repair scheme now underway after detailed technical investigation.

Contact: Judith Roebuck 01483 252048



SITE NAME:	Church of St Mary the Virgin, The Street, Great Chart
DESIGNATION:	Listed Place of Worship Grade I, CA
CONDITION:	Poor
PRIORITY:	D (New entry)
OWNER TYPE:	Religious organisation

Ragstone built church originating in C13, with C15 additions. Repairs required to replace missing copper roof covering to the north aisle and replace eastern valley gutters and tiled roofs to the Chancel and Toke (north Chapel). A Repair Grant for Places of Worship has been offered to support this work.

Contact: Amanda Kearsy 01483 252034

SITE NAME:

Castle Toll Saxon burgh and medieval fort, Newenden

DESIGNATION:	Scheduled Monument (No. 1013041)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Judith Roebuck 01483 252048

CANTERBURY



SITE NAME:	Greyfriars Monastery, Stour Street, Canterbury
DESIGNATION:	Listed Building Grade I, SM, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY:	A (A)
OWNER TYPE:	Housing Association

Boundary walls from Tudor house built on site of the friary and one part of the friary church. Friary built in 1267.

Contact: Judith Roebuck 01483 252048



SITE NAME:	Monuments in the precinct of Canterbury Cathedral, The Precinct, Canterbury
DESIGNATION:	Listed Building Grade I, SM, CA, WHS
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY:	B (B)
OWNER TYPE:	Religious organisation

Very important medieval ruinous structures of Christchurch Priory, which have suffered from years of decline. Major backlog of repairs; work has started with English Heritage grant to Llanfrancs dormitory and the city wall. Slow progress is being made.

Contact: Judith Roebuck 01483 252048



SITE NAME:	Horton Manor Chapel, Horton, Chartham
DESIGNATION:	Listed Building Grade II, SM
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY:	C (C)
OWNER TYPE:	Private

Redundant two cell medieval (C14) chapel now roofless. Located on a farm. Repair schedule prepared.

Contact: Judith Roebuck 01483 252048



SITE NAME:	Barn at Hardres Court, Upper Hardres
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	C (C)
OWNER TYPE:	Private

Late C15 to early C16 aisled timber barn. Damaged by fire in 1993.

Contact: Tom Foxall 01483 252035

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	Church of St Cosmus and St Damian, Tyler Hill Road, Blean
DESIGNATION:	Listed Place of Worship Grade II*, CA
CONDITION:	Poor
PRIORITY:	D (New entry)
OWNER TYPE:	Religious organisation

C13 church built of flint with stone quoins and tiled roofs. North aisle and south porch added in 1866. 800 year old crown-post roof. Repairs required to entire nave roof which is structurally unsafe following discovery of a broken collar purlin in November 2009. Temporary internal scaffolding now supporting the nave roof. A Repair Grant for Places of Worship has been offered to support the repairs work, further fundraising and project development work is now underway.

Contact: Amanda Kearsey 01483 252034

SITE NAME: **Enclosures west of Woodlands, Adisham**

DESIGNATION:	Scheduled Monument (No. 1004191)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Judith Roebuck 01483 252048

DARTFORD

SITE NAME: **Roman enclosure south east of Vagniacae, Southfleet**

DESIGNATION:	Scheduled Monument (No. 1004226)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Judith Roebuck 01483 252048

SITE NAME: **Springhead Roman site, Southfleet**

DESIGNATION:	Scheduled Monument (No. 1005140)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Judith Roebuck 01483 252048

DOVER



SITE NAME:	The Western Heights fortifications, Castle Hill, Dover
DESIGNATION:	Scheduled Monument, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied
PRIORITY:	C (C)
OWNER TYPE:	Government

An Immigration Removal Centre, managed by the Home Office, occupies the Citadel on the Western Heights. The surrounding moats and western outworks are in poor condition and there is no programme for their maintenance. Funding for a quadrennial inspection report has not been secured. There has been no progress since the previous report in 2007.

Contact: Alan Johnson 020 7973 3174



SITE NAME:	Fort Burgoyne, Connaught Barracks, Guston
DESIGNATION:	Scheduled Monument
CONDITION:	Fair
OCCUPANCY:	Vacant
PRIORITY:	C (C)
OWNER TYPE:	Housing Association

1860s polygonal-plan fort now part of a later barracks. The earth-covered terraced casemates are vacant. Structures on the ramparts (the brick-built Haxo casemates) are at risk from lack of maintenance and invasive ivy growth. The site is now owned by Homes and Community Agency.

Contact: Judith Roebuck 01483 252048



SITE NAME:	St Radegunds Abbey, Abbey Road, Hougham Without
DESIGNATION:	Listed Building Grade II*, SM
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY:	A (A)
OWNER TYPE:	Private

A significant C13 monastic site with standing remains of the church and claustral buildings. Heavily overgrown and fabric in a ruinous state. The site is now a farm with buildings used as barns and a farmhouse. These are in fair condition.

Contact: Judith Roebuck 01483 252048

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME: **The Belvedere,
Waldershare Park,
Shepherdswell with Coldred**

DESIGNATION: Listed Building Grade I, RPG II

CONDITION: Very bad

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNER TYPE: Private

Belvedere: 1725-7 by Lord Burlington or Colen Campbell for Sir Henry Furnese located at the southern end of the western side of an early C18 Wilderness, overlooking the park to the north and south. Derelict for many years and now in a ruinous state. A new temporary scaffolding and protective canopy have recently been completed with grant aid from English Heritage.

Contact: Tom Foxall 01483 252035

SITE NAME: **Great Mongeham Anglo-Saxon cemetery, Great Mongeham**

DESIGNATION: Scheduled Monument (No. 1003124)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNER TYPE: Private

CONTACT: Judith Roebuck 01483 252048

SITE NAME: **St Radegund's Abbey, Poulton, Hougham Without**

DESIGNATION: Scheduled Monument (No. 1005196)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Collapse

TREND: Declining

OWNER TYPE: Private

CONTACT: Judith Roebuck 01483 252048

SITE NAME: **Ring ditch and enclosure 200yds (180m) east of Parsonage Farm, Preston**

DESIGNATION: Scheduled Monument (No. 1003121)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNER TYPE: Private

CONTACT: Judith Roebuck 01483 252048

SITE NAME: **Four ring ditches on ridge of Sutton Hill, Sutton**

DESIGNATION: Scheduled Monument (No. 1004204)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNER TYPE: Private

CONTACT: Judith Roebuck 01483 252048

SITE NAME: **Romano-Celtic temple and Iron Age site south of Worth, Worth**

DESIGNATION: Scheduled Monument (No. 1004225)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNER TYPE: Private

CONTACT: Judith Roebuck 01483 252048

GRAVESHAM



SITE NAME: **The Dairy,
Cobham Hall,
Cobham**

DESIGNATION: Listed Building Grade II*, RPG II*

CONDITION: Fair

OCCUPANCY: Vacant

PRIORITY: E (E)

OWNER TYPE: Trust

Unusual Georgian model dairy, part repaired several years ago and awaiting completion of works.

Contact: Tom Foxall 01483 252035



SITE NAME: **Church of St Mildred,
Nurstead Lane,
Meopham**

DESIGNATION: Listed Place of Worship Grade II*

CONDITION: Poor

PRIORITY: D (New entry)

OWNER TYPE: Religious organisation

Church constructed of flint and ragstone. C15, possibly earlier with later windows; west tower C15. Chancel and nave without division and braced trussed rafter roof without tie beams. Vestry and north porch added C19, with tiled roof. Repairs required to north and south slope roofs with associated rainwater goods repairs. A Repair Grant for Places of Worship has been offered to support these repairs.

Contact: Amanda Kearsley 01483 252034

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME: **All Saints Church,
Perry Street,
Northfleet**

DESIGNATION: Listed Place of Worship Grade II*
CONDITION: Very bad
PRIORITY: B (New entry)
OWNER TYPE: Religious organisation

Large, urban, Victorian church. At risk due to roof tiling being defective, especially to south aisle, with slipped and broken tiles, and cracked and defective flashings. The west gable stonework is also decaying and falling onto the footpath beneath. A Repair Grant for Places of Worship has been offered to support the cost of repairs.

Contact: Andy White 01483 252047

MAIDSTONE



SITE NAME: **Boxley Abbey Barn,
Boxley Abbey,
Boxley**

DESIGNATION: Listed Building Grade I, SM, CA
CONDITION: Poor
OCCUPANCY: Vacant
PRIORITY: E (E)
OWNER TYPE: Private

Cistercian abbey founded in 1146. Main threat is to a medieval roofed range used formerly as a barn, but which is now vacant. Agricultural use now no longer feasible.

Contact: Judith Roebuck 01483 252048



SITE NAME: **St Andrews Chapel,
Boarley Lane, Boxley Abbey,
Boxley**

DESIGNATION: Listed Building Grade II*
CONDITION: Fair
OCCUPANCY: Vacant
PRIORITY: E (E)
OWNER TYPE: Private

Redundant late C15 chapel. Currently unoccupied and subject to vandalism. Location affected by proximity of motorway.

Contact: Tom Foxall 01483 252035



SITE NAME: **Dovecotes at Leeds Priory,
Lower Street,
Leeds**

DESIGNATION: Listed Building Grade II, SM
CONDITION: Very bad
OCCUPANCY: Vacant
PRIORITY: B (B)
OWNER TYPE: Trust

Mid C16 overgrown and roofless dovecotes from a post-dissolution mansion. Site purchased for possible new houses.

Contact: Judith Roebuck 01483 252048



SITE NAME: **Slype and associated remains
at Leeds Priory, Lower Street,
Leeds**

DESIGNATION: Listed Building Grade II, SM
CONDITION: Very bad
OCCUPANCY: N/A
PRIORITY: C (C)
OWNER TYPE: Trust

A slype (covered passage) and associated remains of medieval priory. Site purchased for possible new houses.

Contact: Judith Roebuck 01483 252048



SITE NAME: **11 Lower Stone Street,
Maidstone**

DESIGNATION: Listed Building Grade II*, CA
CONDITION: Fair
OCCUPANCY: Vacant
PRIORITY: E (E)
OWNER TYPE: Company

Early C18 house. Vacant for some years.

Contact: Tom Foxall 01483 252035

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA Conservation Area
LB/LBs Listed Building/s
LPA Local Planning Authority
NIP National Park
RPG Registered Park and Garden
SM/SMs Scheduled Monument/s
UA Unitary Authority
WHS World Heritage Site



SITE NAME:	The Dungeons at the Archbishop's Palace, Mill Street, Maidstone
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	C (C)
OWNER TYPE:	Local authority

Partially ruined stone building of medieval date. Previous alterations and lack of repair are contributing to structural problems.

Contact: Tom Foxall 01483 252035



SITE NAME:	Mote House, Mote Park, Maidstone
DESIGNATION:	Listed Building Grade II*, RPG II
CONDITION:	Fair
OCCUPANCY:	Vacant
PRIORITY:	F (F)
OWNER TYPE:	Company

House, 1793-1801. Recently used as an old people's home. Currently under repair for conversion to retirement housing.

Contact: Tom Foxall 01483 252035



SITE NAME:	Church of St Mary Magdalene, Church Lane, Stockbury
DESIGNATION:	Listed Place of Worship Grade I, CA
CONDITION:	Poor
PRIORITY:	D (New entry)
OWNER TYPE:	Religious organisation

Tower dates from C13. A fire in 1836 destroyed the roof and parts of the nave and chancel leading to a scheme of extensive repairs in 1851. Built of flint rubblework on a brick backing with dressings of Kentish ragstone and Bath stone. Urgent masonry repairs are required to the western tower; north transept and east end, with associated drainage works. A Repair Grant for Places of Worship has been offered to support these repair works.

Contact: Amanda Kearsay 01483 252034

SITE NAME:	Leeds Priory: Augustinian Priory of St Mary and St Nicholas with associated dovecotes and slype, and the site of the 18th century Meredith mansion, Leeds		
DESIGNATION:	Scheduled Monument (No. 1011027)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Judith Roebuck 01483 252048

SITE NAME:	Binbury motte and bailey castle, Thurnham		
DESIGNATION:	Scheduled Monument (No. 1010713)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Judith Roebuck 01483 252048

SITE NAME:	Boxley Abbey		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Mike Parkinson (LPA) 01622 602335	NEW ENTRY:	No

SITE NAME:	Elmstone Hole, Grafty Green, Boughton Malherbe		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Mike Parkinson (LPA) 01622 602335	NEW ENTRY:	No

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHs	World Heritage Site

SEVENOAKS



SITE NAME: **Church of St Mary,
Church Road,
Sundridge**

Church founded in 1138, with C13 and C15 elements. Largely rebuilt in C19. Built of stone rubble with a slate roof. High level repairs are required to the roof and rainwater goods; urgent timber repairs required, particularly to the medieval spire structure. A Repair Grant for Places of Worship has been offered to support this work.

DESIGNATION: Listed Place of Worship Grade I, CA

CONDITION: Poor

PRIORITY: D (New entry)

OWNER TYPE: Religious organisation

Contact: Amanda Kearsley 01483 252034

SITE NAME:

Chapel, Maplescombe, West Kingsdown

DESIGNATION: Scheduled Monument (No. 1005134)

CONDITION: Generally unsatisfactory
with major localised problems

PRINCIPAL VULNERABILITY: Scrub / tree growth

TREND: Declining

OWNER TYPE: Private

CONTACT: Judith Roebuck 01483 252048



SITE NAME: **Combe Bank,
Sundridge with Ide Hill / Brasted**

Combe Bank's gardens and pleasure grounds date from the 1720s and 1740s. After WWI the estate was sold and divided up. The house and gardens became a school in 1924. The north park became derelict after construction of the M25; recent attempts to develop it as a burial ground remain unresolved. The gardens suffered considerable storm damage in 1987. A joined up conservation led management approach, in conjunction with sufficient resources, is still required.

DESIGNATION: Registered Park and Garden Grade II*,
also part in CA, 17 LBs

CONDITION: Extensive significant problems

VULNERABILITY: High

TREND: Declining

OWNER TYPE: Mixed, multiple owners

Contact: Peter Kendall 01483 252038

SITE NAME:

Edenbridge

DESIGNATION: Conservation Area

CONDITION: Poor

VULNERABILITY: Medium

TREND: Deteriorating

CONTACT: Nicole Twort (LPA) 01732 227334

NEW ENTRY: No

SITE NAME:

Riverhead

DESIGNATION: Conservation Area

CONDITION: Very bad

VULNERABILITY: Medium

TREND: Deteriorating

CONTACT: Nicole Twort (LPA) 01732 227334

NEW ENTRY: No

SITE NAME:

Seal

DESIGNATION: Conservation Area

CONDITION: Poor

VULNERABILITY: Medium

TREND: Deteriorating

CONTACT: Nicole Twort (LPA) 01732 227334

NEW ENTRY: No

SITE NAME:

Sevenoaks High Street

DESIGNATION: Conservation Area

CONDITION: Very bad

VULNERABILITY: Medium

TREND: Deteriorating

CONTACT: Nicole Twort (LPA) 01732 227334

NEW ENTRY: No

SITE NAME:

South Darenth

DESIGNATION: Conservation Area

CONDITION: Very bad

VULNERABILITY: Medium

TREND: Unknown

CONTACT: Nicole Twort (LPA) 01732 227334

NEW ENTRY: No

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA Conservation Area
LB/LBs Listed Building/s
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM/SMs Scheduled Monument/s
UA Unitary Authority
WHS World Heritage Site

SITE NAME:	The Vine, Sevenoaks		
DESIGNATION:	Conservation Area	CONDITION:	Fair
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Nicole Twort (LPA) 01732 227334	NEW ENTRY?:	No

SITE NAME:	Vine Court, Sevenoaks		
DESIGNATION:	Conservation Area	CONDITION:	Fair
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Nicole Twort (LPA) 01732 227334	NEW ENTRY?:	No

SEVENOAKS / TUNBRIDGE WELLS



SITE NAME:	Swaylands, Penshurst / Bidborough / Chiddingstone
DESIGNATION:	Registered Park and Garden Grade II, also part in CA, 3 LBs
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	High
TREND:	Improving
OWNER TYPE:	Private, multiple owners

Important for its terraced gardens and pleasure grounds, including extensive rockwork developed in the late C19. Work began in 2006 to convert the house into 28 apartments, including the addition of two new wings, and works to the gardens as well. The project stalled last year due to financial difficulties but thankfully work has recommenced. The park is diminutive but in need of management. The lower lake, farm and kitchen garden are in separate ownership and much neglected – here the future remains less certain.

Contact: Peter Kendall 01483 252038

SHEPWAY



SITE NAME:	Martello Tower No. 5, Folkestone
DESIGNATION:	Scheduled Monument
CONDITION:	Fair
OCCUPANCY:	Vacant
PRIORITY:	E (E)
OWNER TYPE:	Local authority

A very good example of a Martello tower. Situated in the grounds of a school and vacant but with potential for re-use by the school. The preservation of archaeological and historical significance will be the main consideration in assessing the suitability of proposals to convert Martello towers for residential use.


Contact: Judith Roebuck 01483 252048



SITE NAME:	Martello Tower No. 4, The Leas, Folkestone
DESIGNATION:	Scheduled Monument, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant
PRIORITY:	C (C)
OWNER TYPE:	Private

A good example of a Martello tower built 1806. Derelict and situated in the grounds of a private house. The preservation of archaeological and historical significance will be the main consideration in assessing the suitability of proposals to convert Martello towers for residential use.

Contact: Judith Roebuck 01483 252048



SITE NAME:	Martello Towers Nos. 6 and 7, Shorncliffe Camp, Folkestone
DESIGNATION:	Listed Building Grade II, SM
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	C (C)
OWNER TYPE:	Private

Martello towers, 1806. Derelict recently sold by Ministry of Defence to private owner. (Photograph shows tower 6). The preservation of archaeological and historical significance will be the main consideration in assessing the suitability of proposals to convert Martello towers for residential or other use.

Contact: Judith Roebuck 01483 252048



SITE NAME:	Martello Tower No. 9, Shorncliffe Camp, Sandgate, Folkestone
DESIGNATION:	Listed Building Grade II, SM
CONDITION:	Very bad
OCCUPANCY:	Vacant
PRIORITY:	C (C)
OWNER TYPE:	Private

Martello tower, 1806. Derelict, disposed by Ministry of Defence to private owner. The preservation of archaeological and historical significance will be the main consideration in assessing the suitability of proposals to convert Martello towers for residential use.

Contact: Judith Roebuck 01483 252048

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: **Dymchurch Redoubt,
Hythe Ranges,
Hythe**

DESIGNATION: Scheduled Monument

CONDITION: Poor

OCCUPANCY: Part occupied

PRIORITY: D (D)

OWNER TYPE: Government

Currently used as a military training facility. The original fort of 1806 is a massive brick circular structure within a dry moat, and has C20 additions. Located on MOD ranges, some parts have been brought back into use. There is brickwork deterioration to both the original fort and later additions. A conservation plan was prepared in 2005. Phased repairs are in progress.

Contact: Alan Johnson 020 7973 3174



SITE NAME: **The Parish Church of St Mary
and St Eanswythe, Church Street,
Folkestone**

DESIGNATION: Listed Place of Worship Grade II*, CA

CONDITION: Poor

PRIORITY: D (New entry)

OWNER TYPE: Religious organisation

Church mentioned in Domesday Book but greatly enlarged and extended in C13, further renovated in C15 and partly rebuilt in C19. Built of sandstone rubble with tiled roofs and shingled spire; the chancel is rendered. Repairs required to the masonry of the crenulated parapets; replacement of lead roofs; repair of internal plaster (damaged due to water ingress) and to the timber panelling. A Repair Grant for Places of Worship has been offered to support this work.

Contact: Amanda Kearsay 01483 252034

SITE NAME:

Romano-British building south of Burch's Rough, Lypnpe

DESIGNATION: Scheduled Monument (No. 1004216)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNER TYPE: Private

CONTACT: Judith Roebuck 01483 252048

SITE NAME:

Motte and Bailey Castle 200m north west of Stowting Church, Stowting

DESIGNATION: Scheduled Monument (No. 1012099)

CONDITION: Generally unsatisfactory
with major localised problems

PRINCIPAL VULNERABILITY: Extensive animal burrowing

TREND: Declining

OWNER TYPE: Private

CONTACT: Judith Roebuck 01483 252048

SITE NAME:

Bowl barrow 150m north east of Red House Farm, Swingfield

DESIGNATION: Scheduled Monument (No. 1011765)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNER TYPE: Private

CONTACT: Judith Roebuck 01483 252048

SITE NAME:

Bowl barrow at Minnis Beeches, Swingfield

DESIGNATION: Scheduled Monument (No. 1011766)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNER TYPE: Private

CONTACT: Judith Roebuck 01483 252048

SWALE



SITE NAME: **The ruins of Shurland Hall,
Leysdown Road,
Eastchurch**

DESIGNATION: Listed Building Grade II*, SM

CONDITION: Fair

OCCUPANCY: Vacant

PRIORITY: F (F)

OWNER TYPE: Trust

Tudor courtier house with long history of neglect. English Heritage has worked with the Spitalfield Trust on a rescue project to which an English Heritage grant was offered. Works are well advanced and attention is turning to the other ruins. The property is for sale.

Contact: Peter Kendall 01483 252038

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

- CA** Conservation Area
- LB/LBs** Listed Building/s
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM/SMs** Scheduled Monument/s
- UA** Unitary Authority
- WHS** World Heritage Site

	<p>SITE NAME: Medieval Stables at Abbey Farm, Abbey Fields, Faversham</p> <p>DESIGNATION: Listed Building Grade II*, CA</p> <p>CONDITION: Very bad</p> <p>OCCUPANCY: Vacant</p> <p>PRIORITY: F (F)</p> <p>OWNER TYPE: Private</p>	<p>Very small medieval farm building in a very poor state of repair. Consent has been granted to use as an outbuilding to an adjacent stable conversion and repairs are underway.</p> <p>Contact: Tom Foxall 01483 252035</p>
	<p>SITE NAME: Provender, Provender Lane, Norton</p> <p>DESIGNATION: Listed Building Grade II*</p> <p>CONDITION: Fair</p> <p>OCCUPANCY: Occupied</p> <p>PRIORITY: F (F)</p> <p>OWNER TYPE: Private</p>	<p>Fine medieval and later house, for which a programme of substantial repairs is nearing completion.</p> <p>Contact: Tom Foxall 01483 252035</p>
	<p>SITE NAME: Former Medway Ports Authority Offices (Dockyard House), Sheerness Docks, Sheerness</p> <p>DESIGNATION: Listed Building Grade II*, CA</p> <p>CONDITION: Fair</p> <p>OCCUPANCY: Vacant</p> <p>PRIORITY: C (C)</p> <p>OWNER TYPE: Trust</p>	<p>House, 1830. Vacant with a growing maintenance problem. Recently taken on by the Spitalfield's Historic Buildings Trust with a view to restoration to a single house.</p> <p>Contact: Tom Foxall 01483 252035</p>
	<p>SITE NAME: Coach Houses, Naval Terrace, Sheerness Docks, Sheerness</p> <p>DESIGNATION: Listed Building Grade II*, CA</p> <p>CONDITION: Very bad</p> <p>OCCUPANCY: Part occupied</p> <p>PRIORITY: B (B)</p> <p>OWNER TYPE: Private</p>	<p>Coach houses ancillary to No.s 1-8 Naval Terrace, 1830. Some are now restored, but others continue to suffer from a lack of repairs and maintenance.</p> <p>Contact: Tom Foxall 01483 252035</p>
	<p>SITE NAME: I-15 (consec) Regency Close, Sheerness Docks, Sheerness</p> <p>DESIGNATION: Listed Building Grade II*, CA</p> <p>CONDITION: Fair</p> <p>OCCUPANCY: Part occupied</p> <p>PRIORITY: C (C)</p> <p>OWNER TYPE: Trust</p>	<p>Row of houses built 1830. Largely vacant, but recently taken on by the Spitalfield's Historic Buildings Trust with a view to restoring to houses.</p> <p>Contact: Tom Foxall 01483 252035</p>
	<p>SITE NAME: Former Royal Dockyard Church and attached wall and railings, Sheerness Dockyard, Sheerness</p> <p>DESIGNATION: Listed Building Grade II*, CA</p> <p>CONDITION: Very bad</p> <p>OCCUPANCY: Vacant</p> <p>PRIORITY: C (B)</p> <p>OWNER TYPE: Private</p>	<p>Redundant former St Paul's Parish Dockyard Church. Built originally in 1828, Architect George Taylor; but destroyed by fire and rebuilt in 1884 incorporating the old clock tower. Empty since 1970 and damaged by fire in 2001, now scaffolded. A consent received for conversion to apartments has now lapsed, but some holding repairs have been executed following the local authority's serving of an Urgent Works Notice.</p> <p>Contact: Tom Foxall 01483 252035</p>

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

	<p>SITE NAME: The Boat Store (No. 78), Sheerness Dockyard, Sheerness</p> <p>DESIGNATION: Listed Building Grade I</p> <p>CONDITION: Fair</p> <p>OCCUPANCY: Part occupied</p> <p>PRIORITY: C (C)</p> <p>OWNER TYPE: Company</p>	<p>Boat store. Built 1859. Since the destruction of the Crystal Palace and the first South Kensington Museum this is the earliest surviving example of a multi-storey iron-frame and panel structure. In minor use for storage. Discussions with Local Planning Authority and port company continuing.</p> <p>Contact: Tom Foxall 01483 252035</p>
	<p>SITE NAME: Former Working Mast House, 26 Jetty Road, Sheerness Dockyard, Sheerness</p> <p>DESIGNATION: Listed Building Grade II*</p> <p>CONDITION: Poor</p> <p>OCCUPANCY: Part occupied</p> <p>PRIORITY: C (C)</p> <p>OWNER TYPE: Company</p>	<p>Large C19 industrial building used for constructing and storing masts and small boats. Disused and marooned at the heart of a working port. Negotiations are ongoing with the port operator to identify a positive new use for the building.</p> <p>Contact: Tom Foxall 01483 252035</p>
	<p>SITE NAME: Murston Old Church, Sittingbourne</p> <p>DESIGNATION: Scheduled Monument</p> <p>CONDITION: Poor</p> <p>OCCUPANCY: Vacant</p> <p>PRIORITY: A (A)</p> <p>OWNER TYPE: Trust</p>	<p>Originally a large church with three aisles and three chancels with a square tower and wooden turret, built between 1375 and 1550; only the southern chapel remains. The rest of the church survives as buried archaeological remains.</p> <p>Contact: Judith Roebuck 01483 252048</p>
	<p>SITE NAME: Sheerness Defences, Swale</p> <p>DESIGNATION: Scheduled Monument, CA</p> <p>CONDITION: Very bad</p> <p>OCCUPANCY: N/A</p> <p>PRIORITY: C (C)</p> <p>OWNER TYPE: Company</p>	<p>Moated artillery fortifications from C17-C20. A major complex defending the dockyard.</p> <p>Contact: Peter Kendall 01483 252038</p>
	<p>SITE NAME: Church of St Mary the Virgin, Church Lane, Newington</p> <p>DESIGNATION: Listed Place of Worship Grade I, CA</p> <p>CONDITION: Poor</p> <p>PRIORITY: B (New entry)</p> <p>OWNER TYPE: Religious organisation</p>	<p>Large church on the northern outskirts of the village dating from C11. Has defective tiling especially to the south aisle roof, inadequate rainwater disposal, including undersized gutters and downpipes. There is decaying stonework and pointing. A Repair Grant for Places of Worship has been offered to assist in the cost of repairs.</p> <p>Contact: Andy White 01483 252047</p>
	<p>SITE NAME: Church of St Giles, Church Road, Tonge</p> <p>DESIGNATION: Listed Place of Worship Grade I</p> <p>CONDITION: Poor</p> <p>PRIORITY: C (New entry)</p> <p>OWNER TYPE: Religious organisation</p>	<p>Originally C12 flint church with unconventional valley gutter arrangement. There is a clear structural crack on the east wall of chancel. Recent repointing and repair of brickwork and active management of vegetation is evident though.</p> <p>Contact: Tom Foxall 01483 252035</p>

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

THANET



SITE NAME: **The Shell Grotto,
Grotto Hill,
Margate**

Early C19 grotto. Extensive shell designs to walls and ceilings, some of which are loose or have detached completely. A first phase of repairs to address damp issues is now complete.

DESIGNATION: Listed Building Grade I

CONDITION: Poor

OCCUPANCY: N/A

PRIORITY: D (D)

OWNER TYPE: Private

Contact: Tom Foxall 01483 252035



SITE NAME: **Dreamland Cinema,
Marine Terrace,
Margate**

Cinema, 1935. The first English cinema in the style based on the Titania Palast of Berlin, a style subsequently used extensively by Odeon. Vacant and with a backlog of repairs.

DESIGNATION: Listed Building Grade II*

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNER TYPE: Company

Contact: Tom Foxall 01483 252035

SITE NAME: **Barn about 50 metres east of
Ozengell Grange, Haine Road,
Ramsgate**

Derelict late medieval grain barn, on land formerly owned by St Augustine's Abbey, Canterbury.

DESIGNATION: Listed Building Grade II*

CONDITION: Very bad

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNER TYPE: Private

Contact: Tom Foxall 01483 252035



SITE NAME: **RC Church of St Augustine
of England with Cloisters attached,
St Augustine's Road, Ramsgate**

Large town church complex standing on a cliff top, constructed by AWG Pugin. It is at risk due to blocked valley gutters, hoppers, downpipes and drains; slipped and missing roof tiles; leaking asphalt roof to tower; blocked outlet from tower; structural cracking and movement to stonework; eroding stonework; missing coping to west side of cloister; rusting ferramenta to windows; fractured and missing stonework to mullions, tracery and jambs; and defective electrical installation. A Repair Grant for Places of Worship has been offered to support the cost of repair works.

DESIGNATION: Listed Place of Worship Grade I, CA

CONDITION: Very bad

PRIORITY: B (New entry)

OWNER TYPE: Religious organisation

SITE NAME: **Ring ditches and enclosures 500yds (450m) ESE of College Farm, Acol**

DESIGNATION: Scheduled Monument (No. 1005489)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNER TYPE: Private

CONTACT: Judith Roebuck 01483 252048

SITE NAME: **Group of ring ditches 400yds (360m) north west of Great Brooks End Farm, Birchington**

DESIGNATION: Scheduled Monument (No. 1004207)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNER TYPE: Private

CONTACT: Judith Roebuck 01483 252048

SITE NAME: **Anglo-Saxon cemetery, Dane Valley Road, Broadstairs and St Peters**

DESIGNATION: Scheduled Monument (No. 1003601)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNER TYPE: Private

CONTACT: Judith Roebuck 01483 252048

SITE NAME: **Double ring ditch and two enclosures 400yds (360m) north west of Danes Court, Broadstairs and St Peters**

DESIGNATION: Scheduled Monument (No. 1004230)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNER TYPE: Private

CONTACT: Judith Roebuck 01483 252048

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

- CA** Conservation Area
- LB/LBs** Listed Building/s
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM/SMs** Scheduled Monument/s
- UA** Unitary Authority
- WHS** World Heritage Site

SITE NAME:	Anglo-Saxon cemetery south of Ozengell Grange, Margate and Ramsgate		
DESIGNATION:	Scheduled Monument (No. 1004228)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Judith Roebuck 01483 252048

SITE NAME:	Quex Park settlements, Margate and Ramsgate		
DESIGNATION:	Scheduled Monument (No. 1005137)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Judith Roebuck 01483 252048

SITE NAME:	Settlement one mile (1610m) east of village, Margate and Ramsgate		
DESIGNATION:	Scheduled Monument (No. 1005135)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Judith Roebuck 01483 252048

SITE NAME:	Enclosure and ring ditches 200yds (180m) ENE of Minster Laundry, Minster		
DESIGNATION:	Scheduled Monument (No. 1004203)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Judith Roebuck 01483 252048

TONBRIDGE AND MALLING



SITE NAME: **Hadlow Tower,
High Street,
Hadlow**

DESIGNATION: Listed Building Grade I, CA

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: D (C)

OWNER TYPE: Trust

Tower of an otherwise demolished late C18 / early C19 country house. Recently taken on by the VIVAT Trust following a compulsory purchase order. A programme of repairs and conversion to a holiday let is due to commence shortly with grant aid from English Heritage and Heritage Lottery Fund.

Contact: Tom Foxall 01483 252035

SITE NAME:	Romano-British villa, Anglo-Saxon cemetery and associated remains at Eccles, Aylesford		
DESIGNATION:	Scheduled Monument (No. 1011770)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Judith Roebuck 01483 252048

SITE NAME:	Chapel of St Blaise, Offham		
DESIGNATION:	Scheduled Monument (No. 1005488)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Judith Roebuck 01483 252048

SITE NAME:	Town banks, Tonbridge		
DESIGNATION:	Scheduled Monument (No. 1003599)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Judith Roebuck 01483 252048

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

- CA** Conservation Area
- LB/LBs** Listed Building/s
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM/SMs** Scheduled Monument/s
- UA** Unitary Authority
- WHS** World Heritage Site

TUNBRIDGE WELLS



SITE NAME: **Providence Chapel,
Stone Street,
Cranbrook**

Strict Baptist chapel, redundant. 1795 with early to mid C19 alterations.

DESIGNATION: Listed Building Grade II*, CA

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNER TYPE: Private

Contact: Tom Foxall 01483 252035

SITE NAME:

High Rocks Camp (part in East Sussex), Tunbridge Wells

DESIGNATION: Scheduled Monument (No. 1003816)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNER TYPE: Private

CONTACT: Judith Roebuck 01483 252048

SITE NAME:

Royal Tunbridge Wells

DESIGNATION: Conservation Area

CONDITION: At risk

VULNERABILITY: Unknown

TREND: Improving

CONTACT: Alan Legg (LPA) 01892 554069

NEW ENTRY?: No

TUNBRIDGE WELLS / TONBRIDGE AND MALLING



SITE NAME: **Somerhill,
Capel**

DESIGNATION: Registered Park and Garden Grade II,
also 4 LBs

CONDITION: Extensive significant problems

VULNERABILITY: Medium

TREND: Declining

OWNER TYPE: Mixed, multiple owners

Early C19 terraced garden probably laid out by William Sawrey Gilpin, with surrounding, later C19, ornamental gardens, all set within parkland. The site is now divided between a school, an estate and several smaller, private owners all operating diverse management regimes. The school is interested in commissioning a Conservation Management Plan if grant aid is available. This could form the basis of a coordinated management approach for the whole site. Discussions with Natural England are underway.

Contact: Peter Kendall 01483 252038

KENT / EAST SUSSEX

TUNBRIDGE WELLS / WEALDEN



SITE NAME: **Bayham Abbey,
Lamberhurst / Frant**

DESIGNATION: Registered Park and Garden Grade II,
also 7 LBs, 1 SM

CONDITION: Unknown

VULNERABILITY: Medium

TREND: Declining

OWNER TYPE: Mixed, multiple owners

Late C19 mansion gardens with formal terraces and informal pleasure ground all set within a Humphry Repton park focussed on the abbey ruins. The property was divided and sold in the 1970s and further fragmented since then. English Heritage looks after the abbey ruins but fragmentation of ownership has severely compromised this significant picturesque landscape. Co-ordinated action is needed to conserve the historic landscape – part of which lies in East Sussex and part in Kent.

Contact: Peter Kendall 01483 252038

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).


- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

OFF KENT



SITE NAME:	London, Thames Estuary
DESIGNATION:	Protected Wreck Site
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Natural decline
OWNERSHIP:	Government
PHOTO:	© Wessex Archaeology and the Port of London Authority

The London was a Second Rate 'Large Ship' built in Chatham in 1654 during the Interregnum. She is known to have participated in the First Dutch War (1652-4) and later formed part of an English Squadron sent to collect Charles II from the Netherlands and restore him to his throne. The London blew up on passage from Chatham in March 1665. A series of artefacts have been identified on the river bed and recovered to the surface. In addition, an abundance of loose material on the bottom has been noted in a remarkably well preserved state. This suggests that the site has been recently disturbed.


Contact: Simon Goodhugh 01483 252037



SITE NAME:	Northumberland, Goodwin Sands
DESIGNATION:	Protected Wreck Site
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Significant decline
OWNERSHIP:	Government
PHOTO:	© Wessex Archaeology

Third Rate 70-gun warship built 1678 as part of Samuel Pepys' regeneration of the English navy. The first third rate ship to be built under contract, after it was realised that the naval dockyards could not cope with the construction of the number of ships requested. She foundered on Goodwin Sands during the 'Great Storm' of 1703. The Goodwin Sands change morphology on a seasonal basis leading to periodic exposure of the vessel's wooden hulls. Exposed timbers are weakened by biological attack and may be subject to detachment and dispersal by tide and wave surge during winter storms.

Contact: Simon Goodhugh 01483 252037



SITE NAME:	Restoration, Goodwin Sands
DESIGNATION:	Protected Wreck Site
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Significant decline
OWNERSHIP:	Government
PHOTO:	© University of St Andrews and Wessex Archaeology

Although there is no definite evidence, this wreck of a wooden warship is thought to be the remains of the Restoration, a Third Rate 70-gun warship built 1678 as part of Samuel Pepys' regeneration of the English navy. Along with the Northumberland and Stirling Castle, she foundered on Goodwin Sands during the 'Great Storm' of 1703. The Goodwin Sands change morphology on a seasonal basis leading to periodic exposure of the vessel's wooden hulls. Exposed timbers are weakened by biological attack and may be subject to detachment and dispersal by tide and wave surge during winter storms.

Contact: Simon Goodhugh 01483 252037



SITE NAME:	Rooswijk, Goodwin Sands
DESIGNATION:	Protected Wreck Site
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	High
TREND:	Declining
OWNER TYPE:	Private
PHOTO:	© Private

The VOC (Dutch East Company) ship Rooswijk was built in Amsterdam in 1737 but stranded on the Goodwin Sands in 1739 while en route from the Texel to the East Indies. The site represents archaeological evidence for the practice of large-scale overseas commerce between the Netherlands and Asia during the C18. As with other sites in the Goodwins, archaeological material is at risk owing to mobile sediments causing periodic exposure.

Contact: Simon Goodhugh 01483 252037



SITE NAME:	Stirling Castle, Goodwin Sands
DESIGNATION:	Protected Wreck Site
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Declining
OWNER TYPE:	Trust
PHOTO:	© Seadive

One of twenty Third Rate 70-gun warships built 1678 at Deptford as part of Samuel Pepys' regeneration of the English navy. Like the Northumberland and the Restoration she was rebuilt at Chatham in 1699. All three ships foundered on the Goodwin Sands during the 'Great Storm' of 1703.

Contact: Simon Goodhugh 01483 252037

MEDWAY (UA)



SITE NAME:	The Chapel of St Bartholomew, High Street, Chatham
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Vacant
PRIORITY:	C (D)
OWNER TYPE:	Private

Redundant hospital Chapel, C12. Now vacant, but potentially for sale.

Contact: Tom Foxall 01483 252035

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME: **Cliffe Fort,
Cliffe**

DESIGNATION: Scheduled Monument

CONDITION: Very bad

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNER TYPE: Company

Fort circa 1860. Fort is now flooded. Much of it is stable due to massive construction, but significant detail is vulnerable to decay or vandalism. Remains of Brennan Torpedo Rail are also vulnerable to erosion. English Heritage has carried out detailed recording in 2010.

Contact: Peter Kendall 01483 252038



SITE NAME: **Cooling Castle,
Cooling**

DESIGNATION: Listed Building Grade I, SM

CONDITION: Very bad

OCCUPANCY: Part occupied

PRIORITY: A (A)

OWNER TYPE: Private

A quadrangular castle with ruined fabric, some of which is in need of major repair.

Contact: Peter Kendall 01483 252038



SITE NAME: **Barn 30 yards south east of
the manor, Upnor Road (south side),
Frindsbury Extra**

DESIGNATION: Listed Building Grade I, CA

CONDITION: Very bad

OCCUPANCY: Vacant

PRIORITY: A (A)

OWNER TYPE: Private

Very fine medieval barn, more or less redundant for agricultural use. Subject to fire damage.

Contact: Tom Foxall 01483 252035



SITE NAME: **Brompton Lines,
Gillingham**

DESIGNATION: Scheduled Monument, CA

CONDITION: Poor

OCCUPANCY: N/A

PRIORITY: D (D)

OWNER TYPE: Government

Landward defences to dockyard at Chatham, subsequently used in part as a pleasure ground for officers. Now cross Ministry of Defence owned land, housing and Brompton Barracks. Lower lines site now released to new owner. Discussions continue about management of retained MOD parts.

Contact: Peter Kendall 01483 252038



SITE NAME: **Fort Darnet,
Gillingham**

DESIGNATION: Scheduled Monument

CONDITION: Very bad

OCCUPANCY: Vacant

PRIORITY: A (A)

OWNER TYPE: Private

A Royal Commission fort circa 1860, in the Medway Estuary, washed by high tides.

Contact: Peter Kendall 01483 252038



SITE NAME: **No. 8 machine shop,
Dock Head Road,
Chatham Dockyard, Gillingham**

DESIGNATION: Listed Building Grade II*

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNER TYPE: Quango

1840 former dry dock cover, later used as Machine Shop, now disused. Cladding removed and awaiting solution.

Contact: Tom Foxall 01483 252035

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	Cockham Wood Fort, Hoo St Werburgh
DESIGNATION:	Scheduled Monument
CONDITION:	Very bad
OCCUPANCY:	Vacant
PRIORITY:	A (A)
OWNER TYPE:	Private

A rare C17 artillery fort. The brick lower battery is very decayed as it is washed by the tidal Medway. The higher earthwork batteries survive but in woodland, with the remains of a redoubt and commander's house.

Contact: Peter Kendall 01483 252038



SITE NAME:	Fort Hoo, Hoo St Werburgh
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	C (C)
OWNER TYPE:	Company

Sister fort to Fort Darnet circa 1860. Fort lies abandoned on an island in the Medway.

Contact: Peter Kendall 01483 252038



SITE NAME:	Artillery Tower (Grain Tower), Isle of Grain
DESIGNATION:	Listed Building Grade II, SM
CONDITION:	Very bad
OCCUPANCY:	Vacant
PRIORITY:	C (C)
OWNER TYPE:	Private

Artillery tower. Late 1840s to early 1850s. Forms part of the defences to Sheerness dockyard. Abandoned and surrounded by the sea at high tide.

Contact: Peter Kendall 01483 252038



SITE NAME:	Brompton Lines (Fort Amherst), Rochester
DESIGNATION:	Scheduled Monument, CA
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	B (B)
OWNER TYPE:	Trust

Part of the major C18 landward defence to the dockyard at Chatham. Open to the public as part of the Great Lines Heritage Park. Grants from English Heritage and local authority have conserved main part but significant areas still derelict.

Contact: Peter Kendall 01483 252038



SITE NAME:	351 High Street, Rochester
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	E (E)
OWNER TYPE:	Company

Early C18 town house, last used as a shop in 1980s. Empty since then, but a programme of repairs is currently under discussion.

Contact: Tom Foxall 01483 252035

SITE NAME:	Gillingham Green	
DESIGNATION:	Conservation Area	CONDITION: Poor
VULNERABILITY:	High	TREND: No significant change
CONTACT:	Alice Brockway (LPA) 01634 334317	NEW ENTRY: Yes

SITE NAME:	Halling	
DESIGNATION:	Conservation Area	CONDITION: Poor
VULNERABILITY:	High	TREND: No significant change
CONTACT:	Alice Brockway (LPA) 01634 334317	NEW ENTRY: Yes

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

- CA Conservation Area
- LB/LBs Listed Building/s
- LPA Local Planning Authority
- NP National Park
- RPG Registered Park and Garden
- SM/SMs Scheduled Monument/s
- UA Unitary Authority
- WHS World Heritage Site

SITE NAME:	Star Hill to Sun Pier		
DESIGNATION:	Conservation Area	CONDITION:	Fair
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Alice Brockway (LPA) 01634 334317	NEW ENTRY?:	Yes

MILTON KEYNES (UA)

SITE NAME: **Orchard House,
67 and 69 High Street,
Olney**

DESIGNATION: Listed Building Grade II*, CA

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: A (A)

OWNER TYPE: Private

Pair of C18 houses converted into a single dwelling in 1904 by Ellis Anderson for Joseph William Mann. Impressive and exceptionally complete Edwardian interior. Flat roofs, parapet gutters and hip and valley soakers are all failing and both stonework and interior plasterwork are being damaged by water ingress. Some urgent works carried out.

Contact: Richard Peats 01483 252026

SITE NAME:	Roman town of Magiovinium and Roman fort, Bletchley and Fenny Stratford		
DESIGNATION:	Scheduled Monument (No. 1006943)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Wood Farm moat, Clifton Keynes		
DESIGNATION:	Scheduled Monument (No. 1006919)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	St Martin's Church (site of), Emberton		
DESIGNATION:	Scheduled Monument (No. 1021373)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Roman villa 300m south east of Newton Lodge Farm, Newton Blossomville		
DESIGNATION:	Scheduled Monument (No. 1014794)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Roman site at Olney, Olney		
DESIGNATION:	Scheduled Monument (No. 1006918)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Group of ring ditches and enclosures at Tyringham, Tyringham and Filgrave		
DESIGNATION:	Scheduled Monument (No. 1006924)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHs	World Heritage Site

OXFORDSHIRE

CHERWELL



SITE NAME: **Hampton Gay Manor House,
Hampton Gay,
Hampton Gay and Poyle**

Manor house, late C16. Burnt down in 1887.
Now a roofless ruin.

DESIGNATION: Listed Building Grade II, SM

CONDITION: Very bad

OCCUPANCY: N/A

PRIORITY: A (A)

OWNER TYPE: Private

Contact: Chris Welch 01483 252027



SITE NAME: **Church of St Peter,
High Street, Hook Norton,
Barnbury**

Large church constructed of coursed rubble iron stone with limestone ashlar dressings, dating from Norman period. Roof coverings are failing and allowing water ingress. Repairs required to chancel roof leadwork, gutters, associated timbers, and stonework repointing. A Repair Grant for Places of Worship has been offered to support this work.

DESIGNATION: Listed Place of Worship Grade I, CA

CONDITION: Poor

PRIORITY: D (New entry)

OWNER TYPE: Religious organisation

Contact: Jane Wilkinson 01483 252029



SITE NAME: **Church of St Peter and St Paul,
Main Road,
Swalcliffe**

Large village church dating to before the Norman Conquest, with its present form largely complete by the end of C14. Constructed of Brown Horton, a local iron-rich limestone, with lead roofs. Tower leadwork and stone walls are decayed and eroded. Repairs required to tower of roof and stonework. A Repair Grant for Places of Worship has been offered to support this work.

DESIGNATION: Listed Place of Worship Grade I, CA

CONDITION: Poor

PRIORITY: D (New entry)

OWNER TYPE: Religious organisation

Contact: Jane Wilkinson 01483 252029

SITE NAME:

Castle Bank Enclosure

DESIGNATION:

Scheduled Monument (No. 1021414)

CONDITION:

Extensive significant problems

PRINCIPAL VULNERABILITY:

Arable ploughing

TREND:

Declining

OWNER TYPE:

Private

CONTACT:

Chris Welch 01483 252027

SITE NAME:

Ilbury Camp hillfort, Deddington

DESIGNATION:

Scheduled Monument (No. 1015167)

CONDITION:

Generally satisfactory
but with significant localised problems

PRINCIPAL VULNERABILITY:

Arable ploughing

TREND:

Declining

OWNER TYPE:

Private

CONTACT:

Chris Welch 01483 252027

SITE NAME:

Islip Roman villa, 300m east of Hillside Farm, Islip

DESIGNATION:

Scheduled Monument (No. 1015161)

CONDITION:

Extensive significant problems

PRINCIPAL VULNERABILITY:

Arable ploughing

TREND:

Declining

OWNER TYPE:

Private

CONTACT:

Chris Welch 01483 252027

SITE NAME:

RAF Bicester: World War II airfield, Laughton

DESIGNATION:

Scheduled Monument (No. 1021455)

CONDITION:

Generally unsatisfactory
with major localised problems

PRINCIPAL VULNERABILITY:

Extensive animal burrowing

TREND:

Declining

OWNER TYPE:

Government or Agency

CONTACT:

Chris Welch 01483 252027

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA Conservation Area
LB/LBs Listed Building/s
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM/SMs Scheduled Monument/s
UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Blenheim Villa, a Roman villa and associated field system 200m north east of Little Cote, Shipton-on-Cherwell and Thrupp		
DESIGNATION:	Scheduled Monument (No. 1021367)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Long barrow 730m south west of Enslow Bridge, Shipton-on-Cherwell and Thrupp		
DESIGNATION:	Scheduled Monument (No. 1021413)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Banbury Grimsbury		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Deteriorating significantly
CONTACT:	Rose Todd (LPA) 01295 221846	NEW ENTRY:	Yes

SITE NAME:	Bicester		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Rose Todd (LPA) 01295 221846	NEW ENTRY:	Yes

SITE NAME:	Cropredy		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	No significant change
CONTACT:	Rose Todd (LPA) 01295 221846	NEW ENTRY:	Yes

SITE NAME:	Duns Tew		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Rose Todd (LPA) 01295 221846	NEW ENTRY:	Yes

SITE NAME:	RAF Bicester, Caversfield		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Deteriorating significantly
CONTACT:	Rose Todd (LPA) 01295 221846	NEW ENTRY:	Yes

SITE NAME:	RAF Upper Heyford, Upper Heyford, Ardley		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Rose Todd (LPA) 01295 221846	NEW ENTRY:	Yes

OXFORD



SITE NAME:	Osney Abbey, Mill Street, Oxford
DESIGNATION:	Listed Building Grade II, SM
CONDITION:	Fair
OCCUPANCY:	Part occupied
PRIORITY:	C (C)
OWNER TYPE:	Company

Only surviving building of Augustinian Priory, founded 1129. Rubble and timber-framed building, probably C15, with C16 roof. Attached wall with C15 archway. Currently included in discussions over the wider Osney Mill site.

Contact: Chris Welch 01483 252027

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME: **Church of St Thomas the Martyr,
St Thomas Street**

Roof in poor condition though structurally sound overall. The rainwater goods are generally adequate apart from one gutter, and stonework is fair to poor.

DESIGNATION: Listed Place of Worship Grade II

CONDITION: Poor

PRIORITY: C (New entry)

OWNER TYPE: Religious organisation

Contact: Kathryn Davies 01483 252028

SITE NAME:

Swing bridge, LNWR Station, Oxford

DESIGNATION: Scheduled Monument (No. 1003651)

CONDITION: Generally unsatisfactory
with major localised problems

PRINCIPAL VULNERABILITY: Scrub / tree growth

TREND: Declining

OWNER TYPE: Local Authority

CONTACT: Chris Welch 01483 252027

SOUTH OXFORDSHIRE



SITE NAME: **Well House,
Wick Farmhouse, Barton,
Beckley and Stowood**

Well House associated with Wick Farmhouse, late C17, in poor condition and not in use. Square plan ashlar structure in Baroque style with stone benches lining walls. Well now filled in. Not in use.

DESIGNATION: Listed Building Grade II*

CONDITION: Poor

OCCUPANCY: N/A

PRIORITY: C (New entry)

OWNER TYPE: Private

Contact: Kathryn Davies 01483 252028



SITE NAME: **Bix Old Church,
Bix,
Bix and Assendon**

Ruins of church of St James. Norman chancel with later additions. Very overgrown. Roofless, with considerable collapse at west end. Further collapse likely. English Heritage Section 17 management agreement with PCC to control vegetation (2010).

DESIGNATION: Listed Building Grade II, SM

CONDITION: Very bad

OCCUPANCY: N/A

PRIORITY: A (A)

OWNER TYPE: Religious organisation

Contact: Chris Welch 01483 252027

SITE NAME: **Gothic Temple,
Shotover Park,
Forest Hill with Shotover**

Gothic Temple within the grade I Shotover Park, designed as a garden temple or boathouse c1740, by William Townsend of Oxford (?) for General James Tyrrell in Gothick style. The temple lies at the eastern end of the main axis of the early C18 layout of the formal garden. Front repaired 10 years ago but rear structure in need of repairs to roof and rainwater goods. Conservation Management Plan completed 2009.

DESIGNATION: Listed Building Grade II*, RPG I

CONDITION: Poor

OCCUPANCY: N/A

PRIORITY: C (C)

OWNER TYPE: Private

Contact: Richard Peats 01483 252026



SITE NAME: **Walled garden approximately
30 metres west of manor,
North Weston, Great Haseley**

Walled garden with loggia dating from early C18. Built of brick with limestone ashlar details and a plain tile roof to the loggia. The wall has a moulded brick coping. It was formerly part of the North Weston Manor which was largely demolished in early C19. The wall tops are disintegrating; there are structural cracks and the loggia is propped to prevent collapse.

DESIGNATION: Listed Building Grade II*

CONDITION: Very bad

OCCUPANCY: N/A

PRIORITY: A (A)

OWNER TYPE: Private

Contact: Richard Peats 01483 252026

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

- CA** Conservation Area
- LB/LBs** Listed Building/s
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM/SMs** Scheduled Monument/s
- UA** Unitary Authority
- WHS** World Heritage Site



SITE NAME:	Fernhouse, archway, gateway and walls, The Street, Mapledurham
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	C (C)
OWNER TYPE:	Private

Fernhouse, archway, gateway and walls. C17 and C18. The Fernhouse is roofless.

Contact: Richard Peats 01483 252026



SITE NAME:	Church of St Peter and St Paul, Checkendon
DESIGNATION:	Listed Place of Worship Grade I, CA
CONDITION:	Poor
PRIORITY:	D (New entry)
OWNER TYPE:	Religious organisation

A small Norman church of flint and stone with ashlar dressing. It is little altered since the medieval period and is in a small rural village location. Rare find of original wall paintings in the north chancel wall were revealed in recent years, dating from 1330-1340. Requires repairs to the roofs of the nave, chancel and apse, to drainage and rainwater disposal systems and remedial works to apse walls and the wall paintings. A Repair Grant for Places of Worship has been offered to support these works.

Contact: Jane Wilkinson 01483 252029



SITE NAME:	Church of St Peter, Main Street, Little Wittenham
DESIGNATION:	Listed Place of Worship Grade II*, CA
CONDITION:	Poor
PRIORITY:	D (New entry)
OWNER TYPE:	Religious organisation

Rural hamlet church with C14 to C15 tower and staircase turret. Nave rebuilt and restored 1862 and extension to north side of chancel 1902. Tower leadwork and stonework is decayed and allowing water ingress. Extensive repairs required to much of tower and associated timbers. A Repair Grant for Places of Worship has been offered to support this work.

Contact: Jane Wilkinson 01483 252029



SITE NAME:	Church of All Saints, Church Street, North Moreton
DESIGNATION:	Listed Place of Worship Grade I, CA
CONDITION:	Very bad
PRIORITY:	F (New entry)
OWNER TYPE:	Religious organisation

Mainly flint and sandstone, with tiled nave and chancel, and copper sheet roof to south aisle. Mostly mid C13 to C14, altered C15 and restored in Victorian era. Tower roof currently under repair but chantry chapel and south aisle in need of urgent repairs too. Several phases of work likely to be required to fully repair and recover the remaining roofs. Two Repair Grants for Places of Worship have been offered to support the work so far.

Contact: Jane Wilkinson 01483 252029

SITE NAME:	North Stoke henge and ring ditch site, Crowmarsh	
DESIGNATION:	Scheduled Monument (No. 1006335)	CONDITION: Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND: Declining
OWNER TYPE:	Private	CONTACT: Chris Welch 01483 252027

SITE NAME:	Dike Hills, Dorchester	
DESIGNATION:	Scheduled Monument (No. 1006364)	CONDITION: Extensive significant problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND: Declining
OWNER TYPE:	Private	CONTACT: Chris Welch 01483 252027

SITE NAME:	Ring ditches, cursus, enclosures and settlement site, Dorchester	
DESIGNATION:	Scheduled Monument (No. 1006344)	CONDITION: Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND: Declining
OWNER TYPE:	Private	CONTACT: Chris Welch 01483 252027

SITE NAME:	Settlement site at Northfield Farm, Long Wittenham	
DESIGNATION:	Scheduled Monument (No. 1002925)	CONDITION: Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND: Declining
OWNER TYPE:	Private	CONTACT: Chris Welch 01483 252027

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Site of Roman kilns, Marsh Baldon		
DESIGNATION:	Scheduled Monument (No. 1006337)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Church Piece cemetery site, Warborough		
DESIGNATION:	Scheduled Monument (No. 1003243)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Long barrow 140m north west of Cooks Cottages, Warborough		
DESIGNATION:	Scheduled Monument (No. 1016629)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Long barrow 340m north west of Cooks Cottages, Warborough		
DESIGNATION:	Scheduled Monument (No. 1016632)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Romano-British settlement 520m north west of Cooks Cottages, Warborough		
DESIGNATION:	Scheduled Monument (No. 1016630)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Thomley deserted medieval village, Waterperry with Thomley		
DESIGNATION:	Scheduled Monument (No. 1006295)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Camp on Bozedown, Whitchurch on Thames		
DESIGNATION:	Scheduled Monument (No. 1003704)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

VALE OF WHITE HORSE

SITE NAME:	Castle mound at Fitzharris, Abingdon		
DESIGNATION:	Scheduled Monument (No. 1006311)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Sutton Wick settlement site, Abingdon		
DESIGNATION:	Scheduled Monument (No. 1003671)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHs	World Heritage Site

SITE NAME:	Settlement site south east of church, Appleford-on-Thames		
DESIGNATION:	Scheduled Monument (No. 1004849)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Settlement site, Drayton		
DESIGNATION:	Scheduled Monument (No. 1004852)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	East Hendred Down bowl barrow, East Hendred		
DESIGNATION:	Scheduled Monument (No. 1016982)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Yew Down round barrow 950m south west of Butterbush Reservoir, Lockinge		
DESIGNATION:	Scheduled Monument (No. 1018719)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Settlement site north of Cow Lane, Marcham		
DESIGNATION:	Scheduled Monument (No. 1004850)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Disc barrow 700m north east of Sevenbarrows House: part of the Seven Barrows cemetery, Sparsholt		
DESIGNATION:	Scheduled Monument (No. 1012343)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Roman villa east of Cornhill Farm, West Challow		
DESIGNATION:	Scheduled Monument (No. 1004854)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

WEST OXFORDSHIRE



SITE NAME:	Church of St Britius, Station Road, Brize Norton
DESIGNATION:	Listed Place of Worship Grade II*
CONDITION:	Poor
PRIORITY:	D (New entry)
OWNER TYPE:	Religious organisation

A Norman church, later enlarged in C13 when West Tower was added. Considerable restoration carried out in 1868. Walls of coursed limestone rubble and roofs of gabled stone slates. Roofs are in a very poor condition; a tarpaulin has been put up inside to catch plaster falls caused by areas of stone slate slippage. A Repair Grant for Places of Worship has been offered to support remedial repairs to high level masonry.

Contact: Jane Wilkinson 01483 252029



SITE NAME:	Church of St Nicholas, Kiddington
DESIGNATION:	Listed Place of Worship Grade II*
CONDITION:	Poor
PRIORITY:	D (New entry)
OWNER TYPE:	Religious organisation

A mostly C14 rural village church with a C12 core, restored 1879 with addition of vestry. Constructed of coursed limestone rubble with lead roofs, except stone slates to chancel. Repairs required to nave roof, which is failing and allowing water ingress, and to parapet stonework and rainwater goods. A Repair Grant for Places of Worship has been offered to support this work.

Contact: Jane Wilkinson 01483 252029

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Iron Age settlement centring 500m south west of Black Bourton, Alvescot		
DESIGNATION:	Scheduled Monument (No. 1002924)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Asthall Barrow: an Anglo-Saxon burial mound 100m SSW of Barrow Farm, Asthal		
DESIGNATION:	Scheduled Monument (No. 1008414)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Pair of confluent bowl barrows 200m SSW of Bockett's Corner on Leigh Hale Plain, Asthal		
DESIGNATION:	Scheduled Monument (No. 1008492)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Ring ditches, Aston, Cote, Shifford and Chimney		
DESIGNATION:	Scheduled Monument (No. 1006341)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Interrupted ditch system, Broadwell		
DESIGNATION:	Scheduled Monument (No. 1006340)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Bowl barrow 525m north of Barter's Hill Farm, Chadlington		
DESIGNATION:	Scheduled Monument (No. 1014562)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Besbury Lane bowl barrow, 450m north east of Conduit Farm, Churchill		
DESIGNATION:	Scheduled Monument (No. 1015324)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	One of a pair of bowl barrows 370m north west of High Lodge, Cornbury and Wychwood		
DESIGNATION:	Scheduled Monument (No. 1011219)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	One of a pair of bowl barrows 370m north west of High Lodge, Cornbury and Wychwood		
DESIGNATION:	Scheduled Monument (No. 1011227)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Pair of bowl barrows immediately south of Blindwell Wood, Crawley		
DESIGNATION:	Scheduled Monument (No. 1015212)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Sites discovered by aerial photography, near Foxley Farm, Eynsham		
DESIGNATION:	Scheduled Monument (No. 1006333)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Oaklands Farm Roman villa, Fawler		
DESIGNATION:	Scheduled Monument (No. 1012901)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Linear earthworks east of Callow Hill Roman villa forming part of the north Oxfordshire Grim's Ditch, Glympton		
DESIGNATION:	Scheduled Monument (No. 1014751)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Ring ditches, Grafton and Radcot		
DESIGNATION:	Scheduled Monument (No. 1006339)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Beaconsfield Farm Roman villa, Great Tew		
DESIGNATION:	Scheduled Monument (No. 1006352)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	145m section of the north Oxfordshire Grim's Ditch situated 200m west of Grimsdyke Farm, Kiddington with Asterleigh		
DESIGNATION:	Scheduled Monument (No. 1012905)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Medieval settlement and church of Asterleigh, Kiddington with Asterleigh		
DESIGNATION:	Scheduled Monument (No. 1020966)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Pump Copse earthwork, Kiddington with Asterleigh		
DESIGNATION:	Scheduled Monument (No. 1003242)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHs	World Heritage Site

SITE NAME:	Enclosures and trackways, Langford		
DESIGNATION:	Scheduled Monument (No. 1006327)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Rectangular enclosures 1100yds (1010m) north west of Mount Owen Farm, Lew		
DESIGNATION:	Scheduled Monument (No. 1006348)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Enclosures 1500m south east of Little Faringdon, Little Faringdon		
DESIGNATION:	Scheduled Monument (No. 1006316)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Skew Plantation bowl barrow, Sarsden		
DESIGNATION:	Scheduled Monument (No. 1015171)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Shipton Barrow: a bowl barrow, Saxon barrow, and associated earthwork enclosure 350m north of Downs Lodge, Shipton-under-Wychwood		
DESIGNATION:	Scheduled Monument (No. 1008493)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Complex of rectangular enclosures, ring ditches and tracks, Standlake		
DESIGNATION:	Scheduled Monument (No. 1006342)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Callow Hill Roman villa, Stonesfield		
DESIGNATION:	Scheduled Monument (No. 1014750)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	90m section of the north Oxfordshire Grim's Ditch 350m south of Grim's Dyke Farm, Wootton		
DESIGNATION:	Scheduled Monument (No. 1012909)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHs	World Heritage Site

PORTSMOUTH, CITY OF (UA)



SITE NAME:	Wymering Manor, Old Wymering Lane, Cosham,
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Vacant
PRIORITY:	C (New entry)
OWNER TYPE:	Local authority

Manor house with Medieval fabric and later work, most recently a youth hostel. In need of some structural repair and general renovation.

Contact: David Brock 01483 252044



SITE NAME:	Fort Southwick, moat and ramparts, Portsdown Hill, Portsmouth
DESIGNATION:	Listed Building Grade I, SM
CONDITION:	Fair
OCCUPANCY:	Part occupied
PRIORITY:	F (F)
OWNER TYPE:	Trust

Fort circa 1860s. Part of Palmerston's Portsmouth defences. In poor condition in parts. Fort is now in private ownership following disposal by Defence Estate, and has benefited from a recent programme of repair and consolidation.

Contact: Richard Massey 01483 252046



SITE NAME:	Fort Cumberland, Fort Cumberland Road, Eastney, Portsmouth
DESIGNATION:	Listed Building Grade II*, SM
CONDITION:	Poor
OCCUPANCY:	Part occupied
PRIORITY:	F (F)
OWNER TYPE:	English Heritage

Coastal fort of 1746-1812 with later buildings and features. Some repairs have been carried out, and the number of buildings being used by the Centre for Archaeology and others has increased. The Guardhouse, a stand-alone structure within the Fort Cumberland complex and the only surviving element of the 1747 Demarets Fort, is suffering from water ingress and associated decay.

Contact: Richard Massey 01483 252046



SITE NAME:	Hilsea Lines – Bastion No. 5, Hilsea, Portsmouth
DESIGNATION:	Scheduled Monument, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY:	A (A)
OWNER TYPE:	Local authority

Earthwork defence dating from 1858-1869, with batteries, magazines and barracks. Bastion No. 5 is continuing to suffer from vandalism and neglect.

Contact: Richard Massey 01483 252046



SITE NAME:	No. 25 Store, Yard Services Manager's Office, 1/118 Jago Road, HM Naval Base, Portsmouth
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Vacant
PRIORITY:	C (C)
OWNER TYPE:	Government

Two storey storehouse of 1782, with internal courtyard. In fair condition but vacant. Future use uncertain.

Contact: Alan Johnson 020 7973 3174



SITE NAME:	2-8 The Parade, HM Naval Base, Portsmouth
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	A (A)
OWNER TYPE:	Government

Terrace of dockyard officers' lodgings, 1715-19. Partially converted to office use c1995, but now empty. Prone to wet rot and some structural movement. An options report is said to have been drawn up. A repairs schedule promised by May 2009 has not been circulated.

Contact: Rory O'Donnell 020 7973 3775

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	Iron and Brass Foundry, 1/140 Victoria Road, HM Naval Base, Portsmouth
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Part occupied
PRIORITY:	C (C)
OWNER TYPE:	Government

The main part of the building was converted to office use in 2003. The east wing (Building 1/136) remains unused and at risk. There are concerns over water ingress.

Contact: Alan Johnson 020 7973 3174

SITE NAME:	Former Royal Naval Academy (Buildings 1/14 and 1/116-9), HM Naval Base Portsmouth, Portsmouth
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	A (New entry)
OWNER TYPE:	Crown

One of the oldest structures in the Dockyard, this building is a Georgian forerunner of the Britannia Royal Naval College at Dartmouth. There are problems with water ingress in the right-hand wing.

Contact: Rory O'Donnell 020 7973 3775



SITE NAME:	The Beneficial School, Kent Street, Portsea, Portsmouth
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Occupied
PRIORITY:	D (D)
OWNER TYPE:	Company

Charity school, 1784 and 1836. Now in use as a dance-drama school but needs further repair.

Contact: David Brock 01483 252044



SITE NAME:	No. 6 Dock, Basin No. 1, Portsmouth Dockyard, Portsmouth
DESIGNATION:	Listed Building Grade I, SM, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY:	C (C)
OWNER TYPE:	Government

Naval dock c1690 rebuilt 1737, immediately adjacent to the Block Mills. The dock is suffering from rotation and mortar joints on the stonework alters on the north side have opened up.

Contact: Rory O'Donnell 020 7973 3775



SITE NAME:	Horse Sand Fort, Solent, Portsmouth
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	C (C)
OWNER TYPE:	Company

C19 sea fort in state of dereliction. Owned by private company which is looking to convert the property.

Contact: Richard Massey 01483 252046



SITE NAME:	Church of St Mary, Kingston, Fratton Road
DESIGNATION:	Listed Place of Worship Grade II*, CA
CONDITION:	Poor
PRIORITY:	F (New entry)
OWNER TYPE:	Religious organisation

The church has received a lot of grant in three phases, which have recently concluded, and this has dealt with the roofs and tower; leaving no major problems, though some stonework repair is still needed to the tower and structural problems at the east end of the sanctuary have been reported. Internally water staining is very clear at the east end though it is unclear if active ingress is occurring. The church is much loved, very well used and in no danger of closing.

Contact: Andy White 01483 252047

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

READING (UA)



SITE NAME: **Chazey Farm barn, The Warren, Reading**

DESIGNATION: Listed Building Grade I

CONDITION: Very bad

OCCUPANCY: Vacant

PRIORITY: A (A)

OWNER TYPE: Company

A very large seven bay red brick barn C17 or earlier. Structural cracking and gable currently has temporary shoring. The building forms part of a larger site proposal for a healthcare development. Ground works for new development undertaken spring 2010. No works to barn.

Contact: Richard Peats 01483 252026

SITE NAME: **Reading Abbey: a Cluniac and Benedictine monastery and Civil War earthwork, Reading**

DESIGNATION: Scheduled Monument (No. 1007932) CONDITION: Generally unsatisfactory with major localised problems

PRINCIPAL VULNERABILITY: Deterioration – in need of management TREND: Declining

OWNER TYPE: Local Authority CONTACT: Chris Welch 01483 252027

SOUTHAMPTON, CITY OF (UA)



SITE NAME: **Star Hotel, 26-27 High Street**

DESIGNATION: Listed Building Grade II*, CA

CONDITION: Poor

OCCUPANCY: Occupied

PRIORITY: C (New entry)

OWNER TYPE: Company

Important coaching inn of C18, suffering from deferred maintenance.

Contact: David Brock 01483 252044



SITE NAME: **Chapel Mills, American Wharf, Elm Street, Southampton**

DESIGNATION: Listed Building Grade II*

CONDITION: Poor

OCCUPANCY: Occupied

PRIORITY: D (C)

OWNER TYPE: Company

Former steam mill, 1781 and 1800, built to produce ship's biscuits for the Navy. Now used as storage and suffering from lack of maintenance. An application for domestic use could now be implemented.

Contact: David Brock 01483 252044



SITE NAME: **Red Lion Public House, 55 High Street, Southampton**

DESIGNATION: Listed Building Grade II*

CONDITION: Poor

OCCUPANCY: Part occupied

PRIORITY: C (C)

OWNER TYPE: Private

C15 hall house now commercial premises, suffering from water ingress and deferred maintenance.

Contact: David Brock 01483 252044



SITE NAME: **St Denys Church, St Denys Road, St Denys**

DESIGNATION: Listed Place of Worship Grade II

CONDITION: Poor

PRIORITY: C (New entry)

OWNER TYPE: Religious organisation

Large suburban church designed by Sir George Gilbert Scott in 1868 and built of brick. At risk due to some severely corroded cast iron down pipes to the north elevation, some slipped and uneven roof tiling and falls of ceiling plaster internally.

Contact: Andy White 01483 252047

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

- CA Conservation Area
- LB/LBs Listed Building/s
- LPA Local Planning Authority
- NP National Park
- RPG Registered Park and Garden
- SM/SMs Scheduled Monument/s
- UA Unitary Authority
- WHS World Heritage Site

SURREY

ELMBRIDGE



SITE NAME: **The Railway Straight-Brooklands Motor Racing Circuit, Byfleet**

DESIGNATION: Scheduled Monument, CA

CONDITION: Very bad

OCCUPANCY: N/A

PRIORITY: B (New entry)

OWNER TYPE: Company

The designated section of the Railway Straight comprising c700m of the 1907 circuit, from the eastern boundary of the Mercedes-Benz History and Technology Centre to the modern break in the circuit north of Avro Way. Agreed works need to be undertaken.

Contact: Richard Massey 01483 252046



SITE NAME: **Former kitchen garden walls to Claremont House, Claremont Park Road, Esher**

DESIGNATION: Listed Building Grade II*, RPG I

CONDITION: Poor

OCCUPANCY: N/A

PRIORITY: C (C)

OWNER TYPE: Private

Garden walls, 1717 by Vanbrugh. Unusually monumental. Suffering from vegetation and mortar loss and in need of general repair. Investigations for possible repairs underway with one of the owners.

Contact: Andy White 01483 252047



SITE NAME: **The Belvedere, Claremont Park, Esher**

DESIGNATION: Listed Building Grade II*, SM, RPG I

CONDITION: Fair

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNER TYPE: Charity

Eye-catcher and viewpoint in the form of a mock castle, 1717 by Sir John Vanbrugh. In need of repair to bring it back into use as a focal point of the grade I landscape of Claremont Park.

Contact: David Brock 01483 252044

SITE NAME:

Brooklands

DESIGNATION:

Conservation Area

CONDITION:

At risk

VULNERABILITY:

Unknown

TREND:

Deteriorating

CONTACT:

Clare Smith (LPA) 01 372 474828

NEW ENTRY:

No

EPSOM AND EWELL



SITE NAME: **Riding School at The Durdans, Chalk Lane, Epsom**

DESIGNATION: Listed Building Grade II*, CA

CONDITION: Fair

OCCUPANCY: N/A

PRIORITY: D (C)

OWNER TYPE: Company

Covered riding school of 1881, designed by George Devey for Lord Rosebery. Now used as part of a stable. The yard is now tenanted and to be repaired.

Contact: David Brock 01483 252044

SITE NAME:

Adelphi Road, Epsom

DESIGNATION:

Conservation Area

CONDITION:

Poor

VULNERABILITY:

Low

TREND:

Deteriorating

CONTACT:

Anthony Evans (LPA) 01 372 732394

NEW ENTRY:

No

SITE NAME:

Epsom Town Centre

DESIGNATION:

Conservation Area

CONDITION:

At risk

VULNERABILITY:

Unknown

TREND:

Deteriorating

CONTACT:

Anthony Evans (LPA) 01 372 732394

NEW ENTRY:

No

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA Conservation Area
LB/LBs Listed Building/s
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM/SMs Scheduled Monument/s
UA Unitary Authority
WHs World Heritage Site

SITE NAME:	Ewell Village		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Anthony Evans (LPA) 01372 732394	NEW ENTRY?:	No

SITE NAME:	Linton's Lane, Epsom		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Anthony Evans (LPA) 01372 732394	NEW ENTRY?:	Yes

SITE NAME:	West Park, Epsom		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Improving significantly
CONTACT:	Anthony Evans (LPA) 01372 732394	NEW ENTRY?:	Yes

GUILDFORD



SITE NAME: **St Mary's Church, Quarry Street**

DESIGNATION: Listed Place of Worship Grade I, CA
 CONDITION: Very bad
 PRIORITY: B (New entry)
 OWNER TYPE: Religious organisation

Impressive medieval town centre church. At risk due to roof tiles being in poor condition, especially to east end, with slipped and missing tiles and ineffective rainwater goods. Decaying stonework including to window surrounds. Deep perimeter drainage channel with defective joints. Water penetration has caused internal water damage at low level to plaster and stonework. A Repair Grant for Places of Worship was offered in 2009 to support repair work, though several phases of repair work will be required overall.

Contact: Andy White 01483 252047

SITE NAME:	Hillbury hillfort, Puttenham		
DESIGNATION:	Scheduled Monument (No. 1017797)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Large univallate hillfort at Felday, Shere		
DESIGNATION:	Scheduled Monument (No. 1007984)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046



SITE NAME: **Clandon Park, West Clandon**

DESIGNATION: Registered Park and Garden Grade II, also part in CA, 8 LBs

CONDITION: Extensive significant problems

VULNERABILITY: High

TREND: Declining

OWNER TYPE: Mixed, multiple owners

Lancelot Brown designed Clandon's landscape park c1776-81. The house and garden are now owned by the National Trust but the park is privately owned. It is currently unsympathetically managed thus affecting the overall integrity of the design and the setting of the house. Discussions regarding a proposed business park development and a future landscape Conservation Management Plan, part funded by Natural England, are ongoing but successful resolution of these issues will hopefully reverse the current trajectory.

Contact: David Brock 01483 252044

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
 If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

MOLE VALLEY



SITE NAME: **Ruins of Betchworth Castle, Reigate Road, Betchworth**

Late C17 ruined house built on site of medieval castle. Consolidation required. Emergency works required urgently. Some areas are in danger of imminent collapse. Project development nearing completion and repairs should take place this year.

DESIGNATION: Listed Building Grade II, SM

CONDITION: Poor

OCCUPANCY: N/A

PRIORITY: B (B)

OWNER TYPE: Private

Contact: Richard Massey 01483 252046



SITE NAME: **Brockham Lime Works, Brockham**

The remains include an eastern battery of eight kilns and a western battery of two. The eastern battery, originally built in 1870, comprises four pairs of linked flare kilns. The northern two pairs were modified to the Brockham patent, as was the western battery, and comprises the type site for this type of kiln. Parts of the kilns are in a very poor condition but some repairs are planned this summer.

DESIGNATION: Listed Building Grade II, SM

CONDITION: Very bad

OCCUPANCY: N/A

PRIORITY: B (B)

OWNER TYPE: Trust

Contact: Richard Massey 01483 252046

SITE NAME: **Lime kilns at Betchworth Quarry, Betchworth**

DESIGNATION: Scheduled Monument (No. 1021346)

CONDITION: Generally unsatisfactory with major localised problems

PRINCIPAL VULNERABILITY: Deterioration – in need of management

TREND: Declining

OWNER TYPE: Private

CONTACT: Richard Massey 01483 252046

SITE NAME: **Betchworth Castle, Brockham**

DESIGNATION: Scheduled Monument (No. 1017996)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Collapse

TREND: Declining

OWNER TYPE: Local Authority

CONTACT: Richard Massey 01483 252046

SITE NAME: **Anstiebury Camp: a large multivallate hillfort south east of Crockers Farm, Capel**

DESIGNATION: Scheduled Monument (No. 1007891)

CONDITION: Generally unsatisfactory with major localised problems

PRINCIPAL VULNERABILITY: Scrub / tree growth

TREND: Declining

OWNER TYPE: Private

CONTACT: Richard Massey 01483 252046

SITE NAME: **Bell barrow in Deerleap Wood, Wotton**

DESIGNATION: Scheduled Monument (No. 1007878)

CONDITION: Generally unsatisfactory with major localised problems

PRINCIPAL VULNERABILITY: Scrub / tree growth

TREND: Declining

OWNER TYPE: Private

CONTACT: Richard Massey 01483 252046



SITE NAME: **Ashtead Park, Ashtead**

Begun as a C17 park, Ashtead was developed during the C18 and C19 by successive owners. Although the estate was sold as 51 lots in the 1920s, the historic landscape is largely in two ownerships. The main house and surrounds are a school which is preparing a new master plan that, it is hoped, will be informed by an almost complete landscape Conservation Management Plan. The northern park is managed as public open space by Surrey Wildlife Trust who are willing to acknowledge the site's history in management decisions.

DESIGNATION: Registered Park and Garden Grade II, also part in CA, 19 LBs, 1 SM

CONDITION: Extensive significant problems

VULNERABILITY: High

TREND: Improving

OWNER TYPE: Mixed, multiple owners

Contact: David Brock 01483 252044

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

REIGATE AND BANSTEAD



SITE NAME: **Alderstead (Merstham) Fort, Shepherd's Hill, Reigate**

C19 mobilisation centre, one of 13 constructed on the North Downs for the defence of London. The scheduling comprises the infantry fort and detached tool store. Tree growth and poor drainage are causing problems and the fort has no current use.

DESIGNATION: Scheduled Monument

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNER TYPE: Private

Contact: Richard Massey 01483 252046

RUNNYMEDE

SITE NAME:

Bronze Age settlement, west of Runnymede Bridge, Runnymede

DESIGNATION: Scheduled Monument (No. 1003807)

CONDITION: Generally satisfactory but with significant localised problems

PRINCIPAL VULNERABILITY: Scrub / tree growth

TREND: Declining

OWNER TYPE: Government or Agency

CONTACT: Richard Massey 01483 252046



SITE NAME: **Woburn Farm, Addlestone**

An Arcadian landscaped 'ferme ornée' designed by Philip Southcote from 1734-5, it was highly influential in the history of garden design but rather ephemeral in nature. The site is now in divided public and private ownership, including a school with intrusive sports facilities, some private residences and an area owned by the local planning authority but leased for various inappropriate uses. A member of the Surrey garden history trust is assessing and recording the survival of historic features on site.

DESIGNATION: Registered Park and Garden Grade II, also 5 LBs

CONDITION: Extensive significant problems

VULNERABILITY: Medium

TREND: Declining

OWNER TYPE: Mixed, multiple owners

Contact: David Brock 01483 252044

SPELTHORNE



SITE NAME: **Church of St Mary the Virgin, Church Street, Sunbury**

The domed tower and cupola of St Mary's forms a prominent local landmark, surrounded by trees, standing alongside the River Thames. The tower and Nave date to 1752, with the chancel and restoration works carried out in 1856 by Teulon. Sgraffito decoration was added in 1892. The tower was repaired with grant aid offered in 2002 but a defective aluminium roof to the nave continues to cause substantial problems. A Repair Grant for Places of Worship has been offered to support repair work.

DESIGNATION: Listed Place of Worship Grade II*, CA

CONDITION: Poor

PRIORITY: D (New entry)

OWNER TYPE: Religious organisation

Contact: Andy White 01483 252047

TANDRIDGE



SITE NAME: **Bletchingly Castle, Bletchingly**

Norman ringwork and bailey. Some trees are growing too close to the fragile masonry which is in need of consolidation. Owners have previously had plans for development approved. A Conservation Management Plan has also been approved and work now needs to start.

DESIGNATION: Scheduled Monument

CONDITION: Very bad

OCCUPANCY: N/A

PRIORITY: D (D)

OWNER TYPE: Private

Contact: Richard Massey 01483 252046

WAVERLEY

SITE NAME:

Four bowl barrows 30m south east of Tilford Barrows: part of The Barrows round barrow cemetery, Tilford

DESIGNATION: Scheduled Monument (No. 1007883)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Scrub / tree growth

TREND: Declining

OWNER TYPE: Private

CONTACT: Richard Massey 01483 252046

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

WOKING



SITE NAME:	Brookwood Cemetery, Brookwood
DESIGNATION:	Registered Park and Garden Grade I, also CA, 18 LBs
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Declining
OWNER TYPE:	Mixed, multiple owners

The largest cemetery in England, founded in 1852 to house London's dead. Part remains a working cemetery and is owned by a limited company. The scale of maintenance and restoration work required is immense. With the help of Woking Borough Council, the company is about to commission a landscape Conservation Management Plan, partly funded by English Heritage. This will help the company to prioritise work, engage with other owners, and fulfil their ambitions to restore this historic site.

Contact: David Brock 01483 252044

WEST BERKSHIRE (UA)



SITE NAME:	Chapel of St Leonard, east of Manor Farmhouse, Brimpton Road, Brimpton
DESIGNATION:	Listed Building Grade II*, SM
CONDITION:	Good
OCCUPANCY:	Vacant
PRIORITY:	E (E)
OWNER TYPE:	Private

Redundant chapel. C12 and later. Structure is generally sound, with repair programme completed. Planning permission and scheduled monument consent granted for sympathetic conversion to office use.

Contact: Chris Welch 01483 252027



SITE NAME:	Pair of gate piers 103 metres south of east end of church, Park Lane, Hamstead Marshall
DESIGNATION:	Listed Building Grade I, RPG II
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY:	A (A)
OWNER TYPE:	Private

Gate piers (built before 1718) to C17 house, burnt down in 1718. The gate piers remain in the north west corner of the park. Stone cornice eroded in places with open joints and weed growth. The landscape is generally in good condition, but other pairs of gate piers and C17 walled gardens are also at risk.

Contact: Richard Peats 01483 252026



SITE NAME:	Pair of gate piers 204 metres east of entrance to Home Farm, Park Lane, Hamstead Marshall
DESIGNATION:	Listed Building Grade I, RPG II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY:	C (C)
OWNER TYPE:	Private

Gate piers (built before 1718) to C17 house, burnt down in 1718. The gate piers remain in the north west corner of the park. Some of the bricks have eroded. The landscape is generally in good condition, but other pairs of gate piers and the C17 walled garden are also at risk.

Contact: Richard Peats 01483 252026



SITE NAME:	Pair of gate piers 210 metres south of church tower, Park Lane, Hamstead Marshall
DESIGNATION:	Listed Building Grade I, RPG II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY:	C (C)
OWNER TYPE:	Private

Gate piers (built before 1718) to C17 house, burnt down in 1718. The gate piers remain in the north west corner of the park. The landscape is generally in good condition, but other pairs of gate piers and the C17 walled gardens are also at risk. The stonework is in poor condition and a section of cornice has fallen away.

Contact: Richard Peats 01483 252026



SITE NAME:	Pair of gate piers 30 metres south of east end of church, Park Lane, Hamstead Marshall
DESIGNATION:	Listed Building Grade I, RPG II
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY:	A (A)
OWNER TYPE:	Private

Gate piers (built before 1718) to C17 house, burnt down in 1718. The gate piers remain in the north west corner of the park. Bricks and pointing have eroded and the stone cornices are damaged. Shrubs are growing from the joints. A section of the base and the pier corner has fallen away. The landscape is generally in good condition, but other pairs of gate piers and the C17 walled gardens are also at risk.

Contact: Richard Peats 01483 252026

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	Three pairs of gate piers and walls around gardens and terrace at Home Farm, Park Lane, Hamstead Marshall
DESIGNATION:	Listed Building Grade I, RPG II
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY:	C (C)
OWNER TYPE:	Private

Two late C17 walled gardens (one with raised terrace) and three pairs of gate piers located in the north west corner of the park. Formerly the gardens to the C17 house, burnt down in 1718. Used by the C19 as kitchen gardens for Hamstead Lodge. The walls are in joint ownership. Some sections have open joints. One of the gate piers has weed growth to the cornice. Parts are being repaired.

Contact: Richard Peats 01483 252026



SITE NAME:	Church of St Mary, Church Street, Hampstead Norreys
DESIGNATION:	Listed Place of Worship Grade I, CA
CONDITION:	Poor
PRIORITY:	D (New entry)
OWNER TYPE:	Religious organisation

Spacious medieval village church, set back from the main street in a large churchyard. At risk due to structural cracking to tower, decaying render and stonework including to north porch and poor rainwater disposal system. A Repair Grant for Places of Worship has been offered to support the repair work required.

Contact: Andy White 01483 252047



SITE NAME:	Church of St Peter and St Paul, Yattendon Lane, Yattendon
DESIGNATION:	Listed Place of Worship Grade I, CA
CONDITION:	Poor
PRIORITY:	B (New entry)
OWNER TYPE:	Religious organisation

Medieval village church with impressive nave roof. The roof tiling to nave and chancel are deteriorating, rainwater disposal system not operating efficiently – underground drainage system to north is blocked. Plaster has fallen internally beneath a defective brick gutter to boiler room. A Repair Grant for Places of Worship has been offered to support the costs of repair work.

Contact: Andy White 01483 252047

SITE NAME: **Round barrow cemetery at Brimpton Common, Brimpton**

DESIGNATION:	Scheduled Monument (No. 1012808)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate visitor erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME: **Long barrow at Combe Gibbet, Gallows Down, Combe**

DESIGNATION:	Scheduled Monument (No. 1013198)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME: **East Ilsley Down round barrows, East Ilsley**

DESIGNATION:	Scheduled Monument (No. 1006986)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME: **Long barrow on Sheep Down, 1km north of East Ilsley, East Ilsley**

DESIGNATION:	Scheduled Monument (No. 1013056)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME: **Bowl barrow 30m north of Bitham Lane, Inkpen**

DESIGNATION:	Scheduled Monument (No. 1009455)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Membury Camp (part in Wiltshire), Lambourn		
DESIGNATION:	Scheduled Monument (No. 1003818)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027

SITE NAME:	Two bowl barrows 500m north east of Stancombe Farm, Lambourn		
DESIGNATION:	Scheduled Monument (No. 1012349)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Chris Welch 01483 252027



SITE NAME:	Aldermaston Court, Aldermaston
DESIGNATION:	Registered Park and Garden Grade II, also part in CA, 11 LBs
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	Medium
TREND:	Declining
OWNER TYPE:	Corporate, single owner

An important mid-late C19 landscape with remains of C17 / C18 pleasure grounds relating to an earlier manor house. Following WWII, the Victorian mansion house was sold for corporate use then converted into a hotel and conference centre. The registered area is a fragment of an extensive park. It is owned by one owner but leased to two tenants. A perceived lack of beneficial use and resources threaten this landscape. A conservation led approach to management is required.

Contact: Kathryn Davies 01483 252028



SITE NAME:	Sandleford Priory, Greenham
DESIGNATION:	Registered Park and Garden Grade II, also 2 LBs
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Declining
OWNER TYPE:	Mixed, multiple owners

A mid/late C18 landscape laid out to designs by Lancelot Brown, surrounding a Gothick house remodelled by James Wyatt. In 1947 the estate was sold into divided ownership, the house, gardens and core of the park being used as a school. Other ownerships have fallen prey to development (housing, waste disposal) leaving the core compromised as a design fragment which in turn is under-resourced in its management. The setting of the house and park and garden is extremely vulnerable to development.

Contact: Kathryn Davies 01483 252028



SITE NAME:	Shaw House, Shaw cum Donnington
DESIGNATION:	Registered Park and Garden Grade II, also CA, 6 LBs
CONDITION:	Extensive significant problems
VULNERABILITY:	Medium
TREND:	Declining
OWNER TYPE:	Local Authority, single owner

This site consists of rare earthworks of a late C16 or early C17 garden laid out by the Dolman family and a complex of early C18 water gardens by the Duke of Chandos. Shaw House is now restored, with Heritage Lottery Fund and English Heritage grant aid, as a conference centre and heritage attraction. The local authority need help and additional funding to restore all the garden areas and to integrate the proposed new facilities within them.

Contact: Kathryn Davies 01483 252028



SITE NAME:	First Battle of Newbury, Enborne / Newbury / Speen
DESIGNATION:	Registered Battlefield
CONDITION:	Generally satisfactory but with minor localised problems
VULNERABILITY:	High
TREND:	Stable
OWNER TYPE:	Private

Site of the 164 First Battle of Newbury (English Civil War) between Parliamentary and Royalist forces. This battle probably represented the best chance King Charles ever had of winning the Civil War. It marked the turning point of the whole war and is accordingly an important place in English history. Already some of the south eastern periphery of the battlefield is built over and the A34 Newbury bypass clips a corner of it. The battlefield is at risk from housing development around its fringes and until such time as the Core Strategy confirms a strategic housing location elsewhere at Newbury.

Contact: Simon Goodhugh 01483 252037

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

WEST SUSSEX

ADUR



SITE NAME: **Shoreham Old Fort,
Old Fort Road,
Shoreham by Sea**

C19 fort, with later coastguards' observation post. Fort is vulnerable to vandalism and the elements. Parts are beginning to deteriorate badly. Proposals for repair agreed and works underway.

DESIGNATION: Scheduled Monument

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: D (D)

OWNER TYPE: Company

Contact: Richard Massey 01483 252046

SITE NAME:

Southlands

DESIGNATION: Conservation Area

CONDITION: Very bad

VULNERABILITY: Medium

TREND: Improving significantly

CONTACT: Colette Blackett (LPA) 01273 263242

NEW ENTRY: Yes

ARUN



SITE NAME: **Maison Dieu,
Mill Road,
Arundel**

C14 remains of the former hospital of the Holy Trinity. The monument is in two distinct parts, with different owners, divided by a road. One part is in a fair condition and not deemed to be at risk, whilst the other is in very bad condition but grant has been offered to investigate what repairs are needed.

DESIGNATION: Listed Building Grade II, SM, CA

CONDITION: Very bad

OCCUPANCY: N/A

PRIORITY: B (B)

OWNER TYPE: Private

Contact: Richard Massey 01483 252046



SITE NAME: **Littlehampton Fort,
Littlehampton**

Fort C19. The fort is partly covered in ivy which poses the main threat to the building. Part of the fort is engulfed by sand dunes which have Site of Special Scientific Interest status.

DESIGNATION: Scheduled Monument

CONDITION: Poor

OCCUPANCY: N/A

PRIORITY: C (C)

OWNER TYPE: Private

Contact: Richard Massey 01483 252046

CHICHESTER



SITE NAME: **Former Church of the Assumption,
Church Farm Lane,
East Wittering**

Medieval church, restored 1875-6. Redundant for some years. Repairs have now been made but future use is not yet agreed.

DESIGNATION: Listed Building Grade II*

CONDITION: Fair

OCCUPANCY: Vacant

PRIORITY: E (E)

OWNER TYPE: Private

Contact: David Brock 01483 252044

SITE NAME:

Graylingwell, Chichester

DESIGNATION: Conservation Area

CONDITION: Very bad

VULNERABILITY: High

TREND: Improving significantly

CONTACT: Lone Le Vay (LPA) 01243 534688

NEW ENTRY: No

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

- CA** Conservation Area
- LB/LBs** Listed Building/s
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM/SMs** Scheduled Monument/s
- UA** Unitary Authority
- WHS** World Heritage Site

HORSHAM



SITE NAME: **St Marys House,
The Street,
Bramber**

Built in the C15 as a home for the Wardens of the Bridge, who were the monks of Sele Priory at Upper Beeding. Repairs are necessary in the medium term but funding from either private or public sources remains uncertain.

DESIGNATION: Listed Building Grade I, CA

CONDITION: Fair

OCCUPANCY: Occupied

PRIORITY: C (C)

OWNER TYPE: Private

Contact: David Brock 01483 252044



SITE NAME: **Sedgwick Castle,
Moated site,
Nuthurst**

Moated medieval castle. Ruinous. The exposed parts of this structure are in a very poor state of repair. Discussions needed with new owners. A conservation strategy has previously been prepared but will need to be updated.

DESIGNATION: Scheduled Monument, RPG II

CONDITION: Poor

OCCUPANCY: N/A

PRIORITY: A (A)

OWNER TYPE: Private

Contact: Richard Massey 01483 252046



SITE NAME: **Parish Church of the Holy Trinity,
Church Street,
Rudgwick**

Large medieval church mostly dating from the C14 with later restoration. There is moss and vegetation growth throughout the exterior, including growth in gutters, at the base of the walls and on the roofs. There are also patches of weathered stonework, and a leaking gutter and downpipe on the north elevation of the nave has resulted in saturation of stonework and the cracking of a brick flue.

DESIGNATION: Listed Place of Worship Grade I, CA

CONDITION: Poor

PRIORITY: C (New entry)

OWNER TYPE: Religious organisation

Contact: David Brock 01483 252044

SITE NAME:

Bowl barrow on Black Hill, Colgate

DESIGNATION:

Scheduled Monument (No. 1011596)

CONDITION:

Generally unsatisfactory
with major localised problems

PRINCIPAL VULNERABILITY:

Other

TREND:

Declining

OWNER TYPE:

Private

CONTACT:

Richard Massey 01483 252046

SITE NAME:

Alfoldean Roman site, Slinfold

DESIGNATION:

Scheduled Monument (No. 1005838)

CONDITION:

Extensive significant problems

PRINCIPAL VULNERABILITY:

Arable ploughing

TREND:

Declining

OWNER TYPE:

Private

CONTACT:

Richard Massey 01483 252046

SITE NAME:

Greatham

DESIGNATION:

Conservation Area

CONDITION:

Very bad

VULNERABILITY:

Medium

TREND:

Deteriorating

CONTACT:

Catherine Jeater (LPA) 01403 215528

NEW ENTRY:

No

MID SUSSEX

SITE NAME:

Motte and bailey castle 240m east of Dean's Mill, Lindfield Rural

DESIGNATION:

Scheduled Monument (No. 1011776)

CONDITION:

Generally unsatisfactory
with major localised problems

PRINCIPAL VULNERABILITY:

Scrub / tree growth

TREND:

Declining

OWNER TYPE:

Private

CONTACT:

Richard Massey 01483 252046

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SOUTH DOWNS (NP)



SITE NAME:	The chapel at the former King Edward VII Hospital, Easebourne, Chichester
DESIGNATION:	Listed Building Grade II*, RPG II
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	B (B)
OWNER TYPE:	Company

Remarkable L-shaped redundant chapel for tuberculosis patients by Charles Holden, 1903-6. In need of roof repairs as part of scheme to convert the hospital.

Contact: David Brock 01483 252044



SITE NAME:	North Park Furnace, Linchmere, Chichester
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	C (D)
OWNER TYPE:	Trust

The furnace is one of the most complete charcoal fired blast furnaces surviving from the Wealden iron industry but is in need of urgent repairs. Heritage Lottery Fund grant application to be made to fund repairs.

Contact: Richard Massey 01483 252046



SITE NAME:	Amberley Limeworks, Houghton Bridge, Amberley, Horsham
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY:	D (D)
OWNER TYPE:	Trust

C19 Limeworks including kilns and associated buildings. The ingress of rain and inadequate maintenance in the past have led to structural weaknesses to two buildings. Site owned by West Sussex County Council but leased to Amberley Museum Trust.


Contact: Richard Massey 01483 252046



SITE NAME:	Chapter house and remains of kitchen, Hardham Priory, Coldwaltham, Horsham
DESIGNATION:	Listed Building Grade I, SM
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	D (D)
OWNER TYPE:	Private

Remains of an Augustinian monastery founded during mid C13 by Sir William Dawtry. The Chapter House is in need of urgent repair. The upstanding remains of the kitchen have been supported to prevent collapse. First stage of repair project completed. Repairs should take place this year.

Contact: Richard Massey 01483 252046



SITE NAME:	Castle Goring, Arundel Road, Worthing
DESIGNATION:	Listed Building Grade I
CONDITION:	Very bad
OCCUPANCY:	Part occupied
PRIORITY:	A (A)
OWNER TYPE:	Private

Large house. Built by Shelley's grandfather, Sir Bysshe Shelley, about 1797-8. Currently let to a language school. The condition is very grave, and enforcement action for repairs must now be considered.

Contact: David Brock 01483 252044



SITE NAME:	Church of St Nicholas, London Road, Arundel, Arun
DESIGNATION:	Listed Place of Worship Grade I, CA
CONDITION:	Very bad
PRIORITY:	A (New entry)
OWNER TYPE:	Religious organisation

Well proportioned town church, re-built in 1380. Unusually the adjacent Fitzalan Chapel and Lady Chapel to the east are in Roman Catholic use. At risk due to blocked and leaking gutters and downpipes leading to damp penetration internally, spalling stonework to tower, rotting timber framing and defective tiling to north porch.

Contact: Andy White 01483 252047

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Romano-British villa and traces of Iron Age occupation 500m WSW of New Barn, Angmering, Arun		
DESIGNATION:	Scheduled Monument (No. 1015886)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Duncton Common round barrow cemetery, Duncton, Chichester		
DESIGNATION:	Scheduled Monument (No. 1009329)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Field system in Lamb Lea, East Dean, Chichester		
DESIGNATION:	Scheduled Monument (No. 1005820)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Harting Beacon: a hilltop enclosure, Anglo-Saxon burial mound and telegraph station on Beacon and Pen Hills, Elsted and Treyford, Chichester		
DESIGNATION:	Scheduled Monument (No. 1015915)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Flint mine and a bowl barrow on Church Hill, 400m south west of Findon Place, Findon, Arun		
DESIGNATION:	Scheduled Monument (No. 1015238)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	A Romano-Celtic temple, Iron Age shrine and associated remains 250m north west of Ratham Mill, Funtington, Chichester		
DESIGNATION:	Scheduled Monument (No. 1018354)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Devil's Ditch, section extending 200yds (180m) east from Chapel Lane, Funtington, Chichester		
DESIGNATION:	Scheduled Monument (No. 1005880)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Devil's Ditch, section extending 400yds (370m) west from Chapel Lane, Funtington, Chichester		
DESIGNATION:	Scheduled Monument (No. 1005881)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Devil's Ditch, section extending 900yds (820m), Lye Wood, West Stoke, Funtington, Chichester		
DESIGNATION:	Scheduled Monument (No. 1005882)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Flint mine on Stoke Down, immediately north of Stoke Clump, Funtington, Chichester		
DESIGNATION:	Scheduled Monument (No. 1018563)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Linear boundary on Stoke Down, 800m north of West Stoke House, Funtington, Chichester		
DESIGNATION:	Scheduled Monument (No. 1018564)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Bowl barrow 350m WNW of Barnett's Bridge, Graffham, Chichester		
DESIGNATION:	Scheduled Monument (No. 1009916)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Bowl barrow 500m WNW of Barnett's Bridge, Graffham, Chichester		
DESIGNATION:	Scheduled Monument (No. 1009910)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Bowl barrow on Gallows Hill, 150m east of Millborough House, Graffham, Chichester		
DESIGNATION:	Scheduled Monument (No. 1009905)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Two bowl barrows on Gallows Hill, 200m east of Millborough House, Graffham, Chichester		
DESIGNATION:	Scheduled Monument (No. 1009906)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Bexley Bushes earthworks, Lavant, Chichester		
DESIGNATION:	Scheduled Monument (No. 1005892)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Devil's Ditch, section 230yds (210m) long from Chichester main road to Pook Lane, Lavant, Chichester		
DESIGNATION:	Scheduled Monument (No. 1005877)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Richard Massey 01483 252046

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Devil's Ditch, section extending 530yds (480m) west from Lavant Lodge, Lavant, Chichester		
DESIGNATION:	Scheduled Monument (No. 1005878)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Devil's Ditch, section extending 960yds (870m) south of Lavant House, Lavant, Chichester		
DESIGNATION:	Scheduled Monument (No. 1005876)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Bowl barrow on Gallows Hill, 300m east of Millborough House, Lodsworth, Chichester		
DESIGNATION:	Scheduled Monument (No. 1009908)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Itford Hill style settlement on Cock Hill, Patching, Arun		
DESIGNATION:	Scheduled Monument (No. 1015881)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Motte and bailey castle in Pulborough Park, Pulborough, Horsham		
DESIGNATION:	Scheduled Monument (No. 1017547)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Bowl barrow on Fitzhall Rough, 330m ENE of Fitzhall: part of Fitzhall Rough round barrow cemetery, Stedham with Iping, Chichester		
DESIGNATION:	Scheduled Monument (No. 1008503)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046

SITE NAME:	Bowl barrow 950m south west of Grey Friars Farm: part of a dispersed round barrow cemetery on Kithurst Hill, Storrington and Sullington, Horsham		
DESIGNATION:	Scheduled Monument (No. 1015711)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Richard Massey 01483 252046



SITE NAME:	Lavington Park, East Lavington / Duncton, Chichester
DESIGNATION:	Registered Park and Garden Grade II, also 7 LBs
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Stable
OWNER TYPE:	Corporate, single owner

Late C18 and C19 garden, laid out on the site of a former late C16 house and garden and further altered in the C20, set within a park largely planted in the C19 but of C18 origin. The property is now a school. Two relatively substantial developments were granted planning permission earlier this year. The opportunity to rationalise development within the park was considered to outweigh the negative impacts. There is now a conservation plan for the landscape, but no management commitment for areas unaffected by development.

Contact: David Brock 01483 252044

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

WORTHING



SITE NAME:	The Dome Cinema, Marine Parade, Worthing
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Good
OCCUPANCY:	Occupied
PRIORITY:	F (F)
OWNER TYPE:	Trust

Early example of leisure complex, built 1911 as a roller skating rink and developed as a cinema in 1923. The Worthing Dome and Regeneration Trust has secured Heritage Lottery Fund and English Heritage funding for repair and enhancement as a cinema, which is now nearly complete.

Contact: David Brock 01483 252044



SITE NAME:	Holy Trinity Church, Shelley Road
DESIGNATION:	Listed Place of Worship Grade II, CA
CONDITION:	Poor
PRIORITY:	C (New entry)
OWNER TYPE:	Religious organisation

Large town church built with stone dressings. Designed by Henry Coe and Stephen Robinson and built 1882-88. At risk due to decayed high level brick and stonework, especially to tower. Roof and lightning conductor repairs and upgrading are also required.

Contact: Andy White 01483 252047

OFF WEST SUSSEX



SITE NAME:	Submarine HMS/m A1, Eastern Solent
DESIGNATION:	Protected Wreck Site
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Declining
OWNER TYPE:	Private
PHOTO:	© Private

Built by Vickers in 1903, the A1 is the first British designed and built submarine used by the Royal Navy. She sank for the second time in 1911 while operating under automatic pilot as a submerged target. The site has been subject to unauthorised access and a chain of shellfish pots was fixed by an unknown diver to the vessel's pressure hull causing abrasive damage.

Contact: Simon Goodhugh 01483 252037

WINDSOR AND MAIDENHEAD (UA)



SITE NAME:	Noahs Boathouse, Stonehouse Lane (Off), Cookham
DESIGNATION:	Listed Building Grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY:	A (A)
OWNER TYPE:	Private

1930, by Colin Lucas for his father, constructed of monolithic reinforced concrete with a flat roof. An early and pioneering example of Modern Movement architecture by one of the major figures in the movement. The building floods regularly and is derelict. The roof is leaking and the concrete is spalling.

Contact: Richard Peats 01483 252026

SITE NAME:	Royal Mausoleum, The Home Park, Windsor
DESIGNATION:	Listed Building Grade I, RPG I
CONDITION:	Fair
OCCUPANCY:	N/A
PRIORITY:	C (C)
OWNER TYPE:	Crown

Mausoleum of Queen Victoria and Prince Albert, 1862-71. Damp problems are placing external and internal historic fabric at risk, including the internal frescoes. The original rainwater drainage is inadequate and poorly designed, running within the wall fabric, and is difficult to maintain. Environmental monitoring has been carried out, and temporary remedial works are proposed.

Contact: Elizabeth Moore 020 7973 3803

SITE NAME:	Beenham's Heath	CONDITION:	At risk
DESIGNATION:	Conservation Area	TREND:	Improving
VULNERABILITY:	Unknown	NEW ENTRY:	No
CONTACT:	Jane Wylie (LPA) 01628 685687		

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

- CA** Conservation Area
LB/LBs Listed Building/s
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM/SMs Scheduled Monument/s
UA Unitary Authority
WHS World Heritage Site

WOKINGHAM (UA)



SITE NAME: **Site of St Bartholomews Church, Arborfield, Arborfield and Newland**

Old parish church, now a roofless ruin. Originally C13 in flint and stone, with substantial probable C18 brick rebuilding. One wall partially standing, with fragments of later brick segments. Very overgrown. Risk of further collapse.

DESIGNATION: Listed Building Grade II, SM

CONDITION: Very bad

OCCUPANCY: N/A

PRIORITY: A (A)

OWNER TYPE: Religious organisation

Contact: Chris Welch 01483 252027



SITE NAME: **Infirmary Stables, Arborfield Garrison, Arborfield, Finchampstead**

A specialised 'horse hospital' built 1911-12. The building is redundant by virtue of changes in army practices (i.e. reduced cavalry activity).

DESIGNATION: Scheduled Monument

CONDITION: Very bad

OCCUPANCY: Vacant

PRIORITY: A (A)

OWNER TYPE: Government

Contact: Chris Welch 01483 252027

SITE NAME: **Cropmark complex south west of St Patrick's Avenue, Charvil**

DESIGNATION: Scheduled Monument (No. 1006964)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNER TYPE: Private

CONTACT: Chris Welch 01483 252027

SITE NAME: **Cropmark enclosure and pits north east of St Patrick's Avenue, Charvil**

DESIGNATION: Scheduled Monument (No. 1006966)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNER TYPE: Private

CONTACT: Chris Welch 01483 252027

SITE NAME: **Ring ditch cropmark east of St Patrick's Avenue, Charvil**

DESIGNATION: Scheduled Monument (No. 1006965)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNER TYPE: Private

CONTACT: Chris Welch 01483 252027

SITE NAME: **Cropmark site east of Broadmoor Lane, Sonning**

DESIGNATION: Scheduled Monument (No. 1006963)

CONDITION: Generally satisfactory but with significant localised problems

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNER TYPE: Private

CONTACT: Chris Welch 01483 252027



SITE NAME: **Bearwood College, Arborfield and Newland / Barkham**

This C19 landscape park and woodland surrounds a Victorian country house standing on formal terraces, with gardens by William Sawrey Gilpin and Pulham. The school which now occupies the house helped secure its future after WWI. The landscape park is now subdivided into two golf courses. Subsequent and current development and management of the gardens and woodland, plus a lack of specialist guidance and resources, challenge the integrity and survival of the historic landscape.

DESIGNATION: Registered Park and Garden Grade II*, also part in CA, 5 LBs

CONDITION: Generally unsatisfactory with major localised problems

VULNERABILITY: High

TREND: Declining

OWNER TYPE: Corporate, multiple owners

Contact: Kathryn Davies 01483 252028

PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA	Conservation Area
LB/LBs	Listed Building/s
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site



ENGLISH HERITAGE

This document is one in a series of publications produced as part of English Heritage's national Heritage at Risk programme. More information about Heritage at Risk and other titles in the series can be found at www.english-heritage.org.uk/risk

HERITAGE AT RISK

Published October 2011 by English Heritage
1 Waterhouse Square, 138-142 Holborn,
London EC1N 2ST

© Copyright English Heritage 2011