



ENGLISH HERITAGE

HERITAGE AT
RISK
REGISTER
2014

WEST MIDLANDS

Contents

Heritage at Risk	III	Wyre Forest	74
The Register	VII		
Content and criteria	VII		
Criteria for inclusion on the Register	VIII		
Reducing the risks	X		
Key statistics	XIII		
Publications and guidance	XIV		
Key to the entries	XVI		
Entries on the Register by local planning authority	XVIII		
Herefordshire, County of (UA)	I		
Shropshire (UA)	15		
<i>Staffordshire</i>	28		
Cannock Chase	28		
East Staffordshire	29		
Lichfield	30		
Newcastle-under-Lyme	31		
Peak District (NP)	32		
South Staffordshire	32		
Stafford	34		
Staffordshire Moorlands	35		
Tamworth	36		
Stoke-on-Trent, City of (UA)	37		
Telford and Wrekin (UA)	40		
<i>Warwickshire</i>	42		
North Warwickshire	42		
Nuneaton and Bedworth	44		
Rugby	45		
Stratford-on-Avon	47		
Warwick	50		
<i>West Midlands</i>	53		
Birmingham	53		
Coventry	57		
Dudley	59		
Sandwell	62		
Walsall	63		
Wolverhampton, City of	64		
<i>Worcestershire</i>	65		
Bromsgrove	65		
Malvern Hills	67		
Redditch	69		
Worcester	69		
Wychavon	70		



ENGLISH HERITAGE

HERITAGE AT RISK

2014

WEST MIDLANDS



HERITAGE AT RISK

Heritage at Risk is our campaign to save listed buildings and important historic sites, places and landmarks from neglect or decay. At its heart is the Heritage at Risk Register, an online database containing details of each site known to be at risk. It is analysed and updated annually and this leaflet summarises the results.

Over the past year we have focused much of our effort on assessing listed Places of Worship, and visiting those considered to be in poor or very bad condition as a result of local reports. We now know that of the 14,775 listed places of worship in

England, 6% (887) are at risk and as such are included on this year's Register. These additions mean the overall number of sites on the Register has increased to 5,753. However, 575 sites have been removed from the 2013 Register, which includes one of our biggest achievements this year, Newman brothers Coffin Furniture Works, Birmingham.

Veryan Heal, Planning and Conservation Director, West Midlands

In 2013 there was an overall decrease in the number of scheduled monuments, listed buildings, registered parks and gardens and conservation areas on the Heritage at Risk Register in the West Midlands. The increase in the number of listed places of worship on the 2014 Register reflects our focus on assessments for this type of listed building. The good news is that in the West Midlands the percentage at risk (5.2%) is lower than the national average. We attach priority to the challenge this presents for congregations and continue to fund Support Officers in the Dioceses of Hereford, Worcester and Lichfield and with their help, find solutions for places of worship at risk. Last year 16 were removed from the Register. The progress made at St Mary, Jackfield is testament to the great efforts being made by congregations to tackle the condition of their buildings.

Many of the archaeological sites, buildings and structures on the Register are not capable of economic use and some have been at risk for many years. Inspirational owners and imaginative solutions are needed for these sites which also tend to be heavily reliant on grant aid. We provided £1.4m in grants to 20 sites in 2013. We are currently working hard with Natural England to ensure that funding for the historic environment remains on the agenda for agri-environment schemes. In 2013 these were instrumental in delivering funding and solutions for many sites including Kilpeck Castle, Herefordshire; Creswell Chapel, Staffordshire and the Romano-British settlement remains near Evesham.

Partnerships continue to be central to our strategy for tackling heritage at risk in 2014. Their efficacy is shown by major achievements in the last year which include the repair and re-use of one of our top ten priority sites, Middleport Pottery, Stoke on Trent. Here, in addition to providing funding, we helped put together a team including the City of Stoke on Trent, The Prince's Regeneration Trust and Burleigh. The team won a substantial grant from the Heritage Lottery Fund which has saved the site and helped regenerate the locality. Helping broker such deals was also instrumental in the rescue of the Coffin Works in Birmingham and the Service Wing at Croome Court, Worcestershire.

The enthusiasm and commitment of owners is, of course, essential for a cared-for historic environment. Last year, almost half the sites removed from the Register were saved by owners, from the Old Foundry, Stourbridge rescued by a medical practice to Lilleshall park and garden and a moated site at Tardebigge in Worcestershire. Tapping into this will continue to be a core priority for our Heritage at Risk Team in 2014.



Sarah Lewis,
Principal Adviser, Heritage at Risk

CHURCH OF ST MARY THE VIRGIN, JACKFIELD, TELFORD AND WREKIN

The first phase of repairs to the spire and roof at St Mary Jackfield are the result of the dedication, tenacity and fund-raising efforts of a small group at the church working with the Building Support and Community Partnership Officers at Hereford Diocese. Without their efforts this church might well have been abandoned. Instead, the need to raise funds has encouraged the parish to look beyond itself for help with the result that the church building is now more valued and supported by the community as a whole.

2014 WEST MIDLANDS REGISTER: WEST MIDLANDS

55 SITES REMOVED FROM THE **2013** REGISTER

£1.4m
20 SITES



WHAT'S ON THE HERITAGE AT RISK REGISTER?

51
CONSERVATION
AREAS (7.3%)



NATIONAL AVERAGE WEST MIDLANDS

IN THE WEST MIDLANDS THERE ARE...



4%



5%

97
BUILDINGS & STRUCTURES



6%



5.2%

76
PLACES OF WORSHIP



15.2%

14.8%

210
SCHEDULED MONUMENTS



5.7%



4.6%

7
PARKS & GARDENS

...ON THE REGISTER



SNODHILL CASTLE, SNODHILL, HEREFORDSHIRE

BACKGROUND AND HISTORY:

The Marches are defined by the remains of castles erected by the Normans as they sought to control and subdue this turbulent area following the Conquest. Snodhill Castle however, stands out as a rare survival of a shell keep with gatehouse and high status accommodation occupied from the 12th to the 16th century. The scheduled monument includes the motte, keep, bailey, remains of bailey walls and towers, defensive earthworks and remnants of fishponds.

The elevated position of the castle affords fantastic views out over the Herefordshire countryside and into Wales. In modern times this romantic ruin became a favourite with local residents for picnics and walks. However, over the last 15 years it has become increasingly overgrown. The owners neglected the monument, preventing

grazing which in the past had kept the vegetation in check. Access is now difficult. The views have been obscured by trees and sections of the old castle walls have collapsed. Local residents have not forgotten Snodhill, however, as they recall what an asset it was and could be again.

IS IT AT RISK?

Snodhill Castle has been at risk since 1998; it is one of our top ten priorities in the West Midlands. The prime concerns are the unstable condition of some sections of the walls to the bailey and the keep. The motte is also home to badgers whose sets have undermined the walls. Unmanaged trees have collapsed, crushing areas of wall beneath them to the point where the remains of the keep and great hall are under threat. Ivy infests the remains of the bailey towers.

WHAT'S THE CURRENT SITUATION?

In 2013 English Heritage helped to negotiate a long lease of the castle to the locally based Vivat Trust. Vivat organised volunteers to carry out vegetation clearance and English Heritage had the monument fully surveyed. Our engineers and architects have inspected the upstanding remains and identified priorities for urgent stabilisation works. We will be working with the Trust over the next year to undertake a more detailed condition survey, design a programme of urgent repairs and source funding. At the same time, we hope to explore the scope for a community based Heritage Lottery Fund project. This would deliver longer term conservation and management of the site with improved access, interpretation and community involvement.

HELP HISTORIC BUILDINGS

Historic buildings are irreplaceable; they give us our sense of place and contribute to our quality of life. These precious buildings need to be looked after for future generations, but how do we know what needs our help the most? English Heritage is encouraging community groups, volunteers, building owners and local authorities, across the country to come together to record the condition of grade II listed buildings in their area. Volunteers will visit a selection of grade II buildings local to them and answer questions, in the form of a survey, about the condition of the building. This information will be collected together and shared with local planning authorities to help identify those grade II buildings most at risk. Visit www.english-heritage.org.uk/help/historicbuildings to find out more.

FOR MORE INFORMATION CONTACT:

Sarah Lewis
English Heritage
West Midlands
The Axis
10 Holiday Street
Birmingham
BI 1TG

Telephone: 0121 625 6820

Email: west.midlands@english-heritage.org.uk



LILLESBALL HALL, NEAR NEWPORT, SHROPSHIRE

BACKGROUND AND HISTORY:

A grade II registered park and garden, Lilleshall was originally a private country estate with a mansion and grounds that appear to have been by a partnership between Sir John Wyattville and the 2nd Duke of Sutherland's wife. After a period as one of the earliest country house visitor attractions in England, Lilleshall was developed as a National Sports Centre, offering a range of facilities to help athletes develop sporting excellence. A separate part of the historic estate is laid out as a golf course.

IS IT AT RISK?

Lilleshall was included in the first group of registered parks and gardens to be added to the Heritage at Risk Register in 2009. The intrusiveness and insensitive location of some post-war development and the lack of an overall plan (informed by the historic significance of the site) were the principal reasons why the site was added to the Heritage at Risk Register.

Lilleshall was removed from the Heritage at Risk Register in 2014 thanks to the strategic work carried out by the National Sports centre in delivering a comprehensive conservation management plan

which has led to a better understanding of the heritage of the site as a whole.

WHAT'S THE CURRENT SITUATION?

Following contact by English Heritage, the National Sports Centre has funded a comprehensive conservation management plan which sets out parameters for future development, priorities for conservation of heritage assets on the site and a long-term management plan.

The National Sports Centre already recognised that the quality and attractiveness of the designed landscape created an environment conducive to the mental concentration sought by aspiring sportsmen and women. The conservation management plan has helped the Centre develop their understanding of the landscape and their enthusiasm for it has grown still further. The result is a tool that will deliver positive outcomes for both the Centre and the designed landscape.

Find out what's at risk by searching or downloading the online Heritage at Risk Register at www.english-heritage.org.uk/har

If you would like this document in a different format, please contact our customer services department on telephone: 0870 333 1181 fax: 01793 414926 textphone: 01793 414878 email: customers@english-heritage.org.uk

THE REGISTER

Content and criteria

DESIGNATION

Definition

All the historic environment matters but there are some elements which warrant extra protection through the planning system. These are included in the National Heritage List for England (NHLE), an online searchable database of designated assets (<http://list.english-heritage.org.uk>). Since 1882, when the first Act protecting ancient monuments and archaeological remains was passed, government has been developing the designation system. Listing, which is applied to buildings, emerged from the post-Blitz 1940s planning acts. There are now nearly 400,000 designated assets on the NHLE including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites.

English Heritage, as the government's expert adviser, is responsible for making recommendations – but it is still the Secretary of State at the Department for Culture Media and Sport who makes the decisions on whether an asset is designated. Understanding and appreciation develop constantly, which makes keeping the designation base up-to-date a never-ending challenge.

While responding to threat-driven cases, we increasingly seek to work strategically through the National Heritage Protection Plan. Recent developments have seen a greater striving for openness and transparency in the process of designating a site, and better communication of what makes something special.

Alongside the nationally designated assets found on the National Heritage List for England are locally designated assets. Best known are conservation areas, but local authorities can also create lists of locally valued assets. Most archaeological sites of significance are not scheduled, but rely on local identification and management for their protection.

LISTED BUILDINGS

Listing is by far the most commonly encountered type of designation. A listed building (or structure) is one that has been designated as being of special architectural or historic interest. The older and rarer a building is, the more likely it is to be listed. Buildings less than 30 years old are listed only if they are of outstanding quality and under threat.

Listed buildings are graded I, II* and II. Grade I buildings are of outstanding interest, and II* are particularly important buildings of more than special interest; together they amount to 8% of all listed buildings. The remaining 92% are of special interest and are listed grade II.

There are almost 376,000 listed entries on the statutory list of buildings of special architectural or historic interest. Entries on the statutory list sometimes group together a number of separate buildings: a terrace will be counted as one entry, rather than as separate units. Entries on this Register reflect how buildings are grouped and recorded on the statutory list.

Structures can occasionally be dual designated (both listed as buildings and scheduled as monuments). In such cases, scheduling controls take precedence.

SCHEDULED MONUMENTS

Scheduled monuments include single archaeological sites and complex archaeological landscapes. 19,833 examples have been designated because of their national importance. Scheduled monuments are not graded. They cover human activity from the prehistoric era, such as burial mounds, to 20th century military and industrial remains. For the millennia before written history, archaeology is the only testament to innumerable generations of people of whom there is no other record.

The later 20th century saw unprecedented changes to the landscape. As a result, types of historic site that once were commonplace began to become rare. Those that survive often represent just small islands of what once characterised broad sweeps of our towns and countryside. Although protected by law, scheduled monuments are still at risk from a wide range of processes and intense pressures outside of the planning system. These include damage from cultivation, forestry and – often most seriously of all – wholly natural processes such as scrub growth, animal burrowing and erosion.

REGISTERED PARKS AND GARDENS

There are 1,628 designed landscapes on the current English Heritage *Register of Historic Parks and Gardens of Special Historic Interest*. These registered landscapes are graded I, II* or II, and include private gardens, public parks and cemeteries, rural parkland and other green spaces. They are valued for their design and cultural importance, and are distinct from natural heritage designations.

Inclusion on the English Heritage *Register of Historic Parks and Gardens* brings no additional statutory controls,

but there is a clear presumption in favour of upholding their significance in government planning guidance. Local authorities are required to consult English Heritage on applications affecting sites registered as grade I or II* and the Garden History Society on sites of all grades. The setting of other designated heritage assets can also protect registered landscapes.

REGISTERED BATTLEFIELDS

English Heritage's *Register of Historic Battlefields* was set up in 1995, and is our youngest category of designation. Its aim is to protect and promote those sites where history was made through conflict. They range from the Battle of Maldon (991) to Sedgemoor (1685); almost half date from the period of the civil wars in the mid-17th century. These special places, where thousands were often killed, deserve our recognition and respect. Recently, additions have been made to the *Register of Historic Battlefields* for the first time since its creation. There are now 46 registered battlefields.

Protection is needed to prevent encroachment through inappropriate development, or insensitive (and damaging) metal detecting, which can permanently alter the archaeological record. As with registered parks and gardens, there is a clear presumption in favour of protecting registered battlefields in Government planning policy.

PROTECTED WRECK SITES

England's 49 protected wreck sites represent a tiny proportion of the 33,000 or so pre-1945 wrecks and recorded casualties that are known to lie in the territorial waters. Wreck sites can be of importance for different reasons: the distinctive design or construction of a ship, the story it can tell about its past, its association with notable people or events and its cargo. The Protection of Wrecks Act 1973 empowers the appropriate Secretary of State to designate a restricted area around a vessel to protect it or its contents from unauthorised interference, and English Heritage administers the attendant licensing scheme for divers seeking access.

CONSERVATION AREAS

Conservation areas are designated by local authorities and are areas of particular architectural or historic interest, the character or appearance of which it is desirable to preserve or enhance. For more than 40 years conservation areas have proved a highly effective mechanism for managing change on an area-wide basis. There are currently 9,848 conservation areas in England including town and city centres, suburbs, industrial areas, rural landscapes, cemeteries and residential areas. They form the historic backcloth to national and local life and are a crucial component of local identity and community cohesion.

Criteria for inclusion on the Register

RISK ASSESSMENTS

A risk assessment of a heritage asset is based on the nature of the site. Building or structure assessments, for instance, include listed buildings (but not listed places of worship) and structural scheduled monuments; archaeology assessments cover earthworks and buried archaeology.

BUILDINGS AND STRUCTURES

Buildings or structures (not in use as public places of worship) considered for inclusion on this Register must be listed grade I or II*, (or grade II in London) or be a structural scheduled monument with upstanding masonry remains. Buildings or structures are assessed for inclusion on the basis of condition and, where applicable, occupancy (or use) reflecting the fact that a building which is occupied is generally less vulnerable than one that is not.

Occupancy (or use) is noted as 'vacant', 'part occupied', 'occupied', 'not applicable', or occasionally, 'unknown'. Many structures fall into the 'not applicable' category as they can be ruins, walls, gates, headstones or boundary stones.

Condition is noted as 'very bad', 'poor', 'fair' or 'good'. The condition of buildings or structures on the Register typically ranges from very bad to poor, fair and (occasionally) good reflecting the fact that some buildings or structures capable of use are vulnerable to becoming at risk because they are empty, under-used or face redundancy without a new use to secure their future. Assessing vulnerability in the case of buildings in fair condition necessarily involves judgement and discretion. A few buildings on the Register are in good condition, having been repaired or mothballed, but a new use or owner is still to be secured.

Buildings or structures are removed from the Register when they are fully repaired/consolidated, and their future secured through either occupation and use, or through the adoption of appropriate management.

PLACES OF WORSHIP

Places of worship considered for inclusion on this Register must be listed grade I, II* or II and be used as a public place of worship at least six times a year.

Places of worship are assessed on the basis of condition only. If the place of worship is in very bad or poor condition it is added to the Register.

English Heritage has visited and assessed listed places of worship considered to be in poor or very bad condition according to local assessments. Those that are identified as at risk are included on the Register.

Once on the Register, places of worship can move through the condition categories (e.g. from very bad to poor, to fair, even good) as repairs are implemented and the condition improves, until they are fully repaired and can be removed from the Register.

ARCHAEOLOGY

Archaeology assessments cover earthworks and buried archaeology. The archaeological sites on this Register have been identified as being at risk because of their condition and vulnerability, the trend in their condition, and their likely future vulnerability. A site's condition is expressed in terms of the scale and severity of adverse effects on it, ranging from those with 'extensive significant problems' to others that have only 'minor localised problems'.

Archaeological entries are removed from the Register once sufficient progress has been made to address identified issues, demonstrating a significant reduction in the level of risk.

PARKS AND GARDENS

The assessment of parks and gardens starts with an appraisal of the condition and vulnerability of each registered landscape. Steps being taken by owners to address problems are also taken into consideration.

Parks and gardens assessed as being at risk are typically affected by development and neglect. They have frequently been altered by development or are faced with major change. The original function of these landscapes has often changed; and divided ownership often results in the loss of the cohesive conservation of the historic designs.

Park and garden entries are removed from the Register once plans are put in place to address issues and positive progress is being made.

BATTLEFIELDS

Battlefields deemed to be at risk of loss of historic significance are included on this Register.

The identified risks and threats come from development pressure - for example, because they lie on urban fringes or are subject to development pressures within the site; arable cultivation, and unregulated metal-detecting. One major impact or a combination of factors can be enough to raise the risk of a particular site.

Battlefields are removed from the Register when either actual damaging activities are reversed or managed, or threats recede due to effective management planning.

WRECK SITES

English Heritage has audited all designated wreck sites to identify those most at risk based on their current condition, vulnerability and the way they are being managed. Wrecks are vulnerable to both environmental and human impacts. Risks that contribute to inclusion on the Register range from unauthorised access to erosion and fishing damage.

The monitoring process ensures that the significance of the site is identified and maintained.

In spite of the inherent difficulties in caring for this type of site, careful management must be maintained.

Wrecks are removed from the Register once an appropriate management and monitoring regime is operational.

CONSERVATION AREAS

English Heritage has asked every local authority in England to complete (and update as appropriate) a survey of its conservation areas, highlighting current condition, threats and trends. Conservation areas that are deteriorating, or are in very bad or poor condition and are not expected to change significantly in the next three years, are defined as being at risk.

The methodology for assessing conservation areas at risk has been refined since the first survey in 2008/2009. The information collated provides a detailed assessment of each conservation area and an overall category for condition, vulnerability and trend is included for each conservation area on this Register. Conservation areas identified as at risk in 2009, but not reassessed since using the revised methodology, are included on the Register but with limited information.

Conservation areas are removed from the Register once plans have been put in place to address the issues that led to the conservation area being at risk, and once positive progress is being made.

Reducing the risks

English Heritage is working to secure a reduction in the number of heritage sites at risk as part of our contribution to the National Heritage Protection Plan (2011-2015). We have set ourselves a target to remove 25% of entries (1,137) published on the 2010 Register by 2015. Despite the challenge, given the number of entries on the Register and the different kinds of risk they face, excellent progress is being made.

The published Heritage at Risk National Strategy (www.english-heritage.org.uk/publications/eh-har-strategy-2011-15) sets out how this will be delivered through our dedicated Heritage at Risk teams in each local office. Key objectives of the strategy are to understand what factors lead to heritage sites becoming at risk, what most influences their removal from the Register, and to achieve this through partnership, stimulating economic regeneration and growth, and maximising the benefit of our expertise and resources.

Whilst each type of heritage asset and individual site will require its own approach and solution, there are some general approaches that are relevant to all 'at risk' assets. Resolving cases requires working in close partnership with owners, local planning authorities and a wide variety of other relevant organisations. The provision of clear advice and understanding are essential.

Maintenance and where appropriate, occupation are key to preventing heritage assets becoming at risk, whilst maintenance of those already at risk will prevent them from decaying further. Without maintenance, the cost of repair and consolidation escalates, the challenge for owners and occupiers increases, and the scope for affordable solutions declines.

English Heritage provides a wide range of published guidance on reducing the risks, including: new uses for heritage assets, finding partners and funding, and on enforcing urgent works and repairs, on our website: www.english-heritage.org.uk or the Historic Environment Local Management (HELM) website: www.helm.org.uk. Key publications and guidance are listed on pages XIV-XV.

Historic Environment Records and local heritage at risk registers, maintained by local authorities, are repositories of information on local historic assets. They underpin the work of local authority historic environment services and can help improve the protection, conservation and management of heritage assets.

BUILDINGS AND STRUCTURES

Our nine local teams can help existing and potential owners, developers and local authorities with the assessment of risk and the identification of appropriate programmes of repair. They can advise on the benefits of additional survey and assessment, help with feasibility studies and with brokering solutions. In particularly difficult cases they can draw on the additional expertise of our national advisers specialising in structural engineering, quantity surveying, development economics, enforcement and planning law. We can help with access to funding as we work closely with grant providers including the Heritage Lottery Fund and Natural England. Our own principal grant stream for buildings and structures is the Historic Buildings, Monuments and Designed Landscapes (HBMDL) grant but Section 17 Management Agreements can also be used to tackle risk to scheduled monuments. More information on funding can be found at www.english-heritage.org.uk/professional/funding.

We know from our own Register how useful it is in managing risk, prioritising action and engaging partners. We are therefore working with local authorities and voluntary groups to enable them to compile local heritage at risk registers and develop strategies for tackling buildings in poor condition. These strategies should include the use of enforcement powers. Our Heritage at Risk Legal Adviser can support local authorities considering enforcement action and we have published guidance at www.english-heritage.org.uk/publications/stoppingtherot. In certain circumstances we can also provide grant aid to underwrite the cost of serving Urgent Works and Repairs Notices.

Building preservation trusts (BPTs) offer a tried and tested way of saving buildings at risk. We have close links with the Architectural Heritage Fund and fund their regional support officers to work across the county. They help BPTs and other not-for-profit organisations access funding, carry out feasibility studies and develop solutions for buildings at risk. For more information on support officers and BPTs visit www.ahfund.org.uk and www.ukapt.org.uk. Guidance and case studies can be found at www.english-heritage.org.uk/publications/pillars-of-the-community.

English Heritage also funds an Industrial Heritage Support Officer to work with groups running industrial heritage sites. For more information please visit www.industrialheritagesupport.wordpress.com.

PLACES OF WORSHIP

Regular maintenance helps to keep all buildings in good condition but those suffering major problems need repairs to minimise the risks to both the structure and the contents. Keeping drains and gutters clear so that water is taken away from the building efficiently is the most important thing congregations can do as this stops small problems developing into unnecessary crises. The overflowing gutter soon soaks the wall beneath, rots the roof timbers behind it and makes the whole building vulnerable.

In some areas congregations group together to engage reputable contractors at competitive rates to clear gutters and rainwater goods. Such co-operation enables them to get good quality work carried out at reasonable prices by firms that understand historic buildings. The Maintenance Co-operatives project run by the Society for the Protection of Ancient Buildings will further help to connect, inform and empower those people who look after places of worship.

The Heritage Lottery Fund runs the new Grants for Places of Worship scheme. The main focus of the scheme is fabric repairs but it also provides funds for modest changes to enhance community use of the building. English Heritage's architects and surveyors, based in our local Heritage at Risk teams, provide technical advice to the Heritage Lottery Fund on fabric repairs to ensure appropriate conservation standards are met.

The Government's Listed Places of Worship scheme, enabling the reclaiming of VAT on eligible repairs, maintenance and authorised alterations, is available to all listed places of worship, whether they have obtained grants or are funding work themselves. Local and national charities also offer grants.

English Heritage supports congregations wanting to keep their places of worship in use and recognises the need for appropriate new facilities such as kitchens and toilets that are sensitive to the building's special character. *New Work in Historic Places of Worship* (published 2012) helps congregations understand how changes can be achieved.

A network of support officers, employed locally but part-funded by English Heritage, offers direct advice and encouragement to congregations. Projects to effect repairs and develop necessary new facilities for both the community and visitors are breathing a new lease of life into these treasured parts of our heritage.

ARCHAEOLOGY

The excellent progress which is being made with reducing the number of scheduled monuments on the Register continues to demonstrate the value which owners and land managers are placing upon the positive management of archaeological sites. The large majority (84%) of the 19,832 scheduled

monuments in England (in 2013) are on land classified as agricultural. Effective information sharing with Natural England and Defra is therefore of great importance for prioritising management action and for targeting agri-environment grant schemes to best effect. This will be especially important with the New Environmental Land Management Scheme (NELMS) which commences in 2015. Natural England now shares our corporate target of removing 25% of the scheduled monuments on the 2010 Register by 2015. We also continue to work closely with the Heritage Lottery Fund to identify the nationally important monuments deserving of grant-aid for enhanced conservation, presentation and access projects.

Loss and damage as a consequence of arable cultivation remains the greatest source of risk to scheduled monuments on the Register. Reporting in late 2013, however, the Conservation of Scheduled Monuments in Cultivation (COSMIC) project has provided updated risk assessments for 1587 sites on the Register, and features bespoke prescriptions for reducing the risks from cultivation damage. In some cases, the COSMIC mitigation recommendations have already been acted upon by our local teams, resulting in a significant number of removals from the 2013 Register.

Analysis of entries on the Register shows that unmanaged woodland, tree, scrub and bracken growth is one of the most widespread causes of long-term damage to both urban and rural archaeological sites - even if the effects are not as visible or as immediately destructive as other processes. In most cases simple, low cost but regular maintenance is the key, the delivery of which will always be reliant upon the help and goodwill of landowners.

PARKS AND GARDENS

Although a statutory list, the *Register of Historic Parks and Gardens of Special Historic Interest in England* in itself brings no additional statutory powers, it instead works through the development control system to provide a valuable tool for the protection of the sites it includes. The Government's *National Planning Policy Framework* (NPPF) stresses the desirability of sustaining and enhancing the significance of all heritage assets and finding viable uses consistent with their conservation. The NPPF states that great weight must be given to the conservation of sites included on the *Register of Historic Parks and Gardens of Special Historic Interest* and that substantial harm or loss of such features can only be justified in exceptional cases.

A great many historic parks and gardens are either privately owned or in trust. In addition, local authorities are responsible for nearly all the public parks and cemeteries in our towns and cities. Registered parks and gardens are typically large, complex heritage assets, many in multiple ownership, and it can take years to identify and implement solutions to reduce the risks to parks and gardens.

To help reduce the risks, English Heritage encourages and works with owners to develop conservation management strategies. Landscape architects working in our Heritage at Risk teams can help tailor conservation management plans and funding packages for individual landscape features or whole sites. We work with partners, such as Natural England and the Heritage Lottery Fund, to help source funding to secure sustainable futures for parks and gardens at risk.

Further information and conservation guidance for parks, gardens and designed landscapes is available at: www.english-heritage.org.uk/professional/advice/advice-by-topic/parks-and-gardens.

BATTLEFIELDS

As with registered parks and gardens, the *Register of Historic Battlefields* brings no additional statutory controls to registered battlefields, but the *National Planning Policy Framework* makes it clear that registered battlefields are of equal significance to scheduled monuments, buildings listed grade I and II* registered parks and gardens and protected wreck sites. Therefore, the positive conservation and management of registered battlefields is a core element of current heritage legislation.

English Heritage continues to work with owners to develop management plans for registered battlefields and, in appropriate cases, contribute towards the cost of management plans. We work to develop positive landscape strategies with owners and partners such as Defra through Environmental Stewardship schemes. In some circumstances, we may encourage the conversion from arable to pasture of especially sensitive locations to protect battlefield archaeology from the effects of ploughing and as part of a wider drive to prevent unauthorised or damaging metal-detecting.

English Heritage also continues to encourage greater access to battlefields and improve their amenity value and visitors' understanding of the impact these historic events had on our development as a nation.

Local authorities can also invite comments from the Battlefields Trust on planning applications affecting the setting of registered battlefield sites.

WRECK SITES

At the strategic level, the major sources of risk to protected wreck sites have been identified. In terms of high-priority sites, practical requirements have also been implemented through conservation management plans and appropriate intervention.

Risks to protected historic wreck sites can often be reduced through education, provision of marker buoys, or planning policies that take full account of their national importance. However, some sites require

significant resources to stabilise their condition or to carry out detailed archaeological assessments of their conservation requirements. Although English Heritage has statutory power to allocate funds to promote the preservation and maintenance of protected wreck sites, its financial resources can solve only a small proportion of the problems.

In spite of the inherent difficulties with caring for this type of site, careful management must be maintained if we are to avoid the loss of wreck sites. It is therefore close co-operation between the owners of protected wreck sites (where known), authorised divers and all organisations charged with care for the marine and coastal environment, that will make the real difference to their long-term survival.

Practical advice on the management of historic wreck sites, whether at the coast-edge or under water, is available from English Heritage (maritime@english-heritage.org.uk) and from www.helm.org.uk

CONSERVATION AREAS

The risks to conservation areas are difficult to address as these designated areas can constitute large areas of land; they include streets, spaces, archaeology and trees as well as buildings and structures and therefore involve many different owners and methods of management. Looking after conservation areas is a responsibility shared by those of us who own homes and businesses within them as well as those of us whose job it is to manage them or make decisions about their future.

The Conservation Areas Survey, completed by local authorities, provides us with an understanding of what is particularly affecting the character and appearance of conservation areas: what is working well or what is putting them at risk. Strong planning policies, guidance and a clear management strategy for individual conservation areas, backed up by effective enforcement, are all critical in managing change in these areas. This is, however, extremely difficult at a time when local authorities across the country are reducing their staff numbers. Armed with the information provided by conservation area surveys, we, local authorities and other partners will have the evidence to direct resources much more accurately towards those conservation areas at greatest risk.

There are opportunities for members of the local community to get involved with protecting and enhancing their conservation area, either individually or through groups. Some local groups have helped to prepare character appraisals and management plans for conservation areas whilst others have carried out their own assessments to identify management issues. Further information on how you can get involved is available at: www.english-heritage.org.uk/caring/get-involved/improve-your-neighbourhood.

Key statistics

BUILDINGS AND STRUCTURES

- Nationally, 4.0% of grade I and II* listed buildings (excluding places of worship) are on the Register. In the West Midlands the percentage is 5.0% (97 listed secular buildings).
- 13 building or structure entries have been removed from the 2013 West Midlands Register because their futures have been secured, and 9 have been added.
- 57.1% of buildings or structures (108) on the West Midlands baseline 1999 Register have been removed because their futures have been secured, compared with the national figure of 59.4%.

PLACES OF WORSHIP

- Nationally, 6.0% of listed places of worship are on the Register. In the West Midlands, 5.2% (76) are on the Register.
- 16 places of worship have been removed from the West Midlands Register following repair work, and 52 have been added.

ARCHAEOLOGY

- 3,012 (15.2%) of England's 19,833 scheduled monuments are on the Register. 210 (14.8%) of the 1,420 scheduled monuments in the West Midlands are on the Register.
- 20 archaeology entries have been removed from the 2013 West Midlands Register for positive reasons, and 8 have been added.
- 41.5% of archaeology entries (108) on the West Midlands baseline 2009 Register have been removed for positive reasons, compared with the national figure of 29.2%.

- Nationally, damage from arable cultivation is the greatest cause of risk affecting 43% of archaeological entries on the Register. In the West Midlands the proportion is 36%.

PARKS AND GARDENS

- 93 (5.7%) of England's 1,628 registered parks and gardens are on the Register. Of the 152 registered parks and gardens in the West Midlands, 7 (4.6%) are on the Register.
- 3 park and garden entries have been removed from the 2013 West Midlands Register for positive reasons.

BATTLEFIELDS

- Of the 46 registered battlefields in England, 6 (13.0%) are on the Register. Of the 10 registered battlefields in the West Midlands, none are on the Register.

WRECK SITES

- There are 49 protected wreck sites around England's coast, 4 of which are at risk. There are no protected wreck sites in the West Midlands.

CONSERVATION AREAS

- 8,206 of England's 9,848 conservation areas have been surveyed by local authorities and 497 (6.1%) are on the Register. Of the 794 conservation areas in the West Midlands, 696 have been surveyed and 51 (7.3%) are on the Register.
- 3 conservation areas have been removed from the 2013 West Midlands Register for positive reasons. None have been added.

ENGLISH HERITAGE FUNDING

- £1.4 million in grant was spent on 20 entries on the West Midlands Register during 2013/14.

Risk assessments of heritage assets are based on the nature of the site. Building and structure assessments include listed buildings (excluding listed places of worship) and structural scheduled monuments; archaeology assessments cover earthworks and buried archaeology.

Publications and guidance

English Heritage has produced the following publications relating to heritage at risk, including:

Assessment of Heritage at Risk from Environmental Threat: Key Message (2013)

Buildings at Risk: a New Strategy (1998)

Caring for Places of Worship 2010 (2010) – a report on the condition of England's listed places of worship and the needs of the congregations

COSMIC 3 – Grappling with a 140-Year-Old Conservation Problem (2014) – English Heritage Research News 21, available online

Counting our Heritage: a Heritage at Risk Survey for High Peak Staffordshire Moorlands by Community Volunteers (2013)

English Heritage's Heritage at Risk National Strategy (2011-2015) (2012)

Heritage at Risk 2010 – report (2010)

Heritage at Risk: Conservation Areas (2009)

Heritage at Risk 2014 – national summary leaflet and regional summary leaflets for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire

Heritage at Risk Register 2014 – detailed listings for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire can be downloaded from our website or viewed on an interactive database: www.english-heritage.org.uk/risk

Monuments at Risk (2008) – summary of scheduled monuments at risk for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire

The Monuments at Risk initiative 2003-08 (2010)

Protected Wreck Sites at Risk: A Risk Management Handbook (2007)

Saving London: 20 Years of Heritage at Risk in the Capital (2010)

Stopping the Rot: A Guide to Enforcement Action to Save Historic Buildings (2011)

Vacant Historic Buildings: An Owner's Guide to Temporary Uses, Maintenance and Mothballing (2011)

HERITAGE AT RISK ON THE WEB

To find out more about the Heritage at Risk programme visit www.english-heritage.org.uk/risk where you will find an interactive database providing detailed information on all heritage sites at risk nationally.

Details of all nationally designated historic places in England are available in one place on the National Heritage List for England online database: <http://list.english-heritage.org.uk>.

For further information about the different classes of designated heritage assets, including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites visit the Heritage Protection section of our website www.english-heritage.org.uk/professional/protection.

CONSERVATION POLICIES AND GUIDANCE

The following publications are among the numerous guidance documents available on our website: www.english-heritage.org.uk/publications and www.english-heritage.org.uk/helm

Caring for Historic Graveyard and Cemetery Monuments (2011)

Caring for Our Shipwreck Heritage: Guidelines on the First Aid Treatment and Conservation Management of Finds Recovered from Designated Wreck Sites Resulting from Licensed Investigations (2012)

Caring for Places of Worship (2010) – a practical booklet for everyone involved in caring for England's listed places of worship

Constructive Conservation in Practice (2008)

Constructive Conservation: Sustainable Growth for Historic Places (2013)

Conservation Principles, Policies and Guidance for the Sustainable Management of the Historic Environment (2008)

The Conservation, Repair and Management of War Memorials (2014)

Creativity and Care: New Works in English Cathedrals (2009)

The Disposal of Historic Buildings: Guidance Note for Government Departments and Non-Departmental Public Bodies (2010)

Enabling Development and the Conservation of Significant Places (2008)

Farming the Historic Landscape: Caring for Archaeological sites on Arable Land (2004)

Farming the Historic Landscape: Caring for Archaeological Sites in Grassland (2004)

Guidance notes and application forms for grants to local authorities:

- *Grants to Local Authorities to Underwrite Urgent Works Notices* (1998)
- *Acquisition Grants to Local Authorities to Underwrite Repairs Notices* (1998)
- *Grants for Historic Buildings, Monuments and Designed Landscapes* (2004)

Heritage Crime Prevention: A guide for Owners, Tenants and Managers of Heritage Assets (2013)

Heritage Crime Risk: Quick Assessment Tool (2013)

Heritage Works: the use of Historic Buildings in Regeneration (2013)

Managing Local Authority Heritage Assets: Some Guiding Principles for Decision Makers (2003)

New Uses for Former Places of Worship (2010)

New Work in Historic Places of Worship (2012)

Options for the Disposal of Redundant Churches and Other Places of Worship (2010)

Paradise Preserved: An Introduction to the Assessment, Evaluation, Conservation and Management of Historic Cemeteries (2002)

Pillars of the Community: the transfer of local authority heritage assets (2014)

Practical Building Conservation – revised ten-part series: Glass & Glazing; Metals, Mortars, Renders & Plasters; Stone; Timber; Building Environment; Concrete; Conservation Basics; Earth, Brick & Terracotta; Roofing (2012–2014)

Scheduled Monument Consent: A Guide for Owners and Occupiers (2009)

Shared Interest: Celebrating Investment in the Historic Environment (2006)

Theft of Metal from Church Buildings (2011)

Understanding Place: Conservation Area Designation, Appraisal and Management (2011)

Valuing Places: Good Practice in Conservation Areas (2011)

If you would like further information about any of these publications, please contact:

English Heritage Customer Services Department
PO Box 569, Swindon SN2 2YP
Telephone: 0870 333 1181
Fax: 01793 414926
Email: customers@english-heritage.org.uk

Key to the entries

This Register includes the following risk assessment types

- Building or structure
(grade I and II* listed buildings and structural scheduled monuments)
- Place of worship
(grade I, II* and II listed buildings)
- Archaeology
(scheduled monuments – earthworks and buried archaeology)
- Park and garden
(Registered parks and gardens)
- Conservation area
(Conservation areas)

ORDER

Entries are grouped and ordered alphabetically, first by County (dark grey bands) or Unitary Authority (light grey bands), and then by Local Planning Authority (National Park/Unitary Authority/District or Borough).

A blank band denotes the end of a county and the beginning of a unitary authority.

Sites that straddle more than one local planning authority are included under the lead authority.

Within each planning authority, entries are grouped by risk assessment type in the following order:

- Buildings or structures
- Places of worship
- Archaeology
- Parks and gardens
- Conservation areas

Within each risk assessment type, entries are ordered alphabetically by parish, locality and street/site name (except for conservation areas which are ordered by site name only).

DESIGNATION

The principal designation is noted for each entry and includes:

- Listed Building (LB) grade I or II*
- Listed Place of Worship grade I, II* or II
- Scheduled Monument (SM)
- Registered Park and Garden (RPG) grade I, II* or II
- Conservation Area (CA)

Other designations that apply to the designated site, including location within a World Heritage Site (WHS), are also noted.

If an entry is dual designated (both listed and scheduled), 'and' rather than a comma is used (eg 'Scheduled Monument and Listed Building grade I'). If a scheduled monument entry is dual designated with a number of listed buildings, each is separated by a semicolon.

The National Heritage List Entry Number is included for all entries (except conservation areas). If a site is dual designated, all relevant List Entry Numbers are noted.

CONDITION

For buildings (including places of worship), condition is graded as: 'very bad', 'poor', 'fair' and 'good'.

For sites that cover areas (scheduled monuments (archaeology assessments) and parks and gardens) one overall condition category is recorded. The category may relate only to the part of the site or monument that is at risk and not the whole site:

- extensive significant problems
- generally unsatisfactory with major localised problems
- generally satisfactory but with significant localised problems
- generally satisfactory but with minor localised problems
- optimal
- unknown (noted for a number of scheduled monuments that are below-ground and where their condition cannot be established).

For conservation areas, condition is categorised as: 'very bad', 'poor', 'fair' and 'optimal'.

If a site has suffered from heritage crime it is noted in the summary. Heritage crime is defined as any offence which harms the heritage asset or its setting and includes arson, graffiti, lead theft and vandalism.

OCCUPANCY/USE

For buildings (excluding places of worship) that can be occupied or have a use, the main vulnerability is vacancy or under-use. Occupancy (or use) is noted as follows:

- vacant
- part occupied
- occupied
- unknown
- not applicable

VULNERABILITY

Principal vulnerability is noted for archaeology assessments and may relate only to the part of the site that is at risk, and include:

- animal burrowing
- arable ploughing
- coastal erosion
- collapse
- deterioration – in need of management
- scrub/tree growth
- visitor erosion

For parks and gardens and conservation areas, vulnerability is noted as high, medium or low.

PRIORITY CATEGORY

Priority for action is assessed on a scale of A to F, where 'A' is the highest priority for a site which is deteriorating rapidly with no solution to secure its future, and 'F' is the lowest priority.

For buildings and structures and places of worship the following priority categories are used as an indication of trend and as a means of prioritising action:

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented
- C** Slow decay; no solution agreed
- D** Slow decay; solution agreed but not yet implemented
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

2013 priority categories are given in brackets, otherwise 'New entry' is noted.

'New entry – re-assessed' indicates an existing site on the Register that has been re-assessed using a different risk assessment methodology and is included on this year's Register under the new assessment type.

TREND

Trend for archaeology entries and parks and gardens may relate only to the part of the site that is at risk and is categorised as:

- declining
- stable
- improving
- unknown

For conservation areas trend is categorised as:

- deteriorating
- deteriorating significantly
- no significant change
- improving
- improving significantly
- unknown

OWNERSHIP

A principal ownership category is given for each entry, and if sites are in divided ownership, a 'multiple' ownership category is noted.

CONTACT

This is the member of the English Heritage local team who acts as a first point of contact for the case, and to whom enquiries should be addressed.

For conservation areas, the contact is the conservation/planning officer at the relevant local planning authority (indicated by 'LPA').

We are not in any sense agents for the owners of the sites included, but we will endeavour to put people in touch with them where appropriate.

ABBREVIATIONS

CA	Conservation Area
EH	English Heritage
HLF	Heritage Lottery Fund
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

Entries on the Register by local planning authority

Local planning authority	Building and structure entries	Place of worship entries	Archaeology entries	Park and garden entries	Battlefield entries	Wreck site entries	Conservation area entries
HEREFORDSHIRE, COUNTY OF (UA)							
Herefordshire, County of (UA)	23	25	27	1	0	0	3
SHROPSHIRE (UA)							
Shropshire (UA)	28	6	47	0	0	0	2
STAFFORDSHIRE							
Cannock Chase	0	0	0	0	0	0	1
East Staffordshire	3	0	5	0	0	0	2
Lichfield	2	0	5	0	0	0	1
Newcastle-under-Lyme	3	0	0	0	0	0	1
Peak District (NP)	1	0	2	0	0	0	0
South Staffordshire	2	0	5	0	0	0	2
Stafford	2	0	2	0	0	0	3
Staffordshire Moorlands	5	1	2	0	0	0	3
Tamworth	2	0	1	0	0	0	0
STOKE-ON-TRENT, CITY OF (UA)							
Stoke-on-Trent, City of (UA)	7	4	0	0	0	0	5
TELFORD AND WREKIN (UA)							
Telford and Wrekin (UA)	2	3	8	0	0	0	0
WARWICKSHIRE							
North Warwickshire	8	0	6	0	0	0	0
Nuneaton and Bedworth	2	0	0	0	0	0	0
Rugby	0	1	9	1	0	0	0
Stratford-on-Avon	6	2	15	0	0	0	2
Warwick	2	1	9	2	0	0	0
WEST MIDLANDS							
Birmingham	11	5	1	0	0	0	9
Coventry	9	0	1	0	0	0	0
Dudley	3	6	2	0	0	0	4
Sandwell	2	0	2	0	0	0	2
Solihull	0	0	0	0	0	0	0
Walsall	1	2	0	0	0	0	7
Walsall / Sandwell [†]	0	0	0	1	0	0	0
Wolverhampton, City of	1	2	0	0	0	0	0
WORCESTERSHIRE							
Bromsgrove	2	3	3	1	0	0	1
Malvern Hills	2	6	2	0	0	0	1
Redditch	0	0	1	0	0	0	0
Worcester	2	0	1	0	0	0	1
Wychavon	6	9	7	1	0	0	0
Wyre Forest	2	0	0	0	0	0	1
TOTAL	139	76	163	7	0	0	51

[†] Sites that cross local planning authority boundaries

HEREFORDSHIRE, COUNTY OF (UA)



© English Heritage

SITE NAME:	Gatehouse buildings at Wigmore Abbey, Grange, Adforton
DESIGNATION:	Scheduled Monument and Listed Building grade I, 2 LBs
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1005359 and 1179921

Remains of late C12 and C14 abbey. The Gatehouse comprises two buildings, one is without a roof and in very poor condition. Survey work to inform conservation is required. Structural assessment by English Heritage has indicated that elements of collapse are likely.

Contact: Sarah Lewis 0121 625 6886



© English Heritage

SITE NAME:	Ruined Church of St Mary, Avenbury
DESIGNATION:	Scheduled Monument and Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1005356 and 1349633

A ruined C12 church. The tower stands to full height, the roof survived to the mid C20 but has fallen in, the walls of the nave and chancel are half collapsed and survive only to a few feet in places. Fragments of decorated interior plaster survive. This building is in very bad condition. Vegetation clearance has been carried out by the owners under a management agreement. The walls are generally stable but are highly exposed.

Contact: Bill Klemperer 0121 625 6847



© English Heritage

SITE NAME:	Belmont House, Clehonger
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1167079

Late C18 country house by James Wyatt, extended and remodelled by EW Pugin c1860. The basement is used as a club house for the golf course, but the rest of the building is unused. Some holding repairs have been carried out and the building is watertight. There are some areas of weathering and deterioration. Resolution lies in finding and funding an appropriate and sustainable solution for building, this should be encouraged through the planning process.

Contact: Ross Brazier 0121 625 6884



© English Heritage

SITE NAME:	Clifford Castle, Clifford
DESIGNATION:	Scheduled Monument and Listed Building grade I
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1001774 and 1167903

Late C13 castle. Some propping and fencing carried out in past and most recently in 2013. New owners have carried out further beneficial vegetation clearance. Archaeological survey has been commissioned and structural inspection has been carried out. Undermining of the tower is a particular concern. Repair scheme in discussion with owner.

Contact: Imogen Sambrook 0121 625 6854



© English Heritage

SITE NAME:	Craswall Priory ruins, Craswall
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private, multiple owners
LIST ENTRY NUMBER:	1014536 and 1342128

The remains of one of only three Grandmontine Houses in England dating from 1220-25. Severely exposed position has contributed to priory's decline. A management agreement is in place for ongoing management of vegetation and urgent repairs to the piscina, now completed. Further consolidation and the repair of exposed and deteriorating architectural details are possibly to be addressed under a Natural England stewardship scheme.

Contact: Imogen Sambrook 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© English Heritage

SITE NAME:	Churchyard cross in St Michael's churchyard, Dewsall
DESIGNATION:	Scheduled Monument, LB grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1016130

The remains of a C14 cross comprising a plinth of two stone steps upon which sits a single large square base stone, from which rises the stump of a shaft. The plinth stones have open joints and have cracked and shifted beneath the base, there has been significant downward movement in the second step. The shaft appears sound but is wedged into an oversized square socket in which water pools and debris collects. An English Heritage Management Agreement has been offered and accepted. Works should be completed in 2014.

Contact: Imogen Sambrook 0121 625 6854



© English Heritage

SITE NAME:	Hereford city walls, Hereford
DESIGNATION:	Scheduled Monument, 2 LBs, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (C)
OWNER TYPE:	Local authority, multiple owners
LIST ENTRY NUMBER:	1005528

Medieval city walls which have been fully recorded. A programme of consolidation work has been carried out to some sections in the Council's ownership, but other sections affected by vegetation still need addressing. Sections in disputed ownership are particularly vulnerable. The Council has produced a Conservation Management Plan which identifies repair needs and a future plan of action. Contact is ongoing with various parties to address the most vulnerable areas.

Contact: Imogen Sambrook 0121 625 6854



© English Heritage

SITE NAME:	Huntington Castle, Huntington
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Fair
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1002939 and 1157544

Castle remains. C13, or earlier, repaired in 1403, abandoned in 1460 (although one tower still in use as prison in 1521). Motte and inner bailey are surrounded by a ditch and outer bailey. Traces of a curtain wall and C13 semi circular tower have survived in a fair condition although they are very overgrown. Work to control vegetation being carried out by owner. Unstable earthworks need long term management plan which will hopefully be addressed through an environmental stewardship agreement.

Contact: Imogen Sambrook 0121 625 6854



© Robert Waddington, copyright form signed

SITE NAME:	The Master's House, St Katherine's Hospital, High Street, Ledbury
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1301731

St Katherine's Hospital was founded in 1232 and the Master's House constructed in the C15 for the overseer. A high quality timber frame survives within later brick facades; the building was extended in the C19. A major repair project funded by the Council and the Heritage Lottery Fund is nearing completion and the building will re-open in early 2015 as a library, information hub and local Council office with heritage interpretation.

Contact: Chris Miners 0121 625 6853



© English Heritage Archive

SITE NAME:	Remains of Limebrook Priory, Limebrook, Lingen
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1001722 and 1157383

C13 nunnery of which only a single ruined building survives. Sheep are damaging the site. An English Heritage structural assessment has been carried out. A solution is now in the early stages of being implemented.

Contact: Imogen Sambrook 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© English Heritage

SITE NAME:	Lyonshall Castle, Lyonshall
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1001720 and 1301287

C13 keep enclosed by inner bailey and outer enclosures. Owners undertaking maintenance of earthwork site in accordance with English Heritage advice. Much vegetation control carried out. Survey carried out to inform repairs and masonry consolidation being discussed with owner.

Contact: Imogen Sambrook 0121 625 6854



© English Heritage

SITE NAME:	Outbuilding east of Marstow Court (formerly listed as the Granary at Marstow), Marstow
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1214715

Reputedly associated with manor of the Knights Hospitallers who held lands in Marstow and probably originally a house, circa C15. Built of sandstone rubble under a Welsh slate roof with C18 and C19 alterations. The building is now in agricultural use. The stonework and pointing are generally in poor condition, there are slipped and missing roof slates and the windows and doors are in poor condition. A scheme for conversion has been approved.

Contact: Sarah Lewis 0121 625 6886



© English Heritage

SITE NAME:	Barn and attached cowhouse built onto Glibes Farmhouse, Michaelchurch Escley
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1223446

A four-bay barn with an extra bay for a cow house and further loft bay linking to farmhouse which has collapsed. Probably C18 in date. A temporary metal sheet roof protects the building which is unused and in need of comprehensive repair. The owner has no proposals for the repair of the building, and its future is uncertain.

Contact: Sarah Lewis 0121 625 6886



© English Heritage

SITE NAME:	Glibes Farmhouse, Michaelchurch Escley
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (E)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1223549

A remote farmhouse probably C17 with C18 alterations. The walls are of thin coursed rubble stone; the roof was of stone tiles but has been temporarily replaced in metal sheet. The building is unoccupied and in need of comprehensive repair. A programme of urgent works including repair of the temporary roof and rebuilding of fallen masonry has improved its condition but the chimney stacks are deteriorating and further long term repairs are necessary.

Contact: Sarah Lewis 0121 625 6886



© English Heritage

SITE NAME:	Dovecote south of Much Cowarne, Much Cowarne
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1349680

A round stone dovecote, probably Medieval, with conical tiled roof and the remains of a C17 or C18 wooden louvre. Originally connected with Much Cowarne Court which no longer exists, the dovecote is now isolated in the corner of a field. There are holes in the roof at eaves allowing small trees to take root in the wall top and resulting in structural deformity below. The interior is in good condition with all nesting boxes in situ. A structural assessment and repairs to the roof are urgently needed.

Contact: Chris Miners 0121 625 6853

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© English Heritage

SITE NAME:	Churchyard cross in St John the Baptist's churchyard, Orcop
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1016112 and 1348859

Standing stone cross principally Medieval, with base of two steps, socket stone and lower part of shaft. Lists substantially to east. Cracked and displaced stone at base. Part of stone step missing at south west corner. In need of stabilisation and consolidation. A scheme of repair is in the early stages of implementation.

Contact: Imogen Sambrook 0121 625 6854



© English Heritage

SITE NAME:	Urishay Castle, Peterchurch
DESIGNATION:	Scheduled Monument and Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1014547 and 1099487

Remains of C12 motte castle, a ruined C17 house and a partly ruined C16 chapel. The chapel is stable and in good condition, the C17 house is not. Without a roof the masonry is disintegrating. Lintels are failing and in danger of collapse. Requires assessment of structure to establish survival of Medieval fabric and future strategy.

Contact: Sarah Lewis 0121 625 6886



© English Heritage

SITE NAME:	Snodhill Castle, Snodhill, Peterchurch
DESIGNATION:	Scheduled Monument and Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1015168 and 1172756

C14 castle with C12 motte. Standing remains in serious condition and heavily overgrown. Part of the curtain wall has collapsed. Undermining by badgers and collapse as a result of fallen trees is putting masonry at great risk. English Heritage has funded a survey which has informed discussions with the owners on a plan for long term care and preservation.

Contact: Bill Klemperer 0121 625 6847



© English Heritage

SITE NAME:	Court Cottage (formerly Court Farmhouse), Preston Wynne
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1099380

A former hall house dating from C14 which retains a spere truss and cruck truss of high architectural quality. This building is now used for storage with residential accommodation in the later C17 house which was added to the south end. Grant aid achieved essential stabilisation and roofing works but the condition of the building continues to decline.

Contact: Sarah Lewis 0121 625 6886



© English Heritage

SITE NAME:	Churchyard cross in St Mary's churchyard, Walterstone
DESIGNATION:	Scheduled Monument, LB grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1016132

A C15 or early C16 churchyard cross of sandstone. The stepped plinth has open joints and fractured stonework and areas of collapse. The octagonal shaft sits in a massive square base with shaped and moulded stops. The condition of the plinth has allowed the base and shaft to move out of true. English Heritage has offered a Management Agreement to fund repairs which has been accepted. Repairs should be completed in 2014.

Contact: Imogen Sambrook 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© English Heritage

SITE NAME:	Penyard Castle, Weston under Penyard
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1005385 and 1099662

Remains of C14 castle in split ownership and land use. Part Medieval and post Medieval. Some remains are overgrown and in a poor state of repair. The remains in private ownership are in a fair state. Programme of vegetation control undertaken by Forestry Commission. A management agreement for survey and stabilisation of Medieval fabric is in discussion.

Contact: Imogen Sambrook 0121 625 6854



© English Heritage

SITE NAME:	Post-Medieval house at Willey Court, Willey
DESIGNATION:	Scheduled Monument
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1017251

This monument includes the buried, earthwork and upstanding remains of the post-Medieval house and gardens at Willey Court. Actively involved in management, the owners are in negotiations with English Heritage to determine an appropriate strategy for consolidation and management of the site, following on from previous successful agreements.

Contact: Imogen Sambrook 0121 625 6854



© English Heritage

SITE NAME:	Chuch of St Andrew, Wolverlow
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1217197

Early C12 church restored in 1863 by Kempson, of stone construction under a clay tile roof with timber framed tower and shingle spire. The church has not been used for worship since 2006 and sits in an isolated location. Rainwater goods are absent and the roof has slipped and broken tiles. A sale has now been agreed by The Church Commissioners and an application for Planning Permission and Listed Building Consent has been submitted to the Local Authority for the conversion of the building for residential use.

Contact: John Yates 0121 625 6846



© English Heritage

SITE NAME:	Church of St Mary, Abbey Dore
DESIGNATION:	Listed Place of Worship grade I, SM
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1099794

Large Anglican parish church created in c1634 from the derelict Abbey church of the dissolved Cistercian Dore Abbey. The c1220 transepts crossing and chancel remain with a C17 tower inserted on the south-east angle of the crossing. There are now repair problems with the roof and drainage from this tower as well as the sandstone ashlar walling. The sandstone slates of all the main roofs have been renewed except the north transept chapel roof which still has the original slates. These have now failed and are leaking and need urgent re-slating.

Contact: Chris Miners 0121 625 6853



© English Heritage

SITE NAME:	Church of St Bartholomew, Church Lane, Ashperton
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Very bad
PRIORITY CATEGORY:	B (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1098909

Large Anglican parish church at the edge of a small village. Cruciform plan of nave chancel and transepts all of the C14. The west tower added in the C18. Tower roof and valley gutter leaks causing rot to the tower roof structure. The partly cement-rendered walls are causing dampness in the walls and floor of the main body of the church. A Heritage Lottery Fund grant has been applied for.

Contact: Chris Miners 0121 625 6853

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
B Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© English Heritage

SITE NAME:	Church of St Peter, Birley with Upper Hill
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1081970

Small Anglican parish church in a large level churchyard in the middle of a scattered village. C12 and C13 nave and chancel and late C14 south chapel. The west tower is circa 1200. Recent grant-aided repairs have remedied tower roof problems and the stonework to the chancel and vestry. However the sandstone rubble stonework is still poor on the tower and south chapel gable.

Contact: Chris Miners 0121 625 6853



© English Heritage

SITE NAME:	Church of Holy Trinity, Main Street, Bosbury
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	B (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1098890

Large rural Anglican parish church. Circa 1200 aisled nave and east chancel with C15 south entrance porch and c1510 chantry chapel, with C19 north vestry. It has a C13 detached bell tower with a C19 roof to the south. Both grade I listed. Walls of sandstone rubble with ashlar dressings, tiled roofs to the chapel. The north aisle roof and the tower slate roof need urgent renewal to stop decay. The north vestry has structural movement at the external corners and there is ground level damp causing internal decay. A Heritage Lottery Fund repair grant has been applied for.

Contact: Chris Miners 0121 625 6853



© English Heritage

SITE NAME:	Chapel at Brockhampton Park, Brockhampton
DESIGNATION:	Listed Place of Worship grade II*, RPG grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1349630

Tiny Anglican chapel in the grounds of Brockhampton Park. Built 1798 by Byfield in the Gothick revival style of a nave and west tower. Grey sandstone ashlar with battlemented parapets on the 'show' sides but coursed rubble and conventional eaves to the north. Structurally deflected slate roof. The ashlar mouldings are heavily eroded.

Contact: Chris Miners 0121 625 6853



© English Heritage

SITE NAME:	Church of St Peter, Bromyard and Winslow
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1307758

Large Anglican Medieval civic church in the centre of Bromyard. The 2006 and 2011 Quinquennial Inspections identified stonework and roof repairs as necessary. A programme of work has been agreed and it is hoped that this will commence soon. The roof valleys have been repaired but now the slate roofs are the main problem with fixing failures.

Contact: Chris Miners 0121 625 6853



© English Heritage

SITE NAME:	Church of St John the Baptist, Upper Road, Eastnor
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1266756

Large Anglican parish church. Rebuilt by GG Scott in 1852 except for the C14 west tower and the C13 arcade and C12 south doorway. Generally sandstone ashlar in the C13 style and with tiled roofs. The sandstone ashlar of the tower is in poor condition with cracking, erosion and open jointing.

Contact: Chris Miners 0121 625 6853

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© English Heritage

SITE NAME:	Church of St Michael, Felton
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	B (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	I177507

Small rural Anglican parish church rebuilt in the Decorated style by T Nicholson in 1853 re-using older fabric. The oak shingled spire added in 1891. The walls are sandstone rubble with ashlar dressings and the roofs are tiled. The tower parapet gutters leak and have decayed the tower roof structure. The chancel valley gutter is also leaking and needing repair. A Heritage Lottery Fund repair grant has been applied for.

Contact: Chris Miners 0121 625 6853



© English Heritage

SITE NAME:	Church of St John the Baptist, Grendon Bishop
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Very bad
PRIORITY CATEGORY:	A (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	I307407

Parish church built in the 1780s, which now looks Victorian in character. The church has damp problems, slipped tiles are allowing water into the chancel.

Contact: Chris Miners 0121 625 6853



© English Heritage

SITE NAME:	Church of St Dubricius, Hentland
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	I288593

Small rural Anglican parish church with C11 vestiges but C13 and C14 nave and chancel. Restored by JP Seddon in 1853 and with C19 vestry and porch. The late C14 tower has structural cracking on the west side. Internal plaster falls have happened in the nave and chancel west end roof. The sandstone rubble walls are heavily eroded. The sandstone slate roof pitches and the plain clay tiled pitches have slipped or missing slates and tiles.

Contact: Chris Miners 0121 625 6853



© English Heritage

SITE NAME:	Church of St Peter, St Peter's Square, Hereford
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	I196883

Large urban Anglican parish church in the city centre of Hereford. C13 tower and 4-bay arcade, chancel and south chapel all from circa 1300. Extensively rebuilt by Thomas Nicholson in 1880-5. The valley between the nave and north aisle leaks and the south pitch slate roof needs urgent renewal.

Contact: Chris Miners 0121 625 6853



© English Heritage

SITE NAME:	Church of St Mary, Hope under Dinmore
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	I301623

Small but lengthy Anglican parish church on an isolated hillside setting next to the A49. Heavily restored by Kempson in 1877 and 1896 but the small west tower and north chapel still have C12 and C13 fabric. The north chapel gable has structural movement, the cast iron gutters are cracked, rusting and leaking. The tower sandstone rubble is heavily eroded.

Contact: Chris Miners 0117 975 0700

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© English Heritage

SITE NAME:	Church of St Andrew and St Mary, How Caple
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	I166452

Anglican parish church in a hillside setting overlooking the River Wye. C14 chancel with a later low-pitched roof. The tower, nave and chancel are all from 1693-5 and the windows C19. The rainwater goods are under sized and failing. The ashlar stonework of the tower is delaminating and falling. The parapet stonework of the tower is structurally unsound next to the vice door.

Contact: Chris Miners 0121 625 6853




© English Heritage

SITE NAME:	Church of St Mary, Middleton on the Hill
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Very bad
PRIORITY CATEGORY:	B (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	I167020

Small Anglican parish church. C12 nave and chancel with C13 west tower. Sandstone rubble walls with sandstone ashlar dressings and tiled roofs. The nave roof tiling is falling off and the rafters have decayed. The tower stonework needs replacement of severely eroded stonework. A Repair Grant for Places of Worship has been awarded and repairs are expected to happen in 2014.

Contact: Chris Miners 0121 625 6853



© English Heritage

SITE NAME:	Church of St Peter, Pipe and Lyde
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	I172739

Small Anglican parish church set at the end of a small village and facing the A49. Late C12 nave and C14 chancel largely rebuilt by F Kempson in 1874 who also added the broach spire to the C13 tower. The roof needs repair and work needed to the tower. Repair Grant for Places of Worship has been allocated to remedy the problem and work is about to start on site.

Contact: Chris Miners 0121 625 6853



© English Heritage

SITE NAME:	Church of St Andrew, Pixley
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	I098989

Small single-cell rural Anglican parish church in a farmyard setting. C13 core, the chancel and roof C14, the integral bellcote C19 with C17 windows. Recent English Heritage grant- aided project repaired the roof, bellcote and rainwater system but structural instability needs repair in the north east corner and the timber-framed entrance porch.

Contact: Chris Miners 0121 625 6853



© English Heritage

SITE NAME:	Church of St Tysilio, Sellack
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	F (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	I214929

Small Anglican parish church. C12 core of nave with continuous chancel, C13 west tower with C14 spire, chancel and chapel. Restoration in 1842 by JL Pearson. Nave and chancel roofs from 1899. Structural and stonework repairs are urgently needed to the spire and tower. A Repair Grant for Places of Worship was awarded in 2013 and repair work is underway.

Contact: Chris Miners 0121 625 6853

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© English Heritage

SITE NAME:	Church of St Mary, Staunton on Wye
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	I166457

Large rural Anglican parish church high in a hillside village overlooking the River Wye. C12 core in the nave, the west tower C13 with the chancel and porch from the C18. The hipped tiled roof has holes. The nave sandstone slate roof has slipped slates. The gutter on the north side has failed. The internal plaster is damp affected and part fallen.

Contact: Chris Miners 0121 625 6853



© English Heritage

SITE NAME:	Church of St Mary, Stoke Edith
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Very bad
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	I099825

Large Anglican parish church, rebuilt by the Foleys of Stoke Edith Park in 1740 in the Palladian Style by Henry Flitcroft. The C14 tower with truncated spire was retained. The roof leaks causing rot in the nave beam and falls in the ornate plasterwork. The ashlar facings are eroding severely. A few stones have fallen from the tower and spire.

Contact: Chris Miners 0121 625 6853



© English Heritage

SITE NAME:	Church of St Mary, Turnastone
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	I224950

Small Anglican parish church in a large level churchyard in the centre of a tiny village. Integral C12 nave and C13 chancel. The east window is C16 where structural cracking in the sandstone rubble has affected the east gable.

Contact: Chris Miners 0121 625 6853



© English Heritage

SITE NAME:	Church of St Michael, Upper Sapey
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Very bad
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	I275895

Small rural Anglican parish church in a sloping churchyard at the edge of a small village. Middle to late C12 chancel and nave with surviving north and south doorways. Restored 1860 with tower and timber broached spire added. There have been recent grant-aided repairs to the roof but the spire boarding, together with stonework and structural issues at the east end, now needs urgent repair.

Contact: Chris Miners 0121 625 6853



© English Heritage

SITE NAME:	Church of St Peter and St Paul, Church Road, Weobley
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	I301343

Large Anglican parish church at the edge of the village of Weobley. C13 nave and flanking aisles with C14 chancel extension and north west tower. Poor sandstone ashlar on the tower and spire is insoluble but is being managed by high level metal guards and ground level fencing.

Contact: Chris Miners 0121 625 6853

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© English Heritage

SITE NAME:	Church of St Lawrence, Church Lane, Weston under Penyard
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1348828

Rural Anglican parish church overlooking a small village. Core of late C12 nave and north arcade, C13 chancel, C14 tower and porch. The sandstone roof slates are failing with splits and falls on the nave and aisle roof pitches.

Contact: Chris Miners 0121 625 6853



© English Heritage

SITE NAME:	Church of St James, Church Street, Wigmore
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1178822

St James is a sandstone church with ashlar and tufa dressings built in C11, set on rising ground in the centre of the village. The chancel, south aisle and tower are additions of the C14 and C15. Few other alterations took place prior to a C19 restoration by G Bodley when the chancel arch was rebuilt. A programme of grant-aided works has been agreed under the Repair Grant for Places of Worship scheme offered in January 2013, with repairs to the tower roof and rainwater goods being urgent. Work is due to be completed by summer 2014.

Contact: Chris Miners 0117 975 0700



© English Heritage

SITE NAME:	Church of St Peter and St Thomas, Wormbridge
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1099588

A Medieval church restored in the mid C19 with a new nave roof, spire and re-facing of the stonework to elevations. Stonework to the tower is badly eroded, the spire slating is allowing water into the structure, rainwater goods and drainage is generally poor. A Repair Grant for Places of Worship was offered in April 2013 to address these issues.

Contact: Chris Miners 0121 625 6853

SITE NAME:	Almeley Castle, Almeley	LIST ENTRY NUMBER:	1001752
DESIGNATION:	Scheduled Monument, CA	TREND:	Declining
CONDITION:	Generally unsatisfactory with major localised problems	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Scrub/tree growth	CONTACT:	Imogen Sambrook 0121 625 6854
OWNER TYPE:	Private		

SITE NAME:	Roman settlement, Canon Frome	LIST ENTRY NUMBER:	1005271
DESIGNATION:	Scheduled Monument	TREND:	Unknown
CONDITION:	Unknown	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Arable ploughing	CONTACT:	Imogen Sambrook 0121 625 6854
OWNER TYPE:	Private		

SITE NAME:	Roman fort and outworks 550 yards (500 metres) south west of Canon Frome Court, Canon Frome	LIST ENTRY NUMBER:	1005347
DESIGNATION:	Scheduled Monument	TREND:	Unknown
CONDITION:	Unknown	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Arable ploughing	CONTACT:	Imogen Sambrook 0121 625 6854
OWNER TYPE:	Private		

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Clifford Castle, Clifford		
DESIGNATION:	Scheduled Monument and Listed Building grade I	LIST ENTRY NUMBER:	1001774 and 1167903
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Craswall Priory, associated building remains, pond bays and hollow ways, Craswall		
DESIGNATION:	Scheduled Monument and Listed Building grade II	LIST ENTRY NUMBER:	1014536 and 1342128
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Site of Rotherwas House, earthwork remains of formal gardens, and Rotherwas Chapel, Dinedor		
DESIGNATION:	Scheduled Monument, LB grade II*	LIST ENTRY NUMBER:	1014880
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Promontory fort on Dorstone Hill, Dorstone		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014544
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Roman settlement, Ford and Stoke Prior / Humber		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005322
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Ring ditches and rectilinear enclosures east of Tupsley, Hampton Bishop		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005348
CONDITION:	Unknown	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Other not for profit group	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Row Ditch (entrenchment), Hereford		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1001780
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Dumping	NEW ENTRY?:	No
OWNER TYPE:	Local authority, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Huntington Castle, Huntington		
DESIGNATION:	Scheduled Monument and Listed Building grade II	LIST ENTRY NUMBER:	1002939 and 1157544
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Turret Castle, Huntington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007314
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Kingsland Castle, Kingsland		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1007318
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Offa's Dyke: section north west of Holme Marsh extending 615 yards (560 metres) to the railway, Lyonshall		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001735
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alison MacDonald 0121 625 6827
SITE NAME:	Ringwork 750 metres west of Grove Farm, Much Dewchurch		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014893
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Bowl barrow 460 metres south of Milton Cross, Pembridge		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014103
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Bowl barrow 490 metres south east of Milton Cross, Pembridge		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014112
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Bowl barrow 550 metres south east of Milton Cross, Pembridge		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014895
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	North Herefordshire Rowe Ditch, Pembridge / Staunton on Arrow		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005382
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Shell keep castle and associated fishponds at Snodhill, Peterchurch		
DESIGNATION:	Scheduled Monument and Listed Building grade II*	LIST ENTRY NUMBER:	1015168 and 1172756
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Bill Klemperer 0121 625 6847
SITE NAME:	Moated site and fishponds immediately west of Upper House Farm, Staunton on Wye		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019476
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Sutton Walls (camp), Sutton / Marden		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001747
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Roman fort at Coppice House, Tedstone Wafer		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005363
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Wall Hills Camp, Thornbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001748
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
B Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Motte and bailey, west of St Mary's Church, Walterstone		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001778
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Roman town of Ariconium, Weston under Penyard		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005364
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Offa's Dyke: Upperton Farm, two sections extending 195 yards (180 metres) and 370 yards (340 metres) south from Yazor, Yazor		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001736
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alison MacDonald 0121 625 6827



© English Heritage

SITE NAME:	Shobdon	Early C18 formal gardens (much modified) and mid C18 landscape park, part of which is open to the public. Although some garden buildings survive, their context is much altered; commercial fruit growing, a caravan park, a chicken farm, commercial forestry and intensive agriculture characterise the historic park.
DESIGNATION:	Registered Park and Garden grade II, 10 LBs, 3 SMs	
CONDITION:	Extensive significant problems	
VULNERABILITY:	Medium	
TREND:	Stable	
NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	
LIST ENTRY NUMBER:	1000894	Contact: Kim Auston 0117 975 0696

SITE NAME:	Kington		
DESIGNATION:	Conservation Area, 122 LBs, SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Robert Walker (LPA) 01432 260140

SITE NAME:	Ross-on-Wye, Ross-on-Wye / Bridstow		
DESIGNATION:	Conservation Area, 151 LBs, 4 SMs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Robert Walker (LPA) 01432 260140

SITE NAME:	Widemarsh Common, Hereford		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Robert Walker (LPA) 01432 260140

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SHROPSHIRE (UA)



© English Heritage Archive

SITE NAME:	Wattlesborough Castle (uninhabited parts), Alberbury with Cardeston
DESIGNATION:	Scheduled Monument and Listed Building grade I, part in LB grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1006285 and 1366883

Remains of large square tower of castle with fine quality detailing, now without roof. Probably late C13 for Sir Robert Corbet. There has been a recent fall of masonry from high level. The owner is considering consolidation and re-roofing for domestic use.

Contact: Sarah Lewis 0121 625 6886



© English Heritage

SITE NAME:	Alberbury Castle, Alberbury, Alberbury with Cardeston
DESIGNATION:	Scheduled Monument and Listed Building grade II*, 2 LBs, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1020662 and 1175344

Remains of tower keep from C13 castle. Rapidly eroding with rampant ivy cover and mortar erosion and undermined masonry. Survey commissioned by English Heritage as a basis for designing a programme of urgent repair works for discussion with owner. Natural England funding may be available via existing Stewardship scheme.

Contact: John Tiernan 0121 625 6839



© English Heritage Archive

SITE NAME:	Barn to west of Hall Farmhouse, Aston Eyre
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1053205

Used as a barn for many years, this building is in fact a Medieval hall with a solar wing and dates from the C15. Consent has been given for conversion back to residential use. The owner is carrying out repairs and has undertaken a detailed recording of the stonework. Structural repairs and re-roofing have been carried out so the building is now wind and weather proof.

Contact: John Yates 0121 625 6846



© English Heritage

SITE NAME:	48, Mill Street, Bridgnorth
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1177762

c1675, this three storey building forms part of a commercial premises used as an antique centre. The oldest building fronting the road was in poor condition but extensive repairs have been completed with the benefit of English Heritage grant. This part of the property is still vacant, but the owners have plans for re-use and the building will be removed from the Register when it is occupied once more.

Contact: John Tiernan 0121 625 6839



© English Heritage Archive

SITE NAME:	Rockley Farmhouse, Chirbury with Brompton
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1054405

Early C17 farmhouse with mid C20 alterations. The farmhouse is run-down but watertight. It is in need of basic repair and maintenance work.

Contact: John Yates 0121 625 6846

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	Old Hall and attached garden wall, Old Marton, Ellesmere Rural	Large farmhouse, mid to late C16 with later additions and alterations. Timber-framed with painted brick and rendered infill. The roof has been repaired and repairs to the timber frame and infill panels have commenced. The adjoining C18 garden wall, of red brick with moulded stone coping, has partially collapsed.
DESIGNATION:	Listed Building grade II*	
CONDITION:	Poor	
OCCUPANCY:	Part occupied/part in use	
PRIORITY CATEGORY:	F (F)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1307787	

Contact: Sarah Lewis 0121 625 6886

© English Heritage



SITE NAME:	Ludlow town walls, Ludlow	Medieval town wall in multiple ownership. English Heritage have helped to fund a town walls management plan and the repair of substantial sections in local authority ownership. A Town Walls Trust has been established to promote the protection and care of the walls. A major section of wall below the parish church collapsed in spring 2013, other small collapses have taken place on the south section where ownership is disputed.
DESIGNATION:	Scheduled Monument and Listed Buildings - 8 grade II, 2 CAs	
CONDITION:	Poor	
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Mixed, multiple owners	
LIST ENTRY NUMBER:	1006278 and 1219038; 1289747; 1291656; 1202827; 1202825; 1202826; 1219077; 1282007	

Contact: Sarah Lewis 0121 625 6886

© English Heritage



SITE NAME:	The Butter Cross, King Street, Ludlow	The Butter Cross was designed by William Baker and built c 1746. It is a dominant public building in centre of Ludlow which was used as the Town Council office and chambers. The Council has moved into new accommodation. External repairs were completed with the help of an English Heritage grant and final repairs to ceiling plaster are now also complete. Although still currently unoccupied, proposals are established to use the building as a Heritage Centre for the town.
DESIGNATION:	Listed Building grade I, CA	
CONDITION:	Good	
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	F (E)	
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1289674	

Contact: Ross Brazier 0121 625 6884

© English Heritage



SITE NAME:	Remains of Lea Castle at Lower Lea Farm, Lea, Lydham	Fragmentary remains of a C12 castle surviving in the middle of a working farm. This was formerly a castle of the Bishops of Hereford. Victorian house abuts the castle remains which are heavily overgrown. Urgent need to reduce ivy growth, to be followed by repair and consolidation of masonry. An application for English Heritage grant is expected.
DESIGNATION:	Scheduled Monument and Listed Building grade II, 2 LBs	
CONDITION:	Poor	
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1021064 and 1054509	

Contact: John Tiernan 0121 625 6839

© English Heritage



SITE NAME:	Charllotte Furnace, Neenton	C17 blast furnace for the manufacture of pig iron from ironstone, using charcoal as fuel. A relic of the long extinct local iron industry. There are structural problems and areas of unconsolidated masonry in need of long term repair. Temporary propping has been carried out and management agreements have been used to control vegetation but a longer term repair solution is needed.
DESIGNATION:	Scheduled Monument	
CONDITION:	Poor	
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	D (D)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1004785	

Contact: Jenny Marriott 01691 780677

© English Heritage

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site



© English Heritage

SITE NAME:	Pentre Isaf, Oswestry
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1054276

Pentre Isaf is a farm complex with an attractive courtyard of outbuildings. The grade II* stone farmhouse is C17 but hides within it a C15 timber-framed hall. The owner has embarked on a comprehensive programme of repairs.

Contact: Sarah Lewis 0121 625 6886



© English Heritage

SITE NAME:	Pitchford Hall, Pitchford
DESIGNATION:	Listed Building grade I, RPG grade II
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1177907

A large timber framed country house built c1560-70 for Adam Ottley but with an earlier C14 or C15 core. This is an outstanding example of a timber framed building. The owner has completed some works but maintenance of the roof, rainwater goods and infill panels is required. The property is vacant, but discussions have been opened about a maintenance regime and the development of plans for re-use.

Contact: Ross Brazier 0121 625 6884



© English Heritage

SITE NAME:	Nag's Head engine house, Pontesbury
DESIGNATION:	Scheduled Monument
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1018467

An engine house on the Pontesford coalfield which provided coal for the Pontesford lead smelters which served the south Shropshire lead mines. The building is in very poor condition, invasion of the structure by ivy and overhanging trees are an additional threat. The monument has been identified as part of a project in the Stiperstones and Corndon Hill Landscape Partnership funded by the Heritage Lottery Fund. A survey, recording and design of a repair programme has been completed, negotiations are underway with the owner.

Contact: Sarah Lewis 0121 625 6886



© English Heritage

SITE NAME:	Brogyntyn Hall, Brogyntyn Park, Selattyn and Gobowen
DESIGNATION:	Listed Building grade II*, RPG grade II, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1367373

An elegant country house, mainly C18 extended in the C19, most of the interior is of this date. The property stands at the centre of the grade II park with pleasure grounds, a walled garden, lodges, cottages and model farm. Last used as offices the property has been unoccupied for over a decade. Rain water and dry rot are the principal threats. Current ownership does not include the whole of the park. The property is for sale and discussions are taking place with the owner about the future of the building, the potential for alteration and about different development options.

Contact: Sarah Lewis 0121 625 6886



© English Heritage

SITE NAME:	Lord Hill's Column, Abbey Foregate, Shrewsbury
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1271374

A Coade stone statue, made in 13 sections, of Lord Hill of Hawkstone mounted on a giant stone column both taller and wider than Nelson's Column. The monument was erected in 1816 to commemorate Rowland Hill as a premier general in the Napoleonic War who was Wellington's second in command at Waterloo. The statue suffers badly from exposure to the weather, small sections are flaking off and cracks have developed in the structure. Repairs to stabilise the statue for the medium term are currently underway with a friends group now formed and a longer term conservation project planned.

Contact: John Yates 0121 625 6846

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site



© English Heritage

SITE NAME:	Town walls, Shrewsbury
DESIGNATION:	Scheduled Monument, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority, multiple owners
LIST ENTRY NUMBER:	1003710

Medieval town walls C13. Coursed and squared sandstone. The defences are subject to ongoing repair but certain sections are deteriorating. Soft sandstone continues to weather and erode. Some damage from traffic. A Conservation Management Plan is needed.

Contact: Imogen Sambrook 0121 625 6854



© English Heritage

SITE NAME:	Apprentice House of former Ditherington Flax Mill, Spring Gardens, Ditherington, Shrewsbury
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	English Heritage
LIST ENTRY NUMBER:	1254855

Former apprentice house for flaxmill circa 1812, now disused. English Heritage is working in partnership with the Local Authority. Outline planning approval was secured for the whole site in 2010, and this will form the basis of the masterplan and future redevelopment proposals. The Friends group is flourishing.

Contact: John Yates 0121 625 6846



© English Heritage

SITE NAME:	Former Ditherington Flax Mill and attached former malt kiln, flax dressing building and flax warehouse, Spring Gardens, Ditherington, Shrewsbury
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	English Heritage
LIST ENTRY NUMBER:	1270576

Former flax mill, five storeys, built 1797 as first iron frame structure in the world. Converted to maltings in 1897. The flax dressing building, c 1803 and a flax warehouse. English Heritage is working in partnership with the Local Authority. Outline planning approval was secured for the whole site in 2010, and this will form the basis of the masterplan and future redevelopment proposals. A masterplan for the site was approved in 2010. A Heritage Lottery Fund grant has been awarded, and engineering designs are currently being developed. The Friends group is flourishing.

Contact: John Yates 0121 625 6846



© English Heritage

SITE NAME:	Stove House and Dye House at former Ditherington Flax Mill, Spring Gardens, Ditherington, Shrewsbury
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	English Heritage
LIST ENTRY NUMBER:	1270566

Former drying stove house and dye house of flax mill, now disused. These buildings are an early and significant component of the flax mill complex. English Heritage is working in partnership with the Local Authority. Outline planning approval was secured for the whole site in 2010, and this will form the basis of the masterplan and future redevelopment proposals. The Friends group is flourishing.

Contact: John Yates 0121 625 6846



© English Heritage

SITE NAME:	Pell Wall Hall, Newport Road, Sutton upon Tern
DESIGNATION:	Listed Building grade II*, RPG grade II
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1190426

Country house, 1822-28 by Sir John Soane. After decades of neglect, compulsorily purchased by the Local Planning Authority and passed to a trust who repaired building shell and restored structural elements of the original Soane building with English Heritage grant. The property has changed hands several times. There has been some progress on the required repairs.

Contact: John Yates 0121 625 6846

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

- CA Conservation Area
- LB Listed Building
- LPA Local Planning Authority
- NP National Park
- RPG Registered Park and Garden
- SM Scheduled Monument
- UA Unitary Authority
- WHS World Heritage Site



© English Heritage

SITE NAME:	Hawkstone Windmill, Hawkstone Park, Weston-under-Redcastle
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1264219

Late C18 windmill located just outside the registered park at Hawkstone Hall which was designed by William Emes in the mid C18. The windmill sits above the Hawk Lake in the part of the Park which is now a golf course and benefits from extensive views. The building is boarded up, internal machinery and floor structures have largely collapsed though principal floor beams survive. A temporary roof erected in 1996 has saved the building but its condition is deteriorating.

Contact: Jenny Marriott 01691 780677



© English Heritage Archive

SITE NAME:	Red Castle, Hawkstone Park, Weston-under-Redcastle
DESIGNATION:	Scheduled Monument and Listed Buildings - 2 grade II, RPG grade I
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1020850 and 1237180; 1264271

Remains of C12/C13 Medieval castle in a largely restored C18 landscape. Masonry in vulnerable condition and deteriorating. Invasive vegetation needs to be brought under control. A management approach needs to be agreed.

Contact: Jenny Marriott 01691 780677



© English Heritage

SITE NAME:	The Old Rectory, Claypit Street, Whitchurch Urban
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1056008

An elegant Georgian rectory of 1749 which was used as a listening station during World War II. Urgent works were enforced to make roof watertight and arrest structural movement but the service wing remains in very poor condition and property boundaries are an issue. Section 106 contributions have been secured for the repair of the building. The owner is clearing debris from within the building and proposes urgent works while exploring options for reuse.

Contact: Sarah Lewis 0121 625 6886



© English Heritage

SITE NAME:	Cheney Longville Castle, Cheney Longville, Wistanstow
DESIGNATION:	Listed Building grade II*, SM, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1269816

A fortified manor house complex dating from 1677 set around a courtyard. The north wing is in use as a farmhouse and in fair condition but the rest of the buildings around the courtyard are only partially in use and are in a vulnerable condition. Long term plans for a mixed use conversion to holiday accommodation and heritage interpretation have not yet been implemented. Emergency repairs have been carried out with English Heritage grants and roof repairs completed under a Natural England stewardship scheme.

Contact: Jenny Marriott 01691 780677



© English Heritage

SITE NAME:	Hargreaves Farmhouse, Winnington, Wollaston
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1055173

Timber-framed farmhouse dating from early C17 with C19 additions including a stone extension. The property has been unoccupied for over 20 years and is very dilapidated. The roof is holed, many infill panels are missing and parts of the frame have collapsed. The erection of scaffolding has provided support and a temporary roof so that the structure is protected and dry. The property is currently for sale.

Contact: Ross Brazier 0121 625 6884

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
B Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© English Heritage

SITE NAME:	Snailbeach New Smeltnill, Worthen with Shelve
DESIGNATION:	Scheduled Monument and Listed Buildings - 2 grade II
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1017764 and 1307989; 1055031

The monument comprises a smeltnill and slagmill built in 1862 for the Snailbeach Mining Company. The slagmill has been stabilised but standing remains of the smeltnill furnaces are in very poor condition due to invasive uncontrolled vegetation. Extensive vegetation clearance and emergency propping has been carried out under a management agreement.

Contact: Sarah Lewis 0121 625 6886



© English Heritage

SITE NAME:	Tankerville Lead Mine, Pennerley, Worthen with Shelve
DESIGNATION:	Scheduled Monument, 4 LBs, part in CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	E (B)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1014865

C19 lead mine complex comprising engine house, chimney, ore hoppers, crushing and dressing floors. Major features including the engine house and shaft consolidated in 1996 with English Heritage grant aid. Tree and scrub growth has recolonized retaining walls to the dressing floor and reservoir. English Heritage grant has been offered and accepted for the repair of the walls and work should be completed in 2014.

Contact: John Tiernan 0121 625 6839



© English Heritage

SITE NAME:	Candle House, Snailbeach Lead Mine, Worthen with Shelve
DESIGNATION:	Scheduled Monument and Listed Buildings - 10 grade II, LB grade II, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1014866 and 1261135; 1055011; 1055012; 1176609; 1176636; 1176648; 1176660; 1366969; 1367007; 1055013

This building is part of the scheduled site of the Snailbeach lead mine and was where miners collected their candles before going underground. It dates from the early C19 and is constructed from coursed rubble with brick dressings under a Welsh slate roof. The structure is very simple, substantially intact, but with large holes in the roof and in a derelict state. Subject to the owner's agreement, it is hoped that the building may be acquired by the Shropshire Mines Trust and reunited with the other mining structures which have already been restored with grant aid.

Contact: Sarah Lewis 0121 625 6886



© English Heritage

SITE NAME:	Church of St Mark, Chirbury with Brompton
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1366951

This small church was designed by Edward Haycock Junior, built in 1855 and consists of a nave with a west bellcote and north porch and a chancel with a south side vestry. The plain clay tile roofs require re-laying and the rainwater goods repair and realignment. The west gable wall requires assorted remedial works at high level and selected areas of repointing to address defects attributable to the variable quality of the local siltstone and the effects of hard Portland cement based repointing.

Contact: John Tiernan 0121 625 6839

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© English Heritage

SITE NAME:	Heath Chapel, Stoke St Milborough, Heath
DESIGNATION:	Listed Place of Worship grade I, SM
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1383722

This small Norman chapel consists of a nave and lower chancel with broad full height clasping buttresses and lesenes, a continuous mid-height string course, tiny round head windows and a richly decorated south doorway. The church was repaired following the Society for the Protection of Ancient Buildings principles by Basil Stallybrass in 1912 but assorted repairs including the relaying of the chancel roof, the renewal of rainwater goods, the installation of a surface water drainage system and assorted masonry consolidation and repointing works are now all urgently required.

Contact: John Tiernan 0121 625 6839



© English Heritage

SITE NAME:	Church of St John the Baptist, Kenley
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Fair
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1055258

Small single-cell church with attached west tower; mainly of the C12 and C14 with C19 restoration. In a rural location with a few buildings nearby, but on a prominent ridge with commanding views of the adjacent valley. Roof appeared tired with some indications of minor water ingress. Apparent lack of maintenance suggested by high level tree growth at junction between the west tower and the nave.

Contact: John Tiernan 0121 625 6839



© English Heritage

SITE NAME:	Church of St Michael, Munslow
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	B (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1383331

This C12 church has a west tower, nave with a north aisle and south porch and a chancel with a south vestry. This church has an assortment of significant building defects that include roof coverings, masonry walls, rainwater goods and subterranean drainage. A repairs grant offered under the Repair Grants for Places of Worship Scheme has been accepted and work to address most of the above defects is due to start on site this year.

Contact: John Tiernan 0121 625 6839



© English Heritage

SITE NAME:	Church of St John the Baptist, Myndtown
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1054598

This small Medieval church consists of a nave and chancel with a west end bellcote and a timber framed south porch which was reconstructed in 1859. The slated roofs and rainwater goods are in very poor condition and the gable abutment between nave and chancel roof is defective and requires reconstruction. The north side of the church is colonised by uncontrolled vegetation and there is extensive cracking to the interior.

Contact: John Tiernan 0121 625 6839



© English Heritage

SITE NAME:	Abbey Church of the Holy Cross, Abbey Foregate, Shrewsbury
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1246392

The parish church of the Holy Cross was formed by the nave and west tower of the former Benedictine Abbey Church. C17 and C19 additions explain the present configuration and appearance of the church which was constructed in red sandstone and now has assorted defects associated with the variable quality of some of the particular building stones used. Parts of the chancel and transept parapets are in urgent need of repair and /or renewal.

Contact: John Yates 0121 625 6846

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Little Shrawardine motte and bailey castle, Alberbury with Cardeston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019198
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Natural erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677

SITE NAME:	Ringwork 540 metres north of Lane Farm, Alberbury with Cardeston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019831
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677

SITE NAME:	Stanwardine moated site and associated fishpond, Baschurch		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017240
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677

SITE NAME:	The Burgs, Bayston Hill		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003016
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Jenny Marriott 01691 780677

SITE NAME:	Lower Cleeton moat, a moat and fishponds 380 metres south east of Cleeton Court, Bitterley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010496
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Jenny Marriott 01691 780677

SITE NAME:	White Ladies (St Leonard's) Priory, Boscobel		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015290
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Bill Klemperer 0121 625 6847

SITE NAME:	Bowl barrow 450 metres north west of Felton Farm, Bromfield		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007712
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Jenny Marriott 01691 780677

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Roman camp north of Bromfield Farm, Bromfield		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006273
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Mineral extraction/related subsidence	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Castle Tump, a motte castle and causeway, 150 metres west of Teme Bridge, Burford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008392
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Moated site and fishponds 250 metres south west of Middleton Farm, Chirbury with Brompton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019009
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Motte and bailey castle 150 metres north east of Wilmington, Chirbury with Brompton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012864
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Offa's Dyke: section 2/3 mile (1170 metres) long, north from southern boundary of Rownal Covert, Chirbury with Brompton		
DESIGNATION:	Scheduled Monument, part in SM	LIST ENTRY NUMBER:	1003013
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Other not for profit group	CONTACT:	Alison MacDonald 0121 625 6827
SITE NAME:	Offa's Dyke: section one mile 750 yards (2290 metres) from Dudston Covert to a point 300 yards (274 metres) north of Lack Brook - Also in Powys: Wales, Chirbury with Brompton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003797
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison MacDonald 0121 625 6827
SITE NAME:	Offa's Dyke: two sections running 400 yards (370 metres) south of Camlad Stream - Also in Powys: Wales, Chirbury with Brompton		
DESIGNATION:	Scheduled Monument, part in SM	LIST ENTRY NUMBER:	1006259
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison MacDonald 0121 625 6827

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
B Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Castle Pulverbatch motte and bailey castle with outer bailey, 100 metres NNW of Brook Cottage, Church Pulverbatch		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012860
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	Yes
OWNER TYPE:	Unknown	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Motte castle 80 metres north east of Home Farm, Church Stretton		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1008396
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Bowl barrow 390 metres south east of Stanley Cottage, Clunbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016664
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Norton Camp: a large multivallate hillfort, Culmington / Craven Arms		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021073
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	The Mount motte and bailey castle, 120 metres north east of Hill House Farm, Diddlebury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012856
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Moated site and associated ridge and furrow cultivation remains, 145 metres south of St Mary Magdalene's Church, Hadnall		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019650
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Roman villa north east of Cottage Coppice, Harley / Much Wenlock		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002934
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Jenny Marriott 01691 780677

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Motte castle 220 metres north west of Higher Kempley Farm, Willaston, Ightfield		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019656
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Offa's Dyke: section 90 metres south of Brynorgan, Llanfair Waterdine		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020905
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Natural erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison MacDonald 0121 625 6827
SITE NAME:	Offa's Dyke: section 890 metres north west and 320 metres west of Little Selley, Llanfair Waterdine		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020903
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison MacDonald 0121 625 6827
SITE NAME:	Offa's Dyke: section on the western slope of Llanfair Hill, 1.4 kilometres south west of Burfield, Llanfair Waterdine		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020902
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison MacDonald 0121 625 6827
SITE NAME:	Motte and bailey castle 100 metres west of Holy Trinity Church, Lydham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013486
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Nickless moat, Milson		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009552
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Callow Hill Camp: a small multivallate hillfort, Minsterley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019828
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Jenny Marriott 01691 780677

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Roman villa at Linley Hall, More		
DESIGNATION:	Scheduled Monument, part in RPG grade II	LIST ENTRY NUMBER:	1006253
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Offa's Dyke: section 175 metres east of Cefn Bronydd, Newcastle on Clun		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020899
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison MacDonald 0121 625 6827
SITE NAME:	Small enclosed settlement on Fron, 340 metres west of St John's Church, Newcastle on Clun		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021069
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Offa's Dyke: section 400 metres south west of Springhill Farm, Newcastle on Clun / Clun / Llanfair Waterdine		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020901
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alison MacDonald 0121 625 6827
SITE NAME:	Roman villa 150 yards (140 metres) south east of Lea Hall, Pontesbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006246
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Roman camps south west of Stoneyford Cottages, Shifnal		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006249
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Roman fort 300 metres east of Drayton Lodge Farm, Shifnal		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020283
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Uxacona Roman site (see also Telford and Wrekin Unitary Authority), Shifnal / St. Georges and Priorslee / Lilleshall and Donnington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003811
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Roman military site at Rhyn Park, St. Martin's		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003716
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Camp Ring motte and bailey castle, enclosure, fishpond and ridge and furrow 400 metres east of Culmington Farm, Stanton Lacy		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012855
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Medieval fishpond reservoir north east of Haughmond Abbey and south west of the hamlet of Haughton, Uffington / Upton Magna		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002953
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Robury Ring: a small enclosed settlement on Wentnor Prolley Moor, Wentnor		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021072
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Hawcocks Mount ringwork castle 200 metres north east of Hawcocks Farm, Westbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013494
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Upper Barn moat, Wistanstow		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012455
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Bowl barrow 120 metres south west of Dorrington Cottage, Pipe Gate, Woore		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016829
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677

SITE NAME:	Bowl barrow at The Napp, Worthen with Shelve		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017347
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677

SITE NAME:	Moated site at Leigh Hall, Worthen with Shelve		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1019010
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677

SITE NAME:	Snailbeach New Smeltnill, 350 metres north east of Green Acres, Worthen with Shelve		
DESIGNATION:	Scheduled Monument and Listed Buildings - 2 grade II	LIST ENTRY NUMBER:	1017764 and 1307989; 1055031
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886

SITE NAME:	Two bowl barrows 290 metres north of Upper House Farm, Worthen with Shelve		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016666
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677

SITE NAME:	Clee View, Highley		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Colin Richards (LPA) 01743 255662

SITE NAME:	Llanymynech, Llanymynech and Pant		
DESIGNATION:	Conservation Area, 12 LBs, 2 SMs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Low	CONTACT:	Colin Richards (LPA) 01743 255662

STAFFORDSHIRE

CANNOCK CHASE

SITE NAME:	Talbot Street/Lichfield Street, Rugeley / Brereton and Ravenhill		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Angela Grove (LPA) 01543 464517

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site

EAST STAFFORDSHIRE



© English Heritage

SITE NAME:	The Orangery, Blithfield
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1038399

The Orangery is a stone building designed by James 'Athenian' Stuart for Sir William Bagot in circa 1769. It is one of a number of listed buildings and structures at Blithfield Hall. Rainwater penetration is causing the deterioration of stonework and internal plasterwork. An English Heritage grant has been offered for repairs: work is due to start on site in summer 2014.

Contact: John Tiernan 0121 625 6839



© English Heritage

SITE NAME:	Sinai Park, Burton on Trent, Branston
DESIGNATION:	Listed Building grade II*, SM
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1038484

Mid C17 timber framed house, one wing of which was repaired some years ago. The remainder is in very poor condition and continues to deteriorate. It is in critical condition with areas of partial collapse but no agreed plans for its repair.

Contact: Sarah Lewis 0121 625 6886



© English Heritage

SITE NAME:	Gates and gatepiers at Hoar Cross Hall, Maker Lane, Hoar Cross, Yoxall
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1038479

Pair of gates and gatepiers of circa 1700, moved to present site circa 1870. The wrought iron gates are corroding, the wall and piers need repair. Inspection carried out by an English Heritage engineer has informed a brief for survey which may be carried out shortly to inform repairs.

Contact: Imogen Sambrook 0121 625 6854

SITE NAME:	Enclosures and cursus 300 yards (270 metres) south east of Efflinch, Barton-under-Needwood		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006073
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ian George 0121 625 6859

SITE NAME:	Timber circle, hengi-form monument and part of a pit alignment at Catholme, Barton-under-Needwood		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019109
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Mineral extraction/related subsidence	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ian George 0121 625 6859

SITE NAME:	Enclosure 350 yards (320 metres) north of Tivey's House, Dunstall		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006075
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Mineral extraction/related subsidence	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Bowl barrow 330 metres east of Weaver Farm, Wootton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009412
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Circular enclosures 100 yards (90 metres) south west of Bonthorn, Wychnor		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006094
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Clarence Street/Anglesey Road, Burton upon Trent, Anglesey		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Ben Williscroft (LPA) 01283 508624

SITE NAME:	George Street, Burton, Burton upon Trent, Burton		
DESIGNATION:	Conservation Area, 7 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	High	CONTACT:	Ben Williscroft (LPA) 01283 508624

LICHFIELD



© English Heritage

SITE NAME:	Angel Croft Hotel, front railings and gates, Beacon Street, Lichfield
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1187354

A fine three storey hotel, built c1750 in brick with ashlar dressings, the railings and gates are included in listing and are also in poor condition. The building has been empty for some time. There has been water damage to ceilings as a result of break-ins but this has now dried out and the building appears to have stabilised. Permission has been granted for conversion to apartments with an agreement to secure the repair of the gates and railings. Work should start in the summer.

Contact: Alan Taylor 0121 625 6848



© English Heritage

SITE NAME:	Church Tower north of Church of St John, St Johns Hill, Shenstone
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1038830

C13 derelict Church tower with later alterations. No plans for future use at the moment. Local Planning Authority building inspectors have visited and structure considered stable at present. English Heritage architect has visited and advised on removal of ivy. The Local Planning Authority is trying to open constructive discussions with the Parish Council and church to agree a repair scheme.

Contact: John Tiernan 0121 625 6839

SITE NAME:	Site of round barrow near River Tame, Alrewas		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006090
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Air photographic site south west of Elford, Fisherwick		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006100
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Local authority, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Causewayed enclosure, Fradley and Streethay		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002964
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Settlement sites and enclosures 500 yards (460 metres) north east of Sittles Farm, Fradley and Streethay		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006091
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Manor House, Hamstall Ridware		
DESIGNATION:	Scheduled Monument, 3 LBs, CA	LIST ENTRY NUMBER:	1006119
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Fazeley and Bonehill, Fazeley / Drayton Bassett		
DESIGNATION:	Conservation Area, 12 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Debbie Boffin (LPA) 01543 308203

NEWCASTLE-UNDER-LYME



© English Heritage Archive

SITE NAME:	Model farm complex south west of Betley Old Hall, Main Street, Betley
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1188395

Early C19 model farm including a range of cowhouses, a granary, cartshed, stables and watermill. The owner is currently repairing the buildings for agricultural and storage use. Repairs to the granary have been completed. The front range and vaults have been stabilised. Repairs have commenced on bottom yard range.

Contact: Alan Taylor 0121 625 6848



© English Heritage Archive

SITE NAME:	Heighley Castle, Heighley Lane, Madeley
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1011070 and 1353703

Castle remains. Medieval, probably mainly early C13. Only fragments of walling survive due to being partly demolished in the Civil War. Heavily overgrown and masonry eroding. In very poor condition. Management Agreement to be considered with owner for vegetation clearance prior to condition survey and masonry consolidation.

Contact: Jenny Marriott 01691 780677


PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	Gatehouse, walls and bollards to Maer Hall, Maer
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1027834

Late C18 gatehouse, walls and bollards, forming the approach to Maer Hall. The Hall is set in an early C19 park by John Webb. Property is associated with Wedgwood and Darwin families. Condition of gatehouse continues to deteriorate. Repairs to roof, gables and stonework required. Further negotiations are underway regarding repairs.

Contact: Alan Taylor 0121 625 6848

SITE NAME:	Butterton, Newcastle under Lyme, Whitmore	
DESIGNATION:	Conservation Area, 5 LBs	NEW ENTRY?: No
CONDITION:	Very bad	TREND: No significant change
VULNERABILITY:	Medium	CONTACT: Louise Wallace (LPA) 01782 717717

PEAK DISTRICT (NP)



SITE NAME:	Critchlow Monument, Sheen, Staffordshire Moorlands
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1374551

Chest tomb and railing c1853. In poor condition.

Contact: Imogen Sambrook 0121 625 6854

© English Heritage

SITE NAME:	Bowl barrow 450 metres east of Stanshope, Alstonefield, Staffordshire Moorlands	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: 1010798
CONDITION:	Generally satisfactory but with significant localised problems	TREND: Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - localised/limited	NEW ENTRY?: No
OWNER TYPE:	Private	CONTACT: Imogen Sambrook 0121 625 6854

SITE NAME:	Copper mines on Ecton Hill, Wetton, Staffordshire Moorlands	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: 1021175
CONDITION:	Generally satisfactory but with minor localised problems	TREND: Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?: No
OWNER TYPE:	Mixed, multiple owners	CONTACT: Ian George 0121 625 6859

SOUTH STAFFORDSHIRE



SITE NAME:	Stable Court at Four Ashes Hall, Four Ashes, Enville
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1277027

Stable court, incorporating extensive farm outbuilding ranges. Mid to late C18, with C20 alterations. One range has virtually collapsed and roofs are in very bad state. A programme of urgent repairs to main frontage of building was completed in 2006 with English Heritage grant, but the rest of the building remains in very poor condition. An English Heritage architect has visited and discussions on a funding package continue.

Contact: John Tiernan 0121 625 6839

© English Heritage Archive

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	The Conservatory, Hilton Park, Hilton
DESIGNATION:	Listed Building grade I
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Commercial company

Unusual circular domed conservatory, thought to have been a forcing house. Built in the early C19 of brick, wood, metal and glass. Derelict and in very poor condition. Cast iron corroding and splitting. Rear half of timber dome has dropped significantly, and currently propped. Pointing is eroding badly and most of glass missing. An English Heritage grant is supporting ongoing repairs.

© English Heritage

LIST ENTRY NUMBER: 1039176

Contact: John Tiernan 0121 625 6839

SITE NAME:	Roman fort west of Eaton House, Brewood and Coven		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006098
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Site of Pennocrucium, east of Stretton Bridge, Brewood and Coven / Lapley, Stretton and Wheaton Aston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006121
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Two Roman camps near Greensforge, Kinver / Swindon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006080
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Rodbaston Old Hall moated site and fishpond, Penkridge		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011893
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Educational (independent)	CONTACT:	Jenny Marriott 01691 780677

SITE NAME:	Roman camp, Kinvaston, Penkridge / Lapley, Stretton and Wheaton Aston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006104
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Penkridge		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Paul Collins (LPA) 01902 6960000

SITE NAME:	Wombourne		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Paul Collins (LPA) 01902 6960000

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

STAFFORD



© English Heritage

SITE NAME:	Trentham Tower, Sandon Park, Sandon, Sandon and Burston
DESIGNATION:	Listed Building grade II*, RPG grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1189768

Folly tower of c1840 located in centre of the C18 to C19 Upper Park, c700 metres north east of the house. Part of one of the stone towers from Trentham Hall, by Sir Charles Barry, moved to this location after Trentham's demolition in 1910-12. There are structural concerns and general weathering and erosion of the stonework. Repairs will now be funded under a Natural England Stewardship scheme.

Contact: Imogen Sambrook 0121 625 6854



© English Heritage Archive

SITE NAME:	Remains of Trentham Hall, the Grand Entrance and Orangery, Park Drive, Trentham Gardens, Swynnerton
DESIGNATION:	Listed Building grade II*, RPG grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (B)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1190243

The remains of a country house of 1833-42 by Sir Charles Barry and Orangery of 1808, situated in C18/C19 park by Lancelot Brown. The site is being redeveloped in accordance with a masterplan. Emergency repairs have been carried out, the buildings stabilised and the adjacent Italian gardens successfully restored. Repairs to the remains of the hall are pending agreement of a scheme for the adjoining land.

Contact: Alan Taylor 0121 625 6848

SITE NAME:	Moated site in Reynold's Orchard, Eccleshall	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: 1011051
CONDITION:	Generally unsatisfactory with major localised problems	TREND: Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?: No
OWNER TYPE:	Commercial company	CONTACT: Jenny Marriott 01691 780677

SITE NAME:	Bowl barrow north of Hargreaves Wood, Swynnerton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: 1009315
CONDITION:	Unknown	TREND: Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?: No
OWNER TYPE:	Private	CONTACT: Imogen Sambrook 0121 625 6854

SITE NAME:	St George's Hospital	
DESIGNATION:	Conservation Area, 6 LBs	NEW ENTRY?: No
CONDITION:	Very bad	TREND: Deteriorating significantly
VULNERABILITY:	Medium	CONTACT: Penny McKnight (LPA) 01785 619337

SITE NAME:	Trentham, Swynnerton	
DESIGNATION:	Conservation Area, 30 LBs, RPG grade II*	NEW ENTRY?: No
CONDITION:	Very bad	TREND: No significant change
VULNERABILITY:	Medium	CONTACT: Penny McKnight (LPA) 01785 619337

SITE NAME:	Walk Mill, Eccleshall	
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?: No
CONDITION:	Very bad	TREND: Deteriorating significantly
VULNERABILITY:	Medium	CONTACT: Penny McKnight (LPA) 01785 619337

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

STAFFORDSHIRE MOORLANDS



© English Heritage

SITE NAME:	Bidulph Old Hall, Bidulph
DESIGNATION:	Scheduled Monument, part in LB grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1014688

Substantial remains of a mansion constructed in the 1580s for Francis Bidulph. It came under siege by the Parliamentarians in 1643 when the east range was destroyed and the house fired. The tower and rest of the remains are in need of consolidation. Works were partially completed with the aid of an English Heritage grant but have stalled for some years now.

Contact: Sarah Lewis 0121 625 6886



© English Heritage

SITE NAME:	Prospect Tower and attached wing, Knypersley, Bidulph
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1037810

Built in 1828 by John Bateman as a gamekeeper's house and eye-catcher on the Knypersley Hall estate. It is a three storey octagonal structure in red sandstone with side wing and crenellated parapets. The building has been disused for about 25 years and the fabric is gradually deteriorating. The County Council is considering alternative options for reuse but have been challenged by the presence of bats.

Contact: Imogen Sambrook 0121 625 6854



© English Heritage Archive

SITE NAME:	Alton Towers and attached garden walls and gatehouse, Alton Park, Farley
DESIGNATION:	Listed Building grade II*, RPG grade I
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1374685

Country house, walls and gatehouse, c1810, set in early C19 valley gardens. Derelict when listed. Complete condition survey undertaken and emergency work completed. A phased programme of further works and a Conservation Management Plan are being prepared.

Contact: Alan Taylor 0121 625 6848



© English Heritage

SITE NAME:	Sharpecliffe Hall, Ipstones
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1374611

A large country house dated 1673 but restored and enlarged in the C19. It may hide earlier fabric. The owner has been undertaking extensive repairs in recent years but essential roof repairs to the wings are still needed.

Contact: Alan Taylor 0121 625 6848



© English Heritage

SITE NAME:	The Gazebo west of Whitehough, Ipstones
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1374612

An early C18 gazebo in the grounds of the C17 farmhouse at Whitehough. Generally in fair condition following repairs to the roof, a small amount of repair work is now required to the stonework and joinery to complete the restoration.

Contact: Sarah Lewis 0121 625 6886

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	Church of St Chad, A 53, Longsdon
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1037805

Designed by Gerald Horsley and built in 1903, this church consists of a west tower with spire, nave and chancel and was inspired by Norman Shaw's All Saints at Leek. The spire masonry is colonised by saplings and requires re-pointing. The rainwater goods are blocked and ineffective and some of the roof tiles are starting to delaminate and fail. The gullies to the surface water system are also blocked and ineffective.

Contact: John Tiernan 0121 625 6839

© English Heritage

SITE NAME:	Paynsley Hall moated site and outer enclosure, Draycott in the Moors		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1011050
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Dumping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Dieu-la-Cres Abbey (remains of), Leek		
DESIGNATION:	Scheduled Monument, 2 LBs	LIST ENTRY NUMBER:	1006107
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Alton and Farley		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Gill Bayliss (LPA) 01538 395400

SITE NAME:	Cheadle		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Gill Bayliss (LPA) 01538 395400

SITE NAME:	Leek		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Gill Bayliss (LPA) 01538 395400

TAMWORTH



SITE NAME:	The Moat House, Lichfield Street
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1208600

One of Tamworth's oldest and most interesting buildings. The Moat House is Elizabethan in style, built of brick with stone details; the interior features include a fine staircase and an elaborate plaster ceiling to the first floor gallery. The ground floor is currently used as a public house and restaurant. The roof is leaking and damaging the plaster ceiling. The Council has recently given grant aid to help stabilise the ceiling but repairs are still needed.

Contact: Alan Taylor 0121 625 6848

© Tamworth Borough Council

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© English Heritage

SITE NAME:	Deanery wall, Lower Gungate, Tamworth
DESIGNATION:	Scheduled Monument and Listed Buildings - 2 grade II, 3 LBs, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Unknown
LIST ENTRY NUMBER:	1006059 and 1197033; 1207833

A C14 masonry wall which was part of St Edith's Deanery. An English Heritage engineer has inspected the three surviving sections of wall, parts of which are in urgent need of maintenance and repair. The removal of plant growth, pointing and resetting of stones to wall tops are all required. As a boundary wall, the ownership is uncertain, and liability for repair unclear. Investigation is necessary.

Contact: Imogen Sambrook 0121 625 6854

SITE NAME:	Saxon defences	
DESIGNATION:	Scheduled Monument, LB grade II, part in CA	LIST ENTRY NUMBER: 1006088
CONDITION:	Unknown	TREND: Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?: No
OWNER TYPE:	Local authority	CONTACT: Imogen Sambrook 0121 625 6854

STOKE-ON-TRENT, CITY OF (UA)



© English Heritage

SITE NAME:	Former Wedgwood Institute (Public Library), Queen Street, Burslem
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1195840

Art school and library built 1869. In brick and terracotta with richly ornamented facade. Building now closed and some emergency repairs carried out. Proposals for the future use of the building are being finalised and the first phase of repair works to the external fabric are planned to commence towards the end of 2014.

Contact: John Tiernan 0121 625 6839



© English Heritage

SITE NAME:	Bethesda Methodist Chapel, Albion Street, Hanley
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1195821

Former Methodist chapel, C19 with intact interiors known as "the Cathedral of the Potteries". The Historic Chapels Trust have completed external repairs with the help of grants from English Heritage and the Heritage Lottery Fund. A final phase of work to allow the re-use of the building is in development.

Contact: Alan Taylor 0121 625 6848



© English Heritage

SITE NAME:	Bottle oven and factory, Price and Kensington Teapot Works, Newcastle Street, Longport
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1290799

An early C19 pottery complex, the bottle oven has been repaired. Only one range is occupied. A fire in the three storey range has resulted in the demolition of walls above the second floor and the removal of the roof structure. Theft of slates and tiles from the roofs of many of the other buildings means that the complex is exposed and highly vulnerable. Urgent works are required to stabilise the buildings while a new use is sought.

Contact: Sarah Lewis 0121 625 6886

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© English Heritage

SITE NAME:	Chatterley Whitfield Colliery, Biddulph Road, Stoke-on-Trent
DESIGNATION:	Scheduled Monument, 5 LBs
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1015947

Large redundant C19/C20 colliery in need of major repair and regeneration. Includes 15 scheduled structures and 5 listed buildings. Heritage-based regeneration programme started based on masterplan. Long-term solution still to be agreed, but progress with re-use of buildings and reclamation works has been slow. Discussions on private sector engagement and longer term proposals ongoing.

Contact: Bill Klemperer 0121 625 6847



© English Heritage

SITE NAME:	Pithead baths and canteen, Biddulph Road, Stoke-on-Trent
DESIGNATION:	Listed Building grade II*, SM
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1260223

Opened in the 1860s, in 1937, Chatterley Whitfield became the first mine in Britain to draw more than a million tons of coal in a year. The pithead baths and canteen were erected at this time and are of special interest as an example of large scale provision for miners in the early C20. On the closure of the mine the buildings were used to accommodate a museum. The whole colliery site is now vacant and these buildings are in very poor condition.

Contact: Bill Klemperer 0121 625 6847



© English Heritage

SITE NAME:	Hulton Abbey, Leek Road, Stoke-on-Trent
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1021284

The remains of Hulton Abbey 1223 comprising transepts and chancel at east end of church which survive as stub walls. The site is owned by the Council and managed as a public amenity space. Below ground remains are not at risk but the hard capped wall tops are vulnerable to weathering and stone decay and require repair.

Contact: Imogen Sambrook 0121 625 6854



© English Heritage

SITE NAME:	Mausoleum, Stone Road, Trentham
DESIGNATION:	Listed Building grade I
CONDITION:	Fair
OCCUPANCY:	N/A
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1210451

Mausoleum for the Dukes of Sutherland c1808 set opposite one of the entrances to Trentham Park. A package of urgent roof repairs was carried out with funding from English Heritage and the Local Authority. Further repairs to doors and the rear window have also been completed and the Council regularly repair the doors when vandalised. The fabric is now sound, but the building remains at risk until responsibility for future upkeep is clearly established.

Contact: Sarah Lewis 0121 625 6886



© English Heritage

SITE NAME:	Church of St John the Baptist, Cross Hill, Burslem
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1291065

This Medieval church was largely rebuilt in 1717 but retains its Medieval tower. Non-breathable paint on the nave is trapping moisture in brickwork, leading to significant internal damp problems and deterioration of outer brick face. Dry rot to timber of apse stained glass windows has spread into walls and inappropriate use of cement tiles on hipped roof is leading to structural problems. The building has multiple fabric defects. This church has been the victim of heritage crime.

Contact: John Tiernan 0121 625 6839

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© English Heritage

SITE NAME:	Roman Catholic Church of St Joseph, Hall Street, Burslem
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1297960

This is a large brick-built, Italianate style church built in 1925 to the designs of the Architect JS Brocklesbury. It has a finely decorated interior. Recent grant-aided repairs to the sanctuary and ambulatory roofs have addressed issues relating to drainage and differential settlement but the nave roof and its asphalt lined eaves gutters are time expired and require renewal. Extensive repointing of the nave clerestory and buttresses is also urgently required to prevent continued water ingress and further damage to the structure, interior decorations and fixtures.

Contact: John Tiernan 0121 625 6839



© English Heritage

SITE NAME:	Church of St John the Evangelist, High Street, Goldenhill
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1220492

Church built in 1841 by Stanley of Shelton, a local architect, in the Byzantine Romanesque style. Blocked or defective rainwater goods in several locations have caused damage to the internal finishes and there are significant areas of rising damp. The nave roof has minor defects. The church has suffered from heritage crime. The external masonry is slowly deteriorating: the latest Quinquennial Inspection report makes recommendations for a steeplejack inspection of both the tower and spire.

Contact: John Tiernan 0121 625 6839



© English Heritage

SITE NAME:	All Saints Church, Leek Road, Hanley
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1245925

All Saints is an Arts and Crafts Gothic church designed by Gerald Horsley in 1910. Built with red brick buttressed walls with sandstone dressings and steeply pitched roofs with both plain clay and replacement concrete tiles. Failed abutment flashings at the east end of the church and defective rainwater goods threaten the integrity and viability of this largely unaltered building.

Contact: John Tiernan 0121 625 6839

SITE NAME:	Caldon Canal, Stoke-on-Trent	NEW ENTRY?:	No
DESIGNATION:	Conservation Area	TREND:	Improving
CONDITION:	Very bad	CONTACT:	Jane Corfield (LPA) 01782 236680
VULNERABILITY:	Medium		

SITE NAME:	Longton Town Centre, Longton	NEW ENTRY?:	No
DESIGNATION:	Conservation Area	TREND:	Improving
CONDITION:	Very bad	CONTACT:	Jane Corfield (LPA) 01782 236680
VULNERABILITY:	Medium		

SITE NAME:	Newcastle Street, Middleport	NEW ENTRY?:	No
DESIGNATION:	Conservation Area	TREND:	No significant change
CONDITION:	Poor	CONTACT:	Jane Corfield (LPA) 01782 236680
VULNERABILITY:	High		

SITE NAME:	Stoke Town, Stoke	NEW ENTRY?:	No
DESIGNATION:	Conservation Area	TREND:	No significant change
CONDITION:	Very bad	CONTACT:	Jane Corfield (LPA) 01782 236680
VULNERABILITY:	High		

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site

SITE NAME:	Trent & Mersey Canal, Stoke-on-Trent		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Jane Corfield (LPA) 01782 236680

TELFORD AND WREKIN (UA)

© English Heritage

SITE NAME:	Bedlam Furnaces, The Gorge
DESIGNATION:	Scheduled Monument, LB grade II*, CA, WHS
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Local authority, multiple owners
LIST ENTRY NUMBER:	1006234

Bedlam Furnace in the Ironbridge Gorge was built in the 1750s and remained active into the C19. It is the likely source of the cast members used in the nearby world famous Ironbridge. Exposure to the elements has led to water damage and the failure of repairs undertaken in the late 1990s. Consolidation and a more permanent solution for the protection of the monument are now urgently needed. The Ironbridge Gorge Museum Trust, the Council and English Heritage are discussing a way forward.

Contact: Bill Klemperer 0121 625 6847



© English Heritage Archive

SITE NAME:	Charlton Castle, Wrockwardine
DESIGNATION:	Scheduled Monument
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1019649

A Medieval moated site which is very overgrown with several uprooted trees damaging the earthworks. There are some elements of standing masonry exposed. The site needs an assessment of condition and the development of an appropriate management regime. There is potential to fund this through a management agreement.

Contact: Jenny Marriott 01691 780677



© Stainburn Taylor architects

SITE NAME:	Church of St Mary the Virgin, Salthouse Road, Jackfield
DESIGNATION:	Listed Place of Worship grade II, CA, WHS
CONDITION:	Poor
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1038241

This church was designed by A W Blomfield and built in 1863. It consists of an aisle-less nave, pseudo transepts, a chancel and a north east tower with an open bell stage, all constructed in polychrome brickwork with steeply pitched tiled roofs. Defective roof coverings, rainwater goods and corroded ferrous metal within the bell stage structure are the principal items of construction that require repair or renewal. A Repair Grant for Places of Worship was offered in 2011 and accepted: work has now started on site and is due to be completed in 2014.

Contact: John Tiernan 0121 625 6839



© English Heritage

SITE NAME:	Church of St Peter, Church Road, Oakengates
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1033297

The church of St Peter was designed by Francis Halley of Shifnal and built in 1825-7 to replace a C12 chapel: it consisted of the present nave and west tower to which the chancel was added in 1903. The church is constructed in brindle brickwork with stone dressings and has slate covered roofs. Concealed ferrous metal dowels have disrupted the masonry to the tower bell lights which has resulted in sections of masonry shearing off. The vestry has settled and rotated away from the chancel wall, all of the roofs require re-laying and the rainwater goods overhauling and repairing and/or renewing.

Contact: John Tiernan 0121 625 6839

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© English Heritage

SITE NAME:	Church of St Peter, Wrockwardine
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1030939

This C12 cruciform church has a nave and chancel, transepts and a crossing tower with later Medieval chapels added to the north and south sides of the chancel. Although much altered with prominent structural reinforcement in the form of angle buttresses to the tower and by subsequent C19 and C20 restoration and repair schemes, assorted works are now urgently required to address time-expired plain clay tiled roof coverings, defective rainwater goods and assorted high level masonry repairs.

Contact: John Tiernan 0121 625 6839

SITE NAME:	Enclosed Iron Age farmstead immediately adjacent to The Croft, Pave Lane, Chetwynd Aston and Woodcote		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020275
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Jenny Marriott 01691 780677

SITE NAME:	Roman camp on Red Hill, Lilleshall and Donnington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006269
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677

SITE NAME:	St Leonard's Priory immediately adjacent to the Church of St Mary and St Leonard, Wombridge, Oakengates		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020661
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Religious organisation	CONTACT:	Bill Klemperer 0121 625 6847

SITE NAME:	Canal aqueduct over River Tern, Rodington		
DESIGNATION:	Scheduled Monument, LB grade I	LIST ENTRY NUMBER:	1006275
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677

SITE NAME:	Uxacona Roman site (See also Shropshire Unitary Authority), Shifnal / St. Georges and Priorslee / Lilleshall and Donnington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006272
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Bill Klemperer 0121 625 6847

SITE NAME:	Site revealed by aerial photography north of Castle Farm, St. Georges and Priorslee		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006274
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Jenny Marriott 01691 780677

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Churchyard of St James's Church, Stirchley and Brookside		
DESIGNATION:	Scheduled Monument, LB grade I	LIST ENTRY NUMBER:	1020852
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Jenny Marriott 01691 780677

SITE NAME:	Moated site and a fishpond 160 metres and 280 metres south of The Farm, Charlton, Wrockwardine		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019649
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Jenny Marriott 01691 780677

WARWICKSHIRE

NORTH WARWICKSHIRE




© English Heritage

SITE NAME:	Beech House, 19 Market Street, Atherstone
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1185175

A fine town house in the Queen Anne style dated 1708. The interiors are largely unaltered and most of the original features are intact. The property has been vacant for several years and is slowly decaying. Discussions are ongoing with the owner and the Local Planning Authority to find a solution for the building, which is on the market to test whether or not there is a need for enabling development.

Contact: Nick Molyneux 0121 625 6857



© English Heritage

SITE NAME:	Grendon Bridge, Grendon / Polesworth
DESIGNATION:	Scheduled Monument and Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1005756 and 1186247

Stone bridge, probably C15 constructed in sandstone. Now in poor condition with parts of the parapet missing. A condition survey is needed to assess the scale of repairs. Discussions are ongoing with the owners about a possible management agreement and grant aid.

Contact: Imogen Sambrook 0121 625 6854



© English Heritage

SITE NAME:	Hartshill Castle, Castle Road, Hartshill
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1011197 and 1034748

C13 castle ruins. Steady decay of surviving masonry due to erosion, structural problems and vandalism. The owner has set up a trust to look after the castle. Vegetation clearance and emergency repairs were carried out some time ago. Discussions are ongoing with the owner for a condition survey prior to masonry repairs.

Contact: Jenny Marriott 01691 780677

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© English Heritage

SITE NAME:	Kingsbury Hall, Kingsbury
DESIGNATION:	Scheduled Monument and Listed Buildings - 1 grade II*; 1 grade II, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1019978 and 1116550; 1034721

A manor house of c1500 with late C16 and C18 rebuilding and early C19 wing. A scheme for the residential conversion of the building has commenced. Final repairs and reuse have yet to be achieved.

Contact: Ian George 0121 625 6859



© English Heritage Archive

SITE NAME:	Maxstoke Priory, Church Road, Maxstoke
DESIGNATION:	Scheduled Monument and Listed Buildings - 6 grade II*, 2 LBs
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private, multiple owners
LIST ENTRY NUMBER:	1011195 and 1034822; 1034823; 1365129; 1034821; 1116038; 1320105

Substantial remains of an early C14 Augustinian monastery including infirmary, precinct walls, outer gatehouse with attached barn and farmhouse. The buildings are steadily decaying, the precinct wall is in very poor condition and the infirmary structure is propped. Natural England will fund some repairs under a Higher Level Stewardship scheme.

Contact: Imogen Sambrook 0121 625 6854



© English Heritage

SITE NAME:	Stables range north east of Middleton Hall, Middleton
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1365197

Originally stables and lodging block c1570. Timber-framed with brick infill panels. Consists of four bay main range with two bay cross wing at north end and two storey gabled porch to left of centre. Courtyard of farm buildings to rear. Structure in need of urgent stabilisation. The building is currently vacant but a condition survey has been undertaken.

Contact: Nick Molyneux 0121 625 6857



© English Heritage

SITE NAME:	Moat, footbridge and gatepiers to Shustoke Hall Farmhouse, Moat House Lane, Shustoke
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (E)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1226189

Homestead moat, footbridge and gate piers c1686, with late C18 service wing which is in poor condition. Substantial sections of overgrown walls and buttresses were previously leaning outwards and required rebuilding. Much of this work has been carried out over the last two years with the brick upper parapet to the south arm awaiting rebuilding (hopefully to be addressed in the 2015/16 financial year). Significant progress has been made since 2013 with repointing and clearance of vegetation, but further work is needed to remove the site from the Register.

Contact: Imogen Sambrook 0121 625 6854



© English Heritage

SITE NAME:	Alvecote priory and dovecote, Shuttington
DESIGNATION:	Scheduled Monument, 2 LBs
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Local authority, multiple owners
LIST ENTRY NUMBER:	1020623

The listed and scheduled remains of a C12 Benedictine Monastery; the primary structure on site represents the C14 remodelling of the building and suffers from vandalism, natural deterioration, and nighthawking. An associated Medieval dovecote is also affected by plant growth and issues with dewatering. The local authority is working with English Heritage to repair damage and address other issues over the coming months.

Contact: Imogen Sambrook 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Double moated site 60 metres east of Baxterley church, Baxterley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014683
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Oldbury Camp univallate hillfort, Hartshill		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018855
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Roman Camp, Mancetter		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1005736
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Manduesedum Roman villa and settlement with associated industrial complex, Mancetter / Witherley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017585
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Merevale Abbey, a Cistercian monastery, associated water control features and industrial remains, Merevale		
DESIGNATION:	Scheduled Monument, 6 LBs, part in RPG grade II*	LIST ENTRY NUMBER:	1014682
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Jenny Marriott 01691 780677

SITE NAME:	Alvecote priory and dovecote, Shuttington		
DESIGNATION:	Scheduled Monument, 2 LBs	LIST ENTRY NUMBER:	1020623
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	Yes
OWNER TYPE:	Local authority	CONTACT:	Imogen Sambrook 0121 625 6854

NUNEATON AND BEDWORTH



© English Heritage

SITE NAME:	Park Farmhouse, Arbury Park, Nuneaton
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

LIST ENTRY NUMBER: 1365048

Late C15 farmhouse with C16 and C17 alterations, to the north west of Arbury Park. In a very bad condition. Following a building survey, works were carried out to support and protect the structure while schemes and options for future use were considered and discussed by the Estate with English Heritage. Temporary measures have subsequently begun to fail and the Estate is now looking to undertake further urgent action to protect the building, particularly its vulnerable timber frame, from further deterioration.

Contact: Imogen Sambrook 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© English Heritage

SITE NAME:	The Tea House, Arbury Park, Nuneaton
DESIGNATION:	Listed Building grade II*, RPG grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1299615

Mid C18 summerhouse located c500 metres east north east of Arbury Hall. The Tea House is situated on the north east shore of a small lake on the eastern edge of the C18 park. In a very bad state of repair (the roof has collapsed), and continues to deteriorate. Action needed urgently to halt decay and save what is left of the building. There are currently no plans to repair the structure.

Contact: Imogen Sambrook 0121 625 6854

RUGBY



© English Heritage

SITE NAME:	Church of St John the Baptist, The Crescent, Brinklow
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1034957

This sandstone church with its prominent tower has Medieval origins and is characterised by its Perpendicular windows. The roof has some tiles dislodged and the overall condition of the nave's roof is poor especially on the south side, where the stonework at high level is particularly poor. Previous cementitious repairs are increasing the stone erosion. The gutters are poor causing internal problems at high level. There is evidence of damp plaster at high level, some has fallen off.

Contact: Cristina Gardiner 0121 625 6850

SITE NAME:	Brandon Castle, Brandon and Bretford	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER: 1011371
CONDITION:	Generally unsatisfactory with major localised problems	TREND: Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?: No
OWNER TYPE:	Commercial company	CONTACT: Imogen Sambrook 0121 625 6854

SITE NAME:	Barrow cemetery 400 metres north east of Bretford, Brandon and Bretford / King's Newnham	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: 1005722
CONDITION:	Unknown	TREND: Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?: No
OWNER TYPE:	Private, multiple owners	CONTACT: Imogen Sambrook 0121 625 6854

SITE NAME:	Prehistoric pit alignment and associated features on Lawford Heath, adjacent to the northernmost Blue Boar Farm, Church Lawford / Thurlaston	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: 1020937
CONDITION:	Unknown	TREND: Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?: No
OWNER TYPE:	Private	CONTACT: Imogen Sambrook 0121 625 6854

SITE NAME:	Bowl barrow 470 metres south west of Coton House, Churchover	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: 1016883
CONDITION:	Generally unsatisfactory with major localised problems	TREND: Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?: No
OWNER TYPE:	Private	CONTACT: Imogen Sambrook 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Tripontium Roman Station, Churchover		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005759
CONDITION:	Unknown	TREND:	Declining
PRINCIPAL VULNERABILITY:	Metal detecting - unlicensed	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Prehistoric circular earthworks, King's Newnham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005717
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Bowl barrow on Lammas Hill, Wolston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016885
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Bowl barrow 490 metres north west of Abbey Farm, Wolvey		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016845
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Bowl barrow 900 metres north of Copston Farm, Wolvey		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016846
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854



© English Heritage

SITE NAME:	Ryton House, Ryton-on-Dunsmore	Small Regency landscape surrounding the shell of grade II listed Regency villa. Late C20 extensions to villa extend over gardens. The boundary belt, historic drive, shrubberies and lakes badly neglected. Setting compromised by roads and residential development. Future uncertain.
DESIGNATION:	Registered Park and Garden grade II, LB grade II	
CONDITION:	Generally unsatisfactory with major localised problems	
VULNERABILITY:	High	
TREND:	Declining	
NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	
LIST ENTRY NUMBER:	1001343	Contact: Kim Auston 0117 975 0696

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

STRATFORD-ON-AVON



© English Heritage

SITE NAME:	Bidford Bridge, Bidford-on-Avon
DESIGNATION:	Scheduled Monument, LB grade I
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1005766

An early C15 bridge over the river Avon thought to have been built by the monks of Bordesley Abbey. Constructed from limestone, it has been repeatedly repaired over the centuries. The bridge is vulnerable to vehicle damage. Inappropriate historic repairs and stone erosion are problems.

Contact: Neil Rimmington 0121 625 6856



© English Heritage

SITE NAME:	The Old Rectory Farmhouse, Friars Lane, Lower Brailes, Brailes
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1024377

Rectory of late C16 with earlier origins. A support scaffolding and temporary roof were grant aided by English Heritage more than 10 years ago but the structure has continued to deteriorate. The property has been empty for some years and in a serious state. A new owner has commenced repairs but there are issues with unauthorised works, these are being dealt with by the local planning authority.

Contact: Nick Molyneux 0121 625 6857



© English Heritage

SITE NAME:	St Nicholas' Church, Ettington Park, Ettington
DESIGNATION:	Scheduled Monument, LB grade I
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1005744

The ruined chapel of St Nicholas is the family mausoleum of the Shirley family. It has suffered from natural erosion and other threats including birds nesting in the tower, structural decay of standing masonry and other issues associated with rainwater goods and cementitious repairs. The owners are in discussions with English Heritage about repairs and management options.

Contact: Imogen Sambrook 0121 625 6854



© English Heritage

SITE NAME:	Toll House, Clopton Bridge, Stratford-upon-Avon
DESIGNATION:	Listed Building grade I, SM
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1204167

Former toll house built in 1814 on the C15 Clopton Bridge in the centre of Stratford-upon-Avon. The building has been disused for many years, the roof and stonework is in poor condition. Some urgent stonework repairs have been carried out but further works are required. The Stratford Historic Buildings Trust has commissioned a feasibility study funded by the Architectural Heritage Fund and is in negotiation with the Council which owns the building to find a new use and implement repairs.

Contact: Cristina Gardiner 0121 625 6850



© English Heritage

SITE NAME:	Umberslade Baptist Chapel, Spring Lane, Tanworth-in-Arden
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1382428

Exceptionally fine Nonconformist estate chapel of 1877 by George Ingall for GF Muntz of Umberslade Park. The chapel has not been used as a place of worship for many years and has been acquired by the Historic Chapels Trust who plan to restore it for educational/community uses and occasional services. Main phase of repairs to external fabric completed, but funding for restoration of the interior still required.

Contact: Sarah Lewis 0121 625 6886

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© English Heritage

SITE NAME:	Packhorse bridge, Todenham / Tidmington
DESIGNATION:	Scheduled Monument, 2 LBs
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1005746

A C16 pack horse bridge of dressed limestone, without kerb or parapet. The bridge was rebuilt in the C18. It suffers from moderate stone decay. English Heritage is now working closely with Natural England and the owner to address the structural decay of this heritage asset. A structural survey has been carried out on the bridge and a brief has gone out to tender for its repair.

Contact: Imogen Sambrook 0121 625 6854



© English Heritage

SITE NAME:	Church of St Botolph, Church Lane, Farnborough
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1299775

The church is set close to Farnborough Hall. Lack of maintenance means that it is in poor condition: the roof shows slipped slates, the gutters have vegetation growing in them and some have become detached. Stonework at high levels also in bad condition.

Contact: Cristina Gardiner 0121 625 6850



© English Heritage

SITE NAME:	Church of St Giles, Church Lane, Gaydon
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1184784

Small ironstone ashlar church with moulded cornices, designed by Squirrill of Leamington and dating from 1852. The church is modest in size but in poor condition externally due to the friability of the Horton Stone. Some parts of the church appear in poor structural condition especially on the east gable. There are large cracks in the masonry and the one on the south west corner is particularly bad. The gutters are also poor.

Contact: Cristina Gardiner 0121 625 6850

SITE NAME:	Oversley Castle, Alcester	LIST ENTRY NUMBER:	1005750
DESIGNATION:	Scheduled Monument	TREND:	Unknown
CONDITION:	Unknown	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Arable ploughing	CONTACT:	Imogen Sambrook 0121 625 6854
OWNER TYPE:	Commercial company		

SITE NAME:	Beaudesert Castle: motte and bailey castle and two fishponds, Beaudesert	LIST ENTRY NUMBER:	1012703
DESIGNATION:	Scheduled Monument	TREND:	Declining
CONDITION:	Generally unsatisfactory with major localised problems	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	CONTACT:	Imogen Sambrook 0121 625 6854
OWNER TYPE:	Commercial company		

SITE NAME:	Castle Hill Motte, Brailes	LIST ENTRY NUMBER:	1018858
DESIGNATION:	Scheduled Monument	TREND:	Declining
CONDITION:	Generally satisfactory but with significant localised problems	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	CONTACT:	Imogen Sambrook 0121 625 6854
OWNER TYPE:	Commercial company		

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Double ditched enclosure east of Thornton Farm, Ettington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002990
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Enclosures north of Old Pasture Farm, Hampton Lucy		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005714
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Site of building and enclosure 460 metres east of Hatton Rock Farm, Hampton Lucy		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005741
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Medieval settlement remains at Hodnell Manor, Hodnell and Wills Pastures		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020421
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Dumping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Rectangular Earthwork on Nebsworth, Ilmington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005734
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Multivallate hillfort on Meon Hill, Quinton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011372
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Nadbury Camp, Ratley and Upton / Warmington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003724
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Enclosures 1200 metres north of Salford Priors, Salford Priors		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005721
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Romano-British cemetery and settlement site, Stretton-on-Fosse		
DESIGNATION:	Scheduled Monument, 2 LBs	LIST ENTRY NUMBER:	1003725
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Studley Old Castle: a motte castle, Studley		
DESIGNATION:	Scheduled Monument, LB grade II*	LIST ENTRY NUMBER:	1013161
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Gardening	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Settlement site west of Welford Weir, Temple Grafton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005719
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Enclosures 550 metres east of King's Mead, Wellesbourne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005716
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Lower Shuckburgh		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Clare Eynon (LPA) 01789 260326
SITE NAME:	Southam		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Clare Eynon (LPA) 01789 260326

WARWICK



© English Heritage Archive

SITE NAME:	Remains of Old Castle Bridge, Mill Street, Warwick
DESIGNATION:	Scheduled Monument and Listed Building grade II*, RPG grade I
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1005772 and 1035499

Late Medieval bridge. Ownership of remains is split three ways. Earlier proposals for stabilisation were very costly and beyond available resources. It has been proposed that ownership should be transferred to a trust who would co-ordinate restoration and funding package but this has not progressed. A fresh survey of condition and repair costs has been suggested to move things forward.

Contact: Ian George 0121 625 6859

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© English Heritage Archive

SITE NAME:	Masters House, Warwick
DESIGNATION:	Listed Building grade II*, SM
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1364850

The Leper Hospital of St Michael was founded in C12; the Master's House survives and is a timber-framed building of C15 date built upon C12 foundations. The timber frame and roof are in very poor condition and there are general structural problems throughout the building which has been propped to prevent collapse and covered in tarpaulins. An options appraisal was carried out by the Local Authority with English Heritage grant and a project is in development. The Local Authority is currently engaged in negotiating the purchase of the site.

Contact: John Tiernan 0121 625 6839



© English Heritage

SITE NAME:	Church of St Michael, Rugby Road, Weston under Wetherley
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Very bad
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1325524

Parish church in red sandstone ashlar situated in an elevated position with evidence of a C12 church in the north and south walls of the chancel. The red sandstone stonework is in extremely poor condition at all levels with delamination, open joints and hollow sections, erosion, cracking and inappropriate repairs. Some structural cracks are present. Deformation on the south elevation appears stable.

Contact: Cristina Gardiner 0121 625 6850

SITE NAME:	Roman settlement at Glasshouse Wood, Ashow / Kenilworth		
DESIGNATION:	Scheduled Monument, part in RPG grade II*	LIST ENTRY NUMBER:	1005723
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Digging	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Circular ditches enclosures south west of Wiggerland Wood Farm, Bishop's Tachbrook		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003740
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Guy's Cave hermitage and other rock cut chambers at Guy's Cliffe, Leek Wootton and Guy's Cliffe		
DESIGNATION:	Scheduled Monument, LB grade II, RPG grade II	LIST ENTRY NUMBER:	1019129
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Religious organisation	CONTACT:	Ian George 0121 625 6859

SITE NAME:	Wedgnock Park pale, dam, two watermill sites, bridge and hollow way 200 metres north east of Goodrest Farm, Leek Wootton and Guy's Cliffe		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013159
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Enclosures 410 metres north east of Sherbourne parish church, Sherbourne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005711
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Warwick Castle (uninhabited parts), Warwick		
DESIGNATION:	Scheduled Monument, part in RPG grade I	LIST ENTRY NUMBER:	1005757
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ian George 0121 625 6859

SITE NAME:	Enclosures 550 metres, SSW of Manor House Farm, Wasperton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005713
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Mineral extraction/related subsidence	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Enclosures and drove road 90 metres south of Manor House Farm, Wasperton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005712
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Enclosures and pits north of Hail End Bridge, Wasperton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005715
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Mineral extraction/related subsidence	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854



© English Heritage

SITE NAME:	Stoneleigh Abbey, Stoneleigh / Ashow
DESIGNATION:	Registered Park and Garden grade II*, 30 LBs, 2 SMs
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	High
TREND:	Improving
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1000377

Complex multi phase landscape, incorporating Medieval deer park and work by Repton, Nesfield and Percy Cane. Deer park now a golf course. Business park and residential enclaves built within historic landscape. Also contains Royal Agricultural Society's permanent showground. Impressive programme of restoration of cascades, bridges and other water features through Natural England's Environmental Stewardship scheme which is complete, with a further phase planned. Other parts of the historic estate remain vulnerable eg route of High Speed 2 (HS2) railway.

Contact: Kim Auston 0117 975 0696

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© English Heritage

SITE NAME:	Guy's Cliffe, Warwick / Leek Wootton and Guy's Cliffe / Old Milverton
DESIGNATION:	Registered Park and Garden grade II, 9 LBs, SM
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Stable
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1001602

Picturesque landscape either side of the River Avon. Main house is a ruinous shell. Chapel now a Masonic temple. Derelict gardens periodically cleared by volunteers. Most of park ploughed and majority of parkland trees lost. Urban expansion (of Warwick), affecting the park, has been mooted although in the latest iteration of the Warwick Local Plan the threat appears to have been removed.

Contact: Kim Auston 0117 975 0696

WEST MIDLANDS

BIRMINGHAM



© English Heritage

SITE NAME:	British Rail goods office (Curzon Street Station), Birmingham
DESIGNATION:	Listed Building grade I
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1343086

Original terminus of the London to Birmingham railway by Philip Hardwick. Built in 1838 in the Ionic style. The building is owned by the City Council and has been vacant for over seven years. Repairs to the roof have been undertaken and the building is now watertight. Potential for redevelopment in association with HS2 exists; the building is included in the Birmingham Curzon HS2 Masterplan, in the 'Visit' quarter, but no use has been identified and the building may lie vacant until 2026 when new station is due to open.

Contact: Katriona Byrne 0121 625 6858



© English Heritage

SITE NAME:	Grand Hotel, Colmore Row, Birmingham
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1391246

A large Victorian hotel dating from 1875. The Grand Hotel is a landmark building overlooking Cathedral Square with an important suite of public rooms. The main elevations are in very bad condition due to the poor quality of the original stone. Repairs to the stonework are well under way with the help of an English Heritage grant. Permissions for re-use as a hotel with shops and offices have been granted.

Contact: Sarah Lewis 0121 625 6886



© English Heritage

SITE NAME:	Methodist Central Hall, Corporation Street, Birmingham
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (D)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1075607

A substantial building constructed in 1903/4 by E and JA Harper in red brick and terracotta. The ground floor is in various retail uses, some vacant, the upper floors are vacant. Planning approval and Listed Building Consent was granted for conversion to mixed office/residential use, but was not implemented and has expired. Birmingham City Council is in contact with the owner regarding unauthorised works.

Contact: Katriona Byrne 0121 625 6858

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© English Heritage

SITE NAME:	The Red Lion Public House, Soho Road, Birmingham
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (F)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1276278

Public house, 1901-2 by James & Lister Lea for the Holt Brewery Company. Built of red brick with terracotta facade, the building is of unusual richness and completeness with interior detailing comparable with best surviving examples nationally. Leaking roofs have caused significant problems; pigeons occupy upper floors. A new owner has undertaken urgent works and has gained Listed Building Consent for re-use as a public house restaurant. Building is for sale/lease. Condition deteriorating.

Contact: Katriona Byrne 0121 625 6858



© English Heritage

SITE NAME:	Perrott's Folly, Waterworks Road, Edgbaston
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Other not for profit group
LIST ENTRY NUMBER:	1076123

Built in 1758 by John Perrott as folly adjacent to his house (long demolished). Six storey structure with circular stair tower attached. Adjoining waterworks tower said to be inspiration for Tolkien's 'Twin Towers'. Urgent repairs to address immediate structural problems completed. A business plan for long-term future use and completion of repairs is necessary.

Contact: Cristina Gardiner 0121 625 6850



© English Heritage

SITE NAME:	303, Icknield Street, Hockley
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1291556

Built 1883, by Martin and Chamberlain, in brick and terracotta with tiled roof as master's house to the Icknield Street School. Now derelict and in poor state of repair with risk of rapid deterioration. Upper storey windows and door now boarded up. Contact has been made with the leasees to seek solution.

Contact: Cristina Gardiner 0121 625 6850



© English Heritage

SITE NAME:	Horseshoe shaped former stables and stores (City of Birmingham Engineers Depot), 23 Sheepcote Street, Ladywood
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1220997

Former stables, originally Corporation Depot 1873, winning competition entry by W H Ward. All four buildings are in poor condition. A repair and development scheme planned in 2013 has not happened. The Roundhouse is mainly vacant and clearly deteriorating. The roof is poor with dislodged tiles and open joints at ridge level. The brickwork is poor in part, with open joints and plant growth. The gutters are generally in fair condition but some are dislodged. The surface of the inclined cobbled courtyard is badly deformed by car traffic and parking.

Contact: Cristina Gardiner 0121 625 6850



© English Heritage

SITE NAME:	Public Baths, Moseley
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1076274

Municipal baths with lavish terracotta decoration and complete interiors. The baths were opened in 1907 as an addition to the Free Library (1895) forming an impressive group of public buildings. A masterplan for future use of the building has been prepared by the City Council but plans to bid for Heritage Lottery Fund grant have been abandoned. Discussion is now focused on urgent interim works to keep the building watertight pending a resurrection of the Heritage Lottery Fund bid.

Contact: Cristina Gardiner 0121 625 6850

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© English Heritage Archive

SITE NAME:	Former School of Art, 496-500 Moseley Road, Moseley
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1343102

Moseley School of Art was designed by Bidlake and built in 1899. It was bought from the Council in the 1960s by the Moseley Muslim Community Association (MMCA). The building is now suffering from neglect; spalling stonework and leaking roofs are problems. English Heritage and the Architectural Heritage Fund have worked with the MMCA to take a project forward and it is hoped that grant aid will be awarded by AHF to appoint a Project Officer to develop an Heritage Lottery Fund grant application.

Contact: Cristina Gardiner 0121 625 6850



© English Heritage

SITE NAME:	100 Sampson Road, Sparkhill
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	E (B)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1076179

Built in 1901 as the vicarage to St Agatha's Church in Sparkbrook and designed in an Arts and Craft style by local Birmingham architect, WH Bidlake. Formerly converted to flats by a Housing Association, the building is now in private ownership but has been subject to vandalism, a small fire and is now suffering from dry rot and isolated structural issues. Localised repairs have recently taken place, but the property is now for sale.

Contact: Katriona Byrne 0121 625 6858



© Shrewsbury and Atcham Borough Council

SITE NAME:	The Bellefield Inn, 36-38 Winson Street, Winson Green
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1276279

Public house and attached outbuildings, C19 with early C20 remodelling by Wood and Kendrick. Outwardly modest, the interiors were unusual for their remarkable completeness. However, a fire has substantially destroyed the interior and much of the building is in very poor condition. The building has changed hands and Planning Permission for residential conversion has been granted, but no repairs carried out.

Contact: Cristina Gardiner 0121 625 6850



© English Heritage

SITE NAME:	Edward Road Baptist Church, Edward Road, Birmingham
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1343405

This is a good example of the Birmingham Terracotta School's work which combines Romanesque and Perpendicular details. There is evidence of damp at high level, roof needs attention and the joints to brick and terracotta blocks are badly eroded.

Contact: Cristina Gardiner 0121 625 6850



© English Heritage

SITE NAME:	Icknield Street School, Icknield Street, Hockley
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	A (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1076315

School 1883, by Martin and Chamberlain. The building is occupied by a religious group for the purpose of worship and community use. The roof to the fire-damaged area has been repaired, but more comprehensive repair of the building is needed. Rainwater goods are in poor shape and unsympathetic security measures detract from the appearance of the building.

Contact: Cristina Gardiner 0121 625 6850

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	Bethel United Church, Coventry Road, Small Heath	An Italianate brick church built in 1911 and designed by JL Ball. Holes in the roof have allowed water to damage plasterwork to the nave ceiling. There is a need for maintenance with some brickwork decay. Some windows are in poor condition and some have been replaced with uPVC.
DESIGNATION:	Listed Place of Worship grade II	
CONDITION:	Poor	
PRIORITY CATEGORY:	A (C)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1234443	

Contact: Cristina Gardiner 0121 625 6850

© English Heritage



SITE NAME:	Parish Church of St Margaret, St Margaret's Road, Ward End	Built in 1834 in a Commissioners' Gothic style with lancet windows and rendered elevations, the church was in a poor condition and vulnerable to vandalism. Though currently closed the church was awarded a grant by the Heritage Lottery Fund and work is now underway to reorder the church to enable worship and extended community use. The project is due to complete at the end of September 2014.
DESIGNATION:	Listed Place of Worship grade II	
CONDITION:	Fair	
PRIORITY CATEGORY:	F (C)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1220802	

Contact: Ross Brazier 0121 625 6884

© English Heritage



SITE NAME:	Bishop Latimer Memorial Church of All Saints, Handsworth New Road, Winson Green	A very large brick church designed by Bidlake and erected in 1903, with important interior. The church is located in a multi-cultural part of the city which is characterised by deprivation. The church has received a series of grants for repairs in the past, but the last in 2010 was stopped because of the threat of church closure. The proposed tenant intends to keep the building in use as a place of worship and is in negotiations with English Heritage over grant aid.
DESIGNATION:	Listed Place of Worship grade II*	
CONDITION:	Poor	
PRIORITY CATEGORY:	B (New entry)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1343061	

Contact: Cristina Gardiner 0121 625 6850

© English Heritage

SITE NAME:	Kent's Moat		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020538
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Barnsley Road		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Medium	CONTACT:	Simon Delahunty-Forrest (LPA) 0121 464 8258

SITE NAME:	Digbeth / Deritend		
DESIGNATION:	Conservation Area, 12 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Simon Delahunty-Forrest (LPA) 0121 464 8258

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site

SITE NAME:	Four Oaks		
DESIGNATION:	Conservation Area, 27 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Simon Delahunty-Forrest (LPA) 0121 464 8258

SITE NAME:	Ideal Village, Bordesley Green		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Simon Delahunty-Forrest (LPA) 0121 464 8258

SITE NAME:	Lozells and Soho Hill		
DESIGNATION:	Conservation Area, 37 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Simon Delahunty-Forrest (LPA) 0121 464 8258

SITE NAME:	School Road		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Simon Delahunty-Forrest (LPA) 0121 464 8258

SITE NAME:	Steelhouse		
DESIGNATION:	Conservation Area, 8 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Unknown
VULNERABILITY:	Medium	CONTACT:	Simon Delahunty-Forrest (LPA) 0121 464 8258

SITE NAME:	Sutton Coldfield High Street		
DESIGNATION:	Conservation Area, 34 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Simon Delahunty-Forrest (LPA) 0121 464 8258

SITE NAME:	Warwick Bar		
DESIGNATION:	Conservation Area, 7 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Simon Delahunty-Forrest (LPA) 0121 464 8258

COVENTRY



© English Heritage

SITE NAME:	Cook Street Gate
DESIGNATION:	Scheduled Monument, LB grade I, part in RPG grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1005908

The only remaining functional medieval gate to Coventry. Construction of the gate began in the early C14 and was completed later that century following a licence to crenellate in 1363. Inappropriate historic repairs, vulnerability to vehicle damage and stone erosion are issues.

Contact: Imogen Sambrook 0121 625 6854


PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© English Heritage Archive

SITE NAME:	Coventry City Walls
DESIGNATION:	Scheduled Monument, 2 LBs, part in RPG grade II, 2 CAs
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (New entry - re-assessed)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1002979

Remains include several stretches of the C14 city defences. English Heritage grant has been used to fund a conservation management plan for the walls. The local authority is now looking to implement the recommendations of the management plan.

Contact: John Tiernan 0121 625 6839



© Acanthus Clews Architects

SITE NAME:	Ruined Cathedral Church of St Michael, Coventry
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1076651

The iconic ruins of the original Coventry Cathedral, destroyed by a bombing raid in November 1940. Areas of exposed walls have become unstable. English Heritage grant aided works have now been successfully concluded: other repair works to the walls and crypt chapels are in process of being completed or are at the planning stage.

Contact: John Tiernan 0121 625 6839



© English Heritage Archive

SITE NAME:	Basement on site of Old Star Inn, Earl Street, Coventry
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1115642

Late Medieval cellar of an inn, now incorporated in the Civic Centre. Significant erosion of sandstone has taken place through water penetration from adjacent road works. The damage to the stone vault was repaired in 2008 and tanked. Temporary support to rib vaulting installed. Phase two works to replace eroded ribs is necessary.

Contact: Sarah Lewis 0121 625 6886



© English Heritage

SITE NAME:	The Old Grammar School (St Johns Hospital), Hales Street, Coventry
DESIGNATION:	Listed Building grade I
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (D)
OWNER TYPE:	Private, multiple owners
LIST ENTRY NUMBER:	1320431

Former chapel of the C12 hospital of St John, used as grammar school from 1545. Plans to repair and convert the building to new use as part of the adjoining Transport Museum won a Heritage Lottery Fund grant. Work commenced in February 2014.

Contact: Nick Molyneux 0121 625 6857



© English Heritage

SITE NAME:	The Charterhouse, London Road
DESIGNATION:	Listed Building grade I and Scheduled Monument, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1076621 and 1005901

Founded as a Carthusian Monastery dedicated to St Anne, the surviving building is a mixture of stone, brick and timber-frame construction incorporating centuries of change and adaptation. Exceptional and vulnerable wall paintings survive from the C15 and C16. The clay tile roof is in poor condition and there is evidence of water damage within the building. Now in the ownership of Charterhouse Coventry Preservation Trust, the building awaits re-use. The Trust is preparing a bid for Heritage Lottery Fund funding.

Contact: John Tiernan 0121 625 6839

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site



© English Heritage

SITE NAME:	The Charterhouse, precinct walls, London Road, Coventry
DESIGNATION:	Scheduled Monument and Listed Buildings - I grade I; I grade II*, LB grade II, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1005901 and 1076621; 1342917

The inner precinct wall built of sandstone was extended in the centuries after the Reformation when the Charterhouse became a dwelling. It is now in very bad condition with sections which have collapsed and others which are destabilised by vegetation growth. Now owned by Charterhouse Coventry Preservation Trust. An English Heritage grant has been offered and accepted and repair works are due to start on site in summer 2014.

Contact: John Tiernan 0121 625 6839



© English Heritage

SITE NAME:	Nonconformist Chapel to the Cemetery, London Road, Coventry
DESIGNATION:	Listed Building grade II*, RPG grade I, CA
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1076624

Cemetery chapel, 1846-47, probably by GH Stokes at southern end of the mid C19 cemetery, landscaped by Joseph Paxton in an informal style. The City Council repaired roof to its original design following a fire and carried out other repairs including capping the pavilion walls, interior pointing, installing security grills and doors. However, the building remains without a use and in a vulnerable condition.

Contact: Nick Molyneux 0121 625 6857



© Coventry HER 2014

SITE NAME:	Numbers 36 and 37 and archway in between (Whitefriars Gate), 36 and 37, Much Park Street
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1087114

A C14 postern gatehouse of the Carmelite Friary of sandstone and tile with later repairs in brick. Damaged by arson attack in 2008 and repaired, the building has remained vacant since then and is slowly deteriorating. Inappropriate window coverings, erosion of sandstone and mortar joints, continuing threat of vandalism and arson, and rotting timbers in the ceiling of the archway.

Contact: Imogen Sambrook 0121 625 6854

SITE NAME:	Priory ruins	LIST ENTRY NUMBER:	1005902
DESIGNATION:	Scheduled Monument, 2 LBs, CA	TREND:	Declining
CONDITION:	Generally satisfactory but with significant localised problems	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Vandalism	CONTACT:	Imogen Sambrook 0121 625 6854
OWNER TYPE:	Local authority		

DUDLEY



© English Heritage

SITE NAME:	Triangular Crane, Bumble Hole Boat Yard, Dudley
DESIGNATION:	Scheduled Monument, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1005884

C19 triangular boat crane, in poor condition. English Heritage funded a report on the condition and repair of the monument. A grant application for repairs was made but later withdrawn as no other funding was available for repairs. The crane collapsed in 2002 and sections of structure remain stored in the yard. A joint initiative is needed for the repair/reinstatement of the structure. An interpretation project has been carried out culminating on several panels, erected along the Boshboil Arm.

Contact: Cristina Gardiner 0121 625 6850

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© English Heritage

SITE NAME:	Brown bear pit at Dudley Zoo, Castle Hill, Dudley
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (D)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1227748

The bear pit was designed by Tecton and erected in 1936-7. A major repair project commenced in Spring 2014 with the benefit of an Heritage Lottery Fund grant.

Contact: Alan Taylor 0121 625 6848



© English Heritage Archive

SITE NAME:	Kiosk to east of Brown Bear Pit, Dudley Zoo, Castle Hill, Dudley
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1076024

A refreshment kiosk designed by Tecton and built in 1936-7 located furthest away from the main cafes and restaurant. The Zoo intends to repair the kiosk following completion of the work to the adjacent brown bear pit.

Contact: Alan Taylor 0121 625 6848



© English Heritage

SITE NAME:	Church of St Edmund, Castle Street, Dudley
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1287455

Situated in the centre of Dudley, this is a red brick church built in the Palladian style in the 1720s. Shallow tile roofs fall to parapets finished with stone dressings which are also a distinctive feature of the round-headed windows and the tower. Vegetation growing out of the tower is impacting on high level stonework and is a significant cause for concern.

Contact: Cristina Gardiner 0121 625 6850



© English Heritage

SITE NAME:	Church of St John, High Street, Dudley
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1229092

A good example of a Neo-Norman Commissioners' Church built in 1844-45 by Thomas Smith. Built in dark brick with yellow dressings it has interesting sandstone carved faces to the kneelers. Stone coped shallow pitched gables and Welsh slate roof. The church is in poor condition: the gutters and downpipes are very bad, the brickwork shows open joints as do the sandstone copings to the gables.

Contact: Cristina Gardiner 0121 625 6850



© English Heritage

SITE NAME:	Parish Church of St Thomas, High Street, Dudley
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	B (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1075998

Large Georgian church built in Perpendicular style designed by William Brooks in 1815-18. The current church is a replacement of a Medieval chapel, the remains of which are visible in the crypt. The last quinquennial report carried out in 2012 identified poor condition of the high level limestone stonework which is shaling away in large sections. The church has been awarded a Heritage Lottery Fund grant for the above repairs and roof access improvements so that maintenance can be carried out more easily.

Contact: Cristina Gardiner 0121 625 6850

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© English Heritage

SITE NAME:	Church of St James the Great, Salop Street, Dudley
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1270305

A Commissioners' Church of the mid C19, designed by William Bournier. Sister church to St John the Evangelist, Kate's Hill. The church is built of limestone with ashlar stone dressings. A Repair Grant for Places of Worship for stonework repairs was offered in March 2013 and Stage One project development is underway, but not completed.

Contact: Cristina Gardiner 0121 625 6850



© English Heritage

SITE NAME:	Church of St John the Evangelist, St Johns Road, Dudley
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1393300

St John's was designed in the Gothic lancet style by William Bournier and is the sister church to St James, Eve Hill also in Dudley. The church opened in 1849 but closed its doors for safety reasons in 2002. Worship now takes place in the parish hall. A feasibility study for re-use for worship, concerts, a cafe and community and educational use has been carried out and fundraising is underway.

Contact: Cristina Gardiner 0121 625 6850



© English Heritage

SITE NAME:	Presbyterian Chapel, Lower High Street, Stourbridge
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1343195

A red brick Presbyterian chapel built in 1788 with round-headed windows, stone detailing, and a projecting porch. Brickwork and cast iron windows are in poor condition.

Contact: Cristina Gardiner 0121 625 6850

SITE NAME:	The Redhouse, Whitehouse and Newhouse glassworks	
DESIGNATION:	Scheduled Monument, LB grade II*, CA	LIST ENTRY NUMBER: 1021378
CONDITION:	Generally unsatisfactory with major localised problems	TREND: Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?: No
OWNER TYPE:	Mixed, multiple owners	CONTACT: Ian George 0121 625 6859

SITE NAME:	Wychbury Camp (see also Bromsgrove, Worcestershire), Hagley	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: 1005900
CONDITION:	Generally unsatisfactory with major localised problems	TREND: Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?: No
OWNER TYPE:	Private, multiple owners	CONTACT: Imogen Sambrook 0121 625 6854

SITE NAME:	Brierley Hill High Street	
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY?: No
CONDITION:	Very bad	TREND: Improving
VULNERABILITY:	Low	CONTACT: Jayne Pilkington (LPA) 01384 814168

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Stourbridge Branch Canal (Canal Street)		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Jayne Pilkington (LPA) 01384 814168

SITE NAME:	Wollaston		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Jayne Pilkington (LPA) 01384 814168

SITE NAME:	Wordsley Church		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Jayne Pilkington (LPA) 01384 814168

SANDWELL



© English Heritage Archive

SITE NAME:	Soho Foundry, Foundry Lane, Smethwick
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1268451

Foundry built in 1795: the world's first integrated manufactory of steam engines. Established by Boulton & Watt. English Heritage and the Local Authority grant-aided a temporary roof to stabilise the structure in 2009. Discussions are ongoing with the owners to ensure continued routine maintenance and to find a new use.

Contact: Nick Molyneux 0121 625 6857



© English Heritage

SITE NAME:	Waterloo Hotel, Shireland Road, Smethwick
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1261644

The Waterloo Hotel was built in 1907 by Wood and Kendrick for local brewers, Mitchells & Butler, in the baroque style with terracotta dressings. This is a near complete example of an Edwardian showpiece pub and commercial hotel, which retains many interior features including the ornately tiled basement grill room. The building is disused but the roof has been repaired. Planning permission was granted in 2013 for conversion of the upper floors to apartments but work has not yet started.

Contact: Alan Taylor 0121 625 6848

SITE NAME:	Chances Glassworks, Smethwick		
DESIGNATION:	Scheduled Monument, 5 LBs	LIST ENTRY NUMBER:	1021387
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Ian George 0121 625 6859

SITE NAME:	Engine Arm Aqueduct, Warley		
DESIGNATION:	Scheduled Monument, LB grade II*	LIST ENTRY NUMBER:	1005904
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Cristina Gardiner 0121 625 6850

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
B Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	High Street, West Bromwich, Black Country		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Mark Stretton (LPA) 0121 569 4033

SITE NAME:	Market Place, Wednesbury, Black Country		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Mark Stretton (LPA) 0121 569 4033

WALSALL



© Walsall Metropolitan Borough Council

SITE NAME:	Great Barr Hall and chapel, Great Barr	Gothic country house of 1777 with 1863 chapel attributed to George Gilbert Scott. Set in a registered late C18 landscaped park. The hall was extended and converted into a hospital in the early C20 but has been vacant since 1978. Extensive fire damage has contributed to general decay, loss of fabric and the site suffered from vandalism. New owners have made an application for enabling development.
DESIGNATION:	Listed Building grade II*, RPG grade II, CA	
CONDITION:	Very bad	
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1076395	



© English Heritage

SITE NAME:	Church of St Matthew, Church Hill, Walsall	St Matthew's was rebuilt in the 1820s by Francis Goodwin. Its soaring spire is a local landmark and its Bath stone facades stand out in the street scene. The style of the church is predominantly Perpendicular but C13 remains survive in the crypt. High level repairs are needed all over this complex building. A Repair Grant for Places of Worship was offered in December 2012 and Stage One project development has been completed. Stage Two (repairs) to commence in June 2014 for 11 weeks.
DESIGNATION:	Listed Place of Worship grade II*, CA	
CONDITION:	Poor	
PRIORITY CATEGORY:	B (B)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1116151	



© English Heritage

SITE NAME:	Life and Light Mission Church (former Trinity Methodist Church), Union Street, Willenhall	Built as a Methodist church in the 1860s, this large rendered church is in the Classical style, with round-headed windows and pilasters, making it prominent on the street frontage. The render is loose in many areas allowing water to enter the building. A Repair Grant for Places of Worship was offered in March 2013 and Stage One project development is currently being prepared but not yet completed.
DESIGNATION:	Listed Place of Worship grade II, CA	
CONDITION:	Poor	
PRIORITY CATEGORY:	B (B)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1077170	

SITE NAME:	Bloxwich High Street		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Andrew Fuller (LPA) 01922 655537

SITE NAME:	Bradford Street, Walsall		
DESIGNATION:	Conservation Area, 5 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Andrew Fuller (LPA) 01922 655537

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.


NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Bridge Street, Walsall		
DESIGNATION:	Conservation Area, 10 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Andrew Fuller (LPA) 01922 655537
SITE NAME:	Caldmore Green, Walsall		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Andrew Fuller (LPA) 01922 655537
SITE NAME:	Church Hill, Walsall		
DESIGNATION:	Conservation Area, 17 LBs, RPG grade II*	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Andrew Fuller (LPA) 01922 655537
SITE NAME:	Elmore Green, Bloxwich		
DESIGNATION:	Conservation Area, 3 LBs, SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Andrew Fuller (LPA) 01922 655537
SITE NAME:	Willenhall		
DESIGNATION:	Conservation Area, 10 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Andrew Fuller (LPA) 01922 655537

WALSALL / SANDWELL



© English Heritage

SITE NAME:	Great Barr Hall, Walsall
DESIGNATION:	Registered Park and Garden grade II, 3 LBs, part in CA
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1001202

Parkland and pleasure grounds, partly by Humphry Repton and John Nash. Much of historic park built over as mental hospital in C20, in turn replaced by modern housing estate circa 2005. Pleasure grounds overgrown and neglected; remaining area of park also in poor condition. Hall is dilapidated and also at risk. In 2010 English Heritage reviewed the area covered by the registered park and enlarged it. Change of ownership in spring 2012. Proposals for Enabling Development under consideration (June 2014) by the Local Authority. Part of the park is in the district of Sandwell.

Contact: Kim Auston 0117 975 0696

WOLVERHAMPTON, CITY OF



© English Heritage

SITE NAME:	The Greyhound and Punchbowl Inn (formerly Stoke Heath Manor House), High Street, Bilston
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1201819

Mid C16 manor house, restored in the 1930s. Of timber framed construction, strengthened with concrete skin in the 1930s. Now suffering complex structural problems to supporting concrete frame requiring long term solution. English Heritage engineer has prepared preliminary report. A more detailed structural survey and investigation will be required to establish the most appropriate method of repair.

Contact: Imogen Sambrook 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site



© English Heritage

SITE NAME:	Church of St Leonard, Church Street, Wolverhampton
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1282492

This church was built in 1825 to designs by Francis Goodwin, and restored in the 1880s by Ewan Christian. It is in the neoclassical style, finished in render with elegant round-headed windows and a fine octagonal tower. The interior has decorative plaster ceilings and balconies. Leaking parapet gutters are affecting the render externally and the plaster internally.

Contact: Cristina Gardiner 0121 625 6850



© English Heritage

SITE NAME:	Church of St Luke, Upper Villiers Street, Wolverhampton
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Very bad
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1293038

Gothic Revival church by GT Robinson of Leamington built in polychromatic brickwork in 1860. The church is large and its soaring, Decorated spire is a local landmark in the Blakenhall area. There are many issues with this very large church. Dry rot was addressed some years ago, but many other issues remain.

Contact: Cristina Gardiner 0121 625 6850

WORCESTERSHIRE

BROMSGROVE



© English Heritage

SITE NAME:	Standing cross in St Leonards churchyard, Frankley
DESIGNATION:	Scheduled Monument, LB grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1017255

A C15 churchyard cross of sandstone restored in 1915. It comprises a plinth of one octagonal stone step on which sits a single octagonal base stone with a rectangular section shaft topped by a cross head. The decorated shaft and cross head are heavily weathered, the cross head shows cracking to the underside and mossy growth on upper surfaces, there is a limited amount of delamination on the west face.

Contact: Imogen Sambrook 0121 625 6854



© English Heritage

SITE NAME:	Temple of Theseus, Hagley Hall, Hagley
DESIGNATION:	Listed Building grade I, RPG grade I
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1348599

Doric temple of 1758 designed by James 'Athenian' Stewart. It stands in the grade I registered landscape park 800 metres north of the Hall. It is separated from the rest of the estate by the A456; this relatively isolated location has rendered it vulnerable to vandalism so security fencing has been erected. Discussions continue with owner on a strategy to secure the future of the building.

Contact: Katriona Byrne 0121 625 6858



© English Heritage

SITE NAME:	Church of St Laurence, Bear Hill, Alvechurch
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1100225

Large Anglican parish church. Mostly rebuilt 1860 to 1861 by W Butterfield retaining only a C15 tower which was remodelled in 1676. Badly eroded or damp affected sandstone on the north side and at low level on the tower. Rainwater goods poor, especially on the tower.

Contact: Chris Miners 0121 625 6853

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© English Heritage

SITE NAME:	Christ Church, Catshill, Catshill and North Marlbrook
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1099541

Large suburban Anglican parish church. Nave and west tower built in 1838 by Harvey Eginton, the east end of chancel and flanking chapels rebuilt by JA Chatwin in 1887, mostly in the Early English style. Red sandstone ashlar with slate roofs. The sandstone is heavily eroded with harmful vegetation growth. Many leaks have sprung from the failing parapet gutters.

Contact: Chris Miners 0121 625 6853



© English Heritage

SITE NAME:	Church of St Bartholomew, High House Lane, Tutnall and Cobley
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1100167

Anglican parish church. Nave and west tower and spire with Baroque bell stage from 1777 by Francis Hiorn. The chancel was added in 1880. The sandstone ashlar is heavily eroded, the downpipes are leaking and seriously degrading the stone behind.

Contact: Chris Miners 0121 625 6853

SITE NAME:	Moated site 130 metres north east of Moorgreen Farm, Alvechurch		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017527
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
OWNER TYPE:	Private, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Dodford Priory moated site, Dodford with Grafton		
DESIGNATION:	Scheduled Monument, 2 LBs, CA	LIST ENTRY NUMBER:	1018278
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Moated site at Blackgreves Farm, Wythall		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1017804
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Other not for profit group	CONTACT:	Imogen Sambrook 0121 625 6854



© English Heritage

SITE NAME:	Hewell Grange, Tutnall and Cobley / Bentley Pauncefoot
DESIGNATION:	Registered Park and Garden grade II*, 15 LBs
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Stable
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1000886

Multi-phase landscape, including work influenced by Humphry Repton. Another major period of activity towards the end of C19 when current house built. Post-war development by Prison Service has had a major impact on legibility of design. Management plan and partnership with County Gardens Trust has led to renewed interest in and care for designed landscape, including restoration of bridge to island.

Contact: Kim Auston 0117 975 0696

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Bromsgrove Town Centre		
DESIGNATION:	Conservation Area, 53 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Mary Worsfold (LPA) 01527 881329

MALVERN HILLS



© English Heritage

SITE NAME:	Mythe Bridge (that part in Civil Parish of Bushley), Tewkesbury Road, Bushley
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1238445

Road bridge over the River Severn. Built 1823-26 by Thomas Telford. Cast iron bridge of 6 segmental arched lattice beams, latticed roadway beam with latticed ironwork filling the spandrels. Each abutment has inner and outer sandstone piers separated by 6 brick arched tunnel vaults with cast iron colonettes. The ironwork of the balustrades is rusting at the connections. The sandstone piers, especially above the roadway level, are severely fractured and eroded, and some are covered in excessive and harmful ivy growth. Also included in the South West Heritage at Risk Register.

Contact: Chris Miners 0121 625 6853



© English Heritage

SITE NAME:	Churchyard cross, St Mary's Church, Shrawley
DESIGNATION:	Scheduled Monument, LB grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1014901

This cross is a good example of a Medieval standing cross base of stepped form with a moulded plinth. It is believed to stand in its original position, and limited development in the area immediately surrounding the cross suggests that archaeological deposits relating to the monument's construction and use in this location are likely to survive intact. The joints between the plinth stones are open, some stones have cracked through and the surface of the stones is mossy. An English Heritage funded Management Agreement has been offered for repairs and accepted.

Contact: Imogen Sambrook 0121 625 6854



© English Heritage

SITE NAME:	Church of St Faith, Berrow
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1098847

Rural Anglican parish church. West tower, nave with south aisle and gabled north entrance porch, lower east chancel. C12 origins, chancel C14, the south aisle, tower and porch C15. Mid-C19 restoration. Coursed sandstone rubble with ashlar dressings. Generally clay tile roofs except for sandstone slates on the north nave and porch pitches. Cast iron rainwater goods. Cracking in walling, generally located to the south side of the church. Structural stitching is needed. Damp within the walling and floors causing internal decay. A Heritage Lottery Fund grant has been applied for.

Contact: Chris Miners 0121 625 6853



© English Heritage Archive

SITE NAME:	Church of St Michael, Great Witley
DESIGNATION:	Listed Place of Worship grade I, RPG grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1082655

Large Anglican parish church attached to Witley Court. Notable for one of the finest English baroque church interiors. The slate roof is failing with rusted fixings and slipped slates that imperil the painted interior below. An English Heritage/Heritage Lottery Fund Repair Grant for Places of Worship has been offered for repairs and the parish is fundraising for their share of the cost of the works.

Contact: Chris Miners 0121 625 6853

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site



© English Heritage

SITE NAME:	Church of St Michael, Knighton on Teme
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1167609

Small rural Anglican parish church. C12 nave and chancel. Nave extended to encompass a detached bell tower in early C13, chancel extended and re-modelled in 1880. Red sandstone rubble walls with some tufa. Tiled roofs. The bell turret and spire were clad in cedar shingles when it was simplified in 1954. These have severely eroded and have been attacked by woodpeckers which have left many holes on all the faces. This has let in rainwater to rot the floorboards. A Heritage Lottery Fund Grant for Places of Worship for the repair work has been offered.

Contact: Chris Miners 0121 625 6853



© English Heritage

SITE NAME:	Christ Church, Avenue Road, Barnards Green, Malvern
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1391823

Large Anglican parish church built in 1875 by Barry & Sons in the Decorated style. Grey rock-faced sandstone walling with lofty west steeple. The fixings of both the tiles and the battens of the upper, steeper, roof pitches are failing. Falls of tiles are smashing the lower shallower slated pitches. A Heritage Lottery Fund Grant for Places of Worship for the repair works has been offered.

Contact: Chris Miners 0121 625 6853



© English Heritage

SITE NAME:	Holy Trinity Church, Worcester Road, Link Top, Malvern
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1392674

Large suburban Anglican parish church. Built in 1851 by SW Daukes in the late-C13 style. Malvern granite stone with stone tiles over the chancel and nave, slates elsewhere. The stone slates have failed on the nave and chancel. The chancel stone slates have just been renewed together with urgent repairs to the belfry. The nave re-slating remains to be carried out. An English Heritage/Heritage Lottery Fund Repair Grant for Places of Worship has been offered for this work and the development stage has been completed. Repairs are expected to commence in 2014.

Contact: Chris Miners 0121 625 6853



© English Heritage

SITE NAME:	Church of St Andrew, Stanford with Orleton
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Very bad
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1082110

Small Anglican parish church. Sandstone rubble C12 nave with south porch and buttressing from the C14 and brick chancel from a 1718 rebuild. Tiled roofs and a boarded bellcote with pyramid slate roof over the nave. Structural work has been carried out on the church with success at the west end but severe structural movement cracking is still evident at the chancel.

Contact: Chris Miners 0121 625 6853

SITE NAME:	Enclosure 110 yards (100 metres) north of St Bartholomew's Church, Grimley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005296
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Religious organisation	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Enclosure west of Church Farm, Grimley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005315
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Religious organisation	CONTACT:	Imogen Sambrook 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Tenbury Wells, Tenbury		
DESIGNATION:	Conservation Area, 55 LBs, part in SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Siân Hughes (LPA) 01684 862257

REDDITCH

SITE NAME:	Feckenham manorial moated site, Feckenham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018361
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - moderate	NEW ENTRY?:	Yes
OWNER TYPE:	Local authority	CONTACT:	Imogen Sambrook 0121 625 6854

WORCESTER



© English Heritage

SITE NAME:	Remains of city wall, Worcester
DESIGNATION:	Scheduled Monument and Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (E)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1005281 and 1063805

Medieval city walls in multiple ownership, which results in a lack of co-ordinated approach. A variety of repair and maintenance has taken place in the past. A Conservation Management Plan for the Medieval defences has been completed. Sections of the wall have been repaired with English Heritage grant aid. Crown Gate has funded the trimming of ivy along The Butts in preparation for further works.

Contact: Imogen Sambrook 0121 625 6854



© English Heritage

SITE NAME:	Waiting Room, Shrub Hill Station, Worcester
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Utility
LIST ENTRY NUMBER:	1390157

This ornate waiting room, circa 1880, is of cast iron frame construction with infill panels of glazed ceramic tiles. A scheme for full restoration and re-use progressed well but has stalled. The structure is fenced off on the platform. Repairs need to be completed.

Contact: Cristina Gardiner 0121 625 6850

SITE NAME:	Moated monastic grange and fishpond complex at Middle Battenhall Farm, 450 metres north of Upper Battenhall Farm, St. Peter the Great County		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017310
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Lowesmoor, Worcester		
DESIGNATION:	Conservation Area, 15 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	James Dinn (LPA) 01905 721132

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

WYCHAVON



© English Heritage

SITE NAME:	Eckington Bridge, Birlingham / Defford / Eckington
DESIGNATION:	Scheduled Monument and Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1005264 and 1116724

Fine example of early C16 bridge of six arches built in sandstone. It is a narrow single track road bridge controlled by traffic lights. The bridge has suffered from frequent traffic collisions. The Local Authority has undertaken stonework repairs and is about to embark on protection measures for the bridge to reduce the harmful impact of traffic. Chemical erosion from roadsalt penetration of structure is causing stonework failure.

Contact: Neil Rimmington 0121 625 6856



© English Heritage

SITE NAME:	31 High Street, Droitwich Spa
DESIGNATION:	Listed Building grade II*, SM, CA
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1296659

The solar wing of a C14 timber framed town house. The front range is rendered but incorporates exceptional timber work in the roof and ceiling structures. C17 extensions to the rear are in very bad condition with structural failure to the timber frame and walls. Failed rainwater goods and a roof in poor condition are letting water into the structure and rotting the frame. The building is only partly occupied.

Contact: Sarah Lewis 0121 625 6886



© English Heritage

SITE NAME:	Abbot Chyryton wall, Boat Lane, Evesham
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1005501 and 1350435

Part of the outer precinct wall of Evesham Abbey, built by abbot William de Chyryton 1317-44, which originally extended from river to Abbey. Previous grant aided consolidation has partially failed due to vandalism. Some parts of wall still in very bad condition, and wall footings are diminishing. Discussions ongoing to agree long term solution.

Contact: Neil Rimmington 0121 625 6856



© English Heritage

SITE NAME:	Abbot Reginalds Wall, Evesham Abbey, Evesham
DESIGNATION:	Scheduled Monument and Listed Buildings - I grade I; I grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private, multiple owners
LIST ENTRY NUMBER:	1005298 and 1081349; 1081350

Abbot Reginalds wall forms part of the main ecclesiastical complex of Evesham Abbey, fragments of which still survive. The rebuilding of the collapsed section and repairs to adjoining wall have been completed with grant aid. Sections of wall are still in poor condition and in need of an overall repair strategy. This may be addressed through a management plan that the Civic Society is looking to prepare for the wider area.

Contact: Imogen Sambrook 0121 625 6854



© English Heritage

SITE NAME:	The Bell Tower, Market Place, Evesham
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1081353

Late Medieval detached bell tower, formerly part of Evesham Abbey. It is a beautiful example of late Gothic carved ornamentation and has become the icon for Evesham. Although looking superficially sound, all faces and elements need carefully conservation and repair. Recent falls of stone triggered detailed surveys which revealed dangerous levels of decay of the limestone, with much loss of historic features. A grant for repairs under the Heritage Lottery Fund Grants for Places of Worship scheme has been offered.

Contact: Chris Miners 0121 625 6853

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© English Heritage

SITE NAME:	West porch of Bengeworth Old Church, Church Street, Bengeworth, Evesham
DESIGNATION:	Scheduled Monument and Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1005299 and 1095958

The old church of St Peter was pulled down in 1870, leaving the remains of the porch that stood under the west tower. It is constructed of rubble masonry, which has been pointed with cement in the past and is now cracking. Issues include missing roof tiles, salt erosion causing stone damage by road and structural cracking on south east corner. The roof structure is also at risk. The Town Council has removed the damaging ivy previously covering the south elevation. English Heritage are working with the Council on next steps.

Contact: Imogen Sambrook 0121 625 6854



© English Heritage

SITE NAME:	Church of St James, Bredicot
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1117084

Tiny Anglican church in the old rectory garden with three-bay nave/chancel, south porch and bellcote. Walls are rubble with ashlar dressings and tiled roof. Restored in 1843 by Perkins. The sandstone of the window masonry is heavily eroded and falling apart.

Contact: Chris Miners 0121 625 6853



© English Heritage

SITE NAME:	Church of St John the Baptist, Church Walk, Crowle
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1081275

The original Medieval church was demolished and rebuilt in the 1880s to designs by Frederick Preedy in the Decorated style with a tall west tower. The church is constructed from lias limestone rubble with ashlar dressings under a plain clay tile roof with decorative ridges. The roof and rainwater goods are in poor condition, minor repairs are required to the stonework. A Repair Grant for Places of Worship was offered in February 2013.

Contact: Chris Miners 0117 975 0700



© English Heritage

SITE NAME:	Church of St Andrew, St Andrew's Street, Droitwich Spa
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1167974

Large Anglican parish church in the centre of Droitwich. Sandstone ashlar with roofs of mixed materials. Nave and chancel flanked by tall aisles, with a truncated integral north tower set in the north range. A parish centre is attached on the south side. Tiled roof and the rainwater system of the north east chapel are leaking, causing decay in the C15 ceiling below. Other roofs and high level walls were repaired with English Heritage grant ten years ago.

Contact: Chris Miners 0121 625 6853



© English Heritage

SITE NAME:	Church of St Peter, Flyford Flavell
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1039144

Small Anglican parish church. The nave, chancel and north transept are mostly from the rebuild by Hopkins in 1883 incorporating older materials, but the west tower is C15. There is structural movement on the west face of the tower, and excessive vegetation growth on all parts of the church.

Contact: Chris Miners 0121 625 6853

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site



© English Heritage

SITE NAME:	Church of St John the Baptist, Grafton Flyford
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1374136

Medieval church dating from the C13 to C14 with Perpendicular window tracery. It was restored in 1875 by Hopkins. There are patches of weathered stonework on the tower and chancel as well as vegetation and moss growth on the tower, nave, vestry and chancel. Leaking guttering on the vestry has resulted in the saturation of surrounding stonework and there are some structural cracks in the east elevation of the vestry.

Contact: Chris Miners 0121 625 6853



© English Heritage

SITE NAME:	Church of St James, Hartlebury
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1288150

Large Anglican parish church. Mostly rebuilt by Rickman who rebuilt the chancel and its chapels in 1825 and the nave and aisles in 1837 retaining the C16 tower. Sandstone ashlar and roofs of mixed materials. Leaks in the nave roof have caused a section of decorative ribbed vaulted plasterwork to fall.

Contact: Chris Miners 0121 625 6853



© English Heritage

SITE NAME:	Church of St Peter, Hinton on the Green
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Very bad
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1215987

Small Anglican parish church. C12 nave, C15 west tower and nave battlements, chancel and porch C19. Lias coursed rubble with ashlar dressings and tiled roofs. Tower has structural cracking and past falls of ashlar.

Contact: Chris Miners 0121 625 6853



© English Heritage

SITE NAME:	Abbey Church of Holy Cross, Church Walk, Pershore
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1387027

Large urban Anglican parish church and former Benedictine Abbey with classic cruciform abbey church plan from the C12 and C13, but now without the nave and north transept. Restored by GG Scott 1864. Walling is mostly limestone ashlar from C13, the high Lierne vaulting from the late C13. Roofs are now tiles except for the stone slates on the hipped apse roof. Water ingress into the north east transept valley has decayed the supporting timber structure and the stonework below. A Heritage Lottery Fund Grant for Places of Worship has been applied for.

Contact: Chris Miners 0121 625 6853



© English Heritage

SITE NAME:	Church of St Michael, Main Street, South Littleton
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1081303

Small Anglican parish church. Circa 1200 nave, chancel and north transept C14, west tower and south porch C15. Roofs, porch and chancel severely restored by Preedy in 1883. Lias coursed rubble with limestone ashlar dressings and clay tiled roof. The stonework is failing on the north side together with excessive vegetation growth and rainwater goods that need urgent renewal.

Contact: Chris Miners 0121 625 6853

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Settlement site NNE of Fernhill Farm, Charlton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005287
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Enclosures north east of Fernhill Farm, Charlton / Cropthorne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005286
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Roman settlement at Bays Meadow, Droitwich Spa		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020620
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Evesham Abbey (remains of), Evesham		
DESIGNATION:	Scheduled Monument, 4 LBs, CA	LIST ENTRY NUMBER:	1005297
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Neil Rimmington 0121 625 6856
SITE NAME:	Settlement site north of Spring Hill, Fladbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005352
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Moated site 120 metres south east of Huntingdrop Farm, Hanbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017311
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Double ditched enclosure north east of Wick village, Wick		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005310
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© English Heritage

SITE NAME:	Westwood Park, Westwood / Hampton Lovett
DESIGNATION:	Registered Park and Garden grade II, 11 LBs
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	High
TREND:	Stable
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1000899

Gardens and pleasure grounds mostly late C19 and early C20. Vast majority of park in intensive cultivation, denuded of parkland trees. Some post-war development in vicinity of main house. Residential development and expansion of business park affect setting, particularly to north and east.

Contact: Kim Auston 0117 975 0696

WYRE FOREST



© English Heritage

SITE NAME:	Baches Forge, Churchill Lane, Churchill, Churchill and Blakedown
DESIGNATION:	Scheduled Monument and Listed Buildings - 3 grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Private, multiple owners
LIST ENTRY NUMBER:	1005274 and 1348320; 1100650; 1100651

Early C19 hand forge building, comprising two brick structures which form part of a water powered spade and shovel mill. The machinery still in working order and is looked after by owners and small local trust. The buildings are now stable but an overall management plan addressing the condition of the monument and surviving plant is required.

Contact: Neil Rimmington 0121 625 6856



© English Heritage Archive

SITE NAME:	Ribbesford House, Ribbesford
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (E)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1329928

Mid C16 country house with late C17 and early C19 alterations. Owner continues to carry out remedial works. Building structurally sound, but still in need of repairs to various parts of the building and still partially occupied. Internal modernisation to commence for reuse as apartments once interiors repaired. Discussions are ongoing with the owner.

Contact: Cristina Gardiner 0121 625 6850

SITE NAME:	Gilgal, Stourport-on-Severn, East of Stourport Town Centre		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Peter Bassett (LPA) 01562 732928

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



ENGLISH HERITAGE

This document is one in a series of publications produced as part of English Heritage's national Heritage at Risk programme. More information about Heritage at Risk and other titles in the series can be found at www.english-heritage.org.uk/risk

HERITAGE AT RISK

Published October 2014 by English Heritage
1 Waterhouse Square, 138-142 Holborn,
London EC1N 2ST

© Copyright English Heritage 2014