

Heritage at **Risk**




Historic England

West Midlands Register 2015

Contents

Heritage at Risk	III
The Register	VII
Content and criteria	VII
Criteria for inclusion on the Register	IX
Reducing the risks	XI
Key statistics	XIV
Publications and guidance	XV
Key to the entries	XVII
Entries on the Register by local planning authority	XIX
Herefordshire, County of (UA)	I
Shropshire (UA)	14
<i>Staffordshire</i>	28
East Staffordshire	28
Lichfield	30
Newcastle-under-Lyme	31
Peak District (NP)	32
South Staffordshire	32
Stafford	33
Staffordshire Moorlands	34
Tamworth	36
Stoke-on-Trent, City of (UA)	37
Telford and Wrekin (UA)	40
<i>Warwickshire</i>	42
North Warwickshire	42
Nuneaton and Bedworth	44
Rugby	45
Stratford-on-Avon	47
Warwick	51
<i>West Midlands</i>	54
Birmingham	54
Coventry	58
Dudley	61
Sandwell	63
Walsall	64
Wolverhampton, City of	65
<i>Worcestershire</i>	67
Bromsgrove	67
Malvern Hills	69
Redditch	72
Worcester	72
Wychavon	73
Wyre Forest	77

Heritage at Risk



Historic England

West Midlands Summary 2015



For the first time, we've compared all sites on the Heritage at Risk Register – from domestic houses to hillforts – to help us better understand which types of site are most commonly at risk. There are things that make each region special, and once lost, will mean a sense of our region's character is lost too. Comparing the West Midlands to the national Register shows that 34.5% of all castles and 16.1% of all enclosures are in our region. There are 450 entries on the West Midlands 2015 Heritage at Risk Register, making up 8.2% of the national total of 5,478 entries. The Register provides an annual snapshot of historic sites known to be at risk from neglect, decay or inappropriate development. Our local HAR team, led by Sarah Lewis, continues to work with owners, funders and other stakeholders to find the right solutions for sites on the Register.

Veryan Heal
Planning Director, West Midlands



In 2014 the West Midlands followed national trends with an overall decrease in scheduled monuments and secular listed buildings on the Heritage at Risk Register but an increase in listed places of worship, registered

parques and gardens and conservation areas.

Analysis of the type of heritage which is most at risk in the West Midlands shows that the **castles** which punctuate the Marches on our border with Wales are particularly vulnerable. Like much of the archaeology and many of the buildings and structures on the Register, few castles are capable of economic use and some have been at risk for many years. Imaginative solutions as well as grant aid are needed to tackle their condition. We are exploring potential for a new charitable trust model working with volunteers to deliver repair and management of Marcher castles.

Our Heritage at Risk team develops and implements solutions for heritage at risk with funding from **Historic England grants**. Management Agreements help owners with the cost of achieving step-changes in the management of archaeology. We also fund condition assessments, options appraisals, feasibility studies and major repairs.

Partnerships continue to be central to our strategy. Local authorities are key partners, we work with them to identify **conservation areas at risk** and now have an almost complete set of conservation area assessments. We continue to fund Partnership Schemes in Conservation Areas with a new scheme approved this year in Stoke Town. We are currently delivering training and advice to encourage local authorities to use their enforcement powers.


Partnerships with **other funders** such as The Prince's Regeneration Trust, the Heritage Lottery Fund, National Trust and Natural England have seen the development of numerous projects. These include a major scheme for the Wedgwood Institute in Burslem, a new use for the Master's House in Ledbury, the repair of the packhorse bridge at Todenham in Warwickshire and of lead mining remains in Shropshire.

93 of our 1,466 **listed places of worship** are at risk. The majority face repair costs of over £125k. To help tackle the challenge this presents for congregations, we continue to fund Support Officers in the Dioceses of Hereford, Worcester and Lichfield. The Support Officers help parishes manage their buildings, plan for the future and apply for grant aid from the main provider, the Heritage Lottery Fund, and the new Listed Places of Worship Roof Repair Fund.


Sarah Lewis
Principal Adviser, Heritage at Risk

Cover image: After centuries of residential use this small, attractive, Queen Anne country house now lies neglected and falling into a state of significant disrepair. **Hales Hall near Cheadle, Staffordshire** was last used as a social club for the caravan site which occupies part of the grounds, but is now empty and at risk. The property, including former stables and outbuildings, is for sale and badly needs a new owner prepared to take on the challenge of repairing and finding a new use for it.

Entries on the 2015 national Register in the **West Midlands**




40 (34.5%)
Castles



27 (16.1%)
Enclosures

Designated assets on the 2015 **West Midlands** Register



There are **454** assets on the **West Midlands** Register, 13 fewer than 2014

The Conservatory **Hilton Park, Hilton, Staffordshire**



Background and history

The conservatory is part of the surviving nucleus of the 18th century Hilton Park Estate. The hall and stables are now occupied by assorted businesses. Tracts of the surrounding land are given over to the M54 and M6 motorways and a service station. This garden building lies a short distance from



the hall and was built c 1825. Its plan is circular with a glazed hemispherical roof, with one half constructed in cast iron and the other in timber. The supporting walls are rendered masonry. The building was originally heated by an external furnace: heat was dissipated through underfloor ducts and the smoke discharged via a central stack disguised as a fluted column.

The conservatory has not been used or maintained in any meaningful way for several decades. As a consequence of this neglect, it was practically at the point of collapse. Its state of disrepair was such that even conservative repair required the complete dismantling and rebuilding of what survived. The masonry walls, arches and central column remained in place but all of the cast iron components were dismantled and repaired off site.

Is it at risk?

Following a successful grant application, Historic England awarded money for repairs. Work started on site in 2013 and was completed in March 2015. The conservatory was then removed from the Heritage at Risk Register.

What's the current situation?

The Hilton Park Company who manages the estate on behalf of its owners intends to use the conservatory for corporate events and weddings. The cost of the project was over £375,000.

Stoke Town Conservation Area

Stoke-on-Trent, Staffordshire

Background and history

This is a compact conservation area of mainly Edwardian or late Victorian commercial buildings. Municipal and industrial buildings, the church, and other key landmarks are still in place. Surviving historic fabric reflects the economic and social history of the last hundred years in Stoke Town. The historic significance of the town is high with the former Spode pottery works having an international reputation.

Is it at risk?

The conservation area is at risk. Poor property maintenance and vacant upper floors are a result of low property values and a low-value trading environment. Some 72% of the buildings are 'at risk' or vulnerable.

What's the current situation?

The City of Stoke on Trent Council and Historic England are jointly funding a Partnership Scheme (PSiCA) which



sets out to address this. Repairs will be focussed on buildings around the Spode Factory, the regeneration of which is critical to the improvement of the conservation area. Further 'gateway' locations and clusters of historic buildings have also been identified for funding in order to maximise the scheme's impact on regeneration and to act as exemplars to encourage future investment.

Historic England Angel Awards

The Historic England Angel Awards were founded in 2011, co-funded by the Andrew Lloyd Webber Foundation. They celebrate local people's extraordinary efforts to save historic buildings and places. Over the past five years, the Angel Awards have showcased inspirational friends groups, communities, worshippers, owners and craftspeople.

From 2016, we'll be looking for projects that champion the historic environment in many ways. These could include:

- community action projects
- heritage research, survey or education projects
- heritage professionals
- lifetime achievements
- and of course, rescues of heritage sites

Shortlisted Angels will continue to be put to the vote in the ever-popular People's Favourite Award.

Look out for news at www.HistoricEngland.org.uk/AngelAwards

For more information contact:

Sarah Lewis, Historic England West Midlands
The Axis, 10 Holliday Street,
Birmingham, B1 1TG
Telephone: 0121 625 6870
Email: west.midlands@HistoricEngland.org.uk
Twitter: @HE_WestMids

For a different format of this document contact our customer services department on:
Telephone: 0370 333 0608 Textphone: 0800 015 0516
Email: customers@HistoricEngland.org.uk
Product code: 52015

Find out what's at risk by searching or downloading the online Heritage at Risk Register at:
HistoricEngland.org.uk/har

THE REGISTER

Content and criteria

DESIGNATION

Definition

All the historic environment matters but there are some elements which warrant extra protection through the planning system. These are included in the [National Heritage List for England](#) (NHLE), an online searchable database of designated assets. Since 1882, when the first Act protecting ancient monuments and archaeological remains was passed, government has been developing the designation system. Listing, which is applied to buildings, emerged from the post-Blitz 1940s Planning Acts. There are now nearly 400,000 designated assets on the NHLE including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites.

Historic England, as the government's expert adviser, is responsible for making recommendations – but it is still the Secretary of State at the Department for Culture Media and Sport who makes the decisions on whether an asset is designated. Understanding and appreciation develop constantly, which makes keeping the designation base up-to-date a never-ending challenge.

While still responding to threat-driven cases, our approach is now more strategic, based around thematic and area-based projects. Recent developments have seen a greater striving for openness and transparency in the process of designating a site, and better communication of what makes something special.

Alongside the nationally designated assets found on the National Heritage List for England are locally designated assets. Best known are conservation areas, but local authorities can also create lists of locally valued assets. Most archaeological sites of significance are not scheduled, but rely on local identification and management for their protection.

LISTED BUILDINGS

Listing is by far the most commonly encountered type of designation. A listed building (or structure) is one that has been designated as being of special architectural or historic interest. The older and rarer a building is, the more likely it is to be listed. Buildings less than 30 years old are listed only if they are of very high quality and under threat. Listing is mandatory: if special interest is believed to be present, then the Department for Culture Media and Sport has a duty to add the building to the List.

Listed buildings are graded I, II* and II. Grade I buildings are of outstanding interest, and II* are particularly

important buildings of more than special interest; together they amount to 8% of all listed buildings. The remaining 92% are of special interest and are listed grade II.

There are over 376,000 listed entries on the NHLE of buildings of special architectural or historic interest. Entries on the statutory list sometimes group together a number of separate buildings: a terrace will be counted as one entry, rather than as separate units. Entries on this Register reflect how buildings are grouped and recorded on the statutory list.

Structures can occasionally be dual designated (both listed as buildings and scheduled as monuments). In such cases, scheduling controls take precedence.

SCHEDULED MONUMENTS

Scheduled monuments include single archaeological sites and complex archaeological landscapes. 19,850 examples have been designated because of their national importance. Scheduled monuments are not graded. They cover human activity from the prehistoric era, such as burial mounds, to 20th century military and industrial remains. For the millennia before written history, archaeology is the only testament to innumerable generations of people of whom there is no other record.

The later 20th century saw unprecedented changes to the landscape. As a result, some types of historic site that once were commonplace began to become rare. Those that survive often represent just small islands of what once characterised broad sweeps of our towns and countryside. Although protected by law, scheduled monuments are still at risk from a wide range of processes and intense pressures outside of the planning system. These include damage from cultivation, forestry and – often most seriously of all – wholly natural processes such as scrub growth, animal burrowing and coastal erosion. Scheduling is discretionary, and many archaeological sites of potential importance are not designated. Instead, they are managed through the planning system and other regimes.

REGISTERED PARKS AND GARDENS

There are 1,635 designed landscapes on the current Historic England Register of Historic Parks and Gardens of Special Historic Interest. These registered landscapes are graded I, II* or II, and include private gardens, public parks and cemeteries, rural parkland and other green spaces. They are valued for their design and cultural importance, and are distinct from natural heritage designations.

Inclusion on the Historic England Register of Historic Parks and Gardens brings no statutory controls, but there is a clear presumption in favour of upholding their

significance in government planning guidance, so they do gain protection. Local authorities are required to consult Historic England on applications affecting sites registered as grade I or II*, and the Gardens Trust on sites of all grades. The setting of other designated heritage assets can also protect registered landscapes.

REGISTERED BATTLEFIELDS

Historic England's Register of Historic Battlefields was set up in 1995, and is our youngest category of designation. Its aim is to protect and promote those sites where history was made through military engagement which can be securely identified on the ground. They range from the Battle of Maldon (991) to Sedgemoor (1685): almost half date from the period of the civil wars in the mid-17th century. These special places, where thousands were often killed, deserve our recognition and respect. Recently, additions have been made to the Register of Historic Battlefields for the first time since its creation. There are now 46 registered battlefields.

Protection is needed to prevent encroachment through inappropriate development, or insensitive (and damaging) metal detecting, which can permanently alter the archaeological record. As with registered parks and gardens, there is a clear presumption in favour of protecting registered battlefields in government planning policy.

PROTECTED WRECK SITES

England's 49 protected wreck sites represent a tiny proportion of the 33,000 or so pre-1945 wrecks and recorded casualties that are known to lie in the territorial waters. Wreck sites can be of importance for different reasons: the distinctive design or construction of a ship, the story it can tell about its past, its association with notable people or events and its cargo. The Protection of Wrecks Act 1973 empowers the appropriate Secretary of State to designate a restricted area around a vessel to protect it or its contents from unauthorised interference, and Historic England administers the attendant licensing scheme for divers seeking access.

CONSERVATION AREAS

Conservation areas are designated by local authorities and are areas of particular architectural or historic interest, the character or appearance of which it is desirable to preserve or enhance. For almost 50 years, ever since the 1967 Civic Amenities Act, conservation areas have proved a highly effective mechanism for managing change on an area-wide basis. There are currently 9,853 conservation areas in England including town and city centres, suburbs, industrial areas, rural landscapes, cemeteries and residential areas. They form the historic backcloth to national and local life and are a crucial component of local identity.

Criteria for inclusion on the Register

RISK ASSESSMENTS

Heritage assets included on the Register are risk assessed according to the nature of the site rather than the type of designation. Building or structure assessments are used for secular listed buildings and structural scheduled monuments, typically masonry remains. Archaeology assessments are used for scheduled earthworks and below-ground remains. Thus a scheduled monument may appear on the Register in either or both the building and structure and the archaeology sections depending upon what puts it at risk. Listed buildings that are in use as places of worship are assessed using the places of worship assessment. Registered parks and gardens, conservation areas, battlefields and protected wreck sites have their own assessments because they each have their own particular characteristics and factors that may put them at risk.

BUILDINGS AND STRUCTURES

To be considered for inclusion on the Register, buildings or structures must be:

- designated and included on the National Heritage List for England
- a grade I or II* listed building
- a grade II listed building in London
- a structural scheduled monument with upstanding remains
- in secular (non-worship) use

Buildings or structures are assessed on the basis of condition and, where applicable, occupancy (or use) reflecting the fact that a building which is occupied is generally less vulnerable than one that is not.

Occupancy (or use) is assessed as 'vacant', 'part occupied', 'occupied', 'not applicable', or occasionally, 'unknown'. Many structures fall into the 'not applicable' category for example: ruins, walls, gates, headstones or boundary stones.

Condition is assessed as 'very bad', 'poor', 'fair' or 'good'. The condition of buildings or structures on the Register is typically very bad or poor, but can be fair or, very occasionally, good. This reflects the fact that some buildings or structures are vulnerable because they are empty, underused or face redundancy without a new use to secure their future. Assessing vulnerability in the case of buildings in fair condition necessarily involves judgement and discretion. A few buildings remain on the Register in good condition, having been

repaired or mothballed, but still awaiting a new use or occupancy.

Buildings or structures are removed from the Register when they are fully repaired/consolidated, and their future secured either through occupation and use, or through the adoption of appropriate management.

PLACES OF WORSHIP

To be considered for inclusion on the Register places of worship must be designated and listed grade I, II* or II on the National Heritage List for England, and be used as a public place of worship at least six times a year.

Places of worship are assessed on the basis of condition only. If a place of worship is in very bad or poor condition it is added to the Register. This includes places of worship which are generally in fair or good condition but have major problems with one key element, like the tower.

Historic England has visited and assessed listed places of worship considered to be in poor or very bad condition according to local assessments. Those that are identified as at risk are included on the Register.

Once on the Register, places of worship can move through the condition categories (e.g. from very bad to poor, to fair, even good) as repairs are implemented and the condition improves, until they are fully repaired and can be removed from the Register. This means that there are some places of worship in good condition on the Register but with outstanding issues still to be resolved at the time when they were assessed.

ARCHAEOLOGY

To be considered for inclusion on the Register archaeological sites must be designated as scheduled monuments and included on the National Heritage List for England. Archaeology assessments cover scheduled earthworks and buried archaeology. The risk assessment is based on their condition and vulnerability, the trend in their condition, and their likely future vulnerability. A site's condition is expressed in terms of the scale and severity of adverse effects on it ranging from 'extensive significant problems', to 'minor localised problems'.

Archaeological entries are removed from the Register once sufficient progress has been made to address the identified issues, and a significant reduction in the level of risk has been demonstrated.

PARKS AND GARDENS

To be considered for inclusion on the Register parks and gardens must be designated as grade I, II* or grade II and included on the National Heritage List for England. Parks and gardens are assessed in terms of condition and vulnerability. Steps being taken by owners to address problems are also taken into consideration.

Parks and gardens assessed as being at risk are typically affected by development and neglect. They have frequently been altered by development or are faced with major change. The original function of these landscapes has often changed and divided ownership leads to the loss of their cohesive historic design.

Park and garden entries are removed from the Register once steps have been taken to address issues and positive progress is being made.

BATTLEFIELDS

To be considered for inclusion on the Register battlefields must be designated and included on the National Heritage List for England. Battlefields deemed to be at risk of loss of cultural significance are included on the Register.

The principal risks and threats are:

- development pressure e.g. encroachment of buildings
- pressures of particular use within the site e.g. arable cultivation
- damage e.g. unregulated metal detecting

Battlefields are removed from the Register either when damaging activities cease, are managed, or when threats recede due to effective planning.

WRECK SITES

To be considered for inclusion on the Register wrecks must be designated and included on the National Heritage List for England. Wreck sites are assessed based on their current condition, vulnerability and the way they are being managed.

Wrecks are vulnerable to both environmental and human impacts. Risks that contribute to inclusion on the Register range from unauthorised access to erosion and fishing damage.

The monitoring process ensures that the significance of the site is identified and maintained. In spite of the inherent difficulties in caring for this type of site, careful management must be maintained.

Wrecks are removed from the Register once an appropriate management and monitoring regime is operational.

CONSERVATION AREAS

Historic England has asked every local authority in England to complete (and update as appropriate) a survey of its conservation areas, highlighting current condition, threats and trends. Conservation areas that are deteriorating, or are in very bad or poor condition and not expected to change significantly in the next three years, are defined as being at risk.

The approach taken to assess conservation areas at risk has been refined since the first survey in 2008/2009. The information provides a detailed assessment of each conservation area. An overall category for condition, vulnerability and trend is included for each conservation area on this Register. Conservation areas identified as at risk in 2009, but not reassessed since using the revised methodology, are included on the Register but with limited information.

Conservation areas are removed from the Register once plans have been put in place to address the issues that led to the conservation area being at risk, and once positive progress is being made.

Reducing the risks

One of the primary aims of the Historic England Corporate Plan 2015-2018 is reducing the risk to heritage assets. In order to achieve this aim we are working to:

- better understand the nature and extent of risk
- encourage others to save and re-use heritage at risk
- build the capacity of the sector to deliver solutions for heritage at risk
- provide advice and grants to help remove heritage from the Register

Dedicated Heritage at Risk teams in our nine regional offices are tasked with achieving this aim.

Whilst each type of heritage asset and individual site will require its own approach and solution, there are some general approaches that are relevant to all 'at risk' assets. Finding solutions for heritage at risk requires working in close partnership with owners, local planning authorities and a wide variety of other organisations. The provision of clear advice is essential to further understanding of heritage at risk.

Maintenance and occupation or use (where appropriate) are essential in preventing heritage from becoming at risk. Maintenance of assets already at risk can prevent them from decaying further. Without maintenance, the cost of repair and consolidation escalates, the challenge for owners and occupiers increases, and the scope for affordable solutions declines.

The Heritage at Risk Register helps us understand what factors lead to heritage assets becoming at risk, what action is most likely to influence their condition and where resources can be focused to best effect. Historic Environment Records and local heritage at risk registers, maintained by local authorities, are additional repositories of information on local historic assets. They underpin the work of local authority historic environment services and can help improve the protection, conservation and management of heritage assets.

Historic England provides a wide range of published guidance on reducing the risks, including: finding partners, funding, new uses for heritage assets, and enforcing urgent works and repairs. These are available to download from our website, www.historicengland.org.uk. Key publications and guidance are listed on pages XV-XVI.

BUILDINGS AND STRUCTURES

Our nine regional teams can help existing and potential owners, developers and local authorities with the assessment of risk and the identification of appropriate programmes of repair. They can advise on the benefits

of additional survey and assessment, help with feasibility studies and with brokering solutions. In particularly difficult cases, they can draw on the additional expertise of our national advisers specialising in structural engineering, quantity surveying, development economics, enforcement and planning law. Historic England can help with access to funding as we work closely with grant providers including the Heritage Lottery Fund and Natural England. We have two principal grant streams ourselves: Repair Grants for Heritage at Risk for all asset types and Section 17 Management Agreements which are smaller grants for scheduled monuments. More information on funding can be found on the Historic England website.

We know how useful our own Register is in managing risk, prioritising action and engaging partners. We are therefore working with Civic Voice and voluntary groups to enable the compilation of local heritage at risk registers. We are also working with local authorities to encourage them to develop strategies for tackling buildings in poor condition. These strategies should include the use of enforcement powers; '[Stopping the Rot](#)' is our published guidance on this. Our Heritage at Risk Solicitor can provide training and support for local authorities considering enforcement action. In certain circumstances we can also provide [grant aid](#) to underwrite the cost of serving Urgent Works and Repairs Notices.

Building preservation trusts (BPTs) offer a tried and tested way of saving buildings at risk. We have close links with the [Architectural Heritage Fund](#) and fund their regional support officers to work across the country. They help BPTs and other not-for-profit organisations to access funding, carry out feasibility studies and develop solutions for buildings at risk. The [United Kingdom Association of Preservation Trusts](#) also provides information about support officers and BPTs. Guidance and case studies are available on the [Historic England](#) website.

PLACES OF WORSHIP

Regular maintenance helps to keep all buildings in good condition but those suffering major problems need repairs to minimise the risks to both the structure and the contents. Keeping drains and gutters clear so that water is taken away from the building efficiently is the most important thing congregations can do as this stops small problems developing into unnecessary crises. The overflowing gutter soon soaks the wall beneath, rots the roof timbers behind it and makes the whole building vulnerable.

In some areas congregations group together to engage reputable contractors at competitive rates to clear gutters and rainwater goods. Such cooperation enables them to get good quality work carried out at reasonable prices by firms that understand historic

buildings. The Maintenance Cooperatives project run by the Society for the Protection of Ancient Buildings will further help to connect, inform and empower those people who look after places of worship.

The Heritage Lottery Fund runs the [Grants for Places of Worship](#) scheme. The main focus of the scheme is fabric repairs but it also provides funds for modest changes to enhance community use of the building. Historic England's architects and surveyors, based in our regional Heritage at Risk teams, provide technical advice to the Heritage Lottery Fund on fabric repairs to ensure appropriate conservation standards are met.

The Government's [Listed Places of Worship scheme](#), enabling the reclaiming of VAT on eligible repairs, maintenance and authorised alterations, is available to all listed places of worship, whether they have obtained grants or are funding work themselves. Local and national charities also offer grants. The Government's [Listed Places of Worship Roof Repair Fund](#) offers grants to help make listed places of worship weather-tight, safe and open for use.

Historic England supports congregations wanting to keep their places of worship in use and recognises the need for appropriate new facilities such as kitchens and toilets that are sensitive to the building's special character. [New Work in Historic Places of Worship](#) helps congregations understand how changes can be achieved.

A network of support officers, employed locally but part funded by Historic England, offers direct advice and encouragement to congregations. Projects to effect repairs and develop necessary new facilities for both the community and visitors are breathing a new lease of life into these treasured parts of our heritage.

ARCHAEOLOGY

The excellent progress which is being made with reducing the number of scheduled monuments on the Register continues to demonstrate the value which owners and land managers are placing upon the positive management of archaeological sites.

The large majority of the 19,832 scheduled monuments in England are on land classified as agricultural. Effective information sharing with Natural England and Defra is therefore of great importance for prioritising management action and for targeting agri-environment grant schemes to best effect. This is especially important under the New Environmental Land Management Scheme (NELMS) which commenced in 2015. Natural England shared our corporate target of removing 25% of the scheduled monuments on the 2010 Register by 2015, which was achieved with 35% being removed. We also continue to work closely with the Heritage Lottery Fund to

identify the nationally important monuments deserving of grant-aid for enhanced conservation, presentation and access projects.

Loss and damage as a consequence of arable cultivation remains the greatest source of risk to scheduled monuments on the Register. The Conservation of Scheduled Monuments in Cultivation (COSMIC) project will provide updated risk assessments for all sites affected by arable cultivation on the Register. It provides bespoke prescriptions for reducing the risks from cultivation damage. In some cases, the COSMIC mitigation recommendations have already been acted upon by our local teams, resulting in over 130 entries being removed from the 2014 Register.

Analysis of entries on the Register shows that prehistoric barrows are one of the most 'at risk' types of archaeological site on the Register. Unmanaged woodland, tree, scrub and bracken growth remains one of the most widespread causes of long-term damage to both urban and rural archaeological sites - even if the effects are not as visible or as immediately destructive as other processes. In most cases simple, low cost but regular maintenance is the key. The delivery of this will always be reliant upon the help and goodwill of landowners.

PARKS AND GARDENS

Although a statutory list, the Register of Historic Parks and Gardens of Special Historic Interest in England in itself brings no additional statutory powers, instead it is used in the development control process to provide a valuable tool for the protection of the sites it includes. The Government's National Planning Policy Framework (NPPF) stresses the desirability of sustaining and enhancing the significance of all heritage assets and finding viable uses consistent with their conservation.

The NPPF states that great weight must be given to the conservation of sites included on the Register of Historic Parks and Gardens of Special Historic Interest and that substantial harm or loss of such features can only be justified in exceptional cases.

A great many historic parks and gardens are either privately owned or held in trust. In addition, local authorities are responsible for nearly all the public parks and cemeteries in our towns and cities. Registered parks and gardens are typically large, complex heritage assets, many of them in multiple ownership. It can take years to identify and implement proposals to improve their condition and trajectory. To help reduce the risks, Historic England encourages and works with owners to develop conservation management strategies. Landscape architects working in our Heritage at Risk teams can help tailor conservation management plans and funding packages

for individual landscape features or whole sites. We work with partners, such as Natural England and the Heritage Lottery Fund, to help source funding to secure sustainable futures for parks and gardens at risk.

BATTLEFIELDS

As with registered parks and gardens, the Register of Historic Battlefields brings no additional statutory controls to registered battlefields, but the National Planning Policy Framework makes it clear that registered battlefields are of equal significance to scheduled monuments, buildings listed grade I and II*, registered parks and gardens and protected wreck sites. Therefore, the positive conservation and management of registered battlefields is a core element of current heritage legislation.

Historic England continues to work with owners to develop management plans for registered battlefields and, in appropriate cases, contribute towards the cost of management plans. We work to develop positive landscape strategies with owners and partners such as Defra through Environmental Stewardship schemes. In some circumstances, we may encourage the conversion from arable to pasture of especially sensitive locations to protect battlefield archaeology from the effects of ploughing and as part of a wider drive to prevent unauthorised or damaging metal detecting.

Historic England also continues to encourage greater access to battlefields and the improvement of their amenity value and visitors' understanding of the impact these dramatic historic events had on our development as a nation.

Local authorities can also invite comments from the Battlefields Trust on planning applications affecting the setting of registered battlefield sites.

WRECK SITES

At the strategic level, the major sources of risk to protected wreck sites have been identified. In terms of high priority sites, practical requirements have also been implemented through conservation management plans and appropriate intervention.

Risks to protected historic wreck sites can often be reduced through education, provision of marker buoys, or planning policies that take full account of their national importance. However, some sites require significant resources to stabilise their condition or to carry out detailed archaeological assessments of their conservation requirements. Although Historic England has statutory power to allocate funds to promote the preservation and maintenance of protected wreck sites, its financial resources can solve only a small proportion of the problems.

In spite of the inherent difficulties with caring for this type of site, careful management must be maintained if we are to avoid the loss of wreck sites. It is therefore close cooperation between the owners of protected wreck sites (where known), authorised divers and all organisations charged with care for the marine and coastal environment, that will make the real difference to their long term survival.

Practical advice on the management of historic wreck sites, whether at the coast edge or under water, is available from [Historic England](#).

CONSERVATION AREAS

The reasons conservation areas become at risk are difficult to address as they can cover large areas of land; they include streets, spaces, archaeology and trees as well as buildings and structures and therefore involve many different owners and approaches to management. Looking after conservation areas is a responsibility shared by those of us who live, work or do business in them as well as those of us whose job it is to manage them or make decisions about their future.

Local authorities complete the Conservation Areas Survey, providing us with an understanding of what is particularly affecting the character and appearance of conservation areas, what is working well or what is putting them at risk. Strong planning policies, guidance and a clear management strategy for individual conservation areas, backed up by effective enforcement, are all critical in managing change in these areas. Local authorities across the country continue to see their resources reduced, and this is making their task more difficult to deliver. Armed with the information provided by conservation area surveys, we, local authorities and other partners will have the evidence to direct resources much more accurately towards those conservation areas at greatest risk.

There are opportunities for members of the local community to get involved with protecting and enhancing their conservation area, either individually or through groups. Some local groups have helped to prepare character appraisals and management plans for conservation areas whilst others have carried out their own assessments to identify management issues.

Key statistics

BUILDINGS AND STRUCTURES

- Nationally, 3.9% of grade I and II* listed buildings (excluding places of worship) are on the Register. In the West Midlands the percentage is 4.7% (92 listed secular buildings).
- 14 building or structure entries have been removed from the 2014 West Midlands Register because their futures have been secured, and 7 have been added.
- 59.3% of buildings or structures (112) on the West Midlands baseline 1999 Register have been removed because their futures have been secured, compared with the national figure of 60.8%.

PLACES OF WORSHIP

- Nationally, 6.3% of listed places of worship are on the Register. In the West Midlands, 6.3% (93) are on the Register.
- 6 places of worship have been removed from the West Midlands Register following repair work, and 23 have been added.

ARCHAEOLOGY

- 2,701 (13.6%) of England's 19,850 scheduled monuments are on the Register. 201 (14.2%) of the 1,416 scheduled monuments in the West Midlands are on the Register.
- 16 archaeology entries have been removed from the 2014 West Midlands Register for positive reasons, and 11 have been added.
- 45.4% of archaeology entries (118) on the West Midlands baseline 2009 Register have been removed for positive reasons, compared with the national figure of 38.6%.

- Nationally, damage from arable cultivation is the greatest cause of risk affecting 39% of archaeological entries on the Register. In the West Midlands the proportion is 35%.

PARKS AND GARDENS

- 94 (5.8%) of England's 1,633 registered parks and gardens are on the Register. Of the 152 registered parks and gardens in the West Midlands, 8 (5.3%) are on the Register.
- 1 park and garden entry has been added to the 2015 West Midlands Register.

BATTLEFIELDS

- Of the 46 registered battlefields in England, 6 (13.0%) are on the Register. Of the 6 registered battlefields in the West Midlands, none are on the Register.

WRECK SITES

- There are 49 protected wreck sites around England's coast, 4 of which are at risk. There are no protected wreck sites in the West Midlands.

CONSERVATION AREAS

- 8,298 of England's 9,853 conservation areas have been surveyed by local authorities and 505 (6.1%) are on the Register. Of the 796 conservation areas in the West Midlands, 738 have been surveyed and 60 (8.1%) are on the Register.
- 2 conservation areas have been removed from the 2014 West Midlands Register for positive reasons and 13 have been added.

HISTORIC ENGLAND FUNDING

- £966,000 in grant was spent on 19 entries on the West Midlands Register during 2014/15.

Risk assessments of heritage assets are based on the nature of the site. Buildings and structures include listed buildings (excluding listed places of worship) and structural scheduled monuments; archaeology assessments cover earthworks and buried archaeology.

Publications and guidance

Historic England has produced the following publications relating to heritage at risk, including:

Assessment of Heritage at Risk from Environmental Threat: Key Message (2013)

Buildings at Risk: a New Strategy (1998)

Caring for Places of Worship 2010 (2010) – a report on the condition of England's listed places of worship and the needs of the congregations

COSMIC 3 – Grappling with a 140-Year-Old Conservation Problem (2014) – Historic England Research News 21, available online

Counting our Heritage: a Heritage at Risk Survey for High Peak Staffordshire Moorlands by Community Volunteers (2013)

Historic England's Heritage at Risk National Strategy (2011-2015) (2012)

Heritage at Risk 2010 – report (2010)

Heritage at Risk: Conservation Areas (2009)

Heritage at Risk 2015 – national summary leaflet and regional summary leaflets for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire

Heritage at Risk Register 2015 – detailed listings for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire can be downloaded from our website or viewed on an interactive database: www.HistoricEngland.org.uk/risk

Monuments at Risk (2008) – summary of scheduled monuments at risk for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire

The Monuments at Risk initiative 2003-08 (2010)

Protected Wreck Sites at Risk: A Risk Management Handbook (2007)

Saving London: 20 Years of Heritage at Risk in the Capital (2010)

Stopping the Rot: A Guide to Enforcement Action to Save Historic Buildings (2011)

Vacant Historic Buildings: An Owner's Guide to Temporary Uses, Maintenance and Mothballing (2011)

HERITAGE AT RISK ON THE WEB

To find out more about the Heritage at Risk programme visit

<http://www.HistoricEngland.org.uk/risk> where you will find an interactive database providing detailed information on all heritage sites at risk nationally. Details of all nationally designated historic places in England are available in one place on the National Heritage List for England online database: <http://list.HistoricEngland.org.uk>.

Further information about the different classes of designated heritage assets, including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites can be viewed at the same address: <http://list.HistoricEngland.org.uk>.

CONSERVATION POLICIES AND GUIDANCE

The following publications are among the numerous guidance documents available on our website: <http://www.historicengland.org.uk/publications>

Caring for Historic Graveyard and Cemetery Monuments (2011)

Caring for Our Shipwreck Heritage: Guidelines on the First Aid Treatment and Conservation Management of Finds Recovered from Designated Wreck Sites Resulting from Licensed Investigations (2012)

Caring for Places of Worship (2010) – a practical booklet for everyone involved in caring for England's listed places of worship

Constructive Conservation in Practice (2008)

Constructive Conservation: Sustainable Growth for Historic Places (2013)

Conservation Principles, Policies and Guidance for the Sustainable Management of the Historic Environment (2008)

The Conservation, Repair and Management of War Memorials (2014)

Creativity and Care: New Works in English Cathedrals (2009)

The Disposal of Historic Buildings: Guidance Note for Government Departments and Non Departmental Public Bodies (2010)

Enabling Development and the Conservation of Significant Places (2008)

Farming the Historic Landscape: Caring for Archaeological Sites on Arable Land (2004)

Farming the Historic Landscape: Caring for Archaeological Sites in Grassland (2004)

Guidance notes and application forms for grants to local authorities:

- *Grants to Local Authorities to Underwrite Urgent Works Notices* (1998)
- *Acquisition Grants to Local Authorities to Underwrite Repairs Notices* (1998)
- *Repair Grants for Heritage at Risk* (2015)

Heritage Crime Prevention: A guide for Owners, Tenants and Managers of Heritage Assets (2013)

Heritage Crime Risk: Quick Assessment Tool (2013)

Heritage Works: the use of Historic Buildings in Regeneration (2013)

Managing Local Authority Heritage Assets: Some Guiding Principles for Decision Makers (2003)

New Uses for Former Places of Worship (2010)

New Work in Historic Places of Worship (2012)

Options for the Disposal of Redundant Churches and Other Places of Worship (2010)

Paradise Preserved: An Introduction to the Assessment, Evaluation, Conservation and Management of Historic Cemeteries (2007)

Pillars of the Community: the transfer of local authority heritage assets (2014)

Practical Building Conservation – revised ten-part series: Glass & Glazing; Metals, Mortars, Renders & Plasters; Stone; Timber; Building Environment; Concrete; Conservation Basics; Earth, Brick & Terracotta; Roofing (2012–2014)

Scheduled Monument Consent: A Guide for Owners and Occupiers (2009)

Shared Interest: Celebrating Investment in the Historic Environment (2006)

Theft of Metal from Church Buildings (2011)

Understanding Place: Conservation Area Designation, Appraisal and Management (2011)

Valuing Places: Good Practice in Conservation Areas (2011)

Key to the entries

This Register includes the following risk assessment types

- Building or structure
(grade I and II* listed buildings and structural scheduled monuments)
- Place of worship
(grade I, II* and II listed buildings)
- Archaeology
(scheduled monuments – earthworks and buried archaeology)
- Park and garden
(Registered parks and gardens)
- Conservation area
(Conservation areas)

ORDER

Entries are grouped and ordered alphabetically, first by County (dark grey bands) or Unitary Authority (light grey bands), and then by Local Planning Authority (National Park/Unitary Authority/District or Borough).

A blank band denotes the end of a county and the beginning of a unitary authority.

Sites that straddle more than one local planning authority are included under the lead authority.

Within each planning authority, entries are grouped by risk assessment type in the following order:

- Buildings or structures
- Places of worship
- Archaeology
- Parks and gardens
- Conservation areas

Within each risk assessment type, entries are ordered alphabetically by parish, locality and street/site name (except for conservation areas which are ordered by site name only).

DESIGNATION

The principal designation is noted for each entry and includes:

- Listed Building (LB) grade I or II*
- Listed Place of Worship grade I, II* or II
- Scheduled Monument (SM)
- Registered Park and Garden (RPG) grade I, II* or II
- Conservation Area (CA)

Other designations that apply to the designated site, including location within a World Heritage Site (WHS), are also noted.

If an entry is dual designated (both listed and scheduled), 'and' rather than a comma is used (eg 'Scheduled Monument and Listed Building grade I'). If a scheduled monument entry is dual designated with a number of listed buildings, each is separated by a semicolon.

The National Heritage List Entry Number is included for all entries (except conservation areas). If a site is dual designated, all relevant List Entry Numbers are noted.

CONDITION

For buildings (including places of worship), condition is graded as: 'very bad', 'poor', 'fair' and 'good'.

For sites that cover areas (scheduled monuments (archaeology assessments) and parks and gardens) one overall condition category is recorded. The category may relate only to the part of the site or monument that is at risk and not the whole site:

- extensive significant problems
- generally unsatisfactory with major localised problems
- generally satisfactory but with significant localised problems
- generally satisfactory but with minor localised problems
- optimal
- unknown (noted for a number of scheduled monuments that are below-ground and where their condition cannot be established).

For conservation areas, condition is categorised as: 'very bad', 'poor', 'fair' and 'optimal'.

If a site has suffered from heritage crime it is noted in the summary. Heritage crime is defined as any offence which harms the heritage asset or its setting and includes arson, graffiti, lead theft and vandalism.

OCCUPANCY/USE

For buildings (excluding places of worship) that can be occupied or have a use, the main vulnerability is vacancy or under-use. Occupancy (or use) is noted as follows:

- vacant
- part occupied
- occupied
- unknown
- not applicable

VULNERABILITY

Principal vulnerability is noted for archaeology assessments and may relate only to the part of the site that is at risk, and include:

- animal burrowing
- arable ploughing
- coastal erosion
- collapse
- deterioration – in need of management
- scrub/tree growth
- visitor erosion

For parks and gardens and conservation areas, vulnerability is noted as high, medium or low.

PRIORITY CATEGORY

Priority for action is assessed on a scale of A to F, where 'A' is the highest priority for a site which is deteriorating rapidly with no solution to secure its future, and 'F' is the lowest priority.

For buildings and structures and places of worship the following priority categories are used as an indication of trend and as a means of prioritising action:

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented
- C** Slow decay; no solution agreed
- D** Slow decay; solution agreed but not yet implemented
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

2014 priority categories are given in brackets, otherwise 'New entry' is noted.

'New entry – re-assessed' indicates an existing site on the Register that has been re-assessed using a different risk assessment methodology and is included on this year's Register under the new assessment type.

TREND

Trend for archaeology entries and parks and gardens may relate only to the part of the site that is at risk and is categorised as:

- declining
- stable
- improving
- unknown

For conservation areas trend is categorised as:

- deteriorating
- deteriorating significantly
- no significant change
- improving
- improving significantly
- unknown

OWNERSHIP

A principal ownership category is given for each entry, and if sites are in divided ownership, a 'multiple' ownership category is noted.

CONTACT

This is the member of the Historic England local team who acts as a first point of contact for the case, and to whom enquiries should be addressed.

For conservation areas, the contact is the conservation/planning officer at the relevant local planning authority (indicated by 'LPA').

We are not in any sense agents for the owners of the sites included, but we will endeavour to put people in touch with them where appropriate.

ABBREVIATIONS

CA	Conservation Area
HE	Historic England
HLF	Heritage Lottery Fund
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

Entries on the Register by local planning authority

Local planning authority	Building and structure entries	Place of worship entries	Archaeology entries	Park and garden entries	Battlefield entries	Wreck site entries	Conservation area entries
HEREFORDSHIRE, COUNTY OF (UA)							
Herefordshire, County of (UA)	20	25	23	1	0	0	3
SHROPSHIRE (UA)							
Shropshire (UA)	26	13	44	0	0	0	2
STAFFORDSHIRE							
Cannock Chase	0	0	0	0	0	0	0
East Staffordshire	2	0	5	0	0	0	2
Lichfield	2	0	5	0	0	0	1
Newcastle-under-Lyme	3	0	1	0	0	0	1
Peak District (NP)	1	0	2	0	0	0	0
South Staffordshire	1	0	4	0	0	0	1
Stafford	3	0	2	0	0	0	3
Staffordshire Moorlands	6	1	2	0	0	0	3
Tamworth	2	0	1	0	0	0	0
STOKE-ON-TRENT, CITY OF (UA)							
Stoke-on-Trent, City of (UA)	7	4	0	0	0	0	5
TELFORD AND WREKIN (UA)							
Telford and Wrekin (UA)	2	3	8	0	0	0	0
WARWICKSHIRE							
North Warwickshire	8	0	6	0	0	0	0
Nuneaton and Bedworth	2	0	0	0	0	0	0
Rugby	0	1	9	1	0	0	0
Stratford-on-Avon	5	6	14	0	0	0	2
Warwick	3	2	9	2	0	0	0
WEST MIDLANDS							
Birmingham	10	6	1	0	0	0	8
Coventry	9	1	2	0	0	0	3
Dudley	1	6	2	0	0	0	4
Sandwell	2	0	2	0	0	0	2
Solihull	0	0	0	0	0	0	0
Walsall	1	2	0	0	0	0	7
Walsall / Sandwell [†]	0	0	0	1	0	0	0
Wolverhampton, City of	1	4	0	0	0	0	9
WORCESTERSHIRE							
Bromsgrove	2	3	2	1	0	0	1
Malvern Hills	2	7	4	1	0	0	1
Redditch	0	0	1	0	0	0	0
Worcester	2	0	1	0	0	0	1
Wychavon	6	9	8	1	0	0	0
Wyre Forest	2	0	0	0	0	0	1
TOTAL	131	93	158	8	0	0	60

[†] Sites that cross local planning authority boundaries

HEREFORDSHIRE, COUNTY OF (UA)



© Historic England

SITE NAME:	Gatehouse buildings at Wigmore Abbey, Grange, Adforton
DESIGNATION:	Scheduled Monument and Listed Building grade I, 2 LBs
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1005359 and 1179921

Remains of a late C12 and C14 abbey. The Gatehouse comprises two buildings, one is without a roof and in very poor condition. Survey work to inform conservation is required. Structural assessment by Historic England has indicated that elements of collapse are likely.

Contact: Sarah Lewis 0121 625 6886



© Historic England

SITE NAME:	Ruined Church of St Mary, Avenbury
DESIGNATION:	Scheduled Monument and Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1005356 and 1349633

A ruined C12 church. The tower stands to full height, the roof survived to the mid C20 but has fallen in. The walls of the nave and chancel are half collapsed and survive only to a few feet in places. Fragments of decorated interior plaster survive. This building is in very bad condition. Vegetation clearance has been carried out by the owners under a Section 17 Management Agreement. The walls are generally stable but are highly exposed.

Contact: Bill Klempereer 0121 625 6847



© Historic England

SITE NAME:	Churchyard cross in St Bridget's churchyard, Bridstow
DESIGNATION:	Scheduled Monument, LB grade II
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1017690

Remains of a scheduled medieval churchyard cross including base and some of the shaft. The fragile nature of the stone steps surrounding this medieval cross is being addressed through a Section 17 Management Agreement funded by Historic England. Large open vertical joints and unstable stones at various levels on the north side of the cross have led to it being placed on the Heritage at Risk Register. Works are due to take place towards the end of 2015.

Contact: Imogen Sambrook 0121 625 6854



© Historic England

SITE NAME:	Belmont House, Clehonger
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1167079

Late C18 country house by James Wyatt, extended and remodelled by EW Pugin c1860. The basement is used as a club house for the golf course, but the rest of the building is unused. Some holding repairs have been carried out and the building is watertight. There are some areas of weathering and deterioration. Resolution lies in finding and funding an appropriate and sustainable solution for building, this should be encouraged through the planning process.

Contact: Bill Klempereer 0121 625 6847



© Historic England

SITE NAME:	Clifford Castle, Clifford
DESIGNATION:	Scheduled Monument and Listed Building grade I
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1001774 and 1167903

Late C13 castle. Some propping and fencing carried out in the past and most recently in 2013. New owners have carried out further beneficial vegetation clearance. An archaeological survey has been commissioned and structural inspection has been carried out. Undermining of the tower is a particular concern. A repair scheme is in discussion with the owner.

Contact: Chris Miners 0121 625 6835

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Craswall Priory ruins, Craswall
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (A)
OWNER TYPE:	Private, multiple owners
LIST ENTRY NUMBER:	1014536 and 1342128

The remains of one of only three Grandmontine houses in England dating from 1220 to 1225. Severely exposed position has contributed to priory's decline. A Section 17 Management Agreement is in place for ongoing management of vegetation and urgent repairs to the piscine have been completed. Further consolidation and the repair of exposed and deteriorating architectural details may be addressed under a new Natural England stewardship scheme.

Contact: Imogen Sambrook 0121 625 6854



© Historic England Archive

SITE NAME:	Hereford city walls, Hereford
DESIGNATION:	Scheduled Monument, 2 LBs, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (B)
OWNER TYPE:	Local authority, multiple owners
LIST ENTRY NUMBER:	1005528

Medieval city walls which have been fully recorded. A programme of consolidation work has been carried out to some sections in the Council's ownership, but other sections affected by vegetation still need addressing. Sections in disputed ownership are particularly vulnerable. The Council has produced a Conservation Management Plan which identifies repair needs and a future plan of action. Contact is ongoing with various parties to address the most vulnerable areas.

Contact: Imogen Sambrook 0121 625 6854



© Historic England

SITE NAME:	Huntingdon Castle, Huntingdon
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Fair
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1002939 and 1157544

Castle remains C13 or earlier. Repaired in 1403 and abandoned in 1460 (although one tower still in use as a prison in 1521). The motte and inner bailey are surrounded by a ditch and outer bailey. Traces of a curtain wall and C13 semi circular tower have survived in a fair condition although they are very overgrown. Work to control vegetation is being carried out by the owner. Unstable earthworks need a long term management plan which will hopefully be addressed through a Countryside Stewardship Agreement.

Contact: Imogen Sambrook 0121 625 6854



© Historic England

SITE NAME:	Remains of Limebrook Priory, Limebrook, Lingen
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (F)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1001722 and 1157383

C13 nunnery of which only a single ruined building survives. Sheep are damaging the site. A Historic England structural assessment has been carried out and a scheme of works has been identified for agreement with the owner.

Contact: Imogen Sambrook 0121 625 6854



© Historic England

SITE NAME:	Lyonshall Castle, Lyonshall
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1001720 and 1301287

C13 keep enclosed by inner bailey and outer enclosures. The owners are undertaking maintenance of earthwork site in accordance with Historic England advice. Much vegetation control has been carried out. A survey was carried out to inform repairs and masonry consolidation. The property has recently changed hands and the new owners hope to carry out the works with a Section 17 Management Agreement.

Contact: Imogen Sambrook 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Outbuilding east of Marstow Court (formerly listed as the Granary at Marstow), Marstow
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1214715

Reputedly associated with manor of the Knights Hospitallers who held lands in Marstow and probably originally a house, C15. Built of sandstone rubble under a Welsh slate roof with C18 and C19 alterations. The building is now in agricultural use. The stonework and pointing are generally in poor condition, there are slipped and missing roof slates and the windows and doors are in poor condition. A scheme for conversion has been approved.

Contact: Imogen Sambrook 0121 625 6854



© Historic England

SITE NAME:	Barn and attached cowhouse built onto Glibes Farmhouse, Michaelchurch Escley
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1223446

A four bay barn with an extra bay for a cow house, and further loft bay linking to farmhouse which has collapsed. Probably C18 in date. A temporary metal sheet roof protects the building which is unused and in need of comprehensive repair. The owner has no proposals for the repair of the building, and its future is uncertain.

Contact: Sarah Lewis 0121 625 6886



© Historic England

SITE NAME:	Glibes Farmhouse, Michaelchurch Escley
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1223549

A remote farmhouse probably C17 with C18 alterations. The walls are of thin coursed rubble stone. The roof was of stone tiles but has been temporarily replaced in metal sheet. The building is unoccupied and in need of comprehensive repair. A programme of urgent works including repair of the temporary roof and rebuilding of fallen masonry has improved its condition but the chimney stacks are deteriorating and further long term repairs are necessary.

Contact: Sarah Lewis 0121 625 6886



© Historic England

SITE NAME:	Dovecote south of Much Cowarne, Much Cowarne
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1349680

A round stone dovecote, probably medieval, with conical tiled roof and the remains of a C17 or C18 wooden louver. Originally connected with Cowarne Court which no longer exists, the dovecote is now isolated in the corner of a field. There are holes in the roof at eaves allowing small trees to take root in the wall top resulting in structural deformity below. The interior is in good condition with all nesting boxes in situ. A structural assessment has been carried out and an Historic England grant aided repair scheme is being developed.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Urishay Castle, Peterchurch
DESIGNATION:	Scheduled Monument and Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1014547 and 1099487

Remains of C12 motte castle, a ruined C17 house and a partly ruined C16 chapel. The chapel is stable and in good condition, the C17 house is not. Without a roof the masonry is disintegrating. Lintels are failing and in danger of collapse. Requires assessment of structure to establish survival of medieval fabric and future strategy.

Contact: Sarah Lewis 0121 625 6886

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Snodhill Castle, Snodhill, Peterchurch
DESIGNATION:	Scheduled Monument and Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1015168 and 1172756

Snodhill Castle was a key element in the Norman line of defence through the English and Welsh Marches. The standing remains are in very bad condition with recent falls of masonry from the walls and undermining by badgers. Historic England has carried out a full survey of the site. A professional team has been appointed to draw up proposals for urgent stabilisation works which will form the basis for working out funding options in the autumn.

Contact: Sarah Lewis 0121 625 6886



© Historic England

SITE NAME:	Court Cottage (formerly Court Farmhouse), Preston Wynne
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1099380

A former hall house dating from C14 which retains a spere truss and cruck truss of high architectural quality. This building is now used for storage with residential accommodation in the later C17 house which was added to the south end. Grant aid achieved essential stabilisation and roofing works but the condition of the building continues to decline.

Contact: Sarah Lewis 0121 625 6886



© Historic England

SITE NAME:	Penyard Castle, Weston under Penyard
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1005385 and 1099662

Remains of C14 castle in split ownership and land use. Part medieval and post medieval. The remains in private ownership are in a fair state. A programme of vegetation control was undertaken by the Forestry Commission. A repair grant from Historic England for stabilisation of the medieval fabric is under discussion, with the survey now completed.

Contact: Imogen Sambrook 0121 625 6854



© Historic England

SITE NAME:	Post-Medieval house at Willey Court, Willey
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1017251

This monument includes the buried, earthwork and upstanding remains of the post-medieval house and gardens at Willey Court. Actively involved in management, the owners are in negotiations with Historic England to determine an appropriate strategy for consolidation and management of the site, following on from previous successful agreements.

Contact: Imogen Sambrook 0121 625 6854



© Historic England

SITE NAME:	Church of St Andrew, Wolferlow
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1217197

Early C12 church restored in 1863 by Kempson. Of stone construction under a clay tile roof with timber framed tower and shingle spire. The church has not been used for worship since 2006 and sits in an isolated location. Rainwater goods are absent and the roof has slipped and broken tiles. A sale has now been agreed by The Church Commissioners and a proposal for re-use as a dwelling has been approved but not implemented.

Contact: John Yates 0121 625 6846

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Church of St Mary, Abbey Dore
DESIGNATION:	Listed Place of Worship grade I, SM
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1099794

Large parish church created in c1634 from the derelict Abbey church of the dissolved Cistercian Dore Abbey. The c1220 transepts crossing and chancel remain with a C17 tower inserted on the south east angle of the crossing. There are now repair problems with the roof and drainage from this tower as well as the sandstone ashlar walling. The sandstone slates of all the main roofs have been renewed except the north transept chapel roof which still has the original slates. These have now failed and are leaking and need urgent re-slating.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Bartholomew, Church Lane, Ashperton
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Very bad
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1098909

Large parish church at the edge of a small village. Cruciform plan of nave chancel and transepts all of the C14. The west tower added in the C18. Tower roof and valley gutter leaks causing rot to the tower roof structure. The partly cement rendered walls are causing dampness in the walls and floor of the main body of the church. A Heritage Lottery Fund grant has been applied for.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Peter, Birley with Upper Hill
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1081970

Small parish church in a large level churchyard in the middle of a scattered village. C12 and C13 nave and chancel and late C14 south chapel. The west tower is c1200. Historic England and Heritage Lottery Fund grant-aided repairs have remedied tower roof problems and the stonework to the chancel and vestry. However the sandstone rubble stonework is still poor on the tower and south chapel gable.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of Holy Trinity, Main Street, Bosbury
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1098890

Large rural parish church. Circa 1200 aisled nave and east chancel with C15 south entrance porch and c1510 chantry chapel, with C19 north vestry. It has a C13 detached bell tower with a C19 roof to the south. Walls of sandstone rubble with ashlar dressings, tiled roofs to the chapel. The north aisle roof and the tower slate roof need urgent renewal to stop decay. The north vestry has structural movement at the external corners and there is ground level damp causing internal decay. A Heritage Lottery Fund repair grant has been applied for and project development work is complete.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Michael, Brampton Abbotts
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1099258

A small rural C15 parish church. The sandstone roof slates over the nave and chancel are in a poor condition with water ingress causing falls of ceiling plaster. The building is currently closed for worship but the Churches Conservation Trust Regeneration Group is working with the Brampton Abbotts Regeneration Group to develop new uses for the building, alongside worship.

Contact: Chris Miners 0121 625 6835

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Chapel at Brockhampton Park, Brockhampton
DESIGNATION:	Listed Place of Worship grade II*, RPG grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1349630

Tiny chapel in the grounds of Brockhampton Park. Built 1798 by Byfield in the Gothic Revival style of a nave and west tower. Grey sandstone ashlar with battlemented parapets on the 'show' sides but coursed rubble and conventional eaves to the north. Structurally deflected slate roof. The ashlar mouldings are heavily eroded.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Peter, Bromyard and Winslow
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1307758

Large medieval civic church in the centre of Bromyard. The 2006 and 2011 Quinquennial Inspections identified stonework and roof repairs as necessary. A programme of work has been agreed and it is hoped that this will commence soon. The roof valleys have been repaired but now the slate roofs are the main problem with fixing failures. A Listed Places of Worship Roof Repair Fund grant has been awarded.

Contact: Chris Miners 0121 625 6835




© Historic England

SITE NAME:	Bollingham Chapel, A4111, Eardisley
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Very bad
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1157325

Small chapel of three bay nave and chancel. Rebuilt between 1865 and 1867 adding south porch and bellcote. The nave roof is C14 and the roof is covered with sandstone slates. These are heavily overgrown with moss and ferns decaying the slates. The interior is now netted to catch falls of plaster from the roof lining.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St John the Baptist, Upper Road, Eastnor
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1266756

Large parish church. Rebuilt by GG Scott in 1852 except for the C14 west tower, C13 arcade and C12 south doorway. Generally sandstone ashlar in the C13 style and with tiled roofs. The sandstone ashlar of the tower is in poor condition with cracking, erosion and open jointing.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Michael, Felton
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1177507

Small rural parish church rebuilt in the Decorated style by T Nicholson in 1853 re-using older fabric. The oak shingled spire was added in 1891. The walls are sandstone rubble with ashlar dressings and the roofs are tiled. The tower parapet gutters leak and have decayed the tower roof structure. The chancel valley gutter is also leaking and needing repair. A Heritage Lottery Fund repair grant has been awarded and project development works are nearly complete.

Contact: Chris Miners 0121 625 6835

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Church of St John the Baptist, Grendon Bishop
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Very bad
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1307407

Parish church built in the 1780s which now looks Victorian in character. The church has severe damp problems, slipped tiles are allowing water into the chancel.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Dubricius, Hentland
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1288593

Small rural parish church with C11 vestiges but C13 and C14 nave and chancel. Restored by JP Seddon in 1853 and with C19 vestry and porch. The late C14 tower has structural cracking on the west side. Internal plaster falls have happened in the nave and chancel west end roof. The sandstone rubble walls are heavily eroded. The sandstone slate roof pitches and the plain clay tiled pitches have slipped or missing slates and tiles.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Peter, St Peter's Square, Hereford
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1196883

Large urban parish church in the city centre of Hereford. C13 tower and 4 bay arcade, chancel and south chapel all from c1300. Extensively rebuilt by Thomas Nicholson between 1880 and 1885. The valley between the nave and north aisle leaks and the south pitch slate roof needs urgent renewal.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Mary, Hope under Dinmore
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1301623

Small but lengthy parish church on an isolated hillside setting next to the A49. Heavily restored by Kempson in 1877 and 1896 but the small west tower and north chapel still have C12 and C13 fabric. The north chapel gable has structural movement, the cast iron gutters are cracked, rusting and leaking. The tower sandstone rubble is heavily eroded.

Contact: Chris Miners 0117 975 1308



© Historic England

SITE NAME:	Church of St Andrew and St Mary, How Caple
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1166452

Parish church in a hillside setting overlooking the River Wye. C14 chancel with a later low pitched roof. The tower, nave and chancel are all from 1693 to 1695 and the windows C19. The rainwater goods are undersized and failing. The ashlar stonework of the tower is delaminating and falling. The parapet stonework of the tower is structurally unsound next to the vice door.

Contact: Chris Miners 0121 625 6835

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Church of St Michael, Knill
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1081487

Small rural parish church on the border with Wales. Heavy moss growth is obscuring a sandstone slate covered nave and chancel roof with many faults that are leading to water ingress. Access difficulties onto the tower roof are leading to faults derived from a lack of maintenance.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Mary, Middleton on the Hill
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Very bad
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1167020

Small parish church. C12 nave and chancel with C13 west tower. Sandstone rubble walls with sandstone ashlar dressings and tiled roofs. The nave roof tiling is falling off and the rafters have decayed. The tower stonework needs replacement of severely eroded stonework. An Historic England and Heritage Lottery Fund Repair Grant for Places of Worship has been awarded and repairs are expected to be complete in 2015.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Peter, Pipe and Lyde
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	F (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1172739

Small parish church set at the end of a small village and facing the A49. Late C12 nave and C14 chancel largely rebuilt by F Kempson in 1874 who also added the broach spire to the C13 tower. The roof needs repair and work also needed to the tower. A Historic England and Heritage Lottery Fund Repair Grant for Places of Worship has been allocated to remedy the problem and the repair work is being completed on site.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Andrew, Pixley
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1098989

Small single-cell rural parish church in a farmyard setting. C13 core with C14 chancel and roof, the integral bellcote is C19 with C17 windows. A Historic England and Heritage Lottery Fund grant-aided project repaired the roof, bellcote and rainwater system but structural instability needs repair in the north east corner and the timber-framed entrance porch.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Mary, Staunton on Wye
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1166457

Large rural parish church high in a hillside village overlooking the River Wye. C12 core in the nave, the west tower C13 with the chancel and porch from the C18. The hipped tiled roof has holes and the nave sandstone slate roof has slipped slates. The gutter on the north side has failed. The internal plaster is damp affected and part fallen.

Contact: Chris Miners 0121 625 6835

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Church of St Mary, Stoke Edith
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Very bad
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1099825

Large parish church, rebuilt by the Foleys of Stoke Edith Park in 1740 in the Palladian style by Henry Flitcroft. The C14 tower with truncated spire was retained. The roof leaks causing rot in the nave beam and falls in the ornate plasterwork. The ashlar facings are eroding severely. A few stones have fallen from the tower and spire.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Mary, Turnastone
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1224950

Small parish church in a large level churchyard in the centre of a tiny village. Integral C12 nave and C13 chancel. C16 east window where structural cracking in the sandstone rubble has affected the east gable.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Michael, Upper Sapey
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Very bad
PRIORITY CATEGORY:	B (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1275895

Small rural parish church in a sloping churchyard at the edge of a small village. Middle to late C12 chancel and nave with surviving north and south doorways. Restored in 1860 with tower and timber broached spire added. There have been recent grant-aided repairs to the roof but the spire boarding, together with stonework and structural issues at the east end, now needs urgent repair. A Heritage Lottery Fund Grant for Places of Worship for the required repairs has been awarded and the specification is being developed.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Peter and St Paul, Church Road, Weobley
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1301343

Large parish church at the edge of the village of Weobley. C13 nave and flanking aisles with C14 chancel extension and north west tower. Flaking sandstone ashlar on the tower and spire is not practical to repair at present but is being managed by high level metal guards and ground level fencing.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Lawrence, Church Lane, Weston under Penyard
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1348828

Rural parish church overlooking a small village. Core of late C12 nave and north arcade, C13 chancel and C14 tower and porch. The sandstone roof slates are failing with splits and falls on the nave and aisle roof pitches. A Listed Places of Worship Roof Repair Fund grant has been awarded for repairs in March 2015.

Contact: Chris Miners 0121 625 6835

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Site of Rotherwas House, earthwork remains of formal gardens, and Rotherwas Chapel, Dinedor		
DESIGNATION:	Scheduled Monument, LB grade II*	LIST ENTRY NUMBER:	1014880
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Promontory fort on Dorstone Hill, Dorstone		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014544
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Roman settlement, Ford and Stoke Prior / Humber		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005322
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Moated site 360m north of Joanshill Farm, Fownhope / Mordiford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019853
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Ring ditches and rectilinear enclosures east of Tupsley, Hampton Bishop		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005348
CONDITION:	Unknown	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Other not for profit group	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Row Ditch (entrenchment), Hereford		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1001780
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Dumping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Huntington Castle, Huntington		
DESIGNATION:	Scheduled Monument and Listed Building grade II	LIST ENTRY NUMBER:	1002939 and 1157544
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Motte castle 280m south of New Buildings Farm, Kentchurch		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016354
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Kingsland Castle, Kingsland		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1007318
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Offa's Dyke: section north west of Holme Marsh extending 615 yards (560 metres) to the railway, Lyonshall		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001735
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alison MacDonald 0121 625 6827
SITE NAME:	Ringwork 750 metres west of Grove Farm, Much Dewchurch		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014893
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Bowl barrow 460 metres south of Milton Cross, Pembridge		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014103
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Bowl barrow 490 metres south east of Milton Cross, Pembridge		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014112
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Bowl barrow 550 metres south east of Milton Cross, Pembridge		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014895
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	North Herefordshire Rowe Ditch, Pembridge / Staunton on Arrow		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005382
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Shell keep castle and associated fishponds at Snodhill, Peterchurch		
DESIGNATION:	Scheduled Monument and Listed Building grade II*	LIST ENTRY NUMBER:	1015168 and 1172756
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Sutton Walls (camp), Sutton / Marden		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001747
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Roman fort at Coppice House, Tedstone Wafer		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005363
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Gardening	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Wall Hills Camp, Thornbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001748
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Motte and bailey, west of St Mary's Church, Walterstone		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001778
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Weobley Castle, Weobley		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1005384
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Roman town of Ariconium, Weston under Penyard		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005364
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Offa's Dyke: Upperton Farm, two sections extending 195 yards (180 metres) and 370 yards (340 metres) south from Yazor, Yazor		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001736
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alison MacDonald 0121 625 6827



© Historic England

SITE NAME:	Shobdon	Early C18 formal gardens (much modified) and mid C18 landscape park, part of which is open to the public. Although some garden buildings survive, their context is much altered; commercial fruit growing, a caravan park, a chicken farm, commercial forestry and intensive agriculture characterise the historic park.
DESIGNATION:	Registered Park and Garden grade II, 10 LBs, 3 SMs	
CONDITION:	Extensive significant problems	
VULNERABILITY:	Medium	
TREND:	Stable	
NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	
LIST ENTRY NUMBER:	1000894	Contact: Kim Auston 0117 975 0696

SITE NAME:	Kington		
DESIGNATION:	Conservation Area, 122 LBs, SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Sarah Lowe (LPA) 01432 261950

SITE NAME:	Ross-on-Wye, Ross-on-Wye / Bridstow		
DESIGNATION:	Conservation Area, 151 LBs, 4 SMs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Sarah Lowe (LPA) 01432 261950

SITE NAME:	Widemarsh Common, Hereford		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Sarah Lowe (LPA) 01432 261950

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SHROPSHIRE (UA)



© Historic England Archive

SITE NAME:	Wattlesborough Castle (uninhabited parts), Alberbury with Cardeston
DESIGNATION:	Scheduled Monument and Listed Building grade I, part in LB grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1006285 and 1366883

Remains of a large square tower of castle with fine quality detailing, now without roof. Probably late C13 for Sir Robert Corbet. There has been a recent fall of masonry from high level. The owner is considering consolidation and re-roofing for domestic use.

Contact: Sarah Lewis 0121 625 6886



© Historic England

SITE NAME:	Alberbury Castle, Alberbury, Alberbury with Cardeston
DESIGNATION:	Scheduled Monument and Listed Building grade II, 2 LBs, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1020662 and 1175344

Remains of tower keep from C13 castle. Rapidly eroding with rampant ivy cover and mortar erosion and undermined masonry. A survey was commissioned by Historic England as a basis for designing a programme of urgent repair works for discussion with the owner. Natural England funding may be available via existing Stewardship scheme.

Contact: John Tiernan 0121 625 6839



© Historic England Archive

SITE NAME:	Barn to west of Hall Farmhouse, Aston Eyre
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1053205

Used as a barn for many years, this building is in fact a medieval hall with a solar wing and dates from the C15. Consent has been given for conversion back to residential use. The owner is carrying out repairs and has undertaken a detailed recording of the stonework. Structural repairs and re-roofing have been carried out so the building is now wind and weather proof.

Contact: Sarah Lewis 0121 625 6886



© Historic England

SITE NAME:	48 Mill Street, Bridgnorth
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1177762

c1675, this three storey building forms part of a commercial premises used as an antique centre. The oldest building fronting the road was in poor condition but extensive repairs have been completed with the benefit of a Historic England grant. This part of the property is still vacant, but the owners have plans for re-use and the building will be removed from the Register when it is occupied once more.

Contact: John Tiernan 0121 625 6839



© Historic England Archive

SITE NAME:	Rockley Farmhouse, Chirbury with Brompton
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1054405

Early C17 farmhouse with mid C20 alterations. The farmhouse is run-down but watertight. It is in need of basic repair and maintenance work.

Contact: John Yates 0121 625 6846

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Trinity Hospital, Hospital Lane, Clun
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Charity (non-heritage)
LIST ENTRY NUMBER:	1054455

Known as The Hospital of the Holy and Undivided Trinity, these almshouses were founded in 1607 by Henry Howard, Earl of Northampton and built in 1618. A Warden's house and chapel were added in the second half of the C19. Parts of the perimeter wall - which incorporates a mortuary and encloses the building complex - are in very poor condition and some sections have collapsed. Large sections of the wall are colonised by vegetation and saplings which threatens further instability and loss of integrity.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Old Hall and attached garden wall, Old Marton, Ellesmere Rural
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1307787

Large farmhouse, mid to late C16 with later additions and alterations. Timber-framed with painted brick and rendered infill. The owner has repaired the roof and repairs to the timber frame and infill panels have commenced. The adjoining C18 garden wall, of red brick with moulded stone coping, has partially collapsed.

Contact: Sarah Lewis 0121 625 6886



© Historic England

SITE NAME:	Ludlow town walls, Ludlow
DESIGNATION:	Scheduled Monument and Listed Buildings - 8 grade II, 2 CAs
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1006278 and 1219038; 1289747; 1291656; 1202827; 1202825; 1202826; 1219077; 1282007

Medieval town wall in multiple ownership. Historic England has helped to fund a town walls management plan and the repair of substantial sections in local authority ownership. A Town Walls Trust has been established to promote the protection and care of the walls. A major section of wall below the parish church collapsed in spring 2013, responsibility for repair is under dispute. Other small collapses have taken place on the south section where ownership is also disputed.

Contact: Sarah Lewis 0121 625 6886



© Historic England

SITE NAME:	Remains of Lea Castle at Lower Lea Farm, Lea, Lydham
DESIGNATION:	Scheduled Monument and Listed Building grade II, 2 LBs
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1021064 and 1054509

Fragmentary remains of a C12 castle surviving in the middle of a working farm. This was formerly a castle of the Bishops of Hereford. Victorian house abuts the castle remains which are heavily overgrown. Urgent need to reduce ivy growth, to be followed by repair and consolidation of masonry. An application for Historic England grant aid is expected.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Charllotte Furnace, Neenton
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1004785

C17 blast furnace for the manufacture of pig iron from ironstone, using charcoal as fuel. A relic of the long extinct local iron industry. There are structural problems and areas of unconsolidated masonry in need of long term repair. Temporary propping has been carried out and management agreements have been used to control vegetation but a longer term repair solution is needed.

Contact: Jenny Marriott 01691 780677

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Pentre Isaf, Oswestry
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1054276

Pentre Isaf is a farm complex with an attractive courtyard of outbuildings. The grade II* stone farmhouse is C17 but hides within it a C15 timber-framed hall. The owner is making good progress with a comprehensive programme of repairs.

Contact: Sarah Lewis 0121 625 6886



© Historic England

SITE NAME:	Pitchford Hall, Pitchford
DESIGNATION:	Listed Building grade I, RPG grade II
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1177907

A large timber-framed country house built c1560-70 for Adam Ottley but with an earlier C14 or C15 core. This is an outstanding example of a timber-framed building. The owner has completed some works but maintenance of the roof, rainwater goods and infill panels is required. The property is vacant, but discussions have been opened about a maintenance regime and the development of plans for re-use.

Contact: Sarah Lewis 0121 625 6886



© Historic England

SITE NAME:	Nag's Head engine house, Pontesbury
DESIGNATION:	Scheduled Monument
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1018467

An engine house on the Pontesford coalfield which provided coal for the Pontesford lead smelters which served the south Shropshire lead mines. The building is in very poor condition and invasion of the structure by ivy and overhanging trees is an additional threat. The monument has been identified as part of a project in the Stiperstones and Corndon Hill Landscape Partnership funded by the Heritage Lottery Fund. A survey, recording and design of a repair programme have been completed and negotiations are underway with the owner.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Brogyntyn Hall, Brogyntyn Park, Selattyn and Gobowen
DESIGNATION:	Listed Building grade II*, RPG grade II, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (A)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1367373

An elegant country house, mainly C18 extended in the C19; most of the interior is of this date. The property stands at the centre of the grade II park with pleasure grounds, a walled garden, lodges, cottages and model farm. Last used as offices, the property has been unoccupied for over a decade. Rainwater and dry rot are the principal threats. Current ownership does not include the whole of the park. Planning permission for an enabling development of housing in the grounds has been permitted to secure the repair of the hall subject to a S.106 agreement.

Contact: Sarah Lewis 0121 625 6886



© Historic England

SITE NAME:	Town walls, Shrewsbury
DESIGNATION:	Scheduled Monument, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Local authority, multiple owners
LIST ENTRY NUMBER:	1003710

Medieval town walls C13. Coursed and squared sandstone. The defences are subject to ongoing repair but certain sections are deteriorating. Soft sandstone continues to weather and erode along roadsides and scrub is affecting the base of the walls in some areas. A Conservation Management Plan has been produced and actions from this should now be implemented.

Contact: Imogen Sambrook 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME: Apprentice House of former Ditherington Flax Mill, Spring Gardens, Ditherington, Shrewsbury

DESIGNATION: Listed Building grade II*, CA

CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: D (D)

OWNER TYPE: Government or agency

LIST ENTRY NUMBER: 1254855

Former apprentice house for flaxmill circa 1812, now disused. Historic England is working in partnership with the Local Authority. Outline planning approval was secured for the whole site in 2010, and this will form the basis of the masterplan and future redevelopment proposals. The Friends group is flourishing.

Contact: John Yates 0121 625 6846



© Historic England

SITE NAME: Former Ditherington Flax Mill and attached former malt kiln, flax dressing building and flax warehouse, Spring Gardens, Ditherington, Shrewsbury

DESIGNATION: Listed Building grade I, CA

CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: B (B)

OWNER TYPE: Government or agency

LIST ENTRY NUMBER: 1270576

Former flax mill, five storeys, built 1797 as the first iron frame structure in the world. Converted to maltings in 1897. Also includes the flax dressing building c1803 and a flax warehouse. Historic England is working in partnership with the Local Authority. Outline planning approval was secured for the whole site in 2010, and this will form the basis of the masterplan and future redevelopment proposals. A masterplan for the site was approved in 2010. A Heritage Lottery Fund grant has been awarded, and the project design is currently under review. The Friends group is flourishing.

Contact: John Yates 0121 625 6846



© Historic England

SITE NAME: Stove House and Dye House at former Ditherington Flax Mill, Spring Gardens, Ditherington, Shrewsbury

DESIGNATION: Listed Building grade II*, CA

CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: B (B)

OWNER TYPE: Government or agency

LIST ENTRY NUMBER: 1270566

Former drying stove house and dye house of flax mill, now disused. These buildings are an early and significant component of the flax mill complex. Historic England is working in partnership with the Local Authority. Outline planning approval was secured for the whole site in 2010, and this will form the basis of the masterplan and future redevelopment proposals. The Friends group is flourishing.

Contact: John Yates 0121 625 6846



© Historic England

SITE NAME: Pell Wall Hall, Newport Road, Sutton upon Tern

DESIGNATION: Listed Building grade II*, RPG grade II

CONDITION: Fair

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C (C)

OWNER TYPE: Private

LIST ENTRY NUMBER: 1190426

Country house, 1822-28 by Sir John Soane. After decades of neglect, compulsorily purchased by the Local Planning Authority and passed to a trust who repaired the building shell and restored structural elements of the original Soane building with Historic England grant. The property has changed hands several times. There has been some progress on the required repairs.

Contact: John Yates 0121 625 6846

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA** Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



© Historic England

SITE NAME:	Hawkstone Windmill, Hawkstone Park, Weston-under-Redcastle
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1264219

Late C18 windmill located just outside the registered park at Hawkstone Hall which was designed by William Emes in the mid C18. The windmill sits above the Hawk Lake in the part of the Park which is now a golf course and benefits from extensive views. The building is boarded up, internal machinery and floor structures have largely collapsed though principal floor beams survive. A temporary roof erected in 1996 has saved the building but its condition is deteriorating.

Contact: Jenny Marriott 01691 780677



© Historic England Archive

SITE NAME:	Red Castle, Hawkstone Park, Weston-under-Redcastle
DESIGNATION:	Scheduled Monument and Listed Buildings - 2 grade II, RPG grade I
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1020850 and 1237180; 1264271

Remains of C12/C13 medieval castle in a largely restored C18 landscape. Masonry in vulnerable condition and deteriorating. Invasive vegetation needs to be brought under control. A management plan for the site is nearing completion and its recommendations will be assessed and implemented as appropriate.

Contact: Jenny Marriott 01691 780677



© Historic England

SITE NAME:	The Old Rectory, Claypit Street, Whitchurch Urban
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1056008

An elegant Georgian rectory of 1749 which was used as a listening station during World War II. Urgent works were undertaken to make the roof watertight and halt structural movement but the service wing remains in very poor condition and property boundaries are an issue. Section 106 contributions have been secured for the repair of the building. The owner is clearing debris from within the building and proposes urgent works while exploring options for re-use.

Contact: Sarah Lewis 0121 625 6886



© Historic England

SITE NAME:	Cheney Longville Castle, Cheney Longville, Wistanstow
DESIGNATION:	Listed Building grade II*, SM, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	D (E)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1269816

A fortified manor house complex dating from 1677 set around a courtyard. The north wing is in use as a farmhouse and in fair condition but the rest of the buildings around the courtyard are only partially in use and are in a vulnerable condition. Long term plans for a mixed use conversion to holiday accommodation and heritage interpretation have not yet been implemented. Emergency repairs have been carried out with Historic England grants and roof repairs completed under a Natural England stewardship scheme.

Contact: Jenny Marriott 01691 780677



© Historic England

SITE NAME:	Hargreaves Farmhouse, Winnington, Wollaston
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1055173

Timber-framed farmhouse dating from early C17 with C19 additions including a stone extension. The property has been unoccupied for over 20 years and is very dilapidated. The roof is holed, many infill panels are missing and parts of the frame have collapsed. The erection of scaffolding has provided support and a temporary roof so that the structure is protected and dry. The property is currently for sale.

Contact: Bill Klempner 0121 625 6847

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site



© Historic England

SITE NAME:	Snailbeach New Smeltnill, Worthen with Shelve
DESIGNATION:	Scheduled Monument and Listed Buildings - 2 grade II
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1017764 and 1307989; 1055031

The monument comprises a smelt mill and slag mill built in 1862 for the Snailbeach Mining Company. The slag mill has been stabilised but standing remains of the smelt mill furnaces are in very poor condition due to invasive uncontrolled vegetation. Extensive vegetation clearance and emergency propping has been carried out under an Historic England Management Agreement.

Contact: Jenny Marriott 01691 780677



© Historic England

SITE NAME:	Candle House, Snailbeach Lead Mine, Worthen with Shelve
DESIGNATION:	Scheduled Monument and Listed Buildings - 10 grade II, LB grade II, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1014866 and 1261135; 1055011; 1055012; 1176609; 1176636; 1176648; 1176660; 1366969; 1367007; 1055013

This building is part of the scheduled site of the Snailbeach Lead Mine and was where miners collected their candles before going underground. It dates from the early C19 and is constructed from coursed rubble with brick dressings under a Welsh slate roof. The structure is very simple and substantially intact, but with large holes in the roof and in a derelict state. Subject to the owner's agreement, it is hoped that the building may be acquired by the Shropshire Mines Trust and reunited with the other mining structures which have already been restored with grant aid.

Contact: Sarah Lewis 0121 625 6886



© Historic England

SITE NAME:	Church of St Catherine, Tugford
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1383393

This C12 century church has a nave and chancel with a raised west tower and a south porch. Urgent works are required to address high level masonry repairs, the renewal of roof coverings, rainwater goods and the installation of a subterranean drainage system. A grant has been awarded under the Listed Places of Worship Roof Repairs Fund in March 2015 and repair works are anticipated to start on site in autumn 2015.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Church of St Mary, Ashford Carbonel
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1383628

This C12 century church consists of a nave and chancel with a west end bellcote and a south porch. Both the nave and chancel are original but were subsequently extended within the first century of construction. The church was restored by Ewan Christian in 1881-2 during which time the roofs were recovered with stone tiles laid in diminishing courses: tile fixings on the nave north slope are now failing and tiles are starting to slide off. A Heritage Lottery Fund grant has been awarded and works to re-lay the nave north slope and porch roof are anticipated to start on site in spring 2016.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Church of St Mary, Bitterley
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1383652

This late C13 church consisting of a nave and chancel and west tower was heavily restored by Thomas Nicholson between 1880 and 1881: he added the timber south porch and the timber framed top stage of the tower and its short broad shingled spire. All of the roofs and the spire coverings are failing and require renewal as do the cast iron rainwater goods. The surface water drainage system is largely ineffective and also needs to be replaced. Limited high level masonry repairs are also required.

Contact: John Tiernan 0121 625 6839

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Parish Church, Boraston
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1383416

This C12 century church was mostly rebuilt between 1884 and 1887 by Henry Curzon at the expense of Lord Northwick of Burford House. Built as a chapel of Burford, it consists of a nave with a west tower and shingled spire, a south porch and an apsidal chancel. Differential settlement has occurred at the east end of the church and is thought to be the result of ineffective surface water drainage. Parts of the plain clay tile roof coverings need attention and the oak shingle covering to the spire requires renewal.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Heath Chapel, Stoke St Milborough, Heath
DESIGNATION:	Listed Place of Worship grade I, SM
CONDITION:	Poor
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1383722

This small Norman chapel consists of a nave and lower chancel with broad full height clasping buttresses and lesenes, a continuous mid-height string course, tiny round head windows and a richly decorated south doorway. The church was repaired following the Society for the Protection of Ancient Buildings principles by Basil Stallybrass in 1912. A repairs scheme to re-lay the chancel roof has recently been completed but works to renew the nave roof covering, to carry out assorted masonry consolidation and repointing works and install a surface water drainage system are still urgently required.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Church of St John the Baptist, Kenley
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	B (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1055258

Small single-cell church with attached west tower; mainly of the C12 and C14 with C19 restoration. In a rural location with a few buildings nearby, but on a prominent ridge with commanding views of the adjacent valley. Roofs in poor condition with some indications of minor water ingress. High level tree growth at junction between the west tower and the nave. A repair grant to address these assorted defects has been awarded under the Listed Places of Worship Roof Repairs Fund.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Church of the Holy Trinity, Minsterley
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1055228

This church was built as a chapel of Westbury between 1688-9 and consists of a nave and chancel in one with a west end bellcote and a south porch. Its use of classical and baroque elements, the extensive use of brickwork, raking buttresses without offsets and steeply pitched tiled roof creates an attractive if unusual composition. The use of Portland cement based mortar in conjunction with soft red bricks and Grinshill ashlar is causing the masonry to decay at an accelerated rate. The latest Quinquennial Inspection report makes recommendations for dealing with these and other defects.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Church of St John the Baptist, Myndtown
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1054598

This small medieval church consists of a nave and chancel with a west end bellcote and a timber framed south porch which was reconstructed in 1859. The slated roofs and rainwater goods are in very poor condition and the gable abutment between nave and chancel roof is defective and requires reconstruction. The north side of the church is covered by a rough cast render which is in poor condition and there is extensive cracking to the interior.

Contact: John Tiernan 0121 625 6839

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site




© Historic England

SITE NAME:	Church of St John the Baptist, Nash
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1383565

This C13 church with a nave and chancel under one continuous roof and west tower was built in a single phase of works. Built as a chapel of Burford, it was given a broached spire in the C14 and a north aisle in 1865. The nave roof structure also dates from C19 and sections of the plaster infill panels between the rafters have started to become detached and fall to the floor without warning. The nave, chancel and north aisle roofs are all affected. Parts of the north aisle timber floor have failed due to damp conditions and the spire timber cladding all requires renewal.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Abbey Church of the Holy Cross, Abbey Foregate, Shrewsbury
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1246392

The parish church of the Holy Cross was formed by the nave and west tower of the former Benedictine Abbey Church. C17 and C19 additions explain the present configuration and appearance of the church, which was constructed in red sandstone: there are assorted defects associated with the variable quality of some of the particular building stones used. Parts of the chancel and transept parapets are in urgent need of repair and renewal.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Church of St Chad, St Chads Terrace, Shrewsbury
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1344941

The church of St Chad was designed by George Stuart and built between 1790-92. It is an original design and considered to be one of the finest neoclassical churches in Britain. It consists of a circular galleried nave incorporating a chancel and a tall broad tower which is fronted by an entrance portico flanked by vestries. Parts of the nave balustrade parapet are unstable and most of the weatherings to the nave cornice are time-expired. There are concerns about the longevity of the nave roof. An application to the Heritage Lottery Fund has been made to address these defects.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Church of St Michael and All Angels, Smethcott
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1177711

This isolated C12 church was largely rebuilt between 1849-50 by J P Harrison in a Decorated style and incorporates medieval walling and some C12 features. The church consists of a chancel and a nave with a south porch and a west end bellcote. The roofs are covered by plain clay tiles interspersed with courses of scalloped tiles which are all now in need of relaying. Rainwater goods are both inadequate and defective and in need of complete renewal. A new surface water drainage installation is also required.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Church of St Lucia, Upton Magna
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1267600

This C12 church has a chancel and a nave with a west tower and a south porch. Some of the primary masonry survives in the chancel but the church was substantially rebuilt and enriched by the architect G E Street between 1860-1. The condition of the plaster infill ceiling panels to the nave and north aisle roofs is fragile and hazardous to those who use the church. There is water ingress at the nave roof abutment to the tower and defective drainage is responsible for damp walls at a low level.

Contact: John Tiernan 0121 625 6839

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Little Shrawardine motte and bailey castle, Alberbury with Cardeston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019198
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Natural erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677

SITE NAME:	Ringwork 540 metres north of Lane Farm, Alberbury with Cardeston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019831
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677

SITE NAME:	Stanwardine moated site and associated fishpond, Baschurch		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017240
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677

SITE NAME:	Lower Cleeton moat, a moat and fishponds 380 metres south east of Cleeton Court, Bitterley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010496
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Jenny Marriott 01691 780677

SITE NAME:	White Ladies (St Leonard's) Priory, Boscobel		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015290
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Bill Klemperer 0121 625 6847

SITE NAME:	Bowl barrow 450 metres north west of Felton Farm, Bromfield		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007712
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Jenny Marriott 01691 780677

SITE NAME:	Roman camp north of Bromfield Farm, Bromfield		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006273
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Mineral extraction/related subsidence	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Jenny Marriott 01691 780677

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA** Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Castle Tump, a motte castle and causeway, 150 metres west of Teme Bridge, Burford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008392
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Motte and bailey castle 150 metres north east of Wilmington, Chirbury with Brompton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012864
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Offa's Dyke: section 2/3 mile (1170 metres) long, north from southern boundary of Rownal Covert, Chirbury with Brompton		
DESIGNATION:	Scheduled Monument, part in SM	LIST ENTRY NUMBER:	1003013
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Other not for profit group	CONTACT:	Alison MacDonald 0121 625 6827
SITE NAME:	Offa's Dyke: section one mile 750 yards (2290 metres) from Dudston Covert to a point 300 yards (274 metres) north of Lack Brook - Also in Powys: Wales, Chirbury with Brompton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003797
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison MacDonald 0121 625 6827
SITE NAME:	Offa's Dyke: two sections running 400 yards (370 metres) south of Camlad Stream - Also in Powys: Wales, Chirbury with Brompton		
DESIGNATION:	Scheduled Monument, part in SM	LIST ENTRY NUMBER:	1006259
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison MacDonald 0121 625 6827
SITE NAME:	Motte castle 80 metres north east of Home Farm, Church Stretton		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1008396
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Bowl barrow 390 metres south east of Stanley Cottage, Clunbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016664
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Norton Camp: a large multivallate hillfort, Culmington / Craven Arms		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021073
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	The Mount motte and bailey castle, 120 metres north east of Hill House Farm, Diddlebury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012856
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Moated site and associated ridge and furrow cultivation remains, 145 metres south of St Mary Magdalene's Church, Hadnall		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019650
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Roman villa north east of Cottage Coppice, Harley / Much Wenlock		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002934
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Offa's Dyke: section 90 metres south of Brynorgan, Llanfair Waterdine		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020905
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison MacDonald 0121 625 6827
SITE NAME:	Offa's Dyke: section 890 metres north west and 320 metres west of Little Selley, Llanfair Waterdine		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020903
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison MacDonald 0121 625 6827
SITE NAME:	Motte and bailey castle 100 metres west of Holy Trinity Church, Lydham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013486
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Nickless moat, Milson		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009552
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Callow Hill Camp: a small multivallate hillfort, Minsterley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019828
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Roman villa at Linley Hall, More		
DESIGNATION:	Scheduled Monument, part in RPG grade II	LIST ENTRY NUMBER:	1006253
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Offa's Dyke: section 175 metres east of Cefn Bronydd, Newcastle on Clun		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020899
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison MacDonald 0121 625 6827
SITE NAME:	Small enclosed settlement on Fron, 340 metres west of St John's Church, Newcastle on Clun		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021069
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Offa's Dyke: section 400 metres south west of Springhill Farm, Newcastle on Clun / Clun / Llanfair Waterdine		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020901
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alison MacDonald 0121 625 6827
SITE NAME:	Roman villa 150 yards (140 metres) south east of Lea Hall, Pontesbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006246
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Jenny Marriott 01691 780677

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Wat's Dyke, 420m long section, 190m west of the junction between Preeshenlle Lane and St Martin's Road, Selattyn and Gobowen		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020617
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Roman camps south west of Stoneyford Cottages, Shifnal		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006249
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Roman fort 300 metres east of Drayton Lodge Farm, Shifnal		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020283
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Uxacona Roman site (see also Telford and Wrekin Unitary Authority), Shifnal / St. Georges and Priorslee / Lilleshall and Donnington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003811
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Roman military site at Rhyn Park, St. Martin's		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003716
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Camp Ring motte and bailey castle, enclosure, fishpond and ridge and furrow 400 metres east of Culmington Farm, Stanton Lacy		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012855
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Medieval fishpond reservoir north east of Haughmond Abbey and south west of the hamlet of Haughton, Uffington / Upton Magna		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002953
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Robury Ring: a small enclosed settlement on Wentnor Prolley Moor, Wentnor		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021072
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677

SITE NAME:	Hawcocks Mount ringwork castle 200 metres north east of Hawcocks Farm, Westbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013494
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677

SITE NAME:	Ringwork and bailey castle 350m south west of Lyndale, Westbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013483
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677

SITE NAME:	Red Castle: an enclosure castle in Hawkstone Park, Weston-under-Redcastle		
DESIGNATION:	Scheduled Monument and Listed Buildings - 2 grade II, RPG grade I	LIST ENTRY NUMBER:	1020850 and 1237180; 1264271
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
OWNER TYPE:	Commercial company	CONTACT:	Jenny Marriott 01691 780677

SITE NAME:	Upper Barn moat, Wistanstow		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012455
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677

SITE NAME:	Bowl barrow 120 metres south west of Dorrington Cottage, Pipe Gate, Woore		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016829
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677

SITE NAME:	Bowl barrow at The Napp, Worthen with Shelve		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017347
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).


ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Snailbeach New Smeltmill, 350 metres north east of Green Acres, Worthen with Shelve		
DESIGNATION:	Scheduled Monument and Listed Buildings - 2 grade II	LIST ENTRY NUMBER:	1017764 and 1307989; 1055031
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Two bowl barrows 290 metres north of Upper House Farm, Worthen with Shelve		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016666
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677
SITE NAME:	Clee View, Highley		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Andy Wigley (LPA) 01743 252561
SITE NAME:	Llanymynech, Llanymynech and Pant		
DESIGNATION:	Conservation Area, 12 LBs, 2 SMs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Low	CONTACT:	Andy Wigley (LPA) 01743 252561

STAFFORDSHIRE

EAST STAFFORDSHIRE

	SITE NAME:	Sinai Park, Burton on Trent, Branston	Mid C17 timber framed house, one wing of which was repaired some years ago. The remainder is in very poor condition and continues to deteriorate. It is in critical condition with areas of partial collapse but no agreed plans for its repair. The owners are in discussion with the Heritage Lottery Fund with regard to bringing forward a scheme for its restoration.
	DESIGNATION:	Listed Building grade II*, SM	
	CONDITION:	Very bad	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1038484	
	SITE NAME:	Gates and gatepiers at Hoar Cross Hall, Maker Lane, Hoar Cross, Yoxall	Pair of gates and gate piers of circa 1700, which were moved to their present site around 1870. The wrought iron gates are corroding while the wall and gate piers need repair. Inspection undertaken by an Historic England engineer has led to a detailed survey being carried out to inform repairs. There is on-going engagement with the owners to encourage them to make a grant application to Historic England to assist funding the repairs.
	DESIGNATION:	Listed Building grade II*, CA	
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1038479	

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Enclosures and cursus 300 yards (270 metres) south east of Efflinch, Barton-under-Needwood		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006073
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ian George 0121 625 6859

SITE NAME:	Timber circle, hengi-form monument and part of a pit alignment at Catholme, Barton-under-Needwood		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019109
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Mineral extraction/related subsidence	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ian George 0121 625 6859

SITE NAME:	Enclosure 350 yards (320 metres) north of Tivey's House, Dunstall		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006075
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Mineral extraction/related subsidence	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Bowl barrow 330 metres east of Weaver Farm, Wootton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009412
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Circular enclosures 100 yards (90 metres) south west of Bonthorn, Wychnor		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006094
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Clarence Street/Anglesey Road, Burton upon Trent, Anglesey		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Ben Williscroft (LPA) 01283 508624

SITE NAME:	George Street, Burton, Burton upon Trent, Burton		
DESIGNATION:	Conservation Area, 7 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	High	CONTACT:	Ben Williscroft (LPA) 01283 508624

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

LICHFIELD



© Historic England

SITE NAME:	Angel Croft Hotel, front railings and gates, Beacon Street, Lichfield
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1187354

A fine three storey hotel, built circa 1750 in brick with ashlar dressings. The railings and gates are included in its listing and are also in poor condition. The building has been empty for some time. There has been water damage to ceilings as a result of break-ins but this has now dried out and the building appears to have stabilised. Permission has been granted for conversion to apartments with an agreement to secure the repair of the gates and railings. There is no confirmed start date for commencement of works on-site.

Contact: Julie Taylor 0121 625 6848



© Historic England

SITE NAME:	Church Tower north of Church of St John, St Johns Hill, Shenstone
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1038830

C13 derelict church tower with later alterations. There are no plans for future use of the church at the moment. Local Planning Authority building inspectors have visited and the structure is considered stable at present. An Historic England architect has visited and advised on the removal of ivy. The Local Planning Authority is in discussion with the Parish Council and church to agree a repair scheme.

Contact: John Tiernan 0121 625 6839

SITE NAME:	Site of round barrow near River Tame, Alrewas	LIST ENTRY NUMBER:	1006090
DESIGNATION:	Scheduled Monument	TREND:	Unknown
CONDITION:	Unknown	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Other	CONTACT:	Imogen Sambrook 0121 625 6854
OWNER TYPE:	Commercial company, multiple owners		

SITE NAME:	Air photographic site south west of Elford, Fisherwick	LIST ENTRY NUMBER:	1006100
DESIGNATION:	Scheduled Monument	TREND:	Unknown
CONDITION:	Unknown	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Arable ploughing	CONTACT:	Imogen Sambrook 0121 625 6854
OWNER TYPE:	Local authority, multiple owners		

SITE NAME:	Causewayed enclosure, Fradley and Streethay	LIST ENTRY NUMBER:	1002964
DESIGNATION:	Scheduled Monument	TREND:	Unknown
CONDITION:	Unknown	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Arable ploughing	CONTACT:	Imogen Sambrook 0121 625 6854
OWNER TYPE:	Private, multiple owners		

SITE NAME:	Settlement sites and enclosures 500 yards (460 metres) north east of Sittles Farm, Fradley and Streethay	LIST ENTRY NUMBER:	1006091
DESIGNATION:	Scheduled Monument	TREND:	Unknown
CONDITION:	Unknown	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Arable ploughing	CONTACT:	Imogen Sambrook 0121 625 6854
OWNER TYPE:	Private		

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Manor House, Hamstall Ridware		
DESIGNATION:	Scheduled Monument, 3 LBs, CA	LIST ENTRY NUMBER:	1006119
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Fazeley and Bonehill, Fazeley / Drayton Bassett		
DESIGNATION:	Conservation Area, 12 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Debbie Boffin (LPA) 01543 308203

NEWCASTLE-UNDER-LYME



© Historic England

SITE NAME:	Model farm complex south west of Betley Old Hall, Main Street, Betley	Early C19 model farm including a range of cowhouses, a granary, cartshed, stables and watermill. The owner is currently repairing the buildings for agricultural and storage use. Repairs to the granary have been completed. The front range and vaults have been stabilised. Repairs are on-going to the bottom yard range.
DESIGNATION:	Listed Building grade II*, CA	
CONDITION:	Fair	
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	F (F)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1188395	



© Historic England Archive

SITE NAME:	Heighley Castle, Heighley Lane, Madeley	Remains of a medieval castle dating mainly from the early C13. Only fragments of walling survive due to it being partly demolished in the Civil War. The castle is heavily overgrown with masonry eroding and is generally in a very poor condition. A Historic England Section 17 Management Agreement is to be considered with the owner for vegetation clearance prior to undertaking a condition survey and masonry consolidation.
DESIGNATION:	Scheduled Monument and Listed Building grade II	
CONDITION:	Poor	
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1011070 and 1353703	



© Historic England

SITE NAME:	Gatehouse, walls and bollards to Maer Hall, Maer	Late C18 gatehouse, walls and bollards forming the approach to Maer Hall. The Hall is set in an early C19 park by John Webb. The property is associated with the Wedgwood and Darwin families. The condition of the gatehouse continues to deteriorate with repairs to the roof, gables and stonework required. Further negotiations are underway regarding repairs.
DESIGNATION:	Listed Building grade II*, CA	
CONDITION:	Poor	
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1027834	

SITE NAME:	Heighley Castle, Madeley		
DESIGNATION:	Scheduled Monument and Listed Building grade II	LIST ENTRY NUMBER:	1011070 and 1353703
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Jenny Marriott 01691 780677

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Butterton, Newcastle under Lyme, Whitmore		
DESIGNATION:	Conservation Area, 5 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Louise Wallace (LPA) 01782 717717

PEAK DISTRICT (NP)

© Historic England

SITE NAME:	Critchlow Monument, Sheen, Staffordshire Moorlands	Chest tomb and railing c1853. In poor condition.
DESIGNATION:	Listed Building grade II*, CA	
CONDITION:	Poor	
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1374551	Contact: Imogen Sambrook 0121 625 6854

SITE NAME:	Bowl barrow 450 metres east of Stanshope, Alstonefield, Staffordshire Moorlands		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010798
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Copper mines on Ecton Hill, Wetton, Staffordshire Moorlands		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021175
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ian George 0121 625 6859

SOUTH STAFFORDSHIRE

© Historic England Archive

SITE NAME:	Stable Court at Four Ashes Hall, Four Ashes, Enville	Stable court incorporating extensive farm outbuilding ranges at Four Ashes Hall dating from the mid to late C18 with C20 alterations. One range has virtually collapsed and the roofs are in very bad state. A programme of urgent repairs to the main frontage of the building was completed in 2006 with a Historic England grant, but the rest of the building remains in very poor condition. A Historic England architect has visited and discussions on a funding package continue.
DESIGNATION:	Listed Building grade II*	
CONDITION:	Very bad	
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1277027	Contact: John Tiernan 0121 625 6839

SITE NAME:	Roman fort west of Eaton House, Brewood and Coven		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006098
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Site of Pennocrucium, east of Stretton Bridge, Brewood and Coven / Lapley, Stretton and Wheaton Aston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006121
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Rodbaston Old Hall moated site and fishpond, Penkridge		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011893
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Educational (independent)	CONTACT:	Jenny Marriott 01691 780677

SITE NAME:	Roman camp, Kinvaston, Penkridge / Lapley, Stretton and Wheaton Aston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006104
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Penkridge		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Planning Policy Team (LPA) 01902 696000

STAFFORD



© Historic England

SITE NAME:	Trentham Tower, Sandon Park, Sandon, Sandon and Burston
DESIGNATION:	Listed Building grade II*, RPG grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1189768

Folly tower of circa 1840 located in the centre of the C18-C19 Upper Park, approximately 700 metres north east of the house. It forms part of one of the stone towers from Trentham Hall, designed by Sir Charles Barry and moved to this location after Trentham's demolition in 1910-12. There are a number of structural concerns and assorted masonry defects present. A repairs contract to address these issues, funded under a Natural England Stewardship scheme, has started and should be complete by October 2015.

Contact: Imogen Sambrook 0121 625 6854



© Historic England

SITE NAME:	Engine House and Boiler House at Mill Meece Pumping Station, Standon
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Utility
LIST ENTRY NUMBER:	1039047

Former pumping station that now operates as a museum, which was built around 1914 for the Staffordshire Potteries Waterworks Company. The building was designed by William Campbell and constructed by Thomas Godwin and Son. The engine house and boiler house form part of an exceptionally complete pumping station site in which the integrated process of water pumping is still readable. Repairs are urgently required to the roof.

Contact: Julie Taylor 0121 625 6848

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England Archive

SITE NAME:	Remains of Trentham Hall, the Grand Entrance and Orangery, Park Drive, Trentham Gardens, Swynnerton
DESIGNATION:	Listed Building grade II*, RPG grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1190243

The remains of a country house of 1833-42 by Sir Charles Barry and Orangery of 1808, situated in an C18/C19 park by Lancelot Brown. Emergency repairs have been carried out and the adjacent Italian gardens have been successfully restored. However, several heritage assets on the site are still in need of repair and viable new uses.

Contact: Julie Taylor 0121 625 6848

SITE NAME:	Moated site in Reynold's Orchard, Eccleshall	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: 1011051
CONDITION:	Generally unsatisfactory with major localised problems	TREND: Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?: No
OWNER TYPE:	Commercial company	CONTACT: Jenny Marriott 01691 780677

SITE NAME:	Bowl barrow north of Hargreaves Wood, Swynnerton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: 1009315
CONDITION:	Unknown	TREND: Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?: No
OWNER TYPE:	Private	CONTACT: Imogen Sambrook 0121 625 6854

SITE NAME:	Foregate and St Georges	
DESIGNATION:	Conservation Area	NEW ENTRY?: Yes
CONDITION:	Very bad	TREND: Improving significantly
VULNERABILITY:	Medium	CONTACT: Penny McKnight (LPA) 01785 619337

SITE NAME:	Trentham, Swynnerton	
DESIGNATION:	Conservation Area, 30 LBs, RPG grade II*	NEW ENTRY?: No
CONDITION:	Very bad	TREND: No significant change
VULNERABILITY:	Low	CONTACT: Penny McKnight (LPA) 01785 619337

SITE NAME:	Walk Mill, Eccleshall	
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?: No
CONDITION:	Very bad	TREND: Deteriorating significantly
VULNERABILITY:	Medium	CONTACT: Penny McKnight (LPA) 01785 619337

STAFFORDSHIRE MOORLANDS



© Historic England

SITE NAME:	Biddulph Old Hall, Biddulph
DESIGNATION:	Scheduled Monument, part in LB grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1014688

Substantial remains of a mansion constructed in the 1580s for Francis Biddulph. It came under siege by the Parliamentarians in 1643 when the east range was destroyed and the house fired. The tower and rest of the remains are in need of consolidation. Works were partially completed with the aid of a Historic England grant but have stalled for some years now.

Contact: Sarah Lewis 0121 625 6886

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Prospect Tower and attached wing, Knypersley, Biddulph
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1037810

Built in 1828 by John Bateman as a gamekeeper's house and eye-catcher on the Knypersley Hall estate. It is a three storey octagonal structure in red sandstone with side wing and crenellated parapets. The building has been disused for about 25 years and the fabric is gradually deteriorating. The County Council is considering alternative options for reuse but have been challenged by the presence of bats.

Contact: Imogen Sambrook 0121 625 6854



© Historic England

SITE NAME:	Hales Hall, Oakamoor Road, Cheadle
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1204735

Baroque style, small country house built in 1712 for Mrs Grosvenor the granddaughter of Sir Matthew Hale, Lord Chief Justice of England (1670-1676). The condition of the house has deteriorated, with water ingress from the roof being of particular concern. Hales Hall is currently for sale.

Contact: Julie Taylor 0121 625 6848



© Historic England Archive

SITE NAME:	Alton Towers and attached garden walls and gatehouse, Alton Park, Farley
DESIGNATION:	Listed Building grade II*, RPG grade I
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1374685

Country house, walls and gatehouse, c1810, set in early C19 valley gardens. Derelict when listed. A complete condition survey was undertaken and emergency work completed. A Conservation Management Plan has been prepared and phased programme of further works is on-going.

Contact: Julie Taylor 0121 625 6848



© Historic England

SITE NAME:	Sharpecliffe Hall, Ipstones
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (E)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1374611

A large country house dated 1673 but restored and enlarged in the C19. It may hide earlier fabric. Some repairs have been undertaken in recent years but essential roof repairs to the wings are still needed.

Contact: Julie Taylor 0121 625 6848



© Historic England

SITE NAME:	The Gazebo west of Whitehough, Ipstones
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1374612

An early C18 gazebo in the grounds of the C17 farmhouse at Whitehough. Some repairs were undertaken in the 1990s with grant assistance from Historic England. However, further repair works are now required to the roof, stonework and joinery to complete the restoration.

Contact: Julie Taylor 0121 625 6848

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Church of St Chad, A 53, Longsdon
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1037805

Designed by Gerald Horsley and built in 1903, this church consists of a west tower with spire, nave and chancel and was inspired by Norman Shaw's All Saints at Leek. The spire masonry is colonised by saplings and requires re-pointing. The rainwater goods are blocked and ineffective and some of the roof tiles are starting to delaminate and fail. The gullies to the surface water system are also blocked and ineffective.

Contact: John Tiernan 0121 625 6839

SITE NAME:	Paynsley Hall moated site and outer enclosure, Draycott in the Moors	
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER: 1011050
CONDITION:	Generally unsatisfactory with major localised problems	TREND: Declining
PRINCIPAL VULNERABILITY:	Dumping	NEW ENTRY?: No
OWNER TYPE:	Private	CONTACT: Imogen Sambrook 0121 625 6854

SITE NAME:	Dieu-la-Cres Abbey (remains of), Leek	
DESIGNATION:	Scheduled Monument, 2 LBs	LIST ENTRY NUMBER: 1006107
CONDITION:	Extensive significant problems	TREND: Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?: No
OWNER TYPE:	Private	CONTACT: Imogen Sambrook 0121 625 6854

SITE NAME:	Alton and Farley	
DESIGNATION:	Conservation Area	NEW ENTRY?: No
CONDITION:	Poor	TREND: Deteriorating
VULNERABILITY:	Low	CONTACT: Gill Bayliss (LPA) 01538 395400

SITE NAME:	Cheadle	
DESIGNATION:	Conservation Area	NEW ENTRY?: No
CONDITION:	Very bad	TREND: Deteriorating
VULNERABILITY:	Low	CONTACT: Gill Bayliss (LPA) 01538 395400

SITE NAME:	Leek	
DESIGNATION:	Conservation Area	NEW ENTRY?: No
CONDITION:	Very bad	TREND: Deteriorating
VULNERABILITY:	Low	CONTACT: Gill Bayliss (LPA) 01538 395400

TAMWORTH



© Tamworth Borough Council

SITE NAME:	The Moat House, Lichfield Street
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1208600

One of Tamworth's oldest and most interesting buildings. The Moat House is Elizabethan in style, built of brick with stone details; the interior features include a fine staircase and an elaborate plaster ceiling to the first floor gallery. The ground floor is currently used as a public house and restaurant. The roof is leaking and damaging the plaster ceiling. The Council has given grant aid to help stabilise the ceiling but repairs are still needed.

Contact: Julie Taylor 0121 625 6848

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Deanery wall, Lower Gungate, Tamworth
DESIGNATION:	Scheduled Monument and Listed Buildings - 2 grade II, 3 LBs, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Unknown
LIST ENTRY NUMBER:	1006059 and 1197033; 1207833

A C14 masonry wall which was part of St Edith's Deanery. An Historic England engineer has inspected the three surviving sections of wall, parts of which are in urgent need of maintenance and repair. The removal of plant growth, pointing and resetting of stones to wall tops are all required. As a boundary wall, the ownership is uncertain, and liability for repair unclear. Investigation is necessary.

Contact: Imogen Sambrook 0121 625 6854

SITE NAME:	Saxon defences	LIST ENTRY NUMBER:	1006088
DESIGNATION:	Scheduled Monument, LB grade II, part in CA	TREND:	Unknown
CONDITION:	Unknown	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Other	CONTACT:	Imogen Sambrook 0121 625 6854
OWNER TYPE:	Local authority		

STOKE-ON-TRENT, CITY OF (UA)



© Historic England

SITE NAME:	Former Wedgwood Institute (Public Library), Queen Street, Burslem
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (D)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1195840

An art school and library built in 1869 in brick and terracotta with richly ornamented facade. The building is now closed and some emergency repairs have been carried out. Proposals for the future use of the building are in the process of being finalised. The first phase of repair works to the external fabric started on site in February 2015 and are due to be completed by the end of July 2015.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Bethesda Methodist Chapel, Albion Street, Hanley
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1195821

A former Methodist chapel built in the C19 with intact interiors known as "the Cathedral of the Potteries". The Historic Chapels Trust have completed external repairs with the help of grants from Historic England and the Heritage Lottery Fund. Further repairs have also been undertaken to some of the outbuildings. A final phase of work to allow the re-use of the building is now in development.

Contact: Julie Taylor 0121 625 6848



© Historic England

SITE NAME:	Bottle oven and factory, Price and Kensington Teapot Works, Newcastle Street, Longport
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1290799

An early C19 pottery complex with a bottle oven that has been repaired and only one range now occupied. A fire in the three storey range has resulted in the demolition of walls above the second floor and the removal of the roof structure. Theft of slates and tiles from the roofs of many of the other buildings means that the complex is exposed and highly vulnerable. Urgent works are required to stabilise the buildings while a new use is sought.

Contact: Sarah Lewis 0121 625 6886

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Chatterley Whitfield Colliery, Biddulph Road, Stoke-on-Trent
DESIGNATION:	Scheduled Monument, 5 LBs
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1015947

Large redundant C19/C20 colliery in need of major repair and regeneration. The site includes 15 scheduled structures and 5 listed buildings. A heritage based regeneration programme has been started based on a masterplan but a long-term solution still needs to be agreed. Progress with the re-use of buildings and reclamation works has been slow however. Discussions on private sector engagement and longer term proposals are ongoing.

Contact: Bill Klemperer 0121 625 6847



© Historic England

SITE NAME:	Pithead baths and canteen, Biddulph Road, Stoke-on-Trent
DESIGNATION:	Listed Building grade II*, SM
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1260223

Originally opened in the 1860s, Chatterley Whitfield became the first mine in Britain to draw more than a million tons of coal in a year in 1937. The pithead baths and canteen were erected at this time and are of special interest as an example of large scale provision for miners in the early C20. On the closure of the mine the buildings were used to accommodate a museum. The whole colliery site is now vacant and these buildings are in very poor condition.

Contact: Bill Klemperer 0121 625 6847



© Historic England

SITE NAME:	Hulton Abbey, Leek Road, Stoke-on-Trent
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1021284

The remains of Hulton Abbey, which was founded in 1223, comprise the transepts and chancel at the east end of church which now survive as stub walls. The site is owned by Stoke-on-Trent Council and managed as a public amenity space. Below ground remains are not at risk but the hard capped wall tops are vulnerable to weathering and stone decay and require repair.

Contact: Imogen Sambrook 0121 625 6854



© Historic England

SITE NAME:	Mausoleum, Stone Road, Trentham
DESIGNATION:	Listed Building grade I
CONDITION:	Fair
OCCUPANCY:	N/A
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1210451

A mausoleum built for the Dukes of Sutherland around 1808 and set opposite to one of the entrances to Trentham Park. A package of urgent roof repairs was carried out with funding from Historic England and the Local Planning Authority. Further repairs to doors and the rear window have also been completed and the Local Planning Authority regularly repair the doors when they are vandalised. The fabric is now sound, but the building remains at risk until responsibility for future upkeep is clearly established.

Contact: Julie Taylor 0121 625 6848



© Historic England

SITE NAME:	Church of St John the Baptist, Cross Hill, Burslem
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1291065

This church was largely rebuilt in 1717 but retains its medieval tower. Non-breathable paint on the nave is trapping moisture in brickwork, leading to significant internal damp problems and deterioration of outer brick face. Dry rot to timber of apse stained glass windows has spread into walls and inappropriate use of cement tiles on the hipped roof is leading to structural problems. The building has multiple fabric defects. This church has been the victim of heritage crime.

Contact: John Tiernan 0121 625 6839

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site



© Historic England

SITE NAME:	Roman Catholic Church of St Joseph, Hall Street, Burslem
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	D (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1297960

This is a large brick-built, Italianate style church built in 1925 to the designs of the architect J S Brocklesbury. It has a finely decorated interior. Historic England grant aided repairs, carried out in 2012, to the sanctuary and ambulatory roofs have addressed assorted building fabric defects but the nave roof and its asphalt lined eaves gutters are failing and require renewal. Extensive repointing of the nave clerestory and buttresses is also urgently required. A grant has been awarded under the Listed Places of Worship Roof Repairs Fund and repair works are due to start in autumn 2015.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Church of St John the Evangelist, High Street, Goldenhill
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1220492

This church was built in 1841 by Stanley of Shelton, a local architect, in the Byzantine Romanesque style. Blocked or defective rainwater goods in several locations have caused damage to the internal finishes and there are significant areas of rising damp. The nave roof has minor defects. The church has suffered from heritage crime. The external masonry is slowly deteriorating. The latest Quinquennial Inspection report makes recommendations for a steeplejack inspection of both the tower and spire. The church is now going through the process of being closed.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	All Saints Church, Leek Road, Hanley
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	B (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1245925

All Saints is an Arts and Crafts Gothic church designed by Gerald Horsley in 1910. Built with red brick buttressed walls with sandstone dressings and steeply pitched roofs with both plain clay and replacement concrete tiles. Failed abutment flashings at the east end of the church and defective rainwater goods threaten the integrity and viability of this largely unaltered building. Unused for the past three years, a scheme to create an enclosed place of worship within the unheated church is now proposed. The Parochial Church Council are to submit an application to the Heritage Lottery Fund.

Contact: John Tiernan 0121 625 6839

SITE NAME:	Caldon Canal, Stoke-on-Trent	NEW ENTRY?:	No
DESIGNATION:	Conservation Area	TREND:	Improving
CONDITION:	Very bad	CONTACT:	Jane Corfield (LPA) 01782 236680
VULNERABILITY:	Medium		

SITE NAME:	Longton Town Centre, Longton	NEW ENTRY?:	No
DESIGNATION:	Conservation Area	TREND:	Improving
CONDITION:	Very bad	CONTACT:	Jane Corfield (LPA) 01782 236680
VULNERABILITY:	Medium		

SITE NAME:	Newcastle Street, Middleport	NEW ENTRY?:	No
DESIGNATION:	Conservation Area	TREND:	No significant change
CONDITION:	Poor	CONTACT:	Jane Corfield (LPA) 01782 236680
VULNERABILITY:	High		

SITE NAME:	Stoke Town, Stoke	NEW ENTRY?:	No
DESIGNATION:	Conservation Area	TREND:	No significant change
CONDITION:	Very bad	CONTACT:	Jane Corfield (LPA) 01782 236680
VULNERABILITY:	High		

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Trent & Mersey Canal, Stoke-on-Trent		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Jane Corfield (LPA) 01782 236680

TELFORD AND WREKIN (UA)



© Historic England

SITE NAME:	Bedlam Furnace, The Gorge
DESIGNATION:	Scheduled Monument, LB grade II*, CA, WHS
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Local authority, multiple owners
LIST ENTRY NUMBER:	1006234

The Bedlam Furnace, located in the Ironbridge Gorge, was built in the 1750s and remained active in to the C19. It is the likely source of the cast members used in the nearby world famous iron bridge. Exposure to the elements has led to water damage and the failure of repairs undertaken in the late 1990s. The Ironbridge Gorge Museum Trust plans consolidation works for collapsing masonry and has applied to Historic England for a Repair Grant which will look to erect a protective canopy over the monument.

Contact: John Tiernan 0121 625 6839



© Historic England Archive

SITE NAME:	Charlton Castle, Wrockwardine
DESIGNATION:	Scheduled Monument
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1019649

A medieval moated site which is very overgrown and has several uprooted trees damaging the earthworks. There are some elements of standing masonry exposed. The site needs an assessment of condition and the development of an appropriate management regime. There is potential to fund this through an Historic England Management Agreement.

Contact: Jenny Marriott 01691 780677



© Stainburn Taylor architects

SITE NAME:	Church of St Mary the Virgin, Salthouse Road, Jackfield
DESIGNATION:	Listed Place of Worship grade II, CA, WHS
CONDITION:	Poor
PRIORITY CATEGORY:	D (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1038241

This church was designed by A W Blomfield and built in 1863. It consists of an aisle less nave, pseudo transepts, a chancel and a north east tower with an open bell stage; all constructed in polychrome brickwork with steeply pitched tiled roofs. Assorted grant aided repairs to the tower and the chancel and transept roofs, funded by the Heritage Lottery Fund and Historic England, were successfully completed in September 2014 but the steeply pitched nave roof is still in need of urgent repair.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Church of St Peter, Church Road, Oakengates
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1033297

The church of St Peter was designed by Francis Halley of Shifnal and built between 1825-7 to replace a C12 chapel which consisted of the present nave and west tower to which the chancel was added in 1903. The church is constructed in brindle brickwork with stone dressings and has slate covered roofs. Concealed ferrous metal dowels have disrupted the masonry to the tower bell lights which has resulted in sections of masonry shearing off. The vestry has settled and rotated away from the chancel wall. All of the roofs require re-laying and the rainwater goods overhauling and repairing.

Contact: John Tiernan 0121 625 6839

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site



© Historic England

SITE NAME:	Church of St Peter, Wrockwardine
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1030939

This C12 cruciform church has a nave and chancel, transepts and a crossing tower with later medieval chapels added to the north and south sides of the chancel. Although much altered with prominent structural reinforcement in the form of angle buttresses to the tower and by subsequent restoration and repair schemes, assorted works are now urgently required to address defective tiled roof coverings, rainwater goods and high level stonework. A Heritage Lottery Fund grant for high level masonry repairs to the crossing tower was awarded in March 2015 and work is likely to start in 2016.

Contact: John Tiernan 0121 625 6839

SITE NAME:	Enclosed Iron Age farmstead immediately adjacent to The Croft, Pave Lane, Chetwynd Aston and Woodcote	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: 1020275
CONDITION:	Unknown	TREND: Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?: No
OWNER TYPE:	Private, multiple owners	CONTACT: Jenny Marriott 01691 780677

SITE NAME:	Roman camp on Red Hill, Lilleshall and Donnington	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: 1006269
CONDITION:	Unknown	TREND: Unknown
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?: No
OWNER TYPE:	Private	CONTACT: Jenny Marriott 01691 780677

SITE NAME:	St Leonard's Priory immediately adjacent to the Church of St Mary and St Leonard, Wombridge, Oakengates	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: 1020661
CONDITION:	Generally unsatisfactory with major localised problems	TREND: Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?: No
OWNER TYPE:	Religious organisation	CONTACT: Bill Klemperer 0121 625 6847

SITE NAME:	Canal aqueduct over River Tern, Rodington	
DESIGNATION:	Scheduled Monument, LB grade I	LIST ENTRY NUMBER: 1006275
CONDITION:	Extensive significant problems	TREND: Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?: No
OWNER TYPE:	Private	CONTACT: Jenny Marriott 01691 780677

SITE NAME:	Uxacona Roman site (See also Shropshire Unitary Authority), Shifnal / St. Georges and Priorslee / Lilleshall and Donnington	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: 1006272
CONDITION:	Unknown	TREND: Unknown
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?: No
OWNER TYPE:	Private, multiple owners	CONTACT: Bill Klemperer 0121 625 6847

SITE NAME:	Site revealed by aerial photography north of Castle Farm, St. Georges and Priorslee	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: 1006274
CONDITION:	Unknown	TREND: Unknown
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?: No
OWNER TYPE:	Mixed, multiple owners	CONTACT: Jenny Marriott 01691 780677

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Churchyard of St James's Church, Stirchley and Brookside		
DESIGNATION:	Scheduled Monument, LB grade I	LIST ENTRY NUMBER:	1020852
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Jenny Marriott 01691 780677

SITE NAME:	Moated site and a fishpond 160 metres and 280 metres south of The Farm, Charlton, Wrockwardine		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019649
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Jenny Marriott 01691 780677

WARWICKSHIRE

NORTH WARWICKSHIRE




© Historic England

SITE NAME:	Beech House, 19 Market Street, Atherstone
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1185175

A fine town house in the Queen Anne style dated 1708. The interiors are largely unaltered and most of the original features are intact. The property has been vacant for several years and is slowly decaying. Discussions are ongoing with the owner and the Local Planning Authority, and a new planning application is expected shortly.

Contact: Nick Molyneux 0121 625 6857



© Historic England

SITE NAME:	Grendon Bridge, Grendon / Polesworth
DESIGNATION:	Scheduled Monument and Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1005756 and 1186247

Stone bridge, probably C15 constructed in sandstone. Now in poor condition with parts of the parapet missing. A condition survey is needed to assess the scale of repairs. Discussions are ongoing with the owners about a possible management agreement and grant aid.

Contact: Imogen Sambrook 0121 625 6854



© Historic England

SITE NAME:	Hartshill Castle, Castle Road, Hartshill
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1011197 and 1034748

C13 castle ruins. Steady decay of surviving masonry due to erosion, structural problems and vandalism. The owner has set up a trust to look after the castle. Vegetation clearance and emergency repairs were carried out some time ago. Discussions are ongoing with the owner for a condition survey prior to masonry repairs.

Contact: Ian George 0121 625 6859

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Kingsbury Hall , Kingsbury
DESIGNATION:	Scheduled Monument and Listed Buildings - 1 grade II*; 1 grade II, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1019978 and 1116550; 1034721

A manor house of c1500 with late C16 and C18 rebuilding and early C19 wing. A scheme for the residential conversion of the building has commenced. Final repairs and reuse have yet to be achieved.

Contact: Ian George 0121 625 6859



© Historic England Archive

SITE NAME:	Maxstoke Priory, Church Road, Maxstoke
DESIGNATION:	Scheduled Monument and Listed Buildings - 6 grade II*, 2 LBs
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private, multiple owners
LIST ENTRY NUMBER:	1011195 and 1034822; 1034823; 1365129; 1034821; 1116038; 1320105

Substantial remains of an early C14 Augustinian monastery including infirmary, precinct walls, outer gatehouse with attached barn and farmhouse. The buildings are steadily decaying, the precinct wall is in very poor condition and the infirmary structure is propped. Natural England are funding some repairs under a Higher Level Stewardship scheme.

Contact: Imogen Sambrook 0121 625 6854



© Historic England

SITE NAME:	Stables range north east of Middleton Hall, Middleton
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1365197

Originally stables and lodging block c1570. Timber-framed with brick infill panels. Consists of a four bay main range with a two bay cross wing at the north end and a two storey gabled porch to the left of the centre. Courtyard of farm buildings to rear. The structure is in need of stabilisation. The building is vacant but a condition survey has been undertaken.

Contact: Nick Molyneux 0121 625 6857



© Historic England

SITE NAME:	Moat, footbridge and gatepiers to Shustoke Hall Farmhouse, Moat House Lane, Shustoke
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1226189

Homestead moat, footbridge and gate piers c1686, with late C18 service wing which is in poor condition. Substantial sections of overgrown walls and buttresses were previously leaning outwards and required rebuilding. Much of this work has been carried out over the last two years with the brick upper parapet to the south arm awaiting rebuilding (hopefully to be addressed in the 2015/16 financial year). Significant progress has been made since 2013 with repointing, but further work is needed to remove the site from the Register.

Contact: Imogen Sambrook 0121 625 6854



© Historic England

SITE NAME:	Alvecote priory and dovecote, Shuttington
DESIGNATION:	Scheduled Monument, 2 LBs
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Local authority, multiple owners
LIST ENTRY NUMBER:	1020623

The listed and scheduled remains of a C12 Benedictine Monastery; the primary structure on site represents the C14 remodelling of the building and suffers from vandalism, natural deterioration, and nighthawking. An associated medieval dovecote is also affected by plant growth and issues with dewatering. The Local Authority is working with Historic England to establish a management plan for the site and carry out repairs to the standing remains of the priory and dovecote.

Contact: Imogen Sambrook 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Double moated site 60 metres east of Baxterley church, Baxterley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014683
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Oldbury Camp univallate hillfort, Hartshill		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018855
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Roman Camp, Mancetter		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1005736
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Manduesedum Roman villa and settlement with associated industrial complex, Mancetter / Witherley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017585
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Merevale Abbey, a Cistercian monastery, associated water control features and industrial remains, Merevale		
DESIGNATION:	Scheduled Monument, 6 LBs, part in RPG grade II*	LIST ENTRY NUMBER:	1014682
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Jenny Marriott 01691 780677

SITE NAME:	Alvecote priory and dovecote, Shuttington		
DESIGNATION:	Scheduled Monument, 2 LBs	LIST ENTRY NUMBER:	1020623
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Imogen Sambrook 0121 625 6854

NUNEATON AND BEDWORTH



© Historic England

SITE NAME:	Park Farmhouse, Arbury Park, Nuneaton	Late C15 farmhouse with C16 and C17 alterations, to the north west of Arbury Park. In a very bad condition. Following a building survey, works were carried out to support and protect the structure while schemes and options for future use were considered and discussed by the Estate with Historic England. Temporary measures have subsequently begun to fail and the Estate is now looking to undertake further urgent action to protect the building, particularly its vulnerable timber frame, from further deterioration.
DESIGNATION:	Listed Building grade II*	
CONDITION:	Very bad	
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1365048	
		Contact: Imogen Sambrook 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	The Tea House, Arbury Park, Nuneaton
DESIGNATION:	Listed Building grade II*, RPG grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1299615

Mid C18 summerhouse located c500 metres east north east of Arbury Hall. The Tea House is situated on the north east shore of a small lake on the eastern edge of the C18 park. In a very bad state of repair (the roof has collapsed), and continues to deteriorate. Action needed urgently to halt decay and save what is left of the building. There are currently no plans to repair the structure.

Contact: Imogen Sambrook 0121 625 6854

RUGBY



© Historic England

SITE NAME:	Church of St John the Baptist, The Crescent, Brinklow
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1034957

This sandstone church with its prominent tower has medieval origins and is characterised by its Perpendicular windows. The roof has some tiles dislodged and the overall condition of the nave's roof is poor especially on the south side, where the stonework at high level is particularly poor. Previous cementitious repairs are increasing the stone erosion. The gutters are poor causing internal problems at high level. There is evidence of damp plaster at high level, some of which has fallen off.

Contact: Cristina Gardiner 0121 625 6850

SITE NAME:	Brandon Castle, Brandon and Bretford	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER: 1011371
CONDITION:	Generally unsatisfactory with major localised problems	TREND: Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?: No
OWNER TYPE:	Commercial company	CONTACT: Imogen Sambrook 0121 625 6854

SITE NAME:	Barrow cemetery 400 metres north east of Bretford, Brandon and Bretford / King's Newnham	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: 1005722
CONDITION:	Unknown	TREND: Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?: No
OWNER TYPE:	Private, multiple owners	CONTACT: Imogen Sambrook 0121 625 6854

SITE NAME:	Prehistoric pit alignment and associated features on Lawford Heath, adjacent to the northernmost Blue Boar Farm, Church Lawford / Thurlaston	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: 1020937
CONDITION:	Unknown	TREND: Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?: No
OWNER TYPE:	Private	CONTACT: Imogen Sambrook 0121 625 6854

SITE NAME:	Bowl barrow 470 metres south west of Coton House, Churchover	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: 1016883
CONDITION:	Generally unsatisfactory with major localised problems	TREND: Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?: No
OWNER TYPE:	Private	CONTACT: Imogen Sambrook 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Tripontium Roman Station, Churchover		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005759
CONDITION:	Unknown	TREND:	Declining
PRINCIPAL VULNERABILITY:	Metal detecting - unlicensed	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Prehistoric circular earthworks, King's Newnham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005717
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Bowl barrow on Lammas Hill, Wolston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016885
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Bowl barrow 490 metres north west of Abbey Farm, Wolvey		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016845
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Bowl barrow 900 metres north of Copston Farm, Wolvey		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016846
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854



© Historic England

SITE NAME:	Ryton House, Ryton-on-Dunsmore
DESIGNATION:	Registered Park and Garden grade II, LB grade II
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	High
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1001343

Small Regency landscape surrounding the shell of grade II listed Regency villa. Late C20 extensions to villa extend over gardens. The boundary belt, historic drive, shrubberies and lakes badly neglected. Setting compromised by roads and residential development. Future uncertain.

Contact: Kim Auston 0117 975 0696

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

STRATFORD-ON-AVON



© Historic England

SITE NAME:	Bidford Bridge, Bidford-on-Avon
DESIGNATION:	Scheduled Monument, LB grade I
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1005766

An early C15 bridge over the river Avon thought to have been built by the monks of Bordesley Abbey. Constructed from limestone, it has been repeatedly repaired over the centuries. The bridge is vulnerable to vehicle damage. Inappropriate historic repairs and stone erosion are problems.

Contact: Neil Rimmington 0121 625 6856



© Historic England

SITE NAME:	The Old Rectory Farmhouse, Friars Lane, Lower Brailes, Brailes
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1024377

Rectory of late C16 with earlier origins. A support scaffolding and temporary roof were grant aided by Historic England more than 10 years ago but the structure has continued to deteriorate. The property has been empty for some years and was in a serious state of decay. The owner commenced repairs last year and work is now well under way. It is hoped that the project will be completed in the coming year.

Contact: Nick Molyneux 0121 625 6857



© Historic England

SITE NAME:	St Nicholas' Church, Ettington Park, Ettington
DESIGNATION:	Scheduled Monument, LB grade I
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1005744

The ruined chapel of St Nicholas is the family mausoleum of the Shirley family. It has suffered from natural erosion and other threats including birds nesting in the tower, structural decay of standing masonry and other issues associated with rainwater goods and cementitious repairs. The owners are in discussions with Historic England about repairs and management options.

Contact: Imogen Sambrook 0121 625 6854



© Historic England

SITE NAME:	Toll House, Clopton Bridge, Stratford-upon-Avon
DESIGNATION:	Listed Building grade I, SM
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1204167

Former toll house built in 1814 on the C15 Clopton Bridge in the centre of Stratford-upon-Avon. The building has been disused for many years, the roof and stonework is in poor condition. Some urgent stonework repairs have been carried out but further works are required. The Stratford Historic Buildings Trust has been awarded grant aid by Historic England for repairs and a stage one Heritage Lottery Fund grant to develop a scheme for conversion to office use.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	Umberslade Baptist Chapel, Spring Lane, Tanworth-in-Arden
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1382428

Exceptionally fine Nonconformist estate chapel of 1877 by George Ingall for GF Muntz of Umberslade Park. The chapel has not been used as a place of worship for many years and has been acquired by the Historic Chapels Trust who plan to restore it for educational/community uses and occasional services. Main phase of repairs to external fabric completed, but funding for restoration of the interior is still required.

Contact: Sarah Lewis 0121 625 6886

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Church of St Lawrence, Barton-on-the-Heath
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1024311

The church has a probable Anglo-Danish origin dating from the C11 and C12. The church was remodelled in the C14 and C15 but was also restored and altered in 1851 by William Butterfield. The addition of the porch, the gable crosses, the arch between the chapel and the nave and changes to the roof, with a scissor braced roof, are all attributable to Butterfield. The church is constructed in square and coursed ironstone. The church roof is failing and the rain water drainage is poor. The church has been given a Heritage Lottery Fund Grant for Places of Worship and repairs should commence in 2015.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	Church of St Botolph, Church Lane, Farnborough
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1299775

The church is set close to Farnborough Hall. It is in poor condition; the roof shows slipped slates, the gutters have vegetation growing in them and some have become detached. Stonework at high levels is also in bad condition.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	Church of St Giles, Church Lane, Gaydon
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1184784

Small ironstone ashlar church with moulded cornices, designed by Squirrill of Leamington and dating from 1852. The church is modest in size but in poor condition externally due to the friability of the Horton Stone. Some parts of the church appear in poor structural condition especially on the east gable. There are large cracks in the masonry and the one on the south west corner is particularly bad. The gutters are also poor.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	Church of St Peter, Warwick Road, Kineton
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1381924

The prominently located Church of St. Peter, Kineton dates from the C13, with alteration from the C14, C15 and C18. It was remodelled and repaired in 1873-89 but the soft local iron stone has not lasted well, the stonework at high level is extremely poor with parts detaching on an ongoing basis from both tower and main body of the church. Some of the rain shedding stone hoods to windows have been eroded and architectural elements like stone mullions are delaminated and fractured in several locations impairing the large nave windows.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	Church of St Mary the Virgin, Church Hill, Ullenhall
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1382494

Built in sandstone ashlar with local Horton (iron) stone, the church was designed by John P Seddon in 1875. In Early English style the church has good proportions and distinctive detailing; the tower has a broached octagonal bell stage and a slender and elegant spire that complements the church. The high level stone work on the tower is poor as is the rain water drainage. The church has been given a Grant for Places of Worship from the Heritage Lottery Fund: preparatory work has commenced and the repairs should take place in 2015 and 2016.

Contact: Cristina Gardiner 0121 625 6850


PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	Church of St Peter, Wormleighton
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1299347

Church with C12 and C13 origins although the aisles were largely rebuilt in the C14 together with the chancel. The east and south walls were rebuilt in the C18. Constructed in squared rubble and course ironstone with slate roofs. The tower and north and south aisle roofs are in very poor condition and drainage from the tower is inadequate and unsightly. The church is in receipt of a Grant for Places of Worship from the Heritage Lottery Fund and repairs should commence in 2015-16.

Contact: Cristina Gardiner 0121 625 6850

© Historic England

SITE NAME:	Oversley Castle, Alcester	LIST ENTRY NUMBER:	1005750
DESIGNATION:	Scheduled Monument	TREND:	Unknown
CONDITION:	Unknown	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Arable ploughing	CONTACT:	Imogen Sambrook 0121 625 6854
OWNER TYPE:	Commercial company		

SITE NAME:	Beaudesert Castle: motte and bailey castle and two fishponds, Beaudesert	LIST ENTRY NUMBER:	1012703
DESIGNATION:	Scheduled Monument	TREND:	Declining
CONDITION:	Generally unsatisfactory with major localised problems	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	CONTACT:	Imogen Sambrook 0121 625 6854
OWNER TYPE:	Commercial company		

SITE NAME:	Castle Hill Motte, Brailes	LIST ENTRY NUMBER:	1018858
DESIGNATION:	Scheduled Monument	TREND:	Declining
CONDITION:	Generally satisfactory but with significant localised problems	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	CONTACT:	Imogen Sambrook 0121 625 6854
OWNER TYPE:	Commercial company		

SITE NAME:	Double ditched enclosure east of Thornton Farm, Ettington	LIST ENTRY NUMBER:	1002990
DESIGNATION:	Scheduled Monument	TREND:	Unknown
CONDITION:	Unknown	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Arable ploughing	CONTACT:	Imogen Sambrook 0121 625 6854
OWNER TYPE:	Private		

SITE NAME:	Enclosures north of Old Pasture Farm, Hampton Lucy	LIST ENTRY NUMBER:	1005714
DESIGNATION:	Scheduled Monument	TREND:	Unknown
CONDITION:	Unknown	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Arable ploughing	CONTACT:	Imogen Sambrook 0121 625 6854
OWNER TYPE:	Private		

SITE NAME:	Site of building and enclosure 460 metres east of Hatton Rock Farm, Hampton Lucy	LIST ENTRY NUMBER:	1005741
DESIGNATION:	Scheduled Monument	TREND:	Unknown
CONDITION:	Unknown	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Arable ploughing	CONTACT:	Imogen Sambrook 0121 625 6854
OWNER TYPE:	Commercial company, multiple owners		

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Medieval settlement remains at Hodnell Manor, Hodnell and Wills Pastures		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020421
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Dumping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Rectangular Earthwork on Nebsworth, Ilmington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005734
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Multivallate hillfort on Meon Hill, Quinton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011372
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Nadbury Camp, Ratley and Upton / Warmington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003724
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Enclosures 1200 metres north of Salford Priors, Salford Priors		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005721
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Romano-British cemetery and settlement site, Stretton-on-Fosse		
DESIGNATION:	Scheduled Monument, 2 LBs	LIST ENTRY NUMBER:	1003725
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Settlement site west of Welford Weir, Temple Grafton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005719
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854
SITE NAME:	Enclosures 550 metres east of King's Mead, Wellesbourne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005716
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Lower Shuckburgh		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Clare Eynon (LPA) 01789 260326

SITE NAME:	Southam		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Clare Eynon (LPA) 01789 260326

WARWICK



© Historic England

SITE NAME:	Hunningham Bridge, Hunningham / Weston under Wetherley
DESIGNATION:	Scheduled Monument, 2 LBs
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1005770

Hunningham Bridge is a mid C17 structure of sandstone ashlar spanning the river Leam and is currently in use as a public highway. The structure is currently in a poor condition with cracking, erosion and open jointing along both parapets. Incidents in spring 2015 have resulted in two demolished sections of the parapet. Discussions with the Local Authority are in progress to address these issues.

Contact: Imogen Sambrook 0121 625 6854



© Historic England Archive

SITE NAME:	Remains of Old Castle Bridge, Mill Street, Warwick
DESIGNATION:	Scheduled Monument and Listed Building grade II*, RPG grade I
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1005772 and 1035499

Late medieval bridge. Ownership of the remains is split three ways. Earlier proposals for stabilisation were very costly and beyond available resources. It has been proposed that ownership should be transferred to a trust who would co-ordinate restoration and funding package but this has not progressed. A fresh survey of condition and repair costs has been suggested to move things forward.

Contact: Ian George 0121 625 6859



© Historic England Archive

SITE NAME:	Masters House, Warwick
DESIGNATION:	Listed Building grade II*, SM
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1364850

The Leper Hospital of St Michael was founded in the C12; the Master's House survives and is a timber-framed building of C15 date built upon C12 foundations. The timber frame and roof are in very poor condition and there are general structural problems throughout the building which has been propped to prevent collapse and covered in tarpaulins. Historic England has provided a development grant to fund the preparation of a specification which will inform future repairs to the building when the site is developed. The Local Authority is currently engaged in negotiating the purchase of the site.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Church of St Mary, Church Lane, Stoneleigh
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	B (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1035159

St Mary's Church is a grade I listed building constructed in red sandstone ashlar in a rural village setting. The church is fundamentally Norman and described by Pevsner as "very ambitious for its date". The nave is very wide for the Norman period and has good quality decorations. The nave roof is in very poor condition. Internally the ceiling and the high level masonry is mouldy. The church has been given a Grant for Places of Worship from the Heritage Lottery Fund: development work is now under way and repairs should take place in 2016.

Contact: Cristina Gardiner 0121 625 6850

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site



© Historic England

SITE NAME:	Church of St Michael, Rugby Road, Weston under Wetherley	Parish church in red sandstone ashlar situated in an elevated position with evidence of a C12 church in the north and south walls of the chancel. The red sandstone stonework is in extremely poor condition at all levels with delamination, open joints and hollow sections, erosion, cracking and inappropriate repairs. Some structural cracks are present. Deformation on the south elevation appears stable.
DESIGNATION:	Listed Place of Worship grade I	
CONDITION:	Very bad	
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1325524	Contact: Cristina Gardiner 0121 625 6850

SITE NAME:	Roman settlement at Glasshouse Wood, Ashow / Kenilworth		
DESIGNATION:	Scheduled Monument, part in RPG grade II*	LIST ENTRY NUMBER:	1005723
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Digging	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Circular ditches enclosures south west of Wiggerland Wood Farm, Bishop's Tachbrook		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003740
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Guy's Cave hermitage and other rock cut chambers at Guy's Cliffe, Leek Wootton and Guy's Cliffe		
DESIGNATION:	Scheduled Monument, LB grade II, RPG grade II	LIST ENTRY NUMBER:	1019129
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Religious organisation	CONTACT:	Ian George 0121 625 6859

SITE NAME:	Wedgcock Park pale, dam, two watermill sites, bridge and hollow way 200 metres north east of Goodrest Farm, Leek Wootton and Guy's Cliffe		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013159
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Enclosures 410 metres north east of Sherbourne parish church, Sherbourne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005711
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Warwick Castle (uninhabited parts), Warwick		
DESIGNATION:	Scheduled Monument, part in RPG grade I	LIST ENTRY NUMBER:	1005757
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ian George 0121 625 6859

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Enclosures 550 metres, SSW of Manor House Farm, Wasperton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005713
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Mineral extraction/related subsidence	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Enclosures and drove road 90 metres south of Manor House Farm, Wasperton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005712
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Enclosures and pits north of Hail End Bridge, Wasperton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005715
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Mineral extraction/related subsidence	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854



© Historic England

SITE NAME:	Stoneleigh Abbey, Stoneleigh / Ashow
DESIGNATION:	Registered Park and Garden grade II*, 30 LBs, 2 SMs
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	High
TREND:	Improving
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1000377

Complex multi-phase landscape, incorporating Medieval deer park and work by Repton, Nesfield and Percy Cane. Deer park now a golf course. Business park and residential enclaves built within historic landscape. Also contains Royal Agricultural Society's permanent showground. Impressive programme of restoration of cascades, bridges and other water features through Natural England's Environmental Stewardship scheme which is complete, with a further phase planned. Other parts of the historic estate remain vulnerable eg route of High Speed 2 (HS2) railway.

Contact: Kim Auston 0117 975 0696



© Historic England

SITE NAME:	Guy's Cliffe, Warwick / Leek Wootton and Guy's Cliffe / Old Milverton
DESIGNATION:	Registered Park and Garden grade II, 9 LBs, SM
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Stable
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1001602

Picturesque landscape either side of the River Avon. Main house is a ruinous shell. Chapel now a Masonic temple. Derelict gardens periodically cleared by volunteers. Most of park ploughed and majority of parkland trees lost. Urban expansion (of Warwick), affecting the park, has been mooted although in the latest iteration of the Warwick Local Plan the threat appears to have been removed.

Contact: Kim Auston 0117 975 0696

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

WEST MIDLANDS

BIRMINGHAM



© Historic England

SITE NAME:	British Rail Goods Office (Curzon Street Station), Birmingham
DESIGNATION:	Listed Building grade I
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1343086

Original terminus of the London to Birmingham railway by Philip Hardwick. Built in 1838 in the Ionic style. The building is owned by the City Council and has been vacant for over eight years. Repairs to the roof have been undertaken but water ingress is still a problem. Potential for redevelopment in association with HS2 exists; the building is included in the Birmingham Curzon HS2 Masterplan, in the 'Visit' quarter, but no use has been identified and the building may lie vacant until 2026 when new station is due to open.

Contact: Katriona Byrne 0121 625 6858



© Historic England

SITE NAME:	Grand Hotel, Colmore Row, Birmingham
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1391246

A large Victorian hotel dating from 1875. The Grand Hotel is a landmark building overlooking Cathedral Square with an important suite of public rooms. The main elevations are in very bad condition due to the poor quality of the original stone. Repairs to the stonework are well under way with the help of a Historic England grant. A further phase of work on repairs to the Barwick Street range is about to start. Permissions for re-use as a hotel with shops and offices have been granted and works are underway.

Contact: Sarah Lewis 0121 625 6886



© Historic England

SITE NAME:	Methodist Central Hall, Corporation Street, Birmingham
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1075607

A substantial building constructed in 1903/4 by E and JA Harper in red brick and terracotta. The ground floor is in various retail uses, some vacant, the upper floors are vacant. Planning approval and Listed Building Consent was granted for conversion to mixed office/residential use, but was not implemented and has expired. Birmingham City Council negotiated with the owner to undo unauthorised works but the building continues to deteriorate with extensive vegetation at upper levels.

Contact: Katriona Byrne 0121 625 6858



© Historic England

SITE NAME:	The Red Lion Public House, Soho Road, Birmingham
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1276278

Public house, 1901-2 by James & Lister Lea for the Holt Brewery Company. Built of red brick with terracotta facade, the building is of unusual richness and completeness with interior detailing comparable with best surviving examples nationally. Leaking roofs have caused significant problems; pigeons occupy upper floors. A new owner undertook urgent works, including repairs to roof, and gained Listed Building Consent for re-use as a public house restaurant. However works have not been carried out and building is for sale/lease again since 2014. Condition is deteriorating.

Contact: Katriona Byrne 0121 625 6858



© Historic England

SITE NAME:	Perrott's Folly, Waterworks Road, Edgbaston
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Other not for profit group
LIST ENTRY NUMBER:	1076123

Built in 1758 by John Perrott as a folly adjacent to his house (long demolished). Six storey structure with circular stair tower attached. Adjoining waterworks tower said to be inspiration for Tolkien's 'The Two Towers'. Urgent repairs to address immediate structural problems completed. A business plan for long-term future use and completion of repairs is necessary.

Contact: Cristina Gardiner 0121 625 6850

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	303, Icknield Street, Hockley
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Local authority, multiple owners
LIST ENTRY NUMBER:	1291556

Built 1883, by Martin and Chamberlain, in brick and terracotta with tiled roof as master's house to the Icknield Street School. Now derelict and in poor state of repair with risk of rapid deterioration. Upper storey windows and door now boarded up. Contact has been made with the leasees to seek solution.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	Horseshoe shaped former stables and stores (City of Birmingham Engineers Depot), 23 Sheepcote Street, Ladywood
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1220997

Former stables, originally Corporation Depot 1873, winning competition entry by W H Ward. All four buildings are in poor condition. The Roundhouse is mainly vacant and clearly deteriorating. The Canal and River Trust is working with the National Trust on a mixed use scheme for re-use with a visitor centre and canal related activities.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	Public Baths, Moseley
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1076274

Municipal baths with lavish terracotta decoration and complete interiors. The baths were opened in 1907 as an addition to the Free Library (1895) forming an impressive group of public buildings. A masterplan for future use of the building has been prepared by the City Council but plans to bid for Heritage Lottery Fund grant have been abandoned. Discussion is now focused on urgent interim works to keep the building watertight pending a resurrection of the Heritage Lottery Fund bid.

Contact: Cristina Gardiner 0121 625 6850



© Historic England Archive

SITE NAME:	Former School of Art, 496-500 Moseley Road, Moseley
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1343102

Moseley School of Art was designed by Bidlake and built in 1899. It was bought from the Council in the 1960s by the Moseley Muslim Community Association (MMCA). The building is now suffering from neglect; spalling stonework and leaking roofs are problems. Historic England and the Architectural Heritage Fund have worked with the MMCA to take a project for more intensive use forward and a stage one Heritage Lottery Fund grant has been awarded

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	100 Sampson Road, Sparkhill
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1076179

Built in 1901 as the vicarage to St Agatha's Church in Sparkbrook and designed in an Arts and Craft style by local Birmingham architect, WH Bidlake. Formerly converted to flats by a Housing Association, the building is now in private ownership but has been subject to vandalism, a small fire and is now suffering from dry rot and isolated structural issues. Localised repairs have been carried out but the property has been for sale since 2013 and continues to deteriorate with missing tiles, decaying windows etc.

Contact: Katriona Byrne 0121 625 6858

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site




© Historic England

SITE NAME:	Edward Road Baptist Church, Edward Road, Birmingham
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1343405

This is a good example of the Birmingham Terracotta School's work which combines Romanesque and Perpendicular details. There is evidence of damp at high level, the roof needs attention, the gutters need cleaning and the joints to brick and terracotta blocks are badly eroded.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	Church of St George, Westbourne Crescent, Edgbaston, Birmingham
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1211414

Constructed in three separate phases to the design of J J Scoles (1836-38), Charles Edge (1855-7) and J A Chatwin (1884-5) in a light colour Alvechurch sandstone and a slate roof. The two southern aisles were part of the original first phase and the chancel north-east vestry and tower were added to these in the second phase. The current large nave and chancel replaced the former south aisle. The stonework at high level is in very poor condition and in need of urgent repairs because of expanding ferrous fixings.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	Icknield Street School, Icknield Street, Hockley
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Local authority, multiple owners
LIST ENTRY NUMBER:	1076315

School designed in 1883 by Martin and Chamberlain. The building is occupied as an Ashram for the purpose of worship and community use. The roof to the fire-damaged area has been repaired, but more comprehensive repair of the building is needed. Rainwater goods are in poor shape and unsympathetic security measures detract from the appearance of the building.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	Roman Catholic Church of St Thomas More, Horse Shoes Lane, Sheldon
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1410131

St Thomas More in Sheldon, Birmingham is designated as a good example of a modern Roman Catholic church designed by Richard Gilbert Scott, with innovative and high quality design and detailing. The exterior of the church expresses the Vatican II fan shape plan form, with concrete ribs and stained glass windows by John Chrestien. The interior is well designed and has good quality fittings. The church received an Historic England and Heritage Lottery Fund Repair Grant for Places of Worship and work is due to commence in 2015.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	Bethel United Church, Coventry Road, Small Heath
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1234443

An Italianate brick church built in 1911 and designed by JL Ball. Holes in the roof have allowed water to damage plasterwork to the nave ceiling. There is a need for maintenance with some brickwork decay. Some windows are in poor condition and some have been replaced with uPVC.

Contact: Cristina Gardiner 0121 625 6850

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site



© Historic England

SITE NAME:	Bishop Latimer Memorial Church of All Saints, Handsworth New Road, Winson Green
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1343061

A very large brick church designed by Bidlake and erected in 1903, with important interior. The church is located in a multi-cultural part of the city with a range of social and economic issues. The church has received a series of grants for repairs in the past, but the last in 2010 was stopped because of the threat of church closure. The proposed tenant intends to keep the building in use as a place of worship and is in negotiations with Historic England over grant aid.

Contact: Cristina Gardiner 0121 625 6850

SITE NAME:	Kent's Moat	LIST ENTRY NUMBER:	1020538
DESIGNATION:	Scheduled Monument	TREND:	Declining
CONDITION:	Generally satisfactory but with significant localised problems	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	CONTACT:	Imogen Sambrook 0121 625 6854
OWNER TYPE:	Local authority		

SITE NAME:	Barnsley Road	NEW ENTRY?:	No
DESIGNATION:	Conservation Area, 4 LBs	TREND:	Deteriorating significantly
CONDITION:	Very bad	CONTACT:	Simon Delahunty-Forrest (LPA) 0121 464 8258
VULNERABILITY:	Medium		

SITE NAME:	Digbeth / Deritend	NEW ENTRY?:	No
DESIGNATION:	Conservation Area, 12 LBs	TREND:	Improving
CONDITION:	Very bad	CONTACT:	Simon Delahunty-Forrest (LPA) 0121 464 8258
VULNERABILITY:	Low		

SITE NAME:	Four Oaks	NEW ENTRY?:	No
DESIGNATION:	Conservation Area, 27 LBs	TREND:	Deteriorating
CONDITION:	Poor	CONTACT:	Simon Delahunty-Forrest (LPA) 0121 464 8258
VULNERABILITY:	Medium		

SITE NAME:	Ideal Village, Bordesley Green	NEW ENTRY?:	No
DESIGNATION:	Conservation Area	TREND:	Deteriorating
CONDITION:	Very bad	CONTACT:	Simon Delahunty-Forrest (LPA) 0121 464 8258
VULNERABILITY:	Medium		

SITE NAME:	Lozells and Soho Hill	NEW ENTRY?:	No
DESIGNATION:	Conservation Area, 37 LBs	TREND:	No significant change
CONDITION:	Very bad	CONTACT:	Simon Delahunty-Forrest (LPA) 0121 464 8258
VULNERABILITY:	High		

SITE NAME:	School Road	NEW ENTRY?:	No
DESIGNATION:	Conservation Area, LB grade II	TREND:	Deteriorating
CONDITION:	Poor	CONTACT:	Simon Delahunty-Forrest (LPA) 0121 464 8258
VULNERABILITY:	Low		

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Steelhouse		
DESIGNATION:	Conservation Area, 8 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Unknown
VULNERABILITY:	Medium	CONTACT:	Simon Delahunty-Forrest (LPA) 0121 464 8258

SITE NAME:	Warwick Bar		
DESIGNATION:	Conservation Area, 7 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Simon Delahunty-Forrest (LPA) 0121 464 8258

COVENTRY




© Historic England

SITE NAME:	Cook Street Gate
DESIGNATION:	Scheduled Monument, LB grade I, part in RPG grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1005908

The only remaining functional medieval gate to Coventry. Construction of the gate began in the early C14 and was completed later that century following a licence to crenellate in 1363. Inappropriate historic repairs, vulnerability to vehicle damage and stone erosion are issues.

Contact: John Tiernan 0121 625 6839



© Historic England Archive

SITE NAME:	Coventry City Walls
DESIGNATION:	Scheduled Monument, 2 LBs, part in RPG grade II, 2 CAs
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1002979

Remains include several stretches of the C14 city defences. A Historic England grant was used to fund a conservation management plan for the walls. The Local Authority is now looking to implement the recommendations of the management plan.

Contact: John Tiernan 0121 625 6839



© Acanthus Clews Architects

SITE NAME:	Ruined Cathedral Church of St Michael, Coventry
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1076651

The iconic ruins of the original Coventry Cathedral, destroyed by a bombing raid in November 1940. Areas of the exposed freestanding walls had become unstable. Historic England grant aid has contributed to the tower and wall head masonry repairs which have now been successfully concluded: other repair works to the crypt chapels to eliminate water ingress are due to commence in summer 2015 and be completed by December 2015.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Basement on site of Old Star Inn, Earl Street, Coventry
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1115642

Late medieval cellar of an inn now incorporated in the Civic Centre. Significant erosion of the sandstone took place as a result of water damage. The stone vault was temporarily propped in 2008 and damaged stonework repaired. Since then the stone structure has been steadily drying out. The next phase of work will be to replace the eroded ribs on the vault.

Contact: Sarah Lewis 0121 625 6886

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	The Old Grammar School (St Johns Hospital), Hales Street, Coventry
DESIGNATION:	Listed Building grade I
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Other not for profit group
LIST ENTRY NUMBER:	1320431

Former chapel of the C12 hospital of St John, used as a grammar school after 1545. The building is being repaired and converted as a part of the extension of the adjoining Transport Museum with Heritage Lottery Funding. Work commenced in February 2014 and is nearing completion externally.

Contact: Nick Molyneux 0121 625 6857



© Historic England

SITE NAME:	The Charterhouse, London Road
DESIGNATION:	Listed Building grade I and Scheduled Monument, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1076621 and 1005901

Founded as a Carthusian Monastery dedicated to St Anne, the surviving building is a mixture of stone, brick and timber-frame construction incorporating centuries of change and adaptation. Exceptional and vulnerable wall paintings survive from the C15 and C16. The clay tile roof is in poor condition and there is evidence of water damage within the building. Now in the ownership of the Historic Coventry Trust, the building is part of a major regeneration project supported by a stage one Heritage Lottery Fund grant.

Contact: John Tiernan 0121 625 6839




© Historic England

SITE NAME:	The Charterhouse, precinct walls, London Road, Coventry
DESIGNATION:	Scheduled Monument and Listed Buildings - I grade I; I grade II*, LB grade II, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1005901 and 1076621; 1342917

The inner precinct wall built of sandstone was extended in the centuries after the Reformation when the Charterhouse became a dwelling. It is now in very bad condition with sections which have collapsed and others which are destabilised by vegetation growth. Now owned by Historic Coventry Trust. A Historic England grant has been offered and accepted and assorted masonry repair works are now in progress.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Nonconformist Chapel to the Cemetery, London Road, Coventry
DESIGNATION:	Listed Building grade II*, RPG grade I, CA
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1076624

Cemetery chapel 1846-47, probably by GH Stokes, at southern end of the mid C19 cemetery, landscaped by Joseph Paxton in an informal style. The building remains without a use and in a vulnerable condition. The Historic Coventry Trust has plans for the cemetery to become part of a Heritage Park, their options appraisal completed as part of these plans has identified potential for re-use of the chapel as an office. The Trust is in negotiations with the City Council regarding asset transfer for the cemetery and the chapel.

Contact: Sarah Lewis 0121 625 6886

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Coventry HER 2014

SITE NAME:	Numbers 36 and 37 and archway in between (Whitefriars Gate), 36 and 37, Much Park Street
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1087114

A C14 postern gatehouse of the Carmelite Friary of sandstone and tile with later repairs in brick. Damaged by arson attack in 2008 and repaired, the building has remained vacant since then and is slowly deteriorating. Inappropriate window coverings, erosion of sandstone and mortar joints, continuing threat of vandalism and arson, and rotting timbers in the ceiling of the archway are all issues. Potential for re-use is being explored by the Historic Coventry Trust.

Contact: Sarah Lewis 0121 625 6886



© Historic England

SITE NAME:	Church of St John the Baptist, Fleet Street, Coventry
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1342889

The Church of St John the Baptist is located at the head of Spon Street in the city centre. Built in the mid C14, it was a collegiate church and is largely Perpendicular in appearance with a crossing tower, transepts, clerestories to nave and chancel and aisles. Changes of plan are visible in several places together with alterations to the fabric. The red sandstone used in its construction is of variable quality and maintenance and repair is an ongoing issue, in particular, the condition of the nave clerestory. Transept roofs will soon need recovering due to material failure.

Contact: John Tiernan 0121 625 6839

SITE NAME:	Allesley Castle	LIST ENTRY NUMBER:	1005907
DESIGNATION:	Scheduled Monument	TREND:	Declining
CONDITION:	Generally unsatisfactory with major localised problems	NEW ENTRY?:	Yes
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	CONTACT:	Imogen Sambrook 0121 625 6854
OWNER TYPE:	Local authority		

SITE NAME:	Priory ruins	LIST ENTRY NUMBER:	1005902
DESIGNATION:	Scheduled Monument, 2 LBs, CA	TREND:	Declining
CONDITION:	Generally satisfactory but with significant localised problems	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Vandalism	CONTACT:	Imogen Sambrook 0121 625 6854
OWNER TYPE:	Local authority		

SITE NAME:	Lady Herbert's Garden, Coventry	NEW ENTRY?:	Yes
DESIGNATION:	Conservation Area, 8 LBs, RPG grade II, 2 SMs	TREND:	Deteriorating significantly
CONDITION:	Very bad	CONTACT:	Chris Patrick (LPA) 02476831271
VULNERABILITY:	Low		

SITE NAME:	London Road, Coventry	NEW ENTRY?:	Yes
DESIGNATION:	Conservation Area, 8 LBs, part in RPG grade I, SM	TREND:	Improving
CONDITION:	Very bad	CONTACT:	Chris Patrick (LPA) 02476831271
VULNERABILITY:	Low		

SITE NAME:	Naul's End, Coventry	NEW ENTRY?:	Yes
DESIGNATION:	Conservation Area, 2 LBs	TREND:	Deteriorating
CONDITION:	Poor	CONTACT:	Chris Patrick (LPA) 02476831271
VULNERABILITY:	Low		

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

DUDLEY



© Historic England

SITE NAME:	Triangular Crane, Bumble Hole Boat Yard, Dudley
DESIGNATION:	Scheduled Monument, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1005884

C19 triangular boat crane, in poor condition. Historic England funded a report on the condition and repair of the monument. A grant application for repairs was made but later withdrawn as no other funding was available for repairs. The crane collapsed in 2002 and sections of structure remain stored in the yard. A joint initiative is needed for the repair/reinstatement of the structure. An interpretation project has been carried out culminating on several panels, erected along the Boshboil Arm.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	Church of St John, High Street, Brierley Hill
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1229092

A good example of a neo-Norman Commissioners' Church built in 1844-45 by Thomas Smith. Built in dark brick with yellow dressings it has sandstone carved faces to the kneelers. Stone coped shallow pitched gables and Welsh slate roof. The church is in poor condition: the gutters and downpipes are defunct, the brickwork shows open joints as do the sandstone copings to the gables.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	Church of St Edmund, Castle Street, Dudley
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1287455

Situated in the centre of Dudley, this is a red brick church built in the Palladian style in the 1720s. Shallow tile roofs fall to parapets finished with stone dressings which are also a distinctive feature of the round headed windows and the tower. Vegetation growing out of the tower is impacting on high level stonework and is a significant cause for concern.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	Parish Church of St Thomas, High Street, Dudley
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1075998

Large Georgian church built in Perpendicular style designed by William Brooks 1815-18. The current church is a replacement of a medieval chapel, the remains of which are visible in the crypt. The last quinquennial report carried out in 2012 identified poor condition of the high level limestone stonework which is shaling away in large sections. The church has been awarded a Heritage Lottery Fund grant for the above repairs and roof access improvements so that maintenance can be carried out more easily.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	Church of St James the Great, Salop Street, Dudley
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1270305

A Commissioners' Church of the mid C19, designed by William Bourner. Sister church to St John the Evangelist, Kate's Hill. The church is built of limestone with ashlar stone dressings. A Repair Grant for Places of Worship for stonework repairs was offered by Historic England and the Heritage Lottery Fund in March 2013.

Contact: Cristina Gardiner 0121 625 6850

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Church of St John the Evangelist, St Johns Road, Dudley
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1393300

St John's was designed in the Gothic lancet style by William Bournier and is the sister church to St James, Eve Hill, also in Dudley. The church opened in 1849 but due to safety reasons worship now takes place in the parish hall. A feasibility study for re-use for worship, concerts, a cafe and community and educational use has been carried out. An application has been made to close the church.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	Presbyterian Chapel, Lower High Street, Stourbridge
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1343195

A red brick Presbyterian chapel built in 1788 with round headed windows, stone detailing, and a projecting porch. Brickwork and cast iron windows are in poor condition.

Contact: Cristina Gardiner 0121 625 6850

SITE NAME:	The Redhouse, Whitehouse and Newhouse glassworks		
DESIGNATION:	Scheduled Monument, LB grade II*, CA	LIST ENTRY NUMBER:	1021378
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ian George 0121 625 6859

SITE NAME:	Wychbury Camp (see also Bromsgrove, Worcestershire), Hagley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005900
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Brierley Hill High Street		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Jayne Pilkington (LPA) 01384 814168

SITE NAME:	Stourbridge Branch Canal (Canal Street)		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Jayne Pilkington (LPA) 01384 814168

SITE NAME:	Wollaston		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Jayne Pilkington (LPA) 01384 814168

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Wordsley Church		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Jayne Pilkington (LPA) 01384 814168

SANDWELL

© Historic England Archive

SITE NAME:	Soho Foundry, Foundry Lane, Smethwick
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1268451

Foundry built in 1795: the world's first integrated steam engine manufactory, established by Boulton & Watt. Historic England and the Local Authority grant-aided a temporary roof to stabilise the structure in 2009. Discussions continue with the owners and the local authority to ensure maintenance of the temporary roof and to find a new use.

Contact: Nick Molyneux 0121 625 6857



© Historic England

SITE NAME:	Waterloo Hotel, Shireland Road, Smethwick
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1261644

The Waterloo Hotel was built in 1907 by Wood and Kendrick for local brewers, Mitchells & Butler, in the baroque style with terracotta dressings. This is a near complete example of an Edwardian showpiece pub and commercial hotel, which retains many interior features including the ornately tiled basement grill room. Planning permission was granted in 2013 for conversion of the upper floors to apartments and works have commenced on site. The owner is expecting to have repaired and restored the former public areas of the building for use by early 2016.

Contact: Julie Taylor 0121 625 6848

SITE NAME:	Chances Glassworks, Smethwick		
DESIGNATION:	Scheduled Monument, 5 LBs	LIST ENTRY NUMBER:	1021387
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Ian George 0121 625 6859

SITE NAME:	Engine Arm Aqueduct, Warley		
DESIGNATION:	Scheduled Monument, LB grade II*	LIST ENTRY NUMBER:	1005904
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Cristina Gardiner 0121 625 6850

SITE NAME:	High Street, West Bromwich, Black Country		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Mark Stretton (LPA) 0121 569 4033

SITE NAME:	Market Place, Wednesbury, Black Country		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Mark Stretton (LPA) 0121 569 4033

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

WALSALL



© Walsall Metropolitan Borough Council

SITE NAME:	Great Barr Hall and chapel, Great Barr
DESIGNATION:	Listed Building grade II*, RPG grade II, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1076395

Gothic country house of 1777 with 1863 chapel attributed to George Gilbert Scott. Set in a registered late C18 landscaped park. The hall was extended and converted into a hospital in the early C20 but has been vacant since 1978. Extensive fire damage and vandalism has contributed to general decay and the extensive loss of fabric. The new owners are in negotiation with the Local Authority.

Contact: Julie Taylor 0121 625 6848



© Historic England

SITE NAME:	Church of St Matthew, Church Hill, Walsall
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1116151

St Matthew's was rebuilt in the 1820s by Francis Goodwin. Its soaring spire is a local landmark and its Bath stone facades stand out in the street scene. The style of the church is predominantly Perpendicular but C13 remains survive in the crypt. High level repairs are needed all over this complex building. A Repair Grant for Places of Worship from the Heritage Lottery Fund and Historic England enabled repairs to the north aisle and east end but other sections are now in need.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	Life and Light Mission Church (former Trinity Methodist Church), Union Street, Willenhall
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1077170

Built as a Methodist church in the 1860s, this large rendered church is in the Classical style, with round headed windows and pilasters, making it prominent on the street frontage. The render is loose in many areas allowing water to enter the building. A Repair Grant for Places of Worship was offered by the Heritage Lottery Fund in March 2013 and Stage One project development has been completed.

Contact: Cristina Gardiner 0121 625 6850

SITE NAME:	Bloxwich High Street	NEW ENTRY?:	No
DESIGNATION:	Conservation Area	TREND:	No significant change
CONDITION:	Very bad	CONTACT:	Planning Policy Team (LPA) 01922 658020
VULNERABILITY:	Low		

SITE NAME:	Bradford Street, Walsall	NEW ENTRY?:	No
DESIGNATION:	Conservation Area, 5 LBs	TREND:	No significant change
CONDITION:	Very bad	CONTACT:	Planning Policy Team (LPA) 01922 658020
VULNERABILITY:	Low		

SITE NAME:	Bridge Street, Walsall	NEW ENTRY?:	No
DESIGNATION:	Conservation Area, 10 LBs	TREND:	Improving
CONDITION:	Very bad	CONTACT:	Planning Policy Team (LPA) 01922 658020
VULNERABILITY:	Low		

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.


NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Caldmore Green, Walsall		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Planning Policy Team (LPA) 01922 658020
<hr/>			
SITE NAME:	Church Hill, Walsall		
DESIGNATION:	Conservation Area, 17 LBs, RPG grade II*	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Planning Policy Team (LPA) 01922 658020
<hr/>			
SITE NAME:	Elmore Green, Bloxwich		
DESIGNATION:	Conservation Area, 3 LBs, SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Planning Policy Team (LPA) 01922 658020
<hr/>			
SITE NAME:	Willenhall		
DESIGNATION:	Conservation Area, 10 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Planning Policy Team (LPA) 01922 658020

WALSALL / SANDWELL



© Historic England

SITE NAME:	Great Barr Hall, Walsall	<p>Parkland and pleasure grounds, partly by Humphry Repton and John Nash. Much of historic park built over as mental hospital in C 20, in turn replaced by modern housing estate circa 2005. Pleasure grounds overgrown and neglected; remaining area of park also in poor condition. Hall is dilapidated and also at risk. In 2010 English Heritage reviewed the area covered by the registered park and enlarged it. Change of ownership in spring 2012. Proposals for Enabling Development remain under consideration by the Local Authority. Part of the park is in the district of Sandwell.</p> <p>Contact: Kim Auston 0117 975 0696</p>
DESIGNATION:	Registered Park and Garden grade II, 3 LBs, part in CA	
CONDITION:	Extensive significant problems	
VULNERABILITY:	High	
TREND:	Declining	
NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	
LIST ENTRY NUMBER:	1001202	

WOLVERHAMPTON, CITY OF



© Historic England

SITE NAME:	The Greyhound and Punchbowl Inn (formerly Stoke Heath Manor House), High Street, Bilston	<p>Mid C16 manor house, restored in the 1930s. Of timber framed construction, strengthened with concrete skin in the 1930s. Now suffering complex structural problems to the supporting concrete frame requiring a long term solution. Historic England engineer has prepared a preliminary report. A more detailed structural survey and investigation will be required to establish the most appropriate method of repair.</p> <p>Contact: Imogen Sambrook 0121 625 6854</p>
DESIGNATION:	Listed Building grade II*	
CONDITION:	Poor	
OCCUPANCY:	Occupied/in use	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1201819	

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site



© Historic England

SITE NAME:	Church of St Leonard, Church Street, Wolverhampton
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1282492

This church was built in 1825 to designs by Francis Goodwin, and restored in the 1880s by Ewan Christian. It is in the neoclassical style, finished in render with elegant round headed windows and a fine octagonal tower. The interior has decorative plaster ceilings and balconies. Leaking parapet gutters are affecting the render externally and the plaster internally.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	Church of St Martin and attached cloister and vicarage, Dixon Street, Wolverhampton
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1282500

Church, cloister and vicarage built 1938-9 by Lavander and Twentyman. Brick Modernist church with pantile roofs, coped gables and parapets. The elevations are plain except for the statue of St Martin by Donald Potter on the west facade above the entrance. The interior is remarkably intact. The church was originally lined with asbestos, which is still in place. The roof and gutters are in need of repair so that leaks do not disturb the asbestos below. Previous water ingress meant the building had to be closed until the leaks were patched up but a comprehensive repair is now needed.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	Catholic Church of St Mary and St John, Snow Hill, Wolverhampton
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1208140

Roman Catholic church built 1851-5 by Charles Hansom and extended 1879-80. Built in ashlar with a slate roof, it has an apsidal chancel and French Gothic treatment. It has a rich interior with excellent fittings and is a good example of a mid-Victorian Catholic church. High level stonework is very poor, causing a hazard and the gutters and rain water pipes are also in need of repair. The church has been awarded a Heritage Lottery Fund Grant for Places of Worship and works should commence in 2015/16.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	Church of St Luke, Upper Villiers Street, Wolverhampton
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Very bad
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1293038

Gothic Revival church by GT Robinson of Leamington built in polychromatic brickwork in 1860. The church is large and its soaring, decorated spire is a local landmark in the Blakenhall area. Dry rot was addressed some years ago, but many other issues remain for this very large building.

Contact: Cristina Gardiner 0121 625 6850

SITE NAME:	Bilston Canal Corridor	
DESIGNATION:	Conservation Area	NEW ENTRY?: Yes
CONDITION:	Very bad	TREND: No significant change
VULNERABILITY:	Low	CONTACT: Jon Beesley (LPA) 01902 555622

SITE NAME:	Bilston Town Centre	
DESIGNATION:	Conservation Area	NEW ENTRY?: Yes
CONDITION:	Very bad	TREND: Deteriorating
VULNERABILITY:	Low	CONTACT: Jon Beesley (LPA) 01902 555622

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site

SITE NAME:	Bushbury Hill	NEW ENTRY?:	Yes
DESIGNATION:	Conservation Area	TREND:	Improving
CONDITION:	Very bad	CONTACT:	Jon Beesley (LPA) 01902 555622
VULNERABILITY:	Medium		
SITE NAME:	Cleveland Road	NEW ENTRY?:	Yes
DESIGNATION:	Conservation Area	TREND:	Deteriorating significantly
CONDITION:	Very bad	CONTACT:	Jon Beesley (LPA) 01902 555622
VULNERABILITY:	Medium		
SITE NAME:	Park	NEW ENTRY?:	Yes
DESIGNATION:	Conservation Area	TREND:	Deteriorating
CONDITION:	Poor	CONTACT:	Jon Beesley (LPA) 01902 555622
VULNERABILITY:	Medium		
SITE NAME:	Springfield Brewery	NEW ENTRY?:	Yes
DESIGNATION:	Conservation Area	TREND:	Improving significantly
CONDITION:	Very bad	CONTACT:	Jon Beesley (LPA) 01902 555622
VULNERABILITY:	High		
SITE NAME:	The Oaks (Merridale Road)	NEW ENTRY?:	Yes
DESIGNATION:	Conservation Area	TREND:	Deteriorating
CONDITION:	Very bad	CONTACT:	Jon Beesley (LPA) 01902 555622
VULNERABILITY:	High		
SITE NAME:	Union Mill	NEW ENTRY?:	Yes
DESIGNATION:	Conservation Area	TREND:	Improving
CONDITION:	Very bad	CONTACT:	Jon Beesley (LPA) 01902 555622
VULNERABILITY:	Medium		
SITE NAME:	Worcester Street	NEW ENTRY?:	Yes
DESIGNATION:	Conservation Area	TREND:	No significant change
CONDITION:	Very bad	CONTACT:	Jon Beesley (LPA) 01902 555622
VULNERABILITY:	Medium		

WORCESTERSHIRE

BROMSGROVE



© Historic England

SITE NAME:	Standing cross in St Leonards churchyard, Frankley
DESIGNATION:	Scheduled Monument, LB grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1017255

A C15 churchyard cross of sandstone restored in 1915. It comprises a plinth of one octagonal stone step on which sits a single octagonal base stone with a rectangular section shaft topped by a cross head. The decorated shaft and cross head are heavily weathered, the cross head shows cracking to the underside and mossy growth on upper surfaces, there is a limited amount of delamination on the west face.

Contact: Imogen Sambrook 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Temple of Theseus, Hagley Hall, Hagley
DESIGNATION:	Listed Building grade I, RPG grade I
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1348599

Doric temple of 1758 designed by James 'Athenian' Stewart. It stands in the Grade I registered landscape park 800 metres north of the Hall. It is separated from the rest of the estate by the A456; this relatively isolated location has rendered it vulnerable to vandalism so security fencing has been erected. Discussions continue with the owner on a strategy to secure the future of the building. A new visitor centre on the estate gained planning permission in 2014.

Contact: Katriona Byrne 0121 625 6858



© Historic England

SITE NAME:	Church of St Laurence, Bear Hill, Alvechurch
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1100225

Large parish church. Mostly rebuilt 1860 to 1861 by W Butterfield retaining only a C15 tower which was re-modelled in 1676. Badly eroded or damp affected sandstone on the north side and at low level on the tower. Rainwater goods poor, especially on the tower.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Christ Church, Catshill, Catshill and North Marlbrook
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1099541

Large suburban parish church. Nave and west tower built in 1838 by Harvey Eginton, the east end of chancel and flanking chapels rebuilt by JA Chatwin in 1887, mostly in the Early English style. Red sandstone ashlar with slate roofs. The sandstone is heavily eroded with harmful vegetation growth. Many leaks have sprung from the failing parapet gutters.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Bartholomew, High House Lane, Tutnall and Copley
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1100167

Parish church; nave and west tower and spire with Baroque bell stage from 1777 by Francis Hiorn. The chancel was added in 1880. The sandstone ashlar is heavily eroded. The downpipes are leaking and seriously degrading the stone behind.

Contact: Chris Miners 0121 625 6835

SITE NAME:	Moated site 130 metres north east of Moorgreen Farm, Alvechurch		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017527
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Imogen Sambrook 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Moated site at Blackgreves Farm, Wythall		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1017804
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Other not for profit group	CONTACT:	Imogen Sambrook 0121 625 6854



© Historic England

SITE NAME:	Hewell Grange, Tutnall and Cobley / Bentley Pauncefoot	Multi-phase landscape, including work influenced by Humphry Repton. Another major period of activity towards the end of C19 when current house built. Post-war development by Prison Service has had a major impact on legibility of design. Management plan and partnership with County Gardens Trust has led to renewed interest in and care for designed landscape, including restoration of bridge to island and the commissioning of a Statement of Significance for the ruined mansion at the heart of the landscape.
DESIGNATION:	Registered Park and Garden grade II*, 15 LBs	
CONDITION:	Extensive significant problems	
VULNERABILITY:	High	
TREND:	Stable	
NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	
LIST ENTRY NUMBER:	1000886	Contact: Kim Auston 0117 975 0696

SITE NAME:	Bromsgrove Town Centre		
DESIGNATION:	Conservation Area, 53 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Mary Worsfold (LPA) 01527 881329

MALVERN HILLS



© Historic England

SITE NAME:	Stone Farmhouse and attached Hop Kiln, Bromyard Road, Broadwas	An attractive C15 timber framed farmhouse which originated as a cruck framed hall house and was enlarged in the C16 and C19; there is a late C19 brick hop kiln attached on the rear gable. The building has a high quality medieval roof and attractive carved timberwork. The condition of the hop kiln roof is very bad, the house roof is poor in places and the timber frame is missing from one gable and is in poor condition elsewhere.
DESIGNATION:	Listed Building grade II*	
CONDITION:	Poor	
OCCUPANCY:	Part occupied/part in use	
PRIORITY CATEGORY:	A (New entry)	
OWNER TYPE:	Unknown	
LIST ENTRY NUMBER:	1082977	



© Historic England

SITE NAME:	Mythe Bridge (that part in Civil Parish of Bushley), Tewkesbury Road, Bushley	Road bridge over the River Severn. Built 1823-26 by Thomas Telford. Cast iron bridge of 6 segmental arched lattice beams, latticed roadway beam with latticed ironwork filling the spandrels. Each abutment has inner and outer sandstone piers separated by 6 brick arched tunnel vaults with cast iron colonettes. The ironwork of the balustrades is rusting at the connections. The sandstone piers, especially above the roadway level, are severely fractured and eroded, and some are covered in excessive and harmful ivy growth. Also included in the South West Heritage at Risk Register.
DESIGNATION:	Listed Building grade II*	
CONDITION:	Poor	
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1238445	

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Church of St Bartholomew, Bayton
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1081471

Small rural parish church in an exposed hilltop location. Mainly C12 core of the nave and the chancel masonry. C15 nave roof. West tower added 1817. The roof tiling is at the end of its economic life and water ingress is beginning to take its toll on the internal plasterwork. Chronic damp problem at low level resulting in stone erosion and the wood block flooring is adversely affected. Considerable erosion of masonry around some windows and cement mortar pointing over lime is causing masonry erosion elsewhere. Heritage Lottery Fund grant awarded and is in the development stage.

Contact: Chris Miners 0117 975 1308



© Historic England

SITE NAME:	Church of St Faith, Berrow
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1098847

Rural parish church. West tower, nave with south aisle and gabled north entrance porch, lower east chancel with C12 origins. Chancel C14, the south aisle, tower and porch C15. Mid-C19 restoration. Coursed sandstone rubble with ashlar dressings. Generally clay tile roofs except for sandstone slates on the north nave and porch pitches. Cast iron rainwater goods. Cracking in walling, generally located to the south side of the church. Structural stitching is needed. Damp within the walling and floors causing internal decay. A Heritage Lottery Fund repair grant has been awarded.

Contact: Chris Miners 0121 625 6835



© Historic England Archive

SITE NAME:	Church of St Michael, Great Witley
DESIGNATION:	Listed Place of Worship grade I, RPG grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	B (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1082655

Large parish church attached to Witley Court. Notable for one of the finest English baroque church interiors. The slate roof is failing with rusted fixings and slipped slates that imperil the painted interior below. A Heritage Lottery Fund and Historic England Repair Grant for Places of Worship has been offered for repairs, the development has been completed and repairs will soon be underway.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Michael, Knighton on Teme
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1167609

Small rural parish church. C12 nave and chancel. Nave extended to encompass a detached bell tower in early C13, chancel extended and re-modelled in 1880. Red sandstone rubble walls with some tufa tiled roofs. The bell turret and spire were clad in cedar shingles when it was simplified in 1954. These have severely eroded and have been attacked by woodpeckers which have left many holes on all the faces. This has let in rainwater to rot the floorboards. A Heritage Lottery Fund Grant for Places of Worship for the repair work has been offered and project development work completed.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Christ Church, Avenue Road, Barnards Green, Malvern
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1391823

Large parish church built in 1875 by Barry & Sons in the Decorated style. Grey rock-faced sandstone walling with lofty west steeple. The fixings of both the tiles and the battens of the upper, steeper, roof pitches are failing. Falls of tiles are smashing the lower shallower slated pitches. A Heritage Lottery Fund Grant for Places of Worship for the repair works has been offered and the development phase has been completed.

Contact: Chris Miners 0121 625 6835

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Holy Trinity Church, Worcester Road, Link Top, Malvern	Large suburban parish church. Built in 1851 by SW Daukes in the late C13 style. Malvern granite stone with stone tiles over the chancel and nave, slates elsewhere. The stone slates have failed on the nave and chancel. The chancel stone slates have just been renewed together with urgent repairs to the belfry. The nave re-slatting remains to be carried out. A Historic England and Heritage Lottery Fund Repair Grant for Places of Worship has been offered for this work and the development stage has been completed. Repairs are underway in 2015.
DESIGNATION:	Listed Place of Worship grade II, CA	
CONDITION:	Poor	
PRIORITY CATEGORY:	F (D)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1392674	Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Andrew, Stanford with Orleton	Small parish church. Sandstone rubble C12 nave with south porch and buttressing from the C14 and brick chancel from a 1718 rebuild. Tiled roofs and a boarded bellcote with pyramid slate roof over the nave. Structural work has been carried out on the church with success at the west end but severe structural movement cracking is still evident at the chancel.
DESIGNATION:	Listed Place of Worship grade II*	
CONDITION:	Very bad	
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1082110	Contact: Chris Miners 0121 625 6835

SITE NAME:	Enclosure 110 yards (100 metres) north of St Bartholomew's Church, Grimley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005296
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Religious organisation	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Enclosure west of Church Farm, Grimley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005315
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Religious organisation	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Motte and bailey castle at Castle Green, Leigh		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018010
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Moated site at Earl's Court, Rushwick		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017229
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Witley Court, Great Witley / Hillhampton / Little Witley
DESIGNATION:	Registered Park and Garden grade II*, 18 LBs, SM
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	High
TREND:	Declining
NEW ENTRY?:	Yes
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1000901

Pre-eminent C19 landscape in multiple ownership. Parts of the registered park and garden are well cared for but there are concerns about intrusive development in the park, loss of parkland trees and a lack of a historically informed management plan for the greater area of the park.

Contact: Kim Auston 0117 975 0696

SITE NAME:	Tenbury Wells, Tenbury	NEW ENTRY?:	No
DESIGNATION:	Conservation Area, 55 LBs, part in SM	TREND:	Improving
CONDITION:	Very bad	CONTACT:	Nicky Wardroper (LPA) 01684 862326
VULNERABILITY:	Medium		

REDDITCH

SITE NAME:	Feckenham manorial moated site, Feckenham	LIST ENTRY NUMBER:	1018361
DESIGNATION:	Scheduled Monument	TREND:	Declining
CONDITION:	Generally satisfactory but with significant localised problems	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Visitor erosion - moderate	CONTACT:	Imogen Sambrook 0121 625 6854
OWNER TYPE:	Local authority		

WORCESTER



© Historic England

SITE NAME:	City walls: section extending 130ft (40m) from the back of No 27 New Street to Windsor Row
DESIGNATION:	Scheduled Monument, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1005282

Medieval city walls in multiple ownership, which results in the lack of a co-ordinated approach. A variety of repair and maintenance has taken place in the past. A Conservation Management Plan for the medieval defences has been completed. Sections of the wall have been repaired with Historic England grant aid.

Contact: Imogen Sambrook 0121 625 6854



© Historic England

SITE NAME:	Waiting Room, Shrub Hill Station, Worcester
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (F)
OWNER TYPE:	Utility
LIST ENTRY NUMBER:	1390157

This ornate waiting room, circa 1880, is of cast iron frame construction with infill panels of glazed ceramic tiles. A scheme for full restoration and re-use progressed well but has stalled. The structure is fenced off on the platform. Repairs need to be completed.

Contact: Cristina Gardiner 0121 625 6850

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Moated monastic grange and fishpond complex at Middle Battenhall Farm, 450 metres north of Upper Battenhall Farm, St. Peter the Great County		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017310
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Lowesmoor, Worcester		
DESIGNATION:	Conservation Area, 15 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	James Dinn (LPA) 01905 721132

WYCHAVON



© Historic England

SITE NAME:	Eckington Bridge, Birlingham / Defford / Eckington
DESIGNATION:	Scheduled Monument and Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1005264 and 1116724

Fine example of early C16 bridge of six arches built in sandstone. It is a narrow single track road bridge controlled by traffic lights. The bridge has suffered from frequent traffic collisions and chemical erosion from roadsalt penetration of structure. The Local Authority has undertaken stonework repairs and waterproofed concrete deck of bridge to reduce impact. A further scheme of repair has been agreed for 2016.

Contact: Neil Rimmington 0121 625 6856



© Historic England

SITE NAME:	31 High Street, Droitwich Spa
DESIGNATION:	Listed Building grade II*, SM, CA
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1296659

The solar wing of a C14 timber framed town house. The front range is rendered but incorporates exceptional timber work in the roof and ceiling structures. C17 extensions to the rear are in very bad condition with structural failure to the timber frame and walls. Failed rainwater goods and a roof in poor condition are letting water into the structure and rotting the frame. The building is only partly occupied. A Historic England repair grant is being applied for.

Contact: Chris Miners 0117 975 1308



© Historic England

SITE NAME:	Abbot Chyryton wall, Boat Lane, Evesham
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1005501 and 1350435

Part of the outer precinct wall of Evesham Abbey, built by abbot William de Chyryton 1317-44, which originally extended from river to abbey. Previous grant aided consolidation has partially failed due to vandalism. Some parts of wall still in very bad condition, and wall footings are diminishing. Discussions are ongoing to agree a long term solution.

Contact: Neil Rimmington 0121 625 6856

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Abbot Reginalds Wall, Evesham Abbey, Evesham
DESIGNATION:	Scheduled Monument and Listed Buildings - I grade I; I grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private, multiple owners
LIST ENTRY NUMBER:	1005298 and 1081349; 1081350

Abbot Reginalds wall forms part of the main ecclesiastical complex of Evesham Abbey, fragments of which still survive. The rebuilding of the collapsed section and repairs to adjoining wall have been completed with grant aid. Sections of wall are still in poor condition and in need of an overall repair strategy.

Contact: Imogen Sambrook 0121 625 6854



© Historic England

SITE NAME:	The Bell Tower, Market Place, Evesham
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	F (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1081353

Late medieval detached bell tower, formerly part of Evesham Abbey. It is a beautiful example of late Gothic carved ornamentation and has become the icon for Evesham. Although looking superficially sound, all faces and elements need carefully conservation and repair. Recent falls of stone triggered detailed surveys which revealed dangerous levels of decay of the limestone, with much loss of historic features. A Heritage Lottery Fund grant for repairs has been accepted and repairs are underway, with completion in December 2015.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	West porch of Bengeworth Old Church, Church Street, Bengeworth, Evesham
DESIGNATION:	Scheduled Monument and Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1005299 and 1095958

The old church of St Peter was pulled down in 1870, leaving the remains of the porch that stood under the west tower. It is constructed of rubble masonry, which has been pointed with cement in the past and is now cracking. Issues include missing roof tiles, salt erosion causing stone damage by road and structural cracking on south east corner. The roof structure is also at risk. The Town Council has removed the damaging ivy previously covering the south elevation. Historic England is seeking to help the Council with an offer of grant aid for the repairs.

Contact: Imogen Sambrook 0121 625 6854



© Historic England

SITE NAME:	Church of St James, Bredicot
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1117084

Tiny church in the old rectory garden with three-bay nave/chancel, south porch and bellcote. Walls are rubble with ashlar dressings and tiled roof. Restored in 1843 by Perkins. The sandstone of the window masonry is heavily eroded and falling apart.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St John the Baptist, Church Walk, Crowle
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1081275

The original medieval church was demolished and rebuilt in the 1880s to designs by Frederick Preedy in the Decorated style with a tall west tower. The church is constructed from lias limestone rubble with ashlar dressings under a plain clay tile roof with decorative ridges. The roof and rainwater goods are in poor condition and minor repairs are required to the stonework. An Historic England and Heritage Lottery Fund Repair Grant for Places of Worship was offered in February 2013 but no work has resulted.

Contact: Chris Miners 0117 975 1308

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Church of St Andrew, St Andrew's Street, Droitwich Spa
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1167974

Large parish church in the centre of Droitwich. Sandstone ashlar with roofs of mixed materials. Nave and chancel flanked by tall aisles, with a truncated integral north tower set in the north range. A parish centre is attached on the south side. Tiled roof and the rainwater system of the north east chapel are leaking, causing decay in the C15 ceiling below. Other roofs and high level walls were repaired with Historic England grant aid 10 years ago.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Peter, Flyford Flavell
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1039144

Small parish church. The nave, chancel and north transept are mostly from the rebuild by Hopkins in 1883 incorporating older materials, but the west tower is C15. There is structural movement on the west face of the tower, and excessive vegetation growth on all parts of the church. A Listed Places of Worship Roof Repair Fund grant was awarded in March 2015.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St John the Baptist, Grafton Flyford
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1374136

Medieval church dating from the C13 to C14 with Perpendicular window tracery. It was restored in 1875 by Hopkins. There are patches of weathered stonework on the tower and chancel as well as vegetation and moss growth on the tower, nave, vestry and chancel. Leaking guttering on the vestry has resulted in the saturation of surrounding stonework and there are some structural cracks in the east elevation of the vestry.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St James, Hartlebury
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	B (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1288150

Large parish church. Mostly rebuilt by Rickman who rebuilt the chancel and its chapels in 1825 and the nave and aisles in 1837 retaining the C16 tower. Sandstone ashlar and roofs of mixed materials. Leaks in the nave roof have caused a section of decorative ribbed vaulted plasterwork to fall. Repairs now underway in 2015.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Peter, Hinton on the Green
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Very bad
PRIORITY CATEGORY:	B (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1215987

Small parish church. C12 nave, C15 west tower and nave battlements, chancel and porch C19. Lias coursed rubble with ashlar dressings and tiled roofs. Tower has structural cracking and past falls of ashlar. A Listed Places of Worship Roof Repair Fund grant was awarded in 2015.

Contact: Chris Miners 0121 625 6835

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Abbey Church of Holy Cross, Church Walk, Pershore
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1387027

Large urban parish church and former Benedictine Abbey with classic cruciform abbey church plan from the C12 and C13, but now without the nave and north transept. Restored by GG Scott 1864. Walling is mostly limestone ashlar from C13, the high Lierne vaulting from the late C13. Roofs are now tiles except for the stone slates on the hipped apse roof. Water ingress into the north east transept valley has decayed the supporting timber structure and the stonework below. A Heritage Lottery Fund Grant for Places of Worship has been awarded.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Michael, Main Street, South Littleton
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1081303

Small parish church. Circa 1200 nave, C14 chancel and north transept, and C15 west tower and south porch. Roofs, porch and chancel severely restored by Preedy in 1883. Lias coursed rubble with limestone ashlar dressings and clay tiled roof. The stonework is failing on the north side together with excessive vegetation growth and rainwater goods that need urgent renewal.

Contact: Chris Miners 0121 625 6835

SITE NAME:	Settlement site NNE of Fernhill Farm, Charlton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: 1005287
CONDITION:	Generally unsatisfactory with major localised problems	TREND: Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?: No
OWNER TYPE:	Private	CONTACT: Imogen Sambrook 0121 625 6854

SITE NAME:	Enclosures north east of Fernhill Farm, Charlton / Cropthorne	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: 1005286
CONDITION:	Unknown	TREND: Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?: No
OWNER TYPE:	Private	CONTACT: Imogen Sambrook 0121 625 6854

SITE NAME:	Roman settlement at Bays Meadow, Droitwich Spa	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: 1020620
CONDITION:	Generally satisfactory but with minor localised problems	TREND: Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?: No
OWNER TYPE:	Private, multiple owners	CONTACT: Imogen Sambrook 0121 625 6854

SITE NAME:	Evesham Abbey (remains of), Evesham	
DESIGNATION:	Scheduled Monument, 4 LBs, CA	LIST ENTRY NUMBER: 1005297
CONDITION:	Generally unsatisfactory with major localised problems	TREND: Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?: No
OWNER TYPE:	Local authority	CONTACT: Neil Rimmington 0121 625 6856

SITE NAME:	Settlement site north of Spring Hill, Fladbury	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: 1005352
CONDITION:	Unknown	TREND: Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?: No
OWNER TYPE:	Private, multiple owners	CONTACT: Imogen Sambrook 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Moated site 120 metres south east of Huntingdrop Farm, Hanbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017311
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Motte castle, moated site, and medieval agricultural remains at Crookbarrow Farm, Whittington		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1014900
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854

SITE NAME:	Double ditched enclosure north east of Wick village, Wick		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005310
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Imogen Sambrook 0121 625 6854



© Historic England

SITE NAME:	Westwood Park, Westwood / Hampton Lovett
DESIGNATION:	Registered Park and Garden grade II, 11 LBs
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	High
TREND:	Stable
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1000899

Gardens and pleasure grounds mostly late C19 and early C20. Vast majority of park in intensive cultivation, denuded of parkland trees. Some post-war development in vicinity of main house. Residential development and expansion of business park affect setting, particularly to north and east.

Contact: Kim Auston 0117 975 0696

WYRE FOREST



© Historic England

SITE NAME:	Baches Forge, Churchill Lane, Churchill, Churchill and Blakedown
DESIGNATION:	Scheduled Monument and Listed Buildings - 3 grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (D)
OWNER TYPE:	Private, multiple owners
LIST ENTRY NUMBER:	1005274 and 1348320; 1100650; 1100651

Early C19 hand forge building, comprising two brick structures which form part of a water powered spade and shovel mill. The machinery is still in working order and is looked after by owners and a small local trust. The buildings are now stable but an overall management plan addressing the condition of the monument and surviving plant is required.

Contact: Neil Rimmington 0121 625 6856

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	Ribbesford House, Ribbesford
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1329928

Mid C16 country house with late C17 and early C19 alterations. The building is largely unoccupied and has been neglected for many years with significant areas open to the elements. Urgent works are required in order to prevent further deterioration

Contact: Cristina Gardiner 0121 625 6850

© Historic England Archive

SITE NAME:	Gilgal, Stourport-on-Severn, East of Stourport Town Centre		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Medium	CONTACT:	Peter Bassett (LPA) 01562 732928

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site

This document is one in a series of publications produced as part of Historic England's national **Heritage at Risk** programme. More information about **Heritage at Risk** and other titles in the series can be found at HistoricEngland.org.uk/har

Heritage at Risk

Published October 2015

1 Waterhouse Square

138–142 Holborn

London EC1N 2ST

© Copyright Historic England 2015

Product code: 52016



Historic England

West Midlands Register 2015