

HERITAGE AT RISK

YORKSHIRE & THE HUMBER

CASTLE HOWARD MAUSOLEUM

Castle Howard Estate, Ryedale, North Yorkshire

The Mausoleum, by Hawksmoor, 1729-42, and modelled on the tomb of Metella, is a major feature of the Howardian Hills. Situated on a bluff east of Castle Howard. The columns were repaired with a grant in the 1980s. The entablature and bastions continue to decay. Much of the damage is due to rusting cramps. The staircase balustrade is collapsing.



HERITAGE AT RISK

YORKSHIRE & THE HUMBER

Of the 176 entries on the baseline 1999 Yorkshire and the Humber buildings at risk register, 91 (52%) have now been removed. Although this is 6% higher than the regional average for 2008, our rate of progress is slowing. Of the five entries removed this year, only one was on the 1999 register:

This is because the core of buildings remaining from the 1999 register are either scheduled monuments with no obvious use, or buildings with a problematic future that require a strategic re-think to provide a viable solution. Despite these problems, we are continuing to work with owners, local authorities, trusts and other funding bodies to try to secure the long-term future of these buildings and structures. Just over half (52%) of the regional grants budget (almost £500,000) was offered to eleven buildings at risk in the last financial year:

There are four new entries this year: in North Yorkshire, St Leonard's Church at Sand Hutton, and in West Yorkshire, Hopton Congregational Church in Mirfield, Westwood Mills at Linthwaite, and Stank Hall near Leeds. This gives a total of 122 Grade I and II* listed buildings and scheduled monuments at risk entries on the Yorkshire and the Humber register. In addition, four registered battlefields at risk are included on the regional register for the first time this year.


Grimsby Ice Factory, North East Lincolnshire, listed Grade II* and dating from 1900, is thought to be the earliest surviving ice factory in Britain, and the sole survivor from this period to retain its machinery. It is a typical example of a longstanding building at risk where yesterday's cutting edge technology has become today's dinosaur. Whilst a creative re-use could catalyse regeneration in the area, we are seriously concerned about the building's current poor condition and are in ongoing discussions about both the need for holding repairs and long term solutions based on the regeneration of the local area generally.



Royal Hall, Harrogate, North Yorkshire. This Grade II* building was designed as a kursaal (a concert hall with promenading space) by Frank Matcham in 1903, to support the very popular spa in Harrogate. Largely funded by the Local Authority and the Heritage Lottery Fund, very careful project management has enabled a repair scheme of the highest quality to be delivered despite a very tight budget of just over £10 million. Heroic fund raising by the Royal Hall Restoration Trust paid for the re-creation of the spectacular decorative scheme. This funding effort was led by the late Lillian Mina MBE who sadly died shortly after the Royal opening by HRH, the Prince of Wales. This project highlights how successful negotiation and co-operation between a number of groups can achieve stunning results. The Hall has now returned to use as a concert hall and conference facility.



BEFORE



AFTER

Maddy Jago, Planning and Development Regional Director, Yorkshire and the Humber

Contact: Susan Daniels, Business Manager, English Heritage, Yorkshire and the Humber Region, Tanner Row, York YO1 6WP
Telephone: 01904 601979 Fax: 01904 601999 E-mail: susan.daniels@english-heritage.org.uk

EAST RIDING OF YORKSHIRE (UA)



SITE NAME: **Gates, gate piers & railings to Norwood House, Norwood, Beverley**

PRIORITY: C (C)

DESIGNATION: Listed Grade I, CA

CONDITION: Poor

OCCUPANCY: Not applicable

OWNERSHIP: Local authority

2 pairs of stone gate piers, 2 pairs of gates and wrought iron railings of c1780. Enclosing the forecourt to Norwood House, which until 1996 was used by Beverley Girls' High School, but has since been vacant. The gates and railings are rusting and the stonework has been damaged.

Contact: Diane Green 01904 601973



SITE NAME: **Norwood House, Norwood, Beverley**

PRIORITY: C (C)

DESIGNATION: Listed Grade I, CA

CONDITION: Poor

OCCUPANCY: Vacant

OWNERSHIP: Local authority

Circa 1765-70, probably built for the attorney Jonathan Midgley, twice Mayor of Beverley. Used by Beverley Girls' High School until 1996 and vacant since. The fire damaged library has been repaired, but the remainder of the building is neglected.

Contact: Diane Green 01904 601973



SITE NAME: **Flamborough Castle, Tower Street, Flamborough**

PRIORITY: C (C)

DESIGNATION: Listed Grade II, SM, CA

CONDITION: Poor

OCCUPANCY: Not applicable

OWNERSHIP: Private

Mid C14 castle comprised of earthworks and upstanding remains within a pasture field in the centre of the village. The upstanding elements consist of an unconsolidated former undercroft which is made of decaying chalk blocks.

Contact: Keith Miller 01904 601990



SITE NAME: **Elmswell Old Hall, Elmswell Lane, Garton**

PRIORITY: A (B)

DESIGNATION: Listed Grade II*

CONDITION: Very bad

OCCUPANCY: Vacant

OWNERSHIP: Private

House, 1634 with later alterations. Once the home of Henry Best, important C17 agricultural diarist. Isolated and abandoned. Urgent works have been carried out but these have not arrested decay. The whole building is roofless. Spitalfields BPT has obtained all consents for full repair; but a stay has been placed on attempts to compulsorily purchase the building.

Contact: Giles Proctor 01904 601981



SITE NAME: **Gates, gatepiers, flanking walls and abutments, Londesborough**

PRIORITY: C (C)

DESIGNATION: Listed Grade I, CA, RPG Grade II*

CONDITION: Poor

OCCUPANCY: Not applicable

OWNERSHIP: Private

Gateway, 1660-70, probably by Robert Hooke, forming the principal entrance to Londesborough Park. The caps of the gatepiers are deteriorating and trees are growing from the joints. The ball finials have fallen.

Contact: Giles Proctor 01904 601981



SITE NAME: **Paul Holme Tower, Thorngumbald Road, Paull**

PRIORITY: A (A)

DESIGNATION: Listed Grade I, SM, CA

CONDITION: Very bad

OCCUPANCY: Vacant

OWNERSHIP: Private

Mid C15 3 storey brick tower house in a scheduled moated site, originally part of a larger manorial complex. A unique survival for this region. Restored and re-roofed in 1871; roofless since the early C20. The building has been surveyed.

Contact: Keith Miller 01904 601990



SITE NAME: Adlingfleet Medieval Rectory,
Church Lane,
Adlingfleet, Twin Rivers

PRIORITY: C (C)
DESIGNATION: Listed Grade II*, SM
CONDITION: Very bad
OCCUPANCY: Not applicable
OWNERSHIP: Private

Part of a C13 dwelling of the wealthy rector and King's councillor, John le Franceys. Re-used as farm buildings in the C18. A unique survival of a stone-built medieval dwelling in this area.

Contact: Keith Miller 01904 601990



SITE NAME: Outbuildings to Watton Abbey,
Church Lane,
Watton

PRIORITY: A (A)
DESIGNATION: Listed Grade II*, SM
CONDITION: Very bad
OCCUPANCY: Vacant
OWNERSHIP: Private

Gilbertine priory buildings, now outbuildings. C16 with later additions and alterations. The structure is derelict and mainly ruinous. Urgent repairs have been undertaken with the help of an English Heritage grant to stabilise the leaning gable.

Contact: Keith Miller 01904 601990



SITE NAME: Haltemprice Priory Farmhouse,
Abbey Lane,
Willerby

PRIORITY: A (A)
DESIGNATION: Listed Grade II*, SM
CONDITION: Very bad
OCCUPANCY: Vacant
OWNERSHIP: Private

Fragmentary remains of a farmhouse dating largely from the C17-C19, incorporating sections of re-used medieval and C16 fabric. In a very advanced state of decay.

Contact: Keith Miller 01904 601990



SITE NAME: Wressle Castle,
Brighton Road,
Wressle

PRIORITY: A (A)
DESIGNATION: Listed Grade I, SM
CONDITION: Poor
OCCUPANCY: Vacant
OWNERSHIP: Private

Very impressive and important surviving range of a major late C14 castle built for the Percy family and occupied by them during the period when they were at the height of their power as the leading family in Northern England. Repaired and consolidated as a roofless ruin in the C19; some repairs in 1970-80s.

Contact: Keith Miller 01904 601990

NORTH EAST LINCOLNSHIRE (UA)



SITE NAME: The Grimsby Ice Factory,
Gorton Street,
Grimsby

PRIORITY: A (A)
DESIGNATION: Listed Grade II*
CONDITION: Very bad
OCCUPANCY: Vacant
OWNERSHIP: Company

1900 ice works with extension factory of 1907-8 and later alterations. Closed in 1990. It is thought that this is the earliest surviving ice factory in Britain, and the sole survivor from this period to retain its machinery. Window damage. Roof is now deteriorating rapidly.

Contact: Diane Green 01904 601973



SITE NAME: Church of Saint Margaret,
Barton Street,
Hawerby cum Beesby

PRIORITY: D (D)
DESIGNATION: Listed Grade II*
CONDITION: Poor
OCCUPANCY: Vacant
OWNERSHIP: Private

Parish church. C12, C13 and C17, with mid C19 restorations. The arcade to the former south aisle survives. The church was made redundant in 1978. It is proposed to convert the church to an artist's studio. Some holding repairs are to be carried out to the north nave roof.

Contact: Giles Proctor 01904 601981

PRIORITY

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applies only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NORTH LINCOLNSHIRE (UA)



SITE NAME: **Hibaldstow Mill and walls to mill pond and wheel race, Ings Lane, Hibaldstow**

Combined wind and watermill, 1802, by James Middleton of Hibaldstow. Recent repair; but further work required to both exterior and interior.

PRIORITY: C (C)

Contact: Keith Miller 01904 601990

DESIGNATION: Listed Grade II*, SM

CONDITION: Fair

OCCUPANCY: Part occupied

OWNERSHIP: Private



SITE NAME: **Manor Farmhouse, East Halton Road, North Killingholme**

Medieval, C17-C19 manor house on a scheduled moated site. Exceptional multi-period survival for this region. The roof was repaired in 1980, but little has been done since and the interior is propped with scaffolding. It is proposed to carry out a feasibility study.

PRIORITY: A (A)

Contact: Giles Proctor 01904 601981

DESIGNATION: Listed Grade II*

CONDITION: Very bad

OCCUPANCY: Vacant

OWNERSHIP: Private

NORTH YORKSHIRE

CRAVEN



SITE NAME: **Dale End Mills, Dale End, Lothersdale**

C19 mill, including disused waterwheel (1861), pit and enclosing building. The mill-wheel is the largest in England and is in poor condition. The base of the stack is also in need of remedial work.

PRIORITY: C (C)

Contact: Keith Emerick 01904 601988

DESIGNATION: Listed Grade II, SM

CONDITION: Poor

OCCUPANCY: Part occupied

OWNERSHIP: Private

HAMBLETON



SITE NAME: **The Coach House, Rounton Grange, East Rounton**

Coach house, built in 1875. Now used as a combined home and workshop. One range is in a fair condition, the rest is in state of collapse.

PRIORITY: A (A)

Contact: Diane Green 01904 601973

DESIGNATION: Listed Grade II*

CONDITION: Very bad

OCCUPANCY: Part occupied

OWNERSHIP: Private



SITE NAME: **Landmoth Hall, Landmoth cum Catto**

Part of the east wing of a medieval manor house. Now in an unstable condition.

PRIORITY: B (B)

Contact: Keith Emerick 01904 601988

DESIGNATION: SM

CONDITION: Very bad

OCCUPANCY: Not applicable

OWNERSHIP: Private



SITE NAME: **West Lodge, Thornton Stud, Newsham Road, Newsham with Breckenbrough**

Late C18 lodge and entrance gateway. Deteriorating.

PRIORITY: C (C)

Contact: Diane Green 01904 601973

DESIGNATION: Listed Grade II*

CONDITION: Poor

OCCUPANCY: Vacant

OWNERSHIP: Private

Note:
If the priority category has altered since the 2007 Buildings at Risk register, the previous category is given in brackets.

ABBREVIATIONS

CA Conservation Area
RPG Registered Park & Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



SITE NAME:	Snape Castle, Snape with Thorp
PRIORITY:	B (B)
DESIGNATION:	Listed Grade I, SM, CA, RPG Grade II
CONDITION:	Very bad
OCCUPANCY:	Part occupied
OWNERSHIP:	Private

Castle dated to c1430, with additions and alterations in the C16 and C18. It is comprised of extensive ruins, including some vaulted rooms and two towers. The rear ranges are in a poor condition. The upper parts of the towers are particularly unstable. Much repointing is required elsewhere. The front ranges are divided into two dwellings.

Contact: Keith Emerick 01904 601988



SITE NAME:	Remains of walls to Upsall Castle, Upsall Road, Upsall
PRIORITY:	C (C)
DESIGNATION:	Listed Grade II, SM
CONDITION:	Poor
OCCUPANCY:	Not applicable
OWNERSHIP:	Private

Remains of walls to medieval castle; now incorporated into garden layout. Walls have many open joints.

Contact: Keith Emerick 01904 601988



SITE NAME:	Stables at Harlsey Castle Farmhouse, West Harlsey
PRIORITY:	D (D)
DESIGNATION:	Listed Grade II*, SM
CONDITION:	Poor
OCCUPANCY:	Occupied
OWNERSHIP:	Private

Remains of medieval castle keep; in use as farm buildings.

Contact: Keith Emerick 01904 601988

HARROGATE



SITE NAME:	Chapel of St Mary attached to the mansion, Allerton Park, Allerton Mauleverer with Hopperton
PRIORITY:	C (C)
DESIGNATION:	Listed Grade II*, RPG Grade II
CONDITION:	Poor
OCCUPANCY:	Vacant
OWNERSHIP:	Trust

Roman Catholic chapel, c1807, attached to the grade I house. The house stands on a promontory in the eastern section of the C18 park, with mid C19 terraces to the north. Much of the interior of the chapel has been stripped out for dry rot treatment. The landscape is in divided ownership. The Hall was severely damaged by fire in Jan 2005 and is undergoing repairs. EH has funded an up-to-date condition survey.

Contact: Hilary Roome 01904 601984



SITE NAME:	Providence Smelt Mill, 500metres south of Minakin Row, Bewerley
PRIORITY:	B (B)
DESIGNATION:	SM
CONDITION:	Very bad
OCCUPANCY:	Not applicable
OWNERSHIP:	Private

Ruined remains of an ore hearth smelt mill built in the 1780s. The flue arch immediately north of the smelt mill building is in danger of imminent collapse. Consolidation is also required for the rest of the complex. Grant has been offered in conjunction with Nidderdale AONB and Harrogate BC.

Contact: Keith Emerick 01904 601988



SITE NAME:	Syningthwaite Priory Farmhouse, Rudgate, Bilton in Ainsty with Bickerton
PRIORITY:	F (D)
DESIGNATION:	Listed Grade I
CONDITION:	Poor
OCCUPANCY:	Vacant
OWNERSHIP:	Private

Farmhouse consists of a front range of c1820 and a rear wing of C12 date with C15-C16 and C19 alterations. The walls and floors are decaying, although the roof was repaired in 1995. A full historical and archaeological survey has been completed by EH. Below ground archaeological investigations are being undertaken. Consent has been granted for conversion to a dwelling and work will start by mid 2008.

Contact: Giles Proctor 01904 601981

PRIORITY

A
Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

B
Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C
Slow decay; no solution agreed.

D
Slow decay; solution agreed but not yet implemented.

E
Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applies only to buildings capable of beneficial use).

F
Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.



SITE NAME: Coach house & bee hives approx 10 metres to north of Nutwith Cote, Grewelthorpe Road, Burton on Yore

PRIORITY: A (A)
DESIGNATION: Listed Grade II*
CONDITION: Poor
OCCUPANCY: Part occupied
OWNERSHIP: Private

Coach house with bee hives. Mid C18 and C16. The rear hall of the coach house is settling and the end return of the bee hives is failing. There are structural cracks to the right hand return and rear, and some of the copings are missing from the rear gable. Pointing is failing to cut stone on facades leaving some stone loose.

Contact: Diane Green 01904 601973



SITE NAME: Outbuilding approx 20 metres to north of Nutwith Cote, Grewelthorpe Road, Burton on Yore

PRIORITY: C (C)
DESIGNATION: Listed Grade II*
CONDITION: Fair
OCCUPANCY: Vacant
OWNERSHIP: Private

Early C18 outbuilding/store. The building has been vacant for some time. Emergency re-roofing in corrugated asbestos was carried out many years ago. Building is slowly decaying, with open joints and defective rainwater goods. The corrugated asbestos roof appears to be failing at the ridge and at one of the gables.

Contact: Diane Green 01904 601973



SITE NAME: Temple of Victory with railed enclosure, Allerton Park, Flaxby

PRIORITY: E (E)
DESIGNATION: Listed Grade II*, RPG Grade II
CONDITION: Fair
OCCUPANCY: Vacant
OWNERSHIP: Trust

Summerhouse or view point, 1790, situated on a knoll in the park, to the north-west of the house. Re-roofed in lead, cornice repaired & building made secure over 10 years ago with grant aid from English Heritage and Harrogate Borough Council. Repairs still needed to stonework below cornice level and to the steps & railings and interior. Extensive views from the Temple over the park and surrounding landscape.

Contact: Hilary Roome 01904 601984



SITE NAME: Church of St Mary, Harlow Terrace, Harrogate

PRIORITY: C (C)
DESIGNATION: Listed Grade II*, CA
CONDITION: Poor
OCCUPANCY: Vacant
OWNERSHIP: Religious organisation

Church c1916 by Sir Walter Tapper. Deterioration of the stone has occurred from an early date. There is evidence that the mineral felt to the aisle roofs is leaking. Grant was offered by English Heritage but the Parish declined. The church has now been declared redundant so the Diocese has responsibility for its care and disposal. A new owner is being actively sought.

Contact: Hilary Roome 01904 601984



SITE NAME: The Old Hall, Middleton Quernhow

PRIORITY: C (C)
DESIGNATION: Listed Grade II, SM
CONDITION: Poor
OCCUPANCY: Not applicable
OWNERSHIP: Private

Gable wall and part of the south wall of an early C17 house. Many open joints are visible and part of chimney stack appears to be unstable.

Contact: Neil Redfern 01904 601897



SITE NAME: Orangery with flanking walls, bothies and pavilion (Ripley Castle), Ripley

PRIORITY: C (C)
DESIGNATION: Listed Grade II*, CA, RPG Grade II
CONDITION: Poor
OCCUPANCY: Part occupied
OWNERSHIP: Private

Classical Orangery in walled garden with flanking pavilions, c1785 by William Belwood. One surviving glasshouse c1840, now repaired. Bothies, in poor condition, to rear: East Pavilion recently repaired and some emergency repairs to Orangery. The balustrade has been dismantled and the cornice has been temporarily supported to prevent collapse.

Contact: Hilary Roome 01904 601984

Note:
 If the priority category has altered since the 2007 Buildings at Risk register, the previous category is given in brackets.

ABBREVIATIONS
 CA Conservation Area
 RPG Registered Park & Garden
 SM Scheduled Monument
 UA Unitary Authority
 WHS World Heritage Site



SITE NAME: **Butterton Bridge,
Sawley**

Medieval bridge, now crossed by a public footpath. The structure is overgrown and decaying and there is danger of structural collapse. English Heritage grant offered but not accepted by owner.

PRIORITY: D (D)

DESIGNATION: SM

CONDITION: Poor

OCCUPANCY: Not applicable

OWNERSHIP: Private

Contact: Neil Redfern 01904 601897



SITE NAME: **Dob Park Lodge,
Dob Park Lane,
Weston**

Ruins of a C17 park lodge, now roofless structure three stories high. Scheduled as an Ancient Monument in 1997.

PRIORITY: C (C)

DESIGNATION: Listed Grade II, SM

CONDITION: Very bad

OCCUPANCY: Not applicable

OWNERSHIP: Private

Contact: Keith Emerick 01904 601988

NORTH YORK MOORS



SITE NAME: **Ruins of Whorlton Castle Undercroft,
Castle Bank,
Whorlton, Hambleton**

C14 castle. Parts of two vaulted chambers remain. Conservation plan complete.

PRIORITY: D (D)

DESIGNATION: Listed Grade II*, SM, CA

CONDITION: Poor

OCCUPANCY: Not applicable

OWNERSHIP: Private

Contact: Keith Emerick 01904 601988



SITE NAME: **Whorlton Castle Gatehouse,
Castle Bank,
Whorlton, Hambleton**

Shell remains of a late C14 gatehouse, which was altered in the C16. Conservation plan complete.

PRIORITY: D (D)

DESIGNATION: Listed Grade I, SM, CA

CONDITION: Poor

OCCUPANCY: Not applicable

OWNERSHIP: Private

Contact: Keith Emerick 01904 601988



SITE NAME: **Ionic Temple,
Duncombe Park Estate,
Helmsley, Ryedale**

Decorative temple, c1730, attributed to Vanbrugh, situated at the north end of the c800m long, grass East Terrace, c120m east of the house. The column shafts are badly decayed. The trial repair of one column is complete, but an overall repair strategy has not yet been agreed.

PRIORITY: C (C)

DESIGNATION: Listed Grade I, RPG Grade I

CONDITION: Poor

OCCUPANCY: Not applicable

OWNERSHIP: Private

Contact: Hilary Roome 01904 601984



SITE NAME: **Duck Bridge,
Eastern Lane East End,
Danby, Scarborough**

Packhorse bridge over the River Esk, rebuilt in 1717. Vulnerable to damage by traffic and floods. Although by-passed by a modern ford, sometimes used by motor vehicles when river is in flood. Scheduled monument consent granted for some recent repairs to the bridge abutments, parapet wall and rail. Limited further repairs needed to complete consolidation.

PRIORITY: F (F)

DESIGNATION: Listed Grade II*, SM

CONDITION: Fair

OCCUPANCY: Not applicable

OWNERSHIP: Local authority

Contact: Keith Emerick 01904 601988

PRIORITY

A
Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

B
Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C
Slow decay; no solution agreed.

D
Slow decay; solution agreed but not yet implemented.

E
Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applies only to buildings capable of beneficial use).

F
Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.



SITE NAME: Ayton Castle,
Castle Rise,
West Ayton, Scarborough

PRIORITY: F (F)

DESIGNATION: Listed Grade I, SM

CONDITION: Poor

OCCUPANCY: Not applicable

OWNERSHIP: Local authority

Pele tower, late C14. The upper storeys are ruinous, but the undercroft still has a vaulted roof. Subject to weathering. The site has been the subject of a detailed condition survey. Conservation plan consultation draft circulated.

Contact: Keith Emerick 01904 601988

RICHMONDshire



SITE NAME: Courthouse to east of Colburn Hall,
Colburn Hall,
Colburn

PRIORITY: D (D)

DESIGNATION: Listed Grade I

CONDITION: Fair

OCCUPANCY: Part occupied

OWNERSHIP: Private

A medieval courthouse built c1300, of rubble stone with sandstone dressings under a pantile roof. Now empty, although latterly used as a barn. The roof covering is in poor condition and work is required to the stonework. The owner is considering options for repair funding.

Contact: Hilary Roome 01904 601984



SITE NAME: The Old Gatehouse,
Jervaux Park,
East Witton Out Parish

PRIORITY: A (A)

DESIGNATION: Listed Grade I, SM

CONDITION: Very bad

OCCUPANCY: Part occupied

OWNERSHIP: Private

The house and gardens known as the Old Gatehouse is probably re-used medieval masonry (probably in the C19) on medieval foundations. Part of the building is occupied but the western end is ruinous and in need of repair.

Contact: Keith Emerick 01904 601988



SITE NAME: Ravensworth Castle and park wall,
The Green,
Ravensworth

PRIORITY: A (A)

DESIGNATION: Listed Grade I, SM, CA

CONDITION: Poor

OCCUPANCY: Not applicable

OWNERSHIP: Private

Late C14, small roofless keep/gate tower and ruins of ancillary buildings together with impressive water defences later adapted to form water gardens. Much repointing and consolidation needed to all parts of the building. Significant parts of the standing remains, including the gate tower are now at risk. A detailed recording of the standing fabric has been completed.

Contact: Keith Emerick 01904 601988



SITE NAME: Cobscar Lead smelt mill,
Redmire

PRIORITY: C (C)

DESIGNATION: SM


CONDITION: Poor

OCCUPANCY: Not applicable

OWNERSHIP: Private

The monument includes the standing, earthwork and buried remains of an ore hearth lead smeltmill, fuel store, and associated buildings, with the remains of a flue system leading to an intact chimney.

Contact: Keith Emerick 01904 601988



SITE NAME: Old Grandstand,
Richmond

PRIORITY: C (C)

DESIGNATION: Listed Grade II*, CA

CONDITION: Poor

OCCUPANCY: Not applicable

OWNERSHIP: Local authority

A rare example of an C18 racecourse grandstand. The racecourse was closed in the late C19 and the Grandstand became derelict. It was partially demolished c1960. Ruins cleared and stonework sorted c1995. A conservation plan for the building has been completed with the support of English Heritage. The Racecourse is now a conservation area.

Contact: Hilary Roome 01904 601984

Note:
If the priority category has altered since the 2007 Buildings at Risk register, the previous category is given in brackets.

ABBREVIATIONS

CA Conservation Area
RPG Registered Park & Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



SITE NAME: **St Martins Priory Ruins,
A6136,
St Martins**

PRIORITY: A (A)
DESIGNATION: Listed Grade I, SM, CA
CONDITION: Poor
OCCUPANCY: Not applicable
OWNERSHIP: Private

The ruins of a small medieval monastic house, of C12 (possibly earlier) and C15. Part of a church, small gate tower and the ruined walls of other buildings also remain. Extensive consolidation and repointing work is required.

Contact: Neil Redfern 01904 601897



SITE NAME: **Keld Heads lead smelting
and mine complex,
Preston-under-Scar, Wensley**

PRIORITY: C (C)
DESIGNATION: SM
CONDITION: Poor
OCCUPANCY: Not applicable
OWNERSHIP: Private

The mine complex displays a wide range of features associated with lead exploitation and processing. The site has been mined since the C12 but the present complex dates from C18 & C19. Scrub clearance was undertaken by NYCC volunteers in 2005 to assist with the preparation of survey documents.

Contact: Keith Emerick 01904 601988

RYEDALE



SITE NAME: **Lime Kilns,
A170,
Allerston**

PRIORITY: C (C)
DESIGNATION: Listed Grade II, SM, CA
CONDITION: Very bad
OCCUPANCY: Not applicable
OWNERSHIP: Private

Bank of four lime kilns c1800. For Sir George Osbaldeston. Situated in woodland. These are in a poor state of repair, due to encroaching tree growth. Some parts are starting to collapse.

Contact: Keith Emerick 01904 601988



SITE NAME: **Yedingham Priory,
Eberston and Yedingham**

PRIORITY: C (C)
DESIGNATION: Listed Grade II*, SM
CONDITION: Poor
OCCUPANCY: Part occupied
OWNERSHIP: Private

Priory, C12-C13. Little standing structure survives except for part of the precinct wall and part of the refectory, which has been incorporated into a cottage and barn. The masonry is cracking and bulging in places.

Contact: Keith Emerick 01904 601988



SITE NAME: **Wall of cascade approximately
100 metres north of Eberston Hall,
A170, Eberston and Yedingham**

PRIORITY: C (C)
DESIGNATION: Listed Grade II*, RPG Grade II*
CONDITION: Poor
OCCUPANCY: Not applicable
OWNERSHIP: Private

Stepped cascade within a water garden of c1718, situated in the narrow valley of Kirk Dale c50m to the north of the Hall by Colen Campbell. Forms the lowest cascade of the two in the water garden. Recently cleared of vegetation but the stonework is in need of repair.

Contact: Hilary Roome 01904 601984



SITE NAME: **Wall of cascade approximately
50 metres north of Eberston Hall,
A170, Eberston and Yedingham**

PRIORITY: C (C)
DESIGNATION: Listed Grade II*, RPG Grade II*
CONDITION: Poor
OCCUPANCY: Not applicable
OWNERSHIP: Private

Stepped cascade within a water garden of c1718, situated in the narrow valley of Kirk Dale c50m to the north of the Hall by Colen Campbell. Forms the upper cascade of the two in the water garden. In need of consolidation and restoration.

Contact: Hilary Roome 01904 601984

PRIORITY

A
Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

B
Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C
Slow decay; no solution agreed.

D
Slow decay; solution agreed but not yet implemented.

E
Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applies only to buildings capable of beneficial use).

F
Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.



SITE NAME: **The Stray,
Castle Howard,
Henderskelfe**

PRIORITY: A (A)

DESIGNATION: Listed Grade I, RPG Grade I

CONDITION: Very bad

OCCUPANCY: Not applicable

OWNERSHIP: Private

Castellated walls, 4m high, with square & round interval towers stretching for one mile to either side of the main drive, immediately S of the pyramid gate. Built to the designs of Sir John Vanbrugh c1723. All needs to be consolidated & sections rebuilt, one tower has recently collapsed. Two phases of repair are now complete but further extensive repair is required for which grant was offered but not taken up.

Contact: Hilary Roome 01904 601984



SITE NAME: **The Mausoleum and bastion wall
with gates and railings, Kirk Hill,
Castle Howard Estate, Henderskelfe**

PRIORITY: C (C)

DESIGNATION: Listed Grade I, RPG Grade I

CONDITION: Poor

OCCUPANCY: Not applicable

OWNERSHIP: Private

Mausoleum by Hawksmoor; 1729-42, modelled on the tomb of Metella. Situated on a bluff c1.2km E of the mansion and visible from the Temple Terrace and the Temple of the Four Winds (1724-28 by Vanbrugh), both SE of the mansion. The columns were repaired with a grant in the 1980s. The entablature and bastions continue to decay. Much of the damage is due to rusting cramps. The staircase balustrade is collapsing.

Contact: Hilary Roome 01904 601984



SITE NAME: **The Pyramid, St Annes Hill,
Castle Howard Estate,
Henderskelfe**

PRIORITY: C (C)

DESIGNATION: Listed Grade I, RPG Grade I

CONDITION: Poor

OCCUPANCY: Not applicable

OWNERSHIP: Private

Commemorative monument of 1728 by Hawksmoor; situated on a knoll and dominating views to the south from the Broad Walk and South Parterre. Decaying stone pyramid suffering from cramp damage. Five of the eight piers at the corners have been repaired with the support of grant. Set in late C17/early C18 park, one of the most historically significant landscapes in the country.

Contact: Hilary Roome 01904 601984



SITE NAME: **Walls to walled garden
with gates and corner piers,
Castle Howard Estate, Henderskelfe**

PRIORITY: C (C)

DESIGNATION: Listed Grade I, RPG Grade I

CONDITION: Very bad

OCCUPANCY: Not applicable

OWNERSHIP: Private

Walls to the walled garden, early C18 by Sir John Vanburgh. The brick walls are in fair condition but the limestone piers are decaying and destabilising, partly collapsed due to lack of maintenance and repair.

Contact: Hilary Roome 01904 601984



SITE NAME: **Screen wall,
north west of Malton Lodge,
Old Maltongate, Malton**

PRIORITY: A (A)

DESIGNATION: Listed Grade II*, CA

CONDITION: Very bad

OCCUPANCY: Not applicable

OWNERSHIP: Private

Courtyard wall c1604 of 'An extraordinary relic of a great Prodigy house of considerable national importance' (list description). Very heavily decayed and potentially unstable.

Contact: Alison Fisher 01904 601975



SITE NAME: **St Leonard's Church and cross base
adjacent to St Mary's Church,
Sand Hutton**

PRIORITY: D (New entry)

DESIGNATION: Listed Grade II, SM

CONDITION: Very bad

OCCUPANCY: Not applicable

OWNERSHIP: Religious organisation

Ruined chapel to rear of existing church. Standing and buried remains of a C12 church and base of associated medieval cross.

Contact: Keith Emerick 01904 601988

Note:
If the priority category has altered since the 2007 Buildings at Risk register, the previous category is given in brackets.

ABBREVIATIONS

CA Conservation Area
RPG Registered Park & Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



SITE NAME:	Sheriff Hutton Castle, Main Street, Sheriff Hutton
PRIORITY:	A (A)
DESIGNATION:	Listed Grade II*, SM, CA
CONDITION:	Poor
OCCUPANCY:	Not applicable
OWNERSHIP:	Private

Ruinous castle begun in 1382 by John, Lord Neville, with C15 gatehouse inserted. Vulnerable to weathering. A condition survey was funded by English Heritage and Phase I repairs, also funded by English Heritage are complete. Phase II repairs on hold.

Contact: Keith Emerick 01904 601988



SITE NAME:	Slingsby Castle, Slingsby
PRIORITY:	C (C)
DESIGNATION:	Listed Grade II, SM
CONDITION:	Very bad
OCCUPANCY:	Not applicable
OWNERSHIP:	Private

C16 Great House built on the site of a medieval castle. Ruinous but surviving up to the eaves in height. In need of urgent consolidation; site is deteriorating as a result of natural erosion and some vandalism.

Contact: Keith Emerick 01904 601988

SCARBOROUGH



SITE NAME:	The Brewhouse, Whitby Abbey, Whitby
PRIORITY:	D (D)
DESIGNATION:	SM, CA
CONDITION:	Very bad
OCCUPANCY:	Not applicable
OWNERSHIP:	Private

Ruins of C17 brewhouse to the west of Abbey House. Converted to a water tank in C19. Unroofed, early C20, and in a derelict condition.

Contact: Keith Emerick 01904 601988



SITE NAME:	Wykeham Priory, Back Lane, Wykeham
PRIORITY:	D (D)
DESIGNATION:	Listed Grade II, SM
CONDITION:	Poor
OCCUPANCY:	Not applicable
OWNERSHIP:	Private

C12 Cistercian priory. Little remains of the priory except some sections of walling, part of the old parish church and a transplanted moorland cross. It is situated in the private grounds of a large country house.

Contact: Keith Emerick 01904 601988

SELBY



SITE NAME:	The Gatehouse, Gatehouse Lane, Bolton Percy
PRIORITY:	D (C)
DESIGNATION:	Listed Grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant
OWNERSHIP:	Trust

C15 timber-framed gatehouse to the medieval Rectory at Bolton Percy. The surviving portion has a jettied upper floor supported on carved braces. The roof structure is carved and moulded. Partly repaired in 1972, but the unrepaired southern end has collapsed.

Contact: Hilary Roome 01904 601984



SITE NAME:	Chapel to Huddleston Hall (now barn), west of house, Laith Staid Lane, Huddleston with Newthorpe
PRIORITY:	C (C)
DESIGNATION:	Listed Grade II*
CONDITION:	Fair
OCCUPANCY:	Part occupied
OWNERSHIP:	Private

Chapel with C15 origins, C16 rebuilding to the east and later alterations.

Contact: Diane Green 01904 601973

PRIORITY

A
Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

B
Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C
Slow decay; no solution agreed.

D
Slow decay; solution agreed but not yet implemented.

E
Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applies only to buildings capable of beneficial use).

F
Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.



SITE NAME: **Huddleston Hall,
Laith Staid Lane,
Huddleston with Newthorpe**

Late C16 manor house, now used as a farmhouse. A full repairs programme has been prepared but work has not yet been carried out.

PRIORITY: C (C)
DESIGNATION: Listed Grade II*
CONDITION: Fair
OCCUPANCY: Part occupied
OWNERSHIP: Private

Contact: Diane Green 01904 601973



SITE NAME: **Stables to Huddleston Hall,
south east of house, Laith Staid Lane,
Huddleston with Newthorpe**

Stables of the late C16 with C19 additions and alterations.

PRIORITY: C (C)
DESIGNATION: Listed Grade II*
CONDITION: Fair
OCCUPANCY: Part occupied
OWNERSHIP: Private

Contact: Diane Green 01904 601973



SITE NAME: **Abbot's Staith Buildings,
Water Lane,
Selby**

C15 or early C16, two storey, 'H' shaped plan warehouse built for Selby Abbey. Mainly of magnesium limestone ashlar with some brick. The roof is modern, the building is in poor condition and the roof is deteriorating.

PRIORITY: C (C)
DESIGNATION: Listed Grade II*, SM, CA
CONDITION: Poor
OCCUPANCY: Part occupied
OWNERSHIP: Company

Contact: Keith Emerick 01904 601988

YORKSHIRE DALES



SITE NAME: **Barden Church,
B6160, Barden,
Craven**

C16 chapel. The interior is derelict but the chapel has been re-roofed. Although the church building itself is not scheduled, the ground beneath it and much of the surrounding manorial complex, is.

PRIORITY: C (C)
DESIGNATION: Listed Grade I
CONDITION: Fair
OCCUPANCY: Vacant
OWNERSHIP: Private

Contact: Diane Green 01904 601973



SITE NAME: **Lead cupola,
flue and chimney,
Grassington, Craven**

Smelt mills, flues and chimney of a lead processing complex. Built in 1792. Some consolidation has been undertaken but the flue system is still in urgent need of repair.

PRIORITY: C (C)
DESIGNATION: SM
CONDITION: Poor
OCCUPANCY: Not applicable
OWNERSHIP: Private

Contact: Keith Emerick 01904 601988



SITE NAME: **Lodge Hall,
Ingman Lodge Road, Selside,
Horton in Ribblesdale, Craven**

Farmhouse dated 1687. Structural cracks to main (east) front and bulge on north side. Roof reported to leak badly with attendant decay. Integral part of a working farm.

PRIORITY: C (C)
DESIGNATION: Listed Grade II*
CONDITION: Poor
OCCUPANCY: Occupied
OWNERSHIP: Private

Contact: Diane Green 01904 601973

Note:
If the priority category has altered since the 2007 Buildings at Risk register, the previous category is given in brackets.

ABBREVIATIONS
CA Conservation Area
RPG Registered Park & Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



SITE NAME: **Nappa Hall,
Askrigg,
Richmondshire**

PRIORITY: C (D)

DESIGNATION: Listed Grade I

CONDITION: Poor

OCCUPANCY: Part occupied

OWNERSHIP: Private

A fortified Manor House built in 1459 for James Metcalf. A wing was added in C17. Most of the medieval portion has not been occupied for some years. English Heritage grant has been offered for emergency repairs.

Contact: Hilary Roome 01904 601984



SITE NAME: **Coverham Abbey Ruins, Coverham Abbey,
Coverham with Agglethorpe,
Richmondshire**

PRIORITY: C (C)

DESIGNATION: Listed Grade I, SM

CONDITION: Fair

OCCUPANCY: Not applicable

OWNERSHIP: Private

The remains of a C13 Premonstratensian abbey, which was converted into a house after the dissolution of the monasteries.

Contact: Neil Redfern 01904 601897



SITE NAME: **Sargill Ore Hearth Lead Smelt Mill,
High Abbotside,
Richmondshire**

PRIORITY: C (C)

DESIGNATION: SM

CONDITION: Poor

OCCUPANCY: Not applicable

OWNERSHIP: Private

Standing remains of the Sargill ore hearth, lead smelt mill and associated structures built in the 1840s. Rectangular smelt mill building, flue and part of chimney.

Contact: Keith Emerick 01904 601988

SOUTH YORKSHIRE

BARNSELY



SITE NAME: **Grimethorpe Hall,
Brierley Road,
Brierley**

PRIORITY: C (D)

DESIGNATION: Listed Grade II*

CONDITION: Poor

OCCUPANCY: Vacant

OWNERSHIP: Company

House, c1670, altered in C18, C19 and C20, which requires extensive repairs. Although standing in an amply sized site, the surrounding area is a densely populated residential area. The setting has been further eroded by recent construction of housing to the west. Consent was granted for conversion to a restaurant in 2005, but work has not commenced. The roof coverings are deteriorating.

Contact: Giles Proctor 01904 601981



SITE NAME: **Conservatory and linking bridge
at north west corner of
Wentworth Castle, Stainborough**

PRIORITY: D (D)

DESIGNATION: Listed Grade II*, CA, RPG Grade I

CONDITION: Very bad

OCCUPANCY: Vacant

OWNERSHIP: Trust

Conservatory and bridge, built in 1877, probably by Crompton and Fawkes, located immediately west of the house and linked to it by a glazed bridge. The conservatory is situated in the early C18 formal gardens on the west side of the house. A support scaffold has been erected to prevent collapse. English Heritage grant has been offered towards a condition survey and conservation plan.

Contact: Giles Proctor 01904 601981



SITE NAME: **Gun Room,
Wentworth Castle,
Stainborough**

PRIORITY: F (F)

DESIGNATION: Listed Grade II*, CA, RPG Grade I

CONDITION: Fair

OCCUPANCY: Vacant

OWNERSHIP: Trust

Probably built as a banqueting house or a bath-house, it was used as a gun room in the C19. The interior has exceptionally fine plasterwork. Repairs to the walls and roof were carried out in 2006-07, but a further phase of conservation is required to the interior.

Contact: Giles Proctor 01904 601981

PRIORITY

A
Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

B
Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C
Slow decay; no solution agreed.

D
Slow decay; solution agreed but not yet implemented.

E
Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applies only to buildings capable of beneficial use).

F
Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.



SITE NAME:	Rotunda Temple, Wentworth Castle, Stainborough
PRIORITY:	F (F)
DESIGNATION:	Listed Grade II*, CA, RPG Grade I
CONDITION:	Good
OCCUPANCY:	Not applicable
OWNERSHIP:	Trust

Garden temple, 1746, modelled on temple of Vesta at Tivoli, Rome. Situated on south-east side of the park on the edge of Ivas Wood, approx 800m south-east of the house and in a remote part of the estate. The stonework was repaired in 2006-07 and EH grant has been offered towards the reconstruction of the steps. A further phase of work is required in order to reinstate the roof.

Contact: Giles Proctor 01904 601981



SITE NAME:	Dovecote at Glebe Farm, Tankersley
PRIORITY:	D (D)
DESIGNATION:	Listed Grade II, SM
CONDITION:	Very bad
OCCUPANCY:	Part occupied
OWNERSHIP:	Private

Stone built dovecote and cart shed, built in 1735 as part of the Glebe Farm for Richard Goodwin, Rector 1715-52. A particularly good example, complete with full interior and a rare set of spiked protective grilles over the dove holes.

Contact: Keith Miller 01904 601990



SITE NAME:	Low Forge, Wortley
PRIORITY:	C (C)
DESIGNATION:	SM
CONDITION:	Poor
OCCUPANCY:	Not applicable
OWNERSHIP:	Private

Roofless remains of an early C18 water-powered iron forge, including waterwheel and tilt-hammer, associated wheelraces, forge and bloomery building; in need of repair.

Contact: Keith Miller 01904 601990

DONCASTER



SITE NAME:	Stable to Hickleton Hall including the Stable Cottage and attached walls and gate piers, Hickleton Hall, Hickleton
PRIORITY:	A (A)
DESIGNATION:	Listed Grade II*, CA, RPG Grade II
CONDITION:	Very bad
OCCUPANCY:	Vacant
OWNERSHIP:	Charity

Mid C18 stable block, now store and house with attached walls and gatepiers. Possibly by James Paine, who designed Hickleton Hall, 1745-48, for Godfrey Wentworth. The stable block stands to the north of the Hall, which occupies an elevated position towards the north end of the registered site. The building continues to deteriorate.

Contact: Giles Proctor 01904 601981

ROTHERHAM



SITE NAME:	St Mary's Rectory, High Street, Rawmarsh
PRIORITY:	F (B)
DESIGNATION:	Listed Grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant
OWNERSHIP:	Company

1752, possibly by James Paine. The Rectory has been vacant since 1977 but work on conversion to flats is now underway and should be complete during 2008.

Contact: Giles Proctor 01904 601981



SITE NAME:	25 and 27 High Street, Rotherham
PRIORITY:	E (E)
DESIGNATION:	Listed Grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Vacant
OWNERSHIP:	Company

Late medieval house. Signs of structural decay, faulty rainwater goods.

Contact: Trevor Mitchell 01904 601972

Note:
If the priority category has altered since the 2007 Buildings at Risk register, the previous category is given in brackets.

ABBREVIATIONS
CA Conservation Area
RPG Registered Park & Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



SITE NAME: **Keppels Column, Admirals Crest, Thorpe Common, Rotherham**

PRIORITY: C (C)
 DESIGNATION: Listed Grade II*
 CONDITION: Very bad
 OCCUPANCY: Not applicable
 OWNERSHIP: Local authority

Monumental column built 1773-80. Now on the edge of Wentworth Woodhouse Estate. The building is closed to the public, although emergency repairs have been carried out to the viewing platform and stairwell. There are significant structural cracks and stonework erosion. Evidence is apparent of recent structural movement.

Contact: Giles Proctor 01904 601981



SITE NAME: **Thorpe Salvin Old Hall (Ruins of), Ladyfield Road, Thorpe Salvin**

PRIORITY: D (C)
 DESIGNATION: Listed Grade II*, SM, CA
 CONDITION: Poor
 OCCUPANCY: Not applicable
 OWNERSHIP: Private

Gatehouse and imposing 3 storey south facade of mid C16 stone-built mansion built by Henry Sanford (died 1582) standing in an open courtyard. Grant has been offered for a condition survey.

Contact: Keith Miller 01904 601990



SITE NAME: **Stable Block and Riding School, Wentworth Woodhouse, Wentworth**

PRIORITY: E (E)
 DESIGNATION: Listed Grade I, RPG Grade II*
 CONDITION: Fair
 OCCUPANCY: Vacant
 OWNERSHIP: Private

Stable block and riding school, 1760s, situated approx 300m north-west of the house. Vacant and vulnerable to under-maintenance and vandalism.

Contact: Trevor Mitchell 01904 601972

SHEFFIELD



SITE NAME: **Loxley United Reformed Church, Loxley Road, Bradfield**

PRIORITY: C (C)
 DESIGNATION: Listed Grade II*
 CONDITION: Fair
 OCCUPANCY: Vacant
 OWNERSHIP: Private

Church, 1787. Closed in 1994. No use identified. Some routine maintenance has been carried out.

Contact: Giles Proctor 01904 601981



SITE NAME: **Manor Lodge (Turret House and ruins at), Sheffield**

PRIORITY: D (C)
 DESIGNATION: Listed Grade II*, SM
 CONDITION: Fair
 OCCUPANCY: Vacant
 OWNERSHIP: Trust

Former gatehouse c1574, restored 1873 and late C20. Ruins of C16 and later mansion of George Talbot, Earl of Shrewsbury, where Mary Queen of Scots was imprisoned for brief periods between 1570 and 1584. Formerly open to the public, now mostly unused, but secure and weather-proof. A major grant has been offered for repair and reinterpretation by the Heritage Lottery Fund and work should start in 2008.

Contact: Keith Miller 01904 601990



SITE NAME: **Leah's Yard, 20-22 Cambridge Street, Sheffield**

PRIORITY: C (C)
 DESIGNATION: Listed Grade II*, CA
 CONDITION: Poor
 OCCUPANCY: Vacant
 OWNERSHIP: Company

Mid C19 cutlery/ silversmithing works, with late C19 alterations. General decay, some fire damage. Use for shops and food/drink agreed and included in "New Retail Quarter" proposals. Some patch repairs to the roof have been carried out.

Contact: Trevor Mitchell 01904 601972

PRIORITY

A
 Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

B
 Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C
 Slow decay; no solution agreed.

D
 Slow decay; solution agreed but not yet implemented.

E
 Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applies only to buildings capable of beneficial use).

F
 Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.



SITE NAME: **Nonconformist Chapel,
General Cemetery,
Cemetery Road, Sheffield**

PRIORITY: C (C)

DESIGNATION: Listed Grade II*, CA

CONDITION: Poor

OCCUPANCY: Vacant

OWNERSHIP: Trust

Cemetery chapel built in c1836. The roof has been repaired with grant from EH, but the interior is derelict. Some lead has been stolen from the roof and has yet to be reinstated.

Contact: Giles Proctor 01904 601981



SITE NAME: **Crucible Steel Shop in south corner
of former Sanderson Kayzers Darnall
Works, Darnall Road, Sheffield**

PRIORITY: C (D)

DESIGNATION: Listed Grade II*, SM

CONDITION: Very bad

OCCUPANCY: Vacant

OWNERSHIP: Company

Crucible steel works, 1872, now disused. Of international significance as a unique survival of its type. This large two-storey high section gives special cause for concern. The temporary roof covering provided in 2003 is now in tatters.

Contact: Keith Miller 01904 601990



SITE NAME: **Crucible Steel Shop on south east side
of former Sanderson Kayzers Darnall
Works, Darnall Road, Sheffield**

PRIORITY: C (D)

DESIGNATION: Listed Grade II*, SM

CONDITION: Poor

OCCUPANCY: Part occupied

OWNERSHIP: Company

Crucible steel works, single storey range dated to 1871 now disused. Of international significance as a unique survival of its type. Temporary coverings have been provided to the roof, doors and windows, and the building is now weather-tight.

Contact: Keith Miller 01904 601990



SITE NAME: **Wicker Arch and adjoining viaduct,
The Wicker,
Sheffield**

PRIORITY: C (C)

DESIGNATION: Listed Grade II*

CONDITION: Poor

OCCUPANCY: Part occupied

OWNERSHIP: Company

Railway viaduct, 1848. Suffering from stone theft (parapets) and general lack of maintenance. Most of the viaduct arches are in use for workshops.

Contact: Alison Fisher 01904 601975



SITE NAME: **Workshop ranges and crucible furnace,
attached to No.35,
Well Meadow Street, Sheffield**

PRIORITY: C (C)

DESIGNATION: Listed Grade II*

CONDITION: Poor

OCCUPANCY: Vacant

OWNERSHIP: Private

Workshops and a crucible furnace, c1840. The buildings are suffering from general decay. The gutters are failing in places and some slates have slipped. Site is generally secure and weathertight. The regeneration of the wider area has yet to impact on this site.

Contact: Trevor Mitchell 01904 601972

WEST YORKSHIRE

BRADFORD



SITE NAME: **Manningham Mill,
Heaton Street,
Heaton, Bradford**

PRIORITY: F (F)

DESIGNATION: Listed Grade II*, CA

CONDITION: Fair

OCCUPANCY: Vacant

OWNERSHIP: Company

Silk mill, with boiler house, chimney and warehouse. Built in 1873. Scheme of residential and office conversion agreed. Conversion of warehouse completed. Works to mill block underway.

Contact: Trevor Mitchell 01904 601972

Note:
If the priority category has altered since the 2007 Buildings at Risk register, the previous category is given in brackets.

ABBREVIATIONS

CA Conservation Area
RPG Registered Park & Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



SITE NAME: **Leventhorpe Hall,
1289 and 1291 Thornton Road,
Lower Grange, Bradford**

PRIORITY: C (C)

DESIGNATION: Listed Grade II*

CONDITION: Poor

OCCUPANCY: Vacant

OWNERSHIP: Private

Late C17 house with C19 additions. Windows are broken, the roof is sagging with missing slates. The east wall is failing. The site in general has substantially deteriorated but not the Hall. Residential scheme under discussion for the whole site.

Contact: Trevor Mitchell 01904 601972



SITE NAME: **Mill Building at Low Mills,
Low Mill Lane,
Keighley**

PRIORITY: D (D)

DESIGNATION: Listed Grade II*

CONDITION: Poor

OCCUPANCY: Vacant

OWNERSHIP: Company

Late C18. Early cotton mill, adjacent to supermarket and car park. Application approved for residential use. English Heritage grant offered towards repair works.

Contact: Richard Jaques 01904 601986



SITE NAME: **Waterloo Mill,
Howden Road,
Silsden**

PRIORITY: F (F)

DESIGNATION: Listed Grade II*, CA

CONDITION: Fair

OCCUPANCY: Part occupied

OWNERSHIP: Company

Main four storey spinning mill block, parts of roof deteriorating & allowing water ingress although extensive repairs to windows and roof covering recently completed. The middle section, which contains the engine, is deteriorating. Part converted to residential use. The Chimney was extensively repaired in 2005.

Contact: Richard Jaques 01904 601986

CALDERDALE



SITE NAME: **Double aisled barn to north west
of Kirklees Priory Gatehouse,
Kirklees Park, Brighouse**

PRIORITY: C (C)

DESIGNATION: Listed Grade I

CONDITION: Fair

OCCUPANCY: Part occupied

OWNERSHIP: Private

Aisled barn. One of the farm buildings of the Priory (now gone), with a C15 timber frame, which was later stone-clad. Whole complex continuing to decay.

Contact: Trevor Mitchell 01904 601972



SITE NAME: **Home Farm Building No. 6,
Kirklees Park,
Brighouse**

PRIORITY: A (A)

DESIGNATION: Listed Grade II*

CONDITION: Very bad

OCCUPANCY: Vacant

OWNERSHIP: Private

Early C17 cowhouse, 2 cell house, possibly slaughterhouse. Gable wall partially collapsed and unstable.

Contact: Trevor Mitchell 01904 601972



SITE NAME: **Kirklees Priory Gatehouse,
Kirklees Park,
Brighouse**

PRIORITY: B (B)

DESIGNATION: Listed Grade II*

CONDITION: Poor

OCCUPANCY: Vacant

OWNERSHIP: Private

Gatehouse to the Priory (now gone). Early C16, part timber-framed. Holding repairs in place, but beginning to fail. Feasibility and consent for office or dwelling recently obtained. Grant offered for repair but not taken up. Timber decay ongoing, so that work is becoming urgently necessary.

Contact: Trevor Mitchell 01904 601972

PRIORITY

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applies only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.



SITE NAME: **L-shaped Aisled Barn,
Kirklees Park,
Brighouse**

Aisled barn, early C16, encased in stone during the early to mid C17. Part of a little used farm complex. Area of roof missing to north. Office conversion agreed.

PRIORITY: B (C)

Contact: Trevor Mitchell 01904 601972

DESIGNATION: Listed Grade II*

CONDITION: Poor

OCCUPANCY: Vacant

OWNERSHIP: Private



SITE NAME: **Malthouse,
Kirklees Park,
Brighouse**

Malthouse, late C17. It forms part of a little used farm complex. Building appears to be in a stable condition. A new scheme for conversion is currently being developed.

PRIORITY: C (C)

Contact: Trevor Mitchell 01904 601972

DESIGNATION: Listed Grade I

CONDITION: Fair

OCCUPANCY: Vacant

OWNERSHIP: Private



SITE NAME: **Scout Hall,
Lee Lane,
Halifax**

Late C17 house. Part repaired with English Heritage grant, part derelict. Repair and reuse under discussion.

PRIORITY: C (C)

Contact: Richard Jaques 01904 601986

DESIGNATION: Listed Grade II*

CONDITION: Poor

OCCUPANCY: Vacant

OWNERSHIP: Private



SITE NAME: **Lumb Mill,
Lumb Lane,
Wainstalls, Halifax**

Watermill c1803. The waterwheel is very rare and in poor condition. English Heritage have offered a grant towards the first phase of a programme of repair.

PRIORITY: E (C)

Contact: Richard Jaques 01904 601986

DESIGNATION: Listed Grade II*

CONDITION: Fair

OCCUPANCY: Part occupied

OWNERSHIP: Private



SITE NAME: **Broad Bottom Old Hall,
Mytholmroyd,
Hebden Royd**

Late medieval timber-framed open hall encased in stone in the mid C16. Watertight but vacant for some years. Vulnerable to decay without a sustaining use.

PRIORITY: C (C)

Contact: Trevor Mitchell 01904 601972

DESIGNATION: Listed Grade II*

CONDITION: Fair

OCCUPANCY: Vacant

OWNERSHIP: Private



SITE NAME: **Birchen Lee Carr and attached barn,
Raw Lane,
Mytholmroyd, Hebden Royd**

House of mid C17 date, with added barn, 1886. Partly re-roofed 30 years ago, rear wing dismantled. Derelict.

PRIORITY: A (A)

Contact: Richard Jaques 01904 601986

DESIGNATION: Listed Grade II*

CONDITION: Very bad

OCCUPANCY: Vacant

OWNERSHIP: Private

Note:
If the priority category has altered since the 2007 Buildings at Risk register, the previous category is given in brackets.

ABBREVIATIONS

CA Conservation Area
RPG Registered Park & Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



SITE NAME:	Barn to north west of Greenwood Lee, Widdop Road, Heptonstall
PRIORITY:	C (C)
DESIGNATION:	Listed Grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant
OWNERSHIP:	Private

Late C16 aisled barn. Major failure of roof structure and loss of roof covering. Residential conversion of the barn and nearby outbuildings has been approved.

Contact: Richard Jaques 01904 601986

KIRKLEES



SITE NAME:	Milnsbridge House, 2-6 Dowker Street, Huddersfield
PRIORITY:	D (D)
DESIGNATION:	Listed Grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Part occupied
OWNERSHIP:	Private

Mid C18 house now in engineering use. Scheme approved for residential conversion. Pediments conceal modern flat roof.

Contact: Trevor Mitchell 01904 601972



SITE NAME:	Folly Hall Mill, Folly Hall, Huddersfield
PRIORITY:	C (C)
DESIGNATION:	Listed Grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant
OWNERSHIP:	Company

Six storey, 17 bay mill, 1844, incorporating some masonry from fire-damaged predecessor of 1825. Some repair in the early 1990s, but now has many broken windows, damaged gutters, tree growth etc. Consents in place for office and residential use.

Contact: Trevor Mitchell 01904 601972



SITE NAME:	18-20 St George's Square, Huddersfield
PRIORITY:	F (C)
DESIGNATION:	Listed Grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Vacant
OWNERSHIP:	Private

Part of Tite's Building. Built as offices and warehousing (Sir William Tite, 1852). Ground floor and basement, Nightclub. Upper floors empty. Walls bowing, partially failed gutter and truss. Refurbishment work underway. English Heritage grant has secured current condition survey, which suggests that bowing of walls is not significant.

Contact: Kathryn Gibson 01904 601939



SITE NAME:	Westwood Mills, Lowestwood Lane, Lintwaite, Huddersfield
PRIORITY:	A (New entry)
DESIGNATION:	Listed Grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant
OWNERSHIP:	Company

An early C19 mill complex, with some later C19 alterations. Buildings include former scribbling, carding and fulling mill, office, warehouse, workshops, boiler and engine house. Interiors and roofs stripped for refurbishment. Part lacks roof covering. Consents for conversion to residential use and new build residential development approved October 2005 but not yet implemented.

Contact: Kathryn Gibson 01904 601939



SITE NAME:	Hopton Congregational Church, Calder Road, Mirfield
PRIORITY:	C (New entry)
DESIGNATION:	Listed Grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant
OWNERSHIP:	Religious organisation

Church and attached school buildings to rear dated 1829. Largely unaltered and retaining box pews in the body of the church and original windows throughout. Water penetration has resulted in patches of timber decay and a falling roof truss. No longer used for worship.

Contact: Kathryn Gibson 01904 601939

PRIORITY

A
Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

B
Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C
Slow decay; no solution agreed.

D
Slow decay; solution agreed but not yet implemented.

E
Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applies only to buildings capable of beneficial use).

F
Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

LEEDS



SITE NAME: **Stank Hall quasi-manorial site,
Dewsbury Road,
Beeston**

Remains of a major yeoman farm of sub-manorial type, with surviving barn of C15 of 8 bays. Southern-most bays rebuilt in stone mid C17.

PRIORITY: A (New entry)

Contact: Keith Miller 01904 601990

DESIGNATION: Listed Grade II*, SM

CONDITION: Very bad

OCCUPANCY: Vacant

OWNERSHIP: Local authority



SITE NAME: **Church of St Margaret,
Cardigan Road,
Burley**

Anglican church 1908-9. Designed by TL Moore. West end finished by GG Pace in 1964. Plan to reuse as a Church and community centre. English Heritage/Heritage Lottery Fund grants offered December 2006 and 2007. Repair work to commence shortly.

PRIORITY: D (D)

Contact: Richard Jaques 01904 601986

DESIGNATION: Listed Grade II*

CONDITION: Poor

OCCUPANCY: Vacant

OWNERSHIP: Religious organisation



SITE NAME: **Temple Works gate lodge,
Marshall Street,
Holbeck**

Small derelict gate lodge to spinning, water, steam and flax mill of 1836-40 designed by Bonomi in the Egyptian style. Walls stable, but lacks a roof.

PRIORITY: C (C)

Contact: Trevor Mitchell 01904 601972

DESIGNATION: Listed Grade II*, CA

CONDITION: Poor

OCCUPANCY: Not applicable

OWNERSHIP: Company



SITE NAME: **Ledston Hall,
Hall Lane,
Ledston**

Country house now partly subdivided into flats, situated in late C17/C18 walled gardens with terraces to south and west, grass terraces to the east and an early C18 park to the north. Five periods of building starting in c1200 with chapel and kitchen. Landscape condition is generally fair to good. Long term future under consideration through preparation of a conservation plan.

PRIORITY: E (E)

Contact: Trevor Mitchell 01904 601972

DESIGNATION: Listed Grade I, RPG Grade II

CONDITION: Fair

OCCUPANCY: Part occupied

OWNERSHIP: Trust



SITE NAME: **First Leeds White Cloth Hall,
98-101 (consec) Kirkgate,
Leeds**

Cloth hall built in 1711. Derelict and deteriorating. An exceptionally rare example of an early C18 arcaded cloth hall. Parts of the building could collapse if full repairs are not undertaken soon.

PRIORITY: C (C)

Contact: Trevor Mitchell 01904 601972

DESIGNATION: Listed Grade II*, CA

CONDITION: Very bad

OCCUPANCY: Vacant

OWNERSHIP: Company



SITE NAME: **Hunslet Mill,
Goodman Street,
Hunslet, Leeds**

Flax mill of 1838 with later infill in south block. Housing development agreed, but not yet underway. A temporary roof has recently been erected.

PRIORITY: D (D)

Contact: Kathryn Gibson 01904 601939

DESIGNATION: Listed Grade II*

CONDITION: Poor

OCCUPANCY: Vacant

OWNERSHIP: Company

Note:
If the priority category has altered since the 2007 Buildings at Risk register, the previous category is given in brackets.

ABBREVIATIONS

CA Conservation Area
RPG Registered Park & Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



SITE NAME:	St Marys Convent Church (Mount Saint Mary), Church Road, Richmond Hill, Leeds
PRIORITY:	C (C)
DESIGNATION:	Listed Grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant
OWNERSHIP:	Company

Redundant Roman Catholic Church, 1852, by Joseph Hansom. Chancel and transepts by EW Pugin, 1866. Gothic style. Presbytery roof slates are partly missing; the windows are boarded and broken and the interior of the church has been stripped. Surveyed following concern of the Council for public safety. Holding works have been undertaken. Housing development under negotiation.

Contact: Trevor Mitchell 01904 601972



SITE NAME:	Memorial to Queen Victoria, Woodhouse Lane, Woodhouse Moor, Leeds
PRIORITY:	C (C)
DESIGNATION:	Listed Grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Not applicable
OWNERSHIP:	Local authority

1903 by Sir George Frampton. Portland stone base supporting an enthroned bronze statue of Queen Victoria. The base is flanked by bronzes of "Peace" and "Industry". The figure of Industry is severely damaged and now in store. The remaining bronzes are corroding. Formerly located in front of the Town Hall.

Contact: Kathryn Gibson 01904 601939



SITE NAME:	Rothwell Castle, Church Street (off), Rothwell
PRIORITY:	C (C)
DESIGNATION:	SM, CA
CONDITION:	Poor
OCCUPANCY:	Not applicable
OWNERSHIP:	Trust

Ruined chapel to medieval manor complex. C14. Masonry needs to be consolidated. The site is part of an active Local Heritage Initiative scheme to investigate its surroundings. Grant aid offered to owners but not accepted.

Contact: Keith Miller 01904 601990



SITE NAME:	Gazebo north of Clumpcliffe Farmhouse, Methley Lane, Methley, Rothwell
PRIORITY:	A (A)
DESIGNATION:	Listed Grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant
OWNERSHIP:	Private

Hunting lodge dated 1708 on rainwater heads. Total collapse of the front elevation. Temporary cover on the flanking roofs failing. Residential conversion agreed. Work still not implemented.

Contact: Kathryn Gibson 01904 601939



SITE NAME:	Thorpe Hall, Middleton Lane, Thorpe on the Hill
PRIORITY:	A (C)
DESIGNATION:	Listed Grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant
OWNERSHIP:	Private

Former farmhouse, 1735. UDP proposes employment land use allocation (offices). Some windows broken and gutters failed. Ceiling collapsed in one room. Roof holed.

Contact: Kathryn Gibson 01904 601939

WAKEFIELD



SITE NAME:	Farm building known as "Monks Refectory", Nostell Park, Huntwick with Foulby and Nostell
PRIORITY:	B (A)
DESIGNATION:	Listed Grade II*, SM, RPG Grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant
OWNERSHIP:	Private

Farm building of uncertain former function, but perhaps refectory or lodgings to former Nostell Priory. Dating from the C15 with alterations in the C17 or C18. Grant has been offered recently for the development and implementation of conservation works which are to commence in April 2008.

Contact: Richard Jaques 01904 601986

PRIORITY

A
Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

B
Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C
Slow decay; no solution agreed.

D
Slow decay; solution agreed but not yet implemented.

E
Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applies only to buildings capable of beneficial use).

F
Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.



SITE NAME: **Pontefract Castle,
Pontefract**

PRIORITY: B (B)

DESIGNATION: SM

CONDITION: Poor

OCCUPANCY: Not applicable

OWNERSHIP: Local authority

Substantial ruins comprising motte, bailey and Saxon cemetery. The fabric of the ruins needs substantial consolidation. A condition survey and conservation management plan have been completed and discussions on future works are underway.

Contact: Richard Jaques 01904 601986



SITE NAME: **Calder & Hebble Navigation
Warehouse, River Calder opposite
Thornes Lane Wharf, Wakefield**

PRIORITY: E (E)

DESIGNATION: Listed Grade II*, CA

CONDITION: Poor

OCCUPANCY: Vacant

OWNERSHIP: Former utility

Two warehouses c1790, converted to a single warehouse and remodelled 1816. Built for the Calder & Hebble Navigation Co. The Wakefield Waterfront area is currently subject to an ambitious programme of regeneration. Temporary roof repair carried out. Scheme for restoration and reuse approved. Works underway (Feb 2007).

Contact: Trevor Mitchell 01904 601972

Registered battlefields

EAST RIDING OF YORKSHIRE (UA)



SITE NAME: **Battle of Stamford Bridge,
Stamford Bridge**

DESIGNATION: Registered battlefield

TRAJECTORY: Declining

OWNERSHIP: Private

PHOTO: © Battlefields Trust

Three weeks before the Battle of Hastings (1066) King Harold defeated a Norwegian army at this crossing point on the River Derwent. The modern settlement of Stamford Bridge grew markedly in the later 20th century and little of the battlefield remains undeveloped.

Contact: Paul Stamper 07967 363312

NORTH YORKSHIRE

HARROGATE



SITE NAME: **Battle of Boroughbridge,
Boroughbridge / Langthorpe / Milby**

DESIGNATION: Registered battlefield

TRAJECTORY: Declining

OWNERSHIP: Private

PHOTO: © Battlefields Trust

Thomas Earl of Lancaster's 1322 revolt against Edward II ended with defeat as his army attempted to retreat north and cross the River Ure. Much of the battlefield lies under modern Boroughbridge; further expansion is possible north of the river.

Contact: Paul Stamper 07967 363312

SELBY



SITE NAME: **Battle of Towton,
Lead / Saxton with
Scarthingwell / Towton**

DESIGNATION: Registered battlefield

TRAJECTORY: Declining

OWNERSHIP: Private

PHOTO: © Battlefields Trust

High, bleak, arable land near Tadcaster was the scene of a ten-hour battle in March 1461 during the Wars of the Roses, costing c28,000 lives. Artefacts and arrowheads from the battle have been consistently targeted by metal detectorists, some unauthorised and working independently of any agreed archaeological survey. At least one episode of deep ploughing may have disturbed a possible mass grave.

Contact: Paul Stamper 07967 363312

WEST YORKSHIRE

BRADFORD / KIRKLEES / LEEDS



SITE NAME: **Battle of Adwalton Moor,
Drighlington**

DESIGNATION: Registered battlefield

TRAJECTORY: Declining

OWNERSHIP: Private

PHOTO: © Battlefields Trust

The 1643 battle during the English Civil Wars on moorland outside Bradford in which some 14,000 men fought gave control of the north of England to the Royalists. The battlefield faces various development pressures, notably from an industrial zone at its west end.

Contact: Paul Stamper 07967 363312

Note:
If the priority category has altered since the 2007 Buildings at Risk register, the previous category is given in brackets.

ABBREVIATIONS

CA Conservation Area
RPG Registered Park & Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



ENGLISH HERITAGE

This document is one of a series of publications produced as part of English Heritage's new national Heritage at Risk campaign. More information about Heritage at Risk and other titles in the series can be found at www.english-heritage.org.uk/har



For copies of this document, or if you would like it in a different format, please contact our Customer Services department.
Tel: 0870 333 1181; Fax: 01793 414926;
Textphone: 01793 414878;
E-mail: customers@english-heritage.org.uk

