

SOUTH WEST

Contents

HERITAGE AT RISK	III	Isles of Scilly (UA)	175
		North Somerset (UA)	180
THE REGISTER	VII	Plymouth, City of (UA)	181
Content and criteria	VII	Poole (UA)	186
Criteria for inclusion on the Register	VIII	Somerset	187
Reducing the risks	X	Exmoor (NP)	187
Publications and guidance	XIII	Mendip	189
Key to the entries	XV	Sedgemoor South Somerset	194 197
Entries on the Register by local planning authority	XVII	Taunton Deane West Somerset	202 204
Bath and North East Somerset (U	A) I	South Gloucestershire (UA)	206
Bournemouth (UA)	4	Swindon (UA)	209
Bristol, City of (UA)	4	Torbay (UA)	212
Cornwall (UA)	7	Wiltshire (UA)	213
Devon	42		
Dartmoor (NP)	42		
East Devon	79		
Exeter	87		
Exmoor (NP)	89		
Mid Devon	90		
North Devon	93		
South Hams	96		
Teignbridge	102		
Torridge	105		
West Devon	112		
Dorset	115		
Christchurch	115		
East Dorset	116		
North Dorset	122		
Purbeck	130		
West Dorset	139		
Weymouth and Portland	156		
Gloucestershire	157		
Cotswold	157		
Forest of Dean	164		
Gloucester	167		
Stroud	170		
Tewkesbury	172		

II





Heritage at Risk is our campaign to save listed buildings and important historic sites, places and landmarks from neglect or decay. At its heart is the Heritage at Risk Register, an online database containing details of each site known to be at risk. It is analysed and updated annually and this leaflet summarises the results. Heritage at Risk teams are now in each of our nine local offices, delivering national expertise locally.

The good news is that we are on target to save 25% (1,137) of the sites that were on the Register in 2010 by 2015. From the Roman site at

Easton Grey to the Porthmeor Studios in St Ives, this success is down to good partnerships with owners, developers, the Heritage Lottery Fund, Natural England, councils and local groups. It will be increasingly important to build on these partnerships to achieve the overall aim of reducing the number of sites on the Register. Andrew Vines, Planning and Conservation Director, South West

Last year in the South West, 59 listed buildings and scheduled monuments were removed from the Register for positive reasons. Although this success is tempered by the addition of 46 new entries, this is a significant achievement with several more removals than additions. However, the results involving other types of heritage assets are less good, with 6 conservation areas and I registered battlefield added to the Register, but only 4 conservation areas being removed. The continuing expansion of our survey of listed places of worship (150 new surveys in 2013) has contributed to 24 additions to the Register. Thankfully many of the churches and chapels on the Register have been offered Heritage Lottery Fund grants to help fund repairs, resulting in 10 listed places of worship being removed from the 2012 Register.

With the continuing challenging economic climate, grant funding remains the overwhelming means of removing assets from the Register. In 2013, English Heritage offered grants worth £1.5 million to 54 sites on the South West Register. Unfortunately, this amount is small compared with the total costs required to secure heritage assets at risk in the South West. Therefore, working with partners who can provide alternative sources of funding is crucial to removing assets from the Register.

With 43% (1,396) of England's scheduled monuments at risk located in the South West, our relationship with Natural England is vital in reducing risk in the rural historic environment. Funding from Natural England's Environmental Stewardship scheme removed 23 scheduled monuments, accounting for almost half of the scheduled monuments removed from the Register this year.

Our investment in a Heritage Support Officer at the Architectural Heritage Fund has helped to stimulate activity by Building Preservation Trusts (BPTs), and progress is being made at a number of sites including Bridport Literary and Scientific Institute.

The cover image shows how important local partnerships are in finding solutions for vulnerable historic assets, particularly conservation areas. In Gillingham, Dorset, the local community are preparing a Neighbourhood Plan to enhance the profile of the market town, boost its economy and improve the condition of key historic buildings within the conservation area. Since 2009, an increasing number of local authorities in the region have participated in the Conservation Areas Survey, with the result that 95% per cent of planning authorities have now participated.

The removal of a priority site from the 2012 South West Register, the scheduled monument at Easton Grey is a notable achievement. In the forthcoming year the South West Heritage at Risk team will work with the owners of assets at risk to try to repeat this success, finding sustainable futures for our most vulnerable heritage assets, including the new priority site of Civil War Earthworks on Brandon Hill, Bristol.

Ruth Garner,

Principal Adviser, Heritage at Risk

GILLINGHAM CONSERVATION AREA, DORSET

Representatives of Gillingham's community teams outside the grade II former Tudor News building in the High Street. This building at risk in the Conservation Area has recently been taken over by a local businessman who aims to repair the building and open a new shop in the next few months. Gillingham has been identified for urban growth within the emerging North Dorset Local Plan. The community are using this opportunity to improve the town's economic performance and profile. A study of Gillingham's historic character and buildings will inform the design of new developments, making sure that they relate well to the existing town.

BUILDINGS AND STRUCTURES

- Nationally, 4.1% of grade I and II* listed buildings (excluding places of worship) are on the Register. In the South West the percentage is 2.9% (154 buildings).
- 7 building or structure entries have been removed from the 2012 South West Register because their futures have been secured, but 6 have been added.

PLACES OF WORSHIP

- Of the 464 listed places of worship assessed in the South West, 50 are on the Register.
- 10 places of worship have been removed from the 2012 Register following repair work.

ARCHAEOLOGY

- 3,265 (16.5%) of England's 19,792 scheduled monuments are on the Register, of which 1,396 are in the South West.
- 52 archaeology entries have been removed from the 2012 Register for positive reasons and 40 have been added.
- 13.7% of archaeology assessments (194) on the South West baseline 2009 Register have been removed for positive reasons, compared to the national figure of 21.1%.
- Nationally, damage from arable cultivation is the greatest risk factor, accounting for 43% of those on the Register. In the South West the proportion is 36%.

PARKS AND GARDENS

• 100 (6.2%) of England's I,624 registered parks and gardens are on the Register. In the South West, 18 are on the Register, the same as last year.

BATTLEFIELDS

• Of the 43 registered battlefields in England, 6 are on the Register. Of the 8 registered battlefields in the South West, I is on the Register, added this year.

WRECK SITES

• Of the 46 protected wreck sites around England's coast, 4 are on the Register. None of the South West's 23 protected wreck sites are on the Register.

CONSERVATION AREAS

- 8,179 of England's 9,839 conservation areas have been surveyed by local authorities. 510 (6.2%) are on the Register. Of the 1,175 conservation areas surveyed in the South West, 57 (4.9%) are on the Register.
- 4 conservation areas have been removed from the 2012 South West Register for positive reasons, but 6 have been added.



TRELILL HOLY WELL, HELSTON, CORNWALL

Extensive plant growth and water erosion were damaging this scheduled monument. A new owner, along with local volunteers, Cornwall's Monument Management Scheme and the local parish council, all contributed towards the repairs, resulting in this site being removed from the 2012 Heritage at Risk Register. Long term it will be maintained by this local partnership.



CONSERVATION AREAS ARE REGISTER

1990 of SCHEDULED MONUMENTS OF THE REGISTER GRANTS
WAS OFFERED TO
54 SITES
PAREGISTER

PRIORITY HAR SITES

- Academy Theatre and Great Western Hotel (Palace Theatre), Union Street, Stonehouse, Plymouth
- Birnbeck Pier, Weston-Super-Mare, North Somerset
- Carriage Works, 104 Stokes Croft, Bristol
- Civil War Earthworks on Brandon Hill, Bristol
- Cloth finishing works at Tone Mills, north range, Langford Budville, Somerset
- Former Saxon church to west of Priory House, Leonard Stanley, Stroud, Gloucestershire
- Grenville Battery 550yds (500m) SSW of Maker Farm, Maker-with-Rame, Cornwall
- Guns Mill Barn, Littledean, Gloucestershire
- The Mechanics Institute, Emlyn Square, Swindon
- Torbay Cinema, Torbay Road, Paignton, Torbay

FOR MORE INFORMATION CONTACT:

Principal Heritage at Risk Adviser English Heritage South West 29 Queen Square Bristol BSI 4ND

Telephone: 0117 975 0700

Email: southwest@ english-heritage.org.uk



ST GILES' HOUSE REGISTERED PARK AND GARDEN, DORSET

BACKGROUND AND HISTORY:

St Giles has been the seat of the Earls of Shaftesbury since the 15th century and in the 18th and 19th centuries the park was an important designed landscape. According to recent research it was a ground-breaking design, influencing other landscapes such as that at Stourhead. It has wider cultural significance through its association with the Shafteburys as politicians, social reformers and philosophers. Today, however, in addition to the park, the main house is deemed to be 'at risk', together with a Shell Grotto and a number of scheduled monuments. This pattern

of neglect is largely the consequence of the abandonment of St Giles as a family home and a lack of historically informed management.

IS IT AT RISK?

The grade II* landscape at St Giles' House has been on the Heritage at Risk Register since 2009. It is still considered to be 'at risk', but with the energy and vision of the present Earl of Shaftesbury, and the commitment of Natural England's Higher Level Stewardship (HLS) scheme, its condition is rapidly improving.

WHAT'S THE CURRENT SITUATION?

A HLS agreement was signed between the St Giles' Estate and Natural England in 2011. With funding through HLS, a start has been made on a comprehensive programme of landscape conservation, restoration and enhancement. Projects already completed include de-silting the 18th century lake, as well as repairs to the Pepperpot Lodges and the Castellated Archway, and replanting of the Great Avenue. The HLS agreement will last for a period

of 10 years and, in addition to the works above, will bring about significantly enhanced management of the parkland landscape and offer related benefits to wildlife.

The restoration of the landscape at St Giles ably demonstrates that Registered Parks and Gardens are large, complex heritage assets, and it can take many years to identify and implement solutions to remove them from risk. The photograph shows the lake de-silting which took place in the winter of 2012/13. This is the first stage in the major HLS project at St Giles to restore the landscape. Progress towards restoring this challenging site has started, with an aim to remove this site and other related assets from the Register in the future.

Building strong relationships with other funding partners, as here at St Giles with Natural England, to assist owners in managing heritage assets will be critical for the success of the South West Heritage at Risk strategy in the forthcoming year.

Find out what's at risk by searching or downloading the online Heritage at Risk Register at www.english-heritage.org.uk/har If you would like this document in a different format, please contact our customer services department on telephone: 0870 333 1181 fax: 01793 414926 textphone: 01793 414878 email: customers@english-heritage.org.uk

THE REGISTER Content and criteria

DESIGNATION

Definition

All the historic environment matters but there are some elements which warrant extra protection through the planning system. These are included in the National Heritage List for England (http://list.english-heritage.org.uk). Since 1882, when the first Act protecting ancient monuments and archaeological remains was passed, government has been developing the designation system. Listing emerged from the post-blitz 1940s Planning Acts, and is now applied to about half a million buildings ranging from palaces to street lamps. Almost 20,000 archaeological sites are scheduled, which introduces management controls. Some 1,624 designed landscapes are registered, as are 43 battlefields, and 46 wreck sites are protected.

English Heritage, as the government's expert adviser, is responsible for making recommendations — but it is still the Secretary of State at the Department for Culture Media and Sport who makes the decisions on whether an asset is designated. Understanding and appreciation develop constantly, which makes keeping the designation base up-to-date a never-ending challenge.

While responding to threat-driven cases, we increasingly seek to work strategically through the National Heritage Protection Plan. Recent developments have seen a greater striving for openness and transparency in the process of designating a site, and better communication of what makes something special. A change in legislation, part of the Enterprise and Regulatory Reform Act, makes this possible.

Alongside the nationally designated assets found on the National Heritage List for England are locally designated assets. Best know are conservation areas, but local authorities can also create lists of locally valued assets. Most archaeological sites of significance are not scheduled, but rely on local identification and management for their protection.

LISTED BUILDINGS

A listed building is a building (or structure) that has been designated as being of 'special architectural or historic interest'. The older and rarer a building is, the more likely it is to be listed. Buildings less than 30 years old are listed only if they are of outstanding quality and under threat. There are over 376,000 listing entries on the National Heritage List for England.

Listed buildings are graded I, II* and II. Grade I and II* are particularly important buildings of outstanding interest; together they amount to 8% of all listed buildings. The remaining 92% are of special interest and are listed grade II.

Entries on the statutory list of buildings of special architectural or historic interest may comprise a number of separate buildings. Formal residential terraces are the most obvious example. Entries on this Register reflect how buildings are grouped and recorded on the statutory list.

Structures can occasionally be dual designated (both listed as buildings and scheduled as monuments). In such cases, scheduling controls take precedence.

SCHEDULED MONUMENTS

Scheduled monuments include single archaeological sites and complex archaeological landscapes. 19,792 examples have been designated because of their national importance. (Scheduled monuments are not graded). They cover human activity from the prehistoric era, such as burial mounds, to 20th century military and industrial remains. For the millennia before written history, archaeology is the only testament to innumerable generations of people of whom there is no other record.

The later 20th century saw unprecedented changes to the landscape. As a result, types of historic site that once were commonplace began to become rare. Those that survive often represent just small islands of what once characterised broad sweeps of our towns and countryside. Although protected by law, scheduled monuments are still at risk from a wide range of processes and intense pressures outside of the planning system. These include damage from cultivation, forestry and – often most seriously of all – wholly natural processes such as scrub growth, animal burrowing and erosion.

REGISTERED PARKS AND GARDENS

There are I,624 designed landscapes on the current English Heritage Register of Historic Parks and Gardens of Special Historic Interest. These registered landscapes are graded I, II* or II, and include private gardens, public parks and other green spaces, country estates and cemeteries. They are valued for their design, diversity and historical importance and in contrast to the number of listed buildings and scheduled monuments, registered parks and gardens is a very small group of assets.

Inclusion on the English Heritage Register of Historic Parks and Gardens brings no additional statutory controls, but there is a presumption in favour of conservation of the

designated site. Local authorities are required to consult English Heritage on applications affecting sites registered as grade I or II* and the Garden History Society on sites of all grades. The setting of designated heritage assets can also protect registered landscapes.

REGISTERED BATTLEFIELDS

English Heritage's Register of Historic Battlefields was set up in 1995, and is our youngest category of designation. Its aim is to protect and promote those sites where history was made through conflict. They range from the Battle of Maldon (991) to Sedgemoor (1185): almost half date from the period of the the civil wars in the mid-17th century. These are cherished for their memory, and for the respect owing to those who were killed, and whose remains still lie in the field.

Protection is needed to prevent encroachment through inappropriate development, or insensitive (and damaging) metal detecting, which can permanently alter the archaeological records. As with registered parks and gardens, there is a clear presumption in favour of protecting registered battlefields in Government planning policy. Battlefields are not graded.

PROTECTED WRECK SITES

England's 46 protected wreck sites represent a tiny proportion of the 33,000 odd pre-1945 wrecks and recorded casualties that are known to lie in the territorial sea. Wreck sites can be of importance for different reasons: the distinctive design or construction of a ship, the story it can tell about its past, its association with notable people or events and its cargo. The Protection of Wrecks Act 1973 empowers the appropriate Secretary of State to designate a restricted area around a vessel to protect it or its contents from unauthorised interference, and English Heritage administers the attendant licensing scheme for divers seeking access.

CONSERVATION AREAS

Conservation areas are designated by local authorities and are areas of special architectural or historic interest the character or appearance of which it is desirable to preserve or enhance. For more than 40 years conservation areas have proved a highly effective mechanism for managing change on an area-wide basis. There are currently over 9,800 conservation areas in England including town and city centres, suburbs, industrial areas, rural landscapes, cemeteries and residential areas. They form the historic backcloth to national and local life and are a crucial component of local identity and community cohesion.

Criteria for inclusion on the Register

RISK ASSESSMENTS

A risk assessment of a heritage asset is based on the nature of the site. Building or structure assessments, for instance, include listed buildings (but not listed places of worship) and structural scheduled monuments; archaeology assessments cover earthworks and buried archaeology.

BUILDINGS AND STRUCTURES

Buildings or structures (not in use as a public place of worship) considered for inclusion on this Register must be listed grade I or II*, (or grade II in London) or be a structural scheduled monument with upstanding masonry remains. Buildings or structures are assessed for inclusion on the basis of condition and, where applicable, occupancy (or use) reflecting the fact that a building which is occupied is generally less vulnerable than one that is not.

Occupancy (or use) is noted as 'vacant', 'part occupied', 'occupied', 'not applicable', or occasionally, 'unknown'. Many structures fall into the 'not applicable' category as they can be ruins, walls, gates, headstones or boundary stones.

Condition is noted as 'very bad', 'poor', 'fair' or 'good'. The condition of buildings or structures on the Register typically ranges from 'very bad' to 'poor', 'fair' and (occasionally) 'good' reflecting the fact that some buildings or structures capable of use are vulnerable to becoming at risk because they are empty, under-used or face redundancy without a new use to secure their future. Assessing vulnerability in the case of buildings in fair condition necessarily involves judgement and discretion. A few buildings on the Register are in good condition, having been repaired or mothballed, but a new use or owner is still to be secured.

Buildings or structures are removed from the Register when they are fully repaired/consolidated, and their future secured through either occupation and use, or through the adoption of appropriate management.

PLACES OF WORSHIP

Places of worship considered for inclusion on this Register must be listed grade I, II* or II and be used as a public place of worship at least six times a year.

Places of worship are assessed on the basis of condition only. If the place of worship is in 'very bad' or 'poor' condition it is added to the Register. Once on the Register, places of worship can move through the condition categories (e.g. from very bad to poor, to fair, even good) as repairs are implemented and the condition improves, until they are fully repaired and can be removed from the Register.

English Heritage has assessed a proportion of the 14,800 listed places of worship. We are working with the respective denominations to assess the remaining places of worship. Those that are identified as at risk will be included on the Register.

ARCHAEOLOGY

Archaeology assessments cover earthworks and buried archaeology. The archaeological sites on this Register have been identified as being at risk because of their condition and vulnerability, the trend in their condition, and their likely future vulnerability. A site's condition is expressed in terms of the scale and severity of adverse effects on it, ranging from those with 'extensive significant problems' to others that have only 'minor localised problems'.

Archaeological entries are removed from the Register once sufficient progress has been made to address identified issues, demonstrating a significant reduction in the level of risk.

PARKS AND GARDENS

The assessment of parks and gardens starts with an appraisal of the condition and vulnerability of each registered landscape. Steps being taken by owners to address problems are also taken into consideration.

Parks and gardens assessed as being at risk are typically affected by development and neglect. They have frequently been altered by development or are faced with major change. The original function of these landscapes has often changed; and divided ownership often results in the loss of the cohesive conservation of the historic designs.

Park and garden entries are removed from the Register once plans are put in place to address issues and positive progress is being made.

BATTLEFIELDS

Battlefields deemed to be at risk of loss of historic significance are included on this Register.

The identified risks and threats come from development pressure – for example, because they lie on urban fringes or are subject to development pressures within the site; arable cultivation, and unregulated metal-detecting. One major impact or a combination of several factors can be enough to raise the risk at a particular site.

Battlefields are removed from the Register when either actual damaging activities are reversed or managed, or threats recede due to effective management planning.

WRECK SITES

English Heritage has audited all designated wreck sites to identify those most at risk based on their current condition, vulnerability and the way they are being managed. Wrecks are vulnerable to both environmental and human impacts. Risks that contribute to the inclusion on the Register range from unauthorised access to erosion and fishing damage.

The monitoring process ensures that the significance of the site is identified and maintained.

In spite of the inherent difficulties in caring for this type of site, careful management must be maintained.

Wrecks are removed from the Register once an appropriate management and monitoring regime is operational.

CONSERVATION AREAS

English Heritage has asked every local authority in England to complete (and update as appropriate) a survey of its conservation areas, highlighting current condition, threats and trends, identifying those that are deteriorating, or are in very bad or poor condition and are not expected to change significantly in the next three years, as being defined as at risk.

The methodology for assessing conservation areas at risk has been refined since the first survey in 2008/2009. The information collated provides a detailed assessment of each conservation area and an overall category for condition, vulnerability and trend is included for each conservation area on this Register. Conservation areas identified as at risk in 2009, but not reassessed since using the revised methodology, are included on the Register but with limited information.

Conservation areas are removed from the Register once plans have been put in place to address the issues that led to the conservation area being at risk, and once positive progress is being made.

Reducing the risks

English Heritage is committed to securing a year-on-year reduction in the number of heritage sites at risk as part of our National Heritage Protection Plan (2011-2015). We have set ourselves a target to remove 25% of entries (1,137) published on the 2010 Register by 2015. Whilst this is a challenge given the number of entries on the Register and the different kinds of risk they face, good progress is being made.

To help address this challenge we have created dedicated Heritage at Risk teams in each local office. We have published our National Heritage at Risk Strategy which is supported by nine local strategies. Key objectives of the strategy are to understand what factors lead to heritage sites becoming at risk, what most influences their removal from the Register, and to achieve this through partnership, stimulating economic regeneration and growth, and maximising the benefit of our expertise and resources.

Whilst each type of heritage asset and individual site will require its own approach and solution, there are some general approaches that are relevant to all at risk assets. Resolving cases requires working in close partnership with owners, local planning authorities and other relevant organisations and partners. The provision of clear advice and understanding are essential.

Maintenance and where appropriate, occupation are key to preventing heritage assets becoming at risk, whilst maintenance of those already at risk will prevent them from decaying further. Without maintenance, the cost of repair and consolidation escalates, the challenge for owners and occupiers increases, and the scope for affordable solutions declines.

English Heritage provides a wide range of published guidance on reducing the risks, including on new uses for heritage assets, finding partners and funding, and on enforcing urgent works and repairs, on our website: www.english-heritage.org.uk or the Historic Environment Local Management (HELM) website: www.helm.org.uk

Historic Environment Records, and local heritage at risk registers maintained by local authorities, are repositories of information on local historic assets. They underpin the work of local authority historic environment services, the inclusion of information about condition can help improve the protection, conservation and management of heritage assets.

BUILDINGS AND STRUCTURES

English Heritage's role in securing the future of buildings and structures that are on the Register is primarily to provide practical advice, guidance and resources to local authorities, owners and developers.

Our local Heritage at Risk teams can help with analysis of the issues, investigating the feasibility of options and brokering solutions. We can advise on sources of grant aid and, where possible and appropriate, the provision of English Heritage's own grants. Our national advisers and specialists in structural engineering, quantity surveying, development economics and law provide support for local teams on particularly difficult cases. We work closely with grant providers, notably the Heritage Lottery Fund and Natural England as these are essential in helping secure the future of buildings or structures on the Register. In very exceptional cases, English Heritage may acquire and repair a particularly important building or structure, where it is clear that this is the only way of securing its long-term future. More information on funding can be found on the HELM website and at www.english-heritage.org.uk/professional/funding

Local authorities have a primary role in protecting the historic environment. The creation of a local heritage at risk register is the first step in tackling neglected buildings. A local register, often compiled with the help of voluntary groups can identify the scale of the problem, promote monitoring and help prioritise resources and action. A range of enforcement powers are available for local authorities to tackle listed buildings at risk but declining resources in local authorities means that these powers are often under-used. In a bid to help, English Heritage now has a legal adviser dedicated to heritage at risk. We can also provide grant aid to underwrite some of the costs involved in serving Urgent Works Notices and Repairs Notices on historic buildings and we hope that this, together with our published guidance (Stopping the Rot) will encourage local authorities to take action to save historic buildings.

Building preservation trusts (BPTs) offer a tried and tested way of saving many buildings at risk. In 2012 English Heritage joined forces with the Architectural Heritage Fund to employ four Heritage at Risk Officers to help not-for-profit organisations take forward building at risk projects. We also provide support for an Industrial Heritage Support Officer based at Ironbridge to work with similar groups running industrial sites. These officers aim to provide a supportive network offering guidance on the establishment of new BPTs, access to funding, training, information and links to associated groups. Case studies and our guidance on the transfer of heritage assets to community and voluntary organisations can be found at www.helm.org.uk/guidance-library/pillarsof-the-community-the-transfer-of-local-authorityheritage-assets

PLACES OF WORSHIP

Regular maintenance helps to keep all buildings in good condition but those suffering major problems need repairs to minimise the risks to both the structure and the contents. Keeping drains and gutters clear so that water is taken away from the building efficiently is the most important thing congregations can do as it stops small problems developing into unnecessary crises. The overflowing gutter soon soaks the wall beneath, rots the roof timbers behind it and makes the whole building vulnerable.

In some areas congregations group together to engage reputable contractors at competitive rates to clear gutters and rainwater goods. Such co-operation enables them to get good quality work carried out at reasonable prices by firms that understand historic buildings. The Maintenance Co-operatives project run by the Society for the Protection of Ancient Buildings will further help to connect, inform and empower those people who look after places of worship.

This year the Heritage Lottery Fund has started funding the new Grants for Places of Worship scheme, the main focus of which is fabric repairs but now also includes small changes to enhance community use of the building. English Heritage's architects and surveyors, based in our local Heritage at Risk teams, provide technical advice to the Heritage Lottery Fund on fabric repairs to ensure appropriate conservation standards are met.

The Government's Listed Places of Worship scheme, enabling the reclaiming of VAT on eligible repairs, maintenance and authorised alterations, is available to all listed places of worship, whether they have obtained grants or are funding work themselves. Local and national charities also offer grants.

English Heritage supports congregations wanting to keep their places of worship in use and recognises the need for appropriate new facilities such as kitchens and toilets that are sensitive to the building's special character. New Work in Historic Places of Worship (published 2012) helps congregations understand how changes can be achieved.

A network of support officers, employed locally but partfunded by English Heritage, offer advice and encouragement to congregations. Projects to effect repairs, develop necessary new facilities, provide community facilities, and welcome visitors are all transforming buildings that were once thought to be unfit for purpose.

ARCHAEOLOGY

The continuing success in reducing the number of archaeological sites on the Register, even in difficult economic times, demonstrates the value which owners and land managers place upon the monuments in their care, and more and more are addressing their long-term

management on a regular basis. Many scheduled monuments are now on land subject to an agreement under Natural England's Environmental Stewardship schemes, administered on behalf of Defra. Continuing partnership with Defra and Natural England has resulted in much more effective information sharing which we use in analysing, updating and publishing so that resources whether Environmental Stewardship or English Heritage – can be more closely targeted where they will have the greatest impact. We have agreed a joint target with Natural England to specifically reduce the number of scheduled monuments on the 2010 Register by 25% by 2015. We also continue to work closely with the Heritage Lottery Fund to help identify those important monuments deserving of grant aid for major stabilisation or repair work.

Nationally, damage from arable cultivation is still the greatest risk factor to archaeological entries on the Register. To help address this, the Conservation of Scheduled Monuments in Cultivation (COSMIC) project, a national survey which looks at ways in which further damage can be avoided whilst enabling cultivation to continue wherever possible will begin reporting in the autumn. Some causes of risk are neither so obvious nor dramatic in their effects however. Analysis of entries on the Register shows that unmanaged woodland, tree, scrub and bracken growth is one of the most widespread causes of long-term damage to both urban and rural archaeological sites, even if the effects are not as visible or as immediately destructive as other processes. In most cases simple, low cost but regular maintenance is the key, the delivery of which will always be reliant upon the help and goodwill of landowners.

PARKS AND GARDENS

Although a statutory list, the Register of Historic Parks and Gardens of Special Historic Interest in itself brings no additional statutory powers, it instead works through the development control system to provide a valuable tool for the protection of the sites it includes. The Government's National Planning Policy Framework (NPPF) stresses the desirability of sustaining and enhancing the significance of all heritage assets and finding viable uses consistent with their conservation. The NPPF states that great weight must be given to the conservation of sites included on the Register of Historic Parks and Gardens of Special Historic Interest and that substantial harm or loss of such features can only be justified in exceptional cases.

Most historic parks and gardens are either privately owned or in trust. In addition, local authorities are responsible for nearly all the public parks and cemeteries in our towns and cities. Registered parks and gardens are typically large, complex heritage assets, many in multiple ownership, and it can take many years to identify and implement solutions to reduce the risks to parks and gardens.

To help reduce the risks, English Heritage encourages and works with owners to develop conservation management strategies. Our landscape architects can help tailor conservation management plans and funding packages for individual landscape features or whole sites. We work with partners, such as Natural England and the Heritage Lottery Fund, to help source funding to secure sustainable futures for parks and gardens at risk.

Further information and conservation guidance for parks, gardens and designed landscapes is available at: www.english-heritage.org.uk/professional/advice/advice-by-topic/parks-and-gardens

BATTLEFIELDS

As with registered parks and gardens, the *Register of Historic Battlefields* brings no additional statutory controls to registered battlefields, but the *National Planning Policy Framework* makes it clear that registered battlefields are of equal significance to scheduled monuments, buildings listed grade I and II*, grade I and II* registered parks and gardens and protected wreck sites. Therefore, the positive conservation and management of registered battlefields is a core element of current heritage legislation.

English Heritage continues to work with owners to develop management plans for registered battlefields and, in appropriate cases, contribute towards the cost of management plans. We work to develop positive landscape strategies with owners and partners such as Defra. In some circumstances, we may encourage the conversion from arable to pasture of especially sensitive locations to protect battlefield archaeology from the effects of ploughing and as part of a wider drive to prevent unauthorised or damaging metal-detecting.

English Heritage also continues to encourage greater access to battlefields and improve their amenity value and visitors' appreciation of the impact these historic events had on our development as a nation.

Local authorities can also invite comments from the Battlefields Trust on planning applications affecting the setting of registered sites.

WRECK SITES

At the strategic level, the major sources of risk to designated wreck sites have been identified. In terms of high-priority sites, practical requirements have also been implemented through conservation management plans.

Risks to protected wreck sites can often be reduced through education, provision of marker buoys, or planning policies that take full account of their national importance. However, some sites require significant resources to stabilise their condition or to carry out detailed archaeological assessments of their conservation

requirements. Although English Heritage has statutory power to allocate funds to promote the preservation and maintenance of protected wreck sites, its financial resources can solve only a small proportion of the problems.

In spite of the inherent difficulties with caring for this type of site, careful management must be maintained if we are to avoid the loss of wreck sites. It is therefore close co-operation between the owners of protected wreck sites (where known), authorised divers and all organisations charged with care for the marine and coastal environment, that will make the real difference to their long-term survival.

Practical advice on the management of historic wreck sites, whether at the coast-edge or under water, is available from English Heritage (maritime@englishheritage.org.uk) and from www.helm.org.uk

CONSERVATION AREAS

The risks to conservation areas are difficult to address as they cover large areas of land: they include the spaces between buildings and trees as well as buildings and structures and therefore involve many different owners and methods of management. Looking after conservation areas is a responsibility shared by those of us who own homes and businesses within them as well as those of us whose job it is to manage the spaces between the buildings or make decisions about their future.

The Conservation Areas Survey, completed by local authorities, provides us with an understanding of what is particularly affecting the character and appearance of conservation areas: what is working well or what is putting them at risk. Strong planning policies, guidance and a clear management strategy for individual conservation areas, backed up by effective enforcement, are all critical in managing change in these areas. This is, however, extremely difficult at a time when local authorities across the country are reducing their staff numbers. Armed with the information provided by conservation area surveys, we, local authorities and other partners will have the evidence to direct resources much more accurately towards those conservation areas at greatest risk.

There are opportunities for members of the local community to get involved as well, either individually or through groups. Some local groups have helped to prepare character Appraisals and Management Plans for conservation areas whilst others have carried out their own assessments to identify management issues. Further information on how you can get involved is available at: www.english-heritage.org.uk/caring/get-involved/improving-your-neighbourhood/

Publications and guidance

English Heritage has produced the following publications relating to heritage at risk, including:

Buildings at Risk: a New Strategy (1998)

Caring for Places of Worship 2010 (2010) — a report on the condition of England's listed places of worship and the needs of the congregations

Heritage at Risk 2010 – report (2010)

Heritage at Risk: Conservation Areas (2009)

Heritage at Risk 2013 – national summary leaflet and regional summary leaflets for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire

Heritage at Risk Register 2013 – detailed listings for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire can be downloaded from our website or viewed on an interactive database: www.english-heritage.org.uk/risk

Monuments at Risk (2008) – summary of scheduled monuments at risk for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire

The Monuments at Risk initiative 2003-08 (2010)

Protected Wreck Sites at Risk: A Risk Management Handbook (2007)

Saving London: 20 Years of Heritage at Risk in the Capital (2010)

Stopping the Rot: A Guide to Enforcement Action to Save Historic Buildings (2011)

Vacant Historic Buildings: An Owner's Guide to Temporary Uses, Maintenance and Mothballing (2011)

HERITAGE AT RISK ON THE WEB

To find out more about the Heritage at Risk programme visit **www.english-heritage.org.uk/risk** where you will find an interactive database providing detailed information on all heritage sites at risk nationally.

Details of all nationally designated historic places in England are available in one place on the National Heritage List for England online database: http://list.english-heritage.org.uk

For further information about the different classes of designated heritage assets, including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites visit the Heritage Protection section of our website www.english-heritage.org.uk/heritageprotection

CONSERVATION POLICIES AND GUIDANCE

The following publications are among the numerous guidance documents available on our website: www.english-heritage.org.uk/publications or www.english-heritage.org.uk/helm

Caring for Historic Graveyard and Cemetery Monuments (2011)

Caring for Our Shipwreck Heritage: Guidelines on the First Aid Treatment and Conservation Management of Finds Recovered from Designated Wreck Sites Resulting from Licensed Investigations (2012)

Caring for Places of Worship (2010) — a practical booklet for everyone involved in caring for England's listed places of worship

Constructive Conservation in Practice (2008)

Constructive Conservation: Sustainable Growth for History Places (2013)

Conservation Principles, Policies and Guidance for the Sustainable Management of the Historic Environment (2008)

Creativity and Care: New Works in English Cathedrals (2009)

The Disposal of Historic Buildings: Guidance Note for Government Departments and Non-Departmental Public Bodies (2010)

Enabling Development and the Conservation of Significant Places (2008)

Farming the Historic Landscape: Caring for Archaeological sites on Arable Land (2004)

Farming the Historic Landscape: Caring for Archaeological Sites in Grassland (2004)

Guidance Notes and Application Forms for Grants to Local Authorities:

- Grants to Local Authorities to Underwrite Urgent Works Notices (1998)
- Acquisition Grants to Local Authorities to Underwrite Repairs Notices (1998)
- Grants for Historic Buildings, Monuments and Designed Landscapes (2004)

Heritage at Risk: Conservation Areas (2009) – guidance for local authorities on conservation area management

Heritage Crime Prevention: A guide for Owners, Tenants and managers of Heritage Assets (2013)

Heritage Crime Risk: Quick Assessment Tool (2013)

Heritage Works: the use of Historic Buildings in Regeneration (2013)

Managing Local Authority Heritage Assets: Some Guiding Principles for Decision Makers (2003)

New Uses for Former Places of Worship (2010)

New Work in Historic Places of Worship (2012)

Options for the Disposal of Redundant Churches and Other Places of Worship (2010)

Paradise Preserved: An Introduction to the Assessment, Evaluation, Conservation and Management of Historic Cemeteries (2002)

Pillars of the Community: the Transfer of Local Heritage Assets (2011)

Scheduled Monument Consent: a Guide for Owners and Occupiers (2009)

Shared Interest: Celebrating Investment in the Historic Environment (2006)

Theft of Metal from Church Buildings (2011)

Understanding Place: Conservation Area Designation, Appraisal and Management (2011)

Valuing Places: Good Practice in Conservation Areas (2011)

If you would like further information about any of these publications, please contact:

English Heritage Customer Services Department PO Box 569, Swindon SN2 2YP Telephone: 0870 333 1181

Fax: 01793 414926

Email: customers@english-heritage.org.uk

Key to the entries

This Register includes the following risk assessment types:

- Buildings and structures
 - grade I and II* listed buildings and structural scheduled monuments
- · Places of worship
 - grade I, II* and II listed buildings
- Archaeology
 - scheduled monuments earthworks and buried archaeology
- · Parks and gardens
- Battlefields
- Conservation areas

ORDER

Entries are grouped and ordered alphabetically, first by County (dark grey bands) or Unitary Authority (light grey bands), and then by Local Planning Authority (National Park/Unitary Authority/District or Borough). A blank band denotes the end of a county and the beginning of a unitary authority.

Sites that straddle more than one local planning authority are included under the lead authority.

Within each planning authority, entries are grouped by risk assessment type in the following order:

- · Buildings and structures
- Places of worship
- Archaeology
- · Parks and gardens
- Battlefields
- Conservation areas

Within each risk assessment type, entries are ordered alphabetically by parish, locality and street/site name (except for conservation areas which are ordered by site name only).

DESIGNATION

The principal designation is noted for each entry and includes:

- Listed Building (LB) grade I or II*
- Listed Place of Worship grade I, II* or II
- Scheduled Monument (SM)
- Registered Park and Garden (RPG) grade I, II* or II
- Registered Battlefield
- Conservation Area (CA)

Other designations that apply to the designated site, including location within a World Heritage Site (WHS), are also noted.

If an entry is dual designated (both listed and scheduled), 'and' rather than a comma is used (eg 'Scheduled Monument and Listed Building grade I'). If a scheduled monument entry is dual designated with a number of listed buildings, each is separated by a semicolon.

The National Heritage List Entry Number is included for all entries (except conservation areas). If a site is dual designated, all relevant List Entry Numbers are included.

CONDITION

For buildings (including places of worship) at risk, condition is graded as: 'very bad', 'poor', 'fair' and 'good'.

For sites that cover areas (scheduled monuments (archaeology assessments), parks and gardens and battlefields) one overall condition category is recorded. The category may relate only to the part of the site or monument that is at risk and not the whole site:

- extensive significant problems
- generally unsatisfactory with major localised problems
- generally satisfactory but with significant localised problems
- generally satisfactory but with minor localised problems
- optimal
- unknown (is noted for a number of scheduled monuments that are below-ground and where their condition cannot be established).

For conservation areas, condition is categorised as: 'very bad', 'poor', 'fair' and 'optimal'.

If a site has suffered from heritage crime it is noted in the summary. Heritage crime is defined as any offence which harms the heritage asset or its setting and includes arson, graffiti, lead theft and vandalism.

OCCUPANCY / USE

For buildings (excluding places of worship) that can be occupied or have a use, the main vulnerability is vacancy, or under-use. Occupancy (or use) is noted as follows:

- vacant
- · part occupied
- occupied
- unknown
- not applicable

VULNERABILITY

Principal vulnerability is noted for archaeology assessments and may relate only to the part of the site that is at risk, and include:

- · animal burrowing
- · arable ploughing
- coastal erosion
- collapse
- deterioration in need of management
- scrub/tree growth
- · visitor erosion.

For parks and gardens, battlefields and conservation areas, vulnerability is noted as high, medium or low.

PRIORITY CATEGORY

Priority for action is assessed on a scale of A to F, where 'A' is the highest priority for a site which is deteriorating rapidly with no solution to secure its future, and 'F' is the lowest priority.

For buildings and structures and places of worship the following priority categories are used as an indication of trend and as a means of prioritising action:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- **B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- **F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

2012 priority categories are given in brackets, otherwise 'New entry' is noted.

For **battlefields** the following priority categories are used as a means of prioritising action:

- A No action/strategy identified or agreed (where trend is declining or unknown)
- **B** Action/strategy agreed but not yet implemented (where trend is declining or unknown)
- C No action/strategy identified or agreed (where trend is stable or improving)

- D Action/strategy agreed but not yet implemented (where trend is stable or improving)
- E Monitoring as appropriate (any trend)
- **F** Action implemented/strategy underway/scheme in progress (any trend)

TREND

Trend for archaeology entries, parks and gardens and battlefields may relate only to the part of the site that is at risk and is categorised as:

- declining
- stable
- improving
- unknown

For conservation areas trend is categorised as:

- deteriorating
- deteriorating significantly
- · no significant change
- improving
- · improving significantly
- unknown

OWNERSHIP

A principal ownership category is given for each entry, and if sites are in divided ownership, a 'multiple' ownership category is noted.

CONTACT

This is the local Heritage at Risk Principal who acts as a first point of contact for the case, and to whom enquiries should be addressed.

For conservation areas, the contact is the conservation/planning officer at the relevant local planning authority (indicated by 'LPA').

We are not in any sense agents for the owners of the sites included, but we will endeavour to put people in touch with them where appropriate.

ABBREVIATIONS

CA Conservation Area
EH English Heritage
HLF Heritage Lottery Fund

LB Listed Building

LPA Local Planning Authority

NP National Park

RPG Registered Park and Garden SM Scheduled Monument

UA Unitary Authority

Entries on the Register by local planning authority

Local Planning Authority	Building and structure entries	Place of worship entries	Archaeology entries	Park and garden entries	Battlefield entries	Wreck site entries	Conservation area entries
BATH AND NORTH EAST	T SOMERSET ((UA)					
Bath and North East Somerset (UA)	4	1	9	0	0	0	9
BOURNEMOUTH (UA)	<u> </u>						
Bournemouth (UA)	0	0	1	0	0	0	0
BRISTOL, CITY OF (UA)							
Bristol, City of (UA)	10	3	3	0	0	0	1
Bristol, City of (UA) / Bath and North East Somerset (UA) [†]	0	0	0	I	0	0	0
CORNWALL (UA)				·			
Cornwall (UA)	27	8	192		1	0	1
DEVON							
Dartmoor (NP)	I	0	249	0	0	0	1
East Devon	4	1	54	0	0	0	3
Exeter		2	-	0	0	0	3
Exmoor (NP)	0	1	10	0	0	0	0
Mid Devon	2	1	17	0	0	0	3
North Devon	2	0	16	0	0	0	1
South Hams	8	0	32	0	0	0	0
Teignbridge	2	2	9	3	0	0	2
Torridge	2	I	43	0	0	0	2
West Devon	5	2	9	0	0	0	3
DORSET							
Christchurch	0	0	2	0	0	0	0
East Dorset	3	0	39	I	0	0	3
North Dorset	3	2	46	0	0	0	3
Purbeck	l	0	65	0	0	0	2
West Dorset	10	1	107	1	0	0	0
Weymouth and Portland	3	0	4	0	0	0	1
GLOUCESTERSHIRE	_						
Cheltenham	0	0	0	0	0	0	0
Cotswold	6	I	36		0	0	0
Forest of Dean	5	4	12	0	0	0	0
Gloucester	/	0	0	0	0	0	2
Stroud	5	2	8	0	0	0	0
Tewkesbury	5	I	12	0	0	0	I
ISLES OF SCILLY (UA)	1		20	0		^	0
Isles of Scilly (UA)			30	0	0	0	0
NORTH SOMERSET (UA)				0	0	0	4
North Somerset (UA)	3		-	0	0	0	4
PLYMOUTH, CITY OF (U. Plymouth, City of (UA)	A)	1	14	0	0	0	
POOLE (UA)	IZ		17	0	U	0	
Poole (UA)	0	0		0	0	0	5
1 0010 (0/1)	0	U		U	0	0	3

Local Planning Authority	Building and structure entries	Place of worship entries	Archaeology entries	Park and garden entries	Battlefield entries	Wreck site entries	Conservation area entries
SOMERSET							
Exmoor (NP)	0	0	20	0	0	0	0
Mendip	3		23	I	0	0	0
Sedgemoor	2	4	12	1	0	0	0
South Somerset	8	6	9	3	0	0	1
Taunton Deane	5	0	11	0	0	0	0
West Somerset	1		8	I	0	0	0
SOUTH GLOUCESTERSH	IIRE (UA)						
South Gloucestershire (UA)	7		4	1	0	0	2
SWINDON (UA)							
Swindon (UA)	2		15	0	0	0	0
TORBAY (UA)							
Torbay (UA)	3	0	3	2	0	0	2
WILTSHIRE (UA)							
Wiltshire (UA)	16	0	239	[0	0	
Wiltshire (UA) / New Forest (NP) [†]	0	0	I	0	0	0	0
TOTAL	179	50	1367	18	l	0	57

[†]Sites that cross local planning authority boundaries

BATH AND NORTH EAST SOMERSET (UA)



© English Heritage Archive

SITE NAME: King Edwards School, Broad Street, Bath

Listed Building grade II*, CA, DESIGNATION: WHS

CONDITION:

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: E (E)

OWNER TYPE: Commercial company

LIST ENTRY NUMBER: 1395027 School, 1752. A scheme for use as a hotel was submitted but withdrawn in 2006. Works to repair the roof have been successfully completed. The threat of decay has therefore diminished but the building remains vacant. Permission for hotel use granted in 2010 and renewed in

Contact: Ruth Garner 0117 975 0696



© Jim Warren

SITE NAME: Cleveland Baths, Hampton Row, Listed Building grade II*, CA, DESIGNATION: WHS CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: D (D)

OWNER TYPE: Local authority

LIST ENTRY NUMBER: 1396146 Dating from 1815, Cleveland Baths are believed to be the oldest surviving public outdoor swimming pools in England. A diminutive Georgian crescent houses the changing rooms and Caretakers Cottage. The Cleveland Pool Trust completed a business plan, condition survey and scheme design with English Heritage grant aid in 2012 and are now seeking capital funding for the works.

Contact: Ruth Garner 0117 975 0696

Contact: Ruth Garner 0117 975 0696

Early C13 Carthusian monastery, chapter house and

in use except chapter house. Some parts in need of

refectory still standing. Later stables, coach house and

garden buildings incorporate earlier material and follow

original complex layout of cloister and cells. All structures



© English Heritage

SITE NAME: Victoria Bridge, Victoria Bridge Road, Bath Listed Building grade II*, CA, DESIGNATION: WHS CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C)

1395490

OWNER TYPE: Local authority Suspension bridge by Dredge c1836. Due to structural instability a temporary Mabey girder has been installed. The council are expected to submit an application for Listed Building Consent to repair the bridge in 2013.



© English Heritage

SITE NAME: Hinton Priory, Hinton Charterhouse Scheduled Monument and Listed DESIGNATION: Buildings - 3 grade I, LB grade II CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C(C)

1320809; 1129461

OWNER TYPE: Private

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

1007014 and 1136191;

Contact: Ruth Garner 0117 975 0696

condition assessment.



© English Heritage

SITE NAME:	Church of St Andrew, Aller
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1227327

Grade II* listed small church. Saxon origins with C12/C13, C15 additions and major restoration 1861-1862 by H John Norton. The church has recently undertaken patch repair to the nave roof which is suffering from nail sickness and this will need proper repair in the near future. The church was visited in 1997 and again in 2010 to assess the issue of cracking through tower parapet stonework and to the staircase turret. Repair of the tower stonework is ongoing.

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

1

SITE NAME:	Camerton Romano-British town and associated Pr Norton-Radstock	ehistoric and early	medieval monuments, Camerton /
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013881
CONDITION:	Extensive significant problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Roman road 720yards (660metres) long, north of	Abbey Farm, Hinton	n Charterhouse
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005421
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Chewton Keynsham packhorse bridge, Keynsham		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1004518
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	Yes
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Stantonbury camp and adjacent sections of Wansd	yke, Marksbury	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002487
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Lansdown Roman camp, North Stoke		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005422
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Little Down camp, North Stoke		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004677
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Wansdyke: south east of Newbarn Farm, Norton I	Malreward	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003066
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Wansdyke: section 1230 yards (1120 metres) eas	twards from Burnt F	louse Inn, Southstoke
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1007003
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Gardening	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Roman villa at Upper Hayes, Wellow		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007002
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Batheaston		
DESIGNATION:	Conservation Area, 81 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	lan Lund (LPA) 01225 477 687
SITE NAME:	Corston		
DESIGNATION:	Conservation Area, 13 LBs	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	lan Lund (LPA) 01225 477 687
SITE NAME:	Keynsham Dapps Hill, Keynsham		
DESIGNATION:	Conservation Area, 9 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	lan Lund (LPA) 01225 477 687
SITE NAME:	Keynsham High Street, Keynsham		
DESIGNATION:	Conservation Area, 30 LBs, SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	lan Lund (LPA) 01225 477 687
SITE NAME:	Midsomer Norton and Welton, Norton-Radstoc	k	
DESIGNATION:	Conservation Area, 36 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
vulnerability:	Medium	CONTACT:	lan Lund (LPA) 01225 477 687
SITE NAME:	Paulton (including Paulton Basin), Paulton		
DESIGNATION:	Conservation Area, 16 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	lan Lund (LPA) 01225 477 687
SITE NAME:	Radstock (including Braysdown and Clandown), I	Norton-Radstock / Pe	easedown St. John / Camerton
DESIGNATION:	Conservation Area, 19 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	lan Lund (LPA) 01225 477 687

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	South Stoke, Southstoke		
DESIGNATION:	Conservation Area, 27 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	lan Lund (LPA) 01225 477 687
SITE NAME:	Wellow		
DESIGNATION:	Conservation Area, 49 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	lan Lund (LPA) 01225 477 687
POLIBNIEMOLITI I (LIA)			

BOURNEMOUTH (UA)

SITE NAME:	Two round barrows 300 yards (270 metres) north	west of Double Dy	ykes, Hengistbury Head
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002397
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696

BRISTOL, CITY OF (UA)



© Bristol City Council

SITE NAME:	Lower Lodge to Ashton Court, Ashton Road, Bristol
DESIGNATION:	Listed Building grade II*, RPG grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Local authority

1203599

LIST ENTRY NUMBER:

Picturesque Gothic style entrance lodge built 1805 by Henry Wood. Limestone ashlar, two storeys with wrought iron gates. Vacant with hole in main roof and signs of structural distress in ashlar. Doors and windows blocked on ground floor but upper storey open to weather. A scheme of repair and alteration has been agreed, and they hope to be on site in 2014.

Contact: Ruth Garner 0117 975 0696



© English Heritage

SITE NAME:	Mortimer House, Clifton Down Road, Bristol
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F(D)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1202096

Imposing mid C18 palladian suburban villa, until recently in hospital use, now vacant. Roofs are deteriorating and there has been significant water ingress. A scheme of repair and conversion was granted consent in 2013 and has commenced on site.

SITE NAME:	Clifton Observatory, Clifton, Bristol
DESIGNATION:	Listed Building grade II*, SM, CA
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private

1282362

Former windmill, now camera obscura. Built C18, camera obscura early C19. Interior winding stair leads up to obscura and down to a tunnel leading to Ghyston's Cave on the side of the Avon Gorge. Following extensive negotiations, a scheme of repair and conversion has been undertaken and consent has been given to restore the observatory dome in conjunction with restaurant use.

Contact: Ruth Garner 0117 975 0696

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG UA Unitary Authority
WHS World Heritage Site

The second of th
THE PERSON NAMED IN

© English Heritage

SITE NAME:	Swing Bridge over North Entrance Lock, Cumberland Basin, Bristol
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	N/A

PRIORITY CATEGORY: D (D)

OWNER TYPE: Local authority

LIST ENTRY NUMBER: 1202186

Wrought iron bridge c1844 by IK Brunel with tubular supporting members. Moved to current location in 1873. It has been redundant and decaying on dock since construction of Plimpsoll Bridge in C20. English Heritage has offered grant for the repair of the bridge.

C15 stair turret attached to C20 building. Situated in middle of a housing estate. The roof has recently been repaired but a long term use is still being sought for the

Contact: Ruth Garner 0117 975 0696



© English Heritage Archive

SITE NAME:	Stair turret (Holy Cross) Inns Court Vicarage, Inns Court Green, Knowle, Bristol	
DESIGNATION:	Listed Building grade II*	
CONDITION:	Fair	
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	D (D)	
OWNER TYPE:	Religious organisation	

LIST ENTRY NUMBER: 1202314 Contact: Ruth Garner 0117 975 0696

building.



© English Heritage

SITE INACIE.	attached railings, St Michaels Hill, Bristol
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (B)
OWNER TYPE:	Religious organisation

Church of St Michael and

Church, rebuilt in 1775-77 in a Gothick style, but retaining the mid CI5 tower; the interior is divided in three aisles by classical colonnades and has some late C19 fittings. The church has been vacant for over six years. A scheme has been proposed for new denominational church use and negotiations are ongoing.

@ Bristol City Council

SITE NAME:	28, Portland Square, St Pauls, Bristol
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company

1202444

1282109

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

One of a terrace of seven houses located in a largely complete Georgian square, c1789-1820. Limestone ashlar, brick stacks, slate mansard roofs, double-depth plan. Late Georgian style, four storeys with attic and basement. Consent for conversion to mixed use granted 2009 has not been implemented and ownership has subsequently changed.

Contact: Ruth Garner 0117 975 0696

Contact: Ruth Garner 0117 975 0696



© English Heritage Archive

SITE NAME:	31 and 32, Portland Square, St Pauls, Bristol
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private

1208879

Terraced houses, 1789-1820. Emergency repairs carried out with English Heritage grant aid in 1996. Wind and weathertight, but masonry continues to decay. There has been a partial collapse of the facade. Consent has been

given for repair and residential conversion but has not been

implemented.

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© English Heritage Archive

SITE NAME:	Carriage Works, 104, Stokes Croft, Bristol
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

1025273

Carriage works, 1862. A notable building in a manner recognised as particular to the city. Large and complex site including 4 Ashley Road (grade II) also in very bad condition. The Local Planning Authority are proactively pursuing a solution for the site.

Contact: Ruth Garner 0117 975 0696



© English Heritage

SITE NAME:	The Trinity Centre, Holy Trinity Church, Trinity Road, Bristol
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	F (D)
OWNER TYPE:	Charity (non-heritage)

1282076

Large perpendicular Gothic revival Commissioners church circa 1829. Trinity Community Arts Ltd lease building for use as arts venue. English Heritage grant aided condition survey in 2008. English Heritage grant aided feasibility study completed in 2012. First phase to be carried out 2013/14 with Big Lottery funding. Repairs to south aisle lead roof due for completion autumn 2013.

Contact: Ruth Garner 0117 975 0696



SITE NAME:

Church of All Hallows, All Hallows Road, Bristol

DESIGNATION:

Listed Place of Worship grade II

CONDITION:

Very bad

PRIORITY CATEGORY:

B (New entry)

OWNER TYPE:

Religious organisation

LIST ENTRY NUMBER:

1201954

Large decorated Gothic Revival church of c1900 by the Bristol architect Sir George Oatley. The plan and form is considered exceptional for its creative fusion of the congregational and liturgical. The site was a former clay quarry and the foundations rest on filled ground at differing levels. The building has suffered from differential settlement and has been the subject of two years' monitoring for structural movement. Surface water drainage works and structural repairs are planned. Repair Grant for Places of Worship offered in 2012 and repairs expected to be completed in 2014.

C13 church with C19 restoration. Roof coverings and rainwater goods are all in poor condition, and there is vegetation growing out of the eroding masonry. Areas of mortar erosion and cement render in need of replacement.

This building has been a victim of heritage crime.

Contact: Ruth Garner 0117 975 0696



© English Heritage

SITE NAME:	Church of St Mary the Virgin, Church Close, Bristol
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1205113

Contact: Ruth Garner 0117 975 0696



© English Heritage

SITE NAME:	Church of St Paul, St Pauls Road, Bristol
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1207682

rebuilt by Charles Hansom 14 years later after fire destroyed all but the tower and spire. The roof coverings probably date from the 1867 build and are all in poor condition and in need of replacement. The valley gutters have been patch repaired many times and also need long-term repair. A Repair Grant for Places of Worship was successfully applied for in 2011.

Church built in 1853 to designs by Manners and Gill, but

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 F. Under repair or in fair to good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS		
CA	Conservation Area	
LB	Listed Building	
LPA	Local Planning Authority	
NP	National Park	
RPG	Registered Park and Garde	
SM	Scheduled Monument	
UA	Unitary Authority	
WHS		

SITE NAME:	Anti-aircraft gun site, Purdown		
DESIGNATION:	Scheduled Monument, RPG grade II, CA	LIST ENTRY NUMBER:	1004531
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Civil War earthworks on Brandon Hill		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1006989
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Heavy Anti-aircraft battery 520 metres east of Hole	es Mouth	
SITE NAME: DESIGNATION:	Heavy Anti-aircraft battery 520 metres east of Hole Scheduled Monument	es Mouth LIST ENTRY NUMBER:	1021291
	·		1021291 Declining
DESIGNATION:	Scheduled Monument Generally unsatisfactory with major localised	LIST ENTRY NUMBER:	
DESIGNATION: CONDITION:	Scheduled Monument Generally unsatisfactory with major localised problems	LIST ENTRY NUMBER:	Declining
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY:	Scheduled Monument Generally unsatisfactory with major localised problems Vandalism	LIST ENTRY NUMBER: TREND: NEW ENTRY?:	Declining No
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument Generally unsatisfactory with major localised problems Vandalism Local authority	LIST ENTRY NUMBER: TREND: NEW ENTRY?:	Declining No
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument Generally unsatisfactory with major localised problems Vandalism Local authority Stokes Croft	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:	Declining No Ruth Garner 0117 975 0696
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument Generally unsatisfactory with major localised problems Vandalism Local authority Stokes Croft Conservation Area, 19 LBs	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: NEW ENTRY?:	Declining No Ruth Garner 0117 975 0696 No

BRISTOL, CITY OF (UA) / BATH AND NORTH EAST SOMERSET (UA)



SITE NAME: Brislington House, Keynsham Registered Park and Garden DESIGNATION: grade II*, 5 LBs, part in CA CONDITION: Extensive significant problems VULNERABILITY: High TREND: Stable NEW ENTRY?: No OWNER TYPE: Mixed, multiple owners

One of the first and most influential asylum landscapes in Britain. Now subdivided between a sixth form college, private residential development, commercial sports facilities, industrial units and a management training centre. Despite this, some components of the designed landscape survive. Its designation is being re-evaluated by English Heritage. Part of the park is in Bath and North East Somerset Unitary Authority.

LIST ENTRY NUMBER: 1001529 Contact: Ruth Garner 0117 975 0696

CORNWALL (UA)



© North Cornwall District Council

SITE NAME: Codda Farmhouse, Bolventor, Altarnun DESIGNATION: Listed Building grade II* CONDITION: Poor OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: F (F) OWNER TYPE: Private

1142823

Farmhouse. C17 or earlier. Partly collapsed. Repairs to the habitable part of the house have been undertaken and works are now underway on the shippon and ancillary buildings which are in poor condition. The collapsed gable end has been re-built.

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise

'New entry' is noted.

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

SITE NAME:

LIST ENTRY NUMBER:



© English Heritage

SITE NAME:	Scraesdon Fort, Antony
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Government or agency

1004347 and 1140707

1004346 and 1159255

Built 1868, used for military training purposes. Vegetation is kept under control to an agreed Conservation Management Plan but works are still outstanding to stop water ingress to the range west of the entrance, and further repairs are required to the main gates and to metalwork throughout the site. Works to the roof have improved access to the site and made it watertight, although significant localised problems remain to be tackled elsewhere on the site. The drawbridge is currently under repair.

Contact: Ruth Garner 0117 975 0696



© Ministry of Defence

SITE NAME:	Tregantle Fort, Antony
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Government or agency

Fort, built 1858-1865. The fort is vacant, with no end use identified. The interior of the Keep is in poor condition and is still drying out following repairs: new doors and windows have been fitted. Elsewhere in the fort, the barracks accommodation is no longer used and the interiors are deteriorating due to outstanding roof repairs which are currently underway. A section of the counterscarp wall has collapsed. Significant localised problems remain to be tackled elsewhere on the site.

Contact: Ruth Garner 0117 975 0696



© English Heritage

SITE NAME:	Barn about 40 metres south east of Tremaer, Maer, Bude- Stratton
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1229361

Rare example of late medieval barn in Cornwall in a hamlet now dominated by a popular caravan site not far from Bude. Approximately one third of the historic roof of cruck type (rare in Cornwall) survived late C20 fire. Historic element not in use and in poor condition. Small cob-built rear wing roofless and collapsing. Remainder re-roofed in corrugated iron and last used as riding stables. Repair and conversion proposals negotiated and agreed in 2012.

Contact: Ruth Garner 0117 975 0696



© Cornwall Council

	Camborne
DESIGNATION:	Listed Building grade II*, CA, WHS
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F(A)
OWNER TYPE:	Private

1142639

Rosewarne House (Gladys

Large early C19 H-plan granite town house in its own grounds. Latterly a residential home but vacant for some time. Lack of maintenance and vandalism resulted in rapidly increasing deterioration. Repairs and conversion agreed in 2012 and works underway (2013).

© Cornwall Council

SITE NAME:	Boiler house to winding engine house at King Edward Mine, Troon, Camborne
DESIGNATION:	Listed Building grade II*, WHS
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1159235

Boiler House to winding engine house, built 1904. Part of the King Edward Mine complex, the most complete surviving mine-head complex in the Cornish Mining World Heritage Site. One of the very few boiler houses for an engine house in the World Heritage Site with an original roof. The roof urgently needs replacing to match existing and repairs are required to the windows, doors and brick

Contact: Ruth Garner 0117 975 0696

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise

'New entry' is noted.

ABBREVIATIONS

CA Conservation Area

LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



© Cornwall Council

Count House, blacksmiths' shop and miners' dry, Kings Edward Mine, Troon, Camborne

DESIGNATION: Listed Building grade II*, WHS

CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: D (C)

Local authority

1142685

Count house, blacksmiths' shop and miners' dry. Mainly built c 1870. Part of the King Edward Mine complex, the most complete surviving mine-head complex in the Cornish Mining World Heritage Site. Repair and conversion scheme agreed 2013.

Contact: Ruth Garner 0117 975 0696



© Cornwall Council

Weighbridge stores, assay office and brass machining shop at King Edward Mine, Troon, Camborne

DESIGNATION: Listed Building grade II*, WHS

CONDITION: Very bad

OWNER TYPE:

LIST ENTRY NUMBER:

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: D (C)

OWNER TYPE: Local authority

LIST ENTRY NUMBER: 1142686

Weighbridge stores, assay office and brass machining shop built in 1870s. Part of the King Edward Mine complex, the most complete surviving mine-head complex in the Cornish Mining World Heritage Site. Repair and conversion scheme agreed 2013.

Contact: Ruth Garner 0117 975 0696



© English Heritage

SITE NAME:

Church of St Rumon, Ruan Major, Grade-Ruan

DESIGNATION:

Listed Building grade I

CONDITION:

Poor

OCCUPANCY:

Vacant/not in use

PRIORITY CATEGORY:

C (C)

OWNER TYPE:

Religious organisation

LIST ENTRY NUMBER: | |4|9|5

LIST ENTRY NUMBER:

Medieval former parish church, in picturesque churchyard. Roof removed shortly after closure in 1963. The Diocese has undertaken consolidation to the low walls but not to the tower which has a tree growing out of it at high level.



© Cornwall Council

SITE NAME: 13, High Street, Launceston

DESIGNATION: Listed Building grade II*, CA

CONDITION: Poor

OCCUPANCY: Part occupied/part in use

PRIORITY CATEGORY: A (A)

OWNER TYPE: Commercial company

1206510

Jettied and timber-framed corner house, prominent on town's market square. Roof structure is in very poor condition and upper level party wall also in very poor condition. Some of the structural work undertaken but condition of building remains serious.

Contact: Ruth Garner 0117 975 0696

Contact: Ruth Garner 0117 975 0696



© Cornwall Council

SITE NAME:

Treffry Viaduct, Luxulyan /
Lanlivery

DESIGNATION:

Scheduled Monument, WHS

CONDITION:

Poor

OCCUPANCY:

N/A

PRIORITY CATEGORY:

A (B)

OWNER TYPE:

Charity (heritage)

LIST ENTRY NUMBER:

1007279

Combined viaduct and aqueduct. Granite built ten-arched bridge with a span approximately 200 metres and which stands up to 27 metres above the valley floor. Water gushes from the leat within the structure. Leaks are evident at the abutments and at locations within the main spans of the structure. The main leaks have to be stopped to prevent progressive damage to the mortar joints in the masonry. A grant application was submitted to English Heritage in mid 2013 to carry out investigations into the condition of the viaduct and to allow temporary piping of water.

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

OWNER TYPE:

SITE NAME:



© English Heritage

,	,
SITE NAME:	Maker Heights Barracks Block, Maker-with-Rame
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Charity (heritage)

1375582

Built in 1804-1808 as a barracks for a line of earlier redoubts built to protect Devonport Dockyard in 1782. It is the most complete and unaltered small garrison barracks from this significant period. The two storey block was altered in the mid C19 when the formerly tile-hung first floor was rebuilt in brick. Partially repaired in use for a community art centre.

Contact: Ruth Garner 0117 975 0696



© English Heritage

	boundary wall and attached ancillary buildings, Maker-with- Rame
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1329099

Maker Heights Guard House

Built in 1804-1808 as Barracks for a line of earlier redoubts built to protect Devonport Dockyard in 1782. Altered in mid C19. Guard House in good condition and used as offices but several of other buildings are in poor to bad condition, in particular the Straw Store, Wash House and Caponier. Negotiations to re-roof the pay store have

Contact: Ruth Garner 0117 975 0696



© Vickery Holman Ltd

SITE NAME:	Boundary wall to Lanherne Carmelite Convent, Mawgan-in- Pydar
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation

1137593

C16 or C17 boundary park wall. Substantial loam bonded random rubble masonry wall almost 3 feet thick standing up to 12 feet in places. Neglected, heavily overgrown with ivy and partially collapsed in places. English Heritage working with agent to encourage urgent remedial repairs but so far only fencing off and clearance of collapses taken place. Condition survey needed to understand and monitor decay and to prioritise repairs.

Contact: Ruth Garner 0117 975 0696



© English Heritage

SITE NAME:	Dry sand and green sand shop, Perran Foundry, Perran Wharf, Mylor
DESIGNATION:	Listed Building grade II*, CA, WHS
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (F)

Commercial company

Early to mid C19 mould and casting buildings. This is the main furnace building. Impressive and surprisingly intact. Urgent repairs carried out early 2005. Listed Building Consent and Planning Permission for repair and conversion granted 2008 and now starting to be implemented in a phased manner, with an expected completion date of 2016. The buildings have been reroofed.

LIST ENTRY NUMBER: Contact: Ruth Garner 0117 975 0696 1141603



© English Heritage

SITE NAME:	Engineers Shop, Perran Foundry, Perran Wharf, Mylor
designation:	Listed Building grade II*, CA, WHS
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Charity (non-heritage)

Engineers shop, boring mill and pattern shop circa early/mid C18. Listed Building Consent and Planning Permission for repair and conversion granted 2008 and now starting to be implemented in a phased manner, with an expected completion date of 2016. However, the buildings remain in a very poor state of repair.

LIST ENTRY NUMBER: 1141643 Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© English Heritage

SITE NAME: New Pattern Shop, Perran Foundry, Perran Wharf, Mylor Listed Building grade II*, CA, DESIGNATION: WHS CONDITION: Very bad

OCCUPANCY: N/A PRIORITY CATEGORY: F (F)

OWNER TYPE: Commercial company

LIST ENTRY NUMBER: 1328668

Early C19 pattern shop. It is one of the most visually exciting buildings on site and despite serious problems retains most of its original structural fabric. Urgent repairs carried out early 2005. Permissions for repair and conversion granted 2008 and now starting to be implemented in a phased manner, with an expected completion date of 2016. Works on reroofing have been undertaken and the building is in the process of conversion.

Contact: Ruth Garner 0117 975 0696



© Penwith District Council

SITE NAME:	Trinity Methodist Chapel, Chywoone Hill, Newlyn, Penzance	
DESIGNATION:	Listed Building grade II*, CA	ľ
CONDITION:	Poor	
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1386515	

enlarged 1866. One of the best and most complete early C19 chapels in Cornwall. No longer used for religious worship. English Heritage grant for investigation and repairs offered 2010. Heritage Lottery Fund bid for multi-purpose community use to be re-submitted.

Former Nonconformist Wesleyan chapel circa 1834,

Contact: Ruth Garner 0117 975 0696



© Cornwall Council

SITE NAME:	Tolgus Calciner, New Portreath Road, Redruth
DESIGNATION:	Scheduled Monument, LB grade II, WHS
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1021240

Remains of a calciner used in the production of arsenic. It has been vacant for many years and is vulnerable with a damaged main roof and a collapsed adjoining tin roofed extension. The main hipped slate roof of the building has been damaged through vandalism and there is an urgent need for weather proofing.

Contact: Ruth Garner 0117 975 0696



© Cornwall Council

SITE NAME:	Sara's Foundry, Tolgus Place, Redruth
DESIGNATION:	Listed Building grade II*, WHS
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

1142573

C19 and C20 iron foundry and engineering works, containing a large quantity of tools and associated machinery. Buildings continue to deteriorate and are now in a very vulnerable condition. Discussions with Cornwall Council to identify an appropriate strategy to secure the building and prevent further deterioration have continued.

Contact: Ruth Garner 0117 975 0696



© Restormel Borough Council

SITE NAME:	Charlestown Methodist Church, Charlestown Road, St. Austell
DESIGNATION:	Listed Building grade II*, CA, WHS
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1144797

(mid C19). No longer used for worship. Building weathertight. Listed Building Consent granted for conversion of rear school block and stabilisation of chapel agreed but work still not started and condition of the school room has deteriorated.

Former Wesleyan chapel (1827) and attached schoolroom

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise

'New entry' is noted.

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© English Heritage

SITE NAME:	Hockings House Bible Christian Chapel, St. Cleer
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Private

1311103

Chapel dated 1846. Exceptionally well-preserved interior with gallery and good quality original fittings including leaders' pew. Now separated from the small Sunday school. Damaging conversion works 2012 will be mitigated by more extensive conversion to domestic use being considered 2013.

Contact: Ruth Garner 0117 975 0696



@ Cornwall Council

SITE NAME:	Flanking walls and gateway to the bridge over moat about 8 metres east of Old Rectory, Old Rectory Drive, St. Columb
	Major

DESIGNATION: Listed Building grade II*

CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C)

LIST ENTRY NUMBER:

OWNER TYPE: Private

LIST ENTRY NUMBER: 1144097

Mid-C19, part of William White's layout for the Bishop's Palace which became a Rectory and latterly a hotel. Obscured and threatened by dense vegetation. White's wrought iron gate, referred to in the List description is not at present hung and its whereabouts is unknown.

Contact: Ruth Garner 0117 975 0696



© Cornwall Council

SITE NAME:	Old Bishops Palace, Old Rectory Drive, St. Columb Major
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Commercial company

Commercial company 1144096 Contact: Ruth Garner 0117 975 0696

1851 by William White. Picturesque Gothic Revival country gentleman's rectory, a classic of the type. In very poor state of repair caused by lack of maintenance, vandalism, vegetation, inappropriate finishes and unlived-in state. Water ingress has resulted in dry rot and damage to historic fabric. Statutory action pending.



LIST ENTRY NUMBER:

© Cornwall Council

Calf House at Lithiack and stable adjacent to north, Port Eliot Estate, St. Germans Listed Building grade II*, RPG DESIGNATION: grade I CONDITION: Poor OCCUPANCY: Occupied/in use PRIORITY CATEGORY: C(C)

OWNER TYPE: Private LIST ENTRY NUMBER: 1140518

Late C18/early C19 estate agricultural building. Attributed to Soane for the Port Eliot Estate. In low key use but condition remains very poor.



© English Heritage

SITE NAME: Little Trethewey Methodist Chapel, Little Trethewey, St. Levan DESIGNATION: Listed Building grade II* CONDITION: Very bad OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: A (New entry) OWNER TYPE: Religious organisation

1311918

Built as Wesleyan Chapel in 1868. Small chapel with stuccoed Italianate front. Modest and complete interior with closed box pews. Raked seating under gallery, stand and communion rail in front of raised choir with organ and open benching. The church is in a bad condition with holes in the roof. The downpipes are blocked and external render is failing. Front gable is unstable and resulted in damage to the interior. Church closed April 2013. The condition continues to deteriorate.

Contact: Ruth Garner 0117 975 0696

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© English Heritage Archive

•	
SITE NAME:	Wesleyan Chapel, Porkellis, Wendron
DESIGNATION:	Listed Building grade II*, WHS
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Other not for profit group

1162569

Former Wesleyan Methodist chapel, built 1866. The congregation has moved into the Sunday school and the chapel was sold to a private buyer. New owner has addressed the most serious roof leaks and obtained Listed Building Consent for conversion to residential use with Cornwall Council and English Heritage.

Contact: Ruth Garner 0117 975 0696



© English Heritage

SITE NAME:	Church of All Saints, Pendarves Street, Tuckingmill, Camborne
DESIGNATION:	Listed Place of Worship grade II, CA, WHS
CONDITION:	Poor
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Religious organisation

1310848

Church built for the new parish of Tuckingmill in 1845. The external walls are suffering from severe erosion on all elevations, particularly on the south aisle walls and the middle stage to the tower. There have been recent high level losses with pieces of stone shearing off, causing safety concerns. The condition of the valley gutter is poor, with very many patch repairs. A Repair Grant for Places of Worship was successfully applied for in 2011, and repairs are underway.

Contact: Ruth Garner 0117 975 0696



SITE NAME:	Church of St David, Davidstow
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1158418

Typical Cornish three aisle church with a tall west tower mostly C15, but with an extensive late Victorian restoration. The roofs were all repaired about 15 years ago including the tower. The tower walls are now showing structural problems at high level and fabric is falling from the bell opening louvres. A Repair Grant for Places of Worship was offered in 2011, and repairs are now underway.

Contact: Ruth Garner 0117 975 0696



© English Heritage

© English Heritage

SITE NAME:	Church of St Michael, Stratton Terrace, Falmouth
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (F)
OWNER TYPE:	Religious organisation

1269974

A large suburban Anglican parish church fronting the estuary north of Falmouth. It was built in 1827 to the design of R Grout and has remained substantially unaltered since. A Repair Grant for Places of Worship was offered for roof repairs and was completed in 2012, however work is still needed to the windows.

Contact: Ruth Garner 0117 975 0696



© English Heritage

SITE NAME:	Church of St Wenappa, Churchtown, Gwennap
DESIGNATION:	Listed Place of Worship grade I, CA, WHS
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1328991

Large rural Anglican parish church, of three parallel aisles and a detached tower. An urgent re-slating of the outer aisle and porch roofs as the current coverings have reached the end of their useful lives. A Repair Grant for Places of Worship was offered in December 2012.

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 F. Under repair or in fair to good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



SITE NAME:	Church of St Briocus, Lezant
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LICT ENITDY NILIMBED.	1201277

Typical Cornish three aisled church overlooked by a tall west tower. The roof slates, especially the rag slate roofs, are failing. The valley gutters and rainwater goods also need repair. A Repair Grant for Places of Worship was offered in late 2012.

Contact: Ruth Garner 0117 975 0696

© English Heritage

© English Heritage

© English Heritage



SITE NAME:	Church of St Enoder, St. Enoder
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1311865

A large three aisled church in mid Cornwall. The six main large roof pitches need relaying because the C19 nails holding the slates on are rusting away. The valleys have split and although patched frequently, still let in water which is causing internal damage. A Repair Grant for Places of Worship for repairs to the roof was offered in 2011 and repairs are expected to start in 2013.

Contact: Ruth Garner 0117 975 0696

1	

Church of St Ida, St. Issey SITE NAME: DESIGNATION: Listed Place of Worship grade II CONDITION: Poor PRIORITY CATEGORY: A (B) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1212700

The church has CI4 and CI5 origins evidenced in the north and south aisle arcades. Rebuilt in 1872 to designs by JP St Aubyn, following collapse of tower and part of the nave. The ring beams were inserted at two levels in the tower walls to address structural weaknesses probably when the bells were lowered in the 1950s. The damp environment of the tower and the inadequate cover to the concrete means the reinforcement is corroding and therefore presenting a structural weakness which will only deteriorate if left unrepaired.

Contact: Ruth Garner 0117 975 0696



SITE NAME:	Church of St George, St George's Road, Truro
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1201533

Large suburban Victorian Anglican parish church, with a cruciform plan and west tower. The tower is in poor condition and the interior is unsafe beyond the first floor. A Repair Grant for Places of Worship was offered in March

© English Heritage

	0 ,
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1201533

Contact: Ruth Garner 0117 975 0696

SITE NAME:	Two hut circles 400 metres WSW of Furhouse, Advent			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004657	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving	
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
	Co-axial field system, hut circle settlements, cairnfield and land boundaries on Carne Down, Altarnun			
SITE NAME:	Co-axial field system, hut circle settlements, cairnfie	eld and land bounda	ries on Carne Down, Altarnun	
SITE NAME: DESIGNATION:	Co-axial field system, hut circle settlements, cairnfie Scheduled Monument	eld and land bounda	ries on Carne Down, Altarnun	
	·			
DESIGNATION:	Scheduled Monument Generally satisfactory but with significant localised	LIST ENTRY NUMBER:	1011726	

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

SITE NAME:	Deserted medieval settlement and field system wit post-medieval farmhouse north west of Tresibbet	h incorporated pre Farm, Altarnun	historic settlement and field system a
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007775
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Prehistoric coaxial field system, incorporated and a medieval settlement on Fox Tor and Treburland Fa		stone setting, linear boundaries and
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008245
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Prehistoric irregular field system and hut circle set deserted settlement south east of Tresibbet Farm,		nt medieval regular field system and
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007776
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Prehistoric stone alignment I kilometre SSE of Eas	tmoorgate, Altarnu	n
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012228
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Nine Stones stone circle 1.03 kilometres NNW of	Bowhayland Farm,	Altarnun / North Hill
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008631
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Scraesdon Fort, Antony		
DESIGNATION:	Scheduled Monument and Listed Building grade II	LIST ENTRY NUMBER:	1004347 and 1140707
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Hut circle group and enclosure north east of Carw	ven, Blisland	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004659
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Castle Pencaire hillfort, two rounds and a field sys	tem, Tregonning Hil	II, Breage / Germoe
DESIGNATION:	Scheduled Monument, LB grade II, CA, WHS	LIST ENTRY NUMBER:	1007293
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Group of round barrows south east of Middle Taphouse, Broadoak		
DESIGNATION:	Scheduled Monument, RB	LIST ENTRY NUMBER:	1004433
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Group of round barrows south of Penadlake, Broa	adoak	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004436
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round barrow 310 yards (280 metres) south of K	ilmansag, Broadoak	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004434
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round barrows west of West Taphouse, Broadoa	k	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004617
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two round barrows north west of Middle Taphou	ıse, Broadoak / St. P	innock
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003077
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Okeltor C19 arsenic, copper and tin mine, Calsto	ck	
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1019440
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

HERITAGE AT RISK 2013 / SOU SITE NAME:	· , ,		
DESIGNATION:	Prince of Wales Mine at Harrowbarrow, Calstock Scheduled Monument, WHS	LIST ENTRY NUMBER:	1021411
CONDITION:	Extensive significant problems	TREND:	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Declining No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
	Clown		Nutri Garrier 0117 773 0070
SITE NAME:	Tamar Canal, Gunnislake, Calstock		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1007302
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	St Bellarmin's Chapel, Cardinham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004442
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Trezance Holy Well and chapel enclosure, Cardinh	nam	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018494
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Carn Brea Castle, Carn Brea		
DESIGNATION:	Scheduled Monument, 2 LBs, CA, WHS	LIST ENTRY NUMBER:	1006704
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Wheal Busy, Chacewater		
DESIGNATION:	Scheduled Monument, LB grade II, WHS	LIST ENTRY NUMBER:	1021392
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Melangoose camp, Colan		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004426
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

HERITAGE AT RISK 2013 / SOU	ITH WEST / CORNWALL (UA)			
SITE NAME:	Killibury Castle later Prehistoric hillfort, Egloshayle	2		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010439	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Tregeare camp, Egloskerry			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006711	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Jewish and Congregationalist cemeteries at Ponsha	rden, Falmouth / Pe	enryn	
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1020815	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving	
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Round barrow 120 metres south east of Parkwood	Round barrow 120 metres south east of Parkwood Hill, Feock		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019087	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Cliff castle west of Gunwalloe Church, Gunwalloe			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004265	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No	
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Grambla Roman camp, Gweek			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003078	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Rectangular camp south west of Trevarnon Round	, Gwinear-Gwithian	1	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004468	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Roseworthy Arsenic Works, 700 metres west of C	Cornhill Farm, Gwin	ear-Gwithian
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021418
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Round near Lower Nanterrow, Gwinear-Gwithian		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007303
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Trevarnon Round, Gwithian, Gwinear-Gwithian		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006696
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Castle Kayle (earthwork), Phillack, Hayle		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006688
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Carvannel cliff castle, Illogan		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004390
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	'Headon Barrow' near Headon Cross, Jacobstow		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005434
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round 200 metres north west of Penventinnie, Ker	nwyn	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016063
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

HERITAGE AT RISK 2013 / SOUT	th West / Cornwall (ua)				
SITE NAME:	Camp north east of Northcott Park Quarry, Kilkha	ampton			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004382		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Five bowl barrows 480 metres and 510 metres north of Hendra Farm, Ladock				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019021		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable		
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Round and annexe 720 metres WSW of Tregear, I	Ladock			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020179		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Old windmill, Landewednack				
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1004397		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	Yes		
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Respryn Bridge, Lanhydrock / St. Winnow				
DESIGNATION:	Scheduled Monument, 2 LBs, RPG grade II*	LIST ENTRY NUMBER:	1006701		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - limited/localised	NEW ENTRY?:	No		
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Neolithic settlement and hut circle on Helman Tor	, Lanlivery			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007306		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving		
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No		
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Giants Hedge, Lerryn to Lanreath, Lanreath / St. V	еер			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006681		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No		
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696		

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

HEKI I AGE AT RISK 2013 / SOU	TH WEST / CORNWALL (UA)			
SITE NAME:	Mabel Barrow, Lansallos			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006683	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Earlier Prehistoric hillfort, two cairns, medieval po transhumance huts on Stowe's Hill, Linkinhorne	und and adjacent Pr	rehistoric field systems, hut circles and	
designation:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1012352	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Early medieval transhumance hut 740 metres west	of Blackcoombe Fa	rm, Linkinhorne	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011899	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Prehistoric funerary cist 1.275 kilometres north west of Wardbrook Farm, Linkinhorne			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012043	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Flooding	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Round cairn with central cist on Bearah Common,	1.106 kilometres n	orth of Wardbrook Farm, Linkinhorn	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010411	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Two adjacent transhumance huts on Caradon Hill,	450 metres north	of East Caradon Farm, Linkinhorne	
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1011900	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Neolithic long cairn, Prehistoric regular and irregu enclosure 625 metres west of Blackcoombe Farm,	lar aggregate field sy Linkinhorne / Nort	ystems, linear boundaries and medieva h Hill	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010221	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Medieval and post-medieval tin and copper mines was northern slopes of Caradon Hill, Linkinhorne / St.		system on the middle and lower
DESIGNATION:	Scheduled Monument, 2 LBs, CA, WHS	LIST ENTRY NUMBER:	1020942
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Round 450 yards (405 metres) north west of Lowe	er Chellew Farm, Lu	udgvan
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004262
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Trencrom Castle, Ludgvan		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006721
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Innis Downs earthwork, Luxulyan		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006684
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Ancient village and fields at Boswarva Carn, Madro	n	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004466
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bosullow Trehyllys (hut circles), Madron		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006697
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Courtyard house 200 yards (180 metres) NNE of	Try Farm, Madron	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004352
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Courtyard house 300 yards (270 metres) north we	est of Middle Carna	quidden, Madron
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004353
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Courtyard houses north east of Newmill, Madron		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004356
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Hut circles with associated field system 400 yards ((360 metres) south	west of Little Higher Bosullow, Madro
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1004316
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round 300 yards (270 metres) north east of Newr	nill, Madron	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004627
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round barrow 530 yards (480 metres) north west	of Nancothan Cott	tages, Madron
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004311
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Settlement 450 yards (400 metres) north west of N	Middle Carnaquidde	en, Madron
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003100
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Chun Downs prehistoric landscape complex, incoryards (180 metres) south west of Chun Farm, Mad	porating Chun Cro ron / Morvah / Sand	mlech, Chun Castle, and barrow 200 creed / St. Just
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007264
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

HERITAGE AT RISK 2013 / SOU	TH WEST / CORNWALL (UA)			
SITE NAME:	Barrow 800 yards (730 metres) WNW of Boswen	s Farm, Madron / S	t. Just	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004286	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Visitor erosion - moderate	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Cawsand Fort, Maker-with-Rame			
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1016102	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Earthwork redoubts Nos. 1, 2 and 3, Maker-with-f	Rame		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004254	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Grenville Battery 550 yards (500 metres) SSW of Maker Farm, Maker-with-Rame			
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1003114	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Incomplete Palmerstonian fort 650 yards (600 met	res) west of Forder	r, Maker-with-Rame	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007299	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Stock erosion - localised/limited	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Mount Edgcumbe round barrow, Maker-with-Rame	e		
DESIGNATION:	Scheduled Monument, RPG grade I	LIST ENTRY NUMBER:	1004496	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	No. 5 redoubt 450 yards (410 metres) north west	of Maker Farm, Ma	ker-with-Rame	
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1004255	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Round barrow 500 yards (460 metres) west of Tre	evassack, Mawgan-ir	n-Meneage
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004499
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Hillfort at Blacketon Farm, Menheniot		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007296
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Inswork Chapel, Millbrook		
DESIGNATION:	Scheduled Monument, LB grade II*	LIST ENTRY NUMBER:	1003095
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Croftoe British village, Morvah		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006740
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round barrow on Bin Down, Morval		
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1006651
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Group of four round barrows east of Bottaboroug	h, Morwenstow / K	ilkhampton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004402
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Trevelgue promontory camp and two barrows, Ne	ewquay	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006712
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Hut circle settlement 975 metres north east of Tre	ewortha Farm, Nor	th Hill
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009806
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Prehistoric co-axial and regular aggregate field syst on Bastreet Downs, south of Bowda Farm, North	ems with incorpora Hill	ated and adjacent hut circle settlemen
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011558
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round cairn 800 metres WSW of Tolcarne Farm,	North Hill	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011507
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round cairn 910 metres WSW of Tolcarne Farm,	North Hill	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011508
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round cairn 1,175 metres WSW of East Castick Fa	arm, North Hill	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010412
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round cairn with double orthostatic kerb and cist	497 metres south e	east of Trewortha Farm, North Hill
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009688
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Other not for profit group	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Stone hut circle 1,225 metres WSW of East Castion	k Farm, North Hill	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010414
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

	(-)			
SITE NAME:	Three adjoining Prehistoric linear boundaries on B Farm, North Hill	earah Tor, 687 met	res south west of Nodmans Bowda	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010220	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Three stone hut circles 1.06 kilometres north east	of Trewortha Farn	n, North Hill	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009807	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Two stone hut circles and adjacent Prehistoric boo	undary wall 575 me	tres west of West Berriow Farm, Nor	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010218	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696	
ITE NAME:	Unenclosed hut circle settlement and adjacent Prehistoric linear boundary 800 metres SSE of Trewortha Farm, North Hill			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008958	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Unknown	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Unenclosed hut circle settlement with incorporate Farm, North Hill	ed enclosure 1.5 kilo	ometres north west of Wardbrook	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008954	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Unknown	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Two adjacent prehistoric coaxial field systems inco and medieval fields on East Moor and Ridge, North	orporating regular fi n Hill / Altarnun	eld systems, stone hut circles, cairns	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008439	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
ITE NAME:	Three barrows 550 metres ENE of Cansford, Otto	erham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005463	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Roundago, hut circle and field system on Castallack	c Carn, Paul	
esignation:	Scheduled Monument	LIST ENTRY NUMBER:	1004654
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
WNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
TE NAME:	Bake Rings later prehistoric-Roman round with att	ached enclosure an	d outwork, Pelynt
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017682
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Group of three round barrows north of Hendra, P	elynt	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004621
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Hall Rings, Pelynt		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006682
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Ten barrows south of Wilton Mill, Pelynt		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004465
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Glasney College, Penryn		
DESIGNATION:	Scheduled Monument, LB grade II, part in CA	LIST ENTRY NUMBER:	1007260
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	Yes
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	St Piran's Oratory and associated early medieval ce	emetery, Perranzabi	ıloe
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1018955
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Flooding	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	The Tolgus arsenic works 80 metres south east of	East Tolgus House,	Redruth
DESIGNATION:	Scheduled Monument, LB grade II, WHS	LIST ENTRY NUMBER:	1021240
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Field system on Boswens Common, Sancreed		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007268
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Unknown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Goldherring British village, Sancreed		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004651
CONDITION:	Extensive significant problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Other not for profit group	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Hut circle north of Botrea, Sancreed		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003072
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Hut cluster Chirgwidden Vean, Sancreed		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006715
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bolster Bank, St. Agnes		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1016444
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Wheal Kitty C20 tin processing works, St. Agnes		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1021164
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
		CONTACT:	D .1.6 01.17.07F.0404
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Promontory fort and Civil War battery, Little Der	nnis Head, St. Antho	ny-in-Meneage	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004431	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Black Head promontory fort, St. Austell Bay			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004391	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696	
ITE NAME:	Prehistoric to post-medieval settlement, and religi west and south of Roughtor, St. Breward	ous and funerary re	mains on the middle and lower slopes	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019172	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696	
ITE NAME:	Stannon Stone Circle, prehistoric field system, hut circle settlement, cairns, cist, linear boundaries and medieval building north of Dinnever Hill, St. Breward			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007764	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
ITE NAME:	Stone circle on Emblance Common, St. Breward			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004459	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Unknown	CONTACT:	Ruth Garner 0117 975 0696	
ITE NAME:	Camp 900 yards (820 metres) south east of St Bur	ryan village, St. Bury	an	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004483	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
ITE NAME:	Round barrow 200 yards (180 metres) north of the	ne Merry Maidens, S	t. Buryan	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004358	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Embanked platform cairn with central mound 375	metres north west	of Trewalla Farm, St. Cleer	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1015976	
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Platform cairn with central mound 760 metres ESE	of Lambadla Farm,	St. Cleer	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1010327	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Platform cairn with central mound 900 metres ESE	of Lambadla Farm,	St. Cleer	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1010328	
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Prehistoric cist, cairns and cairnfield on north east Smallacoombe Downs, 570 metres north west of Smallacoombe Tor, St. Cleer			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018630	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Prehistoric enclosure 325 metres west of Trewalla	Farm, St. Cleer		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1010434	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Prehistoric enclosure and field system, two hut cireast of Sparretts Farm, St. Cleer	cles and parts of a r	medieval field system 350 metres sout	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1013216	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Prehistoric enclosure containing a stone hut circle of Sparretts Farm, St. Cleer	and parts of a med	ieval field system, 500 metres south ea	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1013199	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

SITE NAME:	Prehistoric irregular aggregate field system with inc Farm, St. Cleer	corporated stone h	ut circles 375 metres SSE of Sparretts
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1008765
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	Yes
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Prehistoric irregular and regular aggregate field sys boulder 750 metres ESE of Siblyback Farm, St. Clee	tems, enclosure, sto er	one hut circles, cairnfield and kerbed
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1010060
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Prehistoric irregular and regular aggregate field sys of Siblyback Farm, St. Cleer	tems with incorpor	rated stone hut circles 750 metres EN
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1011315
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Prehistoric regular aggregate field system with inco enclosure 550 metres WSW of Trewalla Farm, St.	orporated and adjac Cleer	ent stone hut circles and an adjacent
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1009731
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Prehistoric to post-medieval field systems, bounda north eastern Siblyback Moor, St. Cleer	ries, settlements an	d railway at Smallacoombe Parks and
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018631
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Round cairn 450 metres east of Sparretts Farm, St	. Cleer	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1009838
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Round cairn 472 metres SSW of Caradon Hill sum	mit, St. Cleer	
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1011824
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Round cairn 480 metres SSW of Caradon Hill sum	mit, St. Cleer	
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1011825
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round cairn 525 metres east of Trewalla Farm, St.	Cleer	
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1012041
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round cairn 527 metres SSW of Caradon Hill sum	mit, St. Cleer	
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1011840
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round cairn 557 metres SSW of Caradon Hill sum	mit, St. Cleer	
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1011844
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round cairn 740 metres SSW of Caradon Hill sum	mit, St. Cleer	
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1011774
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round cairn 800 metres ESE of Lambadla Farm, St.	Cleer	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1010326
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round cairn 840 metres south east of Trewalla Far	rm, St. Cleer	
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1011995
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Round cairn and shelters 812 metres SSW of Cara	don Hill summit, St	. Cleer
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1011784
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Public utilities	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round cairn with peripheral berm 402 metres SSW	of Caradon Hill su	ummit, St. Cleer
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1011822
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	South Caradon C19 copper mine, St. Cleer		
DESIGNATION:	Scheduled Monument, 2 LBs, part in CA, WHS	LIST ENTRY NUMBER:	1020614
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Stone hut circle 425 metres south east of Sparretts	s Farm, St. Cleer	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1013211
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Stone hut circle 685 metres south east of Trewalla	Farm, St. Cleer	
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1011907
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Stone hut circle centred 460 metres ESE of Sparred	tts Farm, St. Cleer	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1009839
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	The Tinners' Dyke 160 yards (150 metres) in lengt	h south of Henderg	grove Wood, St. Cleer
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004364
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Tor cairn with adjacent sub-rectangular hut 650 m	etres SSW of Carao	don Hill summit, St. Cleer	
Designation:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1011793	
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Two adjacent stone hut circles 265 metres WNW	of Trewalla Farm,	St. Cleer	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1009738	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Two adjacent stone hut circles 290 metres west o	f Trewalla Farm, St.	Cleer	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1009703	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Two platform cairns 750 metres and 785 metres east of Sparretts Farm, St. Cleer			
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1010325	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving	
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - moderate	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Two round cairns 455 metres and 475 metres nor	th west of Trewalla	Farm, St. Cleer	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1010324	
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Two stone hut circles and an adjoining Prehistoric	boundary wall 470	metres east of Trewalla Farm, St. Clee	
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1012000	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Prehistoric to medieval settlements, field systems, railway on north east Smallacoombe Down, St. Cle		ns, with post-medieval boundary and	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018629	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving	
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 Slow decay; solution agreed but for tyet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial like) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Prehistoric round cairn on Caradon Hill, 310 metro	es west of Heather	House, St. Cleer / Linkinhorne
esignation:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1020939
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Round 340 metres north west of Tresawle Farm, S	t. Columb Major	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020864
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Bury camp, St. Dominick		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004393
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Stock erosion - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Warren's Barrow, St. Erme		
esignation:	Scheduled Monument	LIST ENTRY NUMBER:	1016888
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Enclosures east of Gurlyn, St. Erth		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1007282
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Promontory fort north of village, St. Gennys		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003097
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Gunpowder storage complex at Kennall Vale, St. G	iluvias	
DESIGNATION:	Scheduled Monument, 3 LBs, WHS	LIST ENTRY NUMBER:	1020441
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Later prehistoric cliff castle, two prehistoric round Dodman Point, St. Goran	barrows, medieval	field system, and associated remains of
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1020865
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Camp 500 yards (460 metres) west of Trenance, So	t. Issey	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004235
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Cadson Bury hillfort, St. Ive		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004494
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Tokenbury camp, St. Ive		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1004469
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Hut circles, Higher Bussow, St. Ives		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006689
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Whitesand Bay (or Tregonhawke) battery, St. John		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004664
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Chambered barrow 100 yards (90 metres) east of	Kerrow Farm, St. J	ust
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004637
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
	•		
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

SITE NAME:	Hut circles 50 yards (45 metres) west of Carnyor	th Farm, St. Just			
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1004277		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696		
ITE NAME:	Round barrow 550 yards (500 metres) north of C	Chycarne, St. Just			
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1004245		
CONDITION:	Extensive significant problems	TREND:	Unknown		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Standing stone 200 yards (180 metres) west of Ch	nycarne, St. Just			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003116		
CONDITION:	Unknown	TREND:	Unknown		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Two barrows on Carn Bean 300 yards (270 metres) NNE of Higher Botallack, St. Just				
designation:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1004279		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable		
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Two barrows on Woon Gumpus Common 700 y	ards (640 metres) N	NW of Boslow Farm, St. Just		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004287		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable		
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Chapel enclosure 150 yards (140 metres) south o	f Trelease Farm, St.	Keverne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004334		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Westcott Cross, 480 metres south east of Westc	ott Lodge, St. Mellio	n / St. Dominick		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018019		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No		

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

HERITAGE AT RISK 2013 / SOU	TH WEST / CORNWALL (UA)		
SITE NAME:	Cliff castle at Winecove Point, St. Merryn		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004234
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	St Constantine's chapel and holy well, St. Merryn		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1018569
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Earthwork on Berry Downs, St. Neot		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004455
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	Yes
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Hobbs Hill tin mine, openwork and lodeback tinwo Chyseger Farm, St. Neot	ork 530 metres east	and 160 metres north east of
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021410
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Hut circle village 330 yards (300 metres) west of V	Vest Northwood Fa	arm, St. Neot
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004662
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Medieval homestead and fields on Redhill Downs,	St. Neot	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003074
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Prehistoric field systems, enclosure, hut circles and field system on Higher Langdon Farm, St. Neot	l rounds, with adjac	ent medieval settlement, longhouse and
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007475
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 Slow decay; solution agreed but for tyet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial like) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

SITE NAME:	Prehistoric settlements and field system with adjac streamworks on the Brown Gelly Downs, St. Neo	ent medieval settle t	ment, field systems, boundaries and t
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007770
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round cairn 1.062 kilometres south west of Highe	r Langdon Farm, St	. Neot
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007476
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round cairn 1.17 kilometres south west of Higher	Langdon Farm, St.	Neot
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007477
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Tregargus stone grinding mill No 2, St. Stephen-in-	Brannel	
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1003101
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	Yes
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two round barrows north east of Fairy Cross, St.	Winnow	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004439
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Gunpowder works at Kennall Vale, Stithians / St. C	Gluvias	
DESIGNATION:	Scheduled Monument, 9 LBs, WHS	LIST ENTRY NUMBER:	1020143
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Condolden Barrow, Tintagel		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004652
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

HERITAGE AT RISK 2013 / SOU	,		
SITE NAME:	The Ballast Pond, Torpoint		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007261
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Wheal Martyn china clay works, Treverbyn		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003265
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Carne Beacon round barrow 320 metres north of	Carne Farm, Verya	n
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019745
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Warbstow Bury camp, Warbstow		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006710
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Ancient village south of Carburrow Tor, Warlegga	n	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003073
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bosigran Castle 900 yards (820 metres) west of Bo	osigran, Zennor	
DESIGNATION:	Scheduled Monument, LB grade II, WHS	LIST ENTRY NUMBER:	1003106
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Porthmeor ancient village, Zennor		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003071
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Treen Common barrows, Zennor		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004473
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696

SITE NAME:	Carclew, Mylor
DESIGNATION:	Registered Park and Garden grade II, 5 LBs, WHS
CONDITION:	Extensive significant problems
VULNERABILITY:	Medium
TREND:	Unknown
NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners
LIST ENTRY NUMBER:	1000544

Mid-C18 formal terraced and water gardens, together with an C18 landscape park. The main house burned down in 1934 and the site is now in divided ownership. Infill residential development has taken place in the park belts, substantial areas of woodland have been cleared and many individual parkland trees have been lost.

Contact: Ruth Garner 0117 975 0696



© English Heritage

SITE NAME:	Battle of Braddock Down, Broadoak / St. Pinnock
DESIGNATION:	Registered Battlefield, LB grade II, 2 SMs
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Declining
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1000005

Battle of Braddock Down, 1643. A large proportion of the designated area of the battlefield is under the plough, including two of the scheduled barrows. The site is therefore at risk.

Contact: Ruth Garner 0117 975 0696

SITE NAME:	Bodmin		
DESIGNATION:	Conservation Area, 96 LBs, SM	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Alyson Cooper (LPA) 01872 323603

DEVON

DARTMOOR (NP)



SITE NAME:	Higher Sigford, Sweet's Sigford, Ilsington, Teignbridge
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1389617

A rare example of a longhouse derivative in a farmstead context which has been used for agricultural storage in more recent years. Conditional consents for re-occupation of the house have been granted. As of 2013, the new owner is negotiating amendments following appeals.

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

CA egory is LB erwise LPA NP RPC

ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park

NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Agglomerated enclosure on the west side of the En	me Valley below St	calldown, Cornwood, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012740
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Blowing house north of Yealm Steps, Cornwood, S	outh Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002628
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Unknown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Enclosure on the west side of the Erme valley belo	w Stalldown, Corn	wood, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012767
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Medieval settlement on Ford Waste, Cornwood, S	outh Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002627
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	The southern of three enclosures north of Ford V	/aste, Cornwood, S	outh Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012700
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Unknown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Three unenclosed stone hut circles on the west sid South Hams	le of the Erme Valle	ey, north of Lower Piles, Cornwood
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012768
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two hut circles on the south east slope of Stalldov	vn, Cornwood, Sou	th Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012766
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

HERITAGE AT RISK 2013 / SOU	, ,		
SITE NAME:	Unenclosed stone hut settlement north east of Yao	•	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012771
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Enclosure and hut circles east of Huntingdon Ford,	Dean Prior, South	Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002536
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Hut circles and two enclosures on Dean Moor, ne	ar River Avon, Dea	n Prior, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003828
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Agglomerated enclosure with hut circles, south of	Lower Piles, Harfor	rd, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009578
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Blowing house at junction of Hook Lake and River	Erme, Harford, Sou	uth Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002605
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Blowing house north of Dry Lake, Harford, South	Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002609
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Cairn in north east corner of Lower Piles, Harford	, South Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009575
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

HERLITAGE AT RISK 2013 / SOUT	TH WEST / DARTMOOR (NP)			
SITE NAME:	Enclosure and hut circles at Piles Corner, Harford,	South Hams		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013108	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Enclosure with hut circles east of Addicombe, Har	ford, South Hams		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012484	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Enclosure with hut circles east of Addicombe, Har	ford, South Hams		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017609	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Enclosure with hut circles in Higher Piles newtake, Harford, South Hams			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013110	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Enclosure with hut circles to the north east of Pile	s Copse, Harford, S	South Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013106	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Hut circles and enclosure to south of Left Lake, Ha	arford, South Hams	3	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004574	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Hut circles in Erme Pound east of River Erme, Har	ford, South Hams		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002604	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Stone row, cairn and enclosures near Hook Lane, I	Erme Valley, Harfor	rd, South Hams
Designation:	Scheduled Monument	LIST ENTRY NUMBER:	1002493
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Unenclosed stone hut settlement on the east side Hams	of the Erme Valley,	north Harford Moor, Harford, South
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012747
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Unenclosed stone hut settlement with enclosures	north of Piles Cops	e, Harford, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012765
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Eight cairns forming part of a cairn cemetery on Ho Horn's Cross, Holne, South Hams	olne Ridge and a sto	one alignment immediately west of
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019273
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Enclosed prehistoric settlement and round cairn 88 South Hams	30 metres south we	est of Venford Reservoir dam, Holne,
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1020095
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Enclosed prehistoric settlement and three round co	airns 870 metres so	outh east of Horn's Cross, Holne, Sou
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020096
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Four cairns 310 metres south of Horn's Cross form South Hams	ming part of a cairn	cemetery on Holne Ridge, Holne,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019272
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696
O E.	Local dudioney		

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

HERITAGE AT RISK 2013 / SOU	TH WEST / DARTMOOR (NP)		
SITE NAME:	Four cairns on Holne Lee 1140 metres north west	of Greatcombe, H	olne, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019268
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Holne Chase Castle, Holne, South Hams		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003842
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Part of the Dartmeet coaxial field system and othe west of Venford Reservoir, Holne, South Hams	r archaeological rer	mains on Holne Moor west and north
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020487
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Partially enclosed stone hut circle settlement 350 metres south west of Horn's Cross, Holne, South Har		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019274
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Partially enclosed stone hut circle settlement 420 r Holne, South Hams	metres north west a	and 440 metres west of Horn's Cross
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1020185
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Partially enclosed stone hut circle settlement 560 r	metres west of Hor	n's Cross, Holne, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019275
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Prehistoric fields and settlements north east of Versystem, Holne, South Hams	nford Reservoir for	ming part of the Dartmeet coaxial fiel
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1020091
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Prehistoric fields, settlements and cairn south east field system, Holne, South Hams	or ventord Keserve	oir forming part of the Dartmeet coas
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020092
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Ringleshutes tinwork, Holne, South Hams		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020098
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Stone hut circle and length of boundary walling 860 South Hams	0 metres south wes	et of Venford Reservoir dam, Holne,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020094
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Three stone hut circles 780 metres SSW of Venfor	rd Reservoir dam, F	Holne, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020093
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Medieval farmstead and field system, post-Medieva west of Gibby Coombe, Holne / West Buckfastleig	l tinworks, Prehisto th, South Hams	oric settlements and cairns north and
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019591
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two ring cairns 330 metres south east of Coldharl	bour Cross, Loddis	well, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014244
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Dumping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	A stone alignment, kerbed cairn, Prehistoric settler 720 metres south west of Great Trowlesworthy T	ment, four pillow m or, Shaugh Prior, So	nounds, a vermin trap and animal runs outh Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016147
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

SITE NAME:	Agglomerated enclosure with hut circles south we	st of Ditsworthy Cl	am, Shaugh Prior, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009573
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	An enclosed settlement, length of reave, two verm Trowlesworthy Warren House, Shaugh Prior, Sou	in traps and a pillov th Hams	w mound 770 metres east of
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015748
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	An unenclosed stone hut circle settlement 760 me Prior, South Hams	tres north east of T	rowlesworthy Warren House, Shau
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014656
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Barrow near Shaugh Cross, Shaugh Prior, South H	ams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003824
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Cairn south of Mill Corner, Shaugh Prior, South H	ams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013413
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Cairn with a cist east of Willings Walls Reave, Shar	ugh Prior, South Ha	ms
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012209
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Cairn with a cist, one of several on the western ed	_	_
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012051
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Cross Dyke reave, Shaugh Prior, South Hams		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010811
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Double stone alignment with a terminal stone setti South Hams	ng south of Great ⁻	Frowlesworthy Tor, Shaugh Prior,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012114
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Eight pillow mounds and a vermin trap on the nort Trowlesworthy Warren, Shaugh Prior, South Hams	hern slope of Little	Trowlesworthy Tor forming part of
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015758
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Enclosed stone hut circle settlement and three rou	nd cairns on Giant'	s Hill, Shaugh Prior, South Hams
PESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019081
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
TE NAME:	Enclosure with hut circles west of Plym Steps, Shau	igh Prior, South Ha	ms
esignation:	Scheduled Monument	LIST ENTRY NUMBER:	1012297
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
TE NAME:	Hentor Warren boundary stone standing 200 metr	es south east of He	en Tor, Shaugh Prior, South Hams
ESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015744
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Hut circles west of Saddlesborough, Shaugh Prior,	South Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002520
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Medieval farmstead and field system, length of Will mounds at Willings Walls Warren, Shaugh Prior, S	outh Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019083
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Multi-period remains at Hentor Warren, Shaugh Pr	rior, South Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019082
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	One of a number of cairns with cists south of Shavercombe Brook, Shaugh Prior, South Hams		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012214
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	One of a number of cairns with cists south of Shavercombe Brook, Shaugh Prior, South Hams		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012172
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	One of three stone hut circles 500 metres SSE of L	egis Tor, Shaugh P	rior, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012631
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Pillow mound 100 metres south east of Great Tro Shaugh Prior, South Hams	wlesworthy Tor, fo	rming part of Trowlesworthy Warre
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014666
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Pillow mound 160 metres south west of Great Tro Shaugh Prior, South Hams	owlesworthy Tor, fo	orming part of Trowlesworthy Wari
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014665
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 Slow decay; solution agreed but for tyet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial like) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Pillow mound 270 metres south east of Ditsworth Prior, South Hams	y Warren House fo	rming part of Hentor Warren, Shaug	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014477	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Pillow mound 530 metres ENE of Trowlesworthy Warren House forming part of Trowlesworthy Warren, Shaugh Prior, South Hams			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014462	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Pillow mound 610 metres SSW of Ditsworthy Warren House forming part of Willings Walls Warren, Shan Prior, South Hams			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014469	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Pillow mound 620 metres ESE of Legis Tor forming	g part of Willings W	/alls Warren, Shaugh Prior, South Ha	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014457	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Pillow mound 630 metres east of Legis Tor forming Hams	g part of Willings V	Valls Warren, Shaugh Prior, South	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015742	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Pillow mound 760 metres ENE of Trowlesworthy Warren House, forming part of Trowlesworthy Warren Shaugh Prior, South Hams			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014611	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
	DI I	NEW ENTRY?:	NI-	
PRINCIPAL VULNERABILITY:	Plant growth	INEVV LINTINI:.	No	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Pillow mound 790 metres NNE of Blackaton Cross, forming part of Trowlesworthy Warren, Shaugh Prior South Hams			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014662	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Pillow mound 840 metres north east of Trowlesworthy Warren House, forming part of Trowlesworthy Warren, Shaugh Prior, South Hams			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014658	
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Pillow mound 860 metres NNW of Blackaton Cross, forming part of Trowlesworthy Warren, Shaugh Pric South Hams			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014664	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Pillow mound 860 metres SSE of Trowlesworthy V Shaugh Prior, South Hams	Varren House, forr	ming part of Trowlesworthy Warren,	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014616	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Pillow mound and animal run 830 metres north east of Trowlesworthy Warren House, forming part of Trowlesworthy Warren, Shaugh Prior, South Hams			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014657	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Pound and hut circles north of Hawk's Tor, Shaugh	Prior, South Ham	s	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002516	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Pounds and hut circles north of Saddlesborough, Shaugh Prior, South Hams			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002517	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

SITE NAME:	Rectangular building 420 metres north west of Hei Prior, South Hams	n Tor, forming an o	outlying part of Hentor Farm, Shaugh	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020011	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Round cairn on Lee Moor 950 metres south east o	of Great Trowleswo	orthy Tor, Shaugh Prior, South Ham	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015753	
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Stone hut circle north east of Hentor Brook, Shaugh Prior, South Hams			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012175	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Stone hut circle north of Hentor Brook, Shaugh Prior, South Hams			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012083	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Stone hut circle settlement 600 metres ENE of Gr	eat Trowlesworthy	Tor, Shaugh Prior, South Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018356	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Three pillow mounds and a linear gully 200 metres Trowlesworthy Warren, Shaugh Prior, South Ham	north of Great Tr	owlesworthy Tor forming part of	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014481	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Two pillow mounds 640 metres ENE of Trowlesworthy Warren House forming part of Trowlesworthy Warren, Shaugh Prior, South Hams			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015747	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

SITE NAME:	Two pillow mounds and a small area of tin streams forming part of Willings Walls Warren, Shaugh Pri	work 510 metres so or, South Hams	outh west of Ditsworthy Warren Hous
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014467
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two pillow mounds and a small area of tin stream forming part of Trowlesworthy Warren, Shaugh Pr		70 metres north of Blackaton Cross,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014663
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two round cairns 600 metres ENE of Great Trow	lesworthy Tor, Sha	ugh Prior, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018357
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two stone hut circles and an enclosure 680 metre South Hams	s ENE of Trowlesw	orthy Warren House, Shaugh Prior,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014615
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two stone hut circles north of Spanish Lake, Lee N	Moor, Shaugh Prior,	South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013058
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Unenclosed stone hut circle settlement on the we	stern edge of Lee M	loor, Shaugh Prior, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012116
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Vermin trap 350 metres south west of Great Trov Shaugh Prior, South Hams	vlesworthy Tor for	ming part of Trowlesworthy Warren,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014475
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

TENTINGE / CT TOSK 2013 / 300	THI WEST / BARTHOOK (IVI)		
SITE NAME:	Vermin trap 510 metres WSW of Great Trowlesw Prior, South Hams	orthy Tor forming	part of Trowlesworthy Warren, Shau
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014465
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	Yes
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Vermin trap 520 metres SSW of Trowlesworthy V Shaugh Prior, South Hams	Varren House form	ning part of Trowlesworthy Warren,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014466
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Vermin trap 700 metres ENE of Trowlesworthy V Shaugh Prior, South Hams	Varren House, form	ning part of Trowlesworthy Warren,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014612
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Vermin trap 730 metres ENE of Trowlesworthy W Shaugh Prior, South Hams	Varren House, form	ning part of Trowlesworthy Warren,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014613
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Vermin trap 800 metres south east of Trowleswor Warren, Shaugh Prior, South Hams	thy Warren House	forming part of Trowlesworthy
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014464
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Cist with a retaining kerb north west of Corringdo	on Ball, South Brent	, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010180
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Enclosure and hut circle north of Old Hill, South B	Frent, South Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003200
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	TH WEST / DARTMOOR (NP)	unds of Dele D	Carrela Danasa Carrela Lla
	Enclosure with hut circles and rectangular pens, so	LIST ENTRY NUMBER:	
DESIGNATION:	Scheduled Monument	LIST ENTRY NOPIBER:	1012775
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Enclosure with hut circles north of Bala Brook inta	ike, South Brent, Sc	outh Hams
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1012776
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Enclosure with hut circles north of Bala Brook inta	ike, South Brent, Sc	outh Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012783
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Enclosures and hut circles at Petre's Pits Bottom, S	South Brent, South	Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004557
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Hut circle and fields, Bishop's Mead, South Brent, S	South Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002537
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Hut enclosure north of Old Hill, South Brent, Sout	th Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002664
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	One of several stone hut circles north of Corringo	lon Ball, South Bren	t, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010202
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- C Slow decay; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 D Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial like). use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

HERITAGE AT RISK 2013 / SOU	TH WEST / DARTMOOR (NP)		
SITE NAME:	Riders Rings (The Rings), South Brent, South Hams	5	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002502
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Three enclosed hut groups, Black Tor, Shipley Brid	lge, South Brent, Sc	outh Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002505
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two conjoined huts between two enclosures north	h of Bala Brook inta	ake, South Brent, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012778
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two hut circles on the right bank of Red Brook, So	outh Brent, South F	łams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013035
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Chambered cairn in Cuckoo Ball newtake, Ugboro	ugh, South Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012284
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Enclosure with hut circles north of Scad Brook, Ug	sborough, South Ha	ms
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012485
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Long cairn east of Butterdon Hill, Ugborough, Sout	th Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012247
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696

- C Slow decay; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 D Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial like). use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Multiple stone alignment and associated cairns wes Hams	t of Glasscombe U	pper Plantation, Ugborough, South
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013031
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	One of a number of cairns at Black Pool, Ugborou	gh, South Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012232
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	One of a number of cairns at Black Pool, Ugborou	gh, South Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012285
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Stone alignment and cairn south east of Western B	Beacon, Ugborough	, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017604
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Hembury Castle, West Buckfastleigh, South Hams		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003859
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Medieval farmstead 340 metres south east of Cold	East Cross, Ashbu	rton, Teignbridge
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019604
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Hut circles and fields on Buckland Common, Buckl	and in the Moor, T	eignbridge
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004589
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Four hut circles north of Bush Down, Chagford, Teignbridge				
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1002646		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Cairn 240 metres north of Crownley Parks, Ilsingto	on, Teignbridge			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019588		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No		
OWNER TYPE:	Other not for profit group	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Pound north east of Holwell Tor, Ilsington, Teignbi	ridge			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002530		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Settlement on Smallacombe Rocks, Ilsington, Teignbridge				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002531		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Settlement west of Holwell Tor, Ilsington, Teignbri	dge			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002529		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Medieval strip field system, tinworks, part of a preb Down, Manaton, Teignbridge	nistoric settlement,	a cairn and reave on Challacombe		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021393		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Medieval strip fields, tinworks, prehistoric settleme Down, Manaton, Teignbridge	ents, and a cairn on	the lower western slopes of Hamel		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021394		
	Generally satisfactory but with significant localised	TREND:	Improving		
CONDITION:	problems		,		
CONDITION: PRINCIPAL VULNERABILITY:	problems Plant growth	NEW ENTRY?:	No		

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Three hut circles at north end of Vogwell Down, N	1anaton, Teignbridg	ge		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002595		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Enclosure south west of Hingston Rocks, Moreton	hampstead, Teignbr	ridge		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002496		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No		
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Wooston Castle, Moretonhampstead, Teignbridge				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003822		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No		
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Prehistoric settlement and field system 240 metres east of Challacombe Cross, North Bovey, Teignbridge				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020097		
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Two hut circles north west of Bush Down, North	Bovey, Teignbridge			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003198		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Deserted medieval settlement at Blackaton, 340 m Widecombe in the Moor, Teignbridge	etres and 400 metr	es north east of Lower Blackaton,		
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1021396		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Enclosure and fields north of Yar Tor, Widecombe	in the Moor, Teigr	nbridge		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003292		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696		
OWINER TIFE:	Tivate		Ruth Garrier 0117 773 0070		

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Foale's Arrishes, huts and fields, Blackslade Down,	Widecombe in the	Moor, Teignbridge		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003283		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696		
ITE NAME:	Hut 700 yards (640 metres) north west of Sharp Tor, Widecombe in the Moor, Teignbridge				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003280		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696		
ITE NAME:	Hut circles east of Pritton, Widecombe in the Moo	or, Teignbridge			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004575		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Hut circles east of Southway, Widecombe in the M	loor, Teignbridge			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002621		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696		
ITE NAME:	Hut circles on Bonehill Down, Widecombe in the	Moor, Teignbridge			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002619		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Hut circles on Hedge Down, Widecombe in the M	oor, Teignbridge			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002620		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Hut circles south east of Yar Tor, Widecombe in t	he Moor, Teignbrid	lge		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003291		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
	Private	CONTACT:	Ruth Garner 0117 975 0696		

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Pound at Newbridge, Widecombe in the Moor, Te	eignbridge			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003295		
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Two cairns on Cator Common, Widecombe in the	Moor, Teignbridge	2		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003297		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Yar Tor stone row and adjacent cist, Widecombe	in the Moor, Teignt	oridge		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003288		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Lizwell Bridge, Widecombe in the Moor / Buckland in the Moor, Teignbridge				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003294		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Natural erosion - extensive	NEW ENTRY?:	No		
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Taw River tin blowing mill, 840 metres south of Ta	wcroft, Belstone / S	South Tawton, West Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019228		
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Hut circles west of Higher Shapley, Chagford, Wes	st Devon			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002651		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	A double stone hut circle and enclosure 280 metre	es south of Deadlak	e Foot, Dartmoor Forest, West Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011569		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696		

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Camp 325 yards (300 metres) south east of Arche	rton, Dartmoor Fo	rest, West Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002636		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No		
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Coaxial fields, Prehistoric settlement, two cairns and a stone alignment in Little Stannon Newtake, 900 metres south east of Stannon Tor, Dartmoor Forest, West Devon				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021339		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Hut circle and field system north west of Saddle Br	idge, Dartmoor Fo	rest, West Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002601		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Medieval settlement 470 metres east of Hartyland, Dartmoor Forest, West Devon				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021338		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Prehistoric enclosed settlement 740 metres north	west of Hartland T	or, Dartmoor Forest, West Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021335		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Two irregular aggregate field systems with associat stones and historic fields on Riddon Ridge, Dartmo	ed settlements, par oor Forest, West D	rt of a coaxial field system, boundary evon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018930		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Prestonbury Castle (hillfort), Drewsteignton, West	Devon			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003861		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696		

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Chambered cairn 430 metres south of Buttern, Gi	dleigh, West Devor	1
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021217
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Chambered cairn 830 metres south of Buttern, Gi	dleigh, West Devor	1
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021216
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Part of a coaxial field system, Prehistoric settlemen	nts and cairns on Bu	ittern Hill, Gidleigh, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021215
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Stone hut circle 380 metres north west of North (Creaber, Gidleigh, \	West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021220
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Stone hut circle and field system 580 metres north system on Buttern Hill, Gidleigh, West Devon	west of North Cre	eaber, forming part of a coaxial field
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021219
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two stone hut circles and field system, 590 metres Buttern Hill, Gidleigh, West Devon	s south of Buttern,	forming part of a coaxial field system o
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021218
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Enclosure, two stone hut circles and an alignment Tor, Lands common to the Parishes of Bridestowe	of upright stones 78 and Sourton, Wes	30 metres north west of Little Links t Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007648
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Hut circles and a length of enclosure wall, forming Nodden Gate, Lands common to the Parishes of B	part of a stone hut ridestowe and Soui	circle settlement 600 metres east o ton / Lydford, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008638
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Stone hut circle 530 metres ESE of Nodden Gate for Lydford, West Devon	orming an outlying	part of a stone hut circle settlement
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008639
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Stone hut circle 610 metres ESE of Nodden Gate for Lydford, West Devon	orming an outlying	part of a stone hut circle settlement
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008656
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Four round barrows on Wigford Down, Meavy, W	est Devon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002522
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Greenwell Girt socket stone 600 metres SSW of L	ovaton hamlet, Me	avy, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008929
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Hut circle on Wigford Down, Meavy, West Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002551
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Hut circles south east of Brisworthy, Meavy, West	Devon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004585
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Prehistoric enclosures on Dewerstone Hill, 500 me Devon	etres south east of	Dewerstone Cottage, Meavy, West
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1020241
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round barrow north of Cadworthy Wood, Meavy,	, West Devon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002552
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Settlement on Wigford Down, Meavy, West Devo	n	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002550
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Settlement on Wigford Down south of Durance, N	1eavy, West Devor	١
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002523
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Three hut circles north west of Cadworthy, Meavy	, West Devon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003057
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Three hut circles on south part of Wigford Down,	Meavy, West Deve	on
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002549
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two hut circles south of Catstor Down, Meavy, W	est Devon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002548
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Cairnfield and two stone hut circles 490 metres an Devon	nd 550 metres sout	h west of Cox Tor, Peter Tavy, Wes
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020004
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Coaxial field system and prehistoric settlement 410	0 metres west of C	Cox Tor, Peter Tavy, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020090
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Prehistoric settlement 610 metres south west of C	Cox Tor, Peter Tav	y, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020002
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Stone hut circle and a short length of boundary wall forming part of an unenclosed stone hut circle settlement on the north east slope of Cox Tor, Peter Tavy, West Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011432
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Cairnfield 460 metres south east of Cox Tor, Pete	r Tavy / Whitchurd	ch, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020005
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Agglomerated enclosure with hut circles and later Devon	farmstead at Whitt	tenknowles Rocks, Sheepstor, West
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010650
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Cairn east of Scout Hut, Sheepstor, West Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011993
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

HERITAGE AT RISK 2013 / SOU	th west / dartmoor (np)		
SITE NAME:	Cairn south west of Lower Hartor Tor, Sheepstor	, West Devon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012293
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Cairn with a cist north of Drizzlecombe stone align	nments, Sheepstor,	West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010654
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Cairn with cist north of Gutter Tor, Sheepstor, W	est Devon	
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1012473
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Enclosed stone hut settlement south west of Gutte	er Tor, Sheepstor, \	West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012251
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Enclosure north west of Gutter Tor, Sheepstor, W	est Devon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012032
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Enclosure with hut circles on Eastern Tor, Sheepst	or, West Devon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010652
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Enclosure with hut circles south east of Eastern To	or, Sheepstor, West	Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010651
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

HERITAGE AT RISK 2013 / SOU 	TH WEST / DARTMOOR (NP)		
SITE NAME:	Part of Eylesbarrow Reave, Sheepstor, West Devo	n	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011958
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Part of Eylesbarrow watershed reave, Sheepstor, V	Vest Devon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010669
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Pillow mound 40 metres east of Legis Tor forming	part of Legistor W	arren, Sheepstor, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008715
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Pillow mound 180 metres west of Legis Tor forming	ng part of Legistor \	Warren, Sheepstor, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008714
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Pillow mound 220 metres south west of Legis Tor	forming part of Leg	gistor Warren, Sheepstor, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008713
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Prehistoric enclosed settlement 950 metres north Devon	east of Ditsworthy	Warren House, Sheepstor, West
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021058
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Prehistoric settlement, three round cairns and a po	ost-Medieval rabbit	warren at Legis Tor, Sheepstor, West
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019876
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Round cairn east of Whittenknowles Rocks, 960 m	netres ENE of Gutte	er Tor, Sheepstor, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021052
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Three stone alignments, 15 cairns, a cist, a partially bridge at Drizzle Combe, Sheepstor, West Devon	enclosed stone hu	t circle settlement and a small clapper
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014145
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two enclosures and a length of the Eylesbarrow w Sheepstor, West Devon	ratershed reave 800	metres WSW of Eylesbarrow,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013474
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Unenclosed stone hut settlement south west of G	utter Tor, Sheepsto	or, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012239
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Vermin trap immediately south west of Legis Tor f	orming part of Legi	stor Warren, Sheepstor, West Devo
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008716
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Warren at Sheeps Tor, 520 metres north of Chub	stone Cottage, She	epstor, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021391
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Agglomerate enclosure and 10 stone hut circles 50 Devon	00 metres west of C	Cawsand Beacon, South Tawton, Wes
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010790
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

SITE NAME:	Agglomerate enclosure and 15 stone hut circles 56 Devon	60 metres west of C	Cawsand Beacon, South Tawton, West
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010791
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	An agglomerated enclosed settlement 480 metres	west of Stoneyhurs	t, South Tawton, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017285
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Cairn cemetery and earthwork bank 340 metres son	outh west of Blacka	ton Brook Ford, South Tawton, West
Designation:	Scheduled Monument	LIST ENTRY NUMBER:	1018906
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Cairnfield 760 metres west of Stoneyhurst, South	Tawton, West Dev	on
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017287
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Partially enclosed stone hut circle settlement 650 i Devon	metres south east o	f Tawcroft, South Tawton, West
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015759
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two hut circles east of Foxes Holt, South Tawton,	, West Devon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002599
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	A prehistoric settlement complex, length of reave, Cosdon Hill, South Tawton / Dartmoor Forest, W		d stamping mill on the western slopes
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015760
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

HERITAGE AT RISK 2013 / SOU		O. 1	L W D
SITE NAME:	Stone hut circle 140 metres north west of Higher		_
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018917
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Coaxial field system, associated and later remains a Gidleigh, West Devon	at Throwleigh Com	mon and Kennon Hill, Throwleigh /
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018916
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	A length of the Great Western Reave, a prehistori Walkhampton Common, Walkhampton, West De	c settlement, three von	cairns and two field systems on
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019589
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	An agglomerate enclosure and seven stone hut circ Walkhampton, West Devon	cles 460 metres WS	SW of Raddick Hill summit,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011171
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	An enclosed stone hut circle settlement and later to Tor, Walkhampton, West Devon	tin working earthwo	orks, 540 metres south east of Down
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009088
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	An enclosure, attached stone hut circle and length West Devon	of reave 180 metre	es NNE of Leather Tor, Walkhampto
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011248
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	An enclosure containing one stone hut circle 460 r	metres west of Cro	ss Gate, Walkhampton, West Devor
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009091
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet
- implemented.

 C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	An enclosure, six stone hut circles, a length of reav Leather Tor, Walkhampton, West Devon	ve and several pros	pecting pits 170 metres north east of
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011247
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	An unenclosed stone hut circle settlement, an irregenclosure on the south east slope of Leeden Tor, V	gular aggregate field Walkhampton, We	d system, a length of reave and an st Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008671
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Cairn 550 metres south west of Raddick Hill summ	nit forming part of a	a cairnfield, Walkhampton, West Dev
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007416
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Cairn 560 metres south west of Raddick Hill summ	nit forming part of a	a cairnfield, Walkhampton, West Dev
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007415
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Eight stone hut circles and two enclosures forming Leeden Tor, Walkhampton, West Devon	part of an unenclo	sed settlement 580 metres south of
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008661
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Eleven stone hut circles, a length of boundary wall settlement on the north east slope of Sharpitor, W		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007435
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Enclosed settlement 380 metres south west of Rac	ldick Hill summit, V	Valkhampton, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011173
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Enclosed settlement 400 metres west of Raddick F	Hill summit, Walkha	mpton, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011172
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Enclosure and stone hut circle 320 metres north e settlement, Walkhampton, West Devon	ast of Sharpitor for	ming part of a stone hut circle
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007434
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Enclosure and stone hut circle 700 metres west of	Sharpitor, Walkhar	mpton, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019590
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Four stone hut circles and an enclosure 100 metres north east of Sharpitor summit, Walkhampton, West Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007419
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Medieval settlement on Peek Hill, 240 metres and West Devon	280 metres north e	east of Lowery Tor, Walkhampton,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020237
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Prehistoric coaxial field system and cairns, an histo around Peek Hill, Walkhampton, West Devon	ric enclosure and p	art of RAF Sharpitor, situated on and
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020238
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Round cairn 190 metres east of Cross Gate, Walk	hampton, West De	von
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008652
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	Yes
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 Slow decay; solution agreed but for tyet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial like) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

SITE NAME:	Round cairn 340 metres ESE of Norsworthy Bridge	e, Walkhampton, W	/est Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008651
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round cairn 650 metres WSW of Raddick Hill sun	nmit, Walkhampton	, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007424
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Routrundle Pound, Walkhampton, West Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002494
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Stone alignment, two round cairns and a length of Sharpitor and Leeden Tor, Walkhampton, West D	Walkhampton Com	nmon reave lying in a valley between
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007433
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Stone hut circle 155 metres east of Sharpitor, Wal	khampton, West D	evon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007421
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Stone hut circle 240 metres south of Down Tor, V	Valkhampton, West	t Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008641
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Stone hut circle 315 metres north east of Sharpito Walkhampton, West Devon	r forming part of a	stone hut circle settlement,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007436
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

circle settlement, 7 8 rner 0117 975 0696 circle settlement, 3 8 rner 0117 975 0696 /est Devon
g rner 0117 975 0696 circle settlement, 3 g
rner 0117 975 0696 circle settlement, 3 g
circle settlement, g g unner 0117 975 0696
circle settlement, g g unner 0117 975 0696
3 g rner 0117 975 0696
g rner 0117 975 0696
rner 0117 975 0696
est Devon
7
g
rner 0117 975 0696
d a medieval and post-
)
g
rner 0117 975 0696
k Tor, Hart Tor and Cramber
)
g
rner 0117 975 0696
etres south west of Raddick
5
g

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Two cairns and a boundary bank forming part of a Walkhampton, West Devon	cairnfield 440 metr	es south west of Kaddick Hill summit
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007426
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two stone hut circles 570 metres south west of D	own Tor, Walkham	npton, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019572
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two stone hut circles, a reave, round cairn and she	elter south east of S	Sharpitor, Walkhampton, West Devo
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011167
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Unenclosed stone hut circle settlement 370 metre	s south west of Ro	utrundle, Walkhampton, West Devo
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019565
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Enclosure and stone hut circle 770 metres south o	f Cox Tor, Whitch	urch, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020006
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Eluvial tin streamworks and Prehistoric coaxial field Whitchurch Common, Whitchurch / Peter Tavy / S	d system together v Sampford Spiney, V	vith other archaeological remains on Vest Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020089
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Horrabridge, West Devon		
DESIGNATION:	Conservation Area, 5 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

EAST DEVON



© English Heritage

SITE NAME: Dunkeswell Abbey, Dunkeswell Scheduled Monument and Listed DESIGNATION: Building grade II, 3 LBs CONDITION: Very bad

OCCUPANCY: N/A PRIORITY CATEGORY: A(A)

OWNER TYPE: Charity (heritage)

LIST ENTRY NUMBER: 1009303 and 1098253

Remains of Gatehouse. There is cracking to elevations and failure of mortar pointing. Remains of west range also showing cracking, mortar failure and instability. English Heritage is monitoring both the gatehouse and west range, and have offered a grant to the Trust which owns it.

Contact: Ruth Garner 0117 975 0696

SITE NAME:	Poltimore House, Poltimore
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1098310

C16 country house with later additions. Acquired by a trust with funding from English Heritage and the Local Planning Authority in 1997. Urgent works carried out in 1998 to make the building wind/weathertight. Emergency roof cover erected 2006. A feasibility study was undertaken in 2007 with grant from Architectural Heritage Fund and English Heritage.

Contact: Ruth Garner 0117 975 0696



© English Heritage

SITE NAME:	Stable block at Bishop's Court, Clyst St Mary, Sowton
DESIGNATION:	Listed Building grade I
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Private

Large mid C14 barn with arch-braced base-cruck roof of seven bays, and long early C16 range of stables. The site is unused with a temporary corrugated roof. The owners undertook an English Heritage grant-aided feasibility study into potential uses, completed 2011.

Contact: Ruth Garner 0117 975 0696

Tithe barn at Bishop's Court, Sowton

1333998

DESIGNATION: Listed Building grade I

CONDITION: Very bad

SITE NAME:

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C (C)

OWNER TYPE: Private

LIST ENTRY NUMBER: 1164637 Long early C16 range of stables attached to Bishop's Court Tithe barn. Site is not in use. Included within English Heritage funded feasibility study completed 2011.



© English Heritage

© English Heritage

Congregational Chapel, Jesu Street, Ottery St. Mary SITE NAME: Listed Place of Worship grade II, DESIGNATION: CONDITION: Poor PRIORITY CATEGORY: D (New entry) OWNER TYPE:

1213322

Religious organisation

Former Meeting House with symmetrical brick elevation facing Jesu Street. Large hipped roof on outer slopes, multiple inner roof slopes with valley gutters. Grade II listed Church Rooms across rear of church. Roofs have a variety of slates. Roofs are in poor condition and leaking. Repair Grant for Places of Worship offered December 2012 for repairs to church roof.

Contact: Ruth Garner 0117 975 0696

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

SITE NAME:	Newenham Abbey, Axminster		
DESIGNATION:	Scheduled Monument, 3 LBs	LIST ENTRY NUMBER:	1011671
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Trinity Beacon, Axminster		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017950
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Hawkesdown Camp and associated outwork, Axm	outh	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017775
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 400 metres north east of Common F	arm, Aylesbeare	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017770
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 130 metres south east of St Mary's C	hurch, Bicton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018056
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Bowl barrow 210 metres north east of Starved Oa	k Cross, Brampford	d Speke
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010633
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow in Long Plantation, 610 metres north	east of Starved Oa	k Cross, Brampford Speke
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010636
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow in Long Plantation, 680 metres north	east of Starved Oa	k Cross, Brampford Speke
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010634
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

SITE NAME:	Bowl barrow 320 metres north east of Starved Oa	k Cross, Brampford	d Speke / Upton Pyne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010632
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Prehistoric field system on the cliffs above Littleco	mbe Shoot, Bransco	ombe
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1020710
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Dolbury hillfort, 320 metres north of Killerton Ho	use, Broad Clyst	
DESIGNATION:	Scheduled Monument, RPG grade II*	LIST ENTRY NUMBER:	1017192
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Ice house 210 metres north west of Killerton Hou	se, Broad Clyst	
DESIGNATION:	Scheduled Monument, RPG grade II*	LIST ENTRY NUMBER:	1017191
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Sections of two deer park pales and a deer park po	ond at Killerton Par	k, Broad Clyst
DESIGNATION:	Scheduled Monument, part in RPG grade II*	LIST ENTRY NUMBER:	1017193
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two bowl barrows at Big Wood, 580 metres soutl	h west and 470 met	res south of Moorland Cottage,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017949
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Bowl barrow 320 metres north west of Farway Ca Hill, Farway	stle, forming part o	f a dispersed barrow group on Farwa
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010267
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 D Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial like). use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Bowl barrow 340 metres north west of Farway Hill, Farway	Castle, forming part o	of a dispersed barrow group on Farw
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010268
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round barrow cemetery on Broad Down, Farwa	y / Southleigh	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017642
CONDITION:	Extensive significant problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	Yes
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	A bowl barrow 370 metres WNW of Ring-in-th- Gittisham Hill, Gittisham	e-Mire, forming part o	of a round barrow cemetery on
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014249
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	A bowl barrow 460 metres NNW of Ring-in-the Gittisham Hill, Gittisham	-Mire, forming part o	f a round barrow cemetery on
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014248
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	A bowl barrow 500 metres WNW of Ring-in-th Gittisham Hill, Gittisham	e-Mire, forming part o	of a round barrow cemetery on
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014250
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	A bowl barrow 570 metres NNE of Putts Corne Hill, Gittisham	er, forming part of a re	ound barrow cemetery on Gittisham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014254
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	A cairn 450 metres WNW of Putts Corner, form Gittisham	ning part of a round b	parrow cemetery on Gittisham Hill,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014255
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	A ring cairn and bowl barrow 54 metres NNE of P Gittisham Hill, Gittisham	utts Corner, formil	g part or a round parrow cemetery
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014253
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	A bowl barrow 420 metres NNW of Ring-in-the-N Gittisham Hill, Gittisham / Honiton	lire, forming part o	f a round barrow cemetery on
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014247
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Two bowl barrows, 220 metres ESE of Putts Corn Hill, Gittisham / Sidmouth	er, forming part of	a round barrow cemetery on Gittish
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014251
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Dumpdon Camp, Luppitt		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018851
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Three bowl barrows on Lympstone Common, 500 metres west of Fryingpans, Lympstone		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020014
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Membury Castle, Membury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017951
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Musbury Castle, Musbury / Combpyne Rousdon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016793
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Cursus, long mortuary enclosure, ring ditch and ot Barton, Nether Exe	ther associated crop	omarks 700 metres east of Netherex
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014144
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two bowl barrows north of Green Lane, 430 met	res and 330 metres	west of Rewe Cross, Nether Exe
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016565
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Round barrow cemetery on Venn Ottery Hill, 660 and Harpford	metres south east	of Happy Valley, Newton Poppleforc
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017476
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Belbury Castle, Ottery St. Mary		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017774
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Hembury Fort, Payhembury / Awliscombe		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018850
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Promontory fort on Seaton Down, Seaton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017776
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	The Beacon on Shute Hill, 200 metres north east of	of Rowlands, Shute	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020312
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	A bowl barrow 120 metres south west of Ring- Gittisham Hill, Sidmouth	5, 131 mmg pt	on comocoly on
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014246
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Cross ridge dyke extending north and south of	The Three Horse Sho	es Inn, Southleigh / Branscombe
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017771
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Stockland Great Castle, Stockland		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017952
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 470 metres east of Fortescue, Sto	ke Canon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016564
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Roman villa 300 yards (270 metres) SSW of Ho	lcombe Farm, Uplyme	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002558
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 280 metres NNE of Starved Oak	Cross, Upton Pyne	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010638
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 300 metres SSE of Stevenstone Fa	ırm, Upton Pyne	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015973
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 350 metres NNE of Starved Oak	Cross, Upton Pyne	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010639
CONDITION:	Extensive significant problems	TREND:	Declining
	Arable ploughing	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Arable plougring		110
PRINCIPAL VULNERABILITY: OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

SITE NAME:	Bowl barrow 450 metres SSE of Stevenstone Farm	. Upton Pyne	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015974
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Earthwork enclosure 330 yards (300 metres) south	n west of Three Ho	rse Shoes Inn, Upton Pyne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002645
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two bowl barrows, 350 metres south of Stevensto	one Farm, Upton Py	ne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010631
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 310 metres south of Widworthy Barr	ton, Widworthy	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017475
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Castle Hill, Widworthy		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017477
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Four bowl barrows at Four Firs on Woodbury Co	mmon, Woodbury	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018052
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
	Two bowl barrows on Colaton Raleigh Common,	500 metres north a	nd 780 metres north east of Woodbur
SITE NAME:	Castle, Woodbury		
		LIST ENTRY NUMBER:	1018053
SITE NAME: DESIGNATION: CONDITION:	Castle, Woodbury	LIST ENTRY NUMBER:	1018053 Declining
DESIGNATION:	Castle, Woodbury Scheduled Monument Generally satisfactory but with significant localised		

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

1E11171GE711 11GH 20157 500	THE TEST PERSON DEPONDED CONTRACTOR		
SITE NAME:	Two bowl barrows on Woodbury Common, both	330 metres east of	Four Firs, Woodbury
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018050
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Woodbury Castle, Woodbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003862
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	Yes
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two bowl barrows on Woodbury Common, 640 r Bicton	metres and 625 me	tres east of Four Firs, Woodbury /
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018051
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Albion Street/Windsor Square, Exmouth		
DESIGNATION:	Conservation Area, 17 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Stephen Guy (LPA) 01395 516551
SITE NAME:	Ottery St Mary, Ottery St. Mary		
DESIGNATION:	Conservation Area, 45 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Stephen Guy (LPA) 01395 516551
SITE NAME:	Seaton		
DESIGNATION:	Conservation Area, 9 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating

EXETER



© Roger Brien, Devon and Exeter

SITE NAME:	The Devon and Exeter Institution, 7 The Close, Exeter
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	C (A)
OWNER TYPE:	Charity (non-heritage)

1104062

C15 Cannon's House, leased as town house from 1672. In 1813 the lease was given to the Devon and Exeter Institution who carried out extensive rebuilding. Since 2009 there has been ongoing cracking to plaster ceilings in the two library ceiling roofs. Investigation has led to major structural deficiencies being revealed and ceilings being scaffolded. Structural repair urgently required. English Heritage grant accepted in 2013 for structural repairs.

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site



© English Heritage

© English Heritage

SITE NAME:	Church of St Thomas the Apostle, Cowick Street, Exeter
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	B (New entry)
OWNER TYPE:	Religious organisation

1169954

LIST ENTRY NUMBER:

The church was largely rebuilt in 1657; the west tower, south aisle and east end of the north aisle are C17. The roofs over the chancel and transepts are in very bad condition. Due to poor original design and lack of maintenance over time, the rainwater disposal arrangements have failed, penetrating the parapet walls and entering the church. The structural integrity of the gable wall is at risk. Water entering above north transept and chapel where decorative detail is being damaged. There is widespread failure of the rendered areas. Repair Grant for Places of Worship accepted in 2012.

Contact: Ruth Garner 0117 975 0696



SITE NAME:

Church of St David, St David's Hill, Exeter

DESIGNATION:

Listed Place of Worship grade I, CA

CONDITION:

Poor

PRIORITY CATEGORY:

A (A)

OWNER TYPE:

Religious organisation

LIST ENTRY NUMBER:

1267226

This highly distinctive church is designed by a leading church architect WD Caroe (1897-9) and is in a freely-treated Gothic style. There have been longstanding issues with the west end of the church, which is moving but has been secured with scaffolding to prevent further cracking. English Heritage has given specialist advice.

1267226 Contact: Ruth Garner 0117 975 0696

SITE NAME:	Danes Castle		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1011673
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Alphin Brook, Exeter		
DESIGNATION:	Conservation Area, 16 LBs, 2 SMs	NEW ENTRY?:	No
CONDITION:	Optimal	TREND:	Deteriorating significantly
VULNERABILITY:	Low	CONTACT:	Katharine Metcalfe (LPA) 01392 265227
SITE NAME:	St David's, Exeter		
DESIGNATION:	Conservation Area, 96 LBs, 2 RPGs, part in SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Katharine Metcalfe (LPA) 01392 265227
SITE NAME:	Ca Ciduralla Franca		
	St Sidwells, Exeter		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
CONDITION.	very bad		1 40 significant change

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

EXMOOR (NP)



© English Heritage

SITE NAME:	Christ Church, Parracombe, North Devon
DESIGNATION:	Listed Place of Worship grade CA

CONDITION: Good PRIORITY CATEGORY: F (B)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1169283

Church built 1878 by W Oliver. Roofs are well maintained but areas of weakness are developing and the roof is beginning to need some major work to address this. The tower is also in need of repair, particularly the south and west faces which are exposed to prevailing weather, strong winds and high rainfall. A Repair Grant for Places of Worship has been offered for roof repairs to north aisle, vestry and nave, as well as emergency works to tower. Works began in 2012 and are expected to be completed in 2013.

Contact: Ruth Garner 0117 975 0696

SITE NAME:	Doone's Houses, Brendon, North Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003886
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two round barrows on Cheriton Ridge, Brendon,	North Devon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002583
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Five barrows and an enclosure on Challacombe Co	ommon, Challacoml	be, North Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002634
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round barrow on East Anstey Common, East Ans	tey, North Devon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002569
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Earthwork defences of Countisbury Castle promo	ntory fort, Lynton a	and Lynmouth, North Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020807
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Roborough Castle, Lynton and Lynmouth, North [Devon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003281
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Natural erosion - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

STE NAME Round barrow south east of Down Linhay, Lynton Junnouth, North Devon DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1002545 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Other NEW ENTRYP: No OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME Two round barrows and cairn cemetery, Ikkerton Ridge, Lynton and Lymouth, North Devon DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1002566 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Plant growth NEW ENTRYP: No OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 SITE NAME Two round barrows near Warcombe Water, Lynto-underwill problems UST ENTRY NUMBER: 1003299 CONDITION: Extensive significant problems TREND: Declining CONDITION: Extensive significant problems NEW ENTRYP: No OWNER TYPE: Stock erosion - extensive NEW ENTRYP: No <th>1121417102711110112013700011</th> <th></th> <th></th> <th></th>	1121417102711110112013700011			
CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Other Other Other NEW ENTRYY: No OWNER TYPE: Private Two round barrows and cairn cemetery, Ikkerton Ridge, Lynton and Lynmouth, North Devon DESIGNATION: Scheduled Monument Extensive significant problems PRINCIPAL VULNERABILITY: Plant growth OWNER TYPE: Commercial company Two round barrows near Warcombe Water, Lynton and Lynmouth, North Devon DESIGNATION: Scheduled Monument Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: No OWNER TYPE: Two round barrows near Warcombe Water, Lynton and Lynmouth, North Devon DESIGNATION: Scheduled Monument DESIGNATION: Scheduled Monument Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: No OWNER TYPE: Private Holwell Castle, Parracombe, North Devon DESIGNATION: Scheduled Monument UIST ENTRY NUMBER: 1003299 CONTACT: Ruth Garner 0117 975 0696 SITE NAME Holwell Castle, Parracombe, North Devon DESIGNATION: Scheduled Monument UIST ENTRY NUMBER: 1003872 CONDITION: Declining PRINCIPAL VULNERABILITY: Scheduled Monument UIST ENTRY NUMBER: 1003872 CONDITION: Scheduled Monument DESIGNATION: Scheduled Monument DESIGNATION: Declining PRINCIPAL VULNERABILITY: Declining DESIGNATION: Declining	SITE NAME:	Round barrow south east of Down Linhay, Lynton	and Lynmouth, No	rth Devon
PRINCIPAL VULNERABILITY: Other Private Two round barrows and cairn cemetery, Ikkerton Ridge, Lynton and Lynmouth, North Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: ONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Plant growth NEW ENTRYP: Commercial company CONTACT: Ruth Garner 0117 975 0696 TREND: Designation: Scheduled Monument LIST ENTRY NUMBER: ONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: No CONTACT: Ruth Garner 0117 975 0696 TREND: Declining PRINCIPAL VULNERABILITY: Scheduled Monument LIST ENTRY NUMBER: ONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Stock erosion - extensive NEW ENTRYP: No OWNER TYPE: Private LIST ENTRY NUMBER: ONDITION: Declining PRINCIPAL VULNERABILITY: Stock erosion - extensive NEW ENTRYP: No OWNER TYPE: Private LIST ENTRY NUMBER: ONDITION: Declining Ruth Garner 0117 975 0696	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002545
OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Two round barrows and cairn cemetery, Ikkerton Ridge, Lynton and Lynmouth, North Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002566 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Two round barrows near Warcombe Water, Lynton and Lynmouth, North Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003299 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Stock erosion - extensive NEW ENTRY!: No OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Holwell Castle, Parracombe, North Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003872 CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1003872 CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1003872	CONDITION:	Extensive significant problems	TREND:	Declining
SITE NAME: Two round barrows and cairn cemetery, Ikkerton Ridge, Lynton and Lymouth, North Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002566 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Plant growth New ENTRY?: No OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Two round barrows near Warcombe Water, Lynton and Lynmouth, North Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003299 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Stock erosion - extensive New ENTRY?: No OWNER TYPE: Holwell Castle, Parracombe, North Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003872 SITE NAME: Holwell Castle, Parracombe, North Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003872 CONDITION: Generally satisfactory but with significant localised TREND: Declining	PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002566 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Two round barrows near Warcombe Water, Lynton and Lynmouth, North Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003299 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Stock erosion - extensive NEW ENTRY?: No OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Holwell Castle, Parracombe, North Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003872 CONDITION: Generally satisfactory but with significant localised TREND: Declining	OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Plant growth OWNER TYPE: Commercial company Two round barrows near Warcombe Water, Lynton and Lynmouth, North Devon DESIGNATION: Scheduled Monument CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Stock erosion - extensive OWNER TYPE: No OWNER TYPE: No Besignation: Contact: Ruth Garner 0117 975 0696 SITE NAME: New ENTRY: No OWNER TYPE: Ruth Garner 0117 975 0696 SITE NAME: Holwell Castle, Parracombe, North Devon DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1003872 CONDITION: Scheduled Monument UST ENTRY NUMBER: 1003872 CONDITION: Declining	SITE NAME:	Two round barrows and cairn cemetery, Ikkerton	Ridge, Lynton and L	ynmouth, North Devon
PRINCIPAL VULNERABILITY: Plant growth	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002566
OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Two round barrows near Warcombe Water, Lynton and Lynmouth, North Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003299 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Stock erosion - extensive OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Holwell Castle, Parracombe, North Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003872 CONDITION: Declining	CONDITION:	Extensive significant problems	TREND:	Declining
SITE NAME: Two round barrows near Warcombe Water, Lynton and Lynmouth, North Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003299 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Stock erosion - extensive NEW ENTRY?: No OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Holwell Castle, Parracombe, North Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003872 CONDITION: Generally satisfactory but with significant localised TREND: Declining	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003299 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Stock erosion - extensive NEW ENTRYP: NO OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Holwell Castle, Parracombe, North Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003872 Generally satisfactory but with significant localised TREND: Declining	OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Stock erosion - extensive NEW ENTRYP: No OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Holwell Castle, Parracombe, North Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003872 CONDITION: TREND: Declining	SITE NAME:	Two round barrows near Warcombe Water, Lynto	on and Lynmouth, N	North Devon
PRINCIPAL VULNERABILITY: Stock erosion - extensive NEW ENTRYP: No OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Holwell Castle, Parracombe, North Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: LONDITION: Generally satisfactory but with significant localised TREND: Declining	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003299
OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Holwell Castle, Parracombe, North Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003872 CONDITION: Generally satisfactory but with significant localised TREND: Declining	CONDITION:	Extensive significant problems	TREND:	Declining
SITE NAME: Holwell Castle, Parracombe, North Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003872 CONDITION: Generally satisfactory but with significant localised TREND: Declining	PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003872 CONDITION: Generally satisfactory but with significant localised TREND: Declining	OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
Generally satisfactory but with significant localised TREND: Declining	SITE NAME:	Holwell Castle, Parracombe, North Devon		
	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003872
	CONDITION:		TREND:	Declining
PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: Yes	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	Yes
OWNER TYPE: Dejugge CONTACT: Duth Corner 0.1.17 975 0404	OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

MID DEVON



© Mid Devon District Council

SITE NAME:	The Walronds, 6, Fore Street, Cullompton
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Charity (heritage)

LIST ENTRY NUMBER: 1105902 Contact: Ruth Garner 0117 975 0696

began in 2012.



© English Heritage

SITE NAME: Prescott Baptist Chapel, Culmstock DESIGNATION: Listed Building grade II* CONDITION: Poor OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C (New entry) OWNER TYPE: Private LIST ENTRY NUMBER: 1147714		
CONDITION: Poor OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C (New entry) OWNER TYPE: Private	SITE NAME:	
OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C (New entry) OWNER TYPE: Private	DESIGNATION:	Listed Building grade II*
PRIORITY CATEGORY: C (New entry) OWNER TYPE: Private	CONDITION:	Poor
OWNER TYPE: Private	OCCUPANCY:	Part occupied/part in use
Tirrace	PRIORITY CATEO	GORY: C (New entry)
LIST ENTRY NUMBER: 477 4	OWNER TYPE:	Private
	LIST ENTRY NUM	1BER: 477 4

This simple, unspoilt C18 church is in an isolated rural location with two other Baptist Churches within a five mile radius and closer to centres of population. Its physical problems are putting historic fabric at risk in respect of windows and could rapidly escalate into more serious repair problems if not remedied. The Chapel has been sold, and is no longer in use as a place of worship.

A large early C17 mansion in the centre of Cullompton. The owner, Cullompton Walronds Preservation Trust, has obtained Stage 1 Heritage Lottery Fund funding. Grant aid for project development and repair work has been provided by English Heritage and the Local Authority. Emergency repairs have been undertaken. Full repair works

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site



SITE NAME:	Church of St Mary, Woolfardisworthy
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Very bad
PRIORITY CATEGORY:	B (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1251331

The tower stonework is cracked for the full height of the wall through to the top of the parapet on the east and west walls, and is displaced from the plane of the tower walls. This condition has been watched by a structural engineer for the last 2 years and it appears to be worsening. Concrete ring beams and a concrete roof slab indicate structural problems have been addressed before. Analysis of the structural failure and partial rebuilding of the corner of the tower are required. Repair Grant for Places of Worship offered in 2012.

Contact: Ruth Garner 0117 975 0696

© Eng	lish	He	ritage
-------	------	----	--------

SITE NAME:	Roman fort 300 metres north east of Cudmore Fa	arm, Bampton / Clay	hanger
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011251
CONDITION:	Unknown	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 80 metres south west of Hampson 0	Cottage, Bow	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016189
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 140 metres south east of Burston C	ross, Bow	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015471
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 220 metres south west of Hampson	Cottage, Bow	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015474
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Ring ditch 150 metres north of Natson Farm, Bow	V	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015477
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two bowl barrows 180 metres south west of Har	npson Cottage, Bov	v
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015475
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 - Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Two bowl barrows 250 metres north of Natson Fa	arm. Bow	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015476
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Canonsleigh Abbey, Burlescombe		
DESIGNATION:	Scheduled Monument, LB grade II, CA	LIST ENTRY NUMBER:	1003830
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Copplestone Cross, Copplestone		
DESIGNATION:	Scheduled Monument, LB grade I	LIST ENTRY NUMBER:	1013728
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Posbury camp, Castle Down, Crediton Hamlets		
Designation:	Scheduled Monument	LIST ENTRY NUMBER:	1003826
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Romano-British villa, Downes, near Crediton, Cred	diton Hamlets	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002668
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two Roman forts and two Roman camps at St And	drew's Hill, Cullomp	oton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019543
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Raddon Hill: a Neolithic causewayed enclosure and	l later hillfort, Shob	rooke / Stockleigh Pomeroy
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016259
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Three bowl barrows 250 metres south east of Gib	bet Moor Cross, To	empleton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017134
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

SITE NAME:	Bowl barrow 260 metres north west of Pu	tson Cross, Tiverton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017132
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Eggesford Castle, 640 metres north east of	Eggesford House, Wembw	orthy
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016208
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 130 metres north east of Bur	ston Cross, Zeal Monacho	rum
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015152
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bow		
DESIGNATION:	Conservation Area, 20 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Sue Warren (LPA) 01884 234264
SITE NAME:	Cullompton		
Designation:	Conservation Area, 46 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Sue Warren (LPA) 01884 234264
SITE NAME:	Tiverton		
DESIGNATION:	Conservation Area, 194 LBs, 2 SMs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Sue Warren (LPA) 01884 234264

NORTH DEVON



(C)	Fnglish	Heritage	Archive

SITE NAME:	Hall House, Bishop's Tawton
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1107730

Built circa 1846-50 by Philip Hardwick, with a rear range by RD Gould. The house lies within an estate containing several other listed structures within the vicinity. The main range is generally fair, but the rear range is in very poor condition, though the roof is now weathertight.

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 - Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site



SITE NAME:	Broomham Farmhouse, King's Nympton
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

Early C16 longhouse with later additions. The roof has been re-thatched with English Heritage grant aid.
Improvements have permitted the family to return to the house, but further structural work is still required.

© English Heritage Archive

LIST ENTRY NUMBER: 1152877

Contact: Ruth Garner 0117 975 0696

SITE NAME:	Barnstaple Castle, Barnstaple		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1020922
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	Yes
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two bowl barrows 170 metres west and 200 metround barrow cemetery on Berry Down, Berrynar		erry Down Cross, forming part of a
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019261
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round barrow cemetery 210 metres south west o	f Hillcrest, Centery	Lane, Bittadon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019252
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Three bowl barrows 170 metres and 270 metres east of Friendship Farm, Bratton Fleming		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017130
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 280 metres north east of Beacon Mo Chulmleigh	oor Cross, forming p	part of a round barrow cemetery,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015153
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 330 metres east of Beacon Moor Cro	oss, forming part of	a round barrow cemetery, Chulmleigh
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015154
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument LPA NP RPG SM UA Unitary Authority
WHS World Heritage Site

HERITAGE AT RISK 2013 / SOU	ITH WEST / NORTH DEVON		
SITE NAME:	Camp in East Kidland Wood, Knowstone		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004588
CONDITION:	Unknown	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Four bowl barrows 560 metres south east of New	Moor Cross, Knov	vstone / Molland
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017135
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Castle Roborough, Loxhore		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002543
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 320 metres east of New Moor Cros	s, Molland	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017136
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two bowl barrows 150 metres and 220 metres so	outh west of Rews C	Cross, North Molton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019255
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	No known threat	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Hillfort 400 metres north west of Woodhouse, Q	ueen's Nympton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015463
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two bowl barrows 100 metres east of Catkill Cro	ss, Rose Ash	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015145
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Camp south of Birch Ham Wood, Stoke Rivers		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002533
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 300 metres north west of Witherid	ge Moor Cross (wes	t), Witheridge
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016652
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 610 metres south east of Elworthy Cross, Witheridge		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016651
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
	117		
SITE NAME:	Ilfracombe		
SITE NAME: DESIGNATION:	Ilfracombe Conservation Area, 117 LBs	NEW ENTRY?:	No
		NEW ENTRY?: TREND:	No Deteriorating

SOUTH HAMS

SITE NAME:	Deer Park wall at Berry Pomeroy Castle, Berry Pomeroy
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1108572

Medieval deer park wall, extended in the C16. Neglected, heavily overgrown with ivy and partially collapsed in places, particularly in the woods where it has no use as a boundary. The Estate has prepared a condition survey in order to understand and monitor mechanisms of decay and to prioritise repairs, some of which have qualified for funding from Natural England.

Contact: Ruth Garner 0117 975 0696



© South Hams District Council

SITE NAME:	Warleigh House, Tamerton Foliot, Bickleigh
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Commercial company

1162274

Medieval site. The present C16 house incorporates late medieval roof structures and was remodelled in the mid C18 and again, importantly, by John Foulston of Plymouth from 1825-31. For sale. Urgent Works Notice outstanding and conditional Listed Building Consent agreed for reinstatement of significant features.

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site



© South Hams District Council

SITE NAME:	Yarde Farmhouse, Malborough
DESIGNATION:	Listed Building grade I
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private

1108479

Late C16 evolved manor house. The house, its detached kitchen and also the early C18 chamber block are now wind and weathertight externally. The greatest area of uncertainty remains the interior of the lodging range and the important painted hangings whose conservation and future display are not resolved.

Contact: Ruth Garner 0117 975 0696

-97
The state of the s
Control of the Contro
Section 1997 (1997) The Principle of the

SITE NAME: Pridhamsleigh Farmhouse, Ashburton, Staverton DESIGNATION: Listed Building grade II* CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: F (B) OWNER TYPE: Private

C16 and C17 Farmhouse. Subdivided into Pridhamsleigh Manor and Pridhamsleigh Farmhouse. Farmhouse only is at risk. Part of the Farmhouse suffered collapse. At risk from exposure and neglect. Listed Building Consent granted for repairs and works were advanced 2013.

© English Heritage

LIST ENTRY NUMBER: 1147332

LIST ENTRY NUMBER

Contact: Ruth Garner 0117 975 0696

Contact: Ruth Garner 0117 975 0696



SITE NAME: 39, The High Street, Totnes DESIGNATION: Listed Building grade II* CONDITION: Poor OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C(C)OWNER TYPE: Private LIST ENTRY NUMBER: 1236133

Fine C17 plasterwork and interior threatened by poor condition of roof and opening up of floor on the second floor. Ground floor is a shop. Upper floors are unoccupied and in need of repair and new services.

© English Heritage Archive



SITE NAME:	Garden wall, steps and gatepiers south of Langdon Court Hotel, Langdon, Wembury
DESIGNATION:	Listed Building grade II*, RPG grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)

Late C17 to early C18 formal terraced garden, the layout little altered since the early C18. Terraces extend south from the house on rising ground, with central axial path and connecting steps. Enclosed by walls to the east, south and west. The northern (larger) terrace has C17 gate piers and gates in the east and west walls and a central pool. The present owner has instigated a programme of repair.

OWNER TYPE: Private LIST ENTRY NUMBER: 1169143

Contact: Ruth Garner 0117 975 0696



© South Hams District Council

SITE NAME:	Pair of garden houses south of Langdon Court Hotel, Langdon, Wembury
DESIGNATION:	Listed Building grade II*, RPG grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

Early C18 gazebos standing at the junction of the northern and southern terraces in the late C17 to early C18 formal terraced garden to the south of the house. The walls, steps and gate piers of the terraced garden are also at risk. Recently reroofed but derelict. In 2012-13 negotiations were underway to restore them as annexes to the hotel.

Contact: Ruth Garner 0117 975 0696 LIST ENTRY NUMBER: 1108587

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



SITE NAME:	Watch House battery and ditch, Wembury
DESIGNATION:	Scheduled Monument
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Government or agency

Constructed 1904 but utilising an 1860s ditch system, with First and Second World War additions. The site was leased to a private company until 2009, and since then has been vacant and subject to vandalism. Recording has been put in hand but no options for repair/reuse have been agreed.

© English Heritage

LIST ENTRY NUMBER: 1002585

Contact: Ruth Garner 0117 975 0696

SITE NAME:	Hilltop enclosure known as Maristow Camp, 240 n	netres east of Midd	le Park House, Bickleigh
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1019784
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Long barrow and two bowl barrows, 200 metres s	outh east of Chape	lcombe, Bigbury
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019239
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Iron Age hillfort known as Wasteberry Camp, med north west of Lyneham House, Brixton / Yealmpto		post-medieval warren, 800 metres
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1020160
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two round barrows on Ridding Down, Cornwood		
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1002586
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Levelling	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Deer park north and north west of Dartington Hal	l, Dartington	
DESIGNATION:	Scheduled Monument, 2 LBs, part in RPG grade II*	LIST ENTRY NUMBER:	1020870
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Hilltop enclosure and woodbanks in Chacegrove V Dartington	Vood, 540 metres r	north west of Dartington Hall,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020553
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site

HERITAGE AT RISK 2013 / SOU		NDA(- (OL L D	Farm David	
SITE NAME:	Hilltop enclosures in North Wood, 780 metres NI		•	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020381	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Four bowl barrows at Bickleigh Brake 540 metres barrow cemetery, Halwell and Moreleigh	Four bowl barrows at Bickleigh Brake 540 metres south west of Bickleigh, forming part of a linear round barrow cemetery, Halwell and Moreleigh		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019238	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Hillfort and two bowl barrows at Halwell Camp, H	lalwell and Moreleig	gh	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019237	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Medieval churchyard cross, 6 metres south east of	the porch of St An	drew's Church, Harberton	
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1019234	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow 470 metres south of Borough Farm,	Holbeton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019316	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Three bowl barrows 140 metres west of Borough	Farm, Holbeton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019317	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	D-Day landing craft maintenance site on the River Kingswear	Dart immediately t	o the south of Lower Noss Point,	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021076	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed but F not yet implemented.

 Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Gomerock Tower, Kingswear		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003852
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Field systems, hut circles and four beacons, 510 me	etres south of Midd	le Soar, Malborough
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020574
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Hilltop enclosure 380 metres east of Middle Soar,	Malborough	
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1019533
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Medieval farmstead, boundary work and earthwork Malborough	c enclosures 350 m	etres south east of Middle Soar,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020575
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two hut circles and associated field systems and er	nclosure at Mouseh	ill Brake, Malborough
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020573
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Coaxial field system, hut circles and medieval farm	buildings at Stareho	ole Bottom, Malborough / Salcombe
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020577
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two bowl barrows at Beacon Hill, 120 metres sou	th of The Beacon, I	Marldon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020164
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Digging	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Iron Age promontory fort known as Oldaport Cam	p, Modbury	
DESIGNATION:	Scheduled Monument, part in RPG grade II	LIST ENTRY NUMBER:	1020234
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Fort Charles, Salcombe		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1020165
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Deer park and rabbit warren at Newnham Park, Spa	rkwell	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020169
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Hut circle 1000 yards (915 metres) east of Coleland	Bridge, Sparkwell	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002596
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Post-medieval deer park, medieval fishpond, and a I Boringdon Park, Sparkwell	9th century lead n	nine, ore works and smelt mill at
DESIGNATION:	Scheduled Monument and Listed Building grade II*, 2 LBs	LIST ENTRY NUMBER:	1020565 and 1386330
CONDITION:	Extensive significant problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Barrow cemetery on western slope of Crownhill Do	own, Sparkwell / S	haugh Prior
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003201
CONDITION:	Unknown	TREND:	Declining
PRINCIPAL VULNERABILITY:	Dumping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Woodbury Camp, Stoke Fleming		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019783
CONDITION:	Extensive significant problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Hillfort known as Slapton Castle, Stokenham			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019236	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Roman settlement site at Bantham Ham, Thurlestone			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019322	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Visitor erosion - moderate	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Hilltop enclosure at Yellowberries Copse, 430 met	res west of Higher	Turtley, Ugborough	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019325	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Fort Bovisand, Wembury			
DESIGNATION:	Scheduled Monument, 2 LBs	LIST ENTRY NUMBER:	1002584	
	,		1002307	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown	
CONDITION: PRINCIPAL VULNERABILITY:	Generally satisfactory but with significant localised	TREND: NEW ENTRY?:		
	Generally satisfactory but with significant localised problems		Unknown	
PRINCIPAL VULNERABILITY:	Generally satisfactory but with significant localised problems Development requiring planning permission	NEW ENTRY?: CONTACT:	Unknown No Ruth Garner 0117 975 0696	
PRINCIPAL VULNERABILITY: OWNER TYPE:	Generally satisfactory but with significant localised problems Development requiring planning permission Government or agency	NEW ENTRY?: CONTACT:	Unknown No Ruth Garner 0117 975 0696	
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Generally satisfactory but with significant localised problems Development requiring planning permission Government or agency World War II Heavy Anti-aircraft gunsite, 100 met	NEW ENTRY?: CONTACT: res west of Princes	Unknown No Ruth Garner 0117 975 0696 Cottages, Wembury	
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Generally satisfactory but with significant localised problems Development requiring planning permission Government or agency World War II Heavy Anti-aircraft gunsite, 100 metals Scheduled Monument Generally satisfactory but with significant localised	NEW ENTRY?: CONTACT: res west of Princes LIST ENTRY NUMBER:	Unknown No Ruth Garner 0117 975 0696 Cottages, Wembury 1021147	

TEIGNBRIDGE



© Teignbridge District Council

SITE NAME:	Former stables to Stover House, Stover, Kingsteignton
DESIGNATION:	Listed Building grade II*, RPG grade II
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1308968

Built as stables, 1779. The stables were stripped out when they were superseded by a new larger stable block in 1843 and converted to a magnificent backdrop to newly laid out gardens for the 11th Duke of Somerset. It is a key feature of the Stover's grade II designed landscape. Now in very bad condition due to spread and distortion of single ashlar front, rusting cramps, and water and vegetation damage. Fenced off.

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 - Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site



© English Heritage Archive

SITE NAME:	The Belvedere, Powderham
DESIGNATION:	Listed Building grade II*, RPG grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1306164

Gothick Belvedere, 1771-1774, situated 600 metres north west of Powderham Castle on the north east fringe of Powderham Old Plantation within the C18 park. Damaged by fire after the war and now a roofless shell. English Heritage grant has been offered towards repairs and a first phase of repairs has been completed. With no prospect of a further phase being funded in the immediate future, the building remains at risk.

Contact: Ruth Garner 0117 975 0696



	SITE NAME:	Church of St Thomas a Becket, Bridford
ı	DESIGNATION:	Listed Place of Worship grade I
	CONDITION:	Poor
ı	PRIORITY CATEGORY:	D (New entry)
	OWNER TYPE:	Religious organisation
	IST ENTRY NUMBER	1097825

A medieval granite church in an exposed location, on the southern fringe of Dartmoor National Park. The pointing on the tower is failing and falling, and this is allowing water ingress into the fabric, while rainwater disposal is inadequate. A Repair Grant for Places of Worship was offered in 2012.

Contact: Ruth Garner 0117 975 0696



© English Heritage

© English Heritage

SITE NAME:	St Michael the Archangel, Den Promenade, Teignmouth
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation

1269103

LIST ENTRY NUMBER:

Multi-phase Norman style church. A Repair Grant for Places of Worship was offered in 2010 for project development work to address the issue with the valley gutters, which have been leaking for several years. The project development work was completed in 2012. Repair works to the valley gutters and associated works are ongoing.

Contact: Ruth Garner 0117 975 0696

SITE NAME:	Earthwork (possibly civil war) on Bovey Heath, Bo	vey Tracey	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002657
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bishop's Palace, Chudleigh		
DESIGNATION:	Scheduled Monument, LB grade II*	LIST ENTRY NUMBER:	1008679
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Cow Cave, Chudleigh Rocks, Chudleigh		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010726
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 F. Lindon repair on in fair to good.

 F. Lindon repair on in fair to good.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

CA ory is LB wise LPA NP RPG SM

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Milber Down ca	mp, Coffinswell / Haccombe with (Combe		
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1003178	
CONDITION:	Generally satisfa problems	ctory but with significant localised	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple	owners	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Earthwork enclo	osure south of Blackall's Copse, Ex	minster		
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1004579	
CONDITION:	Generally unsatis	sfactory with major localised	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable clipping		NEW ENTRY?:	No	
OWNER TYPE:	Private		CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Linear round ba	rrow cemetery at Castle Park, Alp	hington, Exminster		
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1012347	
CONDITION:	Extensive signific	ant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No	
OWNER TYPE:	Private		CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Cotley Castle, H	Cotley Castle, Holcombe Burnell / Dunsford			
DESIGNATION:	Scheduled Monu	Scheduled Monument		1003180	
CONDITION:	Generally unsatis	Generally unsatisfactory with major localised problems		Improving	
PRINCIPAL VULNERABILITY:	Forestry	Forestry		No	
OWNER TYPE:	Mixed, multiple	Mixed, multiple owners		Ruth Garner 0117 975 0696	
SITE NAME:	Kingskerswell M	anor House, Kingskerswell			
DESIGNATION:	Scheduled Monu	ment, LB grade II, CA	LIST ENTRY NUMBER:	1020875	
CONDITION:	Extensive signific	ant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Collapse		NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple	owners	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Prehistoric field	system and settlements on Kerswe	ell Down and Whilb	porough Common, Kingskerswell	
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1021377	
CONDITION:	Extensive signific	ant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree grow	rth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple	Mixed, multiple owners		Ruth Garner 0117 975 0696	
	SITE NAME:	Oxton House, Kenton		he picturesque grounds comprised lawns, peries, parkland and a lake. In the C20, th	
	DESIGNATION:	Registered Park and Garden grade II, 7 LBs	property was occinto apartments.	cupied by a school before being divided The pleasure grounds are neglected and	
	CONDITION:	Generally satisfactory but with significant localised problems	much of the park parkland planting	is ploughed, with considerable loss of	
	VULNERABILITY:	Medium			
	TREND:	Declining			
	NEW ENTRY?:	No			
	OWNER TYPE:	Private, multiple owners			
	LIST ENTRY NUMBER:	1001269	Contact: Ruth G	arner 0117 975 0696	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Mamhead Park, Mamhead / Kenton
DESIGNATION:	Registered Park and Garden grade II*, 17 LBs
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	High
TREND:	Unknown
NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners
LIST ENTRY NUMBER:	1000555

Mamhead contains the remnants of a 'Capability' Brown park overlooking the Exe estuary. Extensive loss of parkland trees, inappropriate land management and subdivision with new boundaries. Historic mixed plantations now largely converted to conifer. Main house currently (June 2013) on the market.

Contact: Ruth Garner 0117 975 0696



© English Heritage

Stover Park, Teigngrace
Registered Park and Garden grade II, 7 LBs
Generally unsatisfactory with major localised problems
High
Stable
No
Mixed, multiple owners

1001268

LIST ENTRY NUMBER:

Formerly a seat of the dukes of Somerset. Late C18 gardens, pleasure grounds and park. Now in divided ownership. Large area of the park now run by the County Council as a country park, another part is an actively worked quarry and the remainder is in use by a school. Setting also under threat with pressure for hotel, retail, residential and industrial development associated with A38 trunk road. English Heritage and Natural England are currently exploring opportunities through Environmental Stewardship for more informed management of the park.

Contact: Ruth Garner 0117 975 0696

SITE NAME:	Bovey Tracey, Pottery Road, Bovey Tracey		
DESIGNATION:	Conservation Area, SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Maureen Pearce (LPA) 01626 215705
SITE NAME:	Chudleigh		
SITE NAME: DESIGNATION:	Chudleigh Conservation Area, 37 LBs	NEW ENTRY?:	No
		NEW ENTRY?: TREND:	No No significant change
DESIGNATION:	Conservation Area, 37 LBs		

TORRIDGE



© English Heritage

SITE NAME:	Richmond Dock, Appledore	
DESIGNATION:	Listed Building grade II*	
CONDITION:	Fair	
OCCUPANCY:	Occupied/in use	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1140140	

Dry dock, 1856. It is said to be the largest dry dock in the Bristol Channel at the time it was built. Now re-occupied and in use. The condition of the gates remains critical.

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



© English Heritage

SITE NAME:	Winsford Hospital, Halwill Junction, Halwill
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Charity (heritage)

1105657

LIST ENTRY NUMBER:

Winsford centre built as a cottage hospital in 1899, designed by Charles Voysey and founded by a local landowner. The NHS closed the hospital in 1998 when it was bought by the Winsford Trust. Since then, it has been run as a day centre and community resource. English Heritage grant aid led to the production of a Conservation Management Plan, options appraisal and a costed condition survey in 2012.

Contact: Ruth Garner 0117 975 0696



SITE NAME: Church of St Mary, High Bickington DESIGNATION: Listed Place of Worship grade I CONDITION: Poor PRIORITY CATEGORY: B (New entry) OWNER TYPE: Religious organisation

A church of Norman origins, but with later alterations. The tower is in a very bad condition, suffering from water ingress and falling masonry. A Repair Grant for Places of Worship was offered in late 2012 and project development work is underway.

LIST ENTRY NUMBER: 1326598 Contact: Ruth Garner 0117 975 0696

(2)	Fnglish	Heri	tage

SITE NAME:	Iron Age enclosure and Roman marching	camp, Alverdiscott	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004558
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 250 metres north east of O	ak Cottage, forming part of	a round barrow cemetery, Ashwate
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020079
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 540 metres south east of Sandymoor Cross, forming part of a round barrow cemetery, Ashwater		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020080
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 770 metres south east of Sa Ashwater	andymoor Cross, forming par	rt of a round barrow cemetery,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020081
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Hillfort known as Castle Hill Settlement,	Hillfort known as Castle Hill Settlement, 350 metres south of Woolleigh Bridge, Beaford	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021417
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP Registered Park and Garden Scheduled Monument RPG UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Hallsannery limekiln, Bideford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004578
ONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 420 metres north west of Dural Cro	ss, Bradworthy	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016643
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 280 metres south west of Upcott Cr	oss, Broadwoodwi	dger
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019546
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Thorn Barrow 520 metres south east of Coop, in Highermoor Plantations, Broadwoodwidger		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017144
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 130 metres north of Wrangworthy C Brewer	Cross, forming part	of a round barrow cemetery, Bucklan
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018527
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Three bowl barrows 250 metres west of Bower, B	ulkworthy	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020340
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Two bowl barrows 690 metres and 760 metres so	uth west of Lewort	chy, Clawton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017974
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

HERITAGE AT RISK 2013 / SOUT			
SITE NAME:	Clovelly Dykes hillfort, Clovelly		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018522
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Holy well and butterwell 120 metres west of Holiv	vell, Clovelly	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018521
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Four bowl barrows 110 metres and 360 metres we cemetery, East Putford	est of Wrangworth	y Cross forming part of a round barro
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018526
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Three fishponds at Winslade, East Putford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017979
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two bowl barrows 600 metres and 750 metres we cemetery, East Putford	est of Wrangworth	y cross forming part of a round barrov
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018515
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two bowl barrows one immediately north and one part of a round barrow cemetery, East Putford	e 100 metres south	of Commonmoor Cottage forming
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018516
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Rothern Bridge, Frithelstock / Great Torrington		
DESIGNATION:	Scheduled Monument, 2 LBs	LIST ENTRY NUMBER:	1020702
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

HERITAGE AT RISK 2013 / SOU	TH WEST / TORRIDGE		
SITE NAME:	Round barrow on south east of Darracott Moor, G	Great Torrington	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012444
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Hender Barrow, Halwill		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019727
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Bowl barrow 300 metres south east of Gorvin, Ha	rtland	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016645
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 520 metres west of Higher Welsford	l, Hartland	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017138
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 580 metres north west of Gorvin, H	artland	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016648
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	St Clare's Well, Philham, Hartland		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003844
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two bowl barrows 400 metres north west of Gor	vin, Hartland	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016647
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow on Ugworthy Moor 510 metres sout	h of West Ugworth	ny House, Holsworthy Hamlets
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017977
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Berry Castle hillfort in Huntshaw Wood, Huntshaw	W	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016225
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
WNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
TE NAME:	Bowl barrow 60 metres west of St James's Church	, Luffincott	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020476
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Cairn 20 metres east of Tibbett's Lookout, Lundy		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016015
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Chapel remains, cemetery and prehistoric settlement on Beacon Hill, Lundy		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016040
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Granite quarry on East Sidelands, Lundy		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016041
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Hut circle and small enclosure 270 metres north w	vest of The Old Lig	hthouse, Lundy
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016014
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Long house and enclosure 160 metres north of W	idow's Tenement, I	_undy
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018547
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Quarry infirmary and surgery, 220 metres north w	est of Quarterwall	Cottages, Lundy
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016026
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Ruined cottages and well 190 metres north west o	f Quarterwall Cott	ages, Lundy
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016027
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Standing stone 100 metres north east of The Old l	Lighthouse, Lundy	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015928
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	The Widow's Tenement medieval settlement and prehistoric settlement sites, Lundy		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017646
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Moated site at Grange Farm, Merton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017867
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Cross ridge dyke on Godborough Castle earthwor	k north west of Tu	rner's Wood, Northam
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002640
CONDITION:	Unknown	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Northcott Wood camp, Northcott / St. Giles on the	he Heath	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003863
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Bowl barrow 685 metres NNE of Moorfield, Shebl	oear / Peters Marlar	nd
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017963
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Beacon on Belland Moor 770 metres north east of	Belland, Tetcott	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020609
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bideford		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Sarah Chappell (LPA) 01237 428742
SITE NAME:	Northam		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Sarah Chappell (LPA) 01237 428742

WEST DEVON



SITE NAME: Gawton Mine complex, Gulworthy / Bere Ferrers DESIGNATION: Scheduled Monument, WHS CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: A (A) Private

Former copper and arsenic mine and processing complex comprising a full range of buildings from cooperage to engine houses. Structures are at risk from a lack of maintenance.

© English Heritage

OWNER TYPE: LIST ENTRY NUMBER: 1002667

SITE NAME:

Contact: Ruth Garner 0117 975 0696

Contact: Ruth Garner 0117 975 0696



DESIGNATION: Listed Building grade I CONDITION: Poor OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C (C) OWNER TYPE: Private LIST ENTRY NUMBER: 1318194		
OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C (C) OWNER TYPE: Private	DESIGNATION:	Listed Building grade I
PRIORITY CATEGORY: C (C) OWNER TYPE: Private	CONDITION:	Poor
OWNER TYPE: Private	OCCUPANCY:	Part occupied/part in use
1111466	PRIORITY CATEGORY:	C (C)
LIST ENTRY NUMBER: 3 8 94	OWNER TYPE:	Private
	LIST ENTRY NUMBER:	1318194

Kelly House, Kelly

renewal, rear medieval wing partly propped. Main house weathertight and maintenance gradually being addressed.

C18 house. Serious maintenance issues. Roof in need of

© English Heritage

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site



© English Heritage

SITE NAME:	Stable block north of Kelly House, Kelly
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

1104813 Contact: Ruth Garner 0117 975 0696

1	LA

© South Hams District Council

SITE NAME:	Lower Sessland Farm including cob walls adjoining to north west and south west, Sessland Lane, South Tawton
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

Late medieval thatched farmhouse with later additions including C17 hall bay and parlour wing. Further C17 addition to north west has been used as a separate cottage and in 2012 was vacant and in very poor condition with severe water penetration and decay of thatch and roof timbers. Temporary protection was erected in 2006 following an Urgent Works Notice.

LIST ENTRY NUMBER: | | 70877

OWNER TYPE:

LIST ENTRY NUMBER:

Contact: Ruth Garner 0117 975 0696

Stables, 1740. Partly used, part collapsed.



© West Devon Borough Council

SITE NAME:	Guildhall and police station, Abbey Place, Guildhall Square, Tavistock
DESIGNATION:	Listed Building grade II*, SM, CA, WHS
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)

Completed 1848, incorporating medieval fabric in part. Court use ended 1997 and police station now relocated. The first known example of a combined police station and magistrates court. Roof is in very poor condition and fabric in general urgently needs attention. Devon Historic Trust is marketing a conversion scheme to raise funds for repairs.

LIST ENTRY NUMBER: 1309358

SITE NAME: Church of St Peter, Lamerton

Charity (heritage)

Contact: Ruth Garner 0117 975 0696

SITE NAME:	Church of St Peter, Lamerton
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1171163

Early C15 church, restored 1870s. Very soon after this the church suffered a major fire which destroyed almost everything except for the external walls and the tower. Rebuilding work was completed in 1880 following the C15 design including the barrel-vaulted roof. The main area of concern is the tower, which suffers from permanent dampness. The condition of the stonework at the top of the tower also gives cause for concern. A Repair Grant for Places of Worship was successfully applied for in 2011, and again in 2012.

Contact: Ruth Garner 0117 975 0696



© English Heritage

SITE NAME:	Church of St Andrew, South Tawton
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation

1106035

The church is mostly C15 and was restored and vestry added in 1881. Good interior with bosses to roofs. There are major leaks in the north and south aisles and both roofs require renewal. A Repair Grant for Places of Worship was offered in 2011 towards repair to roofs and work is planned for 2013.

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

HERITAGE AT RISK 2013 / SOU	ITH WEST / West devon		
SITE NAME:	Motte with two baileys and a multivallate hillfort a	t Burley Wood, Brid	destowe
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018519
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Iron Age defended settlement in Dunterue Wood,	570 metres south	of Castle Head, Dunterton
DESIGNATION:	Scheduled Monument, RPG grade I	LIST ENTRY NUMBER:	1020273
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 375 metres north east of Higher Ewo	orthy, Germanswee	k
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020084
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 620 metres north of Higher Eworthy	, Germansweek	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017971
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Morwellham Quay: transport infrastructure, part of Gulworthy	of the water contro	l system and a manganese mill,
DESIGNATION:	Scheduled Monument, 5 LBs, WHS	LIST ENTRY NUMBER:	1021461
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Gawton arsenic mine and flue, Gulworthy / Bere F	errers	
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1002667
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round barrow cemetery and beacon at Heathfield / Brentor	, 650 metres west o	of Moorlands, Lamerton / Milton Abbo
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020075
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

	TH WEST / WEST DEVON / CHRISTCHURCH		
SITE NAME:	Roman forts, marching camps and associated monu	ıments, North Taw	ton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021151
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Guide post at Place Cross, Okehampton Hamlets		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020069
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bere Alston, Bere Ferrers		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Laura Batham (LPA) 01822 813600
SITE NAME:	North Tawton		
designation:	Conservation Area, 27 LBs, 2 SMs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Laura Batham (LPA) 01822 813600
SITE NAME:	Okehampton		
DESIGNATION:	Conservation Area, 23 LBs, RPG grade II	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Laura Batham (LPA) 01822 813600
DORSET			
CHRISTCHURCH			
SITE NAME:	Bowl barrow on East Parley Common 610 metres	south west of Fir G	Grove Farm, Hurn
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016092
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two bowl barrows at Gibbet Firs, 950 metres sou Works, Hurn	th west and 1080 m	netres south west of Palmers Ford
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016091
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

OWNER TYPE:

LIST ENTRY NUMBER:

EAST DORSET



© English Heritage

SITE NAME: Grotto 250 metres south west of St Giles House, Wimborne St. Giles Listed Building grade II*, RPG DESIGNATION: grade II* CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: C (C)

Private

Grotto, c1751-53, located 250 metres to the south east of the house, at the east end of a winding channel of water running westwards for 300 metres to the northern extremity of the lake (which lies 150 metres to the south of the house). One of several garden buildings situated in the C17 and Ć18 landscape. The Grotto is identified as a priority in the Parkland Plan produced as part of Higher Level Stewardship.

LIST ENTRY NUMBER: 1120131 Contact: Ruth Garner 0117 975 0696



© English Heritage

SITE NAME:	St Giles House, Wimborne St. Giles
DESIGNATION:	Listed Building grade I, RPG grade II*
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Private

1120129

Country house. C17, C18 and C19, situated in a C17 and C18 park. Owner's family have lived in the Dower House since the Second World War when the main house was requisitioned and subsequently used as a school. The south wing of the house has been repaired and the owner and his family are now living in it. Works to the roof, brickwork and windows completed May 2013. Works are currently being undertaken to principal ground floor rooms (May

Contact: Ruth Garner 0117 975 0696

SITE NAME:	Remains of medieval buildings, Witchampton
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private, multiple owners
LIST ENTRY NUMBER:	1002720 and 1155113

On the southern side of the village of Witchampton lie the ruins of a substantial domestic medieval building. It was used as an agricultural building in C19 but has since fallen into a state of disrepair. Scrub/vegetation clearance work has taken place in the past, but has since regenerated.

Contact: Ruth Garner 0117 975 0696

SITE NAME:	Length of deer park bank and ditch at Alderholt, Alderholt		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002394
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Section of Roman Road 150 metres south of Park Farm Cottages, Colehill		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018028
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

SITE NAME:	Bell barrow 500 metres north east of Beacon Farn	n, Ferndown Town	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015995
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Bell barrow known as Belle Vue Barrow, and a bor Town	wl barrow 250 meti	res north east of Hillamsland, Ferndo
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015994
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
RINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Bowl barrow 250 metres west of Ferndown Uppe	r School, Ferndown	Town
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015791
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Barrow near Burtts Harley, Gussage All Saints		
DESIGNATION:	Scheduled Monument, part in RPG grade II*	LIST ENTRY NUMBER:	1002787
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Part of Ackling Dyke (Roman road), including Rom Michael / Pentridge / Wimborne St. Giles	nan road on Oakley	Down, Gussage All Saints / Gussage
DESIGNATION:	Scheduled Monument, part in RPG grade II*	LIST ENTRY NUMBER:	1003309
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Barrow on Parsonage Hill, Gussage St. Michael		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002783
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Long mound 1500 yards (1370 metres) east of Hig	her Farm, Gussage	St. Michael
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002784
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
		CONTACT	D 0 0 1 7 0 7 0 0 0 0 0 0 0
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Two barrows near Ackling Dyke, Gussage St. Mich	ael	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002786
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two long barrows on Gussage Hill, Gussage St. Mi	chael	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002707
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two round barrows on Gussage Down, Gussage S	t. Michael	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002741
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Earthworks on Gussage Down, Gussage St. Michae	l / Sixpenny Handle	ey
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002740
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round barrows near Thickthorn Farm, Gussage St	Michael / Tarrant	Hinton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002816
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round barrow north west of High Lea Farm, Hinto	on Martell	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004552
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow cemetery and a cross dyke on Horto	n Common 800 me	etres south of Bridge Farm, Horton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018411
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 250 metres north west of Veiny Che	ese Pond, Long Cri	ichel
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015191
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

HERITAGE AT RISK 2013 / SOU	TH WEST / EAST DOKSET		
SITE NAME:	Two bowl barrows 165 metres west of Veiny C	heese Pond, Long Cri	chel
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015785
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Disc barrow and a bowl barrow 640 metres sou Launceston	ith west of Veiny Che	ese Pond, Long Crichel / Tarrant
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020444
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bradford Barrow, Pamphill		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002713
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	A linear earthwork north east of West Woodya	tes Manor: part of the	e 'Bokerley Line', Pentridge
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012138
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Barrow west of village, Pentridge		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002794
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Celtic fields on Pentridge Down, Pentridge		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002796
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Long barrows and group of round barrows on B	Sokerly Down, Pentric	lge
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002722
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Part of Dorset Cursus, Pentridge / Wimborne S	t. Giles	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003222
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Roman fort at Crab Farm, Shapwick		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002372
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Camp in Mistlebury Wood, Sixpenny Handley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002455
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Charity (non-heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Enclosure south of Humby's Stock Coppice, Sixper	ny Handley	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005575
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Three bowl barrows in Avon Heath Country Park, Matcham's House, St. Leonards and St. Ives	two 620 metres ar	nd one 700 metres north west of
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016095
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Stephen's Castle, a bowl barrow 720 metres east o	of Eastworth Farm,	Verwood
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021148
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Parley Barrow, a bowl barrow on the corner of Ell-	esfield Drive and D	ruid's Close, West Parley
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015792
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Barrow 30 yards (27 metres) east of Dorset Cursu	ıs, Wimborne St. G	iles
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002793
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
		CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Extensive significant problems TREAD Improving Arable ploughing NEWEXTREAD Arable ploughing NEWEXTREAD Two round barrows south of Cranborne Farm, Wimborne St. Giles Scheduled Monument Cooking Transport Generally unsatisfactory with major localised problems Arable clipping NEWEXTREAD Arable clipping NEWEXTREAD Barrows in and near St Giles Park, Wimborne St. Giles / Edmondsham Designations Scheduled Monument, part in RPG grade II* STENSIVE NUMBERS Barrows in and near St Giles Park, Wimborne St. Giles / Edmondsham Designations Scheduled Monument, part in RPG grade II* STENSIVE NUMBERS Generally satisfactory but with significant localised problems Arable clipping Declining CONTACT: Ruth Garner 0117 975 0696 Barrows in and near The Drive Plantation, Wimborne St. Giles / Gussage All Saints Scheduled Monument, part in RPG grade II* STENSIVE NUMBERS CONTACT: Ruth Garner 0117 975 0696 Barrows in and near The Drive Plantation, Wimborne St. Giles / Gussage All Saints Scheduled Monument, part in RPG grade II* STENSIVE NUMBERS CONTACT: Ruth Garner 0117 975 0696 Barrows in and near The Drive Plantation, Wimborne St. Giles / Gussage All Saints Scheduled Monument, part in RPG grade II* STENSIVE NUMBERS CONTACT: Ruth Garner 0117 975 0696 Barrows in Salisbury Plantation, Wimborne St. Giles / Pentridge Declining NEWEXTREAD Declining NEWEXTREAD Arable ploughing NEWEXTREAD Arable ploughing NEWEXTREAD Arable clipping NEWEXTREAD Declining NEWEXTREAD No CONTACT: Ruth Garner 0117 975 0696 Barrows in Salisbury Plantation, Wimborne St. Giles / Pentridge Declining NEWEXTREAD Declining NEWEXTREAD No CONTACT: Ruth Garner 0117 975 0696 Barrows in Salisbury Plantation, Wimborne St. Giles / Pentridge Declining NEWEXTREAD Declining NEWEXTREAD No CONTACT: Ruth Garner 0117 975 0696 Barrows in Salisbury Plantation, Wimborne St. Giles / Pentridge Declining NEWEXTREAD Declining NEWEXTREAD Declining NEW	SITE NAME:	Parts of Dorset Cursus on Bottlebush Down, Wim	borne St. Giles	
Arable ploughing NEW SNIARTY NO CONTACT: Ruth Garner 0117 975 0696 Two round barrows south of Cranborne Farm, Wimborne St. Giles Scheduled Monument. Sche	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002799
Private CONTACT: Ruth Gamer 0117 975 0696 Two round barrows south of Cranborne Farm, Wimborne St. Giles Scheduled Monument UST BYTRYNLIMBER: 1002459 CONDITION: Generally unsatisfactory with major localised problems Private CONTACT: Ruth Gamer 0117 975 0696 Ruth Gamer 0117	CONDITION:	Extensive significant problems	TREND:	Improving
Two round barrows south of Cranborne Farm, Wimborne St. Giles Scheduled Monument Generally unsatisfactory with major localised problems Private CONDITION: OWNER TYPE Private Barrows in and near St Giles Park, Wimborne St. Giles / Edmondsham Designation: Scheduled Monument, part in RPG grade II* Designation: OWNER TYPE Private CONTACT: Ruth Garner 0117 975 0696 TREND: Designation: Scheduled Monument, part in RPG grade II* Designation: Animal burrowing - extensive Private CONTACT: Ruth Garner 0117 975 0696 TREND: Declining TREND: TREND: Declining TREN	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Scheduled Monument Generally unsatisfactory with major localised problems Private CONTROLE Arable clipping Arable ploughing CONTROLE CONTROLE CONTROLE CONTROLE Ruth Garner 0117 975 0696 STENAME Barrows in and near St Giles Park, Wimborne St. Giles / Edmondsham CONTROLE CO	OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
Generally unsatisfactory with major localised problems Arable clipping New ENTRY: Private Barrows in and near St Giles Park, Wimborne St. Giles / Edmondsham DESIGNATION: Scheduled Monument, part in RPG grade III* DESIGNATION: CONTACT: Ruth Garner 0117 975 0696 STENAME Barrows in and near St Giles Park, Wimborne St. Giles / Edmondsham DESIGNATION: Scheduled Monument, part in RPG grade III* DESIGNATION: CONDITION: Generally satisfactory but with significant localised problems STENAME Barrows in and near The Drive Plantation, Wimborne St. Giles / Gussage All Saints DESIGNATION: Scheduled Monument, part in RPG grade III* DESIGNATION: Scheduled Monument Extensive significant problems RNEW ENTRY: No OWNER TYPE: Private Barrows in Salisbury Plantation, Wimborne St. Giles / Pentridge DESIGNATION: Scheduled Monument UST ENTRY INJURES. IO02817 Generally unsatisfactory with major localised problems TRIND: Declining Private Generally unsatisfactory with major localised problems TRIND: Declining	SITE NAME:	Two round barrows south of Cranborne Farm, W	imborne St. Giles	
problems New Interview No Arable clipping New Interview No CONTACT: Ruth Garner 0117 975 0696 DESIGNATION: Scheduled Monument, part in RPG grade II* Generally satisfactory but with significant localised problems Private CONTACT: Ruth Garner 0117 975 0696 TREND: Declining PRENCIPAL VALUEBURGELITY: Animal burrowing - extensive New BNIRY: No CONTACT: Ruth Garner 0117 975 0696 STE NAME: Barrows in and near The Drive Plantation, Wimborne St. Giles / Gussage All Saints Decisionations: Scheduled Monument, part in RPG grade II* Extensive significant problems TREND: Declining PRENCIPAL VALUEBURGELITY: Animal burrowing - extensive Barrows in and near The Drive Plantation, Wimborne St. Giles / Gussage All Saints Decisionations: Scheduled Monument, part in RPG grade II* Extensive significant problems TREND: Declining PRENCIPAL VALUEBURGELITY: No CONTACT: Ruth Garner 0117 975 0696 DESIGNATION: Scheduled Monument Extensive significant problems TREND: Declining PRENCIPAL VALUEBURGELITY: No CONTACT: Ruth Garner 0117 975 0696 DESIGNATION: Scheduled Monument EXTENDED: Declining PRENCIPAL VALUEBURGELITY: No CONTACT: Ruth Garner 0117 975 0696 DESIGNATION: Scheduled Monument EXTENDED: Declining PRENCIPAL VALUEBURGELITY: No CONTACT: Ruth Garner 0117 975 0696 DESIGNATION: Scheduled Monument, part In RPG grade II* EXTENDED: Declining PRENCIPAL VALUEBURGELITY: No CONTACT: Ruth Garner 0117 975 0696 DESIGNATION: Scheduled Monument, LB grade II* EXTENDED: Declining PRENCIPAL VALUEBURGELITY: No CONTACT: Ruth Garner 0117 975 0696 DESIGNATION: Scheduled Monument, LB grade II* EXTENDED: Declining PRENCIPAL VALUEBURGELITY: No CONTACT: Ruth Garner 0117 975 0696 DECLINING D	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002459
DESIGNATION Scheduled Monument, part in RPG grade II* DECINITION DECINITION DECINITION DECINING CONDITION DECINING DECINING Private CONTACT: Ruth Garner 0117 975 0696 DECINING DECINING DECINING PRIVATE BArrows in and near The Drive Plantation, Wimborne St. Giles / Gussage All Saints DESIGNATION Scheduled Monument, part in RPG grade II* DECINITION DECINING DECINING PRIVATE PRIVATE CONTACT: Ruth Garner 0117 975 0696 DECINING DECINING PRIVATE DECINING DE	CONDITION:		TREND:	Declining
Barrows in and near St Giles Park, Wimborne St. Giles / Edmondsham DEGIGNATION Scheduled Monument, part in RPG grade II* LET ENTRY NUMBER: DEGIGNATION Generally satisfactory but with significant localised problems PRINCIPLA VILINERABILITY: Animal burrowing - extensive NEW ENTRY? No DOWNER TYPE Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Barrows in and near The Drive Plantation, Wimborne St. Giles / Gussage All Saints DEGIGNATION Scheduled Monument, part in RPG grade II* LET ENTRY NUMBER: 1002788 CONDITION: Extensive significant problems TREND: Declining RRINGIPAL VULNERABILITY: Arable ploughing NEW ENTRY? No DEGIGNATION Scheduled Monument UST ENTRY NUMBER: DEGIGNATION Generally unsatisfactory with major localised problems DEGIGNATION: Generally unsatisfactory with major localised problems DEGIGNATION: Generally unsatisfactory with major localised problems GRUNDER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 GRUNDER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 GRUNDER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 GRUNDER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 GRUNDER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 GRUNDER TYPE: PRIVATE DEGIGNATION: Scheduled Monument, LB grade II* LIST ENTRY NUMBER: 1020580 CONTACT: Ruth Garner 0117 975 0696 GRUNDER TYPE: Mixed, multiple owners CONTACT: Ruth Garner 0117 975 0696 GRUNDER TYPE: Mixed, multiple owners CONTACT: Ruth Garner 0117 975 0696 GRUNDER TYPE: Mixed, multiple owners CONTACT: Ruth Garner 0117 975 0696 GRUNDER TYPE: Mixed, multiple owners CONTACT: Ruth Garner 0117 975 0696 GRUNDER TYPE: Mixed, multiple owners CONTACT: Ruth Garner 0117 975 0696 GRUNDER TYPE: Mixed, multiple owners CONTACT: Ruth Garner 0117 975 0696 GRUNDER TYPE: Mixed, multiple owners CONTACT: Ruth Garner 0117 975 0696 GRUNDER TYPE: Mixed Mixed Monument LIST ENTRY NUMBER: Declining RENDORNER TYPE: Mixed Mixed Monument LIST ENTRY NUMBER: Declining RENDORNER TYPE: Declining RENDORNER TYPE: No Declining RENDORNER TYPE: Declining RENDORNER TYPE: Declini	PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
Designation: Scheduled Monument, part in RPG grade * LIST ENTRY NUMBER: 1002782 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Animal burrowing - extensive New ENTRY: No DOWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Barrows in and near The Drive Plantation, Wimborne St. Giles / Gussage All Saints DESIGNATION: Scheduled Monument, part in RPG grade * LIST ENTRY NUMBER: 1002788 EXTENSIVE Significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No DOWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Barrows in Salisbury Plantation, Wimborne St. Giles / Pentridge DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002817 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable elipping NEW ENTRY: No DOWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Barrows on Salisbury Plantation, Wimborne St. Giles / Pentridge DOWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Generally unsatisfactory with major localised problems Arable elipping NEW ENTRY: No DOWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Group of henge monuments, an associated group of round barrows, a Saxon cemetery, and a Norman chu at Knowlton, Woodlands DESIGNATION: Scheduled Monument, LB grade * LIST ENTRY NUMBER: 1020580 CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Arable ploughing NEW ENTRY: No DOWNER TYPE: NO DOWN	OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
Generally satisfactory but with significant localised problems Animal burrowing - extensive NEW ENTRY: No Declining Private CONTACT: Ruth Garner 0117 975 0696 DETENANCE Barrows in and near The Drive Plantation, Wimborne St. Giles / Gussage All Saints DESIGNATION: Scheduled Monument, part in RPG grade II* DECLINING Extensive significant problems TREND: Declining Private CONTACT: Ruth Garner 0117 975 0696 DEVENANCE Barrows in Salisbury Plantation, Wimborne St. Giles / Pentridge DESIGNATION: Scheduled Monument DEVENANCE Barrows in Salisbury Plantation, Wimborne St. Giles / Pentridge DESIGNATION: Scheduled Monument DESIGNATION: Declining Private CONTACT: Ruth Garner 0117 975 0696 DEVENER TYPE: No DEVENER TYPE: No DEVENER TYPE: No DEVENER TYPE: No DESIGNATION: Scheduled Monument, LB grade II* LIST ENTRY NUMBER: 1020580 DESIGNATION: Scheduled Monument, LB grade II* LIST ENTRY NUMBER: 1020580 DESIGNATION: Scheduled Monument, LB grade II* DEVENER TYPE: No DEVE	SITE NAME:	Barrows in and near St Giles Park, Wimborne St. C	Giles / Edmondsham	1
PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEWENTRYP: No DWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 BET NAME: Barrows in and near The Drive Plantation, Wimborne St. Giles / Gussage All Saints DESIGNATION: Scheduled Monument, part in RPG grade II* LIST ENTRY NUMBER: 1002788 Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEWENTRYP: No DWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 BETE NAME: Barrows in Salisbury Plantation, Wimborne St. Giles / Pentridge DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002817 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable clipping NEWENTRYP: No DWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 BETE NAME: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRYP: No DWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 BETE NAME: Group of henge monuments, an associated group of round barrows, a Saxon cemetery, and a Norman chu at Knowlton, Woodlands DESIGNATION: Scheduled Monument, LB grade II* LIST ENTRY NUMBER: 1020580 DENDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No DWNER TYPE: Mixed, multiple owners CONTACT: Ruth Garner 0117 975 0696 BETE NAME: Round barrow cemetery south of New Barn Farm, associated with the Knowlton Circles, Woodlands DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020582	DESIGNATION:	Scheduled Monument, part in RPG grade II*	LIST ENTRY NUMBER:	1002782
Private Barrows in and near The Drive Plantation, Wimborne St. Giles / Gussage All Saints DESIGNATION: Scheduled Monument, part in RPG grade II* LIST ENTRY NUMBER: 1002788 DESIGNATION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYY: No CONTACT: Ruth Garner 0117 975 0696 STENAME Barrows in Salisbury Plantation, Wimborne St. Giles / Pentridge DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002817 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY: No DOWNER TYPE Private CONTACT: Ruth Garner 0117 975 0696 STENAME BARROWS ON TAKEN DECIDING NEW ENTRY: No DESIGNATION: Scheduled Monument CONTACT: Ruth Garner 0117 975 0696 STENAME Group of henge monuments, an associated group of round barrows, a Saxon cemetery, and a Norman churat Knowlton, Woodlands STENAME Group of henge monument, LB grade II* LIST ENTRY NUMBER: 1020580 DESIGNATION: Scheduled Monument, LB grade II* LIST ENTRY NUMBER: 1020580 DESIGNATION: Scheduled Monument, LB grade II* LIST ENTRY NUMBER: No DESIGNATION: Arable ploughing NEW ENTRY: No DOWNER TYPE Mixed, multiple owners CONTACT: Ruth Garner 0117 975 0696 STENAME ROUNDERABILITY: Arable ploughing NEW ENTRY: No DESIGNATION: Scheduled Monument LBT ENTRY NUMBER: 1020582 EXTENAME ROUNDERABILITY: Arable ploughing NEW ENTRY: No DESIGNATION: Scheduled Monument LBT ENTRY NUMBER: 1020582 EXTENAME ROUNDERABILITY: Arable ploughing NEW ENTRY: No DESIGNATION: Scheduled Monument LBT ENTRY NUMBER: 1020582 EXTENAME ROUNDERABILITY: Arable ploughing NEW ENTRY: No DESIGNATION: Scheduled Monument LBT ENTRY NUMBER: 1020582 EXTENAME ROUNDERABILITY: Arable ploughing NEW ENTRY: No	CONDITION:		TREND:	Declining
Barrows in and near The Drive Plantation, Wimborne St. Giles / Gussage All Saints DESIGNATION: Scheduled Monument, part in RPG grade II* Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYY: No CONTACT: Ruth Garner 0117 975 0696 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002817 Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY: No Declining PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY: No DOWNER TYPE: Private Group of henge monuments, an associated group of round barrows, a Saxon cemetery, and a Norman churat Knowlton, Woodlands DESIGNATION: Scheduled Monument, LB grade II* LIST ENTRY NUMBER: 1020580 DECIDITION: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020582 EXTENSIVE ROUND CIrcles, Woodlands DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020582 EXTENSIVE Scheduled Monument LIST ENTRY NUMBER: 1020582 DECIDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: No	PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument, part in RPG grade II* UST ENTRY NUMBER: 1002788 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY): No CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Barrows in Salisbury Plantation, Wimborne St. Giles / Pentridge DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1002817 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY): No DOWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Group of henge monuments, an associated group of round barrows, a Saxon cemetery, and a Norman chu at Knowlton, Woodlands DESIGNATION: Scheduled Monument, LB grade II* UST ENTRY NUMBER: 1020580 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY): No DOWNER TYPE: Mixed, multiple owners CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Round barrow cemetery south of New Barn Farm, associated with the Knowlton Circles, Woodlands DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1020582 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY): No DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1020582 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY): No	OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
Extensive significant problems TREND: Declining RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No CONTACT: Ruth Garner 0117 975 0696 WITE NAME Barrows in Salisbury Plantation, Wimborne St. Giles / Pentridge DESIGNATION: Scheduled Monument USTENTRY NUMBER: DOCUMENTATION: Generally unsatisfactory with major localised problems RINCIPAL VULNERABILITY: Arable clipping NEW ENTRYP: Private CONTACT: Ruth Garner 0117 975 0696 Group of henge monuments, an associated group of round barrows, a Saxon cemetery, and a Norman chural Knowlton, Woodlands DESIGNATION: Scheduled Monument, LB grade II* USTENTRY NUMBER: 1020580 EXTENDED: Declining RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No DOWNER TYPE: Mixed, multiple owners Round barrow cemetery south of New Barn Farm, associated with the Knowlton Circles, Woodlands DESIGNATION: Scheduled Monument USTENTRY NUMBER: 1020582 CONTACT: Ruth Garner 0117 975 0696	SITE NAME:	Barrows in and near The Drive Plantation, Wimbo	rne St. Giles / Guss	age All Saints
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYY: No DWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Barrows in Salisbury Plantation, Wimborne St. Giles / Pentridge DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1002817 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRYY: No DWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Group of henge monuments, an associated group of round barrows, a Saxon cemetery, and a Norman chu at Knowlton, Woodlands DESIGNATION: Scheduled Monument, LB grade II* UST ENTRY NUMBER: 1020580 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYY: No DWNER TYPE: Mixed, multiple owners CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Round barrow cemetery south of New Barn Farm, associated with the Knowlton Circles, Woodlands DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1020582 CONDITION: Extensive significant problems TREND: Declining RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYY: No DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1020582 CONDITION: Extensive significant problems TREND: Declining RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYY: No	DESIGNATION:	Scheduled Monument, part in RPG grade II*	LIST ENTRY NUMBER:	1002788
Private CONTACT: Ruth Garner 0117 975 0696 Barrows in Salisbury Plantation, Wimborne St. Giles / Pentridge DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002817 CONDITION: Generally unsatisfactory with major localised problems Private CONTACT: Declining Declining Private CONTACT: Ruth Garner 0117 975 0696 Group of henge monuments, an associated group of round barrows, a Saxon cemetery, and a Norman chu at Knowlton, Woodlands DESIGNATION: Scheduled Monument, LB grade II* LIST ENTRY NUMBER: 1020580 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No DOWNER TYPE: Mixed, multiple owners CONTACT: Ruth Garner 0117 975 0696 BY ENTRY PETER NOW ENTRYP: No DESIGNATION: CONTACT: Ruth Garner 0117 975 0696 BY ENTRY PETER NOW ENTRYP: No DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020582 CONDITION: Extensive significant problems TREND: Declining BY ENTRY NUMBER: 1020582 CONDITION: Extensive significant problems TREND: Declining BY ENTRY NUMBER: 1020582 CONDITION: Extensive significant problems TREND: Declining BY ENTRYPE: No Declining RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No RINCIPAL VULNERABILITY: No Declining RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No	CONDITION:	Extensive significant problems	TREND:	Declining
Barrows in Salisbury Plantation, Wimborne St. Giles / Pentridge DESIGNATION: Scheduled Monument DESIGNATION: Scheduled Monument Designation: Scheduled Monument Declining REND: Declining NEW ENTRY?: No DOWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 Group of henge monuments, an associated group of round barrows, a Saxon cemetery, and a Norman chu at Knowlton, Woodlands DESIGNATION: Scheduled Monument, LB grade II* DECONDITION: Extensive significant problems REND: Declining REND: Declining REND: No DOWNER TYPE: No Mixed, multiple owners CONTACT: Ruth Garner 0117 975 0696 RUTH NAME: Round barrow cemetery south of New Barn Farm, associated with the Knowlton Circles, Woodlands DESIGNATION: Scheduled Monument DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020582 DECONDITION: Extensive significant problems ROUND BARNOLIPAL VULNERABILITY: Arable ploughing RUTH NAME: Round barrow cemetery south of New Barn Farm, associated with the Knowlton Circles, Woodlands DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020582 DECINITION: Declining REND: Declining REND: Declining REND: Declining	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Scheduled Monument UST ENTRY NUMBER: 1002817 Generally unsatisfactory with major localised problems RINCIPAL VULNERABILITY: Arable clipping Private Group of henge monuments, an associated group of round barrows, a Saxon cemetery, and a Norman churat Knowlton, Woodlands CONDITION: Scheduled Monument, LB grade II* UST ENTRY NUMBER: 1020580 CONDITION: Extensive significant problems TREND: Declining RINCIPAL VULNERABILITY: No DWNER TYPE: Mixed, multiple owners CONTACT: Ruth Garner 0117 975 0696 CONDITION: Scheduled Monument UST ENTRY NUMBER: 1020582 CONDITION: Extensive significant problems TREND: Declining RINCIPAL VULNERABILITY: NUMBER: 1020582 CONDITION: Extensive significant problems TREND: Declining NEW ENTRY: NUMBER: 1020582 CONDITION: Extensive significant problems TREND: Declining NEW ENTRY: NUMBER: 1020582 CONDITION: Extensive significant problems TREND: Declining NEW ENTRY: No	OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable clipping Generally unsatisfactory with major localised problems New ENTRY?: No CONTACT: Ruth Garner 0117 975 0696 Group of henge monuments, an associated group of round barrows, a Saxon cemetery, and a Norman chu at Knowlton, Woodlands Scheduled Monument, LB grade II* LIST ENTRY NUMBER: 1020580 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Mixed, multiple owners CONTACT: Ruth Garner 0117 975 0696 STE NAME: Round barrow cemetery south of New Barn Farm, associated with the Knowlton Circles, Woodlands DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020582 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: No Declining REVENDED: Declining REVENDED: Declining REVENDED: Declining NEW ENTRY?: No	SITE NAME:	Barrows in Salisbury Plantation, Wimborne St. Gile	es / Pentridge	
problems PRINCIPAL VULNERABILITY: Arable clipping Private Group of henge monuments, an associated group of round barrows, a Saxon cemetery, and a Norman chu at Knowlton, Woodlands CONDITION: Scheduled Monument, LB grade II* Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY!: No CONTACT: Ruth Garner 0117 975 0696 Declining NEW ENTRY!: No CONTACT: Ruth Garner 0117 975 0696 BITE NAME: Round barrow cemetery south of New Barn Farm, associated with the Knowlton Circles, Woodlands DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020582 CONDITION: Extensive significant problems TREND: Declining NEW ENTRY!: No CONTACT: Ruth Garner 0117 975 0696 BITE NAME: Round barrow cemetery south of New Barn Farm, associated with the Knowlton Circles, Woodlands DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020582 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY!: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002817
Private CONTACT: Ruth Garner 0117 975 0696 Group of henge monuments, an associated group of round barrows, a Saxon cemetery, and a Norman churat Knowlton, Woodlands DESIGNATION: Scheduled Monument, LB grade II* LIST ENTRY NUMBER: 1020580 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No CONTACT: Ruth Garner 0117 975 0696 Round barrow cemetery south of New Barn Farm, associated with the Knowlton Circles, Woodlands DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020582 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
Group of henge monuments, an associated group of round barrows, a Saxon cemetery, and a Norman chu at Knowlton, Woodlands DESIGNATION: Scheduled Monument, LB grade II* LIST ENTRY NUMBER: 1020580 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Round barrow cemetery south of New Barn Farm, associated with the Knowlton Circles, Woodlands DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020582 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
at Knowlton, Woodlands DESIGNATION: Scheduled Monument, LB grade II* LIST ENTRY NUMBER: 1020580 TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing MEW ENTRY?: No CONTACT: Ruth Garner 0117 975 0696 BITE NAME: Round barrow cemetery south of New Barn Farm, associated with the Knowlton Circles, Woodlands DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020582 CONDITION: Extensive significant problems TREND: Declining NEW ENTRY?: No	OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
Extensive significant problems TREND: Declining Arable ploughing New Entry?: No CONTACT: Ruth Garner 0117 975 0696 Round barrow cemetery south of New Barn Farm, associated with the Knowlton Circles, Woodlands DESIGNATION: Scheduled Monument Extensive significant problems TREND: Declining No Round barrow cemetery south of New Barn Farm, associated with the Knowlton Circles, Woodlands DESIGNATION: Scheduled Monument Extensive significant problems TREND: Declining RINCIPAL VULNERABILITY: No No	SITE NAME:	Group of henge monuments, an associated group of at Knowlton, Woodlands	of round barrows, a	Saxon cemetery, and a Norman chu
Arable ploughing Mixed, multiple owners CONTACT: Ruth Garner 0117 975 0696 Round barrow cemetery south of New Barn Farm, associated with the Knowlton Circles, Woodlands DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: LO20582 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: NO	DESIGNATION:	Scheduled Monument, LB grade II*	LIST ENTRY NUMBER:	1020580
Mixed, multiple owners CONTACT: Ruth Garner 0117 975 0696 Round barrow cemetery south of New Barn Farm, associated with the Knowlton Circles, Woodlands DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020582 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: New ENTRY: No	CONDITION:	Extensive significant problems	TREND:	Declining
Round barrow cemetery south of New Barn Farm, associated with the Knowlton Circles, Woodlands DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020582 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020582 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No	ITE NAME:	Round barrow cemetery south of New Barn Farm,	associated with the	e Knowlton Circles, Woodlands
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020582
1 3 3	CONDITION:	Extensive significant problems	TREND:	Declining
OWNER TYPE: Private, multiple owners CONTACT: Ruth Garner 0117 975 0696	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
	OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

LIST ENTRY NUMBER:



© English Heritage

SITE NAME:	St Giles' House, Wimborne St. Giles / Edmondsham / Gussage All Saints
DESIGNATION:	Registered Park and Garden grade II*, 6 LBs, 6 SMs
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	Medium
TREND:	Improving
NEW ENTRY?:	No
OWNER TYPE:	Private

1000723

Extensive C18 landscape park and pleasure grounds with follies, a grotto, a serpentine lake and a striking beech avenue. The main house, a shell grotto and a number of scheduled barrows are also at risk. The structural elements of the park design survive in moderate condition. In 2010, Natural England's Environmental Stewardship scheme grant-aided a plan for the park and a comprehensive programme of restoration has commenced. Encouragingly, a start has also been made on repairing St Giles House.

Contact: Ruth Garner 0117 975 0696

SITE NAME:	Burts Hill / Merrifield		
DESIGNATION:	Conservation Area	NEW ENTRY?:	Yes
CONDITION:	Fair	TREND:	Deteriorating significantly
VULNERABILITY:	Medium	CONTACT:	Giles Moir (LPA) 01202 495000
SITE NAME:	Wimborne Minster, Wimborne		
DESIGNATION:	Conservation Area	NEW ENTRY?:	Yes
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Giles Moir (LPA) 01202 495000
SITE NAME:	Wimborne St Johns, Wimborne		
DESIGNATION:	Conservation Area	NEW ENTRY?:	Yes
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Giles Moir (LPA) 01202 495000

NORTH DORSET



© English Heritage

SITE NAME:	Sturminster Newton Castle, Sturminster Newton
DESIGNATION:	Scheduled Monument and Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

LIST ENTRY NUMBER: 1002719 and 1324461

Ruins of C14 stone built manor house within Sturminster Newton Castle, a probable Iron Age promontory fort overlooking the River Stour. Upstanding remains are in a very precarious position and considerable amount of consolidation work is urgently required to avoid significant areas of collapse. English Heritage architectural survey team has recorded the structure. Recent change of ownership. English Heritage in discussions with new owners.

Contact: Ruth Garner 0117 975 0696

SITE NAME:	Barn and outbuilding range, Tarrant Abbey Farm, Tarrant Crawford	C15 barn with in agricultural usupport the str
DESIGNATION:	Scheduled Monument and Listed Building grade II*	
CONDITION:	Very bad	
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1002715 and 1110841	Contact: Ruth

n C18 outbuildings and alterations. No longer use. Works have been undertaken to tructure.

Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

	Ĭ
ALL LOS CONTRACTOR	į

© English Heritage Archive

SITE NAME:	Manor Farm barn, Winterborne Clenston
DESIGNATION:	Scheduled Monument and Listed Building grade I
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Mixed, multiple owners

1003215 and 1110166

Huge late C16 tithe barn part used for storage. The hammerbeam roof may have been reused from a monastic building at Milton Abbey. Partial roof collapse resulted in English Heritage funding the erection of scaffolding as a temporary roof support. These repair works were completed in 2008.

Contact: Ruth Garner 0117 975 0696

4	6	
		T T

SITE NAME: Church of St Peter and St Paul, Market Place, Blandford Forum DESIGNATION: Listed Place of Worship grade I CONDITION: Poor PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation

1251913

This grade I church is a notable example of Georgian church architecture outside London. İt was rebuilt after fire between 1732 and 1739 to designs by John and William Bastard. The external stonework is in poor condition and there is water ingress to the interior causing damage to the plaster work. The cupola is in very poor condition and held in place with a temporary supporting structure.

Contact: Ruth Garner 0117 975 0696

© English Heritage



SITE NAME:	St Mary Magdalen, Fifehead Magdalen
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Good
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1171327

A small C14 parish church with C17 or C18 north chapel. The church was extensively restored in 1904. Repairs have been undertaken to the south chancel roof, but the fixings to the stone tiles on the remaining roofs appear to be progressively failing. A Repair Grant for Places of Worship was offered for roof repairs in March 2011. Works began in October 2012 and are near completion as of July 2013.

Contact: Ruth Garner 0117 975 0696

© English H	Heritag
-------------	---------

SITE NAME:	Linear boundary 870 metres south west of Spring F	arm, Ashmore	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020729
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Linear boundary and section of Roman road, 550 m Royal	etres south east of	Ashmore Farm, Ashmore / Tollard
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020728
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	St Leonard's Chapel, Blandford Forum		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1002726
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Local authority, multiple owners	CONTACT:	Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS I PA

Conservation Area Listed Building Local Planning Authority National Park ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

SITE NAME:	Field system in Old Park, Bryanston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002427
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 350 metres south of Gorcombe Farn	n, Charlton Marsha	II
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014848
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 500 metres south west of Gorcombe	Farm, Charlton M	arshall
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014847
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Bowl barrow 650 metres south west of Gorcombe	Farm, Charlton M	arshall
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014849
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 1020 metres south east of Chariswor	rth Cottages, Charl	ton Marshall
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014846
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Long barrow 360 metres SSW of Chettle House, C	Chettle	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013792
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Three bowl barrows 380 metres west of West End	d Barn, Dewlish / M	lilborne St. Andrew
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015031
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Longbury long barrow 600 metres north west of S	laughtergate Farm,	Gillingham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013680
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:		CONTACT:	

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Causewayed camp on Hambledon Hill, Iwerne C	ourtney or Shroton /	Child Okeford / Hanford
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002767
CONDITION:	Extensive significant problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Charity (non-heritage)	CONTACT:	Ruth Garner 0117 975 0696
TE NAME:	Bowl barrow known as Folly Barrow, Iwerne Mi	nster	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020030
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Two bowl barrows 350 metres south west of Ke	eeper's Lodge south e	east of Bareden Down, Iwerne Minst
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013745
CONDITION:	Extensive significant problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Bowl barrow 70 metres south east of West End	Barn, Milborne St. Ar	ndrew
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014854
CONDITION:	Extensive significant problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Bowl barrow 480 metres south east of West En	d Barn, Milborne St. A	Andrew
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014855
CONDITION:	Extensive significant problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Three bowl barrows on Milborne Down 520 me Castle hillfort, Milborne St. Andrew	tres and 585 metres i	north east of obelisk on Weatherby
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019364
CONDITION:	Extensive significant problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Two bowl barrows and two ring ditches 450 me	tres north west of Ha	aywards Farm, Milborne St. Andrew
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019365
CONDITION:	Extensive significant problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Weatherby Castle, an Iron Age hillfort 1020 met	res north west of Asl	hley Barn Farm, Milborne St. Andrev
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1019360
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
	0		

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

SITE NAME:	Stable Barrow 230 metres NNE of Frogmore Farm	n, Milborne St. Andr	rew / Milton Abbas
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014761
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Enclosure south of Pimperne Down, Pimperne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002860
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Site of St John's Church, Shaftesbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005580
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Crawford Castle (or Spetisbury Rings), Spetisbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004563
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Chapel west of Manor Farm, Stourton Caundle		
DESIGNATION:	Scheduled Monument, LB grade II*	LIST ENTRY NUMBER:	1002857
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Slight univallate hillfort 850 metres north east of B	usseys Stool Farm,	Tarrant Gunville
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020611
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 200 metres south east of Pimperne L	ong Barrow, Tarra	nt Hinton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013794
DESIGNATION.			
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
CONDITION:		TREND:	Declining No
	problems		-

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

SITE NAME:	Prehistoric habitation site between north and so	outh Hinton Downs, T	arrant Hinton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003235
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Roman villa on Little Barton Hill, Tarrant Hinton	n / Tarrant Gunville	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002424
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 350 metres south west of Buzbury	Rings, Tarrant Keyne	eston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013789
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 850 metres ESE of Hill Farm, Tarr	ant Keyneston	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015182
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Buzbury Rings, Tarrant Keyneston / Tarrant Rav	vston / Langton Long I	Blandford
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002718
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 600 metres south of Plantation Fa	rm, Tarrant Launcesto	n
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1015190
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow on The Cliff 680 metres east of Lu	iton Farm, Tarrant Rav	wston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015187
	Extensive significant problems	TREND:	Declining
CONDITION:	- · · · · · · · · · · · · · · · · · · ·		N.I.
	Arable ploughing	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Arable ploughing Commercial company	NEW ENTRY?: CONTACT:	Ruth Garner 0117 975 0696
PRINCIPAL VULNERABILITY: OWNER TYPE:	, , ,	CONTACT:	Ruth Garner 0117 975 0696
CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Commercial company Bowl barrow on The Cliff 680 metres NNW of	CONTACT: Smith's Cottages, Tar	Ruth Garner 0117 975 0696
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Commercial company Bowl barrow on The Cliff 680 metres NNW of Scheduled Monument	CONTACT: Smith's Cottages, Tan LIST ENTRY NUMBER:	Ruth Garner 0117 975 0696 rant Rawston 1015186
RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: CONDITION:	Commercial company Bowl barrow on The Cliff 680 metres NNW of Scheduled Monument Extensive significant problems	CONTACT: Smith's Cottages, Tark LIST ENTRY NUMBER: TREND:	Ruth Garner 0117 975 0696 rant Rawston 1015186 Declining

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Long barrow and two bowl barrows 140 metres north west of Dormy House, Tarrant Rawston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014572
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Roman enclosure on Keyneston Down, Tarrant Ra	wston	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002373
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Bowl barrow 150 metres north east of Dunbury, V	Vinterborne Hough	iton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014758
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 800 metres north west of North Barn Farm on Houghton North Down, Winterborne Houghton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013748
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Unknown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 500 metres south of West Down Bar	rn, Winterborne Ki	ngston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020986
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 900 metres north west of Pond Dow	n Buildings, Winter	borne Stickland
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1013749
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Unknown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Rowbarrow, 500 metres north west of Hedge End	Farm, Winterborn	e Stickland
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013747
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No

- C Slow decay; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 D Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial like). use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Bowl barrow 25 metres south of Whitechurch H	lill Barn, Winterborn	e Whitechurch	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013788	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Milling House, West Farm, Winterborne White	hurch		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1002396	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow 120 metres south of the southern / Bere Regis	extent of Horse Clos	e Plantation, Winterborne Whitechur	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015387	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow 550 metres north west of Bulbarrow Farm, Woolland			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013786	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bul Barrow, 750 metres east of Rawlsbury Cam	, Woolland		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013787	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Blandford Forum			
DESIGNATION:	Conservation Area	NEW ENTRY?:	No	
CONDITION:	Very bad	TREND:	Deteriorating	
VULNERABILITY:	Medium	CONTACT:	Kevin Morris (LPA) 01258 484276	
SITE NAME:	Gillingham			
DESIGNATION:	Conservation Area	NEW ENTRY?:	No	
CONDITION:	Very bad	TREND:	Deteriorating	
VULNERABILITY:	Medium	CONTACT:	Kevin Morris (LPA) 01258 484276	
SITE NAME:	Milton Abbas			
DESIGNATION:	Conservation Area	NEW ENTRY?:	No	
CONDITION:	Poor	TREND:	Deteriorating	
VULNERABILITY:	Low	CONTACT:	Kevin Morris (LPA) 01258 484276	

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

PURBECK



© English Heritage

SITE NAME: North Lodges, Lulworth Castle, Coombe Keynes

Scheduled Monument and Listed DESIGNATION: Building grade II*, part in RPG

grade II

CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C (C)

OWNER TYPE: Private

LIST ENTRY NUMBER: 1016685 and 1323333 Gate lodges and gateway to Lulworth Castle, 1785. The estate are exploring funding for the repair of the lodges (2013).

Contact: Ruth Garner 0117 975 0696

SITE NAME:	Bowl barrow in Throop Clump, 450 metres wes	t of Heatherdown, A	ffpuddle	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020734	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	The Double Barrow, a bowl barrow in Kite Hill Affpuddle	Plantation 250 metre	s south east of Roger's Hill Cottages,	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015900	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow on Worgret Heath, 320 metres north west of High Tor, Arne			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018190	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow 190 metres north west of Bere Do	own Farm, Bere Regis		
Designation:	Scheduled Monument	LIST ENTRY NUMBER:	1015376	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow 515 metres south of the southern	extent of Horse Clos	se Plantation, Bere Regis	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015386	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow 590 metres north east of Bere Do	wn Farm, Bere Regis		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015378	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D
- Slow decay; solution agreed but F not yet implemented.
 Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

,	SITE NAME:	Bowl barrow 610 metres east of Bere Heath Far	m, Bere Regis	
problems pro	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015365
CONTRETTEE Government or agency CONTRET: Ruth Gamer 0117 975 0696 Set NAME: Bowl barrow 790 metres north east of Haywards Farm, Bere Regis DESCRIPTION Scheduled Monument DESCRIPTION Extensive significant problems DESCRIPTION Private CONTRET: No CONTRET: No CONTRET: No CONTRET: No CONTRET: No CONTRET: No CONTRET: Ruth Gamer 0117 975 0696 DESCRIPTION DESCRIPTION DESCRIPTION DESCRIPTION Private CONTRET: Ruth Gamer 0117 975 0696 DESCRIPTION DESCRIPTION DESCRIPTION DESCRIPTION DESCRIPTION DESCRIPTION DESCRIPTION DESCRIPTION DESCRIPTION AND DETRY DESCRIPTION AND DETRY DESCRIPTION AND DETRY DESCRIPTION DESCRIPTION DESCRIPTION AND DETRY DESCRIPTION DESCRIPTION DESCRIPTION AND DETRY DESCRIPTION DESCRIPTION DESCRIPTION NO CONTRET: NO CON	CONDITION:		TREND:	Declining
Bowl barrow 790 metres north east of Haywards Farm, Bere Regis Decining	PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
Scheduled Monument IST SKIRY NUMBER 1015330 CONTROL Arable ploughing NEW HAIRTY Private CONTROL Scheduled Monument IST RICE Bowl barrow on Warren Heath, 350 metres south west of Warren House, Bere Regis DEGINATION Scheduled Monument IST RICE CONTROL SCHEDULE MONUMENT PRIVATE Bowl barrow on Warren Heath, 350 metres south west of Warren House, Bere Regis DEGINATION Scheduled Monument IST RICE DEGINATION Scheduled Monument IST RICE SCHEDULE MONUMENT PRIVATE Private CONTROL CONTROL Scheduled Monument IST RICE SCHEDULE MONUMENT IST RICE CONTROL Scheduled Monument IST RICE SCHEDULE MONUMENT IST RICE CONTROL Scheduled Monument IST RICE CONTROL CONTROL Generally unsatisfactory with major localised problems Private CONTROL CONTROL Ruth Garner 0117 975 0696 CONTROL CONTROL RUTH GARNER OIL 17 975 0696 CONTROL CONTROL CONTROL RUTH GARNER OIL 17 975 0696 CONTROL OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696	
Extensive significant problems TREND. Declining NEW CANTACTO. Ruth Garner 0117 975 0696 SENERATIVE Anable ploughing NEW STATES. No CONTRACTO. Ruth Garner 0117 975 0696 STRINAMIC Bowl barrow on Warren Heath, 350 metres south west of Warren House, Bere Regis Scheduled Monument LST ENTRYNUMBER. Unknown PRINCERA VILLESABILITY: Arable ploughing NEW ENTRY: No CONTRACTO. Ruth Garner 0117 975 0696 STRINAMIC Four bowl barrows 240 metre east of Oak Cottage, Bere Regis Scheduled Monument LST ENTRYNUMBER. 1015369 SCHEDULE	SITE NAME:	Bowl barrow 790 metres north east of Hayward	s Farm, Bere Regis	
Arable ploughing New ENTRY: No CONTACT: Ruth Garner 0117 975 0696 EXTERNAME: Bowl barrow on Warren Heath, 350 metres south west of Warren House, Bere Regis DESIGNATION: Extensive significant problems IRNO: Unknown RENAME: Private CONTACT: Ruth Garner 0117 975 0696 EXTERNAME: Private CONTACT: Ruth Garner 0117 975 0696 STERNAME: Pour bowl barrows 240 metre east of Oak Cottage, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015369 CONTACT: Ruth Garner 0117 975 0696 STERNAME: Four bowl barrows 240 metre east of Oak Cottage, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015369 CONTACT: Ruth Garner 0117 975 0696 STERNAME: Four bowl barrows 600 metres east and 650 metres DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015331 CONDITION: Private CONTACT: Ruth Garner 0117 975 0696 STERNAME: Four bowl barrows 600 metres east and 650 metres DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015331 CONDITION: Extensive significant problems Extensive significant problems Extensive significant problems DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015329 CONTACT: Ruth Garner 0117 975 0696 STERNAME: Long barrow on Bere Down, 1100 metres north east of Roke Barn, Bere Regis DESIGNATION: Scheduled Monument Extensive significant problems TRING: Declining DECINIARY: No CONTACT: Ruth Garner 0117 975 0696 STERNAME: The End Barrow, a bowl barrow 320 metres south west of White House, Bere Regis DESIGNATION: Scheduled Monument Extensive significant problems TRING: Declining DECINIARY: No CONTACT: Ruth Garner 0117 975 0696 STERNAME: The End Barrow, a bowl barrow 320 metres south west of White House, Bere Regis DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1017462 CONDITION: Generally unsatisfactory with major localised problems DESIGNATION: Scheduled Monument TRING: Declining DECINIARY: No DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015330	
Private Bowl barrow on Warren Heath, 350 metres south west of Warren House, Bere Regis DESIGNATION Scheduled Monument UST PATRY NUMBER 1019367 CONDITION Extensive significant problems TRAND Unknown Private CONDITION Extensive significant problems New Entry: No CONTACT: Ruth Garner 0117 975 0696 Private Scheduled Monument LIST PATRY NUMBER 1015369 CONDITION: Generally unsatisfactory with major localised problems Private CONTACT: Ruth Garner 0117 975 0696 Private LIST PATRY NUMBER 1015331 CONDITION Extensive significant problems TRAND Declining Private Long barrow on Bere Down, 1100 metres north east of Roke Barn, Bere Regis DESIGNATION Scheduled Monument LIST PATRY NUMBER 1015329 DECIDING Extensive significant problems TRAND Declining Private Long barrow on Bere Down, 1100 metres north east of Roke Barn, Bere Regis DESIGNATION Scheduled Monument LIST PATRY NUMBER 1015329 DECIDING Extensive significant problems TRAND Declining Private CONTACT: Ruth Garner 0117 975 0696 DECIDING Extensive significant problems TRAND Declining TRAND DECIDING Extensive significant problems TRAND Declining DECIDING Extensive significant problems TRAND Declining DECIDI	CONDITION:	Extensive significant problems	TREND:	Declining
Bowl barrow on Warren Heath, 350 metres south west of Warren House, Bere Regis DESIGNATION: Scheduled Monument LIST INTRY NUMBER: LONDTION Extensive significant problems TRAND: Unknown NEW ENTRY: No DOWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 STE NAME Four bowl barrows 240 metre east of Oak Cottage, Bere Regis DESIGNATION: Scheduled Monument LIST INTRY NUMBER: LOSS DESIGNATION: Scheduled Monument Generally unsatisfactory with major localised problems Private CONTACT: Ruth Garner 0117 975 0696 STENAME: Four bowl barrows 600 metres east and 650 metres north east of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: LOS DESIGNATION: Scheduled Monument LOS DESIGNATION: DEClining NEW ENTRY: Private CONTACT: Ruth Garner 0117 975 0696 STE NAME: Long barrow on Bere Down, I 100 metres north east of Roke Barn, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: LOS DEClining DOWNER TYPE: The End Barrow, a bowl barrow 320 metres south west of White House, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: LOS DECLINING DESTENDED TO THE HOUSE	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1019367 CONDITION: Extensive significant problems TREND: Unknown TRENCIPAL VUNERABILITY: Arable ploughing NEW ENTRY: No CONTRACT: Ruth Garner 0117 975 0696 STE NAME: Four bowl barrows 240 metre east of Oak Cottage, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015369 CONDITION: Generally unsatisfactory with major localised problems Private CONTRACT: Ruth Garner 0117 975 0696 STE NAME: Private CONTRACT: Ruth Garner 0117 975 0696 STE NAME: Four bowl barrows 600 metres east and 650 metres north east of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015331 CONTRACT: Ruth Garner 0117 975 0696 STE NAME: Four bowl barrows 600 metres east and 650 metres north east of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015331 CONTRACT: Ruth Garner 0117 975 0696 STE NAME: OCNTRACT: Ruth Garner 0117 975 0696 STE NAME: Long barrow on Bere Down, 1100 metres north east of Roke Barn, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015329 CONDITION: Extensive significant problems TREND: Declining DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015329 CONTRACT: Ruth Garner 0117 975 0696 STE NAME: Long barrow on Bere Down, 1100 metres north east of Roke Barn, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015329 CONDITION: Extensive significant problems TREND: Declining DECINITION: Arabe ploughing NEW BATRY: No DECINITION: Arabe ploughing NEW BATRY: No DECINITION: Scheduled Monument LIST ENTRY NUMBER: 1017462 CONTRACT: Ruth Garner 0117 975 0696 DETERMANE: The End Barrow, a bowl barrow 320 metres south west of White House, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017462 CONTRACT: Ruth Garner 0117 975 0696 DETERMANE: The End Barrow 230 metres south west of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015333 THE NUMBER OF TREND LIST STATE NUMBER: 1015333 DECINITION: DECINITION: Arabe plo	OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
Extensive significant problems Arable ploughing NEW ENTRY: No DOWNER TYPE: Private Four bowl barrows 240 metre east of Oak Cottage, Bere Regis SESIGNATION: Scheduled Monument UST ENTRY NUMBER: Private CONTACT: Ruth Garner 0117 975 0696 RENO: Declining REN	SITE NAME:	Bowl barrow on Warren Heath, 350 metres sou	th west of Warren H	louse, Bere Regis
RENDERLY VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Four bowl barrows 240 metre east of Oak Cottage, Bere Regis DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1015369 CONDITION: Generally unsatisfactory with major localised problems FRENCIPAL VULNERABILITY: Forestry New CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Four bowl barrows 600 metres east and 650 metres north east of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1015331 EXCENDITION: Extensive significant problems TIRUN: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Long barrow on Bere Down, 1100 metres north east of Roke Barn, Bere Regis DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1015329 CONDITION: Extensive significant problems TIREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Long barrow on Bere Down, 1100 metres north east of Roke Barn, Bere Regis DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1015329 CONDITION: Extensive significant problems TIREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME: The End Barrow, a bowl barrow 320 metres south west of White House. Bere Regis DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1017462 CONTACT: Ruth Garner 0117 975 0696 STENAME: The End Barrow, a bowl barrow 320 metres south west of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1017462 CONTACT: Ruth Garner 0117 975 0696 STENAME: Three bowl barrows 230 metres south west of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1015333 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY: No DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1015333 DESIGNATION: Scheduled	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019367
CONTACT: Ruth Garner 0117 975 0696 STENAME Four bowl barrows 240 metre east of Oak Cottage, Bere Regis DESIGNATION: Scheduled Monument USTENTRY NUMBER: 1015369 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL WUNERABILITY: Forestry NUMBER: No CONTACT: Ruth Garner 0117 975 0696 STENAME FOUr bowl barrows 600 metres east and 650 metres north east of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument USTENTRY NUMBER: 1015331 CONDITION: Extensive significant problems TINND: Declining PRINCIPAL WUNERABILITY: No CONTACT: Ruth Garner 0117 975 0696 STENAME Long barrow on Bere Down, 1100 metres north east of Roke Barn, Bere Regis DESIGNATION: Scheduled Monument USTENTRY NUMBER: 1015329 CONDITION: Extensive significant problems TINND: Declining RERNCIPAL WUNERABILITY: No CONTACT: Ruth Garner 0117 975 0696 STENAME Long barrow on Bere Down, 1100 metres north east of Roke Barn, Bere Regis DESIGNATION: Scheduled Monument USTENTRY NUMBER: 1015329 CONDITION: Extensive significant problems TINND: Declining RERNCIPAL WUNERABILITY: No CONTACT: Ruth Garner 0117 975 0696 STENAME The End Barrow, a bowl barrow 320 metres south west of White House, Bere Regis DESIGNATION: Scheduled Monument USTENTRY NUMBER: 1017462 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining RERNCIPAL WUNERABILITY: No OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 STENAME The End Barrow, a bowl barrows 200 metres south west of White House, Bere Regis DESIGNATION: Scheduled Monument USTENTRY NUMBER: 1017462 CONDITION: Generally unsatisfactory with major localised problems Three bowl barrows 230 metres south west of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument USTENTRY NUMBER: 1015333 CONDITION: Extensive significant problems Three bowl barrows 230 metres south west of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument USTENTRY NUMBER: 1015333 DESIGNATION: Scheduled Monument USTENTRY NUMBER: 1015333 DESIGNATION: Scheduled Monument USTEN	CONDITION:	Extensive significant problems	TREND:	Unknown
Four bowl barrows 240 metre east of Oak Cottage, Bere Regis DESIGNATION: Scheduled Monument Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Forestry New INTRY: No CONTACT: Ruth Garner 0117 975 0696 STENAME Four bowl barrows 600 metres east and 650 metres north east of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument UST ENTRY NUMBER. 1015331 CONDITION Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No CONTACT: Ruth Garner 0117 975 0696 STENAME Long barrow on Bere Down, 1100 metres north east of Roke Barn, Bere Regis DESIGNATION: Scheduled Monument UST ENTRY NUMBER. 1015329 CONDITION Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing REMINITY: No CONTACT: Ruth Garner 0117 975 0696 STENAME: Long barrow on Bere Down, 1100 metres north east of Roke Barn, Bere Regis DESIGNATION: Scheduled Monument UST ENTRY NUMBER. 1015329 CONDITION Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No CONTACT: Ruth Garner 0117 975 0696 STENAME The End Barrow, a bowl barrow 320 metres south west of White House, Bere Regis DESIGNATION: Scheduled Monument UST ENTRY NUMBER. 1017462 CONDITION Generally unsatisfactory with major localised problems The End Barrow, a bowl barrow 320 metres south west of White House, Bere Regis DESIGNATION: Scheduled Monument UST ENTRY NUMBER. 1017462 CONDITION: Private Three bowl barrows 230 metres south west of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument UST ENTRY NUMBER. 1015333 DESIGNATION: Scheduled Monument UST EN	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Scheduled Monument LIST ENTRY NUMBER 1015369	OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
Generally unsatisfactory with major localised problems FRINCIPAL VULNERABILITY: Forestry NEW ENTRY: No Declining FRINCIPAL VULNERABILITY: Forestry Private Four bowl barrows 600 metres east and 650 metres north east of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015331 CONDITION: Extensive significant problems TREND: Declining RERINCIPAL VULNERABILITY: No DOWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 STEE NAME: Long barrow on Bere Down, 1100 metres north east of Roke Barn, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015329 CONDITION: Extensive significant problems TREND: Declining RERINCIPAL VULNERABILITY: No DOWNER TYPE: No DOWNER TYPE: No DOWNER TYPE: No DOWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 STEE NAME: Long barrow a bowl barrow 320 metres south west of White House, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017462 CONDITION: Private The End Barrow, a bowl barrow 320 metres south west of White House, Bere Regis DESIGNATION: Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems TREND: Declining PRINCIPAL VULNERABILITY: No DOWNER TYPE: Private Three bowl barrows 230 metres south west of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015333	SITE NAME:	Four bowl barrows 240 metre east of Oak Cott	age, Bere Regis	
PRINCIPAL VULNERABILITY: Forestry Private Four bowl barrows 600 metres east and 650 metres north east of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 101533 CONDITION: Extensive significant problems TREND: Declining Private CONTACT: Ruth Garner 0117 975 0696 DESIGNATION: OCCUPATION: Declining NEW ENTRY: No CONTACT: Ruth Garner 0117 975 0696 DESIGNATION: Arable ploughing NEW ENTRY: No CONTACT: Ruth Garner 0117 975 0696 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015329 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015329 DECINITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: No DOWNER TYPE: No DOWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 STE NAME: The End Barrow, a bowl barrow 320 metres south west of White House, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017462 DECINITION: Generally unsatisfactory with major localised problems FRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY: No DOWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 DECINITION: Generally unsatisfactory with major localised problems FRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY: No DOWNER TYPE: Private Three bowl barrows 230 metres south west of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017462 DECLINING TREND: Declining NEW ENTRY: No DECLINING DECLINING TREND: Declining TREND: Declining DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015333 DESIGNATION: Arable ploughing NEW ENTRY: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015369
Private Four bowl barrows 600 metres east and 650 metres north east of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1015331 CONDITION: Extensive significant problems TREND: Declining NEW ENTRY: No DEWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 STENAME Long barrow on Bere Down, 1100 metres north east of Roke Barn, Bere Regis DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1015329 CONDITION: Extensive significant problems TREND: Declining Private UST ENTRY NUMBER: 1015329 CONDITION: Extensive significant problems TREND: Declining Private CONTACT: Ruth Garner 0117 975 0696 STENAME LONG DEMONSTRATIVE: Arable ploughing NEW ENTRY: No DEWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 STENAME The End Barrow, a bowl barrow 320 metres south west of White House, Bere Regis DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1017462 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY: No Declining PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY: No DEWNER TYPE Private CONTACT: Ruth Garner 0117 975 0696 STENAME Three bowl barrows 230 metres south west of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1017462 CONTACT: Ruth Garner 0117 975 0696 STENAME Three bowl barrows 230 metres south west of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1015333 DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1015333 DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1015333	CONDITION:		TREND:	Declining
Four bowl barrows 600 metres east and 650 metres north east of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 101533 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No DOWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME Long barrow on Bere Down, 1100 metres north east of Roke Barn, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015329 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No DOWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME The End Barrow, a bowl barrow 320 metres south west of White House, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017462 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: No DOWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME The End Barrow, a bowl barrow 320 metres south west of White House, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017462 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: No DOWNER TYPE: No DOWNER TYPE: No DOWNER TYPE: No Three bowl barrows 230 metres south west of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015333 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015333 ENDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: No Declining REND: Declining	PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015331 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No DOWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Long barrow on Bere Down, 1100 metres north east of Roke Barn, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015329 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No DOWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME: The End Barrow, a bowl barrow 320 metres south west of White House, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017462 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY?: No DOWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Three bowl barrows 230 metres south west of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY: NO DOWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Three bowl barrows 230 metres south west of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015333 CONDITION: Scheduled Monument LIST ENTRY?: No	OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No OWNER TYPE: Private Long barrow on Bere Down, 1100 metres north east of Roke Barn, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: Decining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: Private The End Barrow, a bowl barrow 320 metres south west of White House, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: Decining PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRYP: No OWNER TYPE: Private The Declining NEW ENTRYP: No OWNER TYPE: Private The End Barrow, a bowl barrow 320 metres south west of White House, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: Declining PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRYP: No OWNER TYPE: Private Three bowl barrows 230 metres south west of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015333 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No	SITE NAME:	Four bowl barrows 600 metres east and 650 me	tres north east of Ha	ywards Farm, Bere Regis
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Long barrow on Bere Down, 1100 metres north east of Roke Barn, Bere Regis DESIGNATION: Scheduled Monument LUST ENTRY NUMBER: 1015329 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME: The End Barrow, a bowl barrow 320 metres south west of White House, Bere Regis DESIGNATION: Scheduled Monument LUST ENTRY NUMBER: 1017462 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY: No OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Three bowl barrows 230 metres south west of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LUST ENTRY NUMBER: 1015333 CONDITION: Scheduled Monument LUST ENTRY NUMBER: 1015333 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015331
Private CONTACT: Ruth Garner 0117 975 0696 ESTE NAME Long barrow on Bere Down, 1100 metres north east of Roke Barn, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015329 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No CONTACT: Ruth Garner 0117 975 0696 ESTE NAME The End Barrow, a bowl barrow 320 metres south west of White House, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017462 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY?: No CONTACT: Ruth Garner 0117 975 0696 ESTE NAME Three bowl barrows 230 metres south west of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015333 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	CONDITION:	Extensive significant problems	TREND:	Declining
ESTE NAME: Long barrow on Bere Down, 1100 metres north east of Roke Barn, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015329 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: NO CONTACT: Ruth Garner 0117 975 0696 STE NAME: The End Barrow, a bowl barrow 320 metres south west of White House, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017462 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRYP: NO CONTACT: Ruth Garner 0117 975 0696 STE NAME: Three bowl barrows 230 metres south west of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015333 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: NO Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: NO NEW ENTRYP: NO Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: NO	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015329 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY!: No CONTACT: Ruth Garner 0117 975 0696 SITE NAME: The End Barrow, a bowl barrow 320 metres south west of White House, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017462 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY!: No CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Three bowl barrows 230 metres south west of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015333 CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1015333 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY!: No	OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No CONTACT: Ruth Garner 0117 975 0696 BITE NAME: The End Barrow, a bowl barrow 320 metres south west of White House, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017462 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY?: No CONTACT: Ruth Garner 0117 975 0696 BITE NAME: Three bowl barrows 230 metres south west of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015333 CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1015333 CONDITION: Extensive significant problems TREND: Declining NEW ENTRY?: No	SITE NAME:	Long barrow on Bere Down, 1100 metres north	east of Roke Barn, B	Sere Regis
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME: The End Barrow, a bowl barrow 320 metres south west of White House, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017462 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY?: No OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Three bowl barrows 230 metres south west of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015333 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015329
OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 The End Barrow, a bowl barrow 320 metres south west of White House, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017462 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY?: No OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Three bowl barrows 230 metres south west of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015333 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	CONDITION:	Extensive significant problems	TREND:	Declining
The End Barrow, a bowl barrow 320 metres south west of White House, Bere Regis Designation: Scheduled Monument LIST ENTRY NUMBER: 1017462 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY?: No OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Three bowl barrows 230 metres south west of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015333 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1017462 Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable clipping New ENTRY?: No OWNER TYPE: Three bowl barrows 230 metres south west of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1015333 CONDITION: Extensive significant problems Ruth Garner 0117 975 0696 UST ENTRY NUMBER: 1015333 TREND: Declining No	OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable clipping Private CONTACT: Ruth Garner 0117 975 0696 Three bowl barrows 230 metres south west of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: DOCUMENTALY: Arable ploughing NEW ENTRY: No	SITE NAME:	The End Barrow, a bowl barrow 320 metres sou	ith west of White Ho	use, Bere Regis
problems PRINCIPAL VULNERABILITY: Arable clipping Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Three bowl barrows 230 metres south west of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015333 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017462
Private CONTACT: Ruth Garner 0117 975 0696 Three bowl barrows 230 metres south west of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015333 CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No	CONDITION:		TREND:	Declining
Three bowl barrows 230 metres south west of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015333 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015333 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	SITE NAME:	Three bowl barrows 230 metres south west of I	Haywards Farm, Bere	Regis
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015333
1 0 0	CONDITION:	Extensive significant problems	TREND:	Declining
OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
	OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

SITE NAME:	Three bowl barrows 650 metres south west of E		•
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018193
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two bell barrows and a bowl barrow, 200 metre	es north east of Hayw	vards Farm, Bere Regis
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015332
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two bowl barrows on South Heath, 900 metres	SSE of The Bungalow	, Bere Regis
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017694
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bell barrow on Blackhill Clump 470 metres north	h of Mintern's Ferry, I	Bere Regis / Turners Puddle
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015899
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two bowl barrows both 350 metres north east	of Spring Garden Barı	n, Bere Regis / Turners Puddle
	Two bowl barrows both 350 metres north east Scheduled Monument	of Spring Garden Barı	n, Bere Regis / Turners Puddle 1015898
DESIGNATION:			
designation: Condition:	Scheduled Monument Generally unsatisfactory with major localised	LIST ENTRY NUMBER:	1015898
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY:	Scheduled Monument Generally unsatisfactory with major localised problems	LIST ENTRY NUMBER: TREND:	1015898 Declining
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument Generally unsatisfactory with major localised problems Plant growth	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:	Declining No Ruth Garner 0117 975 0696
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME:	Scheduled Monument Generally unsatisfactory with major localised problems Plant growth Private	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:	Declining No Ruth Garner 0117 975 0696
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument Generally unsatisfactory with major localised problems Plant growth Private Bowl barrow on Bloxworth Down, 740 metres s	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: South of Marsh Farm,	1015898 Declining No Ruth Garner 0117 975 0696 Bloxworth
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Scheduled Monument Generally unsatisfactory with major localised problems Plant growth Private Bowl barrow on Bloxworth Down, 740 metres so Scheduled Monument	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: SOuth of Marsh Farm, LIST ENTRY NUMBER:	1015898 Declining No Ruth Garner 0117 975 0696 Bloxworth 1017626
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY:	Scheduled Monument Generally unsatisfactory with major localised problems Plant growth Private Bowl barrow on Bloxworth Down, 740 metres so Scheduled Monument Extensive significant problems	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: SOUTH OF Marsh Farm, LIST ENTRY NUMBER: TREND:	Declining No Ruth Garner 0117 975 0696 Bloxworth 1017626 Declining
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument Generally unsatisfactory with major localised problems Plant growth Private Bowl barrow on Bloxworth Down, 740 metres s Scheduled Monument Extensive significant problems Arable ploughing	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: SOUTH OF Marsh Farm, LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:	1015898 Declining No Ruth Garner 0117 975 0696 Bloxworth 1017626 Declining No
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument Generally unsatisfactory with major localised problems Plant growth Private Bowl barrow on Bloxworth Down, 740 metres some Scheduled Monument Extensive significant problems Arable ploughing Private	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: SOUTH OF Marsh Farm, LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:	1015898 Declining No Ruth Garner 0117 975 0696 Bloxworth 1017626 Declining No
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument Generally unsatisfactory with major localised problems Plant growth Private Bowl barrow on Bloxworth Down, 740 metres some Scheduled Monument Extensive significant problems Arable ploughing Private Round barrow cemetery on Bloxworth Down, Blox	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: SOUTH OF Marsh Farm, LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: Sloxworth	Declining No Ruth Garner 0117 975 0696 Bloxworth 1017626 Declining No Ruth Garner 0117 975 0696
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: CONDITION: CONDITION: CONDITION:	Scheduled Monument Generally unsatisfactory with major localised problems Plant growth Private Bowl barrow on Bloxworth Down, 740 metres of Scheduled Monument Extensive significant problems Arable ploughing Private Round barrow cemetery on Bloxworth Down, Bloxwo	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: SOUTH OF Marsh Farm, LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: Sloxworth LIST ENTRY NUMBER:	Declining No Ruth Garner 0117 975 0696 Bloxworth 1017626 Declining No Ruth Garner 0117 975 0696
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: CONDITION: PRINCIPAL VULNERABILITY:	Scheduled Monument Generally unsatisfactory with major localised problems Plant growth Private Bowl barrow on Bloxworth Down, 740 metres of Scheduled Monument Extensive significant problems Arable ploughing Private Round barrow cemetery on Bloxworth Down, Bloxwo	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: SOUTH OF Marsh Farm, LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: Sloxworth LIST ENTRY NUMBER: TREND:	Declining No Ruth Garner 0117 975 0696 Bloxworth 1017626 Declining No Ruth Garner 0117 975 0696
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: OWNER TYPE: OWNER TYPE:	Scheduled Monument Generally unsatisfactory with major localised problems Plant growth Private Bowl barrow on Bloxworth Down, 740 metres of Scheduled Monument Extensive significant problems Arable ploughing Private Round barrow cemetery on Bloxworth Down, Bound Scheduled Monument Extensive significant problems Arable ploughing	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: SOUTH OF Marsh Farm, LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: SIOXWORTH LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:	Declining No Ruth Garner 0117 975 0696 Bloxworth 1017626 Declining No Ruth Garner 0117 975 0696 1017624 Declining No Ruth Garner 0117 975 0696
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: OWNER TYPE:	Scheduled Monument Generally unsatisfactory with major localised problems Plant growth Private Bowl barrow on Bloxworth Down, 740 metres of Scheduled Monument Extensive significant problems Arable ploughing Private Round barrow cemetery on Bloxworth Down, Bloxwort	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: SOUTH OF Marsh Farm, LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: SIOXWORTH LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:	Declining No Ruth Garner 0117 975 0696 Bloxworth 1017626 Declining No Ruth Garner 0117 975 0696 1017624 Declining No Ruth Garner 0117 975 0696
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: OWNER TYPE:	Scheduled Monument Generally unsatisfactory with major localised problems Plant growth Private Bowl barrow on Bloxworth Down, 740 metres of Scheduled Monument Extensive significant problems Arable ploughing Private Round barrow cemetery on Bloxworth Down, Book Scheduled Monument Extensive significant problems Arable ploughing Private Three bowl barrows on Bloxworth Down, 800 metros	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: SOUTH OF MARSH FARM, LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: SIOXWORTH LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: NEW ENTRY?: CONTACT:	Declining No Ruth Garner 0117 975 0696 Bloxworth 1017626 Declining No Ruth Garner 0117 975 0696 1017624 Declining No Ruth Garner 0117 975 0696 y Bay Barn, Bloxworth
SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY:	Scheduled Monument Generally unsatisfactory with major localised problems Plant growth Private Bowl barrow on Bloxworth Down, 740 metres of Scheduled Monument Extensive significant problems Arable ploughing Private Round barrow cemetery on Bloxworth Down, Bloxwort	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: SOUTH OF Marsh Farm, LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: Sloxworth LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: NEW ENTRY?: CONTACT:	1015898 Declining No Ruth Garner 0117 975 0696 Bloxworth 1017626 Declining No Ruth Garner 0117 975 0696 1017624 Declining No Ruth Garner 0117 975 0696 y Bay Barn, Bloxworth 1017625

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Bowl barrow 200 metres south east of Hill Barr	: one of a group of thi	ree barrows, Chaldon Herring	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008178	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow 470 metres south east of Down Barn: an outlier of the Chaldon Down barrow group, Chal Herring			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008146	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow 550 metres south of Chaldon Dov cemetery, Chaldon Herring	vn Buildings: part of th	e Chaldon Down round barrow	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008520	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow 650 metres south of Chaldon Dov cemetery, Chaldon Herring	vn Buildings: part of th	e Chaldon Down round barrow	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008523	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow 660 metres south of Chaldon Dov cemetery, Chaldon Herring	vn Buildings: part of th	e Chaldon Down round barrow	
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1008521	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
ITE NAME:	The Round Pound, an enclosure on Chaldon Do	own, Chaldon Herring		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018436	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Two bowl barrows 200 metres south east of Hi	II Barn: two of a group	of three barrows, Chaldon Herring	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008162	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
014 (4 150 7) (05	D.,	CONTACT:	Ruth Garner 0117 975 0696	
OWNER TYPE:	Private	2011111011	Rutil Garrier 0117 773 0676	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Wardstone Barrow: a bowl barrow on the Dors Chaldon Herring	et coastal ridge 300 n	netres south of Chideock Farm,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008676
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow on Creech Barrow hill, Church Kn	owle / Steeple	
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1014830
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	The Rings: a ringwork and bailey and a Civil Wal Castle	battery 400 metres	south west of Corfe Castle, Corfe
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1011479
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Three bowl barrows in Holme Lane Plantation, 2	200 metres south wes	st of Squirrel's Cottages, East Holme
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016728
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two barrows known as 'Water Barrows' 650 m cemetery to the south east of East Lulworth, East		eway Farm: part of a round barrow
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008144
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Flower's Barrow: a small multivallate hillfort and	associated outwork o	on Rings Hill, East Lulworth / Tyneha
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008141
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 60 metres north east of Hethfelton	Farm, East Stoke	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018192
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

HERITAGE AT RISK 2013 / SOU	ITH WEST / PURBECK				
SITE NAME:	Bowl barrow on Farm Heath, 470 metres south	east of Hill Cottages,	East Stoke		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016272		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Bowl barrow on Farm Heath, 480 metres south east of Hill Cottages, East Stoke				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016271		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Round barrow cemetery on West Holme Heath	n, 850 metres north w	rest of Hurst Mill, East Stoke		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007691		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No		
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Section of Battery Bank on Binnegar Plain, 830 metres north east of Stokeford Farm, East Stoke				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018189		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Section of Battery Bank on South Heath, East St	oke			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016273		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Two bowl barrows on South Heath, 290 metres	and 370 metres east	of Binnegar Hall, East Stoke		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016276		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Alum works, other multi-period industrial rema Kimmeridge Bay, Kimmeridge	ins and an associated g	group of jetties and breakwaters,		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1017307		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696		

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 D Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial like). use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

HERITAGE AT RISK 2013 / SOU	ITH WEST / PURBECK		
SITE NAME:	Bowl barrow 800 metres NNW of West Morde	en Farm, Morden	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015367
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow in Morden Park 350 metres south	west of Hunting Bridg	ge, Morden
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1016281
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two bowl barrows 760 metres north east of Mi	ller's Farm, Morden	
DESIGNATION:	Scheduled Monument, RPG grade II*	LIST ENTRY NUMBER:	1016283
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Obelisk on Fir Hill, Moreton		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1002425
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Group of three bell barrows and a bowl barrow	on Godlingston Heat	h, Studland
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014291
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow in Piddle Wood, 530 metres north	east of Gate Barn, T	urners Puddle
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015901
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Group of six bowl barrows, forming a round ba	rrow cemetery on Bla	ck Hill, Turners Puddle / Bere Regis
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015897
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Round barrow cemetery on Povington Heath 55	0 metres north east o	of Whiteway Farm, Tyneham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008026
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Digging	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Thorn Barrow: a bowl barrow on East Holme R	ange, 650 metres nort	th east of Whiteway Farm, Tyneham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009610
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Decoy pond and associated overnight shelter on	Decoy Heath, Warel	ham St. Martin
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016916
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Light Anti-aircraft battery on Holton Heath, 210	metres west of Sandf	ford House, Wareham St. Martin
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019153
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Light Anti-aircraft battery on Holton Heath, 650	metres south east of	Sandford House, Wareham St. Mart
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019152
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	Yes
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Royal Naval Cordite Factory at Holton Heath, V	Vareham St. Martin	
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1019151
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bindon Hill camp, West Lulworth		
DESIGNATION:	Scheduled Monument, part in CA, WHS	LIST ENTRY NUMBER:	1002705
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

Immediate risk of further rapid deterioration or loss of fabric; no

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Bowl barrow 370 metres east of Belhuish Farm: one of a group of barrows to the west of Burngate Wood West Lulworth			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008220	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow 400 metres ENE of Belhuish Farm: West Lulworth	one of a group of bar	rows to the west of Burngate Wood	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012050	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow 650 metres south east of Belhuish Wood, West Lulworth	Farm: one of a group	of barrows to the west of Burngate	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008455	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Drove Hill round barrows, Winfrith Newburgh			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002765	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bindon Abbey (site), Wool			
DESIGNATION:	Scheduled Monument, LB grade I	LIST ENTRY NUMBER:	1002703	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow 300 metres south east of Hyford C	Cottage, Wool		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015894	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow 380 metres north west of Hyford	Cottage, Wool		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015895	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Bowl barrow on Emmett's Hill, Worth Matrav	vers	
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1017268
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Lytchett Minster, Purbeck, Lytchett Minster ar	nd Upton	
DESIGNATION:	Conservation Area, 12 LBs	NEW ENTRY?:	Yes
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Benjamin Webb (LPA) 01929 557388
SITE NAME:	Swanage, Purbeck, Swanage		
DESIGNATION:	Conservation Area, 86 LBs, SM, WHS	NEW ENTRY?:	Yes
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Benjamin Webb (LPA) 01929 557388

WEST DORSET



© English Heritage

SITE NAME:	Literary and Scientific Institute, East Street, Bridport
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

LIST ENTRY NUMBER: 1118999

Founded 1835 as Mechanics Institute and reconstituted 1855 as Literary and Scientific Institute. Since 2012 a local trust has carried out project development work, grant aided by English Heritage, which included a condition survey and a feasibility study exploring the viability of using the building for community purposes. The trust is also working on a Conservation Management Plan. Awarded Heritage Lottery Fund Stage I grant to progress project which is underway. An application for English Heritage grant is under consideration.

Contact: Ruth Garner 0117 975 0696

SITE NAME:	Messrs Norman goods warehouse, Station Road, West Bay, Bridport
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1228722

C18, possibly older. Former bonded stores. Vacant. Owner has identified potential end use and is in discussion with the Local Planning Authority and English Heritage.

© English Heritage

SITE NAME:	Wolfeton Riding House, Wolfeton House, Charminster
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Private

1119102

One of the oldest surviving riding schools in England, late C16. Used as an agricultural barn for a long period and now in trust ownership. Repairs, grant aided by English Heritage, have been ongoing since 2007. Two phases of major repairs to stabilise the walls and repair the roof which started early 2012, also grant aided by English Heritage, are underway and yet to be completed as of July

Contact: Ruth Garner 0117 975 0696

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid
- deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

D	SITE NAME:	Marshwood Castle, Marshwood	The site comprises a rectangular earthwork enclosure with		
	DESIGNATION: Scheduled Monument and Listed		a moat (partly filled). There are substantial remains of the internal ramparts and the motte. These masonry structure require consolidation and careful ongoing management.		
	CONDITION:	Poor			
	OCCUPANCY:	N/A			
	PRIORITY CATEGORY:	C (C)			
	OWNER TYPE:	Private			
	LIST ENTRY NUMBER:	1002836 and 1324105	Contact: Ruth Garner 0117 975 0696		
	SITE NAME:	Remains of Old Parish Church of St Mary Magdalene, North Wootton	West tower of former parish church. Early C15. The nave and chancel were demolished circa 1883 when the C19 church was built. Ivy which encased the structure was		
-	DESIGNATION:	Scheduled Monument and Listed Building grade II*	removed in 2011. A condition survey and proposals for its consolidation are underway. The owners are in discussion with English Heritage.		
	CONDITION:	Poor			
	OCCUPANCY:	N/A			
	PRIORITY CATEGORY:	D (D)			
	OWNER TYPE:	Private			
	LIST ENTRY NUMBER:	1003745 and 1303981	Contact: Ruth Garner 0117 975 0696		
	SITE NAME:	Cart shed and stables 10 metres south of Waddon House, Portesham	Former stables and cart shed, dated 1702. Currently disused with roof temporarily protected. Application for repair and conversion to holiday let use has been		
	DESIGNATION:	Listed Building grade II*	approved. Roof has been made temporarily weathertight and intended to be re-thatched shortly.		
CHA	CONDITION:	Poor	,		
	OCCUPANCY:	Vacant/not in use			
	PRIORITY CATEGORY:	D (D)			
	OWNER TYPE:	Private			
	LIST ENTRY NUMBER:	1152606	Contact: Ruth Garner 0117 975 0696		
	SITE NAME:	Sherborne House, Newland, Sherborne	House circa 1720. Former girls' school. An application for Planning Permission for gallery/office use has been		
	DESIGNATION:	Listed Building grade I, CA	approved and proposed new development at the rear is subject to a Section 106 agreement, securing repairs to		
	CONDITION:	Fair	Sherborne House. External repairs are complete but		
	OCCUPANCY:	Part occupied/part in use	internal refurbishment is still awaited and the building remains unoccupied.		
3	PRIORITY CATEGORY:	F (F)			
	OWNER TYPE:	Local authority			
10000	LIST ENTRY NUMBER:	1110694	Contact: Ruth Garner 0117 975 0696		
		T:: D	Impressive C16 barn. It has an interesting constructional		
	SITE NAME:	Tithe Barn, Church Lane, Sydling St. Nicholas	history and is part of an important complex of historic		
	SITE NAME: DESIGNATION:		buildings. Its gradual deterioration has recently shown signs of accelerating with the loss of an area of roof covering. Approval of Planning Permission for change of use to		
		Sydling St. Nicholas Scheduled Monument and Listed	buildings. Its gradual deterioration has recently shown signs of accelerating with the loss of an area of roof covering. Approval of Planning Permission for change of use to community events has been granted and works in		
	DESIGNATION:	Sydling St. Nicholas Scheduled Monument and Listed Building grade II*, CA	buildings. Its gradual deterioration has recently shown signs of accelerating with the loss of an area of roof covering. Approval of Planning Permission for change of use to community events has been granted and works in		
	DESIGNATION: CONDITION:	Sydling St. Nicholas Scheduled Monument and Listed Building grade II*, CA Poor	buildings. Its gradual deterioration has recently shown signs of accelerating with the loss of an area of roof covering. Approval of Planning Permission for change of use to community events has been granted and works in connection with Scheduled Monument Consent still under		
	DESIGNATION: CONDITION: OCCUPANCY:	Sydling St. Nicholas Scheduled Monument and Listed Building grade II*, CA Poor Vacant/not in use	buildings. Its gradual deterioration has recently shown signs of accelerating with the loss of an area of roof covering. Approval of Planning Permission for change of use to community events has been granted and works in connection with Scheduled Monument Consent still under		

© English Heritage

© English Heritage

© English Heritage

© English Heritage Archive

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D

LIST ENTRY NUMBER:

- Slow decay; solution agreed but F not yet implemented.
 Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

1003209 and 1119426

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

Contact: Ruth Garner 0117 975 0696

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument CA LB LPA NP RPG SM UA Unitary Authority
WHS World Heritage Site

LIST ENTRY NUMBER:



© English Heritage

SITE NAME:	Stable Block immediately south east of Little Toller Farm, Toller Fratrum
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

1228876

Mid C16 stable building, forming part of a working farm but currently disused. The thatch is in a very degraded state leading to partial collapse of the roof and rear wall structure at the end of 2011. The building is now scaffolded with a temporary roof structure whilst the Local Authority and English Heritage are discussing the need for urgent repairs with the owner and exploring possible sources of

Methodist church, circa 1818, and the meeting place of the Tolpuddle Martyrs. Discussions are ongoing between West Dorset District Council and the owner, who has indicated a willingness to sell the site, to find an appropriate use for

Contact: Ruth Garner 0117 975 0696

the building.

Care.	

© English Heritage Archive

SITE NAME:	Former Methodist Chapel, Dorchester Road, Tolpuddle
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1119849

Contact: Ruth Garner 0117 975 0696



© English Heritage

SITE NAME:	Church of St Mary, Mosterton
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Very bad
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1289886

Parish church built in 1833 by Edmund Pearce on a new site. The historic nave roof has been replaced with an asbestos sheet roof finish with a suspended ceiling and is in poor condition. The stonework to the diminutive west tower is also in poor condition, particularly to the south side. This is due to extensive cement pointing and patch repairs which are failing. A Repair Grant for Places of Worship was offered in March 2012 for repairs to the tower. Project Development work was completed in May 2013 and repair works are due to start on site in the summer of 2013.

Contact: Ruth Garner 0117 975 0696

SITE NAME:	Barrow east of Burnt House Bottom, Alton Pancras	S	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002862
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Earthwork 80 yards (70 metres) long, north west o	f Coombe Bottom,	Askerswell
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002734
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
OWNER TYPE: SITE NAME:	Private Round barrow north west of Coombe Bottom, Ask		Ruth Garner 0117 975 0696
			Ruth Garner 0117 975 0696
SITE NAME:	Round barrow north west of Coombe Bottom, Ask	kerswell	
SITE NAME: DESIGNATION:	Round barrow north west of Coombe Bottom, Ask Scheduled Monument Generally unsatisfactory with major localised	Kerswell LIST ENTRY NUMBER:	1003061

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS I PA

Conservation Area Listed Building Local Planning Authority National Park ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

HERITAGE AT RISK 2013 / SOU	ith west / west dorset		
SITE NAME:	Group of three round barrows west of Two Ga	ates, Askerswell / Litto	n Cheney
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002736
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow on Beaminster Down 530 metres	south east of East Axr	noller Farm, Beaminster
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015049
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow on Beaminster Down 770 metres	north east of Higher N	Meerhay Farm, Beaminster
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015050
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bell barrow in Highfield Plantation and two bow Bradford Peverell	/l barrows immediately	north west of Forty Acre Plantation
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019415
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 380 metres west of Whitfield Farr	n, Bradford Peverell	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019639
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Group of barrows in Seven Barrow Plantation, I	Bradford Peverell	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002812
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Long barrow and four bowl barrows 500 metre	s north west of Whitfi	ield Farm, Bradford Peverell
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019416
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Discontinuous surviving sections of Roman aqueduct, Bradford Peverell / Dorchester		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002730
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Culliford Tree long barrow and group of round	parrows, Broadmayne	/ Whitcombe
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003304
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two bowl barrows on Lord's Down 580 metres	south east of Crawth	orne Farm, Burleston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017277
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow on Wood Hill 310 metres north ea	sst of Cowden, Charn	ninster
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019395
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round barrow east of Forston Farm, Charminsto	er	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002851
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Group of round barrows north east of Hog Leaz	e, Cheselbourne	
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1002877
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round barrow on Cheselbourne West Down, C	heselbourne	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002878
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 360 metres south of Compton Bar	n, Compton Valence	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019741
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

HERITAGE AT RISK 2013 / SOU	TH WEST / WEST DORSET		
SITE NAME:	Settlement south east of Soaper's Hill Plantation	, Compton Valence	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003234
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 450 metres east of Dennet's Botto	om Barn, Dewlish	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015427
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 550 metres WNW of West End B	arn, Dewlish	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015032
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Earthwork east of Stake Farm, East Chelboroug	า	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002845
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 810 metres NNE of Whatcombe I south western part of Black Down, Kingston Ru		f the round barrow cemetery on the
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013845
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bell barrow and five bowl barrows 1000 metres round barrow cemetery, Kingston Russell / Little	south east of Kingsto	n Russell Farm, part of the Black Down
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011693
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Lime kiln 800 feet (245 metres) north west of L	angton Cross, Langtor	n Herring
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002387
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Bowl barrow 165 metres NNW of White Hill Littlebredy	Barn, forming part of tl	he White Hill round barrow cemeter
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013260
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 200 metres south of Winterbour round barrow cemetery, Littlebredy	ne Poor Lot forming pa	art of the Winterbourne Poor Lot
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013254
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 265 metres north west of White cemetery, Littlebredy	Hill Barn, forming part	of the White Hill round barrow
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013261
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 300 metres WNW of White Hill Littlebredy	Barn, forming part of t	the White Hill round barrow cemete
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013262
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 340 metres north west of White cemetery, Littlebredy	Hill Barn, forming part	of the White Hill round barrow
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013264
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 355 metres north west of White cemetery, Littlebredy	Hill Barn, forming part	of the White Hill round barrow
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013263
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 500 metres west of Well Bottom cemetery, Littlebredy	Wood, forming part o	of the Pitcombe Down round barrow
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013250
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Bowl barrow 600 metres west of Well Bottom V cemetery, Littlebredy	Vood, forming part o	of the Pitcombe Down round barrov
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013253
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 600 metres west of Well Bottom V cemetery, Littlebredy	Vood, forming part o	of the Pitcombe Down round barrow
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013249
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow on Black Down, 870 metres north v	west of the Hardy M	onument, Littlebredy
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019030
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Four bowl barrows 500 metres west of Well Bot barrow cemetery, Littlebredy	tom Wood, forming	part of the Pitcombe Down round
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013252
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Three bowl barrows 300 metres south west of V round barrow cemetery, Littlebredy	Vell Bottom Wood,	forming part of the Pitcombe Down
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013251
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 550 metres north east of Pitcombe Littlebredy / Kingston Russell	Farm, part of the Bl	ack Down round barrow cemetery,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011694
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Barrow 650 yards (600 metres) north of North B	arn Farm, Long Bred	dy
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002798
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Charity (non-heritage)	CONTACT:	Ruth Garner 0117 975 0696
OWNER THE.	Charity (non-heritage)		Ruth Garrier 0117 973 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Barrow 700 yards (640 metres) south west of N	orth Barn Farm, Long	Bredy
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002800
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Earthwork and ancient fields south east of Lysco	mbe Bottom, Melcom	be Horsey / Cheselbourne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002456
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow on Farm Hill 620 metres west of N	linterne Parva Farm, I	Minterne Magna
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015046
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 230 metres north east of Great St	ode House, Netherb	ury
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016372
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Medieval settlement at West Ringstead, Osming	con	
DESIGNATION:	Scheduled Monument, LB grade II*	LIST ENTRY NUMBER:	1019393
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Upton Fort, a coastal artillery battery and two so	earchlight emplaceme	nts, Osmington
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1021435
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	Yes
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Four barrows on Moigns Down, Owermoigne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002774
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

STEWNITE Sound barrow south west of Bourne Farm, Piddlehmorn Scheduled Monument Scheduled Monument Stewnite significant problems STEWNITE Declining Scheduled Monument Scheduled Mon		WEST / WEST BORGET		
EXEMBLIAN Extensive significant problems MANUAL No FINALIZA ATABLE ploughing MEMORIANE MINISTRALIZA ATABLE Ploughing FINALIZA ATABLE Monument METOMITATION MOSQUELLA FINALIZA ATABLE MONUMENTAL FI	SITE NAME:	Round barrow south west of Bourne Farm, Piddleh	ninton	
PRINCIPAL SULPREABULTY: Arable ploughing Commercial company Commercial Commerc	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004550
COMMERT PER PROPERTY OF TWO barrows on Little Puddle Hill, Piddle Inton INSTANCE Two barrows on Little Puddle Hill, Piddle Inton INSTANCE Generally satisfactory but with significant localised problems PRINCIPLY AT THE PROPERTY OF THE	CONDITION:	Extensive significant problems	TREND:	Declining
Two barrows on Little Puddle Hill, Puddlehinton EDGGANTIONE Scheduled Monument CONDITIONS Generally satisfactory but with significant localised problems Arable clipping NEW ENTRY Arable dipping NEW ENTRY No CONTACT: Ruth Garner 0117 975 0696 NINMARS Two barrows west of Little Piddle Down, Piddlehinton DESCRAATIONA Scheduled Monument EXTENSIVE Significant problems TRANDA DOWNERT TYPE Private CONTACT: Ruth Garner 0117 975 0696 NEW ENTRY No CONTACT: Ruth Garner 0117 975 0696 NEW ENTRY No CONTACT: Ruth Garner 0117 975 0696 TRANDA DOWNERT TYPE Private CONTACT: Ruth Garner 0117 975 0696 TRANDA DOWNERT TYPE Private Barrow on College Down, Piddletrenthide DESCRAATIONA Scheduled Monument LISTENSIVE PRIVATE DESCRAATIONA Scheduled Monument CONTACT: Ruth Garner 0117 975 0696 TRANDA TRAND	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Scheduled Monument UST STRITKINSHORES 1003224 CERRISHION Generally satisfactory but with significant localised INNER DECIDING PRINCED AT A CONTACT AT A CONTACT AND PRIVATE AN	OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
CONDITION: Generally satisfactory but with significant localised problems PRINCIPLA VULNERABILITY: Arable clipping Private Two barrows west of Little Piddle Down, Piddlehinton USE PRINCIPLA VULNERABILITY: DESCRIATION: Scheduled Monument Scheduled Monument Private Two barrows west of Little Piddle Down, Piddlehinton USE PRINCIPLA VULNERABILITY: OWNER TYPE: Private Barrow on College Down, Piddletrenthide Edicasanion: Scheduled Monument USE PRIVATE: DESCRIATION: Scheduled Monument Extensive significant problems Barrow on College Down, Piddletrenthide Edicasanion: Scheduled Monument USE PRIVATE: DOWNER TYPE: No OWNER TYPE: Private Bowl barrow on Plush Hill 600 metres ESE of Lower Farm, Plush, Piddletrenthide DESCRIATION: Scheduled Monument USE PRIVATE: Bowl barrow on Plush Hill 600 metres ESE of Lower Farm, Plush, Piddletrenthide DESCRIATION: Scheduled Monument USE PRIVATE: Bowl barrow on Plush Hill 600 metres ESE of Lower Farm, Plush, Piddletrenthide DESCRIATION: Scheduled Monument USE PRIVATE: Private Bowl barrow on Plush Hill 600 metres ESE of Lower Parm, Plush, Piddletrenthide DESCRIATION: Scheduled Monument USE PRIVATE: No OWNER TYPE: No OWNER TYPE: Private Bowl barrow on Plush Hill 740 metres ESE of Lower Parm, Plush, Piddletrenthide DESCRIATION: Scheduled Monument USE PRIVATE: No OWNER TYPE: No OWNER TYPE: No OWNER TYPE: Declining PRIVATE: No OWNER TYPE: No O	SITE NAME:	Two barrows on Little Puddle Hill, Piddlehinton		
PRINCIPAL VULNEMBRUTY Arable clipping Private Two barrows west of Little Piddle Down, Piddlehinton Education Scheduled Monument Education Scheduled Monument Extensive significant problems Extensive significant probl	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003224
Designation Private Private Two barrows west of Little Piddle Down, Piddlehinton DESIGNATION Scheduled Monument UST ENTRY NUMBER 1002805 DESIGNATION CONTROL Private	CONDITION:		TREND:	Declining
TITE NAME TWO barrows west of Little Piddle Down, Piddlehintor DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002805 Declining REND: Declining REND: Declining REND: No Declining REND: RUN Garrier 0117 975 0696 SITE NAME: Barrow on College Down, Piddletrenthide DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1002842 CONDITION: Extensive significant problems REND: DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1002842 CONDITION: REND:	PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
DESIGNATION Scheduled Monument LIST ENTRY NUMBER Declining RINCORD MUNIFICATION Extensive significant problems RINCORD MUNIFICATION Private CONTACT: Ruth Garner 0117 975 0696 STE NAME: Barrow on College Down, Piddletrenthide DESIGNATION Scheduled Monument UST ENTRY NUMBER 1002842 CONDITION Extensive significant problems TREND: Unknown PRINCIPLA WUNDERBUILTY: Arable ploughing NEW ENTRY: No CONTACT: Ruth Garner 0117 975 0696 STE NAME: Bowl barrow on Plush Hill 600 metres ESE of Lower Farm, Plush, Piddletrenthide DESIGNATION Scheduled Monument UST ENTRY NUMBER 1015037 CONDITION Generally satisfactory but with significant localised problems PRINCIPLA WUNDERBUILTY: Arable clipping NEW ENTRY: No CONTACT: Ruth Garner 0117 975 0696 STE NAME: DESIGNATION Scheduled Monument UST ENTRY NUMBER 1015037 Declining PRINCIPLA WUNDERBUILTY: Arable clipping NEW ENTRY: No CONTACT: Ruth Garner 0117 975 0696 STE NAME: Bowl barrow on Plush Hill 740 metres ESE of Lower Farm, Plush, Piddletrenthide DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1015038 CONDITION: PRINCIPLA WUNDERBUILTY: Arable ploughing NEW ENTRY: No CONTACT: Ruth Garner 0117 975 0696 STE NAME: Bowl barrow on Pouts Hill 740 metres ESE of Lower Farm, Plush, Piddletrenthide DESIGNATION: CONDITION: Extensive significant problems TREND: Declining PRINCIPLA WUNDERBUILTY: Arable ploughing NEW ENTRY: No OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 STE NAME: Bowl barrow on Pond Eweleaze 500 metres north east of Dole's Ash Farm, Piddletrenthide DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1015035 TREND: Declining PRINCIPLA WUNDERBUILTY: Arable ploughing NEW ENTRY: No CONTACT: Ruth Garner 0117 975 0696 STE NAME: Bowl barrow on Pond Eweleaze 500 metres north east of Dole's Ash Farm, Piddletrenthide DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1003238 Declining DECLINING DECLINING DECLINING DECLINING DECLINING DECLINING DECLINING DECLINING D	OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
CONDITION Extensive significant problems TREND. Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 STENAME: Barrow on College Down, Piddletrenthide DESIGNATION: Scheduled Monument LET ENTRY NUMBER: 1002842 CONDITION Extensive significant problems TREND: Unknown PRINCIPAL VULNERABILITY: Arable ploughing New ENTRY: No OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 STENAME: Bowl barrow on Plush Hill 600 metres ESE of Lower Farm, Plush, Piddletrenthide DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015037 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Arable clipping New ENTRY: No OWNER TYPE: Ruth Garner 0117 975 0696 STENAME: Bowl barrow on Plush Hill 740 metres ESE of Lower Farm, Plush, Piddletrenthide DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015038 CONDITION: Private CONTACT: Ruth Garner 0117 975 0696 STENAME: Bowl barrow on Plush Hill 740 metres ESE of Lower Farm, Plush, Piddletrenthide DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015038 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 STENAME: Bowl barrow on Pond Eweleaze 500 metres north east of Dole's Ash Farm, Piddletrenthide DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015035 CONDITION: Extensive significant problems TREND: Declining RRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 STENAME: Bowl barrow on Hog Leaze, Piddletrenthide DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015035 CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1003238	SITE NAME:	Two barrows west of Little Piddle Down, Piddlehir	nton	
RRINCIPAL VULNERABILITY: Arable ploughing NEW BTRYY: No OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 STE NAME: Barrow on College Down, Piddletrenthide DESIGNATION: Scheduled Monument LETENTRY NUMBER: 1002842 CONDITION: Extensive significant problems TREND: Unknown RRINCIPAL VULNERABILITY: Arable ploughing NEW BTRYY: No OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 STE NAME: Bowl barrow on Plush Hill 600 metres ESE of Lower Farm, Plush, Piddletrenthide DESIGNATION: Scheduled Monument LETENTRY NUMBER: 1015037 CONDITION: Generally satisfactory but with significant localised problems TREND: Declining PRINCIPAL VULNERABILITY: Arable clipping NEW BTRYY: No OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 STE NAME: Bowl barrow on Plush Hill 740 metres ESE of Lower Farm, Plush, Piddletrenthide DESIGNATION: Scheduled Monument LETENTRY NUMBER: 1015038 STE NAME: Bowl barrow on Plush Hill 740 metres ESE of Lower Farm, Plush, Piddletrenthide DESIGNATION: Scheduled Monument LETENTRY NUMBER: 1015038 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW BTRYY: No OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 STE NAME: Bowl barrow on Pond Eweleaze 500 metres north east of Dole's Ash Farm, Piddletrenthide DESIGNATION: Scheduled Monument LETENTRY NUMBER: 1015035 CONTACT: Ruth Garner 0117 975 0696 STE NAME: Bowl barrow on Pond Eweleaze 500 metres north east of Dole's Ash Farm, Piddletrenthide DESIGNATION: Scheduled Monument LETENTRY NUMBER: 1015035 CONTACT: Ruth Garner 0117 975 0696 STE NAME: Bowl barrow on Pond Eweleaze 500 metres north east of Dole's Ash Farm, Piddletrenthide DESIGNATION: Scheduled Monument LETENTRY NUMBER: 1015035 CONTACT: Ruth Garner 0117 975 0696 STE NAME: Round Barrow on Hog Leaze, Piddletrenthide DESIGNATION: Scheduled Monument LETENTRY NUMBER: 1003238 CONDITION: Generally unsatisfactory with major localised problems	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002805
OWNER TYPE Private CONTACT: Ruth Garner 0117 975 0696 STE NAME Barrow on College Down, Piddletrenthide DESIGNATION Scheduled Monument UST ENTRY NUMBER: 1002842 CONDITION Extensive significant problems TREND: Unknown PRINCIPAL VALINIFABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 STE NAME Bowl barrow on Plush Hill 600 metres ESE of Lower Farm, Plush, Piddletrenthide DESIGNATION Scheduled Monument LET ENTRY NUMBER: 1015037 CONDITION Generally satisfactory but with significant localised problems PRINCIPAL VALINERABILITY: Arable clipping NEW ENTRY: No OWNER TYPE Private CONTACT: Ruth Garner 0117 975 0696 STE NAME Bowl barrow on Plush Hill 740 metres ESE of Lower Farm, Plush, Piddletrenthide DESIGNATION: Scheduled Monument LET ENTRY NUMBER: 1015038 STE NAME Bowl barrow on Plush Hill 740 metres ESE of Lower Farm, Plush, Piddletrenthide DESIGNATION: Scheduled Monument LET ENTRY NUMBER: 1015038 STE NAME Bowl barrow on Plush Hill 740 metres ESE of Lower Farm, Plush, Piddletrenthide DESIGNATION: Scheduled Monument LET ENTRY NUMBER: 1015038 STE NAME CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VALUERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE Commercial company CONTACT: Ruth Garner 0117 975 0696 STE NAME Bowl barrow on Pond Eweleaze 500 metres north east of Dole's Ash Farm, Piddletrenthide DESIGNATION: Scheduled Monument LET ENTRY NUMBER: 1015035 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VALUERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE Commercial company CONTACT: Ruth Garner 0117 975 0696 STE NAME Bowl barrow on Hog Leaze, Piddletrenthide ESIGNATION: Scheduled Monument LET ENTRY NUMBER: 1003238 CONDITION: Scheduled Monument LET ENTRY NUMBER: 1003238 CONDITION: Scheduled Monument LET ENTRY NUMBER: 1003238	CONDITION:	Extensive significant problems	TREND:	Declining
SITE MAME SITE MAME SITE MAME SITE MAME SITE MAME SITE MAME SOND BOY DESIGNATION SCHEDULER SIGNATION SCHED	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument UST ENTRY NUMBER 1002842 CONDITION: Extensive significant problems TREND: Unknown PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNIRE TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME BOWL barrow on Plush Hill 600 metres ESE of Lower Farm, Plush, Piddletrenthide DESIGNATION: Scheduled Monument UST ENTRY NUMBER 1015037 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY: No OWNER TYPE: Ruth Garner 0117 975 0696 SITE NAME BOWL barrow on Plush Hill 740 metres ESE of Lower Farm, Plush, Piddletrenthide DESIGNATION: Scheduled Monument UST ENTRY NUMBER 1015037 CONDITION: Scheduled Monument UST ENTRY NUMBER 1015038 SITE NAME BOWL barrow on Plush Hill 740 metres ESE of Lower Farm, Plush, Piddletrenthide DESIGNATION: Scheduled Monument UST ENTRY NUMBER 1015038 CONDITION: RETURN NUMBER 1015038 SITE NAME BOWL barrow on Pond Eweleaze 500 metres north east of Dole's Ash Farm, Piddletrenthide DESIGNATION: Scheduled Monument UST ENTRY NUMBER 1015035 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: NO OWNER TYPE: NO OWNER T	OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
CONDITION: Extensive significant problems TREND: Unknown PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY! No OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME Bowl barrow on Plush Hill 600 metres ESE of Lower Farm, Plush, Piddletrenthide DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1015037 CONDITION: Generally satisfactory but with significant localised problems TREND: Declining PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY! No OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME Bowl barrow on Plush Hill 740 metres ESE of Lower Farm, Plush, Piddletrenthide DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1015038 CONDITION: Extensive significant problems TREND: Declining SITE NAME Bowl barrow on Pond Eweleaze 500 metres north east of Dole's Ash Farm, Piddletrenthide DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1015035 CONDITION: Extensive significant problems TREND: Declining	SITE NAME:	Barrow on College Down, Piddletrenthide		
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: Ruth Garner 0117 975 0696 SITE NAME Bowl barrow on Plush Hill 600 metres ESE of Lower Farm, Plush, Piddletrenthide DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015037 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY: No OWNER TYPE Bowl barrow on Plush Hill 740 metres ESE of Lower Farm, Plush, Piddletrenthide DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015038 STIE NAME Bowl barrow on Plush Hill 740 metres ESE of Lower Farm, Plush, Piddletrenthide DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015038 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 SITE NAME Bowl barrow on Pond Eweleaze 500 metres north est of Dole's Ash Farm, Piddletrenthide DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015035 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Commercial company LIST ENTRY NUMBER: 1015035 CONDITION: Extensive significant problems REMENTED: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Commercial company LEAZE, Piddletrenthide DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003238 SITE NAME ROUND BORD Scheduled Monument LIST ENTRY NUMBER: 1003238 CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1003238 Declining	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002842
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015037 CONDITION: Generally satisfactory but with significant localised problems Principal Vulnerability: Arable clipping New ENTRY: No OWNER TYPE: Bowl barrow on Plush Hill 740 metres ESE of Lower Farm, Plush, Piddletrenthide Extensive significant problems Scheduled Monument LIST ENTRY NUMBER: 1015038 CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1015038 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: NO OWNER TYPE: No OWNER TYPE: Commercial company Contact: Ruth Garner 0117 975 0696 SITE NAME Bowl barrow on Pond Eweleaze 500 metres north east of Dole's Ash Farm, Piddletrenthide DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015035 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY NUMBER: 1015035 CONDITION: Extensive significant problems REND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: NO OWNER TYPE: Commercial company Contact: Ruth Garner 0117 975 0696 SITE NAME Bowl barrow on Hog Leaze, Piddletrenthide DESIGNATION: Commercial company LIST ENTRY NUMBER: 1003238 CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1003238	CONDITION:	Extensive significant problems	TREND:	Unknown
SITE NAME Bowl barrow on Plush Hill 600 metres ESE of Lower Farm, Plush, Piddletrenthide DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015037 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRYP: No OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME Bowl barrow on Plush Hill 740 metres ESE of Lower Farm, Plush, Piddletrenthide DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015038 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 SITE NAME Bowl barrow on Pond Eweleaze 500 metres north east of Dole's Ash Farm, Piddletrenthide DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015035 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No OWNER TYPE: Ommercial company New ENTRYP: No OWNER TYPE: Ommercial company LIST ENTRY NUMBER: 1015035 CONDITION: Extensive significant problems REND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No OWNER TYPE Commercial company LIST ENTRYP: No OWNER TYPE ROUNT Arable ploughing NEW ENTRYP: No OWNER TYPE Commercial company LIST ENTRYP NUMBER: 1003238 CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1003238 CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1003238 CONDITION: Generally unsatisfactory with major localised problems	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1015037 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Arable clipping DESIGNATION: Arable clipping Bowl barrow on Plush Hill 740 metres ESE of Lower Farm, Plush, Piddletrenthide DESIGNATION: Scheduled Monument DESIGNATION: Scheduled Monument DESIGNATION: Scheduled Monument DESIGNATION: Arable ploughing PRINCIPAL VULNERABILITY: Arable ploughing DESIGNATION: Scheduled Monument DESIGNATION: Scheduled Monument DESIGNATION: Arable ploughing DESIGNATION: Scheduled Monument DESIGNATION: DECIning DESIGNATION: Scheduled Monument DESIGNATION: DECIning DESIGNATION: Scheduled Monument DESIGNATION: DESIGNATION: DECIning DESI	OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
CONDITION: Generally satisfactory but with significant localised problems TREND: Declining PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRYP: No OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME Bowl barrow on Plush Hill 740 metres ESE of Lower Farm, Plush, Piddletrenthide DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015038 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 SITE NAME Bowl barrow on Pond Eweleaze 500 metres north east of Dole's Ash Farm, Piddletrenthide DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015035 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 SITE NAME Round barrow on Hog Leaze, Piddletrenthide LIS	SITE NAME:	Bowl barrow on Plush Hill 600 metres ESE of Lowe	er Farm, Plush, Pido	lletrenthide
PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRYP: No OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME BOWI barrow on Plush Hill 740 metres ESE of Lower Farm, Plush, Piddletrenthide DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015038 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 SITE NAME BOWI barrow on Pond Eweleaze 500 metres north east of Dole's Ash Farm, Piddletrenthide DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015035 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 SITE NAME Arable ploughing NEW ENTRYP: No OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 SITE NAME Round barrow on Hog Leaze, Piddletrenthide DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003238 CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1003238 CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1003238 CONDITION: Scheduled Monument LIST ENTRY NUMBER: Declining	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015037
OWNER TYPE: Private Bowl barrow on Plush Hill 740 metres ESE of Lower Farm, Plush, Piddletrenthide DESIGNATION: Scheduled Monument LUST ENTRY NUMBER: 1015038 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYY: No OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Bowl barrow on Pond Eweleaze 500 metres north east of Dole's Ash Farm, Piddletrenthide DESIGNATION: Scheduled Monument LUST ENTRY NUMBER: 1015035 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYY: No OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Round barrow on Hog Leaze, Piddletrenthide DESIGNATION: Scheduled Monument LUST ENTRY NUMBER: 1003238 CONDITION: Scheduled Monument LUST ENTRY NUMBER: 1003238 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining	CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
SITE NAME Bowl barrow on Plush Hill 740 metres ESE of Lower Farm, Plush, Piddletrenthide DESIGNATION: Scheduled Monument IUST ENTRY NUMBER: 1015038 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Bowl barrow on Pond Eweleaze 500 metres north east of Dole's Ash Farm, Piddletrenthide DESIGNATION: Scheduled Monument IUST ENTRY NUMBER: 1015035 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY!: No OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Round barrow on Hog Leaze, Piddletrenthide DESIGNATION: Scheduled Monument IUST ENTRY NUMBER: 1003238 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining	PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015038 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY!: NO OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Bowl barrow on Pond Eweleaze 500 metres north east of Dole's Ash Farm, Piddletrenthide DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015035 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY!: NO OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Round barrow on Hog Leaze, Piddletrenthide DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003238 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining	OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Bowl barrow on Pond Eweleaze 500 metres north est of Dole's Ash Farm, Piddletrenthide DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015035 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Round barrow on Hog Leaze, Piddletrenthide DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003238 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining	SITE NAME:	Bowl barrow on Plush Hill 740 metres ESE of Lowe	er Farm, Plush, Pido	lletrenthide
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Bowl barrow on Pond Eweleaze 500 metres north east of Dole's Ash Farm, Piddletrenthide DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015035 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Round barrow on Hog Leaze, Piddletrenthide DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003238 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015038
OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Bowl barrow on Pond Eweleaze 500 metres north east of Dole's Ash Farm, Piddletrenthide DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015035 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Round barrow on Hog Leaze, Piddletrenthide DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003238 CONDITION: Generally unsatisfactory with major localised problems Declining	CONDITION:	Extensive significant problems	TREND:	Declining
SITE NAME: Bowl barrow on Pond Eweleaze 500 metres north east of Dole's Ash Farm, Piddletrenthide DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015035 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: Commercial company CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Round barrow on Hog Leaze, Piddletrenthide DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003238 CONDITION: Declining Declining	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015035 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: NO OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Round barrow on Hog Leaze, Piddletrenthide DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003238 CONDITION: Generally unsatisfactory with major localised problems Declining	OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Round barrow on Hog Leaze, Piddletrenthide DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003238 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining	SITE NAME:	Bowl barrow on Pond Eweleaze 500 metres north	east of Dole's Ash	Farm, Piddletrenthide
PRINCIPAL VULNERABILITY: Arable ploughing OWNER TYPE: Commercial company Round barrow on Hog Leaze, Piddletrenthide DESIGNATION: Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: New ENTRY: Ruth Garner 0117 975 0696 Ruth Garner 0117 975 0696 LIST ENTRY NUMBER: 1003238 TREND: Declining	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015035
OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Round barrow on Hog Leaze, Piddletrenthide DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003238 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining	CONDITION:	Extensive significant problems	TREND:	Declining
SITE NAME: Round barrow on Hog Leaze, Piddletrenthide DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003238 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003238 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining	OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
CONDITION: Generally unsatisfactory with major localised problems TREND: Declining	SITE NAME:	Round barrow on Hog Leaze, Piddletrenthide		
problems			LIST ENTRY NUMBER:	1003238
· · · · · · · · · · · · · · · · · · ·	DESIGNATION:	Scheduled Monument		1003230
PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY!: No		Generally unsatisfactory with major localised		
OWNER TYPE: CONTACT: Ruth Garner 0117 975 0696		Generally unsatisfactory with major localised		

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Bowl barrow on Black Down, 80 metres south eas	t of the Hardy Mor	ument, Portesham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017374
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
TE NAME:	Round barrow north east of Friar Waddon, Portes	ham	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002488
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Two bowl barrows on Black Down immediately ea	st of the Hardy Mo	nument, Portesham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016729
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two round barrows on Ridgeway, Portesham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002758
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Barrow near east boundary of parish, Powerstock		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002809
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Group of barrows east of Northdown Barn, Poxwe	ell	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002770
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round barrow west of Druce Higher Barn, Puddle	town	
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1002874
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Three round barrows on Puddletown Down, Pu	ddletown	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002450
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
TE NAME:	Two round barrows south west of Well House	Cottage, Puddletown	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002875
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Bowl barrow 400 metres north east of Look Fai	rm, Puncknowle	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016370
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Bell barrow 70 metres west of Fidler's Green, S	tinsford	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017262
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Roman fort on Waddon Hill, Stoke Abbott		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002410
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Digging	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Round barrow north east of Hog Hill Barn, Stra	tton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003237
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Dumping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round barrow north west of Jackman's Cross, S	tratton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002470
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
1111 1011 / 12 1 12 1 12 1 1 1 1 1 1	7 that biode prode in the		

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Round barrow on Stratton Down, Stratton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002871
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow on Eype Down 275 metres east of Fr	ogmore Farm, Sym	ondsbury
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016100
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Holditch Court Tower, Thorncombe		
DESIGNATION:	Scheduled Monument, LB grade I	LIST ENTRY NUMBER:	1002835
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Four bowl barrows 710 metres north, 750 metres Tolpuddle	north west and 950	metres north west of Clyffe House
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016378
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Barrow near Eggardon, West Compton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004567
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Dyke south east of Eggardon Hill camp, West Con	npton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002404
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two bowl barrows on Frome Hill 520 metres wes	t of Frome Farm, V	Vest Stafford
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019875
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Enclosure on Mount Pleasant Hill, West S	tafford / Dorchester	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002463
CONDITION:	Extensive significant problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Bowl barrow on Whitcombe Hill 500 met	tres north of Whitcombe Fai	rm, West Stafford / Whitcombe
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017282
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Three bowl barrows 530 metres and 350	metres north east of Whitco	ombe Barn, Whitcombe
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019413
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Oval barrow and three bowl barrows 250 Broadmayne	metres and 330 metres sou	nth of Whitcombe Barn, Whitcombe
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019414
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two round barrows north of Came Farm	, Winterborne Came	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002828
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Long barrow immediately north west of N	1aiden Castle, Winterborne	Monkton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015779
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Long barrow, three bell barrows, fancy ba Winterborne Monkton	rrow and a linear earthwork	800 metres north of Maiden Castle
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015783
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round barrow cemetery immediately sou	th east of Maiden Castle, Wi	interborne Monkton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015778
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Settlement remains north of Maiden Castle, Wir	nterborne Monkton / I	Dorchester
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002409
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Group of barrows south of Goldsmith's Plantation	on, Winterborne St. M	1artin
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002810
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Group of round barrows near Eweleaze Barn, V	Vinterborne St. Martir	1
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002756
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Group of round barrows on and to east of Grea	t Hill, Winterborne S	t. Martin
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004564
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round barrow north of Ridgeway, Winterborne	St. Martin	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002759
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round barrows on Four Barrow Hill, Winterboo	ne St. Martin	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002755
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round barrows on Grove Hill, Winterborne St.	Martin	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002757
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Three barrows south of Hart Hill Plantation, Wi	nterborne St. Martin	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002814
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Two barrows at Rew, Winterborne St. Martin		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002811
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Group of round barrows on Shorn Hill and Bronkl	nam Hill, Winterbo	rne St. Martin / Portesham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002699
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Dumping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bell barrow 100 metres south of Winterbourne Pocemetery, Winterbourne Abbas	oor Lot, part of the	Winterbourne Poor Lot round barrow
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012027
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 400 metres north east of Manor Farm Winterbourne Abbas	m, part of the Poun	d Hill round barrow cemetery,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011692
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Unknown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 450 metres north east of Manor Farm Winterbourne Abbas	m, part of the Poun	d Hill round barrow cemetery,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011691
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Unknown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Triple barrow and bowl barrow forming part of a l metres north east of Winterbourne Poor Lot, Win		nd part of an associated field system 250
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012030
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Unknown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two bell barrows 15 metres north of Well Botton Winterbourne Abbas	n Wood, part of the	e Poor Lot round barrow cemetery,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012029
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Unknown	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

Extensive significant problems Arable ploughing New ENTRY: Commercial company Contract: Ruth Garner 0117 975 0696 Commercial company Contract: Ruth Garner 0117 975 0696 Ruth Garner 0117 975 0696 Ruth Garner 0117 975 0696 Commercial company Contract: Ruth Garner 0117 975 0696 R	SITE NAME:	Four round barrows north west of Blagdon Barr	ı, Winterbourne Steep	oleton
RINCOPUL VULNEARABILTY: Arable ploughing Commercial company Commercial	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002750
COMPACT: Ruth Gamer 0117 975 0696 Commercial company COMTACT: Ruth Gamer 0117 975 0696 CERCANTON: Scheduled Monument Extensive significant problems TRINE: Declining New NITES: No COMINGENT NUMBER COMING	CONDITION:	Extensive significant problems	TREND:	Declining
Long barrow on Pound Hill, Winterbourne Steepleton Scheduled Monument Extensive significant problems RINGRA UNISERABITY: Arable ploughing Arable plough	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Scheduled Monument LIST DITAYNUMBERS 1002687 CONDITION Extensive significant problems TILEND Declining RINGER MUNICIPAL MUNICIPAL PRIVATE PRIVATE PRIVATE PRIVATE CONTROL SCHEDULE PRIVATE PRIVATE PRIVATE CONTROL SCHEDULE PRIVATE SCHEDULE PRIVAT	OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
Extensive significant problems TREND: Declining NEW STREAM: Arable ploughing NEW STREAM: No ONDITION: Private CONTACT: Ruth Garner 0117 975 0696 THE MANIE ROUND Arable ploughing NEW STREAM: No ONDITION: Scheduled Monument ILST ENTRY MURRER. 1002870 Declining NEW STREAM: No Scheduled Monument ILST ENTRY MURRER. 1002870 Declining NEW STREAM: No ONDITION: Extensive significant problems IRSD. Declining NEW STREAM: No ONDITION: Private CONTACT: Ruth Garner 0117 975 0696 THE MANIE. Round barrow south west of village, Winterbourne Steepleton USE ONTACT: Ruth Garner 0117 975 0696 THE MANIE. Round barrow south west of village, Winterbourne Steepleton Scheduled Monument USE DITATEN NUMBER. 1002751 UNDITION: Problems Scheduled Monument New STREAM: No ONDITION: Problems SEROMATION: Scheduled Monument New STREAM: No ONDITION: Problems Scheduled Monument ISE ONTACT: Ruth Garner 0117 975 0696 THE MANIE ROUND Scheduled Monument ISE ONTACT: Ruth Garner 0117 975 0696 SEROMATION: Scheduled Monument ISE ONTACT: Ruth Garner 0117 975 0696 SEROMATION: Scheduled Monument ISE ONTACT: Ruth Garner 0117 975 0696 SEROMATION: Scheduled Monument ISE ONTACT: Ruth Garner 0117 975 0696 SEROMATION: Scheduled Monument ISE ONTACT: Ruth Garner 0117 975 0696 SEROMATION: Scheduled Monument ISE ONTACT: Ruth Garner 0117 975 0696 SEROMATION: Scheduled Monument ISE ONTACT: Ruth Garner 0117 975 0696 SEROMATION: Scheduled Monument ISE ONTACT: Ruth Garner 0117 975 0696 SEROMATION: Scheduled Monument ISE ONTACT: Ruth Garner 0117 975 0696 SEROMATION: Scheduled Monument ISE ONTACT: Ruth Garner 0117 975 0696 SEROMATION: Scheduled Monument ISE ONTACT: Ruth Garner 0117 975 0696 SEROMATION: Scheduled Monument ISE ONTACT: Ruth Garner 0117 975 0696 SEROMATION: Scheduled Monument ISE ONTACT: Ruth Garner 0117 975 0696 SEROMATION: Scheduled Monument, part in RPG grade II ISE ONTACT: Ruth Garner 0117 975 0696 SEROMATION: Scheduled Monument, part in RPG grade II ISE ONTACT: Ruth Garner 0117 975 0696 SEROMATION: Scheduled Monument, part in RPG grade II ISE ONTACT: Ruth Ga	ITE NAME:	Long barrow on Pound Hill, Winterbourne Stee	pleton	
RENCIPAL VOLUNERABILITY: Arable ploughing NEW ENTRY: No CONTACT: Ruth Garner 0117 975 0696 (ITE NAME: Round barrow on Pound Hill, Winterbourne Steepleton SEGMATION: Scheduled Monument LETENTRY NUMBER: 1002870 (ITE NAME: Round barrow season of violater bournes) (ITE NAME: Round barrow season of violater bournes) (ITE NAME: Round barrow south west of village, Winterbourne Steepleton SEGMATION: Scheduled Monument INTENTRY NUMBER: 1002751 (ITE NAME: Round barrow south west of village, Winterbourne Steepleton SEGMATION: Scheduled Monument INTENTRY NUMBER: 1002751 (ITE NAME: Round barrow south west of village, Winterbourne Steepleton SEGMATION: Scheduled Monument INTENTRY NUMBER: 1002751 (ITE NAME: Round barrow) (ITE NAME: Round company (ITE	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002687
Private Round barrow on Pound Hill, Winterbourne Steepleton SESCINATION: Scheduled Monument LEST ENTRY NUMBER: 1002870 DECIDING Extensive significant problems TRAND: Declining RENCHAL VULNEMBRUTY: Arable ploughing NEW ENTRY: No DECIDING EXECUTION: Scheduled Monument LEST ENTRY NUMBER: 1002751 RENCHAL VULNEMBRUTY: Arable ploughing NEW ENTRY: No RESIGNATION: Scheduled Monument LEST ENTRY NUMBER: 1002751 CONDITION: Generally unsatisfactory with major localised Problems RENCHAL VULNEMBRUTY: Animal burrowing - moderate NEW ENTRY: No DECIDING EXECUTION: Scheduled Monument LEST ENTRY NUMBER: 1003306 DENTRY NUMBER: Private CONTACT: Ruth Garner 0117 975 0696 DENTRY NUMBER: Private CONTACT: Ruth Garner 0117 975 0696 DETERMINED TO THE OWN DECIDING NEW ENTRY: No DECIDING EXECUTION: Scheduled Monument LEST ENTRY NUMBER: 1003308 DECIDING EXECUTION: Scheduled Monument LEST ENTRY NUMBER: 1003308 DENTRY NUMBER: 1003308 DECIDING EXECUTION: Scheduled Monument LEST ENTRY NUMBER: 1003308 DECIDING EXECUTION: Scheduled Monument LEST ENTRY NUMBER: 1003308 DECIDING EXECUTION: Scheduled Monument LEST ENTRY NUMBER: 1003308 DENTRY NUMBER: 1002865 DECIDING EXECUTION: Arable ploughing NEW ENTRY: No DECIDING EXECUTION: Scheduled Monument LEST ENTRY NUMBER: 1002865 DECIDING EXECUTION: Arable ploughing NEW ENTRY: No DECIDING EXECUTION: Arable company CONTACT: Ruth Garner 0117 975 0696 DENTRY NUMBER: 1002865 DECIDING EXECUTION: Arable cloping NEW ENTRY: NO DECIDING EXECUTION: Arable cloping NEW	CONDITION:	Extensive significant problems	TREND:	Declining
Round barrow on Pound Hill, Winterbourne Steepleton Scheduled Monument Extensive significant problems RINCIPAL VULNERABILITY: Arable ploughing RINCIPAL VULNERABILITY: RINCIPAL VULNERABILITY: Arable ploughing RINCIPAL VULNERABILITY: RINCIPAL VULNERABILITY: Arable ploughing RINCIPAL VULNERABILITY: COMMINIST PRESENCE AND ARABLE PLOUGH AND ARABLE PLOUG	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Scheduled Monument UST ENTRY NUMBER CONDITION: Extensive significant problems TERM: Declining RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No Arable ploughing NEW ENTRY: No RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No RESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1002751 CONDITION: Generally unsatisfactory with major localised problems RINCIPAL VULNERABILITY: Animal burrowing - moderate NEW ENTRY: No CONNECTE: Ruth Garner 0117 975 0696 RINCIPAL VULNERABILITY: Animal burrowing - moderate NEW ENTRY: No CONNECTE: Ruth Garner 0117 975 0696 RIE NAME: Round barrows on Sheep Down, Winterbourne Steepleton ESEGNATION: Scheduled Monument UST ENTRY NUMBER: 1003306 CONDITION: Extensive significant problems TERMD: Declining RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No DOWNER TYPE: Three round barrows east of Smitten Corner, Winterbourne Steepleton ESEGNATION: Scheduled Monument UST ENTRY NUMBER: 1003308 TER NAME: Three round barrows east of Smitten Corner, Winterbourne Steepleton Scheduled Monument UST ENTRY NUMBER: 1003308 CONDITION: Extensive significant problems TERMD: Declining RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No DOWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 TER NAME: Three round barrows on North Hill, Winterbourne Steepleton Scheduled Monument UST ENTRY NUMBER: 1003265 CONDITION: Scheduled Monument UST ENTRY NUMBER: 1002865 CONDITION: Scheduled Monument UST ENTRY NUMBER: 1002696 CONDITION: Scheduled Monument, part in RPG grade II UST ENTRY NUMBER: 1002696 CONDITION: Extensive significant problems RENDED NOTACT: Ruth Garner 0117 975 0696 RENDER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 RENDER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696	OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
Extensive significant problems RENCHAL VOLUNERABILITY: Arable ploughing NEW ENTRY: No Arable ploughing NEW ENTRY: No ROWNER TYPE: Private Round barrow south west of village, Winterbourne Steepleton ESGNATION: Scheduled Monument LIST ENTRY NUMBER: 100275 Generally unsatisfactory with major localised problems RENCHAL VULNERABILITY: Animal burrowing - moderate NEW ENTRY: No OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 RENCHAL VULNERABILITY: Animal burrowing - moderate Round barrows on Sheep Down, Winterbourne Steepleton SESGNATION: Scheduled Monument ESTEND: Declining RENCHAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Private Three round barrows east of Smitten Corner, Winterbourne Steepleton SESGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003306 TENAME: Three round barrows east of Smitten Corner, Winterbourne Steepleton SESGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003308 TRENCHAL VULNERABILITY: Arable ploughing NEW ENTRY: No SCHEDULA VULNERABILITY: No SCHEDULA VULNERABILITY: Arable clipping NEW ENTRY: No OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 TENAME Group of barrows near Big Wood, Winterbourne Steepleton / Winterbourne Abbas SESSNATION: Scheduled Monument, part in RPG grade II LIST ENTRY NUMBER: 1002696 CONDITION: Extensive significant problems NEW ENTRY: No Declining NEW ENTRY: No De	ITE NAME:	Round barrow on Pound Hill, Winterbourne Ste	epleton	
Arable ploughing NEWENTRY: No DWNERTYPE: Private CONTACT: Ruth Garner 0117 975 0696 TENAME ROund barrow south west of village, Winterbourne Steepleton DESONATION: Scheduled Monument UST ENTRY NUMBER: 1002751 CONDITION: Generally unsatisfactory with major localised problems RINGIRAL VULNERABILITY: Animal burrowing - moderate NEWENTRY: No DWNERTYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 THE NAME ROUND Scheduled Monument UST ENTRY NUMBER: 1003306 THE NAME ROUND Scheduled Monument UST ENTRY NUMBER: 1003306 THE NAME Scheduled Monument UST ENTRY NUMBER: 1003306 THE NAME CONTACT: Ruth Garner 0117 975 0696 THE NAME TYPE: Private CONTACT: Ruth Garner 0117 975 0696 THE NAME THE Three round barrows east of Smitten Corner, Winterbourne Steepleton DESONATION: Scheduled Monument UST ENTRY NUMBER: 1003308 THE NAME Three round barrows east of Smitten Corner, Winterbourne Steepleton DESONATION: Scheduled Monument UST ENTRY NUMBER: 1003308 THE NAME Three round barrows east of Smitten Corner, Winterbourne Steepleton DESONATION: Scheduled Monument UST ENTRY NUMBER: 1003308 DECINITION: Extensive significant problems TRUND: Declining PRINCIPLA VULNERABILITY: Arable ploughing NEWENTRY: No DWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 THE NAME Two round barrows on North Hill, Winterbourne Steepleton DESONATION: Scheduled Monument UST ENTRY NUMBER: 1002865 DECINITION: Generally unsatisfactory with major localised TRUND: Declining PRINCIPLA VULNERABILITY: Arable clipping NEWENTRY: No DWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 THE NAME Group of barrows near Big Wood, Winterbourne Steepleton / Winterbourne Abbas DESONATION: Scheduled Monument, part in RPG grade II UST ENTRY NUMBER: 1002696 DECINITION: Extensive significant problems TRUND: Decining DEVENTION: Arable clipping NEWENTRY: No DECIning DECINION: Extensive significant problems TRUND: Decining DEVENTION: Arable clipping NEWENTRY: No DECINION: DECINING	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002870
Private Round barrow south west of village, Winterbourne Steepleton Scheduled Monument International Trend: Declining Scheduled Monument International Trend: No Commercial company Contact: Ruth Garner 0117 975 0696 The NAME Round barrows on Sheep Down, Winterbourne Steepleton Scheduled Monument International Trend: Declining Reschantone: Scheduled Monument International Trend: No Conditional Extensive significant problems Trend: Contact: Ruth Garner 0117 975 0696 The NAME Three round barrows east of Smitten Corner, Winterbourne Steepleton Scheduled Monument International Internati	CONDITION:	Extensive significant problems	TREND:	Declining
Round barrow south west of village, Winterbourne Steepleton Scheduled Monument Generally unsatisfactory with major localised problems RINCIPAL VALINERABILITY: Animal burrowing - moderate NEW ENTRY: No CONTACT: Ruth Garner 0117 975 0696 RESIGNATION: Scheduled Monument UST ENTRY NUMBER: Round barrows on Sheep Down, Winterbourne Steepleton SEGNATION: Scheduled Monument UST ENTRY NUMBER: I 003306 Extensive significant problems RINCIPAL VALINERABILITY: Arable ploughing NEW ENTRY: Private CONTACT: Ruth Garner 0117 975 0696 RITE NAMI: Three round barrows east of Smitten Corner, Winterbourne Steepleton SEGNATION: Scheduled Monument UST ENTRY NUMBER: I 003308 TENNO: Declining NEW ENTRY: No SCHOOLITION: Extensive significant problems TREND: Declining NEW ENTRY: No Declining NEW ENTRY: No Declining NEW ENTRY: No OWNER TYPE: Two round barrows on North Hill, Winterbourne Steepleton Scheduled Monument UST ENTRY NUMBER: I 002865 TREND: Declining NEW ENTRY: No OWNER TYPE: Two round barrows on North Hill, Winterbourne Steepleton Scheduled Monument UST ENTRY NUMBER: I 002865 Generally unsatisfactory with major localised problems RINCIPAL VALUNERABILITY: Arable clipping NEW ENTRY: No OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 TREND: Declining NEW ENTRY: No OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 TREND: Declining NEW ENTRY: No OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 TREND: Declining NEW ENTRY: No Declining NEW ENTRY:	RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Scheduled Monument Scheduled Monument Generally unsatisfactory with major localised problems RINCIPAL VULNERABILITY: Animal burrowing - moderate NEW ENTRY: No OMNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 ATE NAME: Round barrows on Sheep Down, Winterbourne Steepleton Scheduled Monument Extensive significant problems TREND: Declining NEW ENTRY: No OMNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 ATE NAME: Round barrows on Sheep Down, Winterbourne Steepleton Scheduled Monument Extensive significant problems TREND: Declining NEW ENTRY: No OMNER TYPE: Three round barrows east of Smitten Corner, Winterbourne Steepleton Scheduled Monument Extensive significant problems TREND: Declining NEW ENTRY: No OMNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 ATE NAME: Two round barrows on North Hill, Winterbourne Steepleton DESIGNATION: Scheduled Monument Extensive significant problems TREND: Declining NEW ENTRY: No ONTACT: Ruth Garner 0117 975 0696 TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No ONTACT: Ruth Garner 0117 975 0696 TREND: Declining NEW ENTRY: No ONTACT: Ruth Garner 0117 975 0696 TREND: Declining PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY: No ONTACT: Ruth Garner 0117 975 0696 TREND: Declining PRINCIPAL VULNERABILITY: No ONTACT: Ruth Garner 0117 975 0696 TREND: Declining PRINCIPAL VULNERABILITY: No ONTACT: Ruth Garner 0117 975 0696 TREND: Declining DESIGNATION: Scheduled Monument, part in RPG grade II UST ENTRY NUMBER: I 002696 EXTENAME Group of barrows near Big Wood, Winterbourne Steepleton / Winterbourne Abbas DESIGNATION: Scheduled Monument, part in RPG grade II UST ENTRY NUMBER: I 002696 Declining NEW ENTRY: No Declining NEW ENTRY: No	OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
Generally unsatisfactory with major localised problems RINCIPAL WUNERABUTY: Animal burrowing - moderate Animal burrowing - moderate NEW ENTRY: No COMMERTYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 ATE NAME: Round barrows on Sheep Down, Winterbourne Steepleton Sesignation: Scheduled Monument LIST ENTRY NUMBER: 1003306 CONDITION: Extensive significant problems TREND: Declining RINCIPAL WUNERABUTY: Arable ploughing NEW ENTRY: No CONTACT: Ruth Garner 0117 975 0696 ATE NAME: Three round barrows east of Smitten Corner, Winterbourne Steepleton Scheduled Monument LIST ENTRY NUMBER: 1003308 CONDITION: Extensive significant problems TREND: Declining RINCIPAL WUNERABUTY: Arable ploughing RINCIPAL WUNERABUTY: Arable ploughing RINCIPAL WUNERABUTY: No CONTACT: Ruth Garner 0117 975 0696 ATE NAME: Two round barrows on North Hill, Winterbourne Steepleton SESSIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002865 CONDITION: Generally unsatisfactory with major localised problems RINCIPAL WUNERABUTY: Arable clipping RINCIPAL WUNERABUTY: Arable clipping NEW ENTRY: No COMMERTYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 ARE NAME: Two round barrows on North Hill, Winterbourne Steepleton SESSIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002865 CONDITION: Generally unsatisfactory with major localised problems RINCIPAL WUNERABUTY: Arable clipping NEW ENTRY: No CONTACT: Ruth Garner 0117 975 0696 ARE NAME: Group of barrows near Big Wood, Winterbourne Steepleton / Winterbourne Abbas DESIGNATION: Scheduled Monument, part in RPG grade II LIST ENTRY NUMBER: 1002696 CONDITION: Extensive significant problems RINCIPAL WUNERABUTY: Arable ploughing NEW ENTRY: No CONTACT: Ruth Garner 0117 975 0696	ITE NAME:	Round barrow south west of village, Winterbou	rne Steepleton	
Problems Animal burrowing - moderate New ENTRY: No No Noverer type: Commercial company Contact: Ruth Garner 0117 975 0696 Resignation: Scheduled Monument List entry number: Declining No No No No No No No No No N	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002751
Commercial company CONTACT: Ruth Garner 0117 975 0696 RENAME Round barrows on Sheep Down, Winterbourne Steepleton Scheduled Monument UST ENTRY NUMBER: 1003306 CONDITION: Extensive significant problems RENCIPAL VULNERABILITY: Arable ploughing RENCIPAL VULNERABILITY: Arable ploughing RENCIPAL VULNERABILITY: Arable ploughing RENCIPAL VULNERABILITY: Arable ploughing RESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1003308 CONTACT: Ruth Garner 0117 975 0696 RENCIPAL VULNERABILITY: Arable ploughing RENCIPAL VULNERABILITY: Arable ploughing RENCIPAL VULNERABILITY: Arable ploughing RENCIPAL VULNERABILITY: No CONTACT: Ruth Garner 0117 975 0696 TE NAME Two round barrows on North Hill, Winterbourne Steepleton RESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1002865 CONDITION: Generally unsatisfactory with major localised problems RENCIPAL VULNERABILITY: No CONTACT: Ruth Garner 0117 975 0696 RENCIPAL VULNERABILITY: No CONTACT: Ruth Garner 0117 975 0696 RENCIPAL VULNERABILITY: No CONTACT: Ruth Garner 0117 975 0696 RENCIPAL VULNERABILITY: No CONTACT: Ruth Garner 0117 975 0696 RENCIPAL VULNERABILITY: No CONTACT: Ruth Garner 0117 975 0696 RENCIPAL VULNERABILITY: No CONTACT: Ruth Garner 0117 975 0696 RENCIPAL VULNERABILITY: No CONTACT: Ruth Garner 0117 975 0696 RENCIPAL VULNERABILITY: No CONTACT: Ruth Garner 0117 975 0696 RENCIPAL VULNERABILITY: No CONTACT: Ruth Garner 0117 975 0696 RENCIPAL VULNERABILITY: No CONTACT: Ruth Garner 0117 975 0696 RENCIPAL VULNERABILITY: No CONTACT: Ruth Garner 0117 975 0696 RENCIPAL VULNERABILITY: No CONTACT: Ruth Garner 0117 975 0696 RENCIPAL VULNERABILITY: No CONTACT: Ruth Garner 0117 975 0696 RENCIPAL VULNERABILITY: No CONTACT: Ruth Garner 0117 975 0696 RENCIPAL VULNERABILITY: No CONTACT: Ruth Garner 0117 975 0696	ONDITION:		TREND:	Declining
TENAME Round barrows on Sheep Down, Winterbourne Steepleton Scheduled Monument UST ENTRY NUMBER: 1003306 CONDITION: Extensive significant problems TREND: Declining RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1003308 THE NAME Three round barrows east of Smitten Corner, Winterbourne Steepleton DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1003308 CONDITION: Extensive significant problems TREND: Declining RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No DOWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 THE NAME Two round barrows on North Hill, Winterbourne Steepleton DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1002865 THE NAME Two round barrows on North Hill, Winterbourne Steepleton DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1002865 CONDITION: Generally unsatisfactory with major localised problems RINCIPAL VULNERABILITY: No DOWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 DESIGNATION: Generally unsatisfactory with major localised problems RINCIPAL VULNERABILITY: No DOWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 DESIGNATION: Scheduled Monument, part in RPG grade II UST ENTRY NUMBER: 1002696 DESIGNATION: Scheduled Monument, part in RPG grade II UST ENTRY NUMBER: 1002696 DONDITION: Extensive significant problems TREND: Declining RINCIPAL VULNERABILITY: No	PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
ESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003306 CONDITION: Extensive significant problems TREND: Declining RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No Declining RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No DECINITION: Ruth Garner 0117 975 0696 THE NAME: Three round barrows east of Smitten Corner, Winterbourne Steepleton Scheduled Monument LIST ENTRY NUMBER: 1003308 CONDITION: Extensive significant problems TREND: Declining RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No DECINITION: Commercial company CONTACT: Ruth Garner 0117 975 0696 THE NAME: Two round barrows on North Hill, Winterbourne Steepleton Scheduled Monument LIST ENTRY NUMBER: 1002865 CONDITION: Generally unsatisfactory with major localised problems RINCIPAL VULNERABILITY: Arable clipping NEW ENTRYP: No Declining RINCIPAL VULNERABILITY: Arable clipping NEW ENTRYP: No Declining THE NAME: Group of barrows near Big Wood, Winterbourne Steepleton / Winterbourne Abbas ESIGNATION: Scheduled Monument, part in RPG grade II LIST ENTRY NUMBER: 1002696 CONDITION: Extensive significant problems TREND: Declining RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No)WNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
Extensive significant problems TREND: Declining RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No Private CONTACT: Ruth Garner 0117 975 0696 TE NAME: Three round barrows east of Smitten Corner, Winterbourne Steepleton ESIGNATION: Scheduled Monument Extensive significant problems RINCIPAL VULNERABILITY: Arable ploughing RINCIPAL VULNERABILITY: Arable ploughing RINCIPAL VULNERABILITY: Arable ploughing TWO round barrows on North Hill, Winterbourne Steepleton ESIGNATION: Scheduled Monument ESIGNATION: Scheduled Monument ESIGNATION: Scheduled Monument ESIGNATION: Scheduled Monument ESIGNATION: Generally unsatisfactory with major localised problems RINCIPAL VULNERABILITY: Arable clipping NEW ENTRYP: No Declining RINCIPAL VULNERABILITY: Arable clipping NEW ENTRYP: No CONTACT: Ruth Garner 0117 975 0696 TE NAME Group of barrows near Big Wood, Winterbourne Steepleton / Winterbourne Abbas ESIGNATION: Scheduled Monument, part in RPG grade II LIST ENTRY NUMBER: 1002696 CONDITION: Extensive significant problems TREND: Declining RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No	TE NAME:	Round barrows on Sheep Down, Winterbourne	Steepleton	
RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No DWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 THE NAME: Three round barrows east of Smitten Corner, Winterbourne Steepleton DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003308 DOUNDITION: Extensive significant problems TREND: Declining RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No DOWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 THE NAME: Two round barrows on North Hill, Winterbourne Steepleton DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002865 CONDITION: Generally unsatisfactory with major localised problems RINCIPAL VULNERABILITY: Arable clipping NEW ENTRY?: No DOWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 THE NAME: Group of barrows near Big Wood, Winterbourne Steepleton / Winterbourne Abbas DESIGNATION: Scheduled Monument, part in RPG grade II LIST ENTRY NUMBER: 1002696 EXTENAME: Group of barrows significant problems TREND: Declining RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003306
Private CONTACT: Ruth Garner 0117 975 0696 The name: Three round barrows east of Smitten Corner, Winterbourne Steepleton Scheduled Monument LIST ENTRY NUMBER: 1003308 CONDITION: Extensive significant problems TREND: Declining RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYY: No CONTACT: Ruth Garner 0117 975 0696 The name: Two round barrows on North Hill, Winterbourne Steepleton Scheduled Monument LIST ENTRY NUMBER: 1002865 CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1002865 CONDITION: Generally unsatisfactory with major localised problems RINCIPAL VULNERABILITY: Arable clipping NEW ENTRYY: No CONTACT: Ruth Garner 0117 975 0696 THE NAME: Type: Commercial company CONTACT: Ruth Garner 0117 975 0696 THE NAME: Group of barrows near Big Wood, Winterbourne Steepleton / Winterbourne Abbas Declining THE NAME: Group of barrows near Big Wood, Winterbourne Steepleton / Winterbourne Abbas Declining Extensive significant problems TREND: Declining RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYY: No	CONDITION:	Extensive significant problems	TREND:	Declining
Three round barrows east of Smitten Corner, Winterbourne Steepleton Scheduled Monument Extensive significant problems TREND: Declining RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: Commercial company CONTACT: Ruth Garner 0117 975 0696 TE NAME Two round barrows on North Hill, Winterbourne Steepleton Scheduled Monument UST ENTRY NUMBER: CONTACT: Declining RINCIPAL VULNERABILITY: Arable clipping NEW ENTRY?: No Declining RINCIPAL VULNERABILITY: Arable clipping NEW ENTRY?: Commercial company CONTACT: Ruth Garner 0117 975 0696 TREND: Declining NEW ENTRY?: No TREND: Declining NEW ENTRY?: No CONTACT: Ruth Garner 0117 975 0696 THE NAME Group of barrows near Big Wood, Winterbourne Steepleton / Winterbourne Abbas DESIGNATION: Scheduled Monument, part in RPG grade II LIST ENTRY NUMBER: 1002696 CONDITION: Extensive significant problems TREND: Declining NEW ENTRY NUMBER: No No NEW ENTRY NUMBER: No NEW ENTRY NUMBER: No NEW ENTRY NUMBER: No NO NEW ENTRY NUMBER: NO NEW ENTRY NU	RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Scheduled Monument Extensive significant problems TREND: Declining RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No COMTACT: Ruth Garner 0117 975 0696 TENAME: Two round barrows on North Hill, Winterbourne Steepleton Scheduled Monument UST ENTRY NUMBER: 1002865 CONDITION: Generally unsatisfactory with major localised problems RINCIPAL VULNERABILITY: Arable clipping NEW ENTRY?: No CONTACT: Ruth Garner 0117 975 0696 TREND: Declining RINCIPAL VULNERABILITY: Arable clipping NEW ENTRY?: No CONTACT: Ruth Garner 0117 975 0696 TENAME: Group of barrows near Big Wood, Winterbourne Steepleton / Winterbourne Abbas SESIGNATION: Scheduled Monument, part in RPG grade II UST ENTRY NUMBER: 1002696 CONDITION: Extensive significant problems TREND: Declining RINCIPAL VULNERABILITY: No	WNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
Extensive significant problems TREND: Declining RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 TE NAME: Two round barrows on North Hill, Winterbourne Steepleton Scheduled Monument ESIGNATION: Scheduled Monument Generally unsatisfactory with major localised problems RINCIPAL VULNERABILITY: Arable clipping NEW ENTRY?: No OWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 TE NAME: Group of barrows near Big Wood, Winterbourne Steepleton / Winterbourne Abbas SESIGNATION: Scheduled Monument, part in RPG grade II LIST ENTRY NUMBER: 1002696 CONDITION: Extensive significant problems TREND: Declining NEW ENTRY?: No	ITE NAME:	Three round barrows east of Smitten Corner, V	Vinterbourne Steeplet	on
RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No COMMER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 THE NAME: Two round barrows on North Hill, Winterbourne Steepleton Scheduled Monument LIST ENTRY NUMBER: 1002865 CONDITION: Generally unsatisfactory with major localised problems RINCIPAL VULNERABILITY: Arable clipping NEW ENTRY: No CONTACT: Ruth Garner 0117 975 0696 THE NAME: Group of barrows near Big Wood, Winterbourne Steepleton / Winterbourne Abbas Scheduled Monument, part in RPG grade II LIST ENTRY NUMBER: 1002696 CONDITION: Extensive significant problems TREND: Declining RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003308
Commercial company CONTACT: Ruth Garner 0117 975 0696 Two round barrows on North Hill, Winterbourne Steepleton Scheduled Monument LIST ENTRY NUMBER: 1002865 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable clipping CONTACT: Ruth Garner 0117 975 0696 TREND: Declining NEW ENTRY?: No CONTACT: Ruth Garner 0117 975 0696 TRENAME: Group of barrows near Big Wood, Winterbourne Steepleton / Winterbourne Abbas DESIGNATION: Scheduled Monument, part in RPG grade II LIST ENTRY NUMBER: 1002696 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	CONDITION:	Extensive significant problems	TREND:	Declining
Two round barrows on North Hill, Winterbourne Steepleton Sesignation: Scheduled Monument LIST ENTRY NUMBER: 1002865 CONDITION: Generally unsatisfactory with major localised problems RINCIPAL VULNERABILITY: Arable clipping NEW ENTRY?: No DWNER TYPE: Commercial company CONTACT: Ruth Garner 0117 975 0696 THE NAME: Group of barrows near Big Wood, Winterbourne Steepleton / Winterbourne Abbas DESIGNATION: Scheduled Monument, part in RPG grade II LIST ENTRY NUMBER: 1002696 EXTENDITION: Extensive significant problems TREND: Declining RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Scheduled Monument Generally unsatisfactory with major localised problems RINCIPAL VULNERABILITY: Arable clipping New ENTRY?: Commercial company New ENTRY?: Contact: Ruth Garner 0117 975 0696 CONTACT: Ruth Garner 0117 975 0696 LIST ENTRY NUMBER: Declining New ENTRY?: No CONTACT: Ruth Garner 0117 975 0696 Extensive significant problems TREND: Declining New ENTRY?: No No No No No No No No No N	WNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
Generally unsatisfactory with major localised problems RINCIPAL VULNERABILITY: Arable clipping Commercial company Contact: Ruth Garner 0117 975 0696	ITE NAME:	Two round barrows on North Hill, Winterbour	ne Steepleton	
problems PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY?: No Commercial company CONTACT: Ruth Garner 0117 975 0696 Group of barrows near Big Wood, Winterbourne Steepleton / Winterbourne Abbas DESIGNATION: Scheduled Monument, part in RPG grade II LIST ENTRY NUMBER: 1002696 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002865
Commercial company CONTACT: Ruth Garner 0117 975 0696 Group of barrows near Big Wood, Winterbourne Steepleton / Winterbourne Abbas DESIGNATION: Scheduled Monument, part in RPG grade II LIST ENTRY NUMBER: 1002696 Extensive significant problems TREND: Declining RINCIPAL VULNERABILITY: No	CONDITION:		TREND:	Declining
Group of barrows near Big Wood, Winterbourne Steepleton / Winterbourne Abbas DESIGNATION: Scheduled Monument, part in RPG grade II LIST ENTRY NUMBER: 1002696 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: No	PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument, part in RPG grade II LIST ENTRY NUMBER: 1002696 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No		Commercial company	CONTACT:	Ruth Garner 0117 975 0696
Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	OWNER TYPE:			
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No		Group of barrows near Big Wood, Winterbourn	ne Steepleton / Winte	rbourne Abbas
	OWNER TYPE: SITE NAME: DESIGNATION:		•	
DWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696	ITE NAME: DESIGNATION:	Scheduled Monument, part in RPG grade II	LIST ENTRY NUMBER:	1002696
	SITE NAME: DESIGNATION: CONDITION:	Scheduled Monument, part in RPG grade II Extensive significant problems	LIST ENTRY NUMBER: TREND:	1002696 Declining

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

HERITAGE AT RISK 2013 / SOUTH WEST / WEST DORSET / WEYMOUTH AND PORTLAND					
SITE NAME:	Bowl barrow I k	Bowl barrow I kilometre south west of Manor Farm, Wraxall			
DESIGNATION:	Scheduled Monur	Scheduled Monument		1015051	
CONDITION:	Generally satisfactory but with significant localised problems		TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No	
OWNER TYPE:	Private		CONTACT:	Ruth Garner 0117 975 0696	
	SITE NAME:	Kingston Maurward, Stinsford	Designed landscape surrounding early C18 house. Late landscape phases include formal Edwardian gardens, no open to the public. House forms nucleus of expanding land-based college. Many post-war recent buildings, wit impacts on view lines and appreciation of designed landscape. Natural England has grant aided a plan for the park (completed 2011) which may help to guide future restoration and management.		
	DESIGNATION:	Registered Park and Garden grade II*, 8 LBs, part in SM, part in CA			
	CONDITION:	Generally satisfactory but with minor localised problems			
			1 C3C01 attO11 attO1	nanagement.	

© English Heritage

VULNERABILITY: Medium TREND: Stable **NEW ENTRY?:** No OWNER TYPE: Educational (state sector) LIST ENTRY NUMBER: 1000719

Contact: Ruth Garner 0117 975 0696

Contact: Ruth Garner 0117 975 0696

Contact: Ruth Garner 0117 975 0696

WEYMOUTH AND PORTLAND

OWNER TYPE:

OWNER TYPE:

LIST ENTRY NUMBER:



© English Heritage Archive

Rufus Castle, Church Ope SITE NAME: Road, Easton, Portland Scheduled Monument and Listed DESIGNATION: Buildings - I grade I; I grade II*, LB grade II, WHS CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: D (D)

LIST ENTRY NUMBER: 1002698 and 1280727; 1205384

Private

Present structure probably late C15, on site of earlier building captured in 1142 by Earl Robert of Gloucester. Ruinous and in need of conservative repair and consolidation. Scheme of repair and urgent works carried out in 2010 with English Heritage grant.



SITE NAME: Church of St Peter, Grove Road, Grove, Portland DESIGNATION: Listed Building grade II* CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C)

Former robust Romanesque church, erected in 1872. Built by convict labour from Portland's prison and later transferred to the parish. No longer used for worship and in poor condition.



Maiden Street Methodist SITE NAME: Church, Maiden Street, Weymouth DESIGNATION: Listed Building grade II* CONDITION: Very bad OCCUPANCY:

Private

1205607

© English Heritage

Vacant/not in use PRIORITY CATEGORY: D(D)OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1142294

Former church. Fire in January 2002 left the church a gutted, roofless ruin. Subsequent health and safety works completely cleared the interior. Consent has been granted but not implemented for conversion/reconstruction to a mixed residential and commercial use. The new owners submitted an application for restoration of part of the building. An initial meeting was held in 2012 with the new owner but as of May 2013 no further progress had been

made.

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

SITE NAME:	Group of round barrows on Ridgeway		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002760
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Battery 200 yards (180 metres) east of the Naval c	emetery, Portland	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002412
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	RAF Portland, site of Rotor early warning radar sta	tion, Portland	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021302
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:			
	The Verne Citadel, Portland		
DESIGNATION:	The Verne Citadel, Portland Scheduled Monument, 4 LBs	LIST ENTRY NUMBER:	1002411
DESIGNATION: CONDITION:		LIST ENTRY NUMBER: TREND:	1002411 Improving
	Scheduled Monument, 4 LBs Generally satisfactory but with significant localised		
CONDITION:	Scheduled Monument, 4 LBs Generally satisfactory but with significant localised problems	TREND:	Improving
CONDITION: PRINCIPAL VULNERABILITY:	Scheduled Monument, 4 LBs Generally satisfactory but with significant localised problems Deterioration - in need of management	TREND: NEW ENTRY?:	Improving No
CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument, 4 LBs Generally satisfactory but with significant localised problems Deterioration - in need of management Mixed, multiple owners	TREND: NEW ENTRY?:	Improving No
CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument, 4 LBs Generally satisfactory but with significant localised problems Deterioration - in need of management Mixed, multiple owners Lodmoor Hill	TREND: NEW ENTRY?: CONTACT:	Improving No Ruth Garner 0117 975 0696

GLOUCESTERSHIRE

COTSWOLD



Barrington Park, Barrington SITE NAME: Listed Building grade I, RPG DESIGNATION: grade II*, CA CONDITION: Fair OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: F (F) OWNER TYPE: Private

Country house built circa 1736-38, extended late C19. Full repair works began in 2010 and are nearing completion.

LIST ENTRY NUMBER: 1172292 Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 - Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site

and the same of th	SALVE.	
1		-

0	English	a Hari	tago

SITE NAME:	Dovecote, Barrington Park, Barrington
DESIGNATION:	Listed Building grade II*, RPG grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private

1340832

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

C18 domed dovecote with ionic portico on east side, located approximately 500 metres north west of the house in open parkland. Emergency works to arrest further decay have been undertaken and full repairs will start when the house repairs are completed.

Contact: Ruth Garner 0117 975 0696

	4. E.	d .	
			C.
7			

© English Heritage

SITE NAME:	Gothick Seat (Temple), Barrington Park, Barrington
DESIGNATION:	Listed Building grade II*, RPG grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1340831

Mid C18 garden temple, situated 100 metres to south west of the house in the gardens. Emergency works to arrest further decay have been undertaken and full repairs will start when the house repairs are completed.

Contact: Ruth Garner 0117 975 0696

Contact: Ruth Garner 0117 975 0696



© English Heritage

SITE NAME:	Roman Doric Temple, Barrington Park, Barrington
DESIGNATION:	Listed Building grade II*, RPG grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private

1172331

Mid C18 garden temple located in the C18 gardens of Barrington Park. Emergency works to arrest further decay have been undertaken and full repairs will start when the house repairs are completed.

© English Heritage Archive

SITE NAME:	Elizabeth Pengree Memorial, The Square, Blockley
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Unknown
LIST ENTRY NUMBER:	1341728

Commemorative monument (1770s) decaying on one side and the railings are in poor condition. Basic maintenance has been undertaken, but no significant repairs.

SITE NAME:	Alfreds Hall, Cirencester Park, Cirencester
DESIGNATION:	Listed Building grade II*, RPG grade I
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1298719

Folly, begun 1721, designed by Lord Bathurst with Alexander Pope's advice, completed 1732. Probably the earliest C18 mock Gothic castle; part former house, part banqueting house and part mock ruin. Located in Oakley Wood, with rides radiating from it through the wood.

Building is in a poor state of repair.

Contact: Ruth Garner 0117 975 0696

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 F. Under repair or in fair to good.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise
'New entry' is noted.

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



© English Heritage

SITE NAME: Church of St Mary the Virgin, Cowley Listed Place of Worship grade DESIGNATION: II*, RPG grade II*, CA

CONDITION: Very bad PRIORITY CATEGORY: F (F)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1340154

A small Cotswold stone church. The Cotswold stone slates are decaying badly having long reached the end of their life. A Repair Grant for Places of Worship was offered in 2012 for the replacement of the roof coverings, with the works due to be completed in 2013.

Contact: Ruth Garner 0117 975 0696

SITE NAME:	Two bowl barrows 690 metres and 790 metres no	Two bowl barrows 690 metres and 790 metres north of The Manor Farm, Avening			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017337		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Crickley Hill camp, Badgeworth / Coberley				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003586		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No		
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Perrott's Brook dykes, Bagendon / North Cerney				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003436		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No		
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Bowl barrow 800 metres north east of Beverston	Castle Farm, Bevers	ston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008197		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	Long barrow 800 metres north east of Oldwalls Fa	arm, Bibury			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018163		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696		
SITE NAME:	West Barrow: a long barrow 200 metres west of l	_eighterton School,	Boxwell with Leighterton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013590		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Animal burrowing - localised/limited	NEW ENTRY?:	No		
OWNER TYPE:	Unknown	CONTACT:	Ruth Garner 0117 975 0696		

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D
 - Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Chedworth Roman villa, Chedworth		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003324
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Rain entry	NEW ENTRY?:	Yes
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round barrow north of Chedworth Roman villa, C	hedworth	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003346
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Digging	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Settlement south east of Chesterton Farm, Cirence	ester / Siddington	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003444
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two bowl barrows, known as Crippet's Wood rou Dryhill Farm, Coberley	und barrows, 560 m	netres and 590 metres north east of
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017041
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Norbury Camp hillfort, Colesbourne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018167
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Condicote bowl barrow, Condicote		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016080
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Tump Barn bowl barrow, Didmarton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016077
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Camp at Upper Dowdeswell, Dowdeswell		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1003321
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Round barrow 750 metres north east of Eastleachdowns Farm, Eastleach			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016506	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Charity (non-heritage)	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow in Three Ash Belt, 460 metres north	east of Westwood	Farm, Edgeworth	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016840	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Settlement site south of Claydon Cottages, Fairford	d		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003443	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Mineral extraction/related subsidence	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Round barrow 300 metres west of Church Farm, G	Guiting Power		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017338	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Icomb camp, Icomb			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003342	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow 450 metres west of Lasborough, King	gscote		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009159	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	The Chessalls Roman town, Kingscote / Wotton-under-Edge			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018607	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Metal detecting - unlicensed	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Roman villa 600 yards (550 metres) north east of C	Great Lemhill Farm,	Lechlade / Southrop	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003420	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Chessels Roman site, Lower Slaughter		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003466
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	New Court Ground Roman villa (south of new bui	Idings), Naunton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003340
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Summerhill prehistoric site, Naunton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003339
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow in Inlands Plantation, 650 metres sou	th of Hazleton Man	or Farm, Rodmarton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008788
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two bowl barrows 180 metres south east of Hare	sdown Barn, Rodm	arton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008796
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 120 metres north of Home Farm, Sherborne		
DESIGNATION:	Scheduled Monument, RPG grade II, CA	LIST ENTRY NUMBER:	1017082
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	South Cerney castle, South Cerney		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003422
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two bowl barrows 80 metres north of Arch Hollo	w, Swell	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008621
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
THE TOLL TOLL TELL TOLLETTE	, waste proughing		

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

TENTAGE AT NISK 2013 / 300	TH WEST / COTSWOLD		
SITE NAME:	Two bowl barrows 260 metres north of Chalk I cemetery, Swell	Hill Cottage; part of th	ne Cow Common round barrow
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008194
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 990 metres south east of Bemboro cemetery, Temple Guiting	ough Farm: part of the	Bemborough Farm round barrow
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020654
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Educational (independent)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Earthwork north of Lyne's Barn, Temple Guiting		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003328
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 335 metres south east of Broadfie	d Farm, Tetbury Upto	on
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016838
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Four bowl barrows forming part of a round barr east of Eyford Hill Farm, Upper Slaughter	row cemetery, and a l	ong barrow 550 metres north, north
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020987
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners CONTACT: Ruth Garner 0117 975		Ruth Garner 0117 975 0696
SITE NAME:	Syreford Farm bowl barrow, 450 metres south v	west of Oxpens, Whit	tington / Sevenhampton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018155
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS



© English Heritage

SITE NAME:	Hatherop Castle, Hatherop / Quenington
DESIGNATION:	Registered Park and Garden grade II, 2 LBs, part in SM, 2 CAs
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	Medium
TREND:	Stable
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1000767

Hatherop is thought to have been landscaped by 'Capability' Brown's contemporary Richard Woods and then reworked extensively in the C19. The main house is occupied by a school with an adjacent area of new build. The wider parkland, in separate ownership, is neglected: many parkland trees have gone, clumps and ornamental woodland are over-mature and decaying, and sections of park wall and estate railings are in very poor condition.

Former non-conformist chapel, dated 1849. Remarkably complete and architecturally distinctive example of its type. Stonework repairs required. Other repairs ongoing.

Contact: Ruth Garner 0117 975 0696

FOREST OF DEAN



© English Heritage Archive

SITE NAME:	Blakeney United Reformed Church, Cinderford Road, Blakeney, Awre
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private

LIST ENTRY NUMBER: 1186386 Contact: Ruth Garner 0117 975 0696



© English Heritage Archive

SITE NAME:	Guns Mill Barn, Littledean
DESIGNATION:	Scheduled Monument and Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Mixed, multiple owners

Formerly a C17 charcoal blast furnace and later a C18 paper mill. Now unused and in perilous condition, despite some emergency holding repairs. The site has now been taken on by a building preservation trust and they are working with English Heritage and local funders to secure the future of the building. Development grant aid is being organised to assist with this.

1002080 and 1186479 LIST ENTRY NUMBER: SITE NAME: Lydney Docks and Harbour. Contact: Ruth Garner 0117 975 0696



© English Heritage

	Naas Lane, Lydney
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Government or agency
LIST ENTRY NUMBER:	1002079 and 1338556

The docks and harbour date from about 1810 to 1821 and were once the main commercial port serving industry in the district. Outer basin now repaired with surrounding area used for recreation, however the inner basin is still in poor condition.

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS



© English Heritage Archive

SITE NAME:	Tithe Barn, Highleadon Court, Rudford and Highleadon
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1152574

CI5 or early CI6 Tithe barn built for the Abbey of St Peter, Gloucester. The roof is sound, but the framing and infill panels are deteriorating. Used for agricultural storage. Some maintenance has been undertaken.

Small C12 chapel with later Medieval extension to west. Unroofed rubble-built structure with slow deterioration of stonework and internal plasterwork. A condition survey funded by English Heritage highlighted the works needed to halt further deterioration and with a recommendation for

Contact: Ruth Garner 0117 975 0696

the wall heads to be soft-capped.

Contact: Ruth Garner 0117 975 0696

Contact: Ruth Garner 0117 975 0696

	et.		
		ol (A	Vic.
	314		
		0	
			2.14

© English Heritage

SITE NAME:	St James Church, Lancaut, Tidenham
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (F)

1002078 and 1186663

Unknown



© English Heritage

SITE NAME:	Church of St John the Evangelist, Boxbush Road, Coleford
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	A (B)
OWNER TYPE:	Religious organisation

1211330

remainder is leaking badly, which has damaged the interior of the church.

A late Victorian Anglican parish church overlooking the centre of Coleford, the last phase of which was completed in 1907. The roof has been partly repaired but the

OWNER TYPE:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

© Hook Mason Architects

SITE NAME:	Church of St Edward the Confessor, Kempley
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1156349

The church was built in 1903 to the designs of the architect Randall Wells, in the Arts and Crafts style. The valley gutter needs urgent replacement to prevent rainwater from entering the church. Problems of dampness are also evident at low level. The perimeter channel has many cracks and open joints, including next to the walls, where water seeps through and keeps the feet of the walls wet. Horizontal cracks have appeared in all four buttresses. The church successfully applied for a Repair Grant for Places of Worship in 2011 and repairs started in 2013.

Contact: Ruth Garner 0117 975 0696



© English Heritage

SITE NAME:	Church of St Mary, Church Street, Newent
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1078649

the tower is heavily eroded, increasingly badly the higher it gets. The stone parapets are in the worst condition and feel insecure. Past deathwatch beetle attack in the tower and the nave lintels needs to be independently investigated and a control strategy established. A Repair Grant for Places of Worship was successfully applied for and work started in 2013.

A large church in the centre of Newent. The stonework of

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.



© English Heritage

SITE NAME:	Church of St Peter and St Paul, Westbury-on-Severn
DESIGNATION:	Listed Place of Worship grade II*, CA

CONDITION: Very bad

PRIORITY CATEGORY: B (New entry) OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1101724

This church's tower with its tall shingled spire is an exceptional landmark on the Severn estuary; the tower dates from c1270- built as a garrison or watch tower to repel raids by the Welsh. The spire was added C14. The spire is now in need of re-covering. Many shingles have fallen and the fixings have failed so that the steeple jacks can no longer safely rest their ladders against the slopes to carry out repairs. The weathervane is at risk of falling. Rainwater damage to the historic timber frame is now therefore a risk. Repair Grant for Places of Worship offered in December 2012.

Contact: Ruth Garner 0117 975 0696

e English Fichage		Contact: Ruth G	arner 0117 975 0696
SITE NAME:	Whitecliff Iron Works, Coleford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021420
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Symonds Yat promontory fort, English Bicknor		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016760
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Soudley camp, Lower Soudley, Ruspidge and Soudl	еу	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005564
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Medieval defensive and settlement complex at Tay Taynton	nton Parva, 400 me	tres north west of Moorfields Farm,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021434
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	Yes
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Offa's Dyke: section 240 metres north east of Butt	tington Farm, Tiden	ham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020643
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Offa's Dyke: section in Boatwood Plantation, 320 r	metres south west	of Chase Farm, Tidenham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020606
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	English Heritage	CONTACT:	Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

HERITAGE AT RISK 2013 / SOUT	TH WEST / FOREST OF DEAN / GLOUCESTER		
SITE NAME:	Offa's Dyke: section in Caswell Wood, 280 metres	west of Beeches F	arm, Tidenham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020601
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Offa's Dyke: section in Chapelhouse Wood, 240 m	etres west of the R	ecreation Ground, Tidenham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020639
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Offa's Dyke: section in Passage Grove, 660 metres	west of Sheepcot,	Tidenham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020603
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Offa's Dyke: section in Shorncliff Wood including t Tidenham	he Devil's Pulpit, 79	90 metres south west of Sheepcot,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020604
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Offa's Dyke: section in Worgan's Wood, 800 metr	es west of Chase Fa	arm, Tidenham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020605
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Roman villa 600 yards (550 metres) south west of	Woolaston station,	Woolaston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004860
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
TRINGITAL VOLINLIVABILITY.	Al able blodgilling		110

GLOUCESTER



SITE NAME:

Tanner's Hall, north of city centre, Gouda Way, Gloucester

DESIGNATION:

Scheduled Monument, CA

CONDITION:

Very bad

OCCUPANCY:

N/A

PRIORITY CATEGORY:

B (B)

OWNER TYPE:

Private

LIST ENTRY NUMBER:

1015210

This is a rare survival of a C13 merchant's house, later converted to a tannery and Tanner's Hall. Surrounding buildings have been removed for the inner relief road. Scheduled Monument Consent has been granted for a scheme to repair and consolidate the Hall within an encasing new development. However the development is on hold as the site has been put up for sale, with Planning Permission.

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

ABBREVIATIONS

CA Conservation Area
Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



© English Heritage

SITE NAME: Llanthony Priory, range between Outer and Inner Courts, Llanthony Road, Gloucester Scheduled Monument and Listed

part in CA CONDITION:

Very bad OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C (C)

OWNER TYPE: Charity (heritage)

1002091 and 1271693; 1271697; 1271694; 1271696; 1271695; 1271698 LIST ENTRY NUMBER:

Buildings - 6 grade I, LB grade II,

Contact: Ruth Garner 0117 975 0696



© Gloucester City Council

SITE NAME: Llanthony Priory, remains of precinct wall north of Inner

. Gatehouse, Llanthony Road, Gloucester

Scheduled Monument and Listed DESIGNATION: Buildings - 6 grade I, LB grade II, part in CA

CONDITION: Poor

OCCUPANCY: N/A PRIORITY CATEGORY: C (C)

LIST ENTRY NUMBER:

SITE NAME:

OWNER TYPE: Charity (heritage)

1002091 and 1271693;

1271697; 1271694; 1271696; 1271695; 1271698

Stone and brick wall on the west and north sides of the Outer Court of the former Augustinian Priory. Built in the C15, it was rebuilt or extended in the C17 and C18. The Llanthony Priory Trust is looking to raise funds and investigate suitable future uses for the site.

Remains of the range between the Outer and Inner Courts

of the Augustinian Priory of Llanthony Secunda. Late C14

Holding repairs were carried out in March 2012 to make

eradicate dry rot. Heritage Lottery Fund funding is now

being sought by the trustees for some structural repairs.

and early C16. Vacant buildings subject to vandalism. Timber frame decaying; brick and stonework eroded.

the Priory Lodgings wind and weather proof and to





© Gloucester City Council

Llanthony Priory, remains of precinct wall south of Outer

. Gatehouse, Llanthony Road, Gloucester

Scheduled Monument and Listed Buildings - 6 grade I, LB grade II, part in CA DESIGNATION:

CONDITION: Very bad

OCCUPANCY: N/A

PRIORITY CATEGORY: C (C)

OWNER TYPE: Charity (heritage)

1002091 and 1271693; LIST ENTRY NUMBER: 1271697; 1271694; 1271696;

1271695; 1271698

Early C16 brick wall. Badly eroded especially at low level. Two brick piers constructed 1995 to support wall to provide support in event that condition of wall deteriorates, but these have now rotated away from back of wall. The Llanthony Priory Trust is looking to raise funds and investigate suitable future uses for the site.

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS



© English Heritage

SITE NAME: Llanthony Priory, remains of range on south side of Inner Court, Llanthony Road,

Gloucester

Scheduled Monument and Listed DESIGNATION: Buildings - 6 grade I, LB grade II,

part in CA

CONDITION: Very bad

OCCUPANCY: N/A

PRIORITY CATEGORY: C (C)

OWNER TYPE: Charity (heritage)

1002091 and 1271693; LIST ENTRY NUMBER: 1271697; 1271694; 1271696;

1271695; 1271698

Remains of the range on the south side of the Inner Court of the Augustinian Priory of Llanthony Secunda. Early C16. Subject to vandalism. The Llanthony Priory Trust is looking to raise funds and investigate suitable future uses for the

Contact: Ruth Garner 0117 975 0696



@ Gloucester City Council

SITE NAME: The Fleece Hotel, 19, Westgate Street, Gloucester DESIGNATION: Listed Building grade I, CA CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Local authority

LIST ENTRY NUMBER: 1245447

LIST ENTRY NUMBER:

C15 timber-framed range most recently occupied as the Fleece Hotel. The building has been vacant for sometime. It is in poor repair, with some internal decay. A series of opening up works were carried out early summer 2010 to provide more information on the condition. Ownership has passed to Gloucester City Council who are undertaking emergency repairs and considering longer term solutions.

Contact: Ruth Garner 0117 975 0696



© English Heritage

SITE NAME: Old Judges House, 26, Westgate Street, Gloucester DESIGNATION: Listed Building grade I, CA CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C(C)OWNER TYPE:

Commercial company 1245450

Late C15 timber-framed merchant house, greatly enlarged and remodelled in late C16/early C17. Refronted and altered internally c1815. Operated as seed merchant for c100 years until 1989, then partly occupied as bookshop, but vacant for last two years. Whilst some repairs being undertaken, there are many areas which require attention relating to general decay, water ingress and previous use of cement for repairs.

Contact: Ruth Garner 0117 975 0696

SITE NAME:	Barton Street, Gloucester		
DESIGNATION:	Conservation Area, 5 LBs	NEW ENTRY?:	Yes
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Charlotte Lewis (LPA) 01452 396855
SITE NAME:	Southgate Street		
SITE NAME: DESIGNATION:	Southgate Street Conservation Area, 31 LBs	NEW ENTRY?:	No
	-	NEW ENTRY?: TREND:	No Improving

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

STROUD



© English Heritage Archive

SITE NAME: St Marys House, London Road, Chalford

DESIGNATION: Listed Building grade II*, CA

CONDITION: Poor

OCCUPANCY: Part occupied/part in use

PRIORITY CATEGORY: A(A)

OWNER TYPE: Private

LIST ENTRY NUMBER: 1091156

Former mill owner's house and weavers' cottages, late C16 and late C17. Roof in exceptionally poor condition and is covered with tarpaulin.

Contact: Ruth Garner 0117 975 0696



© English Heritage Archive

Main building at Stanley Mills, Ryeford, King's Stanley

DESIGNATION: Listed Building grade I, CA

condition: Fair

OCCUPANCY: Part occupied/part in use

PRIORITY CATEGORY: E (E)

OWNER TYPE: Commercial company

LIST ENTRY NUMBER: | 1171285

Woollen mill, 1813. Ancillary building (grade II) is in poor condition and part occupied. Roof repaired with English Heritage grant. A proposal for repair and conservation has been granted consent.

Contact: Ruth Garner 0117 975 0696



© English Heritage

SITE NAME: Former Saxon church to west of Priory House, Leonard Stanley

Scheduled Monument and Listed
Buildings - I grade II*; I grade II,
4 LBs

CONDITION: Very bad

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: B (B)

OWNER TYPE: Private

OWNER TYPE: Private

LIST ENTRY NUMBER: 1018606 and 1171503; 1090737

Former Saxon and medieval chapel within core of former priory of St Leonard. Later converted to agricultural use including dovecotes and forge. A major collapse of the east end of the north wall occurred in the winter of 2010-11. The rebuilding of this wall has been grant aided and is due to be completed this summer.

Contact: Ruth Garner 0117 975 0696



© English Heritage Archive

Brownshill Court, Wick Street, Painswick

DESIGNATION: Listed Building grade II*

CONDITION: Very bad

OCCUPANCY: Part occupied/part in use

PRIORITY CATEGORY: C (C)

OWNER TYPE: Private
LIST ENTRY NUMBER: 1091567

Early to mid C18 country house converted into flats, which are now vacant. The house has been the subject of a closing order and parts are now in a dangerous condition. The house has been inherited by a new owner; no works have yet been undertaken.

Contact: Ruth Garner 0117 975 0696



© English Heritage

SITE NAME: Woodchester Mansion, Woodchester

DESIGNATION: Listed Building grade I, RPG grade II

CONDITION: Very bad

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: A (A)

OWNER TYPE: Charity (heritage)

1340703

chapel. The Woodchester Mansion Trust was formed in 1989 to do a continuous programme of conservation and display of the uncompleted gothic-style masterpiece. In 1991 a protective scaffold was built to cover the leaking roof of the chapel. The scaffold is now decaying and unsafe. Repairs are immediately needed to the scaffold or, ideally, the roof underneath.

Mansion c1854-68 incorporating a magnificent private

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

LIST ENTRY NUMBER:

- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise

'New entry' is noted.

c CA Conservation Area
y is LB Listed Building
se LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

ABBREVIATIONS



© English Heritage

SITE NAME:	Church of St Mary the Virgin, Church Lane, Berkeley
DESIGNATION:	Listed Place of Worship grade CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)

1304581

Religious organisation

Anglican parish church. C12 foundation on probable site of important early medieval minster church, altered in C13 and C15, and in C19. Random coursed rubblestone, lead roofs with coped verges and cross finials. Nave and aisles of 7 bays with clerestory windows to south only, north porch, lower chancel with flanking chapels. The roof is in poor condition and is vulnerable. The extensive interior wall paintings are at significant risk of decay.

Small Victorian rural church. Cotswold stone walls, roof tiles and tower with a squat spire. The spire has opening joints due to rusting cramps. The PCC are planning to $\,$

Contact: Ruth Garner 0117 975 0696

complete a repair scheme.

SITE NAME:	Church of St John the Baptist, B4072, Painswick
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1172665

Contact: Ruth Garner 0117 975 0696

0	Eng	lish	Н	er	itage
---	-----	------	---	----	-------

SITE NAME:	Two bowl barrows, known as Climperwell round l Cranham	parrows, 310 metre	es south west of Climperwell Farm,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017074
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	The Mount moated site, Haresfield		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020655
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Tresham Farbarrow round barrows, Hillesley and Tresham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002115
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 450 metres south east of Upper Hyd	e Farm, Minchinhan	npton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008626
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Gatcombe long barrow, 400 metres east of Gatcor	mbe Farm, Minchinh	nampton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008623
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
THE VOLUE OF VERY LIBERTY.	,		

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002076 CONDITION: Generally satisfactory but with minor localised problems PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No OWNER TYPE: Bowl barrow 720 metres south east of Longwood Farm, Woodchester DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017084 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Bowl barrow 330 metres north of Symonds' Hall Farm, Wotton-under-Edge DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017083 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017083 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No DOWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696				
Generally satisfactory but with minor localised problems PRINCIPAL VULNERABILITY: Arable ploughing New ENTRY?: No CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Bowl barrow 720 metres south east of Longwood Farm, Woodchester DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017084 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Bowl barrow 330 metres north of Symonds' Hall Farm, Wotton-under-Edge DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017083 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No CONTACT: Ruth Garner 0117 975 0696 Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No CONTACT: Ruth Garner 0117 975 0696	SITE NAME:	West Hill Romano-Celtic temple, Uley		
problems Principal Vulnerability: Arable ploughing New Entry?: No CONTACT: Ruth Garner 0117 975 0696 Site Name: Bowl barrow 720 metres south east of Longwood Farm, Woodchester Designation: Scheduled Monument Extensive significant problems TREND: Declining Private CONTACT: Ruth Garner 0117 975 0696 Declining Private CONDITION: Extensive significant problems New Entry?: No CONTACT: Ruth Garner 0117 975 0696 Site Name: Bowl barrow 330 metres north of Symonds' Hall Farm, Wotton-under-Edge Designation: Scheduled Monument LIST ENTRY NUMBER: 1017083 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: No CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: No OWNER TYPE: No Private CONTACT: Ruth Garner 0117 975 0696	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002076
Bowl barrow 720 metres south east of Longwood Farm, Woodchester DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017084 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No DOWNER TYPE: Bowl barrow 330 metres north of Symonds' Hall Farm, Wotton-under-Edge DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017083 CONDITION: Extensive significant problems TREND: Declining NEW ENTRY?: No Declining NEW ENTRY: NO Declining NEW ENTRY: NO Declining Ruth Garner 0117 975 0696 Ruth Garner 0117 975 0696	CONDITION:		TREND:	Declining
Bowl barrow 720 metres south east of Longwood Farm, Woodchester DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017084 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No CONTACT: Ruth Garner 0117 975 0696 Bowl barrow 330 metres north of Symonds' Hall Farm, Wotton-under-Edge DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017083 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017084 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017083 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696 Ruth Garner 0117 975 0696 CONTACT: Ruth Garner 0117 975 0696	OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
Extensive significant problems FRINCIPAL VULNERABILITY: Arable ploughing Private Bowl barrow 330 metres north of Symonds' Hall Farm, Wotton-under-Edge DESIGNATION: Scheduled Monument Extensive significant problems TREND: Declining No LIST ENTRY NUMBER: 1017083 CONDITION: Extensive significant problems TREND: Declining NEW ENTRY?: No PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No Declining New ENTRY?: No Declining Declining No Declining Declin	SITE NAME:	Bowl barrow 720 metres south east of Longwoo	d Farm, Woodcheste	er
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Bowl barrow 330 metres north of Symonds' Hall Farm, Wotton-under-Edge DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017083 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No CONTACT: Ruth Garner 0117 975 0696	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017084
Private Private CONTACT: Ruth Garner 0117 975 0696 SITE NAME: Bowl barrow 330 metres north of Symonds' Hall Farm, Wotton-under-Edge DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017083 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696	CONDITION:	Extensive significant problems	TREND:	Declining
Bowl barrow 330 metres north of Symonds' Hall Farm, Wotton-under-Edge DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017083 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017083 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696	OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing New Entry?: No OWNER TYPE: CONTACT: Ruth Garner 0117 975 0696	SITE NAME:	Bowl barrow 330 metres north of Symonds' Hall	Farm, Wotton-unde	r-Edge
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017083
OWNER TYPE: Private CONTACT: Ruth Garner 0117 975 0696	CONDITION:	Extensive significant problems	TREND:	Declining
	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
TEWKESBURY	OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
	TEWKESBURY			



© English Heritage

SITE NAME:	Dovecote 3 metres north of Bridge House, Bentham, Badgeworth
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

LIST ENTRY NUMBER:

Dovecote, C17. Movement of structural timbers on south east and north east walls has caused joints to pull apart, leading to brick panels falling out. Wattle and daub panels are also fragmenting. Some timber decay on the west side and cement repairs to the roof are also of concern.

1304753 Contact: Ruth Garner 0117 975 0696

Dovecote approx 75 metres south east of Manor Farm, SITE NAME: Ashchurch, Fiddington DESIGNATION: Listed Building grade II* CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: E (E) OWNER TYPE: Private LIST ENTRY NUMBER: 1091923

Dovecote, 1637. Pointing eroded particularly on the north face. Occasional missing roof tiles, although some roofing works have taken place.

Contact: Ruth Garner 0117 975 0696



© Tewkesbury Borough Council

SITE NAME: Malthouse to the rear of, 23, Barton Street, Tewkesbury DESIGNATION: Listed Building grade II*, CA CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Private

1281018

Workshop, former malthouse. C17. Building has been unoccupied for some time and although discussions have been held with the owner, no applications have yet been forthcoming.

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

OWNER TYPE:

LIST ENTRY NUMBER

LIST ENTRY NUMBER:



Tewkesbury Borough Council

SITE NAME:	88, Church Street, Tewkesbury
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)

Private

1205905

Late C15 town house, altered C16 and C19, with shop under. Building only partly occupied and in poor condition with broken windows on second floor.

Contact: Ruth Garner 0117 975 0696

	ea Pa
4	
	Appropriate the second
- a	A CONTRACTOR OF THE STATE OF TH

© English Heritage Archive

SITE NAME:	Lane, Toddington
DESIGNATION:	Listed Building grade II* and Scheduled Monument, RPG grade II
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Private

1303593 and 1004840

Manor house, 1820-35, set in C19 formal gardens, on the east side of a late C18 landscape park. The house has been mothballed for more than 15 years, but has recently been purchased by a new owner who has installed a temporary roof and is engaging in an extensive programme of urgent works and repairs in consultation with the Local Planning Authority and English Heritage.

Church of St John the Baptist, SITE NAME: Oxenton DESIGNATION: Listed Place of Worship grade I CONDITION: Poor PRIORITY CATEGORY: C (New entry) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1303393

Anglican parish church. C13, C14 and C15, restored 1905. Nave and chancel, except the south wall, coursed limestone rubble; south wall of chancel porch and north aisle coursed squared and dressed limestone; tower and mortuary: ashlar; stone slate roof. Nave with north aisle with mortuary chapel at right angles, chancel and west tower. The key risk is the decay of the interior plaster and the threat that this poses to the wall paintings that are presently preserved.

Contact: Ruth Garner 0117 975 0696

Contact: Ruth Garner 0117 975 0696

© English	Heritage
-----------	----------

SITE NAME:	Deserted Medieval village, Ashchurch Rural		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002071
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	SITE NAME: Nottingham Hill camp, Gotherington / Prescott / Woodmancote		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004864
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Great Witcombe Romano-British villa, Great Witco	ombe / Brockworth	1
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014826
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park I PA ΝP

Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

SITE NAME:	Bowl barrow 690 metres south west of Roel Farm	, Hawling	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017076
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 760 metres south of Roel Farm, Haw	ling	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017077
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Two bowl barrows known as Hawling Downs rour Hawling	nd barrows, 610 me	etres north east of Slade Barn Farm,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017037
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Over earthwork, Highnam		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002092
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Hailes Abbey and ringwork, Stanway		
DESIGNATION:	Scheduled Monument, 3 LBs	LIST ENTRY NUMBER:	1018070
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Hailes Wood camp, Hailes, Stanway		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004843
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Milhampost Roman site, Stanway		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004844
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

Wadfield Roman villa, Sudeley		
Scheduled Monument	LIST ENTRY NUMBER:	1004846
Extensive significant problems	TREND:	Declining
Arable ploughing	NEW ENTRY?:	No
Private	CONTACT:	Ruth Garner 0117 975 0696
Romano-British villa 170 metres south west of Wind	chcombe School, G	Greet Road, Winchcombe
Scheduled Monument	LIST ENTRY NUMBER:	1021449
Extensive significant problems	TREND:	Unknown
Arable ploughing	NEW ENTRY?:	No
Commercial company	CONTACT:	Ruth Garner 0117 975 0696
Woodmancote		
Conservation Area, 10 LBs	NEW ENTRY?:	No
Poor	TREND:	No significant change
	Scheduled Monument Extensive significant problems Arable ploughing Private Romano-British villa 170 metres south west of Wind Scheduled Monument Extensive significant problems Arable ploughing Commercial company Woodmancote Conservation Area, 10 LBs	Scheduled Monument Extensive significant problems Arable ploughing Private CONTACT: Romano-British villa 170 metres south west of Winchcombe School, Content of the significant problems Scheduled Monument Extensive significant problems Arable ploughing Commercial company CONTACT: Woodmancote Conservation Area, 10 LBs NEW ENTRY?:

ISLES OF SCILLY (UA)



© English Heritage Archive

SITE NAME:	Post medieval cottages, Samson, Tresco
DESIGNATION:	Scheduled Monument, part in CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Crown

LIST ENTRY NUMBER: 1016509

Fossilised C18/C19 landscape. The remains of the buildings are at risk from natural weathering, vegetation and erosion caused by visitors. A management plan has been devised and initial phase of consolidation grant aided by English Heritage is now complete. The result of the consolidation trials are being studied to inform a wider programme of repair.

Contact: Ruth Garner 0117 975 0696



SITE NAME:	Church of St Nicholas, Tresco
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1328849

Small Anglican granite walled church with a cruciform plan and a squat tower. The roof slates have a history of failure. The south nave and south transept pitches are the worst but all slopes need repair. A Repair Grant for Places of Worship was offered in March 2013.

Contact: Ruth Garner 0117 975 0696

0	English	Heritage

SITE NAME:	Civil War battery on The Green, Bryher		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1010176
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

HERITAGE AT RISK 2013 / SOU	ITH WEST / ISLES OF SCILLY (UA)		
SITE NAME:	Gig shed on the north coast of Great Porth, Bryhe	r	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1016173
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Dumping	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Prehistoric enclosure south east of The Brow, Bry	her	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1015649
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Prehistoric field system and post-medieval quay in	Great Porth, Bryhe	r
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1014987
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Prehistoric field system and Romano-British cist in Green Bay, Bryher		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1014989
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Prehistoric hut circle south of The Brow, Bryher		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1014990
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Prehistoric linear boundary and cairns south west	of The Bar, Bryher	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1016170
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Prehistoric linear boundary SSE of The Island, Bryh	ier	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1014991
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

HEKITAGE AT KISK 2013 / SOU	TH WEST / ISLES OF SCILLY (UA)		
SITE NAME:	Platform cairn on Cruther's Neck, St. Martin's		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1013806
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Prehistoric cairn cemetery and field system on Tinl	kler's Hill, St. Marti	n's
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1018109
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Prehistoric house platform settlement south west	of English Island Ca	rn, St. Martin's
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1018115
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Prehistoric settlement and Romano-British shrine of	on Nornour, St. Ma	rtin's
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1015674
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Prehistoric to Romano-British ritual, funerary and	settlement remains	on Par Beach, St. Martin's
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1018116
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Ennor Castle, Old Town, St. Mary's		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1014994
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Hut circle settlement in Pendrathen, St. Mary's		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1015663
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Iron Age to Romano-British fogou on northern Per Mary's	illillis medu, 170 m	eu es souur or Carn Gwaver Farm, St.
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1020142
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Kerbed platform cairn on Helvear Hill, 210 metres	ENE of Helvear Fa	rm, St. Mary's
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1010168
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Post-medieval breastwork, curtain wall and associa St. Mary's	ted defensive struc	tures on the periphery of The Garris
DESIGNATION:	Scheduled Monument, LB grade I, CA	LIST ENTRY NUMBER:	1018370
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Prehistoric settlement, Romano-British cist cemete Mary's	ery and Civil War b	attery in northern Toll's Porth, St.
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1015664
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round cairn 137 metres east of Helvear Farm, St. I	Mary's	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1010167
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	The Giant's Castle cliff castle, St. Mary's		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1011935
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	The Old Quay, Old Town Bay, St. Mary's		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1015656
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	World War II pillbox between Thomas' Porth and	World War II pillbox between Thomas' Porth and Porthaloo, St. Mary's		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1016517	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	World War II pillbox west of Porth Hellick, 90 me	tres north of Drum	n Rock, St. Mary's	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1016516	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Post-medieval animal-driven crushing mill 270 metr	res south west of B	lockhouse Cottage, Tresco	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1016186	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Prehistoric field system and settlement in Bathingh	ouse Porth, Tresco		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1016423	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Prehistoric field system and settlement north of Ap	opletree Point, Tres	sco	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1016182	
CONDITION:	Unknown	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Prehistoric round cairn 255 metres south west of	Blockhouse Cottage	es, Tresco	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1016187	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Prehistoric to post-medieval funerary, field system deer park on and adjacent to Samson, Tresco	and settlement ren	nains, with post-medieval kelp pit and	
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1016509	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	Yes	
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).


Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	St Nicholas' Priory, Tresco		
DESIGNATION:	Scheduled Monument, LB grade I, RPG grade I, CA	LIST ENTRY NUMBER:	1016184
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696

NORTH SOMERSET (UA)



SITE NAME: Ashton Court, Long Ashton Listed Building grade I, RPG DESIGNATION: grade II* CONDITION: Very bad OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C (C) OWNER TYPE: Local authority

1129841

Large country house dating from C15, C17, C18 and C19. House partly used but large part remains derelict and subject to slow but ongoing decay. The house has been the subject of negotiations between owners, Local Planning Authority, English Heritage and other interested parties for many years. English Heritage grant offered 2011; project development works for Conservation Management Plan, condition survey and business plan underway and due for completion end 2013.

Contact: Ruth Garner 0117 975 0696



SITE NAME: Elms Colliery, Nailsea Scheduled Monument and Listed DESIGNATION: Building grade II CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: A (B) OWNER TYPE: Mixed, multiple owners

One of the most complete examples of a late C18 colliery remaining in England. There are three standing structures and further exposed archaeological remains. All buildings are unroofed, derelict and subject to neglect and vandalism. Wall top consolidation was completed in 2010 but further works are required.

© English Heritage

LIST ENTRY NUMBER: 1004533 and 1320976

Contact: Ruth Garner 0117 975 0696



© English Heritage Archive

SITE NAME:	Birnbeck Pier, Weston-Super- Mare
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1129718

Main pier which connects Birnbeck Island to the mainland below the Prince Consort Gardens. Dated 1862, opened 1867. Disused apart from the lifeboat station on the island. Negotiations ongoing between the Local Planning Authority, owner, English Heritage and other interested parties about repair of pier and development of island. Trial repairs have been grant aided by English Heritage to help establish likely total repair costs.

Contact: Ruth Garner 0117 975 0696



© English Heritage

SITE NAME:	St Mary's Church, Church Lane, Portbury
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1311826

Anglican parish church C12, altered and extended early C13 and C14/C15, and restored 1870-75. The stone slate roofs of the chancel, vestry and associated lean-to roofs have come to the end of their life. Water has been getting in causing ceiling plaster falls. The PCC have received an offer under the Heritage Lottery Fund Grants for Places of Worship scheme for the repairs.

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

	THE WEST PROPERTY OF COATE TO THE COATE OF COATE		
SITE NAME:	Slight univallate hillfort on Conygar Hill, Portbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007918
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Birnbeck, Weston-Super-Mare		
DESIGNATION:	Conservation Area, 29 LBs, part in SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Marianna Porter (LPA) 01934 426250
SITE NAME:	Boulevard/Montpelier, Weston-Super-Mare		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Marianna Porter (LPA) 01934 426250
SITE NAME:	Clevedon Triangle, Clevedon		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Marianna Porter (LPA) 01934 426250
SITE NAME:	Melrose/Grove Park, Weston-Super-Mare		
DESIGNATION:	Conservation Area, 19 LBs, RPG grade II*, SM	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Marianna Porter (LPA) 01934 426250

PLYMOUTH, CITY OF (UA)



SITE NAME: Woodland Fort, Crownhill Road, Crownhill DESIGNATION: Scheduled Monument CONDITION: Very bad OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C (C) OWNER TYPE: Local authority

Palmerston Fort, built 1863-1869. Part of barrack block in use as social club, but the rest is empty. Remedial repairs have been undertaken and some of the heavy vegetation has recently been cleared. Site is prone to vandalism and rubbish dumping. English Heritage and Plymouth City Council are considering the results of a joint funded study to look at regeneration and conservation options.

© English Heritage

LIST ENTRY NUMBER: 1002615 Contact: Ruth Garner 0117 975 0696



© English Heritage

SITE NAME:	Oddfellows Hall, Ker Street, Devonport
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1322006

Hall by John Foulston, 1823, in the Egyptian style. Part of a group with the Guildhall and Devonport Column. Egyptian columns flank a central, recessed porch. Currently used as a social club and in poor repair. English Heritage grantaided a feasibility study and emergency repairs to the roof, completed in 2007.

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

OWNER TYPE:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN C
THE RESERVE OF THE PARTY OF THE
THE RESERVE OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN TW
The state of the s
HT TO BE TO BE TO THE TOTAL OF THE PERSON OF
一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个
AND LEGISLES AND
The same of the sa
· · · · · · · · · · · · · · · · · · ·
· 思想的 1 10 10 10 10 10 10 10

© Plymouth City Council

SITE NAME:	Efford Fort and Emplacement, Military Road, Efford
DESIGNATION:	Scheduled Monument
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)

1021135

Mixed, multiple owners

Palmerston Fort built 1863-1869. Partially occupied as parade ground is used for seasonal accommodation, while buildings are vacant or used for storage. Buildings are suffering from benign neglect with decay, heavy vegetation growth and extensive water penetration and structural problems are apparent. No solution agreed at present.

Heavy Goods Vehicle testing centre is located within a modern building in the Fort. Some ancillary buildings are vacant but have been subject to remedial repairs.

Contact: Ruth Garner 0117 975 0696

大唐

© English Heritage Archive

SITE NAME:	Agaton Fort, Plymouth
DESIGNATION:	Scheduled Monument
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Government or agency

1002613

Contact: Ruth Garner 0117 975 0696



© English	Heritage

South Saw Mills, South Yard, HM Naval Base, Plymouth
Listed Building grade II*
Fair
Vacant/not in use
E (E)
Government or agency

Sawmill of 1856-59. The saw mills ceased to be used as such in 1987 but the ground floor remained in light industrial use and for storage until 1997. An options report was issued in 2010, but the building remains vacant with no identifiable use.

1388413

SITE NAME: South Smithery, South Yard, HM Naval Base, Plymouth DESIGNATION: Listed Building grade II* CONDITION: Very bad OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: A (A) OWNER TYPE: Government or agency

Dockyard smithery built 1771, modified in the C19 and reconstructed circa 1897. It remained in use until 1987 when structural faults were discovered. There is continued deterioration of the roof, masonry and interiors. An

Designed by Robert Adam and built in 1783, it is believed the arch was built as a triumphal arch and eye-catcher to

options report was issued in 2010, but a repair strategy has not been put in place.

LIST ENTRY NUMBER: 1392692

Contact: Ruth Garner 0117 975 0696

be viewed from Saltram House.

Contact: Ruth Garner 0117 975 0696



© English Heritage

SITE NAME:	Boringdon Arch, Plymbridge Road, Plymouth
DESIGNATION:	Listed Building grade II* and Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (D)
OWNER TYPE:	Private, multiple owners

1386330 and 1020565

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

LIST ENTRY NUMBER:

SITE NAME:



© English Heritage

SITE NAME:	Melville Building, Royal William Yard, Plymouth
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

1378531

The Melville building was constructed circa 1826-32 as stores and offices for the Victualling Board to the design of Sir John Rennie Jnr and forms part of the impressive Royal William Yard. Whilst the majority of the Yard has been successfully developed, with a combination of public and private finance, a sustainable future of Melville has yet to be secured.

Contact: Ruth Garner 0117 975 0696



© English Heritage

© English Heritage

SITE NAME:	Old Cooperage, Royal William Yard, Plymouth
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Local authority

1378536

The Cooperage was built circa 1826-32 for the Victualling Board, to the design of Sir John Rennie Jnr and forms part of the impressive Royal William Yard. Whilst the majority of the Yard has been successfully developed, with a combination of public and private finance, a sustainable future of the Cooperage has yet to be secured. Permission granted in 2013 to convert part of the building into artist studios.

Contact: Ruth Garner 0117 975 0696



SITE NAME:	The coastal fortifications of Drake's Island, Plymouth
DESIGNATION:	Scheduled Monument, 4 LBs
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1010910

The Island incorporates numerous defences/military monuments from 1549-C20. It was held for Parliament during the Civil War and used for defence purposes until 1958. More recently it was used as an outdoor pursuits centre. All buildings and structures are thought to be in a poor state. A planning application for regeneration as hotel conversion has been drawn up in consultation with English Heritage and is currently being considered by the LPA.

Contact: Ruth Garner 0117 975 0696



© English Heritage Archive

	Western Hotel (Palace Theatre), Union Street, Stonehouse, Plymouth
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1386483

Academy Theatre and Great

Former variety theatre and hotel, 1898. Building continues to deteriorate. A significant building in a major regeneration area. English Heritage has offered grant aid in the past, which was not taken up. Temporary repairs undertaken in 1997. In very bad condition with water penetration causing internal floors to become dangerous. Works are proposed to make the building weather tight (2013).

Contact: Ruth Garner 0117 975 0696



© English Heritage

SITE NAME:	Amphitheatre in grounds of Saltram House, Merafield Road, Plympton
DESIGNATION:	Listed Building grade II*, RPG grade II*
CONDITION:	Fair
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1386231

Late C18 screen wall fronting rock-cut grottos overlooking the River Plym. Surrounding rock faces have become unstable and are subject to collapse. Repair of the amphitheatre has been identified as a key objective in a draft landscape masterplan for the Saltram area.

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.



I at the same	W.	m tj	
© English Heritage			

SITE NAME:	Church of St Mary and All Saints, Church Road, Plymouth
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1330541

Roof coverings, particularly the nave and inner slopes of north and south aisle are desperately in need of renewal. Slates to these areas have previously been covered with bitumen-coated hessian and will not be reusable for repairs. Valley gutter also needs renewing. Interior suffers from condensation and poor ventilation. Gullies need clearing out. Downpipe to tower leaking or blocked - wall very green. Some ivy growth to masonry. Buttresses need repointing. Excessive tree growth near north wall. Faculty granted 2011 for some re-roofing work to aisles.

Contact: Ruth Garner 0117 975 0696

SITE NAME:	Austin Fort and section of military road		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021380
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Egg Buckland keep		
Designation:	Scheduled Monument, LB grade II*	LIST ENTRY NUMBER:	1020543
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Efford Fort and Efford Emplacement, Military Road	l, Efford	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021135
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Charity (non-heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Ernesettle battery		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003193
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Fort Stamford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002544
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Knowle Battery		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002614
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Rain entry	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Generally satisfactory but with significant localised problems RRECIPIA VALIFIER SHIPTY Deterioration - in need of management NEW Private, multiple owners CONTRACT: Ruth Garner 0117 975 0696 TRE NAME: Laira Emplacement, immediately south west of Laira Battery Scheduled Monument Generally unsatisfactory with major localised problems Private Generally unsatisfactory with major localised problems Development requiring planning permission NEW PRIVATE Private Development requiring planning permission RECIPIA VALIFIER SHIPTY Private Lee Moor Tramway Bridge Scheduled Monument List ENTRY NUMBER: CONTRACT: Ruth Garner 0117 975 0696 TREND: Declining RRECIPIA VALIFIER SHIPTY CONDITION Generally satisfactory but with significant localised problems RRECIPIA VALIFIER SHIPTY CONTRACT: Ruth Garner 0117 975 0696 TREND: Declining RRECIPIA VALIFIER SHIPTY CONTRACT: Ruth Garner 0117 975 0696 TREND: Declining RRECIPIA VALIFIER SHIPTY CONTRACT: Ruth Garner 0117 975 0696 TREND: Declining RRECIPIA VALIFIER SHIPTY CONTRACT: Ruth Garner 0117 975 0696 TREND: Declining RRECIPIA VALIFIER SHIPTY CONTRACT: Ruth Garner 0117 975 0696 TREND: Declining RRECIPIA VALIFIER SHIPTY Private Plympton Castle Scheduled Monument, LB grade II*, CA USI ENTRY NUMBER: LOUGHACT: RUTH Garner 0117 975 0696 TREND: Declining RRECIPIA VALIFIER SHIPTY No CONTRACT: Ruth Garner 0117 975 0696 TREND: Declining RRECIPIA VALIFIER SHIPTY No CONTRACT: Ruth Garner 0117 975 0696 TREND: Declining RRECIPIA VALIFIER SHIPTY No CONTRACT: RUTH Garner 0117 975 0696 TREND: Declining RRECIPIA VALIFIER SHIPTY No CONTRACT: RUTH Garner 0117 975 0696 TREND: Declining RRECIPIA VALIFIER SHIPTY No CONTRACT: RUTH Garner 0117 975 0696 TREND: Declining RRECIPIA VALIFIER SHIPTY No CONTRACT: RUTH Garner 0117 975 0696 TREND: Declining RRECIPIA VALIFIER SHIPTY No CONTRACT: RUTH Garner 0117 975 0696 TREND: Declining RRECIPIA VALIFIER SHIPTY No CONTRACT: RUTH Garner 0117 975 0696 TREND: Declin	SITE NAME:	Laira Battery		
problems pro	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021134
EVENER TYPE: Private, multiple owners CONTACT: Ruth Garner 0117 975 0696 ITE NAME: Laira Emplacement, immediately south west of Laira Battery Scheduled Monument INTENTRY NUMBER. 1020686 Generally unsatisfactory with major localised media. Declining Private CONDITION: Development requiring planning permission New ENIRY: No Development requiring planning permission New ENIRY: No Development requiring planning permission New ENIRY: No Declining Private Lee Moor Tramway Bridge Scheduled Monument USTONTRY NUMBER. 1002637 Generally satisfactory but with significant localised problems RINCIPAL VOLNERABULTY: Collapse NEW ENTRY: Yes WIKER, multiple owners CONTACT: Ruth Garner 0117 975 0696 THE NAME: Phympton Castle Scheduled Monument, LB grade II*, CA USTONTRY NUMBER: 1003865 Generally satisfactory but with significant localised problems RINCIPAL VOLNERABULTY: Decided Monument, LB grade II*, CA USTONTRY NUMBER: 1003865 CONDITION. Generally satisfactory but with significant localised problems RINCIPAL VOLNERABULTY: Local authority Decidency Decidining RINCIPAL VOLNERABULTY: Local authority CONTACT: Ruth Garner 0117 975 0696 THE NAME: Phympton Priory SENIONAL VOLNERABULTY: Local authority CONTACT: Ruth Garner 0117 975 0696 THE NAME: Phympton Priory SENIONAL VOLNERABULTY: Development requiring planning permission New ENTRY: No CONTACT: Ruth Garner 0117 975 0696 THE NAME: Stonehouse Manor wall SENIONAL VOLNERABULTY: Oldspee New ENTRY: No CONTACT: Ruth Garner 0117 975 0696 THE NAME: Stonehouse Manor wall SENIONAL VOLNERABULTY: Oldspee READ: Declining NEW ENTRY: NUMBER: 1010910 Declining NEW ENTRY: NUMBER: 1010910 Declining RENDER VOLNERABULTY: No CONTACT: Ruth Garner 0117 975 0696 THE NAME: The Coastal fortifications of Drake's Island SENIONAL VOLNERABULTY: Development requiring planning permission NEW ENTRY: No CONDITION. Development pequiring planning permission NEW ENTRY: No	CONDITION:		TREND:	Declining
Laira Emplacement, immediately south west of Laira Battery Scheduled Monument Scheduled Monument, LB grade III*, CA Scheduled Monument Scheduled Monume	PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
RESIGNATION Scheduled Monument UST ENTRY NUMBER: 1020686 CONDITION Generally unsatisfactory with major localised problems RINICIPAL VOLNERABILITY: Development requiring planning permission NEW INTITY: No DOWNER TYPE Private CONTACT: Ruth Garner 0117 975 0696. THE NAME Lee Moor Tramway Bridge SESSIONATION Scheduled Monument UST ENTRY NUMBER: 1002637 Generally satisfactory but with significant localised problems RINICIPAL VOLNERABILITY: Collapse NEW INTITY: Yes WIRKERT PRE Mixed, multiple owners CONTACT: Ruth Garner 0117 975 0696. THE NAME: Plympton Castle Scheduled Monument, LB grade III*, CA UST INTRY NUMBER: 1003865 CONDITION Problems RINICIPAL VOLNERABILITY: No Generally satisfactory but with significant localised problems RINICIPAL VOLNERABILITY: No CONTACT: Ruth Garner 0117 975 0696. THE NAME: Plympton Castle Scheduled Monument, LB grade III*, CA UST INTRY NUMBER: 1003865 CONDITION Problems RINICIPAL VOLNERABILITY: No CONTACT: Ruth Garner 0117 975 0696. THE NAME: Plympton Priory SCHEDING Priory No DOWNER TYPE: NO DO	OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
Generally unsatisfactory with major localised problems RENCHAN VALNERABUTY: Development requiring planning permission New BHIKY: No CONTACT: Ruth Garner 0117 975 0696 THE NAME Lee Moor Tramway Bridge SESGRATION: Scheduled Monument CONTACT: Ruth Garner 0117 975 0696 THE NAME Lee Moor Tramway Bridge SESGRATION: Scheduled Monument CONDITION Generally satisfactory but with significant localised problems RENCHIPAL VALINERABUTY: Collapse Whized, multiple owners CONTACT: Ruth Garner 0117 975 0696 THE NAME Plympton Castle Scheduled Monument, LB grade II*, CA CONTACT: Ruth Garner 0117 975 0696 THE NAME Plympton Castle Scheduled Monument, LB grade II*, CA CONTACT: Ruth Garner 0117 975 0696 THE NAME Plympton Priory SESGRATION: Scheduled Monument LB grade II*, CA LIST ENTRY NUMBER: 1003865 THE NAME Plympton Priory SESGRATION: Scheduled Monument CONDITION Extensive significant problems EXTENSIVE BRINCHA VALINERABUTY: Development requiring planning permission RENCIPAL VALINERABUTY: Development requiring planning permission NEW ENTRY: NO Declining RENCIPAL VALINERABUTY: Development requiring planning permission RENCIPAL VALINERABUTY: No Declining RENCIPAL VALINERABUTY: Collapse NEW ENTRY: NUMBER: 1003850 THE NAME THE NAME THE NAME THE NAME THE COST THE NAME PRIOR VALINERABUTY: No CONTACT: RUTH Garner 0117 975 0696 THE NAME THE NAME THE NAME THE NAME THE COST THE NAME PRIOR VALINERABUTY: No CONTACT: RUTH GARNER 0117 975 0696 THE NAME THE	SITE NAME:	Laira Emplacement, immediately south west of Lair	a Battery	
problems problems problems Development requiring planning permission New Entry: Private Private Private Private CONTACT: Ruth Garner 0117 975 0696	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020686
Private Lee Moor Tramway Bridge Scheduled Monument LST ENTRY NUMBER 1002637 CONDITION Generally satisfactory but with significant localised problems RINCHIPAL VILLINERABILITY: Collapse Mixed, multiple owners CONTACT: Ruth Garner 0117 975 0696 RINCHIPAL VILLINERABILITY: Collapse NEW ENTRY: Yes CONTACT: Ruth Garner 0117 975 0696 RINCHIPAL VILLINERABILITY: Collapse NEW ENTRY: Yes CONTACT: Ruth Garner 0117 975 0696 RINCHIPAL VILLINERABILITY: Collapse NEW ENTRY: No CONTACT: Ruth Garner 0117 975 0696 RINCHIPAL VILLINERABILITY: Plant growth NEW ENTRY: No CONTACT: Ruth Garner 0117 975 0696 RINCHIPAL VILLINERABILITY: Plant growth NEW ENTRY: No CONTACT: Ruth Garner 0117 975 0696 RINCHIPAL VILLINERABILITY: Development requiring planning permission NEW ENTRY: No CONTACT: Ruth Garner 0117 975 0696 RINCHIPAL VILLINERABILITY: Development requiring planning permission NEW ENTRY: No CONTACT: Ruth Garner 0117 975 0696 RINCHIPAL VILLINERABILITY: Development requiring planning permission NEW ENTRY: No CONTACT: Ruth Garner 0117 975 0696 RINCHIPAL VILLINERABILITY: Development requiring planning permission NEW ENTRY: No CONTACT: Ruth Garner 0117 975 0696 RINCHIPAL VILLINERABILITY: Collapse NEW ENTRY: No CONTACT: Ruth Garner 0117 975 0696 RINCHIPAL VILLINERABILITY: Collapse NEW ENTRY: No CONTACT: Ruth Garner 0117 975 0696 RINCHIPAL VILLINERABILITY: Collapse NEW ENTRY: No CONTACT: Ruth Garner 0117 975 0696 RINCHIPAL VILLINERABILITY: Collapse NEW ENTRY: No CONTACT: Ruth Garner 0117 975 0696 RINCHIPAL VILLINERABILITY: Collapse NEW ENTRY: No CONTACT: Ruth Garner 0117 975 0696 RINCHIPAL VILLINERABILITY: Development requiring planning permission NEW ENTRY: No CONTACT: Ruth Garner 0117 975 0696 RINCHIPAL VILLINERABILITY: Development requiring planning permission NEW ENTRY: No CONTACT: Ruth Garner 0117 975 0696 RINCHIPAL VILLINERABILITY: Development requiring planning permission NEW ENTRY: No	CONDITION:		TREND:	Declining
Lee Moor Tramway Bridge Scheduled Monument Generally satisfactory but with significant localised problems RINGIPM, VALINERABILITY: Collapse Mixed, multiple owners CONTACT: Ruth Garner 0117 975 0696 RINGIPM, VALINERABILITY: Collapse Mixed, multiple owners CONTACT: Ruth Garner 0117 975 0696 RINGIPM, VALINERABILITY: Plympton Castle Scheduled Monument, LB grade II*, CA CONTACT: Scheduled Monument, LB grade II*, CA CONTACT: RINGIPM, VALINERABILITY: Plant growth RINGIPM, VALINERABILITY: Plympton Priory SISSIGNATION: Scheduled Monument LIST ENTRY NUMBER: LOCAL authority CONTACT: Ruth Garner 0117 975 0696 RINGIPM, VALINERABILITY: Development requiring planning permission NEW ENTRY: No WANGE TYPE: Mixed, multiple owners CONTACT: Ruth Garner 0117 975 0696 RINGIPM, VALINERABILITY: Development requiring planning permission NEW ENTRY: No WANGE TYPE: Mixed, multiple owners CONTACT: Ruth Garner 0117 975 0696 RINGIPM, VALINERABILITY: Development requiring planning permission RINGIPM, VALINERABILITY: CONDITION: Generally unsatisfactory with major localised problems RINGIPM, VALINERABILITY: COLLAPSE CONTACT: Ruth Garner 0117 975 0696 RINGIPM, VALINERABILITY: COLLAPSE RINGIPM, VALINERABILITY: COLLAPSE TREND: Declining RINGIPM, VALINERABILITY: COLLAPSE TREND: Declining RINGIPM, VALINERABILITY: COLLAPSE TREND: Declining RINGIPM, VALINERABILITY: No RUTE NAME: The coastal fortifications of Drake's Island Scheduled Monument, 4 LBs CONDITION: Generally satisfactory but with significant localised problems RINGIPM, VALINERABILITY: Development requiring planning permission NEW ENTRY: No Declining RINGIPM, VALINERABILITY: Development requiring planning permission NEW ENTRY: No Declining Declining RINGIPM, VALINERABILITY: Development requiring planning permission NEW ENTRY: No Declining Declining RINGIPM, VALINERABILITY: Development requiring planning permission NEW ENTRY: No Declining Declining RINGIPM, VALINERABILITY: Development requiring p	PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
Scheduled Monument UST ENTRY NUMBER 1002637 Generally satisfactory but with significant localised problems RINGUPAL VULNIFABILITY: Collapse Mixed, multiple owners CONTACT: Ruth Garner 0117 975 0696 RINGUPAL VULNIFABILITY: Yes Wixed, multiple owners CONTACT: Ruth Garner 0117 975 0696 RINGUPAL VULNIFABILITY: Yes Wixed Mixed, multiple owners CONTACT: Ruth Garner 0117 975 0696 RINGUPAL VULNIFABILITY: Declining problems RINGUPAL VULNIFABILITY: Plant growth Local authority CONTACT: Ruth Garner 0117 975 0696 RINGUPAL VULNIFABILITY: Plant growth Local authority CONTACT: Ruth Garner 0117 975 0696 RINGUPAL VULNIFABILITY: Development requiring planning permission RINGUPAL VULNIFABILITY: No RINGUPAL VULNIFABILITY: Development requiring planning permission RINGUPAL VULNIFABILITY: No RINGUPAL VULNIFABILITY: Development requiring planning permission RINGUPAL VULNIFABILITY: No RINGUPAL VULNIFABILITY: Occidens RINGUPAL VULNIFABILITY: No RINGUPAL VULNIFABILITY: Collapse CONDITION: Scheduled Monument, part in CA CONDITION: Generally unsatisfactory with major localised problems RINGUPAL VULNIFABILITY: No CONTACT: Ruth Garner 0117 975 0696 RINGUPAL VULNIFABILITY: Collapse CONDITION: RUTHER: No CONTACT: Ruth Garner 0117 975 0696 RINGUPAL VULNIFABILITY: Collapse CONDITION: Scheduled Monument, 4 LBs CONDITION: Development requiring planning permission RINGUPAL VULNIFABILITY: No CONTACT: Ruth Garner 0117 975 0696 RINGUPAL VULNIFABILITY: Development requiring planning permission RINGUPAL VULNIFABILITY: No CONTACT: Ruth Garner 0117 975 0696 RINGUPAL VULNIFABILITY: Development requiring planning permission RINGUPAL VULNIFABILITY: No CONTACT: Ruth Garner 0117 975 0696 RINGUPAL VULNIFABILITY: No CONTACT: Ruth Garner 0117 975 0696 RING	OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
Generally satisfactory but with significant localised problems RINCIPAL VULNERABILITY: Collapse Mixed, multiple owners CONTACT: Ruth Garner 0117 975 0696 RINCIPAL VULNERABILITY: Plympton Castle Scheduled Monument, LB grade II*, CA Generally satisfactory but with significant localised problems RINCIPAL VULNERABILITY: Plant growth Declining RINCIPAL VULNERABILITY: Plant growth Development Priory SESGNATION: Scheduled Monument EXTENAME Plympton Priory SESGNATION: Scheduled Monument Extensive significant problems RINCIPAL VULNERABILITY: Development requiring planning permission RINCIPAL VULNERABILITY: No Declining RINCIPAL VULNERABILITY: Development requiring planning permission RINCIPAL VULNERABILITY: No Declining RINCIPAL VULNERABILITY: Development requiring planning permission RINCIPAL VULNERABILITY: No Development requiring planning permission RINCIPAL VULNERABILITY: No Development requiring planning localised RINCIPAL VULNERABILITY: Development Scheduled Monument, part in CA UST ENTRY NUMBER: 1003850 TREND: Declining RINCIPAL VULNERABILITY: No Development requiring planning localised problems RINCIPAL VULNERABILITY: No CONTACT: Ruth Garner 0117 975 0696 RINCIPAL VULNERABILITY: Collapse Development requiring planning localised problems RINCIPAL VULNERABILITY: No Declining RINCIPAL VULNERABILITY: Development requiring planning permission RINCIPAL VULNERABILITY: No Declining RINCIPAL VULNERABILITY: Development requiring planning permission RINCIPAL VULNERABILITY: No Declining RINCIPAL VULNERABILITY: No Decl	SITE NAME:	Lee Moor Tramway Bridge		
RINCIPAL VULNERABILITY: Collapse NEW ENTRY): Yes Wixed, multiple owners CONTACT: Ruth Garner 0117 975 0696 WITE NAME Plympton Castle Scheduled Monument, LB grade II*, CA LIST ENTRY NUMBER: 1003865 CONDITION: Scheduled Monument, LB grade II*, CA LIST ENTRY NUMBER: 1003865 CONDITION: Generally satisfactory but with significant localised problems RINCIPAL VULNERABILITY: No Declining RINCIPAL VULNERABILITY: No Development Priory SESGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017594 Extensive significant problems TREND: Declining RINCIPAL VULNERABILITY: Development requiring planning permission NEW ENTRY): No DEVELOPMENT TYPE: Mixed, multiple owners CONTACT: Ruth Garner 0117 975 0696 WITE NAME Stonehouse Manor wall Scheduled Monument, part in CA LIST ENTRY NUMBER: 1003850 EXTENSIVE Scheduled Monument, part in CA LIST ENTRY NUMBER: 1003850 ENTRYPE: Stonehouse Manor wall Scheduled Monument, part in CA LIST ENTRY NUMBER: 1003850 ENTRYPE: Collapse NEW ENTRY: No RINCIPAL VULNERABILITY: Collapse RINCIPAL VULNERABILITY: Collapse NEW ENTRY: No CONTACT: Ruth Garner 0117 975 0696 WITE NAME Scheduled Monument, part in CA LIST ENTRY NUMBER: 1003850 ENTRYPE: Local authority Collapse NEW ENTRY: No CONTACT: Ruth Garner 0117 975 0696 WITE NAME The coastal fortifications of Drake's Island ENTRYPE: Local authority Collapse NEW ENTRY: NUMBER: 1010910 ENTRYPE: Local statisfactory but with significant localised problems RINCIPAL VULNERABILITY: Development requiring planning permission NEW ENTRY: No Declining RINCIPAL VULNERABILITY: Development requiring planning permission NEW ENTRY: No	DESIGNATION:		LIST ENTRY NUMBER:	1002637
Development requiring planning permission Rendered 1003850 The NAME Plympton Castle Scheduled Monument, LB grade II*, CA LIST ENTRY NUMBER: 1003865 CONDITION: Scheduled Monument, LB grade II*, CA LIST ENTRY NUMBER: 1003865 CONDITION: Generally satisfactory but with significant localised problems RINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No DWINER TYPE: Local authority CONTACT: Ruth Garner 0117 975 0696 THE NAME Plympton Priory SESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017594 CONDITION: Extensive significant problems TREND: Declining RINCIPAL VULNERABILITY: Development requiring planning permission NEW ENTRY: No DOWNER TYPE: Mixed, multiple owners CONTACT: Ruth Garner 0117 975 0696 THE NAME Stonehouse Manor wall SESIGNATION: Scheduled Monument, part in CA LIST ENTRY NUMBER: 1003850 TREND: Declining RINCIPAL VULNERABILITY: Collapse NEW ENTRY: No DOWNER TYPE: Local authority CONTACT: Ruth Garner 0117 975 0696 THE NAME TYPE: Local authority CONTACT: Ruth Garner 0117 975 0696 THE NAME TYPE: Local authority CONTACT: Ruth Garner 0117 975 0696 THE NAME TYPE: Local authority CONTACT: Ruth Garner 0117 975 0696 THE NAME TYPE: Local authority CONTACT: Ruth Garner 0117 975 0696 THE NAME TYPE: Declining Scheduled Monument, 4 LBs SESIGNATION: Scheduled Monument, 4 LBs DESIGNATION: Scheduled Monument, 4 LBs SESIGNATION: Scheduled Monument, 4 LBs Declining TREND: Declining TREND: Declining TREND: Declining	CONDITION:	,	TREND:	Declining
Plympton Castle Designation: Scheduled Monument, LB grade II*, CA	PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	Yes
Scheduled Monument, LB grade II*, CA LIST ENTRY NUMBER: 1003865 CONDITION: Generally satisfactory but with significant localised problems RINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No CONTACT: Ruth Garner 0117 975 0696 ITE NAME Plympton Priory Scheduled Monument LIST ENTRY NUMBER: 1017594 CONDITION: Extensive significant problems RINCIPAL VULNERABILITY: Development requiring planning permission Mixed, multiple owners CONTACT: Ruth Garner 0117 975 0696 ITE NAME Stonehouse Manor wall SESIGNATION: Scheduled Monument, part in CA LIST ENTRY NUMBER: 1003850 CONTACT: Ruth Garner 0117 975 0696 ITE NAME Scheduled Monument, part in CA LIST ENTRY NUMBER: 1003850 CONTACT: Ruth Garner 0117 975 0696 ITE NAME CONDITION: Scheduled Monument, part in CA LIST ENTRY NUMBER: 1003850 CONDITION: Generally unsatisfactory with major localised problems RINCIPAL VULNERABILITY: Collapse New ENTRY: No CONTACT: Ruth Garner 0117 975 0696 ITE NAME The coastal fortifications of Drake's Island SESIGNATION: Scheduled Monument, 4 LBs LIST ENTRY NUMBER: 1010910 CONDITION: Generally satisfactory but with significant localised problems CONDITION: Scheduled Monument, 4 LBs LIST ENTRY NUMBER: 1010910 Declining RINCIPAL VULNERABILITY: Development requiring planning permission NEW ENTRY: No	OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
Generally satisfactory but with significant localised problems RINCIPAL VULNERABILITY: Plant growth New ENTRY?: No CONTACT: Ruth Garner 0117 975 0696 ITE NAME Plympton Priory Scheduled Monument Scheduled Monument Scheduled Monument Development requiring planning permission Mixed, multiple owners CONTACT: Ruth Garner 0117 975 0696 ITE NAME Stonehouse Manor wall Sesignation: Scheduled Monument, part in CA Scheduled Monument Sched	SITE NAME:	Plympton Castle		
Problems Plant growth NEW ENTRY!: No Device Contact: Ruth Garner 0117 975 0696 THE NAME Plympton Priory Scheduled Monument UST ENTRY NUMBER: 1017594 CONDITION: Scheduled Monument Extensive significant problems RINCIPAL VULNERABILITY: Development requiring planning permission Device Mixed, multiple owners Scheduled Monument Stonehouse Manor wall Stonehouse Manor wall Scheduled Monument, part in CA CONDITION: Scheduled Monument, part in CA Scheduled Monument, part in CA CONDITION: Scheduled Monument, part in CA CONDITION: Generally unsatisfactory with major localised problems RINCIPAL VULNERABILITY: Collapse RINCIPAL VULNERABILITY: No Development requiring planning permission NEW ENTRY: No Development Problems RINCIPAL VULNERABILITY: No CONTACT: Ruth Garner 0117 975 0696 TREND: Declining RINCIPAL VULNERABILITY: No CONTACT: Ruth Garner 0117 975 0696 TREND: Declining Declining RINCIPAL VULNERABILITY: No CONTACT: Ruth Garner 0117 975 0696 TREND: Declining Declining Declining Declining Declining Declining RINCIPAL VULNERABILITY: Development requiring planning permission NEW ENTRY: No	DESIGNATION:	Scheduled Monument, LB grade II*, CA	LIST ENTRY NUMBER:	1003865
DWNERTYPE: Local authority CONTACT: Ruth Garner 0117 975 0696 ITE NAME: Plympton Priory DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017594 CONDITION: Extensive significant problems TREND: Declining RINCIPAL VULNERABILITY: Development requiring planning permission NEW ENTRY?: No DWNER TYPE: Mixed, multiple owners CONTACT: Ruth Garner 0117 975 0696 UST ENAME: Stonehouse Manor wall DESIGNATION: Scheduled Monument, part in CA LIST ENTRY NUMBER: 1003850 CONDITION: Generally unsatisfactory with major localised problems RINCIPAL VULNERABILITY: Collapse NEW ENTRY?: No DWNER TYPE: Local authority CONTACT: Ruth Garner 0117 975 0696 UST ENAME: The coastal fortifications of Drake's Island DESIGNATION: Scheduled Monument, 4 LBS LIST ENTRY NUMBER: 1010910 Generally satisfactory but with significant localised problems RINCIPAL VULNERABILITY: Development requiring planning permission NEW ENTRY?: No Declining RINCIPAL VULNERABILITY: Development requiring planning permission NEW ENTRY?: No	CONDITION:		TREND:	Declining
ITE NAME: Plympton Priory Scheduled Monument LIST ENTRY NUMBER: 1017594 Declining Declining RINCIPAL VULNERABILITY: Development requiring planning permission NEW ENTRY): No Wixed, multiple owners CONTACT: Ruth Garner 0117 975 0696 TREND: Declining NEW ENTRY): No Stonehouse Manor wall Sesignation: Scheduled Monument, part in CA LIST ENTRY NUMBER: 1003850 CONDITION: Generally unsatisfactory with major localised problems RINCIPAL VULNERABILITY: Collapse NEW ENTRY): No Declining RINCIPAL VULNERABILITY: CONTACT: Ruth Garner 0117 975 0696 TREND: Declining TREND: Declining No CONTACT: Ruth Garner 0117 975 0696 TREND: Declining	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
Scheduled Monument Extensive significant problems TREND: Declining RINCIPAL VULNERABILITY: Development requiring planning permission MEW ENTRY?: No CONTACT: Ruth Garner 0117 975 0696 RITE NAME: Stonehouse Manor wall Scheduled Monument, part in CA LIST ENTRY NUMBER: LOORDITION: Generally unsatisfactory with major localised problems RINCIPAL VULNERABILITY: Collapse NEW ENTRY?: No CONTACT: Ruth Garner 0117 975 0696 RINCIPAL VULNERABILITY: Collapse NEW ENTRY?: No CONTACT: Ruth Garner 0117 975 0696 RITE NAME: The coastal fortifications of Drake's Island Scheduled Monument, 4 LBs LIST ENTRY NUMBER: 1010910 Generally satisfactory but with significant localised problems RINCIPAL VULNERABILITY: Development requiring planning permission NEW ENTRY?: No	OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696
Extensive significant problems Extensive significant problems TREND: Declining New Entry: No Mixed, multiple owners Contact: Ruth Garner 0117 975 0696 Trende: Stonehouse Manor wall Sesignation: Scheduled Monument, part in CA LIST Entry Number: Declining RINCIPAL VULNERABILITY: Collapse New Entry: No Declining RINCIPAL VULNERABILITY: Collapse Local authority Contact: Ruth Garner 0117 975 0696 Trend: Declining Rincipal Vulnerability: Collapse Local authority Contact: Ruth Garner 0117 975 0696 Trend: Declining Rincipal Vulnerability: Contact: Ruth Garner 0117 975 0696 Trende: The coastal fortifications of Drake's Island Designation: Scheduled Monument, 4 LBs LIST ENTRY NUMBER: 1010910 Generally satisfactory but with significant localised problems Declining Rincipal Vulnerability: Development requiring planning permission New Entry: No	SITE NAME:	Plympton Priory		
Development requiring planning permission NEW ENTRY?: No Development requiring planning permission NEW ENTRY?: No CONTACT: Ruth Garner 0117 975 0696	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017594
Mixed, multiple owners CONTACT: Ruth Garner 0117 975 0696 Stonehouse Manor wall Sesignation: Scheduled Monument, part in CA CONDITION: Generally unsatisfactory with major localised problems RINCIPAL VULNERABILITY: Collapse Local authority CONTACT: Ruth Garner 0117 975 0696 Ruth Garner 0117 975 0696 TREND: Declining CONTACT: Ruth Garner 0117 975 0696 The coastal fortifications of Drake's Island DESIGNATION: Scheduled Monument, 4 LBs LIST ENTRY NUMBER: 1010910 Generally satisfactory but with significant localised problems RINCIPAL VULNERABILITY: Development requiring planning permission NEW ENTRY?: No	CONDITION:	Extensive significant problems	TREND:	Declining
Stonehouse Manor wall Sesignation: Scheduled Monument, part in CA LIST ENTRY NUMBER: 1003850 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Collapse CONTACT: Ruth Garner 0117 975 0696 The coastal fortifications of Drake's Island CONDITION: Scheduled Monument, 4 LBs CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Development requiring planning permission NEW ENTRY?: No New ENTRY?: No New ENTRY?: No	PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument, part in CA LIST ENTRY NUMBER: 1003850 CONDITION: Generally unsatisfactory with major localised problems RINCIPAL VULNERABILITY: Collapse Local authority CONTACT: Ruth Garner 0117 975 0696 RITE NAME: The coastal fortifications of Drake's Island DESIGNATION: Scheduled Monument, 4 LBs CONDITION: Generally satisfactory but with significant localised problems RINCIPAL VULNERABILITY: Development requiring planning permission NEW ENTRY: NO Declining NEW ENTRY: NO	OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
Generally unsatisfactory with major localised problems RINCIPAL VULNERABILITY: Collapse Local authority The coastal fortifications of Drake's Island DESIGNATION: Scheduled Monument, 4 LBs CONDITION: Generally satisfactory but with significant localised problems RINCIPAL VULNERABILITY: Development requiring planning permission TREND: Declining Declining NEW ENTRY?: No	SITE NAME:	Stonehouse Manor wall		
problems PRINCIPAL VULNERABILITY: Collapse Local authority Contact: Ruth Garner 0117 975 0696	DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1003850
DESIGNATION: CONTACT: Ruth Garner 0117 975 0696 The coastal fortifications of Drake's Island DESIGNATION: Scheduled Monument, 4 LBs CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Development requiring planning permission CONTACT: Ruth Garner 0117 975 0696	CONDITION:		TREND:	Declining
The coastal fortifications of Drake's Island DESIGNATION: Scheduled Monument, 4 LBs LIST ENTRY NUMBER: 1010910 Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Development requiring planning permission NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument, 4 LBs Generally satisfactory but with significant localised problems RINCIPAL VULNERABILITY: Development requiring planning permission LIST ENTRY NUMBER: 1010910 TREND: Declining Declining	OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696
Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Development requiring planning permission	SITE NAME:	The coastal fortifications of Drake's Island		
problems PRINCIPAL VULNERABILITY: Development requiring planning permission NEW ENTRY?: No	DESIGNATION:	Scheduled Monument, 4 LBs	LIST ENTRY NUMBER:	1010910
1 1 01	CONDITION:		TREND:	Declining
DWNER TYPE: Mixed, multiple owners CONTACT: Ruth Garner 0117 975 0696	PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
·	OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Woodland Fort		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002615
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Union Street		
DESIGNATION:	Conservation Area, LB grade II*	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Mike Daniells (LPA) 01752 304397
POOLE (UA)			
SITE NAME:	Round barrow cemetery on Barrow Hill 150 me	tres south west of Br	ookvale Farm
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1018029
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Branksome Park, Canford Cliffs		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Nigel Jacobs (LPA) 01202 633 328
SITE NAME:	Evening Hill, Canford Heath, Poole		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating significantly
VULNERABILITY:	Medium	CONTACT:	Nigel Jacobs (LPA) 01202 633 328
SITE NAME:	Haven Road, Canford Cliffs, Poole		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Nigel Jacobs (LPA) 01202 633 328
SITE NAME:	High Street, Town Centre, Poole		
designation:	Conservation Area, 20 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Nigel Jacobs (LPA) 01202 633 328
SITE NAME:	Sandbanks, Canford Cliffs, Poole		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Nigel Jacobs (LPA) 01202 633 328

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

SOMERSET			
EXMOOR (NP)			
SITE NAME:	Barlinch Priory, Brompton Regis, West Somerset		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006213
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Carnarvon New Pit iron mine and section of miner House, Brompton Regis, West Somerset	al railway trackbed	, 300 metres south west of Heather
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021352
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Later prehistoric defended enclosure, Long Wood,	Carhampton, Wes	st Somerset
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008255
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Dunkery Beacon and adjacent mounds, Cutcombe,	West Somerset	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003026
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	Yes
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Mounsey Castle, Dulverton, West Somerset		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021357
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Almsworthy Common: a stone alignment 560 metr Somerset	res south west of C	hetsford Bridge, Exford, West
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015017
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - localised/limited	NEW ENTRY?:	Yes
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Cow Castle, Exmoor, West Somerset		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002955
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Halscombe stone setting 790 metres south, south-	west of Simonsbath	Bridge, Exmoor, West Somerset
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014281
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	Yes
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Long Chains Combe North: a stone setting 120 mo Somerset	etres west, north-w	rest of the sheepfold, Exmoor, Wes
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014280
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Iron Age defended settlement above Sweetworthy	(eastern of two), L	uccombe, West Somerset
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008471
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - limited/localised	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Iron Age defended settlement above Sweetworthy	(western of two), l	Luccombe, West Somerset
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008472
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Sweetworthy deserted Medieval settlement, Lucco	mbe, West Somers	et
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008469
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	The Mound, Stoke Ridge, Stoke Pero, Luccombe, \	West Somerset	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006190
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - localised/limited	NEW ENTRY?:	Yes
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Allerford New Bridge, Luccombe / Selworthy, We	st Somerset	
DESIGNATION:	Scheduled Monument, LB grade II*	LIST ENTRY NUMBER:	1006197
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

HERITAGE AT RISK 2013 / SOUT	TH WEST / EXMOOR (NP) / MENDIP			
SITE NAME:	Stone circle, Porlock Common, Porlock, West Sor	nerset		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006189	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Berry Castle, Iron Age enclosure in Berry Castle V	Berry Castle, Iron Age enclosure in Berry Castle Wood, Porlock / Luccombe, West Somerset		
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1006204	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Allerford packhorse bridge, immediately north of Cross Lane Farm, Selworthy, West Somerset			
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1020776	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bury Castle, an Iron Age defended settlement, Selworthy, West Somerset			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008808	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Staddon Hill camp, Winsford, West Somerset			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021359	
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Brightworthy Barrows on Withypool Common, W	ithypool and Hawk	ridge, West Somerset	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021264	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	

MENDIP



SITE NAME: Kilmersdon Lodges, Kilmersdon Listed Building grade II*, RPG DESIGNATION: grade II* CONDITION: Very bad OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: A(A)OWNER TYPE: Private

1307411

Pair of lodges, gate piers and gates, associated with Ammerdown House, 1788-94, situated on the edge of late C18 to early C19 park. The lodges were ruinous when listed in the 1960s and their potential for reuse is limited by their size. A feasibility study has been undertaken but the scale of the project indicated was prohibitive. Discussions have commenced with estate owners but no solution yet agreed.

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS



© English Heritage

SITE NAME:	Former Anglo-Bavarian Brewery, Commercial Road Shepton Mallet
DESIGNIATIONI:	Listed Duilding and do II* CA

Listed Building grade II*, CA CONDITION:

Poor

OCCUPANCY: Part occupied/part in use

PRIORITY CATEGORY: A(A)

OWNER TYPE: Commercial company

LIST ENTRY NUMBER: 1296561

Brewery, now warehouses, built 1864. Whilst partly occupied at ground floor level, most of the building has been vacant for many years. A feasibility study has been undertaken which has identified a substantial conservation deficit. A partial collapse has now been repaired.

Early C17 timber-framed brewhouse, later cottage, now part calf shed/hay store. In poor condition due to lack of maintenance and beneficial use for many years. English

regarding possible partnership repair scheme. Emergency

clearance and stabilisation works to the building have been undertaken by Mendip Council. As of 2013 a grant

Heritage is in discussion with the owner and SPAB

application has been made by the owner and is being

Contact: Ruth Garner 0117 975 0696



© Mendip District Council

Outbuilding about 30 metres west of Higher Southtown SITE NAME: Farm, Southtown Lane, West Pennard DESIGNATION: Listed Building grade II* CONDITION: OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C (C) OWNER TYPE: Private

LIST ENTRY NUMBER:

Contact: Ruth Garner 0117 975 0696

considered by English Heritage.



© English Heritage

SITE NAME: Church of St Peter and St Paul. Church Street, Kilmersdon Listed Place of Worship grade I, DESIGNATION: CA CONDITION: Poor PRIORITY CATEGORY: D (New entry) OWNER TYPE: Religious organisation

1307311

1175928

Large predominantly Perpendicular Anglican church with tall west tower. C12 earliest fabric; Chancel predominantly C15; north aisle and tower second half C15. C19 restoration. Lead roof and stonework to tower require repair, and stone conservation work required to hunky punks on north aisle. Repair Grant for Places of Worship offered in December 2012 for repairs.

Contact: Ruth Garner 0117 975 0696

SITE NAME:	Round barrows south west of Cleeve's Plantation, Chewton Mendip			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003027	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow 300 metres north east of Whitnell Corner, Emborough			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011670	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Drying house at The Coach House, Willow Vale, Frome			
DESIGNATION:	Scheduled Monument, LB grade II, CA	LIST ENTRY NUMBER:	1016955	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Glastonbury lake village, Godney		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006156
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Vobster Breach colliery, 890 metres east, north-ea	st of Tweed Farm,	Leigh-on-Mendip / Mells
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014867
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Lake villages north west of Oxenpill, Meare		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006160
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Section of the Abbot's Way trackway, 500 metres west, south-west of Honeygar Farm, Meare		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014432
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Sections of the Sweet Track and Post Track, 240 m	netres south west o	of Sunnyside Farm, Meare
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014440
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Sections of the Sweet Track and Post Track, 250 m	netres ESE of Statio	n House, Meare
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014831
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Timber trackway site, 700 metres west of Honeyga	ar Farm, Meare	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014434
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Fussell's Lower Works: an iron edge tool works, 2	10 metres south ea	st of Wadbury, Mells
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1019796
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

HERITAGE AT RISK 2013 / SOU	JTH WEST / MENDIP			
SITE NAME:	Whatley Combe Roman villa, Nunney			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006188	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow 70 metres north east of King Down	Farm, Priddy		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011531	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow 180 metres south west of Yoxter Fai	rm, Priddy		
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1011532	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow 250 metres north east of King Down Farm, Priddy			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011530	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow 260 metres east of Templedown Fare	m, Priddy		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011534	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow 300 metres south west of Moor View	Bowl barrow 300 metres south west of Moor View, Priddy		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009773	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow 800 metres south of Townsend Farm	n, Priddy		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009740	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

HERITAGE AT RISK 2013 / SOU	TH WEST / MENDIP			
SITE NAME:	Linear barrow co	emetery comprising six bowl barro	ows 510 metres sou	uth west of Townsend Farm, Priddy
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1009744
CONDITION:	Generally unsatis problems	Generally unsatisfactory with major localised problems		Declining
PRINCIPAL VULNERABILITY:	Stock erosion - e	extensive	NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	World War II bo on Black Down,	ombing decoy complex, anti-aircra Priddy / Cheddar	ft obstructions and	Beacon Batch round barrow cemetery
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1020995
CONDITION:	Generally satisfac	ctory but with significant localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion -	extensive	NEW ENTRY?:	No
OWNER TYPE:	Other not for pr	ofit group	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Romano-British	Romano-British settlement on Stoke Moor, Rodney Stoke		
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1011125
CONDITION:	Generally unsatis problems	factory with major localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple of	Mixed, multiple owners		Ruth Garner 0117 975 0696
SITE NAME:	Group of round barrows 750 metres north west of lvy Cottage, St. Cuthbert Out		Cuthbert Out	
DESIGNATION:	Scheduled Monu	Scheduled Monument		1020494
CONDITION:	Extensive signification	Extensive significant problems		Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Marston Moat, T	rudoxhill		
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1016302
CONDITION:	Generally unsatis problems	factory with major localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowin	g - moderate	NEW ENTRY?:	No
OWNER TYPE:	Commercial com	npany	CONTACT:	Ruth Garner 0117 975 0696
	SITE NAME:	Babington House, Kilmersdon / Mells	Regency villa. Much recent development in associ	
	DESIGNATION:	Registered Park and Garden grade II, 7 LBs	development inc	se as club-hotel. New build and ancillary cluding car park and conversion of kitchen However, there are some positives as well
	CONDITION:	Generally satisfactory but with significant localised problems		walled garden along traditional principles.
	VULNERABILITY:	Medium		
	TREND:	Stable		
	NEW ENTRY?:	No		
	OWNER TYPE:	Mixed, multiple owners		
	LIST ENTRY NUMBER:	1001137	Contact: Ruth G	arner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SEDGEMOOR

SITE NAME:	Castle House, Queen Street, Bridgwater
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (A)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1355168

House in early Tudor Revival style, built for William Ackerman in 1851. The building is in a precarious condition. Owned by SAVE Building Preservation Trust. English Heritage has grant-aided scaffolding and project development work. Repairs to roof of rear range are being undertaken with English Heritage grant. SAVE are pursuing a long term future for the building with a local trust. As of 2013 grant aided works are ongoing.

Contact: Ruth Garner 0117 975 0696

SITE NAME:	Westonzoyland Pumping Station, Westonzoyland
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1174295

A former pumping station (early C19) now preserved by the Westonzoyland Engine Trust. The first pumping station to be built to lift floodwater from the Somerset Levels and moors, and the only one to survive with the steam engine still working and the buildings intact. Much work has been done but the buildings are still in need of repair.

Contact: Ruth Garner 0117 975 0696



SITE NAME:	Church of St Congar, Church Lane, Badgworth
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1059100

The nave and north aisle are mostly C14. Tower dates from the C15. The north aisle is of interest for its good proportions and also the attractive C17/18 thrown lime render external finish to the north elevation. The walls are constructed of lias coursed rubble with dressings of limestone. The surface of the exposed walling in all areas of the church is eroded and spalled but no area more so than the tower which requires urgent attention to prevent further deterioration. A Repair Grant for Places of Worship was successfully applied for in 2011 for repairs, with repairs likely to start in 2014.

Contact: Ruth Garner 0117 975 0696

Contact: Ruth Garner 0117 975 0696



SITE NAME:	Church of All Saints, Church Road, East Huntspill
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1060130

Anglican parish church. Built 1839-40 in Neo-Norman style. Predominantly single phase except raising of south porch in 1960s. The roofs are all in poor condition. Roofs and rainwater goods need repair. Repair Grant for Places of Worship offered in 2013.

© English Heritage

© English Heritage



© English Heritage

SITE NAME:	Church of St Mary, Fore Street, North Petherton
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Very bad
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1058924

The church was mostly built in the late C14 and early C15 including the tower, in Perpendicular style. Inside the tower at the height of the nave is a fine fan vault, unusual for a village church. The north aisle parapet is leaning at mid point and needs to be taken down and rebuilt. Roofs to the south aisle are in very poor condition jeopardising timber structure and finishes. The church successfully applied for a Repair Grant for Places of Worship for works to the roof in 2011 with work starting in 2013.

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 F. Under repair or in fair to good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site



SITE NAME:	Church of St Michael, North Lane, Othery
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Very bad
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1060090

Church is C13 with C14, C15 and C16 phases but it was much restored in 1846-47. However, high quality of medieval work remains, especially the tower. High level stonework on the tower, including the carved statues, is at risk and requires stabilising and conserving. A Repair Grant for Places of Worship was offered in 2011 towards the repair of the tower. Repairs are due to start on site in 2013.

Contact: Ruth Garner 0117 975 0696

© English Heritage

SITE NAME:	Chandos Glass Cone, at the junction of Northga	te and Valetta Place,	Bridgwater
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1019899
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Horsey medieval settlement immediately north	of Board's Farm, Bridg	water Without
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1020438
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Ruborough Camp large univallate hillfort, Broom	nfield	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007670
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Timber trackways 850 metres east of Catcott B	urtle Farm, Burtle	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014433
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	World War II anti-aircraft rocket battery and bo Ashridge Farm, Cheddar	ombing decoy control	building 265 metres north east of
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020994
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Duck decoy, 770 metres SSE of Gold Corner Br	idge, Cossington	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014858
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	No known threat	NEW ENTRY?:	Yes
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 - Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Dead Woman's	s Ditch cross-dyke, Robin Upright's	Hill, Over Stowey	
DESIGNATION:	Scheduled Mon	ument	LIST ENTRY NUMBER:	1008254
CONDITION:	Generally unsat problems	isfactory with major localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry		NEW ENTRY?:	No
OWNER TYPE:	Local authority		CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bronze Age and Iron Age timber trackways, 700 metre		metres north west o	f Coppice Gate Farm, Shapwick
DESIGNATION:	Scheduled Mon	ument	LIST ENTRY NUMBER:	1014431
CONDITION:	Unknown		TREND:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewa	atering	NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Sections of the Farm, Shapwick	Sweet Track, the Post Track and a	ssociated remains 5	00 metres north east of Moorgate
DESIGNATION:	Scheduled Mon	ument	LIST ENTRY NUMBER:	1014438
CONDITION:	Generally satisfactory but with minor localised problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bronze Age and	d Iron Age trackways 600 metres n	orth east of Northb	prook Farm, Shapwick / Ashcott
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1014444
CONDITION:	Extensive significant problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Prehistoric timber trackways, 670 metres south, so		outh-east of Parche	y Bridge, Stawell
DESIGNATION:	Scheduled Mon	Scheduled Monument		1014430
CONDITION:	Unknown		TREND:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewa	atering	NEW ENTRY?:	No
OWNER TYPE:	Government or	agency	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Alstone lake se	ttlement site, West Huntspill		
DESIGNATION:	Scheduled Mon	ument	LIST ENTRY NUMBER:	1012311
CONDITION:	Unknown		TREND:	Unknown
PRINCIPAL VULNERABILITY:	Development r	Development requiring planning permission		No
OWNER TYPE:	Private		CONTACT:	Ruth Garner 0117 975 0696
	SITE NAME:	Halswell Park, Goathurst / Broomfield	instigated the res	park. Local preservation trusts have
	DESIGNATION:	Registered Park and Garden grade II, 17 LBs	risk. The main ho venue but its fut	n buildings. Other structures are still at ouse has been in use as a commercial ure is currently uncertain. The majority o
	CONDITION:	Extensive significant problems		intensive cultivation. The centrepiece o Vood, is largely denuded of trees and th
	VULNERABILITY:	High	structures within	it are in a very poor state of repair. Mill
	TREND:	Declining	vvood is current	ly (June 2013) believed to be for sale.
	NEW ENTRY?:	No		
English Heritage	OVA/NIED TYDE:			

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

OWNER TYPE:

LIST ENTRY NUMBER:

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Mixed, multiple owners

1001145

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

Contact: Ruth Garner 0117 975 0696

ABBREVIATIONS

LIST ENTRY NUMBER:

SOUTH SOMERSET



© South Somerset District Council

SITE NAME:	The Grotto at Jordans, Ashill
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	N/A
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Private

1057070

Early C19 grotto within a designed landscape whose principle house was demolished in the mid C20. The building has been subject to vandalism and although now rethatched, elements are still in need of repair.

Late C16 monument. Rusting iron cramps have caused serious damage and threaten further loss of stone.

Contact: Ruth Garner 0117 975 0696

A CONTROL BOOK STORY
The second secon
The second secon
THE PARTY OF THE P
CANADA CA
A STATE OF THE PARTY OF THE PAR
The state of the s
The state of the s
Charles and the second
The state of the s
CANCEL DE SECTION DE LA CONTRACTOR DE LA
The state of the s
THE RESERVE OF THE PERSON OF T
5
THE RESIDENCE OF THE PARTY OF T
以上 2000年 2
AND THE RESIDENCE OF THE PARTY
是是是是一个人的,我们是一个人的。
ACCURATION OF THE PERSON OF TH
是在1000mm 1000mm
后的数据(C) 20 (E) (A) (E) (A) (E) (A) (E) (A) (E) (E) (E) (E) (E) (E) (E) (E) (E) (E

© South Somerset District Council

SITE NAME:	Cosenes monument, Church of All Saints, Church Street, Castle Cary
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)

OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1366395 Contact: Ruth Garner 0117 975 0696



© South Somerset District Council

SITE NAME:	Top mill building, Higher Flax Mills, Torbay Road, Castle Cary
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1056226

Refurbishment works still underway but should be completed in 2013.

This mid C19 former mill has been empty for several years. The building has now been sold and an application for conversion to one live/work unit has now been approved.

Contact: Ruth Garner 0117 975 0696



© South Somerset District Council

SITE NAME:	Waterloo House and Manor Court House, 7A, 7B, 9, 11, 13 and 13A, Fore Street, Chard, Chard Town
designation:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use

PRIORITY CATEGORY: C (C) OWNER TYPE: Commercial company LIST ENTRY NUMBER: 1197449

Late C16/early C17 group of shops/offices, houses and flats with two prominent projecting two and three storey porches. No. 9, which contains important internal features is vacant and in a deteriorating condition. A recent planning appeal refused subdivision to smaller units and as of 2013 the Local Authority is considering commissioning a feasibility study with English Heritage grant aid.

rtock	vva
	are
	is u
	Vial
	inve
	Her
	ide

Contact: Ruth Garner 0117 975 0696

SITE NAME:	Madey Mill, East Street, Martock
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1226550

Water mill with medieval origins, although current buildings largely C17. The building is situated on a working farm, nder-used and is suffering from lack of maintenance. ble new uses and/or funding opportunities need to be estigated to obtain adequate funding for repairs. English ritage funded condition survey has been completed, ntifying urgent repairs.

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS



© English Heritage

Secular college at Parsonage Farm, Stoke Sub Hamdon SITE NAME: Scheduled Monument and Listed DESIGNATION: Buildings - I grade I; 6 grade II,

Attached to this chantry college is a group of medieval and C16 farm buildings most of which are in poor condition and unroofed.

Mid C17 monument. Subsidence has resulted in rising

damp threatening the inscriptions, through increased salt

OCCUPANCY:

CONDITION:

Vacant/not in use

Poor

C (C) PRIORITY CATEGORY:

OWNER TYPE: Charity (heritage)

1020665 and 1260178; LIST ENTRY NUMBER: 1242240; 1260179; 1242150; 1260105; 1260180; 1242246

Contact: Ruth Garner 0117 975 0696

crystallisation in the ledger slabs.



© South Somerset District Council

SITE NAME: Two monuments in churchyard, approx 6 and 8 metres south of south transept, St Mary the Virgin, East Stoke, Stoke Sub Hamdon DESIGNATION: Listed Building grade II*, CA CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: A(A)

OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1242030

Contact: Ruth Garner 0117 975 0696



© South Somerset District Council

SITE NAME: The former Ropewalk, 75 metres north east of Millbrook House, High Street, West Coker DESIGNATION: Listed Building grade II* CONDITION: OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: E (E)

Charity (heritage) OWNER TYPE: LIST ENTRY NUMBER: 1057092

Former twine works, now store and workshop. Late C19 with C20 alterations and extensions. English Heritage grant-aided urgent repairs have been undertaken and supporting scaffolding has been erected. In 2011 the lease was taken over by the Coker Rope and Sail Trust and a Challenge Fund grant was awarded. Discussions regarding the approach to structural repairs took place with English Heritage in 2012 but comprehensive repairs are not yet underway.

Contact: Ruth Garner 0117 975 0696



© English Heritage

SITE NAME:	Church of St Mary the Virgin, Church Street, Chard Town
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1297140

Church mainly dating from the CI5. A grant was applied for in 2009 to determine the cause of a leaking roof; this investigation was completed in 2012, works to remedy the problem have not yet started.

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS



© English Heritage

SITE NAME:	Church of St Peter and St Paul, Maperton
DESIGNATION:	Listed Place of Worship grade I

CA

CONDITION: Poor

PRIORITY CATEGORY: D (New entry)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1366390

LIST ENTRY NUMBER:

Anglican parish church rebuilt in late C19, following a fire, except late C15 Perpendicular tower which survived. Roofs covered in red clay tiles are all in poor condition, except south transept. Heritage Lottery Fund grant offered in 2013 for repair of roofs and rainwater goods.

Contact: Ruth Garner 0117 975 0696



SITE NAME:	Church of St Mary, Mudford
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Very bad
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1056790

A medieval church in a village on the outskirts of Yeovil, most of the fabric appears to date from the CI5 or CI6. The condition of the high level stonework is the subject of a successful Repair Grant for Places of Worship application in 2011, the works for which are on-going in 2013. With this element repaired, the church will be put into good condition and the risk removed.

Contact: Ruth Garner 0117 975 0696

SECTION SECTION	A Justine	
	Atala i	S. Contract
	THE STATE OF	
		1

© English Heritage

© English Heritage

SITE NAME:	St Peter and St Paul, Church Street, Wincanton
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation

1238534

Large town centre church. The tower is all that remains of a medieval church with major enlargement and rebuilding in 1735 and 1887-89. English Heritage has grant-aided work to south east roofs in recent past. All other roofs are showing signs of age and there will need to be a rolling repair programme to these. A Repair Grant for Places of Worship was offered in 2010 for works to northern nave. Repair works to roofing underway and due for completion in 2013.

Contact: Ruth Garner 0117 975 0696



© English Heritage

SITE NAME:	Church of St Stephen, Church Street, Winsham
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1177765

1177765

Parish church dating from C13 with C15 chancel, tower, nave and south porch. The church was substantially restored in the late C19. Slate roofs of the nave and associated stonework was repaired in 2009 under the Repair Grant for Places of Worship scheme. Central threestage tower, of calcareous grit stone and Ham stone parapets, is in poor condition including corrosion of extension surface cramps; the tower roof leadwork is also in poor condition.

Contact: Ruth Garner 0117 975 0696



© English Heritage

SITE NAME:	Church of St John the Baptist, Church Path, Yeovil
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1055713

Perpendicular church largely dating form 1380 when rebuilt probably by William Wynford, master mason of Wells. Major restoration mid C19. Severe external masonry decay resulting in falls of stonework from tower. Major tower conservation and repair programme required.

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

ITE NAME:	Roman house south of Fair View House, Curry Riv	el	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006185
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Roman villa north of Dunnock's Lane, East Coker		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003029
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Low Ham Roman villa, High Ham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006192
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Northover House, late Roman cemetery, llchester		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1006128
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Pill Bridge, Long Sutton / Ilchester		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1006214
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Roman villa north of Stowey Hill, Pitney		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006183
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Melbury Roman villa, Somerton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002954
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Large multivallate	e hillfort and associated earthwork	s at South Cadbury	y, South Cadbury
DESIGNATION:	Scheduled Monu	ment, part in CA	LIST ENTRY NUMBER:	1011980
CONDITION:	Generally satisfac problems	tory but with significant localised	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree grow	th	NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Chessels Roman	villa, West Coker / East Coker		
DESIGNATION:	Scheduled Monui	ment	LIST ENTRY NUMBER:	1006186
CONDITION:	Extensive significa	ant problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple o	owners	CONTACT:	Ruth Garner 0117 975 0696
	SITE NAME:	Redlynch Park, Bruton / Shepton Montague	Redlynch is a larg	ncipal seat of the earls of Ilchester, ge landscape park near Wincanton. The gone and the stables and ancillary buildings
	DESIGNATION:	Registered Park and Garden grade II, 10 LBs	are now in multip	gole and the stables and anchiary buildings gle ownership. The majority of the g has disappeared, boundary walls and e in poor repair and there are ongoing
	CONDITION:	Generally unsatisfactory with major localised problems	development pre	e in poor repair and there are ongoing essures. More positively, a C18 Gothic Towers, has been repaired and is no longe
	VULNERABILITY:	Medium	at risk.	,
	TREND:	Stable		
English Heritage	NEW ENTRY?:	No	Contact: Ruth Garner 0117 975 0696	
	OWNER TYPE:	Private, multiple owners		
	LIST ENTRY NUMBER:	1000420		
	SITE NAME:	Cricket House, Cricket St. Thomas / Winsham	C18 landscape park and pleasure grounds surrounding listed mansion, partly by Soane. Pressure for developm from large hotel and farm diversification into the leisure market. However, encouragingly, parts of the park are being restored through Natural England's Environment Stewardship scheme.	
	DESIGNATION:	Registered Park and Garden grade II*, 8 LBs		
	CONDITION:	Generally satisfactory but with significant localised problems		
les XIII	VULNERABILITY:	Medium		
9.50	TREND:	Stable		
English Heritage	NEW ENTRY?:	No		
	OWNER TYPE:	Local authority, multiple owners		
	LIST ENTRY NUMBER:	1001142	Contact: Ruth G	arner 0117 975 0696
	SITE NAME:	Hazlegrove House, Queen		ark with formal garden in front of house.
	DESIGNATION:	Camel / Sparkford Registered Park and Garden grade II, 3 LBs	Avenues and veteran parkland trees survive, with som replanting. Main house in use as a school. Area close to house subject to development for a range of school facilities. Sports pitches encroaching into parkland. Par bisected by main road in 1980s, severing lodge from d	
	CONDITION:	Generally satisfactory but with minor localised problems		
	VULNERABILITY:	Medium		
	TREND:	Stable		
English Heritage	NEW ENTRY?:	No		
	OWNER TYPE:	Mixed, multiple owners		
		·		
	LIST ENTRY NUMBER:	1000422	Contact: Ruth G	arner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet
- implemented.

 C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Misterton		
DESIGNATION:	Conservation Area, 9 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Adron Duckworth (LPA) 01935 462595

TAUNTON DEANE



© English Heritage

SITE NAME:	Sandhill Park, Bishop's Lydeard
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1295317

Country house c1720. An application for conversion of the house to apartments and construction of enabling development in its grounds is still under discussion. A fire in 2011 caused serious damage to the roof structure and top floor. The building has now been scaffolded with a temporary roof structure while discussions on its repair continue. Four men were convicted of arson at Sandhill in February 2013. The Local Authority was determining the revised Planning and Listed Building Consent applications for enabling development in May 2013.

Contact: Ruth Garner 0117 975 0696



© English Heritage

SITE NAME:	Manor, Cothelstone
DESIGNATION:	Listed Building grade I, RPG grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private

1059192

LIST ENTRY NUMBER:

A mid C16 gatehouse. Part of a much larger estate. Consent has been granted for use as holiday let with associated repairs, but this has not been implemented. Discussions are underway with the Vivat Trust regarding a viable scheme to convert the Gatehouse to a holiday let.

Contact: Ruth Garner 0117 975 0696



© English Heritage

SITE NAME:	Cloth finishing works at Tone Mills, north range, Langford Budville
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1381210

A near-complete example of a C19 cloth dyeing and finishing works which developed between c1830 and c 1920. An application for new development on the adjoining grease works site has been approved and will provide funding for the conversion and repair of some of the buildings to enable their reuse for cloth making purposes. This consent granted for reuse for commercial purposes, with associated enabling development, has not yet been implemented.

Contact: Ruth Garner 0117 975 0696



© English Heritage

SITE NAME:	Castle House, The Castle, Castle Green, Taunton
DESIGNATION:	Scheduled Monument, 17 LBs, part in CA
CONDITION:	Good
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (C)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1013541

C17 house, within castle courtyard but in separate occupation, incorporating medieval fabric. Its former use as workshop and administrative building for the museum has ceased and it is now vacant. The building has been leased by Somerset Building Preservation Trust who have prepared a scheme for its reuse for educational and holiday let purposes and have raised funding. The castle is not at risk. Repairs have been completed, but still unoccupied.

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© English Heritage

SITE NAME:	Tonedale Mills (west complex), Wellington
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

1051987

Western complex of an integrated multi-component wool textile factory, now largely disused. Consent granted for mixed use redevelopment of the complex. Works halted on site in 2008 and owners went into receivership leaving some buildings in a very vulnerable condition. Site has been sold. Discussions underway with new owners. Consent for a revised flood alleviation scheme will be required from Environment Agency. Consented scheme still in abeyance June 2013.

Contact: Ruth Garner 0117 975 0696

SITE NAME:	Two crosses in St Mary's churchyard, Bishop's Lyde	eard	
DESIGNATION:	Scheduled Monument, 2 LBs, CA	LIST ENTRY NUMBER:	1016708
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Religious organisation	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two World War II air traffic control buildings, 620 Whitewall Corner, on the former airfield of RAF C	metres west and 5 Julmhead, Trickey V	60 metres west, south-west of Varren, Churchstanton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019845
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	World War II fighter pens and other airfield remain Trickey Warren Farm, Churchstanton	ns and defences of t	the former airfield of RAF Culmhead, at
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020492
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two groups of World War II pillboxes in the north of RAF Culmhead, Trickey Warren, Churchstanton		western sectors of the former airfield
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019846
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow and folly ruins on Cothelstone Hill, I	kilometre north ea	st of St Agnes' Well, Cothelstone
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015086
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Metal detecting - unlicensed	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site

IENTAGE AT NISK 2013 / 300	III WEST / TAGINTON DE	ANE / WEST SOTTENSET		
SITE NAME:	Bowl barrow at t Cothelstone	he west end of Cothelstone Hill, 8	325 metres north, i	north-east of St Agnes' Well,
DESIGNATION:	Scheduled Monur	ment	LIST ENTRY NUMBER:	1015085
CONDITION:	Generally satisfac problems	tory but with significant localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Metal detecting -	unlicensed	NEW ENTRY?:	No
OWNER TYPE:	Local authority		CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow on	Cothelstone Hill, 885 metres nort	h, north-east of St	Agnes' Well, Cothelstone
DESIGNATION:	Scheduled Monur		LIST ENTRY NUMBER:	1015950
CONDITION:	Generally satisfac problems	tory but with significant localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Metal detecting -	unlicensed	NEW ENTRY?:	No
OWNER TYPE:	Local authority		CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow on	Cothelstone Hill, 1,070 metres no	rth east of St Agne	es' Well, Cothelstone
DESIGNATION:	Scheduled Monur	ment	LIST ENTRY NUMBER:	1015087
CONDITION:	Generally satisfac problems	tory but with significant localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Metal detecting -	unlicensed	NEW ENTRY?:	No
OWNER TYPE:	Local authority		CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Norton Camp la	rge univallate hillfort, Norton Fitzv	varren	
DESIGNATION:	Scheduled Monur	Scheduled Monument		1008467
CONDITION:	Extensive significa	nt problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple o	wners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Poundisford Park	Pale, Pitminster / Trull		
DESIGNATION:	Scheduled Monur grade II	ment, LB grade II, part in RPG	LIST ENTRY NUMBER:	1002957
CONDITION:	Generally satisfac problems	tory but with significant localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree grow	:h	NEW ENTRY?:	Yes
OWNER TYPE:	Private, multiple o	owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Camp south of M	lanor Farm, Wiveliscombe		
DESIGNATION:	Scheduled Monur	ment	LIST ENTRY NUMBER:	1006167
CONDITION:	Extensive significa	nt problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Ruth Garner 0117 975 0696
WEST SOMERSET				
	SITE NAME:	Remains of Chantry at Kilve, Sea Lane, Kilve	to be remains of	ater Medieval additions. Formerly believed
		Scheduled Monument and Listed	an important ma	survey has shown that the ruins are part norial complex. English Heritage funded rs were undertaken 2010, with more
	DESIGNATION:	Building grade II*	emergency repai	13 Were undertaken 2010, with more
	DESIGNATION: CONDITION:	Building grade II* Very bad	works undertake	en 2011. English Heritage has funded a
			works undertake conservation plan works were under	en 2011. English Heritage has funded a n which includes options for reuse. Some ertaken in 2012. Grant application
	CONDITION:	Very bad	works undertake conservation plan works were under	en 2011. English Heritage has funded a n which includes options for reuse. Some
	CONDITION: OCCUPANCY:	Very bad N/A	works undertake conservation plan works were under	en 2011. English Heritage has funded a n which includes options for reuse. Some ertaken in 2012. Grant application

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.
 Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet
- implemented.

 C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS



SITE NAME:	Church of the Blessed Virgin Mary, Brompton Ralph
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Very bad
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1057972

Church dates from C15 but has undergone many changes. It was largely rebuilt in the C18 and the tower restored. North aisle added in 1841 and further restoration in 1881. All roofs are leaking and require repair. A Repair Grant for Places of Worship was offered in 2011 towards the repair of the roofs. Works starting in 2013.

Contact: Ruth Garner 0117 975 0696

© English Heritage

SITE NAME:	Trendle Ring hillfort and associated outwork, Bick	noller	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008249
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	Yes
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Clatworthy hillfort, Clatworthy		
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1006149
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Four cairns on Hurley Beacon, Crowcombe		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017218
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Barrow and cairn cemetery on Black Hill, 490 met	res north west of C	Crowcombe Park Gate, Holford
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1019381
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Dowsborough hillfort and associated round barrov	w, Holford	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010494
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Unknown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Entrenchment on Heydon Hill, Huish Champflowe	r	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006173
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site

		` '		
SITE NAME:	Four medieval fis	h weirs 500 metres east of the Ha	rbour, Minehead	
DESIGNATION:	Scheduled Monur	ment	LIST ENTRY NUMBER:	1020017
CONDITION:	Generally satisfac problems	tory but with significant localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Stringston church	nyard cross, Stringston		
DESIGNATION:	Scheduled Monur	ment, 2 LBs	LIST ENTRY NUMBER:	1006171
CONDITION:	Generally satisfac problems	tory but with significant localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management		NEW ENTRY?:	No
OWNER TYPE:	Religious organisa	ation	CONTACT:	Ruth Garner 0117 975 0696
	SITE NAME:	St Audries (House), West Quantoxhead	C19 gardens and pleasure grounds, surrounding a C19 mansion, together with parkland developed from the r	
		titutional uses; derelict former school in the walled garden. The parkland is		
	CONDITION:	Generally unsatisfactory with major localised problems	mostly under cultivation and few parkland trees survi Currently, St Audries house and gardens are in use as wedding venue.	tivation and few parkland trees survive. dries house and gardens are in use as a
	VULNERABILITY:	Medium	wedding vende.	
	TREND:	Stable		
	NEW ENTRY?:	No		
	OWNER TYPE:	Mixed, multiple owners		
	LIST ENTRY NUMBER:	1001155	Contact: Ruth G	arner 0117 975 0696

SOUTH GLOUCESTERSHIRE (UA)

SITE NAME: Blocks I and 2 and linking arcade to Hanham Hall Hospital, Whittucks Road, Hanham Abbots DESIGNATION: Listed Building grade II* CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: F (New entry) OWNER TYPE: Government or agency LIST ENTRY NUMBER 1278348

Large house built 1655. Building derelict and prone to vandalism. Substantial areas need re-roofing and refurbishment is required to make building habitable.

Edward Somerset, Hawkesbury

DESIGNATION: Listed Building grade II*, CA

CONDITION: Poor

OCCUPANCY: N/A

PRIORITY CATEGORY: C (C)

OWNER TYPE: Private

Monument to Lord Robert

A tall tapering stone tower ashlar monument by Lewis Vulliamy dated 1846. Repairs needed at high-level to cast iron balcony and stonework.

Contact: Ruth Garner 0117 975 0696

© English Heritage Archive LIST ENTRY NUMBER: 1320834 Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

SITE NAME:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA Conservation Area
Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



© English Heritage

SITE NAME:	Ragged Castle or Keeper'
	Lodge, Badminton Park,
	Hawkesbury

Listed Building grade II*, RPG DESIGNATION: grade I

CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C (C)

OWNER TYPE: Private

LIST ENTRY NUMBER: 1156209

Folly Castle. Set on motte at end of a main drive from Badminton House. Circa 1750 by Thomas Wright of Durham. Largely hidden by trees. Shell of structure is in poor condition. Interior has been lost. The council is in discussion with the owners regarding the repair and stabilisation of the walls. There has been clearance of vegetation on and around the structure.

Former chapel, built in 1741. The building has been redundant for many years and a fire has placed the building in an even more vulnerable position. The owners withdrew their application for redevelopment of the site in 2012 and

Contact: Ruth Garner 0117 975 0696

revised schemes are under discussion.

Contact: Ruth Garner 0117 975 0696



© English Heritage Archive

SITE NAME:	Whitfield Tabernacle, Park Road, Kingswood
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private



© English Heritage

SITE NAME:	Brandy Bottom Colliery, Pucklechurch
DESIGNATION:	Scheduled Monument
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Commercial company

1019400

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

1116201

A former C19 steam-powered colliery built on the site of C18 colliery. The Avon Industrial Buildings Trust have commissioned an historical study of the site to inform future work which has just been published. They have also undertaken vegetation clearance and minor repairs to stabilise the structures. A major grant application to English Heritage in 2013 to bring the site out of risk is being put together now.

Contact: Ruth Garner 0117 975 0696

Contact: Ruth Garner 0117 975 0696



© English Heritage

SITE NAME:	Coach House and stables north east of Oxwick Farmhouse, Oxwick Lane, Yate, Wickwar
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (E)
OWNER TYPE:	Mixed, multiple owners

1312305

provincial baroque. The building is under a temporary roof. A planning application was approved in 2011, but repairs are yet to begin as of July 2013.

Coach house and stables, built 1722 in a mannered



SITE NAME:	Oxwick Farmhouse, Oxwick Lane, Yate, Wickwar
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

Farmhouse dated 1722, in flamboyant artisan mannerist/baroque style. Part occupied. Vacant part has serious decay of floor structures and in areas is unsafe, but emergency repairs have commenced. Discussions over full repair are ongoing in 2013.

LIST ENTRY NUMBER: Contact: Ruth Garner 0117 975 0696 1321124 © English Heritage

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS Conservation Area Listed Building I PA

Local Planning Authority National Park ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



SITE NAME:	Church of St James the Great, Church Road, Westerleigh
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Very bad
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1215174

Large church with distinctive tall tower. The roofs are covered with a local sandstone slate, many slates are slipped or missing. It is especially bad over the porch which now has a tarpaulin cover. The north valley gutter is a temporary repair, now leaking, that imperils the nave and aisle roofs. A Repair Grant for Places of Worship for repair of the roofs has been offered and repairs are expected to be completed in 2013.

Contact: Ruth Garner 0117 975 0696

© English Heritas	zе
-------------------	----

SITE NAME:	Round barrow	on Barrow Hill, Bitton		
DESIGNATION:	Scheduled Mon	Scheduled Monument, CA		1004521
CONDITION:	Extensive signific	cant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowi	ng - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Roman villa at 0	Cromhall north west of Tapwell Bri	dge, Cromhall	
DESIGNATION:	Scheduled Mon	ument	LIST ENTRY NUMBER:	1003045
CONDITION:	Extensive signific	cant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughin	g	NEW ENTRY?:	No
OWNER TYPE:	Commercial co	Commercial company		Ruth Garner 0117 975 0696
SITE NAME:	Hillfort and asso	ociated Romano-British occupation	at Little Abbey, Alv	veston, Thornbury
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1010803
CONDITION:	Generally satisfactory but with significant localised problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Other		NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners		CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Wickwar Roma	in small town 680 metres WNW of	f Hall End Farm, Wi	ickwar
DESIGNATION:	Scheduled Mon	ument	LIST ENTRY NUMBER:	1021404
CONDITION:	Extensive signific	cant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughin	Arable ploughing		No
OWNER TYPE:	Private		CONTACT:	Ruth Garner 0117 975 0696
1000	SITE NAME:	Stoke Park, Stoke Gifford	Dramatic locatio	n on a hill overlooking the city of Bristol.
-	designation:	Registered Park and Garden grade II, 11 LBs, SM, part in CA	Park embellished bisected by the N	d out around crenellated Dower House. I by monuments and eye-catchers. Now 132 motorway. Setting compromised by
The same of	CONDITION:	Generally unsatisfactory with	dense residential development. Park under pres heavy and occasionally anti-social use, particular	



© English Heritage

SITE NAME:	Stoke Park, Stoke Gifford
DESIGNATION:	Registered Park and Garden grade II, 11 LBs, SM, part in CA
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	Medium
TREND:	Improving
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1000129

Contact: Ruth Garner 0117 975 0696

park structures. Future now appears more settled following transfer of majority of site to Bristol City Council in 2012.

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Warmley, Siston / Oldland		
DESIGNATION:	Conservation Area, 9 LBs, RPG grade II, SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Rebecca Anthony (LPA) 01454 863465
SITE NAME:	Whitfield Tabernacle		
DESIGNATION:	Conservation Area, 3 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Unknown
VULNERABILITY:	Low	CONTACT:	Rebecca Anthony (LPA) 01454
	LOW		863465

SWINDON (UA)



SITE NAME: The Mechanics Institute, Emlyn Square, Swindon DESIGNATION: Listed Building grade II*, CA CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Commercial company

Mechanics Institute, 1853-1855; now vacant. Outstanding example at heart of railway village. The council served an Urgent Works Notice on the owner in 2009 and implemented works in 2010 to secure the building. The shell of the building has been stabilised.

© English Heritage Archive

LIST ENTRY NUMBER: 1198947 Contact: Ruth Garner 0117 975 0696



SITE NAME: Chain Test House, Rodbourne Road, Swindon DESIGNATION: Listed Building grade II*, CA CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: D(D)OWNER TYPE:

A rare example of a railway chain testing house, 1873. Building currently vacant and in poor condition. An application for mixed use development was submitted in

© English Heritage

Commercial company LIST ENTRY NUMBER: 1355879

Contact: Ruth Garner 0117 975 0696



SITE NAME: Church of St Leonard, Trenchard Road, Stanton Fitzwarren Listed Place of Worship grade I, DESIGNATION: CONDITION: Poor PRIORITY CATEGORY: D (New entry) OWNER TYPE: Religious organisation

Anglican church with Norman nave extended in C19, C13-C14 chancel; C17 tower with rebuilt parapet in late C19 when pinnacles were added. Built from local limestone with stone tile roofs. Lead tower roof and high level stonework in poor conditon. C19 parapet has embedded ironwork which is corroding. Repair Grant for Places of Worship offered December 2012 for repairs.

LIST ENTRY NUMBER: © English Heritage 1023408 Contact: Ruth Garner 0117 975 0696

SITE NAME:	Bowl barrow 280 metres north of Downs Barn, Bishopstone		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010419
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

SITE NAME:	Bowl barrow on Hinton Downs Richardtons		
DESIGNATION:	Bowl barrow on Hinton Downs, Bishopstone Scheduled Monument	LIST ENTRY NUMBER:	1010461
	Generally unsatisfactory with major localised		
CONDITION:	problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Disc barrow on Burderop Down, I kilometre nort	h east of Upper He	erdswick Farm, Chiseldon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010457
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow I kilometre west of Sheppard's Farm	Dairy, Chiseldon /	Ogbourne St. George
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012439
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Field system and earthwork enclosure on Burdero	p Down, Chiseldon	/ Ogbourne St. George
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016383
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Four Highworth circles 150 metres north east of P	ickett's Copse, Hig	hworth
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016386
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Highworth circle 520 metres north west of North	Leaze Farm, Highw	orth
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016382
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Three Highworth circles 600 metres east of North	Leaze Farm, Highv	vorth
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018221
CONDITION:	Extensive significant problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
		CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Bowl barrow 700 metres south west of Liddington	Warren Farm, Lide	dington
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009634
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Liddington Castle, Liddington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016312
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Long barrow 700 metres north of Liddington War	ren Farm, Liddingto	on / Wanborough
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009631
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Remains of Holy Rood Church, The Lawn, Old To	wn	
DESIGNATION:	Scheduled Monument, 4 LBs	LIST ENTRY NUMBER:	1018057
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 150 metres north of Half Moon Woo	od, Wanborough	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011811
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 850 metres north west of North Fan	m, Wanborough	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016381
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Site of Roman town, west of Wanborough House,	Wanborough / Co	vingham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004684
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

TORBAY (UA)



© English Heritage

SITE NAME: Lupton House (Gramercy Hall School), Brixham

Listed Building grade II*, RPG DESIGNATION: grade II*

CONDITION: Poor

OCCUPANCY:

DESIGNATION:

Part occupied/part in use PRIORITY CATEGORY: F (D)

OWNER TYPE: Charity (heritage)

LIST ENTRY NUMBER: 1195173 C18 and C19 country house remodelled by G Wightwick c 1840, with extensive ancillary buildings and fine Italianate garden. Altered after a fire in 1928. In use as school from mid C20 to 2004. A charitable trust have acquired the House and undertook holding repairs. English Heritage have grant aided works to the garden structures, and repairs to the building are underway. Part of the building is now used for wedding ceremonies.

Contact: Ruth Garner 0117 975 0696

SITE NAME: Ilsham Manor Oratory, Ilsham Road, Ilsham

Listed Building grade II*

CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: A(A)

Charity (non-heritage) OWNER TYPE:

LIST ENTRY NUMBER: 1206789

Redundant oratory, part of the demolished medieval Ilsham Manor. Neglected and in poor condition, when assessed in 2012 the chapel was not in use.

Cinema, licensed in 1912. An extremely well preserved

example of an early purpose-built cinema. The building

current owner about the re-use of the building.

closed in the late 1980s and a trust is in discussion with the

Contact: Ruth Garner 0117 975 0696

SITE NAME:

Torbay Cinema, Torbay Road,

Paignton

1208209

DESIGNATION: Listed Building grade II*

CONDITION: Fair

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C (C)

LIST ENTRY NUMBER:

OWNER TYPE: Commercial company

Contact: Ruth Garner 0117 975 0696

© Torbay Council

SITE NAME:	Prehistoric field system at Walls Hill		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019134
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	OWNER TYPE: Local authority		Ruth Garner 0117 975 0696
SITE NAME:	Ashhole Cavern, Brixham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019133
CONDITION:	Generally satisfactory but with significant localised	TREND:	Declining

SITE NIAME:	St Michael's Chanal Chanal Hill		
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No

SITE NAME:	St Michael's Chapel, Chapel Hill
DESIGNATION:	Scheduled Monument, LB grade II
CONDITION:	Extensive significant problems

problems

Extensive significant problems Collapse

Local authority

LIST ENTRY NUMBER: 1019131

Stable

TREND:

NEW ENTRY?: No

CONTACT: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

PRINCIPAL VULNERABILITY:

OWNER TYPE:

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© English Heritage

SITE NAME:	Oldway Mansion
DESIGNATION:	Registered Park and Garden grade II, 12 LBs
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	High
TREND:	Stable
NEW ENTRY?:	No
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1001368

Formal gardens laid out to complement a grand house apparently inspired by the palace of Versailles. Built by the Singer sewing machine dynasty, the property was in local authority ownership for many years. The grounds have been steadily rationalised and simplified. Permission has been granted (spring 2012) for mixed-use development, including a hotel in the main house and housing in the grounds. The consented scheme incorporates some landscape restoration.

Contact: Ruth Garner 0117 975 0696

© English Heritage

SITE NAME:	Princess Gardens and Royal Terrace Gardens
DESIGNATION:	Registered Park and Garden grade II, 4 LBs, 2 CAs
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	Medium
TREND:	Stable
NEW ENTRY?:	No
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1001507

Important formal Victorian seaside park with later phases and additions. Ongoing structural problems relating to seafront location. Proposals for major development on Princess Gardens appear to have been shelved. After a long period when it was closed to the public, Rock Walk has been subject to a major programme of rock stabilisation and redesign, and reopened.

Contact: Ruth Garner 0117 975 0696

SITE NAME:	Brixham Town, Brixham		
DESIGNATION:	Conservation Area, 105 LBs, 2 SMs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Hal Bishop (LPA) 01803 207787
SITE NAME:	Torquay Harbour		
SITE NAME: DESIGNATION:	Torquay Harbour Conservation Area, 74 LBs, part in RPG grade II	NEW ENTRY?:	No
	· <i>'</i>	NEW ENTRY?: TREND:	No Improving significantly
DESIGNATION:	Conservation Area, 74 LBs, part in RPG grade II		
DESIGNATION: CONDITION:	Conservation Area, 74 LBs, part in RPG grade II Very bad	TREND:	Improving significantly

WILTSHIRE (UA)

SITE NAME:	Gay's Cave and Diamond (Amesbury Abbey), Amesbury
DESIGNATION:	Listed Building grade II*, RPG grade II*, SM, CA, WHS
CONDITION:	Fair
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1131081

Gay's Cave or Seat, circa 1734-38, with gateway and wrought iron gates, attributed to Henry Flitcroft, and situated on the axis of Amesbury Abbey and tumulus beyond the River Avon. Some of the shrubbery has been cleared; however, the Diamond pattern paths are overgrown and unrecognisable. One gate has been removed from the Grotto and it is suffering from vandalism and neglect.

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 F. Under repair on in fair to good.

 F. Under repair on in fair to good.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

LIST ENTRY NUMBER

SITE NAME:



© English Heritage

SITE NAME:	Rudloe Manor, Box
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (B)
OWNER TYPE:	Commercial company

1022808

Late C17 manor house surrounded by ancillary buildings including a grade II listed barn. The house was part of a larger Ministry of Defence site which was vacated in 1998. The house has remained vacant. The current owners have consent for a residential scheme with enabling development. Work started in 2012 and is ongoing.

Contact: Ruth Garner 0117 975 0696

SITE NAME:	Buildings to the rear of the Lansdowne Hotel, The Strand, Calne
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1247495

Former coach house, stable and brewhouse to rear of Lansdowne Arms Hotel. Buildings range from mid C17 to mid C19. Condition of roofs and coverings are continuing to degenerate leading to further internal decay. Urgent Works Notices have previously been complied with; however, the condition of these buildings continues to decline. The property has new owners who have indicated an intent to use the buildings.

Contact: Ruth Garner 0117 975 0696

SITE NAME:	Former hangars at Yatesbury Airfield, Cherhill, Compton Bassett
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Good
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1283146

Two aircraft hangars, built circa 1917 as part of a training centre. Two hangars from the first years of military flying. One hangar has been repaired, though there is no current end use. Consent has been granted to demolish the second hangar.

Contact: Ruth Garner 0117 975 0696



© English Heritage Archive

	Police Station, Northgate Street, Devizes	
DESIGNATION:	Listed Building grade II*, CA	
CONDITION:	Very bad	
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	D (D)	
OWNER TYPE:	Commercial company	

Former Law Courts and County

Law courts and police station, 1835. Wind and weathertight. Interior has been gutted. Several schemes have been granted consent, including residential use and a nightclub, but none have been implemented. Planning Permission and Listed Building Consent granted in 2012 for a new residential scheme.

LIST ENTRY NUMBER: 1251744 Contact: Ruth Garner 0117 975 0696



© English Heritage Archive

SITE NAME:	Stable block to Tottenham House, Great Bedwyn
DESIGNATION:	Listed Building grade II*, RPG grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1365488

Impressive stable block of 1818, by Thomas Cundy, located 150 metres north-north west of Tottenham House. Consent for conversion to residential use granted early 1990s but not implemented. Consent has been granted for conversion into a spa, in association with a hotel in the main house. The condition of the building is declining.

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© English Heritage Archive

SITE NAME:	Tottenham House, Great Bedwyn
DESIGNATION:	Listed Building grade I, RPG grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Private

1183809

Country house, 1825, by Thomas Cundy, situated in park, developed from C15 to C17 and landscaped by Lancelot 'Capability' Brown in the 1760s. Previously used as a preparatory school (from the 1950s). The consent for conversion to an hotel has yet to be implemented. However, the fabric is vulnerable to the elements and continues to decline.

Contact: Ruth Garner 0117 975 0696

A 1 A 1 A 1 A 1 A 1 A 1 A 1 A 1 A 1 A 1	
	1
	1
	ā.
	4
AND THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN	
THE RESERVE OF THE PARTY OF THE	
A STATE OF THE PARTY OF THE PAR	
	ě.
	1
	1
	1
THE RESERVE AND ADDRESS OF THE RESERVE AND ADDRE	
	į.
	4
	4

© English Heritage

SITE NAME:	Early wing at Brook Hall, Brokerswood, Heywood
DESIGNATION:	Listed Building grade I
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (A)
OWNER TYPE:	Private

1285019

An important C15 lodging range, attached to the grade II listed house which contains some medieval remnants. Continued decay of building since support scaffolding erected in 2002. The Local Planning Authority served second Urgent Works Notice in March 2012 to extend support scaffold and protect openings. Works were completed in 2012. Discussions for reuse ongoing.

Contact: Ruth Garner 0117 975 0696

Contact: Ruth Garner 0117 975 0696

Contact: Ruth Garner 0117 975 0696



© English Heritage Archive

SITE NAME:	Chapel at Knowle House, Little Bedwyn
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1004708

Early C15 former chapel in curtilage of a listed house. In poor condition and needs some work and repair.



SITE NAME:	93 and 94, Bradenstoke, Lyneham
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Private

1363678

Timber-framed building, C15 to C16, upgraded to II* in 2002. Last known use as a private residence but is now unoccupied. The council is monitoring the condition. Listed Building Consent was granted in 2010 for some repair works.



© English Heritage

Medieval undercroft at Bradenstoke Priory, Bradenstoke, Lyneham and Bradenstoke
Scheduled Monument, LB grade II, part in CA
Poor
N/A
C (C)

Private, multiple owners

C14 undercroft to priory. The building above removed in 1920s to the United States of America by Randolph Hearst. The undercroft has been propped with grant aid from English Heritage, to prevent collapse. There was clearance of scrub and re-pointing in 2012. Gradual improvement but more to do to stabilise overall.

LIST ENTRY NUMBER: 1010807 Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.

OWNER TYPE:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

SITE NAME:	The Red House at Eastwell Manor, Eastwell Road, Potterne	Red brick garden building, Built circa 1700. One of severa buildings on this site that are presently disused and in a		
DESIGNATION:	Listed Building grade II*	decaying condition. An Enforcement Notice has been served in respect of unauthorised alterations. An appeal		
CONDITION:	Poor	was lodged by the owner but was rejected by the planning		
OCCUPANCY:	N/A	inspector.		
PRIORITY CATEG	DRY: C(C)			
OWNER TYPE:	Private			
LIST ENTRY NUMI	DER: 1258775	Contact: Ruth Garner 0117 975 0696		
SITE NAME:	Littlecote Roman Villa, Ramsbury	Roman Villa, C1 to C4 AD. The owners have erected a new permanent cover over the mosaic. English Heritage is		
DESIGNATION:	Scheduled Monument, RPG grade II	working with the owners over a long term management plan for the site including its future repair.		
CONDITION:	Poor			
OCCUPANCY:	N/A			
PRIORITY CATEG	DRY: C(C)			
OWNER TYPE:	Commercial company			
LIST ENTRY NUMI	BER: 1003256	Contact: Ruth Garner 0117 975 0696		
SITE NAME:	Courtfield House, Polebarn Road, Trowbridge	Courtfield House is a clothier's house built in circa 1754 with an earlier C17 building at the rear. The house was		
DESIGNATION:	Listed Building grade II*, CA	used as a preparatory school which closed in April 2012 and is consequently redundant. Adjoining the house is a		
CONDITION:	Poor	relatively unaltered wool store. The roof structure is in poor condition with a collapsing valley gutter. Negotiations		
OCCUPANCY:	Part occupied/part in use	are underway to transfer the building to a trust which will		
PRIORITY CATEG	DRY: A (New entry)	be managed by the Friends of Trowbridge Museum. The Town Council have agreed to lease the site and buildings to		
OWNER TYPE:	Other not for profit group	house the relocated woollen museum.		
LIST ENTRY NUMI	BER: 1021635	Contact: Ruth Garner 0117 975 0696		
SITE NAME:	Chapel, immediately north of Pythouse, Pythouse Park, West Tisbury	Former private chapel to country house circa 1827. Built b John Bennett of Pythouse for his wife nee Lucy Lambert of Boyton. The chapel is derelict and overgrown and the		
DESIGNATION:	Listed Building grade II*	stonework has been vandalised. The building is now scaffolded. Some of the vegetation has been removed and		
CONDITION:	Very bad	a repair schedule is being prepared.		
OCCUPANCY:	Vacant/not in use			
PRIORITY CATEG	DRY: A (A)			
OWNER TYPE:	Private			
LIST ENTRY NUMI	NER: 3 62	Contact: Ruth Garner 0117 975 0696		
SITE NAME:	Phipps Mausoleum, Westbury Cemetery, Bratton Road, Westbury	Late C19 privately owned mausoleum, within a local authority municipal cemetery.		
	Listed Building grade II*			



© English Heritage Archive

© Salisbury District Council

© English Heritage Archive

© Wiltshire Council

SITE NAME:	Phipps Mausoleum, Westbury Cemetery, Bratton Road, Westbury
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1364424

Contact: Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument CA LB LPA NP RPG SM UA Unitary Authority
WHS World Heritage Site

HERITAGE AT RISK 2013 / SOU	THE VVEST / WILLSHIKE (UA)		
SITE NAME:	Banjo enclosure 480 metres south west of Chelder	ne, Aldbourne	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017363
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Lewisham Castle, Aldbourne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017364
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 800 metres south east of Tanhill Pen	ning, Allcannings	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013023
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two bowl barrows 400 metres south of Tanhill Pe	nning, Allcannings	
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1013024
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two Saxon boundary stones 450 yards (410 metre	es) west of New To	wn, Alton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005646
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Educational (state sector)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Earth Burgh (or Eorth Burh) north west of New T	own Farm, Alton /	Stanton St. Bernard
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004717
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Educational (state sector)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Wermere pond, Alvediston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004774
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	A bell barrow and two bowl barrows east of The Accemetery, Amesbury	Avenue on Countes	ss Farm: part of a linear round barrov
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010331
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bell barrow 550 metres east of New Barn, Earl's F	arm Down, Amesbi	ury
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009872
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 60 metres west of A345 on Countes	s Farm, Amesbury	
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1009141
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 150 metres NNE of Seven Barrow C as Old King Barrows, Amesbury	ottages forming par	rt of a round barrow cemetery know
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1009149
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Bowl barrow 170 metres south east of Strangways	on Countess Farm	, Amesbury
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1009145
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Bowl barrow 400 metres SSE of Strangways on Co	ountess Farm, Ames	bury
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1021348
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Henge monument 400 metres south of Stonehenge	e Cottages, Amesbu	ıry
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1012376
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

HERITAGE AT RISK 2013 / SOU	ith West / Wiltshire (UA)		
SITE NAME:	Linear boundary earthwork 250 metres west of S	tockport, Amesbury	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015689
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Linear boundary earthwork on Amesbury Down	west of Stock Botto	m, Amesbury
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015218
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Pond barrow 400 metres south east of Strangway	s, Amesbury	
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1009136
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Pond barrow 480 metres west of Olddown Barn	on Amesbury Down	, Amesbury
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015027
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Three bell barrows 300 metres north east of New	v Barn, Earl's Farm [Down, Amesbury
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009572
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Educational (state sector)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Settlement east of Ashtonfield (Cotswold Commi	unity), Ashton Keyne	es
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004691
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Beckhampton round barrow cemetery 150 metre	s north east of the "	Waggon and Horses', Avebury
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008221
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Bell barrow forming part of a round barrow cemet Overton Hill, Avebury	ery 400 metres no	rth east of West Kennett Farm on
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008099
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 50 metres south of The Sanctuary or round barrow cemetery, Avebury	Overton Hill, form	ning part of the Seven Barrow Hill
designation:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1007489
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 200 metres south of Green Street an forming part of a round barrow cemetery on Aveb	d 1100 metres eas ury Down, Avebur	t of the Avebury henge monument, y
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008110
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 770 metres south west of the junctio round barrow cemetery on Avebury Down, Avebu	n of the Ridgeway	and Green Street, forming part of a
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008107
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 900 metres SSE of Green Bank, Aveb	ury	
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1014029
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow forming part of a Bronze Age cemete Overton Hill, Avebury	ery 400 metres nor	th east of West Kennett Farm on
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008100
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow immediately west of the Ridgeway, 40 Avebury	00 metres north ea	st of its junction with Green Street
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008500
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

SITE NAME:	Earthwork enclosure 950 metres SSE of Manor Fai	rm, Avebury	
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1014031
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Group of six round barrows forming part of a Bro Farm, Avebury	nze Age cemetery 4	100 metres north east of West Kenne
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008102
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Pair of round barrows 400 metres west of the Ridgon Avebury Down, Avebury	geway, forming part	of a round barrow cemetery situated
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008075
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Pair of round barrows forming part of the Bronze West Kennett Farm, Avebury	Age round barrow	cemetery 400 metres north east of
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008101
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Remains of 'Falkner's Circle', a Neolithic stone circ	cle 180 metres east	of the West Kennet Avenue, Avebury
Designation:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008109
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round barrow cemetery 400 metres south of Ave	bury henge monum	ent on Waden Hill, Avebury
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008216
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Ten barrows forming part of Fox Covert round ba	rrow cemetery, W	est Down, Avebury
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008293
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	West Kennet Avenue and an earthwork bank east o	f West Kennett F	arm, Avebury
DESIGNATION:	Scheduled Monument, LB grade II, part in CA, WHS	LIST ENTRY NUMBER:	1015547
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	A henge, four Bronze Age barrows and part of a Ro / Bishops Cannings	man road 500 me	tres south west of Fox Covert, Avebu
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007491
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	West Kennett Farm palisaded enclosures, Avebury /	East Kennett	
DESIGNATION:	Scheduled Monument, 2 LBs, part in CA, WHS	LIST ENTRY NUMBER:	1015157
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Grovely Ditch, Barford St. Martin / Burcombe With	out / Great Wishf	ord / Wilton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005584
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow west of Rotherley Wood, 750 metres	WNW of Park Co	ottage, Berwick St. John
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020464
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Bell barrow situated between Bishop's Cannings Do	wn and Easton Do	own, Bishops Cannings
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013229
CONDITION:	Extensive significant problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Bowl barrow 150 metres east of the wireless station	n on Morgan's Hill	, Bishops Cannings
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014040
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Bowl barrow 300 metres east of Furze Knoll, Bishop	os Cannings	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013068
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY: OWNER TYPE:	Arable ploughing Crown	NEW ENTRY?: CONTACT:	No Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Bowl barrow 550 metres north east of Baltic Farm	, Bishops Cannings		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012629	
CONDITION:	Extensive significant problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow 840 metres north east of Baltic Farm	, Bishops Cannings		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013066	
CONDITION:	Extensive significant problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow 950 metres SSW of Beckhampton Pla Horton Down, Bishops Cannings	antation, forming pa	art of a round barrow cemetery on	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012983	
CONDITION:	Extensive significant problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696	
ITE NAME:	Bowl barrow 1070 metres NNW of Baltic Farm forming part of a barrow cemetery on North Down, Bish Cannings			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013772	
CONDITION:	Extensive significant problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow at east end of Morgan's Hill, Bishops	Cannings		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013070	
CONDITION:	Extensive significant problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow situated 500 metres SSW of Shepher	ds' Shore, Bishops	Cannings	
DESIGNATION:	Scheduled Monument, RB	LIST ENTRY NUMBER:	1013756	
CONDITION:	Extensive significant problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Eleven round barrows 1000 metres north of Baltic enclosed Iron Age farmstead on North Down, Bisl	Farm forming part	of a barrow cemetery, and a probab	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013773	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

SITE NAME:	Enclosed Iron Age farmstead 450 metres south of	Down Barn on Bish	op's Cannings Down, Bishops Canning
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013230
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Five round barrows 1040 metres NNE of Baltic Fa Bishops Cannings	rm forming part of	a barrow cemetery on North Down,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014737
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	Yes
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Four bowl barrows forming part of a cemetery 270 Cannings	0 metres east of lon	ng barrow on Roughridge Hill, Bishops
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014027
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Group of small enclosures on Horton Down, 910 metres north east of Easton Down long barrow, Bishop Cannings		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014561
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Group of three bowl barrows 250 metres north ea	ast of Shepherds' Sh	nore, Bishops Cannings
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013232
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Kitchen Barrow: a long barrow on Kitchen Barrow	/ Hill, Bishops Cann	ings
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012519
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Linear earthworks forming part of a field system o	n Bishop's Cannings	Down, Bishops Cannings
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013233
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

HERITAGE AT RISK 2013 / SOU	TH WEST / WILTSHIKE (UA)			
SITE NAME:	Long barrow 650 metres WSW of Shepherds' Sho	re, Bishops Canning	gs	
DESIGNATION:	Scheduled Monument, RB	LIST ENTRY NUMBER:	1014030	
CONDITION:	Extensive significant problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Long barrow on Easton Down, Bishops Cannings			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013366	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696	
ITE NAME:	Long barrow on Horton Down, Bishops Cannings			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013141	
CONDITION:	Extensive significant problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Saucer barrow 600 metres west of Beckhampton Buildings, Bishops Cannings			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012193	
CONDITION:	Extensive significant problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Saucer barrow on North Down, Bishops Cannings			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012627	
CONDITION:	Extensive significant problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696	
ITE NAME:	Square enclosure 350 metres north of Wansdyke	on Bishop's Canning	gs Down, Bishops Cannings	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013231	
CONDITION:	Extensive significant problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Two saucer barrows and a pair of bowl barrows 7 of a round barrow cemetery on Horton Down, Bis	50 metres SSW of shops Cannings	Beckhampton Plantation, forming par	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012982	
CONDITION:	Extensive significant problems	TREND:	Unknown	
RINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696	
ITE NAME:	Croucheston Down Barn round barrow, Bishopsto	one		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004772	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

SITE NAME:	Bowl barrow 85 metres north of Bishopstrow Hou	use, Bishopstrow	
esignation:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1019507
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Woodminton Down round barrow, Bower Chalke	2	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003729
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Corton long barrow, Boyton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010518
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Scrubbed Oak enclosure and linear boundary earth	nwork, Boyton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017713
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Bowl barrow on Cold Kitchen Hill, 740 metres no	rth east of Seagram	's Barn, Brixton Deverill
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016908
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
TE NAME:	Bowl barrow on Cold Kitchen Hill, 910 metres no	rth east of Seagram	's Barn, Brixton Deverill
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016909
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Long barrow on Pertwood Down, 1400 metres no	orth west of Lower	Pertwood, Brixton Deverill
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010463
CONDITION	Generally satisfactory but with significant localised	TREND:	Declining
CONDITION:	problems		8
RINCIPAL VULNERABILITY:	problems Animal burrowing - extensive	NEW ENTRY?:	No

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Knowle Hill round barrow, Broad Chalke		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003033
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round barrow 860 yards (786 metres) south ea	st of Knighton Hill Bui	ldings, Broad Chalke
Designation:	Scheduled Monument	LIST ENTRY NUMBER:	1004771
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Knighton Roman road (stretching from Reddish	Gore to reservoir), B	road Chalke / Bishopstone
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003728
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Roman road in Spye Park, Bromham		
DESIGNATION:	Scheduled Monument, part in RPG grade II	LIST ENTRY NUMBER:	1003010
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bell barrow 770 metres north west of New Bar	n, Bulford	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015216
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow: one of a group of round barrows	south of Bulford, Bulfo	ord
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009545
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow: one of a group of round barrows	south of Bulford, Bulfo	ord
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009602
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Bowl barrow: one of a group of round barrows	south of Bulford, Bulf	ord
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009604
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
TE NAME:	Bowl barrow: one of a group of round barrows	south of Bulford, Bulf	ord
esignation:	Scheduled Monument	LIST ENTRY NUMBER:	1009564
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
TE NAME:	Bowl barrow: one of a group of round barrows	south of Bulford, Bulfe	ord
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009605
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Nuthills Roman villa, Calne Without		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004723
CONDITION:	Extensive significant problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Long barrow 240 metres south west of Green B	arrow Farm, Castle C	Combe
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018419
CONDITION:	Extensive significant problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 190 metres north east of Nolands	Farm, Yatesbury, Che	erhill
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015808
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 350 metres north east of White H	orse Plantation, Cher	hill
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010134
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 700 metres south east of Field Bar	n, Chicklade	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015937
CONDITION:	Extensive significant problems	TREND:	Unknown
	Amphia plaughing	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Arable ploughing		140

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Fussell's long barrow, Clarendon Park		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005611
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Bowl Barrow, part of the round barrow cemetery	south of Codford D	Down, Codford
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016557
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Three bowl barrows in Colerne Park, 450 metres in	north of Keeper's C	Cottage, Colerne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010758
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow on Wick Down, Collingbourne Ducis	5	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012510
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0690
SITE NAME:	Bowl barrow 650 metres east of Summer Down Fa	arm, Collingbourne	Kingston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012544
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two bowl barrows 400 metres south of Summer E	Down Farm, Colling	bourne Kingston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012518
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
	Amble dissing	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Arable clipping		
	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
OWNER TYPE: SITE NAME:	Commercial company		
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Crowdown Clump earthwork (Godsbury), Colling	bourne Kingston / E	Burbage
OWNER TYPE: SITE NAME: DESIGNATION:	Crowdown Clump earthwork (Godsbury), Collingle Scheduled Monument Generally unsatisfactory with major localised	bourne Kingston / E	Burbage 1004759

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Bowl barrow 430 metres north west of Northdown	n Barn, Coombe Bi	ssett
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017705
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow on Little Toyd Down, 650 metres sou	th west of Grims I	odge Farm, Coombe Bissett
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015704
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Hillfort, two bowl barrows, medieval strip lynchets	and a cross dyke o	on Cley Hill, Corsley
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017296
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Visitor erosion - moderate	NEW ENTRY?:	Yes
OWNER TYPE:	Charity (heritage)	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Moated site and surrounding earthwork enclosure,	100 metres south	of Chelworth Farm, Cricklade
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013353
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Dumping	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Devizes Castle, Devizes		
DESIGNATION:	Scheduled Monument and Listed Building grade II, 3 LBs, CA	LIST ENTRY NUMBER:	1021375 and 1249362
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	Yes
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Berwick Coombe ditch, Donhead St. Andrew / Berv	wick St. John	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005587
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Long barrow on Ashmore Down, 775 metres north	of Ashgrove Cott	ages, Donhead St. Mary
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015938
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
	Animal burrowing - extensive	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Animai burrowing - extensive		110
PRINCIPAL VULNERABILITY: OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Clearbury Down round barrow, Downton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003003
CONDITION:	Extensive significant problems	TREND:	Unknown
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Wick Down round barrow, Downton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004776
CONDITION:	Extensive significant problems	TREND:	Unknown
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
TE NAME:	Long barrow 600 yards (550 metres) south east of	Vanity, Downton /	Whitsbury
esignation:	Scheduled Monument	LIST ENTRY NUMBER:	1003004
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
TE NAME:	Ogbury camp, Durnford		
ESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005677
ONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Nine round barrows forming a round barrow ceme Durrington	etery 400 metres no	orth of the eastern end of The Cursu
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1009067
ONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
RINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
TE NAME:	Bowl barrow 120 metres west of East Kennett Ion	g barrow forming p	art of a cemetery, East Kennett
ESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1014035
ONDITION:	Extensive significant problems	TREND:	Unknown
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
TE NAME:	Bowl barrow 200 metres east of East Kennett long	barrow forming pa	art of a barrow cemetery, East Kenne
ESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1014036
ONDITION:	Extensive significant problems	TREND:	Unknown
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Bowl barrow 200 metres north of East Kennett lo	ng barrow forming _l	part of a cemetery, East Kennett
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1014038
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round barrow on Easton Down, Easton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005693
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Barrow on Fifield Down 700 yards (640 metres) ES	SE of North Barn, E	bbesborne Wake
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003744
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Edington Priory (site of), Edington		
DESIGNATION:	Scheduled Monument, LB grade I, CA	LIST ENTRY NUMBER:	1004709
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Long barrow, Tinhead Hill, Edington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009783
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Natural erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Barrow Clump, bowl barrow, east of Ablington, Fig	gheldean	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009697
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Three round barrows west of Netheravon Aerodr	ome, Figheldean / F	ittleton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010192
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

HERITAGE AT RISK 2013 / SOU	TH WEST / WILTSHIRE (UA)			
SITE NAME:	Bowl barrow 540 metres north of Woodbine Barr	n, Fonthill Bishop		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015943	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
ITE NAME:	North Hill round barrows, Grafton			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004746	
CONDITION:	Extensive significant problems	TREND:	Unknown	
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
ITE NAME:	Bowl barrow 100 metres north of Great Botley C	opse, Grafton / Sha	bourne	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012301	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Romano-British kilns 150 yards (135 metres) SSW of Tottenham House, Great Bedwyn			
DESIGNATION:	Scheduled Monument, RPG grade II*	LIST ENTRY NUMBER:	1004706	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Grovely Castle and earthworks north of Grovely Martin	Wood, Great Wish	ford / Steeple Langford / Barford St.	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005604	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow 340 metres east of Holly Bush Farm,	, Grittleton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018418	
CONDITION:	Extensive significant problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
ITE NAME:	Medieval settlement immediately north west of Up	oper Littlecott Farm	, Hilmarton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018420	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

	Bell barrow 250 metres NNE of the sports grou	ind one of a group of	round barrows north west of Idmistr
SITE NAME:	Down, Idmiston	ind. One of a group of	Tourid barrows north west of familian
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013971
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bell barrow, three bowl barrows and gas testing	trenches on Idmiston	Down, Idmiston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014818
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 260 metres SSE of the southern cobarrows on Porton Down, Idmiston	orner of Moll Harris's	Clump: one of a group of round
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014096
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 440 metres SSW of the southern barrows on Porton Down, Idmiston	corner of Moll Harris's	s Clump: one of a group of round
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014094
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 530 metres SSW of the southern barrows on Porton Down, Idmiston	corner of Moll Harris's	s Clump: one of a group of round
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014092
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 535 metres SSW of the southern barrows on Porton Down, Idmiston	corner of Moll Harris's	s Clump: one of a group of round
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014093
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Bronze Age enclosure and two bowl barrows 52 Down, Idmiston	0 metres north east o	of Moll Harris's Clump on Idmiston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014819
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Long barrow 140 metres WSW of the Battery F	lill triangulation point	, Idmiston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014089
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Saucer barrow 400 metres north east of the spo Idmiston Down, Idmiston	rts ground: one of a g	group of round barrows north west
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013970
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two bowl barrows 265 metres south of the sou round barrows on Porton Down, Idmiston	thern corner of Moll	Harris's Clump: part of a group of
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014095
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two disc barrows and two bowl barrows 900 m Idmiston	etres north of Moll H	larris's Clump on Idmiston Down,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015557
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bell barrow, bowl barrow and section of hollow Winterslow	way 600 metres NN	W of Long Orchard, Idmiston /
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013983
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Barrow north east of Mere Down Farm, Kingsto	n Deverill	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003005
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

SITE NAME:	Bowl barrow 140 metres west of Cleeve, Kingstor	Deverill	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015805
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 200 metres south west of Keysley Fa	ırm, Kingston Deve	rill
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010405
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 670 metres SSE of Kingston Dairy, K	ingston Deverill	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016903
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 700 metres south west of Keysley Fa	rm, Kingston Deve	rill
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010406
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 735 metres SSE of Kingston Dairy, K	ingston Deverill	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019605
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 1480 metres east of Keysley Farm, K	ingston Deverill	
Designation:	Scheduled Monument	LIST ENTRY NUMBER:	1019738
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow east of Court Hill Plantation, Kingsto	n Deverill	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010403
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Bowl barrow on Keysley Down, 250 metres west Deverill	of the A350 Warmi	inster-Shaftesbury Road, Kingston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013877
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Romano-Celtic temple 300 metres south west of k	Keysley Farm, Kings	ton Deverill
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1016907
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	The Park round barrow, Kingston Deverill		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005595
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Moated site and fishponds south east of Rowden F	arm, Lacock	
designation:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1013876
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Settlement south east of Latton, Latton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004690
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Settlement west of Latton, Latton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004689
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Mineral extraction/related subsidence	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Medieval pottery kilns, Milford Farm, Laverstock		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003252
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

HERITAGE AT RISK 2013 / SOU	ith west / wiltshire (ua)		
SITE NAME:	Bell barrow on Rook Hill, 200 metres west of Pert	wood Wood, Long	bridge Deverill
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010470
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 880 metres north east of Field Barn	Farm, Longbridge D	everill
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016675
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round barrow south west of Parsonage Down, Lo	ngbridge Deverill	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005622
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Long barrow 600 metres north of Hebden Farm, L	uckington	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010395
CONDITION:	Extensive significant problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Enclosure on the summit of Rodmead Hill, Maiden	Bradley with Yarnf	ield
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1017704
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two saucer barrows 775 metres south east of Roo	dmead Farm, Maide	n Bradley with Yarnfield
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017697
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bohune Down round barrow, Manningford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003036
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

HERITAGE AT RISK 2013 / SOU	TH WEST / WILTSHIRE (UA)		
SITE NAME:	Bowl barrow 190 metres north east of Burton F	arm, Mere	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017711
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 760 metres north west of The Do	wn House, Mere	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016300
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Pond Bottom round barrow, Mere		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005620
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Two round barrows in Chaddenwick Furze, Mer	re	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015945
CONDITION:	Extensive significant problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Black Field Roman site, Mildenhall		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004726
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Camp on Forest Hill, Mildenhall / Savernake / Ma	ırlborough	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004697
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow: one of three round barrows west	of The Belt, Milston	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009636
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Bowl barrow 200 metres north east of Everleigh A	shes, Milton Lilbou	rne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009543
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Roman tile and brick kiln site 1000 yards (900 met	res) west of Tidling	Corner, Minety
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004702
CONDITION:	Extensive significant problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 900 metres north of Down Farm, Ne	ettleton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018391
CONDITION:	Extensive significant problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Other not for profit group	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Long barrow 400 metres north west of Fox Cover	t, Nettleton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010396
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Other not for profit group	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Long barrow 500 metres north of Lugbury Farm, N	lettleton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010397
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Early medieval settlement, palace, church and Bron Norton	ze Age ring ditches	340 metres east of Cowage Farm,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018389
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow: one of a group of dispersed barrows	south east of Nort	ton Plantation, Norton Bavant
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009830
CONDITION:	Extensive significant problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Round barrow on the south side of Cotley Hill, No	orton Bavant	
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1009835
CONDITION:	Extensive significant problems	TREND:	Declining
	A 11 1 1.	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Arable ploughing	INEVV EIVIKI:	INO

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

IENTAGE AT NISK 2013 / 300	THE WEST / WILLIST IIILE (OA)			
SITE NAME:	Barrow on Coombe Down, 1070 yards (980 me Andrew	tres) north east of Up	oper Poughcombe, Ogbourne St.	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005670	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Barrow on Smeathe's Ridge, Ogbourne St. Andr	ew		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005679	
CONDITION:	Extensive significant problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bell barrow 200 metres north of Rockley Planta	tion, Ogbourne St. Ar	ndrew	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012195	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow 375 metres east of Wick Bottom Barn, Ogbourne St. Andrew			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015814	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow 630 metres north east of Wick Bo	ttom Barn, Ogbourne	e St. Andrew	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015803	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow and a saucer barrow 200 metres n	orth of Rockley Planta	ation, Ogbourne St. Andrew	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012197	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Ogbourne Maizey Down round barrow, Ogbour	ne St. Andrew		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004762	
CONDITION:	Extensive significant problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Round barrow 750 yards (690 metres) south east	st of Smeathe's Planta	tion, Ogbourne St. Andrew	
	Scheduled Monument	LIST ENTRY NUMBER:	1004733	
DESIGNATION:				
DESIGNATION: CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
		TREND: NEW ENTRY?:	Declining No	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Round barrow cemetery 320 metres south east	of Down Farm, Pewse	ey
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1016779
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	The Spectacles, Pewsey		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005638
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Long barrow, Winterbourne, Pitton and Farley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005623
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Moated site 300 metres north east of Potterne F	Park Farm, Potterne	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012152
ONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bell barrow 350 metres south west of Barbury E	arn, Preshute	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012190
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Bowl barrow 300 metres east of Ivy House Farm	n, Preshute	
DESIGNATION:	Scheduled Monument	LICT ENITDY NILIMBED.	1012294
	Scheduled i fortament	LIST ENTRY NUMBER:	1012271
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY: DWNER TYPE:	Extensive significant problems Arable ploughing	TREND: NEW ENTRY?: CONTACT:	Unknown No
PRINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME:	Extensive significant problems Arable ploughing Private	TREND: NEW ENTRY?: CONTACT:	Unknown No
PRINCIPAL VULNERABILITY: DWNER TYPE: JITE NAME: DESIGNATION:	Extensive significant problems Arable ploughing Private Group of round barrows on Rough Hill, Preshut	TREND: NEW ENTRY?: CONTACT:	Unknown No Ruth Garner 0117 975 0696
PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Extensive significant problems Arable ploughing Private Group of round barrows on Rough Hill, Preshut Scheduled Monument	TREND: NEW ENTRY?: CONTACT: e LIST ENTRY NUMBER:	Unknown No Ruth Garner 0117 975 0696 1003034
PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY:	Extensive significant problems Arable ploughing Private Group of round barrows on Rough Hill, Preshut Scheduled Monument Extensive significant problems	TREND: NEW ENTRY?: CONTACT: e LIST ENTRY NUMBER: TREND:	Unknown No Ruth Garner 0117 975 0696 1003034 Declining
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Extensive significant problems Arable ploughing Private Group of round barrows on Rough Hill, Preshut Scheduled Monument Extensive significant problems Arable ploughing	TREND: NEW ENTRY?: CONTACT: E LIST ENTRY NUMBER: TREND: NEW ENTRY?:	Unknown No Ruth Garner 0117 975 0696 1003034 Declining No
CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Extensive significant problems Arable ploughing Private Group of round barrows on Rough Hill, Preshut Scheduled Monument Extensive significant problems Arable ploughing Private	TREND: NEW ENTRY?: CONTACT: E LIST ENTRY NUMBER: TREND: NEW ENTRY?:	Unknown No Ruth Garner 0117 975 0696 1003034 Declining No
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Extensive significant problems Arable ploughing Private Group of round barrows on Rough Hill, Preshut Scheduled Monument Extensive significant problems Arable ploughing Private Preshute Down field system, Preshute	TREND: NEW ENTRY?: CONTACT: E LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:	Unknown No Ruth Garner 0117 975 0696 1003034 Declining No Ruth Garner 0117 975 0696
RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: CONDITION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: CONDITION:	Extensive significant problems Arable ploughing Private Group of round barrows on Rough Hill, Preshut Scheduled Monument Extensive significant problems Arable ploughing Private Preshute Down field system, Preshute Scheduled Monument	TREND: NEW ENTRY?: CONTACT: E LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: LIST ENTRY NUMBER:	Unknown No Ruth Garner 0117 975 0696 1003034 Declining No Ruth Garner 0117 975 0696
PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION:	Extensive significant problems Arable ploughing Private Group of round barrows on Rough Hill, Preshut Scheduled Monument Extensive significant problems Arable ploughing Private Preshute Down field system, Preshute Scheduled Monument Extensive significant problems	TREND: NEW ENTRY?: CONTACT: E LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: LIST ENTRY NUMBER: TREND:	Unknown No Ruth Garner 0117 975 0696 1003034 Declining No Ruth Garner 0117 975 0696 1004763 Declining

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Sharpridge field system, Preshute		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004764
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Membury Camp (see also West Berkshire Unitar	y Authority), Ramsbu	ury / Lambourn
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002994
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Roundway Hill Farm round barrows, Roundway	Bishops Cannings	
DESIGNATION:	Scheduled Monument, RB	LIST ENTRY NUMBER:	1004773
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 450 metres north of Cross Droves	, Shalbourne	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012274
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Long barrow on Smay Down, 300 metres east of	The Hassock, Shalbo	ourne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010467
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Wansdyke: Daniel's Lane section, Shalbourne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005594
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Great Botley Copse long barrow, and disc barro	w near it, Shalbourne	/ Grafton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005692
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Long barrow 250 metres east of Boyton Field Ba	rn, Sherrington / Boy	ton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010520
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696

Immediate risk of further rapid deterioration or loss of fabric; no

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

HERITAGE AT RISK 2013 / SOU	TH WEST / WILTSHIRE (UA)		
SITE NAME:	Newton Barrow, South Newton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005687
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Earthwork enclosure on Milk Hill, Stanton St. Bern	ard	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004735
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Stapleford Castle, Stapleford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005686
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	English Heritage	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Barrow north of 'The Spectacles', Steeple Langford	I	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004742
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 240 metres east of The Penning, Stee	eple Langford	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015025
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Deptford Down round barrow, Steeple Langford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005615
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	East Castle, Steeple Langford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005599
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Little Langford round barrow, north of Upper Farn	n Down, Steeple La	angford
esignation:	Scheduled Monument	LIST ENTRY NUMBER:	1005605
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Round barrow 230 yards (210 metres) north west	of New Field Plant	ation, Steeple Langford
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004725
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Orchard Castle, Stourton with Gasper		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005639
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bell barrow 350 metres north of Haydon Farm, Su	tton Veny	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010517
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bell barrow on Parsonage Down, 1.3 kilometres so	outh east of Lord's	Hill Farm, Sutton Veny
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016677
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow on Littlecombe Down, Sutton Veny		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005683
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Pair of bowl barrows 1050 metres NNW of Pertw	ood Wood, Sutton	Veny
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019739
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

ERITAGE AT RISK 2013 / SOU	TH WEST / WILLSHIKE (OA)		
ITE NAME:	Fosbury camp, Tidcombe and Fosbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005682
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Bowl barrow south east of Sidbury Hill, Tidworth		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010022
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Castle Ditches camp, Tisbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005701
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696
TE NAME:	Romano-British villa complex 330 metres north we	est of Queen Court	Farm, Tockenham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017015
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Bowl barrow on Woodley Down 675 metres NNE	of Ashmore Farm,	Tollard Royal
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020465
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Casterley Camp and associated monuments, Upavo	on	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010074
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Two saucer barrows 250 metres west of John's Pla	inting, Upton Lovell	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007564
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Bowl barrow 500 metres south of Upton Scudamo	re, Upton Scudamo	ore
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010398
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Enclosure and linear earthworks between Bishopst Bishopstrow / Norton Bavant	row Down and Sou	uth Down Sleight, Warminster /
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010283
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Barrow I/4 mile (400 metres) north west of Willo	ughby Hedge, West	: Knoyle
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005666
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow in The Belt, 350 metres north east of	f Hill Barn, West O	verton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019901
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ruth Garner 0117 975 0696
ITE NAME:	Bowl barrow 50 metres south west of Rox Hill Clu	ımp, Wilsford cum	Lake
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010836
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 100 metres north of Rox Hill Clump, Wilsford cum Lake		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1013813
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696
SITE NAME:	Bowl barrow 250 metres south of Westfield Farm	buildings, Wilsford	cum Lake
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010835
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Bowl barrow 350 metres south west of Normanton Gorse, Wilsford cum Lake			
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1013812	
CONDITION:	Extensive significant problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow 400 metres west of Normanton Gorse, Wilsford cum Lake			
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010831	
CONDITION:	Extensive significant problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow 450 metres east of The Diamond	south of the A303, W	ilsford cum Lake	
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1011709	
CONDITION:	Extensive significant problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow south of the A303 and north west of Normanton Gorse, Wilsford cum Lake			
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010832	
CONDITION:	Extensive significant problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Pond barrow south of the A303 and 400 metres Wilsford cum Lake	west of Normanton	Gorse containing the 'Wilsford Shaft',	
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010833	
CONDITION:	Extensive significant problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Seven bowl barrows and a pond barrow forming a round barrow cemetery 200 metres north of The Diamond on Wilsford Down, Wilsford cum Lake			
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010834	
CONDITION:	Extensive significant problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Horse Barrow, Winterbourne			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005610	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No	
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow 350 metres north west of Greenla	nd Farm, Winterbour	ne Stoke	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010892	
CONDITION:	Extensive significant problems	TREND:	Unknown	
	· ·			
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Bowl barrow 830 metres south west of Greenla	nds Bungalow, east of	Shrewton, Winterbourne Stoke	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015217	
CONDITION:	Extensive significant problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bronze Age enclosure and bowl barrow 100 me Stoke Down, Winterbourne Stoke	tres west of Longbarr	ow Cross Roads on Winterbourne	
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1011048	
CONDITION:	Extensive significant problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Disc barrow and pond barrow 350 metres NNV	V of Greenland Farm,	Winterbourne Stoke	
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010891	
CONDITION:	Extensive significant problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bell barrow and bowl barrow 500 metres NNW of Long Orchard, Winterslow			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013984	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow 750 metres NNE of Easton Down	Farm, Winterslow		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013986	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Government or agency	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Heale Hill round barrows and earthworks, Woo	dford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005609	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696	
SITE NAME:	Bowl barrow 175 metres west of Square Copses Rivers	part of the Square C	opse barrow cemetery, Wootton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013352	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Bowl barrow 275 metres west of Square Copse: part of the Square Copse barrow cemetery, Wootton Rivers		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013364
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ruth Garner 0117 975 0696



© English Heritage

SITE NAME:	Tottenham House and Savernake Forest, Savernake / Burbage / Great Bedwyn / Little Bedwyn / Mildenhall
DESIGNATION:	Registered Park and Garden grade II*, 19 LBs, 7 SMs
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1000472

Extensive landscape of rides linking Savernake Forest with ornamental parkland and pleasure grounds around the house. Exemplifies the work of Burlington, Brown, Cundy and others. Main house has planning permission for hotel development, including building over Brown's walled garden and laying out a golf course in the park. Unclear if this will be implemented. Forestry Commission manages Savernake Forest on a long lease.

Contact: Ruth Garner 0117 975 0696

SITE NAME:	Pewsey - Wilcot Road, Pewsey		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Helen Garside (LPA) 01380 724911

WILTSHIRE (UA) / NEW FOREST (NP)

SITE NAME:	Barrows in Bath Hole and Bury Hill Plantations, Redlynch, Wiltshire (UA)		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004754
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ruth Garner 0117 975 0696

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 - Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



This document is one in a series of publications produced as part of English Heritage's national Heritage at Risk programme. More information about Heritage at Risk and other titles in the series can be found at www.english-heritage.org.uk/risk

HERITAGE AT RISK

Published October 2013 by English Heritage I Waterhouse Square, 138-142 Holborn, London ECIN 2ST