Heritage at Risk



Contents

The Register	III
Content and criteria	Ш
Key statistics	V
Key to the entries	VI
Entries on the Register by local planning authority	VIII
Bath and North East Somerset (UA)	I
Bournemouth Christchurch and Poole (UA)	3
Bristol, City of (UA)	5
Cornwall (UA)	8
Devon Dartmoor (NP) East Devon Exeter Exmoor (NP) Mid Devon North Devon South Hams Teignbridge Torridge West Devon Dorset (UA) Gloucestershire Cheltenham Cotswold Forest of Dean Gloucester Stroud	48 48 71 77 78 79 82 86 93 96 103 107 145 146 150 153
Tewkesbury Isles of Scilly (UA)	158 161
North Somerset (UA)	165
Plymouth, City of (UA)	167
Somerset	167 171
Exmoor (NP) Mendip Sedgemoor Somerset West and Taunton South Somerset	171 174 180 184 189
South Gloucestershire (UA)	194
Swindon (UA)	197
Torbay (UA)	199
Wiltshire (UA)	201

II

THE REGISTER

The Heritage at Risk Register includes historic buildings and sites at risk of being lost through neglect, decay or deterioration.

It includes all types of designated heritage assets, including Conservation Areas, which are designated and assessed by Local Planning Authorities.

The aim of the Register is to focus attention on those places in greatest need. Historic England, in partnership with others, is able to help tackle heritage at risk. We work with owners, friends groups, developers and other stakeholders to find imaginative solutions for historic places and sites at risk across England.

More information about our role, the advice and funding available, and useful <u>publications</u> and <u>guidance</u> is available on our <u>website</u>.

Criteria for inclusion on the Register

RISK ASSESSMENTS

Heritage assets included on the Register are assessed according to the nature of the site. The risk assessment methodologies outlined below are based on factors which can threaten the different types of heritage assets and lead to them becoming at risk.

BUILDINGS AND STRUCTURES

To be considered for inclusion on the Register, buildings or structures must be:

- listed on the National Heritage List for England;
- in secular (non-worship) use.

And either:

- a grade I or II* listed building, or
- a grade II listed building in London, or
- a structural scheduled monument with upstanding remains,

Buildings or structures are assessed on the basis of condition and, where applicable, occupancy (or use) reflecting the fact that a building which is occupied is generally less vulnerable than one that is not.

Occupancy (or use) is assessed as 'vacant', 'part-occupied', 'occupied', 'not applicable', or occasionally, 'unknown'.

Many structures fall into the 'not applicable' category, for example: ruins, walls, gates, headstones or boundary stones.

Condition is assessed as 'very bad', 'poor', 'fair' or 'good'. The condition of buildings or structures on the Register is typically very bad or poor, but can be fair or, very occasionally, good. This reflects the fact that some buildings or structures are vulnerable because they are empty, underused or face redundancy without a new use to secure their future. Assessing vulnerability in the case of buildings in fair condition necessarily involves judgement and discretion. A few buildings remain on the Register in good condition, having been repaired or mothballed, but still awaiting a new use or occupancy.

Buildings or structures are removed from the Register when they are fully repaired/consolidated, and their future secured either through occupation and use, or through the adoption of appropriate management.

PLACES OF WORSHIP

To be considered for inclusion on the Register, places of worship must be listed grade I, grade II* or grade II on the National Heritage List for England, and be used as a public place of worship at least six times a year.

Places of worship are assessed on the basis of condition only. If a place of worship is in very bad or poor condition, it is added to the Register. This includes places of worship which are generally in fair or good condition but have major problems with one key element, like the tower.

Once on the Register, places of worship can move through the condition categories (e.g. from very bad to poor, to fair, even good) as repairs are implemented and the condition improves, until they are fully repaired and can be removed from the Register. This means that there are some places of worship in good condition on the Register but with outstanding issues still to be resolved at the time when they were assessed.

ARCHAEOLOGY

To be considered for inclusion on the Register, archaeological sites must be listed as scheduled monuments and included on the National Heritage List for England.

Archaeology assessments cover scheduled earthworks and buried archaeology.

The risk assessment is based on their condition and vulnerability, the trend in their condition, and their likely future vulnerability. A site's condition is expressed in terms of the scale and severity of adverse effects on it, ranging from 'extensive significant problems' to 'minor localised problems'.

Archaeological entries are removed from the Register once sufficient progress has been made to address the identified issues, and a significant reduction in the level of risk has been demonstrated.

PARKS AND GARDENS

To be considered for inclusion on the Register, parks and gardens must be listed as grade I, grade II* or grade II and included on the National Heritage List for England. Parks and gardens are assessed in terms of condition and vulnerability. Steps being taken by owners to address problems are also taken into consideration.

Parks and gardens assessed as being at risk are typically affected by development and neglect. They have frequently been altered by development or are faced with major change. The original function of these landscapes has often changed and divided ownership leads to the loss of their cohesive historic design.

Park and garden entries are removed from the Register once steps have been taken to address issues and positive progress is being made.

BATTLEFIELDS

To be considered for inclusion on the Register, battlefields must be listed and included on the National Heritage List for England. Battlefields deemed to be at risk of loss of cultural significance are included on the Register.

The principal risks and threats are:

- development pressure e.g. encroachment of buildings;
- pressures of particular use within the site e.g. arable cultivation;
- damage e.g. unregulated metal detecting.

Battlefields are removed from the Register either when damaging activities cease/are managed, or when threats recede due to effective planning.

WRECK SITES

To be considered for inclusion on the Register, wrecks must be listed and included on the National Heritage List for England.

Wreck sites are assessed based on their current condition, vulnerability and the way they are being managed.

Wrecks are vulnerable to both environmental and human impacts. Risks that contribute to inclusion on the Register range from unauthorised access to erosion and fishing damage. The monitoring process ensures that the significance of the site is identified and maintained. In spite of the inherent difficulties in caring for this type of site, careful management must be maintained.

Wrecks are removed from the Register once an appropriate management and monitoring regime is operational.

CONSERVATION AREAS

Once a year Historic England asks every local authority in England to consider the state of its conservation areas and fill in (and update as appropriate) risk assessment questionnaires for those that cause concern, or are believed to no longer be at risk.

Conservation areas that are deteriorating, or are in very bad or poor condition and not expected to change significantly in the next three years, are defined as being at risk.

The approach taken to assess conservation areas at risk has been refined since the first survey in 2008/2009. An overall category for condition, vulnerability and trend is included for each conservation area on the Heritage at Risk Register. Conservation areas identified as at risk in 2009, but not reassessed since using the revised methodology, are included on the Register but with limited information.

Conservation areas are removed from the Register once plans have been put in place to address the issues that led to the conservation area being at risk, and once positive progress is being made.

THE EFFECT OF COVID-19 ON THE COLLECTION AND COLLATION OF THE STATISTICS USED FOR THE 2020 REGISTERS

The collection of this year's data has been affected by Covid-19. From the onset of 'lockdown' site visits were not possible for either our staff or local authority colleagues, meaning that the usual level of on-site checking of existing or proposed entries on/for the Register was not possible for that period. However, desk-based assessments and updates were carried out.

Key statistics

BUILDINGS AND STRUCTURES

- Nationally, 766 (3.4%) out of a total of 22,485 grade I and II* listed buildings (excluding places of worship) are on the Register. In the South West the percentage is 3.0% (160 listed secular buildings).
- In addition to this, of the 6,993 scheduled monuments in the South West, 48 (0.7%) structural scheduled monuments are on the Register.
- 5 building or structure entries (including structural scheduled monuments) have been removed from the 2019 South West Register because their futures have been secured, and 18 have been added.

PLACES OF WORSHIP

- Of the 14,788 listed places of worship in England, 932 (6.3%) are on the Register. In the South West, 155 (5.3%) are on the Register.
- 12 places of worship have been removed from the 2019 South West Register following repair work, and 18 have been added.

ARCHAEOLOGY

- Of the 19,895 scheduled monuments in England, 2,090 (10.5%) are on the Register assessed as archaeology. Of the 6,993 archaeological scheduled monuments in the South West, 1,052 (15.0%) are on the Register.
- 30 archaeology entries have been removed from the 2019 South West Register for positive reasons, and 35 have been added.

PARKS AND GARDENS

- Of the 1,670 registered parks and gardens in England 103 (6.2%) are on the Register, the 304 registered parks and gardens in the South West, 17 (5.6%) are on the Register.
- No park and garden entries were added to or removed from the 2019 South West Register.

BATTLEFIELDS

• Of the 47 registered battlefields in England, 3 (6.4%) are on the Register. None of the 10 registered battlefields in the South West are on the Register.

WRECK SITES

• Of the 54 protected wreck sites around England's coast, 3 (5.6%) are on the Register. None of the 27 protected wreck sites in the South West are on the Register.

CONSERVATION AREAS

- There are currently 491 conservation areas on the Register. Of these 20 are in the South West.
- 6 conservation areas have been removed from the 2019 South West Register for positive reasons, and none have been added.

HISTORIC ENGLAND FUNDING

• £1.58 million in grant was spent on 62 entries on the South West Register during 2019/20.

Risk assessments of heritage assets are based on the nature of the site. Buildings and structures include structural scheduled monuments and listed buildings (excluding listed places of worship); archaeology assessments include earthworks and buried archaeology. Please note that some sites may have more than one entry under different risk assessment methodologies, for example if a site has more than one listing for its different elements or if it consists of buried and structural remains.

Key to the entries

The Register includes the following risk assessment types:

• Building or structure

(grade I and II* listed buildings, grade II listed buildings in London and structural scheduled monuments)

Place of worship

(grade I, II* and II listed buildings)

Archaeology

(scheduled monuments – earthworks and buried archaeology)

Park and garden

(Registered parks and gardens)

Battlefield

(Registered battlefields)

Wreck site

(Protected wreck sites)

Conservation area

(Conservation areas)

Details are given here for all risk assessment types even if entries are not present in the Regional Register.

ORDER

Entries are grouped and ordered alphabetically, first by County (dark grey bands) or Unitary Authority (light grey bands), and then by Local Planning Authority (National Park/Unitary Authority/District or Borough).

A blank band denotes the end of a county and the beginning of a unitary authority.

Sites that straddle more than one local planning authority are included under the lead authority.

Within each planning authority, entries are grouped by risk assessment type in the following order:

- Buildings or structures
- Places of worship
- Archaeology
- Parks and gardens
- Battlefields
- Wreck sites
- Conservation areas

Within each risk assessment type, entries are ordered alphabetically by parish, locality and street/site name (except for conservation areas and protected wreck sites which are ordered by site name only).

LISTING

The principal listing type is noted for each entry and includes:

- Listed Building (LB) grade I or II*
- Listed Place of Worship grade I, II* or II
- Scheduled Monument (SM)
- Registered Park and Garden (RPG) grade I, II* or II
- Registered Battlefield (RB)
- Protected Wreck Site (PWS)
- Conservation Area (CÀ)

Other listing types that apply to a given site, including location within a World Heritage Site (WHS), are also noted.

If an entry is a dual list entry (both listed and scheduled), 'and' rather than a comma is used (eg 'Scheduled Monument and Listed Building grade I'). If a scheduled monument entry is a dual list entry with a number of listed buildings, each is separated by a semicolon.

The National Heritage List Entry Number is included for all entries (except conservation areas). If a site has dual list entries, all relevant List Entry Numbers are noted.

CONDITION

For buildings (including places of worship), condition is graded as: 'very bad', 'poor', 'fair' and 'good'.

For sites that cover areas (scheduled monuments – archaeology assessments, parks and gardens, battlefields and wreck sites) one overall condition category is recorded. The category may relate only to the part of the site or monument that is at risk and not the whole site:

- extensive significant problems
- generally unsatisfactory with major localised problems
- generally satisfactory but with significant localised problems
- generally satisfactory but with minor localised problems
- optimal
- unknown (noted for a number of scheduled monuments that are below-ground and where their condition cannot be established)

For conservation areas, condition is categorised as: 'very bad', 'poor', 'fair' and 'optimal'.

If a site has suffered from heritage crime it is noted in the summary. Heritage crime is defined as any offence which harms the heritage asset or its setting and includes arson, graffiti, lead theft and vandalism.

OCCUPANCY/USE

For buildings (excluding places of worship) that can be occupied or have a use, the main vulnerability is vacancy or under-use. Occupancy (or use) is noted as follows:

- vacant
- part occupied
- occupied
- unknown
- not applicable

VULNERABILITY

Principal vulnerability is noted for archaeology assessments and may relate only to the part of the site that is at risk, and include:

- animal burrowing
- arable ploughing
- coastal erosion
- collapse
- deterioration in need of management
- scrub/tree growth
- visitor erosion

For parks and gardens, battlefields, wreck sites and conservation areas, vulnerability is noted as high, medium or low.

PRIORITY CATEGORY

Priority for action is assessed on a scale of A to F, where 'A' is the highest priority for a site which is deteriorating rapidly with no solution to secure its future, and 'F' is the lowest priority.

For buildings and structures and places of worship the following priority categories are used as an indication of trend and as a means of prioritising action:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented
- C Slow decay; no solution agreed
- D Slow decay; solution agreed but not yet implemented
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
- F Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented

For battlefields and wreck sites the following priority categories are used as a means of prioritising action:

- A No action/strategy identified or agreed (where trend is declining or unknown)
- B Action/strategy agreed but not yet implemented (where trend is declining or unknown)
- C No action/strategy identified or agreed (where trend is stable or improving)
- D Action/strategy agreed but not yet implemented (where trend is stable or improving)
- E Monitoring as appropriate (any trend)
- F Action implemented/strategy underway/scheme in progress (any trend)

Previous year priority categories are given in brackets, otherwise 'New entry' is noted.

'New entry – re-assessed' indicates an existing site on the Register that has been re-assessed using a different risk assessment methodology and is included on this year's Register under the new assessment type.

TREND

Trend for archaeology entries, parks and gardens, battlefields and wreck sites may relate only to the part of the site that is at risk and is categorised as:

- declining
- stable
- improving
- unknown

For conservation areas trend is categorised as:

- deteriorating
- deteriorating significantly
- no significant change
- improving
- improving significantly
- unknown

OWNERSHIP

A principal ownership category is given for each entry, and if sites are in divided ownership, a 'multiple' ownership category is noted.

CONTACT

This is the member of the Historic England local team who acts as a first point of contact for the case, and to whom enquiries should be addressed.

For conservation areas, the contact is the conservation/planning officer at the relevant local planning authority (indicated by 'LPA').

We are not in any sense agents for the owners of the sites included, but we will endeavour to put people in touch with them where appropriate.

ABBREVIATIONS

CA Conservation Area
HE Historic England
HLF Heritage Lottery Fund
LB Listed Building

LPA Local Planning Authority

NP National Park

PWS Protected Wreck Site
RB Registered Battlefield

RPG Registered Park and Garden SM Scheduled Monument

UA Unitary Authority
WHS World Heritage Site

Entries on the Register by local planning authority

Local planning authority	Building and structure entries	Place of worship entries	Archaeology entries	Park and garden entries	Battlefield entries	Wreck site entries	Conservation area entries	
BATH AND NORTH EAST SOMERSET (UA)								
Bath and North East Somerset (UA)	4	0	8	ı	0	0	3	
BOURNEMOUTH CHRISTC	HURCH AND PO	OLE (UA)						
Bournemouth Christchurch and Poole (UA)	0	5	4	0	0	0	2	
BRISTOL, CITY OF (UA)		1		1				
Bristol, City of (UA)	9	3	3	0	0	0	1	
Bristol, City of (UA) / Bath and North East Somerset (UA) [†]	0	0	0	I	0	0	0	
CORNWALL (UA)								
Cornwall (UA)	44	19	184	ı	0	0	1	
DEVON								
Dartmoor (NP)	2	3	155	0	0	0	0	
East Devon	5	3	32	I	0	0	0	
Exeter	0	2	I	0	0	0	0	
Exmoor (NP)	0	2	7	0	0	0	0	
Mid Devon	3	0	16	0	0	0	3	
North Devon	3	7	16	0	0	0	I	
South Hams	9	11	21	0	0	0	0	
Teignbridge	2	3	7	2	0	0	1	
Torridge	2	11	33	0	0	0	0	
West Devon	7	3	10	0		0	0	
DORSET (UA)	'			ı				
Dorset (UA)	24	5	230	ı	0	0	2	
GLOUCESTERSHIRE								
Cheltenham	0	2	0	0	0	0	0	
Cotswold	3	4	21	0	0	0	0	
Forest of Dean	4	7	7	0	0	0	0	
Gloucester	5	0	0	0	0	0	I	
Stroud	5	7	4	0	0	0	2	
Tewkesbury	7	4	7	0	0	0	0	
ISLES OF SCILLY (UA)								
Isles of Scilly (UA)	2	0	30	0	0	0	0	
NORTH SOMERSET (UA)								
North Somerset (UA)	3	I	2	0	0	0	0	
PLYMOUTH, CITY OF (UA)								
Plymouth, City of (UA)	14	I	11	0	0	0	0	
SOMERSET								
Exmoor (NP)	2	0	18	0	0	0	0	
Mendip	5	11	17	0	0	0	0	
Sedgemoor	3	10	13	I	0	0	0	
Somerset West and Taunton	7	4	16	I	0	0	I	
South Somerset	8	14	3	2	0	0	0	
SOUTH GLOUCESTERSHIRE	(UA)							
South Gloucestershire (UA)	7	2	3	2	0	0	2	
SWINDON (UA)								
Swindon (UA) TORBAY (UA)	1	0		0	0	0	0	
Torbay (UA)	4	2	2	2	0	0	0	
DEVON								
Torbay (UA) / South	0	0	0	I	0	0	0	
WILTSHIRE (UA)								
Wiltshire (UA)	14	9	159	I	0	0	0	

Local planning authority	Building and structure entries	Place of worship entries	Archaeology entries	Park and garden entries	Battlefield entries	Wreck site entries	Conservation area entries
Wiltshire (UA) / New Forest (NP) [†]	0	0	I	0	0	0	0
TOTAL	208	155	1052	17	0	0	20

 $^{^{\}dagger}$ Sites that cross local planning authority boundaries

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

BATH AND NORTH EAST SOMERSET (UA)



© Historic England

SITE NAME:	Beckford's Tower, Bath
DESIGNATION:	Listed Building grade I, RPG grade II, CA, WHS
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Charity (haritage)

Charity (heritage)

Beckford's Tower was built by William Beckford in 1826-7 as a personal retreat which functioned both as an observatory and as a treasure chest filled with his collections of art, furniture and books. It was connected with his home at 19 & 20 Lansdown Crescent by a milelong garden known as Beckford's Ride, parts of which survive. Between 1997-2000, the tower and lantern structure underwent a programme of significant structural repairs. There is currently water ingress within the lantern. A Development Grant from the National Lottery Heritage Fund was offered at the end of 2019.

Contact: Sarah Ball 0117 975 0666



© Historic England Archive

SITE NAME:	King Edward's School, Broad Street, Bath
DESIGNATION:	Listed Building grade II*, CA, WHS
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Commercial company

1395027

School dating from 1752. A scheme for hotel use was submitted but withdrawn in 2006. Works to repair the roof have been successfully completed. The threat of decay has diminished but the building remains vacant. Permission for hotel use (granted in 2010 and renewed in 2013) has been implemented and Historic England engaged in further pre-app discussion to explore amendments to consent before comprehensive works begin.

Contact: Jacqueline Smith 0117 975 0667




© Jim Warren

SITE NAME:	Cleveland Baths, Hampton Row, Bath
DESIGNATION:	Listed Building grade II*, CA, WHS
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Local authority

1396146

Dating from 1815, Cleveland Baths are believed to be the oldest surviving public outdoor swimming pools in England. A diminutive Georgian crescent houses the changing rooms and Caretaker's Cottage. Listed Building Consent was granted in April 2017 for a scheme of repair and renovation works that will enable the baths to be reopened for use. The Cleveland Pools Trust have confirmed a successful grant from the National Lottery Heritage Fund and aim to complete the works for re-opening in Spring 2021.

Contact: Stephen Guy 0117 975 0725



© Historic England

SITE NAME:	Hinton Priory, Hinton Charterhouse
DESIGNATION:	Scheduled Monument and Listed Buildings - 3 grade I, LB grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

LIST ENTRY NUMBER: 1007014 and 1136191; 1320809: 1129461

Early C13 Carthusian monastery, chapter house and refectory still standing. Later stables, coach house and garden buildings incorporate earlier material and follow original complex layout of cloister and cells. All structures in use except chapter house, which is the area at risk. Some parts are in need of a condition assessment.

Contact: Sarah Ball 0117 975 0666

SITE NAME:	Wansdyke: section 1230 yards (1120 metres) eastwards from Burnt House Inn, Southstoke			
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1007003	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Gardening	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345	

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

SITE NAME:	Camerton Romano-British town and associated pr Norton-Radstock	ehistoric and early	medieval monuments, Camerton /
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013881
CONDITION:	Extensive significant problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Roman road 720 yards (660 metres) long, north of	Abbey Farm, Hinto	on Charterhouse
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1005421
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Stantonbury camp and adjacent sections of Wansd	yke, Marksbury	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002487
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Lansdown Roman camp, North Stoke		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005422
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Little Down camp, North Stoke		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004677
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Wansdyke: south east of Newbarn Farm, Norton I	Malreward	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003066
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
ITE NAME:	Roman villa at Upper Hayes, Wellow		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007002
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.
 Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet
- implemented.

 C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS



© Historic England

SITE NAME:	Lansdown Cemetery and Beckford's Tower
DESIGNATION:	Registered Park and Garden grade II, 4 LBs, CA, WHS
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	Medium
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1000563

A cemetery consecrated in 1848, incorporating features of a former pleasure ground and ride created by William Beckford and the architect Henry Edmund Goodridge in c 1825-7. Key design features have been neglected and are in declining condition including the Grotto Tunnel. The landscape has become fragmented as a result of different ownership. Beckford's Tower (listed II*) has also been placed on Historic England's Heritage at Risk register. The Beckford Tower Trust are currently drawing up plans for an application for National Lottery Heritage Fund grant.

Contact: Jo McAllister 0117 975 0696

SITE NAME:	Keynsham		
DESIGNATION:	Conservation Area, 53 LBs, SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Adrian Neilson (LPA) 01225 477020
CITE NAME	Mel Ni		
SITE NAME:	Midsomer Norton and Welton, Norton-Radstock		
DESIGNATION:	Conservation Area, 37 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Adrian Neilson (LPA) 01225 477020
VULNERABILITY:	Medium	CONTACT:	Adrian Neilson (LPA) 01225 477020
VULNERABILITY: SITE NAME:	Medium Paulton (including Paulton Basin)	CONTACT:	Adrian Neilson (LPA) 01225 477020
		CONTACT: NEW ENTRY?:	Adrian Neilson (LPA) 01225 477020 No
SITE NAME:	Paulton (including Paulton Basin)		,
SITE NAME: DESIGNATION:	Paulton (including Paulton Basin) Conservation Area, 17 LBs	NEW ENTRY?:	No

BOURNEMOUTH CHRISTCHURCH AND POOLE (UA)

LIST ENTRY NUMBER:



© Historic England	

SITE NAME:	Church of St John the Evangelist, Christchurch Road, Bournemouth
designation:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1152799 Contact: Katy Hoskyn 0117 975 1311



© Historic England

SITE NAME:	Church of St Michael, Poole Road, Bournemouth
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1324732

Substantial Victorian church with very large tower. This tower has significant problems and is difficult to access for maintenance. The rainwater goods are not taking water away and interior wall paintings are vulnerable to water ingress.

Flint-clad Victorian church. A Listed Places of Worship Roof Repairs Grant was awarded and stage I repairs to the roof and cast-iron rainwater goods completed in 2017. The west end and tower are also in a poor state, with crumbling stone and falling masonry, and funding is

Contact: Katy Hoskyn 0117 975 1311

currently sought for this second phase.

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



SITE NAME:	Church of St Clement, St Clement's Road, Bournemouth
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1324751

A large Victorian church set in a public park. The tower roof is leaking badly and needs to be replaced. The rainwater goods are inadequate to carry water away from the building and the masonry is showing signs of damp.

© Historic England

	7		
		1	L
	11-1		HELE
A	ZATE	1	100

SITE NAME:	Church of St Stephen, St Stephen's Road, Bournemouth
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1324756

Road, Poole

1273602

Church of St Dunstan (formerly

St Osmund), Bournemouth

Monumental Victorian church with a faceted east end, set within a small, restricted site. There is some water penetration, and there have been falls of interior masonry due to rusting ferramenta (iron fittings). The church has been subject to heritage crime in recent years.

Contact: Katy Hoskyn 0117 975 1311

Contact: Katy Hoskyn 0117 975 1311

© Historic England

DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation

SITE NAME:

LIST ENTRY NUMBER:

Former parish church now in use by Greek Orthodox congregation. Constructed largely of red brick in 1904 by GAB Livesay in the free Byzantine style, and completed by ES Prior in partnership with Arthur Grove between 1913 and 1914. Dome was partially rebuilt in 1922-4 by Sidney Tugwell. Suffering extensively from failure of guttering, drainage and roof maintenance, there has been a substantial impact on the internal decoration and integrity of the brick work. National Lottery Heritage Fund Grant for Places of Worship repair phase commenced March

© Borough of Poole Council

Contact: Sarah Ball 0117 975 0666

SITE NAME:	Two round barrows 300 yards (270 metres) north	west of Double Dy	kes, Hengistbury Head
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002397
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Round barrow cemetery on Barrow Hill 150 metres	s south west of Bro	ookvale Farm, Poole
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018029
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow on East Parley Common 610 metres s	outh west of Fir G	rove Farm, Hurn
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016092
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Katy Hoskyn 0117 975 1311

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

SITE NAME:	Two bowl barrows at Gibbet Firs, 950 metres south west and 1080 metres south west of Palmers Ford Works, Hurn		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016091
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Churchill Gardens, Boscombe		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Caroline Peach (LPA) 01202 451323
SITE NAME:	Town Centre, Poole		
DESIGNATION:	Conservation Area, 162 LBs, 3 SMs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Margo Teasdale (LPA) 01202 633914

BRISTOL, CITY OF (UA)



SITE NAME:

Church of St Peter, Castle Park, Bristol

DESIGNATION:

Listed Building grade II*, CA

CONDITION:

Poor

OCCUPANCY:

Vacant/not in use

PRIORITY CATEGORY:

A (A)

OWNER TYPE:

Local authority

Large Early Perpendicular Gothic church, with elements surviving from C12 and C15 and extensive later rebuilding and remodelling. Damaged and reduced to a roofless shell during the first bombing raid on the City of Bristol in 1940, it has been maintained as a memorial to those lost in war. Emergency works have been carried out in November 2019 to secure the high level stonework. Large areas of internal paving are in need of attention.

© Historic England

LIST ENTRY NUMBER: 1282177

Contact: Alessandra Perrone 0117 975 1345



© Historic England

SITE NAME:	Two lodges and attached garden walls opposite former Kings Weston stables, Napier Miles Road
DESIGNATION:	Listed Building grade II*, RPG grade II, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Educational (state sector)

1763, by Robert Mylne. Square pedimented ashlar lodges, flanking a central square pond and attached to a garden wall. The buildings have been vacant for a number of years and are in poor condition. Damaged rainwater goods have led to water ingress and deterioration of some areas of ashlar stonework. The pond is suffering from water loss, extensive vegetation growth and damage to its lining.

LIST ENTRY NUMBER: | | 187186

Contact: Alessandra Perrone 0117 975 1345



© Historic England

SITE NAME:

Mortimer House, Clifton Down Road, Bristol

DESIGNATION:

Listed Building grade II*, CA

CONDITION:

Fair

OCCUPANCY:

Vacant/not in use

PRIORITY CATEGORY:

F (F)

OWNER TYPE:

Private

LIST ENTRY NUMBER:

1202096

Imposing mid-C18 Palladian suburban villa, until recently in hospital use, now vacant. A scheme of repair and conversion was granted consent in 2013, and works to the exterior of the main building are largely complete. The house was sold to a new owner in November 2015. Permission has been granted for conversion to an office and works are underway.

Contact: Stephen Guy 0117 975 0725

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.

 Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area
Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

© Historic England

SITE NAME:	Swing Bridge over North Entrance Lock, Cumberland Basin, Bristol
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

1202186

Wrought iron bridge with tubular supporting members built c1844 by IK Brunel Moved to current location in 1873. It has been redundant and decaying on the dock since the construction of Plimsoll Bridge in C20. Since 2014 a number of surveys on the condition of the fabric and some trial repairs have been carried out with the help of grant funding from Historic England. In 2019 investigations and repairs have focussed on the condition and functionality of the rotational mechanism.

Contact: Alessandra Perrone 0117 975 1345



© Historic England Archive

SITE NAME:	Stair turret (Holy Cross), Inns Court Vicarage, Inns Court Green, Knowle, Bristol
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

C15 stair turret attached to C20 building. Situated in the middle of a housing estate. The house the turret is attached to changed hands in 2014 and the roof of the stair turret was repaired when improvement works were undertaken to the house.

Contact: Sarah Ball 0117 975 0666



© Historic England

SITE NAME:	Church of St Michael and attached railings, St Michael's Hill, Bristol
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation

1282109

1202314

Church, rebuilt between 1775 and 1777 in a Gothic style, but retaining the mid-C15 tower. The interior is divided in three aisles by classical colonnades and has some late C19 fittings. The church was last in use in the late 1990s, and the roofs of the nave and north aisle were damaged by fire in October 2016. In April 2018 Bristol DAC announced a buyer for the church, although a further sale of the church has recently been confirmed. The new owner intends to convert the church to an events space and is in discussion with stakeholders.

Contact: Stephen Guy 0117 975 0725



© Historic England

SITE NAME:	28, Portland Square, St Pauls, Bristol
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Commercial company

1202444

One of a terrace of seven houses located in a largely complete Georgian square, c1789-1820. Limestone ashlar, brick stacks, slate mansard roofs, double-depth plan. Late Georgian style, four storeys with attic and basement. As of May 2019, works for repair and conversion to hotel use are still in progress.

Contact: Alessandra Perrone 0117 975 1345



© Historic England Archive

SITE NAME:	31 and 32, Portland Square, St Pauls, Bristol
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1208879

Terraced houses, built from 1789 to 1820. Emergency repairs to the roof were carried out with Historic England grant aid in 1996. Further damage occurred in 2005 when part of the facade collapsed. The buildings have been vacant for over 20 years and conditions continue to deteriorate. A planning application for repairs and residential conversion was submitted in 2019.

Contact: Alessandra Perrone 0117 975 1345

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise.

New Entry is noted).

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

LIST ENTRY NUMBER:



© Historic England Archive

SITE NAME:	Carriage Works, 104, Stokes Croft, Bristol
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Private

1025273

Carriage works, 1862. A notable building in a manner recognised as particular to the city. Large and complex site including 4, Ashley Road (grade II), also in very bad condition. Planning permission for a mixed use redevelopment of the site was granted in October 2015 and the site was sold to new owners in summer 2017. Work on site to deliver the approved development are ongoing.

Contact: Stephen Guy 0117 975 0725



© Historic England

SITE NAME:	Church of All Hallows, All Hallows Road, Bristol
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Fair
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1201954

Large Decorated Gothic Revival church of c1900 by Bristol architect Sir George Oatley. Plan and form are a creative fusion of congregational and liturgical style. Site was a former clay quarry and the foundations rest on filled ground at differing levels. The building suffered from differential settlement and was monitored for structural movement. A National Lottery Heritage Fund and Historic England Repair Grant for Places of Worship was accepted in 2012 for surface water drainage works and structural repairs. Repairs completed 2014. Some roofing and drainage issues have yet to be addressed.

Contact: Chris Miners 0117 975 1355

Contact: Katy Hoskyn 0117 975 1311



SITE NAME: Church of St Mary the Virgin, Church Close, Bristol Listed Place of Worship grade DESIGNATION: II*, CA CONDITION: Poor PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1205113

C13 church with C19 restoration. Roof coverings and rainwater goods are all in poor condition and there is vegetation growing out of the eroding masonry. Areas of mortar erosion and cement render are in need of replacement. This building has been subject to heritage crime.

© Histo	oric E	ngla	nd

© Historic England

SITE NAME:	Roman Catholic Church of St Bernadette, Wells Road, Bristol
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Very bad
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1436044

Parish church designed in 1967 by James Leask of Kenneth Nealon, Tanner & Partners to accompany the Catholic school built on the centenary of the apparitions at Lourdes. Bold and innovative in design and materials, it features a double hyperbolic paraboloid roof carried on projecting concrete piers on a rotated square plan. Some of the original materials are now showing signs of deterioration and this has led to serious issues of water ingress through the roof coverings, affecting the ceiling and the roof structure. Some episodes of vandalism have also taken place.

Contact: Alessandra Perrone 0117 975 1345

3		
	WILL A	

SITE NAME Anti-aircraft gun site, Purdown DESIGNATION LIST ENTRY NUMBER Scheduled Monument, RPG grade II, CA 1004531 Generally unsatisfactory with major localised CONDITION: TREND: Declining problems PRINCIPAL VULNERABILITY: NEW ENTRY?: No Deterioration - in need of management OWNER TYPE: CONTACT: Alessandra Perrone 0117 975 1345 Local authority SITE NAME: Civil War earthworks on Brandon Hill DESIGNATION: LIST ENTRY NUMBER: 1006989 Scheduled Monument, CA Generally satisfactory but with significant localised CONDITION: TREND: **Improving** problems PRINCIPAL VULNERABILITY: NEW ENTRY?: No Deterioration - in need of management Alessandra Perrone 0117 975 1345 OWNER TYPE: Local authority CONTACT:

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

St Mary-le-Port Church, High Street		
Scheduled Monument, LB grade II, CA	LIST ENTRY NUMBER:	1021385
Extensive significant problems	TREND:	Declining
Deterioration - in need of management	NEW ENTRY?:	No
Local authority	CONTACT:	Alessandra Perrone 0117 975 1345
Stokes Croft		
Conservation Area, 19 LBs	NEW ENTRY?:	No
Very bad	TREND:	Deteriorating
Low	CONTACT:	Kingsley Fulbrook (LPA) 0117 922 2966
	Scheduled Monument, LB grade II, CA Extensive significant problems Deterioration - in need of management Local authority Stokes Croft Conservation Area, 19 LBs Very bad	Scheduled Monument, LB grade II, CA Extensive significant problems Deterioration - in need of management Local authority Stokes Croft Conservation Area, 19 LBs Very bad TREND: LIST ENTRY NUMBER: ANEW ENTRY?: TREND:

BRISTOL, CITY OF (UA) / BATH AND NORTH EAST SOMERSET (UA)



SITE NAME: **Brislington House** Registered Park and Garden DESIGNATION: grade II*, 4 LBs, CA CONDITION: Extensive significant problems VULNERABILITY: High TREND: Stable NEW ENTRY?: No OWNER TYPE: Mixed, multiple owners LIST ENTRY NUMBER: 1001529

One of the first and most influential asylum landscapes in Britain. Now subdivided between a sixth form college, private residential development, commercial sports facilities, industrial units and a management training centre. Despite this, some elements of the designed landscape survive. Its designation was re-evaluated by Historic England in 2017. Some adjustment to the boundary was made but no change to the grade. Part of the park is within Bath and North East Somerset Unitary Authority.

Contact: Jo McAllister 0117 975 0696

CORNWALL (UA)

© Historic England




SITE NAME: Scraesdon Fort, Antony Scheduled Monument and Listed DESIGNATION: Building grade II CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Government or agency

Built 1868, used for military training purposes. Vegetation is being kept under reasonable control. Works have been undertaken to stop water ingress and repairs to metalwork throughout site. Drawbridge and main gate repairs were completed in 2014. The ditch was cleared in 2015.

© Historic England

LIST ENTRY NUMBER: 1004347 and 1140707

Contact: Annie Evans 0117 975 0673



© Ministry of Defence

SITE NAME:	Tregantle Fort, Antony
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Government or agency
LIST ENTRY NUMBER:	1004346 and 1159255

Fort, built 1858-1865. The fort is vacant, with no end use identified. The interior of the keep is in poor condition, notably the wooden floors. New external doors and windows have been fitted. Interior partitions are still awaiting re-installation. Elsewhere in the fort, the barracks accommodation is no longer used full time with interiors deteriorating in places due to moisture penetration. A section of the counterscarp wall has collapsed. Significant localised problems remain to be tackled elsewhere on the

Contact: Annie Evans 0117 975 0673

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise.

New Entry is noted).

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England

SITE NAME: Medieval chapel of St Thomas Becket 45 metres east of the church, Priory Road, Bodmin

Scheduled Monument, LB grade DESIGNATION: II*, CA

CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: B (B)

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1002937

The monument is the roofless ruin of a C14 chapel, located within the churchyard of St Petroc's church. The building suffers ivy growth on the walls, vandalism and anti-social use of the crypt.

Contact: Ann Preston-Jones 07917 642388



© Historic England

SITE NAME: Rosewarne House (Gladys Holman House), Tehidy Road, Camborne Listed Building grade II*, CA, DESIGNATION: WHS CONDITION: Good OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: F (F) OWNER TYPE: Private

1142639

grounds. Latterly a residential home but vacant for some time. Lack of maintenance and vandalism resulted in rapidly increasing deterioration. Repairs agreed in 2012 and a revised scheme approved in 2013. Works to the house and surrounding buildings largely completed. Awaiting submission of revised application following the discovery of greater decay within the internal fabric of the house. This has resulted in a change of approach to the repair of the building (2020).

Large early C19 H-plan granite town house in its own

Contact: Rhiannon Rhys 0117 975 0685



© Historic England

Former Carharrack Methodist Church, Church Street, Carharrack
Listed Building grade II*, WHS
Poor
Vacant/not in use
C (C)
Private

1160248

Grade II* Methodist chapel built in 1815, was purchased in 2017 following its redundancy as a place of worship. Water ingress through the deterioration of the roof cover and under-sized rainwater goods has resulted in structural issues with the window lintels and floor of gallery. Damage has been caused to the gallery box pews which are some of the oldest remaining in Cornwall. Positive discussions continue with the owner and local planning authority regarding future use.

Contact: Catherine Marlow 0117 975 0732



© Historic England

SITE NAME:	Part of the mining complex associated with Marriott's Shaft once part of South Wheal Francis tin and copper mine, Carn Brea
DESIGNATION:	Scheduled Monument, 5 LBs, WHS
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (New entry)
OWNER TYPE:	Local authority

1005441

South Wheal Francis underwent a major conservation programme some 25 years ago in association with the development of the Mineral Tramway multi-use trail. Since then, cuts in local authority budgets mean that there has been little maintenance and now there are concerns about the stability of some of the ruined structures and potential collapse on this open access site. The site has been added to the Heritage at Risk register, pending a full condition survey, which will help to identify the exact locations and nature of the risk.

Contact: Ann Preston-Jones 07917 642388

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England

SITE NAME:	Marlborough House, Silverdale Road, Falmouth
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Commercial company

1270002

Grade II* former country house now in suburbs of Falmouth. Building was vacant and in poor condition. Discussions with the owner over its repair and use have since taken place. A listed building application for its refurbishment as a single dwelling was made in 2016. A subsequent consent was granted in 2017 and was completed in May 2017, however work continues on the

Contact: Catherine Marlow 0117 975 0732



Major, Grade-Ruan DESIGNATION: Listed Building grade I CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation

Church of St Rumon, Ruan

Medieval former parish church. Roof removed shortly after closure in 1963. The Diocese has undertaken consolidation to the low walls but not to the tower which has a tree growing out of it at high level. Discussions for the future of the ruin are ongoing.

© Historic England

LIST ENTRY NUMBER: 1141915

LIST ENTRY NUMBER:

SITE NAME:

Contact: Chris Miners 0117 975 1355



© Historic England

SITE NAME:	Tower of former church of St Kea, Kea
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1141656

Tower of former church of St Kea, now a ruin. The tower stands in a wooded valley beside the current church of St Kea and is a picturesque and imposing reminder of the first church. The tower has had some stabilisation work carried out to its pinnacles, and some ivy has been removed, however this well-meaning ivy removal may cause longer term damage due to joint loosening. The tower has no active use and may require additional stabilisation and/or repairs which, given the very small and occasional use of the nearby church, will be difficult to fund from existing

Contact: Catherine Marlow 0117 975 0732



© Historic England

SITE NAME:	Chapel at Hall, Lanteglos
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1004361

Site consists of walls and well-preserved bell turret of a C14 manorial chapel. Re-use as a farm building in the C19 caused modifications to the structure which still retained its original oak wagon roof until the 1960s. Conservation in the 1990s helped to stabilise the structure but now water seeping into the rear wall has built up causing it to become unstable. Scaffolding funded by Historic England in 2015 was urgently needed to save the wall from falling and remedial works were carried out in 2017 to sections of wall. Further long term measures are required to protect the ruin from decay.

Contact: Chris Miners 0117 975 1355



© Cornwall Council

SITE NAME:	13, High Street, Launceston
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1206510

lettied and timber-framed corner house, prominent on town's market square. Roof structure and upper level party wall in poor condition. Vacant upper levels have deteriorated badly due to a lack of maintenance. Some repairs have been carried out to the roofs, gutters and slate hung walls. Structural and weatherproofing problems

Contact: Chris Miners 0117 975 1355

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Trekelland Bridge, Lewannick / South Petherwin
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Local authority

1155188

Trekelland Bridge is a grade II* medieval bridge with two main arches and a span flood arch. Carrying the road between Launceston and Liskeard, it is still heavily used. The bridge has been the subject of repeated vehicle impacts that have damaged its approach walls and coping stones in particular. No solution to these traffic impacts has been found to date.

Contact: Catherine Marlow 0117 975 0732

ALL CONTRACTOR OF THE PARTY OF
Comment of the Commen
Sufficiency of the Control of the Co
AND THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER.
MANAGEMENT OF THE PARTY OF THE
STATE OF THE PARTY
©Cornwall Council/Barry Gamble
Contiwali Council/Barry Gamble

© Cornwall Council

SITE NAME:	Treffry Viaduct, Luxulyan / Lanlivery
DESIGNATION:	Scheduled Monument, WHS
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Charity (heritage)

1007279

Combined viaduct and aqueduct. Granite built ten-arched bridge with a span approximately 200 metres, standing up to 27 metres above the valley floor. Water had been gushing from the leat within the structure, so water flow over the viaduct has been stopped. Leaks became evident at abutments and locations within the main spans of the structure. A solution to the leaking channel has now been agreed. The Cornwall Heritage Trust is working with Historic England to develop an investigation project to finalise the solution to the high level leakage problems of the leats within the viaduct.

Contact: Nick Russell 0117 975 0671



© Historic England

Maker Heights Barracks Block, Maker-with-Rame
Listed Building grade II*
Poor
Part occupied/part in use
B (B)
Charity (heritage)

1375582

Built 1804-1808 as a barracks for a line of earlier redoubts built to protect Devonport Dockyard in 1782. The twostorey block was altered in the mid C19 when the formerly tile-hung first floor was rebuilt in brick. It is the most complete small garrison barracks from this significant period. Partially repaired and in use as a community art centre. A scheme of window repairs has been undertaken with Historic England grant aid with another scheme of basement repairs scheduled for 2020.

Contact: Annie Evans 0117 975 0673



© Historic England

SITE NAME:	Maker Heights Guard House, boundary wall and attached ancillary buildings, Maker-with- Rame
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

1329099

Built in 1804-1808 as a barracks for a line of earlier redoubts built to protect Devonport Dockyard in 1782. Altered in mid C19. Guard House in fair condition and used as offices but several of the other buildings are in poor to bad condition, in particular the Straw Store, Wash House and Caponier. Now in seperate private ownership from the Barrack Block that forms the raison d'etre for this group of buildings.



© Historic England

SITE NAME:	English Garden House, Makerwith-Rame
DESIGNATION:	Listed Building grade II*, RPG grade I
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Local authority, multiple owners
LIST ENTRY NUMBER:	1140619

An early C18 Classical garden house, located within Mount Edgcumbe Estate, now a Country Park. Originally a banquetting house, subsequently extended to include a sunken marble bath and additional rooms as a garden building for entertaining and leisure. Water ingress has caused damage to historic fabric, including plasterwork and wall paper. The building is currently used for storage, although Historic England are working with the owners for a grant aided repair scheme.

Contact: Chris Miners 0117 975 1355

Contact: Annie Evans 0117 975 0673

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Vickery Holman Ltd

SITE NAME:	Boundary wall to Lanherne Carmelite Convent, Mawgan-in- Pydar
DESIGNIATIONI:	Listed Duilding and do II* CA

Listed Building grade II*, CONDITION: Poor

OCCUPANCY: N/A

A(A)OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1137593

C16 or C17 boundary park wall. Substantial loam bonded random rubble masonry wall almost one metre thick standing up to four metres in places. Neglected, heavily overgrown with ivy and partially collapsed in places. Condition survey needed to understand and monitor decay and to prioritise repairs.

Contact: Annie Evans 0117 975 0673

4000	
The same of the sa	20 CO
Secretary of the State of the S	Again of
《日本》的《日本》	
	SE 150
	C 31 . 30
ACT TO SECURE OF	£3.132
The second secon	1, 100
40000000	1 FOW.
	Art -
N. T. WARRING	1
ALEXANDER TO VICENSES	1
	173.00
	1000
	400
THE RESIDENCE OF THE PARTY OF T	1
	100
A PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY.	VI - 18
	B () ()
	Total Control

© Historic England

SITE NAME:	Insworke Chapel, Millbrook
DESIGNATION:	Scheduled Monument, LB grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Private

LIST ENTRY NUMBER: 1003095

Ruins of Chapel. Slatestone rubble with limestone dressings. No roof. Chapel has nave and chancel in one, appears to have been of two storeys. C19 cart shed attached to east end. Chapel has previously been fully recorded by Historic England. The structure is now in imminent danger of collapse with a number of risk factors including subsiding walls and extensive damaging vegetation. A programme of investigation work is due to be implimented to seek to stabilise the site.

Contact: Daniel Bashford 07824 103102



© Historic England

SITE NAME:	Remains of Carclew House, Mylor
DESIGNATION:	Listed Building grade II*, RPG grade II, WHS
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private multiple owners

/ate, multiple owners LIST ENTRY NUMBER: 1160291

The remains of Carclew House are the formal centre of a Registered park and garden also at risk. Started in 1720 by Samuel Kemp, this palladian style house was one of Cornwall's finer C18 country houses but was partly burned down in 1934. It is now a ruin, overgrown and neglected. Vegetation management is now ongoing with a program of repairs in development. A steering group has been established with the owners of Carclew House and a brief drawn up under Historic England's guidance to prepare a Conservation Management Statement for the site.

Contact: John Ette 0117 975 0687



© Historic England

SITE NAME:	Dry sand and green sand shop, Perran Foundry, Perran Wharf, Mylor
DESIGNATION:	Listed Building grade II*, CA, WHS
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (F)

OWNER TYPE: Commercial company LIST ENTRY NUMBER 1141603

Early to mid C19 mould and casting buildings. This is the main furnace building, an impressive and intact structure. Urgent repairs carried out early 2005. Listed Building Consent and Planning Permission for repair and conversion granted 2008, with subsequent variations on that consent also permitted 2019. The buildings have been reroofed but the consented scheme for reuse has not yet been implemented.

Contact: Catherine Marlow 0117 975 0732



© Historic England

SITE NAME:	Engineers' Shop, Perran Foundry, Perran Wharf, Mylor
DESIGNATION:	Listed Building grade II*, CA, WHS
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)

1141643

Commercial company

Engineers' shop, boring mill and pattern shop, early-mid C18. Listed Building Consent and Planning Permission for repair and conversion of whole Perran Foundry site granted 2008 and now being implemented in a phased manner. Revised scheme for resuse of the engineers' shop as ancillary car parking and storage area granted permission in 2019 but as yet unimplemented.

Contact: Catherine Marlow 0117 975 0732

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.

OWNER TYPE:

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England

SITE NAME:	Threshing barn on north side of yard at Trebartha Barton, North Hill
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor

OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C)

OWNER TYPE: Charity (heritage)

LIST ENTRY NUMBER: 1250152 Mid C19 threshing barn forming one side of the farmyard to Trebartha Barton Farm. Two-storey 'E' plan with projecting midstryes infilled with first floor lean-to, forming impressive elevation to the yard. Rubble walls with granite dressings. Rag slate covered king post trussed roofs with slate hung infill walls. Slates are slipped or missing causing structural decay. There is harmful vegetation growth. First floor boarding is decayed and unsafe.

Late C16 reused Catacleuse arched gateway with C18 flanking turrets, decorated with crenellations. Slate stone. Narrow blind arrow slits. Capping failure has led to water penetration through the piers (which are thought to be solid and not hollow). There is cracking of stone,

movement of archway, bulging stone plinth and washed out mortar joints. Advice and suggested way forward has been

Contact: Chris Miners 0117 975 1355



© Historic England

SITE NAME:	Entrance gate and flanking walls forming mock fortifications to east of Prideaux Place, Padstow
DESIGNATION:	Listed Building grade I, RPG grade II
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	C (C)

OWNER TYPE: Private

LIST ENTRY NUMBER:

Contact: Chris Miners 0117 975 1355

given with action planned for mid 2019.



© Historic England

SITE NAME:	Trenearne, Padstow
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NILIMBER:	1211508

1289743

House, now farmhouse, circa early C17, possibly remodelled in 1660 (datestone) for 'PW'. The house only survives in part and was probably of overall 'H' shaped plan. It has been a tenanted farm for a number of years but a lack of maintenance had left all the buildings in a poor state of repair. The estate which owns Trenearne has been granted listed building consent to refurbish the house including much needed repairs, as well as the conversion of farm buildings.

Contact: Catherine Marlow 0117 975 0732



© Historic England

SITE NAME:	Anchor Studio, 4, The Meadow, Penzance
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1390877

Anchor Studio was built in 1888 by Arthur Bateman for Stanhope Forbes RA with rubble and weatherboarded timber frame walls and a scantle slate roof. It is a good example of a late Victorian purpose-built artist's studio. One of a group of studios built nearby for the Newlyn School artists, There are bad leaks with large sections of slate roofing starting to slip, parts of the external timber cladding in poor condition, the lower floor area blocked off suffering from extensive damp. National Lottery Heritage Fund repair grant awarded and repairs scheduled for mid 2020.

Contact: Chris Miners 0117 975 1355



© Historic England Archive

SITE NAME:	Market Building, Market Place, Penzance
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1221062

Built c1820. Altered 1925. Partially occupied; the western half by Lloyds Bank, the eastern half is vacant. The roof was repaired approximately five years ago although some leaks persist. Vulnerable historic interiors have had plaster falls on the vacant eastern half. Outbreaks of timber decay persist in the unventilated interiors.

Contact: Chris Miners 0117 975 1355

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise.

New Entry is noted).

ABBREVIATIONS	
CA LB	Conservation Area Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garde
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

© Penwith District Council

SITE NAME:	Trinity Methodist Chapel, Chywoone Hill, Newlyn, Penzance
DESIGNATION:	Listed Building grade II*, C

DESIGNATION: Listed Building grade II*, CA
CONDITION: Poor

OCCUPANCY: N/APRIORITY CATEGORY: C(C)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: | 386515

Former Nonconformist Wesleyan chapel c1834, enlarged 1866. One of the most complete early C19 chapels in Cornwall. No longer used for religious worship. It has been put on the market in the last year.

Contact: Chris Miners 0117 975 1355



© Historic England

Bridge at approximately 150 metres east of Chyverton House, Perranzabuloe

DESIGNATION: Listed Building grade II*, RPG grade II

CONDITION: Poor

OCCUPANCY: Occupied/in use

PRIORITY CATEGORY: C (New entry)

OWNER TYPE: Private

LIST ENTRY NUMBER: | 328680

C18 bridge within parkland associated with Chyverton House, garden and park. Unaltered, but showing signs of movement post-vegetation removal, in particular at the end splays and parapet. Killas stone also spalling and eroding. Access onto the bridge now restricted. Planned funding for repairs has fallen through and there is currently no resolution agreed.

Contact: Catherine Marlow 0117 975 0732



© Cornwall Council

SITE NAME:

Tolgus Calciner, New Portreath Road, Redruth

DESIGNATION:

Scheduled Monument, LB grade II, WHS

CONDITION:

Poor

OCCUPANCY:

Vacant/not in use

PRIORITY CATEGORY:

A (A)

Mixed, multiple owners

LIST ENTRY NUMBER: | 02 | 240

Remains of a calciner used in the production of arsenic. It has been vacant for many years and is vulnerable with a damaged main roof and a collapsed adjoining tin-roofed extension. The main hipped slate roof of the building has been damaged through vandalism and there is an urgent need for weather proofing.

Contact: Ann Preston-Jones 07917 642388



© Cornwall Council

SITE NAME:

Sara's Foundry, Tolgus Place, Redruth

DESIGNATION:

Listed Building grade II*, WHS

CONDITION:

Very bad

OCCUPANCY:

N/A

PRIORITY CATEGORY:

A (A)

OWNER TYPE:

Private

OWNER TYPE: Private
LIST ENTRY NUMBER: 1142573

C19 and C20 iron foundry and engineering works, containing associated machinery. Buildings continue to deteriorate and are now in a very vulnerable condition. Discussions with Cornwall Council to identify an appropriate strategy to secure the building and prevent further deterioration have continued.

Contact: Chris Miners 0117 975 1355



© Historic England

SITE NAME:

Market House, Market Street, St. Austell

DESIGNATION:

Listed Building grade II*, CA

CONDITION:

Poor

OCCUPANCY:

Part occupied/part in use

PRIORITY CATEGORY:

C (C)

OWNER TYPE:

Charity (non-heritage)

LIST ENTRY NUMBER:

1289697

Large town centre Market House built in 1844. It is formed of a town hall facing the church with an imposing street frontage and with a large glazed market area behind. Leaks and other rainwater system faults to the town hall and especially to the glazed market area are getting steadily worse. Occupancy rates in both areas have fallen as a result. Major repairs to all parts of the building are now needed before the building becomes beyond repair. A project is now being developed for which consents have been applied for.

Contact: Chris Miners 0117 975 1355

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS CA Conservation Area is LB Listed Building se, LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

	A
. 1.1	
	Tolly and the last

© Cornwall Council

Charlestown Methodist Church, SITE NAME: Charlestown Road, St. Austell

Listed Building grade II*, CA, DESIGNATION: WHS

CONDITION: Fair

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: F (F)

OWNER TYPE: Private

LIST ENTRY NUMBER: 1144292 Former Wesleyan chapel (1827) and attached schoolroom (mid C19), now closed for worship. A revised Listed Building Consent was granted in May 2018. Work commenced on site 2018/2019 and the shell of the building is now fully repaired. As yet, no end user has been identified (2020).

Contact: Rhiannon Rhys 0117 975 0685



© Historic England

SITE NAME: Engine Sheds, Stack and Turntable, St Blazey Road, St. Blaise

DESIGNATION: Listed Building grade II*

CONDITION:

OCCUPANCY: Part occupied/part in use

PRIORITY CATEGORY: C (C)

OWNER TYPE: Government or agency

LIST ENTRY NUMBER: 1289905

Locomotive turntable associated with adjacent roundhouse is deteriorating through lack of maintenance having been taken out of service in 2002. The roundhouse building is in light industrial use. A community interest group has been formed to develop a project to restore the site and bring it into more sympathetic uses. A Coastal Communities Fund grant was awarded in 2016 to develop the project.

Contact: Catherine Marlow 0117 975 0732



© Historic England

Hockings House Bible Christian SITE NAME: Chapel, St. Cleer DESIGNATION: Listed Building grade II* CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: D (D) OWNER TYPE: Private

LIST ENTRY NUMBER: 1311103

Chapel dated 1846. Good interior with gallery and original fittings including leaders' pew. Separated from the small Sunday school and damaging partial conversion works preceded its sale in 2012. Negotiations with owner are sporadic and relate to the possible extent of an acceptable conversion scheme. The building deteriorated in the interim with its roof falling into a very poor state, with consequential damage occurring to the interior. Listed Building Consent was granted in 2015 for roof repairs, completed in 2017. No agreement has yet been reached on an acceptable scheme for reuse.

Contact: Catherine Marlow 0117 975 0732



© Cornwall Council

the bridge over moat about 8 metres east of Old Rectory, Old Rectory Drive, St. Columb DESIGNATION: Listed Building grade II* CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Private

Flanking walls and gateway to

Mid C19, part of William White's layout for the Bishop's Palace which became a Rectory and latterly a hotel. Obscured and threatened by dense vegetation. White's wrought iron gate, referred to in the List description, is not at present hung and its whereabouts is unknown. Vegetation clearance has taken place to allow for conservation of the moat.

LIST ENTRY NUMBER:

Contact: Chris Miners 0117 975 1355



© Cornwall Council

SITE NAME: Old Bishop's Palace, Old Rectory Drive, St. Columb DESIGNATION: Listed Building grade II* CONDITION: Very bad OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: A(A)OWNER TYPE:

Commercial company

1144097

LIST ENTRY NUMBER: 1144096

1851 by William White. Picturesque Gothic Revival country gentleman's rectory, a classic of the type. In very poor state of repair caused by lack of maintenance, vandalism, vegetation, inappropriate finishes and unlived-in state. Water ingress has resulted in dry rot and damage to historic fabric. Statutory action by Local Planning Authority on hold. Vegetation clearance has taken place and is being maintained.

Contact: Chris Miners 0117 975 1355

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise.

New Entry is noted).

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Cornwall Council

SITE NAME: Calf House at Lithiack and stable adjacent to north, Port Eliot Estate, St. Germans

Listed Building grade II*, RPG DESIGNATION: grade I

CONDITION: Poor

OCCUPANCY: Occupied/in use

PRIORITY CATEGORY: C (C)

OWNER TYPE: Private

LIST ENTRY NUMBER: 1140518

Late C18/early C19 estate agricultural building. Attributed to Soane for the Port Eliot Estate. In low key use but condition remains very poor. Currently tenanted by a roofing company who are undertaking localised repairs. Condition improving.

Contact: Annie Evans 0117 975 0673



© Historic England

SITE NAME: Little Trethewey Methodist Chapel, Little Trethewey, St. Levan DESIGNATION: Listed Building grade II* CONDITION: Very bad OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: A(A)OWNER TYPE: Private

LIST ENTRY NUMBER: 1311918

Built as Wesleyan Chapel in 1868. Small chapel with stuccoed Italianate front. Modest and complete interior with closed box pews. The chapel is in a bad condition with holes in the roof. The downpipes are blocked and external render is failing. Front gable is unstable and resulted in damage to the interior. Chapel closed April 2013. The condition continues to deteriorate. Historic England grant aided repairs in 2015 that covered the roof with a temporary sheet covering. The chapel has been sold and Historic England looks forward to discussing its future with

Contact: Chris Miners 0117 975 1355



© Historic England

Helland Bridge, St. Mabyn / SITE NAME: Helland DESIGNATION: Scheduled Monument, 2 LBs CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: B (New entry) OWNER TYPE: Local authority

1020812

This well-preserved medieval bridge carries a C-class road over the River Camel, between the A30 and B3266 roads. Because it provides a handy short-cut the road (and the bridge) is used by a very high volume of traffic from locals to commercial and tourist traffic. As a result, there are many traffic incidents on the narrow bridge. To date there have been no major incidents but the risk of this is high until measures are taken to protect the structure by suitable signage or other means. Other issues include vegetation growth and a lateral crack in the tarmac at the centre of the bridge.

Contact: Ann Preston-Jones 07917 642388



© Historic England

SITE NAME: Chapel Mill, Gwindra Road, St. Stephen-in-Brannel DESIGNATION: Listed Building grade II* CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: D (New entry) OWNER TYPE: Private

LIST ENTRY NUMBER: 1261837

Chapel Mill is a C19 china stone grinding mill, a rare and intact example of its kind, which still contains machinery. It has been redundant since the 1950s and since then has gradually deteriorated, becoming very overgrown. Large parts of the mill's corrugated iron roof covering have blown off leaving the wall tops open to water penetration and the timberwork rotting and collapsing. Inside, the machinery is in deteriorating condition. Volunteers have cleared the scrub but roof repairs are beyond their capacity.

Contact: Ann Preston-Jones 07917 642388



© Historic England

SITE NAME: Gunpowder works at Kennall Vale, Stithians / St. Gluvias Scheduled Monument, 9 LBs, DESIGNATION: WHS CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: B (B) OWNER TYPE: Charity (non-heritage)

1020143

This large scheduled area is centred on a steep sided, wooded valley, which contains remains of ruined buildings, mills, leats and bridges associated with a C19 gunpowder works. After years of abandonment, the many ruined structures on the site are at risk from tree and vegetation growth, water and footpath erosion and collapse. Recently, the most 'at risk' structures and leats were consolidated through a Natural England Stewardship scheme but there remain many outstanding management needs.

Contact: Ann Preston-Jones 07917 642388

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England

Holmbush Mine: Windsor Lane SITE NAME: rotative engine house with adjacent boiler house, loadings and platform, Stokeclimsland

Scheduled Monument, LB grade DESIGNATION: II, WHS

CONDITION: Very bad

Vacant/not in use PRIORITY CATEGORY: C (C)

OWNER TYPE: Crown

OCCUPANCY:

LIST ENTRY NUMBER: 1020327 This is a substantial mine engine house in deteriorating condition. The building is densely covered in ivy and surrounded by trees. The roof is mostly collapsed but still retains a few slates and roof timbers which are vulnerable to further damage. Timber fittings are deteriorated and rotten. Arched window openings have slipped bricks.

Contact: Ann Preston-Jones 07917 642388



© Historic England

SITE NAME: Part of the china clay works known as Wheal Martyn, Treverbyn DESIGNATION: Scheduled Monument CONDITION: Poor

OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: B (B)

OWNER TYPE: Charity (heritage)

LIST ENTRY NUMBER: 1003265 Site includes well preserved remains of china clay processing works displayed as part of a museum. There are a range of features, including drying sheds, water wheels, settling tanks, machinery. Completion of major NLHF project to undertake conservation works to the main structures and provide new education and gallery space prevented from completion by Covid 19 lockdown.

Contact: Nick Russell 0117 975 0671



© Historic England

SITE NAME:	Wesleyan Chapel, Porkellis, Wendron
DESIGNATION:	Listed Building grade II*, WHS
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Other not for profit group

LIST ENTRY NUMBER: 1162569

Former Wesleyan Methodist chapel, built 1866. The congregation has moved into the Sunday school and the chapel was sold to a private buyer. New owner has addressed the most serious roof leaks and obtained Listed Building Consent for conversion to residential use from Cornwall Council. The repairs are ongoing.

Contact: Chris Miners 0117 975 1355



© Historic England

SITE NAME:	Church of St Protus and St Hyacinth, Blisland
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1142367

Large parish church on the south of the village green, high on the edge of Bodmin Moor. Three aisles, C15 formed from C12 cruciform plan and with projecting south transept and north tower. Rubble stone walling for the early work and granite ashlar for the later. Restored by FC Eden 1896. Graduated Cornish slate roofs. Internal damp problems persist although rainwater goods have been repaired.

Contact: Chris Miners 0117 975 1355



© Historic England

SITE NAME:	Church of St Crewen, Crowan
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1160230

Large rural parish church in the centre of a small village. Cornish three-aisle church with a tall west tower. C14 and C15 restored 1872, with a C20 south organ chamber. All granite ashlar and Cornish slate roofs. The rainwater system has had some repair. A leaking valley gutter has caused interior damage. The window masonary needs repairs.

Contact: Chris Miners 0117 975 1355

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise,

New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



SITE NAME:	Church of St Cuby, Cuby
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1291868

Small parish church. The tower is C14, of slate. The rest of the church is of rubble with granite dressings and has medieval origins but mostly displays the 1828 rebuilding with the 1899 St Aubyn restoration. Cornish slate roofs. The church is in fair condition overall but the tower has major problems with its drainage resulting in a wet north wall with harmful excessive vegetation growth.

© Historic England

Marine Salar	
* A N	,,,,
	1

SITE NAME:	Church of St Grade, Grade- Ruan
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1141938

Small church in an isolated site. Plan of tower, nave and east chancel. C14 origins. The slate roof needs repair and the tower has excessive damp and vegetation growth.

Contact: Chris Miners 0117 975 1355

Contact: Chris Miners 0117 975 1355

Contact: Chris Miners 0117 975 1355

© Historic England



SITE NAME:	Church of St Nivet, Lanivet
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1158241

Large Anglican parish church in the centre of a large village. Classic Cornish pattern plan of three aisles with tall west tower. Granite and slate roofed mostly C15. The rainwater system is under-sized, rusted and part displaced. High level stonework needs repair and some roofs need reslating.

© Historic England



	DESIGNAT
	CONDITIO
	PRIORITY
al community	

SITE NAME:	Church of St Stephen, St Stephen's Hill, Launceston
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1297830

Large urban parish church and the mother church for

© Historic England



© Historic England

SITE NAME:	Church of the English Martyrs and attached walls and steps, St Stephen's Hill, Launceston
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor

OWNER TYPE: Religious organisation

C (C)

LIST ENTRY NUMBER: 1297829 Launceston. Norman core with many additions finishing with the C16 tower. Restored 1883. Granite ashlar tower and outer walls to the west and south, the rest slatestone rubble with granite or greenstone dressings. The roof leaks and needs extensive renewal and repair.

Small Roman Catholic parish church designed by Arthur Langdon in a blend of Byzantine and Romanesque styles. It was built in 1911 and constructed of dressed stones including Slate stone and Polyphant stone, to give a polychrome effect. The Polyphant stone masonry is now

decaying badly. The roofs now need urgent repair as they

are leaking.

Contact: Chris Miners 0117 975 1355

Contact: Chris Miners 0117 975 1355

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.

PRIORITY CATEGORY:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



SITE NAME:	Church of St Martin, Lewannick
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1277508

Small parish church with tall tower. Plan of three parallel aisles with opposing north and south gabled porches and a west tower. Mostly granite ashlar with slate roofs. Extensively rebuilt late C19. The tower has serious faults at high level on the north side. The bell opening and the parapet above have serious structural faults. A crack on the projecting stair turret appears to be active. The roof also needs repair.

Contact: Chris Miners 0117 975 1355

© Historic England

© Historic England



SITE NAME:	Church of St Martin by Looe, Looe
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1282854

Large two aisled church with tall west tower, south transept and north aisle. Structural problems with roof structure reported with major movement across the east end of the nave by the south transept. Although largely historic it is now showing signs of fresh movemnt with plaster falls. A scheme of emergency repairs is proposed with Historic England grant support.

Contact: Chris Miners 0117 975 1355

Church of St Torney, North Hill
DESIGNATION: Listed Place of Worship grade I
CONDITION: Fair
PRIORITY CATEGORY: C (C)
OWNER TYPE: Religious organisation
LIST ENTRY NUMBER: 1249982

Large parish church on the eastern edge of Bodmin Moor. There are structural problems in the tower where the floors are unsafe for use. The rainwater goods are rusted and leaking. There are major damp problems in the east end and structural problems in the tower. The church is in the process of closing with no agreed future use.

Contact: Chris Miners 0117 975 1355

© Historic England



SITE NAME:	Church of St Denis, North Tamerton
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1142437

A parish church set in a hillside churchyard. Plan of twin aisles with south porch, north vestry and west tower. Early C15 with C19 north vestry added in 1875 restoration. Rubble stone with granite dressings, complete ashlar tower and porch. Cornish slate roofs, some pitches rag slate. The rainwater goods are in poor condition and the slate roofs have slipped with fractured slates needing replacement.

Contact: Chris Miners 0117 975 1355

© Historic England



SITE NAME:	Church of St Sampson, South Hill
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
I IST ENITRY NII IMRER-	1140704

The church requires significant repairs to its lathe and plaster ceiling, pieces of which periodically fall causing damage and potentially danger to users. Other repairs needed to window tracery.

LIST ENTRY NUMBER: 1140786 Contact: Chris Miners 0117 975 1355

© Historic England

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



© Eric Berry

Ponsanooth Methodist Church, including forecourt walls, steps and gate piers, Chapel Hill, St. Gluvias

DESIGNATION: Listed Place of Worship grade

DESIGNATION: LISTER FIRE OF THE STREET FIRE STREET FIR

CONDITION: Good PRIORITY CATEGORY: C (C)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: | | 59|0|

Large Methodist chapel with intact horseshoe galleried interior, along with early pews. Congregation has moved to newly refurbished associated hall and chapel is no longer used. They are in discussion with Historic England about reuse of the chapel.

Contact: Catherine Marlow 0117 975 0732



© Historic England

SITE NAME:

Methodist Chuch (former Wesleyan Chapel), Chapel Road, St. Just

DESIGNATION:

Listed Place of Worship grade II*, CA, WHS

CONDITION: Poor

PRIORITY CATEGORY: C (C)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: | |4329|

Large and prominent chapel at the edge of the small town of St Just. Granite walled with slate roof. Generally plain with large multi-paned arch headed windows but with a grand portico on the street front. Complete galleried interior. Serious rain ingress is affecting the interior especially around the organ chamber at the back end, together with falls of gutters. Some repairs to this area have now taken place. Coastal Revival Fund grant has been announced for the regeneration of the chapel.

Contact: Chris Miners 0117 975 1355



© Historic England

SITE NAME:	Church of St Pynnochus, St. Pinnock
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NI IMBER:	1140308

Small parish church. Norman cruciform origins with C15 north aisle and nave rebuilds, the tower of C14, C16 south porch. Coursed rubble with granite dressings. Cornish slated roofs with some slates slipped. Damp tower with much vegetation growth and problem downpipe on the north side. The church is now closed for worship with possible alternative uses being discussed between Historic England, Truro DAC and Cornwall Council.

Contact: Chris Miners 0117 975 1355



SITE NAME:	Church of St Gregory, Treneglos
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Fair
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1310214
OWNER TYPE:	Religious organisation

Small parish church high on the North Cornish plateau. Two aisles and a high west tower are from the C15, heavily restored 1858. Tower rebuilt 1871. A Listed Places of Worship Roof Repair Grant was awarded in 2016 for roof and rainwater repairs. However the outer roof slopes and the timber floor of the tower still need urgent repair.

Contact: Chris Miners 0117 975 1355



© Historic England

© Historic England

SITE NAME:	Church of St Nicholas, Tresmeer
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Fair
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1161299

Village church with C15 two-stage tower and C19 rebuilt nave. Surrounding church yard. Interior contains Norman font. This church is closed and being prepared for disposal and alternative use by the Church of England. Issues such as allocated parking, garden, design of acommodation, use etc. are all unresolved.

Contact: Catherine Marlow 0117 975 0732

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 Full ladar repair on in fair to good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS			
CA	Conservation Area		
LB	Listed Building		
LPA	Local Planning Authority		
NP	National Park		
RPG	Registered Park and Garden		
SM	Scheduled Monument		
UA	Unitary Authority		
WHS			



SITE NAME:	Church of St Werburgh, Warbstow
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1161531

Small parish church. Nave and chancel of Norman origin and of rubblestone, coursed slate tower and granite ashlar north aisle added in CI5 and north porch in 1601. Restored 1861. Cornish slate roofs which have slipped slates, especially the porch. The rainwater system needs overhauling.

Contact: Chris Miners 0117 975 1355

© Historic England



SITE NAME:	Parish Church of St Anne, Whitstone Head, Whitstone
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1142426

Large parish church with a C13 core with C15 upper tower and three-aisle plan. The porch and the chancel originate from the 1882 restoration. Mostly slatestone rubble with granite dressings. Cornish slate roofs. In fair condition overall but very bad damp in the tower due to a leaking downpipe on the north side. Unguttered pitches on the north and south eaves. Slates are starting to slip from the roof pitches.

Contact: Chris Miners 0117 975 1355

(C)	Histo	nia E	-na	anc

SITE NAME:	Deserted medieval settlement and field system v post-medieval farmhouse north west of Tresibbe	vith incorporated pre et Farm, Altarnun	historic settlement and field system and
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007775
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric coaxial field system, incorporated and adjacent hut circles, stone setting, linear boundaries and medieval settlement on Fox Tor and Treburland Farm, Altarnun		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008245
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric irregular field system and hut circle s deserted settlement south east of Tresibbet Fari		ent medieval regular field system and
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007776
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric stone alignment 1 kilometre SSE of Eastmoorgate, Altarnun		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012228
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Nine Stones stone circle 1.03 kilometres NNW of	Rowbayland Farm	Altarnun / North Hill
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008631
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Scraesdon Fort, Antony		
DESIGNATION:	Scheduled Monument and Listed Building grade II	LIST ENTRY NUMBER:	1004347 and 1140707
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Annie Evans 0117 975 0673
SITE NAME:	Hut circle group and enclosure north east of Carw	ren, Blisland	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004659
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Castle Pencaire hillfort, two rounds and a field syst	em, Tregonning Hi	II, Breage / Germoe
Designation:	Scheduled Monument, LB grade II, CA, WHS	LIST ENTRY NUMBER:	1007293
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Group of round barrows south east of Middle Tap	house, Broadoak	
DESIGNATION:	Scheduled Monument, RB	LIST ENTRY NUMBER:	1004433
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Group of round barrows south of Penadlake, Broa	doak	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004436
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Round barrows west of West Taphouse, Broadoak	(
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004617
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

HERITAGE AT RISK 2020 / SOU	JTH WEST / CORNWALL (UA)		
SITE NAME:	Two round barrows north west of Middle Taphous	se, Broadoak	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003077
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Round barrow 310 yards (280 metres) south of Ki	lmansag, Broadoak	/ St. Pinnock
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004434
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Binhamy moat 500 yards (460 metres) west of Binl	namy Farm, Bude-S	tratton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004655
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Gunnislake Clitters copper, tin, arsenic and wolfra	m mine, Calstock	
DESIGNATION:	Scheduled Monument, LB grade II, WHS	LIST ENTRY NUMBER:	1017088
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Okeltor C19 arsenic, copper and tin mine, Calstoo	k	
Designation:	Scheduled Monument, LB grade II, WHS	LIST ENTRY NUMBER:	1019440
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Prince of Wales Mine at Harrowbarrow, Calstock		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1021411
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Tamar Canal, Gunnislake, Calstock		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1007302
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

heki i AGE A i RISK 2020 / SOU	JTH WEST / CORNWALL (UA)		
SITE NAME:	The remains of the Chapel of St la and adjacent ce	II, Camborne	
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1441204
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Cardinham Castle, Cardinham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004443
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Council Barrow, Cardinham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004476
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Carn Brea Castle, Carn Brea		
DESIGNATION:	Scheduled Monument, 2 LBs, CA, WHS	LIST ENTRY NUMBER:	1006704
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Wheal Busy, Chacewater		
DESIGNATION:	Scheduled Monument, LB grade II, WHS	LIST ENTRY NUMBER:	1021392
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Melangoose camp, Colan		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004426
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Round at Lower Treloskan, Cury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004267
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388

- C Slow decay; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 D Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial like) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

HERITAGE AT RISK 2020 / SOL	JTH WEST / CORNWALL (UA)		
SITE NAME:	Killibury Castle later prehistoric hillfort, Eglosha	yle	
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1010439
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Jewish and Congregationalist cemeteries at Pons	sharden, Falmouth / Pe	enryn
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020815
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	An early Christian memorial stone 380 metres s	south east of Worthyv	ale Manor, Forrabury and Minster
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018701
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Flooding	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Dingerein Castle small multivallate hillfort and a	nnexe, 240 metres no	rth west of Curgurrel Farm, Gerrans
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019742
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Group of round barrows north of Hayle Kimbro	o Pool, Grade-Ruan / I	Mullion
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1003082
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Cliff castle west of Gunwalloe Church, Gunwallo	oe	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004265
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Grambla Roman camp, Gweek		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003078
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ann Preston-Jones 07917 642388

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Round barrow 20 yards (18 metres) north west o	f Tolvan Cross, Gw	eek
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004269
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Rectangular camp south west of Trevarnon Round	l, Gwinear-Gwithiar	1
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004468
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ann Preston-Jones 07917 642388
ITE NAME:	Roseworthy Arsenic Works, 700 metres west of	Cornhill Farm, Gwir	near-Gwithian
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021418
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Trevarnon Round, Gwithian, Gwinear-Gwithian		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006696
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Castle Kayle (earthwork), Phillack, Hayle		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006688
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Carvannel cliff castle, Illogan		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004390
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	'Headon Barrow' near Headon Cross, Jacobstow		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005434
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Round barrow 650 metres east of Carrine, Kea		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019086
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Round 200 metres north west of Penventinnie, Ker	nwyn	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016063
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	The Castles, Kilkhampton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003079
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Five bowl barrows 480 metres and 510 metres nor	th of Hendra Farm	, Ladock
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019021
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Round and annexe 720 metres WSW of Tregear, l	_adock	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020179
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Neolithic settlement and hut circle on Helman Tor	, Lanlivery	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007306
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (non-heritage)	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Mabel Barrow, Lansallos		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006683
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102

C Slow decay; no solution agreed.

Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

D Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial list). use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Earlier prehistoric hillfort, two cairns, medieval po transhumance huts on Stowe's Hill, Linkinhorne	und and adjacent p	rehistoric field systems, hut circles an
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1012352
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Early medieval transhumance hut 740 metres west	of Blackcoombe F	arm, Linkinhorne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011899
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Prehistoric funerary cist 1.275 kilometres north w	est of Wardbrook	Farm, Linkinhorne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012043
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Flooding	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Round cairn with central cist on Bearah Common,	1.106 kilometres r	north of Wardbrook Farm, Linkinhor
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010411
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Two adjacent transhumance huts on Caradon Hill,	450 metres north	of East Caradon Farm, Linkinhorne
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1011900
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Two cairns, centred 82 metres and 110 metres so	uth west of Carado	on Hill summit, Linkinhorne
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1011810
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth - General	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Neolithic long cairn, prehistoric regular and irregu enclosure 625 metres west of Blackcoombe Farm,	lar aggregate field s Linkinhorne / Nor	systems, linear boundaries and medie th Hill
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010221
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
	D. t.	CONTACT:	D
OWNER TYPE:	Private	CONTACT.	Daniel Bashford 07824 103102

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.
 Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet
- implemented.

 C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY:	Scheduled Monument, 2 LBs, part in CA, WHS Generally satisfactory but with significant localised	LIST ENTRY NUMBER:	1020942
PRINCIPAL VULNERABILITY:	problems	TREND:	Declining
	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Castle an Dinas, Ludgvan		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1006725
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
ITE NAME:	Round 450 yards (405 metres) north west of Lowe	r Chellew Farm, Lu	udgvan
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004262
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
ITE NAME:	Innis Downs earthwork, Luxulyan		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006684
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Ancient village and fields at Boswarva Carn, Madron	n	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004466
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
ITE NAME:	Courtyard houses north east of Newmill, Madron		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004356
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
		360 metres) south	west of Little Higher Bosullow, Mad
ITE NAME:	Hut circles with associated field system 400 yards (,	<u> </u>
	Hut circles with associated field system 400 yards (Scheduled Monument, WHS	LIST ENTRY NUMBER:	1004316
designation:			
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY:	Scheduled Monument, WHS Generally unsatisfactory with major localised	LIST ENTRY NUMBER:	1004316

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

SITE NAME:	Round 300 yards (270 metres) north east of Newr	mill, Madron	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004627
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Settlement 450 yards (400 metres) north west of N	Middle Carnaquidde	n, Madron
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003100
CONDITION:	Extensive significant problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	St Madron Well 500 yards (460 metres) south east	t of Boswarthen, Ma	adron
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004310
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Flooding	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Village settlement north of Bodrifty, Madron		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004481
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Barrow 800 yards (730 metres) WNW of Boswen	s Farm, Madron / St	t. Just
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004286
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Cawsand Fort, Maker-with-Rame		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1016102
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Earthwork redoubts Nos. 1, 2 and 3, Maker-with-F	Rame	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004254
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Grenville Battery 550 yards (500 metres) SSW of N	Maker Farm, Maker	-with-Rame
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1003114
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Incomplete Palmerstonian fort 650 yards (600 met	res) west of Forder	r, Maker-with-Rame
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007299
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Mount Edgcumbe round barrow, Maker-with-Rame	e	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004496
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	No. 5 redoubt 450 yards (410 metres) north west	of Maker Farm, Ma	ıker-with-Rame
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1004255
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Hillfort at Blacketon Farm, Menheniot		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007296
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Insworke Chapel, Millbrook		
DESIGNATION:	Scheduled Monument, LB grade II*	LIST ENTRY NUMBER:	1003095
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Round barrow on Bin Down, Morval		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006651
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Group of four round barrows east of Bottaboroug	h, Morwenstow / K	ilkhampton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004402
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Group of round barrows south west of Penhale, M	ullion	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004444
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Trevelgue promontory camp and two barrows, Ne	wquay	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006712
CONDITION:	Extensive significant problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Battens Cross, one of three medieval wayside cros	ses 70 metres sout	h west of Trebartha Hall, North Hill
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012045
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Hut circle settlement 975 metres north east of Tre	wortha Farm, Nor	th Hill
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009806
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric co-axial and regular aggregate field syste on Bastreet Downs, south of Bowda Farm, North I	ems with incorpora Hill	ited and adjacent hut circle settlemer
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011558
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Goldherring British village, Sancreed		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004651
	Generally satisfactory but with significant localised	TREND:	Dealtate
CONDITION:	problems	TREIND.	Declining
CONDITION: PRINCIPAL VULNERABILITY:		NEW ENTRY?:	Yes

- C Slow decay; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 D Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial list). use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

HERITAGE AT RISK 2020 / SOL	JTH WEST / CORNWALL (UA)			
SITE NAME:	Round cairn 1,175 metres WSW of East Castick F	arm, North Hill		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010412	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Stone hut circle 1,225 metres WSW of East Castio	ck Farm, North Hill		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010414	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Round 100 yards (90 metres) east of Caer Bran, Sa	ancreed		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004289	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	Yes	
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Three adjoining prehistoric linear boundaries on Bearah Tor, 687 metres south west of Nodmans Bowda Farm, North Hill			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010220	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Three stone hut circles 1.06 kilometres north east	of Trewortha Farr	n, North Hill	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009807	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Maen (or Mayon) Castle, Sennen			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006757	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Visitor erosion - moderate	NEW ENTRY?:	No	
OWNER TYPE:	Charity (heritage)	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Two stone hut circles and adjacent prehistoric boo Hill	undary wall 575 me	tres west of West Berriow Farm, No	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010218	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Ann Preston-Jones 07917 642388	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

SITE NAME:	Unenclosed hut circle settlement and adjacent prel Farm, North Hill	historic linear boun	dary 800 metres SSE of Trewortha
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008958
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Unknown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Unenclosed hut circle settlement with incorporate Farm, North Hill	d enclosure 1.5 kilo	ometres north west of Wardbrook
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008954
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Unknown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Two adjacent prehistoric coaxial field systems inco and medieval fields on East Moor and Ridge, North		eld systems, stone hut circles, cairns
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008439
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Three barrows 550 metres ENE of Cansford, Otte	rham	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005463
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	King Arthur's Hall, St. Breward		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006706
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Roundago, hut circle and field system on Castallack	c Carn, Paul	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004654
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Bake Rings later prehistoric-Roman round with att	ached enclosure an	d outwork, Pelynt
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017682
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

HERITAGE AT RISK 2020 / SOL	JTH WEST / CORNWALL (UA)		
SITE NAME:	Group of three round barrows north of Hendra, P	elynt	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004621
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Glasney College, Penryn		
DESIGNATION:	Scheduled Monument, LB grade II, part in CA	LIST ENTRY NUMBER:	1007260
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Lescudjack Castle, Penzance		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003270
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	St Piran's Oratory and associated early medieval ce	emetery, Perranzab	uloe
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1018955
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Flooding	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Nick Russell 0117 975 0671
SITE NAME:	The Tolgus arsenic works 80 metres south east of	East Tolgus House	, Redruth
DESIGNATION:	Scheduled Monument, LB grade II, WHS	LIST ENTRY NUMBER:	1021240
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Botrea barrows, Sancreed		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004467
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Caer Bran, Sancreed		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006717
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

	JTH WEST / CORNWALL (UA)		
SITE NAME:	Enclosed hut circle settlement and field system, 50		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1418283
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Field system on Boswens Common, Sancreed		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007268
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Unknown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Hut cluster Chirgwidden Vean, Sancreed		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006715
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Bolster Bank, St. Agnes		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1016444
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Wheal Kitty C20 tin processing works, St. Agnes		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1021164
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Promontory fort and Civil War battery, Little Den	nis Head, St. Antho	ny-in-Meneage
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004431
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Black Head promontory fort, St. Austell Bay		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004391
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ann Preston-Jones 07917 642388

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

HERITAGE AT RISK 2020 / SOU	JTH WEST / CORNWALL (UA)			
SITE NAME:	St Cleer's Well and cross, St. Cleer			
DESIGNATION:	Scheduled Monument, LB grade I	LIST ENTRY NUMBER:	1018205	
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	Yes	
OWNER TYPE:	Unknown	CONTACT:	Daniel Bashford 07824 103102	
SITE NAME:	Stone circle on Emblance Common, St. Breward			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004459	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Unknown	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Camp 900 yards (820 metres) south east of St Bur	yan village, St. Bury	ran	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004483	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388	
ITE NAME:	Round barrow 200 yards (180 metres) north of th	e Merry Maidens, S	t. Buryan	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004358	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Embanked platform cairn with central mound 375 metres north west of Trewalla Farm, St. Cleer			
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1015976	
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102	
SITE NAME:	Kerbed platform cairn with kerbed central mound Cleer	and outer bank 600	0 metres east of Trewalla Farm, St.	
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1010323	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102	
SITE NAME:	Prehistoric cist, cairns and cairnfield on north east Smallacoombe Tor, St. Cleer	Smallacoombe Dov	wns, 570 metres north west of	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018630	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Prehistoric enclosure 325 metres west of Trewalla	Farm, St. Cleer	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1010434
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Prehistoric enclosure and field system, two hut circ east of Sparretts Farm, St. Cleer	cles and parts of a r	nedieval field system 350 metres sout
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1013216
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Prehistoric irregular aggregate field system with inc Farm, St. Cleer	corporated stone h	ut circles 375 metres SSE of Sparretts
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1008765
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bowl barrow 130 metres south east of Penglaze, So	t. Erme	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016887
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric irregular and regular aggregate field sys of Siblyback Farm, St. Cleer	tems with incorpor	ated stone hut circles 750 metres EN
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1011315
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Prehistoric irregular and regular aggregate field sys boulder 750 metres ESE of Siblyback Farm, St. Clee	tems, enclosure, sto er	one hut circles, cairnfield and kerbed
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1010060
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Prehistoric regular aggregate field system with inco enclosure 550 metres WSW of Trewalla Farm, St.	orporated and adjac Cleer	ent stone hut circles and an adjacent
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1009731
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
	DI I	NEW ENTRY?:	Na
PRINCIPAL VULNERABILITY:	Plant growth	INCAA CINTIKII.	No
PRINCIPAL VULNERABILITY:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Prehistoric to post-medieval field systems, boundar north eastern Siblyback Moor, St. Cleer	ries, settlements an	nd railway at Smallacoombe Parks and
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018631
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Round cairn 450 metres east of Sparretts Farm, St.	Cleer	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1009838
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Round cairn 525 metres east of Trewalla Farm, St.	Cleer	
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1012041
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Round cairn 740 metres SSW of Caradon Hill sum	mit, St. Cleer	
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1011774
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Round cairn and shelters 812 metres SSW of Cara	don Hill summit, St	t. Cleer
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1011784
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Public utilities	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Round cairn with peripheral berm 402 metres SSV	V of Caradon Hill s	ummit, St. Cleer
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1011822
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	South Caradon C19 copper mine, St. Cleer		
DESIGNATION:	Scheduled Monument, 2 LBs, part in CA, WHS	LIST ENTRY NUMBER:	1020614
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

SITE NAME:	Stone hut circle 750 metres ESE of Trewalla Farm,	St. Cleer	
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1011909
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	The Tinners' Dyke 160 yards (150 metres) in lengt	h south of Henderg	grove Wood, St. Cleer
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004364
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Tor cairn with adjacent sub-rectangular hut 650 me	etres SSW of Cara	don Hill summit, St. Cleer
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1011793
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Two adjacent stone hut circles 265 metres WNW	of Trewalla Farm,	St. Cleer
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1009738
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Two adjacent stone hut circles 290 metres west of	f Trewalla Farm, St.	Cleer
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1009703
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Prehistoric to medieval settlements, field systems, railway on north east Smallacoombe Down, St. Cle	enclosures and cair eer / Altarnun	ns, with post-medieval boundary and
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018629
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Prehistoric round cairn on Caradon Hill, 310 metro	es west of Heather	House, St. Cleer / Linkinhorne
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1020939
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	The Nine Maidens stone alignment, The Fiddler sta Columb Major / St. Issey	inding stone and tw	o Bronze Age round barrows, St.
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021223
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Bury camp, St. Dominick		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004393
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Warren's Barrow, St. Erme		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016888
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Russell 0117 975 0671
SITE NAME:	Enclosures east of Gurlyn, St. Erth		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1007282
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Redcliff Castle, later prehistoric cliff castle 550 met	res south west of I	Bedruthan, St. Eval
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021006
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Promontory fort north of village, St. Gennys		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003097
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Gunpowder storage complex at Kennall Vale, St. G	lluvias	
DESIGNATION:	Scheduled Monument, 3 LBs, WHS	LIST ENTRY NUMBER:	1020441
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Camp 500 yards (460 metres) west of Trenance, S	t. Issey	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004235
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Medieval transhumance hut on Draynes Common,	500 metres south	west of Westerlake Farm, St. Neot
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007779
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - limited/localised	NEW ENTRY?:	No
OWNER TYPE:	Unknown	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Cadson Bury hillfort, St. Ive		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004494
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Hut circles, Higher Bussow, St. Ives		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006689
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric regular aggregate field system with incorporated enclosure and stone hut circles 550 metres NNW of Lamelgate Farm, St. Neot		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007474
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Whitesand Bay (or Tregonhawke) battery, St. John		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004664
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bartine Castle, St. Just		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006716
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388

- C Slow decay; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 D Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial like) use).
 - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

HERITAGE AT RISK 2020 / SOU	JTH WEST / CORNWALL (UA)		
SITE NAME:	Chambered barrow 100 yards (90 metres) east of	Kerrow Farm, St. J	ust
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004637
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Geevor Mine, St. Just		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1021361
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Nick Russell 0117 975 0671
SITE NAME:	Unenclosed hut circle settlement, field boundaries,	enclosure and cair	n on Blacktor Downs, St. Neot
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011701
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	Yes
OWNER TYPE:	Unknown	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Nanjulian Farm courtyard house, St. Just		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004498
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Animal burrowing - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Numphra Common tin streamworking complex, S	t. Just	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007272
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Standing stone 200 yards (180 metres) west of Ch	ycarne, St. Just	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003116
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Chapel enclosure 150 yards (140 metres) south of	Trelease Farm, St.	Keverne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004334
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

SITE NAME:	Settlement sites 500 yards (460 metres) SSE of Tre	ebarveth, St. Keveri	ne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004319
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	St Levan Chapel site, St. Levan		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007285
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Treryn Dinas fort, St. Levan		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006733
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Westcott Cross, 480 metres south east of Westco	ott Lodge, St. Mellic	on / St. Dominick
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1018019
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Veryan Castle multiple enclosure fort and annexe	500 metres south v	vest of Churchtown Farm, Veryan
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019746
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Cliff castle at Winecove Point, St. Merryn		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004234
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	St Constantine's chapel and holy well, St. Merryn		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1018569
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ann Preston-Jones 07917 642388

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

SITE NAME:	Round 790 metres north east of Trebollack, St. Michael Penkevil		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019612
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	The Rumps promontory fort, St. Minver Highlands		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004625
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Hobbs Hill tin mine, openwork and lodeback tinwo Chyseger Farm, St. Neot	ork 530 metres eas	t and 160 metres north east of
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021410
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Hut circle village 330 yards (300 metres) west of West Northwood Farm, St. Neot		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004662
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Prehistoric field systems, enclosure, hut circles and rounds, with adjacent medieval settlement, longhouse and field system on Higher Langdon Farm, St. Neot		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007475
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Prehistoric settlements and field system with adjacent medieval settlement, field systems, boundaries and tir streamworks on the Brown Gelly Downs, St. Neot		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007770
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Round cairn 1.062 kilometres south west of Higher	Langdon Farm, St	. Neot
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007476
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Round cairn 1.17 kilometres south west of Higher Langdon Farm, St. Neot		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007477
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Castle Dore (camp), St. Sampson / Tywardreath ar	nd Par	
DESIGNATION:	Scheduled Monument, RB	LIST ENTRY NUMBER:	1006691
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Tregargus stone grinding mill No. 2, St. Stephen-in-	-Brannel	
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1003101
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Other not for profit group	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Round barrow north east of Kernick, St. Stephens	By Launceston Rur	al
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003272
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Two round barrows north east of Fairy Cross, St.	Winnow	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004439
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	New Consols Mine: surface, buried and undergrou	nd remains, Lucket	t , Stokeclimsland
DESIGNATION:	Scheduled Monument, 5 LBs, part in CA, WHS	LIST ENTRY NUMBER:	1409595
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Condolden Barrow, Tintagel		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004652
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

HERITAGE AT RISK 2020 / SOUTH	TYVEST / CORINVVALL	(07)		
SITE NAME:	The Ballast Pond	, Torpoint		
DESIGNATION:	Scheduled Monur	ment, LB grade II	LIST ENTRY NUMBER:	1007261
CONDITION:	Generally satisfactory but with significant localised problems		TREND:	Unknown
PRINCIPAL VULNERABILITY:	Coastal erosion		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Carne Beacon ro	ound barrow 320 metres north of	Carne Farm, Verya	n
DESIGNATION:	Scheduled Monur	ment	LIST ENTRY NUMBER:	1019745
CONDITION:	Generally satisfac problems	tory but with significant localised	TREND:	Improving
PRINCIPAL VULNERABILITY:	Bracken		NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)		CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Ancient village so	outh of Carburrow Tor, Warlegga	n	
DESIGNATION:	Scheduled Monur	ment	LIST ENTRY NUMBER:	1003073
CONDITION:	Generally satisfac problems	tory but with significant localised	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Chapel Jane medieval chapel 600 yards (550 metres)		s) NNW of Treen,	Zennor
DESIGNATION:	Scheduled Monur	ment	LIST ENTRY NUMBER:	1004631
CONDITION:	Generally satisfactory but with significant localised problems		TREND:	Stable
PRINCIPAL VULNERABILITY:	Coastal erosion		NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)		CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Treen Common	barrows, Zennor		
DESIGNATION:	Scheduled Monur	ment	LIST ENTRY NUMBER:	1004473
CONDITION:	Generally satisfac problems	tory but with significant localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth		NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple o	wners	CONTACT:	Ann Preston-Jones 07917 642388
	SITE NAME:	Carclew, Mylor		terraced and water gardens, together wi
	DESIGNATION:	Registered Park and Garden grade II, 5 LBs, WHS	1934 and the site	e park. The main house burned down in e is now in divided ownership. Infill opment has taken place in the park belts,
	CONDITION:	Extensive significant problems	substantial areas	of woodland have been cleared and mar nd trees have been lost. The ruins of
一种加热工作	VULNERABILITY:	High	Carclew House,	a II* listed building, were added to the
	TREND:	Declining	established with	2017. A steering group has been the owners of Carclew House and a brie
	NEW ENTRY?:	No	drawn up under	Historic England's guidance to prepare a atement for the site.
Historic England	OWNER TYPE:	Private, multiple owners	Conservation Sta	accomplication and site.
	LIST ENTRY NUMBER:	1000544	Contact: Jo McA	llister 0117 975 0696
SITE NAME:	Bodmin			
DESIGNATION:	Conservation Are	ea 96 l Bs SM	NEW ENTRY?:	No
CONDITION:	Poor	5u, 75 LD3, 01 1	TREND:	Deteriorating
	1 001			Deterior ading

VULNERABILITY:

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Low

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

CONTACT:

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument CA LB LPA NP RPG SM

Alyson Cooper (LPA) 01872 323603

DEVON

DARTMOOR (NP)



SITE NAME: Higher Sigford, Sweet's Sigford, Ilsington, Teignbridge DESIGNATION: Listed Building grade II*

CONDITION Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: D (D) OWNER TYPE: Private

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

A rare example of a longhouse derivative in a farmstead context which has been used for agricultural storage in more recent years. Conditional consents for reoccupation of the house have been granted. Historic England has met with the owner and repair works are now proceeding.

LIST ENTRY NUMBER: 1389617 Contact: Annie Evans 0117 975 0673 © Historic England



© Historic England Archive

SITE NAME:	Gunpowder factory at Powder Mills, a partially enclosed stone hut circle settlement and round cairn, Dartmoor Forest, West Devon
DESIGNATION:	Scheduled Monument, 2 LBs
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Crown

1016635

Devon's only C19 gunpowder factory dates to 1844 and comprises at least 18 buildings involved in the production, storage and management of gunpowder. These buildings are now vacant and neglected, and there are unmanaged trees growing across the site. As a result of Historic England grant and match funding from the Duchy of Cornwall, repair works to the collapsed southern gable end of Building 9 have been undertaken. The grant will also fund arboreal works to remove trees and tree limbs that pose a wind blow threat. Tree works will be undertaken in August 2019 after the end of nesting season.

Contact: Andy Crabb 01626 832093



© Historic England

SITE NAME:	Church of St Petrock, Church Street, South Brent, South Hams
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (D)
OWNER TYPE:	Religious organisation

1147794

C12 parish church of which the west tower (formerly at the crossing) of the originally cruciform church survives. The west end was demolished early C14 when the present nave was rebuilt with two transepts. North and south aisles of early C15, restored late C19. The congregation was awarded a National Lottery Heritage Fund Grant for Places of Worship and in 2016-17 the tower was grouted and repointed and the vestry roof was repaired however the nave roof remains in poor condition. Investigative work on damp ingress is also continuing in 2020.

Contact: Annie Evans 0117 975 0673



SITE NAME:	Church of St Thomas à Becket, Bridford, Teignbridge
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1097825

A medieval granite church in an exposed location on the southern fringe of Dartmoor National Park. The pointing on the tower is failing and falling, and this is allowing water ingress into the fabric. The church was awarded a Listed Places of Worship Roof Repair Grant but further work is still needed.

Contact: Annie Evans 0117 975 0673

© Historic England



© Historic England

SITE NAME:	Parish Church of Holy Trinity, Church Hill, Buckfastleigh, Teignbridge
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1209920

Former parish church. Sited on a high hill. C13 tower; chancel and transepts possibly also C13 in origin; C15 aisles and chancel chapels. Thorough restoration in 1844-1845. Left gutted and roofless after fire on 20 July 1992. The stonework, especially the window tracery, needs further repair. Despite the fire damage, services are still held at the

Contact: Annie Evans 0117 975 0673

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise.

New Entry is noted).

I PA ΝP RPG

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Enclosure on the west side of the Erme valley belo	w Stalldown, Corn	wood, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012767
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	The southern of three enclosures north of Ford W	/aste, Cornwood, S	South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012700
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Unknown	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Three unenclosed stone hut circles on the west sid South Hams	le of the Erme Valle	ey, north of Lower Piles, Cornwood,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012768
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Two hut circles on the south east slope of Stalldov	vn, Cornwood, Sou	uth Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012766
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Unenclosed stone hut settlement north east of Yao	dsworthy, Cornwo	od, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012771
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Enclosure and hut circles east of Huntingdon Ford,	Dean Prior, South	Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002536
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Agglomerated enclosure with hut circles, south of	Lower Piles, Harfo	rd, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009578
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Enclosure with hut circles east of Addicombe, Harf	ford, South Hams		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012484	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Enclosure with hut circles east of Addicombe, Hard	ford, South Hams		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017609	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Enclosure with hut circles in Higher Piles newtake,	Harford, South Ha	ıms	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013110	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093	
ITE NAME:	Enclosure with hut circles to the north east of Piles Copse, Harford, South Hams			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013106	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Hut circles and enclosure to south of Left Lake, Ha	arford, South Hams	;	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004574	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Stone row, cairn and enclosures near Hook Lane, I	Erme Valley, Harfoi	rd, South Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002493	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Unenclosed stone hut settlement on the east side of Hams	of the Erme Valley,	North Harford Moor, Harford, South	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012747	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093	

- C Slow decay; no solution agreed.
- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed but F not yet implemented.

 Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

HERITAGE AT RISK 2020 / SOU	JTH WEST / DARTMOOR (NP)		
SITE NAME:	Unenclosed stone hut settlement with enclosures	north of Piles Cops	e, Harford, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012765
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Enclosed prehistoric settlement and three round c Hams	airns 870 metres so	outh east of Horn's Cross, Holne, South
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020096
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Four cairns 560 metres east of Hapstead Ford and cemetery in the Mardle Valley, Holne, South Hams		of Ryder's Hill, forming part of a cairn
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019270
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Part of the Dartmeet coaxial field system and othe west of Venford Reservoir, Holne, South Hams	r archaeological rer	mains on Holne Moor west and north
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020487
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Partially enclosed stone hut circle settlement 350 i	metres south west	of Horn's Cross, Holne, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019274
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Partially enclosed stone hut circle settlement 420 i Holne, South Hams	metres north west a	and 440 metres west of Horn's Cross,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020185
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Prehistoric fields and settlements north east of Ve system, Holne, South Hams	nford Reservoir for	ming part of the Dartmeet coaxial field
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020091
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Andy Crabb 01626 832093

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Barrow near Shaugh Cross, Shaugh Prior, South Ha	ams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003824
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Prehistoric fields, settlements and cairn south east field system, Holne, South Hams	of Venford Reserve	oir forming part of the Dartmeet coax
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020092
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Cross Dyke reave, Shaugh Prior, South Hams		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010811
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Medieval farmstead and field system, post-medieval west of Gibby Coombe, Holne / West Buckfastleig	tinworks, prehisto h, South Hams	oric settlements and cairns north and
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019591
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Hut circles west of Saddlesborough, Shaugh Prior,	South Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002520
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Multi-period remains at Hentor Warren, Shaugh Pi	rior, South Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019082
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	One of a number of cairns with cists south of Shav	ercombe Brook, Sh	naugh Prior, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012172
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Andy Crabb 01626 832093

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	One of a number of cairns with cists south of Shav	ercombe Brook, Sh	augh Prior, South Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012214	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Charity (heritage)	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	One of three stone hut circles 500 metres SSE of l	egis Tor, Shaugh P	rior, South Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012631	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Charity (heritage)	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Pillow mound 100 metres south east of Great Tro Shaugh Prior, South Hams	wlesworthy Tor, fo	rming part of Trowlesworthy Warren,	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014666	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Pillow mound 160 metres south west of Great Trowlesworthy Tor, forming part of Trowlesworthy Warre Shaugh Prior, South Hams			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014665	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Pillow mound 270 metres south east of Ditsworth Prior, South Hams	y Warren House fo	orming part of Hentor Warren, Shaugh	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014477	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Pillow mound 610 metres SSW of Ditsworthy War Prior, South Hams	rren House forming	g part of Willings Walls Warren, Shaugh	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014469	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Pillow mound 620 metres ESE of Legis Tor forming	g part of Willings W	/alls Warren, Shaugh Prior, South Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014457	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Andy Crabb 01626 832093	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Pillow mound 790 metres NNE of Blackaton Crossouth Hams	ss, forming part of T	rowlesworthy Warren, Shaugh Prior
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014662
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Pillow mound 860 metres NNW of Blackaton Cro South Hams	oss, forming part of	Trowlesworthy Warren, Shaugh Pric
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014664
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Prehistoric and historic archaeological landscape a	at Trowlesworthy V	Varren, Shaugh Prior, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020323
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	Yes
OWNER TYPE:	Charity (heritage)	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Pillow mound 860 metres SSE of Trowlesworthy Shaugh Prior, South Hams	Warren House, forr	ming part of Trowlesworthy Warren
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014616
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Pound and hut circles north of Hawk's Tor, Shaug	h Prior, South Ham	s
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002516
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Rectangular building 420 metres north west of He Prior, South Hams	en Tor, forming an o	outlying part of Hentor Farm, Shaugh
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020011
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
ITE NAME:	Stone hut circle north east of Hentor Brook, Shau	ıgh Prior, South Har	ms
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012175
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Andy Crabb 01626 832093

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

HERITAGE AT RISK 2020 / SOU	JTH WEST / DARTMOOR (NP)		
SITE NAME:	Stone hut circle north of Hentor Brook, Shaugh Pr	ior, South Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012083
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Three pillow mounds and a linear gully 200 metres Trowlesworthy Warren, Shaugh Prior, South Ham	north of Great Tr	owlesworthy Tor forming part of
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014481
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Two pillow mounds and a small area of tin streams forming part of Willings Walls Warren, Shaugh Pri	work 510 metres so or, South Hams	outh west of Ditsworthy Warren House
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014467
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Vermin trap 510 metres WSW of Great Trowlesw Prior, South Hams	orthy Tor forming	part of Trowlesworthy Warren, Shaugh
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014465
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Two pillow mounds and a small area of tin streams forming part of Trowlesworthy Warren, Shaugh Pi		70 metres north of Blackaton Cross,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014663
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Vermin trap 520 metres SSW of Trowlesworthy V Shaugh Prior, South Hams	Varren House form	ning part of Trowlesworthy Warren,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014466
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Vermin trap 350 metres south west of Great Troy Shaugh Prior, South Hams	wiesworthy I or for	ming part of Trowlesworthy Warrer
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014475
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Vermin trap 800 metres south east of Trowleswo Warren, Shaugh Prior, South Hams	rthy Warren House	e forming part of Trowlesworthy
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014464
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
ITE NAME:	Cist with a retaining kerb north west of Corringdo	on Ball, South Brent	t, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010180
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
ITE NAME:	Enclosure and hut circle north of Old Hill, South E	Brent, South Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003200
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Enclosure south east of Dockwell Hole, South Bre	ent, South Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002665
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Enclosure with hut circles and rectangular pens, so	outh of Bala Brook,	South Brent, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012775
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
ITE NAME:	Enclosure with hut circles north of Bala Brook into	ake, South Brent, So	outh Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012776
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

	JTH WEST / DARTMOOR (NP)		
SITE NAME:	Enclosure with hut circles north of Bala Brook inta		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012783
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Enclosures and hut circles at Petre's Pits Bottom, S	South Brent, South	Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004557
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Hut circle and fields, Bishop's Mead, South Brent, S	South Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002537
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Hut enclosure north of Old Hill, South Brent, Sout	th Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002664
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	One of several stone hut circles north of Corringd	lon Ball, South Brer	nt, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010202
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Rider's Rings (The Rings), South Brent, South Ham	s	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002502
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Three enclosed hut groups, Black Tor, Shipley Brid	lge, South Brent, Sc	outh Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002505
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

SITE NAME:	Two conjoined huts between two enclosures no	rth of Bala Brook inta	ake, South Brent, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012778
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Two hut circles on the right bank of Red Brook,	South Brent, South F	Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013035
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Enclosure with hut circles north of Scad Brook, l	Jgborough, South Ha	ms
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012485
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Hembury Castle, West Buckfastleigh, South Ham	S	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003859
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Medieval strip field system, tinworks, part of a pr Down, Manaton, Teignbridge	ehistoric settlement,	a cairn and reave on Challacombe
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021393
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	Yes
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Cist on Whitehorse Hill, 910 metres south east	of Taw Head, Dartmo	oor Forest, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020871
CONDITION:	Extensive significant problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Natural erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	One of a number of cairns at Black Pool, Ugboro	ugh, South Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012232
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SILENAME. One of a number of caims at Black Pool, Ugborough, South Hams DESCRIATION: Scheduled Monument ONDITION Generally unsatisfactory with major localised problems Private, multiple owners ONDITION OWNER TITE Private, multiple owners Stone alignment and caim south east of Western Beacon, Ugborough, South Hams DESCRIATION: Scheduled Monument UIT BUTKIYN NUMBER UIT BUTKIYN NUMBER DESCRIATION: Scheduled Monument ONDITION Generally statisfactory but with significant localised problems PRIVATE, multiple owners ONDITION ONNER TITE ONNER TITE ONDITION ONNER TITE	HERITAGE AT RISK 2020 / SOL	JTH WEST / DARTMOOR (NP)		
CONDITION OWNERTING Private, multiple owners CONTACT: Andy Crabb 01626 832093 ATTENANC Stone alignment and cairn south east of Western Beacon, Ugborough, South Hams DESIGNATION Scheduled Monument UST ENTRY NUMBER 1017604 CONDITION Generally satisfactory but with significant localised problems Private, multiple owners CONTACT: Andy Crabb 01626 832093 AND Private, multiple owners CONTACT: Andy Crabb 01626 832093 AND Private, multiple owners CONTACT: Andy Crabb 01626 832093 AND Private, multiple owners CONTACT: Andy Crabb 01626 832093 AND Private, multiple owners CONTACT: Andy Crabb 01626 832093 AND Private, multiple owners CONTACT: Andy Crabb 01626 832093 AND CONTACT: Andy Crabb 01626 832093 AND CONTACT: Andy Crabb 01626 832093 AND CONTACT: AND Crabb 01626 832093 AND CRABBER CRABBE	SITE NAME:	One of a number of cairns at Black Pool, Ugborou	gh, South Hams	
Problems problems Plant growth Plant growth Private, multiple owners Private, Month of Constitution, Teignbridge Problems Problems Problems Problems Problems Problems Problems Problems Problems Private, Month of Private, Mo	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012285
Private, multiple owners Stone alignment and cairn south east of Western Beacon, Ugborough, South Hams DESIGNATION Scheduled Monument Scheduled Monument Scheduled Monument Decining Problems Private, multiple owners CONTACT: Private, multiple owners Contract: Andy Crabb 01626 832093 Scheduled Monument Scheduled Monument Generally satisfactory but with significant localised problems Problems Scheduled Monument Other not for profit group Generally satisfactory but with significant localised problems Scheduled Monument Scheduled Monument Scheduled Monument CONTACT: Andy Crabb 01626 832093 Andy Crabb 01626 832093 BERICANAME Settlement on Smallacombe Rocks, Ilsington, Teignbridge Scheduled Monument CONTACT: Andy Crabb 01626 832093 BERICANAME Scheduled Monument CONTACT: Andy Crabb 01626 832093 BERICANAME Scheduled Monument CONTACT: Andy Crabb 01626 832093 BERICANAME Scheduled Monument Scheduled Mo	CONDITION:		TREND:	Declining
STENAME Stone alignment and cairn south east of Western Beacon, Ugborough, South Hams DESIGNATION Scheduled Monument Scheduled	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
Designation Scheduled Monument UST ENTRY NUMBER CONDITION CONDITIO	OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093
CONDITION Generally satisfactory but with significant localised problems Problems REBINGIBN VILLINERABILITY: Plant growth Private, multiple owners CONTACT: Andy Crabb 01626 832093 SITE NAME: CONDITION: Controll tree growth CONDITION: CONTACT: Andy Crabb 01626 832093 CONDITION: CONDITION: CONTACT: CONDITION: CONTACT: Andy Crabb 01626 832093 CONDITION: CONTACT: CONTACT: Andy Crabb 01626 832093 CONDITION: CONTACT: Andy Crabb 01626 832093 CONTA	SITE NAME:	Stone alignment and cairn south east of Western E	Beacon, Ugborough,	, South Hams
Problems Problems Problems Private, multiple owners CONTACT: Andy Crabb 01626 832093 Private, multiple owners CONDITION: Scheduled Monument Declining Private, multiple owners CONDITION: Contact: Andy Crabb 01626 832093 Private or profit group CONTACT: Andy Crabb 01626 832093 Private or profit group CONTACT: Andy Crabb 01626 832093 Private or profit group CONTACT: Andy Crabb 01626 832093 Private or profit group CONTACT: Andy Crabb 01626 832093 Private or profit group CONTACT: Andy Crabb 01626 832093 Private or profit group Private or profit group Private or profit group CONTACT: Andy Crabb 01626 832093 Private or profit group Private or profit group Private or profit group CONTACT: Andy Crabb 01626 832093 Private or profit group Private or private or private or profit group Private or private or private or private or profit group Private or private or private or private or private or profit group Private or private	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017604
OWNER TYPE Private, multiple owners Contact: Andy Crabb 01626 832093 STEENAME: Cairn 240 metres north of Crownley Parks, Ilsington, Teignbridge DESIGNATION: Scheduled Monument Generally satisfactory but with significant localised problems PRINCIPLE VILLIAGE AND CONTACT: Andy Crabb 01626 832093 STEENAME: Other not for profit group SETTENAME: Settlement on Smallacombe Rocks, Ilsington, Teignbridge DESIGNATION: Scheduled Monument Scheduled Monument OWNER TYPE OWNER TYPE Mixed, multiple owners OWNER TYPE Mixed, multiple owners OWNER TYPE DESIGNATION: Scheduled Monument Scheduled Monument Scheduled Monument OWNER TYPE DESIGNATION: Scheduled Monument DESIGNATION: Scheduled Monument DESIGNATION: Scheduled Monument Declining PRINCIPLE VILLIAGE DECIGNATION: Scheduled Monument Declining Declining PRINCIPLE VILLIAGE DECIGNATION: Scheduled Monument Declining Declining PRINCIPLE VILLIAGE DECIGNATION: Scheduled Monument Declining DECIGNATION: Scheduled Monument Declining DECIGNATION: Scheduled Monument Decignation: New Entire. No Declining DESIGNATION: Scheduled Monument DESIGNATION: Scheduled Monument DESIGNATION: Scheduled Monument DESIGNATION: Scheduled Monument DECIGNATION: Scheduled Monument Decignation Decilning DECIGNATION: Scheduled Monument DECIN NOTICE: Andy Crabb 01626 832093 DECIGNATION: Scheduled Monument DECIN NOTICE: Mon	CONDITION:		TREND:	Declining
STENAME: Cairn 240 metres north of Crownley Parks, Ilsington, Teignbridge DESIGNATION: Scheduled Monument Scheduled Monument Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY: No OWNER TYPE: Other not for profit group Settlement on Smallacombe Rocks, Ilsington, Teignbridge DESIGNATION: Scheduled Monument Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth Mixed, multiple owners Settlement west of Holwell Tor, Ilsington, Teignbridge DESIGNATION: Scheduled Monument Scheduled Monument Settlement west of Holwell Tor, Ilsington, Teignbridge DESIGNATION: Scheduled Monument	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
CONDITION: Scheduled Monument LEST ENTRY NUMBER: 1019588 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Scrub/ tree growth NEW ENTRY: No CONTACT: Andy Crabb 01626 832093 SETE NAME: Settlement on Smallacombe Rocks, Ilsington, Teignbridge DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002531 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth NIVENTRY: No CONNER TYPE: Settlement west of Holwell Tor, Ilsington, Teignbridge DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002539 SETE NAME: Settlement west of Holwell Tor, Ilsington, Teignbridge DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002529 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth NIVENTRY: No CONTRET TYPE: Local authority CONTACT: Andy Crabb 01626 832093 SETE NAME: Prehistoric and medieval settlements and their field systems at Hound Tor, Manaton, Teignbridge DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1016255 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Visitor erosion - extensive NEW ENTRY: No CONNER TYPE: Private CONTACT: Andy Crabb 01626 832093 RETE NAME: Prehistoric and medieval settlements and their field systems at Hound Tor, Manaton, Teignbridge DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1016255 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Visitor erosion - extensive NEW ENTRY: No CONTACT: Andy Crabb 01626 832093 Medieval strip fields, tinworks, prehistoric settlements, and a cairn on the lower western slopes of Habours of the Moor, Teignbridge DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1021394 CONDITION: Generally satisfactory but with minor localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No	OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093
Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY: No OWNER TYPE: Other not for profit group CONTACT: Andy Crabb 01626 832093 SITE NAME: Settlement on Smallacombe Rocks, Ilsington, Teignbridge DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1002531 Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No OWNER TYPE: Mixed, multiple owners CONTACT: Andy Crabb 01626 832093 SITE NAME: Settlement west of Holwell Tor, Ilsington, Teignbridge DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1002529 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No OWNER TYPE: Local authority CONTACT: Andy Crabb 01626 832093 SITE NAME: Prehistoric and medieval settlements and their field systems at Hound Tor, Manaton, Teignbridge DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1016255 CONDITION: Generally satisfactory but with significant localised problems Prehistoric and medieval settlements and their field systems at Hound Tor, Manaton, Teignbridge DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1016255 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Visitor erosion - extensive NEW ENTRY: No OWNER TYPE: Private CONTACT: Andy Crabb 01626 832093 SITE NAME: Medieval strip fields, tinworks, prehistoric settlements, and a cairn on the lower western slopes of Ha Down, Manaton / Widecombe in the Moor, Teignbridge DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1021394 TREND: Improving PRINCIPAL VULNERABILITY: No	SITE NAME:	Cairn 240 metres north of Crownley Parks, Ilsingt	on, Teignbridge	
PRINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY: No OWNER TYPE: Other not for profit group CONTACT: Andy Crabb 01626 832093 SITE NAME: Settlement on Smallacombe Rocks, Ilsington, Teignbridge DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1002531 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No OWNER TYPE: Mixed, multiple owners CONTACT: Andy Crabb 01626 832093 SITE NAME: Settlement west of Holwell Tor, Ilsington, Teignbridge DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1002529 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No OWNER TYPE: Local authority CONTACT: Andy Crabb 01626 832093 SITE NAME: Prehistoric and medieval settlements and their field systems at Hound Tor, Manaton, Teignbridge DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1016255 DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1016255 CONDITION: Generally satisfactory but with significant localised problems Prehistoric and medieval settlements and their field systems at Hound Tor, Manaton, Teignbridge DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1016255 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: No OWNER TYPE: No OWNER TYPE: Private CONTACT: Andy Crabb 01626 832093 STE NAME Medieval strip fields, tinworks, prehistoric settlements, and a cairn on the lower western slopes of Ha Down, Manaton / Widecombe in the Moor, Teignbridge DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1021394 Generally satisfactory but with minor localised TREND: Improving PRINCIPAL VULNERABILITY: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019588
OWNER TYPE Other not for profit group OWNER TYPE Other not for profit group OESIGNATION: Scheduled Monument UST ENTRY NUMBER: IO02531 OESIGNATION: OENDATION: OENDATION: OENDATION: OWNER TYPE OESIGNATION: OWNER TYPE OWNER TYPE OESIGNATION: OENER OESIGN	CONDITION:		TREND:	Declining
SETE NAME: Settlement on Smallacombe Rocks, Ilsington, Teignbridge DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002531 Declining PRINCIPAL VULNERABILITY: Plant growth Mixed, multiple owners Settlement west of Holwell Tor, Ilsington, Teignbridge DESIGNATION: Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No Declining PRINCIPAL VULNERABILITY: Plant growth DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002529 Declining PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No CONTACT: Andy Crabb 01626 832093 SITE NAME: Prehistoric and medieval settlements and their field systems at Hound Tor, Manaton, Teignbridge DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1016255 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Visitor erosion - extensive NEW ENTRY: No OWNER TYPE: Private Medieval strip fields, tinworks, prehistoric settlements, and a cairn on the lower western slopes of Harmer DOWN, Manaton / Widecombe in the Moor, Teignbridge DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1016255 Declining PRINCIPAL VULNERABILITY: No OWNER TYPE: Private Medieval strip fields, tinworks, prehistoric settlements, and a cairn on the lower western slopes of Harmer DOWN, Manaton / Widecombe in the Moor, Teignbridge DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1021394 Improving PRINCIPAL VULNERABILITY: No	PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1002531 CONDITION: Generally satisfactory but with significant localised problems Plant growth NEW ENTRY!: No OWNER TYPE: Mixed, multiple owners CONTACT: Andy Crabb 01626 832093 SITE NAME: Settlement west of Holwell Tor, Ilsington, Teignbridge DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1002529 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY!: No OWNER TYPE: Local authority CONTACT: Andy Crabb 01626 832093 SITE NAME: Prehistoric and medieval settlements and their field systems at Hound Tor, Manaton, Teignbridge DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1016255 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Visitor erosion - extensive NEW ENTRY: No OWNER TYPE: Private CONTACT: Andy Crabb 01626 832093 SITE NAME: Private CONTACT: Andy Crabb 01626 832093 SITE NAME: Declining PRINCIPAL VULNERABILITY: Visitor erosion - extensive NEW ENTRY: No OWNER TYPE: Private CONTACT: Andy Crabb 01626 832093 SITE NAME: Medieval strip fields, tinworks, prehistoric settlements, and a cairn on the lower western slopes of Ha Down, Manaton / Widecombe in the Moor, Teignbridge DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1021394 CONDITION: Generally satisfactory but with minor localised problems PRINCIPAL VULNERABILITY: No	OWNER TYPE:	Other not for profit group	CONTACT:	Andy Crabb 01626 832093
Generally satisfactory but with significant localised problems Plant growth New ENTRY: No DWNER TYPE Mixed, multiple owners Settlement west of Holwell Tor, Ilsington, Teignbridge DESIGNATION: Scheduled Monument Generally unsatisfactory with major localised problems Plant growth New ENTRY: No Declining CONDITION: Generally unsatisfactory with major localised problems Plant growth New ENTRY: No DWNER TYPE: Local authority Prehistoric and medieval settlements and their field systems at Hound Tor, Manaton, Teignbridge DESIGNATION: Scheduled Monument UST ENTRY NUMBER: IO 16255 Generally satisfactory but with significant localised problems Private CONTACT: No Declining PRINCIPAL VULNERABILITY: Visitor erosion - extensive NEW ENTRY: No Medieval strip fields, tinworks, prehistoric settlements, and a cairn on the lower western slopes of Hamber of Down, Manaton / Widecombe in the Moor, Teignbridge DESIGNATION: Scheduled Monument UST ENTRY NUMBER: IO 16256 Declining PRINCIPAL VULNERABILITY: Visitor erosion - extensive NEW ENTRY: No Medieval strip fields, tinworks, prehistoric settlements, and a cairn on the lower western slopes of Hamber of Down, Manaton / Widecombe in the Moor, Teignbridge DESIGNATION: Scheduled Monument UST ENTRY NUMBER: IO 21394 Improving PRINCIPAL VULNERABILITY: Plant growth New ENTRY: No	SITE NAME:	Settlement on Smallacombe Rocks, Ilsington, Teigr	nbridge	
PRINCIPAL VULNERABILITY: Plant growth Mixed, multiple owners Settlement west of Holwell Tor, Ilsington, Teignbridge DESIGNATION: Scheduled Monument UST ENTRY NUMBER: I 002529 Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No OWNER TYPE: Local authority Designation: Scheduled Monument Local authority CONTACT: Andy Crabb 01626 832093 STE NAME: Prehistoric and medieval settlements and their field systems at Hound Tor, Manaton, Teignbridge DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1016255 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Visitor erosion - extensive NEW ENTRY: No OWNER TYPE: Private CONTACT: Andy Crabb 01626 832093 Medieval strip fields, tinworks, prehistoric settlements, and a cairn on the lower western slopes of Hardien and the Moor, Teignbridge DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1016255 Declining PRINCIPAL VULNERABILITY: No Medieval strip fields, tinworks, prehistoric settlements, and a cairn on the lower western slopes of Hardien and Pown, Manaton / Widecombe in the Moor, Teignbridge DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1021394 DESIGNATION: Scheduled Monument UST ENTRY NUMBER: I 021394 Improving PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002531
Mixed, multiple owners CONTACT: Andy Crabb 01626 832093 SITE NAME: Settlement west of Holwell Tor, Ilsington, Teignbridge DESIGNATION: Scheduled Monument Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No OWNER TYPE: Local authority Prehistoric and medieval settlements and their field systems at Hound Tor, Manaton, Teignbridge DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1016255 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Visitor erosion - extensive Medieval strip fields, tinworks, prehistoric settlements, and a cairn on the lower western slopes of Hardown, Manaton / Widecombe in the Moor, Teignbridge DESIGNATION: Scheduled Monument Medieval strip fields, tinworks, prehistoric settlements, and a cairn on the lower western slopes of Hardown, Manaton / Widecombe in the Moor, Teignbridge DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1021394 CONDITION: Generally satisfactory but with minor localised problems PRINCIPAL VULNERABILITY: No Medieval strip fields, tinworks, prehistoric settlements, and a cairn on the lower western slopes of Hardown, Manaton / Widecombe in the Moor, Teignbridge DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1021394 CONDITION: Generally satisfactory but with minor localised problems PRINCIPAL VULNERABILITY: No	CONDITION:		TREND:	Declining
SETE NAME: Settlement west of Holwell Tor, Ilsington, Teignbridge DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002529 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY): No OWNER TYPE: Local authority CONTACT: Andy Crabb 01626 832093 SITE NAME: Prehistoric and medieval settlements and their field systems at Hound Tor, Manaton, Teignbridge DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1016255 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Visitor erosion - extensive NEW ENTRY): No OWNER TYPE: Private CONTACT: Andy Crabb 01626 832093 SITE NAME: Medieval strip fields, tinworks, prehistoric settlements, and a cairn on the lower western slopes of Hardown Manaton / Widecombe in the Moor, Teignbridge DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1021394 CONDITION: Generally satisfactory but with minor localised problems Scheduled Monument LIST ENTRY NUMBER: 1021394 CONDITION: Generally satisfactory but with minor localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY): No	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002529 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth Local authority Declining Problems Prehistoric and medieval settlements and their field systems at Hound Tor, Manaton, Teignbridge DESIGNATION: Scheduled Monument DESIGNATION: Scheduled Monument Declining PRINCIPAL VULNERABILITY: Visitor erosion - extensive Private Declining Private Declining Medieval strip fields, tinworks, prehistoric settlements, and a cairn on the lower western slopes of Harden Down, Manaton / Widecombe in the Moor, Teignbridge DESIGNATION: Scheduled Monument DESIGNATION: Scheduled Monument Declining Private Declining Private CONTACT: Andy Crabb 01626 832093 Medieval strip fields, tinworks, prehistoric settlements, and a cairn on the lower western slopes of Harden Down, Manaton / Widecombe in the Moor, Teignbridge DESIGNATION: Scheduled Monument DESIGNATION: Scheduled Mo	OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth Declining Principal vulnerability: Plant growth Declining Principal vulnerability: Plant growth Downer type: Local authority Prehistoric and medieval settlements and their field systems at Hound Tor, Manaton, Teignbridge DESIGNATION: Scheduled Monument Declining Principal vulnerability: Visitor erosion - extensive Declining Principal vulnerability: Visitor erosion - extensive Medieval strip fields, tinworks, prehistoric settlements, and a cairn on the lower western slopes of Hadown, Manaton / Widecombe in the Moor, Teignbridge DESIGNATION: Scheduled Monument Down, Manaton / Widecombe in the Moor, Teignbridge DESIGNATION: Scheduled Monument D	SITE NAME:	Settlement west of Holwell Tor, Ilsington, Teignbr	idge	
problems problems Principal Vulnerability: Plant growth New Entry?: No Contact: Andy Crabb 01626 832093 Site Name: Prehistoric and medieval settlements and their field systems at Hound Tor, Manaton, Teignbridge Designation: Scheduled Monument List Entry Number: 1016255 Condition: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Visitor erosion - extensive Medieval strip fields, tinworks, prehistoric settlements, and a cairn on the lower western slopes of Harden Down, Manaton / Widecombe in the Moor, Teignbridge Designation: Scheduled Monument List Entry Number: No Contact: Andy Crabb 01626 832093 Medieval strip fields, tinworks, prehistoric settlements, and a cairn on the lower western slopes of Harden Down, Manaton / Widecombe in the Moor, Teignbridge Designation: Scheduled Monument List Entry Number: 1021394 Condition: Generally satisfactory but with minor localised problems PRINCIPAL VULNERABILITY: No New Entry?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002529
DOWNER TYPE: Local authority Prehistoric and medieval settlements and their field systems at Hound Tor, Manaton, Teignbridge DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Visitor erosion - extensive Medieval strip fields, tinworks, prehistoric settlements, and a cairn on the lower western slopes of Hardown, Manaton / Widecombe in the Moor, Teignbridge DESIGNATION: Scheduled Monument Generally satisfactory but with minor localised problems PRINCIPAL VULNERABILITY: Plant growth New ENTRY: Andy Crabb 01626 832093 TREND: Improving New ENTRY: No	CONDITION:		TREND:	Declining
Prehistoric and medieval settlements and their field systems at Hound Tor, Manaton, Teignbridge Designation: Scheduled Monument LIST ENTRY NUMBER: 1016255 Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Visitor erosion - extensive NEW ENTRY?: No OWNER TYPE: Medieval strip fields, tinworks, prehistoric settlements, and a cairn on the lower western slopes of Hardown, Manaton / Widecombe in the Moor, Teignbridge DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1021394 Generally satisfactory but with minor localised problems PRINCIPAL VULNERABILITY: Plant growth New ENTRY?: No	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1016255 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Visitor erosion - extensive NEW ENTRY?: No CONTACT: Andy Crabb 01626 832093 SITE NAME: Medieval strip fields, tinworks, prehistoric settlements, and a cairn on the lower western slopes of Hard Down, Manaton / Widecombe in the Moor, Teignbridge DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1021394 CONDITION: Generally satisfactory but with minor localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No	OWNER TYPE:	Local authority	CONTACT:	Andy Crabb 01626 832093
Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Visitor erosion - extensive NEW ENTRY?: No CONTACT: Andy Crabb 01626 832093 Medieval strip fields, tinworks, prehistoric settlements, and a cairn on the lower western slopes of Harden Down, Manaton / Widecombe in the Moor, Teignbridge DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: Generally satisfactory but with minor localised problems PRINCIPAL VULNERABILITY: Plant growth New ENTRY?: No	SITE NAME:	Prehistoric and medieval settlements and their field	d systems at Hound	Tor, Manaton, Teignbridge
problems PRINCIPAL VULNERABILITY: Visitor erosion - extensive New entry?: No OWNER TYPE: Private Medieval strip fields, tinworks, prehistoric settlements, and a cairn on the lower western slopes of Ha Down, Manaton / Widecombe in the Moor, Teignbridge DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1021394 Generally satisfactory but with minor localised problems PRINCIPAL VULNERABILITY: Plant growth New entry?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016255
Private Medieval strip fields, tinworks, prehistoric settlements, and a cairn on the lower western slopes of Harbard Down, Manaton / Widecombe in the Moor, Teignbridge DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1021394 CONDITION: Generally satisfactory but with minor localised problems PRINCIPAL VULNERABILITY: Plant growth New ENTRY: No	CONDITION:		TREND:	Declining
Medieval strip fields, tinworks, prehistoric settlements, and a cairn on the lower western slopes of Hardon Down, Manaton / Widecombe in the Moor, Teignbridge DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1021394 CONDITION: Generally satisfactory but with minor localised problems PRINCIPAL VULNERABILITY: Plant growth New ENTRY?: No	PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	No
Down, Manaton / Widecombe in the Moor, Teignbridge DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1021394 CONDITION: Generally satisfactory but with minor localised problems PRINCIPAL VULNERABILITY: Plant growth New ENTRY: No	OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
Generally satisfactory but with minor localised problems TREND: Improving	SITE NAME:	Medieval strip fields, tinworks, prehistoric settleme Down, Manaton / Widecombe in the Moor, Teignl	ents, and a cairn on oridge	the lower western slopes of Hamel
problems PRINCIPAL VULNERABILITY: Plant growth New entry: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021394
•	CONDITION:		TREND:	Improving
OWNER TYPE: Crown CONTACT: Andy Crabb 01626 832093	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
	OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Enclosure south west of Hingston Rocks, Moreton	hampstead, Teignb	ridge
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002496
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Hut circles on Hedge Down, Widecombe in the M	oor, Teignbridge	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002620
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Two cairns on Cator Common, Widecombe in the	Moor, Teignbridge	е
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003297
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Camp south east of Okehampton, Okehampton Ha	amlets, West Devo	on
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003873
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Deserted medieval site 400 metres west of Okeha	mpton camp, Okeh	nampton Hamlets, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002654
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth - General	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Deserted medieval site north of Okehampton cam	p, Okehampton Ha	ımlets, West Devon
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1002630
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - moderate	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Deserted medieval site north west of Okehamptor	ı camp, Okehampto	on Hamlets, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004602
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth - General	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 D Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial list). use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Round cairn on Standon Hill, Peter Tavy, West De	von			
Designation:	Scheduled Monument	LIST ENTRY NUMBER:	1016253		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable		
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	No		
OWNER TYPE:	Government or agency	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	A double stone hut circle and enclosure 280 metre	es south of Deadlak	te Foot, Dartmoor Forest, West Devo		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011569		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Camp 325 yards (300 metres) south east of Archerton, Dartmoor Forest, West Devon				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002636		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No		
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Coaxial fields, prehistoric settlement, two cairns ar metres south east of Stannon Tor, Dartmoor Fore		nt in Little Stannon Newtake, 900		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021339		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Medieval settlement 470 metres east of Hartyland,	Dartmoor Forest,	West Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021338		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Prehistoric enclosed settlement 740 metres north	west of Hartland T	or, Dartmoor Forest, West Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021335		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Hut circle and field system north west of Saddle Br	idge, Dartmoor Fo	rest / Holne, West Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002601		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093		

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

DESIGNATION:	Prestonbury Castle (hillfort), Drewsteignton, West	Devon	
	Scheduled Monument	LIST ENTRY NUMBER:	1003861
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Part of a coaxial field system, prehistoric settlemen	ts and cairns on Bu	ttern Hill, Gidleigh, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021215
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Stone hut circle 380 metres north west of North C	Creaber, Gidleigh, V	Vest Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021220
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Two stone hut circles and field system, 590 metres Buttern Hill, Gidleigh, West Devon	south of Buttern,	forming part of a coaxial field system o
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021218
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Enclosure, two stone hut circles and an alignment of Tor, Lands common to the Parishes of Bridestowe		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007648
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Hut circles and a length of enclosure wall, forming Nodden Gate, Lands common to the Parishes of Br	part of a stone hut ridestowe and Sour	circle settlement 600 metres east of ton / Lydford, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008638
323/3/4/110/4.			
	Generally satisfactory but with significant localised problems	TREND:	Declining
CONDITION:		TREND: NEW ENTRY?:	
CONDITION: PRINCIPAL VULNERABILITY:	problems		Declining
CONDITION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME:	problems Plant growth	NEW ENTRY?: CONTACT:	Declining No Andy Crabb 01626 832093
CONDITION: PRINCIPAL VULNERABILITY: DWNER TYPE:	problem's Plant growth Crown Stone hut circle 530 metres ESE of Nodden Gate for	NEW ENTRY?: CONTACT:	Declining No Andy Crabb 01626 832093
CONDITION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME:	problems Plant growth Crown Stone hut circle 530 metres ESE of Nodden Gate for Lydford, West Devon	NEW ENTRY?: CONTACT: orming an outlying	Declining No Andy Crabb 01626 832093 part of a stone hut circle settlement,
CONDITION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION:	problems Plant growth Crown Stone hut circle 530 metres ESE of Nodden Gate for Lydford, West Devon Scheduled Monument Generally satisfactory but with significant localised	NEW ENTRY?: CONTACT: orming an outlying LIST ENTRY NUMBER:	Declining No Andy Crabb 01626 832093 part of a stone hut circle settlement, 1008639

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

SITE NAME:	Stone hut circle 610 metres ESE of Nodden Gate for Lydford, West Devon	orning an outlying	part of a stone hat their settlement		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008656		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Four round barrows on Wigford Down, Meavy, West Devon				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002522		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Greenwell Girt socket stone 600 metres SSW of L	ovaton hamlet, Me	avy, West Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008929		
CONDITION:	Extensive significant problems	TREND:	Stable		
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Hut circles south east of Brisworthy, Meavy, West Devon				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004585		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Commercial company	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Prehistoric enclosures on Dewerstone Hill, 500 me Devon	etres south east of	Dewerstone Cottage, Meavy, West		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020241		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Charity (heritage)	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Settlement on Wigford Down, Meavy, West Devo	n			
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1002550		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Settlement on Wigford Down south of Durance, M	1eavy, West Devor	1		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002523		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
	DI .	NEW ENTRY?:	No		
PRINCIPAL VULNERABILITY:	Plant growth	THE TY EITHING.	INO		
PRINCIPAL VULNERABILITY: OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093		

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

DESIGNATION:			
	Scheduled Monument	LIST ENTRY NUMBER:	1003057
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
ITE NAME:	Two hut circles south of Catstor Down, Meavy, W	est Devon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002548
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
ITE NAME:	An enclosed stone hut circle settlement, three rou Tor, Peter Tavy, West Devon	nd cairns and a leng	gth of reave 650 metres WSW of Ger
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008711
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Andy Crabb 01626 832093
ITE NAME:	Cairnfield and two stone hut circles 490 metres an Devon	d 550 metres soutl	h west of Cox Tor, Peter Tavy, West
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020004
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093
ITE NAME:	Stone alignment, five cairns, two stone hut circles a Walkhampton, West Devon	and a length of reav	re 600 metres north east of Horseyea
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019566
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
TE NAME:	Coaxial field system and prehistoric settlement 410	metres west of C	ox Tor, Peter Tavy, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020090
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093
ITE NAME:	Prehistoric settlement 610 metres south west of Cox Tor, Peter Tavy, West Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020002
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Stone hut circle and a short length of boundary wa settlement on the north east slope of Cox Tor, Pe	ter Tavy, West De	von
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011432
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Cairnfield 460 metres south east of Cox Tor, Pete	r Tavy / Whitchurc	h, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020005
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Cairn south west of Lower Hartor Tor, Sheepstor,	, West Devon	
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1012293
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
ITE NAME:	Cairn with a cist north of Drizzlecombe stone align	nments, Sheepstor,	West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010654
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Cairn with cist north of Gutter Tor, Sheepstor, W	est Devon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012473
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Enclosed stone hut settlement south west of Gutte	er Tor, Sheepstor, '	West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012251
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Enclosure north west of Gutter Tor, Sheepstor, W	est Devon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012032
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Two stone alignments and a round cairn 390 metre	es north west of Sh	narpitor, Walkhampton, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007422
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Part of Eylesbarrow reave, Sheepstor, West Devor	1	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011958
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Prehistoric enclosed settlement 950 metres north Devon	east of Ditsworthy	Warren House, Sheepstor, West
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021058
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Prehistoric settlement, three round cairns and a post-medieval rabbit warren at Legis Tor, Sheepstor, W Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019876
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Round cairn east of Whittenknowles Rocks, 960 m	etres ENE of Gutt	er Tor, Sheepstor, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021052
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Two enclosures and a length of the Eylesbarrow w Sheepstor, West Devon	atershed reave 800) metres WSW of Eylesbarrow,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013474
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Unenclosed stone hut settlement south west of Gu	itter Tor, Sheepsto	or, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012239
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
	Private	CONTACT:	Andy Crabb 01626 832093

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.
 Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Scheduled Monument CONDITION CONTROLLY PRINTED WAY PRI	SITE NAME:	Warren at Sheeps Tor, 520 metres north of Chubs	stone Cottage, She	epstor, West Devon
PRINCIPLY JULIEVASUITY: Plant growth NEW DITTOR: No OWNER TYPE Agglomerate enclosure and 15 stone hut circles 560 metres west of Cawsand Beacon, South Tawton, No OWNER TYPE CONTINUES Agglomerate enclosure and 15 stone hut circles 560 metres west of Cawsand Beacon, South Tawton, No OWNER TYPE CORRESTION CEDEBORATION: Scheduled Monument LIST DATE TAWNERSHIPT Plant growth Andy Crabb 01626 832093 Agglomerate enclosure and ten stone hut circles 500 metres west of Cawsand Beacon, South Tawton, No OWNER TYPE CROWN CROWNER TYPE Agglomerate enclosure and ten stone hut circles 500 metres west of Cawsand Beacon, South Tawton, OWNER TYPE Agglomerate enclosure and ten stone hut circles 500 metres west of Cawsand Beacon, South Tawton, OWNER TYPE Agglomerate enclosure and ten stone hut circles 500 metres west of Cawsand Beacon, South Tawton, OWNER TYPE Agglomerate enclosure and ten stone hut circles 500 metres west of Cawsand Beacon, South Tawton, OWNER TYPE Agglomerate enclosure and ten stone hut circles 500 metres west of Cawsand Beacon, South Tawton, OWNER TYPE Agglomerate enclosure and ten stone hut circles 500 metres west of Cawsand Beacon, South Tawton, Owner Type Cowner Tawton, Owner Type Committee Type Type Type Type Type Type Type Ty	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021391
Mixed, multiple owners Agglomerate enclosure and 15 stone hut circles 560 metres west of Cawsand Beacon, South Tawton, V Devon Scheduled Monument Strikame Agglomerate enclosure and ten stone hut circles 500 metres west of Cawsand Beacon, South Tawton, Devon South Title Crown Agglomerate enclosure and ten stone hut circles 500 metres west of Cawsand Beacon, South Tawton, Devon Scheduled Monument	CONDITION:		TREND:	Stable
Agglomerate enclosure and 15 stone hut circles 560 metres west of Cawsand Beacon, South Tawton, No Devon Scheduled Monument UST DATHY NUMBER: 1010791 CONDITION Generally satisfactory but with significant localised problems PRINCIPLY VILLAGE AND CONTACT: Andy Crabb 01626 832093 ATE NAME: Agglomerate enclosure and ten stone hut circles 500 metres west of Cawsand Beacon, South Tawton, Devon DEVIONATION Scheduled Monument UST ENTRY NUMBER: 1010790 CONDITION: Generally satisfactory but with significant localised problems PRINCIPLY VILLAGEABUTY: No CONDITION: Generally satisfactory but with significant localised problems PRINCIPLY VILLAGEABUTY: No CONDITION: Crown CONDITION: Andy Crabb 01626 832093 ATE NAME: An agglomerated enclosed settlement 480 metres west of Stoneyhurst, South Tawton, West Devon CONDITION: Scheduled Monument UST ENTRY NUMBER: 1017285 CONDITION: Crown CONDITION: Declining PRINCIPLY VILLAGEABUTY: No CONDITION: Declining PRINCIPLY VILLAGEABUTY: No CONDITION: Crown CONDITION: Crown CONDITION: Declining PRINCIPLY VILLAGEABUTY: No CONDITION: Crown CONDITION: Declining PRINCIPLY VILLAGEABUTY: No CONDITION: Crown CO	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
Devon Scheduled Monument Generally satisfactory but with significant localised problems Plant growth Andy Crabb 01626 832093 STE NAME: Agglomerate enclosure and ten stone but circles 500 metres west of Cawsand Beacon, South Tawton, Devon Designations Scheduled Monument Ust ENTRY NUMBER 1010790 Declining Plant growth Scheduled Monument Generally satisfactory but with significant localised problems Plant growth An agglomerated enclosed settlement 480 metres west of Cawsand Beacon, South Tawton, Devon STE NAME: An agglomerated enclosed settlement 480 metres west of Stoneyhurst, South Tawton, West Devon Generally satisfactory but with significant localised problems Plant growth An agglomerated enclosed settlement 480 metres west of Stoneyhurst, South Tawton, West Devon Beackarlone Generally satisfactory but with significant localised problems Plant growth Plant growth Plant growth Aprehistoric settlement complex, length of reave, tin streamwork and stamping mill on the western skeeping of the problems Scheduled Monument Aprehistoric settlement complex, length of reave, tin streamwork and stamping mill on the western skeeping of the problems Scheduled Monument Aprehistoric settlement complex, length of reave, tin streamwork and stamping mill on the western skeeping of the problems Scheduled Monument Aprehistoric settlement complex, length of reave, tin streamwork and stamping mill on the western skeeping of the problems Scheduled Monument Aprehistoric settlement complex, length of reave, tin streamwork and stamping mill on the western skeeping of the problems Scheduled Monument Condition Condition Condition Scheduled Monument Bis ENIRY NUMBER 1018916 Condition Condition Scheduled Monument Iss ENIRY NUMBER 1018916 Condition Plant growth New ENIRY: No Condition Condition Condition Condition Condition Plant growth No Condition No Condition	OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
CONDITION: Generally satisfactory but with significant localised problems PRINCIPLA VILLIERABUTY: Plant growth Andy Crabb 01626 832093 STE-NAME: Agglomerate enclosure and ten stone hut circles 500 metres west of Cawsand Beacon, South Tawton, Devon Designation: Scheduled Monument CONDITION: Generally satisfactory but with significant localised problems PRINCIPLA VILLIERABUTY: Plant growth An agglomerated enclosed settlement 480 metres west of Cawsand Beacon, South Tawton, Deciding Problems STE-NAME: An agglomerated enclosed settlement 480 metres west of Stoneyhurst. South Tawton, West Devon DESIGNATION: Scheduled Monument INTERIOR: No CONTACT: Andy Crabb 01626 832093 STE-NAME: An agglomerated enclosed settlement 480 metres west of Stoneyhurst. South Tawton, West Devon DESIGNATION: Scheduled Monument INTERIOR: Decilining PRINCIPLA VILLIERABUTY: Plant growth No CONTACT: Andy Crabb 01626 832093 TREND: Decilining PRINCIPLA VILLIERABUTY: Plant growth No CONTACT: Andy Crabb 01626 832093 TREND: Decilining PRINCIPLA VILLIERABUTY: Plant growth No CONTACT: Andy Crabb 01626 832093 TREND: Decilining PRINCIPLA VILLIERABUTY: Plant growth No CONTACT: Andy Crabb 01626 832093 TREND: Decilining PRINCIPLA VILLIERABUTY: Plant growth No CONNERTYPE: Crown CONTACT: Andy Crabb 01626 832093 TREND: Decilining PRINCIPLA VILLIERABUTY: Plant growth No CONNERTYPE: Crown CONTACT: Andy Crabb 01626 832093 TREND: Decilining Principla VILLIERABUTY: Plant growth No CONNERTYPE: Convince and ten stone hut circles 500 metres west of Cawsand Beacon, South Tawton, / No CONTACT: Andy Crabb 01626 832093 TREND: Decilining Principla VILLIERABUTY: Plant growth No CONTACT: Andy Crabb 01626 832093 TREND: Decilining Principla VILLIERABUTY: Plant growth No CONTACT: Andy Crabb 01626 832093 TREND: Decilining Principla VILLIERABUTY: Plant growth No CONTACT: Andy Crabb 01626 832093 TREND: Decilining Principla VILLIERABUTY: Plant growth No CONTACT: Andy Crabb 01626 832093 Decilining Principla VILLIERABUT	SITE NAME:		0 metres west of C	Cawsand Beacon, South Tawton, West
Problems Problems Problems Principle Vulnemability: Plant growth Plant	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010791
OWNER TYPE: Crown Agglomerate enclosure and ten stone hut circles 500 metres west of Cawsand Beacon, South Tawton, Description Scheduled Monument Scheduled Monument Scheduled Monument CONTACT: Andy Crabb 01626 832093 Declining PRINCE AND CONTACT: Andy Crabb 01626 832093 BERNORAL VILINERABILITY: Plant growth Andy Crabb 01626 832093 BERNORAL VILINERABILITY: Plant growth Andy Crabb 01626 832093 Andy Crabb 01626 832093 Andy Crabb 01626 832093 BERNORAL VILINERABILITY: Crown CONTACT: Andy Crabb 01626 832093 Andy Crabb 01626 832093 Andy Crabb 01626 832093 BERNORAL VILINERABILITY: Crown CONTACT: Andy Crabb 01626 832093 BERNORAL VILINERABILITY: Plant growth AND CRABB 01626 832093 BERNORAL VILINERABILITY: Plant growth A Length of the Great Western Reave, a prehistoric settlement, three cairns and two field systems on Walkhampton, West Devon BERNORAL VILINERABILITY: Plant growth A Length of the Great Western Reave, a prehistoric settlement, three cairns and two field systems on Walkhampton, West Devon BERNORAL VILINERABILITY: Plant growth AND C	CONDITION:		TREND:	Declining
Agglomerate enclosure and ten stone hut circles 500 metres west of Cawsand Beacon, South Tawton, Devon BESCHATION: Scheduled Monument Scheduled	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
Devon DESIGNATION: Scheduled Monument UST ENTRY NUMBER 1010790 Declining PRENCIPAL WAINERABILITY: Plant growth An agglomerated enclosed settlement 480 metres west of Stoneyhurst, South Tawton, West Devon DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1017.285 SCHEDULED MONUMENTIPE: Plant growth An agglomerated enclosed settlement 480 metres west of Stoneyhurst, South Tawton, West Devon DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1017.285 Declining PRENCIPAL WAINERABILITY: Plant growth NEW ENTRY: No OWNER TYPE: Crown CONTACT: Andy Crabb 01626 832093 STE NAME: A prehistoric settlement complex, length of reave, tin streamwork and stamping mill on the western sk Cosdon Hill, South Tawton / Dartmoor Forest, West Devon DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1015760 DECLINING SCHEDISCHATION: Scheduled Monument UST ENTRY NUMBER: 1015760 TREND: Declining PRENCIPAL WAINERABILITY: Plant growth with significant localised problems PRENCIPAL WAINERABILITY: Plant growth with significant localised problems STE NAME: Coaxial field system, associated and later remains at Throwleigh Common and Kennon Hill, Throwleigh Gidleigh, West Devon SCHEDURAL WAINERABILITY: Occurrence Contact: Andy Crabb 01626 832093 STE NAME: Coaxial field system, associated and later remains at Throwleigh Common and Kennon Hill, Throwleigh Gidleigh, West Devon DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1018916 CONDITION: Plant growth NEW ENTRY: No OWNER TYPE: NO OWN	OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093
CONDITION Generally satisfactory but with significant localised problems PRINCIPLE VULNERABILITY: Plant growth NEW ENTRY: No OWNER TYPE: Crown CONTACT: Andy Crabb 01626 832093 SITE NAME: An agglomerated enclosed settlement 480 metres west of Stoneyhurst, South Tawton, West Devon DESIGNATION: Scheduled Monument LEST ENTRY NUMBER: 1017285 CONDITION: Generally satisfactory but with significant localised problems PRINCIPLA VULNERABILITY: Plant growth NEW ENTRY: No CONTACT: Andy Crabb 01626 832093 SITE NAME: A prehistoric settlement complex, length of reave, tin streamwork and stamping mill on the western sle Cosdon Hill, South Tawton / Dartmoor Forest, West Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 101760 CONDITION Generally satisfactory but with significant localised problems PRINCIPLA VULNERABILITY: Plant growth OWNER TYPE: No CONTACT: Andy Crabb 01626 832093 SITE NAME: Cosail field system, associated and later remains at Throwleigh Common and Kennon Hill, Throwleigh Gidleigh, West Devon CONTACT: Andy Crabb 01626 832093 SITE NAME: Cosail field system, associated and later remains at Throwleigh Common and Kennon Hill, Throwleigh Gidleigh, West Devon CONTACT: Andy Crabb 01626 832093 SITE NAME: Cosail field system, associated and later remains at Throwleigh Common and Kennon Hill, Throwleigh Gidleigh, West Devon CONTACT: Andy Crabb 01626 832093 SITE NAME: Scheduled Monument LIST ENTRY NUMBER: 1018916 CONDITION: Plant growth NEW ENTRY: No OWNER TYPE: No OWNER TYPE: No OWNER TYPE: Mixed, multiple owners CONTACT: Andy Crabb 01626 832093 SITE NAME: A length of the Great Western Reave, a prehistoric settlement, three cairns and two field systems on Walkhampton Common, Walkhampton, West Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1019589 Generally satisfactory but with significant localised problems PRINCIPLA VULNERABILITY: Plant growth NEW ENTRY: No	SITE NAME:		00 metres west of	Cawsand Beacon, South Tawton, West
PRINCIPAL VULNERABILITY: Plant growth NEW ENTRYP: No CONTACT: Andy Crabb 01626 832093 STIE NAME: An agglomerated enclosed settlement 480 metres west of Stoneyhurst, South Tawton, West Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017285 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRYP: No CONTACT: Andy Crabb 01626 832093 STIE NAME: A prehistoric settlement complex, length of reave, tin streamwork and stamping mill on the western skeep of the contact of	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010790
OWNER TYPE Crown Conditions	CONDITION:		TREND:	Declining
An agglomerated enclosed settlement 480 metres west of Stoneyhurst, South Tawton, West Devon DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1017285 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY!: No OWNER TYPE: Crown CONTACT: Andy Crabb 01626 832093 SITE NAME: A prehistoric settlement complex, length of reave, tin streamwork and stamping mill on the western slot Cosdon Hill, South Tawton / Dartmoor Forest, West Devon DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1015760 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No OWNER TYPE: Crown CONTACT: Andy Crabb 01626 832093 SITE NAME: Goaxial field system, associated and later remains at Throwleigh Common and Kennon Hill, Throwleigh Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1018916 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY!: No OWNER TYPE: Mixed, multiple owners CONTACT: Andy Crabb 01626 832093 SITE NAME: A length of the Great Western Reave, a prehistoric settlement, three cairns and two field systems on Walkhampton Common, Walkhampton, West Devon DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1019589 SITE NAME: A length of the Great Western Reave, a prehistoric settlement, three cairns and two field systems on Walkhampton Common, Walkhampton, West Devon DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1019589 Declining PRINCIPAL VULNERABILITY: Declining PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No Declining PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1017285 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRYP: No OWNER TYPE: Crown CONTACT: Andy Crabb 01626 832093 SITE NAME: A prehistoric settlement complex, length of reave, tin streamwork and stamping mill on the western sk Cosdon Hill, South Tawton / Dartmoor Forest, West Devon DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1015760 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRYP: No OWNER TYPE: Crown CONTACT: Andy Crabb 01626 832093 SITE NAME: Coaxial field system, associated and later remains at Throwleigh Common and Kennon Hill, Throwleigh Gidleigh, West Devon DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1018916 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: No OWNER TYPE: No OWNER TYPE: No A length of the Great Western Reave, a prehistoric settlement, three cairns and two field systems on Walkhampton Common, Walkhampton, West Devon DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1019589 STIE NAME: A length of the Great Western Reave, a prehistoric settlement, three cairns and two field systems on Walkhampton Common, Walkhampton, West Devon DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1019589 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth UST ENTRY NUMBER: 1019589 CONDITION: Plant growth UST ENTRY NUMBER: 1019589 CONDITION: Plant growth NEW ENTRYP: No	OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093
Designation: Scheduled Monument UST ENTRY NUMBER: 1017285 CONDITION: Generally satisfactory but with significant localised problems Plant growth NEWENTRY: No OWNER TYPE: Crown CONTACT: Andy Crabb 01626 832093 SITE NAME: A prehistoric settlement complex, length of reave, tin streamwork and stamping mill on the western skeepeng of the streamwork of the streamwork of the western skeepeng of the streamwork of the str	SITE NAME:	An agglomerated enclosed settlement 480 metres west of Stoneyhurst, South Tawton, West Devon		
PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No OWNER TYPE: Crown CONTACT: Andy Crabb 01626 832093 SITE NAME: A prehistoric settlement complex, length of reave, tin streamwork and stamping mill on the western skeepen state of the contact of	DESIGNATION:			
OWNER TYPE: Crown CONTACT: Andy Crabb 01626 832093 SITE NAME: A prehistoric settlement complex, length of reave, tin streamwork and stamping mill on the western slocosdon Hill, South Tawton / Dartmoor Forest, West Devon DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1015760 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No OWNER TYPE: Crown CONTACT: Andy Crabb 01626 832093 SITE NAME: Coaxial field system, associated and later remains at Throwleigh Common and Kennon Hill, Throwleigh Gidleigh, West Devon DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1018916 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No OWNER TYPE: Mixed, multiple owners CONTACT: Andy Crabb 01626 832093 SITE NAME: A length of the Great Western Reave, a prehistoric settlement, three cairns and two field systems on Walkhampton Common, Walkhampton, West Devon DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1019589 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth New Entry: No Declining PRINCIPAL VULNERABILITY: Plant growth New Entry: No Period Trend: UST ENTRY NUMBER: 1019589 CONDITION: Scheduled Monument UST ENTRY NUMBER: 1019589 CONDITION: Plant growth NEW ENTRY: No Period Trend: Declining PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No	CONDITION:		TREND:	Declining
A prehistoric settlement complex, length of reave, tin streamwork and stamping mill on the western slocosdon Hill, South Tawton / Dartmoor Forest, West Devon DESIGNATION: Scheduled Monument	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
Cosdon Hill, South Tawton / Dartmoor Forest, West Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015760 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No OWNER TYPE: Crown CONTACT: Andy Crabb 01626 832093 SITE NAME: Coaxial field system, associated and later remains at Throwleigh Common and Kennon Hill, Throwleigh Gidleigh, West Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1018916 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth Mixed, multiple owners A length of the Great Western Reave, a prehistoric settlement, three cairns and two field systems on Walkhampton Common, Walkhampton, West Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1019589 CONDITION: Generally satisfactory but with significant localised problems Scheduled Monument LIST ENTRY NUMBER: 1019589 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY): No	OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093
CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth COWNER TYPE: Crown CONTACT: No CONTACT: Andy Crabb 01626 832093 SITE NAME: Coaxial field system, associated and later remains at Throwleigh Common and Kennon Hill, Throwleigh Gidleigh, West Devon DESIGNATION: Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth Mixed, multiple owners A length of the Great Western Reave, a prehistoric settlement, three cairns and two field systems on Walkhampton Common, Walkhampton, West Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1019589 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: NO DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1019589 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No	SITE NAME:	A prehistoric settlement complex, length of reave, tin streamwork and stamping mill on the western slopes cosdon Hill, South Tawton / Dartmoor Forest, West Devon		
PRINCIPAL VULNERABILITY: Plant growth Principal vulnerability: Plant growth Principal vulnerability: Plant growth Plant growth Plant growth Plant growth Plant growth Plant growth Contact: Andy Crabb 01626 832093 SITE NAME: Coaxial field system, associated and later remains at Throwleigh Common and Kennon Hill, Throwleigh Gidleigh, West Devon Designation: Scheduled Monument LIST ENTRY NUMBER: Plant growth New ENTRY?: No OWNER TYPE: Mixed, multiple owners Allength of the Great Western Reave, a prehistoric settlement, three cairns and two field systems on Walkhampton Common, Walkhampton, West Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: Declining PRINCIPAL VULNERABILITY: Plant growth New ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015760
OWNER TYPE: Crown Coaxial field system, associated and later remains at Throwleigh Common and Kennon Hill, Throwleigh Gidleigh, West Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: IO18916 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth Mixed, multiple owners Alength of the Great Western Reave, a prehistoric settlement, three cairns and two field systems on Walkhampton Common, Walkhampton, West Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: IO18916 CONTACT: Andy Crabb 01626 832093 SITE NAME: Alength of the Great Western Reave, a prehistoric settlement, three cairns and two field systems on Walkhampton Common, Walkhampton, West Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: IO19589 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth New ENTRY: No	CONDITION:		TREND:	Declining
Coaxial field system, associated and later remains at Throwleigh Common and Kennon Hill, Throwleigh Gidleigh, West Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1018916 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No OWNER TYPE: Mixed, multiple owners CONTACT: Andy Crabb 01626 832093 SITE NAME: A length of the Great Western Reave, a prehistoric settlement, three cairns and two field systems on Walkhampton Common, Walkhampton, West Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1019589 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
Gidleigh, West Devon DESIGNATION: Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth Mixed, multiple owners A length of the Great Western Reave, a prehistoric settlement, three cairns and two field systems on Walkhampton Common, Walkhampton, West Devon DESIGNATION: Scheduled Monument CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth New ENTRY?: No Declining Declining	OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093
Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth Mixed, multiple owners A length of the Great Western Reave, a prehistoric settlement, three cairns and two field systems on Walkhampton Common, Walkhampton, West Devorbesional Scheduled Monument CONDITION: Scheduled Monument Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth TREND: Declining Declining New ENTRY?: No	SITE NAME:		at Throwleigh Com	mon and Kennon Hill, Throwleigh /
problems problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No OWNER TYPE: Mixed, multiple owners A length of the Great Western Reave, a prehistoric settlement, three cairns and two field systems on Walkhampton Common, Walkhampton, West Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1019589 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018916
Mixed, multiple owners CONTACT: Andy Crabb 01626 832093 A length of the Great Western Reave, a prehistoric settlement, three cairns and two field systems on Walkhampton Common, Walkhampton, West Devon DESIGNATION: Scheduled Monument CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth CONTACT: Andy Crabb 01626 832093 LIST ENTRY NUMBER: 1019589 TREND: Declining NEW ENTRY?: No	CONDITION:		TREND:	Declining
A length of the Great Western Reave, a prehistoric settlement, three cairns and two field systems on Walkhampton Common, Walkhampton, West Devorbesing Nation: Scheduled Monument CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth A length of the Great Western Reave, a prehistoric settlement, three cairns and two field systems on Walkhampton, West Devorbes I 019589 TREND: Declining New Entry: No	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
Walkhampton Common, Walkhampton, West Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1019589 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth New ENTRY?: No	OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth Generally satisfactory but with significant localised problems NEW ENTRY?: No	SITE NAME:	A length of the Great Western Reave, a prehistori Walkhampton Common, Walkhampton, West Dev	c settlement, three	cairns and two field systems on
problems PRINCIPAL VULNERABILITY: Plant growth New entry?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019589
-	CONDITION:		TREND:	Declining
OWNER TYPE: Private CONTACT: Andy Crabb 01626 832093	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
	OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

SITE NAME:	An enclosed stone hut circle settlement and later to Tor, Walkhampton, West Devon	in working cardiw	orks, 5 to med es soudi east of Down
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009088
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	An enclosure, attached stone hut circle and length West Devon	of reave 180 metro	es NNE of Leather Tor, Walkhampto
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011248
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	An enclosure containing one stone hut circle 460 r	metres west of Cro	oss Gate, Walkhampton, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009091
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	An enclosure, six stone hut circles, a length of reave and several prospecting pits 170 metres north east c Leather Tor, Walkhampton, West Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011247
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Eleven stone hut circles, a length of boundary wall settlement on the north east slope of Sharpitor, W		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007435
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Enclosure and stone hut circle 320 metres north e settlement, Walkhampton, West Devon	ast of Sharpitor for	rming part of a stone hut circle
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007434
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Enclosure and stone hut circle 700 metres west of	Sharpitor, Walkha	mpton, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019590
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Medieval settlement on Peek Hill, 240 metres and West Devon	280 metres north 6	east of Lowery Tor, Walkhampton,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020237
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Prehistoric coaxial field system and cairns, an histoaround Peek Hill, Walkhampton, West Devon	oric enclosure and p	part of RAF Sharpitor, situated on and
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020238
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Round cairn 340 metres ESE of Norsworthy Bridg	e, Walkhampton, V	Vest Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008651
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Stone alignment, two round cairns and a length of Sharpitor and Leeden Tor, Walkhampton, West D	Walkhampton Con Devon	nmon reave lying in a valley between
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007433
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Stone hut circle 155 metres east of Sharpitor, Walkhampton, West Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007421
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (non-heritage)	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Stone hut circle 240 metres south of Down Tor, V	Walkhampton, Wes	t Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008641
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Stone hut circle 315 metres north east of Sharpitor forming part of a stone hut circle settlement, Walkhampton, West Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007436
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Stone hut circle 350 metres north east of Sharpito Walkhampton, West Devon	r torming part of a	stone hut circle settlement,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007437
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Stone hut circle 370 metres north east of Sharpito Walkhampton, West Devon	r forming part of a	stone hut circle settlement,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007438
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093
ITE NAME:	Stone hut circle settlement 250 metres east of Cuc	koo Rock, Walkha	mpton, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021057
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093
ITE NAME:	Stone hut circle settlement, irregular aggregate fiel medieval field system 700 metres SSW of Black To	d system, two long r, Walkhampton, V	houses and a medieval and post- Vest Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011170
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093
ITE NAME:	Tinworks and other archaeological remains in the l Tor, Walkhampton, West Devon	Meavy valley at Star	nlake, Black Tor, Hart Tor and Cramb
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020129
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093
ITE NAME:	Two stone hut circles 570 metres south west of D	own Tor, Walkham	npton, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019572
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093
ITE NAME:	Two stone hut circles, a reave, round cairn and she	elter south east of S	Sharpitor, Walkhampton, West Devo
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011167
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
	Di I	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Plant growth	INLAA EINIIKI:.	INO

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

SITE NAME:	Enclosure and stone hut circle 770 metres south of Cox Tor, Whitchurch, West Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020006
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Eluvial tin streamworks and prehistoric coaxial field system together with other archaeological remains on Whitchurch Common, Whitchurch / Peter Tavy / Sampford Spiney, West Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020089
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
	•		

EAST DEVON



© Historic England Archive

SITE NAME:	Weycroft Manor and Weycroft Well House, Axminster
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Unknown
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Private

LIST ENTRY NUMBER: 1162537

Circa C16 and possibly earlier, coursed stone with shingle roof and coped gable ends. C18 interior stair and panelling and overmantle painting of hunting scene. Wing known as Well House has chamfered ceiling beams and fireplace bressumer with painting over first floor door. Fire in March 2020 has burnt through the roof with damage to the interior of both Weycroft Manor and Well House. As of May 2020 a temporary roof has been installed to protect the building.

Former parish church, latterly a chapel of ease, and now closed for worship. Dates mainly from late C15. Interior

Contact: Rhiannon Rhys 0117 975 0685



© Historic England

SITE NAME:	Church of St Michael, Honiton
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1306112

destroyed by fire and rebuilt 1912. Metal corroding internally in arcaded capital heads. Leaking due to blocked valley gutters. The church was closed and, in early 2019, was handed to the Diocesan Board of Finance which has since arranged for urgent repairs to be undertaken. Historic England is in discussion with the diocese regarding the future of the building.

Contact: Annie Evans 0117 975 0673



© Historic England

SITE NAME:	Poltimore House, Poltimore
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1098310

C16 country house with later additions. Acquired by a trust with funding from Historic England and the Local Planning Authority in 1997. Urgent works carried out in 1998 to make the building wind/weathertight. Emergency roof cover erected 2006. A feasibility study was undertaken in 2007 with grant-aid from the Architectural Heritage Fund and Historic England. Historic England is offering grant aid and further technical advice to the trust to undertake incremental repairs and project development for the house.

Contact: John Ette 0117 975 0687

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Stable block at Bishop's Court, Clyst St Mary, Sowton
DESIGNATION:	Listed Building grade I
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1333998

Long early C16 range of stables attached to Bishop's Court tithe barn. Site is not in use. Historic England funded a feasibility study, which was completed in 2011.

Contact: Sarah Ball 0117 975 0666



SITE NAME: Tithe barn at Bishop's Court, Clyst St Mary, Sowton DESIGNATION: Listed Building grade I CONDITION: Very bad OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Private

seven bays, and long early C16 range of stables. The site is unused with a temporary corrugated roof. The owners undertook a Historic England grant-aided feasibility study into potential uses, completed 2011.

Large mid-C14 barn with arch-braced base-cruck roof of

LIST ENTRY NUMBER: Contact: Sarah Ball 0117 975 0666 1164637 © Historic England



Church of St Michael and All SITE NAME: Angels, Awliscombe DESIGNATION: Listed Place of Worship grade I CONDITION: Poor PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1098097

Parish church. Largely late C15/early C16, mostly rebuilt in 1846 by Robert Medley Fulford. Mostly local flint with Beerstone dressings and a slate roof. Medieval and C19 features. Tower roof and valley gutter in a poor condition. Some other minor areas of concern.

Contact: Annie Evans 0117 975 0673

© Historic England



© Historic England

SITE NAME:	Church of Holy Trinity, Dunkeswell
DESIGNATION:	Listed Place of Worship grade II, SM
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1308999

Parish church, built on the site of Dunkeswell Abbey Church in 1842. Local stone and flint rubble with Hamstone dressings and detail and a slate roof. The roofs have had substantial leaks which have caused significant water ingress. This has damaged the internal plaster. The congregation reroofed the church in 2015, but considerable interior work is still required and glazing is also in poor condition. Discussions over the future of the church are continuing with the Dunkeswell Abbey Preservation Trust and a new trust being formed for the church.

Contact: Annie Evans 0117 975 0673



© Historic England

SITE NAME:	Church of St Paul, High Street, Honiton
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1116954

Parish church. Completed 1838 by architect Charles Fowler. Romanesque style with apse. Seven bays with round-arched aisle and clerestorey windows. Galleries. Restored 1849. Stone and plaster falling internally. Beerstone hoodmoulds aremade of cement on nails which is causing decay problems. Windows are in need of repair and there are cracks in the tower.

Contact: Annie Evans 0117 975 0673

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBR	EVIATIONS
CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garde
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

HERITAGE AT RISK 2020 / SOC	JIH WESI / EAST DEVON		
SITE NAME:	Newenham Abbey, Axminster		
DESIGNATION:	Scheduled Monument, 3 LBs	LIST ENTRY NUMBER:	1011671
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Hawkesdown Camp and associated outwork, Axmo	outh	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017775
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	The Axe Boat, 22 metres north of the Axmouth Ro	oad Bridge, Axmou	ith
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1433819
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 210 metres north east of Starved Oak Cross, Brampford Speke		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010633
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow in Long Plantation, 610 metres north	east of Starved Oa	ık Cross, Brampford Speke
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1010636
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow in Long Plantation, 680 metres north	east of Starved Oa	ık Cross, Brampford Speke
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010634
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 320 metres north east of Starved Oak Cross, Brampford Speke / Upton Pyne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010632
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Dunkeswell Abbey, Dunkeswell		
DESIGNATION:	Scheduled Monument and Listed Building grade II, 3 LBs	LIST ENTRY NUMBER:	1009303 and 1098253
CONDITION:	Extensive significant problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Charlotte Russell 01271 831505

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017949 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Forestry Mixed, multiple owners CONTACT: Charlotte Russell 01271 83150 STIE NAME: Round barrow cemetery on Broad Down, Farway / Southleigh DESIGNATION: Scheduled Monument Extensive significant problems PRINCIPAL VULNERABILITY: Deterioration - in need of management OWNER TYPE: Mixed, multiple owners CONTACT: Charlotte Russell 01271 83150 STIE NAME: Round barrow 460 metres NNW of Ring-in-the-Mire, forming part of a round barrow cemetery on Gittisham Hill, Gittisham DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014248 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth OWNER TYPE: Private A bowl barrow 500 metres WNW of Ring-in-the-Mire, forming part of a round barrow cemetery on Gittisham Hill, Gittisham DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014248 Declining PRINCIPAL VULNERABILITY: Plant growth NIEW ENTRY: No CONTACT: Charlotte Russell 01271 83150 CONTACT: Charlotte Russell 01271 83150 CONTACT: Charlotte Russell 01271 83150 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014250 DECLINING PRINCIPAL VULNERABILITY: Plant growth NIEW ENTRY: No CONTACT: Charlotte Russell 01271 83150 CONTACT: Charlotte Russell 01271 83150
Problems Problems Problems Procestry Mixed, multiple owners Contact: Charlotte Russell 01271 83150 Designation: Scheduled Monument Extensive significant problems Prencipal vulnerability: Deterioration - in need of management A bowl barrow 460 metres NNW of Ring-in-the-Mire, forming part of a round barrow cemetery on Gittisham Hill, Gittisham Condition: Scheduled Monument List entry number: 1017642 Contact: Charlotte Russell 01271 83150 Contact: Charlotte Russell 01271
Mixed, multiple owners CONTACT: Charlotte Russell 01271 83150 TRENDE Scheduled Monument Extensive significant problems RIRCIPAL VULNERABILITY: Deterioration - in need of management Mixed, multiple owners CONTACT: Charlotte Russell 01271 83150 Mixed, multiple owners CONTACT: Charlotte Russell 01271 83150 Mixed, multiple owners CONTACT: Charlotte Russell 01271 83150 Contact: Charlotte Russell 01271 83150 Contact: Charlotte Russell 01271 83150 Charlotte Russell 01271 83150 Charlotte Russell 01271 83150 Contact: Charlotte Russell 01271 83150 Contact: Charlotte Russell 01271 83150
Round barrow cemetery on Broad Down, Farway / Southleigh DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017642 Extensive significant problems TREND: Improving PRINCIPAL VULNERABILITY: Deterioration - in need of management NEW ENTRY!: No DOWNER TYPE: Mixed, multiple owners CONTACT: Charlotte Russell 01271 83150 SITE NAME: A bowl barrow 460 metres NNW of Ring-in-the-Mire, forming part of a round barrow cemetery on Gittisham Hill, Gittisham DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014248 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY!: No DOWNER TYPE: Private CONTACT: Charlotte Russell 01271 83150 SITE NAME: A bowl barrow 500 metres WNW of Ring-in-the-Mire, forming part of a round barrow cemetery on Gittisham Hill, Gittisham DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014250 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014250 EXTENDIFION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY!: No DOWNER TYPE: Private CONTACT: Charlotte Russell 01271 83150 SCHEDULTION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY!: No DOWNER TYPE: Private CONTACT: Charlotte Russell 01271 83150 STIE NAME: A bowl barrow 570 metres NNE of Putts Corner, forming part of a round barrow cemetery on Gittle Hill, Gittisham DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014254 TREND: Declining DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014254 TREND: Declining DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014254 TREND: Declining
Designation: Scheduled Monument LIST ENTRY NUMBER: 1017642 CONDITION: Extensive significant problems TREND: Improving PRINCIPAL VULNERABILITY: Deterioration - in need of management NEW ENTRY: No DWNER TYPE: Mixed, multiple owners CONTACT: Charlotte Russell 01271 83150 DWNER TYPE: A bowl barrow 460 metres NNW of Ring-in-the-Mire, forming part of a round barrow cemetery on Gittisham Hill, Gittisham DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014248 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No DWNER TYPE: Private CONTACT: Charlotte Russell 01271 83150 STEENAME: A bowl barrow 500 metres WNW of Ring-in-the-Mire, forming part of a round barrow cemetery on Gittisham Hill, Gittisham DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014250 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No DWNER TYPE: Private CONTACT: Charlotte Russell 01271 83150 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014250 DEVENTION: Private CONTACT: Charlotte Russell 01271 83150 DEVENTION: Scheduled Monument LIST ENTRY NUMBER: 1014254 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014254 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014254 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014254 CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1014254 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014254
Extensive significant problems TREND: Improving PRINCIPAL VULNERABILITY: Deterioration - in need of management NEW ENTRY?: No DWNER TYPE: Mixed, multiple owners CONTACT: Charlotte Russell 01271 83150 SITE NAME: A bowl barrow 460 metres NNW of Ring-in-the-Mire, forming part of a round barrow cemetery on Gittisham Hill, Gittisham DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014248 CONDITION: Generally satisfactory but with significant localised problems Plant growth NEW ENTRY?: No DWNER TYPE: Private CONTACT: Charlotte Russell 01271 83150 SITE NAME: A bowl barrow 500 metres WNW of Ring-in-the-Mire, forming part of a round barrow cemetery on Gittisham Hill, Gittisham DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014250 Extensive significant problems TREND: Declining Plant growth NEW ENTRY?: No DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014250 Extensive significant problems TREND: Declining Plant growth NEW ENTRY?: No DWNER TYPE: Private CONTACT: Charlotte Russell 01271 83150 GENICIPAL VULNERABILITY: Plant growth NEW ENTRY?: No DWNER TYPE: Private CONTACT: Charlotte Russell 01271 83150 SITE NAME: A bowl barrow 570 metres NNE of Putts Corner, forming part of a round barrow cemetery on Gittisham ESTENAME: A bowl barrow 570 metres NNE of Putts Corner, forming part of a round barrow cemetery on Gittisham ESTENAME: A bowl barrow 570 metres NNE of Putts Corner, forming part of a round barrow cemetery on Gittisham DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014254 CONDITION: Declining
Deterioration - in need of management NEW ENTRYY: No Deterioration - in need of management NEW ENTRYY: No CONTACT: Charlotte Russell 01271 83150 SITE NAME: A bowl barrow 460 metres NNW of Ring-in-the-Mire, forming part of a round barrow cemetery on Gittisham Hill, Gittisham DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: LIST ENTRY NUMBER: 1014248 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No CONTACT: Charlotte Russell 01271 83150 SITE NAME: A bowl barrow 500 metres WNW of Ring-in-the-Mire, forming part of a round barrow cemetery on Gittisham Hill, Gittisham DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014250 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Plant growth No OWNER TYPE: Private CONTACT: Charlotte Russell 01271 83150 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Plant growth No OWNER TYPE: Private CONTACT: Charlotte Russell 01271 83150 CONTACT: Charlotte Russell 01271 83150 EXTEND: DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014254 CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1014254 CONDITION: DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014254
Mixed, multiple owners CONTACT: Charlotte Russell 01271 83150 SITE NAME: A bowl barrow 460 metres NNW of Ring-in-the-Mire, forming part of a round barrow cemetery on Gittisham Hill, Gittisham DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014248 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY): No DOWNER TYPE: Private CONTACT: Charlotte Russell 01271 83150 SITE NAME: A bowl barrow 500 metres WNW of Ring-in-the-Mire, forming part of a round barrow cemetery on Gittisham Hill, Gittisham DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014250 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Plant growth NO DOWNER TYPE: Private CONTACT: Charlotte Russell 01271 83150 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Plant growth NO DOWNER TYPE: Private CONTACT: Charlotte Russell 01271 83150 SITE NAME: A bowl barrow 570 metres NNE of Putts Corner, forming part of a round barrow cemetery on Gittisham DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014254 CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1014254 CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1014254
A bowl barrow 460 metres NNW of Ring-in-the-Mire, forming part of a round barrow cemetery on Gittisham Hill, Gittisham DESIGNATION: Scheduled Monument Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth New Entry: No OWNER TYPE: Private CONTACT: Charlotte Russell 01271 83150 CONTACT: Charlotte Russell 01271 83150 CONDITION: Scheduled Monument LIST ENTRY NUMBER: A bowl barrow 500 metres WNW of Ring-in-the-Mire, forming part of a round barrow cemetery on Gittisham Hill, Gittisham DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014250 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No OWNER TYPE: Private CONTACT: Charlotte Russell 01271 83150
Gittisham Hill, Gittisham DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014248 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth Deventury: No CONTACT: Charlotte Russell 01271 83150 SITE NAME: A bowl barrow 500 metres WNW of Ring-in-the-Mire, forming part of a round barrow cemetery on Gittisham Hill, Gittisham DESIGNATION: Scheduled Monument Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: No Deventury: No De
Generally satisfactory but with significant localised problems Plant growth Plant growth Private CONTACT: Charlotte Russell 01271 83150 A bowl barrow 500 metres WNW of Ring-in-the-Mire, forming part of a round barrow cemetery on Gittisham Hill, Gittisham Scheduled Monument LIST ENTRY NUMBER: CONTACT: Charlotte Russell 01271 83150 LIST ENTRY NUMBER: 1014250 CONDITION: Extensive significant problems Plant growth NEW ENTRY?: No CONTACT: Charlotte Russell 01271 83150
problems Principal Yulnerability: Plant growth New Entry?: No CONTACT: Charlotte Russell 01271 83150 Site Name: A bowl barrow 500 metres WNW of Ring-in-the-Mire, forming part of a round barrow cemetery on Gittisham Hill, Gittisham Designation: Scheduled Monument Extensive significant problems Principal Yulnerability: Plant growth Dewner type: Private CONTACT: Charlotte Russell 01271 83150 CONDITION: Contact: Charlotte Russell 01271 83150 CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1014254 CONDITION: Contact: Declining CONDITION: Declining CONDITION: Declining
A bowl barrow 500 metres WNW of Ring-in-the-Mire, forming part of a round barrow cemetery on Gittisham Hill, Gittisham DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014250 Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No DWNER TYPE: Private CONTACT: Charlotte Russell 01271 83150 A bowl barrow 570 metres NNE of Putts Corner, forming part of a round barrow cemetery on Gittis Hill, Gittisham DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014254 Generally unsatisfactory with major localised TREND: Declining
A bowl barrow 500 metres WNW of Ring-in-the-Mire, forming part of a round barrow cemetery on Gittisham Hill, Gittisham DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014250 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No DWNER TYPE: Private CONTACT: Charlotte Russell 01271 83150 GITE NAME: A bowl barrow 570 metres NNE of Putts Corner, forming part of a round barrow cemetery on Gittis Hill, Gittisham DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014254 Generally unsatisfactory with major localised TREND: Declining
Gittisham Hill, Gittisham DESIGNATION: Scheduled Monument DESIGNATION: Scheduled Monument Extensive significant problems PRINCIPAL VULNERABILITY: Plant growth Private Declining NEW ENTRY?: No CONTACT: Charlotte Russell 01271 83150 SITE NAME: A bowl barrow 570 metres NNE of Putts Corner, forming part of a round barrow cemetery on Gittis Hill, Gittisham DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014254 Generally unsatisfactory with major localised TREND: Declining
Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Plant growth Private CONTACT: Charlotte Russell 01271 83150 SITE NAME: A bowl barrow 570 metres NNE of Putts Corner, forming part of a round barrow cemetery on Gittis Hill, Gittisham DESIGNATION: Scheduled Monument CONDITION: Declining TREND: Declining
Plant growth Private CONTACT: Charlotte Russell 01271 83150 Contact: Contact: Charlotte Russell 01271 83150 Contact: Charlotte Russell 01271 83150 Contact: Charlotte Russell 01271 83150 Contact:
A bowl barrow 570 metres NNE of Putts Corner, forming part of a round barrow cemetery on Gittis Hill, Gittisham Scheduled Monument CONTACT: Charlotte Russell 01271 83150 LIST ENTRY NUMBER: 1014254 CONDITION: Generally unsatisfactory with major localised TREND: Declining
A bowl barrow 570 metres NNE of Putts Corner, forming part of a round barrow cemetery on Gittis Hill, Gittisham DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014254 CONDITION: Generally unsatisfactory with major localised TREND: Declining
Hill, Gittisham DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014254 Generally unsatisfactory with major localised TREND: Declining
Generally unsatisfactory with major localised TREND: Declining
PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No
OWNER TYPE: CONTACT: Charlotte Russell 01271 83150
A cairn 450 metres WNW of Putts Corner, forming part of a round barrow cemetery on Gittisham I Gittisham
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014255
Generally unsatisfactory with major localised TREND: Declining problems
PRINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY?: No
DWNER TYPE: Commercial company CONTACT: Charlotte Russell 01271 83150
A ring cairn and bowl barrow 54 metres NNE of Putts Corner, forming part of a round barrow ceme Gittisham Hill, Gittisham
Gittisham Hill, Gittisham
Gittisham Hill, Gittisham DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014253 Generally unsatisfactory with major localised TREND: Declining

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Scheduled Monument IRANDER INTO Declining Problems Proble	SITE NAME:	A bowl barrow 420 metres NNW of Ring-in-the Gittisham Hill, Gittisham / Honiton	e-rinie, iorining part o	a round barrow cemetery on
problems problems problems Scrub/tree growth Private CDMIACL Charlotte Russell 01271 831505 DECIMALL Membury Castle, Membury DEGMATION Scheduled Monument UST DYNAMES Decimal Russell 01271 831505 DECIMATION Scheduled Monument UST DYNAMES Decimal Russell 01271 831505 DECIMATION Scheduled Monument UST DYNAMES Decimal Russell 01271 831505 DECIMATION Scheduled Monument CONDOTONE Extensive significant problems TICHO DOWNET THE Mixed, multiple owners CONTACT Charlotte Russell 01271 831505 DECIMAL RUSSELL OF THE RUSSELL O1271 831505 DECIMAL R	designation:	Scheduled Monument	LIST ENTRY NUMBER:	1014247
Private Membury Castle, Membury Scheduled Monument UST DISTRYNUMBER: 1017951 Declining Mixed, multiple owners CONTACT: Charlotte Russell 01271 831505 Declining Mixed, multiple owners CONTACT: Charlotte Russell 01271 831505 Declining Mixed, multiple owners CONTACT: Charlotte Russell 01271 831505 Declining Declining Mixed, multiple owners CONTACT: Charlotte Russell 01271 831505 Declining Declining Mixed, multiple owners CONTACT: Charlotte Russell 01271 831505 Declining Dec	CONDITION:		TREND:	Declining
Membury Castle, Membury Scheduled Monument Extensive significant problems Plant growth Mixed, multiple owners CUSTACT: Cursus, long mortuary enclosure, ring ditch and other associated cropmarks 700 metres east of Netherexe Barton, Nether Exe Barton, Neth	PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
Designation Scheduled Monument Extensive significant problems Plant growth Mixed, multiple owners Contract: Charlotte Russell 01271 831505 Contract: Contract: Contract: Charlotte Russell 01271 831505 Contract: Contract: Charlotte Russell 01271 831505 Contract: Contract: Charlotte Russell 01271 831505 Contract: Contract: Contract: Contract: Charlotte Russell 01271 831505 Contract: Contract: Contract: Charlotte Russell 01271 831505 Contra	OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
Extensive significant problems IREND Declining Plant growth New BATTER: No DEMORATIVE Mixed, multiple owners Cursus, long mortuary enclosure, ring ditch and other associated cropmarks 700 metres east of Netherex Barton, Nether Exe DESIGNATION Scheduled Monument Extensive significant problems TREND: Declining RENDERSHIPM: No DEMORATIVE Private Two bowl barrows north of Green Lane, 430 metres and 330 metres west of Rewe Cross, Nether Exe DESIGNATION Scheduled Monument Extensive significant problems TREND: Declining RENDERSHIPM: No DEMORATIVE Arable ploughing New DATTER: No Declining RENDERSHIPM: No DEMORATIVE Arable ploughing New DATTER: No Declining RENDERSHIPM: No DEMORATIVE Private CONTACT: Charlotte Russell 01271 831505 DEMORATIVE Belbury Castle, Ottery St. Mary DESIGNATION Scheduled Monument UST ENTRY NUMBER: 1017774 DEMORATIVE Private CONTACT: Charlotte Russell 01271 831505 DEMORATIVE Private CONTACT: Charlotte Russell 01271 831505 DEMORATIVE Private Scrub/tree growth New PINTER: No DEMORATIVE Private Scrub/tree growth New PINTER: No DECINING DEMORATIVE Private Scrub/tree growth New PINTER: No Declining DEMORATIVE Private Scrub/tree growth New PINTER: No Declining DEMORATIVE Private Scrub/tree growth Mixed, multiple owners Declining DEMORATIVE Private Scrub-tree growth Mixed, multiple owners Declining DEMORATIVE Private, Multiple owners	SITE NAME:	Membury Castle, Membury		
RENDEMALYQUINETABILITY: Plant growth NEW BATTRY: No No DAMPER TYPE: Mixed, multiple owners CONTACT: Charlotte Russell 01271 831505 on the Part of No DAMPER TYPE: Mixed, multiple owners CONTACT: Charlotte Russell 01271 831505 on the Part of No DAMPER TYPE: CONTACT: Charlotte Russell 01271 831505 on the Part of No DAMPER TYPE: CONTACT: Charlotte Russell 01271 831505 on the Part of No DAMPER TYPE: Private CONTACT: Charlotte Russell 01271 831505 on the Part of No DAMPER TYPE: Private CONTACT: Charlotte Russell 01271 831505 on the Part of No DAMPER TYPE: Private CONTACT: Charlotte Russell 01271 831505 on the Part of No DAMPER TYPE: Private CONTACT: Charlotte Russell 01271 831505 on the Part of No DAMPER TYPE: Private CONTACT: Charlotte Russell 01271 831505 on the Part of No DAMPER TYPE: Private CONTACT: Charlotte Russell 01271 831505 on the Part of No DAMPER TYPE: Private CONTACT: Charlotte Russell 01271 831505 on the Part of No DAMPER TYPE: Private CONTACT: Charlotte Russell 01271 831505 on the Part of No DAMPER TYPE: Private CONTACT: Charlotte Russell 01271 831505 on the Part of No DAMPER TYPE: Private CONTACT: Charlotte Russell 01271 831505 on the Part of No DAMPER TYPE: Private CONTACT: Charlotte Russell 01271 831505 on the Part of No DAMPER TYPE: Private CONTACT: Charlotte Russell 01271 831505 on the Part of No DAMPER TYPE: Private CONTACT: Charlotte Russell 01271 831505 on the Part of No DAMPER TYPE: Private CONTACT: Charlotte Russell 01271 831505 on the Part of No DAMPER TYPE: Private CONTACT: Charlotte Russell 01271 831505 on the Part of No DAMPER TYPE: Private CONTACT: Charlotte Russell 01271 831505 on the Part of No DAMPER TYPE: Private CONTACT: Charlotte Russell 01271 831505 on the Part of No DAMPER TYPE: Private CONTACT: Charlotte Russell 01271 831505 on the Part of No DAMPER TYPE: Private Private Russell 01271 831505 on the Part of No DAMPER TYPE: Private Russell 01271 831505 on the Part of No DAMPER TYPE: Private Russell 01271 831505 on the Part of No DAMPER TYPE: Private Russell 01271 831505 on the Pa	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017951
Mixed, multiple owners Contact: Charlotte Russell 01271 831505 The NAME: Cursus, long mortuary enclosure, ring ditch and other associated cropmarks 700 metres east of Netherex Barton, Nether Exe Barton	CONDITION:	Extensive significant problems	TREND:	Declining
Cursus, long mortuary enclosure, ring ditch and other associated cropmarks 700 metres east of Netherex Barton. Nether Exe BESIGNATION: Scheduled Monument	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
Barton, Nether Exe Schodulon: Scheduled Monument Schodulon: Scheduled Monument Schodulon: TRRND: Declining RENCIPAL VALINERABILITY: Arable ploughing RENCIPAL VALINERABILITY: Scheduled Monument RENCIPAL VALINERABILITY: Scheduled Monument RENCIPAL VALINERABILITY: Scheduled Monument RENCIPAL VALINERABILITY: Scrub / tree growth RENCIPAL VALINERABILITY: Scrub / tree growth RENCIPAL VALINERABILITY: Scrub / tree growth RENCIPAL VALINERABILITY: Scheduled Monument RENCIPAL VALINERABILITY: Scheduled Monument RENCIPAL VALINERABILITY: Scheduled Monument RENCIPAL VALINERABILITY: Arable ploughing RENCIPAL VALINERABILITY: Other RENCIPAL VALINERABILITY: Arable ploughing REN	OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
Extensive significant problems TREND. Declining RENCIPAL VALINERABILITY: Arable ploughing NEW ENTERY: No CONTACT: Charlotte Russell 01271 831505 FIRE NAME: Two bowl barrows north of Green Lane, 430 metres west of Rewe Cross, Nether Exe DESIGNATION: Scheduled Monument LIST ENTERY NUMBER: 1016565 EXTENSIVE Significant problems TREND: Declining RENCIPAL VALINERABILITY: Arable ploughing NEW ENTERY: No CONTACT: Charlotte Russell 01271 831505 FIRE NAME: Belbury Castle, Ottery St. Mary DESIGNATION: Scheduled Monument LIST ENTERY NUMBER: 1017774 CONDITION: Unknown TREND: Unknown RENCIPAL VALINERABILITY: Scrub/tree growth New ENTERY: No DOWNER TYPE: Private CONTACT: Charlotte Russell 01271 831505 FIRE NAME: Scheduled Monument LIST ENTERY NUMBER: 1017752 FIRE NAME: Stockland Great Castle, Stockland DESIGNATION: Scheduled Monument LIST ENTERY NUMBER: 1017952 CONDITION: Extensive significant problems TREND: Declining RENCIPAL VALINERABILITY: Arable ploughing NEW ENTERY: No CONTACT: Charlotte Russell 01271 831505 FIRE NAME: Stockland Little Castle, Stockland DESIGNATION: Scheduled Monument LIST ENTERY NUMBER: 1017952 CONDITION: Extensive significant problems TREND: Declining RENCIPAL VALINERABILITY: Arable ploughing NEW ENTERY: No CONTACT: Charlotte Russell 01271 831505 FIRE NAME: Stockland Little Castle, Stockland DESIGNATION: DECLINING DESIGNATION: Extensive significant problems TREND: Declining RENCIPAL VALINERABILITY: Private, multiple owners CONDITION: Extensive significant problems TREND: Declining RENCIPAL VALINERABILITY: Private, multiple owners CONTACT: Charlotte Russell 01271 831505 FIRE NAME: Stockland Little Castle, Stockland DESIGNATION: Extensive significant problems TREND: Declining RENCIPAL VALINERABILITY: Private, multiple owners CONTACT: Charlotte Russell 01271 831505 FIRE NAME: Stockland Little Castle, Stockland DESIGNATION: Extensive significant problems TREND: Declining PRIVATE: Private, multiple owners CONTACT: Charlotte Russell 01271 831505 DECLINE TREND: DECLIN	SITE NAME:		other associated crop	omarks 700 metres east of Netherex
Arable ploughing NEW ENTRY: No DYNER TYPE: Private CONTACT: Charlotte Russell 01271 831505 STEINAME: Two bowl barrows north of Green Lane, 430 metres and 330 metres west of Rewe Cross, Nether Exe SESSIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1016565 CONDITION: Extensive significant problems TREND: Declining Private CONTACT: Charlotte Russell 01271 831505 STEINAME: Belbury Castle, Ottery St. Mary DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017774 Unknown TREND: Unknown TREND: Unknown TREND: Unknown TREND: Unknown TREND: Unknown TREND: CONTACT: Charlotte Russell 01271 831505 STEINAME: Scrub / tree growth NEW ENTRY: No DYNER TYPE: Private CONTACT: Charlotte Russell 01271 831505 STEINAME: Stockland Great Castle, Stockland DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017952 TENDE: Declining TREND: Declining TREND: Declining TREND: Declining TREND: No DOWNER TYPE: No DECINITION: Extensive significant problems TREND: No DOWNER TYPE: Mixed, multiple owners CONTACT: Charlotte Russell 01271 831505 STEINAME: Stockland Little Castle, Stockland DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017953 DOWNER TYPE: Stockland Little Castle, Stockland DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017953 DOWNER TYPE: Private, multiple owners CONTACT: Charlotte Russell 01271 831505 TREND: Declining TREND: Declining TREND: Declining TREND: Declining TREND: CONTACT: Charlotte Russell 01271 831505 TREND: Declining TREND: Declining TREND: CONTACT: Charlotte Russell 01271 831505 TREND: Declining	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014144
Designation Scheduled Monument List entry number: Unknown Members and 330 metres west of Rewe Cross, Nether Exe Sesignation Scheduled Monument List entry number: 1016565 CONDITION: Extensive significant problems TREND: Declining Members: No	CONDITION:	Extensive significant problems	TREND:	Declining
Two bowl barrows north of Green Lane, 430 metres and 330 metres west of Rewe Cross, Nether Exe Basionation. Scheduled Monument Extensive significant problems Arable ploughing Arable ploughing New Enter: Private Belbury Castle, Ottery St. Mary Sesignation: Scheduled Monument Unknown Tirend: Unknown Unknown Tirend: Contact: Charlotte Russell 01271 831505 Tirend: Tirend: Contact: Charlotte Russell 01271 831505 Tirend: Contact: Charlotte Russell 01271 831505 Tirend: Tirend: Contact: Charlotte Russell 01271 831505	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Scheduled Monument UST ENTRY NUMBER: 1016565 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYS: No CONTACT: Charlotte Russell 01271 831505 SITE NAME Belbury Castle, Ottery St. Mary SESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1017774 CONDITION: Unknown TREND: Unknown CONDITION: Unknown NEW ENTRYS: No CONTACT: Charlotte Russell 01271 831505 SITE NAME STENAME SCHEDULERABILITY: Scrub/tree growth NEW ENTRYS: No CONTACT: Charlotte Russell 01271 831505 SITE NAME SCHEDULERABILITY: No CONTACT: Charlotte Russell 01271 831505 SITE NAME SCHEDULERABILITY: No CONTACT: Charlotte Russell 01271 831505 SITE NAME SCHEDULERABILITY: No CONTACT: Charlotte Russell 01271 831505 SITE NAME SCHEDULERABILITY: No CONTACT: Charlotte Russell 01271 831505 SITE NAME SCHEDULERABILITY: No CONTACT: Charlotte Russell 01271 831505 SITE NAME SCHEDULERABILITY: No CONTACT: Charlotte Russell 01271 831505 SITE NAME SCHEDULERABILITY: No CONTACT: Charlotte Russell 01271 831505 SITE NAME SCHEDULERABILITY: No CONTACT: Charlotte Russell 01271 831505 SITE NAME SCHEDULERABILITY: No CONTACT: Charlotte Russell 01271 831505 SITE NAME SCHEDULERABILITY: Other NEW ENTRYS: Yes CONTACT: Charlotte Russell 01271 831505 SITE NAME SCHEDULERABILITY: Other NEW ENTRYS: Yes CONTACT: Charlotte Russell 01271 831505 SITE NAME SCHEDULERABILITY: Other Private, multiple owners SCHEDULERABILITY: Other SCHEDULERABILITY: Other SCHEDULERABILITY: Other SCHEDULERABILITY: NUMBER: 1016564 SCHEDULERABILITY: NUMBER: 1016564 SCHEDULERABILITY: NUMBER: 1016564 SCHEDULERABILITY: Arable ploughing NEW ENTRYS: No CESSIONATION: Scheduled Monument UST ENTRY NUMBER: 1016564 SCHEDULERABILITY: NUMBER: 1016564 SCHEDULERABILITY: Arable ploughing NEW ENTRYS: NO	OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
Extensive significant problems TREND: Declining RINCIPAL VULNERABILITY: Arable ploughing NEWENTRY: No DEVINER TYPE: Private CONTACT: Charlotte Russell 01271 831505 DEVINER TYPE: Private Belbury Castle, Ottery St. Mary DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1017774 DESIGNATION: Unknown TREND: Unknown RINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY: No DEVINER TYPE: Stockland Great Castle, Stockland DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1017952 DECIDING Extensive significant problems TREND: Declining NEW ENTRY: No DEVINER TYPE: Mixed, multiple owners CONTACT: Charlotte Russell 01271 831505 DETENDER: Stockland Little Castle, Stockland STENAME: Stockland Little Castle, Stockland Scheduled Monument UST ENTRY NUMBER: 1017953 DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1017953 DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1017953 DECLINING EXTENSIVE Stockland Little Castle, Stockland SCHEDITION: Extensive significant problems TREND: Declining RINCIPAL VULNERABILITY: Other NEWENTRY: Yes DEVINER TYPE: Private, multiple owners CONTACT: Charlotte Russell 01271 831505 DETENAME: Bowl barrow 470 metres east of Fortescue, Stoke Canon DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1016564 DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1016564 DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1016564 DENDAL TYPE: Private, multiple owners Scheduled Monument UST ENTRY NUMBER: 1016564 DENDAL TYPE: Declining NEW ENTRY: NUMBER: 1016564 DENDAL TYPE: Declining NEW ENTRY: NUMBER: 1016564	SITE NAME:	Two bowl barrows north of Green Lane, 430 m	etres and 330 metres	west of Rewe Cross, Nether Exe
RENCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No CONTACT: Charlotte Russell 01271 831505 Arable ploughing NEW ENTRY: No CONTACT: Charlotte Russell 01271 831505 Arable ploughing NEW ENTRY: NO CONTACT: Charlotte Russell 01271 831505 Arable ploughing NEW ENTRY: NO CONTACT: Charlotte Russell 01271 831505 Arable ploughing NEW ENTRY: No CONTACT: Charlotte Russell 01271 831505 Arable ploughing NEW ENTRY: No CONTACT: Charlotte Russell 01271 831505 Arable ploughing NEW ENTRY: No CONTACT: Charlotte Russell 01271 831505 Arable ploughing NEW ENTRY: No CONTACT: Charlotte Russell 01271 831505 Arable ploughing NEW ENTRY: No CONTACT: Charlotte Russell 01271 831505 Arable ploughing NEW ENTRY: No CONTACT: Charlotte Russell 01271 831505 Arable ploughing NEW ENTRY: No CONTACT: Charlotte Russell 01271 831505 Arable ploughing NEW ENTRY: No CONTACT: Charlotte Russell 01271 831505 Arable ploughing NEW ENTRY: No CONTACT: Charlotte Russell 01271 831505 Arable ploughing NEW ENTRY: No CONTACT: Charlotte Russell 01271 831505 Arable Stockland Little Castle, Stockland Extensive significant problems TREND: Declining CONDITION: Extensive significant problems TREND: Charlotte Russell 01271 831505 Arable Bowl barrow 470 metres east of Fortescue, Stoke Cano DESIGNATION: Scheduled Monument UST ENTRY NUMBER: Oharlotte Russell 01271 831505 Arable Bowl barrow 470 metres east of Fortescue, Stoke Canon DESIGNATION: Scheduled Monument DESIGNATION: Scheduled Monument DESIGNATION: Scheduled Monument DESIGNATION: Arable ploughing NEW ENTRY: No Declining RENCIPAL VULNERABILITY: Other Declining Arable ploughing NEW ENTRY: No Declining NEW ENTRY: No D	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016565
Private Belbury Castle, Ottery St. Mary Scheduled Monument LIST ENTRY NUMBER: 1017774 Unknown TREND: Unknown RINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY: No OWNER TYPE: Private Contacts, Stockland SESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017952 STENAME: Stockland Great Castle, Stockland SESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017952 CONDITION: Extensive significant problems TREND: Declining RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Mixed, multiple owners CONTACT: Charlotte Russell 01271 831505 STENAME: Stockland Little Castle, Stockland SESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017953 CONDITION: Extensive significant problems TREND: Declining SESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017953 CONDITION: Extensive significant problems TREND: Declining FRINCIPAL VULNERABILITY: Other NEW ENTRY: Yes DOWNER TYPE: Private, multiple owners CONTACT: Charlotte Russell 01271 831505 STENAME: Bowl barrow 470 metres east of Fortescue, Stoke Canon SESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1016564 EXTENAME: Bowl barrow 470 metres east of Fortescue, Stoke Canon SESIGNATION: Scheduled Monument LIST ENTRY NUMBER: Declining RINCIPAL VULNERABILITY: New Entry: No	CONDITION:	Extensive significant problems	TREND:	Declining
Belbury Castle, Ottery St. Mary Scheduled Monument Unknown Unknown TREND: Unknown Unknown TREND: Unknown TREND: Unknown TREND: Unknown TREND: ONACT: Charlotte Russell 01271 831505 TREND: ONACT: Charlotte Russell 01271 831505 TREND: ONTACT: Charlotte Russell 01271 831505 TREND: Declining	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1017774 CONDITION: Unknown TREND: Unknown PRINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRYP: No CONTACT: Charlotte Russell 01271 831505 SETE NAME: Stockland Great Castle, Stockland DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1017952 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No CONTACT: Charlotte Russell 01271 831505 SETE NAME: Stockland Little Castle, Stockland STEE NAME: Stockland Little Castle, Stockland STEE NAME: Stockland Little Castle, Stockland SETE NAME: Scheduled Monument UST ENTRY NUMBER: 1017953 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Other NEW ENTRYP: Yes DOWNER TYPE: Private, multiple owners CONTACT: Charlotte Russell 01271 831505 SETE NAME: Bowl barrow 470 metres east of Fortescue, Stoke Canon DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1016564 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Other NEW ENTRYP: Ves DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1016564 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: NUMBER: 1016564 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: No	OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
CONDITION: Unknown TREND: Unknown PRINCIPAL VULNERABILITY: Scrub/tree growth Private Stockland Great Castle, Stockland DESIGNATION: Scheduled Monument Extensive significant problems PRINCIPAL VULNERABILITY: Mixed, multiple owners CONTACT: Charlotte Russell 01271 831505 TREND: Declining PRINCIPAL VULNERABILITY: A contact: Charlotte Russell 01271 831505 TREND: Declining PRINCIPAL VULNERABILITY: No CONTACT: Charlotte Russell 01271 831505 TREND: Declining PRINCIPAL VULNERABILITY: Declining PRINCIPAL VULNERABILITY: Other Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Other Private, multiple owners CONTACT: Charlotte Russell 01271 831505 TREND: Declining PRINCIPAL VULNERABILITY: Yes CONTACT: Charlotte Russell 01271 831505 TREND: Declining PRINCIPAL VULNERABILITY: Other Private, multiple owners CONTACT: Charlotte Russell 01271 831505 TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing PRINCIPAL VULNERABILITY: No PRINCIPAL VULNERABIL	SITE NAME:	Belbury Castle, Ottery St. Mary		
REINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRYP: No DWINER TYPE: Private CONTACT: Charlotte Russell 01271 831505 SITE NAME: Stockland Great Castle, Stockland DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017952 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No DWINER TYPE: Mixed, multiple owners CONTACT: Charlotte Russell 01271 831505 SITE NAME: Stockland Little Castle, Stockland DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017953 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Other NEW ENTRYP: Yes DWINER TYPE: Private, multiple owners CONTACT: Charlotte Russell 01271 831505 SITE NAME: Bowl barrow 470 metres east of Fortescue, Stoke Canon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1016564 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Other LIST ENTRY NUMBER: 1016564 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: NUMBER: 1016564 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017774
Private CONTACT: Charlotte Russell 01271 831505 STEENAME: Stockland Great Castle, Stockland DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017952 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No CONTACT: Charlotte Russell 01271 831505 STEENAME: Stockland Little Castle, Stockland DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017953 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Other NEW ENTRYP: Yes CONTACT: Charlotte Russell 01271 831505 STEENAME: Bowl barrow 470 metres east of Fortescue, Stoke Canon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1016564 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Other LIST ENTRY NUMBER: 1016564 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Number: 1016564 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No	CONDITION:	Unknown	TREND:	Unknown
STEE NAME: Stockland Great Castle, Stockland DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017952 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No CONTACT: Charlotte Russell 01271 831505 STEE NAME: Stockland Little Castle, Stockland DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017953 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Other NEW ENTRY?: Yes DWNER TYPE: Private, multiple owners CONTACT: Charlotte Russell 01271 831505 STEE NAME: Bowl barrow 470 metres east of Fortescue, Stock Canon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1016564 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Declining DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1016564 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: No	PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
Scheduled Monument Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing Mixed, multiple owners CONTACT: Charlotte Russell 01271 831505 SITE NAME: Stockland Little Castle, Stockland CONDITION: Extensive significant problems TREND: Declining TREND: Declining TREND: Declining TREND: Declining PRINCIPAL VULNERABILITY: Other NEW ENTRYP: Private, multiple owners CONTACT: Charlotte Russell 01271 831505 TREND: Declining	OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
Extensive significant problems TREND: Declining NEW ENTRYP: No Arable ploughing Mixed, multiple owners CONTACT: Charlotte Russell 01271 831505 TREND: CONTACT: Charlotte Russell 01271 831505 TREND: Declining TREND: CONTACT: Charlotte Russell 01271 831505 TREND: Declining TREND: Declining TREND: TREND: Declining TREND: CONTACT: Charlotte Russell 01271 831505 TREND: Declining	ITE NAME:	Stockland Great Castle, Stockland		
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY): No DWNER TYPE: Mixed, multiple owners CONTACT: Charlotte Russell 01271 831505 SITE NAME: Stockland Little Castle, Stockland DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017953 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Other NEW ENTRY): Yes DWNER TYPE: Private, multiple owners CONTACT: Charlotte Russell 01271 831505 SITE NAME: Bowl barrow 470 metres east of Fortescue, Stoke Canon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1016564 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY): No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017952
Mixed, multiple owners CONTACT: Charlotte Russell 01271 831505 STE NAME: Stockland Little Castle, Stockland Scheduled Monument Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Other Bowl barrow 470 metres east of Fortescue, Stoke Canon Scheduled Monument LIST ENTRY NUMBER: 1017953 CONTACT: Charlotte Russell 01271 831505	CONDITION:	Extensive significant problems	TREND:	Declining
Stockland Little Castle, Stockland DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017953 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Other NEW ENTRY?: Yes DESIGNATION: CONTACT: Charlotte Russell 01271 831505 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1016564 CONDITION: Extensive significant problems TREND: Declining DESIGNATION: Scheduled Monument Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017953 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Other Private, multiple owners CONTACT: Charlotte Russell 01271 831505 BOWL BARRE: Bowl barrow 470 metres east of Fortescue, Stoke Canon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1016564 CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Other Other Private, multiple owners Bowl barrow 470 metres east of Fortescue, Stoke Canon DESIGNATION: Scheduled Monument Extensive significant problems TREND: Declining TREND: Declining NEW ENTRY?: 1016564 TREND: Declining NEW ENTRY?: No	SITE NAME:	Stockland Little Castle, Stockland		
PRINCIPAL VULNERABILITY: Other Other Private, multiple owners CONTACT: Charlotte Russell 01271 831505 Bowl barrow 470 metres east of Fortescue, Stoke Canon DESIGNATION: Scheduled Monument Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017953
Private, multiple owners CONTACT: Charlotte Russell 01271 831505 EXECUTE NAME: Bowl barrow 470 metres east of Fortescue, Stoke Canon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: LONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No	CONDITION:	Extensive significant problems	TREND:	Declining
Bowl barrow 470 metres east of Fortescue, Stoke Canon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1016564 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: No	PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	Yes
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1016564 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No	SITE NAME:	Bowl barrow 470 metres east of Fortescue, Stol	ke Canon	
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016564
	CONDITION:	Extensive significant problems	TREND:	Declining
OWNER TYPE: Mixed, multiple owners CONTACT: Charlotte Russell 01271 831505	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
	OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Roman villa 300 yards (270 metres) SSW of Holco	mbe Farm, Uplyme	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002558
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 280 metres NNE of Starved Oak Cro	oss, Upton Pyne	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010638
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 300 metres SSE of Stevenstone Farm	, Upton Pyne	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015973
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 350 metres NNE of Starved Oak Cro	oss, Upton Pyne	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010639
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 450 metres SSE of Stevenstone Farm	, Upton Pyne	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015974
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Earthwork enclosure 330 yards (300 metres) south west of Three Horse Shoes Inn, Upton Pyne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002645
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Two bowl barrows, 350 metres south of Stevenstone Farm, Upton Pyne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010631
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Castle Hill, Widworthy		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017477
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
	•		
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

SITE NAME:	Woodbury Castle, Woodbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003862
CONDITION:	Extensive significant problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Charlotte Russell 01271 831505

Alt the	
	4

Bicton, Bicton / Colaton Raleigh / East Budleigh
Registered Park and Garden grade I, 19 LBs, SM
Generally unsatisfactory with major localised problems
High
Stable
No
Mixed, multiple owners

1000338

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

C18 and C19 country house estate developed from earlier manor. Large park, important gardens and arboretum. Registered park in three main ownerships. The core of the site, including the principal house, has been developed in the post-war era as a land-based college. Continuous pressure for development as the college has expanded has tended to erode the integrity of the designed landscape. The absence of a masterplan to guide and inform development remains a major cause for concern.

Contact: Jo McAllister 0117 975 0696

EXETER

© lames Carter



© Historic England

SITE NAME:	Church of St Thomas the Apostle, Cowick Street, Exeter
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (B)
OWNER TYPE:	Religious organisation

1169954

Church largely rebuilt in 1657. The west tower, south aisle and east end of north aisle are C17. Due to poor original design and lack of maintenance, roofs were in poor condition, rainwater goods failed and water penetrated parapet walls and gutters damaging the structure and decorative detail. A National Lottery Heritage Fund and Historic England Repair Grant for Places of Worship funded a first phase of repairs (2013). Further NHLF Grants for Places of Worship funded additional phases (2015 and 2017). Additional work to the aisle roof and interior of the body of the church is still needed.

Contact: Annie Evans 0117 975 0673



© Historic England

SITE NAME:	Church of St Mary Steps, West Street, Exeter
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1224263

C15 fabric. Restored 1868-72 by Edward Ashworth. Chancel re-ordered 1966 by Lawrence King. Nave, chancel, south west tower, south aisle and chapel, north west vestry. The church is very compact, which reflects its constricted site just within the walls of medieval Exeter. Slate roofs. Red Heavitree stone in large blocks with limestone dressings. A National Lottery Heritage Fund Grant for Places of Worship funded the repair of the tower, completed in early 2018. There are cracks in the south east corner and the aisle roof structure and covering are poor. A further phase of work will be needed.

Contact: Sarah Ball 0117 975 0666

SITE NAME:	Exeter city walls		
DESIGNATION:	Scheduled Monument, 2 RPGs, 4 CAs	LIST ENTRY NUMBER:	1003858
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Andy Crabb 01626 832093

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area
Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

EXMOOR (NP)



SITE NAME:	Church of St Brendan, Church Hill, Brendon, North Devon
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1289343

Parish church. Nave, chancel and south porch of 1738, tower rebuilt 1828; the whole restored and north aisle, north transept and vestry added in 1873. Dressed and roughly dressed stone with some brick dressings to vestry, the C19 work snecked with ashlar dressings. There are problems with the foundation beams and dampness in the tower. The gutters and drainage need repair and the external walls need repointing.

Contact: Annie Evans 0117 975 0673

© Historic England



SITE NAME:	Church of St Martin, Martinhoe, North Devon
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1106778

Small parish church dating from C13 with later additions. Stone rubble, tower roughly coursed, with ashlar dressings and slate roofs. Some slipped slates, cracked cement, ground gutter and rainwater goods in bad condition. Cement pointing round tower arch, blistering paint on north aisle and south wall of chancel.

Contact: Annie Evans 0117 975 0673 1106//8

© Historic England

SITE NAME:	Badgworthy deserted medieval village, Doone's Houses, Brendon, North Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003886
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Two round barrows on Cheriton Ridge, Brendon	, North Devon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002583
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Earthwork defences of Countisbury Castle promo Devon	ontory fort (Wind H	ill), Lynton and Lynmouth, North
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020807
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Remains of leat serving former hydro-electric generating station, on the south bank of the East Lyn River, 210 metres east of Oxen Tor, Lynton and Lynmouth, North Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020808
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Charlotte Russell 01271 831505

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

SITE NAME:	Standing stones on eastern edge of Furzehill Common, Lynton and Lynmouth, North Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003300
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Two round barrows and cairn cemetery, Ilkerton R	lidge, Lynton and L	ynmouth, North Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002566
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Two round barrows near Warcombe Water, Lynto	on and Lynmouth, N	North Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003299
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505

MID DEVON



© Historic England

SITE NAME:	The Manor House Hotel, 2, Fore Street, Cullompton
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Commercial company

1105901

LIST ENTRY NUMBER:

Hotel in partial use, formerly early C17 merchant's house. Concerns regarding the structural stability and public safety led to the Council serving a repairs notice. Most of the external items of work specified in the notice were complied in 2015-16 but subsequent concerns arose regarding the stability of the ornate shell hood porch and the hanging sign on the main facade. A listed building application has now been submitted to address those concerns and stabilise the hood and sign, the site has been scaffolded and work has started. Internal refurbishment on upper floors still to be completed.

Contact: Jenny Chesher 0117 975 0686



© Historic England

SITE NAME:	Prescott Baptist Chapel, Culmstock
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1147714

Simple C18 church in an isolated rural location. There are two other Baptist churches within a five mile radius which are closer to centres of population. Its physical problems are putting historic window fabric at risk, and could rapidly escalate into more serious repair problems if not remedied. The chapel has been sold and is no longer in use as a place of worship. Historic England has had discussions with the owner but work is required.

Contact: Annie Evans 0117 975 0673



© Historic England

SITE NAME:	Old farmhouse with integral barn at East Barton, Exeter Road, Tiverton
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1384813

The building dates from C16 and the house has not been occupied in liviing memory. It is a very rare and probably unique example, being an evolved form of the longhouse which retains considerable evidence of its form and function including important early features such as jointed cruck roof trusses, two internal jetties and substantial floor beams. The building is largely water tight, but there is slow structural failure of internal elements and deterioration of some external cob walls. A previous scheme to convert to holiday cottages lapsed and there are no current proposals for its reuse.

Contact: Jenny Chesher 0117 975 0686

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

HERITAGE AT RISK 2020 / SOU	JTH WEST / MID DEVON		
SITE NAME:	Roman fort 300 metres north east of Cudmore Fa	rm, Bampton / Clay	hanger
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011251
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	A henge, two barrows, two ring ditches, two enclosures and part of a linear feature 420 metres north west of Lower Hampson, Bow		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015472
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Bowl barrow 80 metres south west of Hampson C	Cottage, Bow	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016189
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Bowl barrow 140 metres south east of Burston Cross, Bow		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015471
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
ITE NAME:	Bowl barrow 220 metres south west of Hampson Cottage, Bow		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015474
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093
ITE NAME:	Two bowl barrows 180 metres south west of Hampson Cottage, Bow		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015475
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
ITE NAME:	Two bowl barrows 250 metres north of Natson Fa	arm, Bow	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015476
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Canonsleigh Abbey, Burlescombe		
DESIGNATION:	Scheduled Monument, LB grade II, CA	LIST ENTRY NUMBER:	1003830
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Millsome Castle, Coldridge		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016227
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Posbury camp, Castle Down, Crediton Hamlets		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003826
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Romano-British villa, Downes, near Crediton, Cred	diton Hamlets	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002668
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Two Roman forts and two Roman camps at St And	drew's Hill, Cullomp	oton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019543
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Three bowl barrows 250 metres south east of Gib	bet Moor Cross, T	empleton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017134
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Bowl barrow 260 metres north west of Putson Cro	oss, Tiverton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017132
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
	Eggesford Castle, 640 metres north east of Eggesford House, Wembworthy		
SITE NAME:	Eggesford Castle, 640 metres north east of Eggesfo	ord House, Wembw	vorthy
SITE NAME: DESIGNATION:	Eggesford Castle, 640 metres north east of Eggesfort Scheduled Monument	LIST ENTRY NUMBER:	1016208
DESIGNATION:			•
	Scheduled Monument	LIST ENTRY NUMBER:	1016208
designation: Condition:	Scheduled Monument Extensive significant problems	LIST ENTRY NUMBER:	1016208 Declining

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Bowl barrow 130 metres north east of Burston Cro	oss, Zeal Monachoi	rum
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015152
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Bow		
DESIGNATION:	Conservation Area, 20 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Sue Warren (LPA) 01884 234264
SITE NAME:	Cullompton		
DESIGNATION:	Conservation Area, 46 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Sue Warren (LPA) 01884 234264
SITE NAME:	Tiverton		
DESIGNATION:	Conservation Area, 194 LBs, 2 SMs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Sue Warren (LPA) 01884 234264

NORTH DEVON



SITE NAME: Hall House, Bishop's Tawton DESIGNATION: Listed Building grade II* CONDITION: Poor OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C (C) OWNER TYPE: Private LIST ENTRY NUMBER: 1107730

Built c1846-50 by Philip Hardwick, with a rear range by RD Gould. The house lies within an estate, and there are several other listed structures within the vicinity. The main range is generally in a fair condition. The rear range is still in poor condition, though the roof is weathertight. The owners are very gradually addressing the repair issues.

© Historic England Archive



© Historic England

SITE NAME:	Bunksland Farmhouse and attached outbuildings, East Anstey
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

1106670

A remarkably unspoilt medieval farmhouse, multiphased, with a surviving early roof structure and interesting plan form. The property has been vacant since 2009 and has suffered from deterioration at the external cob wall as well as the collapse of an internal cob partition and roof truss supporting the floor above. Historic England has supported North Devon District Council to serve an Urgent Works Notice which has enabled propping and protection work to be carried out. Ownership uncertainties have delayed further resolution but as of 2020 are beginning to progress.

Contact: Annie Evans 0117 975 0673

Contact: Annie Evans 0117 975 0673



SITE NAME: Broomham Farmhouse, King's Nympton DESIGNATION: Listed Building grade II* CONDITION: Poor OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: F (F) OWNER TYPE: Private

Early C16 longhouse with later additions. The roof was rethatched with Historic England grant aid in 2013. Improvements have permitted the family to return to the house, and work is very gradually continuing, but further structural work is still required.

LIST ENTRY NUMBER: 1152877 Contact: Annie Evans 0117 975 0673 © Historic England Archive

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



© Historic England

SITE NAME:	Church of St James, Arlington
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1106820

Parish church. Late CI5 or early CI6 tower with some C19 work. Set in the landscape of Arlington Court, which is owned by the National Trust. Options are being explored by the very small congregation, possibly in conjunction with the neighbouring National Trust. Blocked downpipes are causing significant damage to the interior and roofing repairs are also required. The congregation has been seeking funding but no substantive work has been carried out to date.

Contact: Annie Evans 0117 975 0673



SITE NAME: Church of St John the Baptist, East Down DESIGNATION: Listed Place of Worship grade II* CONDITION: Poor PRIORITY CATEGORY: A(A)OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1163326

Parish church sited adjacent to the manor house. Surviving C13 fabric to tower, C15 south aisle and some C19 work. The congregation is steadily working through repairs. Roof repairs were completed under the National Lottery Heritage Fund and Historic England Repair Grants for Places of Worship scheme in 2005. Tower is very damp and has structural issues with significant cracking. Condition of windows also remains poor.

Contact: Annie Evans 0117 975 0673



© Historic England

© Historic England

SITE NAME:	Parish Church of Holy Trinity, Church Road, Ilfracombe
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1208207

Large parish church. Early tower with church enlarged in the 1320s and again in the C15. Problems with roof and gutters led to water penetration and subsequent damage of internal fabric. The congregation has been in discussions with Historic England and has repaired the eastern roofs with a Listed Places of Worship Roof Repairs Grant. However the tower (with Norman stonework) and west end of the church, including windows with notable Kempe glass, remain in poor condition.

Contact: Annie Evans 0117 975 0673



© Historic England

SITE NAME:	Church of St Michael, Marwood
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1107157

Parish church. C13 fabric to chancel with two lancets to north side and pointed south doorway. South transept with single lancet in east wall and unmoulded pointed arch into nave. Battered plinth in north aisle indicates former north transept and original cruciform plan. Cracked ridge tiles and missing slates. Rainwater goods need overhauling. Internal damp staining to walls. Bench ends with active insect infestation. Vegetation growth on stonework to tower, vestry chimney and north aisle wall. An application to the Listed Places of Worship Roof Repair Grant scheme in 2016 was unsuccessful.

Contact: Annie Evans 0117 975 0673



© Historic England

SITE NAME:	Church of St John, Satterleigh and Warkleigh
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1258818

deterioration of the fabric and significant works are needed. The east end of the south aisle has cracking and there is some structural movement in the fabric.

Parish church, sited in a farmyard. Damp has caused

Contact: Annie Evans 0117 975 0673

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

SITE NAME:	Barnstaple Castle, Barnstaple		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1020922
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Charlotte Russell 01271 831505



SITE NAME: Church of St Mary Magdalene, The Churchyard, South Molton Listed Place of Worship grade I, DESIGNATION: CONDITION: Poor PRIORITY CATEGORY: B (B) OWNER TYPE: Religious organisation

Large parish church mainly C15, restored in C19. The stonework has started to decay and the roofs are in bad condition. Water ingress to the interior is causing continuing damage. The church was awarded a maximum Listed Places of Worship Roof Repairs Grant and during 2018 the south aisle, south transept and Lady Chapel roofs were re-slated. Timber flooring has also been repaired. Further funding is still required.

LIST ENTRY NUMBER: 1317855 Contact: Annie Evans 0117 975 0673 © Historic England

SITE NAME:	Hillfort on Whitechapel Moors, 640 metres north east of Garliford Mill, Bishop's Nympton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016214
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505



© Historic England

SITE NAME: Church of St Bartholomew, Stoke Rivers DESIGNATION: Listed Place of Worship grade I CONDITION: Poor PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1107658

Parish church. Mainly late C15 to early C16 but may be some earlier fabric. Some C18 work survives. Main restoration in 1880s and in 1905, but possibly some earlier restoration work of 1831. Stone rubble with stone dressings. Slate roofs with coped gabled ends. West tower, nave, chancel, south aisle and south porch. There has been work to the chancel south gutter but an overhaul of other rainwater goods is still needed. Poor drainage. Roofs reported to be in a poor condition. Tower is damp with vegetation growth and tower internal timbers are also reported to be poor.

Contact: Annie Evans 0117 975 0673

SITE NAME:	Round barrow cemetery 210 metres south west of Hillcrest, Centery Lane, Bittadon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019252
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Round barrow cemetery 500 metres east of Little Bray Cross, Bratton Fleming		
DESIGNATION:	C.I. I.I. I.M.		
	Scheduled Monument	LIST ENTRY NUMBER:	1017137
CONDITION:	Generally unsatisfactory with major localised problems	LIST ENTRY NUMBER: TREND:	1017137 Declining
CONDITION: PRINCIPAL VULNERABILITY:	Generally unsatisfactory with major localised		

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Wayside cross known as Eastacott Cross or the St	onen Hammer, Ch	ittlehampton
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1013727
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 280 metres north east of Beacon Mo Chulmleigh	or Cross, forming	part of a round barrow cemetery,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015153
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 330 metres east of Beacon Moor Cro	oss, forming part of	f a round barrow cemetery, Chulmlei
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015154
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Round barrow cemetery on West Burrow Moor, E	ast Worlington	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016215
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Stone Row on Isley Marsh, Lower Yelland, Freming	gton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003847
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Charity (non-heritage)	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Hillfort 400 metres north west of Woodhouse, Qu	ieen's Nympton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015463
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Two bowl barrows 100 metres east of Catkill Cros	ss, Rose Ash	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015145
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Camp south of Birch Ham Wood, Stoke Rivers		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002533
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 225 metres south east of Elworthy	Cross, Witheridge	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016650
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 300 metres north west of Witherio	lge Moor Cross (wes	t), Witheridge
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1016652
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 610 metres south east of Elworthy	Cross, Witheridge	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016651
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow on Dart Raffe Moor lying 550 metr	es south west of Bro	adridge Farm, Witheridge
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015150
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	llfracombe		
DESIGNATION:	Conservation Area, 119 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Collette Hall (LPA) 01271 388352

SOUTH HAMS



© Historic	England

SITE NAME:	Deer Park wall at Berry Pomeroy Castle, Berry Pomeroy
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private

1108572

Medieval deer park wall, extended in the C16. Neglected, heavily overgrown with ivy and partially collapsed in places. The estate has prepared a condition survey in order to understand and monitor mechanisms of decay and to prioritise repairs. A pilot repair scheme was undertaken in 2013/14 with funding from Natural England. This was extended in 2014/15 and a team from the estate continues to make repairs for a period every summer. There have been some further areas of collapse and as of 2020 work is still required to stabilise other sections, but steady progress is being made.

Contact: Annie Evans 0117 975 0673

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site



© Historic England

SITE NAME:	Week, Berry Pomeroy
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private

1108575

Small house reduced in size and now derelict. C16, date 1584 on interior plasterwork now removed to Totnes museum. Also barn at right angles. Stone rubble walls with gabled ends, new slate roof and concrete ring-beam replacing scantle roof. Originally L-shaped on plan but south wing replaced by a linhay. South east wall partly rebuilt in blockwork. No first floor, stair or glazing, wall footings concreted, ground level raised at north sides. Condition stable but vulnerable. Historic England is in discussion with owner and lessee regarding repair and reuse.

Contact: Annie Evans 0117 975 0673



© Historic England

SITE NAME:	Old Postern, Dartington
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Charity (non-heritage)
LIST ENTRY NUMBER:	1219732

A late medieval house of considerable importance and complexity. Formerly the parsonage, extended and remodelled in the 1860s by William White in1928-9 by Rex Gardner for the Elmhirsts; most recently the building has provided accommodation for the Schumacher College at Dartington. It closed for use in November 2018 due to concerns about the poor condition of its slate roof covering, which is not weathertight in several areas. Funding is available for repairs and a schedule of works is being prepared as part of ongoing pre-application discussions between the Trust, the LPA and Historic England.

Contact: Jenny Chesher 0117 975 0686



© South Hams District Council

SITE NAME:	Yarde Farmhouse, Malborough
DESIGNATION:	Listed Building grade I
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1108479

Late C16 evolved manor house. The house, its detached kitchen and also the early C18 chamber block are now wind and weathertight externally. The greatest area of uncertainty remains the interior of the lodging range and the important painted hangings whose conservation and future display are not resolved.

Contact: Annie Evans 0117 975 0673



© Historic England Archive

SITE NAME:	39, The High Street, Totnes
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1236133

Fine C17 plasterwork and interior threatened by poor condition of roof and opening up of floor on the second floor. Ground floor is a shop. Upper floors are unoccupied and in need of repair and new services. Slipped slates and windows in very poor condition. There is increased concern about the condition of the building and Historic England has been in discussion with the Local Authority.

Contact: Annie Evans 0117 975 0673



© Historic England Archive

SITE NAME:	Fort Bovisand, Wembury	
DESIGNATION:	Scheduled Monument, 2 LBs	
CONDITION:	Poor	
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	D (D)	
OWNER TYPE:	Charity (heritage)	
LIST ENTRY NUMBER:	1002584	

Major C19 fort complex forming part of the ring of defences around Plymouth. Most recently used as a base for training divers, it is now disused. A scheme for resdiential conversion with significant levels of public access and interpretation has been agreed and planning permission was granted in 2017. Although some recording and ground investigations have been carried out, meaningful restoration has yet to start.

Contact: Simon Hickman 0117 975 0717

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

OWNER TYPE:

OWNER TYPE:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© Historic England

SITE NAME:

Garden wall, steps and gate piers south of Langdon Court Hotel, Langdon, Wembury

DESIGNATION:

Listed Building grade II*, RPG grade II

CONDITION:

Fair

OCCUPANCY:

N/A

PRIORITY CATEGORY:

F (F)

Private

1169143

Late C17 to early C18 formal terraced garden, the layout little altered since the early C18. Terraces extend south from the house on rising ground, with central axial path and connecting steps. Enclosed by walls to the east, south and west. The northern (larger) terrace has C17 gate piers and gates in the east and west walls and a central pool. The present owner has instigated a programme of phased repair, which is partially completed but condition has remained static for the last few years.

Contact: Jenny Chesher 0117 975 0686



© Historic England

SITE NAME:	Pair of garden houses south of Langdon Court Hotel, Langdon, Wembury
DESIGNATION:	Listed Building grade II*, RPG grade II
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)

Private

1108587

and southern terraces in the late C17 to early C18 formal terraced garden to the south of the house. Extensive repairs have been undertaken to the building exteriors and an application was made in 2014 for their alteration to be used as ancillary accommodation to the hotel in the main house. That was withdrawn pending further discussions with the local planning authority and Historic England. A revised application made in 2018 was approved in July of that year but does not appear to have yet been implemented.

Early C18 gazebos standing at the junction of the northern

Contact: Jenny Chesher 0117 975 0686



© Historic England

SITE NAME:	Watch House battery and ditch, Wembury
DESIGNATION:	Scheduled Monument, LB grade II
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Government or agency

Constructed 1904 but utilising an 1860s ditch system, with First and Second World War additions. The site was leased to a private company until 2009, and since then has been vacant and subject to vandalism. Recording has been put in hand but no options for repair/reuse have been agreed.



© Historic England

SITE NAME:	Church of St Mary, Berry Pomeroy
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1108535

1002585

Parish church. Rebuilt in C15 restored in the late C17 and 1878 to 1879. Tower has C13 or C14 west doorway. Stone rubble with freestone dressings and slate roofs, tower rendered. Nave and chancel in one. The church is generally very well maintained and a number of significant repairs have been undertaken. Despite this, the tower remains damp with problems with the render, and the main roofs also need work. The congregation applied in the last round of grants for Places of Worship Scheme from the National Lottery Heritage Fund but was unsuccessful.

Contact: Annie Evans 0117 975 0673

Contact: Annie Evans 0117 975 0673



© Historic England

SITE NAME:	Church of St Lawrence, Bigbury
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1325078

A C14 and C15 church much rebuilt by Sedding in the C19. Nave, chancel, north aisle, south transept, south porch, west tower with spire. Though the congregation has done a lot of work including undertaking works to the rainwater goods there is still a notice in the church that the plaster is dangerous. Damp tower. Ringing chamber has little ventilation.

Contact: Annie Evans 0117 975 0673

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site



SITE NAME:	Church of St Michael, Main Street, Blackawton
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1108023

Parish church. C14 chancel and possibly tower; nave and aisle rebuilt c later CI5 or early CI6. Restored in 1887, 1893, 1895 and 1898. Local shale rubble with granite and some red sandstone dressings slate roof. The church is generally well-maintained and the roofs are all in good condition. However the tower masonry is damp and friable. Steeplejacks have undertaken emergency tower repairs but it still needs further work.

Contact: Annie Evans 0117 975 0673

© Historic England



SITE NAME:	Church of St Mary, Charleton	
DESIGNATION:	Listed Place of Worship grade II	
CONDITION:	Poor	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1108510	

Parish church. C15 heavily restored in 1849-50. Slatestone rubble walls; windows largely of Caen stone, slate roofs. The fittings are all Victorian and the octagonal font, pulpit and desk are also of Caen stone. High level tower repointed. Rainwater goods rusting and undersized and failing to get the water away from the church resulting in cracking and staining to the interior. Internal decorations poor. The church is generally well maintained and slate roof repairs have been completed. However, significant repairs still need to be undertaken.

Contact: Annie Evans 0117 975 0673

© Historic England



SITE NAME:	Church of St Sylvester, Chivelstone
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1108470

Parish church. C15 restored in late C19 or early C20. Slatestone rubble walls. Gabled slate roofs. Good collection of medieval joinery. Small, rural parish church with a number of problems which add up to a significant amount of work: roofs, rainwater goods, damp ingress and structural movement all need addressing. The congregation made an application to the National Lottery Heritage Fund in 2019 for work to address structural and waterproofing issues, and has commissioned a conservator's report on the Rood and Parclose Screens and Pulpit.

Contact: Annie Evans 0117 975 0673

way		452
	1	
11	1	

SITE NAME:	Church of St Edmund, Fore Street, Kingsbridge
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1165559

Large parish church of cruciform plan with transepts, north and south aisles to nave, chancel aisles and two-storey south porch. The C13 tower remains, church was rebuilt and dedicated 1414. Restored and extended 1849 and 1896. Internal decorations are in poor condition and have staining in numerous places. Staining below valley gutters that may be failing. Windows and stonework problems urgent. A blocked valley gutter has now led to dry rot outbreak in south aisle, the congregation is consulting the church architect on remedial work.

Contact: Annie Evans 0117 975 0673

	-20
ARA.	4
20	7

SITE NAME: Church of the Blessed Virgin Mary, Rattery DESIGNATION: Listed Place of Worship grade I CONDITION: Poor PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1147626

Parish church. C13, enlarged in C15 by addition of aisles and enlargement of transepts. Restored probably c1860s. Roughcast stone with slate roofs. Internally the walls are entirely plastered with unique incised and painted decoration. This has been affected by previous high level roof leaks and more so from rising damp retained by hard cementitious external pointing which is causing significant salt damage internally. The congregation has begun to plan a campaign of repair and to consider sources of funding.

Contact: Annie Evans 0117 975 0673

© Historic England

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



SITE NAME:	Church of St Paul, Staverton
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1108524

Early C14 church, largely rebuilt in the C15, with north and south aisles, western tower and two-storey porch. Rainwater goods have been overhauled. Vestry roof poor. Very damp at low level with damage to tile floors and evidence of beetle in pew platforms and white salts. Cracks in cement render. In need of stonework repair and repointing.

Contact: Annie Evans 0117 975 0673

© Historic England



SITE NAME:	Church of St Michael, Strete
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1165589

Parish church in Perpendicular Gothic style built in 1836 with older tower. Cementitious render over local slate rubble. Single span Welsh slate roof over nave and aisles with gabled ends and eaves brackets to moulded cast-iron gutters. Very damp tower. High level water penetration with salts and damage to interior plaster and decorations. Other works to the church have been done but these issues have not been addressed.

Contact: Annie Evans 0117 975 0673

© Historic England



SITE NAME:	Church of St Mary, High Street, Totnes
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1236065

Former priory church rebuilt 1430-60. Random Devonian rubble with red sandstone dressings, some pale limestone dressings and parapets, and sandstone tower. Tower stonework poor needing repointing and vegetation removal. North aisle parapet and stonework decaying. Ground gutters poor. Rainwater goods need painting and vegetation removed. Internal damage to windows from rusty ferramenta (iron work) and damaged paint to north aisle east end on chancel south wall. Discussions with the church regarding proposals for reordering continue but as of 2019 substantial repairs are still needed.

Contact: Annie Evans 0117 975 0673

© Historic England

SITE NAME:	Hilltop enclosure known as Maristow Camp, 240 metres east of Middle Park House, Bickleigh		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019784
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102



SITE NAME:	Church of St Peter, The Square, Ugborough
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1168309

Large parish church, dubbed 'The Cathedral of the South Hams'. The north aisle roof has become porous allowing significant water ingress, threatening the integrity of medieval carved roof bosses. The congregation has completed a phase of repair with a National Lottery Heritage Fund Grant for Places of Worship but the church remains very damp and further works are still being planned.

Contact: Annie Evans 0117 975 0673

© Le Page Architects

SITE NAME:	Medieval holy well known as St Ann's Well, 120 metres south of Holwell Farm, Bigbury		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1019315
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

SITE NAME:	Iron Age hillfort known as Wasteberry Camp, med north west of Lyneham House, Brixton / Yealmpto	dieval deer park and on	d post-medieval warren, 800 metres
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020160
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Three bowl barrows 310 metres west of Home Fa	rm, forming part of	f a round barrow cemetery, Charleto
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019788
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Two round barrows on Ridding Down, Cornwood	I	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002586
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Levelling	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Hilltop enclosure and woodbanks in Chacegrove Wood, 540 metres north west of Dartington Hall,		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020553
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Charity (non-heritage)	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Hilltop enclosures in North Wood, 780 metres NI	NW of Old Parson	age Farm, Dartington
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020381
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Charity (non-heritage)	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Hillfort and two bowl barrows at Halwell Camp, H	lalwell and Morelei	gh
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019237
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	D-Day landing craft maintenance site on the River Kingswear	Dart immediately t	o the south of Lower Noss Point,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021076
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Gomerock Tower, Kingswear		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003852
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Annie Evans 0117 975 0673
SITE NAME:	Two ring cairns 330 metres south east of Coldhard	oour Cross, Loddis	well
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014244
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Dumping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Hilltop enclosure 380 metres east of Middle Soar,	Malborough	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019533
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Two hut circles and associated field systems and er	nclosure at Mouseh	ill Brake, Malborough
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020573
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Fort Charles, Salcombe		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1020165
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Annie Evans 0117 975 0673
SITE NAME:	Hut circle 1000 yards (915 metres) east of Colelan	id Bridge, Sparkwel	l
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002596
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Post-medieval deer park, medieval fishpond, and a Park, Sparkwell	C19 lead mine, ore	works and smelt mill at Boringdon
DESIGNATION:	Scheduled Monument and Listed Building grade II*	LIST ENTRY NUMBER:	1020565 and 1386330
CONDITION:	Extensive significant problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Immersion bath associated with Leechwell holy we	II, 40 metres north	east of Leechwell Cottage, Totnes
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021390
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth - Notifiable plants	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Woodbury Camp, Stoke Fleming		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019783
CONDITION:	Extensive significant problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Hillfort known as Slapton Castle, Stokenham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019236
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Roman settlement site at Bantham Ham, Thurlesto	ne	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019322
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Hilltop enclosure at Yellowberries Copse, 430 met	res west of Higher	Turtley, Ugborough
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019325
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102

TEIGNBRIDGE



© Teignbridge District Council

SITE NAME:	Former stables to Stover House, Stover, Teigngrace
DESIGNATION:	Listed Building grade II*, RPG grade II
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Commercial company

1308968

Built as stables, 1779. The stables were stripped out when they were superseded by a larger stable block in 1843, and were converted to a magnificent backdrop to the newly laid out gardens for the 11th Duke of Somerset. They are a key feature of Stover's grade II designed landscape. Now in very bad condition due to the spread and distortion of single ashlar front, rusting cramps, and water and vegetation damage. Currently fenced off. Repairs are being discussed as part of a wider improvement scheme to the adjoining park.

Contact: Annie Evans 0117 975 0673

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



© Historic England

SITE NAME:	The Granite Lodge adjacent A38 approx 1550 metres NNW of Stover House, Teigngrace
DESIGNATION:	Listed Building grade II*, RPG grade II
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Local authority

Disused pedimented lodges, with linking screen, gates, and flank walls to former drive to Stover House. Likely c1830, possibly by Philip Hardwick. Banded rusticated granite ashlar with slate roofs. South west lodge has had urgent strucural repair carried out. North east lodge in better condition, but vacant with graffiti on the internal plaster wall. Connecting portico appears to be in reasonable condition but has not been closely inspected. Repairs are being discussed as part of a wider scheme of improvements to the park.

Contact: Annie Evans 0117 975 0673

-	raw .	
	THE THEFT	

Church of St Mary the Virgin, Bickington DESIGNATION: Listed Place of Worship grade I CONDITION: Poor PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1097150

1308943

LIST ENTRY NUMBER:

SITE NAME:

Parish church. C15 Nave, chancel, with early C16 north aisle, west tower restored in 1883-4 when the south wall, south porch, and east and west gables of north aisle were rebuilt. Devonian limestone, with granite detail in the medieval work and Ham stone used in the C19. Slated roofs with lots of tingles. Tall tower with cementitious pointing and vegetation growth. Black and green staining to east end at high level.

Contact: Annie Evans 0117 975 0673



© Historic England

© Historic England

SITE NAME:	Church of St Michael, Ilsington, Teignbridge
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1240794

Sizeable Anglican parish church. Chancel and transepts late C13 or early C14, south transept may be earlier. Nave and aisles enlarged and partly rebuilt in C15 or early C16. Rendered stone walls where exposed, of granite and slatestone rubble. Tower of coursed granite rubble. Slated roofs. Nave, transepts and chancel wagon roofs intersect over crossing as a fine ribbed vault. Very damp; cementicious pointing and render trapping moisture in walls and roofs nearing the end of their lives. Condition of interior has declined since last inspection in 2014 so added to the Register in 2019.

Contact: Annie Evans 0117 975 0673



SITE NAME:	Church of St Thomas, Mamhead
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Fair
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1170048

Parish church. Probably C13 or earlier in origin with surviving early windows in the chancel, C15 three-bay north aisle, south transept (now the baptistery) probably CI3 or CI4 but much altered, CI5 tower. CI9 restorations including one attributable to Anthony Salvin. Red sandstone and grey limestone rubble and red sandstone dressings and slate roofs. Works to repair stonework and remove ivy were undertaken in 2017-2018.

Contact: Annie Evans 0117 975 0673

© Historic England

SITE NAME:	Earthwork (possibly civil war) on Bovey Heath, Bovey Tracey		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002657
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

SITE NAME:	Bishop's Palace,	Chudleigh		
DESIGNATION:	Scheduled Monu	ıment, LB grade II*	LIST ENTRY NUMBER:	1008679
CONDITION:	Generally satisfactory problems	ctory but with significant localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Denbury camp,	Denbury and Torbryan		
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1003857
CONDITION:	Extensive significant problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree grow	Scrub/tree growth		No
OWNER TYPE:	Local authority		CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Earthwork enclosure south of Blackall's Copse, Exminster			
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1004579
CONDITION:	Generally unsatis problems	Generally unsatisfactory with major localised problems		Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Linear round barrow cemetery at Castle Park, Alphington, Exminster			
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1012347
CONDITION:	Extensive significant problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Kingskerswell Manor House, Kingskerswell			
DESIGNATION:	Scheduled Monument, LB grade II, CA		LIST ENTRY NUMBER:	1020875
CONDITION:	Extensive signific	Extensive significant problems		Declining
PRINCIPAL VULNERABILITY:	Collapse	Collapse		No
OWNER TYPE:	Private, multiple	Private, multiple owners		Daniel Bashford 07824 103102
SITE NAME:	Prehistoric field	system and settlements on Kerswe	ell Down and Whilt	porough Common, Kingskerswell
DESIGNATION:	Scheduled Monu	ıment	LIST ENTRY NUMBER:	1021377
CONDITION:	Extensive signific	ant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree grow	∕th	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple of	owners	CONTACT:	Daniel Bashford 07824 103102
	SITE NAME:	Oxton House, Kenton		he picturesque grounds comprised lawns, peries, parkland and a lake. In the C20 the
	DESIGNATION:	Registered Park and Garden grade II, 7 LBs	property was oci into apartments.	cupied by a school before being divided The pleasure grounds are neglected and
	CONDITION:	Generally unsatisfactory with major localised problems	much of the park parkland planting	k is ploughed, with considerable loss of g.
	VULNERABILITY:	Medium		
	TREND:	Declining		
	NEW ENTRY?:	No		
	OWNER TYPE:	Private, multiple owners		
	LIST ENTRY NUMBER:	1001269	Contact: Jo McA	llister 0117 975 0696

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Stover Park, Teigngrace
DESIGNATION:	Registered Park and Garden grade II, 7 LBs
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	High
TREND:	Stable
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners

1001268

Late C18 gardens, pleasure grounds and park in divided ownership. A large area of the park is run by the County Council as a country park and other parts developed as mineral workings. The main house and environs are in use as a school. The setting is under threat from development, including road widening and housing allocation. A parkland plan was produced through a Natural England Stewardship Scheme in 2014. An application to the National Lottery Heritage Fund (to implement the plan's recommendations) is being revised.

Contact: Jo McAllister 0117 975 0696

SITE NAME:	Bovey Tracey, Pottery Road, Bovey Tracey		
DESIGNATION:	Conservation Area, SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Maureen Pearce (LPA) 01626 215705

TORRIDGE



March 1	
THE RESIDENCE OF THE PARTY OF T	
The state of the s	
IV S	TO THE REAL PROPERTY.

0	Historic	Eng	land

SITE NAME:	Richmond Dock, Northam
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1140140

Dry dock, 1856. It is said to have been the largest dry dock in the Bristol Channel at the time it was built. The dock is now vacant. In 2015 the gates were in poor condition, and no repair proposals have been made to Historic England. Ongoing discussions for alternative uses and greater regeneration proposals are being held with the Local Planning Authority. It is understood that the site may now been in new ownership, as of 2020, but this has not been confirmed.

Contact: Catherine Marlow 0117 975 0732



© Historic England Archive

SITE NAME:	World War II air traffic control building 400 metres north west of Seckington Cross, on the former airfield of RAF Winkleigh, Winkleigh
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Commercial company

The monument is a World War II brick and concrete control tower. Although structurally sound, the tower has suffered from vandalism and lack of maintenance and has failing concrete as a result of oxidising steel reinforcement.

LIST ENTRY NUMBER:

Contact: Charlotte Russell 01271 831505



© John Warlow. Source Historic England

SITE NAME:	Church of St Helen, Abbotsham
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1104408

1020765

Anglican parish church. Cruciform plan with early C13 nave and chancel; tower of c.1300 to north east and early C14 south chapel. Restored 1870. Coursed slatestone rubble with ashlar dressings; gabled slate roofs with C19 copings and kneelers. C15 waggon roofs, plastered walls. Pointed chamfered arches to transepts. Beautifully-carved reredos, and other good interior fittings. Water penetration through parapets and historic fractures to south tower wall causing rot to embedded timbers, fracturing and failure of masonry bonding to south transept gable end.

Contact: Annie Evans 0117 975 0673

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS Conservation Area Listed Building I PA ΝP RPG

Unitary Authority World Heritage Site



SITE NAME:	Church of All Saints, Bradford
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1105088

Parish church with Norman origins, C14 chancel, C15 north aisle and porch, restored from a ruinous state in 1869 and between 1875 to 1889. The tower suffers from water ingress and damp and the bell ropes drip with water. The rest of the church is damp. The gutters and downpipes need overhauling.

Contact: Annie Evans 0117 975 0673

© Historic England



SITE NAME:	Church of St Bridget, Bridgerule
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1104976

Externally the tower has black staining, indicating that is damp. There are no rainwater goods and areas of cement ribbon pointing. The church is in need of patch repointing. This has contributed to some paint blistering internally, such as in the east end of the south aisle.

Contact: Annie Evans 0117 975 0673

Contact: Annie Evans 0117 975 0673

© Historic England



SITE NAME:	Church of St Mary and St Gregory, Frithelstock
DESIGNATION:	Listed Place of Worship grade I, SM
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1105177

Parish church. C13 north wall; chancel rebuilt and south aisle built in early C14; c1500 south-east chapel and roofs, and west tower rebuilt in C15. Coursed slatestone rubble; squared and coursed stone to tower; ashlar dressings. Stone-gabled and gabled slate roofs. This church is in need of external patch repointing and the overhaul and renewal of all of the rainwater goods is required.

© Historic England

-	1	

© Douglas G Wood, Source Historic England Archive

SITE NAME:	Church of St Nectan, Hartland
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1333125

Parish church CI4 and CI5 restored cI850 and I910-II. Nave, chancel, north and south aisles, transept chapels and porches, west tower. Coursed rubble walls, gable ended slate roofs. Tall four-stage tower. Fine interior retaining early fabric and with early painted plaster, medieval wagon roofs, rood screen with evidence of ancient colouring, benches c1540 and C17, late Norman font. Water penetration through south aisle walls, affecting fine wall monuments internally, water penetration to tower walls, leaching and mortar wash-out, causing damp and rot to embedded timbers.

Parish church. Mid C13 nave and chancel; late C13 north transept; early C15 south aisle and west tower which was restored in 1892. Rainwater goods do not appear to be

Contact: Annie Evans 0117 975 0673



© Historic	England

SITE NAME:	Church of St Swithun, Littleham
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1105152

Contact: Annie Evans 0117 975 0673

installed. The tower shows signs of damp.

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



(C)	Historic	England

SITE NAME:	Church of Holy Trinity, Milton Damerel
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Very bad
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation

1162778

walls. Gable-ended slate roof. Tower destroyed by lightning in 1879 and in ruins for 20 years but re-opened in 1904. Tower partly re-erected in 1892 and rebuilt 1910-1911. The church is generally well maintained, but needs a significant project to secure loose stones on top of the tower, tackle damp problems, and repair roofs. The congregation has made three applications for National Lottery Heritage Fund Grant for Places of Worship but has not been successful.

Parish church. Late C13 origins with C14 fabric, remodelled in C16 restored c1900 to 1910. Stone rubble

Contact: Annie Evans 0117 975 0673



© Historic England

© Historic England

© Historic England

SITE NAME:	Church of St Margaret, Northam
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1169270

1169270

Large parish church. Mainly C15 although lower part of tower is older. Thoroughly restored between 1849 and 1865. The roof slating is nearing the end of its life, and the ceilings are plastered to the underside of roofing battens. The church was awarded a National Lottery Heritage Fund Grant for Places of Worship in late 2016 for the repair of the nave and vestry roofs. Work was planned to start on site by the end of 2018 but has been delayed awaiting slate supply from the quarry. At least one further phase of work to the roofs will then be needed.

Contact: Annie Evans 0117 975 0673



SITE NAME:	Church of St Petrock, Petrockstow
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1333084

Parish church. C14 aisle and C15 tower, the rest rebuilt from 1878 to 1880. There are some problems with the roof covering, especially verges and eaves, parapets and flashings. The rainwater goods and drainage need repair and overhauling. This has led to water ingress and salt damage to the interior. The congregation made an application for funding under the National Lottery Heritage Fund Grant for Places of Worship scheme in 2017 but was not successful. The congregation is continuing with fund-

Contact: Annie Evans 0117 975 0673



SITE NAME:	Church of St Michael, Shebbear
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1309558

Rural Devon church. Most significant feature is mid-C12 south doorway. Plain nave and south aisle; simple rendered tower. Damp interior with carpet hiding salt damage to floor. Prone to vegetation growth in the external ground gutter and there is a poor vestry valley gutter arrangement, worsening the internal problems. The roof is poor and is likely to require recovering in the forseeable future.

Contact: Annie Evans 0117 975 0673



© Historic England

SITE NAME:	Church of the Holy Cross, Tetcott
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1252173

Parish church. Fabric of nave and chancel C13, south transept C13 or C14, tower C15, vestry probably C19. Stone rubble with granite dressings, the tower ashlar masonry with granite quoins and lacing, slate roofs. Fittings including several good C18 wall monuments. The church forms part of an important group including Tetcott Manor and associated buildings. The north wall is still moving, even after works to stop the roof spreading. Tower masonry needs repointing and the roof re-covering to prevent water ingress to the belfry and ringing chamber.

Contact: Annie Evans 0117 975 0673

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS I PA ΝP

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

SITE NAME:	Bowl barrow 250 metres north east of Oak Cottag	ge, forming part of	a round barrow cemetery, Ashwater
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020079
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 540 metres south east of Sandymoor Ashwater	Cross, forming par	rt of a round barrow cemetery,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020080
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 770 metres south east of Sandymoor Ashwater	Cross, forming par	rt of a round barrow cemetery,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020081
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Hillfort known as Castle Hill Settlement, 350 metr	es south of Woolle	igh Bridge, Beaford
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021417
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Holy well 480 metres north west of Beaford Mill, E	Beaford	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015142
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Hallsannery limekiln, Bideford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004578
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 420 metres north west of Dural Cro	ss, Bradworthy	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016643
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Bowl barrow 280 metres south west of Upcott	Cross, Broadwoodwi	dger
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019546
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
ITE NAME:	Two bowl barrows 690 metres and 760 metres	south west of Lewort	thy, Clawton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017974
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
ITE NAME:	Four bowl barrows 110 metres and 360 metres west of Wrangworthy Cross forming part of a round bar cemetery, East Putford		y Cross forming part of a round barro
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018526
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
ITE NAME:	Three fishponds at Winslade, East Putford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017979
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Two bowl barrows 600 metres and 750 metres west of Wrangworthy Cross forming part of a round bar cemetery, East Putford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018515
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Two bowl barrows one immediately north and opart of a round barrow cemetery, East Putford	one 100 metres south	of Commonmoor Cottage forming
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018516
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
ITE NAME:	Hender Barrow, Halwill		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019727
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Bowl barrow 520 metres west of Higher Welsford	, Hartland	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017138
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Ring cairn and bowl barrow 540 metres south wes	t of Higher Welsfo	rd, Hartland
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017139
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow on Ugworthy Moor 510 metres sout	h of West Ugwort	hy House, Holsworthy Hamlets
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017977
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 60 metres west of St James's Church	, Luffincott	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020476
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Cairn 325 metres north west of Tibbett's Lookout	, Lundy	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016019
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Cairn 530 metres west of Quarterwall Cottages, L	undy	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016012
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Chambered tomb 165 metres north east of the Ro	ocket Pole Pond, Lu	ındy
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1015931
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Charlotte Russell 01271 831505

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Chapel remains, cemetery and prehistoric settleme	ent on Beacon Hill,	Lundy
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016040
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Natural erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Coastal defence platforms at the Mousehole and T	rap, Lundy	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016031
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Granite quarry on East Sidelands, Lundy		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016041
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Hut circle and small enclosure 270 metres north w	est of The Old Ligi	hthouse, Lundy
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016014
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Long house and enclosure 160 metres north of W	idow's Tenement, L	undy
Designation:	Scheduled Monument	LIST ENTRY NUMBER:	1018547
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Medieval settlement immediately south of Halfway	Wall, Lundy	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017647
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Ruined cottages and well 190 metres north west o	f Quarterwall Cott	ages, Lundy
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016027
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505

- A Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	The Widow's Tenement medieval settlement and p	rehistoric settleme	ent sites, Lundy
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017646
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Moated site at Grange Farm, Merton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017867
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Cross ridge dyke on Godborough Castle earthwork north west of Turner's Wood, Northam		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002640
CONDITION:	Unknown	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 685 metres NNE of Moorfield, Shebbear / Peters Marland		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017963
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	World War II air traffic control building 400 metres north west of Seckington Cross, on the former airfield of RAF Winkleigh, Winkleigh		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020765
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Charlotte Russell 01271 831505

WEST DEVON

© Historic England



SITE NAME:

3.7.2.7.4.7.2.	Gulworthy / Bere Ferrers
DESIGNATION:	Scheduled Monument, WHS
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1002667

Gawton Mine complex

Former copper and arsenic mine and processing complex, comprising a full range of buildings from cooperage to engine houses. The site has suffered damage from vehicles. Despite previous extensive clearance and emergency support works, vegetation has reclaimed extensive areas of the monument and the temporary propping is showing signs of failure. The structures remain at risk.

Contact: Nick Russell 0117 975 0671

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 - Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS



Kelly House, Kelly DESIGNATION: Listed Building grade I CONDITION: Poor OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C (C) OWNER TYPE: Private

C18 house with serious maintenance issues. Roof is in need of renewal, rear medieval wing is partly propped. Main house is weathertight and maintenance is gradually being addressed.

© Historic England

LIST ENTRY NUMBER:	1318194	Contact: Annie Evans 0117 975 0673



SITE NAME: Stable block north of Kelly House, Kelly DESIGNATION: Listed Building grade II* CONDITION: Very bad OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY A(A)OWNER TYPE: Private

Stables, 1740. Partly used, part collapsed.

© Historic England

LIST ENTRY NUMBER: 1104813 Contact: Annie Evans 0117 975 0673



SITE NAME: Woolladon Farmhouse, Meeth DESIGNATION: Listed Building grade II* CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: A (New entry) OWNER TYPE: Private LIST ENTRY NUMBER: 1326490

Farmhouse. Dated 1666 and part of an unaltered farm complex. Plastered cob walls. Gable ended thatched roof. Three-room and through-passage plan, outshut and stairs, two-storey porch and adjoining outshut in front of lower end of hall. Two part stairs, both flights rising from the hall to upper and lower ends. It retained original four-light chamfered wooden mullion windows, chamfered door frames and staircase solid oak treads. A remarkably interesting single phase plan surviving unaltered since the C17. Thatch fire in 2019 leaving extensive damage; now (2020) protected by temporary roof.

Contact: Rhiannon Rhys 0117 975 0685



SITE NAME:

	Tawton
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1105370

Farmstead including farmhouse with medieval origins attached jointed cruck barn, further barn probably C19 and southern range with large malthouse as well as further open fronted barns and stabling. Mainly cob-built. Roofing and roof structures in very poor condition. Historic England has been in discussion with the current owners regarding repairs and maintenance. Further work is urgently needed.

© Historic England

© Historic England

Greenslade Farmhouse, North

Contact: Annie Evans 0117 975 0673



© Historic England

SITE NAME:	Tavistock Abbey, Tavistock
DESIGNATION:	Scheduled Monument, 16 LBs, CA, WHS
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1020401

Tavistock Abbey is central to the history and character of the medieval town which developed around it. The Saxon foundation of the abbey places it amongst the earliest of the medieval religious houses founded in Britain. Its occupation from 974 to 1539 included continuous use by the same Benedictine order for over five and a half centuries. The ruins are suffering from water ingress and damaging vegetation growth. Historic England has offered a grant to carry out a full condition survey and conservation management plan for the West Gate House (Betsy Grimbals Tower) and the Still Tower.

Contact: Andy Crabb 01626 832093

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).



© West Devon Borough Council

SITE NAME:	Guildhall and police station, Abbey Place, Guildhall Square, Tavistock
DESIGNATION:	Listed Building grade II*, SM, CA, WHS
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F(D)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1309358

Completed 1848, incorporating medieval fabric in part. Use as court ended 1997 and police station has relocated. The first known example of a combined police station and magistrates' court. Roof in poor condition and fabric in general urgently needs attention. Tavistock Heritage Trust is working with the Town Council owners, who have been awarded a second National Lottery Heritage Fund grant to turn the building into a Mining Landscape WHS Interpretation Information Centre. The volunteers' work progressed well but paused due to Covid 19. It is hoped the interpretation centre may open in 2021.

Contact: Annie Evans 0117 975 0673

		Els.
	E PRE	
THE STATE OF		-
N.A.	4	- 600 - 640
105		201
A.C.	Park	E
014	2	1
	THE	

© Historic England

© Historic England

SITE NAME:	Church of St Mary, Bratton Clovelly
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1326312

Parish church. Mainly mid to late C14 although the chancel may be earlier, porch probably early C15; various repairs made in C19 and restored from 1891 to 1892. Granite and slate rubble walls with granite dressings, tower is constructed of coursed dressed granite blocks of irregular sizes. Medieval structure enhanced by the remarkable survival of a large number of wall paintings. The church suffers from water ingress and there is some structural movement at the east end.

Contact: Annie Evans 0117 975 0673



SITE NAME:	Church of Holy Cross, Highampton
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1165844

Parish church. C12 origins with a late C15 tower and the rest of the church rebuilt in 1837. Restored in 1876. The church suffers from water ingress and damp possibly associated with its very exposed position. The tower walls are damp; the congregation and appointed architect are investigating the causes. Active insect infestation to ceiling timber ribs. Some roof slates cracked and missing. North west window buckled and missing glass.

Contact: Annie Evans 0117 975 0673



© Historic England

Church of St Mary, Walkhampton, West Devon
Listed Place of Worship grade I, CA
Poor
C (C)
Religious organisation

1105371

Church in an elevated position on the edge of Dartmoor about a mile outside the village. Largely C14 but may be pre-conquest in foundation. Aisle and tower added in the C15. Local rubble with granite dressings. Cornish slate roofs. Tower is wet with large amounts of vegetation growth. Valley gutter and rainwater goods in need of work.

Contact: Annie Evans 0117 975 0673

SITE NAME:	Iron Age defended settlement in Dunterue Wood, 570 metres south of Castle Head, Dunterton		
DESIGNATION:	Scheduled Monument, RPG grade I	LIST ENTRY NUMBER:	1020273
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Andy Crabb 01626 832093

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 F. Under repair or in fair to good.

LIST ENTRY NUMBER:

- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

SITE NAME:	Bowl barrow 375 metres north east of Higher Ewo	orthy, Germanswee	k	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020084	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093	
ITE NAME:	Bowl barrow 620 metres north of Higher Eworthy, Germansweek			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017971	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093	
ITE NAME:	Morwellham Quay: transport infrastructure, part of Gulworthy	of the water contro	system and a manganese mill,	
DESIGNATION:	Scheduled Monument, 3 LBs, WHS	LIST ENTRY NUMBER:	1021461	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable	
RINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093	
ITE NAME:	Gawton arsenic mine and flue, Gulworthy / Bere F	errers		
esignation:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1002667	
ONDITION:	Extensive significant problems	TREND:	Declining	
RINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Russell 0117 975 0671	
ITE NAME:	Round barrow cemetery and beacon at Heathfield, / Brentor	, 650 metres west o	of Moorlands, Lamerton / Milton Abbo	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020075	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
RINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093	
TE NAME:	Roman forts, marching camps and associated monu	uments, North Taw	ton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021151	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093	
TE NAME:	Two bowl barrows 200 metres north east of New	land Cross, North	Tawton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017131	
CONDITION:	Extensive significant problems	TREND:	Declining	
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Guide post at Place Cross, Okehampton Hamlets		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020069
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Inscribed stones in vicarage garden, Tavistock		
SITE NAME: DESIGNATION:	Inscribed stones in vicarage garden, Tavistock Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1003871
		LIST ENTRY NUMBER:	1003871 Declining
DESIGNATION:	Scheduled Monument, CA, WHS Generally unsatisfactory with major localised		

DORSET (UA)



© Historic England

SITE NAME:	Maiden Street Methodist Church, Maiden Street, Weymouth
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private

LIST ENTRY NUMBER: | | 42294

SITE NAME:

Former Methodist church. Fire in January 2002 left the church a gutted, roofless ruin. Subsequent health and safety works completely cleared the interior. Consent was granted in 2007 but not implemented for conversion/reconstruction to mixed residential and commercial use. The site changed hands in 2016. Historic England has been in discussions with the new owner regarding the options available to them and in Nov 2019, planning permission and listed building consent applications for residential conversion/reconstruction were granted.

Contact: Eve Van Der Steen 01 179750685

This large scheduled site contains 12 individually listed

buildings, six of which are in poor or very bad condition. Several of the buildings were included in a 2013/14



© Historic England

	gatehouse and walling, gateway, granary and tithe barn, St Peter's Abbey, Abbotsbury
DESIGNATION:	Scheduled Monument and Listed Buildings - 5 grade I; 5 grade II*; 4 grade II, LB grade II, part in CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Mixed, multiple owners
	1015693 and 1305224;

The dovecote, malthouse, outer

condition survey to inform a future repair strategy. The published photo shows the dovecote, which is disused and unstable. It has potential for low-key use in conjunction with a visitor attraction centred on the nearby Tithe Barn complex. In 2018/19, Historic England Repair Grants helped to fund project development work on the Tithe Barn and also works to the Granary.

Contact: Katy Hoskyn 0117 975 1311

| 1118743; 1305209; 1118706; | 1118747; 1172244; 1118746; | 1172220; 1324227; 1118741; | 1118742; 1118744; 1118745;

© Historic England

SITE NAME:	Parnham House, Beaminster
DESIGNATION:	Listed Building grade I, RPG grade II*
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1221178

1118748

C16 country house, much refashioned and extended in 1810 by Nash and remodelled internally in early C20. Suffered catastrophic fire in April 2017. The majority of the roof and internal structure have been destroyed, but the external shell largely survives. Complex ownership circumstances left the building unprotected for three years, and Historic England's Conservation Engineer has assessed its condition as increasingly vulnerable. In March 2020 the property was sold and in April Historic England started pre-application discusions on its restoration with the new owner.

Contact: Jenny Chesher 0117 975 0686

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

OWNER TYPE:

SITE NAME:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Literary and Scientific Institute, East Street, Bridport
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	F (F)

1118999

Charity (non-heritage) Contact: Sarah Ball 0117 975 0666

remain.

6

© Historic England

5.7.2.7.0.4.12.	warehouse, Station Road, West Bay, Bridport
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Private

1228722

Messrs Norman goods

C18, possibly older. Former bonded stores. The yard is being used as an antiques/pop-up market. Discussions between Dorset Council, the head lessee and Historic England regarding the repair of the listed building and use of the site have stalled but in May 2020, a listed building consent application for retrospective works to provide access to the upper floors was under consideration by Dorset Council.

Contact: Eve Van Der Steen 01 179750685

Contact: Jenny Chesher 0117 975 0686

Contact: Katy Hoskyn 0117 975 1311

Founded 1835 as Mechanics Institute and reconstituted 1855 as Literary and Scientific Institute. Bridport

Development Trust delivered project to repair and extend the building with National Lottery Heritage Fund support and grant-aid from Historic England. Works largely completed in 2018 although some outstanding issues

© Historic England

SITE NAME:	North Lodges, Lulworth Castle, Coombe Keynes
DESIGNATION:	Scheduled Monument and Listed Building grade II*, part in RPG grade II, part in CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

Ornamental gate lodges and gateway to Lulworth Castle, 1785. The lodges and gates are stable but the flank walls and mock-fortifications are in poor condition. The estate is exploring possible funding for the repair of the lodges. It is hoped that with the Estate's newly appointed architect working on nearby Bindon, that the Estate's direct labour will be able to carry out repairs to the walls. They are currently successfully repairing outer walls.

	51
484	С
4	С
	C
	Р
	С

© Historic England

SITE NAME:	Marshwood Castle, Marshwood
DESIGNATION:	Scheduled Monument and Listed Building grade II*, LB grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OVA (A JED TV/DE	D. i

1016685 and 1323333

OWNER TYPE: Private

LIST ENTRY NUMBER: 1002836 and 1324105

The site comprises a rectangular earthwork enclosure with a moat (partly filled). There are substantial remains of the internal ramparts and the motte. These masonry structures require consolidation and careful on-going management. The masonry is precarious and currently being eroded by both stock and vegetation.



SITE NAME: Abbey Church of St Mary, St Sansóm and St Branwalader, Milton Abbas Listed Building grade I, RPG DESIGNATION: grade II*, CA CONDITION: Poor OCCUPANCY: Occupied/in use PRIORITY CATEGORY:

Formerly church of a Benedictine abbey now used as a school chapel. Mainly C14, upper part of tower and north transept C15. Restored c1790 by J Wyatt and 1865 by Sir Gilbert Scott. Walls of stone and flint with ashlar dressings. Nave and aisles were not rebuilt after fire in C14. Repairs to roofs, windows, floors and drainage has been completed with Viridor funding. Transept roofs and tower louvres remain vulnerable.

© Historic England

Religious organisation LIST ENTRY NUMBER: 1304822 Contact: Sarah Ball 0117 975 0666

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.

OWNER TYPE:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

LIST ENTRY NUMBER:

OWNER TYPE:

LIST ENTRY NUMBER



© Historic England

SITE NAME:	Icehouse at Ringstead, 660 metres south west of Pit House, Osmington
DESIGNATION:	Scheduled Monument
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1020358

A small C19 icehouse, built to serve the needs of the local fishing community. It is now in unmanaged woodland, with trees and ivy growing over it. The roots will have weakened the roof and there is a high risk of damage from falling trees.

Contact: Katy Hoskyn 0117 975 1311



© Historic England

SITE NAME:	Cart shed and stables 10 metres south of Waddon House, Portesham
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private

repair and conversion to holiday let use has been approved. The roof has been re-thatched, but other works still needed.

Former stables and cart shed, dated 1702. Application for

LIST ENTRY NUMBER: 1152606 Contact: Sarah Ball 0117 975 0666



© Historic England Archive

SITE NAME:	Rufus Castle, Church Ope Road, Easton, Portland
DESIGNATION:	Scheduled Monument and Listed Buildings - I grade I; I grade II*, LB grade II, CA, WHS
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)

Private

Present structure probably late C15, on site of earlier building captured in 1142 by Earl Robert of Gloucester. Ruinous and in need of conservative repair and consolidation. Scheme of repair and urgent works carried out in 2010 with Historic England grant although more work is still needed. Site has a new owner and discussions are at an early stage. The monument also includes the ruins of a C12 grade II* church, St Andrews, believed to stand on the site of an earlier Saxon church.

LIST ENTRY NUMBER: 1002698 and 1280727; 1205384 Contact: Sarah Ball 0117 975 0666



© Historic England Archive

SITE NAME:	Church of St Peter, Grove Road, Grove, Portland
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1205607

Former Church of England church in robust Romanesque style, erected in 1872. Designed by Major General Edmund du Cane, built by convict labour from Portland's prison and later transferred to the parish. No longer used for worship and in poor condition. Relatively complete interior of interest as an undivided space and with robust contemporary fittings. Local Authority considering taking action against owner.

Contact: Eve Van Der Steen 01179750685



© Historic England Archive

SITE NAME:	Sherborne House, Newland, Sherborne
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1110694

Grand town house of c1720 with earlier elements, formerly a school but last used in the 1990s. Fine internal features include a grand stairhall decorated with Thornhill wall paintings. Planning permission for gallery/office use approved in 2015 but only the installation of a lift/stair extension and external repairs were completed. The interior was damaged by dry rot and still requires refurbishment. The house was sold in 2018 and a new charitable trust has been set up for it. Pre-application discussions regarding a new use continue with the Trust, Historic England and the local authority.

Contact: Jenny Chesher 0117 975 0686

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

OWNER TYPE:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

Secure,	
	A 988
© Historic Engla	ınd

SITE NAME:	Sturminster Newton Castle, Sturminster Newton
DESIGNATION:	Scheduled Monument and Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

1002719 and 1324461

1003209 and 1119426

Private, multiple owners

1002715 and 1110841

Ruins of C14 stone built manor house within Sturminster Newton Castle, a probable Iron Age promontory fort overlooking the River Stour. Upstanding remains are in a very precarious position and a considerable amount of consolidation work is urgently required to avoid significant areas of collapse. Historic England architectural survey team has recorded the structure. The site is up for sale and we hope to engage in discussions with the new owner as soon as possible to discuss the most urgent works.

Contact: Katy Hoskyn 0117 975 1311

6.5	
A COLUMN	

© Historic England

SITE NAME: Tithe Barn, Church Lane, Sydling St. Nicholas	
Scheduled Monument and Listed Building grade II*, part in CA	}
CONDITION: Very bad	
OCCUPANCY: Vacant/not in use	
PRIORITY CATEGORY: A (A)	
OWNER TYPE: Private	

Impressive C16 barn. It has an interesting constructional history and is part of an important complex of historic buildings. Its gradual deterioration has recently shown signs of accelerating with the loss of an area of roof covering. Progress on finding a suitable use has stalled and part of the protective roof covering has become dislodged.

C15 barn with C18 outbuildings and alterations. No longer in agricultural use. Works have been undertaken to support the structure but deterioration is on-going and

Contact: Sarah Ball 0117 975 0666

part of the roof has collapsed.



© Historic England

SITE NAME:	Barn and outbuilding range, Tarrant Abbey Farm, Tarrant Crawford
DESIGNATION:	Scheduled Monument and Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)

Contact: Nick Croxson 07795 665645



© Historic England

SITE NAME:	Holditch Court Tower, Thorncombe
DESIGNATION:	Scheduled Monument, LB grade
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1002835

This monument includes part of a fortified house situated within a farmyard. The part of the fortified house survives as a three-storeyed roofless rectangular plan tower with a projecting circular stair-turret in the south west angle and stands to a height of approximately eight metres. Historic England funded a project development grant in 2018 for the removal of the ivy, a condition survey and measured survey which are underway. It is anticipated this will inform a future repair project.

Contact: Sarah Ball 0117 975 0666



© Historic England

SITE NAME:	Stable Block immediately south east of Little Toller Farm, Toller Fratrum
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1228876

Mid C16 stable building, forming part of a working farm but currently disused. The thatch is in a very degraded state leading to partial collapse of the roof and rear wall structure at the end of 2011. The stable building has been scaffolded with a temporary roof structure which is protecting the collapsed historic fabric. The long term repair of the structure needs to be explored along with possible funding sources.

Contact: Sarah Ball 0117 975 0666

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 Full ladar repair on in fair to good.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).



© Historic England

SITE NAME:	Former Methodist Chapel, Dorchester Road, Tolpuddle
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Charity (heritage)

1119849

Contact: Sarah Ball 0117 975 0666

Contact: Katy Hoskyn 0117 975 1311

Contact: Eve Van Der Steen 01179750685

THE CANADA	Marie De
	ATTENDED.
The state of the s	A CONTRACTOR OF STATE
	A STATE OF THE STA
是100 · 2013 · 2013	
1,000,000,000	Principle Apple 12 Sept.
AND THE PARTY NAMED IN	《
	VA. STEELE
The second second	1 10 10
TOTAL STATE OF THE	A STATE OF THE STA
Annual American	Charles 19
	100 Sept 100
We or constant	Section 1985
The second second	A STATE OF THE STA
	The state of the state of
CHANGE OF THE PARTY OF THE PART	MODELLE SANDARDE
	The Report of the Park
Real Control of the Control	

© Historic England

SITE NAME:	Royal Naval Cordite Factory at Holton Heath, Wareham St. Martin
DESIGNATION:	Scheduled Monument, LB grade II
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Mixed, multiple owners

1019151

The cordite factory was built in 1916, and continued to produce explosives until 1945. It covers a large area of land, with lots of small workshops surrounded by earth banks, to contain any accidental blasts. A large number of individual buildings and structures still remain, now in varying degrees of collapse, and a programme of works to identify and repair the most significant of these is urgently needed. Much of the site is within a nature reserve and only open to the public by prior arrangement. The area included in the scheduling was extended in 2016.

Former Methodist church, c1818, and the meeting place of the Tolpuddle Martyrs. Building bought by Tolpuddle Old Chapel Trust at the beginning of 2015. Historic England grant awarded in 2014 to carry out emergency works and undertake project development work; completed in spring 2015. National Lottery Heritage Fund development grant completed in 2017 and the Trust has secured further Lottery funding for Stage 2 repairs starting in 2019. Historic England offered match-funding for repairs to fabric of former chapel anticipated to start on site in 2020.



© Historic England

© Historic England

SITE NAME:	Higher Abbott's Wootton Farmhouse, Abbott's Wootton Lane, Whitchurch Canonicorum
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Private

Former monastic site, now farmhouse. Following sale in 2017, significant unauthorised works were undertaken internally. There has been a partial collapse of the historic ceiling at first floor level and cracks are visible on the east gable. In May 2020 temporary protection had been applied to some windows. Discussions with the owner to reverse the inappropriate works and repair the building have currently stalled and Historic England is exploring all options with Dorset Council to secure the reinstatement of the building.

SITE NAME:

Grotto 250 metres south east of St Giles House, Wimborne St. Giles

DESIGNATION:

Listed Building grade II*, RPG

grade II*

Poor

N/A

E (E)

1120131

1216622

CONDITION:

OCCUPANCY:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

PRIORITY CATEGORY:

OWNER TYPE:
LIST ENTRY NUMBER:

Private

Grotto c1751-53, located 250 metres to the south east of the house, at the east end of a winding channel of water running towards the lake. One of several garden buildings situated in the C17 and C18 landscape. The Grotto was subject to a major programme of repair during 2014, under a Natural England Stewardship scheme. External consolidation and much of the internal shell decoration reinstated. A further and final phase of repair to the structural vaults which are largely below water level, is needed.



SITE NAME:

Manor Farm barn, Winterborne Clenston

DESIGNATION:

Listed Building grade I

CONDITION:

Very bad

OCCUPANCY:

N/A

PRIORITY CATEGORY:

C (C)

OWNER TYPE:

Mixed, multiple owners

Huge late C16 tithe barn part used for storage. The hammerbeam roof may have been reused from a monastic building at Milton Abbey. Partial roof collapse resulted in Historic England funding the erection of scaffolding as a temporary roof support. These repair works were completed in 2008, but there has been no further progress and the building is slowly deteriorating.

© Historic England

LIST ENTRY NUMBER: 1110166 Contact: Sarah Ball 0117 975 0666

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: Sarah Ball 0117 975 0666



© Historic England

SITE NAME:	Bindon Abbey (site), Wool	
DESIGNATION:	Scheduled Monument, LB grade I	
CONDITION:	Fair	
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	E (E)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1002703	

Bindon Abbey was founded as a Cistercian monastic house in 1172 and converted to a fine house in 1539 following the Dissolution. Much of the building was burnt down during the English Civil War but some of the structure survives as a standing ruin of up to seven metres high. The masonry was very precarious, with several recent falls of stone, and supported by scaffolding. In 2018, the estate received a repair grant from Historic England and, as of Summer 2019, most of the main repairs are complete. Still some ivy removal and consolidation needed elsewhere on the site, but progressing well.

Contact: Katy Hoskyn 0117 975 1311



@ Marcus Chantrey, Benjamin Beauchamp Architect

SITE NAME:	Church of St Peter and St Paul, Market Place, Blandford Forum
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation

1251913

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

This church is a prime example of Georgian church architecture outside London. It was rebuilt after a fire between 1732 and 1739 to designs by John and William Bastard. The external stonework is in poor condition and there is water ingress to the interior causing damage to the plaster work. A Development grant was awarded by the National Lottery Heritage Fund in January 2019 for repairs works to nave roof, parapet gutters, high level masonry and internal plasterwork.

Contact: Sarah Ball 0117 975 0666



© Historic England

SITE NAME:	Church of St John, The Harbour, West Bay, Bridport
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Fair
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation

1279418

This 1930s Arts and Crafts church is a simple, low building on the quayside, built to serve the local fishing community. Since it was added to the Heritage at Risk register in 2014, the congregation have made very good progress. Although there are still some areas of damp, and the leaded windows are leaking, the roofs have been repaired and the building is beginning to dry out. Some further work is needed but it is improving.

Contact: Katy Hoskyn 0117 975 1311



© Marcus Chantrey, Benjamin Beauchamp Architects

SITE NAME:	Church of St Andrew, The Street, Charmouth
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1215162

Parish church. Entirely rebuilt 1836-8, by Charles Fowler in Gothic Revival style. Forest marble plinth, chert rubble walls with "long-and-short style" stone dressings. Window dressings of Beer stone. Boscastle slate roofs; nave has tiled ridge. Tower and church walls are cement pointed which is failing causing water ingress. Unsuccessful in attempts to secure funding from National Lottery Heritage Fund. Reroofing of north porch underway in Spring 2019. Further works are planned and funding being sought to address the water ingress and damage caused.

Contact: Sarah Ball 0117 975 0666



© lames Menzies

SITE NAME:	Church of All Saints, Straits, Portland
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1281831

Church built in 1914-17 to design of Crickmay and Sons. Built of Portland ashlar with predominantly tiled roofs. Traditionally orientated with large nave, north and south aisles, north and south transepts, chancel, side chapel and vestry. Windows in south chapel by Clayton and Bell. Strong design of single phase with meticulous detailing and retaining most of its original fittings. Window stonework in poor condition.

Contact: Sarah Ball 0117 975 0666

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Parish Church of St Andrew, Trent
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation

1323927

Medieval church with a richly decorated interior. There is internal damp, and structural work to the tower and spire is needed. The church also has important and high quality medieval and Victorian window glass, some of which is showing signs of structural instability and paint detachment. Conservation works have been undertaken to the east and west windows and external protective glazing installed on the east window. The chancel roof has been recovered. Repair works to the spire are due to commence in June 2019.

Contact: Sarah Ball 0117 975 0666

SITE NAME:	Group of round barrows on Ridgeway			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002760	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311	
SITE NAME:	Abbotsbury Castle (camp), Abbotsbury			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002710	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Sasha Chapman 0117 975 1338	
SITE NAME: Four bowl barrows 725 metres ESE of Wears Farm, Abbotsbury				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002825	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Sasha Chapman 0117 975 1338	
SITE NAME:	Group of five round barrows on White Hill, Abbotsbury			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003213	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Sasha Chapman 0117 975 1338	
SITE NAME:	Round barrow 230 yards (210 metres) east of Wh	ite Hill Plantation, A	Abbotsbury	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002824	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Sasha Chapman 0117 975 1338	
SITE NAME:	Two fishponds in Oddens Wood, Abbotsbury			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015696	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Sasha Chapman 0117 975 1338	

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

SITE NAME:	Two round barrows on Wears Hill, Abbotsbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002731
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sasha Chapman 0117 975 1338
SITE NAME:	The Double Barrow, a bowl barrow in Kite Hill Pla Affpuddle	intation 250 metres	s south east of Roger's Hill Cottages
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015900
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Length of deer park bank and ditch at Alderholt, A	lderholt	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002394
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Barrow east of Burnt House Bottom, Alton Pancra	ıs	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002862
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow on Worgret Heath, 320 metres nort	h west of High Tor	, Arne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018190
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Linear boundary 870 metres south west of Spring	Farm, Ashmore	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020729
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Earthwork 80 yards (70 metres) long, north west o	of Coombe Bottom	, Askerswell
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002734
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

DOWNER TYPE: Private Bowl barrow on Beaminster Down 530 metres south east of East Axnoller Farm, Beaminster Dosphan Scheduled Monument USTENTRY NUMBER, 1015049 CONDITION: Generally unsatisfactory with major localised problems RERECIDENT Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 Arable clipping NEW ENTRY: Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 CONTACT: C	SITE NAME:	Round barrow north west of Coombe Bottom,	Askerswell	
problems Vehicle damage/erosion - extensive NEW DATEN: No DOWNER TYPE Private CONTACT: Katy Hoskyn 0117 975 13 13 13 13 14 14 14 14 14 14 14 14 14 14 14 14 14	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003061
Development Bowl barrow on Beaminster Down 530 metres south east of East Axnoller Farm, Beaminster Scheduled Monument Sched	CONDITION:		TREND:	Declining
Bowl barrow on Beaminster Down 530 metres south east of East Axnoller Farm, Beaminster 2005GRATION: Scheduled Monument LIST ENTRY NUMBER: 1015049 Generally unsatisfactory with major localised problems CONTITION: Arable clipping NEW UNITY: No October New Unity: N	PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
ESEGNATION Scheduled Monument LIST ENTRY NUMBER 1015049 ONDITION Generally unsatisfactory with major localised problems RINCIPAL VULNERABILITY: Arable clipping NEW ENTRY: No Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 TE NAME: Bowl barrow on Beaminster Down 770 metres north east of Higher Meerhay Farm, Beaminster ESIGNATION Scheduled Monument LIST ENTRY NUMBER 1015050 ONDITION Generally unsatisfactory with major localised problems RINCIPAL VULNIRABILITY: Arable clipping NEW ENTRY: No Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 TE NAME: Bowl barrow \$15 metres south of the southern extent of Horse Close Plantation, Bere Regis ESIGNATION Scheduled Monument LIST ENTRY NUMBER 1015386 ONDITION Extensive significant problems TREND: Declining NEW ENTRY: No RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No ONDITION Extensive significant problems REGIS ESIGNATION Scheduled Monument LIST ENTRY NUMBER 1015378 TE NAME: Bowl barrow \$90 metres north east of Bere Down Farm, Bere Regis ESIGNATION Scheduled Monument LIST ENTRY NUMBER 1015378 TE NAME: Bowl barrow \$90 metres north east of Bere Down Farm, Bere Regis ESIGNATION Scheduled Monument LIST ENTRY NUMBER 1015378 TE NAME: Bowl barrow \$10 metres east of Bere Heath Farm, Bere Regis ESIGNATION Scheduled Monument LIST ENTRY NUMBER 1015378 TE NAME: Bowl barrow \$610 metres east of Bere Heath Farm, Bere Regis ESIGNATION Scheduled Monument LIST ENTRY NUMBER 1015365 ONDITION: Contact: Katy Hoskyn 0117 975 13 TE NAME: Bowl barrow \$610 metres east of Bere Heath Farm, Bere Regis ESIGNATION Scheduled Monument LIST ENTRY NUMBER 1015365 ONDITION: Contact: Katy Hoskyn 0117 975 13 TE NAME: Bowl barrow 790 metres north east of Haywards Farm, Bere Regis ESIGNATION Scheduled Monument LIST ENTRY NUMBER 1015330 NEW ENTRY: No ONDITION: Extensive significant problems TRIND: Declining Declining	WNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
Generally unsatisfactory with major localised problems RINCIPAL VULNERABILITY: Arable clipping NEW ENTRYE No DWNER TYPE: Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 HTE NAME Bowl barrow on Beaminster Down 770 metres north east of Higher Meerhay Farm, Beaminster Designation: Scheduled Monument LIST ENTRY NUMBER: 1015050 CONDITION: Generally unsatisfactory with major localised problems RINCIPAL VULNERABILITY: Arable clipping NEW ENTRYE No DWNER TYPE: Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 HIENAME Bowl barrow 515 metres south of the southern extent of Horse Close Plantation, Bere Regis DESIGNATION: Extensive significant problems TREND: Declining NEW ENTRYE No CONTACT: Katy Hoskyn 0117 975 13 HIENAME Bowl barrow 590 metres north east of Bere Down Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015378 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: No DWNER TYPE: Private CONTACT: Katy Hoskyn 0117 975 13 HIENAME Bowl barrow 610 metres east of Bere Heath Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: No DWNER TYPE: Private CONTACT: Katy Hoskyn 0117 975 13 HIENAME Bowl barrow 610 metres east of Bere Heath Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: No DWNER TYPE: No DWNER TYPE: No DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: No DWNER TYPE: Government or agency CONTACT: Katy Hoskyn 0117 975 13 HIENAME Bowl barrow 790 metres north east of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: No DWNER TYPE: Government or agency CONTACT: Katy Hoskyn 0117 975 13 HIENAME Bowl barrow 790 metres north east of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUM	SITE NAME:	Bowl barrow on Beaminster Down 530 metres	south east of East Axr	noller Farm, Beaminster
Problems Problems Arable clipping NEW ENTRY: No Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 STENAME: Bowl barrow on Beaminster Down 770 metres north east of Higher Meerhay Farm, Beaminster DESIGNATION! Scheduled Monument LIST ENTRY NUMBER: DOUBLING Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY: No DOWNER TYPE: Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 STENAME: Bowl barrow 515 metres south of the southern extent of Horse Close Plantation, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: DOUBLING SCHEDING SCHEDING Private CONTACT: Katy Hoskyn 0117 975 13 STENAME: Bowl barrow 590 metres north east of Bere Down Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: DOWNER TYPE: Private CONTACT: Katy Hoskyn 0117 975 13 STENAME: Bowl barrow 590 metres north east of Bere Down Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: DOELINING SCHEDING SCHEDING SCHEDING RENCEPAL VULNERABILITY: Arable ploughing NEW ENTRY: No DOWNER TYPE: Bowl barrow 610 metres east of Bere Heath Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: DOWNER TYPE: Bowl barrow 610 metres east of Bere Heath Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: DOWNER TYPE: Bowl barrow 610 metres east of Bere Heath Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: No DOWNER TYPE: Bowl barrow 610 metres east of Bere Heath Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: No DOWNER TYPE: Bowl barrow 790 metres north east of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: DOWNER TYPE: DOWNER TYPE: Bowl barrow 790 metres north east of Haywards Farm, Bere Regis DESIGNATION: DECLINING DECL	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015049
Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 Bowl barrow on Beaminster Down 770 metres north east of Higher Meerhay Farm, Beaminster Down 770 metres north east of Higher Meerhay Farm, Beaminster Down 770 metres north east of Higher Meerhay Farm, Beaminster Down 770 metres north east of Higher Meerhay Farm, Beaminster Down 770 metres north east of Higher Meerhay Farm, Beaminster Down 770 metres north east of Bere Down Farm, Bere Regis Designation: CONDITION: Generally unsatisfactory with major localised problems Arable dipping Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 EXEND: Declining Mixed multiple owners CONTACT: Katy Hoskyn 0117 975 13 EXEND: Declining Mixed multiple owners CONTACT: Katy Hoskyn 0117 975 13 EXEND: Declining MIXED: Declining MIXED: Declining MIXED: No DOWNER TYPE: No CONTACT: Katy Hoskyn 0117 975 13 EXEND: Declining MIXED: MIXED: MIXED: MIXED: Declining MIXED: DECLINING MIXED:	CONDITION:		TREND:	Declining
Bowl barrow on Beaminster Down 770 metres north east of Higher Meerhay Farm, Beaminster Scheduled Monument Generally unsatisfactory with major localised problems RIRINGIPAL VULNERABILITY: Arable clipping Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 With Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 With Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 With Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 With Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 With Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 With Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 With Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 With Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 With Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 With Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 With Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 With Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 With Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 With Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 With Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 With Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 With Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 With Mixed, multiple owners With Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 With Mixed, multiple owners With Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 With Mixed, multiple owners With Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 With Mixed, multiple owners With Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 With Mixed, multiple owners With Mixed, multiple ow	PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
Scheduled Monument LIST ENTRY NUMBER: 1015050 Generally unsatisfactory with major localised problems PRINCIPAL WUNERABILITY: Arable clipping NEW ENTRY): No Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 STENAME: Bowl barrow 515 metres south of the southern extent of Horse Close Plantation, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015386 Extensive significant problems TREND: Declining PRINCIPAL WUNERABILITY: Arable ploughing NEW ENTRY): No DOWNER TYPE: Private CONTACT: Katy Hoskyn 0117 975 13 STENAME: Bowl barrow 590 metres north east of Bere Down Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015378 DOWNER TYPE: Private CONTACT: Katy Hoskyn 0117 975 13 STENAME: Bowl barrow 610 metres east of Bere Heath Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015365 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015365 STENAME: Bowl barrow 610 metres east of Bere Heath Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015365 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015330 DEVENTED TIPE: NEW ENTRY: No	OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 131
Generally unsatisfactory with major localised problems Generally unsatisfactory with major localised problems Arable clipping MEW ENTRY): Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 Arable clipping Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 Arable clipping Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 Arable ploughing NEW ENTRY): No Declining NEW ENTRY: No Declining NEW ENTRY: No Declining NEW ENTRY: No Deviner Type: Private CONTACT: Katy Hoskyn 0117 975 13 Arable ploughing NEW ENTRY: No Declining DECLINING Raty Hoskyn 0117 975 13 DESIGNATION: CONTACT: Katy Hoskyn 0117 975 13 DESIGNATION: DECLINING DESIGNATION: DECLINING DESIGNATION: DECLINING Stable DESIGNATION: DECLINING REND: DECLINING REND: DECLINING REND: DECLINING DECLINING REND: DECLINING DECLINING REND: DECLINING REND: DECLINING REND: DECLINING REND: DECLINING REND: DECLINING DECLINING REND: DECLINI	SITE NAME:	Bowl barrow on Beaminster Down 770 metres	north east of Higher N	Meerhay Farm, Beaminster
Problems Problems Arable clipping New ENTRY: Arable clipping New ENTRY: No Declining New ENTRY: No Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 Arable Bowl barrow 515 metres south of the southern extent of Horse Close Plantation, Bere Regis Designation: Scheduled Monument LIST ENTRY NUMBER: 1015386 Declining RENCIPAL VULNERABILITY: Arable ploughing New ENTRY: No Declining New ENTRY: No Devener Type: Private Bowl barrow 590 metres north east of Bere Down Farm, Bere Regis Designation: Scheduled Monument LIST ENTRY NUMBER: 1015378 Declining NEW ENTRY: No Declining RENCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No Declining TREND: Descination: Scheduled Monument LIST ENTRY NUMBER: 1015365 Generally unsatisfactory with major localised problems Generally unsatisfactory with major localised problems Descination: CONTACT: Stable PRINCIPAL VULNERABILITY: Animal burrowing - extensive Downer Type: Government or agency CONTACT: Katy Hoskyn 0117 975 13 EXERNATION: CONTACT: Katy Hoskyn 0117 975 13 EXENCIPAL VULNERABILITY: No Downer Type: Declining NEW ENTRY: No Declining New ENTRY: No Declining Declining New ENTRY: No Declining Declin	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015050
Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 13 ATENAME: Bowl barrow 515 metres south of the southern extent of Horse Close Plantation, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015386 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No CONTACT: Katy Hoskyn 0117 975 13 ATENAME: Bowl barrow 590 metres north east of Bere Down Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015378 Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No CONTACT: Katy Hoskyn 0117 975 13 Arable ploughing NEW ENTRY: No CONTACT: Katy Hoskyn 0117 975 13 Arable ploughing NEW ENTRY: No CONTACT: Katy Hoskyn 0117 975 13 Arable ploughing NEW ENTRY: No CONTACT: Katy Hoskyn 0117 975 13 Arable ploughing RENCIPAL VULNERABILITY: Arable ploughing CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Animal burrowing - extensive CONTACT: Katy Hoskyn 0117 975 13 Animal burrowing - extensive NEW ENTRY: No CONTACT: Katy Hoskyn 0117 975 13 Animal burrowing - extensive NEW ENTRY: No CONTACT: Katy Hoskyn 0117 975 13 Arable ploughing REND: Stable CONTACT: Katy Hoskyn 0117 975 13 Arable Downer Type: No CONTACT: Katy Hoskyn 0117 975 13 Arable Downer Type: No CONTACT: Katy Hoskyn 0117 975 13 Arable Downer Type: No CONTACT: Katy Hoskyn 0117 975 13 Arable Downer Type: No CONTACT: Katy Hoskyn 0117 975 13 Arable Downer Type: No CONTACT: Katy Hoskyn 0117 975 13 Arable Downer Type: No CONTACT: Katy Hoskyn 0117 975 13 CONTACT: Katy Hoskyn 0117 975 13 Arable Downer Type: No CONTACT: Katy Hoskyn 0117 975 13 Arable Downer Type: No CONTACT: Katy Hoskyn 0117 975 13 Arable Downer Type: No CONTACT: Katy Hoskyn 0117 975 13 Arable Downer Type: No CONTACT: Katy Hoskyn 0117 975 13 Arable Downer Type: No CONTACT: Katy Hoskyn 0117 975 13 Arable Downer Type: No CONTACT: Katy Hoskyn 0117 975 13 Arable Downer Type: No CONTACT: Katy Hoskyn 0117 975 13 Arable Do	CONDITION:		TREND:	Declining
Bowl barrow 515 metres south of the southern extent of Horse Close Plantation, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015386 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No DWINER TYPE: Private CONTACT: Katy Hoskyn 0117 975 13 SITE NAME: Bowl barrow 590 metres north east of Bere Down Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015378 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No DOWNER TYPE: Private CONTACT: Katy Hoskyn 0117 975 13 SITE NAME: Bowl barrow 610 metres east of Bere Heath Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015365 CONDITION: Generally unsatisfactory with major localised problems CONDITION: Generally unsatisfactory with major localised problems CONDITION: Generally unsatisfactory with major localised problems CONDITION: Government or agency CONTACT: Katy Hoskyn 0117 975 13 SITE NAME: Bowl barrow 790 metres north east of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015330 DESIGNATION: Scheduled Monument LIST ENTRY: NO	PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
Designation: Scheduled Monument LIST ENTRY NUMBER: 1015386 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No DWNER TYPE: Private CONTACT: Katy Hoskyn 0117 975 13 BITE NAME: Bowl barrow 590 metres north east of Bere Down Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015378 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: No DWNER TYPE: Private CONTACT: Katy Hoskyn 0117 975 13 BITE NAME: Bowl barrow 610 metres east of Bere Heath Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015365 CONDITION: Generally unsatisfactory with major localised problems CONDITION: Generally unsatisfactory with major localised problems CONDITION: Government or agency CONTACT: Katy Hoskyn 0117 975 13 BITE NAME: Bowl barrow 790 metres north east of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY: No DWNER TYPE: Government or agency CONTACT: Katy Hoskyn 0117 975 13 BITE NAME: Bowl barrow 790 metres north east of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015330 DESIGNATION: Arable ploughing NEW ENTRY: No	OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 131
Extensive significant problems TREND: Declining RENDCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No CONTACT: Katy Hoskyn 0117 975 13 EXTENAME: Bowl barrow 590 metres north east of Bere Down Farm, Bere Regis CONDITION: Extensive significant problems TREND: Declining REND: Stable REND: WE ENTRY? NO DWNER TYPE: Government or agency REND: REND: Katy Hoskyn 0117 975 13 RETENAME: Bowl barrow 610 metres east of Bere Heath Farm, Bere Regis DESIGNATION: Scheduled Monument LUST ENTRY NUMBER: 1015365 Stable RENDIPAL VULNERABILITY: Animal burrowing - extensive REND: NO DWNER TYPE: Government or agency REND: Katy Hoskyn 0117 975 13 RETENAME: Bowl barrow 790 metres north east of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LUST ENTRY NUMBER: 1015330 DECINION: Extensive significant problems REND: Declining REND: Declining REND: Declining	SITE NAME:	Bowl barrow 515 metres south of the southern	extent of Horse Clos	e Plantation, Bere Regis
Arable ploughing NEWENTRY?: No DOWNER TYPE: Private CONTACT: Katy Hoskyn 0117 975 13 SITE NAME: Bowl barrow 590 metres north east of Bere Down Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015378 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEWENTRY?: No DOWNER TYPE: Private CONTACT: Katy Hoskyn 0117 975 13 SITE NAME: Bowl barrow 610 metres east of Bere Heath Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015365 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No DOWNER TYPE: Government or agency CONTACT: Katy Hoskyn 0117 975 13 SITE NAME: Bowl barrow 790 metres north east of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015330 DECEMBRICIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015386
DWNER TYPE: Private CONTACT: Katy Hoskyn 0117 975 13 SITE NAME: Bowl barrow 590 metres north east of Bere Down Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015378 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No CONTACT: Katy Hoskyn 0117 975 13 SITE NAME: Bowl barrow 610 metres east of Bere Heath Farm, Bere Regis CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1015365 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No CONTACT: Katy Hoskyn 0117 975 13 SITE NAME: Bowl barrow 790 metres north east of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015330 SITE NAME: Bowl barrow 790 metres north east of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015330 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	CONDITION:	Extensive significant problems	TREND:	Declining
Bowl barrow 590 metres north east of Bere Down Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015378 DECIGNATION: Extensive significant problems TREND: Declining De	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Scheduled Monument Extensive significant problems TREND: Declining RINCIPAL VULNERABILITY: Arable ploughing Private Bowl barrow 610 metres east of Bere Heath Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: DESIGNATION: Scheduled Monument CONTACT: Stable TREND: Stable PRINCIPAL VULNERABILITY: Animal burrowing - extensive DEVINITE NAME: Bowl barrow 790 metres north east of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: No CONTACT: Katy Hoskyn 0117 975 13 TREND: DEVINITE NAME: Bowl barrow 790 metres north east of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: No CONTACT: Katy Hoskyn 0117 975 13 TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No	OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 131
Extensive significant problems TREND: Declining Arable ploughing NEW ENTRY?: No CONTACT: Katy Hoskyn 0117 975 13 Extensive significant problems Private Bowl barrow 610 metres east of Bere Heath Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015365 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No DOWNER TYPE: Government or agency CONTACT: Katy Hoskyn 0117 975 13 EXTENAME: Bowl barrow 790 metres north east of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015330 EXEMPTION: Scheduled Monument LIST ENTRY NUMBER: 1015330 EXEMPTION: Scheduled Monument EXEMPTION: Declining REND: Declining NEW ENTRY?: No	SITE NAME:	Bowl barrow 590 metres north east of Bere Do	wn Farm, Bere Regis	
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No DOWNER TYPE: Private CONTACT: Katy Hoskyn 0117 975 13 ENTE NAME: Bowl barrow 610 metres east of Bere Heath Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015365 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No DOWNER TYPE: Government or agency CONTACT: Katy Hoskyn 0117 975 13 ENTE NAME: Bowl barrow 790 metres north east of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015330 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015378
Private Bowl barrow 610 metres east of Bere Heath Farm, Bere Regis Scheduled Monument LIST ENTRY NUMBER: 1015365 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Animal burrowing - extensive Bowl barrow 790 metres north east of Haywards Farm, Bere Regis Scheduled Monument LIST ENTRY: Katy Hoskyn 0117 975 13 CONTACT:	CONDITION:	Extensive significant problems	TREND:	Declining
Bowl barrow 610 metres east of Bere Heath Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015365 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No DOWNER TYPE: Government or agency CONTACT: Katy Hoskyn 0117 975 13 ENTER NAME: Bowl barrow 790 metres north east of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015330 EXTENDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015365 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Animal burrowing - extensive OWNER TYPE: Government or agency CONTACT: Katy Hoskyn 0117 975 13 SITE NAME: Bowl barrow 790 metres north east of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015330 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 131
Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Animal burrowing - extensive New Entry?: No CONTACT: Katy Hoskyn 0117 975 13 Bowl barrow 790 metres north east of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	SITE NAME:	Bowl barrow 610 metres east of Bere Heath Fai	rm, Bere Regis	
problems PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No CONTACT: Katy Hoskyn 0117 975 13 Bowl barrow 790 metres north east of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015330 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015365
Government or agency Bowl barrow 790 metres north east of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing CONTACT: Katy Hoskyn 0117 975 13	CONDITION:		TREND:	Stable
Bowl barrow 790 metres north east of Haywards Farm, Bere Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015330 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015330 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	OWNER TYPE:	Government or agency	CONTACT:	Katy Hoskyn 0117 975 131
Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	SITE NAME:	Bowl barrow 790 metres north east of Hayward	ls Farm, Bere Regis	
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015330
	CONDITION:	Extensive significant problems	TREND:	Declining
DWNER TYPE: Private CONTACT: Katy Hoskyn 0117 975 13	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No

- A Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Bowl barrow on Warren Heath, 350 metres sou	th west of Warren H	louse, Bere Regis
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019367
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Katy Hoskyn 0117 975 131
SITE NAME:	Four bowl barrows 240 metres east of Oak Cot	tage, Bere Regis	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015369
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 131
SITE NAME:	Long barrow on Bere Down, 1100 metres north	east of Roke Barn, B	ere Regis
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015329
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 131
SITE NAME:	The End Barrow, a bowl barrow 320 metres sou	th west of White Ho	use, Bere Regis
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017462
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Katy Hoskyn 0117 975 131
SITE NAME:	Three bowl barrows 230 metres south west of h	Haywards Farm, Bere	Regis
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015333
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 131
SITE NAME:	Two bell barrows and a bowl barrow, 200 metre	es north east of Hayw	vards Farm, Bere Regis
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015332
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 131
SITE NAME:	Two bowl barrows on South Heath, 900 metres	SSE of The Bungalow	, Bere Regis
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017694
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Katy Hoskyn 0117 975 131

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Bell barrow on Blackhill Clump 470 metres north of	of Mintern's Ferry,	Bere Regis / Turners Puddle
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015899
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Two bowl barrows both 350 metres north east of	Spring Garden Bar	n, Bere Regis / Turners Puddle
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015898
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	St Leonard's Chapel, Blandford Forum		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1002726
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Roman villa south east of East Farm, Bradford Abb	as	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002414
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Educational (independent)	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bell barrow in Highfield Plantation and two bowl b Bradford Peverell	arrows immediately	north west of Forty Acre Plantation
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019415
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow 380 metres west of Whitfield Farm, I	Bradford Peverell	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019639
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Group of barrows in Seven Barrow Plantation, Bra	dford Peverell	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002812
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 Slow decay; solution agreed but for tyet implemented.

 Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial like) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

	JTH WEST / DORSET (UA)		
SITE NAME:	Long barrow and four bowl barrows 500 metres n	orth west of Whit	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019416
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Discontinuous surviving sections of Roman aquedu	ct, Bradford Pever	ell / Dorchester
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1002730
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Culliford Tree long barrow and group of round bar	rrows, Broadmayne	e / Whitcombe
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003304
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Field system in Old Park, Bryanston		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1002427
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 66564
SITE NAME:	Two bowl barrows on Lord's Down 580 metres so	outh east of Crawt	horne Farm, Burleston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017277
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	The Castle hillfort, Cattistock		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004545
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Round barrow on Dickley Hill, Cerne Abbas		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002849
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable
	A I. I I I. !	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Arable ploughing	INCAA EINTIKTII.	INO

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Settlement on Dickley Hill, Cerne Abbas		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002852
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow 470 metres south east of Down Ba	rn: an outlier of the (Chaldon Down barrow group, Chaldo
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008146
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow 650 metres south of Chaldon Dow cemetery, Chaldon Herring	n Buildings: part of th	ne Chaldon Down round barrow
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008523
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	The Round Pound, an enclosure on Chaldon Do	wn, Chaldon Herring	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018436
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Two bowl barrows 200 metres south east of Hil	l Barn: two of a group	o of three barrows, Chaldon Herring
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008162
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Wardstone Barrow: a bowl barrow on the Dors Chaldon Herring	et coastal ridge 300 n	netres south of Chideock Farm,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008676
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow 350 metres south of Gorcombe Fa	rm, Charlton Marsha	II
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014848
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Scheduled Monument CONDITION: Extensive significant problems MDD: Declining RENCHAL VOLUMENTAL MARKED Ploughing NOVERTHE NO CONSTRUCT Private CONTROL	SITE NAME:	Bowl barrow 500 metres south west of Gorcom	be Farm, Charlton M	arshall
PRINCE VALUE AGENTY NO. Private Bowl barrow 650 metres south west of Gorcombe Farm, Charlton Marshall Private Bowl barrow 650 metres south west of Gorcombe Farm, Charlton Marshall Private CONDITION. Extensive significant problems RECOMMENTATION Bowl barrow 1020 metres south east of Charlsworth Cottages, Charlton Marshall Declining RECOMMENTATION Scheduled Monument CONDITION. Generally unastificatory with major localised problems Bowl barrow on Wood Hill 310 metres north east of Cowden, Charlminster Bowl barrow on Wood Hill 310 metres north east of Cowden, Charlminster Bowl barrow on Wood Hill 310 metres north east of Cowden, Charlminster Bowl barrow on Wood Hill 310 metres north east of Cowden, Charlminster Bowl barrow on Wood Hill 310 metres north east of Cowden, Charlminster Bowl barrow on Wood Hill 310 metres north east of Cowden, Charlminster Bowl barrow on Wood Hill 310 metres north east of Cowden, Charlminster Bowl barrow on Wood Hill 310 metres north east of Cowden, Charlminster Bowl barrow on Wood Hill 310 metres north east of Cowden, Charlminster Bowl barrow on Wood Hill 310 metres north east of Cowden, Charlminster Bowl barrow on Wood Hill 310 metres north east of Cowden, Charlminster Bowl barrow on Wood Hill 310 metres north east of Cowden, Charlminster Bowl barrow on Wood Hill 310 metres north east of Cowden, Charlminster Bowl barrow on Wood Hill 310 metres north east of Cowden, Charlminster Bowl barrow on Charle significant problems RECOMBINE Bowl barrow on Cheselbourne CONTACT: Katy Hoskyn 0117 975 1311 Bowl barrow on Cheselbourne West Down, Cheselbourne CONTACT: Katy Hoskyn 0117 975 1311 Bowl barrow on Creech Barrow Hill, Church Knowle / Steeple CONTACT: Nick Crosson 07795 665645 Bowl barrow on Creech Barrow Hill, Church Knowle / Steeple Contact: Contact: Contact: Contact: Contact: Contact: Con	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014847
Device Private	CONDITION:	Extensive significant problems	TREND:	Declining
Bowl barrow 650 metres south west of Gorcombe Farm, Charlton Marshall Scheduled Monument Extensive significant problems Private Bowl barrow 1020 metres south east of Charisworth Cottages, Charlton Marshall Bowlows Virginia Private Bowl barrow 1020 metres south east of Charisworth Cottages, Charlton Marshall Basician Inc. Scheduled Monument Basician Inc. Scheduled Monument Basician Inc. Scheduled Monument Bowlows Inc. Arabic clipping New PRIVATE Bowlows Inc. Private Bowl barrow on Wood Hill 310 metres north east of Cowden, Charmismer Bowlows Bowlows Bowlows Bowlows Bowlows Bowlows Bowlows Bow	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Scheduled Monument usT ENTRY NUMBER 1014849 CONDITIONS Extensive significant problems TRANS: Declining MENCIPE VLUNERABUTY: Arable ploughing NEW BYTHY: NICK Crosson 07795 665645 Arable ploughing NEW BYTHY: NICK Crosson 07795 665645 Arable clipping NEW DETRY:	OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
Extensive significant problems IRAND: Declining RRADDAL UNBEARBUTY: Arable ploughing NEW STATES NO CONTACT: Nick Crosson 07795 665645 RRADDAL UNBEARBUTY: Arable ploughing NEW STATES ROOM DEPOSITION Scheduled Monument IBI-BHIRT NUMBER: 1014846 CONTACT: Nick Crosson 07795 665645 RRADDAL ULBEARBUTY: Arable clipping NEW STATES NO CONTACT: Nick Crosson 07795 665645 RRADDAL ULBEARBUTY: Arable clipping NEW STATES NO CONTACT: Nick Crosson 07795 665645 RRADDAL ULBEARBUTY: Arable ploughing NEW STATES RRADDAL ULBEARBUTY: No CONTACT: Nick Crosson 07795 665645 RRADDAL ULBEARBUTY: No CONTACT: RATE NO READ STATES NO READ STATES NO CONTACT: RATE NO READ STATES N	ITE NAME:	Bowl barrow 650 metres south west of Gorcom	be Farm, Charlton M	arshall
RENCEMA VOLUMERABILITY: Arable ploughing NEW BUTTEY: No NICK Croxson 07795 665645 WERNAME: Bowl barrow 1020 metres south east of Charisworth Cottages, Charlton Marshall SESSANION. Scheduled Monument UST BUTTEY NUMBER: 1014846 Generally unsatisfactory with major localised problems NEW BUTTEY: No OCNITACT: Nick Croxson 07795 665645 WERNAME: Bowl barrow on Wood Hill 310 metres north east of Cowden, Charminster SOSGONITON. Scheduled Monument UST BUTTEY NUMBER: 1019395 EXERCIPAL VOLUMERABILITY: No Declining NEW BUTTEY: No OCNITACT: Nick Croxson 07795 665645 WERNAME: Bowl barrow on Wood Hill 310 metres north east of Cowden, Charminster SOSGONITON. Extensive significant problems IRRND: Declining NEW BUTTEY: No OCNITACT: Katy Hoskyn 0117 975 1311 WERNAME: ROUND BUTTEY NO OCNITACT: Katy Hoskyn 0117 975 1311 WERNAME: ROUND BUTTEY NO OCNITACT: Katy Hoskyn 0117 975 1311 WERNAME: ROUND BUTTEY NO OCNITACT: Katy Hoskyn 0117 975 1311 WERNAME: ROUND BUTTEY NO OCNITACT: Katy Hoskyn 0117 975 1311 WERNAME: ROUND BUTTEY NO OCNITACT: Katy Hoskyn 0117 975 1311 WERNAME: ROUND BUTTEY NO OCNITACT: Katy Hoskyn 0117 975 1311 WERNAME: ROUND BUTTEY NO OCNITACT: Katy Hoskyn 0117 975 1311 WERNAME: ROUND BUTTEY NO OCNITACT: Katy Hoskyn 0117 975 1311 WERNAME: ROUND BUTTEY NO OCNITACT: Katy Hoskyn 0117 975 1311 WERNAME: ROUND BUTTEY NO OCNITACT: Katy Hoskyn 0117 975 1311 WERNAME: ROUND BUTTEY NO OCNITACT: Katy Hoskyn 0117 975 1311 WERNAME: ROUND BUTTEY NO OCNITACT: Katy Hoskyn 0117 975 1311 WERNAME: ROUND BUTTEY NO OCNITACT: Katy Hoskyn 0117 975 1311 WERNAME: Long butTEY NO OCNITACT: Katy Hoskyn 0117 975 1311 WERNAME: Long butTEY NO OCNITACT: Katy Hoskyn 0117 975 1311 WERNAME: Long butTEY NO OCNITACT: Nick Croxson 07795 665645 WERNAME TYPE NICK NICK NICK NICK NICK NICK NICK NICK	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014849
Device Private Private Contract: Nick Crosson 07795 665645 STENAME: Bowl barrow 1020 metres south east of Charisworth Cottages, Charlton Marshall DESIGNATION: Scheduled Monument UST DITRY NUMBER: 1014846 CONDITION problems Private CONTACT: Nick Crosson 07795 665645 STENAME: Arable clipping NEW BITTEY: No CONTACT: Nick Crosson 07795 665645 STENAME: Bowl barrow on Wood Hill 310 metres north east of Cowden, Charminster Designation: Scheduled Monument ISTENAME: 1019395 Declining NEW BITTEY: No CONTACT: Katy Hoskyn 0117 975 1311 TENAME: Bowl barrow east of Forston Farm, Charminster DESIGNATION: Scheduled Monument UST DITRY NUMBER: 1002851 DETENAME: Round barrow east of Forston Farm, Charminster DESIGNATION: Scheduled Monument UST DITRY NUMBER: 1002851 DETENAME: Round barrow east of Forston Farm, Charminster DESIGNATION: Scheduled Monument UST DITRY NUMBER: 1002851 DETENAME: Round barrow on Cheselbourne West Down, Cheselbourne DESIGNATION: Scheduled Monument UST DITRY NUMBER: 1002878 DESIGNATION: Scheduled Monument UST DITRY NUMBER: 1013792 DESIGNATION: Scheduled Monument UST DITRY NUMBER: 1013792 DECINING DESIGNATION: Scheduled Monument, CA UST DITRY NUMBER: 1014830 DECINING DECINI	CONDITION:	Extensive significant problems	TREND:	Declining
Bowl barrow 1020 metres south east of Charisworth Cottages, Charlton Marshall Discontation: Scheduled Monument Generally unsatisfactory with major localised problems Private CONTACT: No CONTACT: Nick Croxson 07795 665645 Bowl barrow on Wood Hill 310 metres north east of Cowden, Charminster Bowl barrow on Wood Hill 310 metres north east of Cowden, Charminster Bowl barrow on Wood Hill 310 metres north east of Cowden, Charminster Bowl barrow on Wood Hill 310 metres north east of Cowden, Charminster Bowl barrow on Wood Hill 310 metres north east of Cowden, Charminster Bowl barrow on Wood Hill 310 metres north east of Cowden, Charminster Bowl barrow on Wood Hill 310 metres north east of Cowden, Charminster Bowl barrow on Wood Hill 310 metres north east of Cowden, Charminster Bowl barrow on Wood Hill 310 metres north east of Cowden, Charminster Bowl barrow on Wood Hill 310 metres north east of Cowden, Charminster Bowl barrow on Wood Hill 310 metres north east of Cowden, Charminster Bowl barrow east of Forston Farm, Charminster Declining New Entre: Round barrow east of Forston Farm, Charminster Declining New Entre: Declining New Entre: No Declining Rewich Luinerwalum: Arable ploughing New Entre: Round barrow on Cheselbourne West Down, Cheselbourne DECONITION: Extensive significant problems Ext	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Scheduled Monument UST ENTRY NUMBER: 1014846 CONDITION: Generally unsatisfactory with major localised TREND: Declining RENCEPAL VULNERABILITY: Arable clipping NEW ENTRY: No CONTACT: Nick Croxxon 07795 665645 BIT NAME: Bowl barrow on Wood Hill 310 metres north east of Cowden, Charminster SEGISLANTION: Scheduled Monument UST ENTRY NUMBER: 1019395 CONDITION: Extensive significant problems TREND: Declining BRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No CONTACT: Katy Hoskyn 0117 975 1311 BITE NAME: Round barrow east of Forston Farm, Charminster SEGISLANTION: Scheduled Monument UST ENTRY NUMBER: 1002851 CONDITION: Extensive significant problems TREND: Declining RENCEPAL VULNERABILITY: Arable ploughing NEW ENTRY: No CONTACT: Katy Hoskyn 0117 975 1311 STENAME: Round barrow on Cheselbourne West Down, Cheselbourne CONTACT: Katy Hoskyn 0117 975 1311 STENAME: Round barrow on Cheselbourne West Down, Cheselbourne CONTACT: Katy Hoskyn 0117 975 1311 STENAME: Round barrow on Cheselbourne West Down, Cheselbourne CONDITION: Extensive significant problems TREND: Declining CONDITION: Extensive significant problems TREND: Declining CONDITION: Extensive significant problems CONTACT: Katy Hoskyn 0117 975 1311 CONDITION: Extensive significant problems CONTACT: Katy Hoskyn 0117 975 1311 CONDITION: CONTACT: Katy Hoskyn 0117 975 1311	OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
Generally unsatisfactory with major localised problems PRINCIPAL VILLIERABILITY: Arable clipping Private Private Bowl barrow on Wood Hill 310 metres north east of Cowden, Charminster Seschatron: Scheduled Monument Schedul	SITE NAME:	Bowl barrow 1020 metres south east of Charisw	orth Cottages, Charl	ton Marshall
RINCOPAL VULNERABILITY: Arable clipping NEW ENTRYP: No NoVANDER TYPE: Private CONTACT: Nick Crosson 07795 665645 RIE NAME: Bowl barrow on Wood Hill 310 metres north east of Cowden, Charminster DESGRAFION: Scheduled Monument LST ENTRY NUMBER: 1019395 DECLINING RINCOPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No DEVENTION: CONTACT: Katy Hoskyn 0117 975 1311 Arable ploughing NEW ENTRYP: No DEVENTION: Scheduled Monument LST ENTRY NUMBER: 1002851 DEVENTION: Scheduled Monument LST ENTRY NUMBER: 1002851 DEVENTION: Declining RINCOPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No DEVENTION: Scheduled Monument LST ENTRY NUMBER: 1002851 DEVENTION: Declining RINCOPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No DEVENTION: Scheduled Monument LST ENTRY NUMBER: 1002878 DEVENTION: Scheduled Monument LST ENTRY NUMBER: 1002878 DECLINING RINCOPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No DECLINING RINCOPAL VULNERABILITY: Arable clipping NEW ENTRYP: No DECLINING RINCOPAL VULNERABILITY: Arable clipping NEW ENTRYP: No DECLINING DECLINING RINCOPAL VULNERABILITY: Arable clipping NEW ENTRYP: No DECLINING DECLINING RINCOPAL VULNERABILITY: Arable clipping NEW ENTRYP: No DECLINING DECLINING DECLINING DECLINING RINCOPAL VULNERABILITY: Arable clipping NEW ENTRYP: No DECLINING DEC	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014846
Private Private CONTACT: Nick Croxson 07795 665645 Bowl barrow on Wood Hill 310 metres north east of Cowden, Charminster Scheduled Monument BETEMTRY NUMBER: 1019395 CONDITION: Extensive significant problems IREND: Declining Private CONTACT: Katy Hoskyn 0117 975 1311 STENAME: Round barrow east of Forston Farm, Charminster CONTACT: Katy Hoskyn 0117 975 1311 STENAME: Round barrow east of Forston Farm, Charminster CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1002851 CONDITION: Extensive significant problems TREND: Declining Private CONTACT: Katy Hoskyn 0117 975 1311 STENAME: Round barrow on Cheselbourne West Down, Cheselbourne CONTACT: Katy Hoskyn 0117 975 1311 STENAME: Round barrow on Cheselbourne West Down, Cheselbourne CONTACT: Katy Hoskyn 0117 975 1311 STENAME: Round barrow on Cheselbourne West Down, Cheselbourne CONDITION: Extensive significant problems Extens	CONDITION:		TREND:	Declining
Bowl barrow on Wood Hill 310 metres north east of Cowden, Charminster Scheduled Monument Extensive significant problems Extensive significant problems Rewichter Wulnerability: Arable ploughing Round barrow east of Forston Farm, Charminster Scheduled Monument Extensive significant problems Round barrow east of Forston Farm, Charminster Scheduled Monument Extensive significant problems Rewichter Wulnerability: Arable ploughing Rewichter Wulnerability: Private Round barrow on Cheselbourne West Down, Cheselbourne Scheduled Monument Extensive significant problems Round barrow on Cheselbourne West Down, Cheselbourne Scheduled Monument Extensive significant problems Round barrow on Cheselbourne West Down, Cheselbourne Scheduled Monument Extensive significant problems Round Barrow on Cheselbourne West Down, Cheselbourne Scheduled Monument Extensive significant problems Rewichter Wulnerability: Arable ploughing Rewichter Wulnerability: Arable ploughing Rewichter Wulnerability: Private Contact: Katy Hoskyn 0117 975 1311 Scheduled Monument List Entrity Number: 1013792 Scheduled Monument List Entrity Number: 1013792 Scheduled Monument List Entrity Number: Declining Rewichter Wulnerability: Arable clipping Rewichter Wulnerability: Private Bowl barrow on Creech Barrow Hill, Church Knowle / Steeple Scheduled Monument, CA List Intrity Number: 1014830 Declining Rewichter Wulnerability: Plant growth Rewichter Wulnerability: Plant growth	PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1019395 CONDITION: Extensive significant problems TRIND: Declining NEW ENTRY: No DOWNER TYPE: Private CONTACT: Katy Hoskyn 0117 975 1311 SITE NAME ROUND BARROW East of Forston Farm, Charminster DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002851 CONDITION: Extensive significant problems TRIND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No DOWNER TYPE: Private CONTACT: Katy Hoskyn 0117 975 1311 SITE NAME ROUND BARROW ON Cheselbourne CONTACT: Katy Hoskyn 0117 975 1311 SITE NAME ROUND BARROW ON Cheselbourne West Down, Cheselbourne DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002878 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002878 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: No DOWNER TYPE Private CONTACT: Katy Hoskyn 0117 975 1311 SITE NAME ROUND BARROW ON CHESELBOURNE NEW ENTRY: No DOWNER TYPE Private CONTACT: Katy Hoskyn 0117 975 1311 SITE NAME: Long barrow 360 metres SSW of Chettle House, Chettle DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1013792 CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1013792 CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1013792 CONDITION: Scheduled Monument LIST ENTRY NUMBER: No DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014830 DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1014830 DESIGNATION: Scheduled Monument, CA DESIGNATION: NEW ENTRY: No DESIGNATION: NEW	OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
Extensive significant problems TREND: Declining RENCIPAL VULNERABILITY: Arable ploughing RENCIPAL VULNERABILITY: Arable ploughing ROUNDER TYPE: Private ROUND barrow east of Forston Farm, Charminster DESIGNATION: Scheduled Monument Extensive significant problems RENCIPAL VULNERABILITY: Arable ploughing ROUNDER TYPE: ROUND barrow on Cheselbourne West Down, Cheselbourne DESIGNATION: Scheduled Monument Extensive significant problems ROUNDER TYPE: ROUND barrow on Cheselbourne West Down, Cheselbourne DESIGNATION: Scheduled Monument Extensive significant problems Extensive significant problems DESIGNATION: Scheduled Monument Extensive significant problems Extensive significant problems Declining ROUNDER TYPE: No DOWNER TYPE: No DOWNER TYPE: Private Long barrow 360 metres SSW of Chettle House, Chettle DESIGNATION: Scheduled Monument Extensive Scheduled Monument UST ENTRY NUMBER: 1013792 DECLINING DECLINING PRIVATE PRIVATE Bowl barrow on Creech Barrow Hill, Church Knowle / Steeple DESIGNATION: Scheduled Monument, CA UST ENTRY NUMBER: 1014830 DECLINING DECLINING DECLINING DECLINING PRIVATE DECLINING DECLINING DECLINING PRIVATE DECLINING DECL	SITE NAME:	Bowl barrow on Wood Hill 310 metres north ea	ast of Cowden, Charr	ninster
Arable ploughing NEW ENTRY: No Description: Scheduled Monument LIST ENTRY NUMBER: 1002851 Description: Extensive significant problems TREND: Declining NEW ENTRY: No Description: Scheduled Monument LIST ENTRY NUMBER: 1002851 Declining NEW ENTRY: No Declining Declining NEW ENTRY: No Declining NEW ENTRY: No Declining Private Declining NEW ENTRY: No Declining NEW ENTRY: No Declining NEW ENTRY: No Declining Private Declining Declining NEW ENTRY: No Declining NEW ENTRY: No Declining D	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019395
Private Round barrow east of Forston Farm, Charminster DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002851 DECIDITION: Extensive significant problems TREND: Declining Private CONTACT: Katy Hoskyn 0117 975 1311 DEVINER TYPE Private CONTACT: Katy Hoskyn 0117 975 1311 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002878 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002878 DECIDING DEVINER TYPE Private CONTACT: Katy Hoskyn 0117 975 1311 DECIDING DEVINER TYPE Private CONTACT: Katy Hoskyn 0117 975 1311 DECIDING DEVINER TYPE Private CONTACT: Katy Hoskyn 0117 975 1311 DECIDING DEVINER TYPE Private Long barrow 360 metres SSW of Chettle House, Chettle DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1013792 DECIDING DEVINER TYPE Private CONTACT: Nick Croxson 07795 665645 DEVINER TYPE Private Scheduled Monument, CA LIST ENTRY NUMBER: 1014830 DEVINER TYPE Private Scheduled Monument, CA LIST ENTRY NUMBER: 1014830 DEVINER TYPE DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1014830 DECIDING DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1014830 DECIDING DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1014830 DECIDING DECIDING DECIDING PRIVATE DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1014830 DECIDING DECI	CONDITION:	Extensive significant problems	TREND:	Declining
ROUND BATTON: Scheduled Monument LIST ENTRY NUMBER: LOD 2851 Declining REINCIPAL VULNERABILITY: Arable ploughing REINCIPAL VULNERABILITY: Arable ploughing REINCIPAL VULNERABILITY: ROUND BATTOW ON Cheselbourne DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: LOD 2878 Declining REINCIPAL VULNERABILITY: Arable ploughing REINCIPAL VULNERABILITY: Arable Long barrow 360 metres SSW of Chettle House, Chettle DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1013792 CONDITION: Generally unsatisfactory with major localised problems REINCIPAL VULNERABILITY: Arable clipping NEW ENTRY: No Declining REINCIPAL VULNERABILITY: Arable clipping NEW ENTRY: No DOWNER TYPE Private CONTACT: Nick Croxson 07795 665645 STENAME: Bowl barrow on Creech Barrow Hill, Church Knowle / Steeple DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1014830 Declining REINCIPAL VULNERABILITY: Plant growth New ENTRY: No New ENTRY: No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002851 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: NO CONTACT: Katy Hoskyn 0117 975 1311 STE NAME: Round barrow on Cheselbourne West Down, Cheselbourne DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002878 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No CONTACT: Katy Hoskyn 0117 975 1311 STE NAME: Long barrow 360 metres SSW of Chettle House, Chettle DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1013792 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRYP: No CONTACT: Nick Croxson 07795 665645 STE NAME: Bowl barrow on Creech Barrow Hill, Church Knowle / Steeple DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1014830 CONDITION: Generally unsatisfactory with major localised problems STE NAME: Bowl barrow on Creech Barrow Hill, Church Knowle / Steeple DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1014830 CONDITION: Generally unsatisfactory with major localised problems STE NAME: Bowl barrow on Creech Barrow Hill, Church Knowle / Steeple DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1014830 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRYP: No	OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing Private Round barrow on Cheselbourne West Down, Cheselbourne DESIGNATION: Scheduled Monument CONTACT: Katy Hoskyn 0117 975 1311 STENAME: Round barrow on Cheselbourne West Down, Cheselbourne DESIGNATION: Scheduled Monument CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing Private CONTACT: Katy Hoskyn 0117 975 1311 STENAME: Long barrow 360 metres SSW of Chettle House, Chettle DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1013792 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1013792 CONDITION: Generally unsatisfactory with major localised problems Private CONTACT: Nick Croxson 07795 665645 STENAME: Bowl barrow on Creech Barrow Hill, Church Knowle / Steeple DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1014830 CONDITION: Generally unsatisfactory with major localised problems SCHENAME: Bowl barrow on Creech Barrow Hill, Church Knowle / Steeple DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1014830 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY): No	SITE NAME:	Round barrow east of Forston Farm, Charminsto	er	
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Private CONTACT: Katy Hoskyn 0117 975 1311 SITE NAME: Round barrow on Cheselbourne West Down, Cheselbourne DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002878 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Private CONTACT: Katy Hoskyn 0117 975 1311 SITE NAME: Long barrow 360 metres SSW of Chettle House, Chettle DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1013792 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: No OWNER TYPE: Private CONTACT: Nick Croxson 07795 665645 SITE NAME: Bowl barrow on Creech Barrow Hill, Church Knowle / Steeple DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1014830 CONDITION: Generally unsatisfactory with major localised problems SCHE NAME: Bowl barrow on Creech Barrow Hill, Church Knowle / Steeple DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1014830 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002851
Private CONTACT: Katy Hoskyn 0117 975 1311 STEENAME: Round barrow on Cheselbourne West Down, Cheselbourne DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002878 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No DOWNER TYPE: Private CONTACT: Katy Hoskyn 0117 975 1311 STEENAME: Long barrow 360 metres SSW of Chettle House, Chettle DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1013792 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY?: No DOWNER TYPE: Private CONTACT: Nick Croxson 07795 665645 STEENAME: Bowl barrow on Creech Barrow Hill, Church Knowle / Steeple DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1014830 CONDITION: Generally unsatisfactory with major localised problems SCHEDION: Scheduled Monument, CA LIST ENTRY NUMBER: 1014830 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Declining PRINCIPAL VULNERABILITY: Plant growth New ENTRY?: No NEW ENTRY?: No NEW ENTRY?: No New ENTRY?: No PRINCIPAL VULNERABILITY: Declining PRINCIPAL VULNERABILITY: Plant growth New ENTRY?: No NEW ENTRY?: No	CONDITION:	Extensive significant problems	TREND:	Declining
Round barrow on Cheselbourne West Down, Cheselbourne DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002878 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No CONTACT: Katy Hoskyn 0117 975 1311 SITE NAME: Long barrow 360 metres SSW of Chettle House, Chettle DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1013792 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY): No OWNER TYPE: Private CONTACT: Nick Croxson 07795 665645 SITE NAME: Bowl barrow on Creech Barrow Hill, Church Knowle / Steeple DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1014830 CONDITION: Generally unsatisfactory with major localised problems SCHEDISCONDITION: Scheduled Monument, CA LIST ENTRY NUMBER: 1014830 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRYY: No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Designation: Scheduled Monument LIST ENTRY NUMBER: 1002878 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No CONTACT: Katy Hoskyn 0117 975 1311 SETE NAME: Long barrow 360 metres SSW of Chettle House, Chettle DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1013792 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY?: No CONTACT: Nick Croxson 07795 665645 SETE NAME: Bowl barrow on Creech Barrow Hill, Church Knowle / Steeple DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1014830 CONDITION: Generally unsatisfactory with major localised problems Scheduled Monument, CA LIST ENTRY NUMBER: 1014830 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Declining PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No	OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
Extensive significant problems TREND: Declining New Entry?: No Deviner type: Private Long barrow 360 metres SSW of Chettle House, Chettle Designation: Scheduled Monument List entry number: 1013792 CONDITION: Generally unsatisfactory with major localised problems Private Contact: Katy Hoskyn 0117 975 1311 Declining TREND: Declining Declining New Entry?: No Declining Private Contact: Nick Croxson 07795 665645 Declining Declining New Entry?: No Declining Declining Declining Declining New Entry?: No Declining Declining Declining Declining Declining Declining Declining Declining Private Declining	SITE NAME:	Round barrow on Cheselbourne West Down, C	heselbourne	
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No CONTACT: Katy Hoskyn 0117 975 1311 ETE NAME: Long barrow 360 metres SSW of Chettle House, Chettle DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1013792 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY?: No CONTACT: Nick Croxson 07795 665645 ETE NAME: Bowl barrow on Creech Barrow Hill, Church Knowle / Steeple DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1014830 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: No CONTACT: Nick Croxson 07795 665645 ETE NAME: Bowl barrow on Creech Barrow Hill, Church Knowle / Steeple DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1014830 CONDITION: Plant growth New ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002878
Private Long barrow 360 metres SSW of Chettle House, Chettle DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: LONG Benerally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY?: Private CONTACT: Katy Hoskyn 0117 975 1311 N13792 Declining REND: Declining NEW ENTRY?: No CONTACT: Nick Croxson 07795 665645 DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1014830 Declining TREND: Declining TREND: Declining NEW ENTRY?: No NEW ENTRY NUMBER: No NEW ENTRY?: No NEW ENTRY?: No	CONDITION:	Extensive significant problems	TREND:	Declining
ESTE NAME: Long barrow 360 metres SSW of Chettle House, Chettle DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1013792 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY?: No CONTACT: Nick Croxson 07795 665645 TREND: Declining NEW ENTRY?: No CONTACT: Nick Croxson 07795 665645 TREND: Declining NEW ENTRY?: No Nick Croxson 07795 665645 TREND: Declining TREND: Declining NEW ENTRY?: No No PRINCIPAL VULNERABILITY: Plant growth New ENTRY?: No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Designation: Scheduled Monument LIST ENTRY NUMBER: 1013792 Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable clipping New ENTRY?: Private Bowl barrow on Creech Barrow Hill, Church Knowle / Steeple DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1014830 Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth LIST ENTRY NUMBER: 1014830 Declining No NEW ENTRY?: No	OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable clipping New ENTRY?: No Declining No CONTACT: Nick Croxson 07795 665645 Bowl barrow on Creech Barrow Hill, Church Knowle / Steeple DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1014830 Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth New ENTRY?: No	SITE NAME:	Long barrow 360 metres SSW of Chettle House	, Chettle	
problems problems problems PRINCIPAL VULNERABILITY: Arable clipping Private Private Private Bowl barrow on Creech Barrow Hill, Church Knowle / Steeple DESIGNATION: Scheduled Monument, CA CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth New ENTRY?: No New ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013792
Private Bowl barrow on Creech Barrow Hill, Church Knowle / Steeple Designation: Scheduled Monument, CA CONTACT: Nick Croxson 07795 665645 LIST ENTRY NUMBER: 1014830 Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth CONTACT: Nick Croxson 07795 665645 Nick Croxson 07795 665645	CONDITION:		TREND:	Declining
Bowl barrow on Creech Barrow Hill, Church Knowle / Steeple DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1014830 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument, CA CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth LIST ENTRY NUMBER: 1014830 TREND: Declining NEW ENTRY?: No	OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Generally unsatisfactory with major localised TREND: Declining NEW ENTRY?: No	JITE NAME:	Bowl barrow on Creech Barrow Hill, Church Kr	nowle / Steeple	
problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No	DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1014830
-	CONDITION:		TREND:	Declining
OWNER TYPE: Commercial company CONTACT: Katy Hoskyn 0117 975 1311	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
	OWNER TYPE:	Commercial company	CONTACT:	Katy Hoskyn 0117 975 1311

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

SITE NAME:	Section of Roman road 150 metres south of Pa	rk Farm Cottages, Col	ehill
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018028
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow 360 metres south of Compton Ba	arn, Compton Valence	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019741
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Settlement south east of Soaper's Hill Plantatio	n, Compton Valence	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003234
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	The Rings: a ringwork and bailey and a Civil Wa	ar battery 400 metres s	south west of Corfe Castle, Corfe
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1011479
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow 450 metres east of Dennet's Bott	com Barn, Dewlish	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015427
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow 550 metres WNW of West End	Barn, Dewlish	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015032
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Three bowl barrows 380 metres west of West	End Barn, Dewlish / M	ilborne St. Andrew
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015031
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Earthwork east of Stake Farm, East Chelboroug	gh	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002845
	Generally unsatisfactory with major localised	TREND:	Declining
CONDITION:	problems		
	problems Animal burrowing - extensive	NEW ENTRY?:	No
CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE:	·	NEW ENTRY?: CONTACT:	No Katy Hoskyn 0117 975 1311

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Three bowl barrows in Holme Lane Plantation, 2	200 metres south wes	st of Squirrel's Cottages, East Holme
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016728
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Two barrows known as 'Water Barrows' 650 m cemetery to the south east of East Lulworth, Ea	etres WNW of Whit	eway Farm: part of a round barrow
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008144
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Katy Hoskyn 0117 975 1311
ITE NAME:	Flower's Barrow: a small multivallate hillfort and	associated outwork	on Rings Hill, East Lulworth / Tyneha
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008141
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Katy Hoskyn 0117 975 1311
ITE NAME:	Bowl barrow 60 metres north east of Hethfelto	n Farm, East Stoke	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018192
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow on Farm Heath, 470 metres south	east of Hill Cottages,	East Stoke
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016272
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow on Farm Heath, 480 metres south	east of Hill Cottages,	East Stoke
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016271
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Section of Battery Bank on Binnegar Plain, 830 n	netres north east of S	tokeford Farm, East Stoke
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018189
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

1211771327117131120207 300	THE TREE TO BOILDE TO COMP		
SITE NAME:	Section of Battery Bank on South Heath, East St	oke	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016273
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Two bowl barrows on South Heath, 290 metres	and 370 metres east	of Binnegar Hall, East Stoke
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016276
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bell barrow 500 metres north east of Beacon Fa	ırm, Ferndown Town	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015995
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
ITE NAME:	Bell barrow known as Belle Vue Barrow and a b Town	owl barrow 250 metr	res north east of Hillamsland, Ferndown
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015994
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow 250 metres west of Ferndown Up	per School, Ferndowr	n Town
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015791
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Part of Ackling Dyke (Roman road), including Ro Michael / Pentridge / Wimborne St. Giles	oman road on Oakley	Down, Gussage All Saints / Gussage St
DESIGNATION:	Scheduled Monument, part in RPG grade II*	LIST ENTRY NUMBER:	1003309
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Barrow on Parsonage Hill, Gussage St. Michael		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002783
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Katy Hoskyn 0117 975 1311

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

HERITAGE AT RISK 2020 / SOC	` ,		
SITE NAME:	Long mound 1500 yards (1370 metres) east of Hig	her Farm, Gussage	St. Michael
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002784
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Two barrows near Ackling Dyke, Gussage St. Mich	nael	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002786
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Two long barrows on Gussage Hill, Gussage St. Mi	chael	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002707
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Two round barrows on Gussage Down, Gussage S	st. Michael	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002741
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Earthworks on Gussage Down, Gussage St. Michae	el / Sixpenny Handle	ey
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002740
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Round barrows near Thickthorn Farm, Gussage St	. Michael / Tarrant	Hinton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002816
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Round barrow north west of High Lea Farm, Hinto	on Martell	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004552
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow cemetery and a cross dyke on Horto	on Common 800 m	etres south of Bridge Farm, Horton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018411
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Causewayed camp on Hambledon Hill, Iwerne (Courtney or Shroton /	Child Okeford / Hanford
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002767
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow known as Folly Barrow, Iwerne M	inster	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020030
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Two bowl barrows 350 metres south west of K	eeper's Lodge, south	east of Bareden Down, Iwerne Minste
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013745
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Alum works, other multi-period industrial rema Kimmeridge Bay, Kimmeridge	ins and an associated §	group of jetties and breakwaters,
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1017307
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bell barrow and five bowl barrows 1000 metres round barrow cemetery, Kingston Russell / Littl	south east of Kingsto ebredy	n Russell Farm, part of the Black Dov
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011693
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow 600 metres west of Well Bottom cemetery, Littlebredy	Wood, forming part o	of the Pitcombe Down round barrow
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013249
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
ITE NAME:	Three bowl barrows 300 metres south west of round barrow cemetery, Littlebredy	Well Bottom Wood,	forming part of the Pitcombe Down
	Scheduled Monument	LIST ENTRY NUMBER:	1013251
DESIGNATION:			
	Extensive significant problems	TREND:	Declining
CONDITION:	Extensive significant problems Arable ploughing	TREND: NEW ENTRY?:	Declining No
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE:	· .		<u> </u>

- C Slow decay; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 D Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial like) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Bowl barrow 550 metres north east of Pitcombe F Littlebredy / Kingston Russell	arm, part of the Bla	ack Down round barrow cemetery,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011694
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow 250 metres north west of Veiny Che	ese Pond, Long Cri	chel
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015191
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Two bowl barrows 165 metres west of Veiny Che	ese Pond, Long Cri	chel
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015785
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Disc barrow and a bowl barrow 640 metres south west of Veiny Cheese Pond, Long Crichel / Tarrant Launceston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020444
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Lambert's Castle: an Iron Age hillfort 425 metres v post-medieval fair and a telegraph station, Marshwo	vest of Nash Farm, ood	with a bowl barrow, and the sites o
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017035
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Sasha Chapman 0117 975 1338
SITE NAME:	Earthwork and ancient fields south east of Lyscom	be Bottom, Melcon	nbe Horsey / Cheselbourne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002456
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow 70 metres south east of West End Ba	arn, Milborne St. Aı	ndrew
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014854
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Bowl barrow 480 metres south east of West En	d Barn, Milborne St. A	Andrew	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014855	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Three bowl barrows on Milborne Down 520 me Castle hillfort, Milborne St. Andrew	tres and 585 metres	north east of obelisk on Weatherby	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019364	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Two bowl barrows and two ring ditches 450 me	tres north west of Ha	aywards Farm, Milborne St. Andrew	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019365	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Weatherby Castle, an Iron Age hillfort 1020 metres north west of Ashley Barn Farm, Milborne St. Andre			
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1019360	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Stable Barrow 230 metres NNE of Frogmore Fa	rm, Milborne St. Andı	rew / Milton Abbas	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014761	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Bowl barrow in Morden Park 350 metres south	west of Hunting Bridg	ge, Morden	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016281	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311	
SITE NAME:	Two bowl barrows 760 metres north east of Mi	ler's Farm, Morden		
DESIGNATION:	Scheduled Monument, RPG grade II*	LIST ENTRY NUMBER:	1016283	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

HERITAGE AT RISK 2020 / SOU	UTH VVEST / DOKSET (UA)		
SITE NAME:	Obelisk on Fir Hill, Moreton		
DESIGNATION:	Scheduled Monument, LB grade II, CA	LIST ENTRY NUMBER:	1002425
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	King's Court Palace moated site, Motcombe		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017276
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Hugh Beamish 0117 975 0726
SITE NAME:	Ancient settlement south west of Incombe Woo	d, Nether Cerne	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002438
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Sasha Chapman 0117 975 1338
SITE NAME:	Bowl barrow 230 metres north east of Great Sti	ode House, Netherb	oury
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016372
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Upton Fort, a coastal artillery battery and two se	earchlight emplaceme	nts, Osmington
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1021435
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Four barrows on Moigns Down, Owermoigne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002774
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bradford Barrow, Pamphill		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002713
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Celtic fields on Pentridge Down, Pentridge		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002796
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Long barrow 1200 metres south west of St Rumb	oold's Church, Pentri	dge
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003206
CONDITION:	Unknown	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Long barrows and group of round barrows on Bo	okerley Down, Pentri	idge
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002722
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Part of Dorset Cursus, Pentridge / Wimborne St.	Giles	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003222
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Round barrow south west of Bourne Farm, Piddle	ehinton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004550
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Two barrows on Little Puddle Hill, Piddlehinton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003224
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Two barrows west of Little Piddle Down, Piddleh	ninton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002805
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow on Plush Hill 600 metres ESE of Lov	wer Farm, Plush, Pido	lletrenthide
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015037
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
	A 1.1 1: :	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Arable clipping	TALAA CIATIKII.	INO

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
 - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Bowl barrow on Pond Eweleaze 500 metres north	east of Dole's Ash	Farm, Piddletrenthide
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015035
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Round barrow on Hog Leaze, Piddletrenthide		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003238
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Pilsdon Pen hillfort and associated remains, Pilsdor	1	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019394
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Sasha Chapman 0117 975 1338
SITE NAME:	Enclosure south of Pimperne Down, Pimperne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002860
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Round barrow north east of Friar Waddon, Portes	sham	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002488
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Two round barrows on Ridgeway, Portesham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002758
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Battery 200 yards (180 metres) east of the Naval of	cemetery, Portland	
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1002412
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Katy Hoskyn 0117 975 1311

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Mesolithic sites near Culver Well, Portland		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1002406
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Barrow near east boundary of parish, Powerstock		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002809
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Barrow 500 yards (450 metres) east of village, Pox	well	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004565
CONDITION:	Unknown	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Group of barrows east of Northdown Barn, Poxw	ell	
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1002770
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow on Little Puddle Hill, 920 metres nor	th west of Fidler's (Green Farm, Puddletown
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017261
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Round barrow west of Druce Higher Barn, Puddle	town	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002874
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Three round barrows on Puddletown Down, Pudd	lletown	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002450
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Two bowl barrows 320 metres south west of Layo	ock Dairy Farm, Pu	ıddletown
	Two bowl barrows 320 metres south west of Layo Scheduled Monument	ock Dairy Farm, Pu	iddletown 1017266
DESIGNATION:	,	•	
SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY:	Scheduled Monument	LIST ENTRY NUMBER:	1017266
designation: condition:	Scheduled Monument Extensive significant problems	LIST ENTRY NUMBER:	1017266 Declining

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Two round barrows south west of Well House Cottage, Puddletown		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002875
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow 400 metres north east of Look Farm,	, Puncknowle	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016370
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Castle Hill, Shaftesbury		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1002724
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Camp in Mistlebury Wood, Sixpenny Handley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002455
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Charity (non-heritage)	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Enclosure south of Humby's Stock Coppice, Sixper	nny Handley	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005575
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Crawford Castle (or Spetisbury Rings), Spetisbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004563
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Three bowl barrows in Avon Heath Country Park, Matcham's House, St. Leonards and St. Ives	two 620 metres ar	nd one 700 metres north west of
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016095
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Katy Hoskyn 0117 975 1311

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Bell barrow 70 metres west of Fidler's Green, Stins	sford	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017262
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Hod Hill camp and Lydsbury Rings, Stourpaine / Ha	anford	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002678
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Sasha Chapman 0117 975 1338
SITE NAME:	Round barrow north east of Hog Hill Barn, Stratto	n	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003237
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Dumping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Round barrow north west of Jackman's Cross, Stra	atton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002470
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Round barrow on Stratton Down, Stratton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002871
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Earthworks on Loscombe Hill, Sydling St. Nicholas		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002820
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow on Eype Down 275 metres east of Fr	ogmore Farm, Sym	ondsbury
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016100
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
O TTTE	1117466		,

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Slight univallate hillfort 850 metres north east of B	ussays Stool Farm	Tarrant Gunville
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020611
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 200 metres south east of Pimperne L	ong Barrow, Tarra	nt Hinton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013794
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Prehistoric habitation site between north and sout	h Hinton Downs, T	arrant Hinton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003235
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Roman villa on Little Barton Hill, Tarrant Hinton /	Tarrant Gunville	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002424
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 350 metres south west of Buzbury R	ings, Tarrant Keyne	eston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013789
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 850 metres ESE of Hill Farm, Tarrant	Keyneston	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015182
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Buzbury Rings, Tarrant Keyneston / Tarrant Rawst	on / Langton Long	Blandford
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002718
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Bowl barrow 600 metres south of Plantation Far	m, Tarrant Launcesto	on
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015190
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow on The Cliff 680 metres east of Lu	ton Farm, Tarrant Ra	wston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015187
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow on The Cliff 680 metres NNW of	Smith's Cottages, Tar	rant Rawston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015186
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Long barrow and two bowl barrows 140 metres	north west of Dorm	y House, Tarrant Rawston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014572
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Roman enclosure on Keyneston Down, Tarrant	Rawston	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002373
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Holditch Court Tower, Thorncombe		
DESIGNATION:	Scheduled Monument, LB grade I	LIST ENTRY NUMBER:	1002835
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Ball 0117 975 0666
SITE NAME:	Four bowl barrows 710 metres north, 750 metr Tolpuddle	es north west and 95	0 metres north west of Clyffe House
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016378
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet
- implemented.

 C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
 - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

SITE NAME:	Bowl barrow in Piddle Wood, 530 metres north ea	ast of Gate Barn, T	urners Puddle
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015901
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Group of six bowl barrows, forming a round barro	w cemetery on Bla	ck Hill, Turners Puddle / Bere Regis
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1015897
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	High Cank, a hengi-form monument 520 metres no	orth of Up Cerne M	lanor House, Up Cerne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018413
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Stephen's Castle, a bowl barrow 720 metres east o	of Eastworth Farm,	Verwood
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021148
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Decoy pond and associated overnight shelter on D	ecoy Heath, Ware	ham St. Martin
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016916
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Light Anti-aircraft battery on Holton Heath, 210 m	etres west of Sand	ford House, Wareham St. Martin
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019153
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Light Anti-aircraft battery on Holton Heath, 650 m	etres south east of	Sandford House, Wareham St. Mar
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019152
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Katy Hoskyn 0117 975 1311

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Royal Naval Cordite Factory at Holton Heath, Wa	reham St. Martin	
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1019151
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Four bowl barrows 150 metres north east of Seve	n Barrows Farm, W	/areham Town
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015373
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Dyke south east of Eggardon Hill camp, West Con	npton	
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1002404
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Barrow near Eggardon, West Compton / Powersto	ock	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004567
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bindon Hill camp, West Lulworth / East Lulworth		
DESIGNATION:	Scheduled Monument, part in CA, WHS	LIST ENTRY NUMBER:	1002705
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Parley Barrow, a bowl barrow on the corner of Ell	esfield Drive and D	ruid's Close, West Parley
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015792
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Enclosure on Mount Pleasant Hill, West Stafford /	Dorchester	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002463
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

HERITAGE AT RISK 2020 / SOL	JTH WEST / DORSET (UA)		
SITE NAME:	Coney's Castle camp, Whitchurch Canonicorum		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003208
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Sasha Chapman 0117 975 1338
SITE NAME:	Three bowl barrows 530 metres and 350 metres n	orth east of White	combe Barn, Whitcombe
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019413
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Oval barrow and three bowl barrows 250 metres a Broadmayne	and 330 metres so	uth of Whitcombe Barn, Whitcombe
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019414
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Barrows near Water Lake, Wimborne St. Giles		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002795
CONDITION:	Unknown	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Two round barrows south of Cranborne Farm, W	imborne St. Giles	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002459
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Barrows in and near St Giles Park, Wimborne St. C	Giles / Edmondshan	n
DESIGNATION:	Scheduled Monument, RPG grade II*	LIST ENTRY NUMBER:	1002782
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Barrows in and near The Drive Plantation, Wimbo	rne St. Giles / Guss	sage All Saints
DESIGNATION:	Scheduled Monument, RPG grade II*	LIST ENTRY NUMBER:	1002788
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Barrows in Salisbury Plantation, Wimborne St. Gile	es / Pentridge	
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1002817
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Drove Hill round barrows, Winfrith Newburgh		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002765
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Two round barrows north of Came Farm, Winterl	oorne Came	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002828
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow 150 metres north east of Dunbury, V	Vinterborne Hough	nton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014758
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 500 metres south of West Down Bar	rn, Winterborne K	ingston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020986
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Long barrow immediately north west of Maiden Ca	astle, Winterborne	Monkton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015779
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Long barrow, three bell barrows, fancy barrow and Winterborne Monkton	d a linear earthworl	k 800 metres north of Maiden Castle
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015783
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Katy Hoskyn 0117 975 1311

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Round barrow cemetery immediately south east	of Maiden Castle, W	interborne Monkton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015778
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Settlement remains north of Maiden Castle, Wir	terborne Monkton /	Dorchester
Designation:	Scheduled Monument	LIST ENTRY NUMBER:	1002409
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Group of barrows south of Goldsmith's Plantation	on, Winterborne St. N	1artin
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002810
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Group of round barrows near Eweleaze Barn, Winterborne St. Martin		
Designation:	Scheduled Monument	LIST ENTRY NUMBER:	1002756
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Group of round barrows on and to east of Grea	t Hill, Winterborne S	t. Martin
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004564
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Round barrow north of Ridgeway, Winterborne	St. Martin	
	Round barrow north of Ridgeway, Winterborne Scheduled Monument	St. Martin LIST ENTRY NUMBER:	1002759
DESIGNATION:			1002759 Declining
DESIGNATION: CONDITION:	Scheduled Monument	LIST ENTRY NUMBER:	
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY:	Scheduled Monument Extensive significant problems	LIST ENTRY NUMBER:	Declining
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument Extensive significant problems Arable ploughing	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:	Declining No
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument Extensive significant problems Arable ploughing Crown	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:	Declining No
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument Extensive significant problems Arable ploughing Crown Round barrows on Four Barrow Hill, Winterbor	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:	Declining No Katy Hoskyn 0117 975 1311
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Scheduled Monument Extensive significant problems Arable ploughing Crown Round barrows on Four Barrow Hill, Winterbord Scheduled Monument	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: The St. Martin LIST ENTRY NUMBER:	Declining No Katy Hoskyn 0117 975 1311 1002755
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY:	Scheduled Monument Extensive significant problems Arable ploughing Crown Round barrows on Four Barrow Hill, Winterbort Scheduled Monument Extensive significant problems	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: The St. Martin LIST ENTRY NUMBER: TREND:	Declining No Katy Hoskyn 0117 975 1311 1002755 Declining
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument Extensive significant problems Arable ploughing Crown Round barrows on Four Barrow Hill, Winterbor Scheduled Monument Extensive significant problems Animal burrowing - extensive	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: THE St. Martin LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:	Declining No Katy Hoskyn 0117 975 1311 1002755 Declining No
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument Extensive significant problems Arable ploughing Crown Round barrows on Four Barrow Hill, Winterbort Scheduled Monument Extensive significant problems Animal burrowing - extensive Private, multiple owners	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: THE St. Martin LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:	Declining No Katy Hoskyn 0117 975 1311 1002755 Declining No
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument Extensive significant problems Arable ploughing Crown Round barrows on Four Barrow Hill, Winterbor Scheduled Monument Extensive significant problems Animal burrowing - extensive Private, multiple owners Round barrows on Grove Hill, Winterborne St.	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: THE St. Martin LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: Martin	Declining No Katy Hoskyn 0117 975 1311 1002755 Declining No Katy Hoskyn 0117 975 1311
SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument Extensive significant problems Arable ploughing Crown Round barrows on Four Barrow Hill, Winterbord Scheduled Monument Extensive significant problems Animal burrowing - extensive Private, multiple owners Round barrows on Grove Hill, Winterborne St. Scheduled Monument	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: THE St. Martin LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: Martin LIST ENTRY NUMBER:	Declining No Katy Hoskyn 0117 975 1311 1002755 Declining No Katy Hoskyn 0117 975 1311
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: CONDITION: DWNER TYPE: SITE NAME: DWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Scheduled Monument Extensive significant problems Arable ploughing Crown Round barrows on Four Barrow Hill, Winterbor Scheduled Monument Extensive significant problems Animal burrowing - extensive Private, multiple owners Round barrows on Grove Hill, Winterborne St. Scheduled Monument Extensive significant problems	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: THE St. Martin LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: Martin LIST ENTRY NUMBER: TREND: TREND:	Declining No Katy Hoskyn 0117 975 1311 1002755 Declining No Katy Hoskyn 0117 975 1311 1002757 Declining

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Three barrows south of Hart Hill Plantation, Wi	nterborne St. Martin	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002814
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Two barrows at Rew, Winterborne St. Martin		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002811
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Group of round barrows on Shorn Hill and Bron	kham Hill, Winterbo	rne St. Martin / Portesham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002699
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Dumping	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow 900 metres north west of Pond Do	own Buildings, Winter	rborne Stickland
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013749
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Unknown	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 25 metres south of Whitechurch H	lill Barn, Winterborn	e Whitechurch
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013788
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Milling House, West Farm, Winterborne Whited	hurch	
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1002396
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 120 metres south of the southern / Bere Regis	extent of Horse Clos	e Plantation, Winterborne Whitechurch
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015387
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645

- C Slow decay; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 D Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial list). use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Bell barrow 100 metres south of Winterbourne Po cemetery, Winterbourne Abbas	oor Lot, part of the	Winterbourne Poor Lot round barro
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012027
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow 400 metres north east of Manor Farm Winterbourne Abbas	m, part of the Pound	d Hill round barrow cemetery,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011692
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Unknown	CONTACT:	Katy Hoskyn 0117 975 1311
ITE NAME:	Bowl barrow 450 metres north east of Manor Farm Winterbourne Abbas	m, part of the Pound	d Hill round barrow cemetery,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011691
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Unknown	CONTACT:	Katy Hoskyn 0117 975 1311
ITE NAME:	Triple barrow and bowl barrow forming part of a l metres north east of Winterbourne Poor Lot, Win	parrow cemetery ar nterbourne Abbas	nd part of an associated field system 2
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012030
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Unknown	CONTACT:	Katy Hoskyn 0117 975 1311
ITE NAME:	Two bell barrows 15 metres north of Well Botton Winterbourne Abbas	n Wood, part of the	e Poor Lot round barrow cemetery,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012029
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Unknown	CONTACT:	Katy Hoskyn 0117 975 1311
ITE NAME:	Bowl barrow in Well Bottom Wood, Winterbourn	ne Abbas / Littlebre	dy
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013255
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
TE NAME:	Four round barrows north west of Blagdon Barn, V	Winterbourne Stee	pleton
esignation:	Scheduled Monument	LIST ENTRY NUMBER:	1002750
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Katy Hoskyn 0117 975 1311

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Round barrow on Pound Hill, Winterbourne Stee Scheduled Monument Extensive significant problems Arable ploughing Private Round barrow south west of village, Winterbourd Scheduled Monument Generally unsatisfactory with major localised problems Animal burrowing - moderate	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:	1002870 Declining No Katy Hoskyn 0117 975 1311
CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Extensive significant problems Arable ploughing Private Round barrow south west of village, Winterbound Scheduled Monument Generally unsatisfactory with major localised problems	TREND: NEW ENTRY?: CONTACT: rne Steepleton LIST ENTRY NUMBER:	Declining No Katy Hoskyn 0117 975 1311
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Arable ploughing Private Round barrow south west of village, Winterbound Scheduled Monument Generally unsatisfactory with major localised problems	NEW ENTRY?: CONTACT: rne Steepleton LIST ENTRY NUMBER:	No Katy Hoskyn 0117 975 1311
OWNER TYPE: SITE NAME: DESIGNATION:	Private Round barrow south west of village, Winterbound Scheduled Monument Generally unsatisfactory with major localised problems	CONTACT: rne Steepleton LIST ENTRY NUMBER:	Katy Hoskyn 0117 975 1311
SITE NAME: DESIGNATION:	Round barrow south west of village, Winterbound Scheduled Monument Generally unsatisfactory with major localised problems	rne Steepleton LIST ENTRY NUMBER:	
DESIGNATION:	Scheduled Monument Generally unsatisfactory with major localised problems	LIST ENTRY NUMBER:	1002751
	Generally unsatisfactory with major localised problems		1002751
CONDITION:	problems	TREND:	
	Animal burrowing - moderate		Declining
PRINCIPAL VULNERABILITY:		NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Round barrows on Sheep Down, Winterbourne	Steepleton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003306
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Two conjoined bowl barrows 550 metres north	east of Manor Farm,	Pound Hill, Winterbourne Steepleton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002687
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Two round barrows on North Hill, Winterbour	ne Steepleton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002865
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Group of barrows near Big Wood, Winterbourn	ne Steepleton / Winte	rbourne Abbas
DESIGNATION:	Scheduled Monument, part in RPG grade II	LIST ENTRY NUMBER:	1002696
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Group of henge monuments, an associated group at Knowlton, Woodlands	p of round barrows, a	Saxon cemetery and a Norman church
DESIGNATION:	Scheduled Monument, LB grade II*	LIST ENTRY NUMBER:	1020580
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311

- A Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Round barrow cemetery south of New Barn Farm	, associated with th	e Knowlton Circles, Woodlands
Designation:	Scheduled Monument	LIST ENTRY NUMBER:	1020582
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow 300 metres south east of Hyford Co	ttage, Wool	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015894
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow 380 metres north west of Hyford Co	ottage, Wool	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015895
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bul Barrow, 750 metres east of Rawlsbury Camp,	Woolland	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013787
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow on Emmett's Hill, Worth Matravers		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1017268
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow on North Hill, 400 metres north eas	t of Renscombe Far	m, Worth Matravers
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1017269
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow one kilometre south west of Manor	Farm, Wraxall	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015051
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

OWNER TYPE:

LIST ENTRY NUMBER:

SITE NAME:	Linear boundary and section of Roman road, 550 Royal	0 metres south east o	f Ashmore Farm, Ashmore / Tollard
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020728
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645



© Historic England

SITE NAME:	Kingston Maurward, Stinsford
DESIGNATION:	Registered Park and Garden grade II*, 8 LBs, part in SM, part in CA
CONDITION:	Generally satisfactory but with minor localised problems
VULNERABILITY:	High
TREND:	Stable
NEW ENTRY?:	No

1000719

Educational (state sector)

Designed landscape around early C18 house with notable Edwardian gardens open to the public. House forms nucleus of expanding land-based college. Many post-war buildings which impact on view lines and appreciation of designed landscape. In 2011 Natural England grant-aided a restoration plan for part of the park. Further development proposals appear to have been shelved, for the present. Historic England is being consulted on a new draft masterplan to guide future development.

Contact: Jo McAllister 0117 975 0696

SITE NAME:	Swanage		
DESIGNATION:	Conservation Area, 88 LBs, SM, WHS	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Paul Wyeth (LPA) 01305 251010
SITE NAME:	Weymouth Town Centre		
SITE NAME: DESIGNATION:	Weymouth Town Centre Conservation Area, 361 LBs, SM	NEW ENTRY?:	No
	,	NEW ENTRY?: TREND:	No Deteriorating significantly
DESIGNATION:	Conservation Area, 361 LBs, SM		

GLOUCESTERSHIRE

CHELTENHAM



(C)	Historic	Engl	and
0		6.	

SITE NAME:	Church of St Mark, Church Road, Cheltenham	
DESIGNATION:	Listed Place of Worship grade II	
CONDITION:	Poor	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1386790	

Parish church built in 1860-6 by John Middleton, with transepts of 1888. Drilled Cotswold stone with Bath stone quoins and dressings, Forest of Dean stone forming alternating polychromy in voussoirs (wedge shaped stones), red tile roof. Gothic Revival, Decorated style. Nave roof is in poor condition. Plain clay tile loss on the north vestry and chancel roofs were repaired in 2015. Water ingress in some areas is exacerbating the poor condition of the interior.

Contact: Chris Miners 0117 975 1355

© Historic England

SITE NAME:	Church of St Luke, College Road, Cheltenham
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1387880

Church built in 1853-4 by Frederick W Ordish, partly intended for schoolboys from nearby Cheltenham College. Drilled Cotswold stone with ashlar quoins and dressings and with plain tile roof. Middle Pointed style. Cruciform plan with west tower; four-bay aisled nave with clerestory and south porch, crossing with north and south transepts, four-bay chancel with south Lady Chapel, north vestry. West tower has heavily broached spire. The roof covering is in poor condition and the interior is damaged by water ingress. The rainwater goods were repaired in 2016.

Contact: Chris Miners 0117 975 1355

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

COTSWOLD



© Historic England Archive

Elizabeth Pengree Memorial, SITE NAME: The Square, Blockley DESIGNATION: Listed Building grade II*, CA CONDITION: Poor

OCCUPANCY: N/A PRIORITY CATEGORY: C (C)

OWNER TYPE: Unknown LIST ENTRY NUMBER: 1341728

Contact: Chris Miners 0117 975 1355

repairs.

	*	
10		

© Historic England

SITE NAME:	Alfreds Hall, Cirencester Park, Cirencester
DESIGNATION:	Listed Building grade II*, RPG grade I
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)

Private

LIST ENTRY NUMBER: 1298719

OWNER TYPE:

Folly, begun 1721, designed by Lord Bathurst with Alexander Pope's advice, completed 1732. Probably the earliest C18 mock-Gothic castle; part former house, part banqueting house and part mock ruin. Located in Oakley Wood, with rides radiating from it through the wood. The building is in very bad condition and continues to deteriorate.

Commemorative monument (1770s) decaying on one side

and the railings are displaced and in poor condition. Basic

maintenance has been undertaken, but no significant

© Historic England

SITE NAME:	Dovecote at the Manor House, Lower Slaughter
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company

LIST ENTRY NUMBER: 1341062 A late C16 structure of coursed rubble and Cotswold stone roof. This large dovecote hosts two separate columbaria inside, built of nesting boxes from ground to the roof. It is currently without a use and in poor condition. Some emergency repairs to the roof coverings have been carried out in 2018.

Contact: Alessandra Perrone 0117 975 1345

Contact: Alessandra Perrone 0117 975 1345



© Historic England

SITE NAME:	Church of St Peter, Daylesford, Adlestrop
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation

1341122

Parish church in the high Gothic style by JL Pearson 1863. Cruciform plan with a pyramidal spire. Limestone with red sandstone features, stone slate roofs. The stone slates are slipping or fractured and need renewal. The sandstone colonettes are heavily eroded on the outside and are structurally unsafe. The church is now owned by the St Peter's Daylesford Charitable Trust and shares services between the Church of England and the Roman Catholic church.

Small parish church adjacent to Colesbourne Park. C12 with C15 tower and chancel; largely rebuilt 1851-53 by David Brandon. Random rubble limestone with ashlar tower; stone slate roof. Nave with north and south transept; west tower; south porch; and chancel. The roof slates have slipped or fallen and need repair on the north

Contact: Chris Miners 0117 975 1355



© Historic England

SITE NAME:	Church of St James, Colesbourne
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1341787

1341787

Contact: Chris Miners 0117 975 1355

nave roof.

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



SITE NAME:	Church of St Edward, Evenlode
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1089794

Parish church. C12, C14, C19 vestry and porch, restoration by JEK Cutts 1879. Coursed squared and dressed limestone and sandstone. Stone slate roof. Plan: nave with north vestry, south aisle, projecting porch from west end of south aisle, west tower, chancel. The stone slate roofs, especially on the south side, have reached the end of their life and need renewal.

Contact: Chris Miners 0117 975 1355

© Historic England



SITE NAME: Church of St Bartholomew, Whittington Listed Place of Worship grade DESIGNATION: II*, CA CONDITION: Very bad PRIORITY CATEGORY: F (F) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1341364

Norman in origin; restoration by Waller around 1872 included roofs, porch and vestry, and removal of rood screen formerly dividing nave from chancel. South chapel possibly late C16-17. South asseptions probably C18 rebuilt on smaller scale incorporating C12 elements. Stone slate roofs are in extremely poor condition and are likely to date from the 1872 restoration. National Lottery Heritage Fund Grant for Places of Worship awarded in 2017 for repairs to roofs. Repair phase underway and due for completion in September 2020.

Contact: Sarah Ball 0117 975 0666

© Arnold	Bartosch	Ltd
----------	----------	-----

SITE NAME:	Two bowl barrows 690 metres and 790 metres north of The Manor Farm, Avening		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017337
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Perrott's Brook dykes, Bagendon / North Cerney		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003436
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Long barrow 800 metres north east of Oldwalls Fa	arm, Bibury	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018163
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	West Barrow: a long barrow 200 metres west of l	_eighterton School,	Boxwell with Leighterton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013590
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Animal burrowing - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Chedworth Roman villa, Chedworth		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003324
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Rain entry	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Melanie Barge 0117 975 1300

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

HERITAGE AT RISK 2020 / SOU	5517 GO 1311 GED		
SITE NAME:	Settlement south east of Chesterton Farm, Cirenc	ester / Siddington	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003444
CONDITION:	Extensive significant problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Hullasey Grove medieval village site, Coates		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003359
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Three bowl barrows, known as Emma's Grove rou	ınd barrows, Cobei	rley
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017079
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Two bowl barrows, known as Crippet's Wood rou Dryhill Farm, Coberley	und barrows, 560 m	netres and 590 metres north east of
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017041
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Norbury Camp hillfort, Colesbourne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018167
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Tump Barn bowl barrow, Didmarton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016077
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Camp at Upper Dowdeswell, Dowdeswell		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1003321
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

HERITAGE AT RISK 2020 / SOL	JTH WEST / COTSWOLD		
SITE NAME:	Hoar Stone long barrow, Duntisbourne Abbots		
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1018161
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Bowl barrow in Three Ash Belt, 460 metres nor	th east of Westwood	Farm, Edgeworth
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016840
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Icomb camp, Icomb		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003342
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	The Chessalls Roman town, Kingscote / Wottor	-under-Edge	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018607
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Metal detecting - unlicensed	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Summerhill prehistoric site, Naunton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003339
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Bowl barrow in Inlands Plantation, 650 metres s	outh of Hazleton Man	or Farm, Rodmarton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008788
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Bowl barrow 120 metres north of Home Farm,	Sherborne	
DESIGNATION:	Scheduled Monument, RPG grade II, CA	LIST ENTRY NUMBER:	1017082
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	South Cerney castle, South Cerney		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003422
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Four bowl barrows forming part of a round barrow cemetery, and a long barrow 550 metres NNE of Eyford Hill Farm, Upper Slaughter		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020987
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345

FOREST OF DEAN



© Historic England Archive

SITE NAME:	Blakeney United Reformed Church, Cinderford Road, Blakeney, Awre
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

LIST ENTRY NUMBER: 1186386 Former non-conformist chapel, dated 1849. Remarkably complete and architecturally distinctive example of its type. Stonework repairs required.

Contact: Alessandra Perrone 0117 975 1345



© Historic England Archive

SITE NAME:	Gunns Mill Furnace, Littledean
DESIGNATION:	Scheduled Monument and Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1002080 and 1186479

Formerly a C17 charcoal blast furnace and later an C18 paper mill. Now unused and in perilous condition, despite some emergency holding repairs. The Forest of Dean Building Preservation Trust is working with Historic England to secure the future of the building. Funding to date has completed various surveys and improved the landscape and setting. A 2017 National Lottery Heritage Fund application was rejected. A revised application will be made for funding to develop a proposal to reuse the site and restore the furnace.

Contact: Melanie Barge 0117 975 1300



© Historic England

SITE NAME:	Lydney Docks and Harbour, Naas Lane, Lydney
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Government or agency

LIST ENTRY NUMBER: 1002079 and 1338556

The docks and harbour date from c1810 to 1821 and were once the main commercial port serving industry in the district. The Inner Basin is still in poor condition and needs extensive repairs. The Environment Agency has advertised the site and selected a preferred bidder to take over the ownership of the site. The final details of this sale are still being resolved. A local partnership group through the Local Authority are looking for funding to repair some structures and enhance the visitor experience of the site. Work has also been on-going to clear and control vegetation on the

Contact: Melanie Barge 0117 975 1300



© Historic England Archive

SITE NAME:	Tithe Barn, Highleadon Court, Rudford and Highleadon
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1152574

C15 or early C16 tithe barn built for the Abbey of St Peter, Gloucester. The roof is sound, but the framing and infill panels are deteriorating. Used for agricultural storage. Some maintenance has been undertaken.

Contact: Chris Miners 0117 975 1355

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



Non'	-
© Historic England	

SITE NAME:	Church of St Mary the Virgin, Flaxley, Blaisdon
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1186458

Parish church, 1856, by Sir George Gilbert Scott. Red sandstone ashlar, with grey sandstone ashlar dressings, timber porch, tiled roof with crested ridge, shingles to spire. Nave, north aisle, with tower at its west end, chancel, organ chamber and south porch. The nave roofs have had repairs, however the chancel and organ chamber roofs need urgent re-tiling. The spire shingling needs renewing following woodpecker damage.

Contact: Chris Miners 0117 975 1355

A	

© Historic England

© Historic England

SITE NAME: Church of St Michael and All Angels, Blaisdon DESIGNATION: Listed Place of Worship grade II CONDITION: Poor PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1299195

Parish church, C15 tower, the rest rebuilt 1867-9 by FR Kempson of Hereford in the Early English style. Tower thin coursed rubble, church squared red Forest stone with Bath stone ashlar dressings; slate roof. West tower, four-bay nave, with north aisle, chancel with vestry, south entrance porch. The damp penetration into the church stonework at both high and low level put the building at risk. A Listed Places of Worship Roof Repairs Grant was accepted in 2015 for repairs which have addressed some of the issues.

Contact: Chris Miners 0117 975 1355



SITE NAME:	Church of St Mary, Dymock
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1303073

Large parish church. C11, C12, C14, C15, probably C18, Cl9 restoration. Tower, well-squared coursed stone; west end nave and east end chancel random rubble with ashlar dressings; transepts and vestry roughly squared, coursed stone with ashlar dressings; squared, coursed stone to east end nave, and bottom part west end, also west part of chancel. Tiled roofs, shingled spire. The stonework of the tower and buttresses is heavily eroded and a repair scheme is planned. The tiled roof pitches have been repaired.

Contact: Chris Miners 0117 975 1355

APACE 1	
A A A A A A A A A A A A A A A A A A A	
The last the second sec	-
	A

© Historic England

SITE NAME:	Church of St Michael, High Street, Mitcheldean
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1100286

Large parish church with a tall tower and needle spire. Slate roofs, south aisle flat roof. A National Lottery Heritage Fund and Historic England Repair Grant for Places of Worship remedied some structural problems of the spire and the high level west aisle gables in 2012. A Listed Places of Worship Roof Repairs Grant repaired further roof problems, however more problems remain with instability at the apex of the spire.

Contact: Chris Miners 0117 975 1355



© Historic	England

SITE NAME:	Church of St Saviour, Redbrook, Newland
designation:	Listed Place of Worship grade II
CONDITION:	Very bad
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation

1212814

Small parish church, now sharing community hall uses, by JP Seddon in 1873. Nave with south porch and chancel with south chapel and bellcote; in red sandstone with buff limestone dressings. The limestone and sandstone mix has been auto-destructive with severe erosion of the sandstone on the north wall and to the limestone on the dressings on the south side. The tiled roof on the south nave pitch has slipped or missing tiles.

Contact: Chris Miners 0117 975 1355

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise,

New Entry is noted).

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

ABBREVIATIONS

LIST ENTRY NUMBER:



© Historic England

SITE NAME: Church of St Bartholomew, The Causeway, Redmarley D'abitot Listed Place of Worship grade II, DESIGNATION: CA CONDITION: Poor PRIORITY CATEGORY: A (A) OWNER TYPE: Religious organisation

Large parish church of sandstone ashlar with tiled roofs. C13, and part of the tower probably dates from that time; but the majority of the building goes back only to 1855when most of the church was in serious disrepair, demolished and rebuilt. The stonework of the tower is seriously eroded with open jointing and structural cracking and rainwater disposal problems. Some falls of stone have been reported.

Contact: Chris Miners 0117 975 1355

SITE NAME:	Church of St Mary, Upleadon
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Fair
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1153374

1341976

Small parish church; C12, C15, C18, restored 1850, 1879 by Ewan Christian; vestry added 1884. West tower is close-studded timber-framed tower, brick nogged, on squared, coursed stone plinth: with pyramidal slate roof. Nave sandstone ashlar with south entrance porch, lower east chancel with projecting north vestry. All with graduated stone slate roofs. The timber frame has patches of decay and some stone slates are slipping.

Contact: Chris Miners 0117 975 1355

© Historic	England
------------	---------

SITE NAME:	Whitecliff Iron Works, Coleford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021420
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Melanie Barge 0117 975 1300
SITE NAME:	Offa's Dyke: section in Caswell Wood, 280 metres	west of Beeches F	arm, Tidenham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020601
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Offa's Dyke: section in Chapelhouse Wood, 240 m	etres west of the R	ecreation Ground, Tidenham
SITE NAME: DESIGNATION:	Offa's Dyke: section in Chapelhouse Wood, 240 m Scheduled Monument	netres west of the R	ecreation Ground, Tidenham
DESIGNATION:	Scheduled Monument Generally unsatisfactory with major localised	LIST ENTRY NUMBER:	1020639
DESIGNATION: CONDITION:	Scheduled Monument Generally unsatisfactory with major localised problems	LIST ENTRY NUMBER:	1020639 Declining
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY:	Scheduled Monument Generally unsatisfactory with major localised problems Scrub/tree growth	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:	1020639 Declining No Alessandra Perrone 0117 975 1345
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument Generally unsatisfactory with major localised problems Scrub/tree growth Private, multiple owners	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:	1020639 Declining No Alessandra Perrone 0117 975 1345
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument Generally unsatisfactory with major localised problems Scrub/tree growth Private, multiple owners Offa's Dyke: section in Lippets Grove, 680 metres	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: WSW of Beeches I	1020639 Declining No Alessandra Perrone 0117 975 1345 Farm, Tidenham
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument Generally unsatisfactory with major localised problems Scrub/tree growth Private, multiple owners Offa's Dyke: section in Lippets Grove, 680 metres Scheduled Monument Generally unsatisfactory with major localised	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: WSW of Beeches I	1020639 Declining No Alessandra Perrone 0117 975 1345 Farm, Tidenham 1020602

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

SITE NAME:	Offa's Dyke: section in Passage Grove, 660 metres west of Sheepcot, Tidenham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020603
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Offa's Dyke: section in Worgan's Wood, 800 metr	es west of Chase F	arm, Tidenham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020605
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Roman villa 600 yards (550 metres) south west of	Woolaston Station	, Woolaston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004860
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345

GLOUCESTER



Church of St Nicholas, SITE NAME: Westgate Street DESIGNATION: Listed Building grade I, CA CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (New entry) OWNER TYPE: Charity (heritage)

Large urban church made redundant in 1971 and vested with the Churches Conservation Trust in 1975. Nave and flanking aisles with west tower sumounted by a truncated leaning stone spire. C12 origins with mostly C13 fabric and a CI5 tower. The roof structure needs urgent structural repair and slate roof coverings have come to the end of their life.

LIST ENTRY NUMBER: 1245083 Contact: Chris Miners 0117 975 1355 © Historic England



© Gloucester City Council

SITE NAME:	New Inn, 16, 18 and 20, Northgate Street
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1245714

Mid C15 inn. Four timber-framed ranges around a central courtyard forming the most complete example of a medieval courtyard inn with galleries. In partial use but areas of the building are in poor repair due to long periods of neglect. Some repairs and maintenance ongoing with current owners. Repairs following a fire in 2018 have highlighted the poor condition of the building.

Contact: Chris Miners 0117 975 1355

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site

OCCUPANCY:

PRIORITY CATEGORY:



© Gloucester City Council

SITE NAME:	Llanthony Priory, remains of precinct wall north of Inner Gatehouse, Llanthony Road, Gloucester
DESIGNATION:	Scheduled Monument and Listed Buildings - 6 grade I, LB grade II, part in CA
CONDITION:	Poor

Stone and brick wall on the west and north sides of the Outer Court of the former Augustinian Priory. Built in the C15, it was rebuilt or extended in the C17 and C18. The Llanthony Priory Trust successfully bid for National Lottery Heritage Fund grant and repair works to most of the Priory site are now complete. This length of wall will remain unrepaired for the short term due to budget constraints.

OWNER TYPE: Charity (heritage)

N/A

C (C)

1002091 and 1271693; LIST ENTRY NUMBER: 1271697; 1271694; 1271696;

1271695; 1271698

Contact: Chris Miners 0117 975 1355



© Historic England

SITE NAME:	The Fleece Hotel, 19, Westgate Street, Gloucester
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Local authority

LIST ENTRY NUMBER: 1245447

LIST ENTRY NUMBER:

C15 timber-framed range most recently occupied as the Fleece Hotel. The building has been vacant for some time. It is in poor repair, with some internal decay. A series of opening up works were carried out early summer 2010 to provide more information on the condition. Ownership passed to Gloucester City Council in 2011 who have done some emergency repairs, and a Timber Frame Report and Options Appraisal have now been produced. They are now working with a development partner to produce a comprehensive scheme subject to grant assistance.

Contact: Stephen Guy 0117 975 0725



© Historic England

SITE NAME:	Old Judges House, 26, Westgate Street, Gloucester
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Commercial company

1245450

Late C15 timber-framed merchant house, greatly enlarged and remodelled in late C16/early C17. Refronted and altered internally c1815. Operated as seed merchant for c100 years until 1989, then partly occupied as bookshop, before becoming vacant. Whilst some repairs have been undertaken, there remain many areas which require attention, particularly the roof and significant joinery. The upper floors are now accessible via a new lift, although not yet in use. This will generate income to help fund roof and joinery repairs.

Built in 1733 for Sir John Guise of Elmore Court and his family in neoclassical style, as an exact copy of what the commissioner thought to be Virgil's tomb in Italy. The monument, which includes a burial vault, has been left ruinous after the collapse of its pyramidal roof in the early C20. The ashlar and decorative elements which remain have been affected by weathering and erosion. Vegetation has also taken hold of the plot and is obscuring some of the

Contact: Stephen Guy 0117 975 0725

SITE NAME:	Barton Street, Gloucester		
DESIGNATION:	Conservation Area, 5 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Charlotte Bowles-Lewis (LPA) 01452 396855

STROUD



© Historic England

SITE NAME:	Guise Mausoleum to north west of Church of St John the Baptist, Stroud Road, Brookthorpe, Elmore
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Charity (heritage)

1247875

masonry. Charity (heritage)

Contact: Alessandra Perrone 0117 975 1345

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England

SITE NAME:	Main building at Stanley Mills, Ryeford, King's Stanley
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Commercial company

1171285

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

Woollen mill, 1813. Ancillary building (grade II) is in poor condition and part occupied. Roof repaired with Historic England grant. A proposal for repair and conservation was granted consent in 2011. The planning permission has been implemented by a commencement on the factory building and the enabling development has now also started on site. Main works to the mill are yet to begin and condition is deteriorating. Temporary repairs have been carried out to areas of the roof following a series of lead thefts in 2017.

Contact: Stephen Guy 0117 975 0725



© Historic England Archive

SITE NAME:	St Mary's House, London Road, Minchinhampton
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

1091156

Former mill owner's house and weavers' cottages, late C16 and late C17. Roof in exceptionally poor condition and has been covered with tarpaulin for over 30 years. There are signs of detachment of the shell hood over the front door and external joinery continues to deteriorate. The local planning authority continues to engage with the owner to seek remedial and longer term repairs.

Contact: Stephen Guy 0117 975 0725



© Historic England

SITE NAME:	Old Mill Building at Longfords Mills, Avening Valley, Minchinhampton
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1305339

Centrepiece of an extensive industrial complex, from 1766. This is one of two buildings on site to remain vacant after a residential redevelopment that has refurbished and re-used the rest of the complex. Repairs and conservation proposals are being explored by a local Trust.

© Historic England

SITE NAME:	Woodchester Mansion, Woodchester
DESIGNATION:	Listed Building grade I, RPG grade II
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1340703

Mansion c1854-68 incorporating a magnificent private chapel. The Woodchester Mansion Trust was formed in 1989 to do a continuous programme of conservation and display of the uncompleted Gothic-style masterpiece. In 1991 a protective scaffold was built to cover the leaking roof of the chapel. The scaffold is now decaying and unsafe. Other adjacent roofs are now developing serious faults. Development work is being organised in order to apply for the large grant funding now needed. A CMP and development work for roof repairs are underway. Emergency repairs are also underway for the north gable.

Contact: Chris Miners 0117 975 1355

Contact: Alessandra Perrone 0117 975 1345



© Historic England

SITE NAME:	Church of St Mary the Virgin, Church Lane, Berkeley
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1304581

Parish church. C12 foundation on probable site of important early medieval minster church, altered in C13 and C15, and in C19. Random coursed rubblestone, roofs with coped verges and cross finials. Nave and aisles of seven bays with clerestory windows to south only, north porch, lower chancel with flanking chapels. The roof has been extensively repaired. The extensive interior wall paintings continue to decay.

Contact: Chris Miners 0117 975 1355

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS	
CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garde
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	Church of St Mary, Fretherne with Saul
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1154542

Largel mid-Victorian parish church in an isolated site. Ornate in the decorated style of sandstone with limestone dressings. There has been a loss of stonework with many falls of carved features.

© Historic England

1	-	
		-
	-	· ·
7	0	A PAR
	11.	
	THE RE	

SITE NAME:	Church of St James, Fretherne with Saul
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1090510

LIST ENTRY NUMBER:

Church said to date originally from 1140, with elements from C15 and C16. Enlarged and restored at different times in C19. Roof coverings, which vary from stone slate on some areas to concrete tiles on others, are in very bad condition. The rainwater goods need repairing and replacing where previous patch repairs have failed. The stonework of the tower is delaminated in places.

Contact: Chris Miners 0117 975 1355

© Historic England

SITE NAME:	Church of St Giles, High Street, Hillesley, Hillesley and Tresham
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1129364

Church, 1851 by Reverend B Perkins, Vicar of Wotton Under Edge, in Éarly English style. Coursed rubble with freestone dressing; Cotswold stone slate roofs. Nave with clerestory, north and south aisles, chancel and south porch. The roofs at east end of the church have stone slates in bad condition.

© Historic England



SITE NAME:	Church of St John the Baptist, B4072, Edge, Painswick
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1172665

Small Victorian rural church. Cotswold stone walls, roof tiles and tower with a squat spire. The congregation has completed a repair scheme to the tower and spire, however the stone slate roofs are in need of renewal soon.

© Historic England



SITE NAME:	Church of St Mary Magdalene, Church Place, Rodborough
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1340958

St Mary Magdalene is a parish church with an early C16 west tower. The body of the church dates largely from 1842, to a design by Thomas Foster and Son of Bristol, with 1895 additions by FS and FW Waller all in the Decorated style. The roof pitches have some missing or fractured stone slates and the rainwater goods need an urgent overhaul.

© Historic England

Contact: Chris Miners 0117 975 1355

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England

SITE NAME:	Church of St Andrew, Whitminster
DESIGNATION:	Listed Place of Worship grade

II*, CA CONDITION: Poor PRIORITY CATEGORY: A (A)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1303052 Small church. Cll foundation, earliest work probably of C14, altered and tower added late C15/early C16, north aisle added 1842, restored c1884-5 by Sir Arthur Blomfield. Random coursed and dressed stone, ashlar tower and part ashlar walls, stone slate roof with coped east verges with saddle stones and cross finials. West tower, nave with south porch and north aisle, chancel, with north vestry of 1880s. The stone slates have slipped or fallen on the nave and north aisle pitches and the porch.

Contact: Chris Miners 0117 975 1355

SITE NAME:	Bowl barrow 450 metres south east of Upper Hyd	le Farm, Minchinhar	mpton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008626	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Alessandra Perrone 0117 975 1345	
SITE NAME:	Miserden Castle mound, Miserden			
DESIGNATION:	Scheduled Monument, RPG grade II*	LIST ENTRY NUMBER:	1004870	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345	
SITE NAME:	Bowl barrow 720 metres south east of Longwood Farm, Woodchester			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017084	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345	
SITE NAME:	Bowl barrow 330 metres north of Symonds' Hall F	Bowl barrow 330 metres north of Symonds' Hall Farm, Wotton-under-Edge		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017083	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345	
SITE NAME:	Stanley Mills, Kings Stanley, King's Stanley / Stoneh	Stanley Mills, Kings Stanley, King's Stanley / Stonehouse		
DESIGNATION:	Conservation Area, 7 LBs	NEW ENTRY?:	No	
CONDITION:	Very bad	TREND:	Deteriorating	
VULNERABILITY:	High	CONTACT:	Kate Russell (LPA) 01453 766321	
SITE NAME:	Stroud Industrial Heritage (IHCA), Multiple parishes within Stroud District, Whitminster / Woodchester / Bisley-with-Lypiatt / Brimscombe and Thrupp / Cainscross / Chalford / Eastington / Frampton on Severn / Fretherne with Saul / King's Stanley / Leonard			
DESIGNATION:	Conservation Area, 188 LBs, part in SM	NEW ENTRY?:	No	
CONDITION:	Poor	TREND:	Deteriorating	
VULNERABILITY:	Medium	CONTACT:	Kate Russell (LPA) 01453 766321	

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

TEWKESBURY



© Mr John Brookes. Source Historic

SITE NAME: Dovecote approximately 75 metres south east of Manor Farm, Ashchurch, Ashchurch Rural

DESIGNATION: Listed Building grade II*

CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C)

OWNER TYPE: Private

LIST ENTRY NUMBER: 1091923

Dovecote, 1637. Pointing eroded particularly on the north face. Occasional missing roof tiles, although some roofing works have taken place.

Contact: Alessandra Perrone 0117 975 1345



© Historic England

SITE NAME: Dovecote three metres north of Bridge House, Bentham, Badgeworth

DESIGNATION: Listed Building grade II*

CONDITION: Poor OCCUPANCY: N/A

PRIORITY CATEGORY: C (C) OWNER TYPE: Private

LIST ENTRY NUMBER: 1304753

Dovecote, C17. Movement of structural timbers on south east and north east walls has caused joints to pull apart, leading to brick panels falling out. Wattle and daub panels are fragmenting. Some timber decay on the west side and cement repairs to the roof are also of concern.

Contact: Alessandra Perrone 0117 975 1345



© Historic England

SITE NAME: Southam tithe barn and shelter shed, Southam Lane, Southam DESIGNATION: Listed Building grade II* CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: A(A)

OWNER TYPE: Private LIST ENTRY NUMBER: 1091668

Large late medieval tithe barn converted to assembly uses but now vacant. Weather boarded timber-framed walls on a high stone plinth. Artificial stone (concrete) moulded tile roof has holes. The roof truss frames have structural faults. One bay of the roof (east end) exhibits severe bowing due to failed purlins. Short term holding repairs have prevented an immediate collapse of the roof.

Contact: Chris Miners 0117 975 1355



© Historic England

SITE NAME: Mythe Bridge, A438, Tewkesbury Listed Building grade II*, part in DESIGNATION: CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Local authority, multiple owners

LIST ENTRY NUMBER: 1282810

Road bridge over the River Severn. Built 1823-26 by Thomas Telford, cast iron bridge of six segmental arched latticed beams, latticed roadway beam with latticed ironwork filling the spandrels. Each abutment has outer and inner sandstone piers separated by six brick arched tunnel vaults with cast iron colonettes. Cast iron roadway balustrade between piers. Ironwork of the balustrades is rusting at connections. Traffic damage to north balustrade. Sandstone piers, especially above roadway level, are severely fractured and eroded, some covered in excessive and harmful ivy growth.

Contact: John Ette 0117 975 0687



© Tewkesbury Borough Council

SITE NAME: Malthouse to the rear of 23, Barton Street, Tewkesbury DESIGNATION: Listed Building grade II*, CA CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: D (D) OWNER TYPE: Private

1281018

Workshop, former malthouse. C17. Building has been unoccupied for some time. Listed Building Consent was approved in 2016 for conversion from a workshop to a dwelling. However, the permission has not been implemented and work is yet to start.

Contact: Stephen Guy 0117 975 0725

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

LIST ENTRY NUMBER



ewkesbury Borough Counci

SITE NAME:	88, Church Street, Tewkesbury
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private, multiple owners

1205905

Late C15 town house, altered C16 and C19, with shop under. Building only partly occupied and in poor condition with broken windows on second floor.


Contact: Alessandra Perrone 0117 975 1345

© Historic England Archive

SITE NAME:	Toddington Manor, Toddington
DESIGNATION:	Listed Building grade I, RPG grade II
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1340101

Manor house, 1820-35, set in C19 formal gardens, on the east side of a late C18 landscape park. The house was mothballed for more than 15 years, but has been purchased by a new owner who engaged in an extensive programme of urgent works and repairs in consultation with the Local Planning Authority and Historic England. Following extensive stabilisation work, a temporary protective roof was installed and is in good order. There is no apparent further deterioration to the fabric. Discussions are ongoing with the owner's agent regarding building repairs.

Contact: Stephen Guy 0117 975 0725



SITE NAME:	Church of St Nicholas, Ashchurch Rural
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1153103

Parish church. C12, C13, late C14, and C15, restored 1889 and 1931, small mid-late C20 extension. Nave; random limestone. Clerestory; coursed squared and finely dressed limestone and sandstone. South porch and tower; large blocks coursed finely dressed limestone. Artificial stone slate roof to chancel. Red tile roof to C12 nave with C15 clerestory. Nave south wall; two raking buttresses (possibly added C14). The roof is in bad condition masked behind the nave parapet. The chancel north pitch has slipped

Contact: Chris Miners 0117 975 1355



© Historic England

© Historic England

SITE NAME:	Church of St Mary Magdalene,
	Boddington
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1172312

Small parish church. C12, C13, C14, possibly early C17, C18, restored late C19, mid C20 vestry. Random rubble stone, larger quoins, ashlar buttresses; north and east walls rendered; stone slate roof, band of concrete tiles to north slope nave; concrete tiles to vestry. There are structural problems with the nave that put this church at risk.

Contact: Chris Miners 0117 975 1355



© Historic England

SITE NAME:	Church of St John the Baptist, Oxenton
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1303393

Parish church. C13, C14 and C15, restored 1905. Nave and chancel coursed limestone rubble except the south wall of chancel which is coursed squared and dressed limestone. Porch and north aisle also coursed squared and dressed limestone. Tower and mortuary chapel: ashlar; stone slate roof. Nave with north aisle with mortuary chapel at right angles, chancel and west tower. The key issue is the decay of the interior plaster and the threat that this poses to the wall paintings.

Contact: Chris Miners 0117 975 1355

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



SITE NAME:	Church of St Martin, Charlton Abbotts, Sudeley
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1340100

Tiny parish church in a small hillside churchyard. Nave with south porch and north vestry and lower chancel all in limestone ashlar. All from an 1887 rebuild of a ruin, incorporating medieval features, except for the vestry added in 1933. Graduated limestone slate roofs which are in need of repair especially on the north side.

Contact: Chris Miners 0117 975 1355

© Historic England

SITE NAME:	Great Witcombe Romano-British villa, Great Wi	tcombe / Brockwortl	1
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014826
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Over earthwork, Highnam		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002092
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Hailes Wood camp, Hailes, Stanway		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004843
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Milhampost Roman site, Stanway		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004844
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Spoonley Wood Roman villa, Sudeley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004847
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Melanie Barge 0117 975 1300
SITE NAME:	Wadfield Roman villa, Sudeley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004846
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
 - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Romano-British villa 170 metres south west of Winchcombe School, Greet Road, Winchcombe		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021449
CONDITION:	Extensive significant problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Alessandra Perrone 0117 975 1345

ISLES OF SCILLY (UA)



© Historic England Archive

SITE NAME: Late C19-early C20 Woolpack Battery on The Garrison, St. Mary's Scheduled Monument, LB grade DESIGNATION: II, CA CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C)

OWNER TYPE: Crown LIST ENTRY NUMBER: 1014783

LIST ENTRY NUMBER:

Late C19/early C20 battery. Generally good condition and secure but unoccupied since 2015. Converted to volunteer hostel accommodation in late C20/early C21 but now suffering from problems with water ingress into the former magazines, now dormitories. Discussions regarding repair and potential new uses are underway with the site owner, and the Local Authority.

Contact: Helen Woodhouse 0117 975 0676



© Historic England Archive

SITE NAME: Post-medieval cottages, Samson, Tresco Scheduled Monument, part in DESIGNATION: CA CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Crown

1016509

Fossilised C18/C19 landscape. The remains of the buildings are at risk from natural weathering, vegetation and erosion caused by visitors. A management plan has been devised and initial phase of consolidation grant-aided by Historic England is now complete. The results of the consolidation trials are being studied to ultimately inform a wider programme of repair.

Contact: Ann Preston-Jones 07917 642388

SITE NAME: Gig shed on the north coast of Great Porth, Bryher DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1016173 CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Dumping NEW ENTRY?: No	DESIGNATION: Scheduled Monument, CA Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Vehicle damage/erosion - moderate OWNER TYPE: Crown SITE NAME: Gig shed on the north coast of Great Porth, Bry DESIGNATION: Scheduled Monument, CA CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Dumping OWNER TYPE: Crown SITE NAME: Prehistoric enclosure south east of The Brow, B DESIGNATION: Scheduled Monument, CA CONDITION: Generally satisfactory but with significant localised problems		
CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Vehicle damage/erosion - moderate NEW ENTRY?: No OWNER TYPE: Crown CONTACT: Ann Preston-Jones 07917 642388 SITE NAME: Gig shed on the north coast of Great Porth, Bryher DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1016173 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Dumping NEW ENTRY?: No OWNER TYPE: Crown CONTACT: Ann Preston-Jones 07917 642388 SITE NAME: Prehistoric enclosure south east of The Brow, Bryher DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1015649 CONDITION: Generally satisfactory but with significant localised problems TREND: Declining	CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Vehicle damage/erosion - moderate OWNER TYPE: Crown SITE NAME: Gig shed on the north coast of Great Porth, Bry DESIGNATION: Scheduled Monument, CA CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Dumping OWNER TYPE: Crown SITE NAME: Prehistoric enclosure south east of The Brow, Be DESIGNATION: Scheduled Monument, CA Generally satisfactory but with significant localised problems		
problems PRINCIPAL VULNERABILITY: Vehicle damage/erosion - moderate OWNER TYPE: Crown Contact: Ann Preston-Jones 07917 642388 SITE NAME: Gig shed on the north coast of Great Porth, Bryher DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1016173 CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Dumping OWNER TYPE: Crown Contact: Ann Preston-Jones 07917 642388 SITE NAME: Prehistoric enclosure south east of The Brow, Bryher DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1015649 CONDITION: Generally satisfactory but with significant localised problems TREND: Declining	PRINCIPAL VULNERABILITY: Vehicle damage/erosion - moderate OWNER TYPE: Crown SITE NAME: Gig shed on the north coast of Great Porth, Bry DESIGNATION: Scheduled Monument, CA CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Dumping OWNER TYPE: Crown SITE NAME: Prehistoric enclosure south east of The Brow, B DESIGNATION: Scheduled Monument, CA CONDITION: Generally satisfactory but with significant localised problems	LIST ENTRY NUMBER:	1010176
OWNER TYPE: Crown CONTACT: Ann Preston-Jones 07917 642388 SITE NAME: Gig shed on the north coast of Great Porth, Bryher DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1016173 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Dumping NEW ENTRYP: NO CONTACT: Ann Preston-Jones 07917 642388 SITE NAME: Prehistoric enclosure south east of The Brow, Bryher DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1015649 CONDITION: Generally satisfactory but with significant localised problems Declining	OWNER TYPE: Crown SITE NAME: Gig shed on the north coast of Great Porth, Bry DESIGNATION: Scheduled Monument, CA CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Dumping OWNER TYPE: Crown SITE NAME: Prehistoric enclosure south east of The Brow, Business of	TREND:	Declining
SITE NAME: Gig shed on the north coast of Great Porth, Bryher DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1016173 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Dumping NEW ENTRY?: NO CONTACT: Ann Preston-Jones 07917 642388 SITE NAME: Prehistoric enclosure south east of The Brow, Bryher DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1015649 CONDITION: Generally satisfactory but with significant localised problems TREND: Declining	SITE NAME: Gig shed on the north coast of Great Porth, Bry DESIGNATION: Scheduled Monument, CA CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Dumping OWNER TYPE: Crown SITE NAME: Prehistoric enclosure south east of The Brow, Business	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1016173 CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Dumping OWNER TYPE: Crown CONTACT: Ann Preston-Jones 07917 642388 SITE NAME: Prehistoric enclosure south east of The Brow, Bryher DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1015649 CONDITION: Generally satisfactory but with significant localised problems DESIGNATION: Declining	DESIGNATION: Scheduled Monument, CA CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Dumping OWNER TYPE: Crown SITE NAME: Prehistoric enclosure south east of The Brow, B DESIGNATION: Scheduled Monument, CA CONDITION: Generally satisfactory but with significant localised problems	CONTACT:	Ann Preston-Jones 07917 642388
CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Dumping NEW ENTRY?: No CONTACT: Ann Preston-Jones 07917 642388 SITE NAME: Prehistoric enclosure south east of The Brow, Bryher DESIGNATION: Scheduled Monument, CA CONDITION: Generally satisfactory but with significant localised problems TREND: Declining No CONTACT: Ann Preston-Jones 07917 642388 ILIST ENTRY NUMBER: 1015649 TREND: Declining	CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Dumping OWNER TYPE: Crown SITE NAME: Prehistoric enclosure south east of The Brow, B DESIGNATION: Scheduled Monument, CA CONDITION: Generally satisfactory but with significant localised problems	er	
PRINCIPAL VULNERABILITY: Dumping NEW ENTRY?: NO OWNER TYPE: Crown CONTACT: Ann Preston-Jones 07917 642388 SITE NAME: Prehistoric enclosure south east of The Brow, Bryher DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: LIST ENTRY NUMBER: Declining Declining	PRINCIPAL VULNERABILITY: Dumping OWNER TYPE: Crown SITE NAME: Prehistoric enclosure south east of The Brow, B DESIGNATION: Scheduled Monument, CA Generally satisfactory but with significant localised problems	LIST ENTRY NUMBER:	1016173
OWNER TYPE: Crown CONTACT: Ann Preston-Jones 07917 642388 SITE NAME: Prehistoric enclosure south east of The Brow, Bryher DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: Generally satisfactory but with significant localised problems TREND: Declining	OWNER TYPE: Crown SITE NAME: Prehistoric enclosure south east of The Brow, B DESIGNATION: Scheduled Monument, CA CONDITION: Generally satisfactory but with significant localised problems	TREND:	Declining
SITE NAME: Prehistoric enclosure south east of The Brow, Bryher DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1015649 CONDITION: Generally satisfactory but with significant localised problems Declining	SITE NAME: Prehistoric enclosure south east of The Brow, B DESIGNATION: Scheduled Monument, CA CONDITION: Generally satisfactory but with significant localised problems	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument, CA CONDITION: Scheduled Monument, CA Generally satisfactory but with significant localised problems LIST ENTRY NUMBER: 1015649 TREND: Declining	DESIGNATION: Scheduled Monument, CA CONDITION: Generally satisfactory but with significant localised problems	CONTACT:	Ann Preston-Jones 07917 642388
CONDITION: Generally satisfactory but with significant localised problems TREND: Declining	CONDITION: Generally satisfactory but with significant localised problems	her .	
problems Declining	problems	LIST ENTRY NUMBER:	1015649
PRINCIPAL VULNERABILITY: Other NEW ENTRY: No	DDINICIDAL VI II NIEDADII ITV		Declining
	Trincil At Volumerability. Other	TREND:	
OWNER TYPE: Crown CONTACT: Ann Preston-Jones 07917 642388	OWNER TYPE: Crown		No

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

SITE NAME:	Prehistoric field system and post-medieval quay in Great Porth, Bryher		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1014987
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric field system and Romano-British cist in	Green Bay, Bryher	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1014989
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric hut circle south of The Brow, Bryher		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1014990
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric linear boundary and cairns south west of The Bar, Bryher		
Designation:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1016170
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric linear boundary SSE of The Island, Bryh	er	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1014991
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric cairns, entrance graves, field system and settlements and post-medieval kelp pits on Kittern Hill, Gugh, St. Agnes		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1014792
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Russell 0117 975 0671
SITE NAME:	Prehistoric entrance grave and two round cairns on the Clapper of Works, Gugh, St. Agnes		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1008337
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Prehistoric field system and post-medieval breastw	ork and maze on C	Castella Down, St. Agnes
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1015697
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Kerbed round cairn with central cist on Gun Hill, S	St. Martin's	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1013809
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth - General	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Platform cairn on Turfy Hill, St. Martin's		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1018114
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric cairn cemetery and field system on Tinl	kler's Hill, St. Marti	n's
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1018109
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric entrance grave, the middle one of three on Cruther's Hill, St. Martin's		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1013804
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric entrance grave, the northern one of the	ree on Cruther's H	ill, St. Martin's
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1013803
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric entrance grave, the southern one of the Martin's	ree, and kerbed rou	und cairn with cist on Cruther's Hill,
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1013805
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
	Cromm		,

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Prehistoric field system and kerbed cairn, with pos Island, St. Martin's	t-medieval kelp pit	and linear boundary on southern Wh
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1014789
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Russell 0117 975 0671
ITE NAME:	Ennor Castle, Old Town, St. Mary's		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1014994
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
TE NAME:	Hut circle settlement in Pendrathen, St. Mary's		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1015663
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
ITE NAME:	Post-medieval breastwork, curtain wall and associa St. Mary's	ted defensive struc	tures on the periphery of The Garris
DESIGNATION:	Scheduled Monument, LB grade I, CA	LIST ENTRY NUMBER:	1018370
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	The Old Quay, Old Town Bay, St. Mary's		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1015656
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
ITE NAME:	World War II pillbox between Thomas' Porth and	Porthaloo, St. Mary	y's
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1016517
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	World War II pillbox west of Porth Hellick, 90 me	tres north of Drum	n Rock, St. Mary's
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1016516
CONDITION:	Extensive significant problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

HERITAGE AT RISK 2020 / SOL	JTH WEST / ISLES OF SCILLY (UA) / NORTH SOMERSET (UA)		
SITE NAME:	Prehistoric cairn group on Abbey Hill, Tresco		
DESIGNATION:	Scheduled Monument, LB grade I, RPG grade I, CA	LIST ENTRY NUMBER:	1016183
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Visitor erosion - limited/localised	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric field system and hut circle north of Cra	b's Ledge, Tresco	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1016422
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric field system and settlement in Bathingho	ouse Porth, Tresco)
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1016423
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric field system and settlement north of Ap	pletree Point, Tre	sco
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1016182
CONDITION:	Unknown	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric to post-medieval funerary, field system a deer park on and adjacent to Samson, Tresco	and settlement rer	mains, with post-medieval kelp pit and
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1016509
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	St Nicholas' Priory, Tresco		
DESIGNATION:	Scheduled Monument, LB grade I, RPG grade I, CA	LIST ENTRY NUMBER:	1016184
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388

NORTH SOMERSET (UA)



SITE NAME: Ashton Court, Long Ashton Listed Building grade I, RPG DESIGNATION: grade II* CONDITION: Very bad OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C (C) OWNER TYPE: Local authority LIST ENTRY NUMBER: 1129841

Large country house with various elements dating from C15, C17, C18 and C19. House partly used but large part remains derelict and subject to slow but ongoing decay. The house has been the subject of negotiations between owners, Local Planning Authority, Historic England and other interested parties for many years. Historic England grant offered in 2011 for project development work, the majority of which was completed by 2013. Options Appraisal completed for Bristol City Council in May 2019. Historic England in ongoing discussions with Bristol City

Contact: Sarah Ball 0117 975 0666

PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



© Historic England

SITE NAME:	Elms Colliery, Nailsea
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Local authority

Local authority LIST ENTRY NUMBER: 1004533 and 1320976

Known locally as Middle Engine Pit, this is one of the most complete examples of an early C19 colliery in England. However the surviving structures are in a poor and vulnerable condition. In 2019 Historic England grant-aided a programme of investigations, recording and stabilisation to some of the most vulnerable structures on site.

Contact: Alessandra Perrone 0117 975 1345



© Historic England

© Historic England

SITE NAME:	Birnbeck Pier, Weston-Super- Mare
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Commercial company

1129718

LIST ENTRY NUMBER:

Birnbeck Pier is a unique and nationally important structure connecting the mainland below the Prince Consort Gardens to Birnbeck Island. Enforcement action in the form of a Repairs Notice was served on the owners in September 2019 but has not been complied with. The Council is now working towards the potential Compulsary Purchase Order of the pier with guidance and funding from Historic England.

Contact: John Ette 0117 975 0687



SITE NAME:	St Mary's Church, Church Lane, Portbury
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1311826

C12 parish church, altered and extended early C13 and C14/C15, restored 1870-5. The stone slate roofs of the chancel, vestry and associated lean-to roofs have come to the end of their life. Water has been getting in causing ceiling plaster falls. A National Lottery Heritage Fund Grant for Places of Worship enabled roof repairs to be completed in 2014. However, further problems with the poor state of the sandstone wall, especially on the south transept, keeps the church at risk. A further National Lottery Heritage Fund grant has been awarded and the project development is nearing completion.

Contact: Chris Miners 0117 975 1355

SITE NAME:	Worlebury Camp: a large multivallate hillfort on Worlebury Hill, Weston-Super-Mare		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1011260
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Long barrow 350 metres south west of Cornerpod	ol Farm, Wrington	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008291
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG UA Unitary Authority
WHS World Heritage Site

PLYMOUTH, CITY OF (UA)



© Historic England

SITE NAME: Eggbuckland Keep

DESIGNATION: Listed Building grade II*, SM

CONDITION: Very bad

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: A (New entry)

1390897

OWNER TYPE: Private

LIST ENTRY NUMBER:

Contact: Phil McMahon 0117 975 0699

. 61	
1 1 1 1 1 1 1	
20 1 1 0 1 1	

© Historic England Archive

SITE NAME:

Academy Theatre and Great Western Hotel (Palace Theatre), Union Street, Stonehouse, Plymouth

DESIGNATION:

Listed Building grade II*, CA

CONDITION:

Very bad

OCCUPANCY:

Vacant/not in use

PRIORITY CATEGORY:

A (A)

OWNER TYPE:

Private

Former variety theatre and hotel, built 1898. A significant building in an area where major regeneration has been underway. Historic England has offered grant aid in the past, which was not taken up. Temporary repairs were undertaken in 2013 and 2015 to make the theatre weathertight. Further temporary weatherproofing has been put in place in the last few years but as of 2020 a full condition report and detailed scheme of repairs, and a business plan for reuse of the building, are still required.

Problems with water ingress, thought to be due to deterioration of ashfelt membrane between earthen

discussion with Historic England.

ramparts above and masonry vaults beneath. Owner is in

LIST ENTRY NUMBER: 1386483

LIST ENTRY NUMBER:

Contact: Annie Evans 0117 975 0673



© Historic England Archive

SITE NAME: Knowle Battery

DESIGNATION: Scheduled Monument

CONDITION: Good

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C (C)

OWNER TYPE: Local authority

1002614

Palmerston Fort; part of the site is now the grounds of a primary school. Historic England funded a Condition Survey of the structure with proposals for refurbishment in preparation for re-use of the guardhouse, and a five year Management Agreement to control vegetation. Further funding from Historic England and Plymouth City Council has addressed the most urgent repair issues and the shell is now in good repair. A new user had been identified but sadly negotiations have faltered. Until a new use is in place the site remains very vulnerable to vandalism.

Contact: Annie Evans 0117 975 0673



© Historic England Archive

SITE NAME:	Agaton Fort, Plymouth
DESIGNATION:	Scheduled Monument
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Government or agency
LIST ENTRY NUMBER:	1002613

One of the ring of C19 land forts built to defend Plymouth. Overlooks River Tamar. Irregular pentagonal plan, with deep ditch on four sides protected by caponiers and a counterscarp gallery. Internally the officer's quarters, cookhouse and barracks, seven of twenty open gun positions, one Haxo casement, five expense magazines and two of previous six mortar batteries survive. Ceased military use in 1958 but was used as Heavy Goods Vehicle testing centre (partly in a modern building) until 2015. Vacancy is concerning and there are significant problems with dry rot and vegetation management.

Contact: Annie Evans 0117 975 0673



© Historic England

SITE NAME:	Amphitheatre in grounds of Saltram House, Merafield Road, Plympton
DESIGNATION:	Listed Building grade II*, RPG grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Charity (heritage)

1386231

Late C18 screen wall fronting rock-cut grottos overlooking the River Plym. Surrounding rock faces have become unstable and are subject to collapse. A condition survey of the structure has recently been undertaken, and the owners are in the process of updating their conservation management plan for the Saltram Estate. However, no physical repair works have yet been undertaken.

Contact: Annie Evans 0117 975 0673

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

LIST ENTRY NUMBER:

- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



© Historic England

SITE NAME:	Boringdon Arch, Plymbridge Road, Plymouth
DESIGNATION:	Listed Building grade II* and Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	N/A

PRIORITY CATEGORY: C (C) OWNER TYPE: Private, multiple owners

LIST ENTRY NUMBER: 1386330 and 1020565

Designed by Robert Adam and built in 1783, built as a triumphal arch and eye-catcher to be viewed from Saltram House. Now within a golf course. It was advertised for sale in 2014 but was not sold, and remains in a state of slow decay. There is scope for limited reuse of the former lodges (now roofless ruins) behind the arch flank walls to be reused for beneficial purposes, but access remains a

Contact: Simon Hickman 0117 975 0717



© Plymouth City Council

SITE NAME:	Efford Fort and Emplacement, Military Road, Efford
DESIGNATION:	Scheduled Monument
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Mixed, multiple owners

LIST ENTRY NUMBER: 1021135

Palmerston Fort built between 1863 and 1869. Partially occupied, as the parade ground is used for seasonal accommodation whilst buildings are vacant or used for storage. Buildings are suffering from benign neglect with heavy vegetation growth on the ramparts which may lead to water penetration and structural problems. No solution agreed as of 2019.

Contact: Annie Evans 0117 975 0673



© Historic England

SITE NAME:	Melville Building, Royal William Yard, Plymouth
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Local authority

1378531

The Melville building was constructed c1826-1832 as stores and offices for the Victualling Board to the design of Sir John Rennie Jnr, and forms part of the impressive Royal William Yard. Planning permission in place for the repair of Melville and conversion of most of the building for mixed use development. First phase of repair and conversion works to approximately a third of the building, including the north range, was completed in early 2020, with Historic England grant-aiding the repair of the roofs and external walls. A second phase encompassing the west range is following on.

Contact: Sarah Ball 0117 975 0666



© Historic England

SITE NAME:	Oddfellows Hall, Ker Street, Devonport
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

LIST ENTRY NUMBER: 1322006 Hall built 1823 by John Foulston, in the Egyptian style. Part of a group with the Guildhall and Devonport Column. Egyptian columns flank a central, recessed porch. Currently used as a social club and in poor repair. Historic England grant-aided a feasibility study and emergency repairs to the roof, completed in 2007. The building has been acquired by new owners. Historic England has met with the new owners and is in discussions over the future repair of the building.

Contact: Annie Evans 0117 975 0673



© Historic England

SITE NAME:	Old Cooperage, Royal William Yard, Plymouth
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

1378536

The Cooperage was built c1826-1832 for the Victualling Board, and forms part of the Royal William Yard. Part of the Cooperage has been successfully converted into artists' studios; Historic England grant-aided the stone conservation works. A sustainable future for the rest of the Cooperage is being explored by the leaseholder and Historic England have grant-aided urgent repairs to the rest of undeveloped sections of the building. Historic England is in a continuing dialogue with the leaseholder.

Contact: Sarah Ball 0117 975 0666

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

OWNER TYPE:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

CONDITION:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:



© Historic England

	` '
SITE NAME:	South Saw Mills, South Yard, HM Naval Base, Plymouth
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)

1388413

Government or agency

Sawmill built between 1856 and 1859. The saw mills ceased to be used as such in 1987, but the ground floor remained in light industrial and storage use until 1997. An options report was issued in 2010, but the building remains vacant with no identifiable use. The roof was provided with a large net in 2017 to prevent dislodged roofing materials becoming flying projectiles.

Contact: Simon Hickman 0117 975 0717

-

© Historic England

SITE NAME:	South Smithery, South Yard, HM Naval Base, Plymouth
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Government or agency

1392692

Dockyard smithery built 1771, modified C19 and reconstructed c1897. It remained in use until 1987 when structural faults were discovered. There is continued deterioration of the roof, masonry and interiors. An options report was issued in 2010, but a repair strategy has not yet been put in place. In 2017 a large net was installed on the roof to prevent dislodged roofing materials falling in high winds.

Contact: Simon Hickman 0117 975 0717



© Historic England

SITE NAME:	The coastal fortifications of Drake's Island, Plymouth
DESIGNATION:	Scheduled Monument, LB grade II
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Mixed, multiple owners

The island incorporates numerous defences/military monuments from 1549 to C20. It was held for Parliament during the Civil War and used for defence purposes until 1958. All buildings and structures are in a derelict condition. A planning application for conversion to hotel use was granted in 2017, works are yet to commence.

© Historic England

SITE NAME:	Woodland Fort, Crownhill Road, Crownhill
DESIGNATION:	Scheduled Monument
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority
LIST ENTRY NILIMBER:	1002615

1010910

Palmerston Fort, built between 1863 and 1869. Part of barrack block is in use as a social club, but the rest is empty. Remedial repairs have been undertaken and some of the heavy vegetation has recently been cleared. Site is prone to vandalism and rubbish dumping. Historic England grant-aided repair works in 2016-17 which has cleared part of the ditch and helped to drain the caponier, but considerable further work is still required.

Contact: Helen Woodhouse 0117 975 0676

LIST ENTRY NUMBER:	1002615
SITE NAME:	Church of St Mary and All Saints, Church Road, Plymouth
DESIGNATION:	Listed Place of Worship grade II*

Religious organisation

Poor

D (D)

1330541

Roof coverings are desperately in need of renewal, particularly the nave and inner slopes of north and south aisle. Slates to these areas have previously been covered with bitumen-coated hessian and will not be reusable for repairs. Valley gutter also needs renewing. Interior suffers from condensation and poor ventilation. Gullies need clearing out. Downpipe to tower leaking or blocked. Some ivy growth to masonry. Buttresses need repointing. Excessive tree growth near north wall. A bid to the last

© Historic England

round of Listed Places of Worship Roof Repair Grants in

2016 was unsuccessful.

Contact: Annie Evans 0117 975 0673

Contact: Annie Evans 0117 975 0673

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

HERITAGE AT RISK 2020 / SOU	JTH WEST / PLYMOUTH, CITY OF (UA)		
SITE NAME:	Austin Fort and section of military road		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021380
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Annie Evans 0117 975 0673
SITE NAME:	Efford Fort and Efford Emplacement, Military Road, Efford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021135
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Charity (non-heritage)	CONTACT:	Annie Evans 0117 975 0673
SITE NAME:	Fort Stamford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002544
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Plympton Castle		
DESIGNATION:	Scheduled Monument, LB grade II*, CA	LIST ENTRY NUMBER:	1003865
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Laira Battery		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021134
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Laira Emplacement, immediately south west of Lair	a Battery	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020686
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Plympton Priory		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017594
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Lee Moor Tramway Bridge		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002637
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Stonehouse Manor wall		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1003850
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	The coastal fortifications of Drake's Island		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1010910
DESIGNATION: CONDITION:		LIST ENTRY NUMBER:	1010910 Declining
	Scheduled Monument, LB grade II Generally satisfactory but with significant localised		
CONDITION:	Scheduled Monument, LB grade II Generally satisfactory but with significant localised problems	TREND:	Declining
CONDITION: PRINCIPAL VULNERABILITY:	Scheduled Monument, LB grade II Generally satisfactory but with significant localised problems Development requiring planning permission	TREND: NEW ENTRY?:	Declining No
CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument, LB grade II Generally satisfactory but with significant localised problems Development requiring planning permission Mixed, multiple owners	TREND: NEW ENTRY?:	Declining No
CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument, LB grade II Generally satisfactory but with significant localised problems Development requiring planning permission Mixed, multiple owners Woodland Fort	TREND: NEW ENTRY?: CONTACT:	Declining No Helen Woodhouse 0117 975 0676
CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument, LB grade II Generally satisfactory but with significant localised problems Development requiring planning permission Mixed, multiple owners Woodland Fort Scheduled Monument Generally unsatisfactory with major localised	TREND: NEW ENTRY?: CONTACT: LIST ENTRY NUMBER:	Declining No Helen Woodhouse 0117 975 0676 1002615

SOMERSET

EXMOOR (NP)



© T. Thurlow HBO with kind permission of Exmoor National Park Authority

SITE NAME:	Dovecote at Little Blackford, Selworthy, Somerset West and Taunton	
DESIGNATION:	Scheduled Monument, LB grade II*	
CONDITION:	Poor	
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Charity (heritage)	

This dovecote which survives well requires some repointing, limewashing and repairs to the roof covering in order to secure it in good condition.



SITE NAME:	Packhorse Bridge about 50 metres west of Lyncombe, Winsford, Somerset West and Taunton		
DESIGNATION:	Listed Building grade II*		
CONDITION:	Poor		
OCCUPANCY:	N/A		
PRIORITY CATEGORY:	C (A)		

1020774

LIST ENTRY NUMBER:

Packhorse Bridge. C17-C18, possibly earlier. Lias. Dry stone flat bedded rubble; single span, pointed arch; rubble voussoirs; curved abutments; parapet of undressed stone set on end, ramped up to centre. Hump-backed bridge with remains of pebble pathway. A recent condition survey has identified loss or covering of cobble pathway, partial loss of parapet, cracking above the arch and extensive plant growth including ivy and large saplings rooting into fabric. Historic England has met the owners to discuss repairs.

© T. Thurlow HBO with kind permission of Exmoor National Park Authority

OWNER TYPE: Private LIST ENTRY NUMBER: 1174159 Contact: Annie Evans 0117 975 0673

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise,

New Entry is noted).

Contact: John Ette 0117 975 0687

LPA ΝP RPG

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site

HERITAGE AT RISK 2020 / SOL	JTH WEST / EXMOOR (NP)		
SITE NAME:	Barlinch Priory, Brompton Regis, Somerset West a	and Taunton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006213
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bury Castle, Brompton Regis, Somerset West and	Taunton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006170
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bat's Castle: a small multivallate hillfort and associa	ited outwork, Carh	ampton, Somerset West and Tauntor
DESIGNATION:	Scheduled Monument, RPG grade II*	LIST ENTRY NUMBER:	1007667
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Later prehistoric defended enclosure, Long Wood	, Carhampton, Som	nerset West and Taunton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008255
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Mounsey Castle, Dulverton, Somerset West and Taunton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021357
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Black Ball Camp: a later prehistoric defended settlement on Gallox Hill, Dunster, Somerset West and Taunton		
designation:	Scheduled Monument, RPG grade II*	LIST ENTRY NUMBER:	1007668
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	St Leonard's Well, Dunster, Somerset West and T	aunton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021154
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Charlotte Russell 01271 831505

Immediate risk of further rapid deterioration or loss of fabric; no

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area Listed Building LPA Local Planning Author NP National Park RPG Registered Park and G SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Almsworthy Common: a stone alignment 560 metr West and Taunton	res south west of C	Chetsford Bridge, Exford, Somerset
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015017
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Chains Valley stone alignment 400 metres north west of Exe Head, Exmoor, Somerset West and Taunton		
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1014278
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth - General	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Cow Castle, Exmoor, Somerset West and Tauntor	1	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002955
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Kittuck stone setting and cairn, 200 metres south west of Three Combes Foot, Exmoor, Somerset West and Taunton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014284
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Sweetworthy deserted medieval settlement, Luccombe, Somerset West and Taunton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008469
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Berry Castle, Iron Age enclosure in Berry Castle Wood, Porlock / Luccombe, Somerset West and Taunton		
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1006204
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Allerford packhorse bridge, immediately north of C	Cross Lane Farm, Se	elworthy, Somerset West and Taunto
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1020776
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS CA Conservation Area Listed Building LPA Local Planning Author NP National Park RPG Registered Park and G SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	THE TEST / EXTOOR (NI) / TIENE			
SITE NAME:	Earthwork enclosure on Rodhuish Common, 300 and Taunton	metres west of Moo	or Barn, Withycombe, Somerset West	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021122	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Charlotte Russell 01271 831505	
SITE NAME:	Brewer's Castle, Withypool and Hawkridge, Som	Brewer's Castle, Withypool and Hawkridge, Somerset West and Taunton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021358	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505	
SITE NAME:	Brightworthy Barrows on Withypool Common, Withypool and Hawkridge, Somerset West and Taunton			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021264	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505	
SITE NAME:	Stone circle on Withypool Hill 670 metres ESE o West and Taunton	f Portford Bridge, W	ithypool and Hawkridge, Somerset	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021261	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving	
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505	

MENDIP



© Historic England

SITE NAME:	Kilmersdon Lodges, Kilmersdon
DESIGNATION:	Listed Building grade II*, RPG grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Private

LIST ENTRY NUMBER: | 3074||

Pair of lodges, gate piers and gates, associated with Ammerdown House, built from 1788 to 1794, situated on the edge of late C18 to early C19 park. The lodges were ruinous when listed in the 1960s and their potential for reuse is limited by their size. A feasibility study has been undertaken but the scale of the project indicated was prohibitive. A schedule of work has been undertaken to stabilise the surviving fabric; however, the building has no roof and remains vulnerable (2020).

Contact: Rhiannon Rhys 0117 975 0685



© Historic England

SITE NAME:	Former Anglo-Bavarian Brewery, Commercial Road, Shepton Mallet
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1296561

Brewery, now warehouses, built in 1864. Whilst partly occupied at ground floor level, most of the building has been vacant for many years. A feasibility study has been undertaken which has identified a substantial conservation deficit. A partial collapse has now been repaired. No further work has been undertaken as of 2020.

Contact: Rhiannon Rhys 0117 975 0685

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise,

New Entry is noted).

tegory is L herwise, L P

OWNER TYPE:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© Mendip District Council

SITE NAME:	Outbuilding about 30 metres west of Higher Southtown Farm, Southtown Lane, West Pennard
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C(C)

Private

1175928

Early C17 timber-framed brewhouse later utilised as a cottage, now part calf shed/hay store. In poor condition due to lack of maintenance and beneficial use for many years. Emergency clearance and stabilisation works to the building have been undertaken by Mendip District Council. The site passed into new ownership in Spring 2020 and we look forward to discussing its future with the new owners.

Contact: Sarah Ball 0117 975 0666

THE WAR AL

© Historic England

SITE NAME:	Gatehouse to west of Manor Farmhouse, Whatley
DESIGNATION:	Listed Building grade I
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1175158

Gatehouse, C15 built from random local limestone rubble with a plain tile roof. Two storeys, all window openings blocked apart from left side of ground floor. The arched entry is slightly left of centre and there is a Tudor arch doorway within the passage. Rear has stone steps to first floor doorway on the left side. The building is showing signs of structural movement to the south gable and significant deflection to the roof. Some areas of stone work are very weak, particularly around the small door under the arch. The vegetation to the east side needs to be removed.

Contact: Sarah Ball 0117 975 0666



© Historic England

SITE NAME:	Fenny Castle Cross: a medieval wayside cross 20 metres north west of Castle Farm, Castle, Wookey
DESIGNATION:	Scheduled Monument
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private, multiple owners

A medieval stone cross thought to date back to the early C14. Despite the loss of its shaft, the rest of the structure survives in situ though in very bad condition. Several stones show signs of fracture, the joints are open and missing mortar and vegetation is slowly encroaching.

LIST ENTRY NUMBER: |0|5797 Co

Contact: Alessandra Perrone 0117 975 1345



© Historic England

SITE NAME:	Baptist Chapel, Frome Road, Beckington
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

Chapel dated 1786 now converted to community use as a pre-school as well as a place of worship. Random rubble, with plain corner pilasters, pilasters between each bay and a central pediment with balustraded parapet to each side. Roof aging and some slate slippage. Stone balustraded parapet needs repair work. Some broken panes of glass.

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1296104

Contact: Annie Evans 0117 975 0673



© Historic England

SITE NAME:	Church of the Holy Trinity, Binegar
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER	1058641

Parish church rebuilt in the C15 with the tower dating from 1858. The building is generally very well maintained but the slated roofs require complete recovering and new ceilings. The roofs are covered in asbestos cement slates with fibreboard ceilings below. The slates require annual attention to deal with leaks, which have significantly disfigured the ceilings. The floors also need work due to rotten joists.

Contact: Annie Evans 0117 975 0673

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 F. Under repair on in fair to good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).



© Historic England

© Historic England

SITE NAME:	Church of St John the Baptist, Church Lane, Chilcompton
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation

1345096

LIST ENTRY NUMBER:

Parish church dating from the CI5 much rebuilt in the CI9. The nave north parapet has been secured, and there was a significant problem in the eastward parts of the building which had severe frost damage to limestone copings and string courses and further problems with poor walling stone and pointing. A Listed Places of Worship Roof Repairs Grant awarded in 2015 enabled most work to be completed. Some very significant boundary wall repairs are still required.

Contact: Annie Evans 0117 975 0673

SITE NAME:	Church of All Saints, Pound Lane, Downhead
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1174065

Parish church with a perpendicular tower from the C14. Nave, chancel and south porch from the mid C18, the building also has some C19 restorations. The building is generally well maintained. However it is exposed and water penetration to the tower is now spreading and affecting the nave roof structure as well as the tower arch.

Contact: Annie Evans 0117 975 0673



SITE NAME: Church of St Mary, Evercreech DESIGNATION: Listed Place of Worship grade II* CONDITION: PRIORITY CATEGORY: A (New entry) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1222368

Anglican church. C12, C13, C15, rebuilt 1888, further work of 1925. Rubble, freestone dressings, Nave with west bellcote, south porch, chancel. Inner doorway late C12. Interior plastered on flagstone and tile floors; nave with tiebeam roof restored 1925, though part C17, Norman tub font. Suffered from heritage crime in 2019.

Contact: Annie Evans 0117 975 0673



© Historic England Archive

© Historic England

SITE NAME:	Christ Church, Christchurch Street West, Frome
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1057853

Built 1817-1818 as an aisled nave, with crenellated east tower. Eastern extension built 1904-1905, the south transept in 1899, and the north transept 1929. Perpendicular style, with traceried openwork parapets, pinnacles and gargoyles over buttresses. The rainwater goods are in poor condition. There is detrimental external secondary glazing and large number of tingles (temporary repairs) on chancel roof.

Contact: Annie Evans 0117 975 0673



© Historic England

SITE NAME:	Walk, Leigh-on-Mendip
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1058345

Medieval parish church dating from c1350, rebuilt c1500. Well maintained. Iron cramps are pushing apart the joints in the parapet but as yet not splitting the stones. A programme of repairs addressing the external walling and parapets as well as repairs to the C18 roof coverings is needed. The chancel roof was repaired with Listed Places of Worship Roof Repairs Grant and in 2017, the congregation received National Lottery Heritage Fund Grant for Places of Worship to address the Nave roof. Work is in development. The congregation is also developing proposals for repairs and reordering.

Contact: Annie Evans 0117 975 0673

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).



SITE NAME:	Church of St Mary, St Mary's Road, Meare
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1058750

Anglican parish church C14 of chancel, nave, north and south aisles, north vestry and west tower. Built of coursed lias stone with parapets partly missing. Chancel has queen post roof; wagon roofs elsewhere including good panelled roof to nave. Church suffered heritage crime in early 2020.

Contact: Annie Evans 0117 975 0673

© Historic England Archive



SITE NAME:	Church of St Andrew, Mells
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1295876

Parish church. Predominantly late C15, tower of mid C16, mid C19 restoration. Doulting ashlar; low pitched roofs. Clerestoried nave with north and south aisles, continuing as chapels clasping the chancel and polygonal vestry of 1485. Important fixtures, fittings and furnishings. The church is generally very well maintained but the roofing materials are coming to the end of their lives. The poor condition classification therefore relates to the roof only.

Contact: Annie Evans 0117 975 0673

© Historic England



SITE NAME:	Church of St Leonard, Stoke Street, Rodney Stoke
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1058592

Small Anglican parish church with C12 origins and later additions. Restored in 1879. Perpendicular style. The pierced parapet along the top of the nave is rapidly deteriorating.

Contact: Alessandra Perrone 0117 975 1345

© Historic England



SITE NAME:	Church of St Matthew, High Street, Wookey
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1295105

Parish church, dated predominantly from C15 but with C13 chancel. The building is well maintained, however the nave and aisle roofs are improperly fixed and thus split and leak annually letting water into the C15 roof structure.

Contact: Annie Evans 0117 975 0673

© Historic England

SITE NAME:	Small multivallate promontory fort on Blacker's Hill	, Chilcompton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015493
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
	Bowl barrow 300 metres north east of Whitnell Corner, Emborough		
SITE NAME:	Bowl barrow 300 metres north east of Whitnell Co	rner, Emborough	
SITE NAME: DESIGNATION:	Bowl barrow 300 metres north east of Whitnell Co Scheduled Monument	erner, Emborough	1011670
		,	1011670 Declining
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

HERITAGE AT RISK 2020 / SOL	JTH WEST / MENDIP		
SITE NAME:	Drying house at The Coach House, Willow Vale, F	rome	
DESIGNATION:	Scheduled Monument, LB grade II, CA	LIST ENTRY NUMBER:	1016955
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Glastonbury lake village, Godney		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006156
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Alessandra Perrone 0117 975 1345
ITE NAME:	Lake villages north west of Oxenpill, Meare		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006160
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Section of the Abbot's Way trackway, 500 metres WSW of Honeygar Farm, Meare		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014432
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Sections of the Sweet Track and Post Track, 240 m	netres south west o	of Sunnyside Farm, Meare
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014440
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Sections of the Sweet Track and Post Track, 250 m	netres ESE of Statio	on House, Meare
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014831
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Timber trackway site, 700 metres west of Honeygo	ar Farm, Meare	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014434
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Fussell's Lower Works: an iron edge tool works, 2	10 metres south ea	ast of Wadbury, Mells
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1019796
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Melanie Barge 0117 975 1300

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area Listed Building LPA Local Planning Author NP National Park RPG Registered Park and G SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

IERITAGE AT RISK 2020 / SOU	THE VEST / HEIVEN		
SITE NAME:	Whatley Combe Roman villa, Nunney		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006188
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345
Bowl barrow 250 metres north east of King Down Farm, Priddy			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011530
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Bowl barrow 300 metres south west of Moor View	v, Priddy	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009773
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Bowl barrow 800 metres south of Townsend Farm	, Priddy	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009740
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Romano-British settlement on Stoke Moor, Rodne	y Stoke / Cheddar	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011125
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Group of round barrows 750 metres north west of Ivy Cottage, St. Cuthbert Out		
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1020494
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Marston Moat, Trudoxhill		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016302
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Alessandra Perrone 0117 975 1345

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area Listed Building LPA Local Planning Author NP National Park RPG Registered Park and G SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SEDGEMOOR



© Historic England

© Historic England

SITE NAME:	Castle House, Queen Street, Bridgwater
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Charity (heritage)

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

Contact: Annie Evans 0117 975 0673

long term future for the building.

	SITE NAME:	Church of StMary, Spaxton
	DESIGNATION:	Listed Building grade I
	CONDITION:	Poor
	OCCUPANCY:	Vacant/not in use
	PRIORITY CATEGORY:	C (New entry)
	OWNER TYPE:	Private
	LIST ENTRY NUMBER:	1178212

1355168

Anglican parish church; now deconsecrated. C11, C13, C15; tower probably of 1867; restored 1887. Rubble, coped verges, slate roofs. Chancel, nave, south porch and transeptal south chapel, vestry and organ chamber, west tower. Nave has late Norman south doorway, interior plastered; C15 moulded plaster ceiling; Norman responds to C13 chancel arch. Vegetation growth, roofs and rainwater goods in poor condition.

House in the centre of Bridgwater in the early Tudor Revival style, built for William Ackerman in 1851. It is notable for the earliest surviving use of prefabricated cast concrete and constructional post tensioning. The building has been in a structurally precarious condition and has had an arson attack. Owned by SAVE Building Preservation Trust. Historic England has grant aided phases of repair with a final phase taking place in 2018. However the building remains empty while SAVE pursues a sustainable

Contact: Annie Evans 0117 975 0673



© Historic England

SITE NAME:	Westonzoyland Pumping Station, Westonzoyland
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Charity (heritage)

1174295

A former pumping station, built in the early C19, now preserved by the Westonzoyland Engine Trust. The first pumping station to be built to lift floodwater from the Somerset Levels and Moors, and the only one to survive with the steam engine still working and with the buildings intact. Much work has been done but further repair is needed, and the Trust has been working up a scheme for reuse of underused areas. Parts are under possible threat from rapid alteration of surrounding drainage. Historic England is grant aiding the investigation of cracking to the building close to the riverbank.

Contact: Annie Evans 0117 975 0673



© Historic England

SITE NAME:	Church of All Saints, High Street, Ashcott	
DESIGNATION:	Listed Place of Worship grade II*	
CONDITION:	Poor	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1058957	

Parish church. Mainly C15 with alterations in the C19. The woodblock floor has lifted and is decayed in many places. This could be due to a leak from the buried C19 cast iron heating pipework. The vestry roof needs re-covering and significant masonry repairs to the tower and nave parapets will be needed in the near future.

Contact: Annie Evans 0117 975 0673



© Historic England

SITE NAME:	Baptist Church, St Mary Street, Bridgwater
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1298798

Baptist church, built in 1837 by Edwin Down. Rectangular plan with schoolrooms to the rear. Classical frontage with Bath stone pediment and cornice, flight of steps up to central Egyptian style doors. High level stonework is in poor condition. Rainwater goods are also poor. Rear of the building has vegetation growth and the brickwork needs repointing.

Contact: Annie Evans 0117 975 0673

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 F. Under repair or in fair to good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

SITE NAME:



	Lane, Chilton Polden
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1060126

Church of St Edward. Church

Parish church of C15 origin, largely rebuilt in 1889. Rubble, slate roofs with coped verges and bellcote at west end. Chancel and nave, north aisle, north transept, north and south porches and vestry. Neo-Perpendicular with some Perpendicular features remaining. There is cracking to the vestry wall and the roof covering is failing. The church was awarded a Listed Places of Worship Roof Repairs Grant in 2016 but more repairs are required.

Contact: Annie Evans 0117 975 0673

© Historic England



SITE NAME:	Church of St Edward King and Martyr, Goathurst
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NILIMBER:	1177353

Anglican parish church. Predominantly C14, with C15; C19 work, including restoration of 1884. Rubble, freestone dressings, slate roofs, chancel, nave with south porch and south chapel, west tower. Two bay narrow nave, with C15 wagon roof chancel with late C19 wagon roof; early C17 north chapel with C17 canopied tomb and monuments to Halswell family. The church has sufferd from heritage crime in early 2020, and monuments inside are vulnerable to further damage.

Contact: Annie Evans 0117 975 0673

© Historic England

© Historic England

© Historic England



SITE NAME:	Church of the Holy Cross, Church Road, Middlezoy
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1344695

Anglican parish church. C13, C14, C15, C16, restored C19. Coursed and squared lias, slate and lead roofs, coped verges, finials. Chancel, nave, south aisle and a south porch, north transept. Tall three-stage C15 tower with canopied niches and pinnacles to buttresses. Suffered from heritage crime in early 2020.

LIST ENTRY NUMBER: 1344695 Contact: Annie Evans 0117 975 0673

Church of St Michael and All

SITE NAME:	Church of St Mary, Fore Street, North Petherton		
DESIGNATION:	Listed Place of Worship grade I		
CONDITION:	Poor		
PRIORITY CATEGORY:	F (F)		
OWNER TYPE:	Religious organisation		
LIST ENTRY NUMBER:	1058924		

The church was mostly built in the late C14 and early C15 including the tower, in a Perpendicular style. Inside the tower at the height of the nave is a fine fan vault, unusual for a village church. The north aisle parapet and south aisle roof have been repaired with National Lottery Heritage Fund and Historic England Repair Grant for Places of Worship, completed in 2013. Further work to rainwater goods is now complete, funded by a Listed Places of Worship Roof Repairs Grant. Some unsafe stonework was removed by rope access masons in 2017, but the ornate tower is still in need of repair.

Contact: Annie Evans 0117 975 0673

A PARTIE

	Angels, Rye, Puriton
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1344664

SITE NAME:

Parish church. C14 to C15 chancel nave and north aisle and early C13 unbuttressed west tower with lancet window. South porch, north vestry. Coursed rubble, freestone dressings, mixed material roofs, interior has Perpendicular rood screen. Tower render failing and falling from the tower. Historic England gave advice following removal of the render in late 2016. Additional issues with the vestry wall and aisle roof remain.

Contact: Annie Evans 0117 975 0673

© Historic England

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 F. Under repair on in fair to good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).



SITE NAME:	Church of St Mary Magdalene, Stockland Bristol		
DESIGNATION:	Listed Place of Worship grade II		
CONDITION:	Poor		
PRIORITY CATEGORY:	C (C)		
OWNER TYPE:	Religious organisation		
LIST ENTRY NUMBER:	1059049		

Parish church built in 1865 of blue lias rubble stone. Designed by Arthur of Plymouth for the Daniel family of Stockland Manor. Roofs need re-covering and there are a number of slipped tiles. Structural stability is poor with cracking to window surrounds and major fracture through the tower, loose and bulging stonework. Some repairs to valley gutter and one window which was blown in, were carried out in 2017 and in 2019 the kneeler and copings to the vestry gable were reset. The parish is putting together proposals for repair but the church remains in a very poor state.

Contact: Annie Evans 0117 975 0673

© Historic England

SITE NAME:	Medieval estate boundary earthwork on Shute Shelve Hill, Axbridge / Winscombe and Sandford			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015495	
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Charity (heritage)	CONTACT:	Charlotte Russell 01271 831505	



© Historic England

SITE NAME:

Church of St Peter, Church Lane, West Huntspill

DESIGNATION:

Listed Place of Worship grade I

CONDITION:

Poor

PRIORITY CATEGORY:

C (C)

OWNER TYPE:

Religious organisation

LIST ENTRY NUMBER:

1060138

Large parish church, with chancel, nave, quire aisles and nave aisles, two-storeyed south porch and western tower. Largely C14, lias with Ham stone dressings. The church was gutted by fire in 1878 and restored in neo-Gothic style. The aisle roofs leak and are patched with sealant and flashband as they are too fragile for more reliable repairs. Lias stone has problems, notably the north parapet, north aisle vice turret and the tower which is now roped off for safety. The congregation is putting together a bid to the National Lottery Heritage Fund for the tower and interior improvements.

Contact: Annie Evans 0117 975 0673

SITE NAME:	Horsey medieval settlement immediately north of Board's Farm, Bridgwater Without		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020438
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505



SITE NAME:	Church of St Mary, Main Road, Westonzoyland
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Fair
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1174351

Parish church of C13, C14, C15, C16 and C19 with significant additions by WD Caroe 1933-1939. Notable for housing 500 defeated rebels following the Battle of Sedgemoor in 1685. The C15 timber roof structure is of considerable significance with carved angel corbels. The congregation undertook a large scheme of roof repair in 2016 with a Listed Places of Worship Roof Repairs Grant but there are concerns about the condition of the tower.

Contact: Annie Evans 0117 975 0673

(C)	Historic	Fng	land

SITE NAME:	Ruborough Camp large univallate hillfort, Broomfield		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007670
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 F. Under repair or in fair to good.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

HERITAGE AT RISK 2020 / SOL	JTH WEST / SEDGEMOOR		
SITE NAME:	Timber trackways 850 metres east of Catcott Burn	tle Farm, Burtle	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014433
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
ITE NAME:	Cynwit Castle, Cannington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006225
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
ITE NAME:	World War II anti-aircraft rocket battery and bom Ashridge Farm, Cheddar	bing decoy control	building 265 metres north east of
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020994
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
ITE NAME:	Platform cairn, 180 metres east of Wilmot's Pool,	Over Stowey	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1417363
CONDITION:	Optimal/generally satisfactory	TREND:	Stable
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - limited/localised	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bronze Age and Iron Age timber trackways, 700 m	netres north west o	f Coppice Gate Farm, Shapwick
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014431
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
ITE NAME:	Stowey Castle, the site of St Michael's Chapel and	a medieval kiln site	, Nether Stowey / Over Stowey
DESIGNATION:	Scheduled Monument, LB grade I, part in CA	LIST ENTRY NUMBER:	1019421
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Sections of the Sweet Track, the Post Track and as Farm, Shapwick	ssociated remains 5	00 metres north east of Moorgate
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014438
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area Listed Building LPA Local Planning Author NP National Park RPG Registered Park and G SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Bronze Age and Iron Age trackways 600 metres no		orth east of Northb	rook Farm, Shapwick / Ashcott
DESIGNATION:	Scheduled Monu	ument	LIST ENTRY NUMBER:	1014444
CONDITION:	Extensive signific	Extensive significant problems		Declining
PRINCIPAL VULNERABILITY:	Drainage/dewar	tering	NEW ENTRY?:	No
OWNER TYPE:	Private	•		Charlotte Russell 01271 831505
SITE NAME:	Round barrows	600 yards (550 metres) north wes	st of Longbottom Fa	rm, Shipham
DESIGNATION:	Scheduled Monu	ument	LIST ENTRY NUMBER:	1006223
CONDITION:	Generally satisfa problems	Generally satisfactory but with minor localised problems		Declining
PRINCIPAL VULNERABILITY:	Permitted devel	opment	NEW ENTRY?:	No
OWNER TYPE:	Private	Private		Charlotte Russell 01271 831505
SITE NAME:				
	Prehistoric timb	er trackways, 670 metres SSE of P	Parchey Bridge, Staw	ell
DESIGNATION:	Prehistoric timb Scheduled Monu	•	Parchey Bridge, Staw LIST ENTRY NUMBER:	rell 1014430
		•		
DESIGNATION:	Scheduled Monu	ument	LIST ENTRY NUMBER:	1014430
DESIGNATION: CONDITION:	Scheduled Monu Unknown	ument	LIST ENTRY NUMBER:	1014430 Unknown
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY:	Scheduled Monu Unknown Drainage/dewar	ument	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: An C18 landscap restored two imp	Unknown No Charlotte Russell 01271 831505 The park. Local preservation trusts have contant garden buildings but some other
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY:	Scheduled Monu Unknown Drainage/dewar Government or	tering agency Halswell Park, Goathurst /	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: An C18 landscap restored two important structures remains the design, Mill V however it change	Unknown No Charlotte Russell 01271 831505 The park. Local preservation trusts have cortant garden buildings but some other in in poor condition. The centrepiece of vood, was largely denuded of trees, ged hands in spring 2015 and was reunited.
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY:	Scheduled Monu Unknown Drainage/dewar Government or	tering agency Halswell Park, Goathurst / Broomfield Registered Park and Garden	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: An C18 landscap restored two important the design, Mill V however it change with the house.	Unknown No Charlotte Russell 01271 831505 The park. Local preservation trusts have cortant garden buildings but some other in in poor condition. The centrepiece of vood, was largely denuded of trees, and hands in spring 2015 and was reunited this has led to a major programme of
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY:	Scheduled Monu Unknown Drainage/dewar Government or SITE NAME: DESIGNATION:	tering agency Halswell Park, Goathurst / Broomfield Registered Park and Garden grade II, 17 LBs	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: An C18 landscap restored two important structures remain the design, Mill V however it change with the house. The replanting and restone bridge. Design of the contact o	Unknown No Charlotte Russell 01271 831505 The park. Local preservation trusts have cortant garden buildings but some other in poor condition. The centrepiece of Vood, was largely denuded of trees, and the spring 2015 and was reunited this has led to a major programme of pairs to structures including the listed Bat spite this, the majority of the park remain
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY:	Scheduled Monu Unknown Drainage/dewar Government or SITE NAME: DESIGNATION: CONDITION:	tering agency Halswell Park, Goathurst / Broomfield Registered Park and Garden grade II, 17 LBs Extensive significant problems	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: An C18 landscap restored two important structures remain the design, Mill V however it change with the house. The replanting and restored the second structures remains the design, Mill V however it change with the house. The second structure is the second structure of t	Unknown No Charlotte Russell 01271 831505 The park. Local preservation trusts have cortant garden buildings but some other in poor condition. The centrepiece of Vood, was largely denuded of trees, and the second in specific and was reunited this has led to a major programme of pairs to structures including the listed Bat spite this, the majority of the park remain.

SOMERSET WEST AND TAUNTON



© Historic England

SITE NAME: Sandhill Park, Bishop's Lydeard DESIGNATION: Listed Building grade II* CONDITION: Very bad OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: B (D) OWNER TYPE: Private LIST ENTRY NUMBER: 1295317

1001145

Country house c1720. A fire in 2011 caused serious damage to the roof structure and top floor. In 2013 planning permission was granted for an enabling development scheme which has now been completed, although works to the house did not commence. A second phase of works for the conversion of the ancillary buildings and a new roof to the main house are in progress. Preapplication discussions continue in respect of the principal building as of 2020.

Contact: Rhiannon Rhys 0117 975 0685

Contact: Jo McAllister 0117 975 0696

OWNER TYPE:

LIST ENTRY NUMBER:

Mixed, multiple owners

A mid C16 gatehouse which is part of a much larger estate. Consent has been granted for use as holiday let with associated repairs. As of 2020, no works have been undertaken to the property to implement the scheme.

© Historic England

© Historic England

Gatehouse at Cothelstone SITE NAME: Manor, Cothelstone Listed Building grade I, RPG DESIGNATION: grade II, CA CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: D (D) OWNER TYPE: Private LIST ENTRY NUMBER: 1059192

Contact: Rhiannon Rhys 0117 975 0685

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Remains of Chantry at Kilve, Sea Lane, Kilve
DESIGNATION:	Scheduled Monument and Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Private

1002960 and 1345688

Early C14, with later medieval additions, formerly believed to be remains of collegiate dwelling of chantry priests. A Historic England survey has shown that the ruins are part of an important manorial complex. Historic England funded emergency repairs in 2010 and 2011, a conservation plan and further works in 2013 and 2014. Further jointly funded consolidation works were undertaken in 2015. Structural movement in one gable, which is propped, remains to be addressed and a major phase of work is underway in 2020.

Contact: Annie Evans 0117 975 0673

76	
4	A
**	

SITE NAME:

Cloth finishing works at Tone Mills, North Range, Wellington

DESIGNATION:

Listed Building grade II*

CONDITION:

Very bad

OCCUPANCY:

N/A

PRIORITY CATEGORY:

B (B)

OWNER TYPE:

Private

1271246

A near complete example of a C19 cloth dyeing and finishing works which developed between c1830 and c1920. Somerset West and Taunton Council and Historic England are actively engaged in trying to find a solution to conserve the buildings. The site has asbestos contamination and has suffered from vandalism on multiple occasions during the last five years.

Contact: Annie Evans 0117 975 0673



© Historic England

© Historic England

SITE NAME:	Tonedale Mills (east complex), Milverton Road, Wellington
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Commercial company, multiple owners

1176514

Eastern complex of an integrated multi-component wool textile factory, Split ownership with the eastern part in beneficial use, but western parts disused and in very poor condition. Enforcement Action was undertaken in 2018 to secure Tonedale House following unauthorised works. Some further work has been undertaken in 2019-20 but this has left buildings in worse condition. Discussions between owners, local authority and Historic England, concerning the future and conservation of the site, are ongoing.

Contact: Annie Evans 0117 975 0673



© Historic England

SITE NAME:	Tonedale Mills (west complex), Wellington
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (B)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1051987

Western complex of an integrated multi-component wool textile factory, now largely disused. Consent was granted for mixed use redevelopment of the complex. Works halted on site in 2008 and previous owners went into receivership leaving some buildings in a very vulnerable condition. The site has had some work carried out but buildings are deteriorating rapidly. A section 215 notice has been served and as of early 2020 only partially complied with. Discussions between the local authority, Historic England and the owner concerning the future of the site and its conservation are ongoing.

Contact: Annie Evans 0117 975 0673



© Historic England

SITE NAME:	Wellington Monument, Wellington Without
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1060281

175 feet high triangular tower commemorating the Duke of Wellington's victory at the Battle of Waterloo. Construction began in 1817; money ran out and a cheaper revised design was then followed, completed in 1854. The stonework has extensive cracking, with successive repair campaigns over generations. The National Trust has owned it since 1934, but closed the monument to the public in 2007 due to safety concerns. After extensive investigatory work, and significant fundraising, repairs are now underway, and work is due to be completed in 2021.

Contact: Annie Evans 0117 975 0673

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 Under repair or in fair to good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

LIST ENTRY NUMBER

LIST ENTRY NUMBER:



© Historic England

© Historic England

SITE NAME:	Church of St John, Park Street, Taunton
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1059951

potentially fragile.

Contact: Annie Evans 0117 975 0673

SITE NAME:	Church of St Giles, Bradford- on-Tone
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1060376

Anglican parish church. Circa 1300, refenestrated C15, tower early C16, C19 alterations. Random rubble chert and sandstone, Ham stone dressings, slate roofs. chancel, three-bay aisled nave, north and south chapels, north-east vestry, crenellated three-stage west tower. Fine early C18 pulpit C14 effigy, good monuments and stained glass. The church suffered heritage crime in early 2020.

Built 1858-1863, by George Gilbert Scott. Chancel, nave, north and south aisles; north chapel; south porch and choir vestries at the north-east. Prominent tower and spire with polychrome banded decoration, and figures of the apostles in tabernacles masking the broaches. Alterations have been made to the west end to make the church accessible to a wider range of people. However, the roofs are aging and in need of work, and the elaborate high level stonework is

ER: 1060376 Contact: Annie Evans 0117 975 0673



© Historic England

SITE NAME:	Church of St Andrew and St Mary, Pitminster
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation

1344587

Anglican church largely C13. Chancel nave with clerestorey, north and south aisles, Lady Chapel on north of chancel and organ chamber on south, north and south porches, western tower with spire and vestries. Upper part of the tower is octagonal C14 north and south chapels slightly broader than the aisles, almost as transepts. The church suffered heritage crime in early 2020.

Contact: Annie Evans 0117 975 0673



© Historic England

SITE NAME:	Church of St John the Baptist, High Street, Wellington
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation

1176369

Anglican parish church: mostly C15; short chancel (C13) with tracery to east window and very tall nave. South door and porch also C13 or early C14. Interior has a ceiled wagon roof and two late C18 west galleries in aisles. Tall west tower of red sandstone with pinnacles, and stair turret central on south. Fine Popham tomb, 1607. The church suffered heritage crime in early 2020 which has left church with extensive damage to the fabric and to the organ.

Contact: Annie Evans 0117 975 0673

SITE NAME:	The Castles, Bathealton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019150
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow and folly ruins on Cothelstone Hill, I	kilometre north ea	st of St Agnes' Well, Cothelstone
SITE NAME: DESIGNATION:	Bowl barrow and folly ruins on Cothelstone Hill, I Scheduled Monument	kilometre north ea	ist of St Agnes' Well, Cothelstone
	•		
DESIGNATION:	Scheduled Monument Generally satisfactory but with significant localised	LIST ENTRY NUMBER:	1015086

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 F. Under repair or in fair to good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

SITE NAME:	Bowl barrow on Cothelstone Hill, 1,070 metres no	orth east of St Agne	es' Well, Cothelstone
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015087
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Barrow and cairn cemetery on Black Hill, 490 metr	es north west of C	Crowcombe Park Gate, Holford
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019381
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Dowsborough hillfort and associated round barrov	v, Holford	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010494
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Entrenchment on Heydon Hill, Huish Champflower	r	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006173
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Four medieval fish weirs 500 metres east of the Ha	rbour, Minehead	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020017
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Duck decoy 250 metres north west of Moredon House, North Curry		,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014441
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Norton Camp large univallate hillfort, Norton Fitzy	warren	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008467
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS CA Conservation Area Listed Building LPA Local Planning Author NP National Park RPG Registered Park and G SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Two bowl barrows 210 metres and 600 metres no	orth west of Brown	Down Cottage, Otterford
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016414
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Poundisford Park Pale, Pitminster / Trull		
DESIGNATION:	Scheduled Monument, part in RPG grade II	LIST ENTRY NUMBER:	1002957
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Curdon Wood Camp, Stogumber		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006158
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Stringston churchyard cross, Stringston		
DESIGNATION:	Scheduled Monument, 2 LBs	LIST ENTRY NUMBER:	1006171
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Religious organisation	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Cairn 280 metres south of Triscombe Stone, West	t Bagborough	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016707
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Round barrow cemetery at Battle Gore immediate	ly west of North R	oad, Williton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019032
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Camp south of Manor Farm, Wiveliscombe		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006167
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Charlotte Russell 01271 831505

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet
- implemented.

 C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area Listed Building LPA Local Planning Author NP National Park RPG Registered Park and G SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	St Audries (House), West Quantoxhead / Williton
DESIGNATION:	Registered Park and Garden grade II, 16 LBs
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	Medium
TREND:	Stable
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1001155

C19 gardens and pleasure grounds, surrounding a C19 mansion, together with parkland developed from the mid-C18 and improved in the mid-C19. St Audries has had a succession of institutional uses; derelict former school buildings remain in the walled garden. The parkland is mostly under cultivation and few parkland trees survive. St Audries house and gardens are in use as a wedding venue.

Contact: Jo McAllister 0117 975 0696

SITE NAME:	Wellington		
DESIGNATION:	Conservation Area, 90 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Low	CONTACT:	Nigel Pratt (LPA) 01823 356492

SOUTH SOMERSET



SITE NAME:

Top mill building, Higher Flax Mills, Torbay Road, Castle Cary

DESIGNATION:

Listed Building grade II*, CA

CONDITION:

Poor

OCCUPANCY:

Part occupied/part in use

PRIORITY CATEGORY:

F (F)

OWNER TYPE:

Private

This mid C19 former mill has been sold and an application approved for conversion to one live/work unit in 2011. Works are underway and making slow but good progress. The southern roof is now complete. The building is mostly occupied. Work is still ongoing as of 2020.

© South Somerset District Council

LIST ENTRY NUMBER: 1056226

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

Contact: Rhiannon Rhys 0117 975 0685

Contact: Annie Evans 0117 975 0673



© Historic England

SITE NAME:	Chard School, Fore Street, Chard Town
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Educational (independent)

1205594

The building dates to 1583. It became Chard Grammar School in 1671 and has been a school ever since. It has an L-Plan layout with five bays, a rear wing and two storeys with attics. The building was an advanced plan form for its date, notable for passage access to the main rooms. Features include squared chert Hamstone dressings, window hoods and mullions, plain tile roof and brick stacks. The rainwater goods are inadequate, areas of water ingress and structural issues where trusses have been altered.



© Historic England

SITE NAME:	Waterloo House and Manor Court House, 7A, 7B, 9, 11, 13 and 13A, Fore Street, Chard Town
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Mixed, multiple owners

1197449

Late C16/early C17 group of shops, offices, houses and flats with two prominent projecting two and three storey porches. A 2010 planning appeal refused a proposed subdivision to create smaller units. In 2014 the Local Authority commissioned a feasibility study with Historic England grant-aid. Work to repair the three-storey porch to 7A was completed in 2018 with Historic England grant-aid. Discussions with the multiple owners over options for the building are continuing.

Contact: Annie Evans 0117 975 0673

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).



© Historic England

SITE NAME:	Gatehouse to Cathanger, Cathanger Lane, Fivehead
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1249561

Late C16 gatehouse to Cathanger Manor, with central throughway and first floor over. Banded lias and Ham stone, thatched roof, wood coving to eaves. Principal trusses have spread and wall plates have moved outwards. Crude props inserted to support the collars are causing significant deflection to first floor and damage to partition and door jamb. Decay to main beam and joists on south. Thatch thin with water ingress. Cracking and erosion to east wall with general decay of lias stone. Historic England staff have visited and provided advice for repair by the

Contact: Annie Evans 0117 975 0673



© Historic England

SITE NAME:	Madey Mill, East Street, Martock
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1226550

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

Water mill with medieval origins, although current buildings are largely C17. The building is situated on a working farm, is under-used and is suffering from lack of maintenance. Viable new uses and/or funding opportunities need to be investigated to obtain adequate funding for repairs. A Historic England funded condition survey has been completed, identifying urgent repairs but as of 2019 the condition remains poor. Historic England hopes to work further with the owners regarding repair and reuse.

Contact: Chris Miners 0117 975 1355



© Historic England

SITE NAME:	Secular college at Parsonage Farm, Stoke Sub Hamdon
DESIGNATION:	Scheduled Monument and Listed Buildings - I grade I; 6 grade II, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Charity (heritage)

1020665 and 1260178;

1242240; 1260179; 1242150; 1260105; 1260180; 1242246

Attached to this chantry college is a group of medieval and C16 farm buildings, some of which are in poor condition and unroofed. However others, such as the threshing barn, are capable of beneficial use. Owned by the National Trust, Historic England has had a number of meetings on site and funded an options appraisal to consider ways of bringing the buildings back into use. As of 2020, Historic England and the National Trust are jointly funding the first phase of repair work to the Dovecote. The National Trust is considering ways to improve the use of the site.

Contact: Annie Evans 0117 975 0673



© Historic England

SITE NAME:	The east Rope Walk, at Job Gould's West of England Twine Works, East Street, West Coker
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (B)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1057116

Early C19 Rope walk. Extremely long (97 metres) building of three-storeys, partly open at ground floor level, oak trusses with weatherboarding and windows along the east and west; later brick southern end; undulating double roman clay tile roof, five ropewalks on two levels, some original machinery. The building is fragile, roof has been patched but battens have slipped in numerous places allowing in water; trusses fractured and structure under stress. Historic England grant-aided works to support the structure in 2016 and as of 2020 the building is being gradually repaired by a new owner.

Contact: Annie Evans 0117 975 0673



© Historic England

SITE NAME:	White Horse Hotel, 4, High Street, Wincanton
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1274102

Inn dated 1733 built by Nathaniel Ireson in free baroque style. Local stone cut and squared with painted ashlar dressings; plain clay tile roof behind parapet, simple gables; brick end chimney stacks. Three-storey and three bays to road. Early cross-wing, also second cross-wing with columns that may relate to use as an inn. Early C20 dance hall at the rear. Building in poor condition with façade parting from roof, and floors decayed. The site placed back on the market in 2019 and pre-application discussions were held towards the end of 2019.

Contact: Rhiannon Rhys 0117 975 0685

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS	
CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garde
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

© Historic England

SITE NAME:	Church of St Andrew, Aller
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1227327

Small church of Saxon origin with C12/C13 and C15 additions and major restoration 1861 to 1862 by H John Norton. Tower stonework was repaired under the joint National Lottery Heritage Fund and Historic England Repair Grant for Places for Worship scheme in 2013. The church was offered a Listed Places of Worship Roof Repairs Grant and in 2017-18 the nave and south porch roofs were recovered, and ceilings repaired. The chancel, north aisle and north porch roofs remain in poor condition.

Contact: Annie Evans 0117 975 0673

Andrew Control	
4	

SITE NAME: Church of the Holy Trinity, Main Street, Ash DESIGNATION: Listed Place of Worship grade II CONDITION: Poor PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1057286

Parish church built in 1841 by Sampson Kempthorne, chancel added 1887, and tower added 1919. Ham stone cut and squared with ashlar dressings and a Welsh slate roof between coped gables. The coping stones have become dangerous and the tower masonry is in poor condition.

Contact: Annie Evans 0117 975 0673



© Historic England

Church of St Mary the Virgin, Barrington
Listed Place of Worship grade I, 2 CAs
Fair
A (New entry)
Religious organisation

1056904

Anglican parish church, mainly C13, with central octagonal tower, north and south transepts, south aisle, ornate north porch. Church suffered from heritage crime in early 2020.



SITE NAME:	Church of St Mary Magdalene, Church Lane, Barwick
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1057217

Parish church C13 and later. Ham stone roughly squared and coursed, with ashlar dressings; plain clay tiles between coped gables to chancel south aisle and nave, stone slates to south porch. Chancel is an 1885 rebuild incorporating earlier fragments. The tower roof is in poor condition, the bell frame needs work and the nave and aisle roofs are also in poor condition. The church has been awarded a National Lottery Heritage Fund Grant for Places of Worship and répairs started in 2019.

Contact: Annie Evans 0117 975 0673

Contact: Annie Evans 0117 975 0673



© Historic England

© Historic England

SITE NAME:	Church of St Nicholas, Bratton Seymour
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Very bad
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1177220

Parish church with C13 origins. Two-cell plan, of two-bay chancel and three-bay nave, with west tower and south porch, and small north-east vestry. High level stonework needs repairing urgently. Interior poor with ceilings at risk of falling and some plaster already having fallen.

Contact: Annie Evans 0117 975 0673

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



SITE NAME:	Church of St John the Baptist, Charcroft Hill, Brewham
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1056463

Parish church reputed to date from the C13 with much C19 rebuilding. The tower is inhabited by birds making inspection difficult. The church has been subject to heritage crime previously and the roofs are generally in need of repair. The rainwater goods are in poor condition.

© Historic England



SITE NAME:	Church of St Mary, West Charlton, Charlton Mackrell
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1056728

Parish church. C13 origins, but restored in 1792-1794 and in 1847. Local lias stone cut and squared, with Ham stone ashlar dressings. Stone slate roof between coped gables. Signs in the churchyard warning of the danger of slipping roof slates. All roofs need recovering as the fixings have rusted and the stone tiles are laminating.

Contact: Annie Evans 0117 975 0673

Contact: Annie Evans 0117 975 0673

Contact: Sarah Ball 0117 975 0666

© Historic England



SITE NAME:	Church of St Mary, Church Street, Donyatt
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation

1057074

The current church dates primarily from the C15 and is a rebuild of an earlier church. Consists of nave, chancel, north and south aisles, south porch and west tower. Extensive works carried out in the C19 which included the nave and aisle roofs. The chancel is full width and height. There is severe cracking over the chancel arch and the east window, both full width of the walls.

© Historic England



SITE NAME:	Church of St Peter, Church Road, Ilton
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1057052

Anglican parish church dating from the C13 onwards. Chancel, nave, north aisle, tower on the south clasped by the nave and south transept, effectively forming a south porch. Organ chamber on north probably part of reordering by Street in the 1860s. The church suffered heritage crime in early 2020.

© Historic England



ര	Historic	England

SITE NAME:	Church of All Saints, Isle Brewers
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1263514

Parish church built 1861 by CE Giles. Built of lias stone with Ham stone dressings. The roof tiling is poor and the ceiling, which appears to be plastered directly onto the underside of the rafters, is falling in so that the whole of the interior of the nave is netted. A couple of the windows are in need of repair. The stair tower has severe fracturing. A National Lottery Heritage Fund Grant for Places of Worship Delivery grant has been awarded and is expected to be completed during late 2020.

Contact: Sarah Ball 0117 975 0666

Contact: Annie Evans 0117 975 0673

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 F. Under repair or in fair to good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).



© Historic England

SITE NAME:	Church of St Martin, Church
	Street, Kingsbury Episcopi

DESIGNATION: Listed Place of Worship grade I,

CA

CONDITION: Fair

PRIORITY CATEGORY: A (New entry)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1056885

Anglican parish church. C14, C15, with C19 restoration. Predominantly Perpendicular and symmetrical plan with aisles and chancel aisles. Dominant tower, with elaborate stonework. The church suffered from heritage crime in early 2020.

Contact: Annie Evans 0117 975 0673



© Historic England Archive

SITE NAME: Church of St Thomas a Becket, Sherborne Road, South

Cadbury

DESIGNATION: Listed Place of Worship grade

II*, CA

condition: Fair

PRIORITY CATEGORY: A (New entry)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1258922

Anglican parish church. C13 and C15, restored in 1850s and 1870s. Chancel nave and south aisle, with north porch, south-east vestry and west tower. Cary and lias stone, mostly ashlar, with some doulting stone dressings; plain clay tile roofs with stone slate base courses to chancel, slate over stone to nave, both between stepped coped gables. Interior has work of many periods. Church suffered heritage crime in early 2020.

Contact: Annie Evans 0117 975 0673



© Historic England

DESIGNATION: Listed Place of Worship grade I,

CA

condition: Fair

PRIORITY CATEGORY: A (New entry)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1056959

aisles, C13 chancel and crossing, remainder mostly C15, major restorations in late C19/early C20. Ham stone ashlar, some rubble work; chancel and south porch have pitched tiled roofs. Church suffered heritage crime in early 2020.

Anglican parish church with Saxon origins; cruciform with

Contact: Annie Evans 0117 975 0673



© Historic England

SITE NAME:

Church of St Mary the Virgin, Stoke Sub Hamdon

Listed Place of Worship grade I, CA

CONDITION:

Poor

CONDITION: Poor

PRIORITY CATEGORY: D (D)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1260420

Parish church of mainly C12 and C13 with later additions. Water ingress problems leading to damp as evidenced by the algal growth on the north and south side of the nave (and in the porch). Vegetation needs clearing from between the coping stones and roof slates. Rainwater goods in need of repair. The congregation has been awarded a Listed Places of Worship Roof Repairs Grant and some work was carried out in 2016-17 but more repairs are needed.

Contact: Annie Evans 0117 975 0673

SITE NAME:	Low Ham Roman villa, High Ham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006192
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Northover House, late Roman cemetery, Ilchester		
SITE NAME: DESIGNATION:	Northover House, late Roman cemetery, Ilchester Scheduled Monument, CA	LIST ENTRY NUMBER:	1006128
	· · · · · · · · · · · · · · · · · · ·	LIST ENTRY NUMBER: TREND:	1006128 Stable
DESIGNATION:	Scheduled Monument, CA Generally unsatisfactory with major localised		

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 Full day reasing a fine fairner and the second second
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Hamdon Hill camp, Montacute / Norton Sub Hamdon / Stoke Sub Hamdon				
DESIGNATION:	Scheduled Monument, LB grade II, part in CA		LIST ENTRY NUMBER:	1003678	
CONDITION:	Generally satisfactory but with significant localised problems		TREND:	Declining	
PRINCIPAL VULNERABILITY:	Mineral extraction/related subsidence		NEW ENTRY?:	No	
OWNER TYPE:	Local authority		CONTACT:	Alessandra Perrone 0117 975 1345	
	SITE NAME:	Redlynch Park, Bruton / Shepton Montague	Redlynch is a larg	ermerly the principal seat of the Earls of Ilchester, edlynch is a large landscape park near Wincanton. The lain house has gone and the stables and ancillary building e now in multiple ownership. The majority of the rkland planting has disappeared, boundary walls and tate railings are generally in poor condition. There are so on-going development pressures. An C18 Gothic tehouse, The Towers, was repaired in 2012 and is no	
	DESIGNATION:	Registered Park and Garden grade II, 10 LBs	are now in multi		
	CONDITION:	Generally unsatisfactory with major localised problems	also on-going de		
2 5 5 5	VULNERABILITY:	Medium	longer at risk, and sections of the park wall have been repaired with a Natural England Stewardship Scheme.		
	TREND:	Stable			
© Historic England	NEW ENTRY?:	No			
	OWNER TYPE:	Private, multiple owners			
	LIST ENTRY NUMBER:	1000420	Contact: Jo McA	llister 0117 975 0696	
A VARIABLE AND A	SITE NAME:	Cricket House, Cricket St. Thomas / Winsham	C18 landscape p	ark and pleasure grounds surrounding partly by Sir John Soane. Pressure for	




© Historic England

SITE NAME:	Cricket House, Cricket St. Thomas / Winsham
DESIGNATION:	Registered Park and Garden grade II*, 8 LBs
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	Medium
TREND:	Stable
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1001142

development from a large hotel and from farm diversification into the leisure market. Parts of the park have been restored through a Natural England Stewardship Scheme.

Contact: Jo McAllister 0117 975 0696

SOUTH GLOUCESTERSHIRE (UA)



© Historic England Archive

SITE NAME:	Whitfield Tabernacle, Park Road
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1116201

Former chapel, built in 1741. The building has been redundant for many years and a fire has placed the building in an even more vulnerable position. In 2019 Historic England grant-aided some works to improve access to the site while continuing discussion with the Local Authority and the owners to establish a sustainable and viable long term strategy for the site. An application for emergency repair, consolidation and installation of a new roof has been submitted in April 2020.

Contact: Alessandra Perrone 0117 975 1345

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

-
3

© Historic England Archive

SITE NAME:	Monument to Lord Robert Edward Somerset, Hawkesbury
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1320834

A tall tapering stone tower ashlar monument by Lewis Vulliamy dated 1846. Repairs needed at high-level to cast iron balcony and stonework.

Contact: Sarah Ball 0117 975 0666

	Mr. I	
1		
		1

© Historic England

SITE NAME:	Ragged Castle or Keeper's Lodge, Badminton Park, Hawkesbury
DESIGNATION:	Listed Building grade II*, RPG grade I
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

Folly Castle. Set on a motte at end of a main drive from Badminton House, c1750 by Thomas Wright of Durham. Largely hidden by trees. Shell of structure is in poor condition. Interior has been lost. There has been clearance of vegetation on and around the structure.

LIST ENTRY NUMBER: 1156209

LIST ENTRY NUMBER:

Contact: Sarah Ball 0117 975 0666



© Historic England

	SITE NAME:	Brandy Bottom Colliery, Pucklechurch
	DESIGNATION:	Scheduled Monument
	CONDITION:	Poor
	OCCUPANCY:	N/A
	PRIORITY CATEGORY:	C (C)
	OWNER TYPE:	Commercial company
	LIST ENTRY NUMBER:	1019400

A former C19 steam-powered colliery built on the site of C18 colliery. The Avon Industrial Buildings Trust have taken on the site and run regular work parties. They have undertaken vegetation clearance and minor repairs to stabilise the structures. Historic England grant aided works since 2014 have included repairs to the chimney, the structures within the Old Pit and New Pit and some interpretation. A Heritage Partnership Agreement document forms the basis of an on-going programme of repair and research.

Contact: Alessandra Perrone 0117 975 1345



© Historic England

SITE NAME:	Outer Court of Thornbury Castle and Wall of Kitchen Court, Church Road, Thornbury
DESIGNATION:	Listed Building grade I, part in RPG grade II, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: A (New entry)

OWNER TYPE: Commercial company

LIST ENTRY NUMBER: 1321132

Thornbury Castle outer court walls are currently in a poor condition. Vegetation overgrowth has gone unchecked. As a result ivy, brambles, and trees are growing out of the stonework and completely concealing certain features of the walls. It is also causing the portcullis archway to become increasingly unstable. Previously public access was allowed, however a fence has been installed which prevents people from experiencing the history of the site properly. Overall the condition of the walls requires urgent attention.

Contact: Chris Miners 0117 975 1355



© Historic England

SITE NAME:	Coach House and stables north east of Oxwick Farmhouse, Oxwick Lane, Yate, Wickwar
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private

1312305

Coach house and stables, built 1722 in a mannered provincial baroque. The building is under a temporary roof. Listed Building Consent was approved in 2011 for substantial repair works. A separate application was made for a wind turbine which was approved in 2013 on the basis that the revenue generated from it should assist in funding the repairs to both listed properties on the site. Historic England provided structural advice in early 2018 on the condition of the scaffolding with the view of securing maintenance works to the temporary supporting structure.

Contact: Stephen Guy 0117 975 0725

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 F. Under repair on in fair to good.

LIST ENTRY NUMBER:

- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

y category is LB (otherwise, LPA). NP RPG SM

ABBREVIATIONS CA Conservation

LIST ENTRY NUMBER:



© Historic England	

SITE NAME:	Oxwick Farmhouse, Oxwick Lane, Yate, Wickwar
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1321124

Farmhouse dated 1722, in flamboyant artisan mannerist/baroque style. Part occupied. Vacant part has serious decay of floor structures and in areas is unsafe, but emergency repairs have been implemented. Discussions over full repair remain on-going. Some enabling development has been permitted in the form of renewable energy.

Contact: Stephen Guy 0117 975 0725



SITE NAME:	Parish Church of St Andrew, Church Lane, Cromhall
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER	1114974

Parish church. C12, rebuilt in C13/C14 and altered C15; restored 1852. Rubble with freestone dressings; stone slate roof with coped raised verges, slate to the nave. The sandstone slates have slipped or are missing. The rainwater system is rusted and leaking. There is structural cracking over the south aisle east window and over the west window.

Contact: Chris Miners 0117 975 1355

_

SITE NAME:	Church of St Mary the Virgin, Church Road, Yate
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1128753

Large urban parish church with a nave, chancel, aisles, transepts and west tower. Sandstone with limestone dressings and roofed with stone slates. Localised leaks over many years are steadily worsening over much of the roof. The north aisle and the south chancel roofs should be the first to be repaired.

Contact: Chris Miners 0117 975 1355

(C)	Historic	Fng	lanc
0	I IISLOTIC	LIIg	anc

© Historic England

SITE NAME:	Round barrow on Barrow Hill, Bitton		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1004521
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Roman villa and earlier settlement remains in Badmi Hawkesbury	nton Park, 340 me	tres south of Hinnegar Lodges,
DESIGNATION:	Scheduled Monument, RPG grade I	LIST ENTRY NUMBER:	1021415
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Bury Hill camp, Moorend, Winterbourne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007023
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



© Historic England

SITE NAME:	Tortworth Court, Cromhall / Falfield / Tortworth
DESIGNATION:	Registered Park and Garden grade II*, 7 LBs, part in SM
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	High
TREND:	Stable
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1000394

Important Victorian house and grounds, including renowned arboretum. House now a hotel and part of grounds lost to Leyhill Open Prison. Walled garden being redeveloped for light industrial use. Arboretum neglected. Extensive loss of trees in park. The registered area is in multiple ownership and suffers from a lack of holistic management. In 2016 a Conservation Management Plan for part of the registered park was produced with grant aid from Historic England. This was followed in 2017 by a grant to assist with de-silting the lake (now completed), which forms the centrepiece of the design.

Contact: Jo McAllister 0117 975 0696



© Historic England

SITE NAME:	Stoke Park, Stoke Gifford
DESIGNATION:	Registered Park and Garden grade II, 10 LBs, SM, part in CA
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	High
TREND:	Improving
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1000129

Mid-C18 park laid out around crenellated Dower House. The park is in a dramatic location on a hill overlooking the city of Bristol and is embellished by monuments and eye-catchers. Now bisected by the M32 motorway. Setting compromised by dense residential development. Park under pressure from heavy and occasionally anti-social use, particularly affecting park structures. In 2012, the majority of the site was transferred to Bristol City Council who received Historic England grant towards a Conservation Management Plan in 2015-16 which is now being implemented under Natural England Stewardship.

Contact: Jo McAllister 0117 975 0696

SITE NAME:	Warmley, Siston / Oldland		
DESIGNATION:	Conservation Area, 9 LBs, RPG grade II, SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	lan Gething (LPA) 01454 863578
SITE NAME:	Whitfield Tabernacle		
SITE NAME: DESIGNATION:	Whitfield Tabernacle Conservation Area, 3 LBs	NEW ENTRY?:	No
		NEW ENTRY?: TREND:	No Improving
DESIGNATION:	Conservation Area, 3 LBs		

SWINDON (UA)



© Historic England Archive

SITE NAME:	The Mechanics Institute, Emlyn Square
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (C)
OWNER TYPE:	Commercial company

1198947

Mechanics Institute, 1853-5; now vacant. Outstanding example at heart of railway village. The council served an Urgent Works Notice on the owner in 2009 and implemented works in 2010 to secure the building. The shell of the building has been stabilised but it is not possible to enter due to health and safety concerns. The "Railway Village", of which the Mechanics forms the centrepiece, is now a Historic England Heritage Action Zone. An options appraisal for the future use of the building has now been completed and a project to restore the building is in its early stages.

Contact: Simon Hickman 0117 975 0717

SITE NAME:	Bowl barrow 280 metres north of Downs Barn, Bishopstone		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010419
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 F. Under repair or in fair to good.

LIST ENTRY NUMBER:

- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise.

New Entry is noted).

r is LB Listed Building See, LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

ABBREVIATIONS

HERITAGE AT RISK 2020 / SOU	JTH WEST / SWINDON (UA)		
SITE NAME:	Bowl barrow on Hinton Downs, Bishopstone		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010461
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Disc barrow on Burderop Down, I kilometre nort	th east of Upper He	erdswick Farm, Chiseldon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010457
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow I kilometre west of Sheppard's Farm	Dairy, Chiseldon /	Ogbourne St. George
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012439
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - Badger - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Field system and earthwork enclosure on Burdero	p Down, Chiseldor	ı / Ogbourne St. George
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016383
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Four Highworth circles 150 metres north east of F	ickett's Copse, Hig	hworth
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016386
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Three Highworth circles 600 metres east of North	Leaze Farm, High	worth
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018221
CONDITION:	Extensive significant problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 700 metres south west of Liddington	Warren Farm, Lid	dington
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009634
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area Listed Building LPA Local Planning Author NP National Park RPG Registered Park and G SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Site of Roman town, west of Wanborough House	, Wanborough / Co	vingham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004684
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Long barrow 700 metres north of Liddington Wa	rren Farm, Liddingto	on / Wanborough
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009631
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Remains of Holy Rood Church, The Lawn, Old To	own	
DESIGNATION:	Scheduled Monument, 3 LBs	LIST ENTRY NUMBER:	1018057
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Nick Croxson 07795 665645

TORBAY (UA)



© Historic England

SITE NAME:	Lupton House (Gramercy Hall School)
DESIGNATION:	Listed Building grade II*, RPG grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Charity (heritage)

Charity (heritage) LIST ENTRY NUMBER: 1195173

C18 and C19 country house remodelled by G Wightwick c1840, with extensive ancillary buildings and fine Italianate garden. Altered after a fire in 1928. In use as a school from mid C20 to 2004. A charitable trust has acquired the house and parts are used for weddings and community health activities. Historic England grant-aided development work to the Italianate Garden in 2015, and a condition survey of the house and ancillary structures, and emergency repairs including a trial area of repair to the Italianate Garden, in 2017-18. Further major funding from other sources is still required.

Contact: Annie Evans 0117 975 0673



© Historic England

SITE NAME:	llsham Manor Oratory, llsham Road, llsham
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Charity (non-heritage)

LIST ENTRY NUMBER: 1206789

Redundant oratory, part of the demolished medieval Ilsham Manor. Sited in the grounds of a school, which closed in 2015. Neglected and in poor condition, when assessed in 2012 the chapel was not in use. By 2015 large holes in the roof coverings had opened up and the rainwater goods were missing, causing significant water ingress. Historic England grant-aided a condition survey in 2016 and urgent repairs to the roof were completed with Historic England grant-aid in 2017. Repointing, window, and interior repairs remain to be tackled by new owners.

Contact: Annie Evans 0117 975 0673



© Historic England

SITE NAME:	The Bishop's Palace, Tower Road, Paignton
DESIGNATION:	Scheduled Monument, 2 LBs, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1020764

C14 curtain wall and tower, forming part of the medieval fortified residence of the Bishop of Exeter. Vegetation growth, especially valerian on the wall tops and growing from crevices, threatens the medieval walls. Their root system grows to a large bulbous form within the wall, pushing stones out of line and leading to breakdown of the structure. Ivy has also taken hold and is rapidly spreading along the south wall. In 2016 Historic England grant-aided a programme of vegetation removal and door rerfubishment.

Contact: Daniel Bashford 07824 103102

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise.

New Entry is noted).

I PA ΝP RPG



© Torbay Council

SITE NAME:	Torbay Cinema, Torbay Road, Paignton
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1208209

Cinema first licensed in 1912 and frequented by Agatha Christie. An extremely well preserved example of an early purpose-built cinema which closed in 1999. In 2015 Historic England helped with the transfer of ownership of the building to a new Trust. Coastal Revival funds secured in 2016 allowed the building to be accessible for public visits. A detailed survey and costing assessment of work needed to the front elevation and two-storey bay window has been completed in 2019-20 with grant aid. Further feasibility work has been undertaken by the Trust to look at future uses within the building.

Contact: Annie Evans 0117 975 0673



LIST ENTRY NUMBER:

SITE NAME:	Church of St Mary Magdalene, Upper Union Street, Torquay
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1219197

Parish church. Built between 1843 and 1849 to the designs of A Salvin, by contractor Jacob Harvey. Altered and partly re-fitted under GG Scott 1881-82; further embellishment 1906 and 1927. Local grey limestone rubble with Bath stone dressings; slate roof. Rainwater goods all need overhauling. The church received a Listed Places of Worship Roof Repairs Grant in 2017 and rainwater goods have been overhauled. High level stonework in very bad condition and difficult to access. The clerestory stonework spalling badly. A rope access survey has identified these problems in more detail.

Contact: Annie Evans 0117 975 0673

SITE NAME:

© Historic England

DESIGNATION

CONDITION:

Ashhole Cavern, Brixham	
Scheduled Monument, part in CA	LIST ENTRY NUMB

Generally satisfactory but with significant localised problems

PRINCIPAL VULNERABILITY: **Vandalism**

OWNER TYPE: Local authority

LIST ENTRY NUMBER:	1019133

TREND: Declining

NEW ENTRY?: No

CONTACT: Daniel Bashford 07824 103102



© Dennis Coote. Source Historic England Archive

SITE NAME:	Church of St Mary the Virgin, Drew Street, Brixham
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1195156

Parish church. C15, re-roofed 1867, restored by Tait and Harvey in 1905. Chancel, nave, north and south aisles, north and south transepts, north and south chancel chapels, west tower, south porch. Solid roughcast walls with Beer and red sandstone dresssings, slate roofs. Water penetration through exposed tower buttresses causing damage to exposed stonework and embedded timber beam ends.

Contact: Annie Evans 0117 975 0673

SITE NAME:	Prehistoric field system at Walls Hill		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019134
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - limited/localised	NEW ENTRY?:	Yes
OWNER TYPE:	Local authority	CONTACT:	Daniel Bashford 07824 103102

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England

SITE NAME:	Oldway Mansion
DESIGNATION:	Registered Park and Garden grade II, 12 LBs
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	Medium
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1001368

Formal gardens laid out to complement a grand house, apparently inspired by the Palace of Versailles. Built by the Singer sewing machine dynasty, the grounds have been steadily rationalised and simplified. Permission was granted in 2012 for mixed-use development, including a hotel in the main house and housing in the grounds, but this was never implemented. The property remains in Local Authority ownership, with no scheme identified.

Contact: Jo McAllister 0117 975 0696

© Historic England

SITE NAME:	Princess Gardens and Royal Terrace Gardens, Torquay
DESIGNATION:	Registered Park and Garden grade II, 4 LBs, 2 CAs
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	Medium
TREND:	Improving
NEW ENTRY?:	No
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1001507

Important formal Victorian seaside park with later phases and additions. Major development agreed, including a multi-storey, mixed-use building to be attached to the grade II listed Pavilion and the seasonal installation of a Ferris wheel. A condition report and management plan for the gardens was completed in early 2017.

Contact: Jo McAllister 0117 975 0696

DEVON

TORBAY (UA) / SOUTH HAMS



© Historic England

SITE NAME:	Lupton Park, Kingswear
DESIGNATION:	Registered Park and Garden grade II*, 7 LBs, part in CA
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	High
TREND:	Improving
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1000696

-- D--I. I/:-

The designed landscape was principally developed from the late-C18 through to mid-C19. After World War II the house became a hotel, then a school. Today a trust occupies the house (at risk) with the degraded Italianate garden, while other owners occupy the park, walled garden, pleasure grounds and woodlands. In 2015 Historic England funded a condition report for the Italianate Garden and a further grant for development work on the house and garden was offered with work underway in 2017-18. The condition of the park is being tackled by a Natural England Stewardship Scheme.

Contact: Jo McAllister 0117 975 0696

WILTSHIRE (UA)



© Historic England

SITE NAME:	Rudloe Manor, Box
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1022808

Late C17 manor house surrounded by ancillary buildings including a grade II listed barn. The house was part of a larger Ministry of Defence site which was vacated in 1998. The current owners have consent for a residential scheme with enabling development. Work has been undertaken to the exterior of the listed building to make it watertight but it remains vacant. The property has recently been put up for sale but not sold.

Contact: Jacqueline Smith 0117 975 0667

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 F. Under repair on in fair to good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).



© Wiltshire Council

SITE NAME:	Buildings to the rear of the Lansdowne Arms Hotel, The Strand, Calne
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor

OCCUPANCY: Vacant/not in use PRIORITY CATEGORY:

C (C) OWNER TYPE: Private

LIST ENTRY NUMBER: 1247495

Former coach house, stable and brewhouse to rear of Lansdowne Arms Hotel. Buildings range from mid C17 to mid C19. Condition of roofs and coverings are continuing to degenerate leading to further internal decay. Urgent Works Notices have previously been complied with; however, the condition of these buildings continues to decline. Pre-application discussions and assessment work on-going, with progress meetings having taken place in

Contact: Jacqueline Smith 0117 975 0667



© Historic England

SITE NAME:	The Lansdowne Monument, Calne Without
DESIGNATION:	Listed Building grade II*, SM
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Charity (heritage)

LIST ENTRY NUMBER:

1253569

Obelisk constructed in 1845 by Sir Charles Barry for the 3rd Marguess of Lansdowne in memory of Sir William Petty, ancestor of the Petty-Fitzmaurice family. The condition of this monumental local landmark is in decline due to the effect of weathering on the stonework. Planning Permission and Listed Building Consent to maintain the temporary protection, whilst the project to repair the monument is being developed, were granted in March 2020 on a temporary basis for five years. .

Contact: Sarah Ball 0117 975 0666



© Historic England

SITE NAME:	Former hangars at Yatesbury Airfield, Cherhill
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1283146

Two aircraft hangars, built c1917 as part of a training centre. Two hangars from the first years of military flying. One hangar has been repaired, though there is no current end use. Consent has been granted to demolish the second hangar and this is currently in a collapsed state. As of 2019, previously approved applications not implemented.

Contact: Jacqueline Smith 0117 975 0667



© Historic England Archive

SITE NAME:	Former Law Courts and County Police Station, Northgate Street, Devizes
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1251744

Law courts and police station, 1835. Wind and weather tight. Interior has been gutted. Several schemes have been granted consent, including residential and nightclub use, but none have been implemented. Planning Permission and Listed Building Consent granted in 2012 for a new residential scheme was renewed 2015 and expired 2018. Urgent works carried out in 2015. Purchase by Wiltshire Historic Buildings Trust completed in 2018 and site is now in ownership of Assize Courts Trust. Emergency work is largely complete. There are proposed plans to carry out conversion for use as a museum.

Contact: Jacqueline Smith 0117 975 0667



© Historic England Archive

SITE NAME:	Stable block to Tottenham House, Great Bedwyn
DESIGNATION:	Listed Building grade II*, RPG grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1365488

Impressive stable block of 1818, by Thomas Cundy, located 150 metres NNW of Tottenham House. Following neglect, the structure has recently suffered a collapse to the clock tower and the surviving structure is in an unsafe and partially ruinous condition. A planning application was granted early 2018 supporting the return of Tottenham House to a single family dwelling, with some additional development and the conversion of the Stable Block for ancillary leisure use. The site is now under new ownership and discussions regarding rebuilding and implementation of the agreed scheme are underway.

Contact: Jacqueline Smith 0117 975 0667

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England Archive

SITE NAME:	Tottenham House, Great Bedwyn
DESIGNATION:	Listed Building grade I, RPG grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1183809

Country house 1825 by Thomas Cundy, situated in park, developed from C15 to C17 and landscaped by Lancelot 'Capability' Brown in the 1760s. Previously used as a preparatory school (from the 1950s) now vacant. A planning application was granted early 2018 supporting the return of Tottenham House to a single family dwelling with some additional development and the conversion of the Stable Block for ancillary leisure use. The site is now under new ownership and the implementation of the agreed works will result in the buildings being removed from the Heritage at Risk Register.

Contact: Jacqueline Smith 0117 975 0667

SITE NAME:	Three former World War I aircraft hangars at Old Sarum Airfield, Portway, Laverstock
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1355710

One single and two paired aircraft storage hangars which were designed in 1917 and built in 1918. They are constructed with piers, curtain walls and gantries brickwork with 'Belfast' roof trusses. The hangars are deteriorating fast due to a sustained period of neglect. Recent planning applications relating to the wider Old Sarum Airfield proposed their restoration, but these were dismissed at appeal.

Contact: Jacqueline Smith 0117 975 0667

Contact: Sarah Ball 0117 975 0666



© Historic England

SITE NAME:	Chapel at Knowle House, Little Bedwyn
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	Unknown
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1004708

LIST ENTRY NUMBER:

Early C15 former chapel in curtilage of a listed house. In poor condition and needs some work and repair to roof and gable wall.

SITE NAME:

The Red House at Eastwell Manor, Eastwell Road, Potterne

DESIGNATION:

Listed Building grade II*

CONDITION:

Poor

OCCUPANCY:

N/A

PRIORITY CATEGORY:

C (C)

OWNER TYPE:

Private

LIST ENTRY NUMBER:

1258775

Red brick garden building. Built c1700. One of several buildings on this site that are presently disused and in a decaying condition. An Enforcement Notice has been served in respect of unauthorised alterations. An appeal was lodged by the owner but was rejected by the planning inspector. Access to the site is currently restricted.

Contact: Jacqueline Smith 0117 975 0667



© Historic England

SITE NAME:	Courtfield House, Polebarn Road, Trowbridge
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1021635

Courtfield House is a clothier's house built c1754 with an earlier C17 building to rear. The house was used as a preparatory school which closed in April 2012. Adjoining the house is a relatively unaltered wool store. The roof structure of the house is in poor condition with a collapsing valley gutter. The property is currently vacant and subject to vandalism. Purchased in April 2016 by a developer to convert the main house to residential units with new build residential in the grounds. Building is now scaffolded and secure and negotiations to reach an acceptable application continue.

Contact: Simon Hickman 0117 975 0717

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 Lindon repair on in fair to good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument



© Salisbury District Council

SITE NAME:	Chapel, immediately north of
	Pythouse, Pythouse Park, Wes

Tisbury

DESIGNATION: Listed Building grade II*

CONDITION: Very bad

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: A (A)

OWNER TYPE: Private

LIST ENTRY NUMBER: | | 13| 162

LIST ENTRY NUMBER:

SITE NAME:

Former private chapel to country house, c1827. Built by John Bennett of Pythouse for his wife nee Lucy Lambert of Boyton. The chapel is derelict and overgrown and the stonework has been vandalised. The building is now scaffolded. Some of the vegetation has been removed.

Late C19 privately owned mausoleum, within a local authority municipal cemetery. The building is currently disused and continues to deteriorate. It is the subject of on-going vandalism but has been secured against break-ins.

Contact: Sarah Ball 0117 975 0666



© Historic England Archive

SITE NAME:	Phipps Mausoleum, Westbury Cemetery, Bratton Road, Westbury
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1364424

Contact: Sarah Ball 0117 975 0666

SITE NAME:	Zeals House, Zeals
DESIGNATION:	Listed Building grade I
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1318497

Zeals House is a Grade I country house originally constructed in the late C14 with phases of alterations dated to the C17, C18 and 1860s, the latter for William Chafyn-Grove. The house is currently unoccupied and is falling into a state of disrepair that is exposing historic fabric to conditions that will expedite its deterioration.

Contact: Jacqueline Smith 0117 975 0667



	Without
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1261936

Church of St Peter, Calne

Parish church, probably C13, altered and extended 1859 and restored 1907 by CE Ponting. Rubble stone coped chancel gable and gabled stone slate hung west bellcote. The church has structural movement and monitoring was carried out for over a year to inform a specification for repair. Advice on repairs was given by Historic England in Spring 2018 following which the congregation are progressing a repair project.

Contact: Sarah Ball 0117 975 0666





© Historic England

SITE NAME:	Church of St Nicholas, Baydon
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1034135

Anglican parish church with fabric dating from C12, C13 and C15 with C19 restorations in 1857, 1876 and 1892. Consists of nave, north aisle, chancel, north vestry and west tower. East window by GE Street dated 1857-58. Severe vertical cracking in east and north walls of chancel. Emergency propping erected in February 2019.

Contact: Sarah Ball 0117 975 0666

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 F. Under repair or in fair to good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).



SITE NAME:	Church of St Peter, Charlton
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1365532

Parish church. C16 and 1857-8 by JL Pearson. Medieval work in ashlar limestone. C19 work in flint banded with limestone ashlar and brick. Tiled roof. North porch with tower over and north chapel, all C15-C16. Nave and chancel in one, rebuilding original work. The plain clay tiles to the roof are failing and although regular patching and repair is being undertaken, the roof will need renewing.

Contact: Sarah Ball 0117 975 0666

© Historic England



SITE NAME:	Church of St Mary, A419, Chilton Foliat
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LICT ENITDY NILIMBED.	1024120

Parish church, c1300, early C14 and C19. Flint with Bath stone dressings. North nave wall, tower and chancel rendered. Stone tile roof with slate to nave. Nave, south aisle and porch, chancel, west tower and vestry. Chancel and nave roofs and rainwater goods in poor condition.

LIST ENTRY NUMBER: | 1034|39 Contact: Sarah Ball 0117 975 0666

Road, Kilmington

Church of St Mary, Church



SITE NAME:

DESIGNATION: Listed Place of Worship grade II*

CONDITION: Poor

PRIORITY CATEGORY: D (D)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1318459

Church of England parish church. C15 tower, chancel rebuilt 1864, complete rebuilding 1869, tower restored 1903 by CE Ponting. Dressed limestone, rubblestone, tiled roof with ceramic ridge cresting and coped verges. West tower and entrance, nave and north aisle, south transept, north vestry and chancel. Narrow three-stage tower of Somerset type. Roofs and masonry in poor condition, particularly tower. Unsuccessful in attempts to obtain National Lottery Heritage Fund grant. Repair of tower roof proposed as first phase of repair.

Contact: Sarah Ball 0117 975 0666

© Marcus Chantrey, Benjamin Beauchamp Architects



SITE NAME:	Church of St Peter, Swindon Road, Langley Burrell Without
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1199423

Parish church, c1200, c1300, C14 and C15, carefully restored 1890 (chancel) by CE Ponting and 1898 (nave and north aisle) by H Brakspear. Rubble stone with stone slate roofs and coped gables. Nave, north aisle, transeptal south tower with porch, chancel and south east chapel. Stone tiles to nave roof in poor condition and rainwater goods require overhauling.

Contact: Sarah Ball 0117 975 0666

© Historic England



© Marcus Chantrey, Benjamin Beauchamp Architects

SITE NAME:	Church of St Anne, Bowden Hill, Lacock
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1363962

Church of England parish church 1856-7 by SB Gabriel of Bristol. Consists of nave, chancel and north porch in Early English style with Romanesque style north east tower. There has been past structural movement in the church but since Summer 2018 this has accelerated and large cracks have opened around the chancel arch. Emergency propping has been erected externally in the south-east corner of the nave since October 2018.

Contact: Sarah Ball 0117 975 0666

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 Full lader repair on in fair to good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).



SITE NAME:	All Saints Chapel, Swan Lane, Leigh
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1356042

Church of England parish church. C14 and 1896 by CE Ponting. Squared limestone rubble, stone slate roof. Nave rebuilt from old church and new chancel added. C14 porch entrance with wave moulding and hood. Sundial above. Stone slate roof and rainwater goods are in poor condition. Render to bell turret is failing.

Contact: Sarah Ball 0117 975 0666

© Historic England



SITE NAME:	Church of St Andrew, Church Lane, Melksham
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1286098

Church of England parish church, 1876 by Charles Adye. Ashlar, decorative tiled roof with coped verges, cross finials and cresting. Nave and chancel with south door and north vestry. Early English style. The clay tiled roofs and rainwater goods to the nave and chancel are in poor condition. In 2017, a scheme was drawn up to redevelop the modern extension to provide community use as part of the church. Funding sources for this will be explored.

Contact: Sarah Ball 0117 975 0666

© F	Historic	Eng	land
-----	----------	-----	------

SITE NAME:	Wermere pond, Alvediston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004774
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	A bell barrow and two bowl barrows east of The Accemetery, Amesbury	Avenue on Countes	ss Farm: part of a linear round barrow
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010331
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bell barrow 550 metres east of New Barn, Earl's Fa	arm Down, Amesbi	ury
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009872
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 80 metres north of the A303, north	east of Vespasian's	Camp, Amesbury
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1012128
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

SITE NAME:	Bowl barrow 140 metres north of the A303 on	Countess Farm, Ames	sbury
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1009142
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	Yes
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 150 metres east of Stonehenge Co	ttages on A303, Ame	sbury
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1012129
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow forming part of Normanton Down	round barrow cemet	ery, Amesbury
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010330
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	Yes
OWNER TYPE:	Charity (heritage)	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Bowl barrow on Coneybury Hill, 130 metres N1	NE of Luxenborough I	Plantation, Amesbury
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1012392
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	Yes
OWNER TYPE:	Charity (heritage)	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Bowl barrow on Coneybury Hill, 450 metres so	uth of the A303, Ame	sbury
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1012390
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	Yes
OWNER TYPE:	Charity (heritage)	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Henge monument 400 metres south of Stoneher	nge Cottages, Amesbu	ıry
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1012376
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	Yes
OWNER TYPE:	Charity (heritage)	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	King barrow and another bowl barrow on Cone	ybury Hill, Amesbury	
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1012375
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	Yes
OWNER TYPE:	Charity (heritage)	CONTACT:	Nick Croxson 07795 665645

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area Listed Building LPA Local Planning Author NP National Park RPG Registered Park and G SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Linear boundary earthwork on Amesbury Down w	est of Stock Botto	m, Amesbury	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015218	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Part of Stonehenge Avenue and two adjacent round barrows, Amesbury			
DESIGNATION:	Scheduled Monument, LB grade II, part in CA, WHS	LIST ENTRY NUMBER:	1010140	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	Yes	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Three bell barrows 300 metres north east of New Barn, Earl's Farm Down, Amesbury			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009572	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No	
OWNER TYPE:	Educational (state sector)	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Linear boundary earthwork 250 metres west of Stockport, Amesbury / Idmiston			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015689	
CONDITION:	Extensive significant problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Beckhampton round barrow cemetery 150 metres	north east of the "	Waggon and Horses', Avebury	
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008221	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Bowl barrow 770 metres south west of the junctio round barrow cemetery on Avebury Down, Avebu	n of the Ridgeway ry	and Green Street, forming part of a	
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008107	
CONDITION:	Extensive significant problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Charity (heritage)	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Earthwork enclosure 950 metres SSE of Manor Far	m, Avebury		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1014031	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
		CONTACT:	NEST COMMON 0770F (7574F	
OWNER TYPE:	Charity (heritage)	CONTACT:	Nick Croxson 07795 665645	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Pair of round barrows 400 metres west of the Rid on Avebury Down, Avebury	geway, forming part	t of a round barrow cemetery situate
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008075
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Pair of round barrows forming part of the Bronze West Kennett Farm, Avebury	Age round barrow	cemetery 400 metres north east of
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008101
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Remains of 'Falkner's Circle', a Neolithic stone circ	cle 180 metres east	of the West Kennet Avenue, Avebu
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008109
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Round barrow cemetery 400 metres south of Avebury henge monument on Waden Hill, Avebury		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008216
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Ten barrows forming part of Fox Covert round ba	rrow cemetery, W	est Down, Avebury
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008293
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	West Kennet Avenue and an earthwork bank east	of West Kennett F	arm, Avebury
designation:	Scheduled Monument, LB grade II, 2 CAs, WHS	LIST ENTRY NUMBER:	1015547
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	A henge, four Bronze Age barrows and part of a R / Bishops Cannings	oman road 500 me	tres south west of Fox Covert, Aveb
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007491
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CITE NIAME.	\A/ /	/ Г / У	
SITE NAME:	West Kennett Farm palisaded enclosures, Avebu	•	1015157
DESIGNATION:	Scheduled Monument, 2 LBs, part in CA, WHS	LIST ENTRY NUMBER:	1015157
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Grovely Ditch, Barford St. Martin / Burcombe Without / Great Wishford / Wilton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005584
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	South Lodge camp Bronze Age enclosure with as metres east of Rushmore Farm, Berwick St. John	sociated field system	and round barrow cemetery, 350
DESIGNATION:	Scheduled Monument, RPG grade II	LIST ENTRY NUMBER:	1020962
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Bowl barrow 300 metres east of Furze Knoll, Bisl	nops Cannings	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013068
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Bowl barrow 550 metres north east of Baltic Fare	n, Bishops Cannings	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012629
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Bowl barrow 950 metres SSW of Beckhampton F Horton Down, Bishops Cannings	lantation, forming p	art of a round barrow cemetery on
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012983
CONDITION:	Extensive significant problems	TREND:	Unknown
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Bowl barrow situated 500 metres SSW of Shephe	erds' Shore, Bishops	Cannings
DESIGNATION:	Scheduled Monument, RB	LIST ENTRY NUMBER:	1013756
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
	Crown	CONTACT:	Nick Croxson 07795 665645

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Eleven round barrows 1000 metres north of Baltic enclosed Iron Age farmstead on North Down, Bish	Farm forming part nops Cannings	of a barrow cemetery, and a probabl
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013773
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Enclosed Iron Age farmstead 450 metres south of	Down Barn on Bish	nop's Cannings Down, Bishops Cannir
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013230
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Five round barrows 1040 metres NNE of Baltic Fal Bishops Cannings	rm forming part of	a barrow cemetery on North Down,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014737
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Four bowl barrows forming part of a cemetery 270 Cannings) metres east of lor	ng barrow on Roughridge Hill, Bishop
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014027
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Group of three bowl barrows 250 metres north ea	ast of Shepherds' Sh	nore, Bishops Cannings
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013232
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Kitchen Barrow: a long barrow on Kitchen Barrow	Hill, Bishops Cann	ings
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012519
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Long barrow 650 metres WSW of Shepherds' Sho	re, Bishops Canning	gs
DESIGNATION:	Scheduled Monument, RB	LIST ENTRY NUMBER:	1014030
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
	, 5 5		

- C Slow decay; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 D Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial list). use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

HERITAGE AT RISK 2020 / SOL	JTH WEST / WILTSHIRE (UA)		
SITE NAME:	Long barrow on Easton Down, Bishops Cannings		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013366
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Saucer barrow 600 metres west of Beckhampton E	Buildings, Bishops C	Cannings
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012193
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Two saucer barrows and a pair of bowl barrows 7 of a round barrow cemetery on Horton Down, Bis	50 metres SSW of shops Cannings	Beckhampton Plantation, forming par
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012982
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 85 metres north of Bishopstrow Hou	use, Bishopstrow	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1019507
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Motte and double ringwork east of Bishopstrow Fa	arm, Bishopstrow	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009891
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	Yes
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow: one of a group of round barrows so	uth of Bulford, Bulf	ord
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009545
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Corton long barrow, Boyton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010518
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Bowl barrow: one of a group of round barrows so	uth of Bulford, Bulf	ord
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009564
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Scrubbed Oak enclosure and linear boundary earth	nwork, Boyton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017713
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow: one of a group of round barrows so	uth of Bulford, Bulf	ord
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009602
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Long barrow on Cold Kitchen Hill, Brixton Deveri	II	
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1010416
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow: one of a group of round barrows so	uth of Bulford, Bulf	ord
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009604
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Long barrow on Pertwood Down, 1400 metres no	orth west of Lower	Pertwood, Brixton Deverill
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010463
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow: one of a group of round barrows so	uth of Bulford, Bulf	ord
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009605
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
		CONTACT:	Nick Croxson 07795 665645

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Knowle Hill round harrow Preed Chelles		
DESIGNATION:	Knowle Hill round barrow, Broad Chalke Scheduled Monument	LIST ENTRY NUMBER:	1002022
CONDITION:		TREND:	1003033
	Extensive significant problems	NEW ENTRY?:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		No No 07705 (45(45
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Multiple trackway south of Bulford Camp, Bulfor	rd / Cholderton / Ame	esbury
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1009613
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Round barrow 860 yards (786 metres) south eas	st of Knighton Hill Bui	ildings, Broad Chalke
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004771
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Long barrow 240 metres south west of Green B	Sarrow Farm, Castle C	Combe
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018419
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Knighton Roman road (stretching from Reddish	Gore to reservoir), B	road Chalke / Bishopstone
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003728
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 350 metres north east of White H	orse Plantation, Cher	hill
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010134
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Roman road in Spye Park, Bromham		
DESIGNATION:	Scheduled Monument, part in RPG grade II	LIST ENTRY NUMBER:	1003010
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
	5		

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Bowl barrow 700 metres south east of Field Barn,	Chicklade	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015937
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Three bowl barrows in Colerne Park, 450 metres	north of Keeper's (Cottage, Colerne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010758
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow on Wick Down, Collingbourne Ducis	5	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012510
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 650 metres east of Summer Down Fa	arm, Collingbourne	Kingston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012544
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Two bowl barrows 400 metres south of Summer [Down Farm, Colling	bourne Kingston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012518
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Crowdown Clump earthwork (Godsbury), Colling	bourne Kingston / I	Burbage
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004759
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow on Little Toyd Down, 650 metres so	uth west of Grims	Lodge Farm, Coombe Bissett
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015704
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

SITE NAME:	Motte and bailey castle 600 metres north of Castle	Combe, Castle Co	ombe
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1009580
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth - General	NEW ENTRY?:	Yes
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Moated site and surrounding earthwork enclosure,	100 metres south	of Chelworth Farm, Cricklade
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013353
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Dumping	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Devizes Castle, Devizes		
DESIGNATION:	Scheduled Monument and Listed Building grade II, 3 LBs, part in CA	LIST ENTRY NUMBER:	1021375 and 1249362
CONDITION:	Extensive significant problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Hugh Beamish 0117 975 0726
SITE NAME:	Berwick Coombe ditch, Donhead St. Andrew / Ber	wick St. John	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005587
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Long barrow on Ashmore Down, 775 metres north	of Ashgrove Cot	tages, Donhead St. Mary
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015938
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Ogbury camp, Durnford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005677
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Nine bowl barrows, two disc barrows and two sau cemetery on Durrington Down, Durrington	cer barrows formin	ng the majority of a round barrow
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008943
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.
 Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Nine round barrows forming a round barrow ceme	etery 400 metres n	orth of the eastern end of The Curs
DESIGNATION:	Durrington	LIST ENTRY NUMBER:	1000047
PESIGNATION.	Scheduled Monument, WHS		1009067
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	East Kennett long barrow, 600 metres south of Eas	st Kennett church,	East Kennett
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1012323
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Round barrow on Easton Down, Easton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005693
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Edington Priory (site of), Edington		
DESIGNATION:	Scheduled Monument, LB grade I, CA	LIST ENTRY NUMBER:	1004709
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
RINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Long barrow, Tinhead Hill, Edington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009783
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - Badger - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	North Hill round barrows, Grafton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004746
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 100 metres north of Great Botley Co	opse, Grafton / Sha	lbourne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012301
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1005604 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No OWNER TYPE: Private CONTACT: Nick Croxson 07795 6656 SITE NAME: Bowl barrow 340 metres east of Holly Bush Farm, Grittleton DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1018418 CONDITION: Extensive significant problems TREND: Unknown PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No OWNER TYPE: Private CONTACT: Nick Croxson 07795 6656 SITE NAME: Bell barrow 250 metres NNE of the sports ground: one of a group of round barrows north west DOWN, Idmiston DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1013971 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRYP: No OWNER TYPE: Declining PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRYP: No OWNER TYPE: Government or agency CONTACT: Nick Croxson 07795 6656 SITE NAME: Bell barrow, three bowl barrows and gas testing trenches on Idmiston Down, Idmiston DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014818 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining	.45
problems Arable ploughing New Entry: No OWNER TYPE: Bowl barrow 340 metres east of Holly Bush Farm, Grittleton Scheduled Monument Extensive significant problems TREND: Unknown Arable ploughing NEW ENTRY: No OWNER TYPE: Bell barrow 250 metres NNE of the sports ground: one of a group of round barrows north west Down, Idmiston DESIGNATION: Scheduled Monument UST ENTRY NUMBER: IO18418 CONTACT: Nick Croxson 07795 6656 Nick Croxson 07795 6656 TREND: DESIGNATION: Scheduled Monument UST ENTRY NUMBER: IO13971 CONDITION: Generally unsatisfactory with major localised problems Arable clipping NEW ENTRY: No OWNER TYPE: Government or agency CONTACT: Nick Croxson 07795 6656 TREND: Declining NEW ENTRY: No OWNER TYPE: Government or agency CONTACT: Nick Croxson 07795 6656	.45
Private CONTACT: Nick Croxson 07795 6656 RIE NAME: Bowl barrow 340 metres east of Holly Bush Farm, Grittleton DESIGNATION: Scheduled Monument Extensive significant problems RINCIPAL VULNERABILITY: Arable ploughing DESIGNATION: Private CONTACT: Nick Croxson 07795 6656 RIE NAME: Bell barrow 250 metres NNE of the sports ground: one of a group of round barrows north west Down, Idmiston DESIGNATION: Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems RINCIPAL VULNERABILITY: Arable clipping RINCIPAL VULNERABILITY: Down, Idmiston DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014818 CONDITION: Generally unsatisfactory with major localised TREND: Declining	45
Bowl barrow 340 metres east of Holly Bush Farm, Grittleton Scheduled Monument Extensive significant problems TREND: Unknown Arable ploughing NEW ENTRY! No DWNER TYPE: Private CONTACT: Nick Croxson 07795 6656 Bell barrow 250 metres NNE of the sports ground: one of a group of round barrows north west Down, Idmiston Scheduled Monument UIST ENTRY NUMBER: Declining PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY! No OWNER TYPE: Declining PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY! No OWNER TYPE: Government or agency CONTACT: Nick Croxson 07795 6656 Bell barrow, three bowl barrows and gas testing trenches on Idmiston Down, Idmiston DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: No OWNER TYPE: Government or agency CONTACT: Nick Croxson 07795 6656	45
Scheduled Monument Extensive significant problems TREND: Unknown MEW ENTRY?: No DESIGNATION: Bell barrow 250 metres NNE of the sports ground: one of a group of round barrows north west Down, Idmiston Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems RENCIPAL VULNERABILITY: Arable clipping NEW ENTRY?: No Declining REND: Declining	
Extensive significant problems TREND: Unknown NEW ENTRYP: No NO CONTACT: Nick Croxson 07795 6656 THE NAME: Bell barrow 250 metres NNE of the sports ground: one of a group of round barrows north west Down, Idmiston DESIGNATION: CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRYP: Government or agency TREND: Declining NEW ENTRYP: No CONTACT: Nick Croxson 07795 6656 TREND: Declining NEW ENTRYP: No DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: INC. Nick Croxson 07795 6656 THE NAME: Bell barrow, three bowl barrows and gas testing trenches on Idmiston Down, Idmiston Designation: Generally unsatisfactory with major localised TREND: Declining Declining TREND: Declining TREND: Declining TREND: Declining	
Arable ploughing NEW ENTRYP: No DWNER TYPE: Private CONTACT: Nick Croxson 07795 6656 Bell barrow 250 metres NNE of the sports ground: one of a group of round barrows north west Down, Idmiston DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: LIST ENTRY NUMBER: LIST ENTRY NUMBER: Declining RINCIPAL VULNERABILITY: Arable clipping NEW ENTRYP: No DWNER TYPE: Government or agency CONTACT: Nick Croxson 07795 6656 TE NAME: Bell barrow, three bowl barrows and gas testing trenches on Idmiston Down, Idmiston DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014818 Generally unsatisfactory with major localised TREND: Declining	
Bell barrow 250 metres NNE of the sports ground: one of a group of round barrows north west Down, Idmiston Scheduled Monument LIST ENTRY NUMBER: 1013971 Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable clipping Deventment or agency MEW ENTRY?: No CONTACT: Nick Croxson 07795 6656 TREND: Declining NEW ENTRY?: No CONTACT: Nick Croxson 07795 6656 TREND: Down, Idmiston DESIGNATION: Scheduled Monument DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014818 Generally unsatisfactory with major localised TREND: Declining	
Bell barrow 250 metres NNE of the sports ground: one of a group of round barrows north west Down, Idmiston Designation: Scheduled Monument Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable clipping New Entry?: Government or agency CONTACT: Nick Croxson 07795 6656 Designation: Designation: Scheduled Monument Designation: Scheduled Monument Designation: D	
Down, Idmiston Designation: Scheduled Monument Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable clipping Deventment or agency Mo CONTACT: Declining NEW ENTRY?: No CONTACT: Nick Croxson 07795 6656 Designation: Designation: Scheduled Monument Designation:	45
Generally unsatisfactory with major localised problems RINCIPAL VULNERABILITY: Arable clipping New Entry?: No CONTACT: Nick Croxson 07795 6656 TREND: Declining New Entry?: No CONTACT: Nick Croxson 07795 6656 TREND: Declining No LIST ENTRY NUMBER: 1014818 Generally unsatisfactory with major localised TREND: Declining Declining	of Idmist
problems Principal Vulnerability: Arable clipping New Entry?: No Contact: Nick Croxson 07795 6656 The Name: Bell barrow, three bowl barrows and gas testing trenches on Idmiston Down, Idmiston Designation: Scheduled Monument Condition: Generally unsatisfactory with major localised TREND: Decliping	
Government or agency CONTACT: Nick Croxson 07795 6656 Bell barrow, three bowl barrows and gas testing trenches on Idmiston Down, Idmiston DESIGNATION: Scheduled Monument CONTACT: Nick Croxson 07795 6656 LIST ENTRY NUMBER: 1014818 CONDITION: Declining	
Bell barrow, three bowl barrows and gas testing trenches on Idmiston Down, Idmiston DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014818 Generally unsatisfactory with major localised TREND: Declining	
Scheduled Monument LIST ENTRY NUMBER: 1014818 CONDITION: Generally unsatisfactory with major localised TREND: Declining	45
Generally unsatisfactory with major localised TREND: Declining	
RINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No	
OWNER TYPE: Government or agency CONTACT: Nick Croxson 07795 6656	,45
Bowl barrow 260 metres SSE of the southern corner of Moll Harris's Clump: one of a group of robarrows on Porton Down, Idmiston	ound
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014096	
Generally unsatisfactory with major localised TREND: Declining problems	
RINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No	
OWNER TYPE: Government or agency CONTACT: Nick Croxson 07795 6656	,45
Bowl barrow 440 metres SSW of the southern corner of Moll Harris's Clump: one of a group of a barrows on Porton Down, Idmiston	round
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014094	
Generally unsatisfactory with major localised TREND: Declining problems	
RINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No	,45
	round
Bowl barrow 530 metres SSW of the southern corner of Moll Harris's Clump; one of a group of the	
DWNER TYPE: Government or agency CONTACT: Nick Croxson 07795 6656 Bowl barrow 530 metres SSW of the southern corner of Moll Harris's Clump: one of a group of its page.	
Government or agency CONTACT: Nick Croxson 07795 6656 Bowl barrow 530 metres SSW of the southern corner of Moll Harris's Clump: one of a group of a barrows on Porton Down, Idmiston	
Government or agency CONTACT: Nick Croxson 07795 6656 Bowl barrow 530 metres SSW of the southern corner of Moll Harris's Clump: one of a group of a barrows on Porton Down, Idmiston Scheduled Monument CONTACT: Nick Croxson 07795 6656 LIST ENTRY NUMBER: 1014092 CONDITION: Generally unsatisfactory with major localised TREND: Declining	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

HERITAGE AT RISK 2020 / SOU	ITH WEST / WILTSHIRE (UA)		
SITE NAME:	Bowl barrow 535 metres SSW of the southern of barrows on Porton Down, Idmiston	corner of Moll Harris'	s Clump: one of a group of round
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014093
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bronze Age enclosure and two bowl barrows 52 Down, Idmiston	20 metres north east o	of Moll Harris's Clump on Idmiston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014819
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Long barrow 140 metres WSW of the Battery F	Hill triangulation point	, Idmiston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014089
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Saucer barrow 400 metres north east of the spo Idmiston Down, Idmiston	orts ground: one of a g	group of round barrows north west of
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013970
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Two bowl barrows 265 metres south of the sou round barrows on Porton Down, Idmiston	thern corner of Moll	Harris's Clump: part of a group of
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014095
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Two disc barrows and two bowl barrows 900 m	etres north of Moll H	larris's Clump on Idmiston Down,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015557
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Bowl barrow on Keysley Down, 250 metres west of Deverill	of the A350 Warmi	inster-Shaftesbury Road, Kingston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013877
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Moated site and fishponds south east of Rowden F	arm, Lacock	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1013876
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Settlement west of Latton, Latton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004689
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Mineral extraction/related subsidence	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Medieval pottery kilns, Milford Farm, Laverstock		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003252
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bell barrow on Rook Hill, 200 metres west of Pert	wood Wood, Long	bridge Deverill
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010470
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Two saucer barrows 775 metres south east of Roo	lmead Farm, Maide	n Bradley with Yarnfield
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017697
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Town defences, Malmesbury		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1004681
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
OWNER TYPE:	Religious organisation	CONTACT:	Nick Croxson 07795 665645

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet
- implemented.

 C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Scheduled Monument Generally unsatisfactory with major localised problems Arable clipping Arable clipping Arable clipping Arable clipping Arable clipping Arable clipping Arable ploughing Arable	SITE NAME:	Bowl barrow 190 metres north east of Burton Far	m, Mere	
problems RRCEAR WANDERSHIPS Angle clipping AND GERT IN COMM CONTACT Nick Croxson 07795 665645 ILL NAME Black Field Roman site, Mildenhall Basicharicon Scheduled Monument, part in CA LISTENIET NUMBER Black Field Roman site, Mildenhall Basicharicon Scheduled Monument, part in CA LISTENIET NUMBER BLOODFORD Extensive significant problems TICAC CONTACT Nick Croxson 07795 665645 ILL NAME Company CONTACT Nick Croxson 07795 665645 ILL NAME Compon Forest Hill, Mildenhall / Savernake / Marlborough CONTACT Nick Croxson 07795 665645 ILL NAME Compon Forest Hill, Mildenhall / Savernake / Marlborough CONTACT Nick Croxson 07795 665645 ILL NAME Compon Forest Hill, Mildenhall / Savernake / Marlborough CONTACT Commercial company CONTACT Nick Croxson 07795 665645 ILL NAME COMPONION Scheduled Monument LISTENIET NICK Commercial company, multiple owners CONTACT Nick Croxson 07795 665645 INFORMATION COMPONION	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017711
CONTROL NICK Crosson 07795 665645 TENAME Black Field Roman site, Mildenhall SCHONDTON Scheduled Monument, part in CA LETENTRY NUMBER DOWNER 1779 CONTROL Anable ploughing NEW MILTON Scheduled Monument Extensive significant problems TRANCE Commercial company CONTROL Commercial company CONTROL Commercial company CONTROL Nick Crosson 07795 665645 TRANCE Commercial company CONTROL Nick Crosson 07795 665645 TRANCE Commercial company CONTROL Commercial company CONTROL Commercial company CONTROL Commercial company CONTROL Commercial company Nove MILTON Anable ploughing NEW MILTON Commercial company, multiple owners CONTROL Nick Crosson 07795 665645 TRANCE CONTROL CONTROL	CONDITION:		TREND:	Declining
Black Field Roman site, Mildenhall Scheduled Monument, part in CA UST DITAY NUMBER Declining MINCHAULUKKABUTY Arabie ploughing NOW CHTYTY: Commercial company COMMATTYC: Commercial company Commercial company Commercial company Commercial company Commercial company Declining MINCHAULUKKABUTY Arabie ploughing NEW STRING No COMMATTYC: No Commercial company, multiple owners Commercial company Commercial company Commercial company Commercial company Commercial company Commercial company Com	PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
Scheduled Monument, part in CA LET ENTEY NUMBER Declining Arable ploughing Arabl	OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645
Extensive significant problems TREND: Declining Arable ploughing NEWERLEY: Arable ploughing NEWERLEY: Arable ploughing NEWERLEY: Arable ploughing NEWERLEY: Nick Crosson 07795 665645 STENAMEL Camp on Forest Hill, Mildenhall / Savernake / Mariborough DESIGNATION Scheduled Monument UST ENTIFY NAMES: 1004697 CONTRACT: Nick Crosson 07795 665645 SCHEDING Scheduled Monument UST ENTIFY NAMES: 1004697 CONTRACT: Nick Crosson 07795 665645 STENAME: Bowl barrow 200 metres north east of Everleigh Ashes, Milton Lilbourne Scheduled Monument UST ENTIFY NAMES: 1009543 CONDITION Problems Scheduled Monument UST ENTIFY NAMES: 1009543 CONDITION Problems Arable clipping New ENTIFY: No CONTRACT: Nick Crosson 07795 665645 STENAME: Roman tile and brick kiln site 1000 yards (900 metres) west of Tidling Corner, Minety CONDITION Private Roman tile and brick kiln site 1000 yards (900 metres) west of Tidling Corner, Minety CONDITION Extensive significant problems TREND: Stable CONDITION Extensive significant problems TREND: Stable CONDITION Extensive significant problems TREND: Stable CONTRACT: Nick Crosson 07795 665645 STENAME: No CONTR	SITE NAME:	Black Field Roman site, Mildenhall		
Arable ploughing NEWENTRY: No COMMERTYTE Commercial company CONTACT: Nick Croxson 07795 665645 STEINAME: Camp on Forest Hill, Mildenhall / Savernake / Marlborough Scheduled Monument UST DITAYNUMBER: 1004697 CONDITION: Scheduled Monument UST DITAYNUMBER: 1004697 CONDITION: Extensive significant problems IREND: Declining NEWENTRY: No COMMERTYTE Commercial company, multiple owners CONTACT: Nick Croxson 07795 665645 SITE NAME: Bowl barrow 200 metres north east of Everleigh Ashes, Milton Lilbourne DESIGNATION: Scheduled Monument UST PRITAYNUMBER: 1009543 Generally satisfactory but with significant localised problems PRINCIPAL VUINEABRUITY: Arable clipping NEW ENTRY: No CONTACT: Nick Croxson 07795 665645 SITE NAME: Roman tile and brick kiln site 1000 yards (900 metres) west of Tidling Corner, Minety DESIGNATION: Scheduled Monument UST DITAYNUMBER: 1004702 EXTENSIVE Extensive significant problems TREND: Stable PRINCIPAL VUINEABRUITY: No CONTACT: Nick Croxson 07795 665645 SITE NAME: Roman tile and brick kiln site 1000 yards (900 metres) west of Tidling Corner, Minety DESIGNATION: Scheduled Monument UST DITAYNUMBER: 1004702 EXTENSIVE Extensive significant problems TREND: Stable PRINCIPAL VUINEABRUITY: No CONTACT: Nick Croxson 07795 665645 SITE NAME: Private Contract: Nick Croxson 07795 665645 SITE NAME: Private CONTRACT: Nick Croxson 07795 665645 SITE NAME: Private Library Without DESIGNATION: Scheduled Monument UST DITAYNUMBER: 1018899 CONNERTYTE: No CONTRACT: Nick Croxson 07795 665645 SITE NAME: Bowl barrow: one of a group of dispersed barrows south east of Norton Plantation, Norton Bavant DESIGNATION: Scheduled Monument UST DITAYNUMBER: 1009830 CONTRACT: Nick Croxson 07795 665645 SITE NAME: Bowl barrow: one of a group of dispersed barrows south east of Norton Plantation, Norton Bavant DESIGNATION: Scheduled Monument UST DITAYNUMBER: 1009830 CONTRACT: Nick Croxson 07795 665645 SITE NAME: Bowl barrow on the south side of Cotley Hill, Norton SCHEDURAL VUINEABRUITY: No CONTRACT: Nick Croxs	DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1004726
COMMERTYPE Commercial company COMMERTYPE Commercial company COMMERTYPE COMMER	CONDITION:	Extensive significant problems	TREND:	Declining
Camp on Forest Hill, Mildenhall / Savernake / Mariborough Designation: Scheduled Monument Extensive significant problems Extensive significant problems Extensive significant problems Extensive significant problems Designation: New Entert: Nick Croxson 07795 665645 Designation: Scheduled Monument Designation: Scheduled Mo	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Scheduled Monument LET ENTRY NUMBER CONDITION Extensive significant problems REND CONTROL Arable ploughing Mew ENTRY: No CONTROL	OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
Extensive significant problems TREND Declining Remicipal Vulnerability: Arable ploughing New Entry: No Declining Remicipal vulnerability: Arable ploughing New Entry: No Declining Development Virie: Commercial company, multiple owners CONTACT: Nick Crosson 07795 665645 Declining Declining Declining Declining Declining Declining Declining New Entry: Nick Crosson 07795 665645 Declining Decli	SITE NAME:	Camp on Forest Hill, Mildenhall / Savernake / Marl	borough	
Arable ploughing NEW ENTRY: No DOWNER TYPE: Commercial company, multiple owners CONTACT: Nick Croxson 07795 665645 SITE NAME Bowl barrow 200 metres north east of Everleigh Ashes, Milton Lilbourne DEBIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009543 CONDITION: Generally satisfactory but with significant localised problems RENCIPAL VULNERABILITY: Arable clipping NEW ENTRY: No DOWNER TYPE: Private CONTACT: Nick Croxson 07795 665645 SITE NAME Roman tile and brick kiln site 1000 yards (900 metres) west of Tidling Corner, Minety DEBIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004702 EXTENSIVE VULNERABILITY: Arable ploughing NEW ENTRY: No DEBIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004702 DEBIGNATION: Arable ploughing NEW ENTRY: No DOWNER TYPE: Private CONTACT: Nick Croxson 07795 665645 SITE NAME: Private CONTACT: Nick Croxson 07795 665645 SITE NAME: Barly medieval settlement, palace, church and Bronze Age ring ditches 340 metres east of Cowage Farm, Norton / St. Paul Malmesbury Without DEBIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1018389 CONDITION: Extensive significant problems TREND: Unknown PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No DOWNER TYPE: Mixed, multiple owners CONTACT: Nick Croxson 07795 665645 SITE NAME: Bowl barrow: one of a group of dispersed barrows south east of Norton Plantation, Norton Bavant DEBIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009830 CONNERT TYPE: Bowl barrow: one of a group of dispersed barrows south east of Norton Plantation, Norton Bavant DEBIGNATION: Scheduled Monument LIST ENTRY NUMBER: No DOWNER TYPE: Government or agency CONTACT: Nick Croxson 07795 665645 STE NAME: Round barrow on the south side of Cotley Hill, Norton Bavant DEBIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009835 DOWNER TYPE: Government or agency CONTACT: Nick Croxson 07795 665645 STE NAME: Round barrow on the south side of Cotley Hill, Norton Bavant DEBIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009835 DEBIGNATION: Scheduled Monument LIST E	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004697
CONTACT: Nick Croxson 07795 665645 Bowl barrow 200 metres north east of Everleigh Ashes, Milton Lilibourne DESIGNATION. Scheduled Monument UST ENTRY NUMBER: 1009543 CONDITION: Generally satisfactory but with significant localised problems PRENCIPAL VULNERABILITY: Arable clipping NEW ENTRY: No DOWNER TYPE: Private CONTACT: Nick Croxson 07795 665645 STE NAME: Roman tile and brick kiln site 1000 yards (900 metres) west of Tidling Corner, Minety DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004702 CONDITION: Extensive significant problems TREND: Stable PRENCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No DOWNER TYPE: Private CONTACT: Nick Croxson 07795 665645 STE NAME: Barly medieval settlement, palace, church and Bronze Age ring ditches 340 metres east of Cowage Farm, Norton / Sc. Paul Malmesbury Without DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1018389 CONDITION: Extensive significant problems TREND: Unknown PRENCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No DOWNER TYPE: Bowl barrow: one of a group of dispersed barrows bouth east of Norton Plantation, Norton Bavant DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1009830 CONDITION: Extensive significant problems TREND: Stable Bowl barrow: one of a group of dispersed barrows bouth east of Norton Plantation, Norton Bavant DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1009830 CONDITION: Extensive significant problems TREND: Stable PRENCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No CONDITION: Extensive significant problems TREND: Declining DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1009835 STE NAME: Round barrow on the south side of Cotley Hill, Norton Bavant DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1009835 DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1009835 DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1009835	CONDITION:	Extensive significant problems	TREND:	Declining
Bowl barrow 200 metres north east of Everleigh Ashes, Milton Lilbourne DESIGNATION: Scheduled Monument Generally satisfactory but with significant localised problems TREND: Unknown DESIGNATION: Arable clipping NEW ENTRY: No DOWNER TYPE: Private CONTACT: Nick Croxson 07795 665645 SITE NAME: Roman tile and brick kiln site 1000 yards (900 metres) west of Tidling Corner, Minety DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004702 CONDITION: Extensive significant problems TREND: Stable PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Private CONTACT: Nick Croxson 07795 665645 SITE NAME: Early medieval settlement, palace, church and Bronze Age ring ditches 340 metres east of Cowage Farm, Norton / St. Paul Malmesbury Without Scheduled Monument LIST ENTRY NUMBER: 10 18389 CONDITION: Scheduled Monument LIST ENTRY NUMBER: 10 18389 CONDITION: Extensive significant problems TREND: Unknown PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Mixed, multiple owners CONTACT: Nick Croxson 07795 665645 SITE NAME: Bowl barrow: one of a group of dispersed barrows south east of Norton Plantation, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009830 CONDITION: Extensive significant problems TREND: Stable PRINCIPAL VULNERABILITY: No OWNER TYPE: No CONTACT: Nick Croxson 07795 665645 SITE NAME: Bowl barrow: one of a group of dispersed barrows south east of Norton Plantation, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009830 CONDITION: Extensive significant problems TREND: Stable REND: No OWNER TYPE: No CONTACT: Nick Croxson 07795 665645 SITE NAME: Round barrow on the south side of Cotley Hill, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009835 LIST NAME: ROUNT NUMBER: 1009835 SITE NAME: ROUNT NUMBER: 1009835	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Scheduled Monument UST ENTRY NUMBER: 1009543 Generally satisfactory but with significant localised problems RRINGIPAL VULNERABILITY: Arable clipping MEWENTRY: No OWNER TYPE: Private CONTACT: Nick Croxson 07795 665645 SITE NAME: Roman tile and brick kiln site 1000 yards (900 metres) west of Tidling Corner, Minety DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004702 CONDITION: Extensive significant problems TREND: Stable RRINGIPAL VULNERABILITY: Arable ploughing NEWENTRY: No OWNER TYPE: Private CONTACT: Nick Croxson 07795 665645 SITE NAME: Barly medieval settlement, palace, church and Bronze Age ring ditches 340 metres east of Cowage Farm, Norton / St. Paul Malmesbury Without DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1018389 CONDITION: Extensive significant problems TREND: Unknown RRINGIPAL VULNERABILITY: No OWNER TYPE: No OWNER TYPE: No OWNER TYPE: No OWNER TYPE: Mixed, multiple owners CONTACT: Nick Croxson 07795 665645 SITE NAME: Bowl barrow: one of a group of dispersed barrows south east of Norton Plantation, Norton Bavant DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1009830 CONTACT: Nick Croxson 07795 665645 SITE NAME: Bowl barrow: one of a group of dispersed barrows south east of Norton Plantation, Norton Bavant DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1009830 CONTACT: Nick Croxson 07795 665645 SITE NAME: Bowl barrow: one of a group of dispersed barrows south east of Norton Plantation, Norton Bavant DESIGNATION: Scheduled Monument UST ENTRY NUMBER: No OWNER TYPE: No OW	OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Nick Croxson 07795 665645
Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Arable clipping RINGUINE TYPE: Private Roman tile and brick kiln site 1000 yards (900 metres) west of Tidling Corner, Minety DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004702 CONDITION: Extensive significant problems REND: Stable RRINGIPAL VULNERABILITY: Arable ploughing NIW INTERY: No CONTACT: Nick Croxson 07795 665645 STE NAME: Rary medieval settlement, palace, church and Bronze Age ring ditches 340 metres east of Cowage Farm, Norton / St. Paul Malmesbury Without DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1018389 CONDITION: Extensive significant problems RRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No CONTACT: Nick Croxson 07795 665645 STE NAME: Barly medieval settlement, palace, church and Bronze Age ring ditches 340 metres east of Cowage Farm, Norton / St. Paul Malmesbury Without Scheduled Monument UST ENTRY NUMBER: 1018389 CONDITION: Extensive significant problems RRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Mixed, multiple owners CONTACT: Nick Croxson 07795 665645 STE NAME: Bowl barrow: one of a group of dispersed barrows south east of Norton Plantation, Norton Bavant DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1009830 CONDITION: Extensive significant problems REND: No OWNER TYPE: No Government or agency CONTACT: Nick Croxson 07795 665645 STE NAME: Round barrow on the south side of Cotley Hill, Norton Bavant DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1009835 EXTENAME: Round barrow on the south side of Cotley Hill, Norton Extensive significant problems TREND: Declining RRINCIPAL VULNERABILITY: Arable ploughing RRINCIPAL VULNERABILITY: Arable ploughing RRINCIPAL VULNERABILITY: Arable ploughing RRINCIPAL VULNERABILITY: No	SITE NAME:	Bowl barrow 200 metres north east of Everleigh A	shes, Milton Lilbou	rne
PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRYP: No DOWNER TYPE: Private CONTACT: Nick Croxson 07795 665645 SETE NAME: Roman tile and brick kiln site 1000 yards (900 metres) west of Tidling Corner, Minety DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004702 CONDITION: Extensive significant problems TREND: Stable PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No DOWNER TYPE: Private CONTACT: Nick Croxson 07795 665645 SETE NAME: Early medieval settlement, palace, church and Bronze Age ring ditches 340 metres east of Cowage Farm, Norton / St. Paul Malmesbury Without Scheduled Monument LIST ENTRY NUMBER: 1018389 CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1018389 CONDITION: Extensive significant problems TREND: Unknown PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No DOWNER TYPE: Mixed, multiple owners CONTACT: Nick Croxson 07795 665645 SETE NAME: Bowl barrow: one of a group of dispersed barrows south east of Norton Plantation, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009830 EXTENSIVE Spring NEW ENTRYP: No CONTACT: Nick Croxson 07795 665645 SETE NAME: Bowl barrow on the south side of Cotley Hill, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009835 EXTENSIVE ROUND BOWNER TYPE: Government or agency CONTACT: Nick Croxson 07795 665645 SETE NAME: Round barrow on the south side of Cotley Hill, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009835 EXTENSIVE ROUND BOWNER TYPE: No CONTACT: Nick Croxson 07795 665645 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009835 EXTENSIVE ROUND BOWNER TYPE: No CONTACT: Nick Croxson 07795 665645 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009835 EXTENSIVE ROUND BOWNER ENTRYP: No CONTACT: Nick Croxson 07795 665645 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009835	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009543
Private Roman tile and brick kiln site 1000 yards (900 metres) west of Tidling Corner, Minety Scheduled Monument LIST ENTRY NUMBER 1004702 CONDITION: Scheduled Monument LIST ENTRY NUMBER 1004702 CONDITION: Extensive significant problems TREND: Stable PRINCIPAL YULNERABILITY: Arable ploughing NEW ENTRY! No DWNER TYPE: Private CONTACT: Nick Croxson 07795 665645 SETENAME: Early medieval settlement, palace, church and Bronze Age ring ditches 340 metres east of Cowage Farm, Norton / St. Paul Malmesbury Without Scheduled Monument LIST ENTRY NUMBER: 1018389 CONDITION: Extensive significant problems TREND: Unknown PRINCIPAL YULNERABILITY: Arable ploughing NEW ENTRY! No DWNER TYPE Mixed, multiple owners CONTACT: Nick Croxson 07795 665645 SETENAME: Bowl barrow: one of a group of dispersed barrows south east of Norton Plantation, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009830 CONDITION: Extensive significant problems TREND: Stable CONDITION: Extensive significant problems TREND: Stable CONDITION: Extensive significant problems TREND: No OWNER TYPE: Government or agency CONTACT: Nick Croxson 07795 665645 SETENAME: Round barrow on the south side of Cotley Hill, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009835 SETENAME: Round barrow on the south side of Cotley Hill, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009835 SETENAME: Round barrow on the south side of Cotley Hill, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009835 EXERNATE ROUND BAVENTEY: No DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009835	CONDITION:		TREND:	Unknown
Roman tile and brick kiln site 1000 yards (900 metres) west of Tidling Corner, Minety Scheduled Monument LIST ENTRY NUMBER: 1004702 Extensive significant problems TREND: Stable FRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No DOWNER TYPE: Private CONTACT: Nick Croxson 07795 665645 SETE NAME: Early medieval settlement, palace, church and Bronze Age ring ditches 340 metres east of Cowage Farm, Norton / St. Paul Malmesbury Without LIST ENTRY NUMBER: 1018389 EXCONDITION: Scheduled Monument LIST ENTRY NUMBER: Unknown FRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No DOWNER TYPE: Mixed, multiple owners CONTACT: Nick Croxson 07795 665645 SETE NAME: Bowl barrow: one of a group of dispersed barrows south east of Norton Plantation, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009830 EXTENDIBLE Bowl barrow: one of a group of dispersed barrows south east of Norton Plantation, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009830 EXTENDIBLE Bowl barrow: one of a group of dispersed barrows South east of Norton Plantation, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009830 EXTENDIBLE Government or agency CONTACT: Nick Croxson 07795 665645 SETE NAME: Round barrow on the south side of Cotley Hill, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009835 EXTENDIBLE ROUND Bavant LIST ENTRY NUMBER: 1009835 EXTENDIBLE ROUND Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009835 EXTENDIBLE ROUND Bavant LIST ENTRY NUMBER: 1009835 EXTENDIBLE ROUND Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009835 EXTENDIBLE ROUND Bavant LIST ENTRY NUMBER: 1009835 EXTEND: DEClining	PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004702 CONDITION: Extensive significant problems TREND: Stable PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY): No OWNER TYPE: Private CONTACT: Nick Croxson 07795 665645 SITE NAME: Early medieval settlement, palace, church and Bronze Age ring ditches 340 metres east of Cowage Farm, Norton / St. Paul Malmesbury Without DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1018389 CONDITION: Extensive significant problems TREND: Unknown PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY): No OWNER TYPE: Mixed, multiple owners CONTACT: Nick Croxson 07795 665645 SITE NAME: Bowl barrow: one of a group of dispersed barrows south east of Norton Plantation, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009830 CONDITION: Extensive significant problems TREND: Stable PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY): No OWNER TYPE: Government or agency CONTACT: Nick Croxson 07795 665645 SITE NAME: Round barrow on the south side of Cotley Hill, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009835 EXTENAME: Round barrow on the south side of Cotley Hill, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009835 EXTENAME: Round barrow on the south side of Cotley Hill, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009835 EXTENAME: Round barrow on the south side of Cotley Hill, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009835 EXTENDED: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY): No	OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
Extensive significant problems TREND: Stable PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No CONTACT: Nick Croxson 07795 665645 SITE NAME: Early medieval settlement, palace, church and Bronze Age ring ditches 340 metres east of Cowage Farm, Norton / St. Paul Malmesbury Without DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1018389 CONDITION: Extensive significant problems TREND: Unknown PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Mixed, multiple owners CONTACT: Nick Croxson 07795 665645 SITE NAME: Bowl barrow: one of a group of dispersed barrows south east of Norton Plantation, Norton Bavant DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1009830 CONDITION: Extensive significant problems TREND: Stable PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Government or agency CONTACT: Nick Croxson 07795 665645 SITE NAME: Round barrow on the south side of Cotley Hill, Norton Bavant DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1009835 EXTENAME: Round barrow on the south side of Cotley Hill, Norton Bavant DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1009835 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	SITE NAME:	Roman tile and brick kiln site 1000 yards (900 met	res) west of Tidling	Corner, Minety
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No CONTACT: Nick Croxson 07795 665645 Early medieval settlement, palace, church and Bronze Age ring ditches 340 metres east of Cowage Farm, Norton / St. Paul Malmesbury Without Estensive significant problems TREND: Unknown PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No CONTACT: Nick Croxson 07795 665645 ESTE NAME: Bowl barrow: one of a group of dispersed barrows south east of Norton Plantation, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009830 CONDITION: Extensive significant problems TREND: Stable PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No CONDITION: Extensive significant problems TREND: No CONTACT: Nick Croxson 07795 665645 ESTE NAME: Bowl barrow on the south side of Cotley Hill, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009830 CONTACT: Nick Croxson 07795 665645 ESTE NAME: Round barrow on the south side of Cotley Hill, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009835 ESTE NAME: Round barrow on the south side of Cotley Hill, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009835 EXTENSIVE Significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009835 EXTENSIVE Significant problems REND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004702
Private CONTACT: Nick Croxson 07795 665645 Early medieval settlement, palace, church and Bronze Age ring ditches 340 metres east of Cowage Farm, Norton / St. Paul Malmesbury Without DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1018389 CONDITION: Extensive significant problems TREND: Unknown PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No DOWNER TYPE: Mixed, multiple owners CONTACT: Nick Croxson 07795 665645 SITE NAME: Bowl barrow: one of a group of dispersed barrows south east of Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009830 CONDITION: Extensive significant problems TREND: Stable PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Government or agency CONTACT: Nick Croxson 07795 665645 SITE NAME: Round barrow on the south side of Cotley Hill, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009835 SITE NAME: Round barrow on the south side of Cotley Hill, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009835 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	CONDITION:	Extensive significant problems	TREND:	Stable
Early medieval settlement, palace, church and Bronze Age ring ditches 340 metres east of Cowage Farm, Norton / St. Paul Malmesbury Without DESIGNATION: Scheduled Monument Extensive significant problems TREND: Unknown PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Bowl barrow: one of a group of dispersed barrows south east of Norton Plantation, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: I 009830 CONDITION: Extensive significant problems TREND: Stable PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Government or agency CONTACT: Nick Croxson 07795 665645 No OWNER TYPE: Government or agency CONTACT: Nick Croxson 07795 665645 TREND: Stable Round barrow on the south side of Cotley Hill, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009835 TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Norton / St. Paul Malmesbury Without DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1018389 CONDITION: Extensive significant problems TREND: Unknown PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Mixed, multiple owners CONTACT: Nick Croxson 07795 665645 STE NAME: Bowl barrow: one of a group of dispersed barrows south east of Norton Plantation, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009830 CONDITION: Extensive significant problems TREND: Stable PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Government or agency CONTACT: Nick Croxson 07795 665645 STE NAME: Round barrow on the south side of Cotley Hill, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009835 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009835 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
Extensive significant problems TREND: Unknown PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Mixed, multiple owners CONTACT: Nick Croxson 07795 665645 SITE NAME: Bowl barrow: one of a group of dispersed barrows south east of Norton Plantation, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009830 CONDITION: Extensive significant problems TREND: Stable PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Government or agency CONTACT: Nick Croxson 07795 665645 SITE NAME: Round barrow on the south side of Cotley Hill, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009835 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	SITE NAME:	Early medieval settlement, palace, church and Bron Norton / St. Paul Malmesbury Without	ze Age ring ditches	340 metres east of Cowage Farm,
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Mixed, multiple owners CONTACT: Nick Croxson 07795 665645 SITE NAME: Bowl barrow: one of a group of dispersed barrows south east of Norton Plantation, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009830 CONDITION: Extensive significant problems TREND: Stable PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Government or agency CONTACT: Nick Croxson 07795 665645 SITE NAME: Round barrow on the south side of Cotley Hill, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009835 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018389
Mixed, multiple owners CONTACT: Nick Croxson 07795 665645 Bowl barrow: one of a group of dispersed barrows south east of Norton Plantation, Norton Bavant DESIGNATION: Scheduled Monument Extensive significant problems TREND: Stable PRINCIPAL VULNERABILITY: Arable ploughing Round barrow on the south side of Cotley Hill, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: No CONTACT: Nick Croxson 07795 665645 Round barrow on the south side of Cotley Hill, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009835 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	CONDITION:	Extensive significant problems	TREND:	Unknown
Bowl barrow: one of a group of dispersed barrows south east of Norton Plantation, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009830 CONDITION: Extensive significant problems TREND: Stable PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Government or agency CONTACT: Nick Croxson 07795 665645 SITE NAME: Round barrow on the south side of Cotley Hill, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009835 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009830 CONDITION: Extensive significant problems TREND: Stable PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No CONTACT: Nick Croxson 07795 665645 SITE NAME: Round barrow on the south side of Cotley Hill, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009835 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645
Extensive significant problems TREND: Stable Arable ploughing New Entry?: No CONTACT: Nick Croxson 07795 665645 Round barrow on the south side of Cotley Hill, Norton Bavant DESIGNATION: Scheduled Monument Extensive significant problems TREND: Declining New Entry?: No	SITE NAME:	Bowl barrow: one of a group of dispersed barrows	south east of Nor	ton Plantation, Norton Bavant
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No CONTACT: Nick Croxson 07795 665645 SITE NAME: Round barrow on the south side of Cotley Hill, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: LOO9835 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009830
Government or agency CONTACT: Nick Croxson 07795 665645 Round barrow on the south side of Cotley Hill, Norton Bavant DESIGNATION: Scheduled Monument Extensive significant problems CONTACT: Nick Croxson 07795 665645 Round barrow on the south side of Cotley Hill, Norton Bavant LIST ENTRY NUMBER: 1009835 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: No	CONDITION:	Extensive significant problems	TREND:	Stable
Round barrow on the south side of Cotley Hill, Norton Bavant DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009835 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009835 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	SITE NAME:	Round barrow on the south side of Cotley Hill, No	orton Bavant	
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009835
1 3 3	CONDITION:	Extensive significant problems	TREND:	Declining
OWNER TYPE: Government or agency CONTACT: Nick Croxson 07795 665645	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
	OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

HERITAGE AT RISK 2020 / SOU	JTH WEST / WILTSHIRE (UA)		
SITE NAME:	Barrow on Coombe Down, 1070 yards (980 me Andrew	tres) north east of Up	oper Poughcombe, Ogbourne St.
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005670
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bell barrow 200 metres north of Rockley Planta	tion, Ogbourne St. Ar	ndrew
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012195
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 375 metres east of Wick Bottom	Barn, Ogbourne St. A	ndrew
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015814
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 630 metres north east of Wick Bo	ttom Barn, Ogbourne	St. Andrew
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015803
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow and a saucer barrow 200 metres n	orth of Rockley Plant	ation, Ogbourne St. Andrew
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1012197
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Round barrow cemetery 320 metres south east	of Down Farm, Pews	еу
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016779
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	The Spectacles, Pewsey		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005638
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Long barrow, Winterbourne, Pitton and Farley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005623
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Moated site 300 metres north east of Potterne F	Park Farm, Potterne	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012152
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bell barrow 350 metres south west of Barbury E	Barn, Preshute	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012190
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 300 metres east of Ivy House Farm	n, Preshute	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012294
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Group of round barrows on Rough Hill, Preshut	e	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003034
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Preshute Down field system, Preshute		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004763
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Sharpridge field system, Preshute		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004764
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Roundway Hill Farm round barrows, Roundway	/ Bishops Cannings	
DESIGNATION:	Scheduled Monument, RB	LIST ENTRY NUMBER:	1004773
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Bowl barrow 450 metres north of Cross Droves,	Shalbourne	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012274
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Long barrow on Smay Down, 300 metres east of T	The Hassock, Shalbo	ourne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010467
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Wansdyke: Daniel's Lane section, Shalbourne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005594
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Great Botley Copse long barrow, and disc barrow	near it, Shalbourne	/ Grafton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005692
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Long barrow 250 metres east of Boyton Field Barr	n, Sherrington / Boy	ton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010520
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Six bowl barrows and two disc barrows forming the west of Fargo Road ammunition compound, Shrew		nd barrow cemetery 300 metres nort
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1009124
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Newton Barrow, South Newton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005687
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

SITE NAME:	Earthwork enclosure on Milk Hill, Stanton St. Be	rnard	
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1004735
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Stapleford Castle, Stapleford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005686
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Barrow north of 'The Spectacles', Steeple Langfo	rd	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004742
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 240 metres east of The Penning, St	eeple Langford	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015025
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Deptford Down round barrow, Steeple Langford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005615
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Little Langford round barrow, north of Upper Fa	rm Down, Steeple La	angford
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005605
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Round barrow 230 yards (210 metres) north we	st of New Field Plant	ation, Steeple Langford
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004725
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bell barrow on Parsonage Down, 1.3 kilometres	south east of Lord's	Hill Farm, Sutton Veny
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016677
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Bowl barrow on Littlecombe Down, Sutton Veny		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005683
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Fosbury camp, Tidcombe and Fosbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005682
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Castle Ditches camp, Tisbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005701
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Casterley Camp and associated monuments, Upavo	on	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010074
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 500 metres south of Upton Scudamo	re, Upton Scudamo	ore
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1010398
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Enclosure and linear earthworks between Bishopst Bishopstrow / Norton Bavant	row Down and So	uth Down Sleight, Warminster /
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010283
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow in The Belt, 350 metres north east of	f Hill Barn, West C	verton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019901
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Bowl barrow 400 metres west of Normanton Gor	se, Wilsford cum L	ake
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010831
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Ten bowl barrows, five disc barrows, a bell barrow Wilsford round barrow cemetery, Wilsford cum L	v, a pond barrow ar ake	nd a saucer barrow forming the
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010874
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Bowl barrow forming part of the Normanton Dow	n round barrow ce	emetery, Wilsford cum Lake / Amesbu
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1009616
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Horse Barrow, Winterbourne / Idmiston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005610
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Bell barrow 450 metres south east of Greenland Fa of the Lesser Cursus, Winterbourne Stoke	arm, forming part o	of a linear round barrow cemetery we
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010899
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Bowl barrow 350 metres north west of Greenland	Farm, Winterbour	ne Stoke
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010892
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Bowl barrow 830 metres south west of Greenland		Shrewton, Winterbourne Stoke
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015217
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CITE NIAME.	Bronze Age enclosure and bowl barrow 100 me	tres west of Longbarr	row Cross Roads on Winterbourne
SITE NAME:	Stoke Down, Winterbourne Stoke		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011048
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Disc barrow and pond barrow 350 metres NNV	V of Greenland Farm	, Winterbourne Stoke
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010891
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bell barrow and bowl barrow 500 metres NNW	of Long Orchard, W	'interslow
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013984
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 750 metres NNE of Easton Down	Farm, Winterslow	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013986
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 175 metres west of Square Copse: Rivers	part of the Square C	opse barrow cemetery, Wootton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013352
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
	Arable ploughing Crown	NEW ENTRY?: CONTACT:	No Nick Croxson 07795 665645
OWNER TYPE:	1 3 8	CONTACT:	Nick Croxson 07795 665645
OWNER TYPE:	Crown Bowl barrow 275 metres west of Square Copse:	CONTACT:	Nick Croxson 07795 665645
OWNER TYPE: SITE NAME: DESIGNATION:	Crown Bowl barrow 275 metres west of Square Copse: Rivers	part of the Square C	Nick Croxson 07795 665645 Topse barrow cemetery, Wootton
OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Crown Bowl barrow 275 metres west of Square Copse: Rivers Scheduled Monument	CONTACT: part of the Square C LIST ENTRY NUMBER:	Nick Croxson 07795 665645 Opse barrow cemetery, Wootton 1013364
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Crown Bowl barrow 275 metres west of Square Copse: Rivers Scheduled Monument Extensive significant problems	CONTACT: part of the Square C LIST ENTRY NUMBER: TREND:	Nick Croxson 07795 665645 Topse barrow cemetery, Wootton 1013364 Declining

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS



© Historic England

SITE NAME:	Tottenham House and Savernake Forest, Savernake / Burbage / Great Bedwyn / Little Bedwyn / Marlborough / Mildenhall
DESIGNATION:	Registered Park and Garden grade II*, 20 LBs, 7 SMs
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	High
TREND:	Improving
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1000472

Extensive landscape of rides linking Savernake Forest with ornamental parkland and pleasure grounds around the house. Exemplifies the work of Burlington, Brown, Cundy and others. Planning permission for hotel development has lapsed. The house and core of the landscape have been sold to a private owner and the process of conservation and repair has begun, allied to major development proposals (application under consideration). The Forestry Commission manages Savernake Forest on a long lease. There is a Natural England Stewardship Scheme over part of the park.

Contact: Jo McAllister 0117 975 0696

WILTSHIRE (UA) / NEW FOREST (NP)				
SITE NAME:	Barrows in Bath Hole and Bury Hill Plantations, I	Redlynch, Wiltshire (UA)	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004754	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645	

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site

This document is one in a series of publications produced as part of Historic England's national Heritage at Risk programme. More information about Heritage at Risk and other titles in the series can be found at HistoricEngland.org.uk/har

Heritage at Risk
Published October 2020
4th Floor, Cannon Bridge House
25 Dowgate Hill
London EC4R 2YA
© Copyright Historic England 2020

Product code: HE0048

