Heritage at **Risk**



South West Register 2021

Contents

The Register	
Content and criteria	III
Key statistics	V
Key to the entries	VI
Entries on the Register by local planning authority	VIII
Bath and North East Somerset (UA)	I
Bournemouth Christchurch and Poole (UA)	3
Bristol, City of (UA)	5
Cornwall (UA)	8
Devon Dartmoor (NP) East Devon Exeter Exmoor (NP) Mid Devon North Devon South Hams Teignbridge Torridge West Devon	48 48 71 76 76 78 81 85 92 94 101
Dorset (UA)	105
Gloucestershire	143
Cheltenham Cotswold Forest of Dean Gloucester Stroud Tewkesbury Isles of Scilly (UA)	143 144 148 150 152 155
North Somerset (UA)	162
Plymouth, City of (UA)	163
Somerset Exmoor (NP) Mendip Sedgemoor Somerset West and Taunton South Somerset South Gloucestershire (UA) Swindon (UA) Torbay (UA)	168 171 177 181 185 190 193 195
Wiltshire (UA)	197

THE REGISTER

The Heritage at Risk Register includes historic buildings and sites at risk of being lost through neglect, decay or deterioration.

It includes all types of designated heritage assets, including Conservation Areas, which are designated and assessed by Local Planning Authorities.

The aim of the Register is to focus attention on those places in greatest need. Historic England, in partnership with others, is able to help tackle heritage at risk. We work with owners, friends groups, developers and other stakeholders to find imaginative solutions for historic places and sites at risk across England.

More information about our role, the advice and funding available, and useful <u>publications</u> and <u>guidance</u> is available on our <u>website</u>.

Criteria for inclusion on the Register

RISK ASSESSMENTS

Heritage assets included on the Register are assessed according to the nature of the site. The risk assessment methodologies outlined below are based on factors which can threaten the different types of heritage assets and lead to them becoming at risk.

BUILDINGS AND STRUCTURES

To be considered for inclusion on the Register, buildings or structures must be:

- listed on the National Heritage List for England; and
- in secular (non-worship) use. And either:
- a grade I or II* listed building, or
- a grade II listed building in London, or
- a structural scheduled monument with upstanding remains.

Buildings or structures are assessed on the basis of condition and, where applicable, occupancy (or use) reflecting the fact that a building which is occupied is generally less vulnerable than one that is not.

Occupancy (or use) is assessed as 'vacant', 'partoccupied', 'occupied', 'not applicable', or occasionally, 'unknown'. Many structures fall into the 'not applicable' category, for example: ruins, walls, gates, headstones or boundary stones.

Condition is assessed as 'very bad', 'poor', 'fair' or 'good'. The condition of buildings or structures on the Register is typically very bad or poor, but can be fair or, very occasionally, good. This reflects the fact that some buildings or structures are vulnerable because they are empty, underused or face redundancy without a new use to secure their future. Assessing vulnerability in the case of buildings in fair condition necessarily involves judgement and discretion. A few buildings remain on the Register in good condition, having been repaired or mothballed, but still awaiting a new use or occupancy.

Buildings or structures are removed from the Register when they are fully repaired/consolidated, and their future secured either through occupation and use, or through the adoption of appropriate management.

PLACES OF WORSHIP

To be considered for inclusion on the Register, places of worship must be listed grade I, grade II* or grade II on the National Heritage List for England, and be used as a public place of worship at least six times a year.

Places of worship are assessed on the basis of condition only. If a place of worship is in very bad or poor condition, it is added to the Register. This includes places of worship which are generally in fair or good condition but have major problems with one key element, like the tower.

Once on the Register, places of worship can move through the condition categories (e.g. from very bad to poor, to fair, even good) as repairs are implemented and the condition improves, until they are fully repaired and can be removed from the Register. This means that there are some places of worship in good condition on the Register but with outstanding issues still to be resolved at the time when they were assessed.

ARCHAEOLOGY

To be considered for inclusion on the Register, archaeological sites must be listed as scheduled monuments and included on the National Heritage List for England.

Archaeology assessments cover scheduled earthworks and buried archaeology.

The risk assessment is based on their condition and vulnerability, the trend in their condition, and their likely future vulnerability. A site's condition is expressed in terms of the scale and severity of adverse effects on it, ranging from 'extensive significant problems' to 'minor localised problems'.

Archaeological entries are removed from the Register once sufficient progress has been made to address the identified issues, and a significant reduction in the level of risk has been demonstrated.

PARKS AND GARDENS

To be considered for inclusion on the Register, parks and gardens must be listed as grade I, grade II* or grade II and included on the National Heritage List for England. Parks and gardens are assessed in terms of condition and vulnerability. Steps being taken by owners to address problems are also taken into consideration.

Parks and gardens assessed as being at risk are typically affected by development and neglect. They have frequently been altered by development or are faced with major change. The original function of these landscapes has often changed and divided ownership leads to the loss of their cohesive historic design.

Park and garden entries are removed from the Register once steps have been taken to address issues and positive progress is being made.

BATTLEFIELDS

To be considered for inclusion on the Register, battlefields must be listed and included on the National Heritage List for England. Battlefields deemed to be at risk of loss of cultural significance are included on the Register.

The principal risks and threats are:

- development pressure e.g. encroachment of buildings;
- pressures of particular use within the site e.g. arable cultivation;
- damage e.g. unregulated metal detecting.

Battlefields are removed from the Register either when damaging activities cease/are managed, or when threats recede due to effective planning.

WRECK SITES

To be considered for inclusion on the Register, wrecks must be listed and included on the National Heritage List for England. Wreck sites are assessed based on their current condition, vulnerability and the way they are being managed.

Wrecks are vulnerable to both environmental and human impacts. Risks that contribute to inclusion on the Register range from unauthorised access to erosion and fishing damage. The monitoring process ensures that the significance of the site is identified and maintained. In spite of the inherent difficulties in caring for this type of site, careful management must be maintained.

Wrecks are removed from the Register once an appropriate management and monitoring regime is operational.

CONSERVATION AREAS

Once a year Historic England asks every local authority in England to consider the state of its conservation areas and fill in (and update as appropriate) risk assessment questionnaires for those that cause concern, or are believed to no longer be at risk.

Conservation areas that are deteriorating, or are in very bad or poor condition and not expected to change significantly in the next three years, are defined as being at risk.

The approach taken to assess conservation areas at risk has been refined since the first survey in 2008/2009. An overall category for condition, vulnerability and trend is included for each conservation area on the Heritage at Risk Register. Conservation areas identified as at risk in 2009, but not reassessed since using the revised methodology, are included on the Register but with limited information.

Conservation areas are removed from the Register once plans have been put in place to address the issues that led to the conservation area being at risk, and once positive progress is being made.

THE EFFECT OF COVID-19 ON THE COLLECTION AND COLLATION OF THE STATISTICS USED FOR THE 2021 REGISTERS

As with last year, the collection of this year's data has been affected by Covid-19. Depending on the region, site visits were either not possible or very limited for both our staff and our local authority colleagues throughout the year. Although the usual level of on-site checking of entries on, additions to and removals from the Register was not possible for a second year, deskbased assessments and updates were carried out.

Key Heritage at Risk Statistics for South West 2021

BUILDINGS AND STRUCTURES

- Of the 22,514 grade I and II* listed buildings (excluding places of worship) in England, 772 (3.4%) are on the Register. Of the 5,323 listed secular buildings in the South West 163 (3.1%) are on the Register.
- In addition to this, of the 6,994 scheduled monuments in the South West, 50 (0.7%) are on the Register assessed as structural scheduled monuments (ie using the buildings or structures methodology).
- 3 building or structure entries (including structural scheduled monuments) have been removed from the previous South West Register (2020) for positive reasons and 8 have been added.

PLACES OF WORSHIP

- Of the 14,785 listed places of worship in England, 923 (6.2%) are on the Register. Of the 2,923 listed places of worship in the South West 144 (4.9%) are on the Register.
- 19 places of worship entries have been removed from the previous South West Register (2020) for positive reasons and 8 have been added.

ARCHAEOLOGY

- Of the 19,923 scheduled monuments in England, 2,001 (10.0%) are on the Register assessed as archaeology. Of the 6,994 scheduled monuments in the South West, 1,015 (14.5%) are on the Register assessed as archaeological.
- 54 archaeology entries have been removed from the previous South West Register (2020) for positive reasons, and 18 have been added.

PARKS AND GARDENS

 Of the 1,696 registered parks and gardens in England 104 (6.1%) are on the Register. Of the 305 registered parks and gardens in the South West, 17 (5.6%) are on the Register. No park and garden entries have been removed for positive reasons or added to the previous South West Register (2020).

BATTLEFIELDS

• Of the 47 registered battlefields in England, 3 (6.4%) are on the Register. None of the 10 registered battlefields in the South West are on the Register.

WRECK SITES

 Of the 54 protected wreck sites around England's coast, 4 (7.4%) are on the Register. None of the 27 protected wreck sites in the South West are on the Register.

CONSERVATION AREAS

- There are 491 conservation areas on the Register. Of these, 20 are in the South West.
- No conservation areas have been removed for positive reasons or added to the previous South West Register (2020).

HISTORIC ENGLAND FUNDING

- £1.49 million in grant was spent on 63 entries (including conservation areas) on the South West Register during 2020/21.
- In addition, £0.84 million of Covid-19 pandemic recovery funding was spent on 2 entries.

Risk assessments of heritage assets are based on the nature of the site. Buildings and structures include structural scheduled monuments and listed buildings (excluding listed places of worship); archaeology assessments include earthworks and buried archaeology. Please note that some sites may have more than one entry under different risk assessment methodologies, for example if a site has more than one listing for its different elements or if it consists of both buried and structural remains.

2020 HAR data as at 12am 12 June 2020 2021 HAR data as at 12 am 19 July 2021

Key to the entries

The Register includes the following risk assessment types:

- Building or structure (grade I and II* listed buildings, grade II listed buildings in London and structural scheduled monuments)
- Place of worship
 - (grade I, II* and II listed buildings)
- Archaeology
 - (scheduled monuments earthworks and buried archaeology)
- Park and garden (Registered parks and gardens)
- Battlefield
 - (Registered battlefields)
- Wreck site
 - (Protected wreck sites)
- Conservation area
 - (Conservation areas)

Details are given here for all risk assessment types even if entries are not present in the Regional Register.

ORDER

Entries are grouped and ordered alphabetically, first by County (dark grey bands) or Unitary Authority (light grey bands), and then by Local Planning Authority (National Park/Unitary Authority/District or Borough).

A blank band denotes the end of a county and the beginning of a unitary authority.

Sites that straddle more than one local planning authority are included under the lead authority.

Within each planning authority, entries are grouped by risk assessment type in the following order:

- Buildings or structures
- Places of worship
- Archaeology
- Parks and gardens
- Battlefields
- Wreck sites
- Conservation areas

Within each risk assessment type, entries are ordered alphabetically by parish, locality and street/site name (except for conservation areas and protected wreck sites which are ordered by site name only).

LISTING

The principal listing type is noted for each entry and includes:

- Listed Building (LB) grade I or II*
- Listed Place of Worship grade I, II* or II
- Scheduled Monument (SM)
- Registered Park and Garden (RPG) grade I, II* or II
- Registered Battlefield (RB)
- Protected Wreck Site (PWS)
- Conservation Area (CA)

Other listing types that apply to a given site, including location within a World Heritage Site (WHS), are also noted.

If an entry is a dual list entry (both listed and scheduled), 'and' rather than a comma is used (eg 'Scheduled Monument and Listed Building grade I'). If a scheduled monument entry is a dual list entry with a number of listed buildings, each is separated by a semicolon.

The National Heritage List Entry Number is included for all entries (except conservation areas). If a site has dual list entries, all relevant List Entry Numbers are noted.

CONDITION

For buildings (including places of worship), condition is graded as: 'very bad', 'poor', 'fair' and 'good'.

For sites that cover areas (scheduled monuments – archaeology assessments, parks and gardens, battlefields and wreck sites) one overall condition category is recorded. The category may relate only to the part of the site or monument that is at risk and not the whole site:

- extensive significant problems
- generally unsatisfactory with major localised problems
- generally satisfactory but with significant localised problems
- generally satisfactory but with minor localised problems
- optimal
- unknown (noted for a number of scheduled monuments that are below-ground and where their condition cannot be established)

For conservation areas, condition is categorised as: 'very bad', 'poor', 'fair' and 'optimal'.

If a site has suffered from heritage crime it is noted in the summary. Heritage crime is defined as any offence which harms the heritage asset or its setting and includes arson, graffiti, lead theft and vandalism.

OCCUPANCY/USE

For buildings (excluding places of worship) that can be occupied or have a use, the main vulnerability is vacancy or under-use. Occupancy (or use) is noted as follows:

- vacant
- part occupied
- occupied
- unknown
- not applicable

VULNERABILITY

Principal vulnerability is noted for archaeology assessments and may relate only to the part of the site that is at risk, and include:

- animal burrowing
- arable ploughing
- coastal erosion
- collapse
- deterioration in need of management
- scrub/tree growth
- visitor erosion

For parks and gardens, battlefields, wreck sites and conservation areas, vulnerability is noted as high, medium or low.

PRIORITY CATEGORY

Priority for action is assessed on a scale of A to F, where 'A' is the highest priority for a site which is deteriorating rapidly with no solution to secure its future, and 'F' is the lowest priority.

For buildings and structures and places of worship the following priority categories are used as an indication of trend and as a means of prioritising action:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented
- C Slow decay; no solution agreed
- D Slow decay; solution agreed but not yet implemented
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
- F Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented

For battlefields and wreck sites the following priority categories are used as a means of prioritising action:

- A No action/strategy identified or agreed (where trend is declining or unknown)
- B Action/strategy agreed but not yet implemented (where trend is declining or unknown)
- C No action/strategy identified or agreed (where trend is stable or improving)
- D Action/strategy agreed but not yet implemented (where trend is stable or improving)
- E Monitoring as appropriate (any trend)
- F Action implemented/strategy underway/scheme in progress (any trend)

Previous year priority categories are given in brackets, otherwise 'New entry' is noted.

'New entry – re-assessed' indicates an existing site on the Register that has been re-assessed using a different risk assessment methodology and is included on this year's Register under the new assessment type.

TREND

Trend for archaeology entries, parks and gardens, battlefields and wreck sites may relate only to the part of the site that is at risk and is categorised as:

- declining
- stable
- improving
- unknown

For conservation areas trend is categorised as:

- deteriorating
- deteriorating significantly
- no significant change
- improving
- improving significantly
- unknown

OWNERSHIP

A principal ownership category is given for each entry, and if sites are in divided ownership, a 'multiple' ownership category is noted.

CONTACT

This is the member of the Historic England local team who acts as a first point of contact for the case, and to whom enquiries should be addressed.

For conservation areas, the contact is the conservation/planning officer at the relevant local planning authority (indicated by 'LPA').

We are not in any sense agents for the owners of the sites included, but we will endeavour to put people in touch with them where appropriate.

- CA Conservation Area
- HE Historic England
- HLF Heritage Lottery Fund
- LB Listed Building
- LPA Local Planning Authority
- NP National Park
- PWS Protected Wreck Site
- RB Registered Battlefield
- RPG Registered Park and Garden
- SM Scheduled Monument
- UA Unitary Authority
- WHS World Heritage Site

Entries on the Register by local planning authority

Local planning authority	Building and structure entries	Place of worship entries	Archaeology entries	Park and garden entries	Battlefield entries	Wreck site entries	Conservation area entries
BATH AND NORTH EAST S	OMERSET (UA)	1		1			
Bath and North East Somerset (UA)	4	0	8	I	0	0	3
BOURNEMOUTH CHRISTC	HURCH AND PO	OLE (UA)					
Bournemouth Christchurch and Poole (UA)	0	4	4	0	0	0	2
BRISTOL, CITY OF (UA)							
Bristol, City of (UA)	8	3	3	0	0	0	1
Bristol, City of (UA) / Bath and North East Somerset (UA) [†]	0	0	0	I	0	0	0
CORNWALL (UA)							
Cornwall (UA)	48	18	182		0	0	
DEVON		1			1		
Dartmoor (NP)	2	3	155	0	0	0	0
East Devon	5	3	20	I	0	0	0
Exeter	0			0		0	0
Exmoor (NP)	0		7	0		0	0
Mid Devon	3		16	0		0	3
North Devon	4		13	0		0	
South Hams	9		21	0		0	0
Teignbridge	2		6	2	0	0	
Torridge	2		33	0		0	0
West Devon	7		10	0		0	0
DORSET (UA)	· ·						_
Dorset (UA)	25	6	230		0	0	2
GLOUCESTERSHIRE		-		-	-		
Cheltenham	0	2	0	0	0	0	0
Cotswold	4	2	20	0	0	0	0
Forest of Dean	4	4	7	0	0	0	0
Gloucester	5	1	0	0	0	0	I
Stroud	5	6	4	0	0	0	2
Tewkesbury	7	2	7	0	0	0	0
ISLES OF SCILLY (UA)				·			
Isles of Scilly (UA)	2	0	30	0	0	0	0
NORTH SOMERSET (UA)							
North Somerset (UA)	3	2	2	0	0	0	0
PLYMOUTH, CITY OF (UA)		-		-	-	-	
Plymouth, City of (UA)	14	1	11	0	0	0	0
SOMERSET							
Exmoor (NP)	2	0	16	0	0	0	0
Mendip	5	12	17	0	0	0	0
Sedgemoor	3	10	12	I	0	0	0
Somerset West and Taunton	6	2	15	I	0	0	I
South Somerset	8	12	4	2	0	0	0
SOUTH GLOUCESTERSHIRE (UA)							
South Gloucestershire (UA)	7	2	3	2	0	0	2
SWINDON (UA)	1	1		1	1		
Swindon (UA)	1	0	11	0	0	0	0
TORBAY (UA)		1					
Torbay (UA)	4	2	2	2	0	0	0
DEVON		1					
Torbay (UA) / South Hams [†]	0	0	0	I	0	0	0
WILTSHIRE (UA)							
Wiltshire (UA)	4	8	144		0	0	0

Local planning authority	Building and structure entries	Place of worship entries	Archaeology entries	Park and garden entries	Battlefield entries	Wreck site entries	Conservation area entries
Wiltshire (UA) / New Forest (NP) [†]	0	0	I	0	0	0	0
TOTAL	213	144	1015	7	0	0	20

 † Sites that cross local planning authority boundaries

BATH AND NORTH EAST SOMERSET (UA)

	, ,	'	
	SITE NAME:	Beckford's Tower, Bath	Beckford's Tower was built by William Beckford in 1826-7
	DESIGNATION:	Listed Building grade I, RPG grade II, CA, WHS	as a personal retreat which functioned both as an observatory and home for his art, furniture and book collections. Between 1997-2000, the tower and lantern
	CONDITION:	Poor	structure underwent a programme of significant structural repairs. There is currently water ingress within the lantern.
	OCCUPANCY:	Vacant/not in use	A Development Grant from the National Lottery Heritage
	PRIORITY CATEGORY:	B (B)	Fund was offered at the end of 2019 and a Historic England Project Development grant was awarded in 2020.
	OWNER TYPE:	Charity (heritage)	
ngland	LIST ENTRY NUMBER:	394 33	Contact: Sarah Ball 0117 975 0666

© Historic Eng




.1	SITE NAME:	King Edward's School, Broad Street, Bath	School dating from 1752. A scheme for hotel use was submitted but withdrawn in 2006. Works to repair the
T	DESIGNATION:	Listed Building grade II*, CA, WHS	roof have been successfully completed. The threat of decay has diminished but the building remains vacant. Permission for hotel use (granted in 2010 and renewed in 2013) has
	CONDITION:	Fair	been implemented and Historic England engaged in further pre-app discussion to explore amendments to consent
	OCCUPANCY:	Vacant/not in use	before comprehensive works begin.
1	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1395027	Contact: Jacqueline Smith 0117 975 0667



© Jim Warren

© Histor



	SITE NAME:	Hinton Priory, Hinton Charterhouse	Early C13 Carthusian monastery, chapter house and refectory still standing. Later stables, coach house and
	DESIGNATION:	Scheduled Monument and Listed Buildings - 3 grade I, LB grade II	garden buildings incorporate earlier material and follow original complex layout of cloister and cells. All structures in use except chapter house, which is the area at risk.
	CONDITION:	Poor	Some parts are in need of a condition assessment.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
oric England	LIST ENTRY NUMBER:	1007014 and 1136191; 1320809; 1129461	Contact: Sarah Ball 0117 975 0666

SITE NAME:	Wansdyke: section 1230 yards (1120 metres) eastwards from Burnt House Inn, Southstoke			
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1007003	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Gardening	NEW ENTRY ?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building Local Planning Authority National Park CA
- LB LPA
- NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / SOUTH WEST / BATH AND NORTH EAST SOMERSET (UA)

SITE NAME:	Camerton Romano-British town and associated pr Radstock	Camerton Romano-British town and associated prehistoric and early medieval monuments, Camerton / Radstock			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013881		
CONDITION:	Extensive significant problems	TREND:	Stable		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Private, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345		
SITE NAME:	Roman road 720 yards (660 metres) long, north of	f Abbey Farm, Hinto	on Charterhouse		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005421		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Commercial company	CONTACT:	Alessandra Perrone 0117 975 1345		
SITE NAME:	Stantonbury camp and adjacent sections of Wansd	yke, Marksbury			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002487		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No		
OWNER TYPE:	Crown	CONTACT:	Alessandra Perrone 0117 975 1345		
SITE NAME:	Lansdown Roman camp, North Stoke				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005422		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345		
SITE NAME:	Little Down camp, North Stoke				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004677		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345		
SITE NAME:	Wansdyke: south east of Newbarn Farm, Norton I	Malreward			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003066		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345		
SITE NAME:	Roman villa at Upper Hayes, Wellow				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007002		
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345		

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / SOUTH WEST / BATH AND NORTH EAST SOMERSET (UA) / BOURNEMOUTH CHRISTCHURCH AND POOLE (UA)

		()	
© Historic England	SITE NAME:	Lansdown Cemetery and Beckford's Tower	A cemetery consecrated in 1848, incorporating features of a former pleasure ground and ride created by William
	DESIGNATION:	Registered Park and Garden grade II, 4 LBs, CA, WHS	Beckford and the architect Henry Edmund Goodridge in c1825-7. Key design features have been neglected and are in declining condition including the Grotto Tunnel. The
	CONDITION:	Generally unsatisfactory with major localised problems	landscape has become fragmented as a result of different ownership. Beckford's Tower (II*) has also been placed at risk. The Beckford Tower Trust have secured funding via
	VULNERABILITY:	Medium	the Natoinal Lottery Heritage Fund (2019) and private
	TREND:	Declining	donation (2021) for restoration works and acquisition of the paddocks and grotto.
	NEW ENTRY?:	No	
	OWNER TYPE:	Charity (heritage)	
	LIST ENTRY NUMBER:	1000563	Contact: Jo McAllister 0117 975 0696

SITE NAME:	Keynsham		
DESIGNATION:	Conservation Area, 53 LBs, SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Adrian Neilson (LPA) 01225 477020
SITE NAME:	Midsomer Norton and Welton, Norton-Radstock		
DESIGNATION:	Conservation Area, 37 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Adrian Neilson (LPA) 01225 477020
SITE NAME:	Paulton (including Paulton Basin)		
DESIGNATION:	Conservation Area, 17 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Adrian Neilson (LPA) 01225 477020

BOURNEMOUTH CHRISTCHURCH AND POOLE (UA)

	SITE NAME:	Church of St John the Evangelist, Christchurch Road, Bournemouth	Flint-clad Victorian church. A Listed Places of Worship Roof Repairs Grant was awarded and stage 1 repairs to the roof and cast-iron rainwater goods completed in 2017. The
	DESIGNATION:	Listed Place of Worship grade II*, CA	west end and tower are also in a poor state, with crumbling stone and falling masonry, and funding is currently sought for this second phase.
	CONDITION:	Poor	
	PRIORITY CATEGORY:	C (C)	
Area (F)	OWNER TYPE:	Religious organisation	
© Historic England	LIST ENTRY NUMBER:	1152799	Contact: Daniel Bashford 07824 103102



	SITE NAME:	Church of St Michael, Poole Road, Bournemouth	Substantial Victorian church with very large tower. This tower has significant problems and is difficult to access for				
	DESIGNATION:	Listed Place of Worship grade II*, CA	maintenance. The rainwater goods are not taking water away and interior wall paintings are vulnerable to water ingress.				
	CONDITION:	Poor	-				
	PRIORITY CATEGORY:	C (C)					
	OWNER TYPE:	Religious organisation					
	LIST ENTRY NUMBER:	1324732	Contact: Daniel Bashford 07824 103102				

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

use).

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / SOUTH WEST / BOURNEMOUTH CHRISTCHURCH AND POOLE (UA)

112	SITE NAME:	Church of St Clement, St Clement's Road, Bournemouth	A large Victorian church set in a public park. The tower roof is leaking badly and needs to be replaced. The
	DESIGNATION:	Listed Place of Worship grade I	rainwater goods are inadequate to carry water away from the building and the masonry is showing signs of damp.
	CONDITION:	Poor	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	32475	Contact: Daniel Bashford 07824 103102

© Historic England

	SITE NAME:	Church of St Stephen, St Stephen's Road, Bournemouth	Monumental Victorian church with a faceted east end, set within a small, restricted site. There is some water
THE	DESIGNATION:	Listed Place of Worship grade I, CA	penetration, and there have been falls of interior masonry due to rusting ferramenta (iron fittings). The church has been subject to heritage crime in recent years.
	CONDITION:	Poor	
1	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1324756	Contact: Daniel Bashford 07824 103102

© Historic England

SITE NAME:	Two round barrows 300 yards (270 metres) nor	th west of Double D	ykes, Hengistbury Head
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002397
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Round barrow cemetery on Barrow Hill 150 me	tres south west of Br	ookvale Farm, Poole
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018029
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bowl barrow on East Parley Common 610 metro	es south west of Fir G	Grove Farm, Christchurch and Poole
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016092
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Two bowl barrows at Gibbet Firs, 950 metres so Works, Christchurch and Poole"	outh west and 1080 m	netres south west of Palmers Ford
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016091
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Churchill Gardens, Boscombe		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.

C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument


HERITAGE AT RISK 2021 / SOUTH WEST / BOURNEMOUTH CHRISTCHURCH AND POOLE (UA) / BRISTOL, CITY OF (UA)

SITE NAME:	Town Centre, Poole		
DESIGNATION:	Conservation Area, 162 LBs, 3 SMs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Margo Teasdale (LPA) 01202 633914

BRISTOL, CITY OF (UA)

A hand	SITE NAME:	Church of St Peter, Castle Park, Bristol	Large Early Perpendicular Gothic church, with elements surviving from C12 and C15 and extensive later rebuilding			
	DESIGNATION:	Listed Building grade II*, CA	and remodelling. Damaged and reduced to a roofless shell during the first bombing raid on the City of Bristol in 1940,			
	CONDITION:	Fair	it has been maintained as a memorial to those lost in war. Repair works to secure the walls and high level stonework			
	OCCUPANCY:	Vacant/not in use	have started in 2019 and continuing through Summer 2021.			
	PRIORITY CATEGORY:	E (A)	Large areas of internal paving are in need of attention.			
	OWNER TYPE:	Local authority				
oric England	LIST ENTRY NUMBER:	1282177	Contact: Alessandra Perrone 0117 975 1345			

© Histori





	LIST ENTRY NUMBER:	1187186	Contact: Alessandra Perrone 0117 975 1345
and the second se	SITE NAME:	Swing Bridge over North Entrance Lock, Cumberland Basin, Bristol	Wrought iron bridge with tubular supporting members built c1844 by IK Brunel Moved to current location in 1873. It has been redundant and decaying on the dock
L	DESIGNATION:	Listed Building grade II*, CA	since the construction of Plimsoll Bridge in C20. Since 2014 a number of surveys on the condition of the fabric and
	CONDITION:	Very bad	some trial repairs have been carried out with the help of grant funding from Historic England. Investigations and
100	OCCUPANCY:	N/A	repairs carried out so far have enabled to test the
	PRIORITY CATEGORY:	C (C)	rotational mechanism which is still functioning. However the bridge is still in need of extensive repairs and a
	OWNER TYPE:	Local authority	sustainable use.
	LIST ENTRY NUMBER:	1202186	Contact: Alessandra Perrone 0117 975 1345



	SITE NAME:	Stair turret (Holy Cross), Inns Court Vicarage, Inns Court Green, Knowle, Bristol	C15 stair turret attached to C20 building. Situated in the middle of a housing estate. The house the turret is attached to changed hands in 2014 and the roof of the stair turret		
	DESIGNATION:	Listed Building grade II*	was repaired when improvement works were undertaken to the house.		
	CONDITION:	Fair			
	OCCUPANCY:	Vacant/not in use			
	PRIORITY CATEGORY:	C (C)			
	OWNER TYPE:	Private			
	LIST ENTRY NUMBER:	1202314	Contact: Sarah Ball 0117 975 0666		

© Historic England Archive

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / SOUTH WEST / BRISTOL, CITY OF (UA)

	, .	- (-)	
AA	SITE NAME:	Church of St Michael and attached railings, St Michael's Hill, Bristol	Church, rebuilt between 1775 and 1777 in a Gothic style, but retaining the mid-C15 tower. The interior is divided in three aisles by classical colonnades and has some late C19
	DESIGNATION:	Listed Building grade II*, CA	fittings. The church was last in use in the late 1990s, and the roofs of the nave and north aisle were damaged by fire
	CONDITION:	Poor	in October 2016. In 2019 the church was acquired by the
A A A A A A A A A A A A A A A A A A A	OCCUPANCY:	Vacant/not in use	present owner and consent was granted in November 2020 to convert the church to an events space. The church
	PRIORITY CATEGORY:	A (A)	roof has now been replaced, although the internal works are yet to commence.
	OWNER TYPE:	Private	,
© Historic England	LIST ENTRY NUMBER:	1282109	Contact: Stephen Guy 0117 975 0725

	SITE NAME:	28, Portland Square, St Pauls, Bristol	One of a terrace of seven houses located in a largely complete Georgian square, c1789-1820. Limestone ashlar,
	DESIGNATION:	Listed Building grade I, CA	brick stacks, slate mansard roofs, double-depth plan. Late Georgian style, four storeys with attic and basement. As of
	CONDITION:	Poor	May 2019, works for repair and conversion to hotel use are still in progress.
	OCCUPANCY:	Vacant/not in use	
TTT	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Commercial company	
d	LIST ENTRY NUMBER:	1202444	Contact: Alessandra Perrone 0117 975 1345



© Historic England Archive

© Historic England

	LIST ENTRY NUMBER:	1202444	Contact: Alessandra Perrone 0117 975 1345
	SITE NAME:	31 and 32, Portland Square, St Pauls, Bristol	Terraced houses, built from 1789 to 1820. Emergency repairs to the roof were carried out with Historic England
	DESIGNATION:	Listed Building grade I, CA	grant aid in 1996. Further damage occurred in 2005 when part of the facade collapsed. The buildings have been
	CONDITION:	Very bad	vacant for over 20 years and conditions continue to deteriorate. A planning application for repairs and
CALLER O	OCCUPANCY:	Vacant/not in use	residential conversion was approved in November 2020.
	PRIORITY CATEGORY:	B (A)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1208879	Contact: Alessandra Perrone 0117 975 1345

	SITE NAME:	Carriage Works, 104, Stokes Croft, Bristol	Carriage works, 1862. A notable building in a manner recognised as particular to the city. Large and complex site
	DESIGNATION:	Listed Building grade II*, CA	including 4, Ashley Road (grade II), also in very bad condition. Planning permission for a mixed use
	CONDITION:	Very bad	redevelopment of the site was granted in October 2015 and the site was sold to new owners in summer 2017.
The A A A	OCCUPANCY:	Vacant/not in use	Work on site to deliver the approved development begun
	PRIORITY CATEGORY:	D (B)	in 2019, but are currently delayed.
	OWNER TYPE:	Private	
Historic England Archive	LIST ENTRY NUMBER:	1025273	Contact: Stephen Guy 0117 975 0725

Сŀ



ristol ve
ıl
oric
ted I
1

© Historic England

Contact: Chris Miners 0117 975 1355

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / SOUTH WEST / BRISTOL, CITY OF (UA)

	SITE NAME:	Church of St Mary the Virgin, Church Close, Bristol	C13 church with C19 restoration. Roof coverings and rainwater goods are all in poor condition and there is
	DESIGNATION:	Listed Place of Worship grade II*, CA	vegetation growing out of the eroding masonry. Areas of mortar erosion and cement render are in need of replacement. This building has been subject to heritage
	CONDITION:	Poor	crime.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1205113	Contact: Katy Hoskyn 0117 975 1311
© Historic England			

st v T	SITE NAME:	Roman Catholic Church of St Bernadette, Wells Road, Bristol	Parish church designed in 1967 by James Leask of Kenneth Nealon, Tanner & Partners to accompany the Catholic
	DESIGNATION:	Listed Place of Worship grade II	school built on the centenary of the apparitions at Lourdes. Bold and innovative in design and materials, it features a
	CONDITION:	Very bad	double hyperbolic paraboloid roof carried on projecting concrete piers on a rotated square plan. Some of the
	PRIORITY CATEGORY:	B (B)	original materials are now showing signs of deterioration
	OWNER TYPE:	Religious organisation	and this has led to serious issues of water ingress through the roof coverings, affecting the ceiling and the roof
	LIST ENTRY NUMBER:	1436044	structure. Some episodes of vandalism have also taken place.
© Historic England			Contact: Alessandra Perrone 0117 975 1345
-			Contact. Alessandra remote on 17 773 1345

SITE NAME:	Anti-aircraft gun site, Purdown		
DESIGNATION:	Scheduled Monument, RPG grade II, CA LIST ENTRY NUMBER: Generally unsatisfactory with major localised problems TREND:		1004531
CONDITION:			Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE: Local authority CONTACT:			Alessandra Perrone 0117 975 1345
SITE NAME:	Civil War earthworks on Brandon Hill		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1006989
CONDITION:	Generally satisfactory but with significant localised problems		Improving
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	St Mary-le-Port Church, High Street		
DESIGNATION:	Scheduled Monument, LB grade II, CA	LIST ENTRY NUMBER:	1021385
CONDITION:	Extensive significant problems TREND:		Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Stokes Croft		
DESIGNATION:	Conservation Area, 19 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Kingsley Fulbrook (LPA) 0117 922 2966

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

BRISTOL, CITY OF (UA) / BATH AND NORTH EAST SOMERSET (UA)

		(<i>'</i> /	
	SITE NAME:	Brislington House	One of the first and most influential asylum landscapes in
	DESIGNATION:	Registered Park and Garden grade II*, 4 LBs, CA	Britain. Now subdivided between a sixth form college, private residential development, commercial sports facilities, industrial units and a management training centre.
	CONDITION:	Extensive significant problems	Despite this, some elements of the designed landscape
11: \$ 11: A A A A A A A A A A A A A A A A A A	VULNERABILITY:	High	England in 2017. Some adjustment to the boundary was
and sent the	TREND:	Stable	Bath and North East Somerset Unitary Authority.
Contraction of the second	NEW ENTRY ?:	No	
Historic England	OWNER TYPE:	Mixed, multiple owners	
	LIST ENTRY NUMBER:	1001529	Contact: Jo McAllister 0117 975 0696
distoric England	VULNERABILITY: TREND: NEW ENTRY?: OWNER TYPE:	Extensive significant problems High Stable No Mixed, multiple owners	Despite this, some elements of the designed landsc survive. Its designation was re-evaluated by Historic England in 2017. Some adjustment to the boundary made but no change to the grade. Part of the park Bath and North East Somerset Unitary Authority.

CORNWALL (UA)

© His

. ,			
	SITE NAME:	Scraesdon Fort, Antony	Built 1868, used for military training purposes. Vegetation is
	DESIGNATION:	Scheduled Monument and Listed Building grade II	being kept under reasonable control. Works have been undertaken to stop water ingress and repairs to metalwork throughout site. Drawbridge and main gate repairs were completed in 2014. The ditch was cleared in 2015.
	CONDITION:	Poor	completed in 2014. The ditch was cleared in 2015.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Government or agency	
	LIST ENTRY NUMBER:	1004347 and 1140707	Contact: Annie Evans 0117 975 0673

© Historic England



SITE NAME:	Tregantle Fort, Antony	Fort, built 1858-1865. The fort is vacant, with no end use
DESIGNATION:	Scheduled Monument and Listed Building grade II	identified. The interior of the keep is in poor condition, notably the wooden floors. New external doors and windows have been fitted. Interior partitions are still
CONDITION:	Fair	awaiting re-installation. Elsewhere in the fort, the barracks accommodation is no longer used full time with interiors
OCCUPANCY:	Vacant/not in use	deteriorating in places due to moisture penetration. A
PRIORITY CATEGORY:	C (C)	section of the counterscarp wall has collapsed. Significant localised problems remain to be tackled elsewhere on the
OWNER TYPE:	Government or agency	site.
LIST ENTRY NUMBER:	1004346 and 1159255	Contact: Annie Evans 0117 975 0673

use of the crypt.

Medieval chapel of St Thomas Becket 45 metres east of the

church, Priory Road, Bodmin

II*, CA Poor

B (B)

1002937

Vacant/not in use

Religious organisation

Scheduled Monument, LB grade

© Ministry of Defence



CAN IN	SITE NAME:
	DESIGNATION:
	CONDITION:
A MARKED AND	OCCUPANCY:
the standing	PRIORITY CATEGORY:
ric England	OWNER TYPE:

D

Е

LIST ENTRY NUMBER:

The monument is the roofless ruin of a CI4 chapel, located

within the churchyard of St Petroc's church. The building

suffers ivy growth on the walls, vandalism and anti-social

© Histor

Contact: Ann Preston-Jones 07917 642388

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; в solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument
- SM

UA Unitary Authority WHS World Heritage Site



SITE NAME:	Rosewarne House (Gladys Holman House), Tehidy Road, Camborne	Large early C19 H-plan granite town house in its own grounds. Latterly a residential home but vacant for some time. Lack of maintenance and vandalism resulted in rapidly
DESIGNATION:	Listed Building grade II*, CA, WHS	increasing deterioration. Repairs agreed in 2012 and a revised scheme approved in 2013. Works to the house and surrounding buildings largely completed. A further
CONDITION:	Good	application was received in Spring 2021 to address a change in the repair strategy following the discovery of
OCCUPANCY:	Vacant/not in use	greater decay and further structural issues (2021).
PRIORITY CATEGORY:	F (F)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1142639	Contact: Rhiannon Rhys 0117 975 0685




	SITE NAME:	Former Carharrack Methodist Church, Church Street, Carharrack	Grade II* Methodist chapel built in 1815, was purchased in 2017 following its redundancy as a place of worship. Water ingress through the deterioration of the roof cover and
	DESIGNATION:	Listed Building grade II*, WHS	under-sized rainwater goods has resulted in structural issues with the window lintels and floor of gallery. Damage
	CONDITION:	Poor	has been caused to the gallery box pews which are some of the oldest remaining in Cornwall. Discussions continue
	OCCUPANCY:	Vacant/not in use	with the owner and local planning authority regarding
	PRIORITY CATEGORY:	C (C)	future use.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1160248	Contact: Catherine Marlow 0117 975 0732

© Historic England

© Historic England



© Historic England





SITE NAME: Marlborough House, Silverdale Grade II* former country house now in suburbs of Road, Falmouth Falmouth. Building was vacant and in poor condition. Discussions with the owner over its repair and use have DESIGNATION: Listed Building grade II* since taken place. A listed building application for its refurbishment as a single dwelling was made in 2016. A CONDITION Fair subsequent consent was granted in 2017 and was OCCUPANCY: Vacant/not in use completed in May 2017. Work continues on the property. PRIORITY CATEGORY: F (F)

© Historic England



OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1270002	Contact: Catherine Marlow 0117 975 0732
SITE NAME:	Church of St Rumon, Ruan Major, Grade-Ruan	Medieval former parish church. Roof removed shortly closure in 1963. The Diocese has undertaken consolidation
DESIGNATION:	Listed Building grade I	to the low walls but not to the tower which has a tree growing out of it at high level. Discussions for the future of
CONDITION:	Poor	the ruin are ongoing.
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Religious organisation	

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but $\ \ F$ not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

1141915

LIST ENTRY NUMBER:

D

Е

use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: Chris Miners 0117 975 1355

ABBREVIATIONS

- Conservation Area Listed Building CA
- LB LPA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- ŬA Unitary Authority World Heritage Site WHS



Former Offices and Remains of Late 18th century foundry office, built by Harvey & Co and SITE NAME: incorporating the drawing office. Now used as Hayle Foundry of Harvey and Company, 24, Foundry Square, Heritage Centre. The first floor of the building was supported on Barlow rails - a type of early tram rail. The Hayle Barlow rails are deteriorating due to corrosion and this, as Listed Building grade II*, CA, well as drainage problems, is causing structural movement DESIGNATION: WHS of the building. Historic England is working with the Heritage Centre to find a solution to the problem, but this CONDITION: Poor has yet to be confirmed. OCCUPANCY: Occupied/in use PRIORITY CATEGORY: A (New entry) OWNER TYPE: Charity (heritage) LIST ENTRY NUMBER: 1143685 Contact: Catherine Marlow 0117 975 0732



SITE NAME:	Helland Bridge, Helland / St. Mabyn	This well-preserved medieval bridge carries a C-class road over the River Camel, between the A30 and B3266 roads.
DESIGNATION:	Scheduled Monument, 2 LBs	Because it provides a handy short-cut the road (and the bridge) is used by a very high volume of traffic from locals
CONDITION:	Fair	to commercial and tourist traffic. The bridge is subject to repeated damage and repair events and is still therefore
OCCUPANCY:	N/A	classed as vulnerable until further mitigation is undertaken
PRIORITY CATEGORY:	B (B)	to reduce the risks of repeated damage. Other issues include vegetation growth and a lateral crack in the tarmac
OWNER TYPE:	Local authority	at the centre of the bridge.
LIST ENTRY NUMBER:	1020812	Contact: Ann Preston-Jones 07917 642388

© Historic England



SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY.

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

© Historic England



SITE NAME: Treffry Viaduct, Lanlivery / Luxulvan DESIGNATION: Scheduled Monument, WHS CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: B (B) Charity (heritage) OWNER TYPE: LIST ENTRY NUMBER: 1007279

Tower of former church of St

Listed Building grade II*

Vacant/not in use

Religious organisation

Kea. Kea

Fair

C (C)

1141656

© Cornwall Council



LIST ENTRY NUMBER:	1007279	Contact: Nick Russell 0117 975 0671
SITE NAME:	Chapel at Hall, Lanteglos	Site consists of walls and well-preserved bell turret of a
DESIGNATION:	Scheduled Monument	C14 manorial chapel. Re-use as a farm building in the C19 caused modifications to the structure which still retained its
CONDITION:	Poor	original oak wagon roof until the 1960s. Conservation in the 1990s helped to stabilise the structure but now water
OCCUPANCY:	N/A	seeping into the rear wall has built up causing it to become
PRIORITY CATEGORY:	A (A)	unstable. Scaffolding funded by Historic England in 2015 was urgently needed to save the wall from falling and
OWNER TYPE:	Private	remedial works were carried out in 2017 to sections of wall. Further long term measures are required to protect
LIST ENTRY NUMBER:	1004361	the ruin from decay.

resources.

Contact: Chris Miners 0117 975 1355

the leats within the viaduct.

PRIORITY CATEGORIES

© Historic England

Immediate risk of further rapid deterioration or loss of fabric; no

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed. С

Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

D

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

ΪA

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- RPG

Tower of former church of St Kea, now a ruin. The tower

stands in a wooded valley beside the current church of St

Kea and is a picturesque and imposing reminder of the first

church. The tower has had some stabilisation work carried out to its pinnacles, and some ivy has been removed,

however this well-meaning ivy removal may cause longer

term damage due to joint loosening. The tower has no active use and may require additional stabilisation and/or

repairs which, given the very small and occasional use of the nearby church, will be difficult to fund from existing

Combined viaduct and aqueduct. Granite built ten-arched

bridge with a span approximately 200 metres, standing up

gushing from the leat within the structure, so water flow over the viaduct has been stopped. Leaks became evident

at abutments and locations within the main spans of the

Historic England to develop an investigation project to finalise the solution to the high level leakage problems of

structure. A solution to the leaking channel has now been agreed. The Cornwall Heritage Trust is working with

to 27 metres above the valley floor. Water had been

Contact: Catherine Marlow 0117 975 0732

- Registered Park and Garden Scheduled Monument SM
- Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2021 / SOUTH	WEST / CORNWALL (UA)	
K-LWA	SITE NAME:	Late medieval packhorse bridge 35 metres north of St Thomas's Church, Newport, Launceston	This attractive and well-preserved packhorse bridge has suffered from a lack of maintenance over the last few years, resulting in increased vegetation growth and loss of cobbles from the readway. Recently it has also suffered vandalism
-0.	DESIGNATION:	Scheduled Monument, LB grade I, CA	from the roadway. Recently it has also suffered vandalism with several of the distinctive slates which edge the roadway being either dislodged and thrown into the river
The second se	CONDITION:	Fair	or lost. A repair scheme is proposed but has yet to take place.
	OCCUPANCY:	N/A	place.
	PRIORITY CATEGORY:	B (New entry)	
© Historic England	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1020634	Contact: Ann Preston-Jones 07917 642388
	SITE NAME:	13, High Street, Launceston	Jettied and timber-framed corner house, prominent on
	DESIGNATION:	Listed Building grade II*, CA	town's market square. Roof structure and upper level party wall in poor condition. Vacant upper levels have
	CONDITION:	Poor	deteriorated badly due to a lack of maintenance. Some
	OCCUPANCY:	Vacant/not in use	repairs have been carried out to the roofs, gutters and slate hung walls. Structural and weatherproofing problems
	PRIORITY CATEGORY:	A (A)	remain.
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1206510	Contact: Chris Miners 0117 975 1355
© Cornwall Council			
	SITE NAME:	Trekelland Bridge, Lewannick / South Petherwin	Trekelland Bridge is a grade II* medieval bridge with two main arches and a span flood arch. Carrying the road
	DESIGNATION:	Listed Building grade II*	between Launceston and Liskeard, it is still heavily used. The bridge has been the subject of repeated vehicle
	CONDITION:	Poor	impacts that have damaged its approach walls and coping stones in particular. No solution to these traffic impacts has
and the second	OCCUPANCY:	Occupied/in use	been found to date.
ETHON	PRIORITY CATEGORY:	A (A)	
And the second second	OWNER TYPE:	Local authority	
© Historic England	LIST ENTRY NUMBER:	1155188	Contact: Catherine Marlow 0117 975 0732
4	SITE NAME:	Freemasons Hall, Quay Street, Lostwithiel	C13 former hall of the Duchy Palace, a masonic hall since 1878. A building preservation trust acquired the building;
	DESIGNATION:	Listed Building grade I, CA	an options appraisal carried out and proposals for its re- use developed. English Heritage offered grant for
	CONDITION:	Poor	investigation and repairs which were completed in the spring 2013. Since then, dampness in the lower areas and
	OCCUPANCY:	Vacant/not in use	problems with the heating services have caused a large area
	PRIORITY CATEGORY:	E (New entry)	of decay in the timber of the main hall. the building is now vacant again. A Covid Recovery Fund Grant is
	OWNER TYPE:	Charity (heritage)	implementing a solution to the floor structure.
© Historic England	LIST ENTRY NUMBER:	1327326	Contact: John Ette 0117 975 0687
/	SITE NAME:	Maker Heights Barracks Block, Maker-with-Rame	Built 1804-1808 as a barracks for a line of earlier redoubts built to protect Devonport Dockyard in 1782. The two-
	DESIGNATION:	Listed Building grade II*	storey block was altered in the mid C19 when the formerly tile-hung first floor was rebuilt in brick. It is the most
	CONDITION:	Poor	complete small garrison barracks from this significant
	OCCUPANCY:	Part occupied/part in use	period. Partially repaired and in use as a community art centre. A scheme of window repairs has been undertaken
	PRIORITY CATEGORY:	В (В)	with Historic England grant aid with another scheme of basement repairs scheduled for completion in 2020. The
	OWNER TYPE:	Charity (heritage)	slate roof is now showing signs of distress and needs
© Historic England	LIST ENTRY NUMBER:	1375582	renewal.
			Contact: Annie Evans 0117 975 0673

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

1 3	SITE NAME:	Maker Heights Guard House, boundary wall and attached ancillary buildings, Maker-with- Rame	Built in 1804-1808 as a barracks for a line of earlier redoubts built to protect Devonport Dockyard in 1782. Altered in mid C19. Guard House in fair condition and used as offices but several of the other buildings are in
	DESIGNATION:	Listed Building grade II*	poor to bad condition, in particular the Straw Store, Wash House and Caponier. Now in seperate private ownership
Ft Land	CONDITION:	Very bad	from the Barrack Block that forms the raison d'etre for this group of buildings.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (A)	
Historic England	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1329099	Contact: Annie Evans 0117 975 0673
	SITE NAME:	English Garden House, Maker- with-Rame	An early C18 Classical garden house, located within Mount Edgcumbe Estate, now a Country Park. Originally a
	DESIGNATION:	Listed Building grade II*, RPG grade I	banquetting house, subsequently extended to include a sunken marble bath and additional rooms as a garden building for entertaining and leisure. Water ingress has
	CONDITION:	Poor	caused damage to historic fabric, including plasterwork and
	OCCUPANCY:	Part occupied/part in use	wall paper. The building is currently used for storage, although Historic England are working with the owners for
	PRIORITY CATEGORY:	A (A)	a grant aided repair scheme.
and the second second	OWNER TYPE:	Local authority, multiple owners	
Historic England	LIST ENTRY NUMBER:	1140619	Contact: Chris Miners 0117 975 1355
DANGER TEP OUT	SITE NAME:	Boundary wall to Lanherne Carmelite Convent, Mawgan-in- Pydar	C16 or C17 boundary park wall. Substantial loam bonded random rubble masonry wall almost one metre thick standing up to four metres in places. Neglected, heavily overgrown with ivy and partially collapsed in places.
P Alassa i la	DESIGNATION:	Listed Building grade II*, CA	Condition survey needed to understand and monitor and to prioritise repairs.
	CONDITION:	Poor	and to produse repairs.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
Vickery Holman Ltd	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	37593	Contact: Annie Evans 0117 975 0673
	SITE NAME:	Insworke Chapel, Millbrook	Ruins of Chapel. Slatestone rubble with limestone dressings. No roof. Chapel has nave and chancel in one,
MALL AN	DESIGNATION:	Scheduled Monument, LB grade II*	appears to have been of two storeys. C19 cart shed attached to east end. Chapel has previously been fully
	CONDITION:	Very bad	recorded by Historic England. The structure is now in imminent danger of collapse with a number of risk factors
Alex Alex	OCCUPANCY:	Vacant/not in use	including subsiding walls and extensive damaging
	PRIORITY CATEGORY:	A (A)	vegetation. A programme of investigation work is due to be implimented to seek to stabilise the site.
Section of Section	OWNER TYPE:	Private	
Historic England	LIST ENTRY NUMBER:	1003095	Contact: Ann Preston-Jones 07917 642388
	SITE NAME:	Remains of Carclew House, Mylor	The remains of Carclew House are the formal centre of a Registered park and garden also at risk. Started in 1720 by
	DESIGNATION:	Listed Building grade II*, RPG grade II, WHS	Samuel Kemp, this palladian style house was one of Cornwall's finer C18 country houses but was partly burned down in 1934. It is now a ruin, overgrown and neglected, ir
	CONDITION:	Very bad	private ownership next to the owners home in a private garden. Vegetation management is now ongoing with a
			Surgerie de la contra la contente la nove ongoing with a
199 Ban Ball - 7	OCCUPANCY:	Vacant/not in use	program of repairs in development. A steering group has
- The second second	OCCUPANCY: PRIORITY CATEGORY:	Vacant/not in use A (A)	been established with the owners of Carclew House and a Conservation Management Statement for the site is in

© Historic England

CONDITION:	Very bad	private ownership next to the owners home in a private garden. Vegetation management is now ongoing with a
OCCUPANCY:	Vacant/not in use	program of repairs in development. A steering group ha
PRIORITY CATEGORY:	A (A)	been established with the owners of Carclew House an Conservation Management Statement for the site is in
OWNER TYPE:	Private, multiple owners	preparation.
LIST ENTRY NUMBER:	6029	Contact: John Ette 0117 975 0687

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

D

Е

Slow decay: solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Dry sand and green sand shop, Perran Foundry, Perran Wharf, Mylor	Early to mid C19 mould and casting buildings. This is the main furnace building, an impressive and intact structure. Urgent repairs carried out early 2005. Listed Building
	DESIGNATION:	Listed Building grade II*, CA, WHS	Consent and Planning Permission for repair and conversion granted 2008, with subsequent variations on that consent also permitted 2019. The buildings have been reroofed bu
6 6 - 5 - F - F - F - F - F - F - F - F - F	CONDITION:	Very bad	the consented scheme for reuse has not yet been implemented.
Le Contra contra la seconda	OCCUPANCY:	N/A	inplemented.
AND TAXABLE	PRIORITY CATEGORY:	F (F)	
© Historic England	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1141603	Contact: Catherine Marlow 0117 975 0732
	SITE NAME:	Engineers' Shop, Perran Foundry, Perran Wharf, Mylor	Engineers' shop, boring mill and pattern shop, early-mid C18. Listed Building Consent and Planning Permission for
	DESIGNATION:	Listed Building grade II*, CA, WHS	repair and conversion of whole Perran Foundry site granted 2008 and now being implemented in a phased manner. Revised scheme for reuse of the engineers' shop
	CONDITION:	Very bad	as ancillary car parking and storage area granted permission in 2019 but as yet unimplemented. Current application for
	OCCUPANCY:	Vacant/not in use	removal of entire roof has yet to be determined.
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Commercial company	
© Historic England	LIST ENTRY NUMBER:	4 643	Contact: Catherine Marlow 0117 975 0732
	SITE NAME:	Threshing barn on north side of yard at Trebartha Barton, North Hill	Mid C19 threshing barn forming one side of the farmyard to Trebartha Barton Farm. Two-storey 'E' plan with projecting midstryes infilled with first floor lean-to, forming
	DESIGNATION:	Listed Building grade II*	impressive elevation to the yard. Rubble walls with granite dressings. Rag slate covered king post trussed roofs with
	CONDITION:	Poor	slate hung infill walls. Slates are slipped or missing causing structural decay. There is harmful vegetation growth. First
	OCCUPANCY:	Vacant/not in use	floor boarding is decayed and unsafe.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Charity (heritage)	
© Historic England	LIST ENTRY NUMBER:	1250152	Contact: Chris Miners 0117 975 1355
	SITE NAME:	Entrance gate and flanking walls forming mock fortifications to east of Prideaux Place, Padstow	Late CI6 reused Catacleuse arched gateway with CI8 flanking turrets, decorated with crenellations. Slate stone. Narrow blind arrow slits. Capping failure has led to water
TT BE M	DESIGNATION:	Listed Building grade I, RPG grade II	penetration through the piers (which are thought to be solid and not hollow). There is cracking of stone, movement of archway, bulging stone plinth and washed ou
	CONDITION:	Poor	mortar joints. Advice has been given.
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	C (C)	
© Historic England	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1289743	Contact: Chris Miners 0117 975 1355
	SITE NAME:	Trenearne, Padstow	House, now farmhouse, circa early C17, possibly remodelled in 1660 (datestone) for 'PW'. The house only
	DESIGNATION:	Listed Building grade II*	survives in part and was probably of overall 'H' shaped
	CONDITION:	Poor	plan. It has been a tenanted farm for a number of years but a lack of maintenance had left all the buildings in a poor
	OCCUPANCY:	Vacant/not in use	state of repair. The estate which owns Trenearne has beer granted listed building consent to refurbish the house
	PRIORITY CATEGORY:	C (C)	including much needed repairs, as well as the conversion o
	OWNER TYPE:	Private	farm buildings. Property sold to new owner in 2020.
© Historic England	LIST ENTRY NUMBER:	2 508	Contact: Catherine Marlow 0117 975 0732

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

12

© His


© Penwith Di

© Historic England

	SITE NAME:	Market Building, Market Place, Penzance	Built 1836-38. Altered 1925. Partially occupied; the western half by Lloyds Bank, the eastern half is vacant. The
	DESIGNATION:	Listed Building grade I, CA	roof was repaired approximately five years ago although some leaks persist. Vulnerable historic interiors have had
	CONDITION:	Poor	plaster falls on the vacant eastern half. Outbreaks of timber decay persist in the unventilated interiors. Basement ceiling
	OCCUPANCY:	Part occupied/part in use	collapse has led to the need for floor propping.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
istoric England Archive	LIST ENTRY NUMBER:	1221062	Contact: Chris Miners 0117 975 1355
	SITE NAME:	Trinity Methodist Chapel, Chywoone Hill, Newlyn,	Former Nonconformist Wesleyan chapel c1834, enlarged 1866. One of the most complete early C19 chapels in

District Council		Chywoone Hill, Newlyn, Penzance	Cornwall. No longer used for religious worship. It has been
	DESIGNATION:	Listed Building grade II*, CA	put on the market in the last year.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1386515	Contact: Chris Miners 0117 975 1355





	SITE NAME:	Tolgus Calciner, New Portreath Road, Redruth	Remains of a calciner used in the production of arsenic. It has been vacant for many years and is vulnerable with a damaged main roof and a collapsed adjoining tin-roofed extension. The main hipped slate roof of the building has been damaged through vandalism and there is an urgent
	DESIGNATION:	Scheduled Monument, LB grade II, WHS	
I ENPA	CONDITION:	Poor	need for weather proofing.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (A)	
and the second sec	OWNER TYPE:	Mixed, multiple owners	
© Cornwall Council	LIST ENTRY NUMBER:	1021240	Contact: Ann Preston-Jones 07917 642388



THE REAL PROPERTY IN CONTRACT OF THE PROPERTY IN CONTRACT.	SITE NAME:	Sara's Foundry, Tolgus Place, Redruth	C19 and C20 iron foundry and engineering works, containing associated machinery. Buildings continue to
	DESIGNATION:	Listed Building grade II*, WHS	deteriorate and are now in a very vulnerable condition. Discussions with Cornwall Council to identify an
	CONDITION:	Very bad	appropriate strategy to secure the building and prevent further deterioration have continued.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1142573	Contact: Chris Miners 0117 975 1355

© Cornwall Council

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / SOUTH	SITE NAME:	Market House, Market Street,	Large town centre Market House built in 1844. It is formed
Summer of		St. Austell	of a town hall facing the church with an imposing street frontage and with a large glazed market area behind. Leaks
A LAND	DESIGNATION:	Listed Building grade II*, CA	and other rainwater system faults to the town hall and especially to the glazed market area are getting steadily
	CONDITION:	Poor	worse. Occupancy rates in both areas have fallen as a
	OCCUPANCY:	Part occupied/part in use	result. Major repairs to all parts of the building are now needed before the building becomes beyond repair. A
	PRIORITY CATEGORY:	C (C)	project is now being developed for which consents have
	OWNER TYPE:	Charity (non-heritage)	been applied.
© Historic England	LIST ENTRY NUMBER:	1289697	Contact: Chris Miners 0117 975 1355
	SITE NAME:	Harbour Piers and Quays including Inner Basin, Charleston Port, St. Austell Bay	Charlestown Port is a late Georgian working port dating back to the C18 and located approximately one mile from St Austell on the south coast of Cornwall. It consists of an
	DESIGNATION:	Listed Building grade II*, CA, WHS	inner harbour with two flanking piers projecting out to sea, the larger on to the west. A modern steel lockgate then connects to the long thin dock running inland. The west
	CONDITION:	Poor	pier wall has blown masonry blocks and the east pier wall has tidally undermined wall lengths.
	OCCUPANCY:	Part occupied/part in use	has udany undermined wan lengths.
	PRIORITY CATEGORY:	C (New entry)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1327290	Contact: Catherine Marlow 0117 975 0732
	SITE NAME:	Charlestown Methodist Church, Charlestown Road, St. Austell Bay	Former Wesleyan chapel (1827) and attached schoolroom (mid C19), now closed for worship. A revised Listed Building Consent was granted in May 2018. Work
	DESIGNATION:	Listed Building grade II*, CA, WHS	commenced on site 2018/2019 and the shell of the building is now fully repaired. As of 2021, no end user has been identified for the main chapel. However, the
Chertenium (Lase	CONDITION:	Fair	converted school room has been placed on the open market (2021).
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	F (F)	
© Cornwall Council	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	44292	Contact: Rhiannon Rhys 0117 975 0685
4	SITE NAME:	Engine Sheds, Stack and Turntable, St Blazey Road, St. Blaise	Locomotive turntable associated with adjacent roundhouse is deteriorating through lack of maintenance having been taken out of service in 2002. The roundhouse building is in
	DESIGNATION:	Listed Building grade II*	light industrial use. A community interest group has been formed to develop a project to restore the site and bring it
	CONDITION:	Poor	into more sympathetic uses. A Coastal Communities Fund grant was awarded in 2016 to develop the project.
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Government or agency	
© Historic England	LIST ENTRY NUMBER:	1289905	Contact: Catherine Marlow 0117 975 0732
			Changel dated 1944 Coord interview with a large and building
	SITE NAME:	Hockings House Bible Christian Chapel, St. Cleer	Chapel dated 1846. Good interior with gallery and original fittings including leaders' pew. Separated from the small Sunday school and damaging partial conversion works
	DESIGNATION:	Listed Building grade II*	preceded its sale in 2012. Negotiations with owner are
	CONDITION:	Poor	sporadic and relate to the possible extent of an acceptable conversion scheme. The building deteriorated in the
and and the second second second	OCCUPANCY:	Vacant/not in use	interim with its roof falling into a very poor state, with consequential damage occurring to the interior. Listed
	PRIORITY CATEGORY:	D (D)	Building Consent was granted in 2015 for roof repairs,
	OWNER TYPE:	Private	completed in 2017. No agreement has yet been reached on an acceptable scheme for reuse.
© Historic England	LIST ENTRY NUMBER:	3 03	Contact: Catherine Marlow 0117 975 0732

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- 15



SITE NAME: Flanking walls and gateway to the bridge over moat about 8 metres east of Old Rectory, Old Rectory Drive, St. Columb Major DESIGNATION: Listed Building grade II* conservation of the moat. CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Private LIST ENTRY NUMBER: 1144097 Contact: Chris Miners 0117 975 1355

Mid C19, part of William White's layout for the Bishop's Palace which became a Rectory and latterly a hotel. Obscured and threatened by dense vegetation. White's wrought iron gate, referred to in the List description, is not at present hung and its whereabouts is unknown. Vegetation clearance has taken place to allow for

© Cornwall Council



	SITE NAME:	Old Bishop's Palace, Old Rectory Drive, St. Columb Major	1851 by William White. Picturesque Gothic Revival country gentleman's rectory, a classic of the type. In very poor state of repair caused by lack of maintenance,
	DESIGNATION:	Listed Building grade II*	vandalism, vegetation, inappropriate finishes and unlived-in state. Water ingress has resulted in dry rot and damage to
	CONDITION:	Very bad	historic fabric. Statutory action by Local Planning Authority on hold. Vegetation clearance has taken place and is being
	OCCUPANCY:	Vacant/not in use	maintained.
	PRIORITY CATEGORY:	A (A)	
ile Co	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	44096	Contact: Chris Miners 0117 975 1355

© Cornwall Council



© Cornwall Council



Late C18/early C19 estate agricultural building. Attributed SITE NAME: Calf House at Lithiack and to Soane for the Port Eliot Estate. In low key use but stable adjacent to north, Port Eliot Estate, St. Germans condition remains very poor. Currently tenanted by a roofing company who are undertaking localised repairs. Listed Building grade II*, RPG Condition improving. DESIGNATION: grade l CONDITION: Poor OCCUPANCY: Occupied/in use PRIORITY CATEGORY: C (C) OWNER TYPE: Private LIST ENTRY NUMBER: 1140518 Contact: Annie Evans 0117 975 0673

	SITE NAME:	Botallack Manor House, St. Just	Small C17 manor house. L shaped plan with granite rubble
	DESIGNATION:	Listed Building grade II*, CA, WHS	walls and slate roofs. Vacant since 2013, derelict and subject to vandalism. Windows and doors now removed and covered with temporary boarding as the owners start
	CONDITION:	Poor	a repair project which has been interupted by the Covid pandemic.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	D (New entry)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	43288	Contact: Chris Miners 0117 975 1355

© Historic England



S

D

Е

SITE NAME:	Little Trethewey Methodist Chapel, Little Trethewey, St. Levan	Built as Wesleyan Chapel in 1868. Small chapel with stuccoed Italianate front. Modest and complete interior with closed box pews. The chapel is in a bad condition with
DESIGNATION:	Listed Building grade II*	holes in the roof. The downpipes are blocked and external render is failing. Front gable is unstable and resulted in
CONDITION:	Very bad	damage to the interior. Chapel closed April 2013. The condition continues to deteriorate. Historic England grant
OCCUPANCY:	Vacant/not in use	aided repairs in 2015 that covered the roof with a
PRIORITY CATEGORY:	A (A)	temporary sheet covering. The chapel has been sold and Historic England looks forward to discussing its future with
OWNER TYPE:	Private	the new owner.
LIST ENTRY NUMBER:	1311918	Contact: Chris Miners 0117 975 1355

PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- Conservation Area Listed Building CA
- LB LPA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- ŬA Unitary Authority World Heritage Site WHS

	,	,	
	SITE NAME:	Chapel Mill, Gwindra Road, St. Stephen-in-Brannel	Chapel Mill is a C19 china stone grinding mill, a rare and intact example of its kind, which still contains machinery. It
	DESIGNATION:	Listed Building grade II*	has been redundant since the 1950s and since then has gradually deteriorated, becoming very overgrown. Large
PERF	CONDITION:	Poor	parts of the mill's corrugated iron roof covering have blown off leaving the wall tops open to water penetration
	OCCUPANCY:	Vacant/not in use	and the timberwork rotting and collapsing. Inside, the
	PRIORITY CATEGORY:	D (D)	machinery is in deteriorating condition. Volunteers have cleared the scrub but roof repairs are beyond their
	OWNER TYPE:	Private	capacity.
d	LIST ENTRY NUMBER:	1261837	Contact: Ann Preston-Jones 07917 642388

Holmbush Mine: Windsor Lane

rotative engine house with adjacent boiler house, loadings

II, WHS

Very bad

B (C)

Vacant/not in use

and platform, Stokeclimsland

Scheduled Monument, LB grade

© Historic England

© Historic England



SITE NAME:	Gunpowder works at Kennall Vale, Stithians / Ponsanooth	This large scheduled area is centred on a steep sided, wooded valley, which contains remains of ruined buildings,
DESIGNATION:	Scheduled Monument, 9 LBs, WHS	mills, leats and bridges associated with a C19 gunpowder works. After years of abandonment, the many ruined structures on the site are at risk from tree and vegetation
CONDITION:	Poor	growth, water and footpath erosion and collapse. Recently, the most 'at risk' structures and leats were consolidated
OCCUPANCY:	Vacant/not in use	through a Natural England Stewardship scheme but there
PRIORITY CATEGORY:	B (B)	remain many outstanding management needs.
OWNER TYPE:	Charity (non-heritage)	
LIST ENTRY NUMBER:	1020143	Contact: Ann Preston-Jones 07917 642388

This is a substantial mine engine house in deteriorating

condition. The building is densely covered in ivy and surrounded by trees. The roof is mostly collapsed but still

retains a few slates and roof timbers which are vulnerable

to further damage. Timber fittings are deteriorated and

rotten. Arched window openings have slipped bricks.

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

D

Е

PRIORITY CATEGORY:

© Historic England



OWNER TYPE:	Crown	
LIST ENTRY NUMBER:	1020327	Contact: Ann Preston-Jones 07917 642388
SITE NAME:	Part of the china clay works known as Wheal Martyn, Treverbyn	Site includes well preserved remains of china clay processing works displayed as part of a museum. There are a range of features, including drying sheds, water wheels,
DESIGNATION:	Scheduled Monument	settling tanks, machinery. Completion of major NLHF project to undertake conservation works to the main
CONDITION:	Fair	structures and provide new education and gallery space prevented from completion by Covid 19 lockdown.
OCCUPANCY:	Part occupied/part in use	
PRIORITY CATEGORY:	B (B)	
OWNER TYPE:	Charity (heritage)	
LIST ENTRY NUMBER:	1003265	Contact: Nick Russell 0117 975 0671

© Historic England



SITE NAME:	Wesleyan Chapel, Porkellis, Wendron	Former Wesleyan Methodist chapel, built 1866. The congregation has moved into the Sunday school and the
DESIGNATION:	Listed Building grade II*, WHS	chapel was sold to a private buyer. New owner has addressed the most serious roof leaks and obtained Listed
CONDITION:	Poor	Building Consent for conversion to residential use from Cornwall Council. The repairs are ongoing.
OCCUPANCY:	Part occupied/part in use	controlar council. The repairs are ongoing.
PRIORITY CATEGORY:	F (F)	
OWNER TYPE:	Other not for profit group	
LIST ENTRY NUMBER:	1162569	Contact: Chris Miners 0117 975 1355

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but $\ \ F$ not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no

obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG Registered Park and Garden Scheduled Monument
- SM
- UA WHS Unitary Authority World Heritage Site

ideal.	SITE NAME:	Church of St Protus and St Hyacinth, Blisland	Large parish church on the south of the village green, high on the edge of Bodmin Moor. Three aisles, C15 formed
	DESIGNATION:	Listed Place of Worship grade I, CA	from C12 cruciform plan and with projecting south transept and north tower. Rubble stone walling for the early work and granite ashlar for the later. Restored by FC
	CONDITION:	Poor	Eden 1896. Graduated Cornish slate roofs. Internal damp problems persist although rainwater goods have been
	PRIORITY CATEGORY:	C (C)	repaired.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1142367	Contact: Chris Miners 0117 975 1355
© Historic England			

	SITE NAME:	Church of St Crewen, Crowan	Large rural parish church in the centre of a small village.
	DESIGNATION:	Listed Place of Worship grade II*	Cornish three-aisle church with a tall west tower. CI4 and CI5 restored 1872, with a C20 south organ chamber. All
	CONDITION:	Poor	granite ashlar and Cornish slate roofs. The rainwater system has had some repair. A leaking valley gutter has
	PRIORITY CATEGORY:	C (C)	caused interior damage. The window masonary needs
	OWNER TYPE:	Religious organisation	repairs.
	LIST ENTRY NUMBER:	1160230	Contact: Chris Miners 0117 975 1355

© Historic England

ALC: NO

	SITE NAME:	Church of St Grade, Grade- Ruan	Small church in an isolated site. Plan of tower, nave and east chancel. C14 origins. The slate roof needs repair and
	DESIGNATION:	Listed Place of Worship grade I	the tower has excessive damp and vegetation growth. The parish are ctively seekung funding for repair solutions.
	CONDITION:	Poor	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	
52 L	LIST ENTRY NUMBER:	4 938	Contact: Chris Miners 0117 975 1355

© Historic England

1	SITE NAME:	Church of St Nivet, Lanivet	Large Anglican parish church in the centre of a large village.
	DESIGNATION:	Listed Place of Worship grade I	Classic Cornish pattern plan of three aisles with tall west tower. Granite and slate roofed mostly CI5. The rainwater
TA	CONDITION:	Poor	system is under-sized, rusted and part displaced. High level stonework needs repair and some roofs need reslating.
- III	PRIORITY CATEGORY:	C (C)	stonework needs repair and some roots need restating.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	5824	Contact: Chris Miners 0117 975 1355
and the second se			

© Historic England



SITE NAME:	Church of St Stephen, St Stephen's Hill, Launceston	Large urban parish church and the mother church for Launceston, Norman core with many additions finishing
DESIGNATION:	Listed Place of Worship grade I, CA	with the C16 tower. Restored 1883. Granite ashlar tower and outer walls to the west and south, the rest slatestone rubble with granite or greenstone dressings. The roof leaks
CONDITION:	Poor	and needs extensive renewal and repair.A Covid Recovery Grant has been given which has developed a repair
PRIORITY CATEGORY:	B (A)	program.
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1297830	Contact: Chris Miners 0117 975 1355

© Historic England

PRIORITY	CATEGORIES

- А
- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

1.1.	SITE NAME:	Church of St Martin, Lewannick	Small parish church with tall tower. Plan of three parallel
3	DESIGNATION:	Listed Place of Worship grade II*	aisles with opposing north and south gabled porches and a west tower. Mostly granite ashlar with slate roofs.
1	CONDITION:	Poor	Extensively rebuilt late C19. The tower has serious faults at high level on the north side. The bell opening and the
o-mi-	PRIORITY CATEGORY:	A (A)	parapet above have serious structural faults. A crack on the
L R.	OWNER TYPE:	Religious organisation	projecting stair turret appears to be active. The roof also needs repair.
Piter De .	LIST ENTRY NUMBER:	1277508	Contact: Chris Miners 0117 975 1355

© Historic England

the set	SITE NAME:	Church of St Martin by Looe, Looe	Large two aisled church with tall west tower, south transept and north aisle. Structural problems with roof
	DESIGNATION:	Listed Place of Worship grade I	structure reported with major movement across the east end of the nave by the south transept. Although largely
Dia	CONDITION:	Poor	historic it is now showing signs of fresh movemnt with plaster falls. A scheme of emergency repairs is propose
	PRIORITY CATEGORY:	C (C)	with Historic England grant support.
	OWNER TYPE:	Religious organisation	
Service P.	LIST ENTRY NUMBER:	1282854	Contact: Chris Miners 0117 975 1355

© Historic England

	SITE NAME:	Church of St Torney, North Hill	Large parish church on the eastern edge of Bodmin Moor.
	DESIGNATION:	Listed Place of Worship grade I	There are structural problems in the tower where the floors are unsafe for use. The rainwater goods are rusted
	CONDITION:	Poor	and leaking. There are major damp problems in the east end and structural problems in the tower. The church has
	PRIORITY CATEGORY:	C (C)	closed and is currently in the use seeking period. No new
	OWNER TYPE:	Religious organisation	use or owner has yet been identified.
	LIST ENTRY NUMBER:	1249982	Contact: Chris Miners 0117 975 1355

© Historic England

X	SITE NAME:	Church of St Denis, North Tamerton	A parish church set in a hillside churchyard. Plan of twin aisles with south porch, north vestry and west tower. Early
	DESIGNATION:	Listed Place of Worship grade I	CI5 with CI9 north vestry added in 1875 restoration. Rubble stone with granite dressings, complete ashlar tower
· Kon	CONDITION:	Poor	and porch. Cornish slate roofs, some pitches rag slate. The rainwater goods are in poor condition and the slate roofs
1	PRIORITY CATEGORY:	C (C)	have slipped with fractured slates needing replacement.
	OWNER TYPE:	Religious organisation	
CAREST	LIST ENTRY NUMBER:	1142437	Contact: Chris Miners 0117 975 1355

© Historic England



SITE NAME:	Ponsanooth Methodist Church, including forecourt walls, steps and gate piers, Chapel Hill, Ponsanooth	Large Methodist chapel with intact horseshoe galleried interior, along with early pews. Congregation has moved to newly refurbished associated hall and chapel is no longer used. They are in discussion with Historic England about
DESIGNATION:	Listed Place of Worship grade II*, WHS	reuse of the chapel for associated community uses.
CONDITION:	Good	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1159101	Contact: Catherine Marlow 0117 975 0732

© Eric Berry

- А
- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Church of St Sampson, South Hill	The church requires significant repairs to its lathe and plaster ceiling, pieces of which periodically fall causing
-	DESIGNATION:	Listed Place of Worship grade I	damage and potentially danger to users. Other repairs needed to window tracery.
	CONDITION:	Poor	
illi 🦳	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Religious organisation	
water a state	LIST ENTRY NUMBER:	1140786	Contact: Chris Miners 0117 975 1355

© Historic England

	SITE NAME:	Methodist Chuch (former Wesleyan Chapel), Chapel Road, St. Just	Large and prominent chapel at the edge of the small town of St Just. Granite walled with slate roof. Generally plain with large multi-paned arch headed windows but with a
	DESIGNATION:	Listed Place of Worship grade II*, CA, WHS	grand portico on the street front. Complete galleried interior. Serious rain ingress is affecting the interior especially around the organ chamber at the back end,
	CONDITION:	Poor	together with falls of gutters. Some repairs to this area have now taken place. Coastal Revival Fund grant has been
	PRIORITY CATEGORY:	C (C)	announced for the regeneration of the chapel.
	OWNER TYPE:	Religious organisation	
© Historic England	LIST ENTRY NUMBER:	4329	Contact: Chris Miners 0117 975 1355

	SITE NAME:	Church of St Pynnochus, St. Pinnock	Small parish church. Norman cruciform origins with C15 north aisle and nave rebuilds, the tower of C14, C16 south
	DESIGNATION:	Listed Place of Worship grade I	porch. Coursed rubble with granite dressings. Cornish slated roofs with some slates slipped. Damp tower with
	CONDITION:	Poor	much vegetation growth and problem downpipe on the north side. The church is closed for worship and now it has now been reported as having been sold.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1140308	Contact: Chris Miners 0117 975 1355

© Historic England

	SITE NAME:	Church of St Cuby, Tregony with Cuby	Small parish church. The tower is C14, of slate. The rest of the church is of rubble with granite dressings and has
	DESIGNATION:	Listed Place of Worship grade I, CA	medieval origins but mostly displays the 1828 rebuilding with the 1899 St Aubyn restoration. Cornish slate roofs. The church is in fair condition overall but the tower has major problems with its drainage resulting in a wet north wall with harmful excessive vegetation growth.
	CONDITION:	Poor	
	PRIORITY CATEGORY:	C (C)	wait with harmitic excessive vegetation growth.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1291868	Contact: Chris Miners 0117 975 1355
) Historic England			

© Historic England

- MAL	SITE NAME:	Church of St Gregory, Treneglos	Small parish church high on the North Cornish plateau. Two aisles and a high west tower are from the C15, heavily
	DESIGNATION:	Listed Place of Worship grade II*	restored 1858. Tower rebuilt 1871. A Listed Places of Worship Roof Repair Grant was awarded in 2016 for roof
	CONDITION:	Fair	and rainwater repairs. However the outer roof slopes and the timber floor of the tower still need urgent repair.
1 B ALLANS	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Religious organisation	
A Carton	LIST ENTRY NUMBER:	1310214	Contact: Chris Miners 0117 975 1355
	OWNER TYPE:	Religious organisation	

© Historic England

PRIORITY CATEGORIES

А

- В
- C Slow decay; no solution agreed.

Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. Slow decay; solution agreed but F Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial user. use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	Church of St Nicholas, Tresmeer	Village church with C15 two-stage tower and C19 rebuilt nave. Surrounding church yard. Interior contains Norman
	DESIGNATION:	Listed Place of Worship grade II*	font. This church is closed and is being prepared for disposal and alternative use by the Church of England (2nd
	CONDITION:	Fair	round of marketing currently underway). Issues such as allocated parking, garden, design of acommodation, use
	PRIORITY CATEGORY:	C (C)	etc. are all unresolved.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1161299	Contact: Catherine Marlow 0117 975 0732

© Historic England

	SITE NAME:	Church of St Werburgh, Warbstow	Small parish church. Nave and chancel of Norman origin and of rubblestone, coursed slate tower and granite ashlar
	DESIGNATION:	Listed Place of Worship grade II*	north aisle added in C15 and north porch in 1601. Restored 1861. Cornish slate roofs which have slipped
	CONDITION:	Poor	slates, especially the porch. The rainwater system needs overhauling.
	PRIORITY CATEGORY:	C (C)	overhadning.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1161531	Contact: Chris Miners 0117 975 1355

© Historic England

-

a. Ale	SITE NAME:	Parish Church of St Anne, Whitstone Head, Whitstone	Large parish church with a C13 core with C15 upper tower and three-aisle plan. The porch and the chancel originate
	DESIGNATION:	Listed Place of Worship grade I	from the 1882 restoration. Mostly slatestone rubble with granite dressings. Cornish slate roofs. In fair condition
	CONDITION:	Poor	overall but very bad damp in the tower due to a leaking downpipe on the north side. Unguttered pitches on the
	PRIORITY CATEGORY:	C (C)	north and south eaves. Slates are starting to slip from the
	OWNER TYPE:	Religious organisation	roof pitches.
	LIST ENTRY NUMBER:	1142426	Contact: Chris Miners 0117 975 1355

© Historic England

SITE NAME:	Deserted medieval settlement and field system v post-medieval farmhouse north west of Tresibbe		historic settlement and field system and
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007775
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric coaxial field system, incorporated and medieval settlement on Fox Tor and Treburland	l adjacent hut circles, Farm, Altarnun	stone setting, linear boundaries and
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008245
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric irregular field system and hut circle s deserted settlement south east of Tresibbet Farr	ettlement with adjace n, Altarnun	ent medieval regular field system and
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007776
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В

implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Prehistoric stone alignment I kilometre SSE of East	tmoorgate, Altarnu	n
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012228
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Nine Stones stone circle 1.03 kilometres NNW of	Bowhayland Farm,	Altarnun / North Hill
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008631
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Scraesdon Fort, Antony		
DESIGNATION:	Scheduled Monument and Listed Building grade II	LIST ENTRY NUMBER:	1004347 and 1140707
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Annie Evans 0117 975 0673
SITE NAME:	Hut circle group and enclosure north east of Carw	en, Blisland	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004659
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Group of round barrows south east of Middle Tap	house, Braddock	
DESIGNATION:	Scheduled Monument, RB	LIST ENTRY NUMBER:	1004433
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Group of round barrows south of Penadlake, Brade	dock	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004436
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Round barrows west of West Taphouse, Braddock		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004617
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Castle Pencaire hillfort, two rounds and a field sy	stem, Tregonning Hi	II, Breage / Germoe
DESIGNATION:	Scheduled Monument, LB grade II, CA, WHS	LIST ENTRY NUMBER:	1007293
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Binhamy moat 500 yards (460 metres) west of Binhamy Farm, Bude-Stratton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004655
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Gunnislake Clitters copper, tin, arsenic and wolfr	am mine, Calstock	
DESIGNATION:	Scheduled Monument, LB grade II, WHS	LIST ENTRY NUMBER:	1017088
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Okeltor C19 arsenic, copper and tin mine, Calsto	ock	
DESIGNATION:	Scheduled Monument, LB grade II, WHS	LIST ENTRY NUMBER:	1019440
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prince of Wales Mine at Harrowbarrow, Calstoc	k	
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1021411
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Tamar Canal, Gunnislake, Calstock		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1007302
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	The remains of the Chapel of St la and adjacent o	ell, Camborne	
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1441204
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Council Barrow, Cardinham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004476
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Carn Brea Castle, Carn Brea		
DESIGNATION:	Scheduled Monument, 2 LBs, CA, WHS	LIST ENTRY NUMBER:	1006704
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Wheal Busy, Chacewater		
DESIGNATION:	Scheduled Monument, LB grade II, WHS	LIST ENTRY NUMBER:	1021392
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Melangoose camp, Colan		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004426
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Round at Lower Treloskan, Cury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004267
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Killibury Castle later prehistoric hillfort, Egloshayle	9	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010439
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Jewish and Congregationalist cemeteries at Ponsha	rden, Falmouth / Pe	enryn
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020815
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. В
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	An early Christian memorial stone 380 metres s	outh east of Worthyw	ale Manor, Forrabury and Minster
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018701
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Flooding	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Dingerein Castle small multivallate hillfort and ar	inexe, 240 metres no	rth west of Curgurrel Farm, Gerran
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019742
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Group of round barrows north of Hayle Kimbro	Pool, Grade-Ruan / I	Mullion
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003082
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Cliff castle west of Gunwalloe Church, Gunwallo	e	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004265
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Grambla Roman camp, Gweek		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003078
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Round barrow 20 yards (18 metres) north west	of Tolvan Cross, Gw	eek
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004269
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Rectangular camp south west of Trevarnon Rou	nd, Gwinear-Gwithiar	۱
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004468
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ann Preston-Jones 07917 642388

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Roseworthy Arsenic Works, 700 metres west of 0	rest of Cornhill Farm, Gwinear-Gwithian		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021418	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Trevarnon Round, Gwithian, Gwinear-Gwithian			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006696	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Castle Kayle (earthwork), Phillack, Hayle			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006688	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Carvannel cliff castle, Illogan			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004390	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No	
OWNER TYPE:	Charity (heritage)	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	'Headon Barrow' near Headon Cross, Jacobstow			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005434	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Round barrow 650 metres east of Carrine, Kea			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019086	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Round 200 metres north west of Penventinnie, Ke	nwyn		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016063	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

MithMedThe Castler, KildhamptonLasson Much.Scheduled Monument.Nativer Status Mus.1003079Lasson Much.Scheduled Monument.Nativer Status Mus.ImprovingCONDIGNScheduled Monument.Scheduled Monument.Scheduled Monument.Scheduled Monument.Dasson Much.Scheduled Monument.Scheduled Monument.Scheduled Monument.NoDasson Much.Scheduled Monument.Scheduled Monument.NoDasson Much.Scheduled Monument.Scheduled Monument.NoDasson Much.Scheduled Monument.NoNoScheduled Monument.Scheduled Monument.NoNoScheduled Monument.Scheduled Monument.NoNoScheduled Monument.Scheduled Monument.NoNoScheduled Monument.Scheduled Monument.NoNoScheduled Monument.NoNoNoScheduled Monument.NoNo<	TERTLAGE AT KISK 2021 / SOU	ITH WEST / CORNWALL (UA)		
CONNECTIONGenerally satisfactory but with significant localised problemsImprovingImprovingRINCLANA VULKIKANITYCharly (hertage)CRAINNoCONNECTIONCharly (hertage)CRAINANN Preston-Jones 07917 642388STETAMEFive book barrows 480 metres and 510 metres nort-LalockDEDIGNATIONScheduled MonumentUTCHTY NAMEDE1019021CONNECTIONScheduled MonumentUTCHTY NAMEDENoCONNECTIONScheduled MonumentUTCHTY NAMEDENoCONNECTIONScheduled MonumentUTCHTY NAMEDE102179CONNECTIONGenerally unstatificatory with major localised problemsTRAINNoCONNECTIONGenerally unstatificatory with major localised problemsTRAINNoCONNECTIONGenerally unstatificatory with major localised problemsTRAINNoCONNECTIONGenerally unstatificatory with major localised problemsTRAINNoCONNECTIONCharchyard cross in Lanivet churchyard, S metras1014229CONNECTIONCharchyard cross in Lanivet churchyard, S metras1014229CONNECTIONScheduled Monument, 21BsUTCHTY NAMENE1014229CONNECTIONCharchyard cross in Lanivet churchyard, S metras1014229CONNECTIONScheduled Monument, 21BsUTCHTY NAMENE1014229CONNECTIONChurchyard cross in Lanivet churchyard, S metras1014229CONNECTIONChurchyard cross in Lanivet churchyard, S metras1014229CONNECTIONChurchyard cross in Lanivet chu	SITE NAME:	The Castles, Kilkhampton		
problemsmodelmodelmutuationproblemsSchub / tree growthNEW DATRY:NoBRANDAL WALKRANUUTY:Schub / free growthNEW DATRY:NoStrik / free boxt barrows 480 metres and 510 metres northFI Hendra FarruLdockDESIGNAL WALKRANUUTY:Scheduled MonumentUT DATRY: NAMMER:NoDESIGNAL WALKRANUUTY:Scheduled MonumentNEW DATRY:NoStrik / free growthNEW DATRY:NoStrik / free growthNEW DATRY:NoScheduled MonumentUT DATRY: NAMEC1020179DESIGNAL WALKRANUUTY:Scheduled MonumentUT DATRY: NAMEC1020179CONDOL:Generally unsätifactory with major localised problemsTRADE:DeciningStrik LoringScheduled MonumentUT DATRY: NAMEC1020179CONDOL:Generally unsätifactory with major localised problemsTRADE:DeciningSTIL NAMEChurchyard cross in Lanivet churchyard, 5 metres west of the church. LanivetIntervoNoSTIL NAMEScheduled Monument, 2 LBsINTERNANoSTIL NAMEScheduled Monument, 2 LBsINTERNANoSTIL NAMEScheduled Monument, 2 LBsINTERNANoSTIL NAMEScheduled Monument, 2 LBsINTERNANoSTIL NAMEScheduled Monument, 2 LBsINTERNANoSCHILT TYPEReligious organisationCONTACTAnn Preston-Jones 07917 642388STIL NAMEScheduled Monument, 2 LBsINTERNANoSTIL NAMESch	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003079
OWNERTING:Chartry (heritage)CONTACT:Ann Preston-Jones 07917 642388STREMARE:Five bow barrows 480 metres and 510 metres northLalockDESIGNATIONScheduled MonumentUST ENTRY NURSEN1019021CONTROLGenerally unsatisfactory with major localisedTERIC:ScheluledMIRICINAL WITHERM:Scheduled MonumentCONTACT:NoCONTROLPrivateCONTACT:Ann Preston-Jones 07917 642388STENARE:Round and annexe 720 metres WSW of Tregear-LalockCONTACT:DESIGNATIONScheduled Monument:UST ENTRY NURSEN1020179CONTROLScheduled Monument:CONTACT:Ann Preston-Jones 07917 642388STENARE:Reinerally unsatisfactory with major localisedTERIN:DecliningPrivateControlControlProblemsNoSTENARE:Churchyard cross in Lanivet churchyard, S metresInterveLanivetDESIGNATIONScheduled Monument, 2 LBSUST ENTRY NURSENID14229CONTROLGenerally satisfactory but with significant localisedTERICAnn Preston-Jones 07917 642388STENARE:NeurblinesScheduled Monument, 2 LBSUST ENTRY NURSENID14229CONTROLGenerally unsatisfactory but with significant localisedTERICAnn Preston-Jones 07917 642388STENARE:NeurblinesID160017Scheduled Monument, 2 LBSUST ENTRY NURSENID14229CONTROLGenerally unsatisfactory but with significant localisedTERICAnn Preston-Jones 07917 642388STENARE: <td< td=""><td>CONDITION:</td><td></td><td>TREND:</td><td>Improving</td></td<>	CONDITION:		TREND:	Improving
Characterize Five boow barrows 480 metres and 510 metres north of Hendra Farm, Ladock Designation Scheduled Monument List FNTRE NUMBER: [01902] Constraints: Stable Stable Constraints: Scheduled Monument List FNTRE NUMBER: No Constraint: Scheduled Monument List FNTRE NUMBER: No Constraint: Scheduled Monument List FNTRE NUMBER: 1020179 Constraint: Scheduled Monument, 2 LBS Declining Scheduled Monument, 2 LBS List FNTRE NUMBER: 1014229 Constraint: Scheduled Monument, 2 LBS List FNTRE NUMBER: 1014229 Constraint: Scheduled Monument, 2 LBS List FNTRE NUMBER: 1014229 Constraint: Scheduled Monument LBS FNTRE NUMBER: 1014229 Constraint: Scheduled Monument List FNTRE NUMBER:	PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
DESERVATIONScheduled MonumentUSTENTER NUMBER[01902]CONDITION:Generally unsatisfactory with major localisedmaxio:StablePRINCERE TYPE:Scrub/tree growthNEW PARTYR:NoCONDER TYPE:PrivateCONTACT:Ann Preston-jones 07917 642388STREMARERound and annexe 720 metres WSW of Treger. LaterDecliningCONDER TYPE:Scheduled MonumentIST FIRTER NUMBER[020179DESIGNATIONScheduled MonumentIST FIRTER NUMBERMoCONDERSTORE:Generally unsatisfactory with major localisedmetro:MoOWNERTYPE:Arable ploughingNEW DATTYR:NoOWNERTYPE:PrivateCONTACT:Ann Preston-jones 07917 642388STE NAMEChurchyard cross in Lanivet churchyard, 5 metres:of heurich.DESIGNATION:Scheduled Monument, 2 LBSIST ENRIFEIntereston-Jones 07917 642388STE NAMEChurchyard cross in Lanivet churchyard, 5 metres:of heurich.OctorDESIGNATION:Scheduled Monument, 2 LBSIST ENRIFEIntereston-Jones 07917 642388STE NAMEChurchyard treg growthNoIntereston-Jones 07917 642388STE NAMERegious organisationContrACT:Ann Preston-Jones 07917 642388STE NAMERegious organisationContrACT:Ann Preston-Jones 07917 642388STE NAMEScheduled MonumentIST ENRIFEIntereston-Dones 07917 642388STE NAMERecently statisfactory but with significant localisedIRENONoCONDITION:Generall	OWNER TYPE:	Charity (heritage)	CONTACT:	Ann Preston-Jones 07917 642388
Concentrion-Generally unsatisfactory with major localised problemsRENDERStableRENDERAL ULLERABULTYScrub/tree growthNew WIRTNoCONTACTAnn Preston-Jones 07917 642388RENDERAFrivateCONTACTAnn Preston-Jones 07917 642388RENDERAScheduled MonumentUSI ENTERNMENE[20179CONTACTScheduled MonumentUSI ENTERNMENE[20179CONTACTGenerally unsatisfactory with major localised problemsmake problems[20179RENDERAL ULLERABULTYArable ploughingNo[20179CONTACTAnd Preston-Jones 07917 642388[20179STENAMEChurchyard cross in Lanivet churchyard, 5 metres[20179CONTACTScheduled Monument, 2 LBsUSI ENTERNEMENE[20129CONTACTScheduled Monument, 2 LBsUSI ENTERNEMENE[20179CONTACTReligious organisation[2017[20179CONTACTReligious organisation[20179[20179CONTACTReligious organisation[20179[20179CONTACTReligious organisation[20179[20179CONTACTReligious organisation[20179[20179CONTACTReligious organisation[20179[20179CONTACTReligious organisation[20179[20179CONTACTReligious organisation[20179[20179CONTACTControline[20179[20179[20179CONTACTControline[20179[20179[20179Contact	SITE NAME:	Five bowl barrows 480 metres and 510 metres nor	rth of Hendra Farm	n, Ladock
problemsproblemsproblemsproblemsproblemsproblemsremacher Vou NationaumScrub/tree growthNew DistriceNoremacher Vou NationaumContractContractNostrateRound and annexe 720 metres WSW of Treegar, LactDecliningstrateScheduled MonumentLast Text TX MARREDecliningcontractScheduled MonumentLast Text TX MARREDecliningcontractGenerally unsatisfactory with major localised problemsPreNoNocontractPrivateContractAn Preston-Jones 07917 642388strateChurchyard cross in Lanivet churchyard, 5 metresContractAnn Preston-Jones 07917 642388strateChurchyard cross in Lanivet churchyard, 5 metresDecliningstrateContractScheduled Monument, 2 LBsUST ENTRY MARREN1014229contractGenerally statisfactory but with significant localised problemsIreno:DecliningstrateReligious organisationContract:Ann Preston-Jones 07917 642388strateReligious organisationContract:NocontractReligious organisationIreno:ImprovingstrateScheduled MonumentLatiter trav NARRENNocontractReligious organisationIreno:ImprovingstrateScheduled MonumentIst ENTRY NARRENNocontractScheduled MonumentIst ENTRY NARRENNocontractScheduled MonumentIst ENTRY NARRENNocontract </td <td>DESIGNATION:</td> <td>Scheduled Monument</td> <td>LIST ENTRY NUMBER:</td> <td>1019021</td>	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019021
CONNERT TYPE: Private Round and annexe 720 metres WSW of Tregest. Later Ann Preston-jones 07917 642388 DEMERSTATION: Scheduled Monument UIST BYTEY NUMBER: 1020179 CONNERT: Scheduled Monument UIST BYTEY NUMBER: 1020179 CONNERT: Generally unsatisfactory with major localised problems TRINC: Declining RIBLICENAL VULNER/MELTTY: Anable plouphing NOV LYNTY: No OWNERT TYPE: Churchyard cross in Lanivet churchyard, 5 metres: Lorit PNTY NUMBER: I014229 CONNERT: Churchyard cross in Lanivet churchyard, 5 metres: Lorit PNTY NUMBER: I014229 CONNERT: Scheduled Monument, 2 LBs UIST ENTY: Yes CONNERT: Scheduled Monument CONNERT: Yes CONNERT: Religious organisation CONNERT: Yes CONNERT: Scheduled Monument UIST ENTY: No CONNERT: Scheduled Monument UIST ENTY: Yes CONNERT: Scheduled Monument UIST ENTY: Yes CONNERT: Scheduled Monument, CA, WHS Instren: <td< td=""><td>CONDITION:</td><td></td><td>TREND:</td><td>Stable</td></td<>	CONDITION:		TREND:	Stable
Round and annexe 720 metres WSW of Treger, Later NTRY NUMBER: 1020179 DERIGNATION: Scheduled Monument ILTE NTRY NUMBER: 1020179 CONDITION: Generally unsatisfactory with major localised INEND: Declining RINE CALVELINE VALUE Arable ploughing NEW ENTRY: No OWNER TYPE: Private CONTACT:: Ann Preston-Jones 07917 642388 STEE NAME: Churchyard cross in Lanivet churchyard, 5 metres: wet of the church, Lanivet 1014229 CONTROM: Generally satisfactory but with significant localised problems INTENTRY NUMBER: 1014229 CONTROM: Generally satisfactory but with significant localised problems NEW ENTRY: Yes CONTROM: Religious organisation CONTACT:: Ann Preston-Jones 07917 642388 STEE NAME: Scheduled Monument UIT ENTRY NUMBER: 1007306 CONTROM: Generally satisfactory but with significant localised problems Improving Improving CONTROM: Generally satisfactory but with significant localised problems INEXTON: No CONTROM: Control (non-heritage) CONTACT:: No No STEE NAME: Control (non-heritage) CONTAC	PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
DESERVATION: Scheduled Monument LET ENTRY NUMBER: 1020179 CONDITION Generally unsatisfactory with major localised problems TREND: Declining RENCERAL VULNERABULTY: Arable ploughing NEW ENTRY: No OWNER TYPE: Private CONTACT: An Preston-Jones 07917 642388 STEE NAME: Churchyard cross in Lanivet churchyard, 5 metres west of the church. Lanivet Declining DESIGNATION Scheduled Monument, 2 LBs LBT ENTRY NUMBER 1014229 CONDITION Generally satisfactory but with significant localised problems TREND: Declining REINCIPAL WULNERABULTY: Scrub / tree growth NEW ENTRY: Yes OWNER TYPE: Religious organisation CONTACT: Ann Preston-Jones 07917 642388 STE NAME: Neolithic settlement and hut circle on Helman Tor, LaTIVEY Ves DESIGNATION Scheduled Monument LBT ENTRY NUMBER: 1007306 CONDITION Generally satisfactory but with significant localised problems TREND: Improving STE NAME: Scheduled Monument, CA, WHS LBT ENTRY NUMBER: 1012352 COND	OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
Concentration Concentration Concentration CONDITION Generally unsatisfactory with major localised problems TEND: Declining PRINCURAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Private CONTACT: Ann Preston-Jones 07917 642388 STEENAME: Churchyard cross in Lanivet churchyard, 5 metres west of the church, Lanivet Environment OBEGRATION: Scheduled Monument, 2 LBs UST ENTRY NUMBER: 1014229 CONTACT: Ann Preston-Jones 07917 642388 Environment Declining CONTACT: Scheduled Monument, 2 LBs UST ENTRY NUMBER: 1014229 CONTACT: Religious organisation CONTACT: Ann Preston-Jones 07917 642388 STEENAME: Neolithic settlement and hut circle on Helman Tor, Lanivery Ves DEBIGNATION: Scheduled Monument UST ENTRY NUMBER: 1007306 CONTACT: Renortity satisfactory but with significant localised problems TREND: Improving Streamente: Scheduled Monument, CA, WHS UST ENTRY NUMBER: 1012352 CONTACT: Charity (non-heritage)	SITE NAME:	Round and annexe 720 metres WSW of Tregear, I	adock	
Concention problemis File of the full of the	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020179
OWNER TYPE: Private CONTACT: Ann Preston-Jones 07917 642388 STE NAME: Churchyard cross in Lanivet churchyard, 5 metres wet of the church, Lanivet Eanivet DESIGNATION: Scheduled Monument, 2 LBs UST ENTRY NUMBER: 1014229 CONDITION: Generally satisfactory but with significant localised problems TREND: Declining RRINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY NUMBER: Yes OWNER TYPE: Religious organisation CONTACT: Ann Preston-Jones 07917 642388 STE NAME: Neolithic settlement and hut circle on Helman Tor, Lanivery Yes DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1007306 CONDITION: Generally satisfactory but with significant localised problems TREND: Improving CONTACT: Scheduled Monument, CA, WHS NEW ENTRY: No OWNER TYPE: Charity (non-heritage) CONTACT: Ann Preston-Jones 07917 642388 STE NAME: Earlier prehistoric hillfort, two cairns, medieval problems 1012352 STE NAME: Scheduled Monument, CA, WHS UST ENTRY NUMBER: 1012352 CO	CONDITION:		TREND:	Declining
STRE NAME: Churchyard cross in Lanivet churchyard, 5 metres west of the church, Lanivet STRE NAME: Scheduled Monument, 2 LBs LBT ENTRY NUMBER: 1014229 CONDITION: Generally satisfactory but with significant localised problems TREND: Declining RRINCIPAL VULNERABILTY: Scrub / tree growth NEW ENTRY NUMBER: Yes OWNER TYPE: Religious organisation CONTACT: Ann Preston-Jones 07917 642388 STEE NAME: Neolithic settlement and hut circle on Helman Tor, Lanivery Improving Designation: Scheduled Monument LBT ENTRY NUMBER: 1007306 Condition: Generally satisfactory but with significant localised problems Improving Improving RRINCIPAL VULNERABILTY: Scheduled Monument LBT ENTRY NUMBER: 1007306 CONDITION: Generally satisfactory but with significant localised problems Improving Improving STEE NAME: Scheduled Monument, CA, WHS New ENTRY: No STEE NAME: Earlier prehistoric hillfort, two cairns, medieval pound and adjacent prehistoric field systems, hut circles and transhumance huts on Stowe's Hill, Linkinhorne Interve Improving STEE NAME: Scheduled Monument, CA, WHS LBT ENTRY NUMBER:	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Beside and the answer of the antice transfer of the antite transfer of the antice transfer	OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningRRINCIPAL VULNERABILITY:Scrub / tree growthNEW ENTRY:YesOWNER TYPE:Religious organisationCONTACT:Ann Preston-Jones 07917 642388DEBIGNATION:Neolithic settlement and hut circle on Helman Tor.INTERNITY NUMBER:1007306DEBIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1007306CONDITION:Generally satisfactory but with significant localised problemsTREND:ImprovingRRINCIPAL VULNERABILITY:Scrub / tree growthNEW ENTRY:NoOWNER TYPE:Charity (non-heritage)CONTACT:Ann Preston-Jones 07917 642388STE NAME:Earlier prehistoric hillfort, two cairns, medieval portInterNo101252DEBIGNATION:Scheduled Monument, CA, WHSLIST ENTRY NUMBER:1012352CONDITION:Generally satisfactory but with significant localised problemsTREND:NoDEBIGNATION:Scheduled Monument, CA, WHSLIST ENTRY NUMBER:1012352CONDITION:Generally satisfactory but with significant localised problemsTREND:NoCONDITION:ConvinCrownCONTACT:NoCONDITION:Early medieval transhumance hut 740 metres west Elackcombe Farry problemsNoTET NAME:Early medieval transhumance hut 740 metres west Elackcombe Farry problemsNoCONDITION:Scheduled MonumentUST ENTRY NUMBER:1011899CONDITION:Scheduled MonumentUST ENTRY NUMBER: </td <td>SITE NAME:</td> <td>Churchyard cross in Lanivet churchyard, 5 metres</td> <td>west of the church</td> <td>, Lanivet</td>	SITE NAME:	Churchyard cross in Lanivet churchyard, 5 metres	west of the church	, Lanivet
ConcentionproblemsMatterDecliningPRINCIPAL VULNERABILITY:Scrub/tree growthNEW ENTRY:YesPRINCIPAL VULNERABILITY:Religious organisationCONTACT:Ann Preston-Jones 07917 642388STEE NAME:Neolithic settlement and hut circle on Helman Tor, LarliveryImprovingDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER1007306CONTION:Generally satisfactory but with significant localised problemsTREND:ImprovingRRINCIPAL VULNERABILITY:Scrub/tree growthNEW ENTRY:NoOWNER TYPE:Charity (non-heritage)CONTACT:Ann Preston-Jones 07917 642388STE NAME:Earlier prehistoric hillfort, two cairns, medieval powerAnn Preston-Jones 07917 642388STE NAME:Scheduled Monument, CA, WHSLIST ENTRY NUMBER1012352DESIGNATION:Scheduled Monument, CA, WHSLIST ENTRY NUMBER1012352CONDITION:Generally satisfactory but with significant localised problemsNoNoCONDITION:Plant growthNEW ENTRY:NoOWNER TYPECrownCONTACT:Ann Preston-Jones 07917 642388CONDITION:Scheduled Monument, CA, WHSUST ENTRY NUMBER1012352CONDITION:Generally satisfactory but with significant localised problemsNoCONTACT:NoMIN Preston-Jones 07917 642388STE NAME:Early medieval transhumance hut 740 metres west > Blackcoombe Farr LinkinhorneDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER1011899DESI	DESIGNATION:	Scheduled Monument, 2 LBs	LIST ENTRY NUMBER:	1014229
CONTRCT:Religious organisationCONTACT:Ann Preston-Jones 07917 642388SITE NAME:Neolithic settlement and hut circle on Helman Tor, Lanlivery1007306DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1007306CONDITION:Generally satisfactory but with significant localised problemsTREND:ImprovingRRINCIPAL VULNERABILITY:Scrub / tree growthNEW ENTRY:NoOWNER TYPE:Charity (non-heritage)CONTACT:Ann Preston-Jones 07917 642388SITE NAME:Earlier prehistoric hillfort, two cairns, medieval pound and adjacent pre-bistoric field systems, hut circles and transhumance huts on Stowe's Hill, Linkinhorne1012352DESIGNATION:Scheduled Monument, CA, WHSLIST ENTRY NUMBER:1012352CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningDESIGNATION:Scheduled Monument, CA, WHSLIST ENTRY NUMBER:NoCONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningOWINER TYPE:CrownCONTACT:Ann Preston-Jones 07917 642388SITE NAME:Early medieval transhumance hut 740 metres west of Blackcoombe Farm, LinkinhorneDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1011899CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningCONDITION:Generally unsatisfactory with major localised problemsTREND:NoRRINCIPAL VULNERABILITY:Plan growthNEW ENTRY:No	CONDITION:		TREND:	Declining
STITE NAME: Neolithic settlement and hut circle on Helman Tor, Lanlivery DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1007306 CONDITION: Generally satisfactory but with significant localised problems TREND: Improving RRINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY?: No OWNER TYPE: Charity (non-heritage) CONTACT: Ann Preston-Jones 07917 642388 STE NAME: Earlier prehistoric hillfort, two cairns, medieval pourt transhumance huts on Stowe's Hill, Linkinhorne UST ENTRY NUMBER: 1012352 DESIGNATION: Scheduled Monument, CA, WHS UST ENTRY NUMBER: 102352 CONDITION: Generally satisfactory but with significant localised problems TREND: Declining PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No OWNER TYPE: Crown CONTACT: Ann Preston-Jones 07917 642388 STE NAME: Early medieval transhumance hut 740 metres west of Blackcoombe Farry Linkinhorne Scheduled Monument STE NAME: Scheduled Monument UST ENTRY NUMBER: 1011899 STE NAME: Early medieval transhumance hut 740 metres west of Blackcoombe Farry Linkinhorne Instentin-Jones 07917 642388 S	PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
DESIGNATION: Scheduled Monument LINE of a for a	OWNER TYPE:	Religious organisation	CONTACT:	Ann Preston-Jones 07917 642388
CONDITION:Generally satisfactory but with significant localised problemsTREND:ImprovingRINCIPAL VULNERABILITY:Scrub / tree growthNEW ENTRY?:NoOWNER TYPE:Charity (non-heritage)CONTACT:Ann Preston-Jones 07917 642388SITE NAME:Earlier prehistoric hillfort, two cairns, medieval powerstriktionIst ENTRY NUMBER:1012352DESIGNATION:Scheduled Monument, CA, WHSIst ENTRY NUMBER:1012352CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningRINCIPAL VULNERABILITY:Plant growthNEW ENTRY?:NoOWNER TYPE:CrownCONTACT:Ann Preston-Jones 07917 642388SITE NAME:Early medieval transhumance hut 740 metres west backcoombe FairNoSITE NAME:Scheduled MonumentScheduled MonumentIst ENTRY NUMBER:DESIGNATION:Scheduled MonumentUST ENTRY NUMBER:NoOWNER TYPE:ConvinConvinContact:NoSITE NAME:Early medieval transhumance hut 740 metres west backcoombe FairLinkinhorneDESIGNATION:Scheduled MonumentUST ENTRY NUMBER:1011899CONDITION:Scheduled MonumentIst ENTRY NUMBER:1011899CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningCONDITION:Generally unsatisfactory with major localised problemsNEW ENTRY?:NoRINCIPAL VULNERABILITY:Hant growthNEW ENTRY?No	SITE NAME:	Neolithic settlement and hut circle on Helman Tor	, Lanlivery	
problemsproblem	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007306
OWNER TYPE:Charity (non-heritage)CONTACT:Ann Preston-Jones 07917 642388SITE NAME:Earlier prehistoric hillfort, two cairns, medieval pour transhumance huts on Stowe's Hill, Linkinhorner transhumance huts on Stowe's Hill, LinkinhornerINTE NAME:012352DESIGNATION:Scheduled Monument, CA, WHSINTE ENTRY NUMBER:012352CONDITION:Generally satisfactory but with significant localised problemsINEW ENTRY?NoOWNER TYPE:Plant growthNEW ENTRY?NoOWNER TYPE:CrownCONTACT:Ann Preston-Jones 07917 642388SITE NAME:Early medieval transhumance hut 740 metres westFlanctorone DistributionDESIGNATION:Scheduled MonumentINTE NAMERE:1011899DESIGNATION:Generally unsatisfactory with major localised problemsINTE NAMERE:1011899CONDITION:Plant growthINTENDDecliningCONDITION:Plant growthINTENDDecliningCONDITION:Plant growthINTENDNo	CONDITION:		TREND:	Improving
SITE NAME: Earlier prehistoric hillfort, two cairns, medieval pound and adjacent prehistoric field systems, hut circles and transhumance huts on Stowe's Hill, Linkinhorne Ist ENTRY NUMBER: 1012352 DESIGNATION: Scheduled Monument, CA, WHS Ist ENTRY NUMBER: 1012352 CONDITION: Generally satisfactory but with significant localised problems TREND: Declining PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No OWNER TYPE: Crown CONTACT: Ann Preston-Jones 07917 642388 SISTE NAME: Early medieval transhumance hut 740 metres west of Blackcoombe Farm, Linkinhorne Ist ENTRY NUMBER: 1011899 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining RINCIPAL VULNERABILITY: Plant growth Ist ENTRY NUMBER: 1011899 RINCIPAL VULNERABILITY: Plant growth Ist ENTRY NUMBER: 1011899 RINCIPAL VULNERABILITY: Plant growth Ist ENTRY NUMBER: No	PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
Interventiontranshumance huts on Stowe's Hill, LinkinhorneInterventionDESIGNATION:Scheduled Monument, CA, WHSIJST ENTRY NUMBER:1012352CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Plant growthNEW ENTRY?:NoOWNER TYPE:CrownCONTACT:Ann Preston-Jones 07917 642388SITE NAME:Early medieval transhumance hut 740 metres westBlackcoombe Farry LinkinhorneDESIGNATION:Scheduled MonumentIJST ENTRY NUMBER:1011899CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningCONDITION:Plant growthNajor localised problemsNo	OWNER TYPE:	Charity (non-heritage)	CONTACT:	Ann Preston-Jones 07917 642388
DESIGNATION:Scheduled Monument, CA, WHSLIST ENTRY NUMBER:1012352CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Plant growthNEW ENTRY?:NoOWNER TYPE:CrownCONTACT:Ann Preston-Jones 07917 642388SITE NAME:Early medieval transhumance hut 740 metres west > Blackcoombe Far- UST ENTRY NUMBER1011899DESIGNATION:Scheduled MonumentIIST ENTRY NUMBER:1011899CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningPINCIPAL VULNERABILITY:Plant growthNEW ENTRY?:No	SITE NAME:		und and adjacent pi	rehistoric field systems, hut circles and
problemsproblemsIncreaseDecliningPRINCIPAL VULNERABILITY:Plant growthNEW ENTRY?:NoOWNER TYPE:CrownCONTACT:Ann Preston-Jones 07917 642388SITE NAME:Early medieval transhumance hut 740 metres west of Blackcoombe Farm LinkinhorneDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1011899CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Plant growthNEW ENTRY?:No	DESIGNATION:		LIST ENTRY NUMBER:	1012352
OWNER TYPE:CrownCONTACT:Ann Preston-Jones 07917 642388SITE NAME:Early medieval transhumance hut 740 metres west of Blackcoombe Farry, LinkinhorneDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1011899CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Plant growthNEW ENTRY?:No	CONDITION:		TREND:	Declining
SITE NAME: Early medieval transhumance hut 740 metres west of Blackcoombe Farry Linkinhorne DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1011899 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY ?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1011899 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No	OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Plant growthNEW ENTRY?:No	SITE NAME:	Early medieval transhumance hut 740 metres west	of Blackcoombe Fa	arm, Linkinhorne
problems New ENTRY? No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011899
	CONDITION:		TREND:	Declining
OWNER TYPE: Crown CONTACT: Ann Preston-Jones 07917 642388	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
	OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Prehistoric funerary cist 1.275 kilometres north we	est of Wardbrook I	Farm, Linkinhorne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012043
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Flooding	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Round cairn with central cist on Bearah Common,	1.106 kilometres n	orth of Wardbrook Farm, Linkinhori
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010411
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Two adjacent transhumance huts on Caradon Hill,	450 metres north	of East Caradon Farm, Linkinhorne
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1011900
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Two cairns, centred 82 metres and 110 metres so	uth west of Carado	n Hill summit, Linkinhorne
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1011810
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth - General	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Neolithic long cairn, prehistoric regular and irregul enclosure 625 metres west of Blackcoombe Farm,	ar aggregate field s Linkinhorne / Nort	ystems, linear boundaries and mediev th Hill
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010221
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Medieval and post-medieval tin and copper mines v northern slopes of Caradon Hill, Linkinhorne / St.		system on the middle and lower
DESIGNATION:	Scheduled Monument, 2 LBs, part in CA, WHS	LIST ENTRY NUMBER:	1020942
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
ITE NAME:	Castle an Dinas, Ludgvan		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1006725
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В

implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Round 450 yards (405 metres) north west of Lowe	er Chellew Farm, L	udgvan
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004262
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Innis Downs earthwork, Luxulyan		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006684
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Ancient village and fields at Boswarva Carn, Madro	'n	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004466
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
GITE NAME:	Courtyard houses north east of Newmill, Madron		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004356
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Hut circles with associated field system 400 yards	(360 metres) south	west of Little Higher Bosullow, Madr
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1004316
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Round 300 yards (270 metres) north east of Newr	nill, Madron	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004627
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Settlement 450 yards (400 metres) north west of I	Middle Carnaquidde	en, Madron
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003100
CONDITION:	Extensive significant problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	St Madron Well 500 yards (460 metres) south east	t of Boswarthen, M	adron
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004310
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Flooding	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Village settlement north of Bodrifty, Madron		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004481
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Barrow 800 yards (730 metres) WNW of Boswen	s Farm, Madron / S	t. Just
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004286
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Cawsand Fort, Maker-with-Rame		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1016102
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Earthwork redoubts Nos. 1, 2 and 3, Maker-with-F	Rame	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004254
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Grenville Battery 550 yards (500 metres) SSW of I	Maker Farm, Maker	-with-Rame
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1003114
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Plant growth - General	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Incomplete Palmerstonian fort 650 yards (600 met	res) west of Forder	r, Maker-with-Rame
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007299
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT KISK 2021 / SOU	JTH WEST / CORNWALL (UA)		
SITE NAME:	Mount Edgcumbe round barrow, Maker-with-Ram	e	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004496
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	No. 5 redoubt 450 yards (410 metres) north west	of Maker Farm, Ma	ker-with-Rame
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1004255
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY ?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Hillfort at Blacketon Farm, Menheniot		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007296
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Insworke Chapel, Millbrook		
DESIGNATION:	Scheduled Monument, LB grade II*	LIST ENTRY NUMBER:	1003095
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Round barrow on Bin Down, Morval		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006651
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Group of four round barrows east of Bottaboroug	sh, Kilkhampton / M	lorwenstow
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004402
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Group of round barrows south west of Penhale, M	1ullion	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004444
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Trevelgue promontory camp and two barrows, Ne	ewquay	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006712
CONDITION:	Extensive significant problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Battens Cross, one of three medieval wayside cros	sses 70 metres sout	h west of Trebartha Hall, North Hill
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012045
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Hut circle settlement 975 metres north east of Tro	ewortha Farm, Nor	th Hill
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009806
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric co-axial and regular aggregate field syst on Bastreet Downs, south of Bowda Farm, North	ems with incorpora Hill	ted and adjacent hut circle settlemen
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011558
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Mabel Barrow, Polperro		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006683
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Round cairn 1,175 metres WSW of East Castick F	arm, North Hill	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010412
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Stone hut circle 1,225 metres WSW of East Castic	ck Farm, North Hill	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010414
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
	problems		
	Scrub/tree growth	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY: OWNER TYPE:		NEW ENTRY?: CONTACT:	No Ann Preston-Jones 07917 642388

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

Balack KINNScheduled MonumentBala Bala StableCORRATIONGenerally unsatisfactory with major localised manonNov OrthinNoKINCOLULUDABUTYScrub/Tree growthNov OrthinNoKINCOLULUDABUTYCrownCorronCorronCorronKINCOLULUDABUTYCrownCorronCorronCorronKINCOLULUDABUTYCrownCorronCorronMonumentKINCOLULUDABUTYScrub/Tree growthMajor Interest on Hut circles and adjacent prehistoric boursNoKINCOLULUDABUTYScrub/Tree growthNoNoKINCOLULUDABUTYScrub/Tree growthKINCOLULUNoKINCOLULUDABUTYScrub/Tree growthKINCOLULUNoKINCOLULUDABUTYScrub/Tree growthKINCOLULUNoKINCOLULUDABUTYScrub/Tree growthKINCOLULUNoKINCOLULUDABUTYScrub/Tree growthKINCOLULUDABUTYNoKINCOLULUDABUTYScrub/Tree growthKINCOLULUDABUTYNoKINCOLULUDABUTYScrub/Tree growthKINCOLULUDABUTYNoKINCOLULUDABUTYScrub/Tree growthKINCOLULUDABUTYNoKINCOLULUDABUTYScrub/Tree growthKINCOLULUDABUTYNoKINCOLULUDABUTYScrub/Tree growthKINCOLULUDABUTYNoKINCOLULUDABUTYScrub/Tree growthKINCOLULUDABUTYNoKINCOLULUDABUTYScheduled MonumentKINCOLULUDABUTYNoKINNCOLULUDABUTYScheduled MonumentKINCOLULUDABUTYNoKINNCOLULUDABUTYScheduled Monum	SITE NAME:	Three adjoining prehistoric linear boundaries on B Farm, North Hill	earah Tor, 687 met	tres south west of Nodmans Bowda
problems problems Note that Mathematical Mathematical BissicRAL MULERAWUP: Corver No No Struct Market Three stone hut circles 1.06 kilometres north east of Treworths Farm. North Hill 1009807 Descentron Generally unstatisfactory with major localised 19440 No Struct Market Generally unstatisfactory with major localised 19440 No Struct Market Three stone hut circles and adjacent prehistoric but Market Market 1010218 Struct Market Three stone hut circles and adjacent prehistoric but Market Market 1010218 Struct Market Three stone hut circles and adjacent prehistoric but Market 1010218 Struct Market Growen Tree 1010218 Declining Struct Market Struct Market No Declining Struct Market Goldherring Birtish village. Sancreed No Declining Struct Market Goldhe	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010220
ZMMARK TITP: Crown CONTACT: Ann Preston-jones 07917 642388 ITE MARK- Three stone hut circles 1.06 kilometres north east of Trewortha Farm, North Hill ID09807 Scheduled Monument IDD STEMERY NUMBERS 1009807 Scheduled Monument IDD STEMERY NUMBERS 1009807 Scheduled Monument IDD STEMERY NUMBERS No Scheduled Monument Stable No Scheduled Monument IDD STREW NUMBERS No Scheduled Monument IDD STREW NUMBERS 1010218 Scheduled Monument IDD STREW No Scheduled Monument	CONDITION:		TREND:	Stable
State Three stone hut circles 1.06 kilometres north east of Treworths Farm, North Hill DEBRAME Scheduled Monument LET CMM* NUMER [009007 CEREMINAN Scheduled Monument LET CMM* NUMER [009007 CEREMINAN Scheduled Monument LET CMM* NUMER No MINICIPAL VICTORES Scrub/ tree growth No No MINICIPAL VICTORES Crown CONTACT: Ann Preston-Jones 07917 642388 MINICIPAL VICTORES Crown CONTACT: No SERVERNIES Scheduled Monument LET ENTER NUMER 1010218 SERVERNIES Scheduled Monument LET ENTER NUMER 100218 SERVERNIES Scrub/tree growth No Declining STRICTAL VICUERNIES Scrub/tree growth No No STRICTAL VICUERNIES Scrub/tree growth No Declining STRICTAL VICUERNIES Scrub/tree growth No No STRICTAL VICUERNIES Goldherring British village, Sacreed No No Streeter TM* Goldherring British village, Sacreed No No	PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
Scheduled Monument LIST DATA NUMBER: 1009807 Contonion: Greenarily unsatisfactory with major localised presidems. Taske: Stable PRINCEML VULNEMABUTT: Scrub/tree growth New ENTRY: No Data Taske: Two stone hut circles and adjacent prehistoric bourdary wall 575 metres west of West Berriow Farm, Nor Hill 1010218 Data Taske: Two stone hut circles and adjacent prehistoric bourdary wall 575 metres west of West Berriow Farm, Nor Hill 1010218 Descination: Scheduled Monument IST FATRY NUMBER: 1010218 Descination: Scheduled Monument IST FATRY NUMBER: 1010218 Descination: Goldherring British village, Sancreed Declinaing No Descination: Scheduled Monument UST ENTRY NUMBER: No Descination: Scheduled Monument UST ENTRY NUMBER: No Descination: Scheduled Monument UST ENTRY NUMBER: No DESIGNATION: Scheduled Monument UST ENTRY NUMBER: No DESIGNATION: Scheduled Monument UST ENTRY NUMBER: No DESIGNATION: Scheduled Monument	OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
Control Control Control Stable RENCOM FURNERAL Sendelman TEDD: Stable RENCOM FURNERAL Scrub/tree growth Nov Nov Data Rencom Convert Control: Ann Preston-Jones 07917 642388 data Rate: Two stone hut circles and adjacent prehistoric bourdary wall 575 metres West Berriow Farm, Nor Data Rate: Scheduled Monument UST BATTY NUMBER Declining Data Rate: Scheduled Monument UST BATTY NUMBER Declining Data Rate: Scheduled Monument UST BATTY NUMBER No Data Rate: Control: Control: Ann Preston-Jones 07917 642388 RENCAULULATURALITY: Scheduled Monument UST BATTY NUMBER No Data Rate: Control: Control: No CONTRO: Scheduled Monument UST BATTY NUMBER No CONTRO: Generally satisfactory with with significant localised problems IRENO: Contro: No CONTRO: Generally satisfactory with major localised problems IRENO: Contro: No	ITE NAME:	Three stone hut circles 1.06 kilometres north east	of Trewortha Farr	n, North Hill
NatureproblemsproblemsNoticeStatuteNext DATUREScrub/tree growthNext DATURTNoNext DATURTCrownCONTACTAnn Preston-Jones 07917 642388TRE NAMETwo stone hut circles and adjacent prehistoric bu-try wall S75 metres1010218ESEGNATION:Scheduled MonumentUST DATTRY NUMBER:1010218CONDICION:Generally unsatisfactory with major localised problemsTREND:DecliningREACEAN UNERNALITY:Scrub/tree growthNEW DATRY:NoSAMEE TIFFEContinencial companyCONTACT:Ann Preston-Jones 07917 642388TRE NAME:Goldherring British village, SancreedUST DATRY NUMBER:1004651DECININGGenerally statisfactory but with significant localised problemsTREND:DecliningSINCRAUUNERNALITY:BrackenNew DATRY:NoCONDICION:Generally statisfactory but with significant localised problemsTREND:NoSINCRAUUNERNALITY:BrackenNew DATRY:NoSINCRAUUNERNALITY:BrackenNew DATRY:NoSINCRAUUNERNALITY:BrackenUnernot for profit groupCONTACT:Ann Preston-Jones 07917 642388TITE NAME:Unerclosed hut circle settlement and adjacent prehistoric linear but-tirceNoSINCRAUUNERNALITY:BrackenNew DATRY:NoSINCRAUUNERNALITY:Scheduled MonumentUST ENTRY NUMER:1008958SINCRAUUNERNALITY:Scheduled MonumentUST ENTRY NUMER:1008954SINCRAUUNERNALITY:<	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009807
NUMER TIPECrownCONTACT:Ann Preston-Jones 07917 642388ATE NAME:Two stone hut circles and adjacent prehistoric bourder wills 75 metrose of West Berriow Farm, NotDEGIOATION:Scheduled MonumentUST ENTRY NUMER:1010218DEGIONITON:Generally unstatisfactory with major localisedIRENO:DecliningRINCERN VULKTARUUT:Schub/tree growthNew ENTRY:NoOWNER TIPE:Goldherring British village. SanceedUST ENTRY NUMER:1004651DEGIONITON:Generally satisfactory but with significant localisedIRENO:DecliningRINCERN VULKTARUUT:Scheduled MonumentUST ENTRY NUMER:1004651DOMOTON:Generally satisfactory but with significant localisedIRENO:DecliningRINCERN VULKTARUUT:BrackenNew ENTRY:NoRINCERN VULKTARUUT:BrackenINFEND:Monument:INFEND:DEGIONITON:Generally satisfactory with major localisedIRENO:StableRINCERN VULKTARUUT:Scheduled MonumentINFEND:NoDEGIONITON:Generally unstatisfactory with major localisedIRENO:NoRINCERN VULKTARUUT:Scheduled MonumentINFEND:NoRINCERN VULKTARUUT:Scheduled MonumentINFEND:NoRINCERN VULKTARUUT:Scheduled MonumentINFEND:NoRINCERN VULKTARUUT:Scheduled MonumentINFEND:NoRINCERN VULKTARUUT:Scheduled MonumentINFEND:NoRINCERN VULKTARUUT:Scheduled MonumentINFEND:No<	CONDITION:		TREND:	Stable
ATTE NAME: Two stone hut circles and adjacent prehistoric bourdary wall 575 metres west of West Berriow Farm, Not ATTE NAME: Scheduled Monument ust ENTRY NUMBER: 101018 CONDITION Generally unsatisfactory with major localised TRND: Declining RENORAL VULBERABUTY: Scrub/tree growth NEW ENTRY: No SYNDRETTE: Goldherring British village, Sancreed International Scheduled Monument USTENTRY NUMBER: 1004651 CONDITION Generally satisfactory but with significant localised TRND: No CONDITION Generally satisfactory but with significant localised TRND: No CONDITION Generally satisfactory but with significant localised TRND: No CONDITION Generally satisfactory but with significant localised TRND: No CONDITION Generally unsatisfactory with major localised TRND: No MILE NAME: Checkuled Monument USE ENTRY NUMBER: 1008958 CONDITION Generally unsatisfactory with major localised TRND: Stable CONDITION Generally unsatisfactory with major localised TRND: No CONDITION Generally unsatisfactory with	PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
Hill Hill USE ENTRY NUMBER IO10218 DEGIONATION: Scheduled Monument USE ENTRY NUMBER I010218 DEGIONATION: Generally unsattifactory with major localised TREND: Declining SERICARL VULRERABUTY: Scrub / tree growth NEW ENTRY: No OWNER TYPE: Collderring British village, Sancreed USE ENTRY NUMBER 1004651 Scheduled Monument USE ENTRY NUMBER 1004651 Declining CONTON: Scheduled Monument USE ENTRY NUMBER 1004651 CONDITION: Scheduled Monument USE ENTRY NUMBER 1004651 CONDITION: Bracken NEW ENTRY: No DENDERSTYFE Other not for profit group CONTACT: Ann Preston-Jones 07917 642388 CONDITION: Scheduled Monument ust ENTRY NUMBER 1008958 ENERGIPAL VULNERABUTY: Scheduled Monument ust ENTRY NUMBER 1008958 CONDITION: Generally unsatisfactory with major localised TREND: Scable CONDITION: Generally Unsatisfactory with major localised TREND: Scable	OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningRINCTION VULNERABILITY:Scrub / tree growthNEW ENTRY:NoRINCTION VULNERABILITY:Goldherring British village, SancreedUST ENTRY NUMBER100451RESONATION:Scheduled MonumentUST ENTRY NUMBER100451ConstractionGrenarily satisfactory but with significant localised problemsIREND:DecliningRINCIPAL VULNERABILITY:BrackenNEW ENTRY:NoWINTERTY:BrackenCONTACT:Ann Preston-Jones 07917 642388RINCIPAL VULNERABILITY:BrackenScheduled MonumentUST ENTRY NUMBER1008958RINCIPAL VULNERABILITY:Scheduled MonumentUST ENTRY NUMBER1008958ENDERONAL VULNERABILITY:Scheduled MonumentUST ENTRY NUMBER1008959ENDERONAL VULNERABILITY:Scheduled MonumentUST ENTRY NUMBER1008951ENDERONAL VULNERABILITY:Scheduled MonumentUST ENTRY NUMBER1008954ENDERONAL VULNERABILITY:BrackenNo1ENDERONAL VULNERABILITY:Scheduled MonumentUST ENTRY NUMBER1008954ENDERONAL VULNERABILITY:BrackenNo1 </td <td>ITE NAME:</td> <td></td> <td>ındary wall 575 me</td> <td>tres west of West Berriow Farm, No</td>	ITE NAME:		ındary wall 575 me	tres west of West Berriow Farm, No
problemsproblemsintenderintenderpedimingRINCIPAL VULNERABULTY:Scrub/tree growthNeW ENTRY:NoOWNER TYPE:Commercial companyCONTACT:Ann Preston-Jones 07917 642388UTE NAME:Goldherring British village, SancreedUST ENTRY NUMBER:1004651USEGRATION:Scheduled MonumentLIST ENTRY NUMBER:1004651CONTACT:Scheduled MonumentINFERENCEDecliningCONTACT:BrackenNew ENTRY:NoSIRICIPAL VULNERABULTY:BrackenNEW ENTRY:NoWINDER TYPE:Other not for profit groupCONTACT:Ann Preston-Jones 07917 642388THE NAME:Unenclosed hut circle settlement and adjacent privite inter bourset SEE of Treworthal fram, North HillIST ENTRY NUMBER:1008958RINCIPAL VULNERABULTY:Scheduled MonumentLIST ENTRY NUMBER:1008958RINCIPAL VULNERABULTY:Scheduled MonumentNoStableCONDITION:Generally unsatifiatory with major localised problemsNoStableRINCIPAL VULNERABULTY:UNROWNCONTACT:NoRINCIPAL VULNERABULTY:Scheduled MonumentLIST ENTRY NUMBER:1008954RINCIPAL: VULNERABULTY:Scheduled MonumentIST ENTRY NUMBER:1008954RINCIPAL VULNERABULTY:BrackenNoStableRINCIPAL VULNERABULTY:BrackenNoStableRINCIPAL VULNERABULTY:BrackenNoStableRINCIPAL VULNERABULTY:BrackenNoStableRINCIPA	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010218
WANNER TYPE:Commercial companyCONTACT:Ann Preston-Jones 07917 642388THE NAME:Goldherring British village, SancreedUSTE NITRY NUMBER100451DESIGNATION:Scheduled MonumentUSTE NITRY NUMBER100451CONDITION:BrackenNew ENTRY:NoRINCIPAL VULNERABULTY:BrackenNEW ENTRY:NoWILLER TYPE:Other not for profit groupCONTACT:Ann Preston-Jones 07917 642388MIRE NAME:Unenclosed hut circle settlement and adjacent province innear bound statisfactory with major localisedINEN DURING SET NUMBER1008958RINCIPAL VULNERABULTY:Scheduled MonumentUSE ENTRY:NoNoSCHODITION:Generally unsatisfactory with major localisedINEN DURING SET NUMBERNoCONDITION:Scheduled MonumentUSE ENTRY:NoSCHODITION:Scheduled MonumentUSE ENTRY:NoSCHODITION:Scheduled MonumentUSE ENTRY NUMBER1008954SCHODITION:Scheduled MonumentUSE ENTRY NUMBER1008954SCHODITION:Scheduled MonumentUSE ENTRY NUMBER1008954SCHODITION:Scheduled MonumentUSE ENTRY NUMBERNoSCHODITION:BrackenNoStableSCHODITION:BrackenNONCONTACT:NoSCHODITION:Scheduled MonumentUSE ENTRY NUMBER1008954SCHODITION:BrackenScheduled MonumentUSE ENTRY NUMBERNoSCHODITION:Scheduled MonumentUSE ENTRY NUMBER1004289<	CONDITION:		TREND:	Declining
ATTE NAME: Goldherring British village, Sancreed DesiGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004651 Declining Declining Declining SCHOUTION: Generally satisfactory but with significant localised problems NEW ENTRY: No SIGNER TYPE: Other not for profit group CONTACT: Ann Preston-Jones 07917 642388 ATTE NAME: Unenclosed hut circle settlement and adjacent problems: V800 metres SSE of Trewortha Parm, North Hill Scheduled Monument LIST ENTRY NUMBER: 1008958 CONDITION: Generally unsatisfactory with major localised problems TREND: Stable CONDITION: Generally unsatisfactory with major localised problems NEW ENTRY: No RINCIPAL VULNERABILITY: Scrub / tree growth NEW ENTRY: No ANNER TYPE: Unknown CONTACT: Ann Preston-Jones 07917 642388 ATTE NAME: Scheduled Monument LIST ENTRY NUMBER: 1008954 CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1008954 CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1008954 CONDITION: Scheduled Monument	PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
Designation: Scheduled Monument List ENTRY NUMBER 1004651 CONDITION: Generally satisfactory but with significant localised problems TREND: Declining RINCIRAL VULNERABILITY: Bracken NEW ENTRY: No OWNER TYPE: Other not for profit group CONTACT: Ann Preston-Jones 07917 642388 ATE NAME: Desclosed hut circle settlement and adjacent prebi-toric linear bounters SSE of Trewortha Farm, North Hill IST ENTRY NUMBER: 1008958 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1008958 CONDITION: Generally unsatisfactory with major localised problems REND: Stable Scheduled Monument LIST ENTRY NUMBER: No ISSEGNATION: CONDITION: Generally unsatisfactory with major localised problems REND: No Stable Unknown CONTACT: Ann Preston-Jones 07917 642388 ITTE NAME: Uneclosed hut circle settlement with incorporate triclosure 1.5 kilfer ModeS1 CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1008954 CONDITION: Bracken No Stable	OWNER TYPE:	Commercial company	CONTACT:	Ann Preston-Jones 07917 642388
KONDITION:Generally satisfactory but with significant localised problemsTREND:DeckningRINCIPAL VULNERABILITY:BrackenNEW ENTRY:NoWYNER TYPE:Other not for profit groupCONTACT:Ann Preston-Jones 07917 642388ITE NAME:Jeneclosed hut circle settlement and adjacent problemsIO08958IESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1008958IGNODITION:GrobelmsINEND:StableINNER TYPE:Vulnkrew growthNEW ENTRY:NoINNER TYPE:UnknownCONTACT:Ann Preston-Jones 07917 642388ITE NAME:Scheduled MonumentINEND:StableITE NAME:Schuler growthNEW ENTRY:NoITE NAME:Scheduled MonumentINTE NUTRY NUMBER:1008954INNER TYPE:Scheduled MonumentINTE NITRY NUMBER:1008954INNER TYPE:Scheduled MonumentINTE NITRY NUMBER:1008954INNER TYPE:Ondractific settlement with incorporated Extrement Set of WardbrookNoINNER TYPE:Scheduled MonumentINTE NITRY NUMBER:1008954INNER TYPE:Ondractific settlement Set of Set of Care TestNoINNER TYPE:UnknownNEW ENTRY:NoINNER TYPE:Other of Care TestNoINNER TYPE:UnknownINTE NITRY NUMBER:NoINNER TYPE:UnknownINTE NITRY:NoINNER TYPE:Other of Care TestINTERNONoINNER TYPE:Scheduled MonumentINTE NITRY:NO	ITE NAME:	Goldherring British village, Sancreed		
AND CALLproblemsNote of the profileRINCEAL VULNERABILITY:BrackenNEW ENTRY:NoRINCEAL VULNERABILITY:Deter not for profit groupCONTACT:Ann Preston-Jones 07917 642388WINER TYPE:Unenclosed hut circle settlement and adjacent problemsNoRENAME:Long-Closed hut circle settlement and adjacent problems1008958RENAME:Scheduled MonumentLIST ENTRY NUMBER:1008958CONDITION:Generally unsatisfactory with major localisedTREND:StableRINCIPAL VULNERABILITY:Scrub/tree growthNEW ENTRY:NoRINCIPAL VULNERABILITY:Scheduled MonumentCONTACT:Ann Preston-Jones 07917 642388RINCIPAL VULNERABILITY:Scheduled MonumentCONTACT:NoRINCIPAL VULNERABILITY:Scheduled MonumentUIST ENTRY NUMBER:1008954RINCIPAL VULNERABILITY:Scheduled MonumentLIST ENTRY NUMBER:1008954CONDITION:Generally unsatisfactory with major localised problemsTREND:StableCONDITION:Generally unsatisfactory with major localised problemsTREND:StableCONDITION:Scheduled MonumentLIST ENTRY NUMBER:NoRINCIPAL VULNERABILITY:BrackenNEW ENTRY:NoRINCIPAL VULNERABILITY:Scheduled MonumentLIST ENTRY NUMBER:1004289RINCIPAL VULNERABILITY:Scheduled MonumentLIST ENTRY NUMBER:1004289RINCIPAL VULNERABILITY:Scheduled MonumentLIST ENTRY NUMBER:1004289RINCIPAL VULNERABILITY: </td <td>esignation:</td> <td>Scheduled Monument</td> <td>LIST ENTRY NUMBER:</td> <td>1004651</td>	esignation:	Scheduled Monument	LIST ENTRY NUMBER:	1004651
WNRER TYPE:Other not for profit groupCONTACT:Ann Preston-Jones 07917 642388HTE NAME:Unenclosed hut circle settlement and adjacent pre-burst-ic linear bourst-sets SSE of TreworthanPERGNATION:Scheduled MonumentUST ENTRY NUMBER1008958CONDITION:Generally unsatisfactory with major localisedNEW ENTRY:StableRINCIPAL VULNERABILITY:Scrub/tree growthNEW ENTRY:NoWINER TYPE:UnknownCONTACT:Non Preston-Jones 07917 642388TE NAME:Unenclosed hut circle settlement with incorporateIST ENTRY NUMBER1008954VERGNATION:Scheduled MonumentUST ENTRY NUMBER1008954CONDITION:Generally unsatisfactory with major localisedIST ENTRY NUMBER1008954CONDITION:Generally unsatisfactory with major localisedNEW ENTRY:NoCONDITION:BrackenNEW ENTRY:NoRINCIPAL VULNERABILITY:BrackenCONTACT:NoNUMER TYPE:UnknownCONTACT:NoVENER TYPE:Non Officing (Office Setter S	CONDITION:		TREND:	Declining
ITTE NAME: Henclosed hut circle settlement and adjacent prehistoric linear bounders SSE of Trewortha Farm, North Hill DESIGNATION: Scheduled Monument LIST ENTRY NUMBER 1008958 CONDITION: Generally unsatisfactory with major localised problems TREND: Stable RINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY?: No WINER TYPE: Unknown CONTACT: Ann Preston-Jones 07917 642388 ATTE NAME: Unenclosed hut circle settlement with incorporated enclosure 1.5 kill Marces of Wardbrook DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1008954 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1008954 CONDITION: Generally unsatisfactory with major localised problems REND: Stable CONDITION: Bracken NEW ENTRY: No Stable Unknown CONTACT: Ann Preston-Jones 07917 642388 CONDITION: Bracken NEW ENTRY: No Stable CONTACT: No Stable Stable Stable CONDITION: Bracken NEW ENTRY: No Stable Stable	RINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
Farm, North Hill LIST ENTRY NUMBER 1008958 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER 1008958 DONDITION: Generally unsatisfactory with major localised problems New ENTRY: Stable RINCIPAL VULNERABILITY: Scrub / tree growth New ENTRY: No DWNER TYPE: Unknown CONTACT: Ann Preston-Jones 07917 642388 ITE NAME: Farm, North Hill Stable 1008954 DESIGNATION: Scheduled Monument UST ENTRY NUMBER 1008954 DESIGNATION: Scheduled Monument UST ENTRY NUMBER 1008954 DONDITION: Generally unsatisfactory with major localised problems INEW ENTRY: No DESIGNATION: Scheduled Monument UST ENTRY NUMBER 1008954 DONDITION: Generally unsatisfactory with major localised problems New ENTRY: No DEVENTRYPE: Unknown CONTACT: Ann Preston-Jones 07917 642388 TITE NAME: Round 100 yards (90 metres) east of Caer Bran, Surgers Interve DESIGNATION: Scheduled Monument UST ENTRY NUMBER 1004289 DESIGNATION: Scheduled Monument UST ENTRY	DWNER TYPE:	Other not for profit group	CONTACT:	Ann Preston-Jones 07917 642388
CONDITION:Generally unsatisfactory with major localised problemsTREND:StableRINCIPAL VULNERABILITY:Scrub/tree growthNEW ENTRY:NoDWNER TYPE:UnknownCONTACT:Ann Preston-Jones 07917 642388HE NAME:Denclosed hut circle settlement with incorporate Versure 1.5 killerScheduled MonumentIST ENTRY NUMBERDESIGNATION:Scheduled MonumentIST ENTRY NUMBER1008954CONDITION:Generally unsatisfactory with major localisedTREND:StableCONDITION:BrackenNEW ENTRY:NoDANNORDUnknownCONTACT:NoDESIGNATION:Scheduled MonumentNEW ENTRY:NoCONDITION:BrackenNEW ENTRY:NoDONDERT TYPE:Scheduled MonumentNEW ENTRY:NoDESIGNATION:Scheduled MonumentIST ENTRY NUMBER104289DESIGNATION:Scheduled MonumentIST ENTRY NUMBER104289DESIGNATION:Scheduled MonumentIST ENTRY NUMBER104289CONDITION:Scheduled MonumentIST ENTRY NUMBER104289CONDITION:Generally unsatisfactory with major localisedIST ENTRY NUMBER104289CONDITION:BrackenIST ENTRY NUMBERIST ENTRY NUMBERIST ENTRY NUMBERDESIGNATION:Scheduled MonumentIST ENTRY NUMBER104289CONDITION:BrackenIST ENTRY NUMBERIST ENTRY NUMBERIST ENTRY NUMBERDESIGNATION:Scheduled MonumentIST ENTRY NUMBERIST ENTRY NUMBERIST ENTRY	DITE NAME:	Unenclosed hut circle settlement and adjacent pre Farm, North Hill	historic linear bour	ndary 800 metres SSE of Trewortha
problemsproblemsNote of the of	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008958
DWNER TYPE:UnknownCONTACT:Ann Preston-Jones 07917 642388ATE NAME:Unenclosed hut circle settlement with incorporated enclosure 1.5 kilosement with west of WardbrookDesignation:Scheduled MonumentUST ENTRY NUMBER:1008954Designation:Scheduled MonumentIST ENTRY NUMBER:1008954CONDITION:Generally unsatisfactory with major localised problemsTREND:StableCONTACT:BrackenNEW ENTRY:NoDWNER TYPE:UnknownCONTACT:Ann Preston-Jones 07917 642388ATE NAME:Round 100 yards (90 metres) east of Caer Bran, SarreetIST ENTRY NUMBER:1004289DESIGNATION:Scheduled MonumentUST ENTRY NUMBER:1004289CONDITION:Generally unsatisfactory with major localised problemsTREND:1004289CONDITION:Scheduled MonumentIST ENTRY NUMBER:1004289CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningCONDITION:BrackenNEW ENTRY:No	CONDITION:		TREND:	Stable
ITE NAME: Unenclosed hut circle settlement with incorporated enclosure 1.5 ki/setters north west of Wardbrook DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1008954 CONDITION: Generally unsatisfactory with major localised problems TREND: Stable CONDITION: Bracken NEW ENTRY: No DWNRET TYPE: Unknown CONTACT: Ann Preston-Jones 07917 642388 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004289 DESIGNATION: Scheduled Monument IST ENTRY NUMBER: 1004289 OWNER TYPE: Destination: Scheduled Monument IST ENTRY NUMBER: DESIGNATION: Scheduled Monument IST ENTRY NUMBER: 1004289 CONDITION: Generally unsatisfactory with major localised problems ITREND: Dockage CONDITION: Scheduled Monument IST ENTRY NUMBER: IST ENTRY NUMBER: IST ENTRY NUMBER: CONDITION: Scheduled Monument IST ENTRY NUMBER: IST ENTRY NUMBER: IST ENTRY NUMBER: CONDITION: Scheduled Monument IST ENTRY NUMBER: IST ENTRY NUMBER: IST ENTRY NUMBER: CONDITION: Bracken Monument </td <td>PRINCIPAL VULNERABILITY:</td> <td>Scrub/tree growth</td> <td>NEW ENTRY ?:</td> <td>No</td>	PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No
Initial and the service of the serv	OWNER TYPE:	Unknown	CONTACT:	Ann Preston-Jones 07917 642388
CONDITION:Generally unsatisfactory with major localised problemsTREND:StableRINCIPAL VULNERABILITY:BrackenNew ENTRY:NoDWNER TYPE:UnknownCONTACT:Ann Preston-Jones 07917 642388MITE NAME:Round 100 yards (90 metres) east of Caer Bran, SaccentInternational Scheduled MonumentDESIGNATION:Scheduled MonumentInternational Scheduled MonumentInternational Scheduled MonumentCONDITION:Generally unsatisfactory with major localised problemsInternational Scheduled MonumentInternational Scheduled MonumentRINCIPAL VULNERABILITY:BrackenNew ENTRY:No	DITE NAME:		d enclosure 1.5 kild	ometres north west of Wardbrook
problemsproblemsNoPRINCIPAL VULNERABILITY:BrackenNew ENTRY?:NoDOWNER TYPE:UnknownCONTACT:Ann Preston-Jones 07917 642388SITE NAME:Round 100 yards (90 metres) east of Caer Bran, SarreedInterventionDesignation:Scheduled MonumentLIST ENTRY NUMBER:1004289CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningRRINCIPAL VULNERABILITY:BrackenNEW ENTRY?:No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008954
DWNER TYPE:UnknownCONTACT:Ann Preston-Jones 07917 642388ARTE NAME:Round 100 yards (90 metres) east of Caer Bran, Sar- Forsignation:IST ENTRY NUMBER1004289DESIGNATION:Scheduled MonumentIST ENTRY NUMBER1004289CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningRINCIPAL VULNERABILITY:BrackenNEW ENTRY:No	CONDITION:		TREND:	Stable
STTE NAME: Round 100 yards (90 metres) east of Caer Bran, Sancreed DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004289 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining RINCIPAL VULNERABILITY: Bracken NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY ?:	No
Designation: Scheduled Monument LIST ENTRY NUMBER: 1004289 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining RINCIPAL VULNERABILITY: Bracken NEW ENTRY?: No	OWNER TYPE:	Unknown	CONTACT:	Ann Preston-Jones 07917 642388
CONDITION: Generally unsatisfactory with major localised problems TREND: Declining RINCIPAL VULNERABILITY: Bracken NEW ENTRY?: No	ITE NAME:	Round 100 yards (90 metres) east of Caer Bran, Sa	ancreed	
RINCIPAL VULNERABILITY: Bracken NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004289
	CONDITION:		TREND:	Declining
DWNER TYPE: Private CONTACT: Ann Preston-Jones 07917 642388	PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY ?:	No
	OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Two adjacent prehistoric coaxial field systems inco and medieval fields on East Moor and Ridge, Altarn	rporating regular fi iun / North Hill	eld systems, stone hut circles, cairns
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008439
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Three barrows 550 metres ENE of Cansford, Otte	rham	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005463
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Maen (or Mayon) Castle, Sennen		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006757
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Visitor erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Roundago, hut circle and field system on Castallack	c Carn, "St. Buryan	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004654
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Bake Rings later prehistoric-Roman round with att	ached enclosure an	d outwork, Pelynt
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017682
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Group of three round barrows north of Hendra, P	elynt	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004621
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	King Arthur's Hall, St. Breward		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006706
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / SOU	JTH WEST / CORNWALL (UA)		
SITE NAME:	Glasney College, Penryn		
DESIGNATION:	Scheduled Monument, LB grade II, part in CA	LIST ENTRY NUMBER:	1007260
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Lescudjack Castle, Penzance		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003270
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	St Piran's Oratory and associated early medieval ce	emetery, Perranzab	uloe
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1018955
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Flooding	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Nick Russell 0117 975 0671
SITE NAME:	The Tolgus arsenic works 80 metres south east of	East Tolgus House	, Redruth
DESIGNATION:	Scheduled Monument, LB grade II, WHS	LIST ENTRY NUMBER:	1021240
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Botrea barrows, Sancreed		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004467
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Enclosed hut circle settlement and field system, 50	0 metres north we	st of Jericho Farm, Sancreed
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1418283
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Field system on Boswens Common, Sancreed		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007268
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Unknown	CONTACT:	Ann Preston-Jones 07917 642388

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	JTH WEST / CORNWALL (UA)		
SITE NAME:	Hut cluster Chirgwidden Vean, Sancreed		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006715
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Bolster Bank, St. Agnes		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1016444
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY ?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Wheal Kitty C20 tin processing works, St. Agnes		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1021164
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY ?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Promontory fort and Civil War battery, Little Der	inis Head, St. Antho	ny-in-Meneage
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004431
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Black Head promontory fort, St. Austell Bay		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004391
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Stone circle on Emblance Common, St. Breward		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004459
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Unknown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Camp 900 yards (820 metres) south east of St Bur	yan village, "St. Bur	yan
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004483
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. В
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

Decisionational Scheduled Monument, LB grade I URT INTRAMISE 101205 CONDITIONE Generally statisfactory but with significant localised problems move: Scable RENORAL WURDWALTER Other No No OWNER THT: Unknown CONTACT: Ann Preston-Jones 07917 642388 RENORAL WURDWALTER Scheduled Monument Market National Market Nation	SITE NAME:	St Cleer's Well and cross, St. Cleer		
Constraints Generally satisfactory but with significant localised problems Teston Sable NINCORE UNLEXAUTE: Other NEV ONTRY: No OWNER TYPE Unknown CONTRY: Ann Preston-Jones 07917 642388 SILENAME: Round barrow 200 yards (180 metres) north of the Merry Maidens, "Sc. Buryan DodISS Database Constraints Scheduled Monument Data Network Merry DodISS Contract: Scheduled Monument Data Network Merry No Contract: Scheduled Monument, CA Data Network Merry No Contract: Scheduled Monument, CA, WHS Data Network Merry No Contract: Scheduled Monument, CA, WHS Data Network Merry No Scheduled Monument, CA, WHS Data Network Merk 1010323 No </td <td>DESIGNATION:</td> <td>,</td> <td>LIST ENTRY NUMBER:</td> <td>1018205</td>	DESIGNATION:	,	LIST ENTRY NUMBER:	1018205
PRINCIPAL WULKUNAUUTY: Other NO COMMAN 1796 COMMAN 1796 COMMAN 1796 COMMAN 1796 Ann Preston-Jones 07917 642388 STEE NAME Round barrow 200 yards (180 metres) north of the Metry Maidens, "St. Buryan IOM358 DERIGATION Scheduled Monument INTERNET/NUMERA IOM358 DERIGATION Scheduled Monument INTERNET/NUMERA IOM358 RENDERIA WULKERABUTY Scheduled Monument, CA INTERNET/NUMERA IOIS776 RENDERIA TOTAL Scheduled Monument, CA INTERNET/NUMERA IOIS776 RENDERIA WULKERABUTY Scheduled Monument, CA INTERNET/NUMERA IOIS776 RENDERIA WULKERABUTY Scheduled Monument, CA INTERNET/NUMERA IOIS776 RENDERIA WULKERABUTY Scheduled Monument, CA, WHS INTERNET/NUMERA IOIS23 RENDERIA WULKERABUTY Scheduled Monument, CA, WHS INTERNET/NUMERA IOI323 RENDERIA WULKERABUTY Vandalism IOI323 IOI323 RENDERIA WULKERABUTY Vandalism IOI323 IOI323 RENDERIA WULKERABUTY Vandalism IOI323 IOI323 <td>CONDITION:</td> <td>Generally satisfactory but with significant localised</td> <td></td> <td></td>	CONDITION:	Generally satisfactory but with significant localised		
Disknown CDM An Preston-jones 07917 642388 Mar Preston-jones 07917 642388 Scheduled Monument ISS EVERY NUMBER 1004359 Disknown Scheduled Monument ISS EVERY NUMBER 1004359 Disknown Scheduled Monument ISS EVERY NUMBER 1004359 Disknown Scheduled Monument, CA ISS EVERY NUMBER 1004359 Disknown Scheduled Monument, CA ISS EVERY NUMBER 1015976 Disknown Scheduled Monument, CA ISS EVERY NUMBER 1015976 Disknown Scheduled Monument, CA ISS EVERY NUMBER 1015976 Disknown Scheduled Monument, CA ISS EVERY NUMBER No Disknown Scheduled Monument, CA ISS EVERY NUMBER No Disknown Scheduled Monument, CA, WHS ISS EVERY NUMBER ISS EVERY NUMBER No Disknown Scheduled Monument, CA, WHS ISS EVERY NUMBER No ISS EVERY NUMBER ISS EVERY NUMBER ISS EVERY NUMBER ISS EVERY NUMBER No Disknown Scheduled Monument, CA, WHS ISS EVERY NUMER No ISS EVERY NU	PRINCIPAL VULNERABILITY:	•	NEW ENTRY?:	Νο
Design All EVAL Scheduled Monument Ist Hirt NAMESE DO0358 CONDITION Generally unstatisfactory with major localised problems inexts Declining PRINCIPAL VULREARUTT Scrub/tree growth New EVITERS No CONDITION Original Statisfactory with major localised problems Inexts No Stree Add Platform cairn with central mound 375 metrees north west of Treevalla Farm, St. Cleer Declining DESIGNATION Generally satisfactory but with minor localised problems Interce Poleining RENAME Embanked platform cairn with kerbed central mound and outer bank 600 metree seast of Trevalla Farm, St. Cleer No Streaded Platform cairn with kerbed central mound and outer bank 600 metree seast of Trevalla Farm, St. Cleer No Streaded Platform cairn with kerbed central mound and outer bank 600 metree seast of Trevalla Farm, St. Cleer Declining DESIGNATION Scheduled Monument, CA, WHS Unit Entre Numeric Documing Conditional Statisfactory but with significant localised preview Treview Declining DESIGNATION Scheduled Monument, CA, WHS Unit Entre Numeric No DESIGNATION Scheduled Monument, CA, WHS Unit Entre Num	OWNER TYPE:		CONTACT:	
Control of Control of Problems Generally unsatisfactory with major localised problems Deckning RTRINGTUR VOLUME RELITY: Schuldre growth NN CONTACT: Ann Preston-Jones 07917 642388 ATTE NAME Embanked platform cairn with central mound 375 Treves north west 0 DESIGNATION: Scheduled Monument, CA UST 2017/01/100 Declining DESIGNATION: Scheduled Monument, CA UST 2017/01/100 Declining DESIGNATION: Scheduled Monument, CA NO Declining CONTRACT: Controct: No No CONTRACT: Scheduled Monument, CA, VMS NEW ENTRY: No CONTRACT: Verbed platform cairn with kerbed central mound and user bank 600 Declining CONTRACT: Kerbed platform cairn with kerbed central mound and user bank 600 Declining CONTRACT: Vandalism No Declining CONTRACT: Vandalism No Declining CONTRACT: Vandalism No No CONTRACT: Vandalism No No CONTRACT: Probistoric c	SITE NAME:	Round barrow 200 yards (180 metres) north of the	e Merry Maidens, "S	St. Buryan
Construction problems	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004358
DWNERTITE Private CONTACT: Ann Preston-Jones 07917 642388 STRENAME: Embanked platform cairn with central mound 375 == tree north west of Trewalls Farm, St. Cleer DEBIGNATION: Scheduled Monument, CA UST PATKY NUMBER Declining CONDENT: Scheduled Monument, CA INET PATKY NUMBER Declining CONDENT: Scheduled Monument, CA INET PATKY NUMBER Declining CONDENT: Scheduled Monument, CA, WHS INET PATKY NUMBER INET PATKY CONDENT: Scheduled Monument, CA, WHS UST ENTRY NUMBER ID0323 STEENAME: Scheduled Monument, CA, WHS UST ENTRY NUMBER ID0323 CONDENT Freistoric cist, cairns and cairnfield on north east SMIRY No Streament: Previsitoric cist, cairns and cairnfield on north east SMIRY No Streament: Previsitoric cist, cairns and cairnfield on north east SMIRY No Streament: Previsitoric cist, cairns and cairnfield on north east SMIRY No Streament: Previsitoric cist, cairns and cairnfield on north east SMIRY No Streament: Previsitoric cist, cairns and cairnfield on north east SMIRY N	CONDITION:		TREND:	Declining
Antice Embanked platform cairn with central mound 375 metres north west of Trewalla Farm, St. Cleer Designation: Scheduled Monument, CA List BHRY NUMSEL 1015976 CONDITION: Generally satisfactory but with minor localised TREMD: Declining PRINCIPAL VULNERABUTY: Scrub / tree growth NEW ENTRY: No OWNERT TYPE: Private CONTACT: Ann Preston-jones 07917 642388 SHE NAME: Kerbed platform cairn with kerbed central mound and outer bank 600 metres east of Trewalla Farm, St. Cleer DESIGNATION: Scheduled Monument, CA, WHS LIST ENTRY NUMSER: 1010323 CONTACT: Ann Preston-jones 07917 642388 MIRE NAME: Cleer Declining DESIGNATION: Scheduled Monument, CA, WHS LIST ENTRY NUMSER: 1010323 CONTACT: Ann Preston-jones 07917 642388 MIRE NAME: Prehistoric cist, cairns and cairnfield on north east Smallacoombe Downs, S70 metres north west of Smallacombe Tor, St. Cleer No DESIGNATION: Scheduled Monument LIST ENTRY NUMSER: 101630 CONTACT: Ann Preston-jones 07917 642388 Stable STEE NAME: Prehistoric cist, cairns and cairnfield on north east Smallacoombe Tor, St. Cleer	PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
Designation:Scheduled Monument, CALIST ENTRY NUMBER:1015976CONDITION:Generally satisfactory but with minor localised problemsTREND:DecliningREIRICARL VULNERABUTY:Scrub / tree growthNEW INTRY:NoOWNER TYPE:PrivateCONTACT:Ann Preston-Jones 07917 642388DESIGNATION:Scheduled Monument, CA, WHSUST ENTRY NUMBER:1010323DESIGNATION:Scheduled Monument, CA, WHSUST ENTRY NUMBER:1010323CONTACT:Ann Preston-Jones 07917 642388TREND:DecliningDESIGNATION:Scheduled Monument, CA, WHSUST ENTRY NUMBER:1010323CONDITION:Generally satisfactory but with significant localised problemsTREND:NoOWNER TYPE:YrivateCONTACT:Nan Preston-Jones 07917 642388STEENAME:Scheduled MonumentCONTACT:Nan Preston-Jones 07917 642388STEENAME:Scheduled MonumentUST ENTRY NUMBER:1018630CONTACT:Scheduled MonumentUST ENTRY NUMBER:1018630CONTACT:Scheduled MonumentUST ENTRY NUMBER:1018630CONTACT:Mitted growthNEW ENTRY:NoCONTACT:Mitted multiple ownersCONTACT:NoCONTACT:Mitted growthNEW ENTRY:NoCONTACT:Mitted multiple ownersCONTACT:NoCONTACT:Mitted multiple ownersCONTACT:NoCONTACT:Mitted multiple ownersCONTACT:NoCONTACT:Mitted multiple ownersCONTA	OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
Conduction Constraint Constraint Constraint Constraint Generally satisfactory but with minor localised problems memory Declining PRENEURAL VLANERABULTY: Scrub / tree growth NMW ENTRY: No OWNER TYPE: Private CONTACT: Ann Preston-Jones 07917 642388 BITE NAME: Celer Contract: Ann Preston-Jones 07917 642388 BITE NAME: Celer List ENTRY NUMBER 1010323 DEBIGNATION: Scheduled Monument, CA, WHS List ENTRY NUMBER 1010323 CONTACT: Ann Preston-Jones 07917 642388 Declining RERECENATION: Generally satisfactory but with significant localised problems TREND: No CONTACT: Ann Preston-Jones 07917 642388 Stable Stable GUINTRY TYPE: Protoate CONTACT: Ann Preston-Jones 07917 642388 STEE NAME: Scheduled Monument List ENTRY NUMBER: 101630 CONTRICT: Prehistoric cist; cairns and cairnfield on north east Smallaccoombe Downers Stable CONTRON: Generally satisfactory but with significant localised problems TR	SITE NAME:	Embanked platform cairn with central mound 375	metres north west	of Trewalla Farm, St. Cleer
Construction problems Network Declining PRINCIPAL VULNERABULTY: Scrub / tree growth NeW ENTRY: No PRINCIPAL VULNERABULTY: Scrub / tree growth NeW ENTRY: No Private CONTACT: Ann Preston-Jones 07917 642388 affE NAME: Kerbed platform cairn with kerbed central mound and outer bank 600 metres east of Trewalla Farm, St. Cleer 1010323 DEBIONATION: Scheduled Monument, CA, WHS UST ENTRY NUMBER: 1010323 DEBIONATION: Generally satisfactory but with significant localised problems mREND: No STENAME Vandalism New ENTRY: No OWNER TYPE: Private CONTACT: Ann Preston-Jones 07917 642388 ATE NAME: Scheduled Monument UST ENTRY NUMBER: 101630 CONDITION: Scheduled Monument UST ENTRY NUMBER: 1018630 CONDITION: Scheduled Monument, CA UST ENTRY NUMBER: 101630 CONDITION: Generally satisfactory but with significant localised problems TREND: No CONDITION: Generally unsatisfactory with major localised problems <t< td=""><td>DESIGNATION:</td><td>Scheduled Monument, CA</td><td>LIST ENTRY NUMBER:</td><td>1015976</td></t<>	DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1015976
DVINER TIPE:PrivateCONTACT:Ann Preston-Jones 07917 642388STEE NAME:Kerbed platform cairn with kerbed central mound - Jouter bank 600 metres east of Trewalla Farm, St. CleerDESIGNATION:Scheduled Monument, CA, WHSUST ENTRY NUMBER:1010323CONDITION:Generally satisfactory but with significant localised problemsTRIND:DeciningCONDITION:Generally satisfactory but with significant localised problemsTRIND:NoOWNER TIPE:PrivateCONTACT:Ann Preston-Jones 07917 642388STEE NAME:Prehistoric cist, cairns and cairnfield on north east Mailacoombe Tor, St. CleerISTENME:ISTENME:DESIGNATION:Scheduled MonumentUST ENTRY NUMBER:IO18630CONTACT:Scheduled MonumentUST ENTRY NUMBER:IO18630CONTACT:Scheduled MonumentNoISTENME:CONTACT:Bergenally satisfactory but with significant localised problemsTREND:Scheduled MonumentCONTACT:Mixed, multiple ownersCONTACT:NoOWNER TIPE:Prehistoric enclosure 325 metres west of TrewallsIO10434CONTACT:Scheduled Monument, CAUST ENTRY NUMBER:IO10434CONTACT:REIND:Scheduled Monument, CAUST ENTRY NUMBER:IO10434CONTACT:Prehistoric enclosure 325 metres west of TrewallsFREND:NoCONTACT:Scheduled Monument, CAUST ENTRY NUMBER:IO10434CONTACT:Prehistoric enclosure and field system, two hut cir/Est MURER:IO10434CONTACT: <td< td=""><td>CONDITION:</td><td></td><td>TREND:</td><td>Declining</td></td<>	CONDITION:		TREND:	Declining
STEE NAME: Kerbed platform cairm with kerbed central mound and outer bank 600 weres east of Trewalla Farm, St. DEBRIGNATION: Scheduled Monument, CA, WHS UST ENTRY NUMBER: 1010323 CONDITION: Generally satisfactory but with significant localised problems TREND: Declining REINCIPAL VULNERABILITY: Vandalism NEW ENTRY: No OWNER TYPE: Private CONTACT: Ann Preston-Jones 07917 642388 STEE NAME: Scheduled Monument UST ENTRY NUMBER: 1018630 OWNER TYPE: Prehistoric cist, cairns and cairmfield on north east Strenters Number: 570 metres north west of Smallaccombe Tor, St. Cleer DEBRIGNATION: Scheduled Monument UST ENTRY NUMBER: 1018630 CONTRCT: Prehistoric cist, cairns and cairmfield on north east Strenters verters north west of Smallaccombe Tor, St. Cleer Stable DEBRIGNATION: Scheduled Monument UST ENTRY NUMBER: 1018630 CONTRCT: Mixed, multiple owners CONTACT: Ann Preston-Jones 07917 642388 STEE NAME: Prehistoric enclosure 325 metres west of Trewalls 1010434 CONTRCT: Scheduled Monument, CA UST ENTRY NUMBER: 10	PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
NUMBER Clear Designation Scheduled Monument, CA, WHS UST ENTRY NUMBER 1010323 CONDITION: Generally satisfactory but with significant localised problems TREND: Declining RRINCIPAL VOLNERABILITY: Vandalism New ENTRY: No OWNER TYPE: Private CONTACT: Ann Preston-Jones 07917 642388 SITE NAME: Prehistoric cist, cairns and cairnfield on north east Swallaccombe Downs. 570 metres north west of Smallaccombe Tor, St. Clear DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1018630 CONDITION: Generally satisfactory but with significant localised problems TREND: Stable CONDITION: Scheduled Monument, CA UST ENTRY NUMBER: 1010434 CONDITION: Scheduled Monument, CA UST ENTRY NUMBER: 1010434 CONDITION: Scheduled Monument, CA UST ENTRY NUMBER: <td>OWNER TYPE:</td> <td>Private</td> <td>CONTACT:</td> <td>Ann Preston-Jones 07917 642388</td>	OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningRINCIPAL VULNERABULTY:VandalismNEW BYTRY:NoOWNER TYPE:PrivateCONTACT:Ann Preston-Jones 07917 642388SITE NAME:Prehistoric cist, cairns and cairnfield on north east SurgersJones north west of Smallaccombe Tor, St. CleerInternational ScottagersDEBIGNATION:Scheduled MonumentMEND:Jole300CONTIRCT:Plant growthNEW ENTRY:NoCONTIRCT:Plant growthNEW ENTRY:NoCONTIRCT:Prehistoric enclosure 325 metres west of TrewaltMEND:Jole300CONTIRCT:Scheduled Monument, CAMEND:Jole300CONTIRCT:Plant growthInternational ScottagersJole300CONTIRCT:Plant growthNEW ENTRY:NoCONTIRCT:Plant growth<	SITE NAME:		and outer bank 600) metres east of Trewalla Farm, St.
ConcernedproblemsFind of the financeDetermingPRINCIPAL VULNERABILITY:VandalismNEW ENTRY:NoPrivateCONTACT:Ann Preston-Jones 07917 642388GRIE NAME:Prehistoric cist, cairns and cairnfield on north east Smallacoombe Downser Tor, St. CleerStableBEISONATION:Scheduled MonumentUST ENTRY NUMBER:1018630CONTACT:Generally satisfactory but with significant localised problemsTREND:StableCONTACT:Plant growthNEW ENTRY:NoOWNER TYPE:Mixed, multiple ownersCONTACT:Ann Preston-Jones 07917 642388STE NAME:Prehistoric enclosure 325 metres west of TrewallsTREND:StableCONTACT:Scheduled Monument, CAUST ENTRY NUMBER:1010434CONTACT:Generally unsatifactory with major localised problemsTREND:DecliningCONTACT:Mixed, multiple ownersCONTACT:NoCONTACT:Prehistoric enclosure a125 metres west of TrewallsTREND:DecliningCONTACT:Generally unsatifactory with major localised problemsTREND:DecliningCONTACT:Mixed, multiple ownersCONTACT:NoCONTACT:Mixed, multiple ownersCONTACT:NoCONTACT:Preston-Jones 07917 642388TREND:DecliningCONTACT:Preston-Jones 07917 642388CONTACT:NoCONTACT:Preston-Jones 07917 642388CONTACT:NoCONTACT:Preston-Jones 07917 642388CONTACT:NoCONTACT	DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1010323
DWN RET TYPE:PrivateCONTACT:Ann Preston-Jones 07917 642388ATE NAME:Prehistoric cist, cairns and cairnfield on north east Swallacoombe Downsen Tor, St. CleerUST ENTRY NUMBER1018630DESIGNATION:Scheduled MonumentUST ENTRY NUMBER1018630CONTACT:Reno:StableStableCONTACT:Plant growthNEW ENTRY:NoDWN RET TYPE:Mixed, multiple ownersCONTACT:NoDESIGNATION:Scheduled Monument, CAUST ENTRY NUMBER1010434CONTACT:Prehistoric enclosure 325 metres west of TrewallaTREND:DecliningDESIGNATION:Scheduled Monument, CAUST ENTRY NUMBER1010434CONTACT:Generally unsatisfactory with major localised problemsTREND:NoCONTACT:Mixed, multiple ownersCONTACT:NoCONTACT:Mixed, multiple ownersCONTACT:NoCONTACT:Mixed, multiple ownersCONTACT:NoCONTACT:Mixed, multiple ownersCONTACT:NoCONTACT:Mixed, multiple ownersCONTACT:NoCONTACT:Scheduled Monument, CAUST ENTRY NUMBERIo1216CONTACT:Mixed, multiple ownersCONTACT:NoCONTACT:Scheduled Monument, CAUST ENTRY NUMBERIo13216CONTACT:Scheduled Monument, CAUST ENTRY NUMBERIo13216CONTACT:Scheduled Monument, CAUST ENTRY NUMBERIo13216CONTACT:Scheduled Monument, CAUST ENTRY NUMBERIo13216	CONDITION:		TREND:	Declining
SITE NAME: Prehistoric citic, cairns and cairnfield on north east Smallacoombe Downs, 570 metres north west of Smallacoombe Tor, St. Cleer Interest Not Step Step Step Step Step Step Step Ste	PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY ?:	No
And Note L.Smallacoombe Tor, St. CleerDesignATION:Scheduled MonumentLIST ENTRY NUMBER:1018630conDITION:Generally satisfactory but with significant localised problemsTREND:StableRINCIPAL VULNERABILITY:Plant growthNew ENTRY:NoOWNER TYPE:Mixed, multiple ownersCONTACT:Ann Preston-Jones 07917 642388STE NAME:Prehistoric enclosure 325 metres west of TrewallaTREND:1010434CONDITION:Scheduled Monument, CALIST ENTRY NUMBER:1010434CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningCONDITION:Plant growthNEW ENTRY:NoOWNER TYPE:Mixed, multiple ownersCONTACT:NoCONDITION:Scheduled Monument, CALIST ENTRY NUMBER:1010434CONDITION:Scheduled Monument, CANEW ENTRY:NoOWNER TYPE:Plant growthNEW ENTRY:NoSTE NAME:Prehistoric enclosure and field system, two hut cir/SiNoSTE NAME:Scheduled Monument, CALIST ENTRY NUMBER:1013216STE NAME:Scheduled Monument, CALIST ENTRY NUMBER:1013216DesignATION:Scheduled Monument, CALIST ENTRY NUMBER:1013216DESIGNATION:Scheduled	OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
CONDITION:Generally satisfactory but with significant localised problemsTREND:StablePRINCIPAL VULNERABILITY:Plant growthNEW ENTRY?:NoOWNER TYPE:Mixed, multiple ownersCONTACT:Ann Preston-Jones 07917 642388SITE NAME:Prehistoric enclosure 325 metres west of Trewalla Furry NUMBER1010434DESIGNATION:Scheduled Monument, CALIST ENTRY NUMBER:1010434CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningCONDITION:Mixed, multiple ownersCONTACT:NoOWNER TYPE:Mixed, multiple ownersCONTACT:Ann Preston-Jones 07917 642388SITE NAME:Prehistoric enclosure and field system, two hut circlesNoOWNER TYPE:Mixed, multiple ownersCONTACT:Ann Preston-Jones 07917 642388SITE NAME:Prehistoric enclosure and field system, two hut circlesNoOWNER TYPE:Scheduled Monument, CALIST ENTRY NUMBER:1013216OUNTACT:Scheduled Monument, CALIST ENTRY NUMBER:1013216OUNTACT:Scheduled Monument, CALIST ENTRY NUMBER:1013216CONDITION:Scheduled Monument, CALIST ENTRY NUMBER:1013216CONDITION:Scheduled Monument, CALIST ENTRY NUMBER:1013216CONDITION:Scheduled Monument, CALIST ENTRY NUMBER:1013216CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningCONDITION:Plant growthNEW ENTRY?:No	SITE NAME:		Smallacoombe Dov	wns, 570 metres north west of
problemsproblemsNoPRINCIPAL VULNERABILITY:Plant growthNEW ENTRY?:NoOWNER TYPE:Mixed, multiple ownersCONTACT:Ann Preston-Jones 07917 642388SITE NAME:Prehistoric enclosure 325 metres west of Trewalla Farm, St. Cleer1010434DESIGNATION:Scheduled Monument, CALIST ENTRY NUMBER:1010434CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Plant growthNEW ENTRY?:NoOWNER TYPE:Mixed, multiple ownersCONTACT:Ann Preston-Jones 07917 642388SITE NAME:Prehistoric enclosure and field system, two hut circlesNew ENTRY?:NoOWNER TYPE:Mixed, multiple ownersCONTACT:Ann Preston-Jones 07917 642388SITE NAME:Prehistoric enclosure and field system, two hut circlesNoSITE NAME:Scheduled Monument, CALIST ENTRY NUMBER:Io13216DESIGNATION:Scheduled Monument, CALIST ENTRY NUMBER:Io13216DESIGNATION:Scheduled Monument, CALIST ENTRY NUMBER:Io13216CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningCONDITION:Generally unsatisfactory with major localised problemsTREND:No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018630
OWNER TYPE:Mixed, multiple ownersCONTACT:Ann Preston-Jones 07917 642388SITE NAME:Prehistoric enclosure 325 metres west of Trewalla FUTTRY NUMBER1010434DESIGNATION:Scheduled Monument, CAIST ENTRY NUMBER1010434CONDITION:Generally unsatisfactory with major localised problemsrREND:DecliningPRINCIPAL VULNERABILITY:Plant growthNEW ENTRY:NoOWNER TYPE:Mixed, multiple ownersCONTACT:Ann Preston-Jones 07917 642388SITE NAME:Prehistoric enclosure and field system, two hut circlesCONTACT:Nn Preston-Jones 07917 642388SITE NAME:Prehistoric enclosure and field system, two hut circlesIST ENTRY NUMBER:1013216SITE NAME:Scheduled Monument, CAIST ENTRY NUMBER:1013216CONDITION:Generally unsatisfactory with major localised problemsIST ENTRY NUMBER:1013216CONDITION:Generally unsatisfactory with major localised problemsIST ENTRY NUMBER:IO13216CONDITION:Plant growthNEW ENTRY:No	CONDITION:		TREND:	Stable
SITE NAME: Prehistoric enclosure 325 metres west of Trewalla Farm, St. Cleer DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1010434 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No OWNER TYPE: Mixed, multiple owners CONTACT: Ann Preston-Jones 07917 642388 SITE NAME: Prehistoric enclosure and field system, two hut circles and parts of a metieval field system 350 metres sour east of Sparretts Farm, St. Cleer IO13216 SITE NAME: Scheduled Monument, CA LIST ENTRY NUMBER: IO13216 OCONDITION: Scheduled Monument, CA IST ENTRY NUMBER: IO13216 OCONDITION: Scheduled Monument, CA IST ENTRY NUMBER: IO13216 CONDITION: Prehistoric enclosure and field system, two hut circles and parts of a metieval field system 350 metres sour east of Sparretts Farm, St. Cleer IST ENTRY NUMBER: IO13216 CONDITION: Scheduled Monument, CA IST ENTRY NUMBER: IO13216 CONDITION: Plant growth NEW ENTRY: No	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
DESIGNATION:Scheduled Monument, CALIST ENTRY NUMBER:1010434CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Plant growthNEW ENTRY:NoOWNER TYPE:Mixed, multiple ownersCONTACT:Ann Preston-Jones 07917 642388SITE NAME:Prehistoric enclosure and field system, two hut circles and parts of a east of Sparretts Farm, St. CleerUST ENTRY NUMBER:1013216DESIGNATION:Scheduled Monument, CALIST ENTRY NUMBER:1013216CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningRINCIPAL VULNERABILITY:Plant growthNEW ENTRY:No	OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningRINCIPAL VULNERABILITY:Plant growthNEW ENTRY?:NoDWNER TYPE:Mixed, multiple ownersCONTACT:Ann Preston-Jones 07917 642388SITE NAME:Prehistoric enclosure and field system, two hut circles and parts of a east of Sparretts Farm, St. CleerUST ENTRY NUMBER:1013216DESIGNATION:Scheduled Monument, CALIST ENTRY NUMBER:1013216CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Plant growthNEW ENTRY?:No	SITE NAME:	Prehistoric enclosure 325 metres west of Trewalla	Farm, St. Cleer	
problemsproblemsproblemsDecliningPRINCIPAL VULNERABILITY:Plant growthNEW ENTRY?:NoOWNER TYPE:Mixed, multiple ownersCONTACT:Ann Preston-Jones 07917 642388SITE NAME:Prehistoric enclosure and field system, two hut circles and parts of a medieval field system 350 metres sour east of Sparretts Farm, St. CleerIIST ENTRY NUMBER:1013216DESIGNATION:Scheduled Monument, CAIIST ENTRY NUMBER:1013216CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Plant growthNEW ENTRY?:No	DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1010434
OWNER TYPE:Mixed, multiple ownersCONTACT:Ann Preston-Jones 07917 642388SITE NAME:Prehistoric enclosure and field system, two hut circles and parts of a medieval field system 350 metres sour east of Sparretts Farm, St. CleerLIST ENTRY NUMBER:1013216DESIGNATION:Scheduled Monument, CALIST ENTRY NUMBER:1013216CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Plant growthNEW ENTRY?:No	CONDITION:		TREND:	Declining
SITE NAME: Prehistoric enclosure and field system, two hut circles and parts of a medieval field system 350 metres sour DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1013216 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
Instrume east of Sparretts Farm, St. Cleer DESIGNATION: Scheduled Monument, CA CONDITION: Generally unsatisfactory with major localised problems REND: Declining PRINCIPAL VULNERABILITY: Plant growth	OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
CONDITION: Generally unsatisfactory with major localised problems TREND: Declining PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No	SITE NAME:	Prehistoric enclosure and field system, two hut circ east of Sparretts Farm, St. Cleer	cles and parts of a r	nedieval field system 350 metres sour
problems New ENTRY: No	DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1013216
5	CONDITION:		TREND:	Declining
OWNER TYPE: Private CONTACT: Ann Preston-Jones 07917 642388	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
	OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Prehistoric irregular aggregate field system with inc Farm, St. Cleer	corporated stone h	ut circles 375 metres SSE of Sparretts
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1008765
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric irregular and regular aggregate field syst of Siblyback Farm, St. Cleer	tems with incorpor	rated stone hut circles 750 metres EN
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1011315
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Bowl barrow 130 metres south east of Penglaze, St	. Erme	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016887
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
GITE NAME:	Prehistoric irregular and regular aggregate field syst boulder 750 metres ESE of Siblyback Farm, St. Clee	tems, enclosure, st er	one hut circles, cairnfield and kerbed
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1010060
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric regular aggregate field system with inco enclosure 550 metres WSW of Trewalla Farm, St.	rporated and adjac Cleer	ent stone hut circles and an adjacent
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1009731
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric to post-medieval field systems, boundar north eastern Siblyback Moor, St. Cleer	ries, settlements an	d railway at Smallacoombe Parks and
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018631
	Generally satisfactory but with significant localised	TREND:	Stable
CONDITION:	problems		
	problems Forestry	NEW ENTRY?:	No
RINCIPAL VULNERABILITY:	•	NEW ENTRY?: CONTACT:	No Ann Preston-Jones 07917 642388
PRINCIPAL VULNERABILITY: OWNER TYPE:	Forestry	CONTACT:	
PRINCIPAL VULNERABILITY: DWNER TYPE: DITE NAME:	Forestry Mixed, multiple owners	CONTACT:	
CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Forestry Mixed, multiple owners Round cairn 450 metres east of Sparretts Farm, St.	CONTACT:	Ann Preston-Jones 07917 642388
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Forestry Mixed, multiple owners Round cairn 450 metres east of Sparretts Farm, St. Scheduled Monument, CA Generally unsatisfactory with major localised	CONTACT: Cleer LIST ENTRY NUMBER:	Ann Preston-Jones 07917 642388

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В

implemented. C Slow decay; no solution agreed.

use).

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Round cairn 525 metres east of Trewalla Farm, St.	Cleer	
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1012041
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Round cairn 740 metres SSW of Caradon Hill sum	mit, St. Cleer	
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1011774
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Round cairn and shelters 812 metres SSW of Cara	don Hill summit, St	. Cleer
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1011784
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Public utilities	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Round cairn with peripheral berm 402 metres SSV	√ of Caradon Hill s	ummit, St. Cleer
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1011822
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	South Caradon C19 copper mine, St. Cleer		
DESIGNATION:	Scheduled Monument, 2 LBs, part in CA, WHS	LIST ENTRY NUMBER:	1020614
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Stone hut circle 750 metres ESE of Trewalla Farm,	St. Cleer	
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1011909
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	The Tinners' Dyke 160 yards (150 metres) in lengt	h south of Henders	grove Wood, St. Cleer
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004364
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Tor cairn with adjacent sub-rectangular but 450 m	etres SSW of Cara	Ion Hill summit St Clear
DESIGNATION:	Tor cairn with adjacent sub-rectangular hut 650 metres SSW of Caradon Hill summit, St. C Scheduled Monument, CA, WHS LIST ENTRY NUMBER: 1011793		
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	' Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Two adjacent stone hut circles 265 metres WNW	of Trewalla Farm,	St. Cleer
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1009738
CONDITION:	Generally unsatisfactory with major localised TREND: Declining problems		Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Two adjacent stone hut circles 290 metres west o	f Trewalla Farm, St.	Cleer
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1009703
CONDITION:	Generally unsatisfactory with major localised TREND: Declining problems		Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric to medieval settlements, field systems, enclosures and cairns, with post-medieval boundary an railway on north east Smallacoombe Down, Altarnun / St. Cleer		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018629
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Forestry NEW ENTRY?: No		No
OWNER TYPE:	Mixed, multiple owners CONTACT:		Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric round cairn on Caradon Hill, 310 metres west of Heather House, Linkinhorne / St. Cleer		
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1020939
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Bury camp, St. Dominick		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004393
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Warren's Barrow, St. Erme		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016888
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Russell 0117 975 0671

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Enclosures east of Gurlyn, St. Erth		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1007282
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Redcliff Castle, later prehistoric cliff castle 550 metres south west of Bedruthan, St. Eval		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021006
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Promontory fort north of village, St. Gennys		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003097
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Medieval transhumance hut on Draynes Common,	500 metres south	west of Westerlake Farm, St. Neot
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007779
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - limited/localised	NEW ENTRY?:	No
OWNER TYPE:	Unknown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Gunpowder storage complex at Kennall Vale, Pons	anooth	
DESIGNATION:	Scheduled Monument, 3 LBs, WHS	LIST ENTRY NUMBER:	1020441
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Camp 500 yards (460 metres) west of Trenance, S	t. Issey	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004235
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric regular aggregate field system with inco NNW of Lamelgate Farm, St. Neot	prporated enclosure	e and stone hut circles 550 metres
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007474
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Cadson Bury hillfort, St. Ive and Pensilva		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004494
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Hut circles, Higher Bussow, St. Ives		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006689
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Whitesand Bay (or Tregonhawke) battery, St. Johr		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004664
CONDITION:	Generally unsatisfactory with major localised TREND: Declir problems		Declining
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No
OWNER TYPE:	Commercial company CONTACT:		Ann Preston-Jones 07917 642388
SITE NAME:	Unenclosed hut circle settlement, field boundaries	, enclosure and cair	m on Blacktor Downs, St. Neot
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011701
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Unknown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Chambered barrow 100 yards (90 metres) east of Kerrow Farm, St. Just		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004637
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Round barrow 310 yards (280 metres) south of Ki	lmansag, St. Pinnoc	k / Braddock
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004434
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Geevor Mine, St. Just		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1021361
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY ?:	No
OWNER TYPE:	Local authority	CONTACT:	Nick Russell 0117 975 0671

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Two round barrows north west of Middle Taphou	se, St. Pinnock / Bra	addock
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003077
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Nanjulian Farm courtyard house, St. Just		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004498
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Animal burrowing - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Numphra Common tin streamworking complex, St	t. Just	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007272
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	St Stephen's Beacon hillfort, St. Stephen-in-Brannel		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003091
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - moderate	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Standing stone 200 yards (180 metres) west of Chy	ycarne, St. Just	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003116
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Chapel enclosure 150 yards (140 metres) south of	Trelease Farm, St.	Keverne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004334
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Settlement sites 500 yards (460 metres) SSE of Tre	ebarveth, St. Keverr	ne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004319
	Generally unsatisfactory with major localised problems	TREND:	Declining
CONDITION:	problems		
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
		NEW ENTRY?: CONTACT:	No Ann Preston-Jones 07917 642388

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	St Levan Chapel site, St. Levan		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007285
CONDITION:	Generally unsatisfactory with major localised problems	ised TREND: Declining	
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Treryn Dinas fort, St. Levan		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006733
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Westcott Cross, 480 metres south east of Westco	ott Lodge, St. Domi	nick / St. Mellion
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018019
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Cliff castle at Winecove Point, St. Merryn		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004234
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners CONTACT: Ann Pre		Ann Preston-Jones 07917 642388
SITE NAME:	Veryan Castle multiple enclosure fort and annexe	500 metres south v	vest of Churchtown Farm, Veryan
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019746
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY ?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	St Constantine's chapel and holy well, St. Merryn		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1018569
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Round 790 metres north east of Trebollack, St. Mi	chael Penkevil	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019612
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / SOU	JTH WEST / CORNWALL (UA)		
SITE NAME:	The Rumps promontory fort, St. Minver Highlands		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004625
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Hobbs Hill tin mine, openwork and lodeback tinwork 530 metres east and 160 metres north east of Chyseger Farm, St. Neot		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021410
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Hut circle village 330 yards (300 metres) west of V	Vest Northwood F	arm, St. Neot
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004662
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric field systems, enclosure, hut circles and rounds, with adjacent medieval settlement, longhouse field system on Higher Langdon Farm, St. Neot		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007475
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric settlements and field system with adjac streamworks on the Brown Gelly Downs, St. Neo		ment, field systems, boundaries and tir
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007770
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Round cairn 1.062 kilometres south west of Highe	r Langdon Farm, St	. Neot
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007476
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Round cairn 1.17 kilometres south west of Higher	Langdon Farm, St.	Neot
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007477
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Castle Dore (camp), St. Sampson / Tywardreath ar	nd Par	
DESIGNATION:	Scheduled Monument, RB	LIST ENTRY NUMBER:	1006691
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Tregargus stone grinding mill No. 2, St. Stephen-in-	-Brannel	
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1003101
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Other not for profit group	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Round barrow north east of Kernick, St. Stephens	By Launceston Rur	al
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003272
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners CONTACT: Ann Pres		Ann Preston-Jones 07917 642388
SITE NAME:	Two round barrows north east of Fairy Cross, St. Winnow		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004439
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing NEW ENTRY?:		No
OWNER TYPE:	Commercial company CONTACT:		Ann Preston-Jones 07917 642388
SITE NAME:	New Consols Mine: surface, buried and undergrou	nd remains, Lucket	t , Stokeclimsland
DESIGNATION:	Scheduled Monument, 5 LBs, part in CA, WHS	LIST ENTRY NUMBER:	1409595
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Condolden Barrow, Tintagel		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004652
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	The Ballast Pond, Torpoint		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1007261
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Carne Beacon round barrow 320 metres north of	Carne Farm, Verya	n
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019745
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Ancient village south of Carburrow Tor, Warlegga	n	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003073
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Chapel Jane medieval chapel 600 yards (550 metres) NNW of Treen, Zennor		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004631
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Treen Common barrows, Zennor		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004473
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
<u></u>	SITE NAME: Carclew, Mylor	Mid-C18 formal	terraced and water gardens, together



DESIGNATION:

CONDITION:

NEW ENTRY ?:

OWNER TYPE:

LIST ENTRY NUMBER:

TREND:

VULNERABILITY:

High

No

Declining

1000544

an C18 landscape park. The main house burned down in Registered Park and Garden 1934 and the site is now in divided ownership. Infill grade II, 5 LBs, WHS residential development has taken place in the park belts, substantial areas of woodland have been cleared and many Extensive significant problems individual parkland trees have been lost. The ruins of Carclew House, a II* listed building, were added to the HAR Register in 2017. A steering group has been established with the owners of Carclew House, and a Conservation Statement has been prepared (January 2021) for the core site. Private, multiple owners

© Historic England

Contact: Jo McAllister 0117 975 0696

SITE NAME:	Bodmin		
DESIGNATION:	Conservation Area, 96 LBs, SM	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Alyson Cooper (LPA) 01872 323603

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; в solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA

- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG
- Registered Park and Garden Scheduled Monument SM

UA Unitary Authority WHS World Heritage Site

47

DEVON

DARTMOOR (NP)

Start Ber	SITE NAME:	Gunpowder factory at Powder Mills, a partially enclosed stone hut circle settlement and round cairn, Dartmoor Forest, West	Devon's only C19 gunpowder factory dates to 1844 and comprises at least 18 buildings involved in the production, storage and management of gunpowder. These buildings are now vacant and neglected, and there are unmanaged
c England	LIST ENTRY NUMBER:	1389617	Contact: Annie Evans 0117 975 0673
	OWNER TYPE:	Private	
	PRIORITY CATEGORY:	D (D)	
	OCCUPANCY:	Vacant/not in use	
	CONDITION:	Poor	with the owner and repair works are now proceeding.
	DESIGNATION:	Listed Building grade II*	more recent years. Conditional consents for reoccupation of the house have been granted. Historic England has met
Aller	SITE NAME:	Higher Sigford, Sweet's Sigford, Ilsington, Teignbridge	A rare example of a longhouse derivative in a farmstead context which has been used for agricultural storage in
()			

© Historic E



SITE NAME:	Gunpowder factory at Powder Mills, a partially enclosed stone hut circle settlement and round cairn, Dartmoor Forest, West Devon	Devon's only C19 gunpowder factory dates to 1844 and comprises at least 18 buildings involved in the production, storage and management of gunpowder. These buildings are now vacant and neglected, and there are unmanaged trees growing across the site. As a result of Historic
DESIGNATION:	Scheduled Monument, 2 LBs	England grant and match funding from the Duchy of Cornwall, repair works to the collapsed southern gable end
CONDITION:	Poor	of Building 9 have been undertaken. The grant will also fund arboreal works to remove trees and tree limbs that pose a
OCCUPANCY:	Vacant/not in use	wind blow threat. Tree works will be undertaken in August
PRIORITY CATEGORY:	D (D)	2019 after the end of nesting season.
OWNER TYPE:	Crown	
LIST ENTRY NUMBER:	1016635	Contact: Andy Crabb 01626 832093

© Historic England Archive



SITE NAME: Church of St Petrock, Church C12 parish church of which the west tower (formerly at the crossing) of the originally cruciform church survives. Street, South Brent, South The west end was demolished early CI4 when the present Hams nave was rebuilt with two transepts. North and south aisles Listed Place of Worship grade I, of early CI5, restored late CI9. The congregation was DESIGNATION: CA awarded a National Lottery Heritage Fund Grant for Places of Worship and in 2016-17 the tower was grouted and CONDITION: Poor repointed and the vestry roof was repaired however the PRIORITY CATEGORY: C (C) nave roof remains in poor condition. Investigative work on damp ingress is also continuing in 2020. OWNER TYPE: Religious organisation 1147794 LIST ENTRY NUMBER: Contact: Annie Evans 0117 975 0673

© Historic England



		Contact. 7 mile Evans of 17 775 0075
SITE NAME:	Church of St Thomas à Becket, Bridford, Teignbridge	A medieval granite church in an exposed location on the southern fringe of Dartmoor National Park. The pointing
DESIGNATION:	Listed Place of Worship grade I	on the tower is failing and falling, and this is allowing water ingress into the fabric. The church was awarded a Listed
CONDITION:	Poor	Places of Worship Roof Repair Grant but further work is still needed.
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1097825	Contact: Annie Evans 0117 975 0673

© Historic England

	SITE NAME:	Parish Church of Holy Trinity, Church Hill, Buckfastleigh, Teignbridge	Former parish church. Sited on a high hill. C13 tower; chancel and transepts possibly also C13 in origin; C15 aisles and chancel chapels. Thorough restoration in 1844-1845.
	DESIGNATION:	Listed Place of Worship grade II*	Left gutted and roofless after fire on 20 July 1992. The stonework, especially the window tracery, needs further
	CONDITION:	Poor	repair. Despite the fire damage, services are still held at the church.
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1209920	Contact: Annie Evans 0117 975 0673
and			

© Historic Englar

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

SITE NAME:	Enclosure on the west side of the Erme valley belo	w Stalldown Corn	wood. South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012767
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	The southern of three enclosures north of Ford W	/aste, Cornwood, S	South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012700
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Unknown	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Three unenclosed stone hut circles on the west sid South Hams	de of the Erme Valle	ey, north of Lower Piles, Cornwood,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012768
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Two hut circles on the south east slope of Stalldov	vn, Cornwood, Sou	uth Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012766
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Unenclosed stone hut settlement north east of Yao	dsworthy, Cornwo	od, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012771
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Enclosure and hut circles east of Huntingdon Ford,	, Dean Prior, South	Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002536
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Agglomerated enclosure with hut circles, south of		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009578
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Enclosure with hut circles east of Addicombe, Harf	ord, South Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012484
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Enclosure with hut circles east of Addicombe, Harf	ord, South Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017609
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Enclosure with hut circles in Higher Piles newtake,	Harford, South Ha	ms
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013110
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Enclosure with hut circles to the north east of Piles	s Copse, Harford, S	South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013106
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Hut circles and enclosure to south of Left Lake, Ha	rford, South Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004574
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Stone row, cairn and enclosures near Hook Lane, E	Erme Valley, Harfor	rd, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002493
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
	Unenclosed stone hut settlement on the east side of the Erme Valley, North Harford Moor, Harford, South Hams		
SITE NAME:	Hams	,,,	
SITE NAME: DESIGNATION:		LIST ENTRY NUMBER:	1012747
	Hams		
DESIGNATION:	Hams Scheduled Monument Generally satisfactory but with significant localised	LIST ENTRY NUMBER:	1012747

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Unenclosed stone hut settlement with enclosures	north of Piles Cops	e, Harford, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012765
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
ITE NAME:	Enclosed prehistoric settlement and three round of Hams	cairns 870 metres sc	outh east of Horn's Cross, Holne, Sou
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020096
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093
DITE NAME:	Four cairns 560 metres east of Hapstead Ford and cemetery in the Mardle Valley, Holne, South Ham	l 1660 metres east c s	of Ryder's Hill, forming part of a cairn
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019270
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
RINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Andy Crabb 01626 832093
ITE NAME:	Part of the Dartmeet coaxial field system and othe west of Venford Reservoir, Holne, South Hams	er archaeological rer	nains on Holne Moor west and north
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020487
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
ITE NAME:	Partially enclosed stone hut circle settlement 350	metres south west o	of Horn's Cross, Holne, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019274
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Partially enclosed stone hut circle settlement 420 Holne, South Hams	metres north west a	and 440 metres west of Horn's Cross
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020185
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Andy Crabb 01626 832093
ITE NAME:	Prehistoric fields and settlements north east of Ve system, Holne, South Hams	nford Reservoir for	ming part of the Dartmeet coaxial fiel
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020091
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Andy Crabb 01626 832093

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Barrow near Shaugh Cross, Shaugh Prior, South Ha	ams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003824
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Prehistoric fields, settlements and cairn south east field system, Holne, South Hams	of Venford Reserve	oir forming part of the Dartmeet coaxi
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020092
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Cross Dyke reave, Shaugh Prior, South Hams		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010811
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Medieval farmstead and field system, post-medieval west of Gibby Coombe, Holne / West Buckfastleig		pric settlements and cairns north and
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019591
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Hut circles west of Saddlesborough, Shaugh Prior,	South Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002520
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Multi-period remains at Hentor Warren, Shaugh P	rior, South Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019082
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	One of a number of cairns with cists south of Shav	ercombe Brook, Sł	naugh Prior, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012172
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Andy Crabb 01626 832093

PRIORITY CATEGORIES

А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 D
 Slow decay; solution agreed but not yet implemented.
 F

 Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 D
 Slow decay; solution agreed but to yet implemented.
 F

 Slow decay; solution agreed but deterioration or loss of fabric; solution agreed but not yet implemented.
 D
 Slow decay; solution agreed but repair, but no user identified; or obvious new user (applicable only to buildings capable of beneficial user)

 use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	One of a number of cairns with cists south of Shav	ercombe Brook, Sh	augh Prior, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012214
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	One of three stone hut circles 500 metres SSE of L	egis Tor, Shaugh P	rior, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012631
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Pillow mound 100 metres south east of Great Troy Shaugh Prior, South Hams	wlesworthy Tor, fo	rming part of Trowlesworthy Warren,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014666
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Pillow mound 160 metres south west of Great Trowlesworthy Tor, forming part of Trowlesworthy Warr Shaugh Prior, South Hams		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014665
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Pillow mound 270 metres south east of Ditsworthy Prior, South Hams	y Warren House fo	rming part of Hentor Warren, Shaugh
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014477
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Pillow mound 610 metres SSW of Ditsworthy War Prior, South Hams	rren House forming	g part of Willings Walls Warren, Shaug
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014469
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
Owner TIFE:			
	Pillow mound 620 metres ESE of Legis Tor forming	g part of Willings N	/alls Warren, Shaugh Prior, South Ham
SITE NAME:	Pillow mound 620 metres ESE of Legis Tor forming Scheduled Monument	g part of Willings W LIST ENTRY NUMBER:	/alls Warren, Shaugh Prior, South Han 1014457
SITE NAME: DESIGNATION: CONDITION:			
SITE NAME: DESIGNATION:	Scheduled Monument Generally satisfactory but with significant localised	LIST ENTRY NUMBER:	1014457

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Pillow mound 790 metres NNE of Blackaton Cro South Hams	oss, forming part of T	rowlesworthy Warren, Shaugh Prior,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014662
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY ?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Pillow mound 860 metres NNW of Blackaton C South Hams	ross, forming part of	Trowlesworthy Warren, Shaugh Prio
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014664
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY ?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Prehistoric and historic archaeological landscape	at Trowlesworthy V	Varren, Shaugh Prior, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020323
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY ?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Andy Crabb 01626 832093
DITE NAME:	Pillow mound 860 metres SSE of Trowlesworthy Shaugh Prior, South Hams	Warren House, fori	ning part of Trowlesworthy Warren,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014616
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY ?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Pound and hut circles north of Hawk's Tor, Shau	gh Prior, South Ham	S
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002516
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Rectangular building 420 metres north west of H Prior, South Hams	len Tor, forming an c	outlying part of Hentor Farm, Shaugh
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020011
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
ITE NAME:	Stone hut circle north east of Hentor Brook, Sha	ugh Prior, South Ha	ns
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012175
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY ?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Andy Crabb 01626 832093

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / SOU	JTH WEST / DARTMOOR (NP)				
SITE NAME:	Stone hut circle north of Hentor Brook, Shaugh Prior, South Hams				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012083		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Charity (heritage)	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Three pillow mounds and a linear gully 200 metres north of Great Trowlesworthy Tor forming part of Trowlesworthy Warren, Shaugh Prior, South Hams				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014481		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Two pillow mounds and a small area of tin streamy forming part of Willings Walls Warren, Shaugh Pri		outh west of Ditsworthy Warren Hous		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014467		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Commercial company	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Vermin trap 510 metres WSW of Great Trowlesw Prior, South Hams	vorthy Tor forming	part of Trowlesworthy Warren, Shaug		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014465		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No		
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Two pillow mounds and a small area of tin stream forming part of Trowlesworthy Warren, Shaugh Pi		70 metres north of Blackaton Cross,		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014663		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Vermin trap 520 metres SSW of Trowlesworthy V Shaugh Prior, South Hams	Varren House form	ing part of Trowlesworthy Warren,		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014466		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093		

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

use).

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Vermin trap 350 metres south west of Great Trov Shaugh Prior, South Hams		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014475
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Vermin trap 800 metres south east of Trowleswor Warren, Shaugh Prior, South Hams	thy Warren House	e forming part of Trowlesworthy
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014464
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
ITE NAME:	Cist with a retaining kerb north west of Corringdo	on Ball, South Brent	, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010180
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Enclosure and hut circle north of Old Hill, South B	rent, South Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003200
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Enclosure south east of Dockwell Hole, South Bre	nt, South Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002665
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Enclosure with hut circles and rectangular pens, so	outh of Bala Brook,	South Brent, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012775
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY ?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Enclosure with hut circles north of Bala Brook inta	ike, South Brent, So	outh Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012776
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093

PRIORITY CATEGORIES

А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 D
 Slow decay; solution agreed but not yet implemented.
 F

 Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 D
 Slow decay; solution agreed but to yet implemented.
 F

 Slow decay; solution agreed but deterioration or loss of fabric; solution agreed but not yet implemented.
 D
 Slow decay; solution agreed but repair, but no user identified; or obvious new user (applicable only to buildings capable of beneficial user)

 use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Enclosure with hut circles north of Bala Brook intake, South Brent, South Hams				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012783		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY ?:	No		
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Enclosures and hut circles at Petre's Pits Bottom, S	outh Brent, South	Hams		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004557		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Hut circle and fields, Bishop's Mead, South Brent, S	outh Hams			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002537		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Hut enclosure north of Old Hill, South Brent, Sout	h Hams			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002664		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY ?:	No		
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	One of several stone hut circles north of Corringd	on Ball, South Brer	nt, South Hams		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010202		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY ?:	No		
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Rider's Rings (The Rings), South Brent, South Ham	S			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002502		
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No		
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Three enclosed hut groups, Black Tor, Shipley Brid	ge, South Brent, Sc	outh Hams		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002505		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093		

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Two conjoined huts between two enclosures north of Bala Brook intake, South Brent, South Hams			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012778	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Two hut circles on the right bank of Red Brook,	South Brent, South H	lams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013035	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Enclosure with hut circles north of Scad Brook, I	Jgborough, South Ha	ıms	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012485	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Hembury Castle, West Buckfastleigh, South Ham	S		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003859	
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Charity (heritage)	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Medieval strip field system, tinworks, part of a pr Down, Manaton, Teignbridge	ehistoric settlement,	a cairn and reave on Challacombe	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021393	
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Cist on Whitehorse Hill, 910 metres south east	of Taw Head, Dartmo	oor Forest, West Devon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020871	
CONDITION:	Extensive significant problems	TREND:	Improving	
PRINCIPAL VULNERABILITY:	Natural erosion - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	One of a number of cairns at Black Pool, Ugborc	ugh, South Hams		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012232	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093	

PRIORITY CATEGORIES

А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. Slow decay; solution agreed but Under repair or in fair to good repair, but no user identified; or obvious new user (applicable only to buildings capable of beneficial user. use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

TERTLAGE AT KISK 2021 / SOU	JTH WEST / DARTMOOR (NP)			
SITE NAME:	One of a number of cairns at Black Pool, Ugboroug	gh, South Hams		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012285	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Stone alignment and cairn south east of Western E	Beacon, Ugborough,	South Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017604	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Cairn 240 metres north of Crownley Parks, Ilsingto	on, Teignbridge		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019588	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Other not for profit group	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Settlement on Smallacombe Rocks, Ilsington, Teignbridge			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002531	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Settlement west of Holwell Tor, Ilsington, Teignbri	idge		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002529	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Local authority	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Prehistoric and medieval settlements and their field	d systems at Hound	Tor, Manaton, Teignbridge	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016255	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Medieval strip fields, tinworks, prehistoric settleme Down, Manaton / Widecombe in the Moor, Teignt		the lower western slopes of Hamel	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021394	
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Improving	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME: Enclosure south west of Hingston Rocks, Moretonhampstead, Teignbridge DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002496 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining PRINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY?: No OWNER TYPE: Private, multiple owners CONTACT: Andy Crabb 01626.88				
CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Scrub/tree growthNEW ENTRY?:No				
problems new entry?: No				
0				
OWNER TYPE: Private multiple owners CONTACT: Andy Crabb 01626 8				
	332093			
SITE NAME: Hut circles on Hedge Down, Widecombe in the Moor, Teignbridge	Hut circles on Hedge Down, Widecombe in the Moor, Teignbridge			
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002620				
CONDITION: Generally unsatisfactory with major localised TREND: Declining problems				
PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No				
DWNER TYPE: Private CONTACT: Andy Crabb 01626 8	332093			
Two cairns on Cator Common, Widecombe in the Moor, Teignbridge				
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003297				
CONDITION: Generally satisfactory but with significant localised TREND: Declining problems				
PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No				
OWNER TYPE: Private, multiple owners CONTACT: Andy Crabb 01626 8	332093			
ITE NAME: Camp south east of Okehampton, Okehampton Hamlets, West Devon				
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003873				
CONDITION: Generally satisfactory but with significant localised TREND: Declining problems				
PRINCIPAL VULNERABILITY: Bracken NEW ENTRY?: No				
OWNER TYPE: Private CONTACT: Andy Crabb 01626 8	332093			
Deserted medieval site 400 metres west of Okehampton camp, Okehampton Hamlets, Wes	st Devon			
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002654				
CONDITION: Generally satisfactory but with significant localised TREND: Declining problems				
problems				
	32093			
PRINCIPAL VULNERABILITY: Plant growth - General NEW ENTRY?: No				
Principal VULNERABILITY: Plant growth - General NEW ENTRY?: No DWNER TYPE: Private CONTACT: Andy Crabb 01626 8				
Principal VULNERABILITY: Plant growth - General NEW ENTRY?: No DOWNER TYPE: Private CONTACT: Andy Crabb 01626 8 Deserted medieval site north of Okehampton camp, Okehampton Hamlets, West Devon Deserted medieval site north of Okehampton camp, Okehampton Hamlets, West Devon				
PRINCIPAL VULNERABILITY: Plant growth - General NEW ENTRY?: No OWNER TYPE: Private CONTACT: Andy Crabb 01626 8 SITE NAME: Deserted medieval site north of Okehampton camp, Okehampton Hamlets, West Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002630				
PRINCIPAL VULNERABILITY: Plant growth - General NEW ENTRY?: No DWNER TYPE: Private CONTACT: Andy Crabb 01626 8 SITE NAME: Deserted medieval site north of Okehampton camp, Okehampton Hamlets, West Devon International states and the states				
PRINCIPAL VULNERABILITY: Plant growth - General NEW ENTRY?: No OWNER TYPE: Private CONTACT: Andy Crabb 01626 8 SITE NAME: Deserted medieval site north of Okehampton camp, Okehampton Hamlets, West Devon Scheduled Monument LIST ENTRY NUMBER: 1002630 CONDITION: Generally satisfactory but with minor localised problems TREND: Stable PRINCIPAL VULNERABILITY: Vehicle damage/erosion - moderate NEW ENTRY?: No	332093			
PRINCIPAL VULNERABILITY: Plant growth - General NEW ENTRY?: No DWNER TYPE: Private CONTACT: Andy Crabb 01626 8 DESERTED NAME: Deserted medieval site north of Okehampton camp, Okehampton Hamlets, West Devon International stress of the stress of t				
PRINCIPAL VULNERABILITY: Plant growth - General NEW ENTRY?: No DWNER TYPE: Private CONTACT: Andy Crabb 01626 8 SITE NAME: Deserted medieval site north of Okehampton camp, Okehampton Hambers, West Devon Interstand DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002630 CONDITION: Generally satisfactory but with minor localised problems TREND: Stable PRINCIPAL VULNERABILITY: Vehicle damage/erosion - moderate NEW ENTRY?: No DWNER TYPE: Private CONTACT: Andy Crabb 01626 8 STE NAME: Deserted medieval site north west of Okehampton camp, Okehampton Hambers, West Devon No				
PRINCIPAL VULNERABILITY: Plant growth - General NEW ENTRY?: No OWNER TYPE: Private CONTACT: Andy Crabb 01626 8 SITE NAME: Deserted medieval site north of Okehampton camp, Okehampton Hamlets, West Devon Internet Scheduled Monument Internet Scheduled Monument DESIGNATION: Scheduled Monument Internet Scheduled Monument Internet Scheduled Monument Internet Scheduled Monument CONDITION: Generally satisfactory but with minor localised problems TREND: Stable DEVINER TYPE: Vehicle damage/erosion - moderate NEW ENTRY?: No OWNER TYPE: Private CONTACT: Andy Crabb 01626 8 STIE NAME: Deserted medieval site north west of Okehampton camp, Okehampton Andy Crabb 01626 8 STIE NAME: Deserted medieval site north west of Okehampton camp, Okehampton Hamlets, West Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004602				
PRINCIPAL VULNERABILITY: Plant growth - General NEW ENTRY?: No OWNER TYPE: Private CONTACT: Andy Crabb 01626 8 SITE NAME: Deserted medieval site north of Okehampton camp, Okehampton Hamlets, West Devon Io02630 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002630 CONDITION: Generally satisfactory but with minor localised problems TREND: Stable PRINCIPAL VULNERABILITY: Vehicle damage/erosion - moderate NEW ENTRY?: No OWNER TYPE: Private Deserted medieval site north west of Okehampton camp, Okehampton 2 Andy Crabb 01626 8 SITE NAME: Deserted medieval site north west of Okehampton 2 No Andy Crabb 01626 8 SITE NAME: Deserted medieval site north west of Okehampton 2 West ENTRY? Hamlets, West Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004602				

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	Development of the state of the Development of the NA/444 De		
SITE NAME:	Round cairn on Standon Hill, Peter Tavy, West De		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016253
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY ?:	No
OWNER TYPE:	Government or agency	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	A double stone hut circle and enclosure 280 metro	es south of Deadlak	ke Foot, Dartmoor Forest, West Devo
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011569
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Camp 325 yards (300 metres) south east of Arche	rton, Dartmoor Fo	rest, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002636
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Coaxial fields, prehistoric settlement, two cairns and a stone alignment in Little Stannon Newtake, 900 metres south east of Stannon Tor, Dartmoor Forest, West Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021339
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Medieval settlement 470 metres east of Hartyland,	Dartmoor Forest,	West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021338
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY ?:	No
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Prehistoric enclosed settlement 740 metres north	west of Hartland T	or, Dartmoor Forest, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021335
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY ?:	No
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Hut circle and field system north west of Saddle B	ridge, Dartmoor Fo	orest / Holne, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002601
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY ?:	No
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Prestonbury Castle (hillfort), Drewsteignton, West			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003861	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Part of a coaxial field system, prehistoric settlements and cairns on Buttern Hill, Gidleigh, West Devon			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021215	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093	
ITE NAME:	Stone hut circle 380 metres north west of North C	Creaber, Gidleigh, V	West Devon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021220	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Two stone hut circles and field system, 590 metres Buttern Hill, Gidleigh, West Devon	south of Buttern,	forming part of a coaxial field system	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021218	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Enclosure, two stone hut circles and an alignment of Tor, LCPs of Bridestowe and Sourton, West Devo		80 metres north west of Little Links	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007648	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Hut circles and a length of enclosure wall, forming Nodden Gate, Lydford / LCPs of Bridestowe and S	part of a stone hut ourton, West Deve	circle settlement 600 metres east of on	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008638	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY ?:	No	
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Stone hut circle 530 metres ESE of Nodden Gate for Lydford, West Devon	orming an outlying	part of a stone hut circle settlement,	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008639	
	Generally satisfactory but with significant localised problems	TREND:	Declining	
CONDITION:	F			
CONDITION: PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Stone hut circle 610 metres ESE of Nodden Gate f Lydford, West Devon	orming an outlying	part of a stone hut circle settlement	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008656	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Four round barrows on Wigford Down, Meavy, West Devon			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002522	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Greenwell Girt socket stone 600 metres SSW of L	ovaton hamlet, Me	avy, West Devon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008929	
CONDITION:	Extensive significant problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Hut circles south east of Brisworthy, Meavy, West Devon			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004585	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Prehistoric enclosures on Dewerstone Hill, 500 me Devon	etres south east of	Dewerstone Cottage, Meavy, West	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020241	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Charity (heritage)	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Settlement on Wigford Down, Meavy, West Devo	n		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002550	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Settlement on Wigford Down south of Durance, M	1eavy, West Devor		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002523	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

Contention Contention Unit of the origination of the originatio originatio origination of the originatio origination originatio	heritage at RISK 2021 / SOU	JTH WEST / DARTMOOR (NP)					
Generally unsatisfactory with major localised problems TRND Decking MIRELINE VLOKENSELITY Private No OWNER TYPE Private CONTACT: Andy Crabb 01626 832093 STREMME Two hut circles south of Castor Down, Meay, West Devon Locality Name Docking Decleming Scheduled Monument Locality Name Docking Decleming Scheduled Monument Locality Name No Decleming Private Contract: Andy Crabb 01626 832093 Streams Part growth No Contract: Andy Crabb 01626 832093 Streams An enclosed stone hut circle settlement, three route: arity same at a low revealed to the contract: Contract: No Consentation Scheduled Monument Low revealed to the contract: No Consentation Government or agency Contract: No Contract: Government or agency Contract: No Contract: Government or agency Contract: No Contract: Government or agency Contract: No Contract: <td>SITE NAME:</td> <td colspan="6">Three hut circles north west of Cadworthy, Meavy, West Devon</td>	SITE NAME:	Three hut circles north west of Cadworthy, Meavy, West Devon					
problemsproblemsproblemsproblemsproblemsproblemswave travePrivateNoattendsVariationCastractionAndy Crabb 01626 632093attendsTwo hut circles south of Castra Down, Meay, West DevonLet Extends variationsconverterScheduled MonumentLet Extends variationsconverterGenerally satisfactory but with significant localisednewonproblemsGenerally satisfactory but with significant localisednewonproblemsPrivateCONTACT:Andy Crabb 01626 632093attendsAn enclosed stone hut circle settlement, three rour-caines and a lengthfreave 650 metres WSW of GenconverterScheduled MonumentLet Extends Numeet1008711ConverterGenerally unatificant/owith major localisedmetro.DeciningproblemsGenerally unatificant/owith major localisedmetro.DeciningproblemsGenerally unatificant/owith significant localisedmetro.DeciningproblemsGenerally unatificant/owith significant localisedmetro.DeciningattenseGenerally satisfactory but with significant localisedmetro.DeciningproblemsGenerally satisfactory but with significant localisedmetro.Deci	DESIGNATION:	Scheduled Monument LIST ENTRY NUMBER: 1003057					
Data in MarketTwo hut circles south of Castor Down, Meay, WetterCastor Down, Meay, WetterCERENATION:Scheduled MonumentLIST DITRY MUNICE:1002548CONSTON:Generally satisfactory but with significant localised problemsTreub.DeciningRENADEL VULKDABUTE:Plant growthNONOCONSTON:PrivateCONSTON:NoCONSTON:PrivateCONSTON:NoCONSTON:PrivateCONSTON:NoCONSTON:Scheduled MonumentISS HORNY MUNICE:1008711CONSTON:Scheduled MonumentISS HORNY MUNICE:1008711CONSTON:Generally unstatificatory with major localised problemsISS HORNY MUNICE:1008711CONSTON:Generally unstatificatory with major localised problemsISS HORNY MUNICE:1008711CONSTON:Generally unstatificatory with major localised 	CONDITION:						
Strawner Two hut circles south of Catstor Down, Meavy, West Devon specificial (SNA IESNA Scheduled Monument Ist MIXENAMENA Declining specificial (SNA IESNA Generally satisfactory but with significant localised problems meno: Declining seascing (SNA IESNA Private CONFACE Andy Crabb 01626 832093 seascing (SNA IESNA An enclosed stone hut circle settlement, three routh circles and a length of reave 650 metres WSW of Gen Tor, Peter Tavy, West Devon Lot STATA NUMERA 1008711 COMMENT Generally satisfactory with major localised problems INHAR Declining COMMENT VULCEMABURN Plant growth No Declining COMMENT VULCEMABURN Plant growth No Declining COMMENT VULCEMABURN Plant growth No Declining COMMENT VIEL Government or agency COM ACT Cr. Andy Crabb 01626 832093 State ALIENN Scheduled Monument ISE INFORMENT Declining COMMENT VIEL Convernment or agency CoM CO	PRINCIPAL VULNERABILITY:	Plant growth	No				
DesiGNATION Scheduled Monument IST MARSMARSHE Deckning convarious Generally satisfactory but with significant localised problems nearbit Deckning searbits Mart growth No No searbits An enclosed stone hut circle settlement, three rout CONTRACT: And/ Crabb 01626 832093 stremance An enclosed stone hut circle settlement, three rout carst and a lengther ray, West Deconditions International and the ray of reave 650 metres WSW of Generally satisfactory with major localised reave Decining descentions Generally satisfactory with major localised reave No descentions Generally satisfactory with major localised reave No descentions Generally satisfactory with major localised reave No descentions Generally satisfactory with with significant localised reave No descentions Converter Generally satisfactory but with significant localised reave Declining descentions Converter Converter No Declining descentions Converter Converter Converter	OWNER TYPE:	Private	Andy Crabb 01626 832093				
Constraint Constraint Declining Problems Franch Declining Problems Plant growth No CONTROL Plant growth No CONTROL Plant growth No CONTROL Plant growth No CONTROL An enclosed stone hut circle settlement, three norm cirst stand a length of reave 650 metres WSW of Ger CONTROL Scheduled Monument LIST ENTRY NUMBER 1008711 CONTROL Scheduled Monument LIST ENTRY NUMBER Declining Problems Growth No CONTROL Declining CONTROL Scheduled Monument LIST ENTRY NUMBER 100071 CONTROL Scheduled Monument LIST ENTRY NUMBER 1020004 CONTROL Crown CONTROL Andy Crabb 01626 832093 STE NAME <td>SITE NAME:</td> <td>Two hut circles south of Catstor Down, Meavy, W</td> <td>/est Devon</td> <td></td>	SITE NAME:	Two hut circles south of Catstor Down, Meavy, W	/est Devon				
problems problems problems problems problems problems PRINCIPAL VUNERWARTITY: Plant growth New PATTRY: No PRINCIPAL VUNERWARTITY: Plant growth CONTACT: And Probability of Prave 650 metres WSW of Ger Private An enclosed stone hut circle settlement, three round cirns and a length of reave 650 metres WSW of Ger DocIning Descination: Generally Unsatisfactory with major localised TREND: DocIning PRINCIPAL VULRERWARTITY: Plant growth New PATTRY: No OWNERTTYPE: Government or agency CONTACT: And Crabb 01626 832093 Strendman USE INTRY NUMBER: 1020004 Contact: Andy Crabb 01626 832093 Strendman: Government or agency CONTACT: No Contact: Random PRINCIPAL VULRERWARTITY: Plant growth New PATTRY: No No Contact: Casal field system and prehistoric settlement 410 No No Print growth New PATTRY: No No Contact: Casal field system and prehistoric settlement 410 No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002548			
OWNERTIPEPrivateCONTACT:Andy Crabb 01626 832093STRE NAME:An enclosed stone but circle settlement, three rout cirns and a lengthFreeve 650 metres WSW of GerDEBERNATION:Scheduled MonumentUST DITTRIVUENES:1008711CONTACT:Andy Crabb 01626 832093TREN:DecliningREIKCRA, VULKERARUTY:Plant growthNew ENTRY:NoOWNERTIPE:Convention or agencyCONTACT:Andy Crabb 01626 832093STRENAME:Caremanne or agencyCONTACT:Andy Crabb 01626 832093STRENAME:Caremanne or agencyCONTACT:NoDESIGNATION:Scheduled MonumentUST ENTRY NUMBER:1020004CONTACT:Scheduled MonumentUST ENTRY NUMBER:1020004CONTACT:Plant growthNew ENTRY:NoCONTACT:Plant growthNew ENTRY:NoCONTACT:Contact:Contact:NoCONTACT:Contact:Contact:NoCONTACT:Contact:NoCONTACT:Plant growthNew ENTRY:NoCONTACT:Contact:Contact:NoCONTACT:Contact:Contact:NoCONTACT:Contact:Contact:NoCONTACT:Contact:NoCONTACT:Contact:NoCONTACT:Contact:NoCONTACT:Contact:NoCONTACT:Contact:NoCONTACT:Contact:NoCONTACT:Contact:No	CONDITION:		TREND:	Declining			
STRE NAME: An enclosed stone hut circle settlement, three routs carms and a length of reave 650 metres WSW of Ger STRE NAME: Scheduled Monument UST ENTRY NUMBER 1008711 CONDITION Generally unsatisfactory with major localised problems THEND Declining RENORAL ULNERABUTY: Plant growth NEW ENTRY: No CONTACT: Government or agency CONTACT: Andy Crabb 01626 832093 STRE NAME: Caimfield and two stone hut circles 490 metres and S50 metres souts: west of Cox Tor, Peter Tay, West Devon Declining STRE NAME: Caimfield Monument UST ENTRY NUMBER: 1020004 CONDITION Generally satisfactory but with significant localised problems THEND: Declining STRE NAME: Coaxial field system and prehistoric settlement 410=************************************	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY ?:	No			
Name Tor, Peter Tay, West Devon UST ENTRY NUMBERA (0087) 1 DesiGNATION: Scheduled Monument UST ENTRY NUMBERA (0087) 1 CONDITION: Generally unsatisfactory with major localised TRRD: Declining RINK CMAL VULNERABULY: Plant growth New ENTRY: No OWNER TYPE: Government or agency CONTACT: Andy Crabb 01626 832093 STEENAME: Scheduled Monument UST ENTRY NUMBERA 1020004 DesiGNATION: Scheduled Monument UST ENTRY NUMBERA 1020004 CONTACT: Andy Crabb 01626 832093 TRINC DESIGNATION: Scheduled Monument UST ENTRY NUMBERA 1020004 CONTACT: Plant growth NEW ENTRY: No OWNER TYPE: Crown CONTACT: Andy Crabb 01626 832093 STRE NAME: Coaxial field system and prehistoric settlement 410 No CONTACT: Andy Crabb 01626 832093 Instruct Convent Coavial field system and prehistoric settlement 610/Sine Sine Sine Sine Sine Sine Sine Sine	OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093			
Conduction Conduction Conduction Conduction Generally unsatisfactory with major localised problems TREND. Declining RemclineL UNINERMEIT/P: Plant growth New ENTRY: No OWNER TYPE: Government or agency CONTACT: Andy Crabb 01626 832093 STEE NAME: Carefield and two stone hut circles 490 metres and 550 metres south west of Cox Tor, Peter Tavy, West Descendition: Scheduled Monument UST ENTRY NUMBER: 1020004 CONDITION: Generally satisfactory but with significant localised problems TREND: Declining REINCIPAL VULNERABULTY: Plant growth New ENTRY: No CONDITION: Generally satisfactory but with significant localised problems TREND: Declining STEE NAME: Coaxial field system and prehistoric settlement 410 WERTRY: No CONDITION: Generally satisfactory but with significant localised problems TREND: Declining REINCIPAL VULNERABULTY: Plant growth No No CONDITION: Generally satisfactory with major localised problems TREND: Declining REINCIPAL VULNERABULTY: Plant growt	SITE NAME:		ind cairns and a len	gth of reave 650 metres WSW of Ger			
Concention of a problemin Problemin <thproblemin< th=""> Problemin <thproblemin< <="" td=""><td>DESIGNATION:</td><td>Scheduled Monument</td><td>LIST ENTRY NUMBER:</td><td>1008711</td></thproblemin<></thproblemin<>	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008711			
OWNER TYPE:Government or agencyCONTACT:Andy Crabb 01626 832093STEE NAME:Gainfield and two stone hut circles 490 metres = 50 metres southisst ENTER NUMBERDESIGNATION:Scheduled Monumentisst ENTER NUMBER1020004CONDITION:Generally satisfactory but with significant localised orbemsisst ENTER NUMBERIocaliningRRINCIPAL VULNERABILITY:Plant growthNEW ENTERY:NoOWNER TYPE:Coxial field system and prehistoric settlement HUMBER1020090CONDITION:Scheduled Monumentisst ENTER NUMBER1020090CONDITION:Scheduled Monumentisst ENTER NUMBER1020090CONDITION:Generally satisfactory but with significant localised problemsisst ENTER NUMBER1020090CONDITION:Generally satisfactory but with significant localised problemsisst ENTER NUMBER1020090CONDITION:Generally satisfactory but with significant localised problemsisst ENTER NUMBERNoCONDITION:CrownCorowncontact:NoSTEE NAME:Scheduled Monumentisst ENTER NUMBER102090ERISIONATION:Scheduled Monumentisst ENTER NUMBER1019566CONDITION:Scheduled Monumentisst ENTER NUMBER1019566CONDITION:Scheduled Monumentisst ENTER NUMBERNoDESIGNATION:Scheduled Monumentisst ENTER NUMBERNoCONDITION:Scheduled Monumentisst ENTER NUMBERNoCONDITION:Scheduled Monumentisst ENTER NUMBER <t< td=""><td>CONDITION:</td><td></td><td>TREND:</td><td>Declining</td></t<>	CONDITION:		TREND:	Declining			
STEE NAME: Cainfield and two stone hut circles 490 metres and 550 metres south west of Cox Tor, Peter Tawy, West Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020004 CONDITION: Generally satisfactory but with significant localised problems TREND: Declining RRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No OWNER TYPE: Crown CONTACT: Andy Crabb 01626 832093 STEE NAME: Coaxial field system and prehistoric settlement 410 metres west of Cox Tor, Peter Tawy, West Devon Descining DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020090 CONDITION: Generally satisfactory but with significant localised problems TREND: Declining RRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No OWNER TYPE: Crown Contract: Andy Crabb 01626 832093 STEE NAME: Scheduled Monument LIST ENTRY NUMBER: No OWNER TYPE: Crown Contract: Andy Crabb 01626 832093 STEE NAME: Scheduled Monument LIST ENTRY NUMBER: 1019566 CONDITION: Schedule	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No			
Devon UST ENTRY NUMBER 1020004 DEBIGNATION: Scheduled Monument UST ENTRY NUMBER 1020004 CONDITION: Generally satisfactory but with significant localised problems RENO. Declining REINCIPAL VULNERABILITY: Plant growth New ENTRY: No OWNER TYPE: Crown CONTACT: Andy Crabb 01626 832093 DEBIGNATION: Scheduled Monument UST ENTRY NUMBER 1020090 CONDITION: Generally satisfactory but with significant localised problems INFEND: 1020090 REINCIPAL VULNERABILITY: Plant growth INFEND: Declining OWNER TYPE: Crown CONTACT: Andy Crabb 01626 832093 OWNER TYPE: Plant growth INFEND: Declining OWNER TYPE: Crown CONTACT: Andy Crabb 01626 832093 STEENAME: Scheduled Monument IST ENTRY NUMBER 1019566 CONDITION: Scheduled Monument IST ENTRY NUMBER 1019566 CONTIACT: Scheduled Monument IST ENTRY NUMBER 1019566 CONTIACT: Sch	OWNER TYPE:	Government or agency	CONTACT:	Andy Crabb 01626 832093			
CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningRINCIPAL VULNERABELITY:Plant growthNEW ENTRY:NoOWNER TYPE:CrownCONTACT:Andy Crabb 01626 832093STE NAME:Coastial field system and prehistoric settlement 410UST ENTRY NUMBER:TO 20090DEFIGUATION:Scheduled MonumentUST ENTRY NUMBER:1020090CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningRINCIPAL VULNERABILITY:Plant growthNEW ENTRY:NoOWNER TYPE:CrownCONTACT:Andy Crabb 01626 832093STE NAME:Stone alignment, five cairns, two stone hut circlesHEND:NoSTE NAME:Scheduled MonumentUST ENTRY NUMBER:1019566STE NAME:Scheduled MonumentUST ENTRY NUMBER:1019566CONDITION:Scheduled MonumentUST ENTRY NUMBER:1019566CONDITION:Scheduled MonumentUST ENTRY NUMBER:1019566CONDITION:Scheduled MonumentUST ENTRY NUMBER:1019566CONDITION:Scheduled MonumentUST ENTRY NUMBER:NoCONDITION:Scheduled MonumentUST ENTRY NUMBER:102002CONDITION:Scheduled MonumentUST ENTRY NUMBER:102002CONDITION:Scheduled MonumentUST ENTRY NUMBER:NoCONTACT:Pristoric settlement 610 metres south west of CrownNot CrawbCONTACT:Scheduled MonumentUST ENTRY NUMBER:102002 <td>SITE NAME:</td> <td colspan="6"></td>	SITE NAME:						
Concention of the section of the sectin of the section of the section of the sec	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020004			
OWNER TYPE:CrownCONTACT:Andy Crabb 01626 832093STEE NAME:Coaxial field system and prehistoric settlement 410UST ENTRY NUMBER1020090DESIGNATION:Scheduled MonumentUST ENTRY NUMBER1020090conDiftion:Generally satisfactory but with significant localised problemsTREND:DecliningRRINCIPAL VULNERABILITY:Plant growthNEW ENTRY:NoOWNER TYPE:ConnameContract:Andy Crabb 01626 832093STE NAME:Scheduled MonumentUST ENTRY NUMBER:NoSTE NAME:Scheduled MonumentUST ENTRY NUMBER:1019566Condition:Scheduled MonumentUST ENTRY NUMBER:1019566Condition:Scheduled MonumentUST ENTRY NUMBER:NoCondition:Scheduled MonumentUST ENTRY NUMBER:NoCondition:Scheduled MonumentUST ENTRY NUMBER:NoCondition:Scheduled MonumentUST ENTRY NUMBER:NoOWINER TYPE:PrivateScheduled MonumentUST ENTRY NUMBER:OWINER TYPE:PrivateScheduled MonumentUST ENTRY NUMBER:STEE NAME:Scheduled MonumentUST ENTRY NUMBER:NoDESIGNATION:Scheduled MonumentUST ENTRY NUMBER:1020002STEE NAME:Scheduled MonumentUST ENTRY NUMBER:1020002STEE NAME:Scheduled MonumentUST ENTRY NUMBER:1020002CONDITION:Scheduled MonumentUST ENTRY NUMBER:1020002CONDITION:Scheduled MonumentUST ENTR	CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining			
STITE NAME: Coaxial field system and prehistoric settlement 410 metres west of Cox Tor, Peter Tavy, West Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020090 CONDITION: Generally satisfactory but with significant localised problems TREND: Declining RRINCIPAL VULNERABILITY: Plant growth New ENTRY NUMBER: No OWNER TYPE: Crown CONTACT: Andy Crabb 01626 832093 STEE NAME: Scheduled Monument, five cairns, two stone hut circles and a length of reast of Horseyeet Walkhampton, West Devon Some reast of Horseyeet DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1019566 CONDITION: Generally unsatisfactory with major localised problems INEW ENTRY NUMBER: 1019566 CONDITION: Scrub / tree growth NEW ENTRY NUMBER: 1019566 OWNER TYPE: Private Contact: Andy Crabb 01626 832093 STE NAME: Scheduled Monument LIST ENTRY NUMBER: 1019566 OWNER TYPE: Scrub / tree growth NEW ENTRY: No OWNER TYPE: Private CONTACT: Andy Crabb 01626 832093 STE NAME: Scheduled Monument LIST ENTRY NUMBER: 102	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No			
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020090 conDITION: Generally satisfactory but with significant localised problems TREND: Declining PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No OWNER TYPE: Crown CONTACT: Andy Crabb 01626 832093 STEE NAME: Stone alignment, five cairns, two stone hut circles at a length of rear 600 metres north east of Horseyeat STEE NAME: Scheduled Monument LIST ENTRY NUMBER: 1019566 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining RENCIPAL VULNERABILITY: Scheduled Monument LIST ENTRY NUMBER: 1019566 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining RENCIPAL VULNERABILITY: Scheduled Monument LIST ENTRY NUMBER: No OWNER TYPE: Private CONTACT: Andy Crabb 01626 832093 STEE NAME: Prehistoric settlement 610 metres south west OF V-TOR, Peter Tavy West Devon STEE NAME: Scheduled Monument LIST ENTRY NUMBER: 1020002 STEE NAME: Scheduled Monument LIST ENTRY NUMBER:<	OWNER TYPE:	Crown CONTACT:		Andy Crabb 01626 832093			
Condition:Generally satisfactory but with significant localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Plant growthNEW ENTRY?:NoOWNER TYPE:CrownCONTACT:Andy Crabb 01626 832093Stre NAME:Stone alignment, five cairns, two stone hut circles ar length of reave Walkhampton, West DevonIST ENTRY NUMBER:1019566Stone alignment, five cairns, two stone hut circles ar length of reave Walkhampton, West DevonIST ENTRY NUMBER:1019566Stone alignment, five cairns, two stone hut circles ar length of reave Walkhampton, West DevonIST ENTRY NUMBER:1019566DESIGNATION:Scheduled MonumentIST ENTRY NUMBER:1019566CONDITION:Generally unsatisfactory with major localised problemsREND:DecliningCONTACT:Scrub/tree growthNew ENTRY?:NoOWNER TYPE:PrivateCONTACT:Andy Crabb 01626 832093STRE NAME:Prehistoric settlement 610 metres south west of Contact:NoSTRE NAME:Scheduled MonumentIST ENTRY NUMBER:1020002STRE NAME:Scheduled MonumentIST ENTRY NUMBER:1020002DESIGNATION:Scheduled MonumentIST ENTRY NUMBER:1020002CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningCONDITION:Generally satisfactory but with significant localised problemsNoNoCONDITION:Generally satisfactory but with significant localised problemsNoNoCONDITION:Generally	SITE NAME:	Coaxial field system and prehistoric settlement 41	0 metres west of C	ox Tor, Peter Tavy, West Devon			
problems Declining PRINCIPAL VULNERABILITY: Plant growth New ENTRY: No OWNER TYPE: Crown CONTACT: Andy Crabb 01626 832093 SITE NAME: Stone alignment, five cairns, two stone hut circles and a length of reave 600 metres north east of Horseyeat Mailkhampton, West Devon LIST ENTRY NUMBER: 1019566 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1019566 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining PRINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY: No OWNER TYPE: Private CONTACT: Andy Crabb 01626 832093 SITE NAME: Prehistoric settlement 610 metres south west of ConTACT: No DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020002 SITE NAME: Prehistoric settlement 610 metres south west of ConTACT: May Crabb 01626 832093 SITE NAME: Prehistoric settlement 610 metres south west of Contact: 1020002 CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1020002 CONDITION: Generally satisfactory but with significant localised problems TREND: Declining CONDITION: Plant growth NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020090			
OWNER TYPE:CrownCONTACT:Andy Crabb 01626 832093SITE NAME:Stone alignment, five cairns, two stone hut circles are store are sto	CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining			
SITE NAME: Stone alignment, five cairns, two stone hut circles and a length of reave 600 metres north east of Horseyeat Walkhampton, West Devon DESIGNATION: Scheduled Monument IJST ENTRY NUMBER: 1019566 condition: Generally unsatisfactory with major localised problems TREND: Declining condition: Scrub/tree growth NEW ENTRY?: No owner type: Private CONTACT: Andy Crabb 01626 832093 SISTE NAME: Prehistoric settlement 610 metres south west of Contract: Vest Devon DESIGNATION: Scheduled Monument IJST ENTRY NUMBER: 1020002 SISTE NAME: Prehistoric settlement 610 metres south west of Contract: Vest Devon DESIGNATION: Scheduled Monument IJST ENTRY NUMBER: 1020002 condition: Generally satisfactory but with significant localised problems TREND: Declining condition: Generally satisfactory but with significant localised problems TREND: Declining condition: Plant growth New ENTRY?: No	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No			
And FixedWalkhampton, West DevonIST ENTRY NUMBER:1019566DESIGNATION:Scheduled MonumentIIST ENTRY NUMBER:1019566condition:Generally unsatisfactory with major localised problemsREND:DecliningPRINCIPAL VULNERABILITY:Scrub/tree growthNEW ENTRY?:Noowner TYPE:PrivateCONTACT:Andy Crabb 01626 832093SITE NAME:Prehistoric settlement 610 metres south west of Contact:Vest DevonDESIGNATION:Scheduled MonumentIIST ENTRY NUMBER:1020002CONDITION:Generally satisfactory but with significant localised problemsREND:DecliningCONDITION:Plant growthNEW ENTRY?:No	OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093			
CONDITION:Generally unsatisfactory with major localised problemsREND:DecliningPRINCIPAL VULNERABILITY:Scrub/tree growthNEW ENTRY?:NoOWNER TYPE:PrivateCONTACT:Andy Crabb 01626 832093SITE NAME:Prehistoric settlement 610 metres south west of C-V-Type Peter Tay-Vest DevonDESIGNATION:Scheduled MonumentINST ENTRY NUMBER102002CONDITION:Generally satisfactory but with significant localised problemsIREND:DecliningPRINCIPAL VULNERABILITY:Hant growthNEW ENTRY?:No	SITE NAME:		and a length of reav	ve 600 metres north east of Horseyeatt			
problemsproblemsDecliningprincipal vulnerability:Scrub/tree growthNEW ENTRY?:Noowner type:PrivateCONTACT:Andy Crabb 01626 832093sitte NAME:Prehistoric settlement 610 metres south west of Cox Tor, Peter Tay, West DevonDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningPrincipal vulnerability:Plant growthNEW ENTRY?:No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019566			
OWNER TYPE:PrivateCONTACT:Andy Crabb 01626 832093SITE NAME:Prehistoric settlement 610 metres south west of C-> Tor, Peter Tay-> West DevonDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1020002CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Plant growthNEW ENTRY?:No	CONDITION:		TREND:	Declining			
SITE NAME: Prehistoric settlement 610 metres south west of Cor, Peter Tay, West Devon DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020002 CONDITION: Generally satisfactory but with significant localised problems TREND: Declining PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No			
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020002 CONDITION: Generally satisfactory but with significant localised problems TREND: Declining PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No	OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093			
CONDITION: Generally satisfactory but with significant localised problems TREND: Declining PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No	SITE NAME:	Prehistoric settlement 610 metres south west of C	Cox Tor, Peter Tav	y, West Devon			
problems New ENTRY: Plant growth	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020002			
5	CONDITION:		TREND:	Declining			
OWNER TYPE: Crown CONTACT: Andy Crabb 01626 832093	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY ?:	No			
	OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093			

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Stone hut circle and a short length of boundary wa settlement on the north east slope of Cox Tor, Per	II forming part of a ter Tavy, West De	n unenclosed stone hut circle von			
DESIGNATION:	Scheduled Monument LIST ENTRY NUMBER: 1011432					
CONDITION:	Generally satisfactory but with significant localised TREND: Declining problems					
PRINCIPAL VULNERABILITY:	Plant growth NEW ENTRY?: No					
OWNER TYPE:	Crown	CONTACT: Andy Crabb 01626 832093				
ITE NAME:	Cairnfield 460 metres south east of Cox Tor, Peter	r Tavy / Whitchurc	h, West Devon			
DESIGNATION:	Scheduled Monument LIST ENTRY NUMBER: 1020005					
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining			
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No			
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093			
ITE NAME:	Cairn south west of Lower Hartor Tor, Sheepstor,	, West Devon				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012293			
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable			
PRINCIPAL VULNERABILITY:	Plant growth NEW ENTRY?: No					
OWNER TYPE:	Private CONTACT: Andy Crabb 0162					
ITE NAME:	Cairn with a cist north of Drizzlecombe stone alignments, Sheepstor, West Devon					
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010654			
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining			
PRINCIPAL VULNERABILITY:	Plant growth NEW ENTRY?: No		No			
OWNER TYPE:	Private CONTACT: Andy Crabb 01626					
ITE NAME:	Cairn with cist north of Gutter Tor, Sheepstor, W	est Devon				
esignation:	Scheduled Monument	LIST ENTRY NUMBER:	1012473			
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining			
RINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No			
OWNER TYPE:	Private CONTACT: Andy Crabb 01626 8					
TE NAME:	Enclosed stone hut settlement south west of Gutte	er Tor, Sheepstor, V	West Devon			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012251			
ONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining			
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No			
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093			
ITE NAME:	Enclosure north west of Gutter Tor, Sheepstor, W	/est Devon				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012032			
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining			
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No			
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093			

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Part of Eylesbarrow reave, Sheepstor, West Devor	1				
DESIGNATION:	Scheduled Monument LIST ENTRY NUMBER: 1011958					
CONDITION:	Generally satisfactory but with significant localised _{TREND:} Declining problems					
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No			
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093			
SITE NAME:	Two stone alignments and a round cairn 390 metres north west of Sharpitor, Walkhampton, W					
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007422			
CONDITION:	Generally satisfactory but with minor localised problems	Declining				
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No			
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093			
SITE NAME:	Prehistoric enclosed settlement 950 metres north Devon	east of Ditsworthy	Warren House, Sheepstor, West			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021058			
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining			
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No			
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093			
SITE NAME:	Prehistoric settlement, three round cairns and a post-medieval rabbit warren at Legis Tor, Sheepstor, Wes Devon					
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019876			
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining			
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No			
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093			
SITE NAME:	Round cairn east of Whittenknowles Rocks, 960 m	etres ENE of Gutte	er Tor, Sheepstor, West Devon			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021052			
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining			
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No			
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093			
SITE NAME:	Two enclosures and a length of the Eylesbarrow w Sheepstor, West Devon	atershed reave 800) metres WSW of Eylesbarrow,			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013474			
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining			
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No			
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093			
SITE NAME:	Unenclosed stone hut settlement south west of Gu	utter Tor, Sheepsto	or, West Devon			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012239			
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining			
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No			
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093			

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Warren at Sheeps Tor, 520 metres north of Chubs	stone Cottage, She	epstor, West Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	IST ENTRY NUMBER: 1021391		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Agglomerate enclosure and 15 stone hut circles 56 Devon	0 metres west of 0	Cawsand Beacon, South Tawton, West		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010791		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Agglomerate enclosure and ten stone hut circles 50 Devon	00 metres west of	Cawsand Beacon, South Tawton, Wes		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010790		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	An agglomerated enclosed settlement 480 metres	west of Stoneyhurs	st, South Tawton, West Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017285		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY ?:	No		
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	A prehistoric settlement complex, length of reave, Cosdon Hill, Dartmoor Forest / South Tawton, W	tin streamwork an lest Devon	d stamping mill on the western slopes		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015760		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Coaxial field system, associated and later remains a Throwleigh, West Devon	at Throwleigh Com	nmon and Kennon Hill, Gidleigh /		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018916		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY ?:	No		
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	A length of the Great Western Reave, a prehistori Walkhampton Common, Walkhampton, West Dev	c settlement, three von	e cairns and two field systems on		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019589		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093		
RIORITY CATEGORIES	D Slow decay; solution agreed but F Repair scheme in progress	and NOTE	ABBREVIATIONS CA Conservation Area		
 Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. Slow deray: no solution agreed 		or Last year's pri ally shown in brac w use New Entry is	iority category is LB Listed Building :kets (otherwise, LPA Local Planning Authority		

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

use).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

SITE NAME:	An enclosed stone hut circle settlement and later t Tor, Walkhampton, West Devon	in working earthwo	orks, 540 metres south east of Down		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009088		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
RINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093		
ITE NAME:	An enclosure, attached stone hut circle and length West Devon	of reave 180 metre	es NNE of Leather Tor, Walkhamptor		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011248		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
RINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093		
ITE NAME:	An enclosure containing one stone hut circle 460 n	netres west of Cro	ss Gate, Walkhampton, West Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009091		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
RINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093		
ITE NAME:	An enclosure, six stone hut circles, a length of reav Leather Tor, Walkhampton, West Devon	re and several pros	pecting pits 170 metres north east of		
esignation:	Scheduled Monument	LIST ENTRY NUMBER:	1011247		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
RINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
DWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093		
DITE NAME:	Eleven stone hut circles, a length of boundary wall settlement on the north east slope of Sharpitor, W	and a field system f ′alkhampton, West	orming part of an unenclosed Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007435		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
RINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093		
ITE NAME:	Enclosure and stone hut circle 320 metres north ex settlement, Walkhampton, West Devon	ast of Sharpitor for	ming part of a stone hut circle		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007434		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
	Plant growth	NEW ENTRY ?:	No		
RINCIPAL VULNERABILITY:	0		Andy Crabb 01626 832093		
	Utility	CONTACT:	Andy Crabb 01626 832093		
DWNER TYPE:					
WNER TYPE:	Utility				
DWNER TYPE: ITE NAME: DESIGNATION:	Utility Enclosure and stone hut circle 700 metres west of	Sharpitor, Walkhar	mpton, West Devon		
RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: CONDITION: RINCIPAL VULNERABILITY:	Utility Enclosure and stone hut circle 700 metres west of Scheduled Monument Generally satisfactory but with significant localised	Sharpitor, Walkhar LIST ENTRY NUMBER:	npton, West Devon 1019590		

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.

Е

use).

Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Author NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Medieval settlement on Peek Hill, 240 metres and West Devon	280 metres north e	east of Lowery Tor, Walkhampton,		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020237		
CONDITION:	Generally satisfactory but with significant localised problems				
PRINCIPAL VULNERABILITY:	Plant growth	No			
OWNER TYPE:	Utility	Andy Crabb 01626 832093			
SITE NAME:	Prehistoric coaxial field system and cairns, an histo around Peek Hill, Walkhampton, West Devon	ric enclosure and p	art of RAF Sharpitor, situated on and		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020238		
CONDITION:	Generally satisfactory but with significant localised TREND: Declining problems				
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Round cairn 340 metres ESE of Norsworthy Bridge	e, Walkhampton, W	Vest Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008651		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Stone alignment, two round cairns and a length of Sharpitor and Leeden Tor, Walkhampton, West D	Walkhampton Com evon	nmon reave lying in a valley between		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007433		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth NEW ENTRY?: No		No		
OWNER TYPE:	Mixed, multiple owners CONTACT: Andy Crabb		Andy Crabb 01626 832093		
SITE NAME:	Stone hut circle 155 metres east of Sharpitor, Wal	khampton, West D	evon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007421		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Charity (non-heritage)	CONTACT:	Andy Crabb 01626 832093		
GITE NAME:	Stone hut circle 240 metres south of Down Tor, V	Valkhampton, Wes	t Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008641		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Stone hut circle 315 metres north east of Sharpito Walkhampton, West Devon	r forming part of a	stone hut circle settlement,		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007436		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
	problems				
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Stone hut circle 350 metres north east of Sharpito Walkhampton, West Devon	r forming part of a	stone hut circle settlement,			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007437			
CONDITION:	Generally unsatisfactory with major localised TREND: Declining problems					
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No			
OWNER TYPE:	Utility	Andy Crabb 01626 832093				
SITE NAME:	Stone hut circle 370 metres north east of Sharpito Walkhampton, West Devon	r forming part of a	stone hut circle settlement,			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007438			
CONDITION:	Generally unsatisfactory with major localised _{TREND:} Declining problems					
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No			
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093			
SITE NAME:	Stone hut circle settlement 250 metres east of Cur	ckoo Rock, Walkha	mpton, West Devon			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021057			
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining			
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No			
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093			
SITE NAME:	Stone hut circle settlement, irregular aggregate field system, two long houses and a medieval and post- medieval field system 700 metres SSW of Black Tor, Walkhampton, West Devon					
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011170			
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining			
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No			
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093			
SITE NAME:	Tinworks and other archaeological remains in the Tor, Walkhampton, West Devon	Meavy valley at Star	nlake, Black Tor, Hart Tor and Cramb			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020129			
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining			
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No			
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093			
SITE NAME:	Two stone hut circles 570 metres south west of D	own Tor, Walkhan	npton, West Devon			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019572			
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining			
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No			
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093			
SITE NAME:	Two stone hut circles, a reave, round cairn and she	elter south east of S	Sharpitor, Walkhampton, West Devo			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011167			
	Generally satisfactory but with significant localised TREND: Declining					
	problems	TREND:	Declining			
CONDITION: PRINCIPAL VULNERABILITY:		NEW ENTRY?:	No			

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / SOUTH WEST / DARTMOOR (NP) / EAST DEVON

SITE NAME:	Enclosure and stone hut circle 770 metres south of Cox Tor, Whitchurch, West Devon				
DESIGNATION:	Scheduled Monument	1020006			
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093		
	Eluvial tin streamworks and prehistoric coaxial field system together with other archaeological remains on Whitchurch Common, Peter Tavy / Sampford Spiney / Whitchurch, West Devon				
SITE NAME:	Eluvial tin streamworks and prehistoric coaxial field Whitchurch Common, Peter Tavy / Sampford Spin	d system together v ey / Whitchurch, V	vith other archaeological remains on Vest Devon		
SITE NAME: DESIGNATION:	Eluvial tin streamworks and prehistoric coaxial field Whitchurch Common, Peter Tavy / Sampford Spin Scheduled Monument	d system together v ey / Whitchurch, W list entry number:	vith other archaeological remains on Vest Devon 1020089		
	Whitchurch Common, Peter Tavy / Sampford Spin	ey / Whitchurch, W	Vest Devon		
DESIGNATION:	Whitchurch Common, Peter Tavy / Sampford Spin Scheduled Monument Generally satisfactory but with significant localised	ey / Whitchurch, W LIST ENTRY NUMBER:	Vest Devon 1020089		
DESIGNATION: CONDITION:	Whitchurch Common, Peter Tavy / Sampford Spin Scheduled Monument Generally satisfactory but with significant localised problems	ey / Whitchurch, W LIST ENTRY NUMBER: TREND:	Vest Devon 1020089 Unknown		


EAST DEVON

	SITE NAME:	Weycroft Manor and Weycroft Well House, Axminster	Circa C16 and possibly earlier, coursed stone with shingle roof and coped gable ends. C18 interior stair and panelling
	DESIGNATION:	Listed Building grade II*	and overmantle painting of hunting scene. Wing known as Well House has chamfered ceiling beams and fireplace
	CONDITION:	Poor	bressumer with painting over first floor door. Fire in March 2020 has burnt through the roof with damage to the
Lin and the	OCCUPANCY:	Vacant/not in use	interior of both Weycroft Manor and Well House. An
and the	PRIORITY CATEGORY:	E (A)	application for the repair of the building was submitted in Autumn 2020 and works have now commenced on site
	OWNER TYPE:	Private	(2021).
storic England Archive	LIST ENTRY NUMBER:	1162537	Contact: Rhiannon Rhys 0117 975 0685

	SITE NAME:	Church of St Michael, Honiton	Former parish church, latterly a chapel of ease, and now
	DESIGNATION:	Listed Building grade II*	closed for worship. Dates mainly from late C15. Interior destroyed by fire and rebuilt 1912. Metal corroding
	CONDITION:	Poor	internálly in arcaded capital heads. Leaking due to blocked valley gutters. The church was closed and, in early 2019,
	OCCUPANCY:	Vacant/not in use	was handed to the Diocesan Board of Finance which has since arranged for urgent repairs to be undertaken. Historic England is in discussion with the diocese regard
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	the future of the building.
	LIST ENTRY NUMBER:	1306112	Contact: Annie Evans 0117 975 0673

© Historic England

© Hist



© Historic England

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; в solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Stable block at Bishop's Court, Clyst St Mary, Sowton	Long early C16 range of stables attached to Bishop's Court tithe barn. Site is not in use. Historic England funded a
	DESIGNATION:	Listed Building grade I	feasibility study, which was completed in 2011.
	CONDITION:	Very bad	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
ic England	LIST ENTRY NUMBER:	1333998	Contact: Sarah Ball 0117 975 0666

	SITE NAME:	Tithe barn at Bishop's Court, Clyst St Mary, Sowton	Large mid-C14 barn with arch-braced base-cruck roof of seven bays, and long early C16 range of stables. The site is
	DESIGNATION:	Listed Building grade I	unused with a temporary corrugated roof. The owners undertook a Historic England grant-aided feasibility study
	CONDITION:	Very bad	into potential uses, completed 2011.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
© Historic England	LIST ENTRY NUMBER:	1164637	Contact: Sarah Ball 0117 975 0666

	SITE NAME:	Church of St Michael and All Angels, Awliscombe	Parish church. Largely late C15/early C16, mostly rebuilt in 1846 by Robert Medley Fulford. Mostly local flint with
	DESIGNATION:	Listed Place of Worship grade I	Beerstone dressings and a slate roof. Medieval and C19 features. Tower roof and valley gutter in a poor condition.
	CONDITION:	Poor	Some other minor areas of concern.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1098097	Contact: Annie Evans 0117 975 0673

© Historic England

© Historic

	SITE NAME:	Church of Holy Trinity, Dunkeswell	Parish church, built on the site of Dunkeswell Abbey Church in 1842. Local stone and flint rubble with
	DESIGNATION:	Listed Place of Worship grade II, SM	Hamstone dressings and detail and a slate roof. The roofs have had substantial leaks which have caused significant water ingress. This has damaged the internal plaster. The
	CONDITION:	Poor	congregation reroofed the church in 2015, but considerable interior work is still required and glazing is
	PRIORITY CATEGORY:	C (C)	also in poor condition. Discussions over the future of the
	OWNER TYPE:	Religious organisation	church are continuing with the Dunkeswell Abbey Preservation Trust and a new trust being formed for the
1	LIST ENTRY NUMBER:	1308999	church.
© Historic England			Contact: Annie Evans 0117 975 0673
Ho.	SITE NAME:	Church of St Paul, High Street, Honiton	Parish church. Completed 1838 by architect Charles Fowler. Romanesque style with apse. Seven bays with
	DESIGNATION:	Listed Place of Worship grade II, CA	round-arched aisle and clerestorey windows. Galleries. Restored 1849. Stone and plaster falling internally. Beerstone hoodmoulds aremade of cement on nails which
	CONDITION:	Poor	is causing decay problems. Windows are in need of repair

and there are cracks in the tower. Religious organisation 1116954 Contact: Annie Evans 0117 975 0673

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

OWNER TYPE:

C (C)

 D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

SITE NAME:	Newenham Abbey, Axminster		
DESIGNATION:	Scheduled Monument, 3 LBs	LIST ENTRY NUMBER:	1011671
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Hawkesdown Camp and associated outwork, Axm	outh	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017775
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	The Axe Boat, 22 metres north of the Axmouth R	oad Bridge, Axmou	th
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1433819
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow in Long Plantation, 610 metres north	east of Starved Oa	k Cross, Brampford Speke
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010636
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow in Long Plantation, 680 metres north	east of Starved Oa	k Cross, Brampford Speke
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010634
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth - General	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Two bowl barrows at Big Wood, 580 metres south Exmouth	h west and 470 me	tres south of Moorland Cottage,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017949
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Round barrow cemetery on Broad Down, Farway	/ Southleigh	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017642
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	A cairn 450 metres WNW of Putts Corner, formin Gittisham	ng part of a round l	barrow cemetery on Gittisham Hill,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014255
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	A bowl barrow 420 metres NNW of Ring-in-the-M Gittisham Hill, Gittisham / Honiton	1ire, forming part o	of a round barrow cemetery on
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014247
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Dumpdon Camp, Luppitt		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018851
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
OWNER TYPE:	Charity (heritage) CONTACT: Charlotte Russell C		
SITE NAME:	Membury Castle, Membury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017951
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Cursus, long mortuary enclosure, ring ditch and ot Barton, Nether Exe	her associated cro	pmarks 700 metres east of Nethere
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014144
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Belbury Castle, Ottery St. Mary / West Hill		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017774
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Stockland Great Castle, Stockland		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017952
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Stockland Little Castle, Stockland		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017953
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 470 metres east of Fortescue, Stoke	Canon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016564
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Roman villa 300 yards (270 metres) SSW of Holco	mbe Farm, Uplyme	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002558
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Earthwork enclosure 330 yards (300 metres) south west of Three Horse Shoes Inn, Upton Pyne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002645
CONDITION:	Unknown	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Castle Hill, Widworthy		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017477
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Woodbury Castle, Woodbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003862
CONDITION:	Extensive significant problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Charlotte Russell 01271 831505



© James Carter

C18 and C19 country house estate developed from earlier SITE NAME: Bicton, Bicton / Colaton Raleigh manor. Large park, important gardens and arboretum. / East Budleigh Registered park in three main ownerships. The core of the Registered Park and Garden site, including the principal house, has been developed in DESIGNATION: grade I, 18 LBs, SM the post-war era as a land-based college. Continuous pressure for development as the college has expanded has Generally unsatisfactory with CONDITION: tended to erode the integrity of the designed landscape. major localised problems The absence of a masterplan to guide and inform VULNERABILITY: development remains a major cause for concern. High Stable NEW ENTRY ?: No OWNER TYPE: Mixed, multiple owners LIST ENTRY NUMBER: 1000338 Contact: Jo McAllister 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no

D

Е

use).

obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
 - Registered Park and Garden Scheduled Monument
- SM
- UA WHS Unitary Authority World Heritage Site

SITE NAME:

DESIGNATION:

CONDITION:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

EXETER



SITE NAME:	Church of St Thomas the Apostle, Cowick Street, Exeter	Chur and e
DESIGNATION:	Listed Place of Worship grade I, CA	desig condi parap
CONDITION:	Poor	deco Histo
PRIORITY CATEGORY	· D (D)	funde
OWNER TYPE:	Religious organisation	Gran (2015
LIST ENTRY NUMBER:	1169954	interi

Street, Exeter

Religious organisation

CA

Poor

C (C)

1224263

Church of St Mary Steps, West

Listed Place of Worship grade I,

rch largely rebuilt in 1657. The west tower, south aisle east end of north aisle are C17. Due to poor original gn and lack of maintenance, roofs were in poor lition, rainwater goods failed and water penetrated pet walls and gutters damaging the structure and brative detail. A National Lottery Heritage Fund and oric England Repair Grant for Places of Worship ed a first phase of repairs (2013). Further NHLF nts for Places of Worship funded additional phases 5 and 2017). Additional work to the aisle roof and ior of the body of the church is still needed.

Contact: Annie Evans 0117 975 0673

C15 fabric. Restored 1868-72 by Edward Ashworth. Chancel re-ordered 1966 by Lawrence King. Nave, chancel, south west tower, south aisle and chapel, north west vestry. The church is very compact, which reflects its constricted site just within the walls of medieval Exeter. Slate roofs. Red Heavitree stone in large blocks with limestone dressings. A National Lottery Heritage Fund Grant for Places of Worship funded the repair of the tower, completed in early 2018. There are cracks in the south east corner and the aisle roof structure and covering are poor. A further phase of work will be needed. Contact: Sarah Ball 0117 975 0666

© Historic England

© Historic England

SITE NAME:	Exeter city walls		
DESIGNATION:	Scheduled Monument, 2 RPGs, 4 CAs	LIST ENTRY NUMBER:	1003858
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Charlotte Russell 01271 831505

EXMOOR (NP)

· · ·			
	SITE NAME:	Church of St Brendan, Church Hill, Brendon and Countisbury, North Devon	Parish church. Nave, chancel and south porch of 1738, tower rebuilt 1828; the whole restored and north aisle, north transept and vestry added in 1873. Dressed and
the water and	DESIGNATION:	Listed Place of Worship grade II	roughly dressed stone with some brick dressings to vestry, the C19 work snecked with ashlar dressings. There are
	CONDITION:	Poor	problems with the foundation beams and dampness in the tower. The gutters and drainage need repair and the
CALL.	PRIORITY CATEGORY:	C (C)	external walls need repointing.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1289343	Contact: Annie Evans 0117 975 0673
ric England			

© Historic England



SITE NAME:	Church of St Martin, Martinhoe, North Devon	Small parish church dating from C13 with later additions. Stone rubble, tower roughly coursed, with ashlar dressings
DESIGNATION:	Listed Place of Worship grade II*	and slate roofs. Some slipped slates, cracked cement, ground gutter and rainwater goods in bad condition.
CONDITION:	Poor	Cement pointing round tower arch, blistering paint on north aisle and south wall of chancel. Tower roof leaking
PRIORITY CATEGORY:	C (C)	with floors within tower rotten making access difficult.
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1106778	Contact: Annie Evans 0117 975 0673

© Historic England

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

ÍΙΑ

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- Unitary Authority World Heritage Site WHS

76

SITE NAME:	Badgworthy deserted medieval village, Doone's Ho	ouses, Brendon and	Countisbury, North Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003886
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Two round barrows on Cheriton Ridge, Brendon a	and Countisbury, N	lorth Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002583
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Earthwork defences of Countisbury Castle promo	ntory fort (Wind H	ill), Lynton and Lynmouth, North
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020807
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Remains of leat serving former hydro-electric generating station, on the south bank of the East Lyn River, 2 metres east of Oxen Tor, Lynton and Lynmouth, North Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020808
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Standing stones on eastern edge of Furzehill Comr	non, Lynton and Ly	nmouth, North Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003300
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Two round barrows and cairn cemetery, llkerton l	Ridge, Lynton and L	ynmouth, North Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002566
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Two round barrows near Warcombe Water, Lynt	on and Lynmouth, I	North Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003299
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

MID DEVON

	SITE NAME:	The Manor House Hotel, 2, Fore Street, Cullompton	Hotel in partial use, formerly early C17 merchant's house. Concerns regarding the structural condition and public
	DESIGNATION:	Listed Building grade II*, CA	safety led to a major phase of external and structural works in 2015-16 but subsequent concerns arose regarding the
	CONDITION:	Poor	stability of the ornate shell hood porch and the hanging sign on the main facade. A listed building application was
	OCCUPANCY:	Part occupied/part in use	submitted to stabilise the hood and sign and undertake
	PRIORITY CATEGORY:	F (F)	works to the rear facade, the site has been scaffolded and work was started but due to the impact of Covid-19 is still
	OWNER TYPE:	Commercial company	being completed in June 2021.
gland	LIST ENTRY NUMBER:	1105901	Contact: Jenny Chesher 0117 975 0686

© Historic Engla



	SITE NAME:	Prescott Baptist Chapel, Culmstock	Simple C18 church in an isolated rural location. There are two other Baptist churches within a five mile radius which
	DESIGNATION:	Listed Building grade II*	are closer to centres of population. Its physical problems are putting historic window fabric at risk, and could rapidly
	CONDITION:	Poor	escalate into more serious repair problems if not remedied. The chapel has been sold and is no longer in use
	OCCUPANCY:	Part occupied/part in use	as a place of worship. Historic England has had discussions
	PRIORITY CATEGORY:	C (C)	with the owner but work is required.
1	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	477 4	Contact: Annie Evans 0117 975 0673

© Historic England

© Historic England



	ba	Old farmhouse with integral barn at East Barton, Exeter Road, Tiverton	The building dates from C16 and the house has not been occupied in liviing memory. It is a very rare example of a house with integral barn, being an evolved form of the
	DESIGNATION:	Listed Building grade II*	longhouse. It retains considerable evidence of its form and function including important early features such as jointed
	CONDITION:	Poor	cruck roof trusses, two internal jetties and substantial floor beams. The building is largely water tight, but there is slow
5	OCCUPANCY:	Vacant/not in use	beams. The building is largely water tight, but there is slo structural failure of internal elements and deterioration o some external cob walls. A previous conversion scheme lapsed and there are no current proposals for its reuse o
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	repair.
	LIST ENTRY NUMBER:	1384813	Contact: Jenny Chesher 0117 975 0686

SITE NAME:	Roman fort 300 metres north east of Cudmore Fa	rm, Bampton / Clay	vhanger
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011251
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	A henge, two barrows, two ring ditches, two enclo of Lower Hampson, Bow	osures and part of a	linear feature 420 metres north west
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015472
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 80 metres south west of Hampson C	ottage, Bow	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016189
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.

C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA LB LPA NP RPG SM

- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

UA Unitary Authority WHS World Heritage Site

OWNER TYPE: Private, multiple owners SITE NAME: Two bowl barrows 180 metres south west of Hamp DESIGNATION: Scheduled Monument CONDITION: Unknown PRINCIPAL VULNERABILITY: Arable ploughing OWNER TYPE: Private SITE NAME: Two bowl barrows 250 metres north of Natson Fail DESIGNATION: Scheduled Monument CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: DPSON COttage, Bow LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:	1015471 Unknown No Charlotte Russell 01271 831505 1015474 Declining No Charlotte Russell 01271 831505 V 1015475 Unknown V I015475 Unknown Ko I015476 Declining No
PRINCIPAL VULNERABILITY: Stock erosion - moderate Private Bowl barrow 220 metres south west of Hampson C DESIGNATION: Scheduled Monument CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing OWNER TYPE: Private, multiple owners SITE NAME: Two bowl barrows 180 metres south west of Hamp DESIGNATION: Scheduled Monument CONDITION: Unknown PRINCIPAL VULNERABILITY: Arable ploughing OWNER TYPE: Private Stre NAME: Two bowl barrows 250 metres north of Natson Far DESIGNATION: Scheduled Monument CONDITION: Private SITE NAME: Two bowl barrows 250 metres north of Natson Far DESIGNATION: Scheduled Monument Extensive significant problems STRE NAME: Two bowl barrows 250 metres north of Natson Far DESIGNATION: Scheduled Monument DESIGNATION: Arable ploughing PRINCIPAL VULNERABILITY: Arable ploughing DESIGNATION: Scheduled Monument Extensive significant problems STRE NAME: Two bowl barrows 250 metres north of Natson Far DESIGNATION: Arable ploughing PRINCIPAL VULNERABILITY: Arable ploughing DESIGNATION: Arable ploughing	NEW ENTRY?: CONTACT: LIST ENTRY NUMBER: TREND: NEW ENTRY? CONTACT: CONTACT: IST ENTRY NUMBER: TREND: NEW ENTRY? CONTACT:	No Charlotte Russell 01271 831505 I015474 Declining No Charlotte Russell 01271 831505 V I015475 Unknown No Charlotte Russell 01271 831505 I015475 Unknown I015476 Declining
Desire or order. In order and DOWNER TYPE: Private Bowl barrow 220 metres south west of Hampson C DESIGNATION: Scheduled Monument CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing DOWNER TYPE: Private, multiple owners SITE NAME: Two bowl barrows 180 metres south west of Hamp DESIGNATION: Scheduled Monument DESIGNATION: Scheduled Monument DESIGNATION: Scheduled Monument DESIGNATION: Vulnerown PRINCIPAL VULNERABILITY: Arable ploughing DESIGNATION: Scheduled Monument CONDITION: Unknown PRINCIPAL VULNERABILITY: Arable ploughing DOWNER TYPE: Private SITE NAME: Two bowl barrows 250 metres north of Natson Fai DESIGNATION: Scheduled Monument CONDITION: Extensive significant problems DESIGNATION: Scheduled Monument CONDITION: Extensive significant problems DESIGNATION: Extensive significant problems CONDITION: Extensive significant problems	CONTACT: COTTAGE, BOW LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: DESON COTTAGE, BOW LIST ENTRY NUMBER: TREND: CONTACT: CON	Charlotte Russell 01271 831505 Charlotte Russell 01271 831505 Occiming No Charlotte Russell 01271 831505 Occiming Occimi
SITE NAME: Bowl barrow 220 metres south west of Hampson C DESIGNATION: Scheduled Monument CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing OWNER TYPE: Private, multiple owners SITE NAME: Two bowl barrows 180 metres south west of Hamp DESIGNATION: Scheduled Monument CONDITION: Unknown PRINCIPAL VULNERABILITY: Arable ploughing OWNER TYPE: Private SITE NAME: Two bowl barrows 180 metres south west of Hamp DESIGNATION: Scheduled Monument CONDITION: Unknown PRINCIPAL VULNERABILITY: Arable ploughing OWNER TYPE: Private SITE NAME: Two bowl barrows 250 metres north of Natson Fai DESIGNATION: Scheduled Monument CONDITION: Extensive significant problems CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing	Cottage, Bow LIST ENTRY NUMBER: TREND: CONTACT:	I015474 Declining No Charlotte Russell 01271 831505 I015475 Unknown No Charlotte Russell 01271 831505 I015475 Unknown I015476 Declining
Designation:Scheduled MonumentCONDITION:Extensive significant problemsPRINCIPAL VULNERABILITY:Arable ploughingDWNER TYPE:Private, multiple ownersSITE NAME:Two bowl barrows 180 metres south west of HampDESIGNATION:Scheduled MonumentCONDITION:UnknownPRINCIPAL VULNERABILITY:Arable ploughingDWNER TYPE:PrivateScheduled MonumentScheduled MonumentCONDITION:UnknownPRINCIPAL VULNERABILITY:Arable ploughingDWNER TYPE:Two bowl barrows 250 metres north of Natson FailDESIGNATION:Scheduled MonumentDESIGNATION:Scheduled MonumentCONDITION:Extensive significant problemsPRINCIPAL VULNERABILITY:Arable ploughing	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: CONTACT: LIST ENTRY NUMBER: TREND: CONTACT: CONTACT: LIST ENTRY NUMBER: TREND: LIST ENTRY NUMBER: TREND: NEW ENTRY?:	Declining No Charlotte Russell 01271 831505 V 1015475 Unknown Charlotte Russell 01271 831505 Charlotte Russell 01271 831505
CONDITION:Extensive significant problemsPRINCIPAL VULNERABILITY:Arable ploughingOWNER TYPE:Private, multiple ownersSITE NAME:Two bowl barrows 180 metres south west of HampDESIGNATION:Scheduled MonumentCONDITION:UnknownPRINCIPAL VULNERABILITY:Arable ploughingOWNER TYPE:PrivateSITE NAME:Two bowl barrows 250 metres north of Natson FaiDESIGNATION:Scheduled MonumentCONDITION:Extensive significant problemsPRINCIPAL VULNERABILITY:Arable ploughing	TREND: NEW ENTRY?: CONTACT: CONTACT: UST ENTRY NUMBER: TREND: CONTACT: CONTACT: UST ENTRY NUMBER: TREND: LIST ENTRY NUMBER: TREND: NEW ENTRY?:	Declining No Charlotte Russell 01271 831505 V 1015475 Unknown Charlotte Russell 01271 831505 Charlotte Russell 01271 831505
PRINCIPAL VULNERABILITY: Arable ploughing OWNER TYPE: Private, multiple owners SITE NAME: Two bowl barrows 180 metres south west of Hamp DESIGNATION: Scheduled Monument CONDITION: Unknown PRINCIPAL VULNERABILITY: Arable ploughing OWNER TYPE: Private SITE NAME: Two bowl barrows 250 metres north of Natson Fail DESIGNATION: Scheduled Monument CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing	NEW ENTRY?: CONTACT: CONTACT: IDSON COttage, Bow LIST ENTRY NUMBER: TREND: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: TREND: LIST ENTRY NUMBER: TREND: NEW ENTRY?:	No Charlotte Russell 01271 831505 V 1015475 Unknown No Charlotte Russell 01271 831505 U1015476 Declining
OWNER TYPE:Private, multiple ownersSITE NAME:Two bowl barrows 180 metres south west of HampDESIGNATION:Scheduled MonumentCONDITION:UnknownPRINCIPAL VULNERABILITY:Arable ploughingOWNER TYPE:PrivateSITE NAME:Two bowl barrows 250 metres north of Natson FaiDESIGNATION:Scheduled MonumentCONDITION:Extensive significant problemsPRINCIPAL VULNERABILITY:Arable ploughing	CONTACT: IPSON COTTAGE, BOW LIST ENTRY NUMBER: TREND: CONTACT: CONTACT: INEW ENTRY: LIST ENTRY NUMBER: TREND: NEW ENTRY:	Charlotte Russell 01271 831505
SITE NAME: Two bowl barrows 180 metres south west of Hamp DESIGNATION: Scheduled Monument CONDITION: Unknown PRINCIPAL VULNERABILITY: Arable ploughing OWNER TYPE: Private SITE NAME: Two bowl barrows 250 metres north of Natson Fail DESIGNATION: Scheduled Monument CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing	IST ENTRY NUMBER: TREND: NEW ENTRY? CONTACT: TREND: LIST ENTRY NUMBER: TREND: NEW ENTRY?:	v 1015475 Unknown No Charlotte Russell 01271 831505 1015476 Declining
DESIGNATION: Scheduled Monument CONDITION: Unknown PRINCIPAL VULNERABILITY: Arable ploughing DWNER TYPE: Private SITE NAME: Two bowl barrows 250 metres north of Natson Fail DESIGNATION: Scheduled Monument CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: CONTACT: LIST ENTRY NUMBER: TREND: NEW ENTRY?:	1015475 Unknown No Charlotte Russell 01271 831505
CONDITION: Unknown PRINCIPAL VULNERABILITY: Arable ploughing DWNER TYPE: Private SITE NAME: Two bowl barrows 250 metres north of Natson Failed Monument DESIGNATION: Scheduled Monument CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing	TREND: NEW ENTRY? CONTACT: CONTACT: BOW LIST ENTRY NUMBER: TREND: NEW ENTRY?:	Unknown No Charlotte Russell 01271 831505 1015476 Declining
PRINCIPAL VULNERABILITY: Arable ploughing DWNER TYPE: Private SITE NAME: Two bowl barrows 250 metres north of Natson Fail DESIGNATION: Scheduled Monument CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing	NEW ENTRY?: CONTACT: Imm, Bow LIST ENTRY NUMBER: TREND: NEW ENTRY?:	No Charlotte Russell 01271 831505 1015476 Declining
OWNER TYPE: Private SITE NAME: Two bowl barrows 250 metres north of Natson Fail DESIGNATION: Scheduled Monument CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing	CONTACT: TREND: NEW ENTRY:	Charlotte Russell 01271 831505 1015476 Declining
SITE NAME: Two bowl barrows 250 metres north of Natson Fail DESIGNATION: Scheduled Monument CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing	Irm, Bow LIST ENTRY NUMBER: TREND: NEW ENTRY?:	1015476 Declining
DESIGNATION: Scheduled Monument CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing	LIST ENTRY NUMBER: TREND: NEW ENTRY?:	Declining
CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing	TREND: NEW ENTRY?:	Declining
PRINCIPAL VULNERABILITY: Arable ploughing	NEW ENTRY?:	-
		No
OWNER TYPE: Private	CONTACT:	
		Charlotte Russell 01271 831505
SITE NAME: Canonsleigh Abbey, Burlescombe		
DESIGNATION: Scheduled Monument, LB grade II, CA	LIST ENTRY NUMBER:	1003830
CONDITION: Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY: Other	NEW ENTRY?:	No
OWNER TYPE: Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
ITE NAME: Millsome Castle, Coldridge		
DESIGNATION: Scheduled Monument	LIST ENTRY NUMBER:	1016227
CONDITION: Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY: Plant growth	NEW ENTRY?:	No
OWNER TYPE: Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME: Posbury camp, Castle Down, Crediton Hamlets		
DESIGNATION: Scheduled Monument	LIST ENTRY NUMBER:	1003826
CONDITION: Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY: Plant growth	NEW ENTRY?:	No
OWNER TYPE: Private	CONTACT:	Charlotte Russell 01271 831505
ITE NAME: Romano-British villa, Downes, near Crediton, Cred	liton Hamlets	
DESIGNATION: Scheduled Monument	LIST ENTRY NUMBER:	1002668
CONDITION: Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY: Other	NEW ENTRY ?:	No
OWNER TYPE: Private	CONTACT:	Charlotte Russell 01271 831505

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; no solution agreed but not yet implemented.
C Slow decay; no solution agreed.
D Slow decay; solution agreed but F not yet implemented.
C Slow decay; no solution agreed.
D Slow decay; solution agreed but F not yet implemented.
D Slow decay; solution agreed but or yet implemented.
D Slow decay; solution agreed but F not yet implemented.
D Slow decay; solution agreed but or yet implemented.
D Slow decay; solution agreed but or yet implemented.
D Slow decay; solution agreed but or yet implemented.
D Slow decay; solution agreed but or yet implemented.
D Slow decay; solution agreed but or yet implemented.
D Slow decay; solution agreed but or yet implemented.
D Slow decay; solution agreed but or yet implemented.
D Slow decay; solution agreed but or yet implemented.
D Slow decay; solution agreed but or yet implemented.

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	IAME: Two Roman forts and two Roman camps at St Andrew's Hill, Cullompton			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019543	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505	
SITE NAME:	Three bowl barrows 250 metres south east	of Gibbet Moor Cross, T	empleton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017134	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY ?:	No	
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505	
SITE NAME:	Bowl barrow 260 metres north west of Put	son Cross, Tiverton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017132	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners CONTACT:		Charlotte Russell 01271 831505	
SITE NAME:	Eggesford Castle, 640 metres north east of	Eggesford House, Wembw	vorthy	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016208	
CONDITION:	Extensive significant problems TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505	
SITE NAME:	Bowl barrow 130 metres north east of Burs	ston Cross, Zeal Monacho	rum	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015152	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505	
SITE NAME:	Bow			
DESIGNATION:	Conservation Area, 21 LBs	NEW ENTRY?:	No	
CONDITION:	Very bad	TREND:	No significant change	
VULNERABILITY:	Medium	CONTACT:	Sue Warren (LPA) 01884 234264	
SITE NAME:	Cullompton			
DESIGNATION:	Conservation Area, 46 LBs	NEW ENTRY?:	No	
CONDITION:	Very bad	TREND:	Deteriorating	
VULNERABILITY:	Low	CONTACT:	Sue Warren (LPA) 01884 234264	
SITE NAME:	Tiverton			
DESIGNATION: Conservation Area, 194 LBs, 2 SMs NEW ENTRY?:		No		
DESIGNATION:	Conservation Area, 194 LBs, 2 SMs		INO	
designation: Condition:	Conservation Area, 194 LBs, 2 SMs Very bad	TREND:	Deteriorating	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

NORTH DEVON

SITE NAME:	Old School Coffee House Formerly Horwoods School, Church Lane, Barnstaple	This two storey grade II* listed school house has been in single use, first as a school and then as a coffee shop since the C17. Despite being restored at the beginning of the
DESIGNATION:	Listed Building grade II*, CA	C20, it retains many original features and an intact internal layout. The building has not been in active use for c.3 year
CONDITION:	Fair	and has a new owner. Plans to subdivide the building into two flats are currently lodged with the local authority.
OCCUPANCY:	Vacant/not in use	two hats are currently lodged with the local additiney.
PRIORITY CATEGORY:	C (New entry)	
OWNER TYPE:	Charity (non-heritage)	
LIST ENTRY NUMBER:	1385105	Contact: Catherine Marlow 0117 975 0732



	SITE NAME:	Hall House, Bishop's Tawton	Built c1846-50 by Philip Hardwick, with a rear range by RD
	DESIGNATION:	Listed Building grade II*	Gould. The house lies within an estate, and there are several other listed structures within the vicinity. The main
1	CONDITION:	Poor	range is generally in a fair condition. The rear range is still in poor condition, though the roof is weathertight. The
m	OCCUPANCY:	Part occupied/part in use	owners are very gradually addressing the repair issues.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1107730	Contact: Annie Evans 0117 975 0673

© Historic England Archive

© Historic England

	SITE NAME:	Bunksland Farmhouse and attached outbuildings, East Anstey	A remarkably unspoilt medieval farmhouse, multiphased, with a surviving early roof structure and interesting plan form. The property has been vacant since 2009 and has
	DESIGNATION:	Listed Building grade II*	suffered from deterioration at the external cob wall as we as the collapse of an internal cob partition and roof truss
	CONDITION:	Very bad	supporting the floor above. Historic England has supported North Devon District Council to serve an Urgent Works
	OCCUPANCY:	Vacant/not in use	Notice which has enabled propping and protection work to be carried out. Ownership uncertainties had delayed further resolution but are now progressing.
A STREET	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1106670	Contact: Annie Evans 0117 975 0673

1	SITE NAME:	Broomham Farmhouse, King's Nympton	Early C16 longhouse with later additions. The roof was re- thatched with Historic England grant aid in 2013.
	DESIGNATION:	Listed Building grade II*	Improvements have permitted the family to return to the house, and work is very gradually continuing, but further
	CONDITION:	Poor	structural work is still required.
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Private	
Archive	LIST ENTRY NUMBER:	1152877	Contact: Annie Evans 0117 975 0673

© Historic England A



	SITE NAME:	Church of St James, Arlington	Parish church. Late CI5 or early CI6 tower with some
	DESIGNATION:	Listed Place of Worship grade II*	C19 work. Set in the landscape of Arlington Court, which is owned by the National Trust. Options are being
4	CONDITION:	Poor	explored by the very small congregation, possibly in conjunction with the neighbouring National Trust. Blocked
	PRIORITY CATEGORY:	A (A)	downpipes are causing significant damage to the interior
ALC: NO	OWNER TYPE:	Religious organisation	and roofing repairs are also required. The congregation has been seeking funding but no substantive work has been
de	LIST ENTRY NUMBER:	1106820	carried out to date.
Sale A			Contact: Annie Evans 0117 975 0673

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

Anna and	SITE NAME:	Church of St John the Baptist, East Down	Parish church sited adjacent to the manor house. Surviving C13 fabric to tower, C15 south aisle and some C19 work.
	DESIGNATION:	Listed Place of Worship grade II*	The congregation is steadily working through repairs. Roof repairs were completed under the National Lottery
N/A	CONDITION:	Poor	Heritage Fund and Historic England Repair Grants for Places of Worship scheme in 2005. Tower is very damp
	PRIORITY CATEGORY:	A (A)	and has structural issues with significant cracking. Condition
	OWNER TYPE:	Religious organisation	of windows also remains poor.
Section of	LIST ENTRY NUMBER:	1163326	Contact: Annie Evans 0117 975 0673

© Historic England



	SITE NAME:	Parish Church of Holy Trinity, Church Road, Ilfracombe	Large parish church. Early tower with church enlarged in the 1320s and again in the C15. Problems with roof and
	DESIGNATION:	Listed Place of Worship grade I, CA	gutters led to water penetration and subsequent damage o internal fabric. The congregation has been in discussions with Historic England and has repaired the eastern roofs
	CONDITION:	Poor	with a Listed Places of Worship Roof Repairs Grant. However the tower (with Norman stonework) and wes
	PRIORITY CATEGORY:	C (C)	end of the church, including windows with notable Kempe
	OWNER TYPE:	Religious organisation	glass, remain in poor condition.
	LIST ENTRY NUMBER:	1208207	Contact: Annie Evans 0117 975 0673

© Historic England

	SITE NAME:	Church of St Michael, Marwood	Parish church. C13 fabric to chancel with two lancets to
	DESIGNATION:	Listed Place of Worship grade I, CA	north side and pointed south doorway. South transept with single lancet in east wall and unmoulded pointed arch into nave. Battered plinth in north aisle indicates former north
	CONDITION:	Poor	transept and original cruciform plan. Cracked ridge tiles and missing slates. Rainwater goods need overhauling.
	PRIORITY CATEGORY:	C (C)	Internal damp staining to walls. Bench ends with active
	OWNER TYPE:	Religious organisation	insect infestation. Vegetation growth on stonework to tower, vestry chimney and north aisle wall. An application
	LIST ENTRY NUMBER:	1107157	tower, vestry chimney and north aisle wall. An application to the Listed Places of Worship Roof Repair Grant scheme in 2016 was unsuccessful.
			III 2010 was diffuccessidi.

© Historic England

Contact: Annie Evans 0117 975 0673

	SITE NAME:	Church of St John, Satterleigh and Warkleigh	Parish church, sited in a farmyard. Damp has caused deterioration of the fabric and significant works are	
	DESIGNATION:	Listed Place of Worship grade II*	needed. The east end of the south aisle has cracking and there is some structural movement in the fabric.	
	CONDITION:	Poor		
	PRIORITY CATEGORY:	C (C)		
	OWNER TYPE:	Religious organisation		
	LIST ENTRY NUMBER:	1258818	Contact: Annie Evans 0117 975 0673	

© Historic England



	SITE NAME:	Church of St Mary Magdalene, The Churchyard, South Molton	Large parish church mainly C15, restored in C19. The stonework has started to decay and the roofs are in bad
and a	DESIGNATION:	Listed Place of Worship grade I, CA	condition. Water ingress to the interior is causing continuing damage. The church was awarded a maximum Listed Places of Worship Roof Repairs Grant and during
	CONDITION:	Poor	2018 the south aisle, south transept and Lady Chapel roo were re-slated. Timber flooring has also been repaired.
	PRIORITY CATEGORY:	B (B)	Further funding is still required.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1317855	Contact: Annie Evans 0117 975 0673

© Historic England

- А
- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented В implemented.
- C Slow decay; no solution agreed.

D Е

use).

Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Barnstaple Castle, Barnstaple			
DESIGNATION:	Scheduled Monun	· ·	LIST ENTRY NUMBER:	1020922
CONDITION:	Generally satisfactory but with significant localised problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism		NEW ENTRY?:	No
OWNER TYPE:	Local authority		CONTACT:	Charlotte Russell 01271 831505
P Historic England	SITE NAME: DESIGNATION: CONDITION: PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER:	Church of St Bartholomew, Stoke Rivers Listed Place of Worship grade I Poor C (C) Religious organisation 1107658	some earlier fabr restoration in 18 restoration work dressings. Slate re nave, chancel, so work to the chan rainwater goods reported to be in vegetation growt reported to be p	ainly late C15 to early C16 but may be ic. Some C18 work survives. Main 80s and in 1905, but possibly some earlier of 1831. Stone rubble with stone pofs with coped gabled ends. West tower uth aisle and south porch. There has beer icel south gutter but an overhaul of other is still needed. Poor drainage. Roofs a poor condition. Tower is damp with h and tower internal timbers are also oor.
SITE NAME:	Hillfort on White	chapel Moors, 640 metres north e	east of Garliford M	ill, Bishop's Nympton
DESIGNATION:	Scheduled Monun	nent	LIST ENTRY NUMBER:	1016214
CONDITION:	Generally satisfact problems	ory but with minor localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growt	h	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners		CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Round barrow ce	metery 500 metres east of Little I	Bray Cross, Brattor	n Fleming
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1017137
CONDITION:	Generally unsatisfactory with major localised problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - ex	xtensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple c	owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Wayside cross known as Eastacott Cross or the Sto		onen Hammer, Chi	ttlehampton
DESIGNATION:	Scheduled Monument, LB grade II		LIST ENTRY NUMBER:	1013727
CONDITION:	Generally satisfactory but with significant localised problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/e	erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Local authority		CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 280 Chulmleigh	metres north east of Beacon Moo	or Cross, forming p	part of a round barrow cemetery,
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1015153
CONDITION:	Extensive significant problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 330	metres east of Beacon Moor Cro	ss, forming part of	a round barrow cemetery, Chulmleigh
DESIGNATION:	Scheduled Monun	nent	LIST ENTRY NUMBER:	1015154
CONDITION:	Extensive significa	nt problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Charlotte Russell 01271 831505

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Hillfort 400 metres north west of Woodhouse, Qu	een's Nympton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015463
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private CONTACT: Charlotte Russell		
SITE NAME:	Two bowl barrows 100 metres east of Catkill Cros	s, Rose Ash	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015145
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Camp south of Birch Ham Wood, Stoke Rivers		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002533
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 225 metres south east of Elworthy C	ross, Witheridge	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016650
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 300 metres north west of Witheridge	e Moor Cross (wes	t), Witheridge
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016652
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 610 metres south east of Elworthy C	ross, Witheridge	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016651
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow on Dart Raffe Moor lying 550 metres	south west of Bro	adridge Farm, Witheridge
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015150
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	llfracombe		
DESIGNATION:	Conservation Area, 119 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	No significant change

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

SOUTH HAMS




SITE NAME Deer Park wall at Berry Pomeroy Castle, Berry Pomeroy DESIGNATION: Listed Building grade II* CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: F (F) OWNER TYPE: Private LIST ENTRY NUMBER: 1108572

© Historic England



SITE NAME:	Week, Berry Pomeroy
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1108575

© Historic England



Yarde Farmhouse, Malborough

Listed Building grade I

Part occupied/part in use

Fair

C (C)

Private

1108479

Contact: Jenny Chesher 0117 975 0686

Late CI6 evolved manor house. The house, its detached kitchen and also the early C18 chamber block are now wind and weathertight externally. The greatest area of uncertainty remains the interior of the lodging range and the important painted hangings whose conservation and future display are not resolved.

Medieval deer park wall, extended in the C16. Neglected,

heavily overgrown with ivy and partially collapsed in places.

prioritise repairs. A pilot repair scheme was undertaken in 2013/14 with funding from Natural England. This was

extended in 2014/15 and a team from the estate continues to make repairs for a period every summer. There have

been some further areas of collapse and as of 2020 work is

still required to stabilise other sections, but steady progress

Small house reduced in size and now derelict. C16, date

museum. Also barn at right angles. Stone rubble walls with gabled ends, new slate roof and concrete ring-beam

1584 on interior plasterwork now removed to Totnes

replacing scantle roof. Originally L-shaped on plan but

south wing replaced by a linhay. South east wall partly rebuilt in blockwork. No first floor, stair or glazing, wall

footings concreted, ground level raised at north sides. Condition stable but vulnerable. Historic England is in

discussion with owner and lessee regarding repair and

The estate has prepared a condition survey in order to

understand and monitor mechanisms of decay and to

Contact: Annie Evans 0117 975 0673

Contact: Annie Evans 0117 975 0673

is being made.

reuse.

Contact: Annie Evans 0117 975 0673

© South Hams District Council



	SITE NAME:	39, The High Street, Totnes	Fine C17 plasterwork and interior threatened by poor
	DESIGNATION:	Listed Building grade II*	condition of roof and opening up of floor on the second floor. Ground floor is a shop. Upper floors are unoccupied
	CONDITION:	Poor	and in need of repair and new services. Slipped slates and windows in very poor condition. There is increased
CLU I	OCCUPANCY:	Part occupied/part in use	concern about the condition of the building and Historic
	PRIORITY CATEGORY:	C (C)	England has been in discussion with the Local Authority.
4	OWNER TYPE:	Private	
6	LIST ENTRY NUMBER:	1236133	Contact: Annie Evans 0117 975 0673

© Historic England Archive

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed. С
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

D

Е

use)

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

ΪA

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM
- Unitary Authority World Heritage Site WHS

	SITE NAME:	Fort Bovisand, Wembury	Major C19 fort complex forming part of the ring of
	DESIGNATION:	Scheduled Monument, 2 LBs	defences around Plymouth. Most recently used as a base for training divers, it is now disused. A scheme for
	CONDITION:	Poor	resdiential conversion with significant levels of public access and interpretation has been agreed and planning
-5-)	OCCUPANCY:	Vacant/not in use	permission was granted in 2017. Although some recording
	PRIORITY CATEGORY:	D (D)	and ground investigations have been carried out, meaningful restoration has yet to start.
A CONTRACTOR	OWNER TYPE:	Charity (heritage)	
and the second	LIST ENTRY NUMBER:	1002584	Contact: Simon Hickman 0117 975 0717

© Historic England Archive

© Historic England



	SITE NAME:	Garden wall, steps and gate piers south of Langdon Court Hotel, Langdon, Wembury	Late C17 to early C18 formal terraced to Langdon Court, the layout little altered since the early C18. Terraces extend south from the house on rising ground, with central
	DESIGNATION:	Listed Building grade II*, RPG grade II	axial path and connecting steps. Enclosed by walls to the east, south and west. The northern (larger) terrace has C17 gate piers and gates in the east and west walls and a
	CONDITION:	Fair	central pool. A programme of phased repairs to the wal was only partially completed by the time the property w
	OCCUPANCY:	N/A	put on the market in November 2020. At the beginning of
	PRIORITY CATEGORY:	F (F)	June 2021 it was marked as being under offer.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1169143	Contact: Jenny Chesher 0117 975 0686

ALL MARKED	SITE NAME:	Pair of garden houses south of Langdon Court Hotel, Langdon, Wembury	Early C18 gazebos standing at the junction of the northern and southern terraces in the late C17 to early C18 formal terraced garden to the south of the house. Extensive
	DESIGNATION:	Listed Building grade II*, RPG grade II	repairs have been undertaken to the building exteriors and an application was made in 2014 for their alteration to be used as ancillary accommodation to the hotel in the main
	CONDITION:	Fair	house. This was finally approved in July 2018 but has not yet been implemented. The hotel closed in April 2020 and
AND	OCCUPANCY:	Vacant/not in use	was put on the market in November 2020. At the
	PRIORITY CATEGORY:	F (F)	beginning of June 2021 it was recorded as being under offer.
© Historic England	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1108587	Contact: Jenny Chesher 0117 975 0686

nd	SITE NAME:	Watch House battery and ditch, Wembury	Constructed 1904 but utilising an 1860s ditch system, with First and Second World War additions. The site was leased
	DESIGNATION:	Scheduled Monument, LB grade II	to a private company until 2009, and since then has been vacant and subject to vandalism. Recording has been put in hand but no options for repair/reuse have been agreed.
	CONDITION:	Very bad	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Government or agency	
	LIST ENTRY NUMBER:	1002585	Contact: Annie Evans 0117 975 0673

	SITE NAME:	Church of St Mary, Berry Pomeroy	Parish church. Rebuilt in C15 restored in the late C17 and 1878 to 1879. Tower has C13 or C14 west doorway.
	DESIGNATION:	Listed Place of Worship grade I	Stone rubble with freestone dressings and slate roofs, tower rendered. Nave and chancel in one. The church is
EL Lan	CONDITION:	Poor	generally very well maintained and a number of significant repairs have been undertaken. Despite this, the tower
and the	PRIORITY CATEGORY:	C (C)	remains damp with problems with the render, and the
11.000	OWNER TYPE:	Religious organisation	main roofs also need work. The congregation applied in the last round of grants for Places of Worship Scheme from
TIT	LIST ENTRY NUMBER:	1108535	the National Lottery Heritage Fund but was unsuccessful.
			Contact: Annie Evans 0117 975 0673

© Historic England

© Historic England

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).


Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	Church of St Lawrence, Bigbury	A C14 and C15 church much rebuilt by Sedding in the C19.
	DESIGNATION:	Listed Place of Worship grade II*	Nave, chancel, north aisle, south transept, south porch, west tower with spire. Though the congregation has done
	CONDITION:	Poor	a lot of work including undertaking works to the rainwater goods there is still a notice in the church that the plaster is
	PRIORITY CATEGORY:	D (D)	dangerous. Damp tower. Ringing chamber has little
	OWNER TYPE:	Religious organisation	ventilation.
	LIST ENTRY NUMBER:	1325078	Contact: Annie Evans 0117 975 0673

© Historic England



Parish church. C14 chancel and possibly tower; nave and aisle rebuilt c later CI5 or early CI6. Restored in 1887, 1893, 1895 and 1898. Local shale rubble with granite and some red sandstone dressings slate roof. The church is generally well-maintained and the roofs are all in good condition. However the tower masonry is damp and friable. Steeplejacks have undertaken emergency tower repairs but it still needs further work.

© Historic England

SITE NAME: DESIGNATION: CONDITION: PRIORITY CATEGORY: OWNER TYPE:	SITE NAME:	Church of St Mary, Charleton	Parish church. C15 heavily restored in 1849-50. Slatestone
	DESIGNATION:	Listed Place of Worship grade II	rubble walls; windows largely of Caen stone, slate roofs. The fittings are all Victorian and the octagonal font, pulpit
	Poor	and desk are also of Caen stone. High level tower repointed. Rainwater goods rusting and undersized and	
	C (C)	failing to get the water away from the church resulting in	
	OWNER TYPE:	Religious organisation	cracking and staining to the interior. Internal decorations poor. The church is generally well maintained and slate
	LIST ENTRY NUMBER:	1108510	roof repairs have been completed. However, significant
			repairs suil need to be undertaken.

© Historic England

Contact: Annie Evans 0117 975 0673

Church of St Sylvester, Chivelstone	Parish church. C15 restored in late C19 or early C20. Slatestone rubble walls. Gabled slate roofs. Good	
Listed Place of Worship grade II*	collection of medieval joinery. Small, rural parish church with a number of problems which add up to a significant	
Poor	amount of work: roofs, rainwater goods, damp ingress and structural movement all need addressing. The congregation	
C (C)	made an application to the National Lottery Heritage Fund	
Religious organisation	in 2019 for work to address structural and waterproofing issues, and work on the repairs started in the spring of	
1108470	2021.	
	Contact: Annie Evans 0117 975 0673	

© Historic England



SITE NAME:	Church of St Edmund, Fore Street, Kingsbridge	Large parish church of cruciform plan with transepts, north and south aisles to nave, chancel aisles and two-storey south porch. The C13 tower remains, church was rebuilt and dedicated 1414. Restored and extended 1849 and 1896. Internal decorations are in poor condition and have
DESIGNATION:	Listed Place of Worship grade I	
CONDITION:	Poor	1896. Internal decorations are in poor condition and have staining in numerous places. Staining below valley gutters
PRIORITY CATEGORY:	C (C)	that may be failing. Windows and stonework problems
OWNER TYPE:	Religious organisation	urgent. A blocked valley gutter has now led to dry rot outbreak in south aisle, the congregation is consulting the
LIST ENTRY NUMBER:	1165559	church architect on remedial work.

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

SITE NAME:

DESIGNATION:

CONDITION:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: Annie Evans 0117 975 0673

- CA
- Conservation Area Listed Building Local Planning Authority National Park LB LPA
- NP
- RPG Registered Park and Garden Scheduled Monument
- SM ŬA
- Unitary Authority World Heritage Site WHS

A W	SITE NAME:	Church of the Blessed Virgin Mary, Rattery	Parish church. C13, enlarged in C15 by addition of aisles and enlargement of transepts. Restored probably c1860s.
	DESIGNATION:	Listed Place of Worship grade I	Roughcast stone with slate roofs. Internally the walls are entirely plastered with unique incised and painted
	CONDITION:	Poor	decoration. This has been affected by previous high level roof leaks and more so from rising damp retained by hard
	PRIORITY CATEGORY:	C (C)	cementitious external pointing which is causing significant
	OWNER TYPE:	Religious organisation	salt damage internally. The congregation has begun to plan a campaign of repair and to consider sources of funding.
	LIST ENTRY NUMBER:	1147626	Contact: Annie Evans 0117 975 0673

© Historic England

	SITE NAME:	Church of St Paul, Staverton	Early C14 church, largely rebuilt in the C15, with north and
	DESIGNATION:	Listed Place of Worship grade I	south aisles, western tower and two-storey porch. Rainwater goods have been overhauled. Vestry roof poor.
	CONDITION:	Poor	Very damp at low level with damage to tile floors and evidence of beetle in pew platforms and white salts. Cracks
	PRIORITY CATEGORY:	C (C)	in cement render. In need of stonework repair and
	OWNER TYPE:	Religious organisation	repointing.
17.	LIST ENTRY NUMBER:	1108524	Contact: Annie Evans 0117 975 0673
And the second second second second			

© Historic England

	SITE NAME:	Church of St Michael, Strete	Parish church in Perpendicular Gothic style built in 1836
TI	DESIGNATION:	Listed Place of Worship grade II	with older tower. Cementitious render over local slate rubble. Single span Welsh slate roof over nave and aisles
8	CONDITION:	Poor	with gabled ends and eaves brackets to moulded cast-iron gutters. Very damp tower. High level water penetration
4 1	PRIORITY CATEGORY:	C (C)	with salts and damage to interior plaster and decorations.
	OWNER TYPE:	Religious organisation	Other works to the church have been done but these issues have not been addressed.
	LIST ENTRY NUMBER:	1165589	Contact: Annie Evans 0117 975 0673

© Historic England

	SITE NAME:	Church of St Mary, High Street, Totnes	Former priory church rebuilt 1430-60. Random Devonian rubble with red sandstone dressings, some pale limestone
	DESIGNATION:	Listed Place of Worship grade I	dressings and parapets, and sandstone tower. Tower stonework poor needing repointing and vegetation
	CONDITION:	Poor	removal. North aisle parapet and stonework decaying. Ground gutters poor. Rainwater goods need painting and
A KANS	PRIORITY CATEGORY:	C (C)	vegetation removed. Internal damage to windows from
	OWNER TYPE:	Religious organisation	rusty ferramenta (iron work) and damaged paint to north aisle east end on chancel south wall. Discussions with the
	LIST ENTRY NUMBER:	1236065	church regarding proposals for reordering continue but as of 2019 substantial repairs are still needed.
			or zor / substantial repairs are still needed.

© Historic England

SITE NAME: Hilltop enclosure known as Maristow Camp, 240 metres east of Middle Park House, Bickleigh LIST ENTRY NUMBER: DESIGNATION: Scheduled Monument 1019784 Generally unsatisfactory with major localised CONDITION: TREND: Declining problems PRINCIPAL VULNERABILITY: NEW ENTRY ?: Forestry No OWNER TYPE: CONTACT: Andy Crabb 01626 832093 Private

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

 D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: Annie Evans 0117 975 0673

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
 - Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Church of St Peter, The Square, Ugborough	Large parish church, dubbed 'The Cathedral of the South Hams'. The north aisle roof has become porous allowing
	DESIGNATION:	Listed Place of Worship grade I	significant water ingress, threatening the integrity of medieval carved roof bosses. The congregation has
	CONDITION:	Poor	completed a phase of repair with a National Lottery Heritage Fund Grant for Places of Worship but the church
	PRIORITY CATEGORY:	C (C)	remains very damp and further works are still being
	OWNER TYPE:	Religious organisation	planned.
	LIST ENTRY NUMBER:	1168309	Contact: Annie Evans 0117 975 0673

© Le Page Architects

SITE NAME:	Medieval holy well known as St Ann's Well, 120 m	etres south of Holv	vell Farm, Bigbury
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1019315
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Iron Age hillfort known as Wasteberry Camp, medieval deer park and post-medieval warren, 800 metres north west of Lyneham House, Brixton / Yealmpton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020160
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Three bowl barrows 310 metres west of Home Fa	ırm, forming part ol	f a round barrow cemetery, Charleton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019788
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Two round barrows on Ridding Down, Cornwood	ł	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002586
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Levelling	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Hilltop enclosure and woodbanks in Chacegrove V Dartington	Vood, 540 metres i	north west of Dartington Hall,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020553
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Charity (non-heritage)	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Hilltop enclosures in North Wood, 780 metres N	NW of Old Parson	age Farm, Dartington
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020381
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Charity (non-heritage)	CONTACT:	Andy Crabb 01626 832093

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В

implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Hillfort and two bowl barrows at Halwell Camp, H	alwell and Moreleig	gh
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019237
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	D-Day landing craft maintenance site on the River Kingswear	Dart immediately t	o the south of Lower Noss Point,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021076
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Gomerock Tower, Kingswear		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003852
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Annie Evans 0117 975 0673
SITE NAME:	Two ring cairns 330 metres south east of Coldhard	oour Cross, Loddis	well
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014244
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Dumping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Hilltop enclosure 380 metres east of Middle Soar,	Malborough	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019533
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Two hut circles and associated field systems and er	nclosure at Mouseh	ill Brake, Malborough
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020573
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Fort Charles, Salcombe		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1020165
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Annie Evans 0117 975 0673

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Hut circle 1000 yards (915 metres) east of Colelan	d Bridge Sparkwei		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002596	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Post-medieval deer park, medieval fishpond, and a C19 lead mine, ore works and smelt mill at Boring Park, Sparkwell			
DESIGNATION:	Scheduled Monument and Listed Building grade II*	LIST ENTRY NUMBER:	1020565 and 1386330	
CONDITION:	Extensive significant problems	TREND:	Improving	
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Immersion bath associated with Leechwell holy we	II, 40 metres north	east of Leechwell Cottage, Totnes	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021390	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth - Notifiable plants	NEW ENTRY?:	No	
OWNER TYPE:	Local authority	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Woodbury Camp, Stoke Fleming			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019783	
CONDITION:	Extensive significant problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Hillfort known as Slapton Castle, Stokenham			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019236	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Roman settlement site at Bantham Ham, Thurlesto	ne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019322	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Visitor erosion - moderate	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Hilltop enclosure at Yellowberries Copse, 430 met	res west of Higher	Turtley, Ugborough	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019325	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

TEIGNBRIDGE



SITE NAME:	Former stables to Stover House, Stover, Teigngrace	Built as stables, 1779. The stables were stripped out when they were superseded by a larger stable block in 1843, and
DESIGNATION:	Listed Building grade II*, RPG grade II	were converted to a magnificent backdrop to the newly laid out gardens for the 11th Duke of Somerset. They are a key feature of Stover's grade II designed landscape. Now in
CONDITION:	Very bad	very bad condition due to the spread and distortion of single ashlar front, rusting cramps, and water and
OCCUPANCY:	Vacant/not in use	vegetation damage. Currently fenced off. Repairs are being
PRIORITY CATEGORY:	D (D)	discussed as part of a wider improvement scheme to the adjoining park.
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1308968	Contact: Annie Evans 0117 975 0673

© Teignbridge District Council



SITE NAME:	The Granite Lodge adjacent A38 approx 1550 metres NNW of Stover House, Teigngrace	Disused pedimented lodges, with linking screen, gates, and flank walls to former drive to Stover House. Likely c1830, possibly by Philip Hardwick. Banded rusticated granite
DESIGNATION:	Listed Building grade II*, RPG grade II	ashlar with slate roofs. South west lodge has had urgent strucural repair carried out. North east lodge in better condition, but vacant with graffiti on the internal plaster
CONDITION:	Poor	wall. Connecting portico appears to be in reasonable condition but has not been closely inspected. Repairs are
OCCUPANCY:	Vacant/not in use	being discussed as part of a wider scheme of improvements
PRIORITY CATEGORY:	D (D)	to the park.
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1308943	Contact: Annie Evans 0117 975 0673

© Historic England



Parish church. C15 Nave, chancel, with early C16 north SITE NAME: Church of St Mary the Virgin, aisle, west tower restored in 1883-4 when the south wall, Bickington south porch, and east and west gables of north aisle were DESIGNATION: Listed Place of Worship grade I rebuilt. Devonian limestone, with granite detail in the medieval work and Ham stone used in the C19. Slated CONDITION: Poor roofs with lots of tingles. Tall tower with cementitious PRIORITY CATEGORY: pointing and vegetation growth. Black and green staining to C (C) east end at high level. OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1097150 Contact: Annie Evans 0117 975 0673

© Historic England



SITE NAME:

Church of St Michael, Ilsington, CI3 or early CI4, south transept may be earlier. Nave and Teignbridge aisles enlarged and partly rebuilt in C15 or early C16. Listed Place of Worship grade I, Rendered stone walls where exposed, of granite and DESIGNATION: CA slatestone rubble. Tower of coursed granite rubble. Slated roofs. Nave, transepts and chancel wagon roofs intersect CONDITION: Poor over crossing as a fine ribbed vault. Very damp; PRIORITY CATEGORY: C (C) cementicious pointing and render trapping moisture in walls and roofs nearing the end of their lives. Condition of OWNER TYPE: Religious organisation interior has declined since last inspection in 2014 so added to the Register in 2019. LIST ENTRY NUMBER: 1240794 Contact: Annie Evans 0117 975 0673

© Historic England



	SITE NAME:	Church of St Thomas, Mamhead	Parish church. Probably C13 or earlier in origin with
	DESIGNATION:	Listed Place of Worship grade II*	surviving early windows in the chancel, CI5 three-bay north aisle, south transept (now the baptistery) probably
	CONDITION:	Fair	C13 or C14 but much altered, C15 tower. C19 restorations including one attributable to Anthony Salvin.
	PRIORITY CATEGORY:	C (C)	Red sandstone and grey limestone rubble and red
	OWNER TYPE:	Religious organisation	sandstone dressings and slate roofs. Works to repair stonework and remove ivy were undertaken in 2017-2018.
	LIST ENTRY NUMBER:	1170048	Contact: Annie Evans 0117 975 0673
100			

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

D

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Sizeable Anglican parish church. Chancel and transepts late

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM

ÍΙΑ WHS

Unitary Authority World Heritage Site

SITE NAME:	Earthwork (poss	ibly civil war) on Bovey Heath, Bo	vey Tracey	
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1002657
CONDITION:	Generally satisfac problems	ctory but with significant localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree grow	th	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners		CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bishop's Palace, (Chudleigh		
DESIGNATION:	Scheduled Monu	Scheduled Monument, LB grade II*		1008679
CONDITION:	Generally satisfactory but with significant localised problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Other		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Earthwork enclo	sure south of Blackall's Copse, Ex	minster	
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1004579
CONDITION:	Generally unsatisfactory with major localised problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Linear round bar	row cemetery at Castle Park, Alp	hington, Exminster	
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1012347
CONDITION:	Extensive significant problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Kingskerswell Manor House, Kingskerswell			
DESIGNATION:	Scheduled Monu	Scheduled Monument, LB grade II, CA		1020875
CONDITION:	Extensive significa	ant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse		NEW ENTRY ?:	No
OWNER TYPE:	Private, multiple	owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Prehistoric field	system and settlements on Kerswo	ell Down and Whill	borough Common, Kingskerswell
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1021377
CONDITION:	Extensive significa	ant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree grow	th	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple c	owners	CONTACT:	Charlotte Russell 01271 831505
	SITE NAME:	Oxton House, Kenton	In the mid-CI9 t	he picturesque grounds comprised lawns
	DESIGNATION:	Registered Park and Garden grade II, 7 LBs	parterres, shrubberies, parkland and a lake property was occupied by a school before into apartments. The pleasure grounds are	cupied by a school before being divided The pleasure grounds are neglected and
	CONDITION:	Generally unsatisfactory with major localised problems		k is ploughed, with considerable loss of
	VULNERABILITY:	Medium		
	TREND:	Declining		
	NEW ENTRY?:	No		
	OWNER TYPE:	Private, multiple owners		
	LIST ENTRY NUMBER:	1001269	Contact: Jo McA	llister 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / SOUTH WEST / TEIGNBRIDGE / TORRIDGE

	SITE NAME:	Stover Park, Teigngrace	Late C18 gardens, pleasure grounds and park in divided
Selection of the sel	DESIGNATION:	Registered Park and Garden grade II, 7 LBs	ownership. A large area of the park is run by the County Council as a country park and other parts developed as mineral workings. The main house and environs are in use
	CONDITION:	Generally unsatisfactory with major localised problems	as a school. The setting is under threat from development, including road widening and housing allocation. A parkland plan was produced through a Natural England Stewardship
	VULNERABILITY:	High	Scheme in 2014. An application to the National Lottery
	TREND:	Improving	Heritage Fund successfully secured funding for restoration works in 2020.
	NEW ENTRY?:	No	
	OWNER TYPE:	Mixed, multiple owners	
	LIST ENTRY NUMBER:	1001268	Contact: Jo McAllister 0117 975 0696

SITE NAME:	Bovey Tracey, Pottery Road, Bovey Tracey		
DESIGNATION:	Conservation Area, SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Maureen Pearce (LPA) 01626 215705

TORRIDGE

-			
	SITE NAME:	Richmond Dock, Northam	Dry dock, 1856. It is said to have been the largest dry dock in the Bristol Channel at the time it was built. The dock is
	DESIGNATION:	Listed Building grade II*	now vacant. In 2015 the gates were in poor condition, and
	CONDITION:	Poor	no repair proposals have been made to Historic England. Ongoing discussions for alternative uses and greater
	OCCUPANCY:	Vacant/not in use	regeneration proposals are being held with the Local
	PRIORITY CATEGORY:	C (C)	Planning Authority. It is understood that the site has now been sold and is in new ownership, as of 2020.
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1140140	Contact: Catherine Marlow 0117 975 0732

© Historic England

©Ні

-			
Historic England Archive	SITE NAME:	World War II air traffic control building 400 metres north west of Seckington Cross, on the former airfield of RAF Winkleigh, Winkleigh	The monument is a World War II brick and concrete control tower. Although structurally sound, the tower has suffered from vandalism and lack of maintenance and has failing concrete as a result of oxidising steel reinforcement.
	DESIGNATION:	Scheduled Monument	
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1020765	Contact: Charlotte Russell 01271 831505



\$

ſ

D

Е

use).

SITE NAME:	Church of St Helen, Abbotsham	
DESIGNATION:	Listed Place of Worship grade II*	
CONDITION:	Poor	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1104408	

Anglican parish church. Cruciform plan with early CI3 nave and chancel; tower of c.1300 to north east and early C14 south chapel. Restored 1870. Coursed slatestone rubble with ashlar dressings; gabled slate roofs with C19 copings and kneelers. C15 waggon roofs, plastered walls. Pointed chamfered arches to transepts. Beautifully-carved reredos, and other good interior fittings. Water penetration through parapets and historic fractures to south tower wall causing rot to embedded timbers, fracturing and failure of masonry bonding to south transept gable end.

Contact: Annie Evans 0117 975 0673

© John Warlow. Source Historic England Archive

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; в solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no

obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument
- SM

UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Church of All Saints, Bradford	Parish church with Norman origins, C14 chancel, C15
	DESIGNATION:	Listed Place of Worship grade II*	north aisle and porch, restored from a ruinous state in 1869 and between 1875 to 1889. The tower suffers from
	CONDITION:	Poor	water ingress and damp and the bell ropes drip with water. The rest of the church is damp. The gutters and downpipes
	PRIORITY CATEGORY:	C (C)	need overhauling.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1105088	Contact: Annie Evans 0117 975 0673

© Historic England

	SITE NAME:	Church of St Bridget, Bridgerule	Externally the tower has black staining, indicating that is			
A.	DESIGNATION:	Listed Place of Worship grade I	damp. There are no rainwater goods and areas of cement ribbon pointing. The church is in need of patch repointing.			
AA	CONDITION:	Poor	This has contributed to some paint blistering internally, such as in the east end of the south aisle.			
	PRIORITY CATEGORY:	C (C)	such as in the east end of the south asie.			
all set \$	OWNER TYPE:	Religious organisation				
	LIST ENTRY NUMBER:	1104976	Contact: Annie Evans 0117 975 0673			

© Historic England

	SITE NAME:	Church of St Mary and St Gregory, Frithelstock	Parish church. C13 north wall; chancel rebuilt and south aisle built in early C14; c1500 south-east chapel and roofs,
T	DESIGNATION:	Listed Place of Worship grade I, SM	and west tower rebuilt in C15. Coursed slatestone rubble; squared and coursed stone to tower; ashlar dressings. Stone-gabled and gabled slate roofs. This church is in need
-/ 4022	CONDITION:	Poor	of external patch repointing and the overhaul and renewal of all of the rainwater goods is required.
T	PRIORITY CATEGORY:	C (C)	of all of the rainwater goods is required.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1105177	Contact: Annie Evans 0117 975 0673

© Historic England

	SITE NAME:	Church of St Nectan, Hartland	Parish church C14 and C15 restored c1850 and 1910-11.
	DESIGNATION:	Listed Place of Worship grade I	Nave, chancel, north and south aisles, transept chapels and porches, west tower. Coursed rubble walls, gable ended
	CONDITION:	Poor	slate roofs. Tall four-stage tower. Fine interior retaining early fabric and with early painted plaster, medieval wagon
	PRIORITY CATEGORY:	C (C)	roofs, rood screen with evidence of ancient colouring,
	OWNER TYPE:	Religious organisation	benches c1540 and C17, late Norman font. Water penetration through south aisle walls, affecting fine wall
	LIST ENTRY NUMBER:	1333125	monuments internally, water penetration to tower walls, leaching and mortar wash-out, causing damp and rot to
			embedded timbers.
listoric			Contact, Annia Evana 0117 975 0(72

© Douglas G Wood, Source Historic England Archive

	à
A	
110	

		Contact: Annie Evans 0117 975 0673
SITE NAME:	Church of St Swithun, Littleh	
DESIGNATION	Listed Place of Worship grade	
CONDITION:	Poor	installed. The tower shows signs of damp.
PRIORITY CAT	EGORY: C (C)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NU	JMBER: 1105152	Contact: Annie Evans 0117 975 0673

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lacttified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

Parish church. Late CI3 origins with CI4 fabric, re- modelled in CI6 restored c1900 to 1910. Stone rubble
walls. Gable-ended slate roof. Tower destroyed by lightning in 1879 and in ruins for 20 years but re-opened in
1904. Tower partly re-erected in 1892 and rebuilt 1910- 1911. The church is generally well maintained, but needs a
significant project to secure loose stones on top of the
tower, tackle damp problems, and repair roofs. The congregation has made three applications for National
Lottery Heritage Fund Grant for Places of Worship but has not been successful.


© Historic England



SITE NAME:	Church of St Margaret, Northam	Large parish church. Mainly C15 although lower part of tower is older. Thoroughly restored between 1849 and
DESIGNATION:	Listed Place of Worship grade I, CA	1865. The roof slating is nearing the end of its life, and the ceilings are plastered to the underside of roofing battens. The church was awarded a National Lottery Heritage Fund
CONDITION:	Poor	Grant for Places of Worship in late 2016 for the repair of the nave and vestry roofs. Work was planned to start on
PRIORITY CATEGORY:	D (D)	site by the end of 2018 but has been delayed awaiting slate
OWNER TYPE:	Religious organisation	supply from the quarry. At least one further phase of work to the roofs will then be needed.
LIST ENTRY NUMBER:	1169270	Contact: Annie Evans 0117 975 0673

Contact: Annie Evans 0117 975 0673

© Historic England



© Historic England

	SITE NAME:	Church of St Michael, Shebbear	Rural Devon church. Most significant feature is mid-Cl2
	DESIGNATION:	Listed Place of Worship grade II*	south doorway. Plain nave and south aisle; simple rendered tower. Damp interior with carpet hiding salt damage to
	CONDITION:	Poor	floor. Prone to vegetation growth in the external ground gutter and there is a poor vestry valley gutter arrangement,
PRIORITY CATEGORY: C (C) worsening th	worsening the internal problems. The roof is poor and is		
	OWNER TYPE:	Religious organisation	likely to require recovering in the forseeable future.
	LIST ENTRY NUMBER:	1309558	Contact: Annie Evans 0117 975 0673

© Historic England



SITE NAME:	Church of the Holy Cross, Tetcott	Parish church. Fabric of nave and chancel C13, south transept C13 or C14, tower C15, vestry probably C19.
DESIGNATION:	Listed Place of Worship grade I	Stone rubble with granite dressings, the tower ashlar masonry with granite quoins and lacing, slate roofs. Fittings
CONDITION:	Poor	including several good C18 wall monuments. The church forms part of an important group including Tetcott Manor
PRIORITY CATEGORY:	C (C)	and associated buildings. The north wall is still moving, even
OWNER TYPE:	Religious organisation	after works to stop the roof spreading. Tower masonry needs repointing and the roof re-covering to prevent water
LIST ENTRY NUMBER:	1252173	ingress to the belfry and ringing chamber.
		Contact: Annie Evans 0117 975 0673

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
 - Registered Park and Garden Scheduled Monument
- SM UA WHS
 - Unitary Authority World Heritage Site

packake trainScheduled MonumentINT HENEY NUMBER(D20079CONDUCKExtensive significant problemsTEND:DecliningCONDUCKATORPrivateCONTACT:Charlotte Russell 01271 831505STRINAMEScheduled MonumentUST DATE NUMER:100080CONDUCKATOR:Extensive significant problemsTEND:DecliningCONDUCKATOR:Extensive significant problemsTEND:DecliningCONDUCKATOR:Extensive significant problemsTEND:DecliningCONDUCKATOR:Bow barrow TO'metres south ests of Sandymory Cress, forming partNoCONDUCKATOR:Bow barrow TO'metres south ests of Sandymory Cress, forming partI and Date NoteSTRINAME:Scheduled MonumentIST HINT NUMER:NoBow barrow TO'metres south ests of SandymoryControl Date NoteDecliningCONDUCKATOR:Scheduled MonumentIST HINT NUMER:NoCONDUCKATOR:Scheduled MonumentIST HINT NUMER:NoCONDUCKATOR:Scheduled MonumentIST HINT NUMER:NoCONDUCKATOR:PrivateCONTACT:Charlotte Russell 01271 831503STR NUME:Scheduled MonumentIST HINT NUME:NoCONDUCKATOR:Scheduled MonumentIST HINT NUME:NoCONDUCKATOR:Scheduled MonumentIST HINT NUME:NoCONDUCKATOR:Scheduled MonumentIST HINT NUME:NoCONDUCKATOR:Generally Unstatificatory With major localisedIST HINT NUME:NoCONDUCKATOR:Generally Scheduled Mon	SITE NAME:	Bowl barrow 250 metres north east of Oak Cottag	ge, forming part of a	a round barrow cemetery, Ashwate
Readershi Visu Rayaka HTY:OtherNoCONTRCT:Charlotte Russell 01271 831505Sale NAME:Bow barrow 540 metres south east of Sandymoor Cross, forming part of a round barrow cenetery. AvavaterControlottiScheduled MonumentIST ENTRY NUMERA102080ControlottiScheduled MonumentIST ENTRY NUMERA102080DescinationalScheduled MonumentIST ENTRY NUMERANoControlottiExtensive significant problemsTRID:DecliningReactional Visu RayakaOtherNoNoControlottiBow barrow 770 metres south east of Sandymoor Cross, forming partof a round barrow cenetery. RayakaSasterianiScheduled MonumentIST ENTRY NUMERA1020081SasterianiScheduled MonumentIST ENTRY NUMERANoControlottiScheduled MonumentIST ENTRY NUMERANoControlottiScheduled MonumentIST ENTRY NUMERANoControlottiControlottiControlottiStableControlottiGenerality unstificatory with major localisedInstroCharlotte Russell 01271 831505STE NAME:Hilffort known as Castle HIII Settlement, 350 metresStableInstrolControlotti TrolScheduled MonumentIST ENTRY NUMERANoControlotti TrolGenerality unstificatory with major localised problemsInstrolStableSetterianiGenerality unstificatory with major localised problemsInstrolNoControlottiGenerality staffactory but with major localised problem	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020079
CONTRACTIONPrivatePrivateCONTRACTIONCharlotte Russell 01271 8315051BESIGNATIONScheduled MonumentLatt DITRY NUMBER100080ESCIGNATIONScheduled MonumentLatt DITRY NUMBER100080ENCIRCINGScheduled MonumentNoNoENRICEDecliningNoNoENRICEOtherNONoENRICEOtherNONoENRICEScheduled MonumentUST ENTER NUMBER102081EDESCARTIONScheduled MonumentUST ENTER NUMBERNoEDESCARTIONScheduled MonumentUST ENTER NUMBERNo </td <td>CONDITION:</td> <td>Extensive significant problems</td> <td>TREND:</td> <td>Declining</td>	CONDITION:	Extensive significant problems	TREND:	Declining
Bin More Bow barrow S40 metres south east of Sandymor JUNE Partier Part	PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
ActivationActivaterUSE DATA NO.DesignationScheduled MonumentUSE DATA NO.DesignationCheensive significant problemsNeW DATA?:NoPrivateOtherNeW DATA?:Charlotte Russell 01271 831505WIE NAME.Bow barrow 770 metres south east of Sandymoor Cross, forming part of a round barrow cemetery. AstivaterNoSNEENAME.Scheduled MonumentINTERTRY NUMBER1020081CONDITIONExtensive significant problemsTERMSDecliningCONDITIONExtensive significant problemsTERMSDecliningCONDITIONExtensive significant problemsCONTACT:Charlotte Russell 01271 831505STEENAMEOtherNoCONTACT:Charlotte Russell 01271 831505STEENAMEHillfort known as Castle Hill Settlement, 350 metres:NoContactCONDITION:Scheduled MonumentUST ENTRY NUMBER1021417CONDITION:Generally unsatisfactory with major localised problemsTERMSSableSTE NAME:Holy well 480 metres north west of Beaford Mill, BeafordContact Russell 01271 831505STE NAME:Scheduled MonumentUST ENTRY NUMBER105142CONDITION:Scheduled MonumentUST ENTRY NUMBER105142CONDITION:Scheduled MonumentUST ENTRY NUMBER105142CONDITION:Scheduled MonumentUST ENTRY NUMBER105142CONDITION:CollapseNoContact Russell 01271 831505STE NAME:Hallsannery limekiln, LittlehamTERMSNo <td>OWNER TYPE:</td> <td>Private</td> <td>CONTACT:</td> <td>Charlotte Russell 01271 831505</td>	OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
CONDITIONExtensive significant problemsTHEND.DecliningRENCEAN VILL NERABILITY:OtherNOVNoRENCEAN VILL NERABILITY:OtherCONTACT:Charlotte Russell 012/11831500STETE NAME:Scheduled MonumentLST ENTRY NURBER1020081CONDITIONScheduled MonumentLST ENTRY NURBER1020081CONDITIONScheduled MonumentNoDecliningCONDITIONCherNoNoSTETE NAME:OtherNOCONTACT:NoOWNER TYPE:PrivateCONTACT:NoCONDITIONScheduled MonumentUST ENTRY NURBER1021417CONDITIONScheduled MonumentMCN ENTRY:NoCONDITIONScheduled MonumentNoScheduled MonumentCONDITIONScheduled MonumentNoContact:CONDITIONScheduled MonumentNoScheduled MonumentCONDITIONScheduled MonumentNoContact:CONDITIONScheduled MonumentUST ENTRY NURBER105142CONDITIONScheduled MonumentUST ENTRY NURBERNoCONDITIONScheduled MonumentUST ENTRY NURBER105142CONDITIONScheduled MonumentUST ENTRY NURBER105142CONDITIONScheduled MonumentUST ENTRY NURBER104578CONDITIONScheduled MonumentUST ENTRY NURBER104578CONDITIONScheduled MonumentUST ENTRY NURBER104578CONDITIONScheduled MonumentUST ENTRY NURBER<	SITE NAME:		Cross, forming pai	rt of a round barrow cemetery,
NRINCIPAL VLINERABILITY: Other New RATEY: No OWNER TYPE: Private CONTACT: Charlotte Russell 01271 831505 STRE NAME: Bowl barrow 770 metres south east of Sandymoor Cross, forming part of a round barrow cemetery, Streamer Scheduled Monument LIST ENTRY NUMBER Declining DESIGNATION: Scheduled Monument LIST ENTRY NUMBER Declining RRINCIPAL VLINERABILITY: Other New ENTRY: No OWNER TYPE: Private CONTACT: Charlotte Russell 01271 831505 STRE NAME: Hillfort known as Castle Hill Settlement, 350 metres: Subtle Beaford DESIGNATION: Scheduled Monument LIST ENTRY NUMBER 1021417 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER 1021417 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER 1021417 CONTACT: Charlotte Russell 01271 831505 Stable ENRINCENAL VLINERABILITY: Scheduled Monument LIST ENTRY NUMBER 105142 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER 105142 DESIGNATION: Sc	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020080
Constraint Private Constract:	CONDITION:	Extensive significant problems	TREND:	Declining
Bit NAME: Body havers 770 meris south east of Sandymor / Sector intra per values of a condition of scheduled Monument UST ENTRY NURBER 1020081 DESIGNATION Scheduled Monument UST ENTRY NURBER 1020081 CONDITION Extensive significant problems New ENTRY: No REINCIPAL VULNERABILITY: Other New ENTRY: No OWNER TYPE: Hillfort known as Castle Hill Settlement, 350 metr: US1417 DESIGNATION: Scheduled Monument UST ENTRY NUMBER 1021417 CONDITION: Scheduled Monument UST ENTRY NUMBER No CONDITION: Scheduled Monument UST ENTRY NUMBER No CONDITION: Scheduled Monument NEW ENTRY: No OWNER TYPE: Miked, multiple owners CONTACT: No CONDITION: Scheduled Monument UST ENTRY NUMBER 105142 CONDITION: Scheduled Monument UST ENTRY NUMBER 105142 CONDITION: Scheduled Monument UST ENTRY NUMBER No CONTROT: Collapse NEW ENTRY: No CONTROT:	PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
Antwace Astwater UST BATTLY NUMBER UST BATTLY NUMBER 1020081 DesiGNATIONE Scheduled Monument UST BATTLY NUMBER 1000081 CONDITIONE Extensive significant problems TREND: No DEMICIPAL VULNERABULTY: Other No Charlotte Russell 01271 831505 STEENAME: Hillfort known as Castle Hill Settlement, 350 metrus Sund Younger No DESIGNATIONE Scheduled Monument UST ENTRY NUMBER TREND: Stable CONDITIONE Generally unsatisfactory with major localised problems TREND: Stable OWNER TYPE: Mixed, multiple owners CONTACT: No OWNER TYPE: Mixed, multiple owners CONTACT: Charlotte Russell 01271 831505 STEENAME: Holy well 480 metres north west of Beaford Mill. Estensive Steeduled Monument Declining OWNER TYPE: Collapse Instruments No Steeduled Monument Declining Conditions Scheduled Monument UST ENTRY NUMBER 105142 Declining Conditions Scheduled Monument UST ENTRY NUMBER No Conditions Scheduled Monument UST ENTRY NUMBER No Conditions Frivate Contract: Charlotte Russell 01271 831505	OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
CONDITIONExtensive significant problemsTREND:DecliningRINCURAL VULNERABILITY:OtherNoOWNER TYPE:PrivateCONTACT:Charlotte Russell 01271 831505BEIGRAATION:Scheduled MonumentLIST ENTRY NUMBER:1021417CONDITION:Generally unsatisfactory with major localised problemsIREND:StableRINCURAL VULNERABILITY:Scrub/tree growthNew ENTRY:NoRINCIPAL VULNERABILITY:Scrub/tree growthNew ENTRY:NoRINCIPAL VULNERABILITY:Scheduled MonumentUST ENTRY NUMBER:1015142CONDITION:Generally unsatisfactory with major localised problemsINEN ENTRY:NoCONDITION:Scheduled MonumentUST ENTRY NUMBER:1015142CONDITION:Generally unsatisfactory with major localised problemsINEN ENTRY:NoCONDITION:Generally unsatisfactory with major localised 	SITE NAME:		Cross, forming par	rt of a round barrow cemetery,
NRINCIPAL VOLUNERABILITY: Other NRIVE NRIVE No OWNER TYPE: Private CONTACT: Charlotte Russell 01271 831505 OWNER TYPE: Hillfort known as Castle Hill Settlement, 350 metres south of Wooller Bridge, Beaford DEBIGNATION: Scheduled Monument UST ENTRY NUMBER: 1021417 CONDITION: Generally unsatisfactory with major localised problems TREND: Stable OWNER TYPE: Crub / tree growth NEW ENTRY: No OWNER TYPE: Mixed, multiple owners CONTACT: Charlotte Russell 01271 831505 STETENAME: Holy well 480 metres north west of Beaford MILL FUTTY NUMBER: 1015142 CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1015142 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining CONDITION: Generally unsatisfactory with major localised problems TREND: No CONDITION: Generally unsatisfactory with significant localised problems TREND: No CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1004578	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020081
WINER TYPE:PrivateCNITACT:Charlotte Russell 01271 831505STE NAME:Hilfort known as Castle Hill Settlement, 350 metrosFRIND101417DESIGNATION:Scheduled MonumentUST ENTRY NUMBER1021417CONDITION:Grub/Irage growthIngelolTREND:StableRRINCIPAL VULNERABILITY:Scrub/Irage growthNEW ENTRY:NoOWNER TYPE:Mixed, multiple ownersCONTACT:National Control (Control Control Contro	CONDITION:	Extensive significant problems	TREND:	Declining
STRE NAME: Hilfort known as Castle Hill Settlement, 350 metres with Woolek Woolek, Berker, Automatic Moolek, Berker, Automatic Moolek, Berker, Automatic Moolek, Berker, MUMBER Io21417 DESIGNATION: Scheduled Monument LST ENTRY NUMBER Io21417 CONDITION: Generally unsatisfactory with major localised problems NEW ENTRY NUMBER No RINCIPAL VULNERABULTY: Scrub/tree growth NEW ENTRY NUMBER No OWNER TYPE: Holy well 480 metres north west of Beaford Mill, BET ENTRY NUMBER Io15142 Condition: Generally unsatisfactory with major localised problems ISTE NAME: Io15142 Condition: Generally unsatisfactory with major localised problems INEW ENTRY: No Condition: Generally unsatisfactory with major localised problems NEW ENTRY: No Condition: Generally unsatisfactory with major localised problems NEW ENTRY: No STE NAME: Collapse Contract: Contract: Contract: DESIGNATION: Scheduled Monument UST ENTRY NUMBER No CONDITION: Generally satisfactory but with significant localised problems New ENTRY: No RRINGPAL VULINERABULTY: Other Netret te	PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
Designation: Scheduled Monument UST ENTRY NUMBER: 1021417 condition: Generally unsatisfactory with major localised problems TREND: Stable RRINDRAL VULINERABILITY: Scrub/tree growth NEW ENTRY: No DWNER TYPE: Mixed, multiple owners CONTACT: Charlotte Russell 01271 831505 STEE NAME: Holy well 480 metres north west of Beaford Mill, Beator UST ENTRY NUMBER: I015142 condition: Scheduled Monument LIST ENTRY NUMBER: I015142 condition: Generally unsatisfactory with major localised problems TREND: Declining RRINCIPAL VULINERABILITY: Collapse New ENTRY: No OWNER TYPE: Collapse NEW ENTRY: No STEE NAME: Hallsannery limekiln, Littleham UST ENTRY NUMBER: 104578 condition: Scheduled Monument LIST ENTRY NUMBER: No condition: Generally satisfactory but with significant localised problems Rev ENTRY: No condition: Generally satisfactory but with significant localised problems Rev ENTRY: No condition	OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
Concording FrontierFor FirstConcording FrontierSchooleersStableCONDITION:SchooleersSchooleersPRINCIPAL VULNERABULITY:Scrub/tree growthNEW ENTRY:NoOWNER TYPE:Mixed, multiple ownersCONTACT:Charlotte Russell 01271 831505DESIGNATION:Scheduled MonumentUIST ENTRY NUMBER:1015142CONDITION:Scheduled MonumentUIST ENTRY NUMBER:1015142CONDITION:CollapseNEW ENTRY:NoDESIGNATION:CollapseNEW ENTRY:NoCONDITION:PrivateCollapseNEW ENTRY:NoDESIGNATION:Scheduled MonumentUIST ENTRY NUMBER:104578CONDITION:Generally unsatisfactory with major localised problemsNEW ENTRY:NoDESIGNATION:CollapseNEW ENTRY:NoDESIGNATION:Scheduled MonumentUIST ENTRY NUMBER:104578DESIGNATION:Scheduled MonumentUIST ENTRY NUMBER:104578CONTACT:OtherNEW ENTRY:NoDESIGNATION:OtherNEW ENTRY:NoDESIGNATION:Scheduled MonumentUIST ENTRY NUMBER:1016433DESIGNATION:Scheduled Monument<	SITE NAME:	Hillfort known as Castle Hill Settlement, 350 metro	es south of Woolle	igh Bridge, Beaford
problemsproblemsNote thatStableRRINCIPAL VULNERABILITY:Scrub/tree growthNEW ENTRY:NoOWINER TYPE:Mixed, multiple ownersCONTACT:Charlotte Russell 01271 831505SITE NAME:Holy well 480 metres north west of Beaford Mill, BeatriceInternet Russell 01271 831505DESIGNATION:Scheduled MonumentLust ENTRY NUMBER:1015142CONDITION:Generally unsatisfactory with major localised problemsREND:DecliningRRINCIPAL VULNERABILITY:CollapseNEW ENTRY:NoOWINER TYPE:Hallsannery limekiln, LittlehamContact:InprovingDESIGNATION:Scheduled MonumentLust ENTRY NUMBER:1004578DESIGNATION:Scheduled MonumentLust ENTRY NUMBER:1004578DESIGNATION:Scheduled MonumentLust ENTRY NUMBER:1004578DESIGNATION:Scheduled MonumentNEW ENTRY:NoOWINER TYPE:OtherNEW ENTRY:NoDESIGNATION:Scheduled MonumentLust ENTRY NUMBER:10164331505DESIGNATION:Bowl barrow 420 metres north west of Dural CressBradworthyScheduled No.DESIGNATION:Scheduled MonumentLust ENTRY NUMBER:1016643DESIGNATION:Scheduled MonumentLust ENTRY NUMBER:1016643DESIGNATION:Scheduled MonumentLust ENTRY NUMBER:1016643DESIGNATION:Scheduled MonumentLust ENTRY NUMBER:1016643DESIGNATION:Scheduled MonumentNEW ENTRY:NoDESIGN	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021417
Mixed, multiple ownersCONTACT:Charlotte Russell 01271 831505SITE NAME:Holy well 480 metres north west of Beaford Mill, Beaford1015142DESIGNATION:Scheduled MonumentLUST ENTRY NUMBER:1015142CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningRRINCIPAL VULNERABILITY:CollapseNEW ENTRY:NoOWNER TYPE:CollapseNEW ENTRY:NoOWNER TYPE:PrivateCONTACT:Charlotte Russell 01271 831505SITE NAME:Hallsannery limekiln, LittlehamUST ENTRY NUMBER:1004578DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1004578CONDITION:Generally satisfactory but with significant localised problemsTREND:ImprovingCONDITION:OtherNew ENTRY:NoCONDITION:Scheduled MonumentLIST ENTRY NUMBER:1004578CONDITION:Scheduled MonumentNEW ENTRY:NoOWNER TYPE:PrivateCONTACT:Charlotte Russell 01271 831505STE NAME:Bowl barrow 420 metres north west of Dural CrewNoOWNER TYPE:Scheduled MonumentLIST ENTRY NUMBER1016643DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER1016643CONDITION:Extensive significant problemsTREND:DecliningDESIGNATION:Arable ploughingNEW ENTRY:No	CONDITION:		TREND:	Stable
SITE NAME: Holy well 480 metres north west of Beaford Mill, Beaford DESIGNATION: Scheduled Monument IJST ENTRY NUMBER: 1015142 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining RRINCIPAL VULNERABILITY: Collapse NEW ENTRY: No OWNER TYPE: Private CONTACT: Charlotte Russell 01271 831505 STEE NAME: Hallsannery limekiln, Littleham UST ENTRY NUMBER: 1004578 CONDITION: Scheduled Monument UST ENTRY NUMBER: 1004578 CONDITION: Generally satisfactory but with significant localised problems TREND: Improving CONDITION: Other NEW ENTRY: No CONDITION: Other CONTACT: No STE NAME: Desident Statisfactory but with significant localised problems TREND: Improving CONDITION: Other CONTACT: No No STE NAME: Desident Statisfactory but with significant localised problems TREND: No OWNER TYPE: Other CONTACT: No No OWNER TYPE: Scheduled Monument UST ENTRY NUMBER	PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER1015142CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningRINCIPAL VULNERABILITY:CollapseNEW ENTRY?NoOWNER TYPE:PrivateCollapseCONTACT:NoSITE NAME:Hallsannery limekiln, LittlehamLIST ENTRY NUMBER1004578DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER1004578CONDITION:Generally satisfactory but with significant localised problemsTREND:NoRINCIPAL VULNERABILITY:OtherNEW ENTRY?NoOwner TYPE:OtherNEW ENTRY?NoSTE NAME:Boxl barrow 420 metres north west of Dural CrossStradworthyScheduled MonumentDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER1016643STE NAME:Boxl barrow 420 metres north west of Dural CrossStradworthyScheduled MonumentDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER1016643CONDITION:Scheduled MonumentLIST ENTRY NUMBER1016643CONDITION:Ketnsive significant problemsTREND:DecliningRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?No	OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:CollapseNEW ENTRY:NoOWNER TYPE:PrivateCONTACT:Charlotte Russell 01271 831500SITE NAME:Hallsannery limekiln, LittlehamUST ENTRY NUMBER1004578CONDITION:Scheduled MonumentUST ENTRY NUMBER1004578CONDITION:Generally satisfactory but with significant localised problemsTREND:NoCONDITION:OtherNEW ENTRY:NoOWNER TYPE:PrivateCONTACT:Nairotte Russell 01271 831505SITE NAME:Box barrow 420 metres north west of Dural CrossCoNTACT:Nairotte Russell 01271 831505SITE NAME:Scheduled MonumentUST ENTRY NUMBER106643SITE NAME:Scheduled MonumentUST ENTRY NUMBER106643SITE NAME:Scheduled MonumentUST ENTRY NUMBER106643CONDITION:Extensive significant problemsTREND:DecliningCONDITION:Arable ploughingNEW ENTRY:No	SITE NAME:	Holy well 480 metres north west of Beaford Mill, E	Beaford	
problemsproblemsDecliningPRINCIPAL VULNERABILITY:CollapseNew ENTRY?:NoOWNER TYPE:PrivateCONTACT:Charlotte Russell 01271 831505SITE NAME:Hallsannery limekiln, LittlehamIJST ENTRY NUMBER:1004578DESIGNATION:Scheduled MonumentIJST ENTRY NUMBER:1004578CONDITION:Generally satisfactory but with significant localised problemsImprovingCONDITION:OtherNEW ENTRY?:NoOWNER TYPE:PrivateCONTACT:Charlotte Russell 01271 831505SITE NAME:Bowl barrow 420 metres north west of Dural Cross stres name:NoDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1016643OWNER TYPE:Scheduled MonumentLIST ENTRY NUMBER:1016643DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1016643CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015142
OWNER TYPE:PrivatePrivateCONTACT:Charlotte Russell 01271 831505SITE NAME:Hallsannery limekiln, LittlehamISTE ENTRY NUMBER:1004578DESIGNATION:Scheduled MonumentIST ENTRY NUMBER:1004578CONDITION:Generally satisfactory but with significant localised problemsIREND:ImprovingCONDITION:OtherNEW ENTRY?:NoOWNER TYPE:PrivateContact:Scheduled MonumentSITE NAME:Bowl barrow 420 metres north west of Dural CrossSradworthyDESIGNATION:Scheduled MonumentIST ENTRY NUMBER:1016643CONDITION:Extensive significant problemsTREND:DecliningRINCIPAL VULNERABILITY:Arable ploughingNew ENTRY:No	CONDITION:		TREND:	Declining
STE NAME: Hallsannery limekiln, Littleham DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004578 CONDITION: Generally satisfactory but with significant localised problems TREND: Improving PRINCIPAL VULNERABILITY: Other New ENTRY: No OWNER TYPE: Frivate Bowl barrow 420 metres north west of Dural Cross- stre NAME: Scheduled Monument LIST ENTRY NUMBER: 1016643 DESIGNATION: Scheduled Monument ILST ENTRY NUMBER: 1016643 Improving DESIGNATION: Extensive significant problems TREND: Information: Information: ONDITION: Extensive significant problems MEND: Information: Information: REND: Kensive significant problems MEND: Information: Information: REND: Kensive significant problems MEND: Information: Information: REND: Kensive significant problems MEND: Information: Information:	PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
Designation:Scheduled MonumentLIST ENTRY NUMBER:1004578condition:Generally satisfactory but with significant localised problemstrend:ImprovingPRINCIPAL VULNERABILITY:OtherNEW ENTRY?:NoOwner type:PrivateContact:Charlotte Russell 01271 831505SISTE NAME:Bowl barrow 420 metres north west of Dural Cross strenzeIntervenzeDesignation:Scheduled MonumentLIST ENTRY NUMBER:1016643CONDITION:Extensive significant problemstrend:DecliningRunder Louge PrivateArable ploughingNEW ENTRY?:No	OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
CONDITION:Generally satisfactory but with significant localised problemsTREND:ImprovingPRINCIPAL VULNERABILITY:OtherNew ENTRY?:NoOWNER TYPE:PrivateCONTACT:Charlotte Russell 01271 831505SITE NAME:Boxl barrow 420 metres north west of Dural CrossBradworthyDesignation:Scheduled MonumentIIST ENTRY NUMBER:1016643CONDITION:Extensive significant problemsTREND:DecliningRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:No	SITE NAME:	Hallsannery limekiln, Littleham		
problemsInterformInterformingproblemsOtherNew ENTRY?:NoprivateContact:Charlotte Russell 01271 831505pesignation:Scheduled MonumentList ENTRY NUMBER:1016643pesignation:Extensive significant problemsTREND:DecliningprivateArable ploughingNEW ENTRY?:No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004578
OWNER TYPE:PrivateCONTACT:Charlotte Russell 01271 831505STITE NAME:Bowl barrow 420 metres north west of Dural CrossBradworthyDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1016643CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY:No	CONDITION:		TREND:	Improving
Bowl barrow 420 metres north west of Dural Cross Bradworthy DESIGNATION: Scheduled Monument CONDITION: Extensive significant problems DERINCIPAL VULNERABILITY: Arable ploughing	PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1016643 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	SITE NAME:	Bowl barrow 420 metres north west of Dural Cro	ss, Bradworthy	
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016643
	CONDITION:	Extensive significant problems	TREND:	Declining
OWNER TYPE: Private CONTACT: Charlotte Russell 01271 831505	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
	OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Bowl barrow 280 metres south west of Upcott	Cross, Broadwoodwi	dger
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019546
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Two bowl barrows 690 metres and 760 metres	south west of Lewort	hy, Clawton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017974
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
ITE NAME:	Four bowl barrows 110 metres and 360 metres cemetery, East Putford	west of Wrangworth	y Cross forming part of a round barro
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018526
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
ITE NAME:	Three fishponds at Winslade, East Putford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017979
CONDITION:	Extensive significant problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
ITE NAME:	Two bowl barrows 600 metres and 750 metres cemetery, East Putford	west of Wrangworth	y Cross forming part of a round barro
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018515
CONDITION:	Extensive significant problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
DWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Two bowl barrows one immediately north and o part of a round barrow cemetery, East Putford	one 100 metres south	of Commonmoor Cottage forming
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018516
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
DWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
ITE NAME:	Hender Barrow, Halwill		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019727
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
DWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:		L la atla a d	
	Bowl barrow 520 metres west of Higher Welsford		1017120
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017138
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Ring cairn and bowl barrow 540 metres south wes	t of Higher Welsfoi	rd, Hartland
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017139
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow on Ugworthy Moor 510 metres sout	h of West Ugworth	y House, Holsworthy Hamlets
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017977
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 60 metres west of St James's Church	, Luffincott	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020476
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Cairn 325 metres north west of Tibbett's Lookout	, Lundy	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016019
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Cairn 530 metres west of Quarterwall Cottages, L	undy	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016012
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Chambered tomb 165 metres north east of the Ro	cket Pole Pond, Lu	ndy
	Chambered tomb 165 metres north east of the Ro Scheduled Monument	LIST ENTRY NUMBER:	ndy 1015931
SITE NAME: DESIGNATION: CONDITION:			
DESIGNATION:	Scheduled Monument Generally satisfactory but with significant localised	LIST ENTRY NUMBER:	1015931

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / SOUTH WEST / TORRIDGE

HERITAGE AT RISK 2021 / SOU	JTH WEST / TORRIDGE		
SITE NAME:	Chapel remains, cemetery and prehistoric settleme	ent on Beacon Hill,	Lundy
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016040
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Natural erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Coastal defence platforms at the Mousehole and T	rap, Lundy	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016031
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Granite quarry on East Sidelands, Lundy		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016041
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
GITE NAME:	Hut circle and small enclosure 270 metres north west of The Old Lighthouse, Lundy		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016014
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY ?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Long house and enclosure 160 metres north of W	idow's Tenement, l	Lundy
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018547
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Medieval settlement immediately south of Halfway	Wall, Lundy	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017647
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY ?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Ruined cottages and well 190 metres north west o	f Quarterwall Cott	ages, Lundy
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016027
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY ?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / SOUTH WEST / TORRIDGE / WEST DEVON

SITE NAME:	The Widow's Tenement medieval settlement and p	prehistoric settleme	ent sites, Lundy
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017646
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Moated site at Grange Farm, Merton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017867
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Cross ridge dyke on Godborough Castle earthwor	k north west of Tu	rner's Wood, Northam
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002640
CONDITION:	Unknown	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 685 metres NNE of Moorfield, Peters Marland / Shebbear		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017963
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	World War II air traffic control building 400 metres north west of Seckington Cross, on the former airfield of RAF Winkleigh, Winkleigh		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020765
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Charlotte Russell 01271 831505

WEST DEVON

SITE NAME: Gawton Mine complex, Bere Ferrers / Gulworthy DESIGNATION: Scheduled Monument, WHS CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: A (A) OWNER TYPE: Private LIST ENTRY NUMBER: 1002667

Former copper and arsenic mine and processing complex, comprising a full range of buildings from cooperage to engine houses. The site has suffered damage from vehicles. Despite previous extensive clearance and emergency support works, vegetation has reclaimed extensive areas of the monument and the temporary propping is showing signs of failure. The structures remain at risk.

© Historic England

Contact: Nick Russell 0117 975 0671

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

use).

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; в solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- NP RPG
- Conservation Area Listed Building Local Planning Authority National Park
 - Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / SOUTH WEST / WEST DEVON


	SITE NAME: Kelly House, Kelly C18 house with serious maintenance issues. Roof is in of renewal, rear medieval wing is partly propped. Main house is weathertight and maintenance is gradually bein addressed. CONDITION: Poor		
	DESIGNATION:	Listed Building grade I	of renewal, rear medieval wing is partly propped. Main house is weathertight and maintenance is gradually being
MILLIN,	CONDITION:	Poor	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1318194	Contact: Annie Evans 0117 975 0673
istania Fueland			

© Historic England



aller.	SITE NAME:	Stable block north of Kelly House, Kelly	Stables, 1740. Partly used, part collapsed.
	DESIGNATION:	Listed Building grade II*	
	CONDITION:	Very bad	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	A (A)	
and a	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1104813	Contact: Annie Evans 0117 975 0673

© Historic England



© Historic England

Aller	SITE NAME:	Greenslade Farmhouse, North Tawton	Farmstead including farmhouse with medieval origins, attached jointed cruck barn, further barn probably C19 and
	DESIGNATION:	Listed Building grade II*	southern range with large malthouse as well as further open fronted barns and stabling. Mainly cob-built. Roofing
	CONDITION: Poor and roof structures in very poor condition. Histori England has been in discussion with the new owne	and roof structures in very poor condition. Historic	
OCCUPANCY: Occupied/in use reg	regarding repairs and maintenance. Emergency repairs		
	PRIORITY CATEGORY:	A (A)	carried out and longer term plan for the site and other repairs are ongoing.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1105370	Contact: Annie Evans 0117 975 0673

© Historic England

	SITE NAME:	Tavistock Abbey, Tavistock	Tavistock Abbey is central to the history and character of
	DESIGNATION:	IGNATION: Scheduled Monument, 16 LBs, CA, WHS foundation of the abbey places it amongst the earlies the medieval religious houses founded in Britain. Its	the medieval town which developed around it. The Saxon foundation of the abbey places it amongst the earliest of the medieval religious houses founded in Britain. Its
	CONDITION:	Poor	occupation from 974 to 1539 included continuous use by the same Benedictine order for over five and a half centuries. The ruins are suffering from water ingress and damaging vegetation growth. Historic England has offered grant to carry out a full condition survey and conservation
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Mixed, multiple owners	management plan for the West Gate House (Betsy Grimbals Tower) and the Still Tower.
ngland	LIST ENTRY NUMBER:	1020401	Contact: Andy Crabb 01626 832093

© Historic Eng

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- UA WHS Unitary Authority World Heritage Site

HERITAGE AT RISK 2021 / SOUTH WEST / WEST DEVON



Å	SITE NAME:	Guildhall and police station, Abbey Place, Guildhall Square, Tavistock	Completed 1848, incorporating medieval fabric in part. Use as court ended 1997 and police station has relocated. The irst known example of a combined police station and magistrates' court. Roof in poor condition and fabric in
	DESIGNATION:	Listed Building grade II*, SM, CA, WHS	magistrates' court. Roof in poor condition and fabric in general urgently needs attention. Tavistock Heritage Trust is working with the Town Council owners, who have been
	CONDITION:	Fair	awarded a second National Lottery Heritage Fund grant t turn the building into a Mining Landscape WHS
	OCCUPANCY:	Vacant/not in use	Interpretation Information Centre. The volunteers' work
	PRIORITY CATEGORY:	F (F)	progressed well but paused due to Covid 19. It is hoped the interpretation centre may open in 2021.
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1309358	Contact: Annie Evans 0117 975 0673

© West Devon Borough Council



SITE NAME:	Church of St Mary, Bratton Clovelly	Parish church. Mainly mid to late C14 although the chancel may be earlier, porch probably early C15; various repairs made in C19 and restored from 1891 to 1892. Granite and
DESIGNATION:	Listed Place of Worship grade I, CA	slate rubble walls with granite dressings, tower is constructed of coursed dressed granite blocks of irregular
CONDITION:	Poor	sizes. Medieval structure enhanced by the remarkable survival of a large number of wall paintings. The church
PRIORITY CATEGORY:	C (C)	suffers from water ingress and there is some structural
OWNER TYPE:	Religious organisation	movement at the east end.
LIST ENTRY NUMBER:	1326312	Contact: Annie Evans 0117 975 0673

© Historic England

SITE NAME: Church of Holy Cross, Parish church. C12 origins with a late C15 tower	ind the
Highampton rest of the church rebuilt in 1837. Restored in 18	
DESIGNATION: Listed Place of Worship grade II* church suffers from water ingress and damp poss associated with its very exposed position. The to	vér walls
CONDITION: Poor are damp; the congregation and appointed archite investigating the causes. Active insect infestation to	ct are
PRIORITY CATEGORY: C (C) timber ribs. Some roof slates cracked and missing	
OWNER TYPE: Religious organisation west window buckled and missing glass.	
LIST ENTRY NUMBER: 1165844 Contact: Annie Evans 0117 975 0673	

© Historic England

	SITE NAME:	Church of St Mary, Walkhampton, West Devon	Church in an elevated position on the edge of Dartmoor about a mile outside the village. Largely C14 but may be
all with	DESIGNATION:	Listed Place of Worship grade I, CA	pre-conquest in foundation. Aisle and tower added in the CI5. Local rubble with granite dressings. Cornish slate roofs. Tower is wet with large amounts of vegetation
AIA A	CONDITION:	Poor	growth. Valley gutter and rainwater goods in need of w
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
England	LIST ENTRY NUMBER:	1105371	Contact: Annie Evans 0117 975 0673

© Historic England

SITE NAME:	Gawton arsenic mine and flue, Bere Ferrers / Gulworthy		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1002667
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Russell 0117 975 0671

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

use).

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lacentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / SOUTH WEST / WEST DEVON

SITE NAME:	Round barrow cemetery and beacon at Heathfield, Milton Abbot	, oou metres west (or moonands, Brentor / Lamerton /
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020075
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Iron Age defended settlement in Dunterue Wood,	570 metres south	of Castle Head, Dunterton
DESIGNATION:	Scheduled Monument, RPG grade I	LIST ENTRY NUMBER:	1020273
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No
OWNER TYPE:	Commercial company	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Bowl barrow 375 metres north east of Higher Ewo	orthy, Germanswee	ek
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020084
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Bowl barrow 620 metres north of Higher Eworthy	, Germansweek	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017971
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Morwellham Quay: transport infrastructure, part c Gulworthy	of the water contro	l system and a manganese mill,
DESIGNATION:	Scheduled Monument, 3 LBs, WHS	LIST ENTRY NUMBER:	1021461
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Roman forts, marching camps and associated mon	uments, North Taw	rton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021151
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Two bowl barrows 200 metres north east of New	land Cross, North	Tawton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017131
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / SOUTH WEST / WEST DEVON / DORSET (UA)

SITE NAME:	Guide post at Place Cross, Okehampton Hamlets		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020069
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Inscribed stones in vicarage garden, Tavistock		
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1003871
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth - General	NEW ENTRY?:	No
OWNER TYPE:	Religious organisation	CONTACT:	Andy Crabb 01626 832093

DORSET (UA)

· · /			
	SITE NAME:	Maiden Street Methodist Church, Maiden Street, Weymouth	Former Methodist church. Fire in January 2002 left the church a gutted, roofless ruin. Subsequent health and safety works completely cleared the interior. Consent was
	DESIGNATION:	Listed Building grade II*, CA	granted in 2007 but not implemented for conversion/ reconstruction to mixed residential and commercial use.
	CONDITION:	Very bad	The site changed hands in 2016. Historic England has been in discussions with the new owner regarding the options
	OCCUPANCY:	Vacant/not in use	available to them and in Nov 2019, planning permission
	PRIORITY CATEGORY:	D (D)	and listed building consent applications for residential conversion/reconstruction were granted.
	OWNER TYPE:	Private	-
ind	LIST ENTRY NUMBER:	42294	Contact: Eve Van Der Steen 01179750685



SITE NAME: Due to coastal erosion, the site is in imminent danger of Sandsfoot Castle, Weymouth collapse Scheduled Monument and Listed DESIGNATION: Building grade II*, WHS CONDITION: Fair OCCUPANCY: N/A PRIORITY CATEGORY: C (New entry) OWNER TYPE: Local authority LIST ENTRY NUMBER: 1020062 and 1096763 Contact: John Ette 0117 975 0687

© Historic England

© Historic Englan



© Historic England

This large scheduled site contains 12 individually listed SITE NAME: The dovecote, malthouse, outer buildings, six of which are in poor or very bad condition. gatehouse and walling, gateway, Several of the buildings were included in a 2013/14 granary and tithe barn, St Peter's Abbey, Abbotsbury condition survey to inform a future repair strategy. The published photo shows the dovecote, which is disused and Scheduled Monument and Listed unstable. It has potential for low-key use in conjunction DESIGNATION: Buildings - 5 grade I; 5 grade II*; with a visitor attraction centred on the nearby Tithe Barn 4 grade II, LB grade II, part in CA complex. In 2018/19, Historic England Repair Grants helped to fund project development work on the Tithe CONDITION: Poor Barn and also works to the Granary. OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: D (D) OWNER TYPE: Mixed, multiple owners 1015693 and 1305224; Contact: Daniel Bashford 07824 103102 1118743; 1305209; 1118706; 1118747; 1172244; 1118746; LIST ENTRY NUMBER: ||72220; |324227; |||874|;

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D Under repair or in fair to good

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

1118742; 1118744; 1118745;

1118748

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).


- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- ŬA Unitary Authority World Heritage Site WHS

© Historic

© Historic England

	SITE NAME:	Parnham House, Beaminster	Picturesque 16th century country house, much refashioned
	DESIGNATION:	Listed Building grade I, RPG grade II*	and extended in 1810 by Nash and remodelled in early C20. Suffered catastrophic fire in April 2017. The majority of the roof and internal structure have been destroyed, but
	CONDITION:	Very bad	the external shell largely survives although in an increasingly fragile state. In March 2020 the property was sold and
	OCCUPANCY:	Part occupied/part in use	shortly afterwards Historic England started pre-applicati
	PRIORITY CATEGORY:	A (A)	discussions. The owner's plans for its use are now crystallizing and a restoration strategy is developing for a
. 23	OWNER TYPE:	Private	phased repair approach. It is hoped that scaffolding will soon be erected.
ic England	LIST ENTRY NUMBER:	1221178	Contact: Jenny Chesher 0117 975 0686

	SITE NAME:	Literary and Scientific Institute, East Street, Bridport	Founded 1835 as Mechanics Institute and reconstituted 1855 as Literary and Scientific Institute. Bridport
	DESIGNATION:	Listed Building grade II*, CA	Development Trust delivered project to repair and extend the building with National Lottery Heritage Fund support
	CONDITION:	Fair	and grant-aid from Historic England. Works largely ' completed in 2018 although some outstanding issues
M	OCCUPANCY:	Part occupied/part in use	remain.
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Charity (non-heritage)	
	LIST ENTRY NUMBER:	8999	Contact: Sarah Ball 0117 975 0666



	SITE NAME:	North Lodges, Lulworth Castle, Coombe Keynes	Ornamental gate lodges and gateway to Lulworth Castle, 1785. The lodges and gates are stable but the flank walls
	DESIGNATION:	Scheduled Monument and Listed Building grade II*, part in RPG grade II, part in CA	and mock-fortifications are in poor condition. The estate is exploring possible funding for the repair of the lodges. It is hoped that with the Estate's newly appointed architect working on nearby Bindon, that the Estate's direct labour
	CONDITION:	Poor	will be able to carry out repairs to the walls. They are currently successfully repairing outer walls.
AND - TO COM	OCCUPANCY:	Vacant/not in use	currently successfully repairing outer wails.
	PRIORITY CATEGORY:	C (C)	
© Historic England	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1016685 and 1323333	Contact: Jenny Chesher 0117 975 0686



		1010005 and 1525555	Contact. Jenny Chesnel 0117 775 0000
	SITE NAME:	Marshwood Castle, Marshwood	The site comprises a rectangular earthwork enclosure with
	DESIGNATION:	Scheduled Monument and Listed Building grade II*, LB grade II	a moat (partly filled). There are substantial remains of the internal ramparts and the motte. These masonry structures require consolidation and careful on-going management.
	CONDITION:	Poor	The masonry is precarious and currently being eroded by both stock and vegetation.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1002836 and 1324105	Contact: Daniel Bashford 07824 103102

© Historic England

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

use).

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG Registered Park and Garden Scheduled Monument
- SM

UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / SOUTH	I WEST / DORSET (UA)		
	SITE NAME:	Abbey Church of St Mary, St Sansom and St Branwalader, Milton Abbas	Formerly church of a Benedictine abbey now used as a school chapel. Mainly C14, upper part of tower and north transept C15. Restored c1790 by J Wyatt and 1865 by Sir
	DESIGNATION:	Listed Building grade I, RPG grade II*, CA	Gilbert Scott. Walls of stone and flint with ashlar dressings. Nave and aisles were not rebuilt after fire in C14. Repairs to roofs, windows, floors and drainage has been completed
	CONDITION:	Poor	with Viridor funding. Transept roofs and tower louvres remain vulnerable.
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	E (E)	
© Historic England	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1304822	Contact: Sarah Ball 0117 975 0666
	SITE NAME:	Icehouse at Ringstead, 660 metres south west of Pit House, Osmington	A small C19 icehouse, built to serve the needs of the local fishing community. It is now in unmanaged woodland, with trees and ivy growing over it. The roots will have
	DESIGNATION:	Scheduled Monument	weakened the roof and there is a high risk of damage from falling trees.
Contract Street Land	CONDITION:	Very bad	0
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
© Historic England	LIST ENTRY NUMBER:	1020358	Contact: Daniel Bashford 07824 103102
	SITE NAME:	Cart shed and stables 10 metres south of Waddon House, Portesham	Former stables and cart shed, dated 1702. Application for repair and conversion to holiday let use has been approved. The roof has been re-thatched, but other works
	DESIGNATION:	Listed Building grade II*	still needed.
	CONDITION:	Fair	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Private	
© Historic England	LIST ENTRY NUMBER:	1152606	Contact: Sarah Ball 0117 975 0666
	SITE NAME:	Rufus Castle, Church Ope Road, Easton, Portland	Present structure probably late C15, on site of earlier building captured in 1142 by Earl Robert of Gloucester.
	DESIGNATION:	Scheduled Monument and Listed Buildings - I grade I; I grade II*, LB grade II, CA, WHS	Ruinous and in need of conservative repair and consolidation. Scheme of repair and urgent works carried out in 2010 with Historic England grant although more work is still needed. Site has a new owner and discussions
	CONDITION:	Poor	are at an early stage. The monument also includes the ruins of a C12 grade II* church, St Andrews, believed to stand on
The Area and the	OCCUPANCY:	N/A	the site of an earlier Saxon church.
a second second	PRIORITY CATEGORY:	C (C)	
© Historic England Archive	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1002698 and 1280727; 1205384	Contact: Sarah Ball 0117 975 0666
	SITE NAME:	Church of St Peter, Grove Road, Grove, Portland	Former Church of England church in robust Romanesque style, erected in 1872. Designed by Major General Edmund
	DESIGNATION:	Listed Building grade II*, CA	du Cane, built by convict labour from Portland's prison and later transferred to the parish. No longer used for worship
The second second	CONDITION:	Poor	and in poor condition. Relatively complete interior of interest as an undivided space and with robust
	OCCUPANCY:	Vacant/not in use	contemporary fittings. Local Authority considering taking
The state	PRIORITY CATEGORY:	C (C)	action against owner.
	OWNER TYPE:	Private	
© Historic England Archive	LIST ENTRY NUMBER:	1205607	Contact: Eve Van Der Steen 01179750685
PRIORITY CATEGORIES A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.	E Under repair or in fa	d. (where applicable) end use o hir to good user identified; or functionally	r Last year's priority category is LB Listed Building shown in brackets (otherwise, LPA Local Planning Authority
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). redundant buildings with new use New Entry is noted). agreed but not yet implemented. NP National Park C Slow decay; no solution agreed. No solution agreed. NP National Park			

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

	. ,		
	SITE NAME:	Sherborne House, Newland, Sherborne	Grand town house of c1720 with earlier elements, formerly a school but last used in the 1990s. Fine internal
	DESIGNATION:	Listed Building grade I, CA	features include a grand stairhall decorated with Thornhill wall paintings. External reparirs undertaken in 2012 were
	CONDITION:	Fair	funded by developent of part of the rear garden but the house remained unused with internal refurbishment still to
	OCCUPANCY:	Vacant/not in use	be completed. It was sold in 2018 and a new charitable
	PRIORITY CATEGORY:	E (E)	trust was set up for it. Following extensive pre-application discussions, the Council has resolved in May 2021 to
	OWNER TYPE:	Charity (heritage)	approve applications for its reuse and development as an arts and community centre.
© Historic England Archive	LIST ENTRY NUMBER:	0694	Contact: Jenny Chesher 0117 975 0686

	SITE NAME:	Sturminster Newton Castle, Sturminster Newton	Ruins of C14 stone built manor house within Sturminster Newton Castle, a probable Iron Age promontory fort
	DESIGNATION:	Scheduled Monument and Listed Building grade II*, CA	overlooking the River Stour. Upstanding remains are in a very precarious position and a considerable amount of consolidation work is urgently required to avoid significant
	CONDITION:	Very bad	areas of collapse. Historic England architectural survey team has recorded the structure. The site is up for sale ar we hope to engage in discussions with the new owner as soon as possible to discuss the most urgent works.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
Historic England	LIST ENTRY NUMBER:	1002719 and 1324461	Contact: Daniel Bashford 07824 103102

Tithe Barn, Church Lane, Sydling St. Nicholas

Scheduled Monument and Listed

Building grade II*, part in CA

Very bad

A (A)

Private

Crawford

Very bad

N/A

C (C)

Building grade II*

Private, multiple owners

1002715 and 1110841

Vacant/not in use

1003209 and 1119426

Barn and outbuilding range,

Tarrant Abbey Farm, Tarrant

Scheduled Monument and Listed



SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

D

Е

PRIORITY CATEGORY:

LIST ENTRY NUMBER

PRIORITY CATEGORY:

LIST ENTRY NUMBER:



© Hi



© Historic England



SITE NAME:	Holditch Court Tower, Thorncombe
DESIGNATION:	Scheduled Monument, LB grade I
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1002835

This monument includes part of a fortified house situated within a farmyard. The part of the fortified house survives as a three-storeyed roofless rectangular plan tower with a projecting circular stair-turret in the south west angle and stands to a height of approximately eight metres. Historic England funded a project development grant in 2018 for the removal of the ivy, a condition survey and measured survey which were completed in 2020. It is anticipated this will inform a future repair project.

Impressive CI6 barn. It has an interesting constructional

history and is part of an important complex of historic buildings. Its gradual deterioration has recently shown signs

of accelerating with the loss of an area of roof covering.

protective roof covering has become dislodged.

Contact: Sarah Ball 0117 975 0666

part of the roof has collapsed.

Contact: Daniel Bashford 07824 103102

Progress on finding a suitable use has stalled and part of the

C15 barn with C18 outbuildings and alterations. No longer

in agricultural use. Works have been undertaken to

support the structure but deterioration is on-going and

Contact: Sarah Ball 0117 975 0666

PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM
- ΪA Unitary Authority World Heritage Site WHS



SITE NAME:	Stable Block immediately south east of Little Toller Farm, Toller Fratrum	Mid C16 stable building, forming part of a working farm but currently disused. The thatch is in a very degraded state leading to partial collapse of the roof and rear wall
DESIGNATION:	Listed Building grade II*	structure at the end of 2011. The stable building has been scaffolded with a temporary roof structure which is
CONDITION:	Very bad	protecting the collapsed historic fabric. The long term repair of the structure needs to be explored along with
OCCUPANCY:	Vacant/not in use	possible funding sources.
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1228876	Contact: Sarah Ball 0117 975 0666



K	SITE NAME:	Former Methodist Chapel, Dorchester Road, Tolpuddle	Former Methodist church, c1818, and the meeting place of the Tolpuddle Martyrs. Building bought by Tolpuddle Old
	DESIGNATION:	Listed Building grade II*, CA	Chapel Trust at the beginning of 2015. Historic England grant awarded in 2014 to carry out emergency works and
	CONDITION:	Poor	undertake project development work; completed in spring 2015. National Lottery Heritage Fund development grant
	OCCUPANCY:	N/A	completed in 2017 and the Trust has secured further
	PRIORITY CATEGORY:	D (D)	Lottery funding for Stage 2 repairs. Historic England offered match-funding for repairs to fabric of former chapel
	OWNER TYPE:	Charity (heritage)	anticipated to start on site in 2021-2022.
	LIST ENTRY NUMBER:	9849	Contact: Sarah Ball 0117 975 0666

© Historic England

© Historic England



SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY.


OWNER TYPE:

PRIORITY CATEGORY:

© Historic England

© Historic England





Royal Naval Cordite Factory at Holton Heath, Wareham St.

Scheduled Monument, LB grade

Martin

Very bad

A (A)

Vacant/not in use

Mixed, multiple owners

Ш

Former monastic site, now farmhouse. Following sale in 2017, significant unauthorised works were undertaken internally. There has been a partial collapse of the historic ceiling at first floor level and cracks are visible on the east gable. In May 2020 temporary protection had been applied to some windows. Discussions with the owner to reverse the inappropriate works and repair the building have currently stalled and Historic England is exploring all options with Dorset Council to secure the reinstatement

The cordite factory was built in 1916, and continued to

produce explosives until 1945. It covers a large area of land, with lots of small workshops surrounded by earth

individual buildings and structures still remain, now in

needed. Much of the site is within a nature reserve and

only open to the public by prior arrangement. The area included in the scheduling was extended in 2016.

banks, to contain any accidental blasts. A large number of

varying degrees of collapse, and a programme of works to identify and repair the most significant of these is urgently

Contact: Eve Van Der Steen 01179750685



e name:	Grotto 250 metres south east of St Giles House, Wimborne St. Giles
SIGNATION:	Listed Building grade II*, RPG grade II*
NDITION:	Poor
CUPANCY:	N/A
ORITY CATEGORY:	E (E)
VNER TYPE:	Private
T ENTRY NUMBER:	1120131

Grotto c1751-53. located 250 metres to the south east of the house, at the east end of a winding channel of water running towards the lake. One of several garden buildings situated in the C17 and C18 landscape. The Grotto was subject to a major programme of repair during 2014, under a Natural England Stewardship scheme. External consolidation and much of the internal shell decoration reinstated. A further and final phase of repair to the structural vaults which are largely below water level, is needed.

Contact: Sarah Ball 0117 975 0666

PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric: solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

OW

LIST

D

Е

use)

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

ΪA

- Conservation Area Listed Building
- LB I PA
 - Local Planning Authority National Park
- NP RPG
- Registered Park and Garden Scheduled Monument SM
- Unitary Authority World Heritage Site WHS

	. ,		
	SITE NAME:	Manor Farm barn, Winterborne Clenston	Huge late C16 tithe barn part used for storage. The hammerbeam roof may have been reused from a monastic
	DESIGNATION:	Listed Building grade I	building at Milton Abbey. Partial roof collapse resulted in Historic England funding the erection of scaffolding as a
	CONDITION:	Very bad	temporary roof support. These repair works were completed in 2008, but there has been no further progress
	OCCUPANCY:	N/A	and the building is slowly deteriorating.
	PRIORITY CATEGORY:	C (C)	
Con the	OWNER TYPE:	Mixed, multiple owners	
© Historic England	LIST ENTRY NUMBER:	1110166	Contact: Sarah Ball 0117 975 0666



© Historic England

©

	SITE NAME:	Bindon Abbey (site), Wool	Bindon Abbey was founded as a Cistercian monastic house
DESIGNATION: Scheduled Monument, LB grade I Dissolution. N the English Ci	in 1172 and converted to a fine house in 1539 following the Dissolution. Much of the building was burnt down during the English Civil War but some of the structure survives as		
	CONDITION:	Fair	a standing ruin of up to seven metres high. The masonry was very precarious, with several recent falls of stone, and
OCCUPANCY:	OCCUPANCY:	N/A	supported by scaffolding. In 2018, the estate received a
CELL.	PRIORITY CATEGORY:	E (E)	repair grant from Historic England and, as of Summer 2019, most of the main repairs are complete. Still some ivy
OWNER TYPE: Private	removal and consolidation needed elsewhere on the site, but progressing well.		
	LIST ENTRY NUMBER:	1002703	Contact: Daniel Bashford 07824 103102

© Marcus Chantrey, Benjamin Beauchamp Architects



	SITE NAME:	Church of St Peter and St Paul, Market Place, Blandford Forum	This church is a prime example of Georgian church architecture outside London. It was rebuilt after a fire between 1732 and 1739 to designs by John and Willian Bastard. The external stonework is in poor condition a there is water ingress to the interior causing damage to
	DESIGNATION:	Listed Place of Worship grade I, CA	
	CONDITION:	Poor	plaster work. A Development grant was awarded by the National Lottery Heritage Fund in January 2019 for repairs
	PRIORITY CATEGORY:	B (B)	works to nave roof, parapet gutters, high level masonry
5	OWNER TYPE:	Religious organisation	and internal plasterwork.
	LIST ENTRY NUMBER:	1251913	Contact: Sarah Ball 0117 975 0666

	SITE NAME:	Church of St John, The Harbour, West Bay, Bridport	This 1930s Arts and Crafts church is a simple, low building on the quayside, built to serve the local fishing community.
	DESIGNATION: Listed Place of Worship grade II, CA the congregation have made very good there are still some areas of damp, an are leaking, the roofs have been repai	Since it was added to the Heritage at Risk register in 2014, the congregation have made very good progress. Although there are still some areas of damp, and the leaded windows	
		are leaking, the roofs have been repaired and the building is beginning to dry out. Some further work is needed but it is	
	PRIORITY CATEGORY:	D (D)	improving.
	OWNER TYPE:	Religious organisation	
1.	LIST ENTRY NUMBER:	1279418	Contact: Daniel Bashford 07824 103102

© Historic England



SITE NAME:	Church of St Andrew, The Street, Charmouth	Parish church. Entirely rebuilt 1836-8, by Charles Fowl Gothic Revival style. Forest marble plinth, chert rubble walls with "long-and-short style" stone dressings. Wind
DESIGNATION:	Listed Place of Worship grade II, CA	walls with "long-and-short style" stone dressings. Window dressings of Beer stone. Boscastle slate roofs; nave has tiled ridge. Tower and church walls are cement pointed which is
CONDITION:	Poor	failing causing water ingress. Unsuccessful in attempts to secure funding from National Lottery Heritage Fund. Re-
PRIORITY CATEGORY:	C (C)	roofing of north porch underway in Spring 2019. Further
OWNER TYPE:	Religious organisation	works are planned and funding being sought to address the water ingress and damage caused.
LIST ENTRY NUMBER:	1215162	Contact: Sarah Ball 0117 975 0666

© Marcus Chantrey, Benjamin Beauchamp Architects

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lacentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Parish Church of St Martin, Cheselbourne	C13-15 church. Nave, chancel, south aisle with south porch, 3-stage west tower. Flint walls with ashlar dressing and variety of roof finishes. Restorations in 1874 and 1924 Building has been subjected to heritage crime.
Set 1	DESIGNATION:	Listed Place of Worship grade I	
	CONDITION:	Poor	
	PRIORITY CATEGORY:	A (New entry)	
	OWNER TYPE:	Religious organisation	
s ni	LIST ENTRY NUMBER:	1324023	Contact: Sarah Ball 0117 975 0666

© Yes

an ang	SITE NAME:	Church of All Saints, Straits, Portland	Church built in 1914-17 to design of Crickmay and Sons. Built of Portland ashlar with predominantly tiled roofs.
To	DESIGNATION: Listed Place of Wo	Listed Place of Worship grade II, CA	Traditionally orientated with large nave, north and south aisles, north and south transepts, chancel, side chapel and vestry. Windows in south chapel by Clayton and Bell.
	CONDITION:	Poor	Strong design of single phase with meticulous detailing and retaining most of its original fittings. Window stonework in
	C (C)	poor condition.	
	OWNER TYPE:	Religious organisation	
1 10 10 -	LIST ENTRY NUMBER:	1281831	Contact: Sarah Ball 0117 975 0666

© James Menzies



	SITE NAME:	Parish Church of St Andrew, Trent	Medieval church with a richly decorated interior. There i internal damp, and structural work to the tower and spir	
Listed Place of Worship grade I, CA	is needed. The church also has important and high qual medieval and Victorian window glass, some of which is showing signs of structural instability and paint detachm			
1	CONDITION Poor Conservation works have been undertaken t	Conservation works have been undertaken to the east and		
	PRIORITY CATEGORY:	F (F)	west windows and external protective glazing installed on the east window. The chancel roof has been recovered.	
	Repair works to the spire are due to commence in June 2019.			
	LIST ENTRY NUMBER:	1323927	Contact: Sarah Ball 0117 975 0666	

© Historic England

SITE NAME:	Group of round barrows on Ridgeway		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002760
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Sandsfoot Castle		
DESIGNATION:	Scheduled Monument and Listed Building grade II*, WHS	LIST ENTRY NUMBER:	1020062 and 1096763
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	Yes
OWNER TYPE:	Local authority	CONTACT:	John Ette 0117 975 0687
SITE NAME:	Abbotsbury Castle (camp), Abbotsbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002710
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sasha Chapman 0117 975 1338

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	Four bowl barrows 725 metres ESE of Wears Farm	, Abbotsbury	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002825
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sasha Chapman 0117 975 1338
SITE NAME:	Group of five round barrows on White Hill, Abbot	sbury	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003213
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sasha Chapman 0117 975 1338
SITE NAME:	Round barrow 230 yards (210 metres) east of Whi	te Hill Plantation, A	Abbotsbury
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002824
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sasha Chapman 0117 975 1338
SITE NAME:	Two fishponds in Oddens Wood, Abbotsbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015696
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No
	Private	CONTACT:	Sasha Chapman 0117 975 1338
OWNER TYPE:			
	Two round barrows on Wears Hill, Abbotsbury		
SITE NAME:	Two round barrows on Wears Hill, Abbotsbury Scheduled Monument	LIST ENTRY NUMBER:	1002731
SITE NAME: DESIGNATION:	,	LIST ENTRY NUMBER:	1002731 Declining
OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY:	Scheduled Monument Generally satisfactory but with significant localised		
SITE NAME: DESIGNATION: CONDITION:	Scheduled Monument Generally satisfactory but with significant localised problems	TREND:	Declining
SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: DWNER TYPE:	Scheduled Monument Generally satisfactory but with significant localised problems Scrub/tree growth	TREND: NEW ENTRY?: CONTACT:	Declining No Sasha Chapman 0117 975 1338
SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument Generally satisfactory but with significant localised problems Scrub/tree growth Private	TREND: NEW ENTRY?: CONTACT:	Declining No Sasha Chapman 0117 975 1338
SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument Generally satisfactory but with significant localised problems Scrub/tree growth Private Bowl barrow in Piddle Wood, 530 metres north ea	TREND: NEW ENTRY?: CONTACT: st of Gate Barn, Af	Declining No Sasha Chapman 0117 975 1338 ffpuddle and Turnerspuddle
SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY:	Scheduled Monument Generally satisfactory but with significant localised problems Scrub/tree growth Private Bowl barrow in Piddle Wood, 530 metres north ea Scheduled Monument	TREND: NEW ENTRY?: CONTACT: st of Gate Barn, Af	Declining No Sasha Chapman 0117 975 1338 ffpuddle and Turnerspuddle 1015901
SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY:	Scheduled Monument Generally satisfactory but with significant localised problems Scrub/tree growth Private Bowl barrow in Piddle Wood, 530 metres north early Scheduled Monument Extensive significant problems	TREND: NEW ENTRY?: CONTACT: st of Gate Barn, Af LIST ENTRY NUMBER: TREND:	Declining No Sasha Chapman 0117 975 1338 ffpuddle and Turnerspuddle 1015901 Declining
SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument Generally satisfactory but with significant localised problems Scrub/tree growth Private Bowl barrow in Piddle Wood, 530 metres north ear Scheduled Monument Extensive significant problems Forestry	TREND: NEW ENTRY?: CONTACT: St of Gate Barn, Af LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:	Declining No Sasha Chapman 0117 975 1338 ffpuddle and Turnerspuddle 1015901 Declining No Daniel Bashford 07824 103102
SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument Generally satisfactory but with significant localised problems Scrub/tree growth Private Bowl barrow in Piddle Wood, 530 metres north early Scheduled Monument Extensive significant problems Forestry Commercial company The Double Barrow, a bowl barrow in Kite Hill Pla	TREND: NEW ENTRY?: CONTACT: St of Gate Barn, Af LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:	Declining No Sasha Chapman 0117 975 1338 ffpuddle and Turnerspuddle 1015901 Declining No Daniel Bashford 07824 103102
SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION:	Scheduled Monument Generally satisfactory but with significant localised problems Scrub/tree growth Private Bowl barrow in Piddle Wood, 530 metres north early Scheduled Monument Extensive significant problems Forestry Commercial company The Double Barrow, a bowl barrow in Kite Hill Pla Affpuddle and Turnerspuddle	TREND: NEW ENTRY?: CONTACT: st of Gate Barn, Af LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: ntation 250 metres	Declining No Sasha Chapman 0117 975 1338 ffpuddle and Turnerspuddle 1015901 Declining No Daniel Bashford 07824 103102 south east of Roger's Hill Cottages,
SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Scheduled Monument Generally satisfactory but with significant localised problems Scrub/tree growth Private Bowl barrow in Piddle Wood, 530 metres north earner Scheduled Monument Extensive significant problems Forestry Commercial company The Double Barrow, a bowl barrow in Kite Hill Pla Affpuddle and Turnerspuddle Scheduled Monument	TREND: NEW ENTRY?: CONTACT: St of Gate Barn, Af LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: CONTACT:	Declining No Sasha Chapman 0117 975 1338 ffpuddle and Turnerspuddle 1015901 Declining No Daniel Bashford 07824 103102 south east of Roger's Hill Cottages, 1015900

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Length of deer park bank and ditch at Alderholt,	Length of deer park bank and ditch at Alderholt, Alderholt		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002394	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102	
SITE NAME:	Barrow east of Burnt House Bottom, Alton Pane	cras		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002862	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102	
SITE NAME:	Bowl barrow on Worgret Heath, 320 metres no	orth west of High Tor	, Arne	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018190	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102	
SITE NAME:	Linear boundary 870 metres south west of Sprin	g Farm, Ashmore		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020729	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102	
SITE NAME:	Earthwork 80 yards (70 metres) long, north wes	t of Coombe Bottom	n, Askerswell	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002734	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102	
SITE NAME:	Round barrow north west of Coombe Bottom, a	Askerswell		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003061	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102	
SITE NAME:	Bowl barrow on Beaminster Down 530 metres	south east of East Axi	noller Farm, Beaminster	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015049	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

ITE NAME:	Bowl barrow on Beaminster Down 770 metres i	orth east of Higher N	1eerhay Farm, Beaminster
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015050
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bowl barrow 515 metres south of the southern	extent of Horse Clos	e Plantation, Bere Regis
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015386
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bowl barrow 590 metres north east of Bere Do	wn Farm, Bere Regis	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015378
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bowl barrow 610 metres east of Bere Heath Far	m, Bere Regis	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015365
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bowl barrow 790 metres north east of Hayward	s Farm, Bere Regis	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015330
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bowl barrow on Warren Heath, 350 metres sou	th west of Warren H	ouse, Bere Regis
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019367
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Four bowl barrows 240 metres east of Oak Cot	age, Bere Regis	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015369
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Long barrow on Bere Down, 1100 metres north	east of Roke Barn, B	ere Regis
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015329
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Author NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

Construction Construction Construction Construction Construction Construction Daniel Bashford 07824 103 102 Strate Market Three bowl barrows 230 metress south west of Haywards Farm, Bere Regis Daniel Bashford 07824 103 102 Dissignation Scheduled Monument Instration Daniel Bashford 07824 103 102 Strate Strate Private Construction Daniel Bashford 07824 103 102 Strate Strate Private Construction Daniel Bashford 07824 103 102 Strate Strate Private Construction Daniel Bashford 07824 103 102 Strate Strate Private Construction Daniel Bashford 07824 103 102 Strate Strate Two bell barrows and a bowl barrow, 200 metres Instrate Daniel Bashford 07824 103 102 Strate Strate Two bowl barrows on South Heath, 900 metres SSE of The Bungalow, Bere Regis Daniel Bashford 07824 103 102 Strate Strate Two bowl barrows on South Heath, 900 metres SSE of The Bungalow, Bere Regis Daniel Bashford 07824 103 102 Strate Strate Two bowl barrows on South Heath, 900 metres North Res	SITE NAME:	The End Barrow, a bowl barrow 320 metres sou	ith west of White Ho	use, Bere Regis
problemsproblemsproblemsDetailingDetailingseascard VLINEARMENTYArabic clippingNovNoseascard VLINEARMENTYCommercial companyCNACC::Daniel Bashford 07824 103102VERNEALTYNEThree bowl barrows 230 metres south west of Haywards Farm, Bere RegisDaniel Bashford 07824 103102VERNEALTYNEScheduled MonumentItsti MURTINUERMEN1015333CONTROPHExtensive significant problemsTREDO:Daniel Bashford 07824 103102VERNEALTYNEArabic ploughingNoDaniel Bashford 07824 103102VERNEALTYNETwo bell barrows and a bowl barrow, 200 metresDaniel Bashford 07824 103102VERNEALTYNETwo bell barrows and a bowl barrow 200 metresDaniel Bashford 07824 103102VERNEALTYNEScheduled Monumentutre VITAN MURSexID15332VERNEALTYNEArabic ploughingNoNoVERNEALTYNEArabic ploughingNoNoVERNEALTYNEArabic ploughingNoNoVERNEALTYNEYerive stremsNoNoVERNEALTYNEYerive stremsNoNoVERNEALTYNEScheduled MonumentUtre VITAN MURSexID16904VERNEALTYNEScheduled MonumentUtre VITANNoVERNEALTYNEScheduled MonumentUtre VITANNoVERNEALTYNEScheduled MonumentUtre VITANNoVERNEALTYNEScheduled MonumentUtre VITAN MURSexID15899VERNEALTYNEScheduled MonumentUtre VITAN MURSexID15899VE	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017462
Devines TIPE: Commercial company CONTRCT: Daniel Bashford 07824 103102 Data TAMPE: Three bowl barrows 230 metres south west of Haywards Farm, Bere Regis 1015333 Declining Extensive significant problems TREND: Declining Declining Private Daniel Bashford 07824 103102 Daniel Bashford 07824 103102 DEGRAMIDAL MULADMAUTT: Arabie ploughing No Daniel Bashford 07824 103102 DEGRAMIDAL MULADMAUTT: Arabie ploughing No Daniel Bashford 07824 103102 DEGRAMIDAL MULADMAUTT: Arabie ploughing No Daniel Bashford 07824 103102 DEGRAMIDAL MULADMAUTT: Arabie ploughing No Daniel Bashford 07824 103102 DEGRAMIDAL MULADMAUTT: Arabie ploughing No Daniel Bashford 07824 103102 DEGRAMIDAL MULADMAUTT: Arabie ploughing No Daniel Bashford 07824 103102 DEGRAMIDAL MULADMAUTT: Arabie ploughing No Daniel Bashford 07824 103102 DEGRAMIDAL MULADMAUTT: Arabie ploughing No Daniel Bashford 07824 103102 DEGRAMIDAL MULADMAUTT: Scheduled Monument UT DITTTT NUMER No <td>CONDITION:</td> <td></td> <td>TREND:</td> <td>Declining</td>	CONDITION:		TREND:	Declining
STIP MARKE. Three bowl barrows 200 metres south west of Haywards Farm. Bere Regis SEGRAMTADNE Scheduled Monument UPT ENTRY NUMBER [015333 CONDITIONE Extensive significant problems TRUD. Declining MIRE NAME. Arable ploughing New MIRE No OWNER TYPE. Private CONTACT: Daniel Bashford 07824 103102 MIRE NAME. Two bell barrows and a bowl barrow, 200 metres north east of Haywards Farm, Bere Regis Declining DESIGNATIONE Extensive significant problems TRUD. Declining DESIGNATIONE Extensive significant problems TRUD. Declining DEVENTIONE Extensive significant problems TRUD. Declining DEVENTIONE Extensive significant problems TRUD. Daniel Bashford 07824 103102 STELNAME. Two bowl barrows on South Heath, 900 metres SEE of The Bungalow. Bere Regis DEVENTIONE Scheduled Monument UPT ENTRY NUMERE [017694 DEVENTIONE Scheduled Monument UPT ENTRY NUMERE [017694 DEVENTIONE Scheduled Monument UPT ENTRY NUMERE [017694 DEVENTIONE Scheduled Monument I	PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
DESIGNATION:Scheduled MonumentUST ENTRY NUMBER1015333CONDICINO:Extensive significant problemsTRNDDecliningRERACIAN VULNERABULTY:Arable ploughingNEW ENTRY:NoOWNER TYPE:PrivateCONTACT:Daniel Bashford 07824 103102STIE MARE:Two bell barrows and a bool barrow, 200 metres north east of HaywardISS33DESIGNATION:Scheduled MonumentUST ENTRY NUMBERDecliningEDESIGNATION:Scheduled MonumentUST ENTRY NUMBERDecliningENRORE:Scheduled MonumentUST ENTRY NUMBERIO15332ENRORE:PrivateCONTACT:Daniel Bashford 07824 103102ENRORE:Scheduled MonumentUST ENTRY NUMBERNoENRORE:PrivateCONTACT:Daniel Bashford 07824 103102ENRORE:Two bool barrows on South Heath, 900 metres SSE of The BunglowBere RegisENRORE:Scheduled MonumentUST ENTRY NUMBER1017694ENRORE:Scheduled MonumentUST ENTRY NUMBER1017694ENRORE:Commercial companyCONTACT:Daniel Bashford 07824 103102ENRORE:Commercial companyCONTACT:Daniel Bashford 07824 103102ENRORE:Scheduled MonumentUST ENTRY NUMBER:1015899ENRORE:Enrore:Bell Barrow on Blackhill Clump 470 metres north of Mintern's Ferry.NoENRORE:FrenzersResisAffpuddle andENRORE:FrenzersCONTACT:Daniel Bashford 07824 103102ENRORE:Generally unsatisfactory	OWNER TYPE:	Commercial company	CONTACT:	Daniel Bashford 07824 103102
Construction Declining Reservant WURDERABULTY: Arable ploughing NEW DUTKY: No OWNER TYPE: Private CONTACT: Daniel Bashford 07824 103102 STREMARE: Two bell barrows and a bowl barrow, 200 metres CONTACT: Daniel Dashford 07824 103102 STREMARE: Two bell barrows and a bowl barrow, 200 metres CONTACT: Daniel Bashford 07824 103102 STREMARE: Two bell barrows and a bowl barrow, 200 metres CONTACT: Daniel Bashford 07824 103102 STREMARE: Two bowl barrows on South Heath, 900 metres STREMARE: No OWNERTTYPE: Private CONTACT: Daniel Bashford 07824 103102 STREMARE: Two bowl barrows on South Heath, 900 metres SEC OTTACT: No OWNERTTYPE: Two bowl barrows on South Heath, 900 metres SEC OTTACT: No DESIGNATION Scheduled Monument UIS FUTRY NUMBER: No Declining StreMARE: Commercial company CONTACT: Daniel Bashford 07824 103102 StreMARE: Scheduled Monument UIS FUTRY NUMBER: No CONNERTTYP	SITE NAME:	Three bowl barrows 230 metres south west of l	Haywards Farm, Bere	Regis
PRINCERAL VULNERABILITI: Arabie ploughing NEW PITTR:: No OWNER TYPE: Private CONTACT: Daniel Bashford 07824 103102 DESIGNATION: Two bell barrows and a bowl barrow, 200 metres north east of Haywards Farm, Bere Regis Dis332 DESIGNATION: Scheduled Monument Ext Ensive significant problems IREND: Declining PRINCERAL VULNERABILITI: Arabie ploughing New WENTR:: No OWNER TYPE: Private CONTACT: Daniel Bashford 07824 103102 STEENAME: Two bowl barrows on South Heath, 900 metres SSE of The Bungalow, Bere Regis Declining DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1017694 CONTRACT: Commercial company CONTACT: Daniel Bashford 07824 103102 STEENAME: Commercial company CONTACT: Daniel Bashford 07824 103102 ST	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015333
Demonstration Private CONTRACT: Daniel Bashford 07824 103102 ATTE NAME: Two bell barrows and a bowl barrow, 200 metres Last FARM, WILLEN, MURERA 1015332 DEBIGNATION Scheduled Monument UST ENTRY NUMBER, 1015332 CONDITION Extensive significant problems TREND: Declining CONDITION Extensive significant problems No Declining CONDITION Atable ploughing No Declining CONDITION Contract: Daniel Bashford 07824 103102 MIRE NAME: Two bowl barrows on South Heath, 900 metres SEF of The Bungalow, Bere Regis DEBIGNATION: Scheduled Monument UST ENTRY NUMBER; 101694 CONDITION: Scheduled Monument UST ENTRY NUMBER; No CONDITION: Scheduled Monument UST ENTRY NUMBER; 1015899 EXENDER: Scheduled Monument UST ENTRY NUMBER; 101699 CONTRACT: Berl Barrow on Blackhill Clump 470 metres northe/ STRY NUMBER; 1015897 ECONDITION: Scheduled Monument UST ENTRY NUMBER; 1015899 CONTRACT:	CONDITION:	Extensive significant problems	TREND:	Declining
STREMARE Two bell barrows and a bolt barrow, 200 metres Set extensive significant problems Instruments	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DesiGNATION: Scheduled Monument INIT ENTRY NUMBER: [015332] CONDITION: Extensive significant problems TRIND: Declining RERICEAL VULNERABILITY: Arable ploughing NEW ENTRY: No CONDITION: Private CONDITION: Daniel Bashford 07824 103102 STEE NAME: Two bowl barrows on South Heath, 900 metres SSE of The Bungalow. Beer Regis DESIGNATION: Scheduled Monument IDT ENTRY NUMBER: [017694 CONDITION: Scheduled Monument IDT ENTRY NUMBER: [015899 EDEGGNATION: Scheduled Monument IDT ENTRY NUMBER: [015899 EDEGGNATION: Scheduled Monument IDT ENTRY NUMBER: [015899 EDEGGNATION: Scheduled Monument IDT ENTRY NUMBER: [015897 EDEGGNATION: Scheduled Monument IDT ENTRY NUMBER: [015897	OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
CONDITION: Extensive significant problems TREND: Declining TREND: Declining NEW ENTRY: No OWNER TYPE: Private CONTACT: Daniel Bashford 07824 103102 TITE NAME: Two bowl barrows on South Heath, 900 metres SSE of The Bunglow. Beer Regis DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017694 CONTOR: Generally unsatisfactory with major localised TREND: Declining CONTACT: Scheduled Monument NEW ENTRY: No CONTACT: Daniel Bashford 07824 103102 Scheduled Monument NEW ENTRY: No STREND: Commercial company CONTACT: Daniel Bashford 07824 103102 STREND: Scheduled Monument LIST ENTRY NUMBER: 1015899 CONTITON: Generally unsatisfactory with major localised TREND: Declining CONTITON: Generally unsatisfactory with major localised TREND: Declining CONTITON: Forestry NEW ENTRY: No CONTITON: Generally unsatisfactory with major localised TREND: Dec	SITE NAME:	Two bell barrows and a bowl barrow, 200 metro	es north east of Hayw	vards Farm, Bere Regis
REINCIPAL VOLINERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Private CONTACT: Daniel Bashford 07824 103102 SITE NAME: Two bowl barrows on South Heath, 900 metres SSE of The Bungalow. Bere Regis Declining DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017694 CONTACT: Declining Declining REINCRAL VOLINERABILITY: Scrub / tree growth NEW ENTRY: No OWNER TYPE: Commercial company CONTACT: Daniel Bashford 07824 103102 SITE NAME: Bell barrow on Blackhill Clump 470 metres north of Mintern's Ferry. Bere Regis / Affpuddle and Turnerspuddle CONTACT: Daniel Bashford 07824 103102 SITE NAME: Scheduled Monument LIST ENTRY NUMBER: 1015899 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015899 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: No CONTACT: Daniel Bashford 07824 103102 NEW ENTRY: No OWNER TYPE: Frivate, multiple owners CONTACT: Daniel Bashford 07824 103102 STEE NAME: Generally unsat	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015332
DYNER TYPEPrivateCONTACT:Daniel Bashford 07824 103102BERGRATION:KNo book barrows on South Heath, 900 meters SUF The BungawI (17694DEBIGRATION:Scheduled MonumentINTENTIVI NUMBERI (17694CONDITION:Generally unsatisfactory with major localisedREND:DecliningRENDER TYPE:Scrub / tree growthKEW ENTRY:NoOWNER TYPE:Commercial companyCONTACT:Daniel Bashford 07824 103102DESIGNATION:Scheduled MonumentINTENTIVI NUMBERI (15899DESIGNATION:Scheduled MonumentINTENTIVI NUMBERI (15899CONDITION:Generally unsatisfactory with major localisedINENO:Daniel Bashford 07824 103102CONDITION:Generally unsatisfactory with major localisedINENO:DecliningCONDITION:Generally unsatisfactory with major localisedINENO:Daniel Bashford 07824 103102CONDITION:ForestryNoDaniel Bashford 07824 103102CONDITION:Scheduled MonumentINTENTIONENoCONDITION:Scheduled MonumentINTENTIONENoCONDITION:ForestryNoDaniel Bashford 07824 103102CONDITION:Private, multiple ownersNoDaniel Bashford 07824 103102 <td>CONDITION:</td> <td>Extensive significant problems</td> <td>TREND:</td> <td>Declining</td>	CONDITION:	Extensive significant problems	TREND:	Declining
STRE NAME: Two book barrows on South Heath, 900 metres SSE of The Bungalow, Bere Regis STRE NAME: Two book barrows on South Heath, 900 metres SSE of The Bungalow, Bere Regis DESIGNATION: Scheduled Monument UST ENTRY NUMBER 1017694 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining RRINCIPAL VULNERABUTY: Scrub / tree growth NEW ENTRY: No OWNER TYPE: Commercial company CONTACT: Daniel Bashford 07824 103102 STRE NAME: Bell barrow on Blackhill Clump 470 metres north of Vintern's Ferry. Eregis / Affpuddle and Turnerspuddle DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1015899 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining CONTACT: Daniel Bashford 07824 103102 Stres NAME: No CONTACT: Private, multiple owners CONTACT: No DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1015897 Stres NAME: Frestry No No CONDITION: Generally unsatisfactory with major localised problems INER ND: Declining DESIGNATION:	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Designation: Scheduled Monument LIST ENTRY NUMBER: 1017694 CCONDITION: Generally unsatisfactory with major localised problems TREND: Declining RRINCIPAL VOLUERABILITY: Scrub/tree growth New ENTRY: No OWNER TYPE: Commercial company CONTACT: Daniel Bashford 07824 103102 SITE NAME: Bell barrow on Blackhill Clump 470 metres north of Hinterr's Ferry. Ber Regis / Affpuddle and Turnerspuddle INSTENTRY NUMBER: 1015899 DESIGNATION: Scheduled Monument INSTENTRY NUMBER: 1015899 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining RRINCIPAL VOLUERABILITY: Forestry New ENTRY: No OWNER TYPE: Private, multiple owners CONTACT: Daniel Bashford 07824 103102 SITE NAME: Generally unsatisfactory with major localised problems TREND: No OWNER TYPE: Private, multiple owners CONTACT: Daniel Bashford 07824 103102 SITE NAME: Scheduled Monument INST ENTRY NUMBER: 1015897 CONDITION: Generally unsatisfactory with major localised problems	OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningRRINCIPAL VULNERABILITY:Scrub / tree growthNEW ENTRY:NoOWNER TYPE:Commercial companyCONTACT:Daniel Bashford 07824 103102STE NAME:Bell barrow on Blackhill Clump 470 metres north of Untern's Ferry: UrnerspuddleScheduled MonumentUST ENTRY NUMBERDESIGNATION:Scheduled MonumentUST ENTRY NUMBER1015899CONTACT:Generally unsatisfactory with major localised problemsTREND:DecliningRRINCIPAL VULNERABILITY:ForestryNEW ENTRY:NoOWNER TYPE:Group of six bowl barrows, forming a round barrow: urnerspuddleCONTACT:Daniel Bashford 07824 103102STE NAME:Generally unsatisfactory with major localised problemsTREND:DecliningBERIGNATION:Scheduled MonumentUST ENTRY NUMBER:1015897CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningCONDITION:Generally unsatisfactory with major localised problemsTREND:NoCONDITION:Private, multiple ownersCONTACT:Daniel Bashford 07824 103102CONDITION:Private, multiple ownersCONTACT:Daniel Bashford 07824 103102CONDITION:Private, multiple ownersCONTACT:Daniel Bashford 07824 103102CONDITION:Private, multiple ownersCONTACT:Daniel Bashford 07824 103102CONTACT:Private, multiple ownersCONTACT:Daniel Bashford 07824 103102S	SITE NAME:	Two bowl barrows on South Heath, 900 metres	SSE of The Bungalow	v, Bere Regis
Concention:problemisIndextDecliningRRINCIPAL VULNERABILITY:Scrub/tree growthNoOWNER TYPE:Commercial companyCONTACT:Daniel Bashford 07824 103102STE NAME:Bell barrow on Blackhill Clump 470 metres north of Mintern's Ferry.Ere Regis / Affpuddle andSTE NAME:Scheduled MonumentLIST ENTRY NUMBER:1015899Decliningrenormality unsatisfactory with major localised problemsTREND:DecliningCONTACT:ForestryNoNoOWNER TYPE:Private, multiple ownersCONTACT:Daniel Bashford 07824 103102STE NAME:Group of six bowl barrows, forming a round barrow cemetery on BlackHill, Bere Regis / Affpuddle and UTT merspuddleDEGIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1015897DEGIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1015897DEGIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1015897CONDITION:Private, multiple ownersCONTACT:Daniel Bashford 07824 103102CONDITION:Scheduled MonumentLIST ENTRY NUMBER:1015897DEGIGNATION:Scheduled MonumentNoNoCONDITION:Private, multiple ownersCONTACT:Daniel Bashford 07824 103102STE NAME:Two bowl barrows both 350 metres north east of Spring Garden BarryNoOWNER TYPE:VinwerspuddleUST ENTRY NUMBER:1015898STE NAME:Scheduled MonumentLIST ENTRY NUMBER:1015898STE NAME:Wo bowl barrows both 350 m	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017694
CONTACT: Daniel Bashford 07824 103102 CONTACT: Daniel Bashford 07824 103102 SITE NAME: Bell barrow on Blackhill Clump 470 metres north of Mintern's Ferry, Bere Regis / Affpuddle and Turnerspuddle Designation: Scheduled Monument LIST ENTRY NUMBER: 1015899 Designation: Scheduled Monument LIST ENTRY NUMBER: 1015899 CONTACT: Declining Declining Problems NEW ENTRY: No DOWNER TYPE: Forestry New ENTRY: No DOWNER TYPE: Forologing of six bowl barrows, forming a round barrow cemetery on Black Hill, Bere Regis / Affpuddle and Turnerspuddle DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015897 CONTACT: Daniel Bashford 07824 103102 Stre NAME: 1015897 CONTACT: Scheduled Monument LIST ENTRY NUMBER: 1015897 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining Private, multiple owners CONTACT: Daniel Bashford 07824 103102 Stre NAME: Turnerspuddle Turnerspuddle Scheduled Monument UST ENTRY NUMBER: You Sowl barrows both 350 metres north east of Stree	CONDITION:		TREND:	Declining
SITE NAME: Bell barrow on Blackhill Clump 470 metres north of Mintern's Ferry, Bere Regis / Affpuddle and Turnerspuddle Designation: Scheduled Monument ust ENTRY NUMBER 1015899 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining PRINCIPAL VULNERABILITY: Forestry New ENTRY: No DOWNER TYPE: Private, multiple owners CONTACT: Daniel Bashford 07824 103102 STE NAME: Group of six bowl barrows, forming a round barrow cemetery on Black Hill, Bere Regis / Affpuddle and Turnerspuddle Internerspuddle DESIGNATION: Scheduled Monument Ust ENTRY NUMBER: 1015897 CONDITION: Generally unsatisfactory with major localised 	PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
Internet Turnerspuddle LIST ENTRY NUMBER: Io15899 DESIGNATION: Generally unsatisfactory with major localised problems TREND: Declining RRINCIPAL VULNERABILITY: Forestry NEW ENTRY: No OWNER TYPE: Private, multiple owners CONTACT: Daniel Bashford 07824 103102 SITE NAME: Group of six bowl barrows, forming a round barrow cemetery on Black Just ENTRY NUMBER: 1015897 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015897 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1015897 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining RRINCIPAL VULNERABILITY: Plant growth NeW ENTRY: No SITE NAME: Two bowl barrows both 350 metres north east of Spring Garden Barry Bere Regis / Affpuddle and Turnerspuddle UST ENTRY NUMBER: 1015898 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015898 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015898 DESIGNATION: <td< td=""><td>OWNER TYPE:</td><td>Commercial company</td><td>CONTACT:</td><td>Daniel Bashford 07824 103102</td></td<>	OWNER TYPE:	Commercial company	CONTACT:	Daniel Bashford 07824 103102
CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningRINCIPAL VULNERABILITY:ForestryNew ENTRY?NoOWNER TYPE:Private, multiple ownersCONTACT:Daniel Bashford 07824 103102SITE NAME:Group of six bowl barrows, forming a round barrowCONTACT:Daniel Bashford 07824 103102DESIGNATION:Scheduled MonumentUST ENTRY NUMBER:1015897CONDITION:Scheduled MonumentNEW ENTRY?NoCONDITION:Private, multiple ownersCONTACT:DecliningCONDITION:Plant growthNEW ENTRY?NoOWNER TYPE:Plant growthCONTACT:Daniel Bashford 07824 103102SITE NAME:Two bowl barrows both 350 metres north east of SPIIng Garden BarrSere Regis / Affpuddle andDESIGNATION:Scheduled MonumentUST ENTRY NUMBER:Io15898CONDITION:Scheduled MonumentUST ENTRY NUMBER:1015898DESIGNATION:Scheduled MonumentUST ENTRY NUMBER:Io15898CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningCONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningCONDITION:Generally unsatisfactory with major localised problemsNew ENTRY?NoCONDITION:Plant growthNew ENTRY?No	SITE NAME:		h of Mintern's Ferry, I	Bere Regis / Affpuddle and
problemsnetworkDecliningPRINCIPAL VULNERABILITY:ForestryNew ENTRY:NoOWNER TYPE:Private, multiple ownersCONTACT:Daniel Bashford 07824 103 102SITE NAME:Group of six bowl barrows, forming a round barrow cemetery on BlackHill, Bere Regis / Affpuddle and TurnerspuddleDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1015897CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningCONTACT:Plant growthNew ENTRY:NoOWNER TYPE:Private, multiple ownersCONTACT:Daniel Bashford 07824 103 102SITE NAME:Two bowl barrows both 350 metres north east of SPTING Garden Barry.Besign ATION:SITE NAME:Two bowl barrows both 350 metres north east of SPTING Garden Barry.Bere Regis / Affpuddle and TurnerspuddleSITE NAME:Two bowl barrows both 350 metres north east of SPTING Garden Barry.Bere Regis / Affpuddle and TurnerspuddleSITE NAME:Generally unsatisfactory with major localised problemsINSTENT NUMBER:1015898CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningCONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningCONDITION:Generally unsatisfactory with major localised problemsNew ENTRY?NoCONDITION:Plant growthNEW ENTRY?No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015899
DWINER TYPE: Private, multiple owners CONTACT: Daniel Bashford 07824 103102 SITE NAME: Group of six bowl barrows, forming a round barrow cemetery on Black Hill, Bere Regis / Affpuddle and Turnerspuddle DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015897 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No SITE NAME: Two bowl barrows both 350 metres north east of Spring Garden Barr. Bere Regis / Affpuddle and Unstrement Scheduled Monument SITE NAME: Two bowl barrows both 350 metres north east of Spring Garden Barr. Bere Regis / Affpuddle and Unstrement Scheduled Monument SITE NAME: Generally unsatisfactory with major localised problems INEW ENTRY NUMBER: 1015898 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015898 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining CONDITION: Generally unsatisfactory with major localised problems TREND: Declining CONDITION: Generally unsatisfactory with major localised problems TREND: Declining	CONDITION:		TREND:	Declining
SITE NAME: Group of six bowl barrows, forming a round barrow cemetery on Black Hill, Bere Regis / Affpuddle and furnerspuddle DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015897 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No OWNER TYPE: Private, multiple owners CONTACT: Daniel Bashford 07824 103102 SITE NAME: Two bowl barrows both 350 metres north east of Suring Garden Barry Bere Regis / Affpuddle and furnerspuddle ISTE NAME: IO15898 SITE NAME: Generally unsatisfactory with major localised problems ISTE ONTACT: Daniel Bashford 07824 103102 SITE NAME: Two bowl barrows both 350 metres north east of Suring Garden Barry Bere Regis / Affpuddle and furnerspuddle ISTE INTRY NUMBER: IO15898 CONDITION: Scheduled Monument LIST ENTRY NUMBER: IO15898 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining CONDITION: Plant growth NEW ENTRY: No	PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY ?:	No
And FunderTurnerspuddleList entry number:1015897DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1015897CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Plant growthNEW ENTRY?:NoOWNER TYPE:Private, multiple ownersCONTACT:Daniel Bashford 07824 103102SITE NAME:Two bowl barrows both 350 metres north east of Spring Garden BarrBere Regis / Affpuddle andDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1015898CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningCONDITION:Plant growthNew ENTRY?No	OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102
CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Plant growthNEW ENTRY?:NoOWNER TYPE:Private, multiple ownersCONTACT:Daniel Bashford 07824 103 102SITE NAME:Two boody barrows both 350 metres north east of SurgendanceSere Regis / Affpuddle and UnrerspuddleDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1015898CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningRINCIPAL VULNERABILITY:Plant growthNEW ENTRY?:No	SITE NAME:		row cemetery on Bla	ck Hill, Bere Regis / Affpuddle and
problems problems Private Private Private New ENTRY? No OWNER TYPE: Private, multiple owners CONTACT: Daniel Bashford 07824 103102 SITE NAME: Two bowl barrows both 350 metres north east of Spring Garden Barn, Bere Regis / Affpuddle and DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1015898 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015897
OWNER TYPE:Private, multiple ownersCONTACT:Daniel Bashford 07824 103102SITE NAME:Two bowl barrows both 350 metres north east of Spring Garden Barn, Bere Regis / Affpuddle and TurnerspuddleDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1015898CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Plant growthNEW ENTRY?No	CONDITION:		TREND:	Declining
SITE NAME: Two bowl barrows both 350 metres north east of Spring Garden Barn, Bere Regis / Affpuddle and Turnerspuddle DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015898 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY ?:	No
Instruction Turnerspuddle DESIGNATION: Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth	OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102
CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Plant growthNEW ENTRY?:No	SITE NAME:		of Spring Garden Barı	n, Bere Regis / Affpuddle and
problems Including PRINCIPAL VULNERABILITY: Plant growth	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015898
PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No	CONDITION:		TREND:	Declining
OWNER TYPE: Private, multiple owners CONTACT: Daniel Bashford 07824 103102	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY ?:	No
	OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Bowl barrow 120 metres south of the southern ex Whitechurch	tent of Horse Clos	se Plantation, Bere Regis / Winterborn
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015387
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	St Leonard's Chapel, Blandford Forum		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1002726
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY ?:	No
OWNER TYPE:	Local authority	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Roman villa south east of East Farm, Bradford Abb	as	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002414
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Educational (independent)	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bell barrow in Highfield Plantation and two bowl b Bradford Peverell	arrows immediatel	y north west of Forty Acre Plantation
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019415
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bowl barrow 380 metres west of Whitfield Farm, Bradford Peverell		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019639
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Group of barrows in Seven Barrow Plantation, Bra	dford Peverell	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002812
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Long barrow and four bowl barrows 500 metres n	orth west of Whit	field Farm, Bradford Peverell
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019416
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Discontinuous surviving sections of Roman aquedu	ct, Bradford Pevere	ell / Dorchester
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1002730
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Culliford Tree long barrow and group of round bar	rrows, Broadmayne	e / Whitcombe
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003304
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Oval barrow and three bowl barrows 250 metres a Whitcombe	and 330 metres sou	ith of Whitcombe Barn, Broadmayne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019414
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
ITE NAME:	Field system in Old Park, Bryanston		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1002427
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Crown	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Two bowl barrows on Lord's Down 580 metres so	outh east of Crawth	orne Farm, Burleston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017277
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	The Castle hillfort, Cattistock		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004545
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Round barrow on Dickley Hill, Cerne Abbas		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002849
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable
	problems		
	Arable ploughing	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY: OWNER TYPE:		NEW ENTRY?: CONTACT:	No Daniel Bashford 07824 103102

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Settlement on Dickley Hill, Cerne Abbas		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002852
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bowl barrow 470 metres south east of Down Ba Herring	arn: an outlier of the (Chaldon Down barrow group, Chaldo
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008146
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bowl barrow 650 metres south of Chaldon Dow cemetery, Chaldon Herring	n Buildings: part of th	ne Chaldon Down round barrow
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008523
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	The Round Pound, an enclosure on Chaldon Do	wn, Chaldon Herring	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018436
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Two bowl barrows 200 metres south east of Hi	l Barn: two of a grou	o of three barrows, Chaldon Herring
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008162
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Wardstone Barrow: a bowl barrow on the Dors Chaldon Herring	et coastal ridge 300 r	netres south of Chideock Farm,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008676
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bowl barrow 350 metres south of Gorcombe Fa	rm, Charlton Marsha	II
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014848
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Bowl barrow 500 metres south west of Gorcon	nbe Farm, Charlton M	arshall
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014847
CONDITION:	Extensive significant problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bowl barrow 650 metres south west of Gorcon	nbe Farm, Charlton M	arshall
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014849
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
TE NAME:	Bowl barrow 1020 metres south east of Charisv	vorth Cottages, Charl	ton Marshall
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014846
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bowl barrow on Wood Hill 310 metres north e	ast of Cowden, Charn	ninster
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019395
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
ITE NAME:	Round barrow east of Forston Farm, Charminst	er	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002851
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Round barrow on Cheselbourne West Down, C	Cheselbourne	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002878
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
ITE NAME:	Earthwork and ancient fields south east of Lysco	ombe Bottom, Cheselt	oourne / Melcombe Horsey
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002456
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
ITE NAME:	Long barrow 360 metres SSW of Chettle House	e, Chettle	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013792
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
RIORITY CATEGORIES Immediate risk of further rapid deterioration or loss of fabric; solution agreed. Immediate risk of further rapid	no not yet implemented. (where applicable) end E Under repair or in fair to good user identified; or functi	use or Last year's prio onally shown in brack	ABBREVIATIONS CA Conservation Area ority category is LB Listed Building kets (otherwise, LPA Local Planning Authori toted). NP National Park

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

redundant buildings with new use agreed but not yet implemented.

- LPA
 Local Planning Authority

 NP
 National Park

 RPG
 Registered Park and Garden

 SM
 Scheduled Monument

 UA
 Unitary Authority

 WHS
 World Heritage Site

SHERMARE Bow barrow on Creech Barrow Hill, Church Knowle / Steeple with Tyneham SERGEMENTION: Scheduled Monument, CA LET ENTERY NUMBER 1014830 CONDITION Generally unsatifactory with major localised problems TREND Declining RENCIPAL VILLINERMAILTY Plant growth Nove MTXY Daniel Bashford 07824 103 SITE NAME: Bow barrow 360 metres south of Compton Barn, Compton Valence Declining SERGEMENTION: Scheduled Monument LET ENTER NUMBER 1019741 CONNERTITE: Arable ploughing No Declining RENCERTION: Scheduled Monument LET ENTER NUMBER 103234 CONNERTITE: Settlement south east of Soaper's Hill Plantation, Compton Valence Declining DESCANTON: Scheduled Monument LIST ENTER NUMBER 103234 CONNERTITE: Settlement south east of Soaper's Hill Plantation, Compton Valence No DESCANTON: Scheduled Monument, problems 1603244 10334 Sontellone Steeploughing No No 101479 Sontellone Steeploughing No No 101479 S						
CONDITION:Extensive significant problemsTIEND:DecliningERRECAL VULKERABUTY:Arable ploughingNew ENTRY:NoCONDITION:Miked, multiple ownersCONDITION:Daniel Bashford 07824 103Satte NATC:Bow barrow on Creech Barrow Hill, Church Know-V-/ Steeple with T-whan014830CONDITION:Scheduled Monument, CALIST ENTRY/MERRE1014830CONDITION:Scheduled Monument, CALIST ENTRY/MERREDaniel Bashford 07824 103STENAME:Commercial companyCONTACT:Daniel Bashford 07824 103STENAME:Bow barrow 360 metres south of Compton ValenceDaniel Bashford 07824 103STENAME:Bow barrow 360 metres south of Compton ValenceDaniel Bashford 07824 103STENAME:Scheduled MonumentLIST ENTRY/MERREID19741CONTROM:Extensive significant problemsTEND:Daniel Bashford 07824 103STENAME:Scheduled MonumentLIST ENTRY/MERREID03234CONTROM:Extensive significant problemsLIST ENTRY/MERREID03234CONTROM:Scheduled MonumentLIST ENTRY/MERREID03241CONTROM:Extensive significant problemsLIST ENTRY/MERREID03244CONTROM:Scheduled Monument, part in CALIST ENTRY/MERREID11479CONTROM:Extensive significant problemsLIST ENTRY/MERREID1479CONTROM:Extensive significant problemsLIST ENTRY/MERREID1479CONTROM:Extensive significant problemsLIST ENTRY/MERREID1479CONTROM:Extens	SITE NAME:	Causewayed camp on Hambledon Hill, Child Ok	eford / Hanford / Iwe	erne Courtney or Shroton		
RENAULYLUNERAULTY: Arable ploughing NOVERTY:: No DOWNER TYPE: Mixed, multiple owners CONTACT: Daniel Bashford 07824 103 Stream ALL Bowl barrow on Creech Barrow Hill, Church Knowle / Steeple with Tymeham Iol (430) DEGRATION: Scheduled Monument, CA Lat ENTRY NUMBER: Iol (430) CONTRET: Problems Iol (430) Declining RENAURAL VOLKERAUTY: Plant growth New Duttor: No CONTRET: Commercial company Controct: Daniel Bashford 07824 103 Stream Autor Scheduled Monument Lat ENTRY NUMBER: Iol (1974) CONTRET: Controct: Declining CONTRET: Private Controct: Declining CONTRET: Private Controct: Daniel Bashford 07824 103 Stream Autor Scheduled Monument Lat ENTRY NUMBER: Iol (2072) CONTRET: Private Contract: Daniel Bashford 07824 103 Stream Autor Scheduled Monument Lat ENTRY NUMBER: Iol (2072) CONTRET: Private Contrac	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002767		
DWNER TIPS:Mixed, multiple ownersCONTACT:Daniel Bashford 07824 103BILE NAME:Bowl barrow on Creech Barrow Hill, Church Knowley / Steeple with Tymen1014930DESIGNATION:Scheduled Monument, CABTE DATT:DecliningDecliningTIRE Do:DecliningDecliningDOWNER TIPE:Commercial companyCONTACT:Daniel Bashford 07824 103STE NAME:Bowl barrow 360 metres south of Compton Barr.ControlDaniel Bashford 07824 103STE NAME:Bowl barrow 360 metres south of Compton Barr.DecliningDEGRATION:Extensive significant problemsTIRE Do:DecliningDEGRATION:Extensive significant problemsTIRE DO:Daniel Bashford 07824 103STE NAME:Settlement south east of Soaper's Hill Plantation.Daniel Bashford 07824 103STE NAME:Settlement south east of Soaper's Hill Plantation.DecliningCONTACT:PrivatePrivateDaniel Bashford 07824 103STE NAME:Settlement south east of Soaper's Hill Plantation.DecliningCONTACT:Private, multiple ownersCONTACT:Daniel Bashford 07824 103STE NAME:Settlement south east of Soaper's Hill Plantation.DecliningCONTACT:Private, multiple ownersCONTACT:Daniel Bashford 07824 103STE NAME:Settlement south east of Soaper's Hill Plantation.DecliningCONTACT:Private, multiple ownersCONTACT:Daniel Bashford 07824 103STE NAME:Settled Monument;CONTACT:Daniel Bashford 07824 103 <td< td=""><td>CONDITION:</td><td>Extensive significant problems</td><td>TREND:</td><td>Declining</td></td<>	CONDITION:	Extensive significant problems	TREND:	Declining		
Bowl barrow on Creech Barrow Hill, Church Knowl / Steeple with Tyneham DEBIGNATION: Scheduled Monument, CA LET INTRY NUMBER [01430 CONDITION: Generally unsatisfactory with major localised problems ReNO Declining WIRKORL VULNEARUUTY Plant growth No Declining CONDITION: Contract: Daniel Bashford 07824 103 Daniel Bashford 07824 103 STETNAME: Bowl barrow 360 metres south of Compton Barr. Contract: Daniel Bashford 07824 103 STETNAME: Scheduled Monument LIST ENTRY NUMBER: [01711 CONTRACT: Daniel Bashford 07824 103 Declining STETNAME: Scheduled Monument LIST ENTRY NUMBER: [00324 CONTRACT: Scheduled Monument, problems TENO: No CONTRACT: Scheduled Monument, problems TENO: No CONTRACT: Contra	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
Desknamment, CA List ENTRY NUMBER 1014830 CONDITION: Generally unsatisfactory with major localised problems Intervo: Declining RENCENT, VULNERABUTY: Plant growth NEW ENTRY: No OWNER TYPE: Commercial company CONTACT: Daniel Bashford 07824 103 STET NAME: Bowl barrow 360 metres south of Compton Barn, Compton Valence Entry Declining PERSIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1019741 CONNERTTYPE: Private CONTACT: Daniel Bashford 07824 103 STET NAME: Settlement south east of Soaper's Hill Plantation, Compton Valence Daniel Bashford 07824 103 STET NAME: Settlement south east of Soaper's Hill Plantation, Compton Valence Declining DEGONATION: Scheduled Monument, ITENS: Declining RENCARDIN: Arable ploughing NEW ENTRY: No CONTACT: Daniel Bashford 07824 103 Stensive significant problems ITENS: Settement south east of Soaper's Hill Plantation, Compton No Daniel Bashford 07824 103 Stensone Bignificant problems ITENS:	OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102		
Conduction Generally unsatisfactory with major localised problems INEND: Declining PRINCIPAL VULNERWAUTY: Plant growth NEW BATRY: No CONTRET TYPE: Commercial company CONTRET: Datal Bashford 07824 103 STEENAME: Bowl barrow 360 metres south of Compton Barr, Contret: Declining BERIGRATION: Scheduled Monument INTERNIX WERR: 1019741 DEGINATION: Extensive significant problems TRAND: Declining REINCHER TYPE: Private CONTRET: Daniel Bashford 07824 103 STEENAME: Settement south east of Scaper's Hill Plantation, Contret: Daniel Bashford 07824 103 STEENAME: Scheduled Monument UST ENTRY NUMERS: 1003234 CONTION: Extensive significant problems TRAND: Declining RENAME: Private, multiple owners Contret: Daniel Bashford 07824 103 STEENAME: Charling: a ringwork and balley and a Civil War WIRK: No Daniel Bashford 07824 103 STEENAME: Charling: a ringwork and balley and a Civil War WIRK: No Daniel Bashford 07824 103 STEENAME:	SITE NAME:	Bowl barrow on Creech Barrow Hill, Church Ki	nowle / Steeple with 7	Гупеham		
Concention problems Prime of the the second	DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1014830		
CONTRETTIP: Connenctal company CONTRET: Daniel Bashford 07824 103 DESCRATION: Scheduled Monument LOT ENTRY NUMBER 1019741 CONTROM Extensive significant problems TREND: Declining CONTROM Fixensive significant problems TREND: Daniel Bashford 07824 103 CONTROM Fixensive significant problems TREND: Daniel Bashford 07824 103 STENAME Settlement south east of Soaper's Hill Plantation, Contract: Daniel Bashford 07824 103 STENAME Settlement south east of Soaper's Hill Plantation, Contract: No CONTROM Extensive significant problems TREND: Doalel Bashford 07824 103 STENAME Scheduled Monument LDT ENTRY NUMBER 1003234 CONTROM Extensive significant problems TREND: Declining STENAME Private, multiple owners CONTACT: Daniel Bashford 07824 103 STENAME Scheduled Monument, part in CA LDT ENTRY NUMBER ID11479 CONTROM Extensive significant problems TREND: Declining STENAME Scheduled Monument, part in CA LDT ENTRY NUMBER ID11479 CONTROM Extensive significant problems TREND: Declining STENAME Scheduled Monument LDT ENTRY NUMER	CONDITION:		TREND:	Declining		
STRE NAME Bowl barrow 360 metres south of Compton Barn, Compton Valence DERIGNATION Scheduled Monument ILBT ENTRY NUMBER: 1019741 CONDITION: Extensive significant problems TREND: Declining REBULATION: Arable ploughing New ENTRY: No OWNER TYPE Private CONTACT: Daniel Bashford 07824 103 STEE NAME Settlement south east of Soaper's Hill Plantation, Compton Valence Declining DERIGNATION: Scheduled Monument UIST ENTRY NUMBER: 1003234 CONDITION: Extensive significant problems TREND: Declining OWNER TYPE: Private, multiple owners CONTACT: Daniel Bashford 07824 103 STEE NAME: The Rings: a ringwork and bailey and a Civil War battery 400 metres south west of Corfe Castle, CCONTACT: Daniel Bashford 07824 103 STEE NAME: The Rings: a ringwork and bailey and a Civil War battery 400 metres No CONTACT: Daniel Bashford 07824 103 Controct: Daniel Bashford 07824 103 STEE NAME: Scheduled Monument, part in CA LIST ENTRY NUMBER: 1011479 CONTRITION: Extensive significan	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
DEBIGNATION: Scheduled Monument LBT ENTRY NUMBER: [01974] CONDITION: Extensive significant problems TREND: Declining RRENDERAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Private CONTACT: Daniel Bashford 07824 103 SITE NAME: Settlement south east of Soaper's Hill Plantation, Compton Valence Declining DEBIGNATION: Scheduled Monument LBT ENTRY NUMBER: 1003234 CONDITION: Extensive significant problems TREND: Declining RRINCHAR VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Private, multiple owners CONTACT: Daniel Bashford 07824 103 SITE NAME: Scheduled Monument, part in CA LBT ENTRY NUMBER: 1011479 CONDITION: Extensive significant problems TREND: Declining CONDITION: Scheduled Monument, part in CA LBT ENTRY: No CONDITION: Extensive significant problems TREND: Declining CONDITION: Scheduled Monument LBT ENTRY NUMBER: 1011479<	OWNER TYPE:	Commercial company	CONTACT:	Daniel Bashford 07824 103102		
CONDITION:Extensive significant problemsTREND:DecliningRRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY:NoOWNER TYPE:PrivateCONTACT:Daniel Bashford 07824 103STETNAME:Settlement south east of Soaper's Hill Plantation.USTENTRY NUMBER:1003234DEBIGNANTON:Scheduled MonumentUSTENTRY NUMBER:1003234CONTACT:DecliningTREND:DecliningCONTACT:Arable ploughingNEW ENTRY:NoOWNER TYPE:Private, multiple ownersCONTACT:Daniel Bashford 07824 103ORISINATION:Scheduled Monument, part in CAUST ENTRY NUMBER:1011479ODISIGNATION:Scheduled Monument, part in CAUST ENTRY NUMBER:1011479CONTON:Extensive significant problemsTREND:DecliningRINKIRA:Charity (heritage)NEW ENTRY:NoODISIGNATION:Scheduled Monument, part in CAUST ENTRY NUMBER:1011479CONDITION:Extensive significant problemsTREND:Daniel Bashford 07824 103STETNAME:Bowl barrow 250 metres north west of Veiny CheeseDecliningCONDITION:Extensive significant problemsINEW ENTRY:NoDESIGNATION:Scheduled MonumentUST ENTRY NUMBER:1015191DESIGNATION:Scheduled MonumentUST ENTRY NUMBER:1015191CONDITION:Extensive significant problemsTREND:DecliningRINKIRKA: VULNERABILITY:Arable ploughingNEW ENTRY:NoCONDITION: <td>SITE NAME:</td> <td>Bowl barrow 360 metres south of Compton Bar</td> <td>rn, Compton Valence</td> <td></td>	SITE NAME:	Bowl barrow 360 metres south of Compton Bar	rn, Compton Valence			
REINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Private CONTACT: Daniel Bashford 07824 103 STEE NAME: Settlement south east of Soaper's Hill Plantation, Compton Valence Designation: Scheduled Monument UST ENTRY NUMBER: 1003234 CONTION: Scheduled Monument UST ENTRY NUMBER: 1003234 CONTION: Extensive significant problems TREND: Declining REINCIPAL VULNERABILITY: Arable ploughing New ENTRY: No OWNER TYPE: Private, multiple owners CONTACT: Daniel Bashford 07824 103 SITE NAME: The Rings: a ringwork and bailey and a Civil War battery 400 metres south west of Corfe Castle, Castle Scheduled Monument, part in CA LIST ENTRY NUMBER: 1011479 CONDITION: Extensive significant problems TREND: Declining CONDITION: Extensive significant problems TREND: Daniel Bashford 07824 103 STEE NAME: Bowl barrow 250 metres north west of Veiny Cheese Fond, Crichel Declining Designation: Scheduled Monument LIST ENTRY NUMBER: 1015191 CONITACT:	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019741		
OWNER TYPEPrivateCONTACT:Daniel Bashford 07824 103STEE NAMESettlement south east of Soaper's Hill Plantation, Compton ValenceI003234DESIGNATION:Scheduled MonumentUST ENTRY NUMBER:1003234CONDITION:Extensive significant problemsTREND:DecliningRRINCIPAL VULNERABUTY:Arable ploughingNEW ENTRY:NoOWNER TYPE:Private, multiple ownersCONTACT:Daniel Bashford 07824 103STE NAME:The Rings: a ringwork and bailey and a Civil War battery 400 metres but west of Corfe Castle, CastleDecliningEDESIGNATION:Scheduled Monument, part in CALIST ENTRY NUMBER:1011479CONDITION:Extensive significant problemsTREND:DecliningCONDITION:Extensive significant problemsTREND:Daniel Bashford 07824 103STE NAME:Bowl barrow 250 metres north west of Veiny CheeseDond, CrichelDEGIONATION:Scheduled MonumentLIST ENTRY NUMBER:1015191CONDITION:Extensive significant problemsTREND:DecliningSTE NAME:Bowl barrow 250 metres north west of Veiny CheeseDond, CrichelDEGIONATION:Scheduled MonumentLIST ENTRY NUMBER:1015191CONDITION:Extensive significant problemsNEW ENTRY:NoOWNER TYPE:PrivateTwo bowl barrows 165 metres west of Veiny CheeseDecliningSTE NAME:Two bowl barrows 165 metres west of Veiny CheeseDecliningSTE NAME:Scheduled MonumentLIST ENTRY NUMBER:1015785<	CONDITION:	Extensive significant problems	TREND:	Declining		
Strte NAME: Settlement south east of Soaper's Hill Plantation, Comparing March 1003234 DERIGNATION: Scheduled Monument UST ENTRY NUMBER: 1003234 CONDITION: Extensive significant problems TEEND: Declining RRINGIPAL VOLNERABILITY: Arable ploughing NeW ENTRY: No OWNER TYPE: Private, multiple owners CONTACT: Daniel Bashford 07824 103 STEE NAME: Castle Control Daniel Bashford 07824 103 OGINTON: Scheduled Monument, part in CA UST ENTRY NUMBER: 1011479 DERIGNATION: Scheduled Monument, part in CA UST ENTRY NUMBER: 1011479 CONDITION: Extensive significant problems TEEND: Declining OWNER TYPE: Charity (heritage) CONTACT: No OWNER TYPE: Bowl barrow 250 metres north west of Veiny Cheese Pond, Crichel Declining DERIGNATION: Scheduled Monument UST ENTRY NUMBER: 1015191 CONDITION: Extensive significant problems TEEND: Declining STEE NAME: Bowl barrows 165 metres west of Veiny Cheese TORON Decli	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003234 CONDITION: Extensive significant problems TREND: Declining RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Private, multiple owners CONTACT: Daniel Bashford 07824 103 SITE NAME: The Rings: a ringwork and bailey and a Civil War buttery 400 metres south west of Corfe Castle, Castle Declining DESIGNATION: Scheduled Monument, part in CA LIST ENTRY NUMBER: 1011479 CONDITION: Extensive significant problems TREND: Declining CONDITION: Extensive significant problems No Ontract: Daniel Bashford 07824 103 SITE NAME: Bowl barrow 250 metres north west of Veiny Cheese Vernerre: Daniel Bashford 07824 103 SITE NAME: Bowl barrow 250 metres north west of Veiny Cheese Vernerre: Declining CONDITION: Extensive significant problems TREND: Declining CONDITION: Extensive significant problems TREND: Declining CONDITION: Extensive significant problems TREND: Decl	OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102		
CONDITION:Extensive significant problemsTREND:DecliningRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY:NoOWNER TYPE:Private, multiple ownersCONTACT:Daniel Bashford 07824 103SITE NAME:CastleContract:VIDIATORDESIGNATION:Scheduled Monument, part in CAUST ENTRY NUMBER:I011479CONTOTON:Extensive significant problemsTREND:DecliningCONTOTON:Extensive significant problemsNEW ENTRY:NoCONTROT:Charity (heritage)CONTACT:Daniel Bashford 07824 103STE NAME:Bowl barrow 250 metres north west of Veiny CheeseDecliningCONTOTON:Scheduled MonumentLIST ENTRY NUMBER:1015191CONTOTON:Scheduled MonumentUST ENTRY NUMBER:1015191CONTOTON:Scheduled MonumentUST ENTRY NUMBER:1015191CONTOTON:Scheduled MonumentUST ENTRY NUMBER:1015191CONTOTON:PrivateContract:Daniel Bashford 07824 103CONTACT:PrivateContract:New ENTRY:NoCONTACT:PrivateContract:Daniel Bashford 07824 103STE NAME:Two bowl barrows 165 metres west of Veiny CheeseEntryNoCONTACT:PrivateContract:NoCONTACT:Scheduled MonumentUST ENTRY NUMBER:1015785CONTACT:Scheduled MonumentUST ENTRY NUMBER:1015785CONTACT:Scheduled MonumentUST ENTRY NUMBER:1015785C	SITE NAME:	Settlement south east of Soaper's Hill Plantation	Settlement south east of Soaper's Hill Plantation, Compton Valence			
RRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Private, multiple owners CONTACT: Daniel Bashford 07824 103 SITE NAME: The Rings: a ringwork and bailey and a Civil War battery 400 metres south west of Corfe Castle, Castle Designation: Scheduled Monument, part in CA UST ENTRY NUMBER: 1011479 CONDITION: Scheduled Monument, part in CA UST ENTRY NUMBER: 1011479 CONDITION: Extensive significant problems TREND: Declining OWNER TYPE: Charity (heritage) CONTACT: Daniel Bashford 07824 103 SITE NAME: Bowl barrow 250 metres north west of Veiny Cheese Pond, Crichel Declining DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1015191 CONDITION: Extensive significant problems TREND: Declining CONDITION: Scheduled Monument UST ENTRY NUMBER: 1015191 CONDITION: Scheduled Monument UST ENTRY NUMBER: 1015191 CONDITION: Scheduled Monument UST ENTRY NUMBER: No SITE NAME: Two bowl barrows 165 metres west of Veiny Cheese Pond, Crichel </td <td>DESIGNATION:</td> <td>Scheduled Monument</td> <td>LIST ENTRY NUMBER:</td> <td>1003234</td>	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003234		
OWN RER TYPE: Private, multiple owners CONTACT: Daniel Bashford 07824 103 SITE NAME: The Rings: a ringwork and bailey and a Civil War battery 400 metres such west of Corfe Castle, Castle Image: Control Castle <td< td=""><td>CONDITION:</td><td>Extensive significant problems</td><td>TREND:</td><td>Declining</td></td<>	CONDITION:	Extensive significant problems	TREND:	Declining		
SITE NAME: The Rings: a ringwork and bailey and a Civil War battery 400 metres south west of Corfe Castle, Castle DesignATION: Scheduled Monument, part in CA UST ENTRY NUMBER: 1011479 CONDITION: Extensive significant problems TREND: Declining RRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY: No OWNER TYPE: Charity (heritage) CONTACT: Daniel Bashford 07824 103 SITE NAME: Bowl barrow 250 metres north west of Veiny Cheese Pond, Crichel 1015191 CONDITION: Extensive significant problems TREND: Declining CONDITION: Extensive significant problems TREND: Declining CONDITION: Extensive significant problems TREND: Declining CONDITION: Extensive significant problems TREND: No OWNER TYPE: Private CONTACT: Daniel Bashford 07824 103 OWNER TYPE: Private CONTACT: Daniel Bashford 07824 103 SITE NAME: Two bowl barrows 165 metres west of Veiny Cheese FORMICATION: Scheduled Monument UIST ENTRY NUMBER: 1015785 DESIGNATION: Scheduled Monument UIST ENTRY NUMBER:	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
And Model Castle Castle Castle DESIGNATION: Scheduled Monument, part in CA LIST ENTRY NUMBER: 10 1479 CONDITION: Extensive significant problems TREND: Declining CONDITION: Animal burrowing - extensive No No OWNER TYPE: Charity (heritage) CONTACT: Daniel Bashford 07824 103 SITE NAME: Bowl barrow 250 metres north west of Veiny Cheese Pond, Crichel ISTENTRY NUMBER: 1015191 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015191 CONDITION: Extensive significant problems TREND: Declining CONDITION: Extensive significant problems NEW ENTRY: No CONDITION: Private CONTACT: Daniel Bashford 07824 103 OWNER TYPE: Private CONTACT: Daniel Bashford 07824 103 STE NAME: Two bowl barrows 165 metres west of Veiny Cheese Pond, Crichel Declining DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015785 CONDITION: Extensive significant problems TREND: Declining DESIGNATION: Scheduled Monument LIST	OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102		
CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:Animal burrowing - extensiveNEW ENTRY:NoOWNER TYPE:Charity (heritage)CONTACT:Daniel Bashford 07824 103SITE NAME:Bowl barrow 250 metres north west of Veiny CheessFond, CrichelDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1015191CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY:NoOWNER TYPE:Two bowl barrows 165 metres west of Veiny CheessVein Entry:NoSITE NAME:Scheduled MonumentLIST ENTRY NUMBER:1015785DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1015785SITE NAME:Two bowl barrows 165 metres west of Veiny CheessPoliciningSITE NAME:Scheduled MonumentLIST ENTRY NUMBER:1015785DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1015785CONDITION:Arable ploughingNEW ENTRY:NoOWNER TYPE:Scheduled MonumentLIST ENTRY NUMBER:1015785CONDITION:Arable ploughingNEW ENTRY:NoOWNER TYPE:PrivateOontact:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY:NoOWNER TYPE:PrivateCONTACT:Daniel Bashford 07824 103STE NAME:Bowl barrow 450 metres east of Dennet's Bottom ErrorDevision Contact:STE NAME:Bowl barrow 450 metres	SITE NAME:	The Rings: a ringwork and bailey and a Civil War battery 400 metres south west of Corfe Castle, Corfe Castle				
PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY: No OWNER TYPE: Charity (heritage) CONTACT: Daniel Bashford 07824 103 SITE NAME: Bowl barrow 250 metres north west of Veiny Cheese Pond, Crichel Image: Contact: Daniel Bashford 07824 103 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015191 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Private CONTACT: Daniel Bashford 07824 103 SITE NAME: Two bowl barrows 165 metres west of Veiny Cheese Pond, Crichel Daniel Bashford 07824 103 SITE NAME: Two bowl barrows 165 metres west of Veiny Cheese Pond, Crichel Declining DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015785 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No <	DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1011479		
owner type:Charity (heritage)CONTACT:Daniel Bashford 07824 103SITE NAME:Bowl barrow 250 metres north west of Veiny CheeseFond, CrichelDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1015191CONDITION:Extensive significant problemsTREND:DecliningCONTACT:Arable ploughingNEW ENTRY?:NoOWNER TYPE:PrivateCONTACT:Daniel Bashford 07824 103SITE NAME:Two bowl barrows 165 metres west of Veiny CheeseInie Bashford 07824 103SITE NAME:Scheduled MonumentLIST ENTRY NUMBER:1015785DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1015785CONDITION:Extensive significant problemsTREND:DecliningCONDITION:Extensive significant problemsTREND:DecliningCONDITION:Extensive significant problemsNEW ENTRY?:NoPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:NoOWNER TYPE:PrivateCONTACT:Daniel Bashford 07824 103OWNER TYPE:Bowl barrow 450 metres east of Dennet's Bottometry. DewlishDeclining	CONDITION:	Extensive significant problems	TREND:	Declining		
SITE NAME: Bowl barrow 250 metres north west of Veiny Cheese Pond, Crichel DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015191 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Private CONTACT: Daniel Bashford 07824 103 SITE NAME: Two bowl barrows 165 metres west of Veiny Cheese Pond, Crichel DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015785 CONDITION: Extensive significant problems TREND: Declining OWNER TYPE: Private CONTACT: Declining DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015785 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Private CONTACT: Daniel Bashford 07824 103 STE NAME: Bowl barrow 450 metres east of Dennet's Bottom Europeuish Stension 2000	PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No		
DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1015191CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:NoOWNER TYPE:PrivateCONTACT:Daniel Bashford 07824 103SITE NAME:Two bowl barrows 165 metres west of Veiny Cheese Pond, CrichelIo15785DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1015785CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:NoOWNER TYPE:PrivateCONTACT:DecliningOWNER TYPE:PrivateScheduled MonumentScheduled MonumentPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:NoOWNER TYPE:PrivateCONTACT:Daniel Bashford 07824 103STE NAME:Bowl barrow 450 metres east of Dennet's Bottom ExtensionScheduled 07824 103	OWNER TYPE:	Charity (heritage)	CONTACT:	Daniel Bashford 07824 103102		
CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:NoOWNER TYPE:PrivateTwo bowl barrows 165 metres west of Veiny CheeseerDaniel Bashford 07824 103SITE NAME:Two bowl barrows 165 metres west of Veiny CheeseerIST ENTRY NUMBER:1015785DESIGNATION:Scheduled MonumentIST ENTRY NUMBER:1015785CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:NoOWNER TYPE:PrivateBowl barrow 450 metres east of Dennet's Bottom EvertsDaniel Bashford 07824 103	SITE NAME:	Bowl barrow 250 metres north west of Veiny C	heese Pond, Crichel			
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Private CONTACT: Daniel Bashford 07824 103 SITE NAME: Two bowl barrows 165 metres west of Veiny Cheese Pond, Crichel Ist ENTRY NUMBER: 1015785 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015785 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Private CONTACT: Daniel Bashford 07824 103 SITE NAME: Bowl barrow 450 metres east of Dennet's Bottom Barn, Dewlish No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015191		
OWNER TYPE:PrivateCONTACT:Daniel Bashford 07824 103SITE NAME:Two bowl barrows 165 metres west of Veiny CheesePond, CrichelDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1015785CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:NoOWNER TYPE:PrivateCONTACT:Daniel Bashford 07824 103SITE NAME:Bowl barrow 450 metres east of Dennet's Bottom Ery.Furshish	CONDITION:	Extensive significant problems	TREND:	Declining		
SITE NAME: Two bowl barrows 165 metres west of Veiny Cheese Pond, Crichel DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015785 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Private CONTACT: Daniel Bashford 07824 103	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015785 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Private CONTACT: Daniel Bashford 07824 103	OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102		
CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Private CONTACT: Daniel Bashford 07824 103 STEE NAME: Bowl barrow 450 metres east of Dennet's Bottom Barn, Dewlish Vertical Steeles S	SITE NAME:	Two bowl barrows 165 metres west of Veiny C	heese Pond, Crichel			
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Private CONTACT: Daniel Bashford 07824 103 SITE NAME: Bowl barrow 450 metres east of Dennet's Bottom Barn, Dewlish Example 100 metres	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015785		
OWNER TYPE: Private CONTACT: Daniel Bashford 07824 103 SITE NAME: Bowl barrow 450 metres east of Dennet's Bottom Barn, Dewlish	CONDITION:	Extensive significant problems	TREND:	Declining		
SITE NAME: Bowl barrow 450 metres east of Dennet's Bottom Barn, Dewlish	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
	OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102		
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015427	SITE NAME:	Bowl barrow 450 metres east of Dennet's Botto	om Barn, Dewlish			
	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015427		
CONDITION: Extensive significant problems TREND: Declining	CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE: Private CONTACT: Daniel Bashford 07824 103	OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102		

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В

implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Bowl barrow 550 metres WNW of West End E	Barn, Dewlish		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015032	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Daniel Bashford 07824 103102	
SITE NAME:	Three bowl barrows 380 metres west of West	End Barn, Dewlish / M	lilborne St. Andrew	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015031	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102	
ITE NAME:	Enclosure on Mount Pleasant Hill, Dorchester /	West Stafford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002463	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No	
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102	
SITE NAME:	Settlement remains north of Maiden Castle, Dorchester / Winterborne Monkton			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002409	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Daniel Bashford 07824 103102	
SITE NAME:	Earthwork east of Stake Farm, East Chelboroug	h		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002845	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102	
SITE NAME:	Three bowl barrows in Holme Lane Plantation,	200 metres south wes	st of Squirrel's Cottages, East Holme	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016728	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102	
SITE NAME:	Two barrows known as 'Water Barrows' 650 metres WNW of Whiteway Farm: part of a round barrow cemetery to the south east of East Lulworth, East Lulworth			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008144	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY ?:	No	
OWNER TYPE:	Government or agency	CONTACT:	Daniel Bashford 07824 103102	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Flower's Barrow: a small multivallate hillfort and with Tyneham	associated outwork	on Rings Hill, East Lulworth / Steeple
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008141
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bindon Hill camp, East Lulworth / West Lulwort	h	
DESIGNATION:	Scheduled Monument, part in CA, WHS	LIST ENTRY NUMBER:	1002705
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bowl barrow 60 metres north east of Hethfelto	n Farm, East Stoke	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018192
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bowl barrow on Farm Heath, 470 metres south	east of Hill Cottages,	East Stoke
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016272
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bowl barrow on Farm Heath, 480 metres south	east of Hill Cottages,	East Stoke
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016271
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Section of Battery Bank on Binnegar Plain, 830 n	netres north east of S	tokeford Farm, East Stoke
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018189
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Section of Battery Bank on South Heath, East St	oke	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016273
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Two bowl barrows on South Heath, 290 metres ar	nd 370 metres east	of Binnegar Hall, East Stoke
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016276
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Barrows in and near St Giles Park, Edmondsham /	Wimborne St. Gile	s
DESIGNATION:	Scheduled Monument, part in RPG grade II*	LIST ENTRY NUMBER:	1002782
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bell barrow 500 metres north east of Beacon Farm	n, Ferndown Town	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015995
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
DWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
ITE NAME:	Bell barrow known as Belle Vue Barrow and a bow Town	/l barrow 250 metr	es north east of Hillamsland, Ferndow
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015994
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
ITE NAME:	Bowl barrow 250 metres west of Ferndown Upper	r School, Ferndowr	1 Town
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015791
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Part of Ackling Dyke (Roman road), including Rom Michael / Wimborne St. Giles / Sixpenny Handley a	an road on Oakley Ind Pentridge	Down, Gussage All Saints / Gussage S
DESIGNATION:	Scheduled Monument, part in RPG grade II*	LIST ENTRY NUMBER:	1003309
CONDITION:	Extensive significant problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102
ITE NAME:	Barrows in and near The Drive Plantation, Gussage	e All Saints / Wimb	orne St. Giles
DESIGNATION:	Scheduled Monument, part in RPG grade II*	LIST ENTRY NUMBER:	1002788
CONDITION:	Extensive significant problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Barrow on Parsonage Hill, Gussage St. Michael		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002783
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Long mound 1500 yards (1370 metres) east of Hig	her Farm, Gussage	St. Michael
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002784
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Commercial company	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Two barrows near Ackling Dyke, Gussage St. Mich	nael	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002786
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
ITE NAME:	Two long barrows on Gussage Hill, Gussage St. Mi	ichael	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002707
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY ?:	No
OWNER TYPE:	Commercial company	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Two round barrows on Gussage Down, Gussage S	St. Michael	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002741
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Earthworks on Gussage Down, Gussage St. Michae	el / Sixpenny Handle	ey and Pentridge
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002740
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
ITE NAME:	Round barrows near Thickthorn Farm, Gussage St	. Michael / Tarrant	Hinton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002816
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bowl barrow cemetery and a cross dyke on Horto	on Common 800 m	etres south of Bridge Farm, Horton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018411
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
RIORITY CATEGORIES Immediate risk of further rapideterioration or loss of fabric; solution agreed. Immediate risk of further rapideterioration or loss of fabric; solution agreed but not yet	no not yet implemented. (where applicable) end use E Under repair or in fair to good user identified; or functiona d repair, but no user identified; or redundant buildings with ne	e or Last year's privally shown in brac ew use New Entry is i	ABBREVIATIONS CA Conservation Area ority category is LB Listed Building kets (otherwise, LPA Local Planning Authority noted). NP National Park RPG Registered Park and Gar SM Scheduled Monument

solution agreed but not yet implemented. C Slow decay; no solution agreed.

under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- RPG Registered Park and Ga SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

SITE NAME:	Bowl barrow known as Folly Barrow, Iwerne Mi	nster	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020030
DESIGNATION.		EIST EINTRY HUCHBER.	1020030
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No
OWNER TYPE:	Commercial company	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Two bowl barrows 350 metres south west of K	eeper's Lodge, south	east of Bareden Down, Iwerne Minste
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013745
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Alum works, other multi-period industrial remai Kimmeridge Bay, Kimmeridge	ns and an associated g	group of jetties and breakwaters,
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1017307
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bell barrow and five bowl barrows 1000 metres south east of Kingston Russell Farm, part of the Black Do round barrow cemetery, Kingston Russell / Littlebredy		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011693
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bowl barrow 550 metres north east of Pitcombe Farm, part of the Black Down round barrow cemetery, Kingston Russell / Littlebredy		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011694
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Buzbury Rings, Langton Long Blandford / Tarran	t Keyneston / Tarrant	Rawston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002718
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bowl barrow 600 metres west of Well Bottom cemetery, Littlebredy	Wood, forming part c	of the Pitcombe Down round barrow
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013249
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Three bowl barrows 300 metres south west of We round barrow cemetery, Littlebredy	ell Bottom Wood,	forming part of the Pitcombe Down
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013251
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bowl barrow in Well Bottom Wood, Littlebredy /	Winterbourne Abb	Das
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013255
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bowl barrow 70 metres south east of West End Ba	arn, Milborne St. A	ndrew
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014854
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bowl barrow 480 metres south east of West End Barn, Milborne St. Andrew		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014855
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Three bowl barrows on Milborne Down 520 metr Castle hillfort, Milborne St. Andrew	es and 585 metres	north east of obelisk on Weatherby
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019364
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Two bowl barrows and two ring ditches 450 metro	es north west of H	aywards Farm, Milborne St. Andrew
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019365
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Weatherby Castle, an Iron Age hillfort 1020 metre	es north west of As	hley Barn Farm, Milborne St. Andre
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1019360
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No
OWNER TYPE:	Commercial company	CONTACT:	Daniel Bashford 07824 103102

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Stable Barrow 230 metres NNE of Frogmore Far	m, Milborne St. Andı	rew / Milton Abbas
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014761
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bowl barrow in Morden Park 350 metres south v	vest of Hunting Bridg	ge, Morden
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016281
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Two bowl barrows 760 metres north east of Mill	er's Farm, Morden	
DESIGNATION:	Scheduled Monument, RPG grade II*	LIST ENTRY NUMBER:	1016283
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Obelisk on Fir Hill, Moreton		
DESIGNATION:	Scheduled Monument, LB grade II, CA	LIST ENTRY NUMBER:	1002425
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	King's Court Palace moated site, Motcombe		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017276
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Ancient settlement south west of Incombe Wood	l, Nether Cerne	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002438
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Sasha Chapman 0117 975 1338
SITE NAME:	Bowl barrow 230 metres north east of Great Str	ode House, Netherb	ury
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016372
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY ?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Lipton Fort a coastal artillary bettern, and the	rchlight omble come	nts Osmington
DESIGNATION:	Upton Fort, a coastal artillery battery and two sea	LIST ENTRY NUMBER:	1021435
Designation.	Scheduled Monument, LB grade II	LIST EINTRE NORIBER.	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Four barrows on Moigns Down, Owermoigne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002774
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bradford Barrow, Pamphill		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002713
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Round barrow south west of Bourne Farm, Piddle	hinton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004550
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Two barrows on Little Puddle Hill, Piddlehinton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003224
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Two barrows west of Little Piddle Down, Piddlehin	nton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002805
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bowl barrow on Plush Hill 600 metres ESE of Low	er Farm, Plush, Pido	lletrenthide
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015037
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Bowl barrow on Pond Eweleaze 500 metres nor	th east of Dole's Ash	Farm, Piddletrenthide
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015035
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Round barrow on Hog Leaze, Piddletrenthide		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003238
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Enclosure south of Pimperne Down, Pimperne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002860
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Round barrow north east of Friar Waddon, Por	tesham	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002488
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Two round barrows on Ridgeway, Portesham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002758
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Group of round barrows on Shorn Hill and Bro	nkham Hill, Portesham	n / Winterborne St. Martin
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002699
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Dumping	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Battery 200 yards (180 metres) east of the Nava	l cemetery, Portland	
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1002412
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Daniel Bashford 07824 103102

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

Constrained Constrained Constrained Constrained Bioleners IV satisfactory but with significant localised problems No No NUMECON VALUE/SUUTY Other No No OWNER TYPE Private CONTACT: Daniel Bashford 07824 103102 ATT NAME Barrow near east boundary of parish. Powerstock Declining Declining CONTACT: Generally unsatisfactory with major localised reval Declining CONTACT: Generally unsatisfactory with major localised reval Declining CONTACT: Generally unsatisfactory with major localised reval Declining CONTACT: Scheduled Monument UID ENTITIALMOSE DO05507 CONTACT: Generally unsatisfactory with major localised TRAD: Declining CONTACT: Generally unsatisfactory with major localised </th <th>SITE NAME:</th> <th>Mesolithic sites near Culver Well, Portland</th> <th></th> <th></th>	SITE NAME:	Mesolithic sites near Culver Well, Portland		
problemisproblemisNatureJudgeInscriptionNew DMARNew DMARNoInscriptionPrivateNew DMARNew DMARConstantineBarrow near east boundary of parish, PowerstockDecliningDecliningScheduled MonumentUIT DMARDecliningConstantineGenerally unstatisfactory with major localisedTHMARNoScheduled MonumentUIT DMARNoNoConstantineScheduled MonumentUIT DMARNoConstantineScheduled MonumentUIT DMARDecliningConstantineScheduled MonumentUIT DMARDecliningConstantineScheduled MonumentUIT DMARDecliningConstantineScheduled MonumentUIT DMARNoConstantineScheduled MonumentUIT DMARNoConstantineScheduled MonumentUIT DMARNoConstantineScheduled Monument, part in CAUIT DMARNoConstantineScheduled MonumentUIT	DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1002406
SWARTINGPrivateCONTACT:Daniel Bashford 07824 103102MITLANDCBarrow near east boundary of parish, PowerscokUSE DITTY NUMBERS1002809Scheduled MonumentUSE DITTY NUMBERS1002809CONDITIONAGenerally unastificatory with major localizedHENDDecliningPRINCENUMERABULTYArable clippingNEVENTIVYNoSCHARDINArable clippingNEVENTIVYNoSCHARDINBarrow near Eggerdon, Powerstock / West ComputDouble Bashford 07824 103102RENAMENBarrow near Eggerdon, Powerstock / West ComputDouble Bashford 07824 103102SCHARDINScheduled MonumentLIST ENTER NUMBERIOM567CONSTRUCTPrivatePrivateOxenactivDaniel Bashford 07824 103102SCHARDINOArable clippingNEW NEWOutsford 07824 103102SCHARDINOArable clippingNEW NEWDaniel Bashford 07824 103102SCHARDINOArable clippingNEW NEWDaniel Bashford 07824 103102SCHARDINOScheduled Monument, partin CALIST ENTER NUMBERIOM565SCHARDINOScheduled Monument, partin CALIST ENTER NUMBERIO02707SCHARDINOScheduled MonumentLIST ENTER NUMBERIO02707SCHARDINOScheduled MonumentLIST ENTER NUMBERIO02	CONDITION:		TREND:	Stable
Barrow near east boundary of parish, Powerstock Second Secon	PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
DesignationScheduled Monumentust DRTRY NAMER002809concernonGenerally unstatisfactory with major localised pressionALVULENABUTYArable clippingNoresultArable clippingNoONEACT:Daniel Bashford 07824 103102RIST NAMERBarrow near Eggardon, Powerstock / West ComputIO04567DecliningDESIGNATIONScheduled MonumentUST ENTRY NAMER1004567DESIGNATIONGenerally unstatisfactory with major localised generally unstatisfactory with major localised problemsNoDecliningRIST NAMERMarket, Major localised 	OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
ConstraintGenerally unsatisfactory with major localised problemsINSMUDecliningRENGEME VULNERABILITYAnabe clippingNEW ENTRYNoCONTACTBarrow near Eggardon, Powerstock / West Comput passional in a straint and probability of the straint of the stra	SITE NAME:	Barrow near east boundary of parish, Powerstock		
problemsproblemsproblemsNew PartmeDeclamingmancaney, vou basing unitsArable clippingNew PartmeNoowned, threePrivateConstractionConstractionScheduled MonumentIst Entra Numees1004567constractionGenerally unsatisfactory with major localised problemsTRANGDecliningconstractionGenerally unsatisfactory with major localised problemsRev PartmeNoconstractionGenerally unsatisfactory with major localised problemsRev PartmeNoconstractionGenerally unsatisfactory with major localised problemsRev PartmeNoconstractionGenerally unsatisfactory with major localised problemsRev PartmeNoconstractionBarrow 500 yards (450 metres) east of village, PoxyNoconstractionScheduled MonumentIST ENTRY NUMBER,1004565constractionUnknownTRANGNoconstractionUnknownRev PartmeNoconstractionConstractionNoconstractionConstractionNoconstractionConstractionNoconstractionScheduled Monument, part in CAUD TENTRY NUMBER,NoconstractionScheduled MonumentIST ENTRY NUMBER,NoconstractionConstractionDaniel Bashford 07824 103102strestarterArable ploughingNew Partme,NoconstractionScheduled Monument <t< td=""><td>DESIGNATION:</td><td>Scheduled Monument</td><td>LIST ENTRY NUMBER:</td><td>1002809</td></t<>	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002809
DWNEXTITE Private Daniel Bashford 07824 103102 VIETNAME Barrow near Eggardon, Powerstock / West Compton 1004567 DEBIGNATIONE Scheduled Monument IDT INTRY NUMBER 1004567 DEBIGNATIONE Generally unsatisfactory with major localised problems TRANDIC Decining RENOME Arable clipping No Daniel Bashford 07824 103102 RENOME Arable clipping No Daniel Bashford 07824 103102 RENOME Barrow 500 yards (450 metres) east of village, Powell Decining DESIGNATIONE Scheduled Monument DE DINTRY NUMBER 1004565 COMMENTARE Scheduled Monument, Dart in CA Decining Daniel Bashford 07824 103102 RENOME Group of barrows east of Northdown Barn, Powell Docolining Daniel Bashford 07824 103102 RENOME Group of barrows east of Northdown Barn, Powell Docolining Daniel Bashford 07824 103102 RENOME Group of barrow seast of Northdown Barn, Powell Docolining Docolining RENOME Commercial company Contract: Daniel Bashford 07824 103102 RENOME Scheduled Monume	CONDITION:		TREND:	Declining
SITE NAME: Barrow near Eggardon, Powerstock / West Computed Segment No. List ENTRY NUMBER: I004567 DEBIGNATION: Scheduled Monument LIST ENTRY NUMBER: I004567 CONDITION: Generally unsatisfactory with major localised problems: No. PRENCIPAL VULBRABULY: Arable clipping NEW ENTRY: No OWNER TYPE: Private, multiple owners CONTACT: Declining DESIGNATION: Scheduled Monument LIST ENTRY: NUMBER: I004565 CONDITION: Unknown TREND: Declining PRIVATE: Scrub / tree growth NEW ENTRY: No REINAME: Group of barrows east of Northdown Barn, Poxumer: Daniel Bashford 07824 103102 STETENME: Group of barrows east of Northdown Barn, Poxumer: Daniel Bashford 07824 103102 STETENME: Group of barrows east of Northdown Barn, Poxumer: Declining DESIGNATION: Extensive significant problems TREND: Declining DESIGNATION: Extensive significant problems LIST ENTRY: NUMBER: I017261 CONDITION: Extensive significant problems TREND: Decl	PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
DESIGNATION:Scheduled MonumentLST FINTY NUMBER:1004567CONDITION:Generally unsatisfactory with major localised problemsTRBND:DecliningRRINCIPAL VILUNERABILITY:Arable clippingNEW ENTRY:NoOWNER TYTS:Private, multiple ownersCONTACT:Daniel Bashford 07824 103102STE NAME:Barrow 500 yards (450 metres) east of village, PoswertIo04565CONDITIONUnknownTBEND:DecliningDERIGUAL VILNERABILITY:Scheduled MonumentNEW ENTRY:NoCONDITIONUnknownTBEND:DecliningRRINCERL VILNERABILITY:Scrub / Tree growthNEW ENTRY:NoOWNER TYTS:PrivateGroup of barrows east of Northdown Barn, Poswert:NoDEGIGNATION:Scheduled Monument, part in CAUST ENTRY NUMBERIO02770CONDITIONExtensive significant problemsTBEND:DecliningOWNER TYTS:Commercial companyCONTACT:Daniel Bashford 07824 103102UTTE NAME:Bowl barrow on Little Puddle Hill, 920 metres northSct of Hild's CompanyCONDITION:Extensive significant problemsTBEND:DecliningRRINCERL VILNERABILITY:Arable plouphingNEW ENTRY:NoOWNER TYTE:PrivateCONTACT:Daniel Bashford 07824 103102TITE NAME:Scheduled MonumentLST ENTRY NUMBERIO1261CONDITION:Extensive significant problemsTBEND:DecliningRRINCERL VILNERABILITY:Arable plouphingNEW ENTRY:No <t< td=""><td>OWNER TYPE:</td><td>Private</td><td>CONTACT:</td><td>Daniel Bashford 07824 103102</td></t<>	OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
ConstraintGenerally unsatisfactory with major localised problemsTHEND:DeckningNUMERED VIEWArable clippingNEW ENTRY:NoOWNER TYPE:Private, multiple ownersCONTACT:Daniel Bashford 07824 103102ITTE NAME:Barrow 500 yards (450 metres) east of village, PowersUST ENTRY NUMBER104565DESIGNATION:Scheduled Monument, Scheduled Monument, part in CAINEND:DecliningOWNER TYPE:Group of barrows east of Northdown Ban, PowerDaniel Bashford 07824 103102TITE NAME:Scheduled Monument, part in CAUST ENTRY NUMBER.1002707DESIGNATION:Scheduled Monument, part in CAUST ENTRY NUMBER.1002701CONTACT:Scheduled Monument, part in CAUST ENTRY NUMBER.1002701CONTACT:Scheduled Monument, part in CAUST ENTRY NUMBER.1002701CONTACT:Scheduled Monument, part in CAUST ENTRY NUMBER.1002701CONTACT:Commercial companyCONTACT:Daniel Bashford 07824 103102DYNER TYPE:Commercial companyCONTACT:Daniel Bashford 07824 103102DYNER TYPE:Scheduled MonumentUST ENTRY NUMBER.101261CONTACT:Bowl barrow on Little Puddle Hill, 920 metres nut:NoDYNER TYPE:PrivateContact:Daniel Bashford 07824 103102DYNER TYPE:PrivateContact:Daniel Bashford 07824 103102DYNER TYPE:PrivateContact:Daniel Bashford 07824 103102DYNER TYPE:PrivateContact:Daniel Bashford 07824 1031	SITE NAME:	Barrow near Eggardon, Powerstock / West Comp	ton	
problemsproblemsfinal of problemsDeciningRRINCIPAL VULNERABULTY:Arable clippingNew ENTRY:NoPrivate, multiple ownersCONTACT:Daniel Bashford 07824 103102STEENAME:Barrow 500 yards (450 metres) east of village, PoxwellUst ENTRY NUMBER:1004565Deskenationa:Scheduled MonumentUst ENTRY NUMBER:1004565CONTACT:DacilingDecliningNoDeskenationa:Scheduled Monument, part in CAMEW ENTRY:NoCONTACT:Daciling1002770Scheduled Monument, part in CAUst ENTRY NUMBER:1002770CONTACT:Scheduled Monument, part in CAUst ENTRY NUMBER:1002770Scheduled Monument, part in CAUst ENTRY NUMBER:1002770CONDITION:Extensive significant problemsTREND:DecliningScheduled Monument, part in CAUst ENTRY NUMBER:1002770CONDITION:Extensive significant problemsREND:NoScheduled Monument, part in CAUst ENTRY NUMBER:1002770CONDITION:Extensive significant problemsREND:DecliningScheduled Monument, part in CAUst ENTRY NUMBER:1002770CONDITION:Extensive significant problemsREND:DecliningScheduled Monument, part in CAUst ENTRY NUMBER:1002770CONDITION:Extensive significant problemsREND:DecliningScheduled MonumentScheduled MonumentScheduled MonumentScheduled MonumentScheduled MonumentNoEXTENAME:Round Barrow west of Druce Higher Barry,	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004567
OWNER TYPE:Private, multiple ownersCONTACT:Daniel Bashford 07824 103102STEE NAME:Barrow 500 yards (450 metres) east of village, PoxwerIO4565DESIGNATION:Scheduled MonumentIREND:DeclinigDESIGNATION:UnknownREND:DeclinigRRINCERAL WURKERABULTY:Scrub/tree growthNEW ENTRY:NoOWNER TYP:Group of barrows east of Northdown Barn, PoxwerDaniel Bashford 07824 103102STEE NAME:Group of barrows east of Northdown Barn, PoxwerIO02770Scheduled Monument, part in CAStEE NTRY: NUMBER1002770CONDITION:Extensive significant problemsTREND:DecliningRINCIPAL VULNERABULTY:Arable ploughingNEW ENTRY:NoOWNER TYPI:Commercial companyCONTACT:Daniel Bashford 07824 103102STEE NAME:Bowl barrow on Little Puddle Hill, 920 metres networksISTENTRY: NUMBER1017261CONDITION:Scheduled MonumentLIST ENTRY: NUMBERIO17261CONDITION:Scheduled MonumentLIST ENTRY: NUMBERIO17261CONDITION:Extensive significant problemsTREND:DecliningRINCRAL VULNERABULTY:Arable ploughingNEW ENTRY:NoOWNER TYPE:Round barrow west of Druce Higher Barr, PuddletowDecliningRINCRAL VULNERABULTY:Arable ploughingNEW ENTRY:NoOWNER TYPE:Rincral problemsTREND:DecliningRINCRAL VULNERABULTY:Arable ploughingNEW ENTRY:NoOWNER TYPE:Private<	CONDITION:		TREND:	Declining
STRE NAME: Barrow S00 yards (450 metres) east of village, Poxwell UESIGNATION: Scheduled Monument LIST ENTRY NUMBER 1004565 CONDITION: Unknown TREND: Declining RINCIPAL VULNERABLITY: Scrub/tree growth NEW CONTACT: Daniel Bashford 07824 103102 STRE NAME: Group of barrows east of Northdown Barn, Poxwell UESIGNATION: Scheduled Monument, part in CA LIST ENTRY NUMBER 1002770 Stress Scheduled Monument, part in CA LIST ENTRY NUMBER 1002770 Stress Scheduled Monument, part in CA LIST ENTRY NUMBER 1002770 CONDITION: Scheduled Monument, part in CA LIST ENTRY NUMBER 1002770 Scheduled Monument, part in CA LIST ENTRY NUMBER 1002770 Scheduled Monument, part in CA LIST ENTRY NUMBER 1002770 Scheduled Monument LIST ENTRY NUMBER 1002770 Scheduled Monument LIST ENTRY NUMBER 1002770 Scheduled Monument EXTERNATION: Scheduled Monument CONDITION: Scheduled M	PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY ?:	No
DEBIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1004565CONDITION:UnknownTREND:DecliningPRINCIPAL VULNERABILITY:Scrub/tree growthNEW ENTRY:NoOWNER TYPE:PrivateCONTACT:Daniel Bashford 07824 103102STE NAME:Group of barrows east of Northdown Barn, Poxwel1002770DESIGNATION:Scheduled Monument, part in CALIST ENTRY NUMBER:1002770CONTION:Extensive significant problemsIREND:DecliningCONTION:Extensive significant problemsNEW ENTRY:NoOWNER TYPE:Commercial companyCONTACT:Daniel Bashford 07824 103102OWNER TYPE:Bowl barrow on Little Puddle Hill, 920 metres north:West of Fidler's Green Farm, PuddletoomDESIGNATION:Scheduled MonumentUST ENTRY NUMBER:1017261CONTION:Extensive significant problemsTREND:DecliningDESIGNATION:Scheduled MonumentUST ENTRY NUMBER:1017261CONTION:Extensive significant problemsNoNoOWNER TYPE:PrivateRend barrow est of Druce Higher Barn, PuddletowNoOWNER TYPE:Round barrow west of Druce Higher Barn, PuddletowNoStenswise significant problemsIST ENTRY NUMBER:1002874OWNER TYPE:Round barrow set of Druce Higher Barn, PuddletowNoOWNER TYPE:Renders significant problemsIST ENTRY NUMBER:1002874OWNER TYPE:Renders significant problemsIST ENTRY NUMBER:1002874Stenswis	OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102
CONDITION:UnknownTREND:DecliningRINCCIAL VOLUERABULTY:Scrub/tree growthNEW ENTRY:NoDEVENTERY:PrivateCONTACT:Daniel Bashford 07824 103102DESIGNATION:Group of barrows east of Northdown Barn, PoxwellUST ENTR NUMBER;1002770DESIGNATION:Scheduled Monument, part in CAUST ENTR NUMBER;1002770CONTOTION:Extensive significant problemsTREND:DecliningRINICIPAL VOLUERABULTY:Arable ploughingNEW ENTRY:NoDESIGNATION:Commercial companyCONTACT:Daniel Bashford 07824 103102DESIGNATION:Scheduled MonumentUST ENTRY NUMBER;1017261DESIGNATION:Scheduled MonumentUST ENTRY NUMBER;NoDESIGNATION:Scheduled MonumentUST ENTRY NUMBER;NoDESIGNATION:Scheduled MonumentUST ENTRY NUMBER;NoDESIGNATION:Fransve significant problemsTREND:Daniel Bashford 07824 103102DESIGNATION:Fransve significant problemsTREND:NoDESIGNATION:Scheduled MonumentUST ENTRY NUMBER;NoDESIGNATION:Scheduled MonumentUST ENTRY	SITE NAME:	Barrow 500 yards (450 metres) east of village, Pox	well	
Control No CONTRET TYPE: Scrub/tree growth NeW ENTRY: No CONTACT: Daniel Bashford 07824 103 102 STEE NAME: Group of barrows east of Northdown Barn, Poxwell STEE NAME: Group of barrows east of Northdown Barn, Poxwell DESIGNATION: Scheduled Monument, part in CA UST ENTRY NUMBER: 1002770 CONDITION: Extensive significant problems TEEND: Declining RRINCIPAL VULNERABULTY: Arable ploughing NeW ENTRY: No OWNER TYPE: Commercial company CONTACT: Daniel Bashford 07824 103 102 STEE NAME: Bowl barrow on Little Puddle Hill, 920 metres north West ENTRY: No DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1017261 CONDITION: Extensive significant problems TEEND: Declining PRINCIPAL VULNERABULTY: Arable ploughing NeW ENTRY: No OWNER TYPE: Private CONTACT: Daniel Bashford 07824 103 102 EXTENAME: Scheduled Monument UST ENTRY NUMBER: No CONDITION: <	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004565
DWNER TYPE:PrivateCONTACT:Daniel Bashford 07824 103102DESIGNATION:Group of barrows east of Northdown Barn, Poxwell1002770DESIGNATION:Scheduled Monument, part in CALIST ENTRY NUMBER:1002770CONTOTION:Extensive significant problemsTREND:DecliningRRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:NoOWNER TYPE:Commercial companyCONTACT:Daniel Bashford 07824 103102STET NAME:Bowl barrow on Little Puddle Hill, 920 metres northSet FITRY NUMBER:1017261DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1017261CONDITION:Scheduled MonumentLIST ENTRY NUMBER:1017261CONDITION:Scheduled MonumentUST ENTRY NUMBER:101261CONDITION:Scheduled MonumentLIST ENTRY NUMBER:1002874CONDITION:Arable ploughingNEW ENTRY:NoDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1002874CONDITION:RENDCONTACT:Daniel Bashford 07824 103102STET NAME:Scheduled MonumentLIST ENTRY NUMBER:1002874CONDITION:Scheduled MonumentLIST ENTRY NUMBER:1002874CONDITION:Scheduled MonumentLIST ENTRY NUMBER:1002874CONDITION:Scheduled MonumentLIST ENTRY NUMBER:1002874CONDITION:Scheduled MonumentLIST ENTRY NUMBER:1002450CONDITION:Scheduled MonumentLIST ENTRY NUMBER:1002450STE NAME:Sc	CONDITION:	Unknown	TREND:	Declining
site NAME: Group of barrow seast of Northdown Barn, Poxwell UST ENTRY NUMBER: 1002770 DESIGNATION: Scheduled Monument, part in CA UST ENTRY NUMBER: 1002770 Extensive significant problems TREND: Declining RRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Commercial company CONTACT: Daniel Bashford 07824 103102 STE NAME: Scheduled Monument UST ENTRY NUMBER: 1017261 CONTACT: 017261 DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1017261 CONTORN: Scheduled Monument UST ENTRY NUMBER: 1017261 CONTORN: Scheduled Monument New ENTRY: No Designation: Arable ploughing NEW ENTRY: No NEW ENTRY: No Designation: CONTORN: Scheduled Monument UST ENTRY NUMBER: 1017261 CONTORN: Scheduled Monument UST ENTRY NUMBER: 1017261 CONTORN: Scheduled Monument UST ENTRY NUMBER: 1017261 CONTORN: Scheduled Monument UST ENTRY NUMBER: 1017261 DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1017261 DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1002874 103102 STE NAME: ROUD Barrow west of Druce Higher Barn, Puddlet ENTRY NUMBER: 1002874 CONTACT: Declining Scheduled Monument UST ENTRY NUMBER: 1002874 CONTACT: NO Declining RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: NUMBER: 1002874 CONTORN: Scheduled Monument UST ENTRY NUMBER: 1002874 CONTORN: Scheduled Monument UST ENTRY NUMBER: 1002874 CONTACT: Declining RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: NO Scheduled Monument UST ENTRY NUMBER: 1002874 CONTACT: Declining RINCIPAL VULNERABILITY: Scheduled Monument UST ENTRY NUMBER: 1002874 CONTACT: Declining RINCIPAL VULNERABILITY: Scheduled Monument UST ENTRY NUMBER: 1002874 CONTACT: Declining RINCIPAL VULNERABILITY: MUMBER: 1002850 CONTACT: Declining RINCIPAL VULNERABILITY: NUMBER: 1002850 CONTACT: Declining RINCIPAL VULNERABILITY: NU	PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No
Designation:Scheduled Monument, part in CALIST ENTRY NUMBER:1002770CONDITION:Extensive significant problemsTREND:DecliningCONDITION:Arable ploughingNeW ENTRY:NoOWNER TYPE:Commercial companyCONTACT:Daniel Bashford 07824 103102SITE NAME:Bowl barrow on Little Puddle Hill, 920 metres northwest of Fidler's Green Farm, PuddletownDESIGNATION:Scheduled MonumentUST ENTRY NUMBER:1017261CONDITION:Scheduled MonumentUST ENTRY NUMBER:DecliningCONDITION:Extensive significant problemsTREND:DecliningCONDITION:Extensive significant problemsNEW ENTRY:NoOWNER TYPE:PrivateOUNTACT:Daniel Bashford 07824 103102STRE NAME:Round barrow west of Druce Higher Barn, PuddletownDecliningDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1002874CONDITION:Extensive significant problemsTREND:DecliningSTRE NAME:Round barrow west of Druce Higher Barn, PuddletownDecliningCONDITION:Extensive significant problemsREND:DecliningCONDITION:Extensive significant problemsREND:DecliningSTRE NAME:PrivateOuter true for the form of t	OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
CONDITION:Extensive significant problemsTREND:DecliningRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY:NoOWNER TYPE:Commercial companyCONTACT:Daniel Bashford 07824 103102SITE NAME:Book barrow on Little Puddle Hill, 920 metres nor	site name:	Group of barrows east of Northdown Barn, Poxw	ell	
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Commercial company CONTACT: Daniel Bashford 07824 103102 SITE NAME: Bowl barrow on Little Puddle Hill, 920 metres north west of Fidler's Green Farm, Puddletown ISTE NAME: ISTE NAME: ISTE NAME: Bowl barrow on Little Puddle Hill, 920 metres north west of Fidler's Green Farm, Puddletown DESIGNATION: Scheduled Monument ISTE ENTRY NUMBER: 1017261 CONDITION: Extensive significant problems TREND: Declining OWNER TYPE: Private CONTACT: No OWNER TYPE: Private CONTACT: Daniel Bashford 07824 103102 STEE NAME: Round barrow west of Druce Higher Barn, Puddletown No DESIGNATION: Scheduled Monument IST ENTRY NUMBER: 1002874 CONDITION: Extensive significant problems REND: Declining DESIGNATION: Scheduled Monument IST ENTRY NUMBER: 1002874 CONDITION: Private CONTACT: Daniel Bashford 07824 103102 STE NAME: Three round barrows on Puddletown Down, PudLetown WENTRY? No	DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1002770
DWNER TYPE:Commercial companyCONTACT:Daniel Bashford 07824 103102SITE NAME:Bowl barrow on Little Puddle Hill, 920 metres north west of Fidler's Green Farm, PuddletownDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1017261CONDITION:Extensive significant problemsTREND:DecliningCONTACT:Arable ploughingNEW ENTRY:NoOWNER TYPE:PrivateCONTACT:Daniel Bashford 07824 103102SITE NAME:Round barrow west of Druce Higher Barn, PuddletownDecliningDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1002874DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1002874CONDITION:Extensive significant problemsTREND:DecliningRRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY:NoDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1002874DOWNER TYPE:PrivateContact:Daniel Bashford 07824 103102DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1002874DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1002450DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1002450DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1002450DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1002450DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1002450CONDITION:Extensive significant problemsTREND:DecliningRRINCIPAL	CONDITION:	Extensive significant problems	TREND:	Declining
STEE NAME: Bowl barrow on Little Puddle Hill, 920 metres nort. Stet on Fielder's En Farm, Puddletown DESIGNATION: Scheduled Monument LIST ENTRY NUMBER 1017261 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Private CONTACT: Daniel Bashford 07824 103102 STEE NAME: Round barrow west of Druce Higher Barn, Puddletown ISTE ENTRY NUMBER 1002874 CONDITION: Scheduled Monument LIST ENTRY NUMBER 1002874 CONDITION: Extensive significant problems TREND: Declining CONDITION: Arable ploughing NEW ENTRY: No OWNER TYPE: Private Three round barrows on Puddletown Down, Puddletown No STEE NAME: Three round barrows on Puddletown Down, Puddletown IST ENTRY NUMBER: 1002450 Steensive significant problems LIST ENTRY NUMBER: 1002450 OWNER TYPE: Scheduled Monument LIST ENTRY NUMBER: 1002450 OWNER TYPE: Three round barrows on Puddletown Down, Puddletown IST ENTRY NUMBER: 1002450	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1017261CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY:NoOWNER TYPE:PrivateCONTACT:Daniel Bashford 07824 103102SITE NAME:Round barrow west of Druce Higher Barn, PuddletowJone State Stat	OWNER TYPE:	Commercial company	CONTACT:	Daniel Bashford 07824 103102
CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?NoOWNER TYPE:PrivateCONTACT:Daniel Bashford 07824 103102STRE NAME:Round barrow west of Druce Higher Barn, Puddlet-1002874DESIGNATION:Scheduled MonumentUST ENTRY NUMBER:1002874CONDITION:Extensive significant problemsTREND:DecliningOWNER TYPE:PrivateCONTACT:DecliningOWNER TYPE:PrivateCONTACT:Daniel Bashford 07824 103102STRE NAME:Frie round barrows on Puddletown Down, PuddletownNew ENTRY?NoOWNER TYPE:Scheduled MonumentUST ENTRY NUMBER:1002450STRE NAME:Three round barrows on Puddletown Down, Puddletown1002450DESIGNATION:Scheduled MonumentUST ENTRY NUMBER:1002450CONDITION:Extensive significant problemsTREND:DecliningDESIGNATION:Scheduled MonumentUST ENTRY NUMBER:1002450CONDITION:Scheduled MonumentNEW ENTRY:NoCONDITION:Extensive significant problemsTREND:DecliningCONDITION:Arable ploughingNEW ENTRY:No	SITE NAME:	Bowl barrow on Little Puddle Hill, 920 metres nor	th west of Fidler's (Green Farm, Puddletown
PRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY:NoOWNER TYPE:PrivateCONTACT:Daniel Bashford 07824 103 102SITE NAME:Round barrow west of Druce Higher Barn, PuddletownID02874DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1002874CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY:NoOWNER TYPE:PrivateThree round barrows on Puddletown Down, PuddletownDaniel Bashford 07824 103 102SITE NAME:Three round barrows on Puddletown Down, PuddletownUIST ENTRY NUMBER:1002450DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1002450ODDITION:Extensive significant problemsTREND:DecliningOWNER TYPE:Scheduled MonumentLIST ENTRY NUMBER:1002450DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1002450CONDITION:Extensive significant problemsTREND:DecliningCONDITION:Extensive significant problemsTREND:DecliningCONDITION:Extensive significant problemsTREND:DecliningCONDITION:Extensive significant problemsTREND:DecliningCONDITION:Extensive significant problemsTREND:DecliningCONDITION:Extensive significant problemsTREND:DecliningCONDITION:Extensive significant problemsNEW ENTRY:No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017261
Number productingNoticeOWNER TYPE:PrivateCONTACT:Daniel Bashford 07824 103102SITE NAME:Round barrow west of Druce Higher Barn, PuddletownISTE ENTRY NUMBER:1002874DESIGNATION:Scheduled MonumentISTE ENTRY NUMBER:1002874CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:NoOWNER TYPE:Three round barrows on Puddletown Down, PuddletownDaniel Bashford 07824 103102SITE NAME:Three round barrows on Puddletown Down, PuddletownISTE ENTRY NUMBER:1002450CONDITION:Scheduled MonumentIST ENTRY NUMBER:1002450CONDITION:Extensive significant problemsTREND:DecliningCONDITION:Extensive significant problemsISTE ENTRY NUMBER:1002450CONDITION:Extensive significant problemsTREND:DecliningCONDITION:Extensive significant problemsNEW ENTRY:NoPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY:No	CONDITION:	Extensive significant problems	TREND:	Declining
STE NAME: Round barrow west of Druce Higher Barn, Puddlet- DESIGNATION: Scheduled Monument IJST ENTRY NUMBER: 1002874 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing New ENTRY: No OWNER TYPE: Private Three round barrows on Puddletown Down, Puddletown Daniel Bashford 07824 103102 VERSIGNATION: Scheduled Monument IJST ENTRY NUMBER: 1002450 DESIGNATION: Scheduled Monument IJST ENTRY NUMBER: IO02450 ONDITION: Extensive significant problems IJST ENTRY NUMBER: IO02450 ONDITION: Extensive significant problems IST ENTRY NUMBER: IO02450 ONDITION: Extensive significant problems TREND: Declining	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1002874CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:NoOWNER TYPE:PrivateCONTACT:Daniel Bashford 07824 103102SITE NAME:Three round barrows on Puddletown Down, PuddletownUST ENTRY NUMBER:1002450DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1002450CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:No	OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:NoDWNER TYPE:PrivateCONTACT:Daniel Bashford 07824 103102STEE NAME:Three round barrows on Puddletown Down, PuddletownUST ENTRY NUMBER:1002450DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1002450CONDITION:Extensive significant problemsTREND:DecliningRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:No	SITE NAME:	Round barrow west of Druce Higher Barn, Puddle	town	
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Private CONTACT: Daniel Bashford 07824 103102 SITE NAME: Three round barrows on Puddletown Down, Puddletown V DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002450 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002874
OWNER TYPE:PrivateCONTACT:Daniel Bashford 07824 103102SITE NAME:Three round barrows on Puddletown Down, PuddletownVDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1002450CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:No	CONDITION:	Extensive significant problems	TREND:	Declining
SITE NAME: Three round barrows on Puddletown Down, Puddletown DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002450 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002450 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No		Three round barrows on Puddletown Down, Pudd	lletown	
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002450
	CONDITION:	Extensive significant problems	TREND:	Declining
OWNER TYPE: Private CONTACT: Daniel Bashford 07824 103102	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
	OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102

A Immediate risk of further rapid deterioration or loss of fabric; no

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Two bowl barrows 320 metres south west of La	ycock Dairy Farm, Pu	Iddletown
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017266
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Two round barrows south west of Well House	Cottage, Puddletown	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002875
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bowl barrow 400 metres north east of Look Far	m, Puncknowle	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016370
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Castle Hill, Shaftesbury		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1002724
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Camp in Mistlebury Wood, Sixpenny Handley an	d Pentridge	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002455
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Charity (non-heritage)	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Celtic fields on Pentridge Down, Sixpenny Hand	ley and Pentridge	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002796
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Enclosure south of Humby's Stock Coppice, Sixp	enny Handley and Pe	ntridge
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005575
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Commercial company	CONTACT:	Daniel Bashford 07824 103102

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Long barrow 1200 metres south west of St Rumbo	old's Church, Sixper	ny Handley and Pentridge
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003206
CONDITION:	Unknown	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Long barrows and group of round barrows on Bol	kerley Down, Sixper	nny Handley and Pentridge
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002722
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Crawford Castle (or Spetisbury Rings), Spetisbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004563
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Three bowl barrows in Avon Heath Country Park, two 620 metres and one 700 metres north west of Matcham's House, St. Leonards and St. Ives		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016095
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No
OWNER TYPE:	Local authority	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bell barrow 70 metres west of Fidler's Green, Stin	sford	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017262
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Round barrow north east of Hog Hill Barn, Stratto	n	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003237
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Dumping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Round barrow north west of Jackman's Cross, Stra	atton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002470
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / SOU			
SITE NAME:	Round barrow on Stratton Down, Stratton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002871
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
ITE NAME:	Earthworks on Loscombe Hill, Sydling St. Nicholas	5	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002820
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
ITE NAME:	Bowl barrow on Eype Down 275 metres east of F	rogmore Farm, Sym	ondsbury
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016100
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Slight univallate hillfort 850 metres north east of Busseys Stool Farm, Tarrant Gunville		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020611
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Roman villa on Little Barton Hill, Tarrant Gunville	/ Tarrant Hinton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002424
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bowl barrow 200 metres south east of Pimperne I	Long Barrow, Tarra	nt Hinton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013794
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Prehistoric habitation site between north and sout	th Hinton Downs, T	arrant Hinton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003235
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Bowl barrow 350 metres south west of Buzbury	Rings, Tarrant Keyne	eston	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013789	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No	
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102	
SITE NAME:	Bowl barrow 850 metres ESE of Hill Farm, Tarra	int Keyneston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015182	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY ?:	No	
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102	
SITE NAME:	Bowl barrow 600 metres south of Plantation Far	m, Tarrant Launcesto	n	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015190	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102	
SITE NAME:	Disc barrow and a bowl barrow 640 metres south west of Veiny Cheese Pond, Tarrant Launceston / Cr			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020444	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No	
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102	
SITE NAME:	Bowl barrow on The Cliff 680 metres east of Lu	ton Farm, Tarrant Ra	wston	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015187	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Daniel Bashford 07824 103102	
SITE NAME:	Bowl barrow on The Cliff 680 metres NNW of	Smith's Cottages, Tar	rant Rawston	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015186	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Daniel Bashford 07824 103102	
SITE NAME:	Long barrow and two bowl barrows 140 metres	north west of Dorm	y House, Tarrant Rawston	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014572	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Daniel Bashford 07824 103102	
SITE NAME:	Roman enclosure on Keyneston Down, Tarrant	Rawston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002373	
CONDITION:	Extensive significant problems	TREND:	Declining	
	A 11 1 1.	NEW ENTRY?:	No	
PRINCIPAL VULNERABILITY:	Arable ploughing	INEVV EINTRE:	INO	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Holditch Court Tower, Thorncombe		
DESIGNATION:	Scheduled Monument, LB grade I	LIST ENTRY NUMBER:	1002835
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Ball 0117 975 0666
SITE NAME:	Four bowl barrows 710 metres north, 750 metres Tolpuddle	north west and 95	0 metres north west of Clyffe House,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016378
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	High Cank, a hengi-form monument 520 metres no	orth of Up Cerne M	1anor House, Up Cerne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018413
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Stephen's Castle, a bowl barrow 720 metres east c	of Eastworth Farm,	Verwood
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021148
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No
OWNER TYPE:	Local authority	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Decoy pond and associated overnight shelter on D	ecoy Heath, Ware	ham St. Martin
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016916
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Light Anti-aircraft battery on Holton Heath, 210 m	etres west of Sand	ford House, Wareham St. Martin
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019153
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Light Anti-aircraft battery on Holton Heath, 650 m	etres south east of	Sandford House, Wareham St. Marti
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019152
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Daniel Bashford 07824 103102

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Royal Naval Cordite Factory at Holton Heath, Wa	reham St. Martin		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1019151	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102	
SITE NAME:	Four bowl barrows 150 metres north east of Sever	n Barrows Farm, W	/areham Town	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015373	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Private CONTACT: Daniel Bashford			
SITE NAME:	Dyke south east of Eggardon Hill camp, West Com	npton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002404	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102	
SITE NAME:	Parley Barrow, a bowl barrow on the corner of Ell	esfield Drive and D	ruid's Close, West Parley	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015792	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102	
SITE NAME:	Three bowl barrows 530 metres and 350 metres n	orth east of Whitc	ombe Barn, Whitcombe	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019413	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102	
SITE NAME:	Section of Roman road 150 metres south of Park F	arm Cottages, Wir	nborne Minster	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018028	
CONDITION:	Extensive significant problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102	
SITE NAME:	Barrows near Water Lake, Wimborne St. Giles			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002795	
CONDITION:	Unknown	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	E NAME: Two round barrows south of Cranborne Farm, Wimborne St. Giles				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002459		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No		
OWNER TYPE:	Private CONTACT: Daniel				
SITE NAME:	Barrows in Salisbury Plantation, Wimborne St. Giles / Sixpenny Handley and Pentridge				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002817		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102		
SITE NAME:	Part of Dorset Cursus, Wimborne St. Giles / Sixpe	enny Handley and P	entridge		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003222		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No		
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102		
SITE NAME:	Drove Hill round barrows, Winfrith Newburgh				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002765		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No		
OWNER TYPE:	Mixed, multiple owners CONTACT: Danie		Daniel Bashford 07824 103102		
SITE NAME:	Two round barrows north of Came Farm, Winter	borne Came			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002828		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102		
SITE NAME:	Bowl barrow 150 metres north east of Dunbury, V	Vinterborne Hougł	nton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014758		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No		
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102		
SITE NAME:	Bowl barrow 500 metres south of West Down Ba	rn, Winterborne K	ingston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020986		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102		

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Bowl barrow 550 metres north of North Down	Barn, Winterborne K	Lingston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014852		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	Yes		
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102		
SITE NAME:	Bowl barrow 560 metres NNE of North Down	Barn, Winterborne K	ingston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014853		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	Yes		
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102		
SITE NAME:	Long barrow immediately north west of Maiden	Castle, Winterborne	Monkton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015779		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No		
OWNER TYPE:	Crown	CONTACT:	Daniel Bashford 07824 103102		
SITE NAME:	Long barrow, three bell barrows, fancy barrow a Winterborne Monkton	and a linear earthworl	k 800 metres north of Maiden Castle		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015783		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No		
OWNER TYPE: Crown		CONTACT:	Daniel Bashford 07824 103102		
SITE NAME:	Round barrow cemetery immediately south east of Maiden Castle, Winterborne Monkton				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015778		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE: Private, multiple owners		CONTACT:	Daniel Bashford 07824 103102		
SITE NAME:	Group of barrows south of Goldsmith's Plantation	on, Winterborne St. N	1 artin		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002810		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102		
SITE NAME:	Group of round barrows near Eweleaze Barn, V	/interborne St. Martir	1		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002756		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No		
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102		
SITE NAME:	Group of round barrows on and to east of Grea	t Hill, Winterborne S	t. Martin		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004564		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No		
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Daniel Bashford 07824 103102		

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В

implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Round barrow north of Ridgeway, Winterborne	St. Martin	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002759
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Round barrows on Four Barrow Hill, Winterbo	rne St. Martin	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002755
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Round barrows on Grove Hill, Winterborne St.	Martin	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002757
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Three barrows south of Hart Hill Plantation, Wi	nterborne St. Martin	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002814
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Two barrows at Rew, Winterborne St. Martin		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002811
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bowl barrow 900 metres north west of Pond D	own Buildings, Winter	rborne Stickland
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013749
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	' Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Unknown	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bowl barrow 25 metres south of Whitechurch H	Hill Barn, Winterborn	e Whitechurch
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013788
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Milling House, West Farm, Winterborne Whited	church	
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1002396
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
	Ũ		

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

use).

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Bell barrow 100 metres south of Winterbourne Po cemetery, Winterbourne Abbas	oor Lot, part of the	Winterbourne Poor Lot round barro
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012027
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bowl barrow 400 metres north east of Manor Farr Winterbourne Abbas	m, part of the Pound	d Hill round barrow cemetery,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011692
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Unknown	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bowl barrow 450 metres north east of Manor Farr Winterbourne Abbas	m, part of the Pound	d Hill round barrow cemetery,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011691
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
DWNER TYPE:	Unknown	CONTACT:	Daniel Bashford 07824 103102
ITE NAME:	Bowl barrow 700 metres NNW of Whitefriars Bro	oiler Houses, Winte	erbourne Abbas
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011690
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
ITE NAME:	Bowl barrow 850 metres north west of Whitefrian	rs Broiler Houses, V	Vinterbourne Abbas
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011689
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
ITE NAME:	Triple barrow and bowl barrow forming part of a b metres north east of Winterbourne Poor Lot, Wir	barrow cemetery ar nterbourne Abbas	nd part of an associated field system 2
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012030
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Unknown	CONTACT:	Daniel Bashford 07824 103102
ITE NAME:	Two bell barrows 15 metres north of Well Botton Winterbourne Abbas	n Wood, part of the	e Poor Lot round barrow cemetery,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012029
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Unknown	CONTACT:	Daniel Bashford 07824 103102

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.

Slow decay; solution agreed but not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Е

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Autho NP National Park RPG Registered Park and (SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Group of barrows near Big Wood, Winterbourne Abbas / Winterbourne Steepleton				
DESIGNATION:	Scheduled Monument, part in RPG grade II	LIST ENTRY NUMBER:	1002696		
CONDITION:	Generally unsatisfactory with major localised problems	Declining			
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102		
SITE NAME:	Four round barrows north west of Blagdon Barn, Winterbourne Steepleton				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002750		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Commercial company	CONTACT:	Daniel Bashford 07824 103102		
SITE NAME:	Round barrow on Pound Hill, Winterbourne Ste	epleton			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002870		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102		
SITE NAME:	Round barrow south west of village, Winterbou	rne Steepleton			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002751		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No		
OWNER TYPE:	Commercial company CONTACT: Daniel Bashfor		Daniel Bashford 07824 103102		
SITE NAME:	Round barrows on Sheep Down, Winterbourne	Steepleton			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003306		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No		
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102		
SITE NAME:	Two conjoined bowl barrows 550 metres north	east of Manor Farm,	Pound Hill, Winterbourne Steepleton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002687		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102		
SITE NAME:	Two round barrows on North Hill, Winterbour	ne Steepleton			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002865		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No		
		Daniel Bashford 07824 103102			

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Group of henge monuments, an associated grou at Knowlton, Woodlands	p of round barrows, a	saxon cemetery and a Norman ch
DESIGNATION:	Scheduled Monument, LB grade II*	LIST ENTRY NUMBER:	1020580
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Round barrow cemetery south of New Barn Fa	rm, associated with th	e Knowlton Circles, Woodlands
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020582
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102
ITE NAME:	Bowl barrow 300 metres south east of Hyford (Cottage, Wool	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015894
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
ITE NAME:	Bowl barrow 380 metres north west of Hyford	Cottage, Wool	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015895
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bul Barrow, 750 metres east of Rawlsbury Cam	p, Woolland	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013787
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No
OWNER TYPE:	Commercial company	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bowl barrow on Emmett's Hill, Worth Matraver	-S	
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1017268
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bowl barrow on North Hill, 400 metres north e	ast of Renscombe Far	m, Worth Matravers
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017269
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / SOUTH WEST / DORSET (UA) / CHELTENHAM

SITE NAME:	Bowl barrow on	e kilometre south west of Manor F	arm, Wraxall	
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1015051
CONDITION:	Generally satisfactory but with significant localised problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Linear boundary Royal	and section of Roman road, 550 n	netres south east o	f Ashmore Farm, Ashmore / Tollard
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1020728
CONDITION:	Extensive signific	ant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Private, multiple	owners	CONTACT:	Nick Croxson 07795 665645
	SITE NAME:	Kingston Maurward, Stinsford		ape around early C18 house with notable
	DESIGNATION:	Registered Park and Garden grade II*, 8 LBs, part in SM, part in CA	nucleus of expan buildings which in	ens open to the public. House forms Iding land-based college. Many post-war mpact on view lines and appreciation of Ipe. In 2011 Natural England grant-aided a
A REAL PROPERTY OF A REAL PROPERTY OF		Generally unsatisfactory with		for part of the park. Historic England has

© Historic England

	DESIGNATION:	Registered Park and Garden grade II*, 8 LBs, part in SM, part in CA	nucleus of expanding land-based college. Many post-w buildings which impact on view lines and appreciation designed landscape. In 2011 Natural England grant-aic
	CONDITION:	Generally unsatisfactory with major localised problems	restoration plan for part of the park. Historic England been consulted on a new masterplan to guide future development of the college.
	VULNERABILITY:	Medium	development of the conege.
	TREND:	Stable	
	NEW ENTRY?:	No	
	OWNER TYPE:	Educational (state sector)	
	LIST ENTRY NUMBER:	1000719	Contact: Jo McAllister 0117 975 0696

SITE NAME:	Swanage		
DESIGNATION:	Conservation Area, 88 LBs, SM, WHS	NEW ENTRY ?:	No
CONDITION:	Very bad		Deteriorating
VULNERABILITY:	Low	CONTACT:	Paul Wyeth (LPA) 01305 251010
SITE NAME:	Weymouth Town Centre		
SITE NAME: DESIGNATION:	Weymouth Town Centre Conservation Area, 361 LBs, SM	NEW ENTRY?:	No
	1	NEW ENTRY?: TREND:	No Deteriorating significantly
DESIGNATION:	Conservation Area, 361 LBs, SM		

GLOUCESTERSHIRE

CHELTENHAM



SITE NAME:	Church of St Mark, Church Road, Cheltenham	Parish church built in 1860-6 by John Middleton, with transepts of 1888. Drilled Cotswold stone with Bath stone
 DESIGNATION:	Listed Place of Worship grade II	quoins and dressings, Forest of Dean stone forming alternating polychromy in voussoirs (wedge shaped
CONDITION:	Poor	stones), red tile roof. Gothic Revival, Decorated style. Nave roof is in poor condition. Plain clay tile loss on the
PRIORITY CATEGORY:	C (C)	north vestry and chancel roofs were repaired in 2015.
OWNER TYPE:	Religious organisation	Water ingress in some areas is exacerbating the poor condition of the interior.
LIST ENTRY NUMBER:	1386790	Contact: Chris Miners 0117 975 1355

© Historic England

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / SOUTH WEST / CHELTENHAM / COTSWOLD

	SITE NAME:	Church of St Luke, College Road, Cheltenham	Church built in 1853-4 by Frederick W Ordish, partly intended for pupils from nearby Cheltenham College.
	DESIGNATION:	Listed Place of Worship grade II, CA	Drilled Cotswold stone with ashlar quoins and dressings and with plain tile roof. Middle Pointed style. Cruciform plan with west tower; four-bay aisled nave with clerestory
	CONDITION:	Poor	and south porch, crossing with north and south transepts, four-bay chancel with south Lady Chapel, north vestry. The
	PRIORITY CATEGORY:	D (D)	roof covering is in poor condition and the interior is
	OWNER TYPE:	Religious organisation	damaged by water ingress, although the lady chapel, vestry and chancel roofs have been repaired. The rainwater
	LIST ENTRY NUMBER:	1387880	goods were repaired in 2016.
			Contact: Chris Miners 0117 975 1355

© Historic England

COTSWOLD


© Historic England Archive

© Historic England

© Historic England



1	SITE NAME:	Elizabeth Pengree Memorial, The Square, Blockley	Commemorative monument (1770s) decaying on one side and the railings are displaced and in poor condition. Basic
	DESIGNATION:	Listed Building grade II*, CA	maintenance has been undertaken, but no significant repairs.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
i di	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1341728	Contact: Chris Miners 0117 975 1355



	SITE NAME:	Alfreds Hall, Cirencester Park, Cirencester	Folly, begun 1721, designed by Lord Bathurst with Alexander Pope's advice, completed 1732. Probably the
	DESIGNATION:	Listed Building grade II*, RPG grade I	earliest C18 mock-Gothic castle; part former house, part banqueting house and part mock ruin. Located in Oakley Wood, with rides radiating from it through the wood. The
	CONDITION:	Very bad	building is in very bad condition and continues to deteriorate.
TAL	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	B (A)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1298719	Contact: Katy Hoskyn 0117 975 1311

	SITE NAME:	Dovecote at the Manor House, Lower Slaughter	A late C16 structure of coursed rubble and Cotswold stone roof. This large dovecote hosts two separate
	DESIGNATION:	Listed Building grade II*, CA	columbaria inside, built of nesting boxes from ground to the roof. It is currently without a use and in poor condition.
	CONDITION:	Poor	Some emergency repairs to the roof coverings have been carried out in 2018.
	OCCUPANCY:	Vacant/not in use	
and the second sec	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
© Historic England	LIST ENTRY NUMBER:	1341062	Contact: Katy Hoskyn 0117 975 1311

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; в solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument
- SM UA WHS
 - Unitary Authority World Heritage Site

HERITAGE AT RISK 2021 / SOUTH WEST / COTSWOLD

		Church of St Peter, Daylesford, Adlestrop	Parish church in the high Gothic style by JL Pearson 1863. Cruciform plan with a pyramidal spire. Limestone with red
A.	DESIGNATION:	Listed Place of Worship grade I, CA	sandstone features, stone slate roofs. The stone slates are slipping or fractured and need renewal. The sandstone colonettes are heavily eroded on the outside and are
	CONDITION:	Very bad	structurally unsafe. The church is now owned by the St Peter's Daylesford Charitable Trust and shares services
	PRIORITY CATEGORY:	A (A)	between the Church of England and the Roman Catholic
	OWNER TYPE:	Religious organisation	church.
	LIST ENTRY NUMBER:	1341122	Contact: Chris Miners 0117 975 1355
listoric England			

© Hist



	SITE NAME:	Church of St Edward, Evenlode	Parish church. C12, C14, C19 vestry and porch,
	DESIGNATION:	Listed Place of Worship grade II*, CA	restoration by JEK Cutts 1879. Coursed squared and dressed limestone and sandstone. Stone slate roof. Plan: nave with north vestry, south aisle, projecting porch from
	CONDITION:	Poor	west end of south aisle, west tower, chancel. The stone slate roofs, especially on the south side, have reached the
	PRIORITY CATEGORY:	C (C)	end of their life and need renewal.
M	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1089794	Contact: Chris Miners 0117 975 1355

© Historic England

SITE NAME:	Two bowl barrows 690 metres and 790 metres north of The Manor Farm, Avening		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017337
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
site name:	Perrott's Brook dykes, Bagendon / North Cerney		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003436
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Long barrow 800 metres north east of Oldwalls Fa	rm, Bibury	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018163
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	West Barrow: a long barrow 200 metres west of L	eighterton School,	Boxwell with Leighterton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013590
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Animal burrowing - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Chedworth Roman villa, Chedworth		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003324
		LIST ENTRY NUMBER:	1003324 Declining
DESIGNATION:	Scheduled Monument Generally satisfactory but with significant localised		

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В

implemented. C Slow decay; no solution agreed.

use).

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / SOUTH WEST / COTSWOLD

SITE NAME:	Settlement south east of Chesterton Farm, Cirence	ester / Siddington	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003444
CONDITION:	Extensive significant problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Three bowl barrows, known as Emma's Grove rou	nd barrows, Cober	ley
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017079
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Two bowl barrows, known as Crippet's Wood rou Dryhill Farm, Coberley	ind barrows, 560 m	netres and 590 metres north east of
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017041
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Tump Barn bowl barrow, Didmarton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016077
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Camp at Upper Dowdeswell, Dowdeswell		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1003321
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Hoar Stone long barrow, Duntisbourne Abbots		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018161
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow in Three Ash Belt, 460 metres north	east of Westwood	Farm, Edgeworth
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016840
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / SOUTH WEST / COTSWOLD

SITE NAME:	Icomb camp, Icomb		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003342
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	The Chessalls Roman town, Kingscote / Wotton	-under-Edge	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018607
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Metal detecting - unlicensed	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Summerhill prehistoric site, Naunton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003339
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow in Inlands Plantation, 650 metres so	outh of Hazleton Mar	nor Farm, Rodmarton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008788
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Hullasey Grove medieval village site, Rodmarton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003359
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow 120 metres north of Home Farm,	Sherborne	
DESIGNATION:	Scheduled Monument, RPG grade II, CA	LIST ENTRY NUMBER:	1017082
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	South Cerney castle, South Cerney		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003422
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Four bowl barrows forming part of a round barr Hill Farm, Upper Slaughter	ow cemetery, and a l	ong barrow 550 metres NNE of Eyford
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020987
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / SOUTH WEST / FOREST OF DEAN

LIST ENTRY NUMBER:

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

FOREST OF DEAN



Blakeney United Reformed SITE NAME Church, Cinderford Road, Blakeney, Awre DESIGNATION: Listed Building grade II* CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Private

1186386

Former non-conformist chapel, dated 1849. Remarkably complete and architecturally distinctive example of its type. Stonework repairs required.

The docks and harbour date from c1810 to 1821 and were

district. The Inner Basin is still in poor condition and needs

extensive repairs. The Environment Agency has advertised

being resolved. A local partnership group through the Local

Authority are looking for funding to repair some structures and enhance the visitor experience of the site. Work has

also been on-going to clear and control vegetation on the

the site and selected a preferred bidder to take over the ownership of the site. The final details of this sale are still

once the main commercial port serving industry in the

Contact: Katy Hoskyn 0117 975 1311

© Historic England Archive



Gunns Mill Furnace, Littledean Formerly a C17 charcoal blast furnace and later an C18 SITE NAME: paper mill. Now unused and in perilous condition, despite Scheduled Monument and Listed some emergency holding repairs. The Forest of Dean DESIGNATION: Building grade II* Building Preservation Trust is working with Historic England to secure the future of the building. Funding to CONDITION: Very bad date has completed various surveys and improved the landscape and setting. The mill wheel pit structure was repaired wth Historic England Repair grant aid in 2020 and OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: B (B) the collapsing north wall in 2021. Surveys of the roof strructures are scheduled to develop the repair of the OWNER TYPE: Charity (heritage) timber-framed elements. LIST ENTRY NUMBER: 1002080 and 1186479 Contact: Melanie Barge 0117 975 1300

site.

© Historic England Archive



© Historic England



SITE NAME:

LIST ENTRY NUMBER: 1002079 and 1338556 Contact: Melanie Barge 0117 975 1300 CI5 or early CI6 tithe barn built for the Abbey of St Peter, Tithe Barn, Highleadon Court, Gloucester. The roof is sound, but the framing and infill Rudford and Highleadon panels are deteriorating. Used for agricultural storage. DESIGNATION: Listed Building grade II* Some maintenance has been undertaken. CONDITION: Poor OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C (C) OWNER TYPE: Private

Lydney Docks and Harbour,

Scheduled Monument and Listed

Naas Lane, Lydney

Government or agency

Building grade II

Poor

N/A

C (C)

1152574

© Historic England Archive



SITE NAME:	Church of St Mary the Virgin, Flaxley, Blaisdon	Parish church, 1856, by Sir George Gilbert Scott. Red sandstone ashlar, with grey sandstone ashlar dressings,
DESIGNATION:	Listed Place of Worship grade II*	timber porch, tiled roof with crested ridge, shingles to spire. Nave, north aisle, with tower at its west end,
CONDITION:	Poor	chancel, organ chamber and south porch. The nave roofs have had repairs, however the chancel and organ chamber
PRIORITY CATEGORY:	C (C)	roofs need urgent re-tiling. Covid Recovery Fund grant
OWNER TYPE:	Religious organisation	funding has repaired the chancel roof however the spire shingling needs renewing following woodpecker damage.
LIST ENTRY NUMBER:	1186458	Contact: Chris Miners 0117 975 1355

© Historic England

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed. С
- Slow decay; solution agreed but not yet implemented. Under repair or in fair to good

D

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

Contact: Chris Miners 0117 975 1355

ABBREVIATIONS

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ΪA
- Unitary Authority World Heritage Site ŴĤS

148

HERITAGE AT RISK 2021 / SOUTH WEST / FOREST OF DEAN

	SITE NAME:	Church of St Michael and All Angels, Blaisdon	Parish church, C15 tower, the rest rebuilt 1867-9 by FR Kempson of Hereford in the Early English style. Tower thin
ALL I	DESIGNATION:	Listed Place of Worship grade II	coursed rubble, church squared red Forest stone with Bath stone ashlar dressings; slate roof. West tower, four-bay
and in	CONDITION: PRIORITY CATEGORY:	Poor	nave, with north aisle, chancel with vestry, south entrance porch. The damp penetration into the church stonework at
		C (C)	both high and low level put the building at risk. A Listed
-	OWNER TYPE:	Religious organisation	Places of Worship Roof Repairs Grant was accepted in 2015 for repairs which have addressed some of the issues.
	LIST ENTRY NUMBER:	1299195	Contact: Chris Miners 0117 975 1355

© Historic England

	SITE NAME:	Church of St Saviour, Redbrook, Newland	Small parish church, now sharing community hall uses, by JP Seddon in 1873. Nave with south porch and chancel with
	DESIGNATION:	Listed Place of Worship grade II	south chapel and bellcote; in red sandstone with buff limestone dressings. The limestone and sandstone mix has
	CONDITION:	Very bad	been auto-destructive with severe erosion of the sandstone on the north wall and to the limestone on the
	PRIORITY CATEGORY:	A (A)	dressings on the south side. The tiled roof on the south
	OWNER TYPE:	Religious organisation	nave pitch has slipped or missing tiles.
	LIST ENTRY NUMBER:	1212814	Contact: Chris Miners 0117 975 1355

© Historic England

L	SITE NAME:	Church of St Bartholomew, The Causeway, Redmarley D'abitot	Large parish church of sandstone ashlar with tiled roofs. C13, and part of the tower probably dates from that time;
A A	DESIGNATION:	Listed Place of Worship grade II, CA	but the majority of the building goes back only to 1855 when most of the church was in serious disrepair, demolished and rebuilt. The stonework of the tower is
THE ALLERY OF	CONDITION:	Poor	seriously eroded with open jointing and structural cracking and rainwater disposal problems. Some falls of stone have
	PRIORITY CATEGORY:	A (A)	been reported.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1341976	Contact: Chris Miners 0117 975 1355

© Historic England

SITE NAME:	Whitecliff Iron Works, Coleford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021420
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Melanie Barge 0117 975 1300
SITE NAME:	Offa's Dyke: section in Caswell Wood, 280 metres	west of Beeches F	arm, Tidenham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020601
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Offa's Dyke: section in Chapelhouse Wood, 240 m	etres west of the R	Recreation Ground, Tidenham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020639
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / SOUTH WEST / FOREST OF DEAN / GLOUCESTER

SITE NAME:	Offa's Dyke: section in Lippets Grove, 680 metres	WSW of Beeches	Farm, Tidenham	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020602	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - Badger - moderate	NEW ENTRY?:	No	
OWNER TYPE:	Government or agency	CONTACT:	Katy Hoskyn 0117 975 1311	
SITE NAME:	Offa's Dyke: section in Passage Grove, 660 metres	west of Sheepcot,	Tidenham	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020603	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311	
SITE NAME:	Offa's Dyke: section in Worgan's Wood, 800 metr	Offa's Dyke: section in Worgan's Wood, 800 metres west of Chase Farm, Tidenham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020605	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving	
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No	
OWNER TYPE:	Government or agency	CONTACT:	Katy Hoskyn 0117 975 1311	
SITE NAME:	Roman villa 600 yards (550 metres) south west of	Woolaston Station	, Woolaston	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004860	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311	

GLOUCESTER

© Historic England

Westgate Street	Church of St Nicholas, Westgate Street	Large urban church made redundant in 1971 and vested with the Churches Conservation Trust in 1975. Nave and	
	DESIGNATION:	Listed Building grade I, CA	flanking aisles with west tower sumounted by a truncated leaning stone spire. CI2 origins with mostly CI3 fabric and
	CONDITION:	Poor	a C15 tower. The roof structure needs urgent structural repair and slate roof coverings have come to the end of
	OCCUPANCY:	Vacant/not in use	their life.
PRIORITY CATEGORY: C (C) OWNER TYPE: Charity (heritage)		C (C)	
		Charity (heritage)	
	LIST ENTRY NUMBER:	1245083	Contact: Chris Miners 0117 975 1355



SITE NAME:	New Inn, 16, 18 and 20, Northgate Street	Mid C15 inn. Four timber-framed ranges around a central courtyard forming the most complete example of a
DESIGNATION:	Listed Building grade I, CA	medieval courtyard inn with galleries. In partial use but areas of the building are in poor repair due to long periods
CONDITION:	Poor	of neglect. Some repairs and maintenance ongoing with current owners. Repairs following a fire in 2018 have
OCCUPANCY:	Part occupied/part in use	highlighted the poor condition of the building.
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1245714	Contact: Chris Miners 0117 975 1355

© Gloucester City Council

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

use).

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / SOUTH WEST / GLOUCESTER

© Gloucester City Council	SITE NAME:	Llanthony Priory, remains of precinct wall north of Inner Gatehouse, Llanthony Road, Gloucester	Stone and brick wall on the west and north sides of the Outer Court of the former Augustinian Priory. Built in the C15, it was rebuilt or extended in the C17 and C18. The Llanthony Priory Trust successfully bid for National Lottery
	DESIGNATION:	Scheduled Monument and Listed Buildings - 6 grade I, LB grade II, part in CA	Heritage Fund grant and repair works to most of the Priory site are now complete. This length of wall will remain unrepaired for the short term due to budget constraints.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Charity (heritage)	
	LIST ENTRY NUMBER:	1002091 and 1271693; 1271697; 1271694; 1271696; 1271695; 1271698	Contact: Chris Miners 0117 975 1355

Westgate Street, Gloucester

Listed Building grade I, CA

Part occupied/part in use

Commercial company

Poor

D (D)



4		Old ludges House, 26.	Contact: Stephen Guy 0117 975 0725 Late C15 timber-framed merchant house, greatly enlarged	
	LIST ENTRY NUMBER:	1245447		
E	Local authority	development works in association with Historic England funding through the High Street Heritage Action Zone.		
	D (D)	Options Appraisal have now been produced. The council are presently seeking funding for conservation and		
	OCCUPANCY: Vacant/not in use	Vacant/not in use	emergency repairs, and a Timber Frame Report and	
DESIGNATION: Listed Building grade I, CA CONDITION: Poor	more information on the condition. Ownership passed to Gloucester City Council in 2011 who have done some			
	Listed Building grade I, CA	poor repair, with some internal decay. A series of opening up works were carried out early summer 2010 to provide		
SITE NAME: The Fleece Hotel, 19, West Street, Gloucester	The Fleece Hotel, 19, Westgate Street, Gloucester	Fleece Hotel. The building was vacant for some time. It is in		

and remodelled in late CI6/early CI7. Refronted and

undertaken, there remain many areas which require

altered internally c1815. Operated as seed merchant for

c100 years until 1989, then partly occupied as bookshop, before becoming vacant. Whilst some repairs have been

attention, particularly the roof and significant joinery. The

yet in use. The owner is seeking match funding for roof repairs through Gloucester's High Street Heritage Action

upper floors are now accessible via a new lift, although not

© Historic England



DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

© Historic England



	LIST ENTRY NUMBER:	1245450	Contact: Stephen Guy 0117 975 0725
	SITE NAME:	Christ Church, Brunswick Road, Gloucester	Urban church built 1823 by Rickman and Hutchinson; West front remodelled iin the French Romanesque style with
ĺ	DESIGNATION:	Listed Place of Worship grade II, CA	terra cotta detailing 1899-1900 by H A Prothero. Orientated north-west to south-east and includes a nave of seven bays, a sanctuary with projecting polygonal apse,
	CONDITION:	Poor	north vestry and west gallery. The west front comprises an added wide bay. Stuccoed brick with vermilion terracotta
	PRIORITY CATEGORY:	D (New entry)	and grey roughcast dressings. The roof is clad in slate. Long
	OWNER TYPE:	Religious organisation	term water ingress has manifested itself with significant falls of plaster.at high level. A Covid Recovery Fund Grant has
12	LIST ENTRY NUMBER:	1245963	developed a repair project.
			Contact: Chris Miners 0117 975 1355

Zone scheme.

© Historic England

SITE NAME:	Barton Street, Gloucester		
DESIGNATION:	Conservation Area, 5 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Charlotte Bowles-Lewis (LPA) 01452 396855

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
 - Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

STROUD

	SITE NAME:	Guise Mausoleum to north west of Church of St John the Baptist, Stroud Road, Brookthorpe, Elmore	Built in 1733 for Sir John Guise of Elmore Court and his family in neoclassical style, as an exact copy of what the commissioner thought to be Virgil's tomb in Italy. The monument, which includes a burial vault, has been left
	DESIGNATION:	Listed Building grade II*	ruinous after the collapse of its pyramidal roof in the early C20. The ashlar and decorative elements which remain
	CONDITION:	Very bad	have been affected by weathering and erosion. In 2019 Historic England grant aided a programme of surveys and
	OCCUPANCY:	N/A	vegetation removal to inform the future consolidation of
	PRIORITY CATEGORY:	C (C)	the monument.
© Historic England	OWNER TYPE:	Charity (heritage)	
	LIST ENTRY NUMBER:	1247875	Contact: Katy Hoskyn 0117 975 1311
	SITE NAME:	Main building at Stanley Mills, Ryeford, King's Stanley	Woollen mill, 1813. Ancillary building (grade II) is in poor condition and part occupied. Roof repaired with Historic
No. Contraction of the second	DESIGNATION:	Listed Building grade I, CA	England grant. A proposal for repair and conservation was granted consent in 2011. The planning permission has been
	CONDITION:	Fair	implemented by a commencement on the factory building and the enabling development has now also started on site.
	OCCUPANCY:	Part occupied/part in use	Main works to the mill are yet to begin and condition is
	PRIORITY CATEGORY:	D (D)	deteriorating. Temporary repairs have been carried out to areas of the roof following heritage crime in 2017.
and the second	OWNER TYPE:	Commercial company	5 5
© Historic England	LIST ENTRY NUMBER:	1171285	Contact: Stephen Guy 0117 975 0725
	SITE NAME:	St Mary's House, London Road,	Former mill owner's house and weavers' cottages, late CI6

Old Mill Building at Longfords

Listed Building grade II*, CA

Mills, Avening Valley,

Minchinhampton

Vacant/not in use

Commercial company

Fair

D (D)

1305339



© Historic	England	Archive

© Historic England



SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

and late C17. Roof in exceptionally poor condition and has Minchinhampton been covered with tarpaulin for over 30 years. There are DESIGNATION: Listed Building grade II*, CA signs of detachment of the shell hood over the front door and external joinery continues to deteriorate. The property CONDITION: Poor has recently changed ownership and the local planning OCCUPANCY: Part occupied/part in use authority aims to engage with the owner to seek remedial and longer term repairs. PRIORITY CATEGORY: A (A) OWNER TYPE: Private LIST ENTRY NUMBER: 1091156 Contact: Stephen Guy 0117 975 0725

> Centrepiece of an extensive industrial complex, from 1766. This is one of two buildings on site to remain vacant after a residential redevelopment that has refurbished and re-used the rest of the complex. Repairs and conservation proposals are being explored by a local Trust.

Contact: Katy Hoskyn 0117 975 1311

	SITE NAME:	Woodchester Mansion, Woodchester	Mansion c1854-68 incorporating a magnificent private chapel. The Woodchester Mansion Trust was formed in
	DESIGNATION:	Listed Building grade I, RPG grade II	1989 to do a continuous programme of conservation and display of the uncompleted Gothic-style masterpiece. In 1991 a protective scaffold was built to cover the leaking
	CONDITION:	Very bad	roof of the chapel. The scaffold is now decaying and unsa Other adjacent roofs then developed serious faults. The
	OCCUPANCY:	Vacant/not in use	east range roofs and north range chimneys have just been
	PRIORITY CATEGORY:	A (B)	repaired with Historic England and Historic Houses Foundation grant aid but the chapel and other roofs are
	OWNER TYPE:	Charity (heritage)	steadily deteriorating.
	LIST ENTRY NUMBER:	1340703	Contact: Chris Miners 0117 975 1355

PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA LB
- I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM ŬA
- Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2021 / SOUTH WEST / STROUD

	SITE NAME:	Church of St Mary, Church Road, Arlingham	Large rural church in a small village. West tower, nave and east chancel with a south entrance porch. C14, restored
	DESIGNATION:	Listed Place of Worship grade I, CA	c1868 and with north vestry of 1864. Roughcast faced, with ashlar tower and dressings. Stone slate roofs with coped verges. Three-stage tower with stepped diagonal buttresses, with parapet of pierced trefoils, and pitched roof. The south roof slopes are badly in need of repair. A
	CONDITION:	Poor	
	PRIORITY CATEGORY:	C (New entry)	Covid Recovery Fund Grant developed a repair project.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1340704	Contact: Chris Miners 0117 975 1355
© Historic England			



SITE NAME:	Church of St Mary the Virgin, Church Lane, Berkeley	Parish church. C12 foundation on probable site of important early medieval minster church, altered in C13
DESIGNATION:	Listed Place of Worship grade I, CA	and C15, and in C19. Random coursed rubblestone, roofs with coped verges and cross finials. Nave and aisles of seven bays with clerestory windows to south only, north
CONDITION:	Very bad	porch, lower chancel with flanking chapels. The roof has been extensively repaired. The extensive interior wall
PRIORITY CATEGORY:	C (C)	paintings continue to decay.
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1304581	Contact: Chris Miners 0117 975 1355

© Historic England

SITE NAME:	Church of St Mary, Fretherne with Saul	Largel mid-Victorian parish church in an isolated site. Ornate in the decorated style of sandstone with limestone
DESIGNATION:	Listed Place of Worship grade II*	dressings. There has been a loss of stonework with many falls of carved features.
CONDITION:	Poor	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1154542	Contact: Chris Miners 0117 975 1355
	DESIGNATION: CONDITION: PRIORITY CATEGORY: OWNER TYPE:	with SaulDESIGNATION:Listed Place of Worship grade II*CONDITION:PoorPRIORITY CATEGORY:C (C)OWNER TYPE:Religious organisation

© Historic England

	SITE NAME:	Church of St James, Fretherne with Saul	Church said to date originally from 1140, with elements from C15 and C16. Enlarged and restored at different
	DESIGNATION:	Listed Place of Worship grade II*, CA	times in C19. Roof coverings, which vary from stone slate on some areas to concrete tiles on others, are in very bad condition. The rainwater goods need repairing and
	CONDITION:	Very bad	replacing where previous patch repairs have failed. The stonework of the tower is delaminated in places.
	PRIORITY CATEGORY:	C (C)	stonework of the tower is detaininated in places.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1090510	Contact: Chris Miners 0117 975 1355
land			

© Historic Engla



	SITE NAME:	Church of St Giles, High Street, Hillesley, Hillesley and Tresham	Church, 1851 by Reverend B Perkins, Vicar of Wotton Under Edge, in Early English style. Coursed rubble with
L.L	DESIGNATION:	Listed Place of Worship grade II	freestone dressing; Cotswold stone slate roofs. Nave with clerestory, north and south aisles, chancel and south porch.
V	CONDITION:	Poor	The roofs at east end of the church have stone slates in bad condition.
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1129364	Contact: Chris Miners 0117 975 1355

© Historic England

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user latentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / SOUTH WEST / STROUD

Poor

A (A)



Small church. Cll foundation, earliest work probably of Church of St Andrew, CI4, altered and tower added late CI5/early CI6, north Whitminster aisle added 1842, restored c1884-5 by Sir Arthur Listed Place of Worship grade Blomfield. Random coursed and dressed stone, ashlar II*, CA tower and part ashlar walls, stone slate roof with coped east verges with saddle stones and cross finials. West tower, nave with south porch and north aisle, chancel, with north vestry of 1880s. The stone slates have slipped or fallen on the nave and north aisle pitches and the porch. Religious organisation 1303052 Contact: Chris Miners 0117 975 1355

© Historic England

SITE NAME: Bowl barrow 450 metres south east of Up DESIGNATION: Scheduled Monument CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing	pper Hyde Farm, Minchinha List entry number: trend:	1008626
CONDITION: Extensive significant problems		
	TREND:	Declining
PRINCIPAL VULNERABILITY: Arable plaughing		Declining
Alable plougining	NEW ENTRY ?:	No
OWNER TYPE: Commercial company	CONTACT:	Katy Hoskyn 0117 975 1311
ITE NAME: Miserden Castle mound, Miserden		
DESIGNATION: Scheduled Monument, RPG grade II*	LIST ENTRY NUMBER:	1004870
CONDITION: Generally satisfactory but with significant lo problems	calised _{TREND:}	Declining
PRINCIPAL VULNERABILITY: Forestry	NEW ENTRY ?:	No
DWNER TYPE: Private	CONTACT:	Katy Hoskyn 0117 975 1311
Bowl barrow 720 metres south east of Los	ngwood Farm, Woodchest	er
DESIGNATION: Scheduled Monument	LIST ENTRY NUMBER:	1017084
CONDITION: Extensive significant problems	TREND:	Declining
RINCIPAL VULNERABILITY: Arable ploughing	NEW ENTRY ?:	No
DWNER TYPE: Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME: Bowl barrow 330 metres north of Symon	ds' Hall Farm, Wotton-unde	er-Edge
DESIGNATION: Scheduled Monument	LIST ENTRY NUMBER:	1017083
CONDITION: Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY: Arable ploughing	NEW ENTRY?:	No
OWNER TYPE: Private	CONTACT:	Katy Hoskyn 0117 975 1311
ITE NAME: Stanley Mills, Kings Stanley, King's Stanley	/ Stonehouse	
DESIGNATION: Conservation Area, 7 LBs	NEW ENTRY?:	No
CONDITION: Very bad	TREND:	Deteriorating
/ULNERABILITY: High	CONTACT:	Kate Russell (LPA) 01453 766321
Stroud Industrial Heritage (IHCA), Multiple ITE NAME: Bisley-with-Lypiatt / Brimscombe and Thru	upp / Cainscross / Chalford	
Fretherne with Saul / King's Stanley / Leon		
	NEW ENTRY?:	No
Fretherne with Saul / King's Stanley / Leon		No Deteriorating

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA WHS
 - Unitary Authority World Heritage Site

OWNER TYPE:

LIST ENTRY NUMBER:

TEWKESBURY



© Mr John Brookes. Source Historic

England Archive.

SITE NAME: Dovecote approximately 75 metres south east of Manor Farm, Ashchurch, Ashchurch Rural DESIGNATION: Listed Building grade II* CONDITION: Poor OCCUPANCY. N/A PRIORITY CATEGORY: C (C)

Private

1091923


Dovecote, 1637. Pointing eroded particularly on the north face. Occasional missing roof tiles, although some roofing works have taken place.


Contact: Katy Hoskyn 0117 975 1311



	SITE NAME:	Dovecote three metres north of Bridge House, Bentham, Badgeworth	Dovecote, C17. Movement of structural timbers on south east and north east walls has caused joints to pull apart, leading to brick panels falling out. Wattle and daub panels
	DESIGNATION:	Listed Building grade II*	are fragmenting. Some timber decay on the west side and cement repairs to the roof are also of concern.
	CONDITION:	Poor	
il in	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1304753	Contact: Katy Hoskyn 0117 975 1311

© Historic England





© Historic England



	SITE NAME:	Malthouse to the rear of 23,	Workshop, former malthouse. C17. Building has been
		Barton Street, Tewkesbury	unoccupied for some time. Listed Building Consent was approved in 2016 for conversion from a workshop to a
	DESIGNATION:	Listed Building grade II*, CA	dwelling. However, the permission has not been
N/M	CONDITION:	Poor	implemented and work is yet to start.
	OCCUPANCY:	Vacant/not in use	
and a	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1281018	Contact: Stephen Guy 0117 975 0725

PRIORITY CATEGORIES

© Tewkesbury Borough Council

Immediate risk of further rapid deterioration or loss of fabric; no

D

Е

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ΪA
- Unitary Authority World Heritage Site ŴĤS

HERITAGE AT RISK 2021 / SOUTH WEST / TEWKESBURY

	SITE NAME:	88, Church Street, Tewkesbury	Late C15 town house, altered C16 and C19, with shop
	DESIGNATION:	Listed Building grade II*, CA	under. Building only partly occupied and in poor condition with broken windows on second floor.
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private, multiple owners	
	LIST ENTRY NUMBER:	1205905	Contact: Katy Hoskyn 0117 975 1311

© Tewkesbury Borough Council

a Astr	SITE NAME:	Toddington Manor, Toddington	Manor house, 1820-35, set in C19 formal gardens, on the
	DESIGNATION:	Listed Building grade I, RPG grade II	east side of a late C18 landscape park. The house was mothballed for more than 15 years, but has been purchased by a new owner who engaged in an extensive
HI-H-HARD	CONDITION:	Fair	programme of urgent works and repairs in consultation with the Local Planning Authority and Historic England.
	OCCUPANCY:	Vacant/not in use	Following extensive stabilisation work, a temporary
	PRIORITY CATEGORY:	F (F)	protective roof was installed and is in good order. There is no apparent further deterioration to fabric. Discussions
Provide States	OWNER TYPE:	Private	with the owner's agent regarding building repairs have yet to progress to a formal Listed Building Consent.
© Historic England Archive	LIST ENTRY NUMBER:	1340101	Contact: Stephen Guy 0117 975 0725

	SITE NAME:	Church of St John the Baptist, Oxenton	Parish church. C13, C14 and C15, restored 1905. Nave and chancel coursed limestone rubble except the south wall of chancel which is coursed squared and dressed limestone. Porch and north aisle also coursed squared ar dressed limestone. Tower and mortuary chapel: ashlar; stone slate roof. Nave with north aisle with mortuary
	DESIGNATION:	Listed Place of Worship grade I	
	CONDITION:	Poor	
	PRIORITY CATEGORY:	C (C)	chapel at right angles, chancel and west tower. The key
	OWNER TYPE:	Religious organisation	issue is the decay of the interior plaster and the threat that this poses to the wall paintings.
	LIST ENTRY NUMBER:	1303393	Contact: Chris Miners 0117 975 1355

© Historic England

	SITE NAME:	Church of St Martin, Charlton Abbotts, Sudeley	Tiny parish church in a small hillside churchyard. Nave with south porch and north vestry and lower chancel all in
	DESIGNATION:	Listed Place of Worship grade II	limestone ashlar. All from an 1887 rebuild of a ruin, incorporating medieval features, except for the vestry
	CONDITION:	Poor	added in 1933. Graduated limestone slate roofs which are in need of repair especially on the north side.
	PRIORITY CATEGORY:	C (C)	inneed on epair especially on the north side.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1340100	Contact: Chris Miners 0117 975 1355

© Historic England

SITE NAME:	Great Witcombe Romano-British villa, Brockworth / Great Witcombe			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014826	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	Katy Hoskyn 0117 975 1311		
SITE NAME:	Over earthwork, Highnam			
SITE NAME: DESIGNATION:	Over earthwork, Highnam Scheduled Monument	LIST ENTRY NUMBER:	1002092	
		LIST ENTRY NUMBER: TREND:	1002092 Declining	
DESIGNATION:	Scheduled Monument Generally unsatisfactory with major localised			

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / SOUTH WEST / TEWKESBURY / ISLES OF SCILLY (UA)

	(-)		
SITE NAME:	Hailes Wood camp, Hailes, Stanway		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004843
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Milhampost Roman site, Stanway		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004844
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE: Private		CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Spoonley Wood Roman villa, Sudeley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004847
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY: Scrub/tree growth NEW		NEW ENTRY?:	No
OWNER TYPE: Private		CONTACT:	Melanie Barge 0117 975 1300
SITE NAME:	Wadfield Roman villa, Sudeley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004846
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Romano-British villa 170 metres south west of V	Vinchcombe School, (Greet Road, Winchcombe
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021449
CONDITION:	Extensive significant problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Katy Hoskyn 0117 975 1311

ISLES OF SCILLY (UA)



© Historic England Archive

	SITE NAME:	Late C19-early C20 Woolpack Battery on The Garrison, St. Mary's	Late C19/early C20 battery. Generally good condition and secure but unoccupied since 2015. Converted to volunteer hostel accommodation in late C20/early C21 but now
	DESIGNATION:	Scheduled Monument, LB grade II, CA	suffering from problems with water ingress into the former magazines, now dormitories. Discussions regarding repair and potential new uses are underway with the site owner,
	CONDITION:	Poor	and the Local Authority.
1	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Crown	
	LIST ENTRY NUMBER:	1014783	Contact: Helen Woodhouse 0117 975 0676

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Post-medieval cottages, Samson, Tresco	Fossilised C18/C19 landscape. The remains of the buildings are at risk from natural weathering, vegetation
	DESIGNATION:	Scheduled Monument, part in CA	and erosion caused by visitors. A management plan has been devised and initial phase of consolidation grant-aided by Historic England is now complete. The results of the
A State of the sta	CONDITION:	Poor	consolidation trials are being studied to ultimately inform a wider programme of repair.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
© Historic England Archive	OWNER TYPE:	Crown	
	LIST ENTRY NUMBER:	1016509	Contact: Ann Preston-Jones 07917 642388

SITE NAME:	Civil War battery on The Green, Bryher			
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1010176	
CONDITION:	Generally unsatisfactory with major localised problems	Declining		
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - moderate	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Gig shed on the north coast of Great Porth, Bryhe	r		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1016173	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Dumping	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Prehistoric enclosure south east of The Brow, Bry	her		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1015649	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY ?:	No	
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Prehistoric field system and post-medieval quay in Great Porth, Bryher			
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1014987	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Prehistoric field system and Romano-British cist in	Green Bay, Bryher		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1014989	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Prehistoric hut circle south of The Brow, Bryher			
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1014990	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В

implemented. C Slow decay; no solution agreed.

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / SOU	JTH WEST / ISLES OF SCILLY (UA)			
SITE NAME:	Prehistoric linear boundary and cairns south west	of The Bar, Bryher		
DESIGNATION:	Scheduled Monument, CA	1016170		
CONDITION:	Generally satisfactory but with significant localised problems	Declining		
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No	
OWNER TYPE:	TYPE: Crown CONTACT: Ann Preston-Jone			
SITE NAME:	Prehistoric linear boundary SSE of The Island, Bryher			
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1014991	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY ?:	No	
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Prehistoric cairns, entrance graves, field system an Gugh, St. Agnes	d settlements and p	oost-medieval kelp pits on Kittern Hill	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1014792	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No	
OWNER TYPE:	Crown	Nick Russell 0117 975 0671		
SITE NAME:	Prehistoric entrance grave and two round cairns o	n the Clapper of W	/orks, Gugh, St. Agnes	
DESIGNATION:	Scheduled Monument, CA LIST ENTRY NUMBER:		1008337	
CONDITION:	Generally satisfactory but with significant localised TREND: Dec problems		Declining	
PRINCIPAL VULNERABILITY:	Plant growth NEW ENTRY: No		No	
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Prehistoric field system and post-medieval breastw	ork and maze on C	Castella Down, St. Agnes	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1015697	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Kerbed round cairn with central cist on Gun Hill,	St. Martin's		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1013809	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth - General NEW ENTRY?: No		No	
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Platform cairn on Turfy Hill, St. Martin's			
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1018114	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth NEW ENTRY?: No			
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Prehistoric cairn cemetery and field system on Tinkler's Hill, St. Martin's			
DESIGNATION:	Scheduled Monument, CA LIST ENTRY NUMBER: 1018109		1018109	
CONDITION:	Generally satisfactory but with significant localised TREND: Declining problems			
PRINCIPAL VULNERABILITY:	Scrub/tree growth	No		
OWNER TYPE:	TYPE: Crown CONTACT: Ann Preston-Jones			
SITE NAME:	Prehistoric entrance grave, the middle one of three on Cruther's Hill, St. Martin's			
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1013804	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Prehistoric entrance grave, the northern one of th	ree on Cruther's H	ill, St. Martin's	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1013803	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388	
ITE NAME:	Prehistoric entrance grave, the southern one of three, and kerbed round cairn with cist on Cruther's Hill, S Martin's			
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1013805	
CONDITION:	Generally unsatisfactory with major localised TREND: Decli		Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth NEW ENTRY?: No		No	
OWNER TYPE:	Crown CONTACT:		Ann Preston-Jones 07917 642388	
SITE NAME:	Prehistoric field system and kerbed cairn, with pos Island, St. Martin's	t-medieval kelp pit	and linear boundary on southern Wh	
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1014789	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Nick Russell 0117 975 0671	
SITE NAME:	Ennor Castle, Old Town, St. Mary's			
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1014994	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Hut circle settlement in Pendrathen, St. Mary's			
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1015663	
CONDITION:	Extensive significant problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Post-medieval breastwork, curtain wall and associated defensive structures on the periphery of The Garrison St. Mary's			
DESIGNATION:	Scheduled Monument, LB grade I, CA	LIST ENTRY NUMBER:	1018370	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	The Old Quay, Old Town Bay, St. Mary's			
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1015656	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	World War II pillbox between Thomas' Porth and I	Porthaloo, St. Mar	y's	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1016517	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No	
OWNER TYPE:	WNER TYPE: Crown CONTACT:			
SITE NAME:	World War II pillbox west of Porth Hellick, 90 metres north of Drum Rock, St. Mary's			
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1016516	
CONDITION:	Extensive significant problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	ITY: Plant growth NEW ENTRY?: No		No	
OWNER TYPE:	Crown CONTACT:		Ann Preston-Jones 07917 642388	
SITE NAME:	Prehistoric cairn group on Abbey Hill, Tresco			
DESIGNATION:	Scheduled Monument, LB grade I, RPG grade I, CA	LIST ENTRY NUMBER:	1016183	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Visitor erosion - limited/localised	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Prehistoric field system and hut circle north of Cral	b's Ledge, Tresco		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1016422	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No	
OWNER TYPE:	Crown CONTACT: Ann Preston-Jones		Ann Preston-Jones 07917 642388	
SITE NAME:	Prehistoric field system and settlement in Bathingho	ouse Porth, Tresco		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1016423	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. В
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / SOUTH WEST / ISLES OF SCILLY (UA) / NORTH SOMERSET (UA)

SITE NAME:	Prehistoric field system and settlement north of Appletree Point, Tresco			
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1016182	
CONDITION:	Unknown	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Prehistoric to post-medieval funerary, field system and settlement remains, with post-medieval kelp pit an deer park on and adjacent to Samson, Tresco		nains, with post-medieval kelp pit and	
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1016509	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY ?:	No	
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	St Nicholas' Priory, Tresco			
DESIGNATION:	Scheduled Monument, LB grade I, RPG grade I, CA	LIST ENTRY NUMBER:	1016184	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388	

NORTH SOMERSET (UA)

	SITE NAME:	Ashton Court, Long Ashton	Large country house with various elements dating from
	DESIGNATION:	Listed Building grade I, RPG grade II*	C15, C17, C18 and C19. House partly used but large part remains derelict and subject to slow but ongoing decay. The house has been the subject of negotiations between
	CONDITION:	Very bad	owners, Local Planning Authority, Historic England and other interested parties for many years. Historic England
	OCCUPANCY:	Part occupied/part in use	grant offered in 2011 for project development work, the
	PRIORITY CATEGORY:	C (C)	majority of which was completed by 2013. Options Appraisal completed for Bristol City Council in May 2019.
	OWNER TYPE:	Local authority	Historic England in ongoing discussions with Bristol City Council.
c England	LIST ENTRY NUMBER:	2984	Contact: Sarah Ball 0117 975 0666

1	SITE NAME:	Elms Colliery, Nailsea	Known locally as Middle Engine Pit, this is one of the most
- Internet	DESIGNATION:	Scheduled Monument and Listed Building grade II	complete examples of an early C19 colliery in England. However the surviving structures are in a poor and vulnerable condition. In 2019 Historic England grant-aided
	CONDITION:	Poor	a programme of investigations, recording and stabilisation to some of the most vulnerable structures on site.
	OCCUPANCY: Vacant/not in use	Vacant/not in use	to some of the most value able stratter is on site.
	PRIORITY CATEGORY:	C (A)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1004533 and 1320976	Contact: Alessandra Perrone 0117 975 1345

© Historic England

mni

© Historic



F	SITE NAME:	Birnbeck Pier, Weston-Super- Mare	Birnbeck Pier is a unique and nationally important structure connecting the mainland below the Prince Consort
	DESIGNATION:	Listed Building grade II*, CA	Gardens to Birnbeck Island. Enforcement action in the form of a Repairs Notice was served on the owners in
	CONDITION:	Very bad	September 2019 but has not been complied with. The Council is now working towards the potential Compulsary
	OCCUPANCY:	Vacant/not in use	Purchase Order of the pier with guidance and funding from
and a second	PRIORITY CATEGORY:	A (A)	Historic England.
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1129718	Contact: John Ette 0117 975 0687

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

use).

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / SOUTH WEST / NORTH SOMERSET (UA) / PLYMOUTH, CITY OF (UA)

	SITE NAME:	St George's Church, Church Road, Pill and Easton-in- Gordano	Anglican parish Church. C14 and C15, restored in 1871-72 by Ewan Christian. West tower, nave with clerestorey, north and south aisle, south porch, chancel and vestry.
	DESIGNATION:	Listed Place of Worship grade II*	Coursed rubble with freestone dressings; slate roofs behind embattled parapets. South roofs poor; walling and
	CONDITION:	Poor	pointing in poor condition and spalling; drainage poor with damp and water ingress affecting floors.
	PRIORITY CATEGORY:	C (New entry)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1129826	Contact: Annie Evans 0117 975 0673

Contact: Chris Miners 0117 975 1355



SITE NAME:	St Mary's Church, Church Lane, Portbury	CI2 parish church, altered and extended early CI3 and CI4/CI5, restored 1870-5. The stone slate roofs of the
DESIGNATION:	Listed Place of Worship grade I	chancel, vestry and associated lean-to roofs have come to the end of their life. Water has been getting in causing
CONDITION:	Poor	ceiling plaster falls. A National Lottery Heritage Fund Grant for Places of Worship enabled roof repairs to be
PRIORITY CATEGORY:	C (C)	completed in 2014. However, further problems with the
OWNER TYPE:	Religious organisation	poor state of the sandstone wall, especially on the south transept, keeps the church at risk. A further National
LIST ENTRY NUMBER:	1311826	Lottery Heritage Fund grant has been awarded and the project development is nearing completion.
		project development is nearing completion.

© Historic England

SITE NAME: Worlebury Camp: a large multivallate hillfort on Worlebury Hill, Weston-Super-Mare LIST ENTRY NUMBER: DESIGNATION: 1011260 Scheduled Monument, part in CA Generally unsatisfactory with major localised CONDITION: TREND: Declining problems PRINCIPAL VULNERABILITY: NEW ENTRY? Forestry No OWNER TYPE: CONTACT: Alessandra Perrone 0117 975 1345 Local authority SITE NAME: Long barrow 350 metres south west of Cornerpool Farm, Wrington DESIGNATION: LIST ENTRY NUMBER: 1008291 Scheduled Monument Generally unsatisfactory with major localised CONDITION: TREND: Declining problems PRINCIPAL VULNERABILITY: NEW ENTRY? No Arable ploughing OWNER TYPE: CONTACT: Alessandra Perrone 0117 975 1345 Private

PLYMOUTH, CITY OF (UA)

-	SITE NAME:	Eggbuckland Keep	Problems with water ingress, thought to be due to
The Contraction	DESIGNATION:	Listed Building grade II*, SM	deterioration of ashfelt membrane between earthen ramparts above and masonry vaults beneath. Owner is in
	CONDITION:	Very bad	discussion with Historic England.
m 100 L	OCCUPANCY:	Vacant/not in use	
AND-	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1390897	Contact: Phil McMahon 0117 975 0699

© Historic England

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- Conservation Area Listed Building CA
- LB LPA
- Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument

- SM
- UA WHS Unitary Authority World Heritage Site

163

HERITAGE AT RISK 2021 / SOUTH WEST / PLYMOUTH, CITY OF (UA)

No. 1	SITE NAME:	Academy Theatre and Great Western Hotel (Palace Theatre), Union Street, Stonehouse, Plymouth	Former variety theatre and hotel, built 1898. A significant building in an area where major regeneration has been underway. Historic England has offered grant aid in the past, which was not taken up. Temporary repairs were
101 Min	DESIGNATION:	Listed Building grade II*, CA	undertaken in 2013 and 2015 to make the theatre weathertight. Further temporary weatherproofing has bee
	CONDITION:	Very bad	put in place in the last few years but as of 2020 a full
	OCCUPANCY:	Vacant/not in use	condition report and detailed scheme of repairs, and a business plan for reuse of the building, are still required.
	PRIORITY CATEGORY:	A (A)	
Historic England Archive	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1386483	Contact: Annie Evans 0117 975 0673
E TAT MANAGEMENT OF	SITE NAME:	Knowle Battery	Palmerston Fort; part of the site is now the grounds of a
	DESIGNATION:	Scheduled Monument	primary school. Historic England funded a Condition Survey of the structure with proposals for refurbishment in
	CONDITION:	Fair	preparation for re-use of the guardhouse, and a five year Management Agreement to control vegetation. Funding
	OCCUPANCY:	Vacant/not in use	from Historic England and Plymouth City Council
	PRIORITY CATEGORY:	C (C)	addressed the most urgent repair issues and the shell is now in good repair, but there are still issues with water
ALL	OWNER TYPE:	Local authority	ingress from the land behind the guardhouse. Long-term
	LIST ENTRY NUMBER:	1002614	use is still required. Until a new use is in place the site remains very vulnerable to vandalism.
Historic England Archive			, Contact: Annie Evans 0117 975 0673
C. Medine William	SITE NAME:	Agaton Fort, Plymouth	One of the ring of C19 land forts built to defend Plymouth
AN MARKEN LAND	DESIGNATION:	Scheduled Monument	Overlooks River Tamar. Irregular pentagonal plan, with
	CONDITION:	Fair	deep ditch on four sides protected by caponiers and a counterscarp gallery. Internally the officer's quarters,
ATT A A L	OCCUPANCY:		cookhouse and barracks, seven of twenty open gun
		Vacant/not in use	positions, one Haxo casement, five expense magazines and two of previous six mortar batteries survive. Ceased
	PRIORITY CATEGORY:	C (C)	military use in 1958 but was used as Heavy Goods Vehicle testing centre (partly in a modern building) until 2015.
	OWNER TYPE:	Government or agency	Vacancy is concerning and there are significant problems
D Historic England Archive	LIST ENTRY NUMBER:	1002613	with dry rot and vegetation management. Contact: Annie Evans 0117 975 0673
Cash.	SITE NAME:	Amphitheatre in grounds of Saltram House, Merafield Road, Plympton	Late C18 screen wall fronting rock-cut grottos overlooking the River Plym. Surrounding rock faces have become unstable and are subject to collapse. A condition survey of
	DESIGNATION:	Listed Building grade II*, RPG grade II*	the structure has recently been undertaken, and the owners are in the process of updating their conservation management plan for the Saltram Estate. However, no
	CONDITION:	Poor	physical repair works are believed to have been
	OCCUPANCY:	N/A	undertaken yet.
	PRIORITY CATEGORY:	C (C)	
D Historic England	OWNER TYPE:	Charity (heritage)	
	LIST ENTRY NUMBER:	1386231	Contact: Annie Evans 0117 975 0673
	SITE NAME:	Boringdon Arch, Plymbridge Road, Plymouth	Designed by Robert Adam and built in 1783, built as a triumphal arch and eye-catcher to be viewed from Saltram House. Now within a golf course. It was advertised for sale
1010	DESIGNATION:	Listed Building grade II* and Scheduled Monument	in 2014 but was not sold, and remains in a state of slow decay. There is scope for limited reuse of the former
E E	CONDITION:	Poor	lodges (now roofless ruins) behind the arch flank walls to be reused for beneficial purposes, but access remains a
	OCCUPANCY:	N/A	constraint.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private, multiple owners	
D Historic England	OWNER TYPE: LIST ENTRY NUMBER:	Private, multiple owners 1386330 and 1020565	Contact: Simon Hickman 0117 975 0717
∋ Historic England			Contact: Simon Hickman 0117 975 0717

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.

Е

- Slow decay; solution agreed but not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.
- Last year's priority category is shown in brackets (otherwise, New Entry is noted).
- Area
- CA Conservation Area LB Listed Building LPA Local Planning Autho NP National Park RPG Registered Park and (SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERI

HERITAGE AT RISK 2021 / SOUTH WEST / PLYMOUTH, CITY OF (UA)				
	SITE NAME:	Efford Fort and Emplacement, Military Road, Efford	Palmerston Fort built between 1863 and 1869. Partially occupied, as the parade ground is used for seasonal	
	DESIGNATION:	Scheduled Monument	accommodation whilst buildings are vacant or used for storage. Buildings are suffering from benign neglect with	
and the state of the state of the	CONDITION:	Very bad	heavy vegetation growth on the ramparts which may lead to water penetration and structural problems. No solution	
	OCCUPANCY:	Part occupied/part in use	agreed as of 2019.	
TTT	PRIORITY CATEGORY:	A (A)		
	OWNER TYPE:	Mixed, multiple owners		
© Plymouth City Council	LIST ENTRY NUMBER:	1021135	Contact: Annie Evans 0117 975 0673	
1	SITE NAME:	Melville Building, Royal William Yard, Plymouth	The Melville building was constructed c1826-1832 as stores and offices for the Victualling Board to the design of Sir	
1	DESIGNATION:	Listed Building grade I, CA	John Rennie Jnr, and forms part of the impressive Royal William Yard. Planning permission in place for conversion	
A DESCRIPTION OF THE OWNER OWNER OF THE OWNER OWNE	CONDITION:	Poor	to mixed use development. First phase of repair and conversion works to approximately a third of the building,	
	OCCUPANCY:	Part occupied/part in use	including the north range, was completed in early 2020,	
	PRIORITY CATEGORY:	F (F)	with Historic England grant-aiding the repair of the roofs and external walls. A second phase, partly funded by the	
	OWNER TYPE:	Local authority	Cultural Recovery Fund, encompasses the west range and	
© Historic England	LIST ENTRY NUMBER:	37853	is due for completion in 2021. Contact: Sarah Ball 0117 975 0666	
	SITE NAME:	Oddfellows Hall, Ker Street,	Hall built 1823 by John Foulston, in the Egyptian style. Part	
ODD FELLOWS HALL		Devonport	of a group with the Guildhall and Devonport Column.	
	DESIGNATION:	Listed Building grade I, CA	Egyptian columns flank a central, recessed porch. Currently used as a social club and in poor repair. Historic England	
	CONDITION:	Poor	grant-aided a feasibility study and emergency repairs to the roof, completed in 2007. The building has been acquired by	
	OCCUPANCY:	Occupied/in use	new owners. Historic England has met with the new	
	PRIORITY CATEGORY:	C (C)	owners and is in discussions over the future repair of the building.	
	OWNER TYPE:	Private	-	
© Historic England	LIST ENTRY NUMBER:	1322006	Contact: Annie Evans 0117 975 0673	
	SITE NAME:	Old Cooperage, Royal William Yard, Plymouth	The Cooperage was built c1826-1832 for the Victualling Board, and forms part of the Royal William Yard. Part of	
	DESIGNATION:	Listed Building grade I, CA	the Cooperage has been successfully converted into artists' studios; Historic England grant-aided the stone	
	CONDITION:	Poor	conservation works. A sustainable future for the rest of the	
	OCCUPANCY:	Vacant/not in use	Cooperage is being explored by the leaseholder and Historic England have grant-aided urgent repairs to the rest	
	PRIORITY CATEGORY:	C (C)	of undeveloped sections of the building. Historic England is in a continuing dialogue with the leaseholder.	
AND IN A	OWNER TYPE:	Local authority	0 0	
© Historic England	LIST ENTRY NUMBER:	1378536	Contact: Sarah Ball 0117 975 0666	
	SITE NAME:	South Saw Mills, South Yard,	Sawmill built between 1856 and 1859. The saw mills	
	SHE NAPE:	HM Naval Base, Plymouth	ceased to be used as such in 1987, but the ground floor	
A	DESIGNATION:	Listed Building grade II*	remained in light industrial and storage use until 1997. An options report was issued in 2010, but the building remains	
FF Prese	CONDITION:	Fair	vacant with no identifiable use. The roof was provided with	
	OCCUPANCY:	Vacant/not in use	a large net in 2017 to prevent dislodged roofing materials becoming flying projectiles.	
	PRIORITY CATEGORY:	E (E)		
	OWNER TYPE:	Government or agency		
© Historic England	LIST ENTRY NUMBER:	3884 3	Contact: Simon Hickman 0117 975 0717	

© Historic England

Contact: Simon Hickman 0117 975 0717

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / SOUTH WEST / PLYMOUTH, CITY OF (UA)


- /	SITE NAME:	South Smithery, South Yard, HM Naval Base, Plymouth	Dockyard smithery built 1771, modified C19 and reconstructed c1897. It remained in use until 1987 when
	DESIGNATION:	Listed Building grade II*	structural faults were discovered. There is continued deterioration of the roof, masonry and interiors. An
	CONDITION:	Very bad	options report was issued in 2010, but a repair strategy has not yet been put in place. In 2017 a large net was installed
	OCCUPANCY:	Vacant/not in use	on the roof to prevent dislodged roofing materials falling in
	PRIORITY CATEGORY:	A (A)	high winds.
1	OWNER TYPE:	Government or agency	
nd	LIST ENTRY NUMBER:	1392692	Contact: Simon Hickman 0117 975 0717



© Historic England

© Historic England

SITE NAME:	The coastal fortifications of Drake's Island, Plymouth	The island incorporates numerous defences/military monuments from 1549 to C20. It was held for Parliament
DESIGNATION:	Scheduled Monument, LB grade II	during the Civil War and used for defence purposes until 1958. All buildings and structures are in a derelict condition. A planning application for conversion to hotel
CONDITION:	Poor	use was granted in 2017, works are yet to commence.
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	D (D)	
OWNER TYPE:	Mixed, multiple owners	
LIST ENTRY NUMBER:	1010910	Contact: Helen Woodhouse 0117 975 0676



	SITE NAME:	Church of St Mary and All Saints, Church Road, Plymouth	Roof coverings are desperately in need of renewal, particularly the nave and inner slopes of north and south
and the second	DESIGNATION:	Listed Place of Worship grade II*	aisle. Slates to these areas have previously been covered with bitumen-coated hessian and will not be reusable for
and a second	CONDITION:	Poor	repairs. Valley gutter also needs renewing. Interior suffers from condensation and poor ventilation. Gullies need
	PRIORITY CATEGORY:	D (D)	clearing out. Downpipe to tower leaking or blocked. Some
	OWNER TYPE:	Religious organisation	ivy growth to masonry. Buttresses need repointing. Excessive tree growth near north wall. A bid to the last
d E	LIST ENTRY NUMBER:	1330541	round of Listed Places of Worship Roof Repair Grants in 2016 was unsuccessful.

© Historic England

Contact: Annie Evans 0117 975 0673

SITE NAME:	Austin Fort and section of military road		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021380
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Annie Evans 0117 975 0673

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; в solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / SOUTH WEST / PLYMOUTH, CITY OF (UA)

SITE NAME:	NAME: Efford Fort and Efford Emplacement, Military Road, Efford			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021135	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No	
OWNER TYPE:	Charity (non-heritage)	CONTACT:	Annie Evans 0117 975 0673	
SITE NAME:	Fort Stamford			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002544	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Plympton Castle			
DESIGNATION:	Scheduled Monument, LB grade II*, CA	LIST ENTRY NUMBER:	1003865	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Local authority	CONTACT:	Andy Crabb 01626 832093	
ITE NAME:	Laira Battery			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021134	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Laira Emplacement, immediately south west of Lair	a Battery		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020686	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Plympton Priory			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017594	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093	
ITE NAME:	Lee Moor Tramway Bridge			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002637	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- 167

HERITAGE AT RISK 2021 / SOUTH WEST / PLYMOUTH, CITY OF (UA) / EXMOOR (NP)

SITE NAME:	Stonehouse Manor wall		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1003850
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	The coastal fortifications of Drake's Island		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1010910
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE: Mixed, multiple owners		CONTACT:	Helen Woodhouse 0117 975 0676
SITE NAME:	Woodland Fort		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002615
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Annie Evans 0117 975 0673

SOMERSET

EXMOOR (NP)



	SITE NAME:	Dovecote at Little Blackford, Selworthy, Somerset West and Taunton	This dovecote which survives well requires some repointing, limewashing and repairs to the roof covering in order to secure it in good condition.
	DESIGNATION:	Scheduled Monument, LB grade II*	
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (A)	
© T. Thurlow HBO with kind permission of Exmoor National Park Authority	OWNER TYPE:	Charity (heritage)	
	LIST ENTRY NUMBER:	1020774	Contact: John Ette 0117 975 0687



© T. Thurlow HBO with kind permission of Exmoor National Park Authority

SITE NAME:	Packhorse Bridge about 50 metres west of Lyncombe, Winsford, Somerset West and Taunton	Packhorse Bridge. C17-C18, possibly earlier. Lias. Dry stone flat bedded rubble; single span, pointed arch; rubble voussoirs; curved abutments; parapet of undressed stone set on end, ramped up to centre. Hump-backed bridge
DESIGNATION:	Listed Building grade II*	with remains of pebble pathway. A recent condition survey has identified loss or covering of cobble pathway, partial
CONDITION:	Poor	loss of parapet, cracking above the arch and extensive plan growth including ivy and large saplings rooting into fabric.
OCCUPANCY:	N/A	Historic England has met the owners to discuss repairs.
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1174159	Contact: Annie Evans 0117 975 0673

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site
- 168

HERITAGE AT RISK 2021 / SOUTH WEST / EXMOOR (NP)

HERITAGE AT RISK 2021 / SOU	JTH WEST / EXMOOR (NP)		
SITE NAME:	Bury Castle, Brompton Regis, Somerset West and	Taunton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006170
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bat's Castle: a small multivallate hillfort and associated outwork, Carhampton, Somerset West and Taun		
DESIGNATION:	Scheduled Monument, RPG grade II*	LIST ENTRY NUMBER:	1007667
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	rype: Crown		Charlotte Russell 01271 831505
SITE NAME:	Mounsey Castle, Dulverton, Somerset West and T	aunton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021357
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Black Ball Camp: a later prehistoric defended settlement on Gallox Hill, Dunster, Somerset West and Taunton		
DESIGNATION:	Scheduled Monument, RPG grade II*	LIST ENTRY NUMBER:	1007668
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	St Leonard's Well, Dunster, Somerset West and T	aunton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021154
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:			Charlotte Russell 01271 831505
SITE NAME:	Almsworthy Common: a stone alignment 560 metres south west of Chetsford Bridge, Exford, Somerset West and Taunton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015017
CONDITION:	Generally satisfactory but with minor localised TREND: Declining problems		Declining
PRINCIPAL VULNERABILITY:	Stock erosion - localised/limited NEW ENTRY?: No		No
OWNER TYPE:	Charity (heritage)		Charlotte Russell 01271 831505
SITE NAME:	Chains Valley stone alignment 400 metres north w	est of Exe Head, Ex	kmoor, Somerset West and Taunton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014278
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth - General	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Charlotte Russell 01271 831505

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / SOUTH WEST / EXMOOR (NP)

SITE NAME:	Cow Castle, Exmoor, Somerset West and Tauntor	1	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002955
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Kittuck stone setting and cairn, 200 metres south v Taunton	west of Three Com	bes Foot, Exmoor, Somerset West a
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014284
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Sweetworthy deserted medieval settlement, Lucco	mbe, Somerset We	est and Taunton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008469
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Berry Castle, Iron Age enclosure in Berry Castle V	Vood, Luccombe /	Porlock, Somerset West and Tauntor
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006204
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Allerford packhorse bridge, immediately north of C	Cross Lane Farm, So	elworthy, Somerset West and Taunto
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1020776
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners		Charlotte Russell 01271 831505
SITE NAME:	Earthwork enclosure on Rodhuish Common, 300 r and Taunton	netres west of Moo	or Barn, Withycombe, Somerset Wes
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021122
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Brewer's Castle, Withypool and Hawkridge, Somer	rset West and Tau	nton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021358
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
	Scrub/tree growth	NEW ENTRY ?:	No
PRINCIPAL VULNERABILITY:	Scrub/ tree growth		
PRINCIPAL VULNERABILITY:	Private	CONTACT:	Charlotte Russell 01271 831505

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / SOUTH WEST / EXMOOR (NP) / MENDIP

SITE NAME:	Brightworthy Barrows on Withypool Common, Withypool and Hawkridge, Somerset West and Taunton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021264
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Stone circle on Withypool Hill 670 metres ESE of P West and Taunton	Portford Bridge, W	ithypool and Hawkridge, Somerset
SITE NAME: DESIGNATION:		Portford Bridge, W	ithypool and Hawkridge, Somerset
	West and Taunton	C ·	
DESIGNATION:	West and Taunton Scheduled Monument Generally satisfactory but with significant localised	LIST ENTRY NUMBER:	1021261

MENDIP

	SITE NAME:	Kilmersdon Lodges, Kilmersdon	Pair of lodges, gate piers and gates, associated with
	DESIGNATION:	Listed Building grade II*, RPG grade II*	Ammerdown House, built from 1788 to 1794, situated on the edge of late C18 to early C19 park. The lodges were ruinous when listed in the 1960s and their potential for
	CONDITION:	Poor	reuse is limited by their size. A feasibility study has been undertaken but the scale of the project indicated was
	OCCUPANCY:	Vacant/not in use	prohibitive. A schedule of work has been undertaken to
	PRIORITY CATEGORY:	E (E)	stabilise the surviving fabric; however, the building has no roof and remains vulnerable (2021).
	OWNER TYPE:	Private	
gland	LIST ENTRY NUMBER:	3074	Contact: Rhiannon Rhys 0117 975 0685

Former Anglo-Bavarian

Shepton Mallet

Poor

A (A)

Brewery, Commercial Road,

Listed Building grade II*, CA

Part occupied/part in use

Commercial company

© Historic Engla



SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

© Historic	England



© Mendip District Council

	LIST ENTRY NUMBER:	1296561	Contact: Rhiannon Rhys 0117 975 0685
	SITE NAME:	Outbuilding about 30 metres west of Higher Southtown Farm, Southtown Lane, West Pennard	Early C17 timber-framed brewhouse later utilised as a cottage, now part calf shed/hay store. In poor condition due to lack of maintenance and beneficial use for many years. Emergency clearance and stabilisation works to the
	DESIGNATION:	Listed Building grade II*	building have been undertaken by Mendip District Council. The site passed into new ownership in Spring 2020 and we
	CONDITION:	Poor	look forward to discussing its future with the new owners.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1175928	Contact: Sarah Ball 0117 975 0666

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Brewery, now warehouses, built in 1864. Whilst partly

occupied at ground floor level, most of the building has

been vacant for many years. A feasibility study has been

deficit. A partial collapse has now been repaired. No further work has been undertaken as of 2021.

undertaken which has identified a substantial conservation

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
 - Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Gatehouse to west of Manor Farmhouse, Whatley	Gatehouse, C15 built from random local limestone rubble with a plain tile roof. Two storeys, all window openings
	DESIGNATION:	Listed Building grade I	blocked apart from left side of ground floor. The arched entry is slightly left of centre and there is a Tudor arch
	CONDITION:	Poor	doorway within the passage. Rear has stone steps to first floor doorway on the left side. The building is showing signs
	OCCUPANCY:	Vacant/not in use	of structural movement to the south gable and significant deflection to the roof. Some areas of stone work are very weak, particularly around the small door under the arch.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	The vegetation to the east side needs to be removed.
England	LIST ENTRY NUMBER:	1175158	Contact: Sarah Ball 0117 975 0666

© Historic E

© Historic England

	SITE NAME:	Fenny Castle Cross: a medieval wayside cross 20 metres north west of Castle Farm, Castle, Wookey	A medieval stone cross thought to date back to the early C14. Despite the loss of its shaft, the rest of the structure survives in situ though in very bad condition. Several stones show signs of fracture, the joints are open and missing
	DESIGNATION:	Scheduled Monument	mortar and vegetation is slowly encroaching.
	CONDITION:	Very bad	
No	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
ł	OWNER TYPE:	Private, multiple owners	
	LIST ENTRY NUMBER:	1015797	Contact: Alessandra Perrone 0117 975 1345

1.	SITE NAME:	Baptist Chapel, Frome Road, Beckington	Chapel dated 1786 now converted to community use as a pre-school as well as a place of worship. Random rubble,
	DESIGNATION:	Listed Place of Worship grade II, CA	with plain corner pilasters, pilasters between each bay and a central pediment with balustraded parapet to each side. Roof aging and some slate slippage. Stone balustraded parapet needs repair work. Some broken panes of glass.
	CONDITION:	Poor	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1296104	Contact: Annie Evans 0117 975 0673
© Historic England			

sund.	SITE NAME:	Church of the Holy Trinity, Binegar	Parish church rebuilt in the C15 with the tower dating from 1858. The building is generally very well maintained but the
the second second	DESIGNATION:	Listed Place of Worship grade II*	slated roofs require complete recovering and new ceilings. The roofs are covered in asbestos cement slates with
	CONDITION:	Poor	fibreboard ceilings below. The slates require annual attention to deal with leaks, which have significantly
T	PRIORITY CATEGORY:	C (C)	disfigured the ceilings. The floors also need work due to
BAR BAR BAR	OWNER TYPE:	Religious organisation	rotten joists.
自己与这一	LIST ENTRY NUMBER:	1058641	Contact: Annie Evans 0117 975 0673

© Historic England



	SITE NAME:	Church of St John the Baptist, Church Lane, Chilcompton	Parish church dating from the C15 much rebuilt in the C19. The nave north parapet has been secured, and there was a
	DESIGNATION:	Listed Place of Worship grade II*	significant problem in the eastward parts of the building which had severe frost damage to limestone copings and
	CONDITION:	Poor	string courses and further problems with poor walling stone and pointing. A Listed Places of Worship Roof
	PRIORITY CATEGORY:	D (D)	Repairs Grant awarded in 2015 enabled most work to be
	OWNER TYPE:	Religious organisation	completed. Some very significant boundary wall repairs are still required.
	LIST ENTRY NUMBER:	1345096	Contact: Annie Evans 0117 975 0673

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

La la	SITE NAME:	Church of All Saints, Pound Lane, Downhead	Parish church with a perpendicular tower from the CI4. Nave, chancel and south porch from the mid CI8, the
	DESIGNATION:	Listed Place of Worship grade II*	building also has some C19 restorations. The building is generally well maintained. However it is exposed and water
	CONDITION:	Poor	penetration to the tower is now spreading and affecting nave roof structure as well as the tower arch.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	174065	Contact: Annie Evans 0117 975 0673

© Historic England

	SITE NAME:	Church of St Mary, Evercreech	Anglican church. CI2, CI3, CI5, rebuilt 1888, further
	DESIGNATION:	Listed Place of Worship grade II*	work of 1925. Rubble, freestone dressings, Nave with west bellcote, south porch, chancel. Inner doorway late C12.
	CONDITION:	Fair	Interior plastered on flagstone and tile floors; nave with t beam roof restored 1925, though part C17, Norman tub font. Suffered from heritage crime in 2019. Small
	PRIORITY CATEGORY:	A (A)	
-	OWNER TYPE:	Religious organisation	community and at risk of closure.
	LIST ENTRY NUMBER:	1222368	Contact: Annie Evans 0117 975 0673
and the second of the state			


© Historic England Archive

	SITE NAME:	Christ Church, Christchurch Street West, Frome	Built 1817-1818 as an aisled nave, with crenellated east tower. Eastern extension built 1904-1905, the south
	DESIGNATION:	Listed Place of Worship grade II*, CA	transept in 1899, and the north transept 1929. Perpendicular style, with traceried openwork parapets, pinnacles and gargoyles over buttresses. The rainwater
	CONDITION:	Poor	goods are in poor condition. There is detrimental extern secondary glazing and large number of tingles (temporary
	PRIORITY CATEGORY:	C (C)	repairs) on chancel roof.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1057853	Contact: Annie Evans 0117 975 0673

© Historic England

© Historic England

	SITE NAME:	Church of St Giles, Church Walk, Leigh-on-Mendip	Medieval parish church dating from c1350, rebuilt c1500. Well maintained. Iron cramps are pushing apart the joints
	DESIGNATION:	Listed Place of Worship grade I	in the parapet but as yet not splitting the stones. A programme of repairs addressing the external walling and
	CONDITION:	Poor	parapets as well as repairs to the C18 roof coverings is needed. The chancel roof was repaired with Listed Places
	PRIORITY CATEGORY:	C (C)	of Worship Roof Repairs Grant and in 2017, the
	OWNER TYPE:	Religious organisation	congregation received National Lottery Heritage Fund Grant for Places of Worship to address the Nave roof.
	LIST ENTRY NUMBER:	1058345	Work is in development. The congregation is also developing proposals for repairs and reordering.
			Contact: Annie Evans 0117 975 0673
	SITE NAME:	Church of St Mary St Mary's	Anglican parish church C14 of chancel, nave, north and



© Historic England Archive

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Church of St Andrew, Mells	Parish church. Predominantly late C15, tower of mid C16,
	DESIGNATION:	Listed Place of Worship grade I, CA	mid C19 restoration. Doulting ashlar; low pitched roofs. Clerestoried nave with north and south aisles, continuing as chapels clasping the chancel and polygonal vestry of 1485.
	CONDITION:	Poor	Important fixtures, fittings and furnishings. The church is generally very well maintained but the roofing materials ar
	PRIORITY CATEGORY:	D (D)	coming to the end of their lives. The poor condition
	OWNER TYPE:	Religious organisation	classification therefore relates to the roof only.
E HAL	LIST ENTRY NUMBER:	1295876	Contact: Annie Evans 0117 975 0673

© Historic England



	SITE NAME:	Church of St Leonard, Stoke Street, Rodney Stoke	Small Anglican parish church with C12 origins and later additions. Restored in 1879. Perpendicular style. The
	DESIGNATION:	Listed Place of Worship grade I	pierced parapet along the top of the nave is rapidly deteriorating.
- 16	CONDITION:	Poor	-
1.40	PRIORITY CATEGORY:	A (A)	
5	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1058592	Contact: Alessandra Perrone 0117 975 1345

© Historic England

SITE NAME:	Church of St Katherine, Selwood	Anglican parish church. The tower was built around 1712 but the nave, chancel, north and south aisles, and south
DESIGNATION:	Listed Place of Worship grade II*	porch were added by JL Pearson in 1880 in a mixture of Geometrical and Decorated styles. Rubble, tile roofs,
CONDITION:	Poor	coped verges, with cruciform finials, ashlar west tower with tall stone spire, In the process of being closed and will
PRIORITY CATEGORY:	C (New entry)	become the responsability of the Diocesan Board of
OWNER TYPE:	Religious organisation	Finance. Risk of little maintenance until a new use and owner is found and agreed.
LIST ENTRY NUMBER:	1175821	Contact: Annie Evans 0117 975 0673

SITE NAME:	Church of St Matthew, High Street, Wookey	Parish church, dated predominantly from C15 but with C13 chancel. The building is well maintained, however the
DESIGNATION:	Listed Place of Worship grade I	nave and aisle roofs are improperly fixed and thus split and leak annually letting water into the C15 roof structure.
CONDITION:	Poor	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1295105	Contact: Annie Evans 0117 975 0673
	DESIGNATION: CONDITION: PRIORITY CATEGORY: OWNER TYPE:	Street, WookeyDESIGNATION:Listed Place of Worship grade ICONDITION:PoorPRIORITY CATEGORY:C (C)OWNER TYPE:Religious organisation

© Historic England

SITE NAME: Small multivallate promontory fort on Blacker's Hill, Chilcompton DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015493
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015493
CONDITION: Generally satisfactory but with significant localised TREND: Declining problems
PRINCIPAL VULNERABILITY: Animal burrowing - moderate NEW ENTRY?: No
OWNER TYPE: Private CONTACT: Alessandra Perrone 0117 975 134
SITE NAME: Bowl barrow 300 metres north east of Whitnell Corner, Emborough
SITE NAME: Bowl barrow 300 metres north east of Whitnell Corner, Emborough DESIGNATION: Scheduled Monument
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1011670

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В

implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Drying house at The Coach House, Willow Vale, F	rome	
DESIGNATION:	Scheduled Monument, LB grade II, CA	LIST ENTRY NUMBER:	1016955
CONDITION:	Extensive significant problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY ?:	No
OWNER TYPE:	Commercial company	CONTACT:	Alessandra Perrone 0117 975 1345
ITE NAME:	Glastonbury lake village, Godney		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006156
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Lake villages north west of Oxenpill, Meare		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006160
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Section of the Abbot's Way trackway, 500 metres	WSW of Honeygar	- Farm, Meare
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014432
CONDITION:	Extensive significant problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Sections of the Sweet Track and Post Track, 240 m	netres south west o	of Sunnyside Farm, Meare
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014440
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Sections of the Sweet Track and Post Track, 250 m	netres ESE of Statio	n House, Meare
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014831
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Timber trackway site, 700 metres west of Honeyga	ar Farm, Meare	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014434
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Fussell's Lower Works: an iron edge tool works, 2	10 metres south ea	st of Wadbury, Mells
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1019796
	Generally satisfactory but with significant localised	TREND:	Stable
CONDITION:	problems		
CONDITION: PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

75 1345
75 1345
75 345
75 345
75 345
75 345
75 345
75 345
75 1345
75 1345
75 345
75 1345
75 345

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SEDGEMOOR

GENOOR			
	SITE NAME:	Castle House, Queen Street, Bridgwater	House in the centre of Bridgwater in the early Tudor Revival style, built for William Ackerman in 1851. It is
	DESIGNATION:	Listed Building grade II*, CA	notable for the earliest surviving use of prefabricated cast concrete and constructional post tensioning. The building
A	CONDITION:	Poor	has been in a structurally precarious condition and has had an arson attack. Owned by SAVE Building Preservation
	OCCUPANCY:	Vacant/not in use	Trust. Historic England has grant aided phases of repair
	PRIORITY CATEGORY:	F (F)	with a final phase taking place in 2018. However the building remains empty while SAVE pursues a sustainable
	OWNER TYPE:	Charity (heritage)	long term future for the building.
oric England	LIST ENTRY NUMBER:	1355168	Contact: Annie Evans 0117 975 0673

© Histori



8	SITE NAME:	Church of StMary, Spaxton	Anglican parish church; now deconsecrated. C11, C13,
	DESIGNATION:	Listed Building grade I	C15; tower probably of 1867; restored 1887. Rubble, coped verges, slate roofs. Chancel, nave, south porch and
ALL DE	CONDITION:	Poor	transeptal south chapel, vestry and organ chamber, west tower. Nave has late Norman south doorway, interior
	OCCUPANCY:	Vacant/not in use	plastered; C15 moulded plaster ceiling; Norman responds
	PRIORITY CATEGORY:	C (C)	to C13 chancel arch. Vegetation growth, roofs and rainwater goods in poor condition.
100	OWNER TYPE:	Private	
È.	LIST ENTRY NUMBER:	1178212	Contact: Annie Evans 0117 975 0673

© Historic England

© Historic England

	SITE NAME:	Westonzoyland Pumping Station, Westonzoyland	A former pumping station, built in the early C19, now preserved by the Westonzoyland Engine Trust. The first
	DESIGNATION:	Listed Building grade II*	pumping station to be built to lift floodwater from the Somerset Levels and Moors, and the only one to survive
	CONDITION:	Poor	with the steam engine still working and with the buildings intact. Much work has been done but further repair is
	OCCUPANCY:	N/A	needed, and the Trust has been working up a scheme for
	PRIORITY CATEGORY:	C (C)	reuse of underused areas. Parts are under possible threat from rapid alteration of surrounding drainage. Historic
- All and a second	OWNER TYPE:	Charity (heritage)	England is grant aiding the investigation of cracking to the building close to the riverbank.
	LIST ENTRY NUMBER:	1174295	Contact: Annie Evans 0117 975 0673

	R	
1	ĥ	Sa
	N	
	1	712

	SITE NAME:	Church of All Saints, High Street, Ashcott	Parish church. Mainly C15 with alterations in the C19. The woodblock floor has lifted and is decayed in many places.
	DESIGNATION:	Listed Place of Worship grade II*	This could be due to a leak from the buried C19 cast iron heating pipework. The vestry roof needs re-covering and
-	CONDITION:	Poor	significant masonry repairs to the tower and nave parapets will be needed in the near future.
-	PRIORITY CATEGORY:	C (C)	
3.4	OWNER TYPE:	Religious organisation	
1	LIST ENTRY NUMBER:	1058957	Contact: Annie Evans 0117 975 0673

© Historic England



SITE NAME:	Baptist Church, St Mary Street, Bridgwater	Baptist church, built in 1837 by Edwin Down. Rectangular plan with schoolrooms to the rear. Classical frontage with
DESIGNATION:	Listed Place of Worship grade II*, CA	Bath stone pediment and cornice, flight of steps up to central Egyptian style doors. High level stonework is in poor condition. Rainwater goods are also poor. Rear of
CONDITION:	Poor	the building has vegetation growth and the brickwork needs repointing.
PRIORITY CATEGORY:	C (C)	heeds repointing.
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1298798	Contact: Annie Evans 0117 975 0673

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Church of St Edward, Church Lane, Chilton Polden	Parish church of C15 origin, largely rebuilt in 1889. Rubble, slate roofs with coped verges and bellcote at west end.
	DESIGNATION:	Listed Place of Worship grade II	Chancel and nave, north aisle, north transept, north and south porches and vestry. Neo-Perpendicular with some
	CONDITION:	Poor	Perpendicular features remaining. There is cracking to the vestry wall and the roof covering is failing. The church was
	PRIORITY CATEGORY:	C (C)	awarded a Listed Places of Worship Roof Repairs Grant in
guinny Alar	OWNER TYPE:	Religious organisation	2016 but more repairs are required.
and the second	LIST ENTRY NUMBER:	1060126	Contact: Annie Evans 0117 975 0673

© Historic England

Large Anglican parish church dating from the C15 with C17 and C19 alterations and chancel 1845 by William Butterfield. Nave (with gallery), north aisle, south transept and organ chamber, chancel, vestry and south porch. Random rubble stone, with dressed stone piers, window surrounds, stringcourses and copings under lead roof coverings. North aisle roof in particuarly poor condition
and organ chamber, chancel, vestry and south porch. Random rubble stone, with dressed stone piers, window surrounds, stringcourses and copings under lead roof
surrounds, stringcourses and copings under lead roof
but issues on other roofs also; rainwater goods rusting; lias stonework deteriorated and damage to fine ceiling inside.
A grant by Virridor will pay for for an initial phase of urgent work but much more is needed.
Contact: Annie Evans 0117 975 0673



SITE NAME: Church of the Holy Cross, Church Road, Middlezoy Anglican parish church. C13, C14, C15, C16, rest	ored
DESIGNATION: Listed Place of Worship grade I north transept. Tall three-stage C15 tower with ca	inopied
CONDITION: Poor niches and pinnacles to buttresses. Suffered from A crime in early 2020. The roof now has a temporar	from heritage
PRIORITY CATEGORY: A (A) covering.	, icit
OWNER TYPE: Religious organisation	
LIST ENTRY NUMBER: 1344695 Contact: Annie Evans 0117 975 0673	

© Historic England

	SITE NAME:	Church of St Mary, Fore Street, North Petherton	The church was mostly built in the late C14 and early C15 including the tower, in a Perpendicular style. Inside the
	DESIGNATION:	Listed Place of Worship grade I	tower at the height of the nave is a fine fan vault, unusual for a village church. The north aisle parapet and south aisle
	CONDITION:	Poor	roof have been repaired with National Lottery Heritage Fund and Historic England Repair Grant for Places of
	PRIORITY CATEGORY:	F (F)	Worship, completed in 2013. Further work to rainwater
	OWNER TYPE:	Religious organisation	goods is now complete, funded by a Listed Places of Worship Roof Repairs Grant. Some unsafe stonework was
	LIST ENTRY NUMBER:	1058924	removed by rope access masons in 2017, but the ornate tower is still in need of repair.
			Contact: Annie Evans 0117 975 0673

© Historic England



SITE NAME:	Church of St Michael and All Angels, Rye, Puriton	Parish church. C14 to C15 chancel nave and north aisle and early C13 unbuttressed west tower with lancet
DESIGNATION:	Listed Place of Worship grade I	window. South porch, north vestry. Coursed rubble, freestone dressings, mixed material roofs, interior has
CONDITION:	Poor	Perpendicular rood screen. Tower render failing and falling from the tower. Historic England gave advice following
PRIORITY CATEGORY:	C (C)	removal of the render in late 2016. Additional issues with
OWNER TYPE:	Religious organisation	the vestry wall and aisle roof remain.
LIST ENTRY NUMBER:	1344664	Contact: Annie Evans 0117 975 0673

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

OWNER TYPE:

DESIGNATION:

CONDITION:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

SITE NAME: Church of St Mary Magdalene, Stockland Bristol Parish church built in 1865 of blue lias rub Designed by Arthur of Plymouth for the I	Daniel family of
DESIGNATION: Listed Place of Worship grade II Stockland Manor. Roofs need re-covering number of slipped tiles. Structural stability	y is poor with
CONDITION: Poor cracking to window surrounds and major the tower, loose and bulging stonework.	fracture through
PRIORITY CATEGORY: C (C) valley gutter and one window which was	blown in, were
OWNER TYPE: Religious organisation carried out in 2017 and in 2019 the kneel the vestry gable were reset. The parish is	putting together
LIST ENTRY NUMBER: 1059049 proposals for repair but the church remainstance.	ins in a very poor

© Historic England

SITE NAME: Medieval estate boundary earthwork on Shute Shelve Hill, Axbridge / Winscombe and Sandford LIST ENTRY NUMBER: DESIGNATION: 1015495 Scheduled Monument Generally satisfactory but with minor localised CONDITION: TREND: Declining problems PRINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY? No OWNER TYPE: CONTACT: Charlotte Russell 01271 831505 Charity (heritage) Church of St Peter, Church Large parish church, with chancel, nave, quire aisles and SITE NAME: Lane, West Huntspill nave aisles, two-storeyed south porch and western tower. Largely C14, lias with Ham stone dressings. The church DESIGNATION: Listed Place of Worship grade I was gutted by fire in 1878 and restored in neo-Gothic style. The aisle roofs leak and are patched with sealant and CONDITION: Poor flashband as they are too fragile for more reliable repairs. PRIORITY CATEGORY: C (C)

Lias stone has problems, notably the north parapet, north aisle vice turret and the tower which is now roped off for safety. The congregation is putting together a bid to the National Lottery Heritage Fund for the tower and interior improvements.

Contact: Annie Evans 0117 975 0673

Contact: Annie Evans 0117 975 0673

SITE NAME:	Horsey medieva	l settlement immediately north of E	Board's Farm, Bridg	gwater Without
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1020438
CONDITION:	Extensive signific	ant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners		CONTACT:	Charlotte Russell 01271 831505
	SITE NAME: Church of St Mary, Main Road.		Parish church of	CI3. CI4. CI5. CI6 and CI9 with



Westonzoyland

Listed Place of Worship grade I

Religious organisation

Religious organisation

1060138

Fair

F (F)

1174351

significant additions by WD Caroe 1933-1939. Notable for housing 500 defeated rebels following the Battle of Sedgemoor in 1685. The CI5 timber roof structure is of considerable significance with carved angel corbels. The congregation undertook a large scheme of roof repair in 2016 with a Listed Places of Worship Roof Repairs Grant but there are concerns about the condition of the tower.

Contact: Annie Evans 0117 975 0673

© Historic England

© Historic England

SITE NAME:	Ruborough Camp large univallate hillfort, Broomfield		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007670
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric: solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM ÍΙΑ
- Unitary Authority World Heritage Site WHS

SITE NAME:	Timber trackways 850 metres east of Catcott Burt	le Farm, Burtle	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014433
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Cynwit Castle, Cannington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006225
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	World War II anti-aircraft rocket battery and bom Ashridge Farm, Cheddar	bing decoy control	building 265 metres north east of
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020994
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bronze Age and Iron Age timber trackways, 700 m	etres north west o	f Coppice Gate Farm, Shapwick
DESIGNATION:	Scheduled Monument		1014431
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Sections of the Sweet Track, the Post Track and as Farm, Shapwick	sociated remains 5	00 metres north east of Moorgate
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014438
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	John Ette 0117 975 0687
SITE NAME:	Bronze Age and Iron Age trackways 600 metres no	orth east of Northb	prook Farm, Ashcott / Shapwick
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014444
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Stowey Castle, the site of St Michael's Chapel and a	a medieval kiln site,	, Nether Stowey / Over Stowey
DESIGNATION:	Scheduled Monument, LB grade I, part in CA	LIST ENTRY NUMBER:	1019421
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / SOUTH WEST / SEDGEMOOR / SOMERSET WEST AND TAUNTON

SITE NAME:	Round barrows 600 yards (550 metres) north west of Longbottom Farm, Shipham			
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1006223
CONDITION:	Generally satisfactory but with minor localised problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Permitted develo	opment	NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Prehistoric timbe	er trackways, 670 metres SSE of P	Parchey Bridge, Staw	vell
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1014430
CONDITION:	Unknown		TREND:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering		NEW ENTRY?:	No
OWNER TYPE:	Government or a	agency	CONTACT:	Charlotte Russell 01271 831505
	SITE NAME:	Halswell Park, Broomfield / Goathurst	restored two im	pe park. Local preservation trusts have portant garden buildings but some other
	DESIGNATION:	Registered Park and Garden grade II, 17 LBs	structures remain in poor condition. The centrepiec the design, Mill Wood, was largely denuded of trees however it changed hands in spring 2015 and was re	
	CONDITION:	Extensive significant problems	with the house.	This has led to a major programme of pairs to structures including the listed Bat
	VULNERABILITY:	High	stone bridge. Despite this, the majority of the par	
	TREND:	Declining	under intensive o	cultivation.
	NEW ENTRY?:	No		
© Historic England	OWNER TYPE:	Mixed, multiple owners		
	LIST ENTRY NUMBER:	1001145	Contact: Jo McA	llister 0117 975 0696

SOMERSET WEST AND TAUNTON

	SITE NAME:	Sandhill Park, Bishop's Lydeard	Country house c1720. A fire in 2011 caused serious
	DESIGNATION:	Listed Building grade II*	damage to the roof structure and top floor. In 2013 planning permission was granted for an enabling
	CONDITION:	Very bad	development scheme which has now been completed, although works to the house did not commence. A second
	OCCUPANCY:	Vacant/not in use	phase of works for the conversion of the ancillary buildin and a new roof to the main house are in progress. Pre- application discussions continue in respect of the princip
	PRIORITY CATEGORY:	B (B)	
	OWNER TYPE:	Private	building as of 2021.
	LIST ENTRY NUMBER:	1295317	Contact: Rhiannon Rhys 0117 975 0685

© Historic England



© Historic England

	SITE NAME:	Gatehouse at Cothelstone Manor, Cothelstone	A mid C16 gatehouse which is part of a much larger estate. Consent has been granted for the repair of the gatehouse
	DESIGNATION:	Listed Building grade I, RPG grade II, CA	and work is anticipated to commence in 2021.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1059192	Contact: Rhiannon Rhys 0117 975 0685

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / SOUTH WEST / SOMERSET WEST AND TAUNTON

HERITAGE AT RISK 2021 / SOUTH	WEST / SOMERSET W	est and taunton	
	SITE NAME:	Remains of Chantry at Kilve, Sea Lane, Kilve	Early C14, with later medieval additions, formerly believed to be remains of collegiate dwelling of chantry priests. A
	DESIGNATION:	Scheduled Monument and Listed Building grade II*	Historic England survey has shown that the ruins are part of an important manorial complex. Historic England funded emergency repairs in 2010 and 2011, a conservation plan
	CONDITION:	Very bad	and further works in 2013 and 2014. Further jointly funded
	OCCUPANCY:	N/A	consolidation works were undertaken in 2015. Structural movement in one gable, which is propped, remains to be
	PRIORITY CATEGORY:	F (F)	addressed and a major phase of work is underway in 2020.
and the second sec	OWNER TYPE:	Private	
© Historic England	LIST ENTRY NUMBER:	1002960 and 1345688	Contact: Annie Evans 0117 975 0673
	SITE NAME:	Cloth finishing works at Tone Mills, North Range, Wellington	A near complete example of a C19 cloth dyeing and finishing works which developed between c1830 and
	DESIGNATION:	Listed Building grade II*	c1920. Somerset West and Taunton Council and Historic England are actively engaged in trying to find a solution to
the second second	CONDITION:	Very bad	conserve the buildings. The site has asbestos contamination and has suffered from vandalism on multiple occasions
	OCCUPANCY:	N/A	during the last five years.
	PRIORITY CATEGORY:	B (B)	
	OWNER TYPE:	Private	
© Historic England	LIST ENTRY NUMBER:	1271246	Contact: Annie Evans 0117 975 0673
SHEELEN.	SITE NAME:	Tonedale Mills (east complex), Milverton Road, Wellington	Eastern complex of an integrated multi-component wool textile factory, Split ownership with the eastern part in
	DESIGNATION:	Listed Building grade II*	beneficial use, but western parts disused and in very poor condition. Enforcement Action was undertaken in 2018 to
	CONDITION:	Very bad	secure Tonedale House following unauthorised works. Some further work has been undertaken in 2019-20 but
	OCCUPANCY:	Part occupied/part in use	this has left buildings in worse condition. Discussions
	PRIORITY CATEGORY:	B (B)	between owners, local authority and Historic England, concerning the future and conservation of the site, are
	OWNER TYPE:	Commercial company, multiple owners	ongoing.
© Historic England	LIST ENTRY NUMBER:	1176514	Contact: Annie Evans 0117 975 0673
	SITE NAME:	Tonedale Mills (west complex), Wellington	Western complex of an integrated multi-component wool textile factory, now largely disused. Consent was granted
	DESIGNATION:	Listed Building grade II*	for mixed use redevelopment of the complex. Works halted on site in 2008 and previous owners went into
	CONDITION:	Very bad	receivership leaving some buildings in a very vulnerable condition. The site has had some work carried out but
	OCCUPANCY:	Vacant/not in use	buildings are deteriorating rapidly. A section 215 notice has
	PRIORITY CATEGORY:	A (A)	been served and as of early 2020 only partially complied with. Discussions between the local authority, Historic
	OWNER TYPE:	Private	England and the owner concerning the future of the site
© Historic England	LIST ENTRY NUMBER:	1051987	and its conservation are ongoing. Contact: Annie Evans 0117 975 0673
San Bar	SITE NAME:	Church of St John, Park Street, Taunton	Built 1858-1863, by George Gilbert Scott. Chancel, nave, north and south aisles; north chapel; south porch and choir
	DESIGNATION:	Listed Place of Worship grade I, CA	vestries at the north-east. Prominent tower and spire with polychrome banded decoration, and figures of the apostles in tabernacles masking the broaches. Alterations have been
	CONDITION:	Poor	made to the west end to make the church accessible to a
	PRIORITY CATEGORY:	C (C)	wider range of people. However, the roofs are aging and in need of work, and the elaborate high level stonework is
	OWNER TYPE:	Religious organisation	potentially fragile.
	LIST ENTRY NUMBER:	1059951	Contact: Annie Evans 0117 975 0673
© Historic England			

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / SOUTH WEST / SOMERSET WEST AND TAUNTON

	SITE NAME:	Church of St Mary, Nettlecombe, Somerset West and Taunton	Church dates from C13-14 with later phases in C15, C16 and C19, and consists of nave, chancel, north and south aisles, chantry chapel and west tower. Its history and
	DESIGNATION:	Listed Place of Worship grade I, RPG grade II	development are closed related to that of the families in possession of Nettlecombe Court, situated nearby. In February 2021 a primary beam to the tower's third floor
	CONDITION: PRIORITY CATEGORY:	Poor	dramatically failed at its west bearing. Emergency propping was erected in March 2021, but the tower interior remains
		A (New entry)	roped off until a more permanent solution is put in place.
	OWNER TYPE:	Religious organisation	
© Historic England	LIST ENTRY NUMBER:	1173837	Contact: Sarah Ball 0117 975 0666

SITE NAME:The Castles, BathealtonDEGRAMTOR:Scheduled MonumentURTENTITIONER:[019150CONDITIONGrobbersGrobbersDecliningPRENDAR AUGURERRAUTOSchub/tree growchNoNoOWNERTY:Schub/tree growchKew NKTR:NoStruttoreBow barrow and folly ruins on Cohelstone Hill:Enter The SchubersSchubersStruttoreSchub barrow and folly ruins on Cohelstone Hill:Enter The NoDecliningCONDITIONGenerally satisfactory but with significant localisedINFONoCONDITIONGenerally satisfactory but with significant localisedNoNoCONDITIONGenerally satisfactory but with significant localisedNoNoCONDITIONScheduled MonumentNONONOConDITIONScheduled MonumentNONONO </th <th></th> <th></th> <th></th> <th></th>				
concernineGenerally satisfactory but with significant localised problemsTRINODecliningRINCEAR VALINERABILITY:Sorval/tree growthNON PATERY:NoOWNET TITE:Bowl barrow and folly ruins on Cothelstone Hill, I bitmere north:St Andree Russell 01271 831505STENART:Bowl barrow and folly ruins on Cothelstone Hill, I bitmere north:St Anges' Well, CothelstoneDESIGNATION:Generally satisfactory but with significant localised problemsIntendoNoCONDITION:Generally satisfactory but with significant localised problemsNoNoCONDITION:Generally satisfactory but with significant localised problemsNoNoCONDITION:Good authorityCONIACT:Charlotte Russell 01271 831505STENART:Local authorityCONIACT:Charlotte Russell 01271 831505STENART:Bowl barrow on Cothelstone Hill, 1070 metresNoNoCONDITION:Generally satisfactory but with significant localised problemsIRENONoSTENART:ConduityContact Russell 01271 831505NoSTENART:ConduityContact Russell 01271 831505NoSTENART:ConduityContact Russell 01271 831505NoSTENART:ConduityStatisfactory but with significant localised problemsNoSTENART:ConduityContact Russell 01271 831505NoSTENART:ConduityStatisfactory but with significant localised problemsNoSTENART:Contact Russell 01271 831505NoSTENART: <td< td=""><td>SITE NAME:</td><td>The Castles, Bathealton</td><td></td><td></td></td<>	SITE NAME:	The Castles, Bathealton		
Proclemin TYPINCENT VALUE TYPINCENT VALUE<	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019150
DVMRETIPEPrivate, multiple ownersCONTACT:Charlotte Russell 01271 831505SITE IMME:Bow barrow and folly ruins on Cochelstone Hill, I JUTTER YMMERE015086DEGENATION:Scheduled MonumentINTERN:016086CONDITION:Generally satisfactory but with significant localisedmr.no:DecliningPRIVECTIV. VULNERWARDITY:Visitor erosion - limited/localisedNEW ENTRY:NoOWNER TITP:Local authorityCONTACT:Charlotte Russell 01271 831505DESIGNATION:Scheduled MonumentLOT FUTTE YMMEREUS DOBYDESIGNATION:Scheduled MonumentINTERN:NoCONDITION:Generally satisfactory but with significant localised provingmr.no:NoCONDITION:Scrub / tree growthNEW ENTRY:NoSITE MME:Barrow and cain centery on Black Hill, 490 metrs:VISIORNoSITE MME:Generally satisfactory but with significant localised provingmr.no:NoSITE MME:Scheduled MonumentUST FUTTE YMMERE101981DESIGNATION:Scheduled MonumentUST FUTTE YMMERENoSITE MME:Scheduled MonumentUST FUTTE YMMERENoSITE MME:Designificant localised provingmr.no:NoSITE MME:Designificant localised provingmr.no:NoSITE MME:Scheduled MonumentUST FUTE YMMERENoSITE MME:Designificant localised provingmr.no:NoSITE MME:Designificant localised provingmr.no: <td>CONDITION:</td> <td></td> <td>TREND:</td> <td>Declining</td>	CONDITION:		TREND:	Declining
Sile NAME: Bowl barrow and folly ruis on Cothelstone Hill, I view environment USE ENTRY NUMBER: I Of SOB DESIGNATION: Scheduled Monument UST ENTRY NUMBER: I Of SOB CONDITON: Generally statisfactory but with significant localised TREND: No OWNERT TYPE: Visitor erosion - limited/localised NEW ENTRY: No OWNERT TYPE: Cocal authority CONDITION: Coharlotte Russell 01271 831 SOS DESIGNATION: Scheduled Monument UST ENTRY NUMBER: Marco Algenesity 10271 831 SOS DESIGNATION: Scheduled Monument UST ENTRY NUMBER: Inproving CONDITION: Scheduled Monument UST ENTRY NUMBER: Inproving OWNERT TYPE: Scrub / tree growth NEW ENTRY: No OWNERT TYPE: Cocal authority CONDITION: ID19381 DESIGNATION: Scheduled Monument UST ENTRY NUMBER: ID19381 CONDITION: Generally statisfactory but with significant localise IPEND: Condition Entry NUMBER: CONDITION: Generally statisfactory but with significant localise IPEND: Condinotte Russell 01271 831505 </td <td>PRINCIPAL VULNERABILITY:</td> <td>Scrub/tree growth</td> <td>NEW ENTRY?:</td> <td>No</td>	PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1015086condition:Generally satisfactory but with significant localised problemsNEND:DecliningPRINCIPAL VULNERABILITY:Visitor erosion - limited/localisedNEW ENTRY:NoCONTRCT:Controlter Russell 01271 831505DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1015087CONTRCT:Scheduled MonumentLIST ENTRY NUMBER:1015087CONTRCT:Generally satisfactory but with significant localised problemsTREND:ImprovingCONTRCT:Generally satisfactory but with significant localised problemsTREND:NoCONTRCT:Controlter Russell 01271 831505CONTRCT:Controlter Russell 01271 831505STEL MARE:Barrow and cairn centery on Black Hill, 490 metres:NoCONTRON:Generally satisfactory but with significant localised problemsTREND:IngrovingCONTRON:Generally satisfactory but with significant localised problemsTREND:NoCONTRON:Generally satisfactory but with significant localised problemsTREND:NoCONTRON:Generally satisfactory but with significant localised problemsTREND:NoCONTRON:Controlter Russell 01271 831505NoSTE MARE:DescontrolterIST ENTRY NUMBER:101494Controlter:Vehicle damage/erosion - moderateNEW ENTRY:NoCONTRON:Scheduled MonumentIST ENTRY NUMBER:101494Controlter:Scheduled MonumentI	OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
CONDITION:Generally satisfactory but with significant localisedTREND:DecliningPRINCIPAL VULUERABATIC:Visitor erosion - limited/localisedNAW ENTRY:NoOWNER TYPE:Local authorityCONTACT:Charlotte Russell 01271 831505SITE NAME:Bow barrow on Cochelstone Hill, 1,070 metres	SITE NAME:	Bowl barrow and folly ruins on Cothelstone Hill, I	kilometre north ea	ast of St Agnes' Well, Cothelstone
Condensitie problems Induction Detailing PRINCIPAL VOLINERABULT? Visitor erosion - limited/localised NetWENTRY: No OWNER TYPE: Local authority CONTACT: Charlotte Russell 01271 831505 SITE NAME: Bowl barrow on Cothelstone Hill, 1,070 metres nort east of St Agness' Well, Cothelstone IDISOR DISIGNATION: Scheduled Monument Lot INTRY NUMBER IDISOR CONDITION: Scheduled Monument Lot INTRY NUMBER Inproving CONDITION: Scheduled Monument No Improving OWNER TYPE: Local authority CONTACT: No OWNER TYPE: Local authority CONTACT: Charlotte Russell 01271 831505 SITE NAME: Barrow and cairn centery on Black Hill, 490 metry: No CONDITION: Scheduled Monument Lot BITRY NUMBER: 1019381 CONDITION: Scheduled Monument Lot BITRY NUMBER: No CONDITION: Scheduled Monument Lot BITRY: No CONDITION: Generally satisfactory but with significant localised TREND: Declining	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015086
OWNERT TYPE:Local authorityCONTACT:Charlotte Russell 01271 831505STITE NAME:Book barrow on Cothelstone Hill, 1070 metres	CONDITION:		TREND:	Declining
STIE NAME Bow barrow on Cothelstone Hill, 1,070 metres nor best of St Agnet VILL, Cothelstone DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015087 CONDITION: Generally satisfactory but with significant localised problems TREND: Improving PRINCIPAL VULNERABILITY: Scrub / tree growth NEW ENTRY: No OWNER TYPE: Local authority CONTACT: Charlotte Russell 01271 831505 DISIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1019381 CONDITION: Generally satisfactory but with significant localised problems TREND: Improving CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1019381 CONDITION: Generally satisfactory but with significant localised problems No OWNER TYPE: Vehicle damage/erosion - moderate New ENTRY: No OWNER TYPE: Dowsborough hillfort and associated round barrow-WETTY: No CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1010494 CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1010494 CONDITION: Scheduled Monument	PRINCIPAL VULNERABILITY:	Visitor erosion - limited/localised	NEW ENTRY?:	No
DEIGRANTION:Scheduled MonumentUST ENTRY NUMERE1015087CONDITION:Generally satisfactory but with significant localised problemsTREND:ImprovingPRINCIPAL VULNERABILITY:Scrub/tree growthNEW ENTRY:NoOWNER TYPE:Local authorityCONTACT:Charlotte Russell 01271 831505SITE NAMEBarrow and cairn cemetery on Black Hill, 490 metry:Notatte Russell 01271 831505DISIGNATION:Scheduled MonumentIDTE NTRY NUMERE1019381CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningRRINCIPAL VULNERABILITY:Vehicle damage/erosion - moderateNEW ENTRY:NoOWNER TYPE:Dowsborough hilfort and associated round barrowHOFOTDISIGNATION:Scheduled MonumentIDTE INTRY NUMBER1010494ONDITION:Scheduled MonumentIDTE INTRY NUMBER1010494DISIGNATION:Scheduled MonumentIDTE INTRY NUMBER1010494CONDITION:Generally satisfactory but with significant localised problemsTREND:NoRINCIPAL VULNERABILITY:Vehicle damage/erosion - moderateNEW ENTRY:NoOWNER TYPE:PrivateCONTACT:Charlotte Russell 01271 831505STE NAME:Entrenchment on Heydon Hill, Huish ChampflowerNEW ENTRY:NoOWNER TYPE:Scheduled MonumentIDTE INTRY NUMBER1006173STE NAME:Entrenchment on Heydon Hill, Huish ChampflowerIDTE INTRY NUMBER1006173Stenation:Scheduled MonumentI	OWNER TYPE:	Local authority	CONTACT:	Charlotte Russell 01271 831505
CONCINCINAL CONDITION:Generally satisfactory but with significant localised problemsTREND:ImprovingPRINCIPAL VULNERABILITY:Scrub/tree growthNEW ENTRY:NoOWNER TYPE:Local authorityCONTACT:Charlotte Russell 01271 831505STE NAME:Barrow and cairn cemetery on Black Hill, 490 metresCONTACT:Charlotte Russell 01271 831505DESIGNATION:Scheduled MonumentUST ENTRY NUMBER:1019381CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Vehicle damage/erosion - moderateNEW ENTRY:NoOWNER TYPE:Dowsborough hilfort and associated round barrow.NoSTE NAME:Dowsborough hilfort and associated round barrow.IntenD:Did10494CONDITION:Generally satisfactory but with significant localised problemsTREND:Did10494CONDITION:Scheduled MonumentUST ENTRY NUMBER:1010494CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningREINCIPAL VULNERABILITY:Vehicle damage/erosion - moderateNEW ENTRY:NoCONDITION:Generally satisfactory but with significant localised problemsTREND:Did10494CONDITION:Scheduled MonumentUST ENTRY NUMBER:1010494CONDITION:PrivateCONTACT:Charlotte Russell 01271 831505STET NAME:Entrenchment on Heydon Hill, Huish ChampflowerIST ENTRY NUMBER:1006173CONDITION:Schedul	SITE NAME:	Bowl barrow on Cothelstone Hill, 1,070 metres no	orth east of St Agne	s' Well, Cothelstone
CONDITION:problemsProbl	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015087
OWNER TYPE:Local authorityCONTACT:Charlotte Russell 01271 831505SITE NAME:Barrow and cairn cemetery on Black Hill, 490 metersIVENTERY NUMBERF1019381DESIGNATION:Scheduled MonumentIVEN TRY NUMBERF1019381CONDITION:Generally satisfactory but with significant localised problemsIREND:DecliningPRINCIPAL VULNERABILITY:Vehicle damage/erosion - moderateNEW ENTRY:NoOWNER TYPE:PrivateCONTACT:Charlotte Russell 01271 831505SITE NAME:Dowsborough hillfort and associated round barrow-HoffordIVEN ENTRY NUMBERF1010494CONDITION:Generally satisfactory but with significant localised problemsIVEN ENTRY NUMBERF1010494CONDITION:Generally satisfactory but with significant localised problemsIVEN ENTRY:NoCONDITION:Scheduled MonumentUST ENTRY NUMBERFIO10494CONDITION:Vehicle damage/erosion - moderateNEW ENTRY:NoOWNER TYPE:Fitzenchment on Heydon Hill, Huish Champflow-IVEN ENTRY NUMBERFIO6173SITE NAME:Scheduled MonumentUST ENTRY NUMBERFIO6173DESIGNATION:Scheduled MonumentUST ENTRY NUMBERFIO6173SITE NAME:Scheduled MonumentUST ENTRY NUMBERFIO6173DESIGNATION:Scheduled MonumentUST ENTRY NUMBERFIO6173DESIGNATION:Scheduled MonumentUST ENTRY NUMBERFIO6173DESIGNATION:Scheduled MonumentUST ENTRY NUMBERFIO6173CONDITION:Ge	CONDITION:		TREND:	Improving
strte NAME:Barrow and cairn cemetery on Black Hill, 490 metvorth west of C-vocombe Park Gate, HolfordDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1019381coNDITION:Generally satisfactory but with significant localised problemsREND:DecliningPRINCIPAL VULNERABILITY:Vehicle damage/erosion - moderateNew ENTRY:NoOWNER TYPE:PrivateCONTACT:Charlotte Russell 01271 831505SITE NAME:Dowsborough hilfort and associated round barrow-IUST ENTRY NUMBER:1010494CONDITION:Scheduled MonumentLIST ENTRY NUMBER:1010494CONDITION:Generally satisfactory but with significant localised problemsINEND:DecliningPRINCIPAL VULNERABILITY:Vehicle damage/erosion - moderateNEW ENTRY:NoOWNER TYPE:FrivateCONTACT:Charlotte Russell 01271 831505PRINCIPAL VULNERABILITY:Vehicle damage/erosion - moderateNEW ENTRY:NoOWNER TYPE:FrivateCONTACT:Charlotte Russell 01271 831505SITE NAME:Entrenchment on Heydon Hill, Huish ChampflowerNoNoSITE NAME:Scheduled MonumentLIST ENTRY NUMBER:1006173SITE NAME:Scheduled MonumentLIST ENTRY NUMBER:1006173OWNER TYPE:Scheduled MonumentLIST ENTRY NUMBER:1006173SITE NAME:Scheduled MonumentLIST ENTRY NUMBER:1006173SITE NAME:Scheduled MonumentLIST ENTRY NUMBER:1006173SITE NAME:Scheduled MonumentLIST ENTR	PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
DESIGNATION:Scheduled MonumentUST ENTRY NUMBER:1019381CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Vehicle damage/erosion - moderateNEW ENTRY?NoOWNER TYPE:PrivateCONTACT:Charlotte Russell 01271 831505SITE NAME:Dowsborough hillfort and associated round barrow.HoffordDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1010494CONDITION:Scheduled MonumentILST ENTRY NUMBER:1010494CONDITION:Generally satisfactory but with significant localised problemsNEW ENTRY:NoOWNER TYPE:Vehicle damage/erosion - moderateNEW ENTRY:NoOWNER TYPE:FrivateContact:Charlotte Russell 01271 831505SITE NAME:DefiningCONTACT:NoOWNER TYPE:Vehicle damage/erosion - moderateNEW ENTRY:NoOWNER TYPE:Entrenchment on Heydon Hill, Huish ChampflowerUST ENTRY NUMBER:1006173Scheduled MonumentLIST ENTRY NUMBER:1006173Condition:CONDITION:Scheduled MonumentUST ENTRY NUMBER:1006173Condition:Scheduled MonumentNEW ENTRY:NoCondition:Scheduled MonumentNEW ENTRY:NoCondition:Scheduled MonumentNEW ENTRY:NoProblemsWeite damage/erosion - moderateNEW ENTRY:NoProblemsScheduled MonumentNEW ENTRY:No	OWNER TYPE:	Local authority	CONTACT:	Charlotte Russell 01271 831505
condition:Generally satisfactory but with significant localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Vehicle damage/erosion - moderateNEW ENTRY?:Noowner TYPE:PrivateContact:Charlotte Russell 01271 831505STE NAME:Dowsborough hilfort and associated round barrowHofortDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER1010494condition:Generally satisfactory but with significant localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Vehicle damage/erosion - moderateNEW ENTRY?:NoOWNER TYPE:FirstenInternchment JettingNew ENTRY?:NoSTE NAME:Enternchment Jetting NumberInternchment JettingNoSTE NAME:Enternchment Heydon Hill, Huish ChampflowerScheduled MonumentInternchment JettingSTE NAME:Scheduled MonumentInternchment Jetting106173ONDITION:Generally satisfactory but with significant localised problemsInternchment JettingInternchment JettingSTE NAME:Scheduled MonumentInternchment JettingJolof173Jolof173ONDITION:Scheduled MonumentInternchment JettingJolof173ONDITION:Scheduled MonumentInternchment JettingJolof173ONDITION:Scheduled MonumentInternchment JettingJolof173ONDITION:Scheduled MonumentInternchment JettingJolof173ONDITION:Scheduled MonumentInternchment JettingJolof173ONDITION: <td>SITE NAME:</td> <td>Barrow and cairn cemetery on Black Hill, 490 metr</td> <td>res north west of C</td> <td>rowcombe Park Gate, Holford</td>	SITE NAME:	Barrow and cairn cemetery on Black Hill, 490 metr	res north west of C	rowcombe Park Gate, Holford
PRINCIPAL VULNERABILITY:Vehicle damage/erosion - moderateNEW ENTRY:NoOWNER TYPE:PrivateCONTACT:Charlotte Russell 01271 831505SITE NAME:Dowsborough hillfort and associated round barrow, HolfordInterdet Russell 01271 831505DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1010494CONDITION:Generally satisfactory but with significant localised problemsNEW ENTRY:NoPRINCIPAL VULNERABILITY:Vehicle damage/erosion - moderateNEW ENTRY:NoOWNER TYPE:FrivateCONTACT:Contact:Contact:SITE NAME:Entrenchment on Heydon Hill, Huish ChampflowerUST ENTRY NUMBER:1006173SITE NAME:Scheduled MonumentLIST ENTRY NUMBER:1006173ONDITION:Generally satisfactory but with significant localised problemsINEW ENTRY:NoOWNER TYPE:Entrenchment on Heydon Hill, Huish ChampflowerInterdet Russell 01271 831505SITE NAME:Generally satisfactory but with significant localised problemsINTERN NUMBER:1006173CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningCONDITION:Generally satisfactory but with significant localised problemsNEW ENTRY:NoPRINCIPAL VULNERABILITY:Vehicle damage/erosion - moderateNEW ENTRY:No		•		
OWNER TYPE:PrivateCONTACT:Charlotte Russell 01271 831505STE NAME:Dowsborough hilffort and associated round barrowHoffordDESIGNATION:Scheduled MonumentIST ENTRY NUMBER1010494CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Vehicle damage/erosion - moderateNEW ENTRY:NoOWNER TYPE:PrivateCONTACT:Charlotte Russell 01271 831505SITE NAME:Entrenchment OHEydon Hill, Huish ChampflowerScheduled MonumentScheduled MonumentDESIGNATION:Scheduled MonumentIST ENTRY NUMBER106173CONDITION:Generally satisfactory but with significant localised problemsIST ENTRY NUMBER106173DESIGNATION:Scheduled MonumentIST ENTRY NUMBERIocalistation ControlCONDITION:Scheduled MonumentIST ENTRY NUMBERIocalistation ControlCONDITION:Scheduled MonumentIST ENTRY NUMBERIocalistation ControlCONDITION:Scheduled MonumentIST ENTRY NUMBERIocalistation ControlCONDITION:Scheduled MonumentIST ENTRY NUMBERIocalistation ControlPRINCIPAL VULNERABILITY:Vehicle damage/erosion - moderateNEW ENTRY:No	DESIGNATION:		LIST ENTRY NUMBER:	1019381
STE NAME:Dowsborough hillfort and associated round barrowHolfortDEGIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1010494CONDITION:Generally satisfactory but with significant localised problemsREND:DecliningPINICIPAL VULNERABILITY:Vehicle damage/erosion - moderateNEW ENTRY:NoOWNER TYPE:FirvateEnterchment on Heydon Hill, Huish ChampflowScheduled MonumentIST ENTRY NUMBER:1006173DESIGNATION:Scheduled MonumentIST ENTRY NUMBER:1006173Scheduled MonumentCONDITION:Generally satisfactory but with significant localised problemsIREND:DecliningDESIGNATION:Scheduled MonumentIST ENTRY NUMBER:1006173CONDITION:Generally satisfactory but with significant localised problemsIREND:DecliningPINCIPAL VULNERABILITY:Vehice damage/erosion - moderateNEW ENTRY:No		Scheduled Monument Generally satisfactory but with significant localised		
DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1010494CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Vehicle damage/erosion - moderateNEW ENTRY?NoOWNER TYPE:PrivateCONTACT:Charlotte Russell 01271 831505SITE NAME:Entrenchment on Heydon Hill, Huish ChampflowerVenice Ausge/erosion - moderateIST ENTRY NUMBER:DESIGNATION:Scheduled MonumentIST ENTRY NUMBER:1006173condition:Generally satisfactory but with significant localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Vehicle damage/erosion - moderateNEW ENTRY?No	CONDITION:	Scheduled Monument Generally satisfactory but with significant localised problems	TREND:	Declining
CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningPINCIPAL VULNERABILITY:Vehicle damage/erosion - moderateNEW ENTRY?:NoOWNER TYPE:PrivatePrivateCONTACT:Charlotte Russell 01271 831505SITE NAME:Entrenchment on Heydon Hill, Huish ChampflowerVVDESIGNATION:Scheduled MonumentIST ENTRY NUMBER1006173CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningPINCIPAL VULNERABILITY:Vehicle damage/erosion - moderateNEW ENTRY:No	CONDITION: PRINCIPAL VULNERABILITY:	Scheduled Monument Generally satisfactory but with significant localised problems Vehicle damage/erosion - moderate	TREND: NEW ENTRY?:	Declining No
PRINCIPAL VULNERABILITY:Vehicle damage/erosion - moderateNEW ENTRY:NoOWNER TYPE:PrivateCONTACT:Charlotte Russell 01271 831505SITE NAME:Entrenchment on Heydon Hill, Huish ChampflowerCONTACT:Charlotte Russell 01271 831505DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1006173CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Vehicle damage/erosion - moderateNEW ENTRY:No	CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument Generally satisfactory but with significant localised problems Vehicle damage/erosion - moderate Private	TREND: NEW ENTRY?: CONTACT:	Declining No
OWNER TYPE:PrivateCONTACT:Charlotte Russell 01271 831505SITE NAME:Entrenchment on Heydon Hill, Huish ChampflowerDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1006173CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Vehicle damage/erosion - moderateNEW ENTRY:No	CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument Generally satisfactory but with significant localised problems Vehicle damage/erosion - moderate Private Dowsborough hillfort and associated round barrow	TREND: NEW ENTRY?: CONTACT: v, Holford	Declining No Charlotte Russell 01271 831505
SITE NAME: Entrenchment on Heydon Hill, Huish Champflower DESIGNATION: Scheduled Monument IJST ENTRY NUMBER: 1006173 CONDITION: Generally satisfactory but with significant localised problems TREND: Declining PRINCIPAL VULNERABILITY: Vehicle damage/erosion - moderate NEW ENTRY?: No	CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument Generally satisfactory but with significant localised problems Vehicle damage/erosion - moderate Private Dowsborough hillfort and associated round barrow Scheduled Monument Generally satisfactory but with significant localised	TREND: NEW ENTRY?: CONTACT: VHOIFORD LIST ENTRY NUMBER:	Declining No Charlotte Russell 01271 831505 1010494
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006173 CONDITION: Generally satisfactory but with significant localised problems TREND: Declining PRINCIPAL VULNERABILITY: Vehicle damage/erosion - moderate NEW ENTRY?: No	CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Scheduled Monument Generally satisfactory but with significant localised problems Vehicle damage/erosion - moderate Private Dowsborough hillfort and associated round barrow Scheduled Monument Generally satisfactory but with significant localised problems	TREND: NEW ENTRY?: CONTACT: VHOIfOrd LIST ENTRY NUMBER: TREND:	Declining No Charlotte Russell 01271 831505 1010494 Declining
CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Vehicle damage/erosion - moderateNEW ENTRY?:No	CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY:	Scheduled Monument Generally satisfactory but with significant localised problems Vehicle damage/erosion - moderate Private Dowsborough hillfort and associated round barrow Scheduled Monument Generally satisfactory but with significant localised problems Vehicle damage/erosion - moderate	TREND: NEW ENTRY?: CONTACT: WHOIFORD LIST ENTRY NUMBER: TREND: NEW ENTRY?:	Declining No Charlotte Russell 01271 831505 1010494 Declining No
PRINCIPAL VULNERABILITY: Vehicle damage/erosion - moderate NEW ENTRY?: No	CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument Generally satisfactory but with significant localised problems Vehicle damage/erosion - moderate Private Dowsborough hillfort and associated round barrow Scheduled Monument Generally satisfactory but with significant localised problems Vehicle damage/erosion - moderate Private	TREND: NEW ENTRY?: CONTACT: WHOIFOORD IJST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:	Declining No Charlotte Russell 01271 831505 1010494 Declining No
	CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument Generally satisfactory but with significant localised problems Vehicle damage/erosion - moderate Private Dowsborough hillfort and associated round barrow Scheduled Monument Generally satisfactory but with significant localised problems Vehicle damage/erosion - moderate Private Entrenchment on Heydon Hill, Huish Champflower	TREND: NEW ENTRY?: CONTACT: CONTACT: Holford LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:	Declining No Charlotte Russell 01271 831505 1010494 Declining No Charlotte Russell 01271 831505
OWNER TYPE: Private CONTACT: Charlotte Russell 01271 831505	CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: CONDITION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument Generally satisfactory but with significant localised problems Vehicle damage/erosion - moderate Private Dowsborough hillfort and associated round barrow Scheduled Monument Generally satisfactory but with significant localised problems Vehicle damage/erosion - moderate Private Entrenchment on Heydon Hill, Huish Champflower Scheduled Monument Generally satisfactory but with significant localised Private	TREND: NEW ENTRY?: CONTACT: (DIST ENTRY NUMBER: TREND: (DIST ENTRY): (CONTACT: (DIST ENTRY): (DIST ENTRY): (DIST ENTRY NUMBER: (DIST ENTRY NUMBER:	Declining No Charlotte Russell 01271 831505 1010494 Declining No Charlotte Russell 01271 831505
	CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: CONDITION:	Scheduled Monument Generally satisfactory but with significant localised problems Vehicle damage/erosion - moderate Private Dowsborough hillfort and associated round barrow Scheduled Monument Generally satisfactory but with significant localised problems Vehicle damage/erosion - moderate Private Entrenchment on Heydon Hill, Huish Champflower Scheduled Monument Generally satisfactory but with significant localised problems Vehicle damage/erosion - moderate Private Entrenchment on Heydon Hill, Huish Champflower Scheduled Monument Generally satisfactory but with significant localised problems	TREND: NEW ENTRY?: CONTACT: CONTACT: Holford IIST ENTRY NUMBER: CONTACT: CONTACT: LIST ENTRY NUMBER: TREND: LIST ENTRY NUMBER: TREND:	Declining No Charlotte Russell 01271 831505 1010494 Declining No Charlotte Russell 01271 831505

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В

implemented. C Slow decay; no solution agreed.

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / SOUTH WEST / SOMERSET WEST AND TAUNTON

SITE NAME:	Four medieval fish weirs 500 metres east of the Ha	rbour, Minehead	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020017
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Duck decoy 250 metres north west of Moredon H	ouse, North Curry	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014441
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Two bowl barrows 210 metres and 600 metres no	rth west of Brown	Down Cottage, Otterford
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016414
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Poundisford Park Pale, Pitminster / Trull		
DESIGNATION:	Scheduled Monument, part in RPG grade II	LIST ENTRY NUMBER:	1002957
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Curdon Wood Camp, Stogumber		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006158
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Stringston churchyard cross, Stringston		
DESIGNATION:	Scheduled Monument, 2 LBs	LIST ENTRY NUMBER:	1006171
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Religious organisation	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Cairn 280 metres south of Triscombe Stone, West	: Bagborough	
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1016707
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / SOUTH WEST / SOMERSET WEST AND TAUNTON / SOUTH SOMERSET

SITE NAME:	Round barrow c	emetery at Battle Gore immediate	e immediately west of North Road, Williton	
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1019032
CONDITION:	Generally unsatis problems	factory with major localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping		NEW ENTRY ?:	No
OWNER TYPE:	Private		CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Camp south of N	1anor Farm, Wiveliscombe		
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1006167
CONDITION:	Extensive significant problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Commercial company		CONTACT:	Charlotte Russell 01271 831505
	SITE NAME:	St Audries (House), West Quantoxhead / Williton	C19 gardens and pleasure grounds, surrounding a C mansion, together with parkland developed from the C18 and improved in the mid-C19. St Audries has h succession of institutional uses. The parkland is most under cultivation and few parkland trees survive. St <i>J</i> house and gardens are in use as a wedding venue. In walled garden, former school buildings have recently converted to wedding accommodation.	
	DESIGNATION:	Registered Park and Garden grade II, 16 LBs		
	CONDITION:	Generally satisfactory but with significant localised problems		
	VULNERABILITY:	Medium	converted to we	
	TREND:	Improving		
	NEW ENTRY?:	No		
	OWNER TYPE:	Mixed, multiple owners		
	LIST ENTRY NUMBER:	1001155	Contact: lo McA	llister 0117 975 0696

SITE NAME:	Wellington		
DESIGNATION:	Conservation Area, 90 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Low	CONTACT:	Nigel Pratt (LPA) 01823 356492

SOUTH SOMERSET

	SITE NAME:	Top mill building, Higher Flax Mills, Torbay Road, Castle Cary	This mid C19 former mill has been sold and an application approved for conversion to one live/work unit in 2011.
	DESIGNATION:	Listed Building grade II*, CA	Works are underway and making slow but good progress. The southern roof is now complete. The building is mostly
	CONDITION:	Poor	occupied. Work is still ongoing as of 2021.
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Private	
© South Somerset District Council	LIST ENTRY NUMBER:	1056226	Contact: Rhiannon Rhys 0117 975 0685



D

Е

SITE NAME:	Chard School, Fore Street, Chard Town
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Educational (independent)
LIST ENTRY NUMBER:	1205594

The building dates to 1583. It became Chard Grammar School in 1671 and has been a school ever since. It has an L-Plan layout with five bays, a rear wing and two storeys with attics. The building was an advanced plan form for its date, notable for passage access to the main rooms. Features include squared chert Hamstone dressings, window hoods and mullions, plain tile roof and brick stacks. The rainwater goods are inadequate, areas of water ingress and structural issues where trusses have been altered.

Contact: Annie Evans 0117 975 0673

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument
- SM

UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Waterloo House and Manor Court House, 7A, 7B, 9, 11, 13 and 13A, Fore Street, Chard Town	Late C16/early C17 group of shops, offices, houses and flats with two prominent projecting two and three storey porches. A 2010 planning appeal refused a proposed subdivision to create smaller units. In 2014 the Local
	DESIGNATION:	Listed Building grade I, CA	Authority commissioned a feasibility study with Historic England grant-aid. Work to repair the three-storey porch
	CONDITION:	Poor	to 7A was completed in 2018 with Historic England grant- aid. Discussions with the multiple owners over options for
	OCCUPANCY:	Part occupied/part in use	the building are continuing.
and the second second	PRIORITY CATEGORY:	C (C)	
Historic England	OWNER TYPE:	Mixed, multiple owners	
	LIST ENTRY NUMBER:	1197449	Contact: Annie Evans 0117 975 0673
6	SITE NAME:	Gatehouse to Cathanger, Cathanger Lane, Fivehead	Late C16 gatehouse to Cathanger Manor, with central throughway and first floor over. Banded lias and Ham
	DESIGNATION:	Listed Building grade II*	stone, thatched roof, wood coving to eaves. Principal trusses have spread and wall plates have moved outwards.
	CONDITION:	Poor	Crude props inserted to support the collars are causing significant deflection to first floor and damage to partition
	OCCUPANCY:	Vacant/not in use	and door jamb. Decay to main beam and joists on south.
	PRIORITY CATEGORY:	C (C)	Thatch thin with water ingress. Historic England staff have provided advice and temporary roof repair has been
	OWNER TYPE:	Private	carried out by the owners.
Historic England	LIST ENTRY NUMBER:	1249561	Contact: Annie Evans 0117 975 0673
	SITE NAME:	Madey Mill, East Street, Martock	Water mill with medieval origins, although current building
T	DESIGNATION:	Listed Building grade II*	are largely C17. The building is situated on a working farm, is under-used and is suffering from lack of maintenance.
	CONDITION:	Poor	Viable new uses and/or funding opportunities need to be
	CONDITION: OCCUPANCY:	Poor Part occupied/part in use	Viable new uses and/or funding opportunities need to be investigated to obtain adequate funding for repairs. A Historic England funded condition survey has been
			Viable new uses and/or funding opportunities need to be investigated to obtain adequate funding for repairs. A Historic England funded condition survey has been completed, identifying urgent repairs but as of 2019 the condition remains poor. Historic England hopes to work
	OCCUPANCY:	Part occupied/part in use	Viable new uses and/or funding opportunities need to be investigated to obtain adequate funding for repairs. A Historic England funded condition survey has been completed, identifying urgent repairs but as of 2019 the
	OCCUPANCY: PRIORITY CATEGORY:	Part occupied/part in use C (C)	Viable new uses and/or funding opportunities need to be investigated to obtain adequate funding for repairs. A Historic England funded condition survey has been completed, identifying urgent repairs but as of 2019 the condition remains poor. Historic England hopes to work
THE HEAD	OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER:	Part occupied/part in use C (C) Private 1226550	Viable new uses and/or funding opportunities need to be investigated to obtain adequate funding for repairs. A Historic England funded condition survey has been completed, identifying urgent repairs but as of 2019 the condition remains poor. Historic England hopes to work further with the owners regarding repair and reuse. Contact: Chris Miners 0117 975 1355
THE HEAD	OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:	Part occupied/part in use C (C) Private	Viable new uses and/or funding opportunities need to be investigated to obtain adequate funding for repairs. A Historic England funded condition survey has been completed, identifying urgent repairs but as of 2019 the condition remains poor. Historic England hopes to work further with the owners regarding repair and reuse. Contact: Chris Miners 0117 975 1355 Attached to this chantry college is a group of medieval and C16 farm buildings, some of which are in poor condition
THE HEAD	OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER:	Part occupied/part in use C (C) Private 1226550 Secular college at Parsonage	Viable new uses and/or funding opportunities need to be investigated to obtain adequate funding for repairs. A Historic England funded condition survey has been completed, identifying urgent repairs but as of 2019 the condition remains poor. Historic England hopes to work further with the owners regarding repair and reuse. Contact: Chris Miners 0117 975 1355 Attached to this chantry college is a group of medieval and C16 farm buildings, some of which are in poor condition and unroofed. However others, such as the threshing barr are capable of beneficial use. Owned by the National Trus Historic England has had a number of meetings on site and
THE HEAD	OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER: SITE NAME:	Part occupied/part in use C (C) Private 1226550 Secular college at Parsonage Farm, Stoke Sub Hamdon Scheduled Monument and Listed Buildings - 1 grade 1; 6 grade II,	Viable new uses and/or funding opportunities need to be investigated to obtain adequate funding for repairs. A Historic England funded condition survey has been completed, identifying urgent repairs but as of 2019 the condition remains poor. Historic England hopes to work further with the owners regarding repair and reuse. Contact: Chris Miners 0117 975 1355 Attached to this chantry college is a group of medieval and C16 farm buildings, some of which are in poor condition and unroofed. However others, such as the threshing barr are capable of beneficial use. Owned by the National Trus Historic England has had a number of meetings on site and funded an options appraisal to consider ways of bringing the buildings back into use. As of 2020, Historic England
THE HEAD	OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER: SITE NAME: DESIGNATION:	Part occupied/part in use C (C) Private 1226550 Secular college at Parsonage Farm, Stoke Sub Hamdon Scheduled Monument and Listed Buildings - 1 grade I; 6 grade II, CA	Viable new uses and/or funding opportunities need to be investigated to obtain adequate funding for repairs. A Historic England funded condition survey has been completed, identifying urgent repairs but as of 2019 the condition remains poor. Historic England hopes to work further with the owners regarding repair and reuse. Contact: Chris Miners 0117 975 1355 Attached to this chantry college is a group of medieval and C16 farm buildings, some of which are in poor condition and unroofed. However others, such as the threshing barr are capable of beneficial use. Owned by the National Trus Historic England has had a number of meetings on site and funded an options appraisal to consider ways of bringing

© Historic England



1020665 and 1260178; Contact: Annie Evans 0117 975 0673 LIST ENTRY NUMBER: 1242240; 1260179; 1242150; 1260105; 1260180; 1242246 SITE NAME: Early C19 Rope walk. Extremely long (97 metres) building The east Rope Walk, at Job Gould's West of England Twine Works, East Street, West of three-storeys, partly open at ground floor level, oak trusses with weatherboarding and windows along the east and west; later brick southern end; undulating double Coker roman clay tile roof, five ropewalks on two levels, some original machinery. The building is fragile, roof has been DESIGNATION: Listed Building grade II*, CA patched but battens have slipped in numerous places CONDITION: Poor allowing in water; trusses fractured and structure under OCCUPANCY: stress. Historic England grant-aided works to support the Vacant/not in use structure in 2016 and as of 2020 the building is being PRIORITY CATEGORY: D (D) gradually repaired by a new owner. OWNER TYPE: Private

PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; в solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

1057116

LIST ENTRY NUMBER:

D

Е

OWNER TYPE:

Charity (heritage)

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: Annie Evans 0117 975 0673

ABBREVIATIONS

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG Registered Park and Garden Scheduled Monument
- SM

UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / SOUTH WEST / SOUTH SOMERSET

	SITE NAME:	White Horse Hotel, 4, High Street, Wincanton	Inn dated 1733 built by Nathaniel Ireson in free baroque style. Local stone cut and squared with painted ashlar
	DESIGNATION:	Listed Building grade II*, CA	dressings; plain clay tile roof behind parapet, simple gables; brick end chimney stacks. Three-storey and three bays to
	CONDITION:	Poor	road. Building in poor condition with façade parting from roof, and floors decayed. As of Spring 2021, the site was
	OCCUPANCY:	Vacant/not in use	the subject of an application for a repair and change of use
	PRIORITY CATEGORY:	D (D)	of the main building.
	OWNER TYPE:	Commercial company	
Historic England	LIST ENTRY NUMBER:	1274102	Contact: Rhiannon Rhys 0117 975 0685

	SITE NAME:	Church of St Andrew, Aller	Small church of Saxon origin with C12/C13 and C15
	DESIGNATION:	Listed Place of Worship grade II*	additions and major restoration 1861 to 1862 by H John Norton. Tower stonework was repaired under the joint
	CONDITION:	Poor	National Lottery Heritage Fund and Historic England Repair Grant for Places for Worship scheme in 2013. The
	PRIORITY CATEGORY:	C (C)	church was offered a Listed Places of Worship Roof
	OWNER TYPE:	Religious organisation	Repairs Grant and in 2017-18 the nave and south porch roofs were recovered, and ceilings repaired. The chancel,
SAT S	LIST ENTRY NUMBER:	1227327	north aisle and north porch roofs remain in poor conditio
			Contact: Annie Evans 0117 975 0673

© Historic England

©Ні

	SITE NAME:	Church of the Holy Trinity, Main Street, Ash	Parish church built in 1841 by Sampson Kempthorne, chancel added 1887, and tower added 1919. Ham stone
	DESIGNATION:	Listed Place of Worship grade II	cut and squared with ashlar dressings and a Welsh slate roof between coped gables. The coping stones have
	CONDITION:	Poor	become dangerous and the tower masonry is in poor condition.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1057286	Contact: Annie Evans 0117 975 0673

© Historic England

	SITE NAME:	Church of St Mary Magdalene, Church Lane, Barwick and Stoford	Parish church C13 and later. Ham stone roughly squared and coursed, with ashlar dressings; plain clay tiles between coped gables to chancel south aisle and nave, stone slates
	DESIGNATION:	Listed Place of Worship grade II*	to south porch. Chancel is an 1885 rebuild incorporating earlier fragments. The tower roof is in poor condition, the
	CONDITION:	Poor	bell frame needs work and the nave and aisle roofs are also in poor condition. The church has been awarded a
	PRIORITY CATEGORY:	D (D)	National Lottery Heritage Fund Grant for Places of Worship and repairs started in 2019.
	OWNER TYPE:	Religious organisation	Worship and repairs started in 2019.
	LIST ENTRY NUMBER:	1057217	Contact: Annie Evans 0117 975 0673

© Historic England



	SITE NAME:	Church of St Nicholas, Bratton Seymour	Parish church with C13 origins. Two-cell plan, of two-bay chancel and three-bay nave, with west tower and south
	DESIGNATION:	Listed Place of Worship grade II*	porch, and small north-east vestry. High level stonework needs repairing urgently. Interior poor with ceilings at risk
	CONDITION:	Very bad	of falling and some plaster already having fallen.
E	PRIORITY CATEGORY:	A (A)	
Se 1	OWNER TYPE:	Religious organisation	
N. N. N.	LIST ENTRY NUMBER:	177220	Contact: Annie Evans 0117 975 0673

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / SOUTH WEST / SOUTH SOMERSET

	SITE NAME:	Church of St John the Baptist, Charcroft Hill, Brewham	Parish church reputed to date from the CI3 with much CI9 rebuilding. The tower is inhabited by birds making
	DESIGNATION:	Listed Place of Worship grade II*	inspection difficult. The church has been subject to heritage crime previously and the roofs are generally in need of
	CONDITION:	Poor	repair. The rainwater goods are in poor condition.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1056463	Contact: Annie Evans 0117 975 0673

© Historic England

urch of St Mary, Church	The current church dates primarily from the C15 and is a rebuild of an earlier church. Consists of nave, chancel		
	Contact: Annie Evans 0117 975 0673		
45984	resources. Some funding secured for roof repair but more needed.		
ligious organisation	of two wide bays with added south porch and western bell turret. C13 fenestration to chancel C15 traceried windows and door to nave. Reordered in 1878 but retaining C17 box pews, pulpit with tester and readers desk. Roofs and rainwater goods poor. Rare C15 bellcote in poor structural condition. Plaster bulging and falling in places. Timber floors under box pews are decayed. Very small parish with limited		
(New entry)			
or			
ted Place of Worship grade I			
urch of St Vincent, Chilton ntelo	Parish church. C13 and later. Local stone with Ham stone dressings and banded clay tile roof. Nave and Chancel each		
	,		



		Contact: Annie Evans 0117 975 0673
SITE NAME:	Church of St Mary, Church Street, Donyatt	The current church dates primarily from the CI5 and is a rebuild of an earlier church. Consists of nave, chancel,
DESIGNATION:	Listed Place of Worship grade II*, CA	north and south aisles, south porch and west tower. Extensive works carried out in the C19 which included the nave and aisle roofs. The chancel is full width and height.
CONDITION:	Poor	There is severe cracking over the chancel arch and the east window, both full width of the walls.
PRIORITY CATEGORY:	D (D)	window, both full width of the walls.
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1057074	Contact: Sarah Ball 0117 975 0666

© Historic England

	SITE NAME:	Church of St Peter, Church Road, Ilton	Anglican parish church dating from the C13 onwards. Chancel, nave, north aisle, tower on the south clasped by		
	DESIGNATION:	Listed Place of Worship grade II*	the nave and south transept, effectively forming a south porch. Organ chamber on north probably part of		
	CONDITION:	Poor	reordering by Street in the 1860s. The church suffered heritage crime in early 2020. The roof has been repaired as		
	PRIORITY CATEGORY:	A (A)	of 2021 but there is significant interior damage as yet		
	OWNER TYPE:	Religious organisation	unaddressed.		
	LIST ENTRY NUMBER:	1057052	Contact: Annie Evans 0117 975 0673		

© Historic England



SITE NAME:	Church of St Martin, Church Street, Kingsbury Episcopi	Anglican parish church. C14, C15, with C19 restoration. Predominantly Perpendicular and symmetrical plan with
DESIGNATION:	Listed Place of Worship grade I, CA	aisles and chancel aisles. Dominant tower, with elaborate stonework. The church suffered from heritage crime in early 2020. Repairs have been made to part, but as of
CONDITION:	Fair	2021, funding for the main repairs is still needed.
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1056885	Contact: Annie Evans 0117 975 0673

© Historic England

DRIODITY	CATECODIEC
PRIORITY	CATEGORIES

- А
- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / SOUTH WEST / SOUTH SOMERSET

	SITE NAME:	Church of St Thomas a Becket, Sherborne Road, South Cadbury and Sutton Montis	Anglican parish church. C13 and C15, restored in 1850s and 1870s. Chancel nave and south aisle, with north porch, south-east vestry and west tower. Cary and lias stone,
	DESIGNATION:	Listed Place of Worship grade II*, CA	mostly ashlar, with some doulting stone dressings; plain clay tile roofs with stone slate base courses to chancel, slate over stone to nave, both between stepped coped
	CONDITION:	Fair	gables. Interior has work of many periods. Church suff heritage crime in early 2020. Temporary repairs have l
and the second	PRIORITY CATEGORY:	A (A)	made but re-roofing is still required.
	OWNER TYPE:	Religious organisation	
© Historic England Archive	LIST ENTRY NUMBER:	1258922	Contact: Annie Evans 0117 975 0673



	SITE NAME:	Church of St Mary the Virgin, Stoke Sub Hamdon	Parish church of mainly CI2 and CI3 with later additions. Water ingress problems leading to damp as evidenced by
DESIGNATION: CONDITION: PRIORITY CATE	DESIGNATION:	Listed Place of Worship grade I, CA	the algal growth on the north and south side of the nave (and in the porch). Vegetation needs clearing from between the coping stones and roof slates. Rainwater
	CONDITION:	Poor	goods in need of repair. The congregation has been awarded a Listed Places of Worship Roof Repairs Grant
	PRIORITY CATEGORY:	D (D)	and some work was carried out in 2016-17 but more
	OWNER TYPE:	Religious organisation	repairs are needed.
1	LIST ENTRY NUMBER:	1260420	Contact: Annie Evans 0117 975 0673

© Historic England



FA	SITE NAME:	Church of St Mary, West Charlton, The Charltons	Parish church. C13 origins, but restored in 1792-1794 and in 1847. Local lias stone cut and squared, with Ham stone
	DESIGNATION:	Listed Place of Worship grade II*, CA	ashlar dressings. Stone slate roof between coped gables. Signs in the churchyard warning of the danger of slipping roof slates. All roofs need recovering as the fixings have
	CONDITION:	Poor	rusted and the stone tiles are laminating.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1056728	Contact: Annie Evans 0117 975 0673

© Historic England

SITE NAME:	Roman villa north of Dunnock's Lane, East Coker		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003029
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	Yes
OWNER TYPE:	Private, multiple owners	CONTACT:	John Ette 0117 975 0687
SITE NAME:	Low Ham Roman villa, High Ham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006192
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Commercial company		Alessandra Perrone 0117 975 1345
SITE NAME:	Northover House, late Roman cemetery, llchester		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1006128
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:		NEW ENTRY?:	No
	Scrub/tree growth		INU

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.

C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / SOUTH WEST / SOUTH SOMERSET / SOUTH GLOUCESTERSHIRE (UA)

SITE NAME:	Hamdon Hill can	np, Montacute / Norton Sub Hamo	lon / Stoke Sub Ha	mdon
DESIGNATION:	Scheduled Monu	ment, LB grade II, part in CA	LIST ENTRY NUMBER:	1003678
CONDITION:	Generally satisfactory but with significant localised problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Mineral extractio	n/related subsidence	NEW ENTRY?:	No
OWNER TYPE:	Local authority		CONTACT:	Alessandra Perrone 0117 975 1345
	SITE NAME:	Redlynch Park, Bruton / Shepton Montague	Redlynch is a larg	ncipal seat of the Earls of Ilchester, ge landscape park near Wincanton. The
	DESIGNATION:	Registered Park and Garden grade II, 10 LBs	main house has gone and the stables and ancillary buil are now in multiple ownership. The majority of the parkland planting has disappeared, boundary walls and estate railings are generally in poor condition. There a also on-going development pressures. An C18 Gothic gatehouse, The Towers, was repaired in 2012 and is r longer at risk, and sections of the park wall have been repaired with a Natural England Stewardship Scheme.	
	CONDITION:	Generally unsatisfactory with major localised problems		
and a starter	VULNERABILITY:	Medium		
	TREND:	Stable		
© Historic England	NEW ENTRY ?:	No		
	OWNER TYPE:	Private, multiple owners		
	LIST ENTRY NUMBER:	1000420	Contact: Jo McA	llister 0117 975 0696
·//	SITE NAME:	Cricket House, Cricket St. Thomas / Winsham	C18 landscape park and pleasure grounds surroundin listed mansion, partly by Sir John Soane. Under multi	artly by Sir John Soane. Under multiple
	DESIGNATION:	Registered Park and Garden grade II*, 8 LBs	hotel and from fa	pressure for development from a large arm diversification into the leisure marke have been restored through a Natural
	CONDITION:	Generally satisfactory but with	England Steward	

significant localised problems

Mixed, multiple owners

Medium

1001142

Stable

No

U	Historic	England

oric England	NEW ENTRY ?:
	OWNER TYPE:

VULNERABILITY:

LIST ENTRY NUMBER:

TREND:

SOUTH GLOUCESTERSHIRE (UA)						
	SITE NAME:	Whitfield Tabernacle, Park Road	Former chapel, built in 1741. The building has been redundant for many years and a fire has placed the building			
	DESIGNATION:	Listed Building grade I, CA	in an even more vulnerable position. In 2020 Historic England grant-aided a programme of emergency repairs			
	CONDITION:	Very bad	and consolidation which is now underway.			
	OCCUPANCY:	Vacant/not in use				
	PRIORITY CATEGORY:	F (A)				
	OWNER TYPE:	Private				
© Historic England Archive	LIST ENTRY NUMBER:	620	Contact: Alessandra Perrone 0117 975 1345			

© Historic England Archive

Contact: Jo McAllister 0117 975 0696

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

D

Е

Slow decay: solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / SOUTH WEST / SOUTH GLOUCESTERSHIRE (UA)

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

1.	SITE NAME:	dward Somerset, Hawkesbury Vulliamy dated 1846. Repairs needed at hig	A tall tapering stone tower ashlar monument by Lewis Vulliamy dated 1846. Repairs needed at high-level to cast
DESIGNATION:	DESIGNATION:	Listed Building grade II*, CA	iron balcony and stonework.
	CONDITION:	Poor	
OCCUPANCY: PRIORITY CATEGORY:	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
Archive	LIST ENTRY NUMBER:	1320834	Contact: Sarah Ball 0117 975 0666

© Historic England Ar



SITE NAME:	Ragged Castle or Keeper's Lodge, Badminton Park, Hawkesbury	Folly Castle. Set on a motte at end of a main drive from Badminton House, c1750 by Thomas Wright of Durham. Largely hidden by trees. Shell of structure is in poor
DESIGNATION:	Listed Building grade II*, RPG grade I	condition. Interior has been lost. There has been clearance of vegetation on and around the structure.
CONDITION:	Poor	
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1156209	Contact: Sarah Ball 0117 975 0666

Brandy Bottom Colliery, Pucklechurch / Emersons Green

Scheduled Monument

Commercial company

Poor

N/A

C (C)



© Historic England

© Historic England



© Historic England



	LIST ENTRY NUMBER:	1019400	Contact: Alessandra Perrone 0117 975 1345
SITE NAME: DESIGNATION: CONDITION:	Outer Court of Thornbury Castle and Wall of Kitchen Court, Church Road, Thornbury	Thornbury Castle outer court walls are currently in a poor condition. Vegetation overgrowth has gone unchecked. As a result ivy, brambles, and trees are growing out of the stonework and completely concealing certain features of	
	Listed Building grade I, part in RPG grade II, CA	the walls. It is also causing the portcullis archway to become increasingly unstable. Previously public access was allowed, however a fence has been installed which	
	Poor	prevents people from experiencing the history of the site properly. Overall the condition of the walls requires urgent	
	OCCUPANCY: Vacant/nc	Vacant/not in use	attention.
PRIORITY CATEGORY:	A (A)		
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1321132	Contact: Chris Miners 0117 975 1355
	SITE NAME:	Coach House and stables north east of Oxwick Farmhouse, Oxwick Lane, Yate, Wickwar	Coach house and stables, built 1722 in a mannered provincial baroque. The building is under a temporary roof. Listed Building Consent was approved in 2011 for
	DESIGNATION:	Listed Building grade II*	substantial repair works. A separate application was made for a wind turbine which was approved in 2013 on the
	CONDITION:	Very bad	basis that the revenue generated from it should assist in funding the repairs to both listed properties on the site.
	OCCUPANCY:	N/A	Historic England provided structural advice in early 2018
- Lan	PRIORITY CATEGORY:	D (D)	on the condition of the scaffolding with the view of securing maintenance works to the temporary supporting structure.
A CONTRACT	OWNER TYPE:	Private	

Contact: Stephen Guy 0117 975 0725

A former CI9 steam-powered colliery built on the site of

C18 colliery. The Avon Industrial Buildings Trust have taken on the site and run regular work parties. They have

undertaken vegetation clearance and minor repairs to stabilise the structures. Historic England grant aided works

since 2014 have included repairs to the chimney, the structures within the Old Pit and New Pit and some

document forms the basis of an on-going programme of

interpretation. A Heritage Partnership Agreement

repair and research.

PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but $\ \ F$ not yet implemented.

1312305

LIST ENTRY NUMBER:

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument
- SM
- UA WHS Unitary Authority World Heritage Site

HERITAGE AT RISK 2021 / SOUTH WEST / SOUTH GLOUCESTERSHIRE (UA)

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

OWNER TYPE:

A (A)

1114974

Religious organisation

	SITE NAME:	Oxwick Farmhouse, Oxwick Lane, Yate, Wickwar	Farmhouse dated 1722, in flamboyant artisan mannerist/baroque style. Part occupied. Vacant part has
	DESIGNATION:	Listed Building grade II*	serious decay of floor structures and in areas is unsafe, but emergency repairs have been implemented. Discussions
	CONDITION:	Poor	over full repair remain on-going. Some enabling development has been permitted in the form of renewable
	OCCUPANCY:	Part occupied/part in use	energy.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
Historic England	LIST ENTRY NUMBER:	1321124	Contact: Stephen Guy 0117 975 0725
	SITE NAME:	Parish Church of St Andrew, Church Lane, Cromhall	Parish church. C12, rebuilt in C13/C14 and altered C15; restored 1852. Rubble with freestone dressings; stone slate
	DESIGNATION:	Listed Place of Worship grade I	roof with coped raised verges, slate to the nave. The sandstone slates have slipped or are missing. The rainwater
	CONDITION:	Poor	system is rusted and leaking. There is structural cracking over the south aisle east window and over the west
			over the south asic cast window and over the west

© Historic England

٥I

Church Road, Yate	SITE NAME:	Church of St Mary the Virgin, Church Road, Yate	Large urban parish church with a nave, chancel, aisles, transepts and west tower. Sandstone with limestone
	DESIGNATION:	Listed Place of Worship grade I	dressings and roofed with stone slates. Localised leaks over many years are steadily worsening over much of the roof.
	Poor	The north aisle and the south chancel roofs should be the first to be repaired.	
	PRIORITY CATEGORY:	C (C)	
III and III	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1128753	Contact: Chris Miners 0117 975 1355

window.

Contact: Chris Miners 0117 975 1355

© Historic England

SITE NAME:	Round barrow on Barrow Hill, Bitton		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1004521
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Roman villa and earlier settlement remains in Badm Hawkesbury	inton Park, 340 me	etres south of Hinnegar Lodges,
DESIGNATION:	Scheduled Monument, RPG grade I	LIST ENTRY NUMBER:	1021415
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Bury Hill camp, Moorend, Winterbourne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007023
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / SOUTH WEST / SOUTH GLOUCESTERSHIRE (UA) / SWINDON (UA)

	SITE NAME:	Tortworth Court, Cromhall / Falfield / Tortworth	Important Victorian house and grounds, including renowned arboretum. House now a hotel and part of
	DESIGNATION:	Registered Park and Garden grade II*, 7 LBs, part in SM	grounds lost to Leyhill Open Prison. Walled garden being redeveloped for light industrial use. Arboretum neglected. Extensive loss of trees in park. The registered area is in
	CONDITION:	Generally unsatisfactory with major localised problems	multiple ownership and suffers from a lack of holistic management. In 2016 a Conservation Management Plan fo part of the registered park was produced with grant aid
	VULNERABILITY:	High	from Historic England. This was followed in 2017 by a gran
A REAL PROPERTY AND	TREND:	Stable	to assist with de-silting the lake (now completed), which forms the centrepiece of the design.
© Historic England	NEW ENTRY ?:	No	
	OWNER TYPE:	Mixed, multiple owners	
	LIST ENTRY NUMBER:	1000394	Contact: Jo McAllister 0117 975 0696
	SITE NAME:	Stoke Park, Stoke Gifford	Mid-C18 park laid out around crenellated Dower House.
and the second	DESIGNATION:	Registered Park and Garden grade II, 10 LBs, SM, part in CA	The park is in a dramatic location on a hill overlooking the city of Bristol and is embellished by monuments and eye-catchers. Now bisected by the M32 motorway. Setting
The second	CONDITION:	Generally unsatisfactory with major localised problems	compromised by dense residential development. Park under pressure from heavy and occasionally anti-social use particularly affecting park structures. In 2012, the majority
A Standard March 199	VULNERABILITY:	Medium	of the site was transferred to Bristol City Council who
	TREND:	Improving	received Historic England grant towards a Conservation Management Plan in 2015-16 which is now being
	TREND: NEW ENTRY?:	Improving No	received Historic England grant towards a Conservation Management Plan in 2015-16 which is now being implemented under Natural England Stewardship.
© Historic England		1 0	Management Plan in 2015-16 which is now being

SITE NAME:	Warmley, Siston / Oldland		
DESIGNATION:	Conservation Area, 9 LBs, RPG grade II, SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	lan Gething (LPA) 01454 863578
SITE NAME:	Whitfield Tabernacle		
SITE NAME: DESIGNATION:	Whitfield Tabernacle Conservation Area, 3 LBs	NEW ENTRY?:	No
		NEW ENTRY?: TREND:	No Improving

SWINDON (UA)

SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:	SITE NAME:	The Mechanics Institute, Emlyn Square	Mechanics Institute, 1853-5; now vacant. Outstanding example at heart of railway village. The council served an
	DESIGNATION:	Listed Building grade II*, CA	Urgent Works Notice on the owner in 2009 and implemented works in 2010 to secure the building. The
	Poor	shell of the building has been stabilised but it is not possible to enter due to health and safety concerns. The "Railway	
	OCCUPANCY:	Vacant/not in use	Village", of which the Mechanics forms the centrepiece
	PRIORITY CATEGORY:	B (B)	now a Historic England Heritage Action Zone. An options appraisal for the future use of the building has now been
	Commercial company	completed and a project to restore the building is in its early stages.	
d Archive	LIST ENTRY NUMBER:	1198947	Contact: Simon Hickman 0117 975 0717

© Historic England /

SITE NAME:	Bowl barrow 280 metres north of Downs Barn, Bishopstone			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010419	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645	

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / SOUTH WEST / SWINDON (UA)

SITE NAME:	Bowl barrow on Hinton Downs, Bishopstone		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010461
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Disc barrow on Burderop Down, I kilometre nor	rth east of Upper He	erdswick Farm, Chiseldon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010457
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow I kilometre west of Sheppard's Farm	n Dairy, Chiseldon /	Ogbourne St. George
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012439
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - Badger - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Field system and earthwork enclosure on Burdero	op Down, Chiseldon) / Ogbourne St. George
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016383
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Site of Roman town, west of Wanborough House	, Covingham / Want	porough
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004684
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Four Highworth circles 150 metres north east of	Pickett's Copse, Hig	hworth
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016386
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Three Highworth circles 600 metres east of Nort	h Leaze Farm, Highv	worth
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018221
CONDITION:	Extensive significant problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / SOUTH WEST / SWINDON (UA) / TORBAY (UA)

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

ī

PRIORITY CATEGORY

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

OWNER TYPE:

D

Е

SITE NAME:	E NAME: Bowl barrow 700 metres south west of Liddington Warren Farm, Liddington			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009634	
CONDITION: Generally satisfactory but with significant loca problems		TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No	
OWNER TYPE: Private, multiple owners		CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Long barrow 700 metres north of Liddington War	ren Farm, Liddingto	on / Wanborough	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009631	
CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable clipping OWNER TYPE: Private, multiple owners		TREND:	Declining	
		NEW ENTRY?:	No	
		CONTACT: Nick Croxson 07795 66564		
SITE NAME:	Remains of Holy Rood Church, The Lawn, Old To	wn		
DESIGNATION:	Scheduled Monument, 3 LBs	LIST ENTRY NUMBER:	1018057	
CONDITION: Generally unsatisfactory with major localised problems		TREND:	Declining	
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No	
OWNER TYPE:	Local authority	CONTACT:	Nick Croxson 07795 665645	

TORBAY (UA)



© Historic England



HIGHT CATEGORI.	D (D)	2017-18. Fu	
OWNER TYPE:	Charity (heritage)	required.	
LIST ENTRY NUMBER:	1195173	Contact: An	
SITE NAME:	llsham Manor Oratory, llsham Road, llsham	Redundant c Manor. Sitec	
DESIGNATION:	Listed Building grade II*	2015. Negle 2012 the cha	
CONDITION:	Poor	roof coverir were missin	
OCCUPANCY:	Vacant/not in use	Fngland gran	

Charity (non-heritage)

Lupton House (Gramercy Hall

Listed Building grade II*, RPG

Part occupied/part in use

School)

grade II*

Poor

D (D)

1206789

C18 and C19 country house remodelled by G Wightwick c1840, with extensive ancillary buildings and fine Italianate garden. Altered after a fire in 1928. In use as a school from mid C20 to 2004. A charitable trust has acquired the house and parts are used for weddings and community health activities. Historic England grant-aided development work to the Italianate Garden in 2015, and a condition survey of the house and ancillary structures, and emergency repairs including a trial area of repair to the Italianate Garden, in Irther major funding from other sources is still

nie Evans 0117 975 0673

Contact: Annie Evans 0117 975 0673

oratory, part of the demolished medieval IIsham d in the grounds of a school, which closed in ected and in poor condition, when assessed in apel was not in use. By 2015 large holes in the ngs had opened up and the rainwater goods ng, causing significant water ingress. Historic ant-aided a condition survey in 2016 and urgent repairs to the roof were completed with Historic England grant-aid in 2017. Repointing, window, and interior repairs remain to be tackled by new owners.

© Historic England



SITE NAME:	The Bishop's Palace, Tower Road, Paignton
DESIGNATION:	Scheduled Monument, 2 LBs, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1020764

CI4 curtain wall and tower, forming part of the medieval fortified residence of the Bishop of Exeter. Vegetation growth, especially valerian on the wall tops and growing from crevices, threatens the medieval walls. Their root system grows to a large bulbous form within the wall, pushing stones out of line and leading to breakdown of the structure. Ivy has also taken hold and is rapidly spreading along the south wall. In 2016 Historic England grant-aided a programme of vegetation removal and door rerfubishment.

Contact: Charlotte Russell 01271 831505

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

- Conservation Area Listed Building LB
- I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM
- ΪA Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2021 / SOUTH WEST / TORBAY (UA)

	SITE NAME:	Torbay Cinema, Torbay Road, Paignton	Cinema first licensed in 1912 and frequented by Agatha Christie. An extremely well preserved example of an early
	DESIGNATION:	Listed Building grade II*	purpose-built cinema which closed in 1999. In 2015 Historic England helped with the transfer of ownership of
	CONDITION:	Poor	the building to a new Trust. Repairs to the front elevation and two-storey bay window have been completed in 2021
	OCCUPANCY:	Vacant/not in use	with grant aid from Historic England. Further feasibility work has been undertaken by theTrust to look at futu uses within the building and the first phase of its re-use
	PRIORITY CATEGORY:	C (C)	
A R	OWNER TYPE:	Charity (heritage)	be developed with money from the Future High Streets
© Torbay Council	LIST ENTRY NUMBER:	1208209	Contact: Annie Evans 0117 975 0673

	SITE NAME:	Church of St Mary Magdalene, Upper Union Street, Torquay	Parish church. Built between 1843 and 1849 to the designs of A Salvin, by contractor Jacob Harvey. Altered and partly
	DESIGNATION:	Listed Place of Worship grade II*, CA	re-fitted under GG Scott 1881-82; further embellishment 1906 and 1927. Local grey limestone rubble with Bath stone dressings; slate roof. Rainwater goods all need
	CONDITION:	Poor	overhauling. The church received a Listed Places of Worship Roof Repairs Grant in 2017 and rainwater goods
AL ON	PRIORITY CATEGORY:	C (C)	have been overhauled. High level stonework in very bad condition and difficult to access. The clerestory stonework
	OWNER TYPE:	Religious organisation	condition and difficult to access. The clerestory stonework spalling badly. A rope access survey has identified these
	LIST ENTRY NUMBER:	1219197	problems in more detail.
			Contact: Annie Evans 0117 975 0673

© Historic England

SITE NAME:	Ashhole Cavern,	Brixham		
DESIGNATION:	Scheduled Monument, part in CA		LIST ENTRY NUMBER:	1019133
CONDITION:	Generally satisfactory but with significant localised problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism		NEW ENTRY?:	No
OWNER TYPE:	Local authority		CONTACT:	Charlotte Russell 01271 831505
4	SITE NAME:	Church of St Mary the Virgin, Drew Street, Brixham	Parish church. C15, re-roofed 1867, restored by Tait ar Harvey in 1905. Chancel, nave, north and south aisles, north and south transepts, north and south chancel chapels, west tower, south porch. Solid roughcast walls with Beer and red sandstone dresssings, slate roofs. Wa penetration through exposed tower buttresses causing damage to exposed stonework and embedded timber beam ends.	
	DESIGNATION:	Listed Place of Worship grade II*, CA		
	CONDITION:	Poor		
	PRIORITY CATEGORY:	C (C)		
the manual of a	OWNER TYPE:	Religious organisation		
1 6 1A	LIST ENTRY NUMBER:	1195156	Contact: Annie E	Evans 0117 975 0673
© Dennis Coote, Source Historic England				

© Dennis Coote. Source Historic England Archive

SITE NAME:	Prehistoric field system at Walls Hill, Babbacombe Bay			
DESIGNATION:	Scheduled Monument	1019134		
CONDITION: Generally satisfactory but with significant localised problems		TREND:	Declining	
PRINCIPAL VULNERABILITY:	Visitor erosion - limited/localised	NEW ENTRY ?:	No	
OWNER TYPE:	Local authority	CONTACT:	Charlotte Russell 01271 831505	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERIT

ALC: NOT	SITE NAME:	Princess Gardens and Royal Terrace Gardens, Torquay	Important formal Victorian seaside park with later phases and additions. Major development agreed, including a
	LIST EINTRY MORIBER.	0021001	Contact. Jo FicAllister 0117 773 0676
	LIST ENTRY NUMBER:	1001368	Contact: Jo McAllister 0117 975 0696
storic England	OWNER TYPE:	Private	
	NEW ENTRY?:	No	
	TREND:	Declining	
	VULNERABILITY:	Medium	ownership, with no scheme identified.
	CONDITION:	Generally unsatisfactory with major localised problems	in 2012 for mixed-use development, including a hotel in the main house and housing in the grounds, but this was never implemented. The property remains in Local Authority
ALL AND A	DESIGNATION:	Registered Park and Garden grade II, 12 LBs	apparently inspired by the Palace of Versailles. Built by the Singer sewing machine dynasty, the grounds have been steadily rationalised and simplified. Permission was granted
No. Star	SITE NAME:	Oldway Mansion	Formal gardens laid out to complement a grand house,



	SITE NAME:	Princess Gardens and Royal Terrace Gardens, Torquay	Important formal Victorian seaside park with later phases and additions. Major development agreed, including a
	DESIGNATION:	Registered Park and Garden grade II, 4 LBs, 2 CAs	multi-storey, mixed-use building to be attached to the grade II listed Pavilion and the seasonal installation of a Ferris wheel. A condition report and management plan for
	CONDITION:	Generally satisfactory but with significant localised problems	the gardens was completed in early 2017.
-	VULNERABILITY:	Medium	
	TREND:	Stable	
	NEW ENTRY?:	No	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1001507	Contact: Jo McAllister 0117 975 0696

DEVON

© Historic England

© Hist

TORBAY (UA) / SOUTH HAMS

· · /			
© Historic England	SITE NAME:	Lupton Park, Kingswear	The designed landscape was principally developed from the
	DESIGNATION:	Registered Park and Garden grade II*, 7 LBs, part in CA	late-C18 through to mid-C19. After World War II the house became a hotel, then a school. Today a trust occupies the house (at risk) with the degraded Italianate
	CONDITION:	Generally unsatisfactory with major localised problems	garden, while other owners occupy the park, walled garden, pleasure grounds and woodlands. In 2015 Historic England funded a condition report for the Italianate Garden
	VULNERABILITY:	Medium	and a further grant for development work on the house
	TREND:	Improving	and garden was offered with work underway in 2017-1 The condition of the park is being tackled by a Natural
	NEW ENTRY ?:	No	England Stewardship Scheme.
	OWNER TYPE:	Mixed, multiple owners	
	LIST ENTRY NUMBER:	1000696	Contact: Jo McAllister 0117 975 0696

WILTSHIRE (UA)

SMA	X!	esta.
W.		
		-
in the second	1. 2	T

SITE NAME:	Rudloe Manor, Box
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1022808

Late C17 manor house surrounded by ancillary buildings including a grade II listed barn. The house was part of a larger Ministry of Defence site which was vacated in 1998. The current owners have consent for a residential scheme with enabling development. Work has been undertaken to the exterior of the listed building to make it watertight but it remains vacant. The property has recently been put up for sale but not sold.

Contact: Jacqueline Smith 0117 975 0667

PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
 - Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site



Former coach house, stable and brewhouse to rear of SITE NAME: Buildings to the rear of the Lansdowne Arms Hotel. Buildings range from mid C17 to Lansdowne Arms Hotel, The Strand, Calne mid C19. Condition of roofs and coverings are continuing to degenerate leading to further internal decay. Urgent DESIGNATION: Listed Building grade II*, CA Works Notices have previously been complied with; however, the condition of these buildings continues to CONDITION: Poor decline. Pre-application discussions and assessment work OCCUPANCY: on-going, with progress meetings having taken place in Vacant/not in use 2018. PRIORITY CATEGORY: C (C) OWNER TYPE: Private LIST ENTRY NUMBER: 1247495 Contact: Jacqueline Smith 0117 975 0667

© Wiltshire Council



	SITE NAME:	The Lansdowne Monument, Calne Without	Obelisk constructed in 1845 by Sir Charles Barry for the 3rd Marquess of Lansdowne in memory of Sir William	
	DESIGNATION:	Listed Building grade II*, SM	Petty, ancestor of the Petty-Fitzmaurice family. The condition of this monumental local landmark is in decline due to the effect of weathering on the stonework. Plann Permission and Listed Building Consent to maintain the	
	CONDITION:	Poor		
	OCCUPANCY:	N/A	temporary protection, whilst the project to repair the	
P	PRIORITY CATEGORY:	A (A)	monument is being developed, were granted in March 2020 on a temporary basis for five years.	
	OWNER TYPE:	Charity (heritage)		
	LIST ENTRY NUMBER:	1253569	Contact: Sarah Ball 0117 975 0666	

© Historic England

© Historic England



Two aircraft hangars, built c1917 as part of a training SITE NAME: Former hangars at Yatesbury Airfield, Cherhill centre. Two hangars from the first years of military flying. One hangar has been repaired, though there is no current DESIGNATION: Listed Building grade II*, CA end use. Consent has been granted to demolish the second hangar and this is currently in a collapsed state. As of 2019, CONDITION Poor previously approved applications not implemented. OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: E (E) OWNER TYPE: Private LIST ENTRY NUMBER: 1283146 Contact: Jacqueline Smith 0117 975 0667



© Historic England Archive

Former Law Courts and County Law courts and police station, 1835. Wind and weather SITE NAME: tight. Interior has been gutted. Several schemes have been Police Station, Northgate granted consent, including residential and nightclub use, but Street, Devizes none have been implemented. Planning Permission and DESIGNATION: Listed Building grade II*, CA Listed Building Consent granted in 2012 for a new residential scheme was renewed 2015 and expired 2018. CONDITION: Very bad Urgent works carried out in 2015. Purchase by Wiltshire OCCUPANCY: Vacant/not in use Historic Buildings Trust completed in 2018 and site is now in ownership of Assize Courts Trust. Emergency work is PRIORITY CATEGORY: D (D) largely complete. There are proposed plans to carry out conversion for use as a museum. OWNER TYPE: Commercial company LIST ENTRY NUMBER: 1251744 Contact: Jacqueline Smith 0117 975 0667

ht NMR ref: BB

Impressive stable block of 1818, by Thomas Cundy, SITE NAME: Stable block to Tottenham located 150 metres NNW of Tottenham House. Following House, Great Bedwyn neglect, the structure has recently suffered a collapse to the Listed Building grade II*, RPG clock tower and the surviving structure is in an unsafe and DESIGNATION: grade II* partially ruinous condition. A planning application was granted early 2018 supporting the return of Tottenham CONDITION: Very bad House to a single family dwelling, with some additional OCCUPANCY. Vacant/not in use development and the conversion of the Stable Block for ancillary leisure use. The site is now under new ownership PRIORITY CATEGORY: A(A)and discussions regarding rebuilding and implementation of the agreed scheme are underway. OWNER TYPE: Private LIST ENTRY NUMBER: 1365488 Contact: Jacqueline Smith 0117 975 0667

PRIORITY CATEGORIES

© Historic England Archive

Immediate risk of further rapid deterioration or loss of fabric; no

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM
- ΪA Unitary Authority World Heritage Site WHS

OWNER TYPE:

LIST ENTRY NUMBER:

	(•	,	
	SITE NAME:	Tottenham House, Great Bedwyn	Country house 1825 by Thomas Cundy, situated in park, developed from C15 to C17 and landscaped by Lancelot
A CANADA	DESIGNATION:	Listed Building grade I, RPG grade II*	'Capability' Brown in the 1760s. Previously used as a preparatory school (from the 1950s) now vacant. A planning application was granted early 2018 supporting the return of Tottenham House to a single family dwelling with
And the second se	CONDITION:	Poor	
212	OCCUPANCY:	Vacant/not in use	some additional development and the conversion of the Stable Block for ancillary leisure use. The site is now under
	PRIORITY CATEGORY:	D (D)	new ownership and the implementation of the agreed works will result in the buildings being removed from the
n Copyright NMR ref: BB86/05409	OWNER TYPE:	Private	Heritage at Risk Register.
© Historic England Archive	LIST ENTRY NUMBER:	83809	Contact: Jacqueline Smith 0117 975 0667
	SITE NAME:	Three former World War I aircraft hangars at Old Sarum Airfield, Portway, Laverstock	One single and two paired aircraft storage hangars which were designed in 1917 and built in 1918. They are constructed with piers, curtain walls and gantries brickwork
	DESIGNATION:	Listed Building grade II*, CA	with 'Belfast' roof trusses. The hangars are deteriorating fast due to a sustained period of neglect. Recent planning
	CONDITION:	Very bad	applications relating to the wider Old Sarum Airfield proposed their restoration, but these were dismissed at
	OCCUPANCY:	Vacant/not in use	appeal.
	PRIORITY CATEGORY:	A (A)	

Commercial company

1355710

Contact: Jacqueline Smith 0117 975 0667



© Historic England

	SITE NAME:	Chapel at Knowle House, Little Bedwyn	Early C15 former chapel in curtilage of a listed house. In poor condition and needs some work and repair to roof
	DESIGNATION:	Scheduled Monument	and gable wall.
	CONDITION:	Poor	
	OCCUPANCY:	Unknown	
- FA	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1004708	Contact: Sarah Ball 0117 975 0666

SITE NAME:	The Red House at Eastwell Manor, Eastwell Road, Potterne	Red brick garden building. Built c1700. One of several buildings on this site that are presently disused and in a
DESIGNATION:	Listed Building grade II*	decaying condition. An Enforcement Notice has been served in respect of unauthorised alterations. An appeal
CONDITION:	Poor	was lodged by the owner but was rejected by the planning inspector. Access to the site is currently restricted.
OCCUPANCY:	N/A	inspector. The case to the site is carrenally resulted.
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1258775	Contact: Jacqueline Smith 0117 975 0667



SITE NAME:	Courtfield House, Polebarn Road, Trowbridge	Courtfield House is a clothier's house built c1754 with an earlier C17 building to rear. The house was used as a
DESIGNATION:	Listed Building grade II*, CA	preparatory school which closed in April 2012. Adjoining the house is a relatively unaltered wool store. The roof
CONDITION:	Poor	structure of the house is in poor condition with a collapsing valley gutter. The property is currently vacant and subject
OCCUPANCY:	Part occupied/part in use	to vandalism. Purchased in April 2016 by a developer to
PRIORITY CATEGORY:	A (A)	convert the main house to residential units with new build residential in the grounds. Building is now scaffolded and
OWNER TYPE:	Private	secure and negotiations to reach an acceptable application continue.
LIST ENTRY NUMBER:	1021635	Contact: Simon Hickman 0117 975 0717

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

D

Е

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site



© Salisbury District Council

Former private chapel to country house, c1827. Built by John Bennett of Pythouse for his wife nee Lucy Lambert of SITE NAME: Chapel, immediately north of Pythouse, Pythouse Park, West **T**isbury Boyton. The chapel is derelict and overgrown and the stonework has been vandalised. The building is now DESIGNATION: Listed Building grade II* scaffolded. Some of the vegetation has been removed. CONDITION: Very bad OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: A (A) OWNER TYPE: Private LIST ENTRY NUMBER: 1131162 Contact: Sarah Ball 0117 975 0666

	SITE NAME:	Phipps Mausoleum, Westbury Cemetery, Bratton Road, Westbury	Late C19 privately owned mausoleum, within a local authority municipal cemetery. The building is currently disused and continues to deteriorate. It is the subject of
	DESIGNATION:	Listed Building grade II*	on-going vandalism but has been secured against break-ins.
STATE D	CONDITION:	Very bad	
TAAT	OCCUPANCY:	N/A	
AL SUS	PRIORITY CATEGORY:	C (C)	
A MINING &	OWNER TYPE:	Private	
© Historic England Archive	LIST ENTRY NUMBER:	1364424	Contact: Sarah Ball 0117 975 0666

SITE NAME:	Zeals House, Zeals	Zeals House is a Grade I country house originally
DESIGNATION:	Listed Building grade I	constructed in the late CI4 with phases of alterations dated to the CI7, CI8 and I860s, the latter for William
CONDITION:	Poor	Chafyn-Grove. The house is currently unoccupied and is falling into a state of disrepair that is exposing historic fabric
OCCUPANCY:	Vacant/not in use	to conditions that will expedite its deterioration.
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	3 8497	Contact: Jacqueline Smith 0117 975 0667

	SITE NAME:	Church of St Peter, Calne Without	Parish church, probably C13, altered and extended 1859 and restored 1907 by CE Ponting. Rubble stone coped
and a	DESIGNATION:	Listed Place of Worship grade II*	chancel gable and gabled stone slate hung west bellcote. The church has structural movement and monitoring was
F	CONDITION:	Poor	carried out for over a year to inform a specification for repair. Advice on repairs was given by Historic England
	PRIORITY CATEGORY:	B (B)	Spring 2018 following which the congregation are
	OWNER TYPE:	Religious organisation	progressing a repair project.
	LIST ENTRY NUMBER:	1261936	Contact: Sarah Ball 0117 975 0666

© Historic England

*	SITE NAME:	Church of St Nicholas, Baydon	Anglican parish church with fabric dating from C12, C13
TUNNEL	DESIGNATION:	Listed Place of Worship grade II*, CA	and C15 with C19 restorations in 1857, 1876 and 1892. Consists of nave, north aisle, chancel, north vestry and west tower. East window by GE Street dated 1857-58.
	CONDITION:	Poor	Severe vertical cracking in east and north walls of chancel. Emergency propping erected in February 2019.
	PRIORITY CATEGORY:	A (A)	Energency propping elected in rebruary 2017.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1034135	Contact: Sarah Ball 0117 975 0666

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
 - Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Church of St Peter, Charlton	Parish church. C16 and 1857-8 by JL Pearson. Medieval
n nn _j	DESIGNATION:	Listed Place of Worship grade II*, CA	work in ashlar limestone. C19 work in flint banded with limestone ashlar and brick. Tiled roof. North porch with tower over and north chapel, all C15-C16. Nave and chancel in one, rebuilding original work. The plain clay tile to the roof are failing and although regular patching and
	CONDITION:	Poor	
	PRIORITY CATEGORY:	C (C)	repair is being undertaken, the roof will need renewing.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1365532	Contact: Sarah Ball 0117 975 0666

© Historic England



	SITE NAME:	Church of St Mary, Church Road, Kilmington	Church of England parish church. C15 tower, chancel rebuilt 1864, complete rebuilding 1869, tower restored
	DESIGNATION:	Listed Place of Worship grade II*	1903 by CE Ponting. Dressed limestone, rubblestone, tiled roof with ceramic ridge cresting and coped verges. West
	CONDITION:	Poor	tower and entrance, nave and north aisle, south transept, north vestry and chancel. Narrow three-stage tower of
	PRIORITY CATEGORY:	D (D)	Somerset type. Roofs and masonry in poor condition,
	OWNER TYPE:	Religious organisation	particularly tower. Unsuccessful in attempts to obtain National Lottery Heritage Fund grant. Repair of tower roof
	LIST ENTRY NUMBER:	1318459	proposed as first phase of repair.
1004			Contact: Sarah Ball 0117 975 0666

© Marcus Chantrey, Beniamin Beauchamp Architects



Church of St Anne, Bowden Church of England parish church 1856-7 by SB Gabriel of SITE NAME: Bristol. Consists of nave, chancel and north porch in Early Hill, Lacock English style with Romanesque style north east tower. Listed Place of Worship grade II, There has been past structural movement in the church but DESIGNATION: CA since Summer 2018 this has accelerated and large cracks have opened around the chancel arch. Emergency propping CONDITION: Poor was erected externally in the south-east corner of the nave PRIORITY CATEGORY: A (C) in October 2018. The propping was increased in March 2020 following further structural movement. OWNER TYPE: Religious organisation LIST ENTRY NUMBER: Contact: Sarah Ball 0117 975 0666 1363962

© Marcus Chantrey, Benjamin Beauchamp Architects

	SITE NAME:	Church of St Peter, Swindon Road, Langley Burrell Without	Parish church, c1200, c1300, C14 and C15, carefully restored 1890 (chancel) by CE Ponting and 1898 (navi north aisle) by H Brakspear. Rubble stone with stone s				
	DESIGNATION:	Listed Place of Worship grade I	roofs and coped gables. Nave, north aisle, transeptal so				
	CONDITION:	Poor	tower with porch, chancel and south east chapel. Stone tiles to nave roof in poor condition and rainwater goods				
	PRIORITY CATEGORY:	C (C)	require overhauling.				
	OWNER TYPE:	Religious organisation					
	LIST ENTRY NUMBER:	1199423	Contact: Sarah Ball 0117 975 0666				

© Historic England



SITE NAME:	All Saints Chapel, Swan Lane, Leigh	Church of England parish church. C14 and 1896 by CE Ponting. Squared limestone rubble, stone slate roof. Nave
DESIGNATION:	Listed Place of Worship grade II*	rebuilt from old church and new chancel added. C14 porch entrance with wave moulding and hood. Sundial above.
CONDITION:	Poor	Stone slate roof and rainwater goods are in poor condition. Render to bell turret is failing.
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1356042	Contact: Sarah Ball 0117 975 0666

© Historic England

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D


Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM UA WHS
 - Unitary Authority World Heritage Site



© Historic England

SITE NAME:	Wermere pond, Alvediston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004774
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	A bell barrow and two bowl barrows east of The Avenue on Countess Farm: part of a linear round barrow cemetery, Amesbury		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010331
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bell barrow 550 metres east of New Barn, Earl's F	arm Down, Amesb	ury
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009872
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 50 metres south of A303, Amesbury		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1012131
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	Yes
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 70 metres south of A303, Amesbury		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1012130
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow forming part of Normanton Down re	ound barrow ceme	tery, Amesbury
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010330
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY ?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Nick Croxson 07795 665645

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.

C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no

obvious new user (applicable only to buildings capable of beneficial

D

Е

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA LB

- LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG
- Registered Park and Garden Scheduled Monument SM

UA WHS

Unitary Authority World Heritage Site

SITE NAME:	Henge monument 400 metres south of Stonehenge Cottages, Amesbury			
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1012376	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Charity (heritage)	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Linear boundary earthwork on Amesbury Down west of Stock Bottom, Amesbury			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015218	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Lynchets at Southmill Hill, Amesbury			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015220	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes	
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Part of Stonehenge Avenue and two adjacent round	l barrows, Amesbu	ıry	
DESIGNATION:	Scheduled Monument, LB grade II, part in CA, WHS	LIST ENTRY NUMBER:	1010140	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Three bell barrows 300 metres north east of New	Barn, Earl's Farm D	Down, Amesbury	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009572	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No	
OWNER TYPE:	Educational (state sector)	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Three bowl barrows 220 metres west of Vespasian'	s Camp, Amesbur	у	
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1012132	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	Yes	
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Linear boundary earthwork 250 metres west of Sto	ckport, Amesbury	/ Idmiston	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015689	
CONDITION:	Extensive significant problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Bowl barrow forming part of the Normanton Down round barrow cemetery, Amesbury / Wilsford cum La				
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1009616		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645		
SITE NAME:	Beckhampton round barrow cemetery 150 metres north east of the 'Waggon and Horses', Avebury				
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008221		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No		
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645		
SITE NAME:	Bowl barrow 770 metres south west of the junction of the Ridgeway and Green Street, forming part of a round barrow cemetery on Avebury Down, Avebury				
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008107		
CONDITION:	Extensive significant problems	TREND:	Unknown		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Charity (heritage)	CONTACT:	Nick Croxson 07795 665645		
GITE NAME:	Earthwork enclosure 950 metres SSE of Manor Far	m, Avebury			
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1014031		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Charity (heritage)	CONTACT:	Nick Croxson 07795 665645		
SITE NAME:	Pair of round barrows 200 metres SSE of Windmill Avebury	Hill: part of the W	/indmill Hill round barrow cemetery.,		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008447		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Animal burrowing - Badger - moderate	NEW ENTRY?:	Yes		
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645		
SITE NAME:	Pair of round barrows 400 metres west of the Ridgeway, forming part of a round barrow cemetery situate on Avebury Down, Avebury				
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008075		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No		
OWNER TYPE:	Charity (heritage)	CONTACT:	Nick Croxson 07795 665645		
SITE NAME:	Pair of round barrows forming part of the Bronze West Kennett Farm, Avebury	Age round barrow	cemetery 400 metres north east of		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008101		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Charity (heritage)	CONTACT:	Nick Croxson 07795 665645		

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- 204

SITE NAME:	Remains of 'Falkner's Circle', a Neolithic stone circle 180 metres east of the West Kennet Avenue, Aven			
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008109	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Charity (heritage)	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Round barrow cemetery 400 metres south of Ave	Round barrow cemetery 400 metres south of Avebury henge monument on Waden Hill, Avebury		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008216	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Charity (heritage)	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Ten barrows forming part of Fox Covert round ba	rrow cemetery, W	est Down, Avebury	
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008293	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Local authority	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	West Kennet Avenue and an earthwork bank east	of West Kennett F	arm, Avebury	
DESIGNATION:	Scheduled Monument, LB grade II, 2 CAs, WHS	LIST ENTRY NUMBER:	1015547	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	A henge, four Bronze Age barrows and part of a R / Bishops Cannings	oman road 500 me	tres south west of Fox Covert, Aveb	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007491	
CONDITION:	Extensive significant problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	West Kennett Farm palisaded enclosures, Avebury	/ East Kennett		
DESIGNATION:	Scheduled Monument, 2 LBs, part in CA, WHS	LIST ENTRY NUMBER:	1015157	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	A causewayed enclosure, the core of a round barry associated mortuary enclosure on Windmill Hill, A			
	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008446	
DESIGNATION:				
	Generally satisfactory but with significant localised problems	TREND:	Declining	
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY:	Generally satisfactory but with significant localised	TREND: NEW ENTRY?:	Declining Yes	
CONDITION:	Generally satisfactory but with significant localised problems		-	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Grovely Ditch, Barford St. Martin / Burcombe Without / Great Wishford / Wilton				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005584		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Charity (heritage)	CONTACT:	Nick Croxson 07795 665645		
SITE NAME:	Bowl barrow 300 metres east of Furze Knoll, Bishops Cannings				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013068		
CONDITION:	Extensive significant problems	TREND:	Unknown		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645		
ITE NAME:	Bowl barrow 550 metres north east of Baltic Farm	, Bishops Cannings			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012629		
CONDITION:	Extensive significant problems	TREND:	Unknown		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645		
ITE NAME:	Bowl barrow 950 metres SSW of Beckhampton Plantation, forming part of a round barrow cemetery on Horton Down, Bishops Cannings				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012983		
CONDITION:	Extensive significant problems	TREND:	Unknown		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No		
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645		
SITE NAME:	Bowl barrow situated 500 metres SSW of Shepher	ds' Shore, Bishops	Cannings		
DESIGNATION:	Scheduled Monument, RB	LIST ENTRY NUMBER:	1013756		
CONDITION:	Extensive significant problems	TREND:	Unknown		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645		
SITE NAME:	Eleven round barrows 1000 metres north of Baltic enclosed Iron Age farmstead on North Down, Bish	Farm forming part lops Cannings	of a barrow cemetery, and a probable		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013773		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No		
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645		
ITE NAME:	Enclosed Iron Age farmstead 450 metres south of	Down Barn on Bish	op's Cannings Down, Bishops Cannin		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013230		
CONDITION:	Extensive significant problems	TREND:	Unknown		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Five round barrows 1040 metres NNE of Baltic Fa Bishops Cannings	rm forming part of	a barrow cemetery on North Down
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014737
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Four bowl barrows forming part of a cemetery 270 Cannings	0 metres east of lor	ng barrow on Roughridge Hill, Bishop
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014027
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Group of three bowl barrows 250 metres north e	ast of Shepherds' Sl	nore, Bishops Cannings
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013232
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Kitchen Barrow: a long barrow on Kitchen Barrow Hill, Bishops Cannings		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012519
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Long barrow 650 metres WSW of Shepherds' Sho	re, Bishops Canning	gs
DESIGNATION:	Scheduled Monument, RB	LIST ENTRY NUMBER:	1014030
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Long barrow on Easton Down, Bishops Cannings		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013366
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Saucer barrow 600 metres west of Beckhampton I	Buildings, Bishops C	Cannings
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012193
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Two saucer barrows and a pair of bowl barrows of a round barrow cemetery on Horton Down,		Beckhampton Plantation, forming p
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012982
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Roundway Hill Farm round barrows, Bishops Ca	nnings / Devizes	
DESIGNATION:	Scheduled Monument, RB	LIST ENTRY NUMBER:	1004773
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow: one of a group of round barrows	south of Bulford, Bulf	ord
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009545
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Knighton Roman road (stretching from Reddish	Gore to reservoir), B	ishopstone / Broad Chalke
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003728
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow: one of a group of round barrows	south of Bulford, Bulf	ord
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009564
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 85 metres north of Bishopstrow H	ouse, Bishopstrow	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1019507
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow: one of a group of round barrows	south of Bulford, Bulf	ord
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009602
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Motte and double ringwork east of Bishopstrow	Farm, Bishopstrow	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009891
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow: one of a group of round barrows	south of Bulford, Bulf	ord
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009604
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Enclosure and linear earthworks between Bisho Norton Bavant / Warminster	pstrow Down and Sou	uth Down Sleight, Bishopstrow /
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010283
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow: one of a group of round barrows south of Bulford, Bulford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009605
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Corton long barrow, Boyton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010518
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Long barrow 250 metres east of Boyton Field B	arn, Boyton / Sherring	ton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010520
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Long barrow 240 metres south west of Green E	Barrow Farm, Castle C	Combe
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018419
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / SOU			
SITE NAME:	Long barrow on Cold Kitchen Hill, Brixton Deveri	II	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010416
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 350 metres north east of White Hor	se Plantation, Cher	hill
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010134
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Long barrow on Pertwood Down, 1400 metres no	orth west of Lower	Pertwood, Brixton Deverill
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010463
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 700 metres south east of Field Barn,	Chicklade	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015937
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Knowle Hill round barrow, Broad Chalke		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003033
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Round barrow 860 yards (786 metres) south east o	of Knighton Hill Bu	ildings, Broad Chalke
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004771
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Three bowl barrows in Colerne Park, 450 metres	north of Keeper's (Cottage, Colerne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010758
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Bowl barrow on Wick Down, Collingbourne Ducis		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012510
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 650 metres east of Summer Down Fa	rm, Collingbourne	Kingston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012544
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Two bowl barrows 400 metres south of Summer D	Oown Farm, Colling	bourne Kingston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012518
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Crowdown Clump earthwork (Godsbury), Burbage	e / Collingbourne K	lingston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004759
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow on Little Toyd Down, 650 metres sou	uth west of Grims	Lodge Farm, Coombe Bissett
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015704
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Moated site and surrounding earthwork enclosure,	100 metres south	of Chelworth Farm, Cricklade
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013353
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Dumping	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Devizes Castle, Devizes		
DESIGNATION:	Scheduled Monument and Listed Building grade II, 3 LBs, part in CA	LIST ENTRY NUMBER:	1021375 and 1249362
CONDITION:	Extensive significant problems	TREND:	Stable
CONDITION: PRINCIPAL VULNERABILITY:	Extensive significant problems Collapse	TREND: NEW ENTRY?:	Stable No

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

7 g oxson 07795 665645) g oxson 07795 665645			
g oxson 07795 665645) g			
oxson 07795 665645			
) g			
) g			
g			
g			
oxson 07795 665645			
oxson 07795 665645			
nhead St. Mary			
3			
g			
oxson 07795 665645			
Moated site and fishponds south east of Rowden Farm, Chippenham			
6			
g			
oxson 07795 665645			
7			
ng			
oxson 07795 665645			
ority of a round barrow			
3			
g			
oxson 07795 665645			
e eastern end of The Cursu			
7			
7 ng			

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	East Kennett long barrow, 600 metres south of Ea	st Kennett church,	East Kennett
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1012323
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Edington Priory (site of), Edington		
DESIGNATION:	Scheduled Monument, LB grade I, CA	LIST ENTRY NUMBER:	1004709
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Long barrow, Tinhead Hill, Edington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009783
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - Badger - extensive	NEW ENTRY ?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	North Hill round barrows, Grafton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004746
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 100 metres north of Great Botley Co	opse, Grafton / Sha	lbourne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012301
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY ?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Grovely Castle and earthworks north of Grovely V Langford	Wood, Barford St. I	Martin / Great Wishford / Steeple
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005604
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 340 metres east of Holly Bush Farm,	Grittleton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018418
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Bell barrow, three bowl barrows and gas testing	trenches on Idmistor	n Down, Idmiston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014818
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY ?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Great Botley Copse long barrow, and disc barro	w near it, Grafton / S	halbourne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005692
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645
DITE NAME:	Bronze Age enclosure and two bowl barrows 52 Down, Idmiston	0 metres north east o	of Moll Harris's Clump on Idmiston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014819
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
DITE NAME:	Saucer barrow 400 metres north east of the spo Idmiston Down, Idmiston	rts ground: one of a g	group of round barrows north west o
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013970
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Two disc barrows and two bowl barrows 900 m Idmiston	etres north of Moll H	larris's Clump on Idmiston Down,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015557
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Horse Barrow, Idmiston / Winterbourne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005610
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY ?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Bowl barrow on Keysley Down, 250 metres wes Deverill	t of the A350 Warmi	inster-Shaftesbury Road, Kingston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013877
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
	Private	CONTACT:	Nick Croxson 07795 665645

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Settlement west of Latton, Latton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004689
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Mineral extraction/related subsidence	NEW ENTRY ?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Medieval pottery kilns, Milford Farm, Laverstock		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003252
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bell barrow on Rook Hill, 200 metres west of Pe	ertwood Wood, Long	bridge Deverill
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010470
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Two saucer barrows 775 metres south east of R	odmead Farm, Maide	n Bradley with Yarnfield
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017697
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Town defences, Malmesbury		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1004681
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Religious organisation	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 190 metres north east of Burton F	arm, Mere	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017711
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Black Field Roman site, Mildenhall		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1004726
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

use).

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Bowl barrow 200 metres north east of Everleigh A	shes, Milton Lilbou	rne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009543
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Roman tile and brick kiln site 1000 yards (900 met	res) west of Tidling	corner, Minety
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004702
CONDITION:	Extensive significant problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Early medieval settlement, palace, church and Bron Norton / St. Paul Malmesbury Without	ze Age ring ditches	340 metres east of Cowage Farm,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018389
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow: one of a group of dispersed barrows	south east of Nor	ton Plantation, Norton Bavant
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009830
CONDITION:	Extensive significant problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Round barrow on the south side of Cotley Hill, No	orton Bavant	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009835
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bell barrow 200 metres north of Rockley Plantatio	n, Ogbourne St. Ar	ndrew
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012195
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 375 metres east of Wick Bottom Bar	m, Ogbourne St. Ai	ndrew
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015814
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 630 metres north east of Wick Botto	om Barn, Ogbourne	e St. Andrew
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015803
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

OWNER TYPE:			
PRINCIPAL VULNERABILITY:	Arable ploughing Private	NEW ENTRY?: CONTACT:	No Nick Croxson 07795 665645
	Extensive significant problems		Declining
designation: condition:	Scheduled Monument	TREND:	1004763
SITE NAME:	Preshute Down field system, Preshute	LIST ENTRY NUMBER:	1004742
	Preskurs Davis fold survey D. J. J.		
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
CONDITION:	Extensive significant problems	TREND:	Declining
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003034
SITE NAME:	Group of round barrows on Rough Hill, Preshute	2	
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
CONDITION:	Extensive significant problems	TREND:	Unknown
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012294
SITE NAME:	Bowl barrow 300 metres east of Ivy House Farm	, Preshute	
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012152
SITE NAME:	Moated site 300 metres north east of Potterne P	ark Farm, Potterne	
OWNER TYPE:	Local authority	CONTACT:	Nick Croxson 07795 665645
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
	Extensive significant problems		Unknown
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005623
	Long barrow, Winterbourne, Pitton and Farley		1005(22
DWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005638
SITE NAME:	The Spectacles, Pewsey		
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016779
SITE NAME:	Round barrow cemetery 320 metres south east	of Down Farm, Pewse	ey
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
CONDITION:	Extensive significant problems	TREND:	Declining
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012197

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; no solution agreed but not yet implemented.
C Slow decay; no solution agreed.
D Slow decay; solution agreed but F not yet implemented.
C Slow decay; no solution agreed.
D Slow decay; solution agreed but F not yet implemented.
D Slow decay; solution agreed but ot yet implemented.
D Slow decay; solution agreed but F not yet implemented.
D Slow decay; solution agreed but ot yet implemented.
D Slow decay; solution agreed but ot yet implemented.
D Slow decay; solution agreed but ot yet implemented.
D Slow decay; solution agreed but ot yet implemented.
D Slow decay; solution agreed but ot yet implemented.
D Slow decay; solution agreed but ot yet implemented.
D Slow decay; solution agreed but ot yet implemented.
D Slow decay; solution agreed but ot yet implemented.

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

Decision Decision Rescience VULNERABLITY: Arable ploughing NEW DATATES: No Rescience VULNERABLITY: Arable ploughing NEW DATATES: No RESCIENCE VULNERABLITY: Arable ploughing NEW DATATES: No RESCIENCE VULNERABLITY: Arable ploughing CONTACT: Nick Crosson 07795 665645 Scheduled Monument UST ENTRY NUMBER Declining RENORD Scheduled Monument UST ENTRY NUMBER RENORD Scheduled Monument No CONTRON Scheduled Monument UST ENTRY NUMBER DECINITY Arable ploughing No CONTRON Scheduled Monument UST ENTRY NUMBER CONTRON Generally satisfactory but with significant localised problems TRNO SendedNALVULERABLITY: Velicle damage/encision - extensive Nick Crosson 07795 665645 SendedNALVULERABLITY: Velicle damage/encision - extensive Nick Crosson 07795 665645 SendedNALVULERABLITY: Velicle damage/encision - extensive Nick Crosson 07795 665645 SendedNALVULERABLITY: Velicle damage/encision - extensive Ni	SITE NAME:	Sharpridge field system, Preshute		
PRINCIPAL VULBERMETTER Arable ploughing New PRITTER No DIMMER TYPE: Private, multiple owners CONTACT: Nick Crosson 07795 665645 BILE NAME: Bowl barrow 450 metres north of Cross Droves, Shalbourne 1012274 BERDAME: Scheduled Monument METERTANUMER: 1012274 BOWL Barrow 450 metres north of Cross Droves, Shalbourne Declining Declining BOWL Barrow 400 metres significant problems No Declining BOWL Barrow on Rivar Down, Shalbourne UST ENTRANMERS: No BERGAMION: Scheduled Monument UST ENTRANMERS: Declining BOWL Barrow on Rivar Down, Shalbourne UST ENTRANMERS: Declining BERGAMION: Scheduled Monument UST ENTRANMERS: Declining BOWRER TYPE: Verite: TST ENTRANMERS: Nick Crosson 07795 665645 BITE NAME: Long barrow on Smay Down, 300 metres east ONTENTERS: Nick Crosson 07795 665645 BOWRER TYPE: Long barrow on Smay Down TST ENTRANMERS: No BOWRER TYPE: Long barrow on Smay Down TST ENTRANMERS: No BOWRENTYPE:	DESIGNATION:		LIST ENTRY NUMBER:	1004764
Descent Private, multiple owners CONTACT. Nick Crosson 07795 665645 Bart NAME Bowl barrow 450 metres north of Cross Droves, Shalbourne 1012274 Descent Tools Scheduled Monument ust ENTRY NUMBER 1012274 Descent Tools Extensive significant problems TRAND. Declining Descent Tools Extensive significant problems Not Not Descent Tools Bowl barrow on Rivar Down, Stabbourne Not Crosson 07795 665645 Descent Tools Bowl barrow on Rivar Down, Stabbourne Ust ENTRY NUMBER Not Crosson 07795 665645 Descent Tools Generally satisfactory but with significant localised problems TREND. Declining Descent Tools Generally satisfactory but with significant localised problems TREND. Declining Descent Tools Construct Long barrow on Smay Down, 300 metres east of The Hassock, Shalbourne Declining Descent Tools Extensive significant problems TREND. Declining Descent Tools Extensive significant problems TREND. Declining Descent Tools Extensive significant problems TREND. Declining	CONDITION:	Extensive significant problems	TREND:	Declining
School barrow 450 metres north of Cross Droves, Shalbourne Intervante	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DesiGNATIONScheduled MonumentUST ENTRY NUMBER1012274CONTACTExtensive significant problemsIRENDDecliningRIRCDAL MULKRARAULTY:Arable ploughingNew KRTW?NoOWNER TYPE:PrivateCONTACT:Nick Crosson 07795 665645Beston AllowUST ENTRY NUMBER1012514DesiGNATIONScheduled MonumentUST ENTRY NUMBERDecliningDesiGNATIONScheduled MonumentUST ENTRY NUMBERDecliningCONTINCT:Vehicle damage/erosion - extensiveNew INTRY.YesPRINCRAN UN NERRAUTY:Vehicle damage/erosion - extensiveNew INTRY.YesOWNER TYPE:PrivateCONTACT:Nick Crosson 07795 665645Stre MARE:Long barrow on Smay Down, 300 metres east of THE MERY NUMBER101067CONTACT:Scheduled MonumentINTE PRIFY NUMBER101067CONTACT:PrivateCONTACT:Nick Crosson 07795 665645Stre MARE:Long barrow on Smay Down, 300 metres east of THE MARE:101067CONTACT:PrivateCONTACT:Nick Crosson 07795 665645Stre MARE:Vansdyke: Daniel's Lane section, ShalbourneINTENTY NUMBER1005594CONTACT:PrivateCONTACT:Nick Crosson 07795 665645Stre NAME:Scheduled MonumentUST ENTRY NUMBER1005594CONTACT:Private, multiple ownersCONTACT:Nick Crosson 07795 665645Stre NAME:Stre Outprive of Arago Road ammunition compound, ShrevoScheduled Monument, WHSINTE VHTRY NUMBER1005594	OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645
COMMINANExtensive significant problemsTREND:DeckningRENDERAL VILLINERABILITY:Arable ploughingNow DATRY:NoRENDERAL VILLINERABILITY:Arable ploughingNow DATRY:Nick Crossen 07795 665645WITE NAME:Bowl barrow on Rivar Down, ShalbourneUST DATRY: NAME:102514Steeduled MonumentUST DATRY: NAME:102514Condition:Generally statisfactory but with significant localleTREND:DecliningCondition:Generally statisfactory but with significant localleNick Crossen 07795 665645RENDERAL VILLINERABILITY:Vehicle damage/erosion - extensiveNick Crossen 07795 665645OWNER TYPE:Cond barrow on Smay Down, 300 metres east of The Name:DecliningDEGULATIONScheduled MonumentUST DATRY: NAME:NoDEGULATIONScheduled MonumentUST DATRY: NAME:DecliningDEGULATIONScheduled MonumentUST DATRY: NAME:NoDEGULATIONScheduled MonumentUST DATRY: NAME:NoDEGULATIONScheduled MonumentUST DATRY: NAME:NoDEGULATIONGenerally unsatisfactory with major localised problemsIDEND:NoDEGULATIONGenerally unsatisfactory with major localised problemsIDEND:NoDEGULATIONScheduled Monument, WHSIDTENTY: NAME:NoDEGULATIONScheduled Monument, WHSIDTENTY: NAME:IDEND:DEGULATIONScheduled Monument, WHSIDTENTY: NAME:IDEND:DEGULATIONScheduled Monument, WHSIDTE	SITE NAME:	Bowl barrow 450 metres north of Cross Droves, S	Shalbourne	
Decision of generally consistion Decision of generally consistion No Decision of generally consistion NEW ENTRY: Nick Crossen 07795 665645 DESIGNATION: Scheduled Monument UST ENTRY NUMBER: Nick Crossen 07795 665645 DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1012514 CONTION: Generally castificatory but with significant localised problems TRENCIP. Declining DESIGNATION: Contract: Nick Crossen 07795 665645 DESIGNATION: Contract: Nick Crossen 07795 665645 DESIGNATION: Contract: Nick Crossen 07795 665645 DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1010467 DESIGNATION: Scheduled Monument UST ENTRY: No DESIGNATION: Scheduled Monument UST ENTRY:	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012274
DWNER TYPE Private CONTACT: Nick Crosson 07795 665645 Bowl barrow on Rivar Down, Shalbourne UST DYNY NUMBER 1012514 DISSERVATION: Scheduled Monument UST DYNY NUMBER 1012514 CONDITION: Generally satisfactory but with significant localised problems TREND: Declining RENCERAL VULNERABUTY: Vehicle damage/erosion - extensive NEW DYRY: Yes DWNER TYPE Private CONTACT: Nick Crosson 07795 665645 STEE NAME: Long barrow on Smay Down, 300 metres east of The Hassock, Shalbourne Declining DESIGNATION: Scheduled Monument UST BYTY NUMBER 101047 CONTACT: Nick Crosson 07795 665645 Scheduled Monument UST BYTY NUMBER No CONTACT: Nick Crosson 07795 665645 Scheduled Monument UST BYTY NUMBER No CONTACT: Nick Crosson 07795 665645 Scheduled Monument UST BYTY NUMBER No CONTACT: Nick Crosson 07795 665645 Scheduled Monument UST BYTY NUMBER 1005794 Scheduled Monument UST BYTY NUMBER Incota Scheduled Monument <td>CONDITION:</td> <td>Extensive significant problems</td> <td>TREND:</td> <td>Declining</td>	CONDITION:	Extensive significant problems	TREND:	Declining
STRE NAME Sowbarrow on Rivar Down, Shalbourne USE INTRY NUMBER [012514 DEBIGNATION: Scheduled Monument USE INTRY NUMBER [012514 CONDITION: Generally satisfactory but with significant localised problems TREND: Declining PRENCIPAL VULNERABILTY: Vehicle damage/erosion - extensive NEW ENTRY: Yes OWNER TYPE: Private CONTACT: Nick Crosson 07795 6656453 STE NAME: Long barrow on Smay Down, 300 metres east of THENO: Declining DESIGNATION: Atable ploughing TRENO: Declining OWNER TYPE: Private NEW ENTRY: Nick Crosson 07795 665645 RIKKIPAL VULNERABUTY: Atable ploughing NEW ENTRY: Nick Crosson 07795 665645 STET NAME: Control Null Scheduled Monument UST ENTRY NUMBER Nick Crosson 07795 665645 STET NAME: Vansdyke: Daniel's Lane section, Shalbourne Nick Crosson 07795 665645 Nick Crosson 07795 665645 STE NAME: Vansdyke: Daniel's Lane section, Shalbourne Nick Crosson 07795 665645 Nick Crosson 07795 665645 Ste Nowl barrows and two disc barrow Storm Storm VITY: Nick Cr	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DeskGNATION: Scheduled Monument UKT ENTRY NUMBER: 1012514 CONDITION: Generally satisfactory but with significant localised problems TREND: Declining CONDITION: Generally satisfactory but with significant localised problems NEW ENTRY: Yes CONTACT: Private CONTACT: Nick Crosson 07795 665645 STEE NAME: Long barrow on Smay Down, 300 metres east of THE MANDER: 1010467 DESIGNATION: Scheduled Monument LST ENTRY NUMBER: 1010467 CONDITION: Extensive significant problems TREND. Declining CONDITION: Arable ploughing NEW ENTRY: Nick Crosson 07795 665645 STEE NAME: Wansdyke: Daniel's Lane section, Shalbourne Declining DEGIGNATION: Scheduled Monument LST ENTRY NUMBER: 1005594 CONDITION: Scheduled Monument LST ENTRY NUMBER: 1005594 CONDITION: Scheduled Monument LST ENTRY NUMBER: 1005594 CONDITION: Scheduled Monument, WHM LST ENTRY NUMBER: 1005696 CONDITION: Scheduled Monument, WHM LST ENTRY NUM	OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
ConditionGenerally satisfactory but with significant localised problemsINEEND:DecliningRENCIEND VULNERABILITY:Vehicle damage/erosion - extensiveNEW ENTRY:YesRENCIEND VULNERABILITY:PrivateCONTACT:Nick Crosson 07795 665645ATTE NAME:Long barrow on Smay Down, 300 metres east of THE NUMEE1010467DESIGNATION:Scheduled MonumentUST ENTRY NUMEE1010467DESIGNATION:Scheduled MonumentUST ENTRY NUMEENoDecliningREND:DecliningNoSMINER TYPE:Na Pab alboughingNEW ENTRY:NoOWNER TYPE:Vansdyke: Daniel's Lane section, ShalboureVENCENTRY:NoDESIGNATION:Scheduled MonumentUST ENTRY NUMEE1005594DESIGNATION:ConditionGenerally unsatisfactory with major localised problemsREND:DecliningDENDITION:Private, multiple ownersConTACT:Nick Crosson 07795 665645ATE NAME:Skebul barrows and two disc barrows forming the majority of a renze venteery 300 metres nort west of Fargo Road ammunition compound, Shreev	SITE NAME:	Bowl barrow on Rivar Down, Shalbourne		
Concention problems NetWork Declining PRINCIPAL VULNERABULTY: Vehicle damage/erosion - extensive NEW ENTRY: Yes DWINER TYPE: Private CONTACT: Nick Croxson 07795 665645 SITE NAME: Long barrow on Smay Down, 300 metres east of The Hassock, Shalbourne Io10467 DEBIGNATION: Scheduled Monument LIST ENTRY NUMBER Io10467 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABULTY: Arable ploughing NEW ENTRY: No DOWNER TYPE: Private CONTACT: Nick Croxson 07795 665645 STEE NAME: Wansdyke: Daniel's Lane section, Shalbourne IO05594 DEBIGNATION: Scheduled Monument LIST ENTRY NUMBER 1005594 CONDITION: Generally unsatisfactory with major localised TREND: Declining DOWNER TYPE: Private, multiple owners CONTACT: Nick Croxson 07795 665645 Six bowl barrows and two disc barrows formig the superity of a route strow createry 300 metres nort west of Fargo Road ammunition compound, Shrewen Strew: No DEBIGNATION: Scheduled Monument,	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012514
MANNER TYPE: Private CONTACT: Nick Crosson 07795 665645 BITE NAME: Long barrow on Smay Down, 300 metres east of The Hassock, Shalbourne 1010467 DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1010467 CONDITION: Extensive significant problems TREND: Declining REINCIPAL VULNERABILITY: Arable ploughing New ENTRY: No OWNER TYPE: Private CONTACT: Nick Crosson 07795 665645 STEE NAME: Wansdyke: Daniel's Lane section, Shalbourne Vansdyke: Daniel's Lane section, Shalbourne CONTACT: Nick Crosson 07795 665645 Declining CONDITION: Scheduled Monument UST ENTRY NUMBER: 1005594 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining REINCIPAL VULNERABILITY: Arable clipping NEW ENTRY: No OWNER TYPE: Private, multiple owners CONTACT: Nick Crosson 07795 665645 Stre NAME: Sty bowl barrows and two disc barrows forming the majority of a router strow cemetery 300 metres nort west of Fargo Road ammunition compound, Shrewton Declining CONDIT	CONDITION:		TREND:	Declining
STRE NAME: Long barrow on Smay Down, 300 metres east of THE MESSICk, Shalbourne DESIGNATION: Scheduled Monument UST ENTRY NUMBER: [010467 CONDITION: Extensive significant problems TREND: Declining CONDITION: Arable ploughing New ENTRY: No DOWNER TYPE: Private CONTACT: Nick Crosson 07795 665645 STEE NAME: Scheduled Monument LST ENTRY NUMBER: 1005594 CONDITION: Generally unsatisfactory with major localised problems New ENTRY: No CONDITION: Six bowl barrows and two disc barrows forming the mest of Fargo Road ammunition compound, Shrew: Nick Crosson 07795 665645 Stre NAME: Six bowl barrows and two disc barrows forming the mest of Fargo Road ammunition compound, Shrew: No CONDITION: Scheduled Monument, WHS UST ENTRY NUMBER: 1009 [24 CONDITION: Scheduled Monument or agen	PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	Yes
Designation:Scheduled MonumentLIST ENTRY NUMBER:1010467CONDITION:Extensive significant problemsTREND:DecliningRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY:NoOWNER TYPE:PrivateCONTACT:Nick Croxson 07795 665645BITE NAME:Wansdyke: Daniel's Lane section, Shalbourne1005594DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1005594CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningRINCIPAL VULNERABILITY:Arable clippingNEW ENTRY:NoOWNER TYPE:Private, multiple ownersCONTACT:Nick Croxson 07795 665645STE NAME:Six bowl barrows and two disc barrows forming the majority of a route barrow cemetery 300 metres nort west of Fargo Road ammunition compound, ShrewtonDoo1124DESIGNATION:Scheduled Monument, WHSLIST ENTRY NUMBER:1009124CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningDESIGNATION:Scheduled Monument, WHSLIST ENTRY NUMBER:1009124CONDITION:Government or agencyCONTACT:Nick Croxson 07795 665645STE NAME:Newton Barrow, South NewtonCONTACT:Nick Croxson 07795 665645STE NAME:Newton Barrow, South NewtonCONTACT:Nick Croxson 07795 665645STE NAME:Newton Barrow, South NewtonCONTACT:Nick Croxson 07795 665645Steaduled MonumentLIST ENTRY NUMBER:1005687DESIGNATION:Sche	OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
CODDITION:Extensive significant problemsTREND:DecliningRINCLEAL VULNERABILITY:Arable ploughingNEW ENTRY?:NoWINER TYPE:PrivateCONTACT:Nick Crosson 07795 665645WINER TYPE:Wansdyke: Daniel's Lane section, Shalbourne1005594CONDITION:Scheduled MonumentUIST ENTRY NUMBER:1005594CONDITION:Scheduled MonumentUIST ENTRY NUMBER:NoCONDITION:Arable clippingNEW ENTRY:NoWINER TYPE:Private, multiple ownersCONTACT:Nick Crosson 07795 665645CONDITION:Six bowl barrows and two disc barrows forming the majority of a TENTRY NUMBER:1009124CONDITION:Scheduled Monument, WHSUIST ENTRY NUMBER:1009124CONDITION:Scheduled Monument, WHSUIST ENTRY NUMBER:NoCONDITION:Generally satisfactory but with significant localised problemsTREND:NoCONDITION:Government or agencyCONTACT:Nick Crosson 07795 665645CONDITION:Government or agencyCONTACT:Nick Crosson 07795 665645CONDITION:Government or agencyCONTACT:Nick Crosson 07795 665645CONDITION:Government or agencyCONTACT:Nick Crosson 07795 665645CONTACT:Nick Crosson 07795 665645Nick Crosson 07795 665645 <td>SITE NAME:</td> <td>Long barrow on Smay Down, 300 metres east of T</td> <td>he Hassock, Shalbo</td> <td>ourne</td>	SITE NAME:	Long barrow on Smay Down, 300 metres east of T	he Hassock, Shalbo	ourne
REINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY:NoDWNER TYPE:PrivateCONTACT:Nick Crosson 07795 665645DWNER TYPE:Wansdyke: Daniel's Lane section, ShalbourneNEW ENTRY:Nick Crosson 07795 665645DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1005594DODDITION:Generally unsatisfactory with major localised problemsTREND:DecliningDONNER TYPE:Arable clippingNEW ENTRY:NoDONNER TYPE:Private, multiple ownersCONTACT:Nick Crosson 07795 665645DWNER TYPE:Six bowl barrows and two disc barrows forming the majority of a routbarrow cemetery 300 metres nort west of Fargo Road ammunition compound, ShrewtonNoDESIGNATION:Scheduled Monument, WHSLIST ENTRY NUMBER:1009 124DONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningDONDITION:Generally satisfactory but with significant localised problemsNew ENTRY:NoDONDITION:Government or agencyCONTACT:Nick Crosson 07795 665645STRE NAME:Newton Barrow, South NewtonNEW ENTRY:NoDESIGNATION:Scheduled Monument, WHSLIST ENTRY NUMBER:1009 124CONDITION:Government or agencyCONTACT:Nick Crosson 07795 665645STRE NAME:Newton Barrow, South NewtonNick Crosson 07795 665645DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1005687DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010467
DVINER TYPE:PrivateCONTACT:Nick Crosson 07795 665645STE NAME:Wansdyke: Daniel's Lane section, Shalbourne1955 94DESIGNATION:Scheduled MonumentINTE ENTRY NUMBER1005594CONDITION:Generally unsatisfactory with major localised problemsIREND:DecliningRINCIPAL VULNERABILITY:Arable clippingNEW ENTRY:NoOWNER TYPE:Trivate, multiple ownersCONTACT:Nick Crosson 07795 665645STE NAME:Six bowl barrows and two disc barrows forming the majority of a row water of Fargo Road ammunition compound, Shrew:Vontact:100124STE NAME:Scheduled Monument, WHSINFE INTRY NUMBER100124International Control of StephensCONDITION:Scheduled Monument, WHSINFE INTRY NUMBER100124CONDITION:Generally satisfactory but with significant localised problemsINEND:DecliningCONDITION:Animal burrowing - moderateNEW ENTRY:NoOWNER TYPE:Scheduled Monument of a control of a control of the section of the	CONDITION:	Extensive significant problems	TREND:	Declining
SITE NAME: Wansdyke: Daniel's Lane section, Shalbourne DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1005594 CONDITION: Generally unsatisfactory with major localised problems InreND: Declining RRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY?: No OWNER TYPE: Private, multiple owners CONTACT: Nick Crosson 07795 665645 SITE NAME: Siz bowl barrows and two disc barrows forming the majority of a rourberrow cemetery 300 metres nort west of Fargo Road ammunition compound, Shrewton: 1009124 DESIGNATION: Scheduled Monument, WHS LIST ENTRY NUMBER: 1009124 CONDITION: Generally satisfactory but with significant localised problems INEW ENTRY?: No DESIGNATION: Scheduled Monument, WHS LIST ENTRY NUMBER: 1009124 CONDITION: Generally satisfactory but with significant localised problems INEW ENTRY?: No SITE NAME: Newton Barrow, South Newton Scheduled Monument UST ENTRY NUMBER: 1005687 SITE NAME: Newton Barrow, South Newton UST ENTRY NUMBER: 1005687 DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1005687 CONDITIO	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Design ATION:Scheduled MonumentLIST ENTRY NUMBER:1005594conDiftion:Generally unsatisfactory with major localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable clippingNEW ENTRY:NoOWNER TYPE:Private, multiple ownersCONTACT:Nick Crosson 07795 665645STE NAME:Six bowl barrows and two disc barrows forming the west of Fargo Road ammunition compound, Shreet- west of Fargo Road ammunition compound, Shreet- west of Fargo Road ammunition compound, Shreet- problems1009124DESIGNATION:Scheduled Monument, WHSLIST ENTRY NUMBER:1009124CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningCONDITION:Government or agencyCONTACT:Nick Crosson 07795 665645CONDITION:Newton Barrow, South NewtonNEW ENTRY:NoStre NAME:Newton Barrow, South NewtonScheduled MonumentNEW ENTRY:CONDITION:Scheduled MonumentUIST ENTRY NUMBER:1005687CONDITION:Scheduled MonumentUIST ENTRY NUMBER:1005687CONTACT:Scheduled MonumentUIST ENTRY NUMBER:1005687CONDITION:Scheduled MonumentUIST ENTRY NUMBER:1005687CONDITION:Generally satisfactory but with significant localised problemsTREND:StableCONDITION:Generally satisfactory but with significant localised problemsTREND:NoCONDITION:Generally satisfactory but with significant localised problemsTREND:Stable<	OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningRINCIPAL VULNERABILITY:Arable clippingNEW ENTRY?:NoOWNER TYPE:Private, multiple ownersCONTACT:Nick Crosson 07795 665645STE NAME:Six bowl barrows and two disc barrows forming the majority of a router west of Fargo Road ammunition compound, ShrewtorJarrow Cemetery 300 metres nortSTE NAME:Scheduled Monument, WHSLIST ENTRY NUMBER:1009124CONDITION:Scheduled Monument, WHSIST ENTRY NUMBER:1009124CONDITION:Generally satisfactory but with significant localised problemsREND:DecliningCONDITION:Government or agencyCONTACT:NoOWNER TYPE:Government or agencyCONTACT:Nick Crosson 07795 665645CONDITION:Scheduled MonumentLIST ENTRY NUMBER:NoCONTACT:Nick Crosson 07795 665645Scheduled MonumentLIST ENTRY NUMBER:CONTACT:Nick Crosson 07795 665645Scheduled MonumentLIST ENTRY NUMBER:CONDITION:Scheduled MonumentLIST ENTRY NUMBER:1005687CONDITION:Scheduled MonumentLIST ENTRY NUMBER:1005687CONDITION:Scheduled MonumentLIST ENTRY NUMBER:1005687CONDITION:Scheduled MonumentLIST ENTRY NUMBER:NoCONDITION:Scheduled MonumentLIST ENTRY NUMBER:1005687CONDITION:Scheduled MonumentLIST ENTRY NUMBER:NoCONDITION:Scheduled MonumentLIST ENTRY NUMBER: </td <td>SITE NAME:</td> <td>Wansdyke: Daniel's Lane section, Shalbourne</td> <td></td> <td></td>	SITE NAME:	Wansdyke: Daniel's Lane section, Shalbourne		
problemsnotedDecliningPRINCIPAL VULNERABILITY:Arable clippingNEW ENTRY:NoPrivate, multiple ownersCONTACT:Nick Croxson 07795 665645Site NAME:Six bowl barrows and two disc barrows forming the majority of a rourd barrow cemetery 300 metres nort west of Fargo Road ammunition compound, Shrewton- west of Fargo Road ammunition compound, Shrewton- source of fargo Road ammunition compound, Shrewton- besignation:LIST ENTRY NUMBER:1009124CONDITION:Scheduled Monument, WHSLIST ENTRY NUMBER:1009124CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Animal burrowing - moderateNEW ENTRY?NoOWNER TYPE:Government or agencyCONTACT:Nick Croxson 07795 665645Siste NAME:Newton Barrow, South NewtonUIST ENTRY NUMBER:1005687Designation:Scheduled MonumentLIST ENTRY NUMBER:1005687CONDITION:Generally satisfactory but with significant localised problemsILST ENTRY NUMBER:1005687CONDITION:Scheduled MonumentLIST ENTRY NUMBER:1005687CONDITION:Generally satisfactory but with significant localised problemsTREND:StableCONDITION:Generally satisfactory but with significant localised problemsREND:StableCONDITION:Arable clippingNEW ENTRY?No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005594
Downer TYPE:Private, multiple ownersCONTACT:Nick Crosson 07795 665645SITE NAME:Six bowl barrows and two disc barrows forming the majority of a row west of Fargo Road ammunition compound, Shrewtonbarrow cemetery 300 metres nortDESIGNATION:Scheduled Monument, WHSUST ENTRY NUMBER:1009124CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningRRINCIPAL VULNERABILITY:Animal burrowing - moderateNEW ENTRY ?:NoOWNER TYPE:Government or agencyCONTACT:Nick Crosson 07795 665645SITE NAME:Newton Barrow, South NewtonScheduled MonumentUST ENTRY NUMBER:1005687DESIGNATION:Scheduled MonumentUST ENTRY NUMBER:1005687CONDITION:Generally satisfactory but with significant localised problemsIST ENTRY NUMBER:1005687SITE NAME:Newton Barrow, South NewtonIST ENTRY NUMBER:1005687CONDITION:Generally satisfactory but with significant localised problemsIST ENTRY NUMBER:1005687CONDITION:Generally satisfactory but with significant localised problemsIREND:StableCONDITION:Arable clippingNEW ENTRY?:No	CONDITION:		TREND:	Declining
SITE NAME: Six bowl barrows and two disc barrows forming the majority of a round barrow cemetery 300 metres nort west of Fargo Road ammunition compound, Shrewton DESIGNATION: Scheduled Monument, WHS LIST ENTRY NUMBER: 1009124 CONDITION: Generally satisfactory but with significant localised problems TREND: Declining CONDITION: Animal burrowing - moderate NEW ENTRY: No OWNER TYPE: Government or agency CONTACT: Nick Crosson 07795 665645 SITE NAME: Newton Barrow, South Newton ISTE ENTRY NUMBER: 1005687 Scheduled Monument UIST ENTRY NUMBER: 1005687 ODESIGNATION: Scheduled Monument IIST ENTRY NUMBER: 1005687 STEE NAME: Newton Barrow, South Newton IIST ENTRY NUMBER: 1005687 CONDITION: Generally satisfactory but with significant localised problems TREND: Stable CONDITION: Generally satisfactory but with significant localised problems New ENTRY: No	PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
An El Nor Lewest of Fargo Road ammunition compound, ShrewtonLIST ENTRY NUMBER:1009124DESIGNATION:Scheduled Monument, WHSLIST ENTRY NUMBER:1009124CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Animal burrowing - moderateNEW ENTRY?:NoDOWNER TYPE:Government or agencyCONTACT:Nick Croxson 07795 665645DIFE NAME:Newton Barrow, South NewtonLIST ENTRY NUMBER:1005687DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1005687CONDITION:Generally satisfactory but with significant localised problemsTREND:StableCONDITION:Arable clippingNEW ENTRY?:No	OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645
CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Animal burrowing - moderateNEW ENTRY?:NoOWNER TYPE:Government or agencyCONTACT:Nick Croxson 07795 665645SITE NAME:Newton Barrow, South NewtonIST ENTRY NUMBER:1005687Designation:Scheduled MonumentIST ENTRY NUMBER:1005687Condition:Generally satisfactory but with significant localised problemsTREND:StablePRINCIPAL VULNERABILITY:Arable clippingNEW ENTRY?:No	SITE NAME:			nd barrow cemetery 300 metres north
problemsproblemsPrivate and	DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1009124
DWNER TYPE:Government or agencyCONTACT:Nick Croxson 07795 665645SITE NAME:Newton Barrow, South NewtonUST ENTRY NUMBER:1005687DESIGNATION:Scheduled MonumentUST ENTRY NUMBER:1005687CONDITION:Generally satisfactory but with significant localised problemsTREND:StablePRINCIPAL VULNERABILITY:Arable clippingNEW ENTRY?:No	CONDITION:		TREND:	Declining
Site NAME: Newton Barrow, South Newton DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1005687 CONDITION: Generally satisfactory but with significant localised problems TREND: Stable PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
Designation:Scheduled MonumentLIST ENTRY NUMBER:1005687CONDITION:Generally satisfactory but with significant localised problemsTREND:StablePRINCIPAL VULNERABILITY:Arable clippingNEW ENTRY?:No	OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
CONDITION:Generally satisfactory but with significant localised problemsTREND:StablePRINCIPAL VULNERABILITY:Arable clippingNEW ENTRY?:No	ITE NAME:	Newton Barrow, South Newton		
problems New ENTRY? No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005687
	CONDITION:		TREND:	Stable
OWNER TYPE: Private CONTACT: Nick Croxson 07795 665645	PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
		Privato	CONTACT:	Nick Crosson 07795 665645

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Stapleford Castle, Stapleford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005686
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Barrow north of 'The Spectacles', Steeple Langford	l	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004742
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 240 metres east of The Penning, Stee	eple Langford	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015025
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Deptford Down round barrow, Steeple Langford		
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1005615
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Little Langford round barrow, north of Upper Farm	n Down, Steeple La	angford
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005605
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY ?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Round barrow 230 yards (210 metres) north west	of New Field Plant	ation, Steeple Langford
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004725
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bell barrow on Parsonage Down, 1.3 kilometres sc	outh east of Lord's	Hill Farm, Sutton Veny
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016677
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
	Private	CONTACT:	Nick Croxson 07795 665645
OWNER TYPE:			
OWNER TYPE:	Bowl barrow on Littlecombe Down, Sutton Veny		
	Bowl barrow on Littlecombe Down, Sutton Veny Scheduled Monument	LIST ENTRY NUMBER:	1005683
SITE NAME:	· · · · · · · · · · · · · · · · · · ·	LIST ENTRY NUMBER:	1005683 Declining
SITE NAME: DESIGNATION:	Scheduled Monument		

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Fosbury camp, Tidcombe and Fosbury			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005682	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	' Stock erosion - localised/limited	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Castle Ditches camp, Tisbury			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	RY NUMBER: 1005701	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Casterley Camp and associated monuments, Upavo	on		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010074	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Bowl barrow 500 metres south of Upton Scudamore, Upton Scudamore			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010398	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Bowl barrow in The Belt, 350 metres north east of Hill Barn, West Overton			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019901	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Bowl barrow 400 metres west of Normanton Gor	se, Wilsford cum La	ake	
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010831	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Ten bowl barrows, five disc barrows, a bell barrow Wilsford round barrow cemetery, Wilsford cum La	v, a pond barrow an ake	d a saucer barrow forming the	
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010874	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY ?:	No	
	8			
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Hare Warren Control Station, Wilton		
DESIGNATION:	Scheduled Monument, RPG grade I	LIST ENTRY NUMBER:	1417594
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	Yes
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bell barrow 450 metres south east of Greenland Fa of the Lesser Cursus, Winterbourne Stoke	arm, forming part c	of a linear round barrow cemetery we
DESIGNATION:	Scheduled Monument, WHS	cheduled Monument, WHS LIST ENTRY NUMBER:	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 350 metres north west of Greenland	Farm, Winterbour	ne Stoke
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010892
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 830 metres south west of Greenland	s Bungalow, east of	Shrewton, Winterbourne Stoke
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015217
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Tithe barn, Roche Old Court, Winterslow		
DESIGNATION:	Scheduled Monument LIST ENTRY NUMBER: 1002995		1002995
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bronze Age enclosure and bowl barrow 100 metres west of Longbarrow Cross Roads on Winterbourne Stoke Down, Winterbourne Stoke		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011048
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Disc barrow and pond barrow 350 metres NNW of Greenland Farm, Winterbourne Stoke		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010891
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

ITE NAME:	Bowl barrow 175 metres west of Square Copse: part of the Square Copse barrow cemetery, Wootton Rivers				
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1013352	
CONDITION:	Extensive significant problems		TREND:	Declining	
RINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No	
OWNER TYPE:	Crown		CONTACT:	Nick Croxson 07795 665645	
ITE NAME:	Bowl barrow 275 Rivers	metres west of Square Copse: pa	rt of the Square C	opse barrow cemetery, Wootton	
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1013364	
CONDITION:	Extensive significant problems		TREND:	Declining	
RINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No	
OWNER TYPE:	Crown		CONTACT:	Nick Croxson 07795 665645	
	SITE NAME:	Tottenham House and Savernake Forest, Burbage / Great Bedwyn / Little Bedwyn / Marlborough / Mildenhall / Savernake	Extensive landscape of rides linking Savernake Forest wit ornamental parkland and pleasure grounds around the house. Exemplifies the work of Burlington, Brown, Cunc and others. Planning permission for hotel development I lapsed. The house and core of the landscape have been sold to a private owner and the process of conservation and repair has begun, allied to major development proposals (application under consideration). The Forest Commission manages Savernake Forest on a long lease. There is a Natural England Stewardship Scheme over pa of the park.		
	DESIGNATION:	Registered Park and Garden grade II*, 20 LBs, 7 SMs			
© Historic England	CONDITION:	Generally unsatisfactory with major localised problems			
	VULNERABILITY:	Medium	or the park.		
	TREND:	Improving			
	NEW ENTRY?:	No			
	OWNER TYPE:	Mixed, multiple owners			

WILTSHIRE (UA) / NEW FOREST (NP)

LIST ENTRY NUMBER:

1000472

SITE NAME:	Barrows in Bath Hole and Bury Hill Plantations, Landford, Wiltshire (UA)		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004754
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: Jo McAllister 0117 975 0696

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

This document is one in a series of regional registers produced as part of Historic England's national Heritage at Risk programme. The registers for other regions and previous Heritage at Risk publications can be found at historicengland.org.uk/advice/heritage-at-risk/ registers-and-publications/ More information about Historic England's Heritage at Risk programme can be found at historicengland.org.uk/advice/heritage-at-risk/

Heritage at Risk Published November 2021 4th Floor, Cannon Bridge House 25 Dowgate Hill London EC4R 2YA © Copyright Historic England 2021 Product code: HE0065



South West Register 2021