

LONDON

Contents

HERITAGE AT RISK	3
Reducing the risks	7
Publications and guidance	10
THE REGISTER	12
Content and assessment criteria	12
Key to the entries	15
London heritage assets at risk	17
Barking and Dagenham Barnet Bexley Brent Bromley Camden City of London Croydon Ealing Enfield Greenwich Hackney Hammersmith and Fulham Haringey Harrow Havering Hillingdon Hounslow Islington Kensington and Chelsea Kingston upon Thames Lambeth Lewisham Merton Newham Redbridge Richmond upon Thames Southwark Sutton Tower Hamlets Waltham Forest Wandsworth Westminster, City of	18 19 21 22 26 34 35 37 40 43 47 52 54 57 71 74 77 77 82 84 85 89 90 91 97 98 104 106 108



In its fourth year, the Heritage at Risk Register now includes grade I and II* listed buildings, listed places of worship, scheduled monuments, registered parks and gardens, registered battlefields, protected wreck sites and conservation areas known to be at risk as a result of neglect, decay or inappropriate development. This year, for the first time, we have published a list of 'priority sites': important heritage at risk sites where we will focus our resources to secure their futures.

There is a tangible change to the atmosphere in London as it completes the arrangements to welcome the world for the Olympic Games in less than a year. With the venues largely complete and test events in progress, ensuring that the city presents an attractive and vibrant setting for visitors to enjoy outside of the Games is essential. An important part of this has been renewed effort to improve the condition of the historic environment across the city, from repairing the grade II* listed National Sports Centre at Crystal Palace to restoring and improving the buildings in conservation areas in east London as part of the High Street 2012 initiative.

However, managing Heritage at Risk is more a marathon than a sprint. We are in the middle of the race and making steady progress on reducing the number of entries on the Register by securing a successful future for them. This progress is going to be even more difficult to maintain in the coming years as resources become more constrained, which will inevitably make finding economic uses for buildings at risk more challenging. It will also make finding a sustainable future for local authority owned assets more difficult. As half of the Registered parks and gardens at risk in London are in local authority ownership this is a particular concern. The difficult economic conditions not only affect assets already on the Register, but could also be the reason for others being added, like Bow Street Magistrates' Court and Police Station, a dignified late C19 former civic building that still awaits conversion into a hotel.

Perhaps the biggest challenge facing London is managing and caring for its outstanding legacy of cemeteries, several of them Registered landscapes, some, like Abney Park, needing significant resourcing to save them from further decline. These will be a major priority for English Heritage in London in the next year and we will be looking to work with partners to try and make their future more secure. However, cemeteries and funerary architecture are not without friends groups, who can achieve success if supported. This has been demonstrated at St John the Evangelist in Great Stanmore where a number of collapsing monuments are now being repaired by the PCC using Section 106 monies.

The role of communities in managing their historic environment is going to become ever more significant. In the last two years, in partnership with 32 out of 33 London boroughs, we have managed to assess the condition of conservation areas across the capital so that we know where effort on improvement needs to be made. This is the everyday historic environment that can add so much to our lives. Supporting interested communities to achieve their ambitions takes determination but the rewards, when successful, can be very satisfying. The achievement of the St Stephen's Restoration and Preservation Trust in securing the repair and adaptation of St Stephen's Rosslyn Hill as a community lifelong learning centre, means that one of the buildings on the first ever Buildings at Risk Register for London can now be removed after 20 years. That is surely worthy of a Gold medal!

Nigel Barker, Planning Director LONDON

BUILDINGS AT RISK

- Nationally, 3.0% of grade I and II* listed buildings are at risk. In London this rises to 4.1%, representing 80 sites.
- 2.4% (395) of London's grade II listed buildings are at risk.
- 9 grade I and II* and 47 grade II buildings have been removed from the 2010 Register, but 4 grade I and II* and 44 grade II buildings have been added.
- 68% of grade I and II* listed and structural monument entries (71 buildings) on the baseline 1999 Register for London have been removed as their futures have been secured, compared to the national figure of 53% (757 buildings).
- Nationally, £5.2m was offered to 71 grade I and II* listed buildings on the Register during 2010/11. In London, we awarded grants totalling £187k to 5 sites.
- In addition, grants of £327 were offered to 10 grade II buildings at risk.
- 29 listed places of worship are included on our Register this year. We estimate the cost of repairing these buildings is £8.6m.

SCHEDULED MONUMENTS

- 16.9% (3,339) of England's 19,748 scheduled monuments are at risk, compared to 23% (35 sites) in London.
- In London, 5 sites have been removed from the 2010 Register, but 3 sites have been added.
- 24.3% of entries (9 sites) on the baseline 2009 Register for London have been removed due to positive reasons, compared to the national figure of 11.9% (399 sites).
- Arable ploughing and unrestricted plant, scrub or tree growth account for nearly two thirds of sites at risk nationally.
 In London it is uncontrolled vegetation (31.4%) and general deterioration due to lack of management (20%) that are the commonest risks.
- Nationally, 82% of scheduled monuments at risk are in private ownership, but in London over half (57%) are owned by local authorities.
- Of the £357k offered by English Heritage to owners of scheduled monuments at risk in 2010/11, £29k was to 5 sites in London.

REGISTERED PARKS AND GARDENS

- 103 of England's 1,610 registered parks and gardens are at risk, an increase from 6.2% (99) in 2010 to 6.4% this year. In London, 14 of our 149 sites are at risk (9.4%).
- Nationally, 6 sites have been added and 2 removed from the 2010 Register. There has been no change in London.
- Of the £26k offered by English Heritage to owners of registered parks and gardens at risk in 2010/11, £10k was to 1 site in London.

REGISTERED BATTLEFIELDS

• Of the 43 registered battlefields in England, 6 are at risk, 2 less than the 2008 baseline. London's single registered battlefield is not at risk.

PROTECTED WRECK SITES

• Of the 46 protected wreck sites off England's coast, 7 are at risk, 3 less than the 2008 baseline. London has no protected wreck sites.

CONSERVATION AREAS

- 288 local planning authorities (86%) have taken part in the national survey of conservation areas, of which 32 are in London. This is 97% of our local planning authorities.
- We now have information on the condition of 7,841 of England's 9,600 designated conservation areas and 516 (6.6%) are at risk.
- Of the 941 conservation areas surveyed in London, 60 (6.4%) are at risk.



WILLES POOL, KENTISH TOWN BATHS, CAMDEN

Restored at a cost of £25million, the refurbished Willes Pool is the centrepiece of Kentish Town Baths. Originally the men's first class bath, this 33m pool sits beneath a dramatic top-lit barrel vaulted roof.

© Roberts Limbrick Ltd

IN LONDON:

60% OF BUILDINGS AT RISK ON THE 1999 REGISTER HAVE BEEN SAVED 23% OF SCHEDULED MONUMENTS ARE AT RISK

970/0 OF OUR LOCAL AUTHORITIES HAVE SURVEYED THEIR CONSERVATION AREAS 693K
IN GRANTS WAS
OFFERED
TO SITES ON THE
2010 REGISTER

INDUSTRIAL HERITAGE

Britain was the world's first industrial nation and has a wealth of industrial heritage but many industrial sites have been lost or are at risk due to functional redundancy. Our survey has shown that the percentage of listed industrial buildings at risk is three times greater than the national average for listed buildings at risk.

The conservation of industrial sites can pose considerable challenges. However, industrial sites often have great potential for re-use. Our research shows that the best way of saving industrial buildings is, where possible, to find an adaptive new use. We know this isn't easy, and is not always possible, but we hope those who own or are thinking of developing an industrial building will find our new web pages an invaluable source of information.

Voluntary groups and owners have saved a number of key industrial sites, often sites which contain working machinery. However, research has shown that many of these groups need support to encourage more and younger members to achieve the rescue of the site.

Building preservation trusts can provide the answer for industrial buildings where there is no apparent commercial solution by repairing the site and then selling it, or retaining and letting the space.

What we know

- 4% of listed buildings and scheduled monuments are industrial
- Nationally there are proportionally more grade II* industrial listed buildings than grade II (4.6% compared to 4.4%)
- 10.6% of industrial grade I and II* listed buildings are at risk, making industrial buildings over three times more likely to be at risk than the national average for grade I and II* listed buildings
- The average estimated conservation deficit (cost of repair in excess of the end value) of industrial buildings at risk is twice that of non-industrial buildings at risk
- About 10% of industrial buildings at risk are economic to repair, compared to 13% of non-industrial buildings at risk
- Approximately 40% of industrial buildings at risk are capable of beneficial use, compared to 44% of non-industrial buildings at risk
- 10.9% of industrial scheduled monument are at risk, making industrial scheduled monuments less likely to be at risk than the national average for scheduled monuments
- 3% of conservation areas were designated because of their industrial significance
- Industrial conservation areas in the North West and West Midlands are over twice are likely to be at risk than the national average
- In the last 10 years, English Heritage has offered grants totalling £25m to industrial sites



GRANARY COMPLEX, KINGS CROSS

Works are nearing completion to transform this grade II listed building into a new campus for Central Saint Martins College of Art and Design. The Granary will contain the library and reception, whilst the linked rear transit sheds have been redeveloped to accommodate the theatre and study spaces.

© John Sturrock and Argent

What are we doing?

- Providing new guidance for owners on maintaining vacant historic buildings.
- Publishing a developers' portal on the English Heritage website where advice for all types of heritage asset including industrial sites can be found.
- Funding a new Industrial Heritage Support Officer, who will build capacity for industrial museums.
- Publishing an industrial themed issue of Conservation Bulletin in October 2011.
- Supporting a new Architectural Heritage Fund grant scheme which aims to encourage local groups to take on industrial buildings.
- Publishing an updated Stopping the Rot: a guide to enforcement action to save historic buildings.
- Using the National Heritage Protection Programme (2011-2015) to shape an industrial designation programme.

If you are a developer, member of a building preservation trust, work in a local authority, own a visitor attraction or have an interest in England's industrial heritage, visit our website for more information:

www.english-heritage.org.uk/industrial-heritage-at-risk


PRIORITY SITES

- Abney Park Cemetery, Hackney
- Crossways, 134 Church Road, Hanwell, Ealing
- Finsbury Health Centre, Pine Street, Islington
- Gunnersbury Park (including the west and east stables, the large and small mansions and other structures), Hounslow
- Hanwell flight of locks and brick boundary wall of St Bernard's Hospital, Ealing
- Kensal Green (All Souls) Cemetery (including the Anglican Chapel, a number of monuments and other structures), Kensington and Chelsea
- Manor Farm barn, High Street, Harmondsworth, Hillingdon
- Tide Mill (known as the House Mill), Three Mill Lane, Newham
- Whitechapel High Street and Stepney Green Conservation Areas (High Street 2012), Tower Hamlets
- 94 Piccadilly, Westminster

COVER IMAGE:

Tide Mill (known as the House Mill), Tower Hamlets. Building at Risk and Priority Site

CONTACT: Cindy Molenaar, Business Manager, English Heritage London, I Waterhouse Square, 138-142 Holborn, London ECIN 2ST. Telephone: 0207 973 3720 Fax: 0207 973 3792 Email: cindy.molenaar@english-heritage.org.uk



For more information on Heritage at Risk visit www.english-heritage.org.uk/risk



If you would like this document in a different format, please contact our customer services department on telephone: 0870 333 1181 fax: 01793 414926 textphone: 01793 414878 email: customers@english-heritage.org.uk



Reducing the risks

English Heritage is committed to securing a year-on-year reduction in the number of heritage sites at risk as part of our national plan for the protection of England's historic environment (National Heritage Protection Plan 2011-2015). This will be challenging given the number of assets now on the Register and the different kinds of risk they face. Each asset type and individual case will require its own approach and solution.

There are, however, some general approaches that are relevant to all assets at risk. Resolving cases requires working in close partnership with owners, local planning authorities and other relevant organisations and partners. Advice and understanding are essential. Historic Environment Records, maintained by local authorities, are repositories of information on local historic assets. They underpin the work of local authority historic environment services and can help improve the protection, conservation and management of heritage assets.

Maintenance of heritage assets is essential if they are not to become at risk, and to prevent those that are already at risk from decaying further and thereby escalating the cost of their repair and consolidation. Buildings, for instance, decay rapidly when left empty. Avoiding vacancy through short-term lets or schemes that provide protection through residential occupation are low-cost ways of maintaining buildings until permanent solutions can be found. English Heritage has published guidance for owners on options for maintaining vacant buildings (Vacant Historic Buildings: An Owner's Guide to Temporary Uses, Maintenance and Mothballing).

English Heritage provides on-line advice and guidance to local authorities, owners and managers of sites through the Historic Environment Local Management (HELM) website www.helm.org.uk.

LISTED BUILDINGS Buildings at risk

English Heritage's role in securing the future of buildings at risk is primarily to provide practical advice, guidance and resources to local authorities, owners and developers. Our involvement in cases is determined by the importance of the building and the complexity of the issues. We can help with analysis of the issues, investigation of the feasibility of options and brokering solutions. Although buildings at risk will continue to be a priority for English Heritage repair grants, grant aid is limited in relation to demand. Grants from other public sources, notably the Heritage Lottery Fund, continue to be essential in helping secure the future of buildings at risk.

In very exceptional cases, English Heritage may acquire and repair a particularly important building at risk, where it is clear that the scale and complexity of problems are such that direct involvement is the best way of securing the building's long-term future.

Local authorities have a primary role in protecting the historic environment. The creation of a local heritage at risk register is the first step in tackling neglected buildings in order to assess and monitor the scale of the problem and prioritise resources and action. Local authorities can also take action to secure the preservation of historic buildings through the use of statutory notices. Some local authorities have a successful track record, but generally these powers are under-used. It is essential that local authorities make best use of their powers to secure buildings at risk, to 'stop the rot' and prevent the costs escalating beyond the point where it is economic to repair. For this reason, English Heritage has published revised guidance (Stopping the Rot) for local planning authorities on taking action to save historic buildings.

To help local authorities make more frequent and timely use of their statutory powers, English Heritage runs grant schemes to underwrite a significant proportion of the irrecoverable costs involved in serving Urgent Works Notices and Repairs Notices.

Building preservation trusts can be the key to saving many buildings at risk. Some trusts cover geographical areas; others specialise in particular types of building or are formed to save just one building. Determined individuals and trusts have saved numerous buildings at risk, working in partnership with other organisations such as local and national amenity societies, including SAVE Britain's Heritage, the Society for the Protection of Ancient Buildings, the Georgian Group, The Victorian Society and the Twentieth Century Society.

Places of worship at risk

Regular maintenance helps to keep buildings and places of worship in good condition but those that are in poor or very bad condition need help to minimise the risks to both the structure and the contents. Keeping drains and gutters clear so that water is taken away from the building efficiently is the most important thing that congregations can do as it stops small problems in the building fabric developing into unnecessary crises. English Heritage supports the Society for the Protection of Ancient Buildings's Faith in Maintenance scheme, giving volunteers practical local training and on-going support. It also encourages the establishment of gutter-clearance projects, enabling congregations to get good quality work done at reasonable prices by reputable contractors.

Where major structural repairs are required, the Repair Grants for Places of Worship scheme helps under resourced buildings in urgent need. The Listed Places of Worship scheme is another source of funding for repairs and maintenance that is available more widely, while local and national charities can offer small grants.

Many congregations wish to adapt and change their places of worship to encourage wider community use alongside worship and faith-focussed events. English Heritage supports the efforts of congregations to keep their places of worship in use wherever possible and welcomes proposals for appropriate new facilities such as kitchens and toilets that are sensitive to the building's special character.

English Heritage is aware of the need for practical, hands-on help to be given to individual congregations and is working with partner organisations to enable this. Support Officers are employed by local denominational groups but part-funded by English Heritage. They give advice and encouragement to congregations so that they can achieve repair projects, develop necessary new facilities or re-engage with the wider community, depending on local circumstances and needs.

SCHEDULED MONUMENTS

The continuing success in reducing the number of monuments at risk, even in difficult economic times, demonstrates the value of the dialogue that the initiative has fostered between English Heritage, owners, managers and other partners. More and more owners and managers of scheduled monuments are addressing their long-term care on a regular basis. Over half of all scheduled monuments are now on land subject to an agreement under Natural England's Environmental Stewardship agri-environment scheme, administered on behalf of Defra. Work in the coming years with Defra and Natural England will concentrate upon ensuring that the right options are being used in

the correct way, maximising the conservation benefits whilst at the same time delivering value for money. We will also work closely with the Heritage Lottery Fund to help identify those important monuments deserving of grant aid for major stabilisation or repair work.

Progress is also reliant upon better understanding. As a result, as part of the National Heritage Protection Plan – which sets out English Heritage's commitment to safeguarding heritage up to 2015 – the Conservation of Scheduled Monuments in Cultivation project will be rolled out nationally from 2011 onwards. The project, already successfully trialled amongst farmers in the East Midlands, will address what is still the biggest threat by far to monuments – their gradual degradation and loss through arable cultivation. Some causes of risk are neither so obvious nor dramatic in their effects however. Heritage at risk shows that unmanaged tree, scrub and bracken growth is the most widespread cause of long term damage to both urban and rural monuments, even if the effects are not as visible or immediately destructive as other processes. Further work will therefore be needed to better understand how these effects can be minimised.

In all cases, however – whether for rural or urban monuments – close co-operation with owners and land managers is still key to making further progress in ever more challenging circumstances.

REGISTERED PARKS AND GARDENS

Inclusion on the Register of Historic Parks and Gardens of Special Historic Interest brings no additional statutory controls, but there is a presumption in favour of the conservation of all designated assets in the planning system. The Government's Planning Policy Statement 5 Planning for the Historic Environment (PPS 5) and its supporting Practice Guide helps planning authorities to assess and mitigate the impact of development on our irreplaceable heritage of designed landscapes.

English Heritage can engage only with the proposals for change to the highest graded designed landscapes and where the impact on historic significance is greatest. Our landscape architects can help tailor plans and funding packages for individual landscape features as well as strategies for the whole site. We will continue to tackle the skills crisis facing historic parks and gardens through sector-wide initiatives.

English Heritage encourages the development of conservation management plans for registered historic parks and gardens, especially those in multiple ownership. We are keen for bursars and estate teams to use management plans to help conserve important but fragile landscapes in the care of schools, hospitals, hotels and other institutional owners.

REGISTERED BATTLEFIELDS

As with registered parks and gardens, this designation brings no additional statutory controls, but there is a presumption in favour of conservation of registered battlefields in Planning Policy Statement 5.

English Heritage will continue to work with owners to develop management plans for registered sites and, in appropriate cases, contribute towards the cost of management plans. We will develop positive landscape strategies with owners and partners such as Defra. In some circumstances, we may encourage the conversion from arable to pasture of especially sensitive locations to protect battlefield archaeology from the effects of ploughing and as part of a wider drive to prevent unauthorised or damaging metal-detecting.

English Heritage will also continue to encourage greater access to battlefields and improve their amenity value and visitors' appreciation of the impact these historic events had on our development as a nation.

Local authorities can also invite comments from the Battlefields Trust on planning applications affecting the setting of registered sites.

PROTECTED WRECK SITES

At the strategic level, the major sources of risk to designated wreck sites have been identified. In terms of high-priority sites, practical requirements have also been implemented through conservation management plans.

Risks to protected wreck sites can often be reduced through education, provision of marker buoys, or planning policies that take full account of their national importance. However, some sites require significant resources to stabilise their condition or to carry out detailed archaeological assessments of their conservation requirements. Although English Heritage has statutory power to allocate funds to promote the preservation and maintenance of protected wreck sites, its financial resources can solve only a small proportion of the problems.

In spite of the inherent difficulties with caring for this type of site, careful management must be maintained if we are to avoid the loss of wreck sites. It is therefore close co-operation between the owners of protected wreck sites (where known), authorised divers and all organisations charged with care for the marine and coastal environment, that will make the real difference to their long-term survival.

Practical advice on the management of historic wreck sites, whether at the coast-edge or under water, is available from English Heritage (maritime@english-heritage.org.uk) and from www.helm.org.uk

CONSERVATION AREAS

The risks to conservation areas are difficult to address as they cover large areas of land: they include the spaces between buildings and trees as well as buildings and structures and therefore involve many different owners. Looking after them is a responsibility shared by those of us who own homes and businesses in them and those of us whose job it is to manage the spaces between the buildings or make decisions about their future.

The conservation area survey provides us with an understanding of what is particularly affecting the character and appearance of our conservation areas: what is working well or what is putting them at risk. Strong planning policies, guidance and a clear management strategy for individual conservation areas are critical in managing change in these areas. This is difficult at a time when local authorities across the country are reducing the number of staff managing changes in conservation areas. There are, of course, opportunities for members of the local community to engage, either individually or through groups such as civic societies or conservation area advisory committees which are proven to help achieve positive action.

Armed with the information provided by the surveys, we, local authorities and other partners will have the evidence to direct resources much more accurately towards those conservation areas at greatest risk. We will also want to target those with the greatest potential to improve the quality of life and economic prospects of people in the villages, towns and cities of which they are such crucially important components.

Publications and guidance

English Heritage has produced the following publications relating to heritage at risk, including:

Buildings at Risk: a New Strategy (1998)

Caring for Places of Worship 2010 (2010) — a report on the condition of England's listed places of worship and the needs of the congregations

Heritage at Risk 2010

Heritage at Risk: Conservation Areas (2009)

Heritage at Risk 2011 — national report and summaries for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, Yorkshire and the Humber

Heritage at Risk Register 2011 — detailed listings for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, Yorkshire and the Humber can be downloaded from our website or viewed as an interactive database: www.english-heritage.org.uk/risk

Monuments at Risk (2008) – summary of scheduled monuments at risk for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, Yorkshire and the Humber

Protected Wreck Sites at Risk: A Risk Management Handbook (2007)

Saving London: 20 Years of Heritage at Risk in the Capital (2010)

Stopping the Rot: A Guide to Saving Historic Buildings Through Enforcement Action (2011)

The Monuments at Risk initiative 2003–08 (2010)

Vacant Historic Buildings: An Owner's Guide to Temporary Uses, Maintenance and Mothballing (2011)

HERITAGE AT RISK ON THE WEB

To find out more about the Heritage at Risk programme visit www.english-heritage.org.uk/risk where you will find an interactive database providing detailed information on all heritage sites at risk nationally.

For further information about the different classes of designated heritage assets, including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites visit the Heritage Protection section of our website www.english-heritage.org.uk/heritageprotection.

Details of all nationally designated historic places in England are now available in one place on the National Heritage List for England online database: http://list.english-heritage.org.uk

CONSERVATION POLICIES AND GUIDANCE

The following publications are among the numerous helpful guidance documents now available on our website: www.english-heritage.org.uk/publications or www.english-heritage.org.uk/helm

Caring for Places of Worship (2010) — a practical booklet for everyone involved in caring for England's listed places of worship

Constructive Conservation in Practice (2008)

Conservation Principles, Policies and Guidance for the Sustainable Management of the Historic Environment (2008)

Creativity and Care: New Works in English Cathedrals (2009)

Enabling Development and the Conservation of Significant Places (2008)

Farming the Historic Landscape: Caring for Archaeological sites on Arable Land (2004)

Farming the Historic Landscape: Caring for Archaeological Sites in Grassland (2004)

Guidance on the Management of Conservation Areas (2006)

Guidance on Conservation Area Appraisals (2006)

Guidance Notes and Application Forms for Grants to Local Authorities:

- Grants to Local Authorities to Underwrite Urgent Works Notices (1998)
- Acquisition Grants to Local Authorities to Underwrite Repairs Notices (1998)
- Grants for Historic Buildings, Monuments and Designed Landscapes (2004)

Heritage at Risk: Conservation Areas (2009) – guidance for local authorities

Managing Local Authority Heritage Assets: Some Guiding Principles for Decision Makers (2003)

New Uses for Former Places of Worship (2010)

Options for the Disposal of Redundant Churches and Other Places of Worship (2010)

Paradise Preserved: An Introduction to the Assessment, Evaluation, Conservation and Management of Historic Cemeteries (2002)

Scheduled Monument Consent: a Guide for Owners and Occupiers (2009)

Shared Interest: Celebrating Investment in the Historic Environment (2006)

The Disposal of Historic Buildings: Guidance Note for Government Departments and Non-Departmental Public Bodies (2010).

Valuing Places: Good Practice in Conservation Areas (2011)

If you would like further information about any of these publications, please contact:

English Heritage Customer Services Department PO Box 569, Swindon SN2 2YP Telephone: 0870 333 1181

Fax: 01793 414926

Email: customers@english-heritage.org.uk

THE REGISTER

Content and criteria

DESIGNATION

All the historic environment matters but there are some elements which warrant extra protection through the planning system. Since I 882, when the first Act protecting ancient monuments and archaeological remains was passed, government has been developing the designation system. Listing emerged from the post-blitz I 940s Planning Acts, and is now applied to about half a million buildings ranging from palaces to street lamps. Almost 20,000 archaeological sites are scheduled, which introduces tight management controls. Some I,610 designed landscapes are registered, as are 43 battlefields, and 46 wreck sites are protected.

English Heritage, as the government's expert adviser, is responsible for making recommendations — but it is still the Secretary of State at the Department for Culture Media and Sport who makes the decisions on whether a site is designated. Understanding and appreciation develop constantly, which makes keeping the designation base up-to-date a never-ending challenge. While responding to threat-driven cases, we also seek to work strategically. Recent developments have seen a greater striving for openness and transparency in the process of designating a site, and better communication of what makes something special.

Conservation areas are designated locally by local planning authorities. They are areas of special architectural or historic interest the character or appearance of which it is desirable to preserve or enhance.

LISTED BUILDINGS

Definition

A listed building is a building (or structure) that has been designated as being of 'special architectural or historic interest'. The older and rarer a building is, the more likely it is to be listed. Buildings less than 30 years old are listed only if they are of outstanding quality and under threat.

Listed buildings are graded I, II* and II. Grade I and II* are particularly important buildings of outstanding interest; together they amount to 8% of all listed buildings. The remaining 92% are of special interest and are listed grade II.

Entries on the statutory list of buildings of special architectural or historic interest may comprise a number of separate buildings. Formal residential terraces are the most obvious example. Entries on this Register reflect how buildings are grouped and recorded on the statutory list.

Structures can occasionally be both listed as buildings and scheduled as monuments.

Criteria for inclusion on this Register

Buildings (not in use as a public place of worship) considered for inclusion on this Register must be listed grade I or II*, (or grade II in London) or be a structural scheduled monument. Buildings are assessed for inclusion on the basis of condition and, where applicable, occupancy (or use). The condition of buildings on the Register ranges from 'very bad' to 'poor', 'fair' and (occasionally) 'good'. The Register also includes buildings that are vulnerable to becoming at risk because they are empty, under-used or face redundancy without a new use to secure their future.

Occupancy (or use) is noted as 'vacant', 'part occupied', 'occupied', or occasionally, 'unknown'; for many structural monuments, occupancy is not applicable.

Assessing vulnerability in the case of a building in fair condition necessarily involves judgement and discretion. A few buildings on the Register are in good condition, having been repaired or mothballed, but a new use or owner is still to be secured.

Buildings are removed from the Register when they are fully repaired/consolidated, their future secured, and where appropriate, occupied or in use.

Listed places of worship

Places of worship are the largest single group of non-domestic historic buildings still in use primarily for the purpose for which they were built. Their complex development over centuries is a testament to the changes in social, political and liturgical attitudes over time. This reflects the developing mission of congregations and means that they protect a wide range of fittings and furnishings of national and international, importance. Their architectural, archaeological, aesthetic and historic significance is outstanding but so too is their value as the record of the endeavours and experiences of individuals and communities.

To date English Heritage has assessed only a small proportion of the 14,500 listed places of worship so the number identified so far as 'at risk' and included on this year's Register is small. In the coming years an increasing number of places of worship will be assessed to identify those that are at risk. Future registers will provide stronger evidence and build up our understanding of the challenges.

Criteria for inclusion on this Register

Places of worship considered for inclusion on this Register must be listed grade I, II* or II and be used as a public place of worship at least six times a year.

Places of worship are assessed on the basis of condition only. If the place of worship is in 'very bad' or 'poor' condition it is added to the Register Places of worship previously included on the Register may be in any condition category.

Once on the Register, all places of worship can move through the condition categories (e.g. from very bad to poor, to fair, even good) as repairs are implemented and the condition improves, until they are fully repaired and can be removed from the Register.

Priority for action

Once a building is identified as at risk or vulnerable and included on the Register, priority for action is assessed on a scale of A to F, where 'A' is the highest priority for a building which is deteriorating rapidly with no solution to secure its future, and 'F' is the lowest priority where a repair scheme is in progress and an end use has been secured.

SCHEDULED MONUMENTS Definition

Scheduled monuments include archaeological sites and landscapes, and 19,731 examples have been designated because of their national importance. Scheduled monuments are not graded, and most have limited potential for beneficial use. They cover human activity from the prehistoric era, such as burial mounds, to 20th century military and industrial remains. For the millennia before written history, archaeology is the only testament to innumerable generations of people of whom there is no other record.

The later 20th century saw unprecedented changes to the landscape. As a result, types of historic site that once were commonplace began to become rare. Those that survive often represent just small islands of what once characterised broad sweeps of our towns and countryside. Although protected by law, scheduled monuments are still at risk from a wide range of processes. In particular, they can frequently be exposed to intense pressures beyond the reach of the planning system. These include damage from cultivation, forestry and — often most seriously of all — wholly natural processes such as scrub growth, animal burrowing and erosion.

Criteria for inclusion on this Register

Scheduled monuments included on this Register have been identified as being at risk because of their condition and vulnerability, the trend in their condition, and their likely future vulnerability. A site's condition is expressed in terms of the scale and severity of adverse effects on it, ranging from those with 'extensive significant problems' to others that have only 'minor localised problems'.

Monuments are removed from the Register once sufficient progress has been made to address identified issues, demonstrating a significant reduction in the level of risk.

REGISTERED PARKS AND GARDENS Definition

There are 1,610 designed landscapes on the current English Heritage Register of Historic Parks and Gardens of Special Historic Interest. These registered landscapes are graded I, II* or II, and include private gardens, public parks and other green spaces, country estates and cemeteries. They are valued for their design, diversity and historical importance and in contrast to the number of listed buildings and scheduled monuments, registered parks and gardens is a very small group of assets.

Inclusion on the English Heritage Register of Historic Parks and Gardens brings no additional statutory controls, but there is a presumption in favour of conservation of the designated site. Local authorities are required to consult English Heritage on applications affecting sites registered as grade I or II* and the Garden History Society on sites of all grades.

Criteria for inclusion on this Register

The identification of registered parks and gardens at risk begins with an appraisal of the condition and vulnerability of each registered landscape. Steps being taken by owners to address problems are also taken into consideration.

Landscapes assessed as being at risk are typically affected by development and neglect. They have frequently been altered by development or are faced with major change. The original function of these landscapes has often changed; and divided ownership often results in the loss of the cohesive conservation of the historic designs.

Landscapes are removed from the Register once plans are put in place to address issues and positive progress is being made.

REGISTERED BATTLEFIELDS Definition

English Heritage's Register of Historic Battlefields has identified 43 nationally significant sites ranging in date from 991 to 1685. These are places where people risked their lives fighting for a cause and where history was made. The outcome of these battles was influenced by where they were fought and traces of the events will have been left across the landscape. Battlefields are cherished for many reasons, as a commemoration of the event and those who died, as a resource for understanding the course of the battle, and for the light they can shed on the times in which the battle was fought. They are vulnerable to insensitive development and to poorly managed investigation such as large-scale metal-detecting. While this designation introduces no additional statutory controls, one of its primary objectives is to encourage policies and other mechanisms that ensure that change and development affecting battlefields is sensitive and appropriate.

Criteria for inclusion on this Register

Battlefields deemed to be at risk of loss of historic significance are included on this Register.

The identified risks and threats come from development pressure – for example, because they lie on urban fringes or are subject to development pressures within the site; arable cultivation, and unregulated metal-detecting. One major impact or a combination of several factors can be enough to raise the risk at a particular site.

Battlefields are removed from the Register when either actual damaging activities are reversed or managed, or threats recede due to effective management planning.

PROTECTED WRECK SITES Definition

England's 46 protected wreck sites represent a tiny proportion of the 32,476 pre-1945 wrecks and recorded casualties that are known to lie in the territorial sea. Wreck sites can be of importance for different reasons: the distinctive design or construction of a ship, the story it can tell about its past, its association with notable people or events, its cargo, flora and fauna or its role as a focus for the local community. The Protection of Wrecks Act 1973 empowers the appropriate Secretary of State to designate a restricted area around a vessel to protect it or its contents from unauthorised interference.

Local authorities are able to react to foreshore infrastructure projects through the planning process, thereby securing the preservation of important remains in this intertidal zone.

Criteria for inclusion on this Register

English Heritage has audited all designated wreck sites to identify those most at risk based on their current condition, vulnerability and the way they are being managed. Wrecks are vulnerable to both environmental and human impacts. Risks that contribute to the inclusion on the Register range from unauthorised access to erosion and fishing damage.

The monitoring process ensures that the significance of the site is identified and maintained.

In spite of the inherent difficulties in caring for this type of site, careful management must be maintained.

Wrecks are removed from the Register once an appropriate management and monitoring regime is operational.

CONSERVATION AREAS Definition

Conservation areas are designated by local authorities and are areas of special architectural or historic interest the character or appearance of which it is desirable to preserve or enhance. For more than 40 years conservation areas have proved a highly effective mechanism for managing change on an area-wide basis. There are currently some 9,300 conservation areas in England including town and city centres, suburbs, industrial areas, rural landscapes, cemeteries and residential areas. They form the historic backcloth to national and local life and are a crucial component of local identity and community cohesion.

Criteria for inclusion on this Register

English Heritage has asked every local authority in England to complete (and update as appropriate) a survey of its conservation areas, highlighting current condition, threats and trends, identifying those that are deteriorating, or are in very bad or poor condition and are not expected to change significantly in the next three years, as being defined as at risk.

The methodology for assessing conservation areas at risk has been refined since the first survey in 2008/2009. The information collated provides a detailed assessment of each conservation area and an overall category for condition, vulnerability and trend is included for each conservation area on this Register. Conservation areas identified as at risk in 2009, but not reassessed since using the revised methodology, are included on the Register but with more limited information.

Conservation areas are removed from the Register once plans have been put in place to address the issues that led to the conservation area being at risk, and once positive progress is being made.

Key to the entries

This register includes the following heritage assets at risk:

- grade I, II* and II listed buildings and structural scheduled monuments
- grade I, II* and II listed places of worship
- scheduled monuments
- registered parks and gardens
- registered battlefields (where applicable)
- protected wreck sites (where applicable)
- conservation areas

ORDER

Entries are ordered alphabetically by London Borough. Within each Borough the assets are grouped in the following order:

- · listed buildings and structural monuments
- places of worship
- registered parks and gardens
- scheduled monuments
- conservation areas

Within each asset type, sites are ordered alphabetically by locality, street/site name.

DESIGNATION

The principal designation is noted for each entry, and includes:

- Listed Building (LB) grade I, II* or II
- Listed Place of Worship grade I, II* or II
- Scheduled Monument (SM)
- Registered Park and Garden (RPG) grade I, II* or II
- Conservation Area (CA)

Other designations that apply to buildings at risk and registered parks and gardens at risk, including their location within a World Heritage Site (WHS), are also noted where applicable.

The National Heritage List for England reference number is noted for scheduled monuments.

CONDITION

For buildings (including places of worship) at risk, condition is graded as: 'very bad', 'poor', 'fair' and 'good'.

For sites that cover areas (scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites) one overall condition category is recorded. The category may relate only to the part of the site or monument that is at risk and not the whole site:

- extensive significant problems
- generally unsatisfactory with major localised problems
- generally satisfactory but with significant localised problems
- generally satisfactory but with minor localised problems
- optimal
- unknown (is noted for a number of scheduled monuments that are below-ground and where their condition cannot be established).

For conservation areas, condition is categorised as: 'very bad', 'poor', 'fair' and 'optimal'.

OCCUPANCY / USE

For buildings (excluding places of worship) that can be occupied or have a use, the main vulnerability is vacancy, or under-use. Occupancy (or use) is noted as follows:

- vacant
- · part occupied
- occupied
- unknown
- not applicable

VULNERABILITY

Principal vulnerability is noted for scheduled monuments and may relate only to the part of the monument which is at risk, and include:

- animal burrowing
- arable ploughing
- coastal erosion
- collapse
- deterioration in need of management
- scrub / tree growth
- visitor erosion.

For registered parks and gardens, registered battlefields, protected wreck sites and conservation areas, vulnerability is noted as high, medium or low.

PRIORITY

For buildings at risk, the following priority categories are used as an indication of trend and as a means of prioritising action:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- **B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- **D** Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- **F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

If the priority category has changed since the 2010 Register, the previous category is given in brackets.

TREND

Trend for scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites may relate only to the part of the site that is at risk and is categorised as:

- declining
- stable
- improving
- unknown

For conservation areas trend is categorised as:

- deteriorating
- deteriorating significantly
- no significant change
- improving
- · improving significantly
- unknown

OWNERSHIP

A principal ownership category is given for each entry, although many scheduled monuments, registered parks and gardens, and registered battlefields are in divided ownership. For registered parks and gardens, single or multiple ownership is noted.

CONTACT

This is the member of the English Heritage regional team who acts as a first point of contact for the case, and to whom enquiries should be addressed.

For conservation areas and grade II listed buildings, the contact is the conservation/planning officer at the relevant local planning authority (indicated by 'LPA' on the Register).

We are not in any sense agents for the owners of the sites included, but we will endeavour to put people in touch with them where appropriate.

ABBREVIATIONS

CA Conservation Area
EH English Heritage
HLF Heritage Lottery Fund
LA/LPA Local Planning Authority

LB/LBs Listed Building/s NP National Park

RPG Registered Park and Garden
SM/SMs Scheduled Monument/s
UA Unitary Authority
WHS World Heritage Site

London heritage assets at risk

	Buildings at risk	Places of worship at risk	Scheduled monuments at risk	Registered parks and gardens at risk	Registered battlefields at risk	Protected wreck sites at risk	Conservation areas at risk
LONDON BOROUGH							
Barking and Dagenham	4	I	I	0	0	0	1
Barnet	12	0	- 1	0	0	0	1
Bexley	2	0	0	I	0	0	0
Brent	5	0	0	0	0	0	2
Bromley	20	0	3	I	0	0	0
Camden	44	3	0	I	0	0	0
City of London	2	2	4	0	0	0	0
Croydon	7	0	3	0	0	0	1
Ealing	9	2	4	0	0	0	10
Enfield	11	I	I	2	0	0	2
Greenwich	24	1	I	0	0	0	0
Hackney	27	3	0	I	0	0	2
Hammersmith and Fulham	9	I	0	0	0	0	1
Haringey	17	1	0	0	0	0	3
Harrow	7	0	5	I	0	0	0
Havering	12	0	I	0	0	0	1
Hillingdon	26	0	2	0	0	0	9
Hounslow	21	0	3	I	0	0	2
Islington	16	2	0	0	0	0	7
Kensington and Chelsea	10	1	0	2	0	0	1
Kingston upon Thames	3	0	I	0	0	0	0
Lambeth	26	2	0	2	0	0	0
Lewisham	8	0	0	0	0	0	1
Merton	8	0	2	0	0	0	1
Newham	21	0	0	0	0	0	2
Redbridge	3	0	0	I	0	0	2
Richmond upon Thames	8	0	0	0	0	0	1
Southwark	29	1	2	I	0	0	1
Sutton	3	2	0	0	0	0	0
Tower Hamlets	29	5	1	0	0	0	9
Waltham Forest	9	0	0	0	0	0	0
Wandsworth	16	0	0	0	0	0	0
Westminster, City of	29	I	0	0	0	0	0
TOTAL	477	29	35	14	0	0	60

GREATER LONDON

BARKING AND DAGENHAM



SITE NAME The Marks Stones, Whalebone Lane North, Chadwell Heath

DESIGNATION: Listed Building Grade II

Very bad CONDITION: N/A OCCUPANCY: D (C) PRIORITY:

OWNER TYPE: Crown

Boundary marker of the Liberty of Havering-atte-Bower, originally set up in 1642. Two stones: one 12 inches high inscribed 'Marks Stone', one 30 inches high inscribed 'Marks Stone Sept 1642'. One stone is broken and is in safekeeping, the other remains in its original position. To be repaired by quarry operators as part of planning condition for adjacent quarry.

Contact: Francesca Cliff (LPA) 020 8227 3910



The Warren Stone, SITE NAME: Whalebone Lane North, Chadwell Heath

DESIGNATION: Listed Building Grade II

Poor CONDITION: OCCUPANCY: N/A D(C)Crown

OWNER TYPE:

Boundary stone erected in 1642. The stone marked the boundary of Hainault Forest, along with the Marks Stones and the Forest Bounds Stone. The stone is in storage at Warren Farm during ongoing quarrying operations. The intention is to reinstate the stone in its original position when the quarrying is finished. To be reinstated by quarry operators as part of planning condition.

Contact: Francesca Cliff (LPA) 020 8227 3910



Chadwell Heath Anti-Aircraft Gun Site, SITE NAME: Whalebone Lane North (off), Chadwell Heath

DESIGNATION: Listed Building Grade II, CA

Poor OCCUPANCY: N/A C (C) PRIORITY: OWNERTYPE: Crown The substantial remains of a World War II Anti-Aircraft Battery with pits for eight guns in two groups of four and associated structures. The buildings are subject to vandalism and are in an isolated spot, surrounded by a quarry, increasing their chances of further deterioration.

Contact: Francesca Cliff (LPA) 020 8227 3910



The Old Vicarage, SITE NAME Crown Street,

Dagenham

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION:

Part occupied OCCUPANCY:

C (C) Private OWNER TYPE:

House, dated 1665, remodelled in C19. The building is currently part occupied and at risk of vandalism. Interest has been expressed in developing the site and revised proposals are being discussed with the Local Authority.

Contact: Francesca Cliff (LPA) 020 8227 3910



Church of St Peter and St Paul. SITE NAME: Crown Street, Dagenham

DESIGNATION: Listed Place of Worship Grade II*, CA

CONDITION:

C (New entry) PRIORITY:

OWNER TYPE: Religious organisation

Medieval origins, rebuilt with red brick gothic tower 1800. Nave part ashlar and random rubble, and rendered chancel. Slipped and missing tiles on chancel and blocked rainwater hoppers.

Contact: Donald Wahlberg 020 7973 3786

0	1	
•		

SITE NAME

Barking Abbey, Barking and Dagenham

DESIGNATION:	Scheduled Monument (No. 1003581)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Jane Sidell 020 7973 3738

Chadwell Heath Anti-Aircraft Gun Site, Marks Gate

DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Francesca Cliff (LPA) 020 8227 3910	NEW ENTRY?:	No

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.


NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS

BARNET



SITE NAME: Monuments at St Mary's Churchyard, Church End,

Hendon NW4

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION: N/A OCCUPANCY: C(C)PRIORITY:

OWNER TYPE: Local authority Churchyard to grade II* listed C13 church. Widespread disrepair of tombs and monuments, including the tomb of Henry Joynes, the builder of Blenheim Palace.

Contact: Jonathan Hardy (LPA) 020 8359 4655



Colindale Hospital SITE NAME: Administration Block, Colindale Avenue NW9

Listed Building Grade II, CA DESIGNATION:

CONDITION: Vacant OCCUPANCY: F (F) PRIORITY: OWNER TYPE: Company Hospital administration block dated 1899. Baroque style. Consent granted for conversion of the building and site to housing. Works have commenced.

Contact: Jonathan Hardy (LPA) 020 8359 4655



SITE NAME: The Bothy, East End Road, Finchley N3

DESIGNATION: Listed Building Grade II, CA

Fair CONDITION: Vacant C (C) PRIORITY Trust OWNER TYPE:

Garden compound in the grounds of Avenue House, comprising summer house, living accommodation and storage. Completed in 1882. Building is vacant and options for future use are being considered by the Trust.

Contact: Jonathan Hardy (LPA) 020 8359 4655



The Water Tower, SITE NAME: East End Road,

Finchley N3

DESIGNATION: Listed Building Grade II, CA Very bad CONDITION:

OCCUPANCY: Vacant A (A) PRIORITY-OWNER TYPE: Trust

Water tower of massed concrete. Overgrown and vacant, no proposals.



College Farm - main building, SITE NAME: Fitzalan Road N3

DESIGNATION: Listed Building Grade II, CA Fair CONDITION:

Occupied C (C) Trust OWNER TYPE:

OWNER TYPE:

Stables, teashop and dairy, built 1883 to the design of Frederick Chancellor in a picturesque style. Model dairy farm of the Express Dairy Company. Acquired by the College Farm Trust who are developing plans for the site. Emergency repairs undertaken.

Contact: Jonathan Hardy (LPA) 020 8359 4655

Contact: Jonathan Hardy (LPA) 020 8359 4655



College Farm Dairy, SITE NAME: Fitzalan Road N3

Trust

DESIGNATION: Listed Building Grade II, CA CONDITION: Fair **Vacant** OCCUPANCY: PRIORITY C (C)

Dairy built 1883 to the design of Frederick Chancellor, with ornate timber lantern roof and decorative tilework to interior. Condition of building is deteriorating. See also entry for College Farm main building.

Contact: Jonathan Hardy (LPA) 020 8359 4655

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS CA LB/LBs LPA NP RPG SM/SMs UA WHS



Silo, SITE NAME:

Fitzalan Road, College Farm N3

DESIGNATION: Listed Building Grade II, CA

Fair CONDITION: N/A OCCUPANCY: C (C) Silo built 1883 to the design of Frederick Chancellor as part of the Express Dairy Company's pioneering model farm. Condition of building is deteriorating. See entry for College Farm main building.

Contact: Jonathan Hardy (LPA) 020 8359 4655



Garden House. SITE NAME: Friern Barnet Road. Former Friern Hospital N12

DESIGNATION: Listed Building Grade II

Trust

Poor CONDITION: Vacant A (New entry) PRIORITY:

OWNERTYPE: Private

Octagonal Garden House with arcaded veranda and seated area. Slated roof. Constructed of yellow stock bricks, I 850. The roof is in poor condition along with the arcade ceiling. The building is infested with pigeons and has no established sustainable use. Building also known as the Well House or Pump House.

Contact: Jonathan Hardy (LPA) 020 8359 4655



Monument to Major John Cartwright, SITE NAME: St Mary at Finchley Churchyard, Hendon Lane N3

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION: N/A OCCUPANCY: PRIORITY: A(A)

OWNERTYPE: Local authority

Monument erected in 1835 to Major John Cartwright by public subscription. Yellow oolitic limestone. Square tapering obelisk with armorial and portrait roundels. Monument dismantled due to dangerous condition. Restoration under discussion.

Contact: Jonathan Hardy (LPA) 020 8359 4655



Monuments at St Mary's Churchyard, SITE NAME:

Hendon Lane, Finchley N3

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION: N/A OCCUPANCY: C (C) PRIORITY-

Local authority OWNER TYPE:

Churchyard to grade II* listed C15 church. Number of tombs and monuments in disrepair including the grade II listed Cartwright memorial see separate entry.

Contact: Jonathan Hardy (LPA) 020 8359 4655



Access gates to Hadley Common, SITE NAME: The Crescent,

Monken Hadley EN5

DESIGNATION: Listed Building Grade II, CA

CONDITION: N/A OCCUPANCY: F(D) PRIORITY-Trust OWNER TYPE:

Two timber gates at east and west ends of The Crescent. Five bar gate divided into three parts vertically. Octagonal piers with caps and decorative ironwork. Timber in poor condition. Gates are currently under repair with partnership funding from English Heritage and the Heritage of London Trust.

Contact: Jonathan Hardy (LPA) 020 8359 4655



SITE NAME: Physic Well, Well Approach EN5

DESIGNATION: Listed Building Grade II

Poor CONDITION: N/A PRIORITY: C(C)

OWNERTYPE: Local authority

Timber framed cruciform cover to well circa 1937. Beneath is the original C17 barrel-vaulted brick well chamber. Once a fashionable rendezvous for Londoners for the medicinal qualities of the mineral waters. Proposals for refurbishment being discussed.

Contact: Jonathan Hardy (LPA) 020 8359 4655

SITE NAME

Brockley Hill Romano-British pottery and settlement, Barnet

Scheduled Monument (No. 1018006) Extensive significant problems DESIGNATION: CONDITION: Arable ploughing Unknown PRINCIPAL VULNERABILITY: TREND Jane Sidell 020 7973 3738 Private OWNER TYPE: CONTACT:

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented

NOTE:

If the priority category has changed since the 2010 register, the previous category given in brackets

ABBREVIATIONS

SITE NAME:	College Farm, Finchley		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	High	TREND:	Improving
CONTACT:	Jonathan Hardy (LPA) 020 8359 4655	NEW ENTRY?:	No

BEXLEY



Crossness Pumping Station, SITE NAME: Belvedere Road

DESIGNATION: Listed Building Grade I, CA

Good CONDITION: Occupied OCCUPANCY: PRIORITY: F (F) OWNER TYPE: Trust

Opened 4 April 1865. Engineer: Joseph Bazalgette. Retains important cast-iron interior fittings and four colossal beam engines by James Watt and Co. Run by volunteers. Heritage Lottery Fund project in progress. Roof repairs with English Heritage grant completed.

Contact: Malcolm Woods 020 7973 3769



Chapel House, SITE NAME: 497 Blackfen Road.

DESIGNATION: Listed Building Grade II Fair CONDITION: Part occupied C (C) PRIORITY: OWNER TYPE: Company

An existing building is thought to have been altered to become an eye-catcher as part of layout of Danson Park, perhaps in 1761 by Lancelot 'Capability' Brown. It was intended to be culminating point of view from the house across the lake; now separated from house by A2 trunk road and modern houses. Some render repairs have been carried out.

Contact: Gordon Fraser (LPA) 020 3045 5789



Lamorbey Park SITE NAME:

DESIGNATION: Registered Park and Garden Grade II, also part in CA, 4 LBs Extensive significant problems CONDITION: VULNERABILITY: High Declining Mixed, multiple owners OWNER TYPE:

An C18 landscape park with early C19 pleasure grounds and C20 gardens. The park was partially converted to a golf course in the early C20 and further subdivided by the construction of three schools. Part of the gardens are managed by Bexley as a public park. The gardens and pleasure grounds are in need of repair, and management of the historic landscape is disjointed due to the separate ownerships.

Contact: Zosia Mellor 020 7973 3473

BRENT



Cambridge Hall, SITE NAME: Cambridge Avenue,

Kilburn NW6

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION:

Part occupied OCCUPANCY:

PRIORITY: C(C)

OWNER TYPE: Housing Association

Built 1863 as St James's Episcopal Chapel. Prefabricated structure of corrugated iron with boarded roof covered in corrugated asbestos. The Hall is within the South Kilburn New Deal for Communities area and is the subject of a conservation study and assessment. The Local Authority is exploring possible uses.

Contact: Mark Smith (LPA) 020 8937 5267



Old Oxgate Farm, Coles Green Road. Cricklewood NW2

DESIGNATION: Listed Building Grade II*

CONDITION: Poor Occupied OCCUPANCY:

C (C) OWNERTYPE: Private

PRIORITY:

C16 and C17 timber-frame building possibly the oldest surviving house in the Borough. Suffering from subsidence to brick plinth and structural failure of beam ends to ground floor due to damp penetration. Local authority are discussing possible options with the owners.

Contact: Richard Parish 020 7973 3717

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



Dollis Hill House, SITE NAME: Dollis Hill Lane,

Gladstone Park NW2

DESIGNATION: Listed Building Grade II

Very bad CONDITION: Vacant OCCUPANCY: B (A) PRIORITY:

Local authority OWNER TYPE:

House of 1825. Temporarily roofed following fire in April 1996. In need of extensive repairs. The Secretary of State has granted permission for the demolition of the building.

Contact: Mark Smith (LPA) 020 8937 5267



Monuments at St Andrew's SITE NAME: Old Churchyard, Old Church Lane, Kingsbury NW2

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION: N/A OCCUPANCY: A(A)PRIORITY:

Religious organisation OWNER TYPE:

Churchyard with a number of good monuments including six listed grade II. Some tombs are collapsing. Extensive tree clearance has opened the churchyard, helping to discourage vandalism. New use for the redundant church should establish a presence on the site to further help discourage vandalism.

Contact: Mark Smith (LPA) 020 8937 5267



St Andrew's Old Church, SITE NAME: Old Church Lane,

Kingsbury NW2

Listed Building Grade I, CA DESIGNATION:

Good CONDITION: Vacant OCCUPANCY: F (F) PRIORITY:

OWNER TYPE: Religious organisation

C12 to C13 redundant church. Repairs completed. To be vested in the Churches Conservation Trust. Confirmation is awaited of future use.

Contact: Richard Parish 020 7973 3717

Harlesden

Conservation Area Poor DESIGNATION: CONDITION: Medium Deteriorating VULNERABILITY: TREND: Mark Smith (LPA) 020 8937 5267 CONTACT: NEW ENTRY? No

Kilburn SITE NAME

Conservation Area DESIGNATION: CONDITION: Poor VULNERABILITY: Deteriorating Mark Smith (LPA) 020 8937 5267 CONTACT: NEW ENTRY?

BROMLEY



The Studio,

28 Beckenham Road. Beckenham

DESIGNATION: Listed Building Grade II

Fair CONDITION: Vacant OCCUPANCY: D (C) PRIORITY:

OWNERTYPE: Local authority

Technical Institute, later arts centre. Built in Dutch style in 1898 for Beckenham Urban District Council. Vacant. Applications for planning and listed building consent have been granted for community use. Work is yet to commence.



Building 10 (Junior Ranks Mess), SITE NAME:

West Camp, Main Road, A233 (east side), Biggin Hill

DESIGNATION: Listed Building Grade II, CA

CONDITION: Poor Vacant OCCUPANCY: C (C) PRIORITY: OWNERTYPE: Private Airmen's Institute and recreation centre, with dining room. Circa 1926 design, built 1930. Vacant since Royal Air Force withdrew from Biggin Hill in 1993. No new use has been identified.

Contact: Jacinta Fisher (LPA) 020 8313 4664

Contact: Jacinta Fisher (LPA) 020 8313 4664

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



Building 12 (Candidate's Club, SITE NAME: Former Sergeant's Mess), West Camp,

Main Road, A233 (east side), Biggin Hill

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION: Vacant OCCUPANCY: C(C)PRIORITY

Private

Sergeant's mess, 1932. By the Air Ministry's Directorate of Works and Buildings. Vacant since RAF withdrew from Biggin Hill in 1993. No new use has been secured.

Contact: Jacinta Fisher (LPA) 020 8313 4664



Building 15, Hawkinge Block, SITE NAME: West Camp, Main Road, A233 (east side), Biggin Hill

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION: Vacant C (C) PRIORITY: OWNERTYPE: Private Barrack block. Dated 1934. By the Air Ministry's Directorate of Works and Buildings. Vacant since RAF withdrew from Biggin Hill in 1993. No new use has been secured.

Contact: Jacinta Fisher (LPA) 020 8313 4664



Building 33 (Station HQ), SITE NAME: West Camp, Main Road, A233 (east side), Biggin Hill

Listed Building Grade II, CA DESIGNATION:

CONDITION: Vacant OCCUPANCY: C(C)PRIORITY: OWNERTYPE: Private Office block, formerly station headquarters building. Dated 1931. Vacant since RAF withdrew from Biggin Hill in 1993. No new use has been secured.

Contact: Jacinta Fisher (LPA) 020 8313 4664



Buildings I-5 (Airmen's barrack blocks), SITE NAME:

West Camp, Main Road, A233 (east side), Biggin Hill

DESIGNATION: Listed Building Grade II, CA

CONDITION: Poor Vacant C(C)PRIORITY-Private OWNER TYPE:

Group of five airmen's barracks blocks, 1930. The buildings have been vacant since the RAF withdrew from Biggin Hill in 1993. They have generally been kept in good order but no new use has been identified.

Contact: Jacinta Fisher (LPA) 020 8313 4664



The Royal Bell Hotel, SITE NAME: 173 - 177 High Street, **Bromley**

DESIGNATION: Listed Building Grade II, CA

CONDITION: Vacant OCCUPANCY: E (E) PRIORITY OWNERTYPE: Private This range of buildings was rebuilt in 1898 on the site of an earlier hostelry of I 666. The Royal Bell Hotel is currently vacant and boarded up.

Contact: Jacinta Fisher (LPA) 020 8313 4664



SITE NAME: Ice house to Sundridge Park, Plaistow Lane,

Bromley

DESIGNATION: Listed Building Grade II, RPG II

Very bad CONDITION: N/A

PRIORITY: A (A) OWNER TYPE: Company Ice house circa I 800, in the south-west corner of late C18 landscape park designed by Humphry Repton, now a golf course. Ice house subject to continuous vandalism despite strenuous efforts by owners to prevent access. Negotiations about its future have so far failed to find

a suitable solution.

Contact: Jacinta Fisher (LPA) 020 8313 4664

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



SITE NAME:	Ice house to Old Palace,
	Stockwell Close,

Bromley Palace Park
DESIGNATION: Listed Building Grade II

CONDITION: Poor OCCUPANCY: N/A PRIORITY: C (C)

OWNERTYPE: Local authority

Ice house to Bromley Old Palace. Located in the gardens of the Palace at the southern end of the ornamental lake, near the waterfall. Probably late C18, remodelled in early C19 as a garden shelter, possibly used as a stopping-off point when guests at the Old Palace were taken for a perambulation of the grounds. In poor condition and in need of conservation and repair.

Contact: Jacinta Fisher (LPA) 020 8313 4664



Pulhamite Fernery,
Stockwell Close,
Bromley Palace Park

DESIGNATION: Listed Building Grade II

condition: Poor occupancy: N/A priority: C (C)

OWNERTYPE: Local authority

Pulhamite rock-work garden feature constructed c1865 as part of the improvements to the gardens of Bromley Palace that had been acquired by Coles Child, a wealthy coal merchant. The Fernery is at the northern end of the ornamental lake.

Contact: Jacinta Fisher (LPA) 020 8313 4664



SITE NAME: Pulhamite waterfall, Stockwell Close, Bromley Palace Park

DESIGNATION: Listed Building Grade II

condition: Poor occupancy: N/A priority: C (C)

OWNERTYPE: Local authority

Pulhamite rock-work garden feature constructed c1865 as part of the improvements to the gardens of Bromley Palace that had been acquired by Coles Child, a wealthy coal merchant. The waterfall is at the southern end, adjacent to a probably late C18 ice house.

Contact: Jacinta Fisher (LPA) 020 8313 4664



SITE NAME: Old Town Hall, Tweedy Road, Bromley

DESIGNATION: Listed Building Grade II, CA

condition: Fair occupancy: Vacant Priority: E (E)

OWNERTYPE: Local authority

Former Town Hall building built in 1906. Had been used as premises of Bromley College until 2006/07. The building is currently vacant and awaiting a suitable use.

Contact: Jacinta Fisher (LPA) 020 8313 4664



SITE NAME: Crystal Palace Low Level Station, Crystal Palace

DESIGNATION: Listed Building Grade II, CA

condition: Fair

occupancy: Part occupied

priority: F (F)

OWNERTYPE: Company

Extensive repairs and restoration works completed in November 2001. The building is partially occupied. However, the booking hall remains unoccupied pending implementation of the listed building consent for its reuse in conjunction with the newly-opened East London line.

Contact: Jacinta Fisher (LPA) 020 8313 4664



SITE NAME: Pedestrian subway

under Crystal Palace Parade, Crystal Palace

DESIGNATION: Listed Building Grade II

condition: Poor occupancy: N/A priority: C (C)

ownertype: Local authority

Pedestrian subway circa I 854. Included in the 2008 master plan application for the regeneration of the park as site of a proposed new museum. Holding repairs currently being considered.

Contact: Jacinta Fisher (LPA) 020 8313 4664

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS



Upper and Lower Terraces, SITE NAME:

Crystal Palace Park

DESIGNATION: Listed Building Grade II, CA, RPG II*

CONDITION: N/A OCCUPANCY: C (C) PRIORITY

OWNERTYPE: Local authority

Terraces designed by Sir Joseph Paxton and situated to the east of the site of Crystal Palace (re-erected here in 1852-4 and burnt down in 1936), on the west of Crystal Palace Park. In a ruinous condition and suffering from erosion.

Contact: Jacinta Fisher (LPA) 020 8313 4664



Crystal Palace Park SITE NAME: DESIGNATION: Registered Park and Garden Grade II*, also CA, 6 LBs Generally unsatisfactory CONDITION: with major localised problems

vulnerability: Low Declining TREND: Local Authority, single owner OWNER TYPE:

for the Crystal Palace (re-erected here 1852-4 and burnt down in 1936). Park is in deteriorating condition and the associated grade II listed Upper and Lower Terraces are also at risk. English Heritage supported a master plan for repair and regeneration of the park and buildings and this needs to be taken forward. Capel Manor College is developing a new community garden. London Borough of Bromley is undertaking conservation work on the ornamental basin.

C19 pleasure grounds designed by Sir Joseph Paxton as a setting

Contact: Zosia Mellor 020 7973 3473



20-22 Hamlet Road, SITE NAME Crystal Palace

Pair of mid C19 stuccoed houses suffering from structural problems.

DESIGNATION: Listed Building Grade II, CA Poor CONDITION: OCCUPANCY: Occupied C (C) PRIORITY OWNER TYPE: Private

Contact: Jacinta Fisher (LPA) 020 8313 4664



Derwent House, SITE NAME: 68 Camden Park Road, Chislehurst

DESIGNATION: Listed Building Grade II, CA

Fair CONDITION: Vacant OCCUPANCY: PRIORITY: E (E) Private OWNER TYPE:

Substantial house (1899) by Ernest Newton. Latterly used as a nursing home. Permission granted for conversion to flats and scheme recently permitted for single residential use. Work has commenced.

Contact: Jacinta Fisher (LPA) 020 8313 4664



Downe Court Manor. SITE NAME Cudham Road, Downe

DESIGNATION: Listed Building Grade II

Poor CONDITION: Vacant OCCUPANCY: PRIORITY: A(A)OWNER TYPE: Private Modest red brick house of 1690. Starting to show the effects of long term neglect. Roof and joinery repairs have been undertaken to arrest the decline of the building. However, this work, which included alterations, is subject to enforcement action.

Contact: Jacinta Fisher (LPA) 020 8313 4664



Frontage building to Richard Klinger Factory, Edgington Way, Sidcup

DESIGNATION: Listed Building Grade II Poor CONDITION: OCCUPANCY: Vacant

C (C) PRIORITY:

OWNERTYPE: Private

Offices, cutting shop, tool room and storage factory. Completed in 1937 to the designs of Wallis Gilbert and Partners for Richard Klinger Ltd, founded in Austria in 1893. The building has been vacant for many years. Crittal window frames intact, interior dilapidated. Previous planning application for IKEA store withdrawn.

Future use uncertain.

Contact: Jacinta Fisher (LPA) 020 8313 4664

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category given in brackets

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



316 and 318 High Street, SITE NAME: St Mary Cray

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION: Vacant OCCUPANCY:

C (New entry) PRIORITY:

OWNERTYPE: Private

Pair of C18 cottages. Vacant and showing signs of neglect.

Contact: Jacinta Fisher (LPA) 020 8313 4664

SITE NAME:	High Elms ice house I 30m south of Flint Lodge, I	Bromley	
DESIGNATION:	Scheduled Monument (No. 1018959)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Jane Sidell 020 7973 3738

SITE NAME:	Iron Age settlement and Roman villa at Warbank,	, Keston, Broi	nley
DESIGNATION:	Scheduled Monument (No. 1002024)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Jane Sidell 020 7973 3738

SITE NAME:	Romano-British masonry building and Saxon cen	netery, Fordc	roft, Orpington, Bromley
DESIGNATION:	Scheduled Monument (No. 1001973)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Jane Sidell 020 7973 3738

CAMDEN

9 Calthorpe Street WCI SITE NAME:

DESIGNATION: Listed Building Grade II, CA Fair OCCUPANCY: Vacant E (E) PRIORITY: OWNER TYPE: Local authority

One of a terrace of 21 houses dating from 1821-26, constructed in yellow stock brick over four storeys plus basement. The property remains vacant but has been squatted intermittently. Repairs have been undertaken to the roof to ensure building is watertight. Future plans for the building are uncertain.

Contact: Joanna Ecclestone (LPA) 020 7974 2078



Cattle trough to south east SITE NAME: of the Roundhouse, Chalk Farm Road NWI DESIGNATION: Listed Building Grade II, CA Poor CONDITION: N/A OCCUPANCY:

Late C19 granite cattle trough. Placed by the Metropolitan Cattle Trough and Drinking Fountain Association in memory of the Christian Socialist Charles Kingsley. Some repairs carried out but investigation needed into the security of the trough on the plinth. Vulnerable from being situated adjacent to the bus lane and bus stop.

Contact: Catherine Bond (LPA) 020 7974 2669



Drinking fountain SITE NAME: set in wall next to the Roundhouse, Chalk Farm Road NWI

DESIGNATION: Listed Building Grade II, CA Poor N/A OCCUPANCY:

C (C)

OWNERTYPE: Unknown

PRIORITY:

C (C)

Late C19 Gothic style drinking fountain presented by the Metropolitan Cattle Trough and Drinking Fountain Association. Cleaning has been carried out, but remains prone to littering and damage.

Contact: Charlie Rose (LPA) 020 7974 1971

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS CA LB/LBs LPA NP



Stanley Sidings: industrial stables SITE NAME: (inc. stables A, B, C, D),

Chalk Farm Road NWI

DESIGNATION: Listed Building Grade II, CA Fair CONDITION: Part occupied

OCCUPANCY:

D(D)PRIORITY OWNERTYPE: Company Important complex of industrial stabling built 1883-1895 for the Camden Goods Yard of the London and North Western Railway. Scheme approved for refurbishment of stables with new development for arts/retail use.

Contact: Victoria Pound (LPA) 020 7974 2659



SITE NAME: Monuments in St John's Churchyard, Church Row. Hampstead NW3

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION: N/A C (D) PRIORITY:

OWNER TYPE: Religious organisation

Parish churchyard to St John's Church (listed grade I) containing 20 listed monuments. A repair programme with support from the Heritage Lottery Fund has been completed, leaving some outstanding works of repair to some unlisted monuments and grave stones and to base wall of railings along Holly Walk.

Contact: Joanna Ecclestone (LPA) 020 7974 2078

Philanthropic flats built in 1865 to design by Matthew Allen

under guidance of Sydney Waterlow. Proposals for mixed use

scheme included in Kings Cross Central planning application.



Stanley Buildings South, SITE NAME: Flats 21-30, Clarence Passage, Kings Cross NWI

Listed Building Grade II, CA DESIGNATION:

Poor CONDITION: Vacant OCCUPANCY: C(C)PRIORITY-OWNERTYPE: Private

Contact: Charlie Rose (LPA) 020 7974 1971



26 Denmark Street WC2 SITE NAME:

Early C18 terraced house; windows altered in C20. Bar on ground floor. Windows, parapets and gutters still in poor condition.

DESIGNATION: Listed Building Grade II, CA Poor CONDITION:

Part occupied

C(C)PRIORITY Private OWNER TYPE:

Contact: Joanna Ecclestone (LPA) 020 7974 2078



9 Downshire Hill NW3 SITE NAME:

DESIGNATION: Listed Building Grade II, CA Very bad CONDITION: Vacant OCCUPANCY: A (B) PRIORITY OWNERTYPE: Private

Early C19 villa. The property is in a very poor condition. Partial demolition of the roof, rear wall and rear wing has been undertaken in order to stabilise the majority of the building. Extensively scaffolded and propped whilst new applications for the redevelopment of the site are being considered.

Contact: Victoria Pound (LPA) 020 7974 2659



SITE NAME: Elizabeth Garrett Anderson Hospital, Euston Road NWI

DESIGNATION: Listed Building Grade II, CA Fair CONDITION: Vacant PRIORITY: F (F) OWNER TYPE: Company

Hospital for women built 1889-90 to the design of JM Brydon. Queen Anne style. Works to stabilise the original building and to rebuild the damaged Churchway bay are now complete. Listed building consent and planning permission have been granted for a mixed use scheme which sees the original building retained and restored, this work is nearing completion (April 2011).

Contact: Victoria Pound (LPA) 020 7974 2659

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



SITE NAME:	The Elms (formerly Elm Lodge),
	Fitzroy Park N6

DESIGNATION: Listed Building Grade II, CA

CONDITION: Poor Vacant OCCUPANCY: F (F)

Detached house built 1838-40 to the design of George Basevi. Under refurbishment for residential use with new development but progress slow with extensive works yet to be completed.

Contact: Catherine Bond (LPA) 020 7974 2669



SITE NAME: 43 Fitzroy Street WI

DESIGNATION: Listed Building Grade II, CA CONDITION:

Vacant A (C) PRIORITY: Private OWNER TYPE:

One of a terrace of four houses, dating from the late C18, constructed from darkened multi-coloured stock brick with some stucco dressings. Comprising four storeys and basements. The property appears to be vacant and in a deteriorating condition.

Contact: Catherine Bond (LPA) 020 7974 2669



Three linked Gasholders, SITE NAME: Goods Way NWI

DESIGNATION: Listed Building Grade II, CA

Fair CONDITION: N/A OCCUPANCY: D (D) PRIORITY: OWNER TYPE: Company Gasholders, 1864-1880. Now dismantled and stored in and around the remaining single listed gasholder. Relocation and reuse proposed as part of ongoing redevelopment for Kings Cross Central.

Contact: Michelle O'Doherty (LPA) 020 7974 2537



SITE NAME: Gasholder No 8, Goods Way,

Kings Cross NWI DESIGNATION: Listed Building Grade II, CA

Fair CONDITION: N/A D (D) PRIORITY: OWNER TYPE: Company

Single gasholder erected in 1883 for the Imperial Gas Light and Coke Company. Relocated and reuse proposed as part of the ongoing redevelopment of King's Cross Central. The now dismantled three linked gasholders are stored at the base of this still standing one.

Contact: Alan Wito (LPA) 020 7974 6392



39 Great James Street WCI SITE NAME:

DESIGNATION: Listed Building Grade II*

CONDITION: Vacant OCCUPANCY: D (D) PRIORITY-OWNERTYPE: Company One of a terrace of 14 houses, dating from 1720-24, comprising four storeys and basement, constructed from brown brick. The property is currently empty. The property was being marketed, although sale position not known.

Contact: Richard Parish 020 7973 3717



SITE NAME: Ladies and gentlemen's public conveniences,

Guilford Place WCI DESIGNATION: Listed Building Grade II, CA

Poor CONDITION: N/A PRIORITY: C (C)

OWNER TYPE: Educational Body

Disused late C19 public lavatory sited on a traffic island. Enriched railings and gates with overthrows and lanterns. No current proposals.

Contact: Edward Jarvis (LPA) 020 7974 4578

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS CA LB/LBs LPA NP RPG SM/SMs

UA WHS



66 Guilford Street WCI SITE NAME:

One of terrace of six houses built circa 1793-99 by James Burton. Interest in the property for re-use shown in the last year, but no solution or scheme agreed to date.

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION:

Part occupied OCCUPANCY:

C (C) Private OWNER TYPE:

Contact: Charlie Rose (LPA) 020 7974 1971



SITE NAME: 67-69 (consecutive) Guilford Street WCI

Terrace of three houses built circa 1793-99 by James Burton. Buildings acquired by private company and

repair works yet to take place.

DESIGNATION: Listed Building Grade II, CA

Fair CONDITION:

Part occupied OCCUPANCY:

C (C) PRIORITY: Private OWNER TYPE:

Contact: Charlie Rose (LPA) 020 7974 1971

Terrace of three houses built circa 1793-99 by James

was designed to close the vista from Queen Square. Consent granted for structural repairs at Nos. 70 and 72.

Current use as a Backpacker hostel unresolved, public

Burton. The grand elevation with giant Doric half columns



70-72 (consecutive) SITE NAME: Guilford Street WCI

DESIGNATION: Listed Building Grade II, CA

Fair CONDITION: Occupied OCCUPANCY: E (E) PRIORITY:

OWNER TYPE:

Contact: Charlie Rose (LPA) 020 7974 1971

inquiry held in March 2011, awaiting decision.



SITE NAME: 77-82 (consecutive) Guilford Street WCI

Private

DESIGNATION: Listed Building Grade II, CA

CONDITION: Poor

Part occupied

C(C)PRIORITY Private OWNER TYPE:

Terrace built circa 1793-99 by James Burton. Various degrees of deterioration and condition. Interest shown in several of the properties on a pre-application basis within the last year but no solution or scheme agreed to date.

Contact: Charlie Rose (LPA) 020 7974 1971



Railings to Water Reservoir, SITE NAME: Upper Terrace, Hampstead Grove, Hampstead

DESIGNATION: Listed Building Grade II, CA

CONDITION: Poor N/A OCCUPANCY: C (C) PRIORITY-

OWNER TYPE: Company

Railings surrounding reservoir of 1856. Cast iron, with urn finials and secondary lower rails. Larger finials at each seventeenth upright. Moulded kerb of cast iron above brick plinth. The railings are at risk due to lack of maintenance which is causing damage to the plinth and ironwork. Repairs/reinstatement scheme expected from Thames Water (April 2011).

Contact: Joanna Ecclestone (LPA) 020 7974 2078



SITE NAME: I Hawley Road NWI

DESIGNATION: Listed Building Grade II

Poor CONDITION: Vacant PRIORITY: B (B) OWNERTYPE: Private Early C19 detached villa. Forms part of a builder's yard, and has been used as an office and also for storage. Poor condition, in discussions with owners over refurbishment, work due to start in Spring 2011.

Contact: Joanna Ecclestone (LPA) 020 7974 2078

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



Fountain and pond SITE NAME:

in the Italianate Garden, Witanhurst, Highgate West Hill N6

DESIGNATION: Listed Building Grade II, CA

Very bad CONDITION: N/A OCCUPANCY: D(A)

Private

(April 2011).

Fountain set in circular pond forming a central feature of the Italianate Garden, built circa 1913, probably to design of Harold Peto for Sir Arthur Crosfield. Site is in new ownership and works on the house have commenced

Contact: Catherine Bond (LPA) 020 7974 2669



Four sculptures surrounding pond SITE NAME: in Italianate Garden, Witanhurst, Highgate West Hill N6

DESIGNATION: Listed Building Grade II, CA

Very bad CONDITION: N/A D (A) PRIORITY: Private OWNER TYPE:

Four carved figures, circa 1913, probably part of Harold Peto's design for Sir Arthur Crosfield's garden. Two are now missing; the remaining two are in storage. Property is in new ownership and works to the house have commenced.

Contact: Hannah Walker (LPA) 020 7974 5786



Garden steps and retaining wall SITE NAME: in grounds of Witanhurst, Highgate West Hill N6

Listed Building Grade II, CA DESIGNATION:

Very bad CONDITION: N/A OCCUPANCY: PRIORITY:

D (A) OWNERTYPE: Private Garden steps and retaining wall, circa 1913 by Harold Peto as part of his design for Sir Arthur Crosfield's garden. Property is in new ownership and works to the house

have commenced.



SITE NAME: Italianate Garden

in grounds of Witanhurst, Highgate West Hill N6

DESIGNATION: Listed Building Grade II, CA

Very bad CONDITION: N/A A(A)PRIORITY-Private OWNER TYPE:

Italianate Garden comprising walls, steps, gateway, sunken pond and pergola. Built circa 1913, probably designed by Harold Peto for Sir Arthur Crosfield. Property is in new ownership and works to the house have commenced.

Contact: Hannah Walker (LPA) 020 7974 5786

Contact: Hannah Walker (LPA) 020 7974 5786



Tennis Pavilion SITE NAME:

in the grounds of Witanhurst, Highgate West Hill N6

Listed Building Grade II, CA DESIGNATION:

Very bad CONDITION: Vacant OCCUPANCY: A (A) PRIORITY-

OWNERTYPE: Private

his design for Sir Arthur Crosfield's garden. Urgent works have been carried out to make the building wind and weather tight. Property is in new ownership and works to the house have commenced.

Contact: Hannah Walker (LPA) 020 7974 5786

Tennis Pavilion, 1913. Designed by Harold Peto as part of



SITE NAME: Witanhurst.

41 Highgate West Hill N6

DESIGNATION: Listed Building Grade II*, CA

Fair CONDITION: Vacant PRIORITY: F (C) OWNERTYPE: Private

Substantial detached house, 1913-20 by George Hubbard for Sir Arthur Crosfield. Incorporating early C18 house 'Parkfield' enlarged in 1881. Vacant for many years, now in new ownership. Listed building consent granted in 2009 for full repairs to roof. Consented repair works undertaken. Planning and LBC granted for full repair and refurbishment for use as a dwelling house. Works are underway (April 2011).

Contact: Claire Brady 020 7973 3777

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented

NOTE:

If the priority category has changed since the 2010 register, the previous category given in brackets

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



SITE NAME:	Former Westminster
	and Kingsway College,
	87 Holmes Road, Kentish Town NW!

DESIGNATION: Listed Building Grade II, CA

CONDITION: Fair Vacant OCCUPANCY: F (C) PRIORITY: OWNERTYPE: Private

OWNERTYPE: Private

Former London Board School, currently vacant, with a nursery school, primary and secondary schools. Planning and listed building consent granted for works of conversion and restoration, a new extension is underway and the school is scheduled to open in September 2011.

Contact: Catherine Bond (LPA) 020 7974 2669



SITE NAME: 93 Judd Street WCI

DESIGNATION: Listed Building Grade II, CA Poor CONDITION: Vacant F (C) PRIORITY:

House with shop at ground floor level built circa 1816 by James Burton. Although in a poor and deteriorating condition in recent years, the building's new owner has obtained permission to refurbish and convert the bedsit accommodation to self contained residential units, and work is in progress (April 2011).

Contact: Catherine Bond (LPA) 020 7974 2669



46 and 48 Maple Street WI SITE NAME:

DESIGNATION: Listed Building Grade II CONDITION: Poor Part occupied OCCUPANCY: C (C) PRIORITY: Private OWNER TYPE:

Two terraced houses dating from circa 1777-87, constructed from yellow stock brick, four storeys on basements, with slated mansard roofs. Alterations were made to the roofs in C20 and to the rear. Both houses have been sub-divided into flats. In a poor, deteriorating condition.

Contact: Joanna Ecclestone (LPA) 020 7974 2078



SITE NAME: 23 Mornington Crescent NWI

DESIGNATION: Listed Building Grade II, CA Poor CONDITION: Part occupied C(C)PRIORITY-Private OWNER TYPE:

House forming part of a crescent, built circa 1821-23 by I Bryant for the Southampton Estate. In use as a house of multiple occupation and in a poor and deteriorating condition. New ownership from 2008.

Contact: Alan Wito (LPA) 020 7974 6392



25 Mornington Crescent NWI SITE NAME:

House forming part of a crescent, built circa 1821-23 by I Bryant for the Southampton Estate. In use as a house of multiple occupation and in a poor and deteriorating condition.

DESIGNATION: Listed Building Grade II, CA occupancy: Occupied C (C) PRIORITY: OWNERTYPE: Private

Contact: Catherine Bond (LPA) 020 7974 2669



SITE NAME: St Luke and St Paul's Church, Oseney Crescent NW3

DESIGNATION: Listed Building Grade II*, CA Poor CONDITION: Part occupied

PRIORITY: A (F)

OWNERTYPE: Religious organisation

Redundant church built 1867-69 to the design of Basil Champneys in Early English style with North German influences. Previous repairs completed with English Heritage grant aid. Wet and dry rot were affecting structure. Building is intended to be returned to church

use in autumn 2011.

Contact: Richard Parish 020 7973 3717

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



The 'Lighthouse' block, SITE NAME:

295-297 (odd) Pentonville Road NI

DESIGNATION: Listed Building Grade II, CA

Very bad CONDITION: Vacant OCCUPANCY: D(D)

OWNER TYPE: Company Also includes 378-380 (even) Gray's Inn Road. 'Flat iron' block of shops with offices over, circa 1875, prominently situated at the junction of Gray's Inn Road and Pentonville Road. A tall lead-clad tower at the apex gives it its 'lighthouse' identity. Scheme approved for refurbishment for office and retail use, but not yet implemented.

Contact: Charlie Rose (LPA) 020 7974 1971



SITE NAME: Section of boundary wall to St Stephen's Church. Rosslyn Hill NW3

DESIGNATION: Listed Building Grade II, CA

Very bad CONDITION: N/A F (F) PRIORITY: Trust OWNER TYPE:

Brick and stone boundary wall along Hampstead Green, 1869. Applications approved for repair and underpinning, some work underway.

Contact: Catherine Bond (LPA) 020 7974 2669

Contact: Antonia Powell (LPA) 020 7974 2648



Kingsway Tram Subway SITE NAME: (northern section), Southampton Row WCI

Listed Building Grade II, CA DESIGNATION:

Good CONDITION: N/A OCCUPANCY: PRIORITY: F (F)

OWNERTYPE: Local authority

Tram subway built 1904-6 by the London County Council. Refurbishment close to completion, reinstatement of lamp standards and associated works scheduled for 2011. Site due to be leased to Crossrail for 5 years from late 2011.



SITE NAME: Baptist Church House, 2-6 (even) Southampton Row WCI

DESIGNATION: Listed Building Grade II*, CA

Fair CONDITION:

Part occupied

D (D) PRIORITY-Company OWNER TYPE:

Redundant Baptist Chapel, offices and shop built 1901-3 to the design of Arthur Keen, architect for the Baptist Union of Great Britain and Ireland. 'Wrenaissance' style with Flemish-inspired shaped gables and eclectic baroque and Arts and Crafts details. Planning and listed building consent granted for restoration and conversion to a hotel, but not yet implemented.

Contact: Richard Parish 020 7973 3717



Toll Gate House, SITE NAME: Spaniards Road, Highgate NW3

DESIGNATION: Listed Building Grade II

CONDITION: Vacant OCCUPANCY:

PRIORITY-

E (E) OWNER TYPE: Local authority Late C18 toll house restored 1967, marking the spot where the road entered the Bishop of London's estate. It stands at a traffic bottleneck on a busy road and has suffered impact damage from heavy vehicles. Bollard erected late 2008 to provide protection from traffic. Roof and guttering repair works undertaken.

Contact: Joanna Ecclestone (LPA) 020 7974 2078



SITE NAME: 108 St Pancras Way, Kentish Town NWI

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION: Vacant PRIORITY: C (D) OWNERTYPE: Private

End of terrace house dating from the mid 1820s, with early C19 shop front. Interior suffering from water ingress at roof level. Consent has been granted for the repair, refurbishment and alteration of the building but the approval works have not commenced.

Contact: Alan Wito (LPA) 020 7974 6392

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category given in brackets

ABBREVIATIONS



Monuments at Highgate Cemetery SITE NAME:

(east and west sides), Swains Lane N6

DESIGNATION: Listed Building Grade II, CA, RPG I

Fair CONDITION: N/A OCCUPANCY: F (F) PRIORITY: Trust OWNER TYPE:

Cutting Catacombs grant-aided repair work finished (January 2010), but additional repair works remain for other monuments.

Contact: Antonia Powell (LPA) 020 7974 2648



Highgate Cemetery SITE NAME: DESIGNATION: Registered Park and Garden Grade I, also CA, 62 LBs

with major localised problems

Generally unsatisfactory CONDITION:

VULNERABILITY: High Declining TREND:

Corporate, single owner OWNER TYPE:

Laid out by the London Cemetery Company and opened in 1839. Eastern Cemetery added in 1855. The boundary walls, railings and gates to the Eastern Cemetery are in need of major repairs. The principal monuments in the Western Cemetery have been repaired and conserved with English Heritage and Heritage Lottery Fund grants. A landscape management plan is in place to help conserve the historic character of the cemetery and the monuments.

Contact: Zosia Mellor 020 7973 3473



16 Swinton Street WCI SITE NAME

DESIGNATION: Listed Building Grade II, CA Very bad CONDITION: Vacant OCCUPANCY: A(A)PRIORITY Private OWNER TYPE:

One of I2 early to mid C19 terrace houses, yellow stock brick with rusticated stucco ground floor. Some works commenced with consent. Currently vacant, in a state of disrepair while awaiting a finalised application from the owner.

Contact: Michelle O'Doherty (LPA) 020 7974 2537



65 Swinton Street WCI SITE NAME:

DESIGNATION: Listed Building Grade II, CA Very bad CONDITION: Vacant OCCUPANCY: PRIORITY: A(A)

Terraced house circa 1775, with late C19 shop front. Unoccupied and deteriorating. Building is in poor condition, interior removed. Discussions regarding future uses are ongoing.

Contact: Alan Wito (LPA) 020 7974 6392



Eastern coal drops SITE NAME: at Kings Cross Goods Yard, York Way NW I

Private

DESIGNATION: Listed Building Grade II, CA

Fair CONDITION:

OWNER TYPE:

Part occupied OCCUPANCY:

PRIORITY: E(E)

OWNER TYPE: Company

OWNER TYPE: Company

Coal drops built in 1851-2 probably to design of Lewis Cubitt, to carry high-level track for transport of coal into storage bins. Part of a system of distributing coal from the North East and Yorkshire to the London market. Currently used as a club. Proposals for mixed-use scheme included in the Kings Cross Central planning application.

Contact: Michelle O'Doherty (LPA) 020 7974 2537



The Granary, York Way NWI

DESIGNATION: Listed Building Grade II, CA CONDITION: Good OCCUPANCY: Vacant F (F) PRIORITY:

Immense warehouse built in 1851-2 probably to design of Lewis Cubitt; the primary feature of the goods interchange facilities at Kings Cross. Proposals for mixed-use scheme included in the Kings Cross project are being implemented. Part of the current restoration/redevelopment for the University of the Arts, occupation is envisaged for September 2011.

Contact: Alan Wito (LPA) 020 7974 6392

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS CA LB/LBs LPA NP RPG SM/SMs UA WHS



St George's Cathedral, SITE NAME: Redhill Street, Camden Town NWI

DESIGNATION: Listed Place of Worship Grade II*, CA

CONDITION:

PRIORITY: A (New entry)

Religious organisation OWNER TYPE:

Early Victorian church with later alterations. Grey stock brick with stucco and stone dressings. Used on weekends for services. Several vertical cracks were identified on the eastern section of the principal façade. Penetrating damp and vegetation growth was prominent in the spire and pediment on central projecting bay of principal façade. Plaster work and stone work to spire also highly worn in places.

Contact: Don Bianco 020 7973 3745



SITE NAME: Church of the Holy Trinity with St Barnabus. Clarence Way NWI

DESIGNATION: Listed Place of Worship Grade II

C (D) PRIORITY:

Religious organisation OWNER TYPE:

Built 1849-50 in a C14 Gothic style to design of Thomas H Wyatt and David Brandon. Bomb damaged during World War II; now suffering from structural movement. Phase I repairs to roof complete with English Heritage / Heritage Lottery Fund grant aid. Phase II grant offered for stonework repairs to tower and underpinning, but this was not taken up.

Contact: Don Bianco 020 7973 3745



Christ Apostolic Church SITE NAME: (formerly Church of St John), Highgate Road, Kentish Town, Hampstead NW5

Listed Place of Worship Grade II DESIGNATION:


Poor CONDITION: C (C) PRIORITY:

Religious organisation

Formerly St John's Church. Chapel built on site of the Kentish Town Chapel of 1783 by James Wyatt, of which the nave walls and apse remain. The rest was rebuilt in 1843-45 by JH Hakewill. Now occupied by religious group. English Heritage / Heritage Lottery Fund grant-aided high level repairs to west end roof completed, but further works required to roofs, high level stonework, boundary wall and gates.

Contact: Don Bianco 020 7973 3745

CITY OF LONDON



Partner's House. SITE NAME: 50-51 Chiswell Street ECI

DESIGNATION: Listed Building Grade II*, CA

CONDITION: OCCUPANCY: Vacant

E (E) PRIORITY-

OWNER TYPE: Company

Terrace of early C18 red brick buildings with well preserved interiors, formerly part of the Whitbread Brewery. Current planning permission and listed building consent for conversion to a hotel. Works on site.

Contact: Michael Dunn 020 7973 3774



St Mary Somerset Tower, SITE NAME: Upper Thames Street EC4

DESIGNATION: Listed Building Grade I

Fair CONDITION: Vacant OCCUPANCY: E (E)

OWNERTYPE: Local authority

Redundant church built between 1686-94 by Wren. Body of church destroyed in 1871. Permission has been granted for renovations and extension in connection with conversion to residential use.

Contact: Michael Dunn 020 7973 3774



Church of St Giles SITE NAME Without Cripplegate, Fore Street EC2

DESIGNATION: Listed Place of Worship Grade I

Very bad CONDITION: PRIORITY: D (New entry)

OWNER TYPE: Religious organisation

Mid C16 church incorporating earlier tower. Building was extensively refaced in C19 in Kentish ragstone to the tower. Much of the ragstone is now failing due to poor quality repairs. Joint English Heritage / Heritage Lottery Fund grant offered towards stonework repair and development phase

is underway.

Contact: Don Bianco 020 7973 3745

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS Conservation Area

CA LB/LBs LPA NP RPG SM/SMs UA WHS



DESIGNATION:

SITE NAME: Church of St Bartholomew the Great, West Smithfield EC I

Church has been heavily altered but retains fabric dating from as early as C12. External repairs are underway and are the subject of English Heritage grant funding. These works will address water penetration to interior as a result of roof and stonework decay and are due for completion soon.

DESIGNATION: Listed Place of Worship Grade I, CA

CONDITION: Poor

PRIORITY: F (New entry)

OWNER TYPE: Religious organisation

Contact: Don Bianco 020 7973 3745

SITE NAME:	London W	'all: remains	of	Roman	and	medieval	wall :	from	west	end
	CAHLLI			20.0		·1 C	C:.			

of All Hallows Church to 38 Camomile Street, City of London

Scheduled Monument (No. 1002050) condition: Generally satisfactory

but with significant localised problems

PRINCIPAL VULNERABILITY: Deterioration — in need of management TREND: Declining

OWNERTYPE: Local Authority contact: Jane Sidell 020 7973 3738

SITE NAME: London Wall: section of Roman and Medieval wall

at St Alphage garden, incorporating remains of St Alphage's Church, City of London

DESIGNATION: Scheduled Monument (No. 1018886) CONDITION: Generally satisfactory but with significant localised problems

PRINCIPAL VULNERABILITY: Deterioration – in need of management TREND: Declining

OWNER TYPE: Local Authority CONTACT: Jane Sidell 020 7973 3738

SITE NAME: London Wall: the west gate of Cripplegate Fort and a section of Roman wall

in London Wall underground car park, adjacent to Noble Street, City of London

DESIGNATION: Scheduled Monument (No. 1018889) condition: Generally unsatisfactory with major localised problems

PRINCIPAL VULNERABILITY: Rain entry TREND: Declining

OWNERTYPE: Local Authority contact: Jane Sidell 020 7973 3738

SITE NAME: Roman wall in basement of 90 Gracechurch Street, City of London

DESIGNATION:	Scheduled Monument (No. 1002035)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Jane Sidell 020 7973 3738

CROYDON



SITE NAME: Ice house,

Geoffrey Harris House, Coombe Road

DESIGNATION: Listed Building Grade II

condition: Poor occupancy: N/A priority: C (C)

OWNER TYPE: Local authority

C18 ice house to Coombe House, now Geoffrey Harris House. Disused and partly overgrown, some loose brickwork and deterioration of pointing.

Contact: Sarah Freeman (LPA) 020 8726 6000



SITE NAME: Former Kennedys Butchers,

18a High Street, South Norwood

DESIGNATION: Listed Building Grade II, CA

CONDITION: Poor OCCUPANCY: Vacant

PRIORITY

OWNERTYPE: Private

B (B)

Built in 1926 for Kennedys, a chain of South London butchers, now closed. The building is partially secured but vulnerable to vandalism.

Contact: Sarah Freeman (LPA) 020 8726 6000

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA Conservation Area
LB/LBs Listed Building/s
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM/SMs Scheduled Monument/s
UA Unitary Authority
WHS WOrld Heritage Site



Lesley Arms Public House, SITE NAME: 62 Lower Addiscombe Road, Addiscombe

DESIGNATION: Listed Building Grade II Poor CONDITION:

Vacant

C (D) OWNER TYPE: Company Public house circa 1900 in Arts and Crafts style. Vacant for several years. The upper floors have been converted and new applications for the ground floor and exterior are being considered. A Section 215 notice was served in 2009 and has been largely implemented. Upper floors have now been converted and a new application for the ground floor and exterior are currently in consideration.

Contact: Sarah Freeman (LPA) 020 8726 6000

Contact: Sarah Freeman (LPA) 020 8726 6000



Segas Offices, SITE NAME: 32 Park Lane. Croydon

DESIGNATION: Listed Building Grade II

Fair CONDITION: Vacant C(C)PRIORITY: OWNER TYPE: Company

Gas company showroom and office, built 1939-41 in Moderne style. In sound condition but vacant. As part of the emerging Mid Croydon Masterplan, the Local Authority is currently seeking potential new uses for the building.



Lion Lodge, SITE NAME: including gate piers, 2 Spout Hill, Addington

Listed Building Grade II, CA, RPG II DESIGNATION: CONDITION: Vacant OCCUPANCY:

OWNERTYPE: Company

C(D)

One of a pair of single-storey lodges at the former east entrance to Addington Palace. Built 1773-78 by Robert Mylne. Vacant for several years. Planning permission and listed building consent have previously been granted to repair, extend and return to residential use. Gates in local authority ownership. Planning permission and listed building consent given and gates due to be replaced in 2011.

Contact: Sarah Freeman (LPA) 020 8726 6000



Surrey Street Pumping Station, SITE NAME: Surrey Street, Croydon

DESIGNATION: Listed Building Grade II, CA CONDITION: Fair Vacant C(C)PRIORITY

Pumping station, built in four phases. Earliest engine house 1851, by Cox, with a further engine house of 1862 by Baldwin Latham, extended 1876-7 by Smith of South Norwood. Exterior repairs complete. Improvements to the surrounding public realm and new commercial and residential development around Waterworks Yard have recently been completed. Positive new uses for the Pumping Station under consideration.

Contact: Sarah Freeman (LPA) 020 8726 6000



2 Woodside Green, SITE NAME: South Norwood

Private

OWNER TYPE:

DESIGNATION: Listed Building Grade II CONDITION: Very bad OCCUPANCY: Vacant A (New entry) PRIORITY-OWNERTYPE: Private

Early C18 two storey weatherboarded house with a box cornice, tiled gambrel roof with two hipped dormers and a large catslide roof to the north. The house is unoccupied and in very poor condition internally and externally following extensive fire damage in 1991. The condition of the building is being monitored by the Local Authority who are discussing the need for urgent repairs with the owners.

Contact: Sarah Freeman (LPA) 020 8726 6000

MATERIAL VIEW	100 PRA
4	
AH .	
1 7	

SITE NAME

SITE NAME

Group of four World War II fighter pens at the former airfield of RAF Kenley, Croydon

DESIGNATION:	Scheduled Monument (No. 1021242)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Jane Sidell 020 7973 3738

Group of seven World War II fighter pens at the former airfield of RAF Kenley, Croydon

DESIGNATION:	Scheduled Monument (No. 1021243)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Jane Sidell 020 7973 3738

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented

NOTE: If the priority category has changed since the 2010 register, the previous category given in brackets

ABBREVIATIONS CA LB/LBs

SITE NAME:	Surrey Iron Railway embankment, approxim	ately I30m south	west of Lion Green Road, Coulsdon, Croydon
DESIGNATION:	Scheduled Monument (No. 1021441)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Jane Sidell 020 7973 3738

SITE NAME:	Wellesley Road North, Croydo
SITE NAME:	Wellesley Road North, Croyd

DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	High	TREND:	Improving
CONTACT:	Sarah Freeman (LPA) 020 8726 6000	NEW ENTRY?:	No





Stable Block at Brent Lodge Park, Church Road, Hanwell W7

DESIGNATION: Listed Building Grade II, CA

CONDITION: Fair

OCCUPANCY: Vacant

PRIORITY: E (A)

OWNERTYPE: Local authority

Late C19, yellow stock brick, two storey building. The slate hipped roof had been in a very poor condition causing water ingress and subsequent structural faults. The building is only partially occupied. Urgent works to control water ingress and underpinning completed. Plans for future use being prepared for consultation. Statement of significance and condition survey completed 2010.

Contact: Rosemarie Wakelin (LPA) 020 8825 6600



SITE NAME: Crossways,
134 Church Road,
Hanwell W7

DESIGNATION: Listed Building Grade II, CA

CONDITION: Very bad

OCCUPANCY: Vacant

PRIORITY: A (A)

OWNER TYPE: Private

C18 or earlier house. In a very bad condition, vacant and has been deteriorating for some time. Some site clearance has been carried out. Urgent works notice issued September 2010. Now shored up with scaffolding supporting tin roof.

Contact: Rosemarie Wakelin (LPA) 020 8825 6600



SITE NAME: Hanwell Community Centre, Cuckoo Avenue, Hanwell W7

DESIGNATION: Listed Building Grade II, CA

CONDITION: Fair

OCCUPANCY: Part occupied

PRIORITY: E (C)

OWNERTYPE: Local authority

Administration block of former London District Schools, I 856. The Council have raised over $\pounds 3m$ for the Community Centre and for local regeneration. Major repairs carried out to the roof, now watertight with insulation. Repair and repointing undertaken. Conservation Management Plan completed and Ealing Council working with English Heritage and local community on long-term use.

Contact: Rosemarie Wakelin (LPA) 020 8825 6600



Goldsmiths' Almshouses, chapel and railings fronting road, East Churchfield Road W3

DESIGNATION: Listed Building Grade II*, CA

CONDITION: Poor
OCCUPANCY: Part occupied
PRIORITY: F (C)

OWNERTYPE: Private

1811 by C Beazley, architect. Comprises three ranges of two storey almshouses arranged around an open court with a central stucco-fronted chapel. The almshouses are in fair condition and partially occupied. The chapel's interior was stripped out in the late 1980s and is now derelict and suffering from dry rot. An approved scheme for conversion to housing is being implemented.

Contact: Samantha Johnson 020 7973 3749



SITE NAME: Norwood Hall,
Norwood Green Road,
Southall

DESIGNATION: Listed Building Grade II, CA CONDITION: Fair

occupancy: Part occupied PRIORITY: F (D)

OWNERTYPE: Private

Contact: Rosemarie Wakelin (LPA) 020 8825 6600

Built 1801-3 by Sir John Soane for the auctioneer and

estate agent John Robins. Extended in the late C19 and includes substantial grounds, outbuildings and a walled

garden. Most recently used as a horticultural college and

is now used as community centre by the present owner.

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

Works are ongoing.

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



SITE NAME:	Hanwell Station, main up side building
	and down side island platform,
	Station Road Hanwell W7

DESIGNATION: Listed Building Grade II

Poor CONDITION: N/A OCCUPANCY: A(C) when the track numbers were quadrupled. The timber platform structures have been repaired, however, the buildings remain in a poor condition. Drainage issues are causing further deterioration to the fabric.

Circa 1875-77. Important station canopies and ironwork especially on central platform. The least altered example remaining of the general station rebuilding of the 1870s

Contact: Rosemarie Wakelin (LPA) 020 8825 6600



Southall Manor House, SITE NAME: The Green. Southall

DESIGNATION: Listed Building Grade II*

Fair CONDITION:

Part occupied

E (C) PRIORITY:

Local authority OWNER TYPE:

Substantial timber-framed manor house of 1587, with later extensions and alterations. Recently cleared to make way for urgent and much needed maintenance. Following a survey a programme of repairs and refurbishment has been drawn up and is now underway. Ongoing negotiations regarding long-term management.

Contact: Samantha Johnson 020 7973 3749



Twyford Abbey, SITE NAME: Twyford Abbey Road NW10

DESIGNATION: Listed Building Grade II

Very bad CONDITION: Vacant OCCUPANCY: C(C)PRIORITY:

OWNER TYPE: Company

Gothick country house built I 807-9 by William Atkinson. Last used as a nursing home. Discussions are ongoing for substantial enabling development in the grounds to pay for the repair and maintenance of the historic building and site. Some urgent work undertaken alongside marketing of the site.

Contact: Rosemarie Wakelin (LPA) 020 8825 6600



SITE NAME: St Bernard's Hospital, Uxbridge Road, Southall

DESIGNATION: Listed Building Grade II

CONDITION: Fair

Part occupied

C(C)PRIORITY

Health Authority OWNER TYPE:

Former mental asylum (1829) by William Alderson; extended 1854-57. Part of the original complex has been restored for continuing healthcare use. Site now partially refurbished, but chapel, ballroom and remaining wards are still vacant with no agreed use, and a rolling programme of repairs agreed. Further applications pending for residential/new build.

Contact: Rosemarie Wakelin (LPA) 020 8825 6600



Church of St Mary, SITE NAME: Brentmead Gardens, Twyford, Park Royal NW10


DESIGNATION: Listed Place of Worship Grade II

CONDITION: Fair E (E) PRIORITY:

OWNER TYPE: Religious organisation

Early C19 church with 1958 Cachemaille-Day extension built in the grounds of Twyford Abbey. Some salt damage on the facade was noted and scaffolding was erected on the southern facade to repair windows. Access to the rear of the structure was blocked by construction fencing. At the time of visit, the church was closed for restoration. Services are temporarily being held in a neighbouring building.

Contact: Don Bianco 020 7973 3745



SITE NAME: Church of St Peter. Mount Park Road W5

DESIGNATION: Listed Place of Worship Grade II*, CA

CONDITION:

B (New entry) PRIORITY:

owner type: Religious organisation

Church in free gothic style by JD Sedding and H Wilson dating from 1889 to 1892. Generally well maintained but has issues with high level stonework decay. Joint English Heritage / Heritage Lottery Fund grant offered towards high level stonework repairs and development phase is underway.

Contact: Don Bianco 020 7973 3745

SITE NAME:

Hanwell flight of locks and brick boundary wall of St Bernard's Hospital, Ealing

DESIGNATION:	Scheduled Monument (No. 1001963)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Jane Sidell 020 7973 3738

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable)
 end use or user identified;
 functionally redundant buildings
 with new use agreed but not yet implemented

NOTE:

If the priority category has changed since the 2010 register, the previous category given in brackets

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS

Private Convex Jane Sidell 020 7973 3738 Moated site at Sudbury golf course, Wembley, Ealing Scheduled Monument (No. 1001971) Construct Drainage/dewatering Jane Sidell 020 7973 3738 Drainage/dewatering Jane Sidell 020 7973 3738 STENAME Windmill Bridge, Ealing Scheduled Monument (No. 1002020) Construct Private Construct Scheduled Monument (No. 1002020) Construct Dama Sidell 020 7973 3738 STENAME Windmill Bridge, Ealing Scheduled Monument (No. 1002020) Construct Description Scheduled Monument (No. 1002020) Construct Actor Town Centre, Actor Conservation Area Conservation Conservation Area Conservation Conservation Area Conservation A	SITE NAME:	Moated site at Down Barns Farm, Ealing		
PRINCES ACCURATIONS Private Mosted site at Sudbury golf course, Wembley, Ealing Private Mosted site at Sudbury golf course, Wembley, Ealing Private Mosted site at Sudbury golf course, Wembley, Ealing Private Scheduled Monument (No. 1001971) CONDITION CON	DESIGNATION:	Scheduled Monument (No. 1005552)	CONDITION:	· · · · · · · · · · · · · · · · · · ·
Description of the content of the co	PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	-
Scheduled Monument (No. 1001971) Condition Generally satisfactory but with significant localised proble Unknown Control Vundamatum: Drainage/dewatering TRINCH Unitary Private Windmill Bridge, Ealing Scheduled Monument (No. 1002020) Conditions Scheduled Monument (No. 1002020) Conditions Scheduled Monument (No. 1002020) Conditions Conditions Generally satisfactory but with significant localised proble unitary significant localised proble of the property of the	OWNER TYPE:			Jane Sidell 020 7973 3738
Scheduled Monument (No. 1001971) CONDITION Generally satisfactory but with significant localised proble on the provided manager of the provided mana				
Drainage/dewatering TREND Unknown CONTROL Jane Sidell 020 7973 3738 STENME Windmill Bridge, Ealing SECHMEN VINDERABURY Moderate vehicle damage/erosion FREND VINDERABURY MODERATE MO	SITE NAME:		, Ealing	
DESCRIPTION PRIVATE Windmill Bridge, Ealing SETE NAME: Windmill Bridge, Ealing SCHEDULAR SCHEDULAR STATE WHITE Windmill Bridge, Ealing SCHEDULAR SCHEDULAR STATE WHITE Moderate vehicle damage/erosion TREND: Declining CONTRICT: Jane Sidell 020 7973 3738 Declining CONTRIC	DESIGNATION:		CONDITION:	Generally satisfactory but with significant localised problems
DESIGNATION Scheduled Monument (No. 1002020) CONDITION: Generally satisfactory but with significant localised problement localised problement with significant localised problement lo	PRINCIPAL VULNERABILITY:		TREND:	
Scheduled Monument (No. 1002020) Schedu	OWNER TYPE:	Private	CONTACT:	Jane Sidell 020 7973 3738
but with significant localised problet prescription then Declining Declining Contract: Jane Sidell 020 7973 3738 afte name: Acton Town Centre, Acton DESIGNATION: Conservation Area Condition: Very bad Inproving No December Wakelin (LPA) 020 8825 6600 STET NAME: Cuckoo Estate, Hanwell DESIGNATION: Conservation Area Condition: Poor Deteriorating No Deteriorating Step Name: Designation: Conservation Area Condition: New Entire: No Deteriorating Step Name: Designation: Conservation Area Condition: New Entire: No Deteriorating Step Name: Designation: Conservation Area Condition: New Entire: No Deteriorating Step Name: Designation: Conservation Area Condition: New Entire: No Deteriorating Step Step Name: Deteriorating Name: Deteriorating Name: Deteriorating Name: Deteriorating Step Name: Deteriorating Step Name: Deteriorating Name: Deterioration Name: Deteri	SITE NAME:	Windmill Bridge, Ealing		
Moderate vehicle damage/erosion Government or Agency Government Governm	DESIGNATION:	Scheduled Monument (No. 1002020)	CONDITION:	· · · · · · · · · · · · · · · · · · ·
OWNERTHYPE Government or Agency CONTACT: Jane Sidell 020 7973 3738 SITE NAME: Acton Town Centre, Acton CONSCIENT		NA L . L'IL L		=
SITE NAME: Acton Town Centre, Acton DESIGNATION: CONSERVATION: LOW ROSEMATION: LOW ROSEMATICH: ROSEMATICH: ROSEMATICH: ROSEMATICH: COLKOO Estate, Hanwell DESIGNATION: CONSERVATION: CONSERVATION: CONSERVATION: CONSERVATION: CONSERVATION: CONSERVATION: CONSERVATION: ROSEMATION: CONSERVATION: CONSERVA	PRINCIPAL VULNERABILITY:	-		_
DESIGNATION: Conservation Area CONDITION: Very bad Improving New ENTERY: No Improving New Entery New Ente	OWNER TYPE:	Government or Agency	CONTACT:	Jane Sidell 020 7973 3738
AULINERABLITY: LOW Rosemarie Wakelin (LPA) 020 8825 6600 NEW ENTER: ROSEMARIE Cuckoo Estate, Hanwell STE NAME: Conservation Area CONDITION: Rosemarie Wakelin (LPA) 020 8825 6600 NEW ENTER: Deteriorating NO STE NAME: Ealing Town Centre, Ealing DESIGNATION: Conservation Area CONDITION: Poor TEND: Deteriorating significantly NO STE NAME: Ealing Town Centre, Ealing DESIGNATION: CONSERVATION: LOW TEND: Deteriorating significantly NO STE NAME: Hanwell Clock Tower, Hanwell DESIGNATION: Conservation Area CONDITION: ROSEMARITY: LOW TEND: DESIGNATION: Conservation Area CONDITION: Very bad TEND: Improving NO STE NAME: Hanwell Village Green, Hanwell DESIGNATION: CONTACT: ROSEMARIE Wakelin (LPA) 020 8825 6600 NEW ENTRY: NO STE NAME: Hanwell Village Green, Hanwell CONTACT: ROSEMARITY: LOW TEND: Deteriorating Designation: No STE NAME: Hanwell Village Green, Hanwell DESIGNATION: CONTACT: ROSEMARIE Wakelin (LPA) 020 8825 6600 NEW ENTRY: NO STE NAME: Hanwell Village Green, Hanwell Deteriorating No Poor TEND: Deteriorating No Poor TEND: Deteriorating No Poor TEND: Deteriorating No Poor TEND: Deteriorating No Poor	SITE NAME:	Acton Town Centre, Acton		
AULINERABLITY: LOW ROSEMARIE WAkelin (LPA) 020 8825 6600 NEW ENTER: NO STE NAME Cuckoo Estate, Hanwell STE NAME Conservation Area Condition: Rosemarie Wakelin (LPA) 020 8825 6600 NEW ENTER: Deteriorating No STE NAME Ealing Town Centre, Ealing DESIGNATION: Conservation Area Condition: Poor TREND: Deteriorating No STE NAME Ealing Town Centre, Ealing Conservation Area Condition: Deteriorating significantly No STE NAME Hanwell Clock Tower, Hanwell DESIGNATION: Conservation Area Condition: Very bad TREND: DESIGNATION: No STE NAME Hanwell Clock Tower, Hanwell DESIGNATION: Conservation Area Condition: Very bad TREND: Improving No STE NAME Hanwell Village Green, Hanwell DESIGNATION: Contract: Rosemarie Wakelin (LPA) 020 8825 6600 NEW ENTER: No STE NAME Hanwell Village Green, Hanwell DESIGNATION: Conservation Area Condition: Poor TREND: Deteriorating No STE NAME Hanwell Village Green, Hanwell DESIGNATION: Conservation Area Condition: Poor TREND: Deteriorating No STE NAME Hanwell Village Green, Hanwell DESIGNATION: Conservation Area Condition: Poor TREND: Deteriorating No Poor TREND: Deteriorating No Poor TREND: Deteriorating No Contract: Rosemarie Wakelin (LPA) 020 8825 6600 NEW ENTER: No	DESIGNATION:	Conservation Area	CONDITION:	Very bad
Cuckoo Estate, Hanwell DESIGNATION: Conservation Area Condition: Deteriorating CONTACT: Rosemarie Wakelin (LPA) 020 8825 6600 NEW ENTRY: No SITE NAME Ealing Town Centre, Ealing ESIGNATION: Conservation Area Condition: Condition: Conservation Area Condition: Con	VULNERABILITY:	Low	TREND:	•
Conservation Area CONDITION: CONSERVATION: LOW ROSEMARIE Wakelin (LPA) 020 8825 6600 NEW ENTRY: No SITE NAME: Ealing Town Centre, Ealing DESIGNATION: CONSERVATION: CONSERVATION Area CONDITION: Poor TREND: Deteriorating significantly No Deteriorating significantly No SITE NAME: Hanwell Clock Tower, Hanwell DESIGNATION: CONSERVATION Area CONDITION: Very bad TREND: Improving CONTACT: Rosemarie Wakelin (LPA) 020 8825 6600 NEW ENTRY: No SITE NAME: Hanwell Village Green, Hanwell DESIGNATION: CONSERVATION: CONSERVATION: CONSERVATION: Rosemarie Wakelin (LPA) 020 8825 6600 NEW ENTRY: No SITE NAME: Hanwell Village Green, Hanwell DESIGNATION: CONSERVATION: CONDITION: POOR POOR POOR	CONTACT:	Rosemarie Wakelin (LPA) 020 8825 6600	NEW ENTRY?:	No
AULNERABILITY: LOW ROSEMARIE Wakelin (LPA) 020 8825 6600 NEW ENTRY: NO SITE NAME: Ealing Town Centre, Ealing DESIGNATION: Conservation Area CONDITION: ROSEMARIE Wakelin (LPA) 020 8825 6600 NEW ENTRY: NO TREND: Deteriorating significantly No Deteriorating significantly No SITE NAME: Hanwell Clock Tower, Hanwell DESIGNATION: Conservation Area CONDITION: Very bad UNUNERABILITY: LOW TREND: Improving NO SITE NAME: Hanwell Village Green, Hanwell DESIGNATION: Conservation Area CONDITION: Poor WILLIERABILITY: LOW TREND: DETERIOR: NO SITE NAME: Hanwell Village Green, Hanwell DESIGNATION: Conservation Area CONDITION: Poor TREND: No SITE NAME: Hanwell Village Green, Hanwell DESIGNATION: CONSERVATION: CONSERVATION: CONSERVATION: CONSERVATION: CONSERVATION: ROSEMARIE Wakelin (LPA) 020 8825 6600 NEW ENTRY: NO TREND: Deteriorating NO POOR WILLIERABILITY: NO TREND: Deteriorating NEW ENTRY: NO SITE NAME: Haven Green, Ealing DESIGNATION: CONDITION: Poor	SITE NAME:	Cuckoo Estate, Hanwell		
Rosemarie Wakelin (LPA) 020 8825 6600 NEW ENTRY: No SITE NAME: Ealing Town Centre, Ealing Conservation Area CONDITION: Poor WULNERABILITY: LOW TREND: Deteriorating significantly No SITE NAME: Hanwell Clock Tower, Hanwell DESIGNATION: Conservation Area CONDITION: Very bad TREND: Improving CONTACT: Rosemarie Wakelin (LPA) 020 8825 6600 NEW ENTRY: No SITE NAME: Hanwell Village Green, Hanwell DESIGNATION: Conservation Area CONDITION: Poor WULNERABILITY: LOW TREND: Deteriorating No SITE NAME: Hanwell Village Green, Hanwell DESIGNATION: Conservation Area CONDITION: Poor WULNERABILITY: LOW TREND: Deteriorating No WULNERABILITY: No SITE NAME: Haven Green, Ealing DESIGNATION: Conservation Area CONDITION: Poor	DESIGNATION:	Conservation Area	CONDITION:	Poor
Ealing Town Centre, Ealing DESIGNATION: Conservation Area CONDITION: Poor WILLIERABILITY: LOW TREND: Deteriorating significantly No SITE NAME: Hanwell Clock Tower, Hanwell DESIGNATION: CONTACT: Rosemarie Wakelin (LPA) 020 8825 6600 TREND: DESIGNATION: Very bad WILLIERABILITY: LOW TREND: Improving CONTACT: Rosemarie Wakelin (LPA) 020 8825 6600 NEW ENTRY: No SITE NAME: Hanwell Village Green, Hanwell DESIGNATION: Conservation Area CONDITION: Poor WILLIERABILITY: LOW TREND: DESIGNATION: CONSERVATION Area CONDITION: Poor Hanwell Village Green, Hanwell DESIGNATION: LOW TREND: Deteriorating NEW ENTRY: No SITE NAME: Haven Green, Ealing DESIGNATION: CONSERVATION Area CONDITION: Poor	VULNERABILITY:	Low	TREND:	Deteriorating
Conservation Area Condition: Poor VULNERABILITY: Low TREND: Deteriorating significantly No SITE NAME: Hanwell Clock Tower, Hanwell Designation: Conservation Area Condition: Very bad VULNERABILITY: Low TREND: Improving CONTACT: Rosemarie Wakelin (LPA) 020 8825 6600 SITE NAME: Hanwell Village Green, Hanwell DESIGNATION: Conservation Area CONDITION: No SITE NAME: Hanwell Village Green, Hanwell DESIGNATION: Conservation Area CONDITION: Poor VULNERABILITY: Low TREND: Deteriorating CONTACT: Rosemarie Wakelin (LPA) 020 8825 6600 SITE NAME: Hanwell Village Green, Hanwell DESIGNATION: Conservation Area CONDITION: No SITE NAME: Haven Green, Ealing DESIGNATION: Conservation Area CONDITION: Poor	CONTACT:	Rosemarie Wakelin (LPA) 020 8825 6600	NEW ENTRY?:	No
TREND: Deteriorating significantly Rosemarie Wakelin (LPA) 020 8825 6600 NEW ENTRY: No SITE NAME: Hanwell Clock Tower, Hanwell DESIGNATION: Conservation Area CONDITION: Very bad VULNERABILITY: LOW TREND: Improving CONTACT: Rosemarie Wakelin (LPA) 020 8825 6600 NEW ENTRY: No SITE NAME: Hanwell Village Green, Hanwell DESIGNATION: Conservation Area CONDITION: Poor VULNERABILITY: LOW TREND: Deteriorating CONTACT: Rosemarie Wakelin (LPA) 020 8825 6600 NEW ENTRY: No SITE NAME: Haven Green, Ealing DESIGNATION: Conservation Area CONDITION: Poor	SITE NAME:	Ealing Town Centre, Ealing		
TREND: Deteriorating significantly Rosemarie Wakelin (LPA) 020 8825 6600 NEW ENTRY: No SITE NAME: Hanwell Clock Tower, Hanwell DESIGNATION: Conservation Area CONDITION: Very bad VULNERABILITY: LOW TREND: Improving CONTACT: Rosemarie Wakelin (LPA) 020 8825 6600 NEW ENTRY: No SITE NAME: Hanwell Village Green, Hanwell DESIGNATION: Conservation Area CONDITION: Poor VULNERABILITY: LOW TREND: Deteriorating CONTACT: Rosemarie Wakelin (LPA) 020 8825 6600 NEW ENTRY: No SITE NAME: Haven Green, Ealing DESIGNATION: Conservation Area CONDITION: Poor	DESIGNATION:	Conservation Area	CONDITION:	Poor
Rosemarie Wakelin (LPA) 020 8825 6600 NEW ENTRY?: No SITE NAME: Hanwell Clock Tower, Hanwell DESIGNATION: Conservation Area CONDITION: Very bad TREND: Improving CONTACT: Rosemarie Wakelin (LPA) 020 8825 6600 NEW ENTRY: No SITE NAME: Hanwell Village Green, Hanwell DESIGNATION: Conservation Area CONDITION: Poor VULNERABILITY: Low TREND: Deteriorating CONTACT: Rosemarie Wakelin (LPA) 020 8825 6600 NEW ENTRY?: No SITE NAME: Haven Green, Ealing DESIGNATION: CONSERVATION: Poor	VULNERABILITY:			
DESIGNATION: Conservation Area CONDITION: Very bad VULNERABILITY: LOW TREND: Improving CONTACT: Rosemarie Wakelin (LPA) 020 8825 6600 NEW ENTRY?: NO SITE NAME: Hanwell Village Green, Hanwell DESIGNATION: Conservation Area CONDITION: Poor VULNERABILITY: LOW TREND: Deteriorating CONTACT: Rosemarie Wakelin (LPA) 020 8825 6600 NEW ENTRY?: NO SITE NAME: Haven Green, Ealing DESIGNATION: CONSERVATION: Poor	CONTACT:			
VULNERABILITY: LOW ROSEMARIE WAKEIIN (LPA) 020 8825 6600 NEW ENTRY: NO SITE NAME: Hanwell Village Green, Hanwell DESIGNATION: Conservation Area CONDITION: Poor VULNERABILITY: LOW TREND: Deteriorating ROSEMARIE WAKEIIN (LPA) 020 8825 6600 NEW ENTRY: NO SITE NAME: Haven Green, Ealing DESIGNATION: CONSERVATION: CONSERVATION: Poor	SITE NAME:	Hanwell Clock Tower, Hanwell		
VULNERABILITY: LOW ROSEMARIE WAKEIIN (LPA) 020 8825 6600 NEW ENTRY: NO SITE NAME: Hanwell Village Green, Hanwell DESIGNATION: Conservation Area CONDITION: Poor VULNERABILITY: LOW TREND: Deteriorating ROSEMARIE WAKEIIN (LPA) 020 8825 6600 NEW ENTRY: NO SITE NAME: Haven Green, Ealing DESIGNATION: CONSERVATION: CONSERVATION: Poor	DESIGNATION:	Conservation Area	CONDITION:	Very bad
Rosemarie Wakelin (LPA) 020 8825 6600 NEW ENTRY?: No SITE NAME: Hanwell Village Green, Hanwell DESIGNATION: Conservation Area CONDITION: Poor VULNERABILITY: LOW TREND: Deteriorating CONTACT: Rosemarie Wakelin (LPA) 020 8825 6600 NEW ENTRY?: No SITE NAME: Haven Green, Ealing DESIGNATION: CONSERVATION Area CONDITION: Poor				,
DESIGNATION: Conservation Area CONDITION: Poor VULNERABILITY: LOW TREND: Deteriorating CONTACT: Rosemarie Wakelin (LPA) 020 8825 6600 NEW ENTRY: No DESIGNATION: CONSERVATION: Poor	CONTACT:			
DESIGNATION: Conservation Area CONDITION: Poor VULNERABILITY: LOW TREND: Deteriorating CONTACT: Rosemarie Wakelin (LPA) 020 8825 6600 NEW ENTRY: No DESIGNATION: CONSERVATION: Poor	SITE NAME:	Hanwell Village Green, Hanwell		
VULNERABILITY: LOW TREND: Deteriorating CONTACT: Rosemarie Wakelin (LPA) 020 8825 6600 NEW ENTRY: No SITE NAME: Haven Green, Ealing DESIGNATION: Conservation Area CONDITION: Poor	DECICNIATION	-	CONDITION	Poor
CONTACT: Rosemarie Wakelin (LPA) 020 8825 6600 NEW ENTRY?: No SITE NAME: Haven Green, Ealing DESIGNATION: Conservation Area CONDITION: Poor				
designation: Conservation Area condition: Poor	CONTACT:			
designation: Conservation Area condition: Poor	SITE NAME:	Haven Green, Ealing		
	DECICNIATION	•	CONDITION	Poor
TOUR DOUGHOUTE				
D ' \A\ ' \	CONTACT:			

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category
has changed since the 2010
register, the previous category
is given in brackets.

ABBREVIATIONS

CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

SITE NAME:	Northold Village Green, Northolt		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating significantly
CONTACT:	Rosemarie Wakelin (LPA) 020 8825 6600	NEW ENTRY?:	No
SITE NAME:	Norwood Green, Southall		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating significantly
CONTACT:	Rosemarie Wakelin (LPA) 020 8825 6600	NEW ENTRY?:	No
SITE NAME:	St Mark's Church and Canal, Hanwell		
SITE NAME: DESIGNATION:	St Mark's Church and Canal, Hanwell Conservation Area	CONDITION:	Poor
	·	CONDITION: TREND:	Poor Deteriorating
DESIGNATION:	Conservation Area		· ·
DESIGNATION: VULNERABILITY:	Conservation Area Low	TREND:	Deteriorating
DESIGNATION: VULNERABILITY:	Conservation Area Low	TREND:	Deteriorating
DESIGNATION: VULNERABILITY: CONTACT:	Conservation Area Low Rosemarie Wakelin (LPA) 020 8825 6600	TREND:	Deteriorating
DESIGNATION: VULNERABILITY: CONTACT: SITE NAME:	Conservation Area Low Rosemarie Wakelin (LPA) 020 8825 6600 St Stephen's, Ealing	TREND: NEW ENTRY?:	Deteriorating No
DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION:	Conservation Area Low Rosemarie Wakelin (LPA) 020 8825 6600 St Stephen's, Ealing Conservation Area	TREND: NEW ENTRY?: CONDITION:	Deteriorating No Poor





SITE NAME: Broomfield House, Broomfield Park, Broomfield Lane

DESIGNATION: Listed Building Grade II*, RPG II

CONDITION: Very bad OCCUPANCY: Vacant PRIORITY: C (D)

OWNER TYPE: Local authority

C16 house with late C18 additions, situated in public park. Severely fire damaged. Consents granted October 2003 for community, restaurant, function rooms and educational facilities. A scheme for sheltered housing is under consideration.

Contact: Dorian Crone 020 7973 3763



Stable block in Broomfield Park,
Broomfield Lane

DESIGNATION: Listed Building Grade II*, RPG II

CONDITION: Poor
OCCUPANCY: Vacant
PRIORITY: C (C)

OWNER TYPE: Local authority

Early C18 stable block to Broomfield House. Currently empty although weathertight and secure. Scheme for sheltered housing under consideration.



SITE NAME: Nonconformist Chapel, Lavender Hill Cemetery, Cedar Road

DESIGNATION: Listed Building Grade II

CONDITION: Poor
OCCUPANCY: Vacant
PRIORITY: C (C)

OWNERTYPE: Local authority

1870-1 Gothic Revival cemetery chapel. In need of an appropriate use. In poor condition.

Contact: Christine White (LPA) 020 8379 3852

Contact: Dorian Crone 020 7973 3763



Former Edmonton
Girl's Charity School,
Church Street, Edmonton

DESIGNATION: Listed Building Grade II, CA CONDITION: Fair

Part occupied

PRIORITY: C (New entry)
OWNER TYPE: Charity

OCCUPANCY:

Single storey building, central arched doorway to the street and sash window to either side, externally above doorway is a statuette of a female pupil. A panel below has inscribed "A structure of Hope, Founded in Faith and Based on Charity, 1784". The building is used by community groups. Condition of the building is slowly deteriorating and the current use is unable to provide adequate income

for its upkeep.

Contact: Christine White (LPA) 020 8379 3852

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



SITE NAME: 24 Church Street, Edmonton

DESIGNATION: Listed Building Grade II, CA

occupancy: Occupied

PRIORITY: C (New entry)

OWNERTYPE: Charity

Former teacher's accommodation to the Charity School adjoining. C18 cottage of red brick with renewed pantiled roof. Two storeys, two windows, those on the 1st floor modern casements; ground floor windows are sash with glazing bars in box frames. Doorways with architrave, cut brackets, frieze and dentilled comice hood. Building is slowly deteriorating with worthwhile but financially unviable usage.

Contact: Christine White (LPA) 020 8379 3852



SITE NAME: Statue of Hercules and Autaeus, Bramley Road,

Trent Park


DESIGNATION: Listed Building Grade II, CA, RPG II

CONDITION: Very bad OCCUPANCY: N/A PRIORITY: B (B)

OWNERTYPE: Educational Body

Statue of circa I700 by Nost after da Bologna, brought from Stowe Park, Buckinghamshire in the I920s by Sir Philip Sassoon. To be relocated to Stowe for conservation work and returned to Trent Park, and Stowe to have a replica statue, timetable to be established.

Contact: Christine White (LPA) 020 8379 3852



SITE NAME: Statue of Samson defeating a Philistine, Bramley Road, Trent Park

DESIGNATION: Listed Building Grade II, CA, RPG II

CONDITION: Very bad

OCCUPANCY: N/A
PRIORITY: B (B)

OWNER TYPE: Educational Body

Statue of circa 1700 by Nost after da Bologna, brought from Stowe Park, Bucks, in the 1920s by Sir Philip Sassoon. Middlesex University have agreed with the National Trust that the statue will be repaired, a copy made for Stowe, the original to return to Trent Park Timetable awaited.

Contact: Christine White (LPA) 020 8379 3852



Trent Park House terrace, Cockfosters Road,

Trent Park

DESIGNATION: Listed Building Grade II, CA, RPG II

CONDITION: Very bad OCCUPANCY: N/A
PRIORITY: C (C)

OWNERTYPE: Educational Body

Brick and stone terrace reconstructed in the 1920s. The terrace is in poor condition and needs repair and repaving.





SITE NAME: Trent Park

DESIGNATION: Registered Park and Garden Grade II,

also CA, 19 LBs, 1 SM

CONDITION: Generally satisfactory but with

significant localised problems

VULNERABILITY: Medium
TREND: Declining

OWNER TYPE: Mixed, multiple owners

Late C18 landscape park further developed early C20 by Sir Philip Sassoon. The central mansion house, gardens and pleasure grounds are occupied by Middlesex University and the surrounding parkland is managed by Enfield as a country park. The mansion house's terrace and a number of statues are at risk. The garden sculptures will be restored and replicas placed in National Trust Gardens. The restored originals will be returned to Trent Park, however the time scale has not been confirmed.

Contact: Zosia Mellor 020 7973 3473



SITE NAME: Truro House and stable block, 176 Green Lanes

DESIGNATION: Listed Building Grade II

CONDITION: Poor
OCCUPANCY: Vacant
PRIORITY: C (C)

OWNERTYPE: Company

Early to mid C19 detached villa with C19 stable block. Enfield have written to owners with a suggested schedule for repair works, awaiting timetable. A residential scheme was agreed in 2009 and the legal agreement remains to be concluded.

Contact: Christine White (LPA) 020 8379 3852

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified, or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS



Enfield Electricity Works, SITE NAME: 20 Ladysmith Road,

Enfield

Former Enfield Electricity Works 1906, architect unknown. Partially occupied. Future operational requirements under consideration.

DESIGNATION: Listed Building Grade II

Fair CONDITION:

Part occupied OCCUPANCY:

C (C) PRIORITY

Former utility OWNER TYPE:

Contact: Christine White (LPA) 020 8379 3852



Barn at Whitewebbs Farm, SITE NAME: Whitewebbs Road EN2

DESIGNATION: Listed Building Grade II

Very bad CONDITION: Vacant OCCUPANCY: A(A)PRIORITY:

OWNER TYPE: Company

Simple, timber-framed barn probably dating from later C17. The barn has partly collapsed. A variation to an approved scheme for residential conversion is under consideration.

Contact: Christine White (LPA) 020 8379 3852



Grovelands Park SITE NAME:

DESIGNATION: Registered Park and Garden Grade II*,

Generally satisfactory but with

significant localised problems

VULNERABILITY: Medium

Declining TREND

Mixed, multiple owners OWNER TYPE:

Late C18 landscape park and lake by Humphry Repton, extended in the mid C19, and laid out as a public park in early C20 by Thomas Mawson. The mansion is now a private hospital. The management is fragmented due to the separate ownerships. Enfield Borough Council has produced a historic environment assessment and is implementing repair and restoration of the park.

Contact: Zosia Mellor 020 7973 3473



All Saint's Church, SITE NAME: Church Street

DESIGNATION: Listed Place of Worship Grade II*, CA

Very bad CONDITION:

PRIORITY: B (C)

OWNER TYPE: Religious organisation

C15 parish church. Restored in 1855 and 1871 by Ewan Christian and 1889 by W Gilbee Scott. There are monuments to Charles Lamb and William Cowper. The east end has a spectacular Victorian wall painting of angels and saints. Following a very bad winter the tower stonework and roofs are now in a poor condition. English Heritage / Heritage Lottery Fund have awarded a grant for tower repairs and development phase is underway.

Contact: Don Bianco 020 7973 3745

	1000				Vil
				100	
					ı
			層		
	21		題		
- 56	September 1	100	1000		

SITE NAME

DESIGNATION:

Old Park moated site, Enfield

Scheduled Monument (No. 1001972) CONDITION: Generally satisfactory

but with significant localised problems

Scrub / tree growth Declining PRINCIPAL VULNERABILITY: TREND:

Local Authority Jane Sidell 020 7973 3738 OWNER TYPE: CONTACT:

SITE NAME:	Church	Street.	Edmonton

DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	No significant change
CONTACT:	Mike Brown (LPA) 0208 379 3865	NEW ENTRY?:	No

Fore Street, Edmonton

DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Improving
CONTACT:	Mike Brown (LPA) 0208 379 3865	NEW ENTRY?:	No

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS

GREENWICH



Lock and Swing Bridge, SITE NAME: **Broadwater Estate SE28**

DESIGNATION: Listed Building Grade II

Poor CONDITION: N/A C(C)PRIORITYowner type: Company The canal was built 1812-14 to bring supplies into the Arsenal. The swing bridge was built circa 1876 to carry railway tracks across the canal. Some work was done to the bridge in the early 1980s but since then the lock and bridge have both lain derelict.

Contact: Steve Crow (LPA) 020 8921 5034



Garden House to north west SITE NAME: of Charlton House,

Charlton Road, Charlton SE7

DESIGNATION: Listed Building Grade I, CA

CONDITION: Vacant OCCUPANCY: C(C)PRIORITY:

OWNERTYPE: Local authority

Small red brick garden house with undercroft. High pyramidal swept roof. Mid to late C17 and attributed to Inigo Jones. Previously used as a public lavatory, now vacant. In need of repair, maintenance and beneficial use.

Contact: Malcolm Woods 020 7973 3769



SITE NAME: The Cutty Sark, Cutty Sark Gardens SE10

DESIGNATION: Listed Building Grade I, CA, WHS

Poor CONDITION: N/A F (F) PRIORITY Trust OWNER TYPE:

The Cutty Sark is the internationally renowned tea clipper, launched 1869, and the fastest ship of her time. She is now the national memorial for maritime sailors, and a museum. Repairs scheme funded by the Heritage Lottery Fund with additional grant following a fire in May 2007, approaching completion. Due to reopen in 2012.

Contact: Malcolm Woods 020 7973 3769



SITE NAME: 24 Royal Hill SE10

DESIGNATION: Listed Building Grade II, CA CONDITION: OCCUPANCY: Vacant D (C) PRIORITY Private OWNER TYPE:

Early C18 small urban house of central chimneystack plan, smallest known example of the 1703 Moxon Plan. Vacant for some years and in poor condition. Scheme for restoration and conversion recently agreed but not yet implemented.

Contact: Steve Crow (LPA) 020 8921 5034



70-84 River Way SEI0 SITE NAME:

DESIGNATION: Listed Building Grade II Fair CONDITION: Part occupied OCCUPANCY:

PRIORITY: C (C) OWNER TYPE: Quango

Row of eight cottages, according to date-stone built in 1801 and known as Ceylon Place. Constructed for workers at adjacent tidal mill and chemical works and a rare survival of late Georgian artisans' housing. Partially vacant and, due to isolated location, vulnerable to vandalism.

Contact: Steve Crow (LPA) 020 8921 5034



Old brick wall between gardens SITE NAME in front of Nos. 34 and 36,

Court yard, Eltham SE9

DESIGNATION: Listed Building Grade II*, CA

CONDITION: Fair N/A OCCUPANCY: PRIORITY: C(C)OWNERTYPE: Private

Brick wall with sloped coping of C16 appearance. In poor structural condition and suffering from vandalism.

Contact: Malcolm Woods 020 7973 3769

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

CA LB/LBs LPA NP UA WHS



ITE NAME:	Winter Garden of former
	Avery Hill Training College,
	Bexley Road, Eltham SE9

DESIGNATION: Listed Building Grade II

CONDITION: Poor N/A OCCUPANCY: F (F) PRIORITY:

OWNER TYPE: **Educational Body** Large conservatory with domed glass roofs, surmounted by a figure of Mercury. Built in 1889 in a classical style previously suffering from long term neglect and major deterioration of the fabric. Access to some parts was restricted on health and safety grounds. Listed building consent approved in 2009 for comprehensive internal repairs and renovations. Restoration of the East House is now complete.

Contact: Steve Crow (LPA) 020 8921 5034



95A Eltham High Street, SITE NAME: Eltham SE9

DESIGNATION: Listed Building Grade II

Fair CONDITION:

Part occupied OCCUPANCY:

C (C) PRIORITY-OWNER TYPE: Private

C17 or earlier stable building with three diagonal chimney shafts. Although it has been made weathertight, it is vulnerable to vandalism and pigeons. Previously in use as a joinery workshop, most appropriate future uses would be commercial/office use. Currently in residential use and subject to enforcement action.

Contact: Steve Crow (LPA) 020 8921 5034



Coronet Cinema, SITE NAME: Well Hall Road, Eltham SE9

DESIGNATION: Listed Building Grade II

Poor CONDITION: Vacant OCCUPANCY: F(D) PRIORITY:

OWNER TYPE: Company

Former Odeon cinema built 1936 to the design of Andrew Mather and Horace Ward. Faience cladding to front. Good internal features in foyers, stairs and auditorium. Closed in 1999 and subject to vandalism. Now in new ownership. Planning permission and listed building consent granted in 2008; redevelopment scheme underway.

Contact: Steve Crow (LPA) 020 8921 5034



SITE NAME: Orangery to former Eltham House, Eltham High Street (north side), Eltham SE9

DESIGNATION: Listed Building Grade II*

CONDITION: Fair Vacant E (New entry) PRIORITY-

Orangery, 1717-25, to Eltham House (demolished in the 1920s). A fine example of a Baroque garden building. A long running building at risk case. It was repaired, converted to an office and removed from the Register in 2003. A scheme for reuse and redevelopment to west of the Orangery approved in 2010 but not implemented and building remains vacant.

Contact: Malcolm Woods 020 7973 3769



The Greyhound Public House, SITE NAME: 86 Eltham High Street, Eltham SE9

DESIGNATION: Listed Building Grade II

Company

Poor Vacant OCCUPANCY: C (D) PRIORITY-

OWNER TYPE: Company

Unusual early C18 house with two entrance doorways. Vacant for a number of years and deteriorating. Scheme for repair and refurbishment approved in 2009 but not implemented. Under new ownership. New scheme under consideration.

Contact: Steve Crow (LPA) 020 8921 5034



SITE NAME: Enderby House, 100 Christchurch Way, Greenwich SEI0

DESIGNATION: Listed Building Grade II

Very bad CONDITION: Vacant PRIORITY: B (New entry)

OWNER TYPE: Company

Early-mid C19 wharf-side building of Samuel Enderby, largest whalers and sealers in Britain and pioneers of Atlantic exploration. Unusual octagonal room giving onto projecting bay, allowing views of approaching vessels. Vandalism, lack of security and exposure to the elements has resulted in deterioration of the fabric. Scheme agreed in principle, subject to a Section 106 agreement, but currently unresolved.

Contact: Rebecca Duncan (LPA) 020 8921 5355

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



Severndroog Castle, SITE NAME: Shooters Hill SE18

DESIGNATION: Listed Building Grade II*

Fair CONDITION: Vacant OCCUPANCY:

D(D)PRIORITY:

OWNER TYPE: Local authority

Gothick tower built in 1784 to commemorate the conquest of the Malabar Coast by Sir William James in 1755. Stands in woodlands and suffers from vandalism. Preservation Trust set up to secure restoration of the building. Heritage Lottery Funded scheme of repairs and alterations agreed, with English Heritage grant.

Contact: Malcolm Woods 020 7973 3769



91 Genesta Road, SITE NAME: Woolwich SE18

DESIGNATION: Listed Building Grade II*

Poor CONDITION: Vacant

C (New entry) PRIORITY:

OWNERTYPE: Unknown

Part of a terrace of four houses, numbers 85 to 91 by Berthold Lubetkin 1933-4. Reinforced concrete construction with flat roof. Original Crittall metal window frames, and with distinctive classic Lubetkin design. The only completed terrace in England built in the modern idiom during the 1930s. Lack of maintenance and neglect have resulted in external deterioration with concrete cracking and spalling.

Contact: Malcolm Woods 020 7973 3769



The Rotunda, SITE NAME:

Greenhill, Woolwich Common, Woolwich SE18

DESIGNATION: Listed Building Grade II*

Fair CONDITION: Vacant OCCUPANCY: C (C) PRIORITY:

OWNERTYPE: Government

24-side polygon, single storey building designed by John Nash. Concave conoid lead-covered roof; first erected in grounds of Carlton House in 1814 for (premature) celebration of Allied victory in Napoleonic wars. Housed the reserve collection of 'Firepower' museum but now vacant. Lead-sheet roof covering is failing.

Contact: Alan Johnson 020 7973 3174



SITE NAME: Drinking Fountain,

Ha Ha Rd/Woolwich Common SE18

Obelisk of unpolished granite. Inscription to Robert John Little of Royal Marines (died 1861). Funding for restoration in place; scheme currently being drawn up.

DESIGNATION: Listed Building Grade II, CA Fair CONDITION: N/A D(C)PRIORITY-

OWNER TYPE: Unknown

Contact: Steve Crow (LPA) 020 8921 5034



Former Granada Cinema, SITE NAME: 174-186 Powis Street,

Woolwich SE18

DESIGNATION: Listed Building Grade II*

CONDITION: occupancy: Occupied

A (New entry) PRIORITY:

OWNER TYPE: Company

Former Granada Cinema, built 1936-7 and designed by Cecil Masey and Reginald Uren with interior design by Theodore Komisarjevsky. Since 1966 it has operated as a Bingo club. There is evidence of severe water penetration. Roof repairs are required.

Contact: Malcolm Woods 020 7973 3769



SITE NAME: Royal Military Academy, Academy Road,

Woolwich SE18

DESIGNATION: Listed Building Grade II*, CA

Fair CONDITION: Vacant PRIORITY: F (F) OWNERTYPE: Private

Military college built 1805 to the designs of James Wyatt. Site sold and planning permission granted for residential conversion. Works on site began Spring 2008, and are continuing in phases.

Contact: Malcolm Woods 020 7973 3769

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS



Gatehouse to former Red Barracks, SITE NAME: Frances Street.

Woolwich SE18

DESIGNATION: Listed Building Grade II Fair CONDITION:

C(C)PRIORITY

OCCUPANCY:

OWNER TYPE: Local authority

Vacant

Probably built in 1859 at same time as main Barracks building (now demolished), originally a Marine Infirmary. Roofless shell but structurally sound. Repair and refurbishment of railings and wall completed. Ruined remains of the gatehouse stabilised but long-term use to be agreed. Further repairs to be implemented.

Contact: Steve Crow (LPA) 020 8921 5034



Riverside Guard Rooms, SITE NAME: Royal Arsenal, Plumstead Road, Woolwich SE18

DESIGNATION: Listed Building Grade II, CA

Fair CONDITION: Vacant E (E) PRIORITY: owner type: Company

Royal Arsenal's guardrooms, 1814. The Royal Arsenal site is owned by Berkeley Homes who are progressing repairs. Planning permission has been given for Arsenal master plan. Shell repairs have been carried out.

Contact: Steve Crow (LPA) 020 8921 5034



Royal Laboratory to Royal Arsenal, SITE NAME: Plumstead Road. Woolwich SE18

DESIGNATION: Listed Building Grade II, CA

Very bad CONDITION: Vacant OCCUPANCY: C(C)PRIORITY:

OWNERTYPE: Company

Royal Arsenal's laboratory, two buildings originally built in 1696, reconstructed 1802 after fire. Both buildings secured and within the area covered by the Arsenal master plan. Scheme for restoration and conversion to residential use agreed in principle and applications for planning permission and LBC expected Spring 2011.

Contact: Steve Crow (LPA) 020 8921 5034



Officers Quarters, SITE NAME: Royal Arsenal (building II), Seymour Street, Woolwich SE18

DESIGNATION: Listed Building Grade II

CONDITION: Poor Vacant C(C)PRIORITY-Quango

OWNER TYPE:

Officers block for Royal Academy 1717-20. The Royal Arsenal site is owned by the London Development Agency which is progressing repairs. A master plan for the whole site has been approved by the Local Authority. Proposals for shell repairs have been submitted. Currently protected by sheeted scaffold and temporary roof, but much timber decay in interior.

Contact: Steve Crow (LPA) 020 8921 5034



Government House, SITE NAME: Woolwich New Road, Woolwich SE18

DESIGNATION: Listed Building Grade II CONDITION:

Vacant OCCUPANCY: D (C) PRIORITY-OWNERTYPE: Private House circa 1800, set in fairly extensive grounds in isolated site. Severe internal damage caused by periodic attacks of vandalism. Built originally as private dwelling, it was used by the military from 1841-1937. Urgent works carried out early 2010 to enhance security and increase ventilation and weatherproofing. Scheme for restoration, conversion and enabling development agreed in 2010 but not implemented.

Contact: Steve Crow (LPA) 020 8921 5034



Garrison Church of St George, SITE NAME: Grand Depot Road, Royal Artillery Barracks, Woolwich SE18

DESIGNATION: Listed Building Grade II

Poor CONDITION: N/A OCCUPANCY: PRIORITY: D (D) OWNER TYPE: Government

Redundant Italianate church of 1863, a roofless ruin after bomb damage in 1944. Temporary scaffolding now in place to protect mosaics, including one commemorating members of the Royal Artillery awarded the Victoria Cross. The last remaining Royal Artillery Regiment departed Woolwich June 2007. Scheme to stabilise and protect ruined structure currently under consideration.

Contact: Steve Crow (LPA) 020 8921 5034

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented

NOTE:

If the priority category has changed since the 2010 register, the previous category given in brackets

ABBREVIATIONS

Conservation Area CA LB/LBs Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s LPA NP RPG SM/SMs UA WHS



SITE NAME: Church of St Mary Magdalene, Church Hill, Woolwich SE18

DESIGNATION: Listed Place of Worship Grade II*

Poor CONDITION:

PRIORITY: A (New entry)

Religious organisation OWNER TYPE:

Nave and tower built 1732-8 in stock brick with Portland stone dressing. East end added by Scott 1894. There has been a recent serious outbreak of dry rot following roof leaks from defects in valley gutters and flashing. Emergency investigations underway to determine scope of works to prevent further deterioration. An application for grant aid is anticipated.

Contact: Donald Wahlberg 020 7973 3786

SITE NAME:	Linear Training Fortification, Royal Military Repository, Greenwich		
DESIGNATION:	Scheduled Monument (No. 1021456)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Jane Sidell 020 7973 3738

HACKNEY

Cleeve Workshops, SITE NAME: Calvert Avenue E2

DESIGNATION: Listed Building Grade II, CA

Part occupied OCCUPANCY:

PRIORITY: C (C) OWNER TYPE: Private

Contact: Margaret Gustafsson (LPA) 020 8356 8605

local authority.




7 Clapton Square E5 SITE NAME:

Early C19 terraced house. Local authority enforcement action taken against unauthorised works.

Row of workshops, built 1895-8 to the design of Reginald

the Boundary Estate. Some are in use but all require repair. The owners have had pre-application discussions with the

Minton Taylor of the London County Council as part of




Contact: Margaret Gustafsson (LPA) 020 8356 8605



55 and 59 Clapton Terrace N16 SITE NAME:

Terraced houses, mid to late C18. Suffering from disrepair and under use.



Contact: Margaret Gustafsson (LPA) 020 8356 8605



Clissold House. SITE NAME: Clissold Park N16

DESIGNATION: Listed Building Grade II*, CA, RPG II

Good CONDITION: OCCUPANCY: Vacant PRIORITY F (F)

OWNER TYPE: Local authority

House built circa 1770 for Jonathan Hoare, a Quaker banker. Located in late C18 park, developed in 1880s into public park. Repair works are in progress and completion anticipated autumn 2011. Building currently vacant during repair works.

Contact: Rachel Godden 020 7973 3716

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



Marlow House, SITE NAME: 160 Dalston Lane F8 Early-mid C18 house. Listed building consent granted for conversion to residential and works expected throughout 2011.

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION:

Part occupied OCCUPANCY:

D (D) PRIORITY: Private

Contact: Margaret Gustafsson (LPA) 020 8356 8605



St Columba's Vicarage SITE NAME: and link to church. Kingsland Road E2

DESIGNATION: Listed Building Grade I, CA

Poor CONDITION: Occupied OCCUPANCY: C (C) PRIORITY:

OWNER TYPE: Religious organisation

Gothic Revival vicarage built 1873-4 to design of James Brooks. Feasibility study grant-aided by English Heritage to assess condition and explore compatible new uses. Proposals are awaited from the owners.

Contact: Rachel Godden 020 7973 3716



320 Kingsland Road E8 SITE NAME:

Early C19 terraced house suffering from under use and lack of maintenance.



Contact: Margaret Gustafsson (LPA) 020 8356 8605



SITE NAME: 592 Kingsland Road E8

C18 terraced house. Shop on ground floor. Upper floors disused. Listed building consent granted in 2008 for rebuilding the upper parts of the north and east wall following DESIGNATION: Listed Building Grade II, CA structural problems. Poor

Part occupied D (D) PRIORITY-

CONDITION:

OWNER TYPE:

Contact: Margaret Gustafsson (LPA) 020 8356 8605



The Griffin, SITE NAME: Leonard Street EC2

Private

Public house circa 1889. Suffering from lack of maintenance. Proposals awaited from owners in conjunction with adjoining site.

DESIGNATION: Listed Building Grade II, CA CONDITION: Occupied OCCUPANCY: C (C) PRIORITY-OWNERTYPE: Private

Contact: Margaret Gustafsson (LPA) 020 8356 8605



SITE NAME: Forecourt wall to Pond House, 162 Lower Clapton Road E5

Forecourt wall, early C19. In need of extensive repair. See entry for Pond House.

DESIGNATION: Listed Building Grade II, CA Very bad CONDITION: N/A OCCUPANCY: PRIORITY: C(C)

Contact: Margaret Gustafsson (LPA) 020 8356 8605

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

OWNER TYPE: Company

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS



Pond House, SITE NAME: 162 Lower Clapton Road E5

DESIGNATION: Listed Building Grade II*, CA

Poor CONDITION: Vacant OCCUPANCY: C(C)

OWNER TYPE: Company

Villa circa 1800. In need of repair and full beneficial use. Applications for planning permission and listed building consent for repair and residential conversion submitted May 2011.

Contact: Rachel Godden 020 7973 3716



Stables to north of Pond House, SITE NAME: 162 Lower Clapton Road E5

DESIGNATION: Listed Building Grade II, CA

Very bad CONDITION: Vacant A(A)PRIORITY: Company OWNER TYPE:

Early C19 stable block. In need of repair and full beneficial use. Repairs for planning permission and listed building consent for repair and residential conversion submitted May 2011.

Contact: Margaret Gustafsson (LPA) 020 8356 8605



New Lansdowne Club, SITE NAME: 195 Mare Street E8

DESIGNATION: Listed Building Grade II*

Poor CONDITION:

PRIORITY:

Part occupied OCCUPANCY: C(C)

OWNER TYPE: Company

Substantial detached house, 1715. Front elevation repaired after enforcement warning from the Local Authority. Receivers handling new uses and potential sale of the property in 2011.

Contact: Rachel Godden 020 7973 3716



Hackney Borough Disinfecting Station, SITE NAME: Millfields Road E5

DESIGNATION: Listed Building Grade II

CONDITION: Poor Vacant C(C)PRIORITY:

Local authority OWNER TYPE:

Disinfecting station. Built 1900. Site used as an animal warden's base and as the Council's cleansing depot. Proposals underway to make building watertight pending feasibility study for new uses.

Contact: Margaret Gustafsson (LPA) 020 8356 8605



Court House and Police Station, SITE NAME: Old Street ECI

DESIGNATION: Listed Building Grade II

CONDITION: Vacant OCCUPANCY: D (D) PRIORITY-OWNERTYPE: Private Former magistrates' court and police station. Planning permission and listed building consent granted in 2010 for conversion to hotel but work not yet started on site.

Contact: Margaret Gustafsson (LPA) 020 8356 8605



Air Raid Precaution Centre, SITE NAME: Rossendale Street (east side) E5

DESIGNATION: Listed Building Grade II Poor CONDITION: Vacant

D (D) OWNERTYPE: Local authority

PRIORITY:

Air raid shelter. Built in 1938. Suffered from flooding and in poor condition. Potential uses very limited. "Adopted" as a monument by local school, Horizon School in Stoke Newington. Planning permission and listed building consent granted in 2004 for retention of air raid shelter as a museum and construction of flats above. Demolition of later structure above air raid shelter complete.

Contact: Margaret Gustafsson (LPA) 020 8356 8605

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS CA LB/LBs LPA NP



Walls and gates SITE NAME:

> to Bishopsgate Goods Station, Shoreditch High Street EI

DESIGNATION: Listed Building Grade II

Poor CONDITION: N/A OCCUPANCY: D(D)PRIORITY: OWNER TYPE: Company Late C19 walls to demolished goods station. Gates have been repaired off site. Future use of structure currently being discussed as part of the redevelopment of the Goods Yard.

Contact: Margaret Gustafsson (LPA) 020 8356 8605



SITE NAME: 187 Shoreditch High Street EI

DESIGNATION: Listed Building Grade II

Very bad CONDITION: Vacant OCCUPANCY: A(A)PRIORITY: Company OWNER TYPE:

Early C18 terraced house with altered facade. Vacant and in deteriorating condition. Temporary tarpaulin covering dormer and roof to provide protection against water ingress. Pre-application discussions underway with local planning authority.

Contact: Margaret Gustafsson (LPA) 020 8356 8605



196 Shoreditch High Street EI SITE NAME:

DESIGNATION: Listed Building Grade II CONDITION: Good Part occupied OCCUPANCY: PRIORITY: F (E) OWNERTYPE: Quango

works now complete and upper floors occupied. Pre-application discussions underway for use of ground floor.

Early C18 building. Stabilisation and repair



Walls to St Leonard's Churchyard, SITE NAME: Shoreditch High Street

and Boundary Street EI

DESIGNATION: Listed Building Grade II, CA

CONDITION: Poor N/A C (F) PRIORITY:

Local authority OWNER TYPE:

The C19 churchyard walls and stone coped brick piers that occur at intervals along the walls are in poor repair with missing bricks, plant growth, missing or inappropriate pointing and damaged stone coping. C18 and C19 railings and gates around forecourt to St Leonard's Church were repaired in 2010 with grant aid from English Heritage. The churchyard is maintained by London Borough of Hackney.

Contact: Margaret Gustafsson (LPA) 020 8356 8605

Contact: Margaret Gustafsson (LPA) 020 8356 8605



Shrubland Road Evangelical Church, SITE NAME:

An early, rare, and complete example of a temporary iron Shrubland Road E8 mission church. In need of some repair. Church is being advertised for sale, presumed vacant.

DESIGNATION: Listed Building Grade II, CA CONDITION: Vacant OCCUPANCY: C (C) PRIORITY OWNERTYPE: Private

Contact: Margaret Gustafsson (LPA) 020 8356 8605



SITE NAME: White Lodge, Springfield Park E5

Early/mid C19 villa. Café on ground floor. Application for listed building consent in preparation for repair and for use of the upper floor for community uses.



Contact: Margaret Gustafsson (LPA) 020 8356 8605

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: If the priority category has changed since the 2010 register, the previous category

is given in brackets

CA LB/LBs LPA NP RPG SM/SMs UA WHS



91 Stoke Newington Church Street N16 Mid C18 house of three storeys with pedimented front. Although at least partially occupied, the building is falling into disrepair.

DESIGNATION: Listed Building Grade II, CA

condition: Poor

occupancy: Part occupied

PRIORITY: C (C)
OWNER TYPE: Private

Contact: Margaret Gustafsson (LPA) 020 8356 8605



Monuments at Abney Park Cemetery, Stoke Newington High Street N16

Laid out as arboretum cemetery in 1840 from gardens of two C17 houses. London's most important Nonconformist cemetery. Chapel ruinous; landscape and many tombs and

monuments in poor condition.

DESIGNATION: Listed Building Grade II, CA, RPG II

condition: Poor occupancy: N/A PRIORITY: C (C)

OWNER TYPE: Local authority

Contact: Margaret Gustafsson (LPA) 020 8356 8605



SITE NAME: Mortuary Chapel,
Abney Park Cemetery,
Stoke Newington High Street N16

DESIGNATION: Listed Building Grade II, CA, RPG II

CONDITION: Very bad
OCCUPANCY: Vacant

PRIORITY: A (A)
OWNER TYPE: Trust

Gothic Revival cemetery chapel, 1839, now ruinous. Situated in the centre of the early C19 cemetery and a feature of views along the main avenues. See entry for Abney Park Cemetery.

Contact: Margaret Gustafsson (LPA) 020 8356 8605



SITE NAME: Abney Park Cemetery

DESIGNATION: Registered Park and Garden Grade II,

also CA, 16 LBs

сомытюм: Extensive significant problems

vulnerability: High

TREND: Declining

OWNER TYPE: Corporate, single owner

Laid out as an arboretum cemetery in 1840 from the gardens of two C17 houses. London's most important Nonconformist cemetery. The landscape, many tombs and monuments are in poor condition; the chapel is a building at risk in very bad condition. Stakeholder meetings are planned throughout 2011 to discuss and agree a future strategy for repairs and improvements.

Contact: Zosia Mellor 020 7973 3473



Premises of Testi and Sons Millwrights, Waterworks Lane E5

DESIGNATION: Listed Building Grade II, CA

CONDITION: Poor
OCCUPANCY: Vacant
PRIORITY: C (E)
OWNER TYPE: Company

Mid C19 Tudor style building, probably originally a school. Currently vacant. Surrounding redevelopment completed but new use required for this building. Repairs required to roof and stonework.

Contact: Margaret Gustafsson (LPA) 020 8356 8605



SITE NAME: Haggerston Baths, Whiston Road E2

Public baths and swimming pool, 1904. Now vacant. Pre application discussions took place during 2010.



PRIORITY: C (C)
OWNER TYPE: Local authority

Contact: Margaret Gustafsson (LPA) 020 8356 8605

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA C
LB/LBs L
LPA L
NP F
SM/SMs S
UA L
WHS



Church of St Mary of Eton SITE NAME: with St Augustine, East Way E9

DESIGNATION: Listed Place of Worship Grade II*

CONDITION:

PRIORITY: C (New entry)

Religious organisation OWNER TYPE:

Late Victorian brick with stone dressings by Bodley and Garner. A former mission church of Eton College. The nave roof slating appears to be in serviceable condition although the 2010 Quinquennial Inspection report recommends its replacement in the foreseeable future. The church has suffered damage in the past from water penetration at parapet gutters and gable flashings and it is reported that leaks continue to occur.

Contact: Donald Wahlberg 020 7973 3786

Contact: Donald Wahlberg 020 7973 3786



Church of St John of Jerusalem, SITE NAME: Lauriston Road E9

DESIGNATION: Listed Place of Worship Grade II*, CA

D (New entry) PRIORITY:

Religious organisation OWNER TYPE:

limestone dressings and slate roofs. There is deterioration of high level stonework with an anticipated programme of English Heritage / Heritage Lottery Fund grant-aided repairs being worked up.

style. Cruciform with west tower in Kentish ragstone with

Church by E C Hakewill of 1845-8 in the early English



Church of St Leonard, SITE NAME: Shoreditch High Street EI

DESIGNATION: Listed Place of Worship Grade I, CA

Poor CONDITION: C (D) PRIORITY:

OWNER TYPE: Religious organisation

Church built between 1736 and 1740 to the design of George Dance the Elder. The church recently received a joint Heritage Lottery Fund / English Heritage grant for repair of roofs at south west and north west corners and works are underway. Recent investigation work has identified issues with high level stonework which needs repair.

Contact: Donald Wahlberg 020 7973 3786

SITE NAME:	Dalston Lane West

DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Unknown
CONTACT:	Margaret Gustafsson (LPA) 020 8356 8605	NEW ENTRY?:	No

Sun Street SITE NAME

DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Deteriorating significantly
CONTACT:	Margaret Gustafsson (LPA) 020 8356 8605	NEW ENTRY?:	Yes

HAMMERSMITH AND FULHAM



Walls of Old Garden, Fulham Palace. Bishop's Avenue SW6

DESIGNATION: Listed Building Grade II, SM, CA, RPG II* Very bad CONDITION: N/A OCCUPANCY: PRIORITY:

F (B) OWNERTYPE: Local authority Walled gardens built between C15 – late C18 within grounds of Fulham Palace. A vinery and bothies located at the NW corner, originating from the 1820s, require substantial repairs. Following detailed recording both structures have now been made safe and key components conserved. HLF Stage II grant and English Heritage grant for works to restore both structures to their original function has begun.

Contact: Timothy Jones 020 7973 3780



34 Black Lion Lane, SITE NAME: St Peter's Square W6

DESIGNATION: Listed Building Grade II, CA CONDITION: Very bad Vacant OCCUPANCY: A (F) PRIORITY: OWNERTYPE: Private

Cottage, early/mid C19. Stuccoed and painted brick. Windows have been boarded up. Listed building consent for restoration approved 2005, and local planning authority has been proactive in seeking implementation. Works halted on site. Awaiting resolution of key issues in new listed building consent application. Negotiations with owner continuing.

Contact: Adam O'Neill (LPA) 020 8753 3318

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



SITE NAME: Lodge on north-east side of entrance, Fulham Palace, Fulham Palace Road SW6

DESIGNATION: Listed Building Grade II, CA, RPG II*

condition: Fair

occupancy: Part occupied

PRIORITY: F (C)

OWNERTYPE: Local authority

Porter's lodge to Fulham Palace built in 1821 in the Tudor Gothic style. The building is now used as a store and staff facilities. A successful Stage II Parks for People grant for the restoration of Palace grounds awarded in 2010. Repair works have commenced.

Contact: Adam O'Neill (LPA) 020 8753 3318



SITE NAME: Monuments at St Mary's
Roman Catholic Cemetery,
Harrow Road NW10

DESIGNATION: Listed Building Grade II, CA

condition: Poor occupancy: N/A priority: A (A)

OWNER TYPE: Religious organisation

Contains five listed memorials vulnerable to petty theft and vandalism as well as decay through exposure to elements. The listed mausolea are deteriorating.





Former Wormholt Library and Infant Welfare Centre, Hemlock Road W12

DESIGNATION: Listed Building Grade II, CA

condition: Pool

OCCUPANCY: Part occupied

PRIORITY: A (C)

PRIORITY: A (C)
OWNERTYPE: Local authority

Former public library and infant welfare centre, 1930, partly occupied. Building is vulnerable to theft and vandalism. Copper stolen from dome in 2009. Urn finials have been placed in storage. Some damage from water ingress. Listed Building Application received for the refurbishment of the library part of the building for a new Free School.

Contact: Adam O'Neill (LPA) 020 8753 3318



SITE NAME: Kent House including front boundary railings and gate, 10 Lower Mall W6

DESIGNATION: Listed Building Grade II, CA

CONDITION: Fair
OCCUPANCY: Vacant
PRIORITY: E (E)
OWNER TYPE: Private

House circa 1762, but the wrought iron railings and gate are thought to be earlier. The gate has an overthrow illustrated in the Survey of London. Works commenced on site and significant restoration including the reinstatement of the railings has been undertaken. Negotiations with owner ongoing.

Contact: Adam O'Neill (LPA) 020 8753 3318



Former West London County Court, 43-45 North End Road W14

DESIGNATION: Listed Building Grade II, CA

CONDITION: Poor
OCCUPANCY: Vacant
PRIORITY: F (B)
OWNER TYPE: Private

Court House, 1908. Red brick in early English baroque style. Vacant since closure. Broken into and vandalised in 2009. Listed building consent for refurbishment and conversion to office and residential use approved in 2010. Works underway on site.

Contact: Adam O'Neill (LPA) 020 8753 3318



Monuments at St Paul's Churchyard,
Queen Caroline Street W6

DESIGNATION: Listed Building Grade II, CA CONDITION: Poor

PRIORITY: B (B)

OWNER TYPE: Religious organisation

N/A

Contains three listed tombs and others of interest. North section is now part of a new landscaped public open space. Remainder of churchyard very dilapidated and many important tombs deteriorating. Planning permission granted by local authority for extension to church to be built on the churchyard. Works underway on site.

Contact: Adam O'Neill (LPA) 020 8753 3318

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA C
LB/LBs Li
LPA Lc
NP N
RPG R
SM/SMs SG
UA U
WHS W



Former Odeon cinema, 58 Shepherd's Bush Green, Hammersmith W12

DESIGNATION: Listed Building Grade II, CA

CONDITION: Poor
OCCUPANCY: Vacant
PRIORITY: B (B)
OWNER TYPE: Private

Formerly a cinema built in 1923 by Frank Verity, then a bingo hall, now vacant. New hotel scheme approved in 2010 and Section 106 Agreement completed.

Contact: Adam O'Neill (LPA) 020 8753 3318



SITE NAME: Church of St John, North End Road, Walham Green SW6

DESIGNATION: Listed Place of Worship Grade II, CA

condition: Poor

PRIORITY: D (New entry)
ownertype: Religious organisation

Built 1827 designed by George Ledwell Taylor. Reordered in 1980s creating upper and lower halls. Spaces now in full use by a nursery. Grant offered towards high level works and due to commence shortly.

Contact: Tracey Craig 020 7973 3756

SITE NAME:	St Mary's, Kensal Green
ITE NAME:	or mary s, Rensar Green

DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Adam O'Neill (LPA) 020 8753 3318	NEW ENTRY?:	Yes

HARINGEY



SITE NAME: Alexandra Palace,
Alexandra Palace Way,
Wood Green N22

DESIGNATION: Listed Building Grade II, CA, RPG II

condition: Poor

occupancy: Part occupied

PRIORITY: C (C)
OWNER TYPE: Trust

Entertainment complex including exhibition hall, music hall and theatre, built 1868-73. First ever television centre, 1935. Theatre in process of being repaired to meet Health and Safety standards for limited use. The east end of the Palace was least affected by the 1980 fire, this part includes the original BBC TV studios as well as the theatre. The Trust are exploring options for expanding uses.

Contact: Mortimer MacSweeney (LPA) 020 8489 2841



SITE NAME: Hornsey Town Hall, Broadway N8

DESIGNATION: Listed Building Grade II*, CA
CONDITION: Poor
OCCUPANCY: Part occupied
PRIORITY: D (C)

Built in 1935 to the design of RH Uren. Modelled on Dudock's seminal town hall at Hilversum and an important influence in subsequent British town hall design. Well preserved interior. Part occupied for Council use. Proposals for the repair, conversion and future use of the listed building, as well as the enabling development at the rear of the site, have been approved by the Council.

Contact: Richard Parish 020 7973 3717



Former Gaumont Palace cinema, Broadway,

Wood Green N22

DESIGNATION: Listed Building Grade II*

condition: Fair

occupancy: Part occupied

OWNER TYPE: Local authority

PRIORITY: D (D)

OWNER TYPE: Religious organisation

Cinema built 1934, later a bingo hall, with fine original Art Deco interiors. Church group uses part of the building for worship.

Contact: Eleni Makri (LPA) 020 8489 5222



SITE NAME: Public toilets, Bruce Grove,

Tottenham N17

DESIGNATION: Listed Building Grade II, CA

condition: Poor occupancy: N/A priority: C (C)

OWNER TYPE: Local authority

Public toilet circa 1920, with fine external ironwork. Empty and deteriorating. A feasibility/future use and fabric survey has been undertaken, but no proposals at present are likely to be implemented.

Contact: Mortimer MacSweeney (LPA) 020 8489 2841

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS CA Conservation Area

CA LB/LBs LPA NP RPG SM/SMs UA WHS



7 Bruce Grove, SITE NAME: Tottenham N17

Private

DESIGNATION: Listed Building Grade II, CA

Very bad CONDITION: Vacant OCCUPANCY: A(A)PRIORITY

One of a pair of early C19 houses. The building is vacant and has suffered substantial internal collapse. An urgent works notice has been served and urgent works have been undertaken. The local authority is seeking an appropriate refurbishment scheme.

Contact: Mortimer MacSweeney (LPA) 020 8489 2841



West wall, Bruce Castle Park, SITE NAME: Church Lane.

Tottenham N17

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION: N/A B (B) PRIORITY:

OWNERTYPE: Local authority

C17 red brick boundary wall to Bruce Castle Park. In urgent need of essential repairs as brickwork is deteriorating. An initial programme of repairs is scheduled for summer 2011.

Contact: Mortimer MacSweeney (LPA) 020 8489 2841



All Hallows Churchyard, SITE NAME:

> Church Lane. Tottenham N17

Scheduled Monument, CA DESIGNATION:

CONDITION: N/A OCCUPANCY: PRIORITY: C(C)

OWNER TYPE: Religious organisation

Churchyard to medieval church of All Hallows. Contains very fine tombs and monuments which have suffered from vandalism.

Contact: Mortimer MacSweeney (LPA) 020 8489 2841



Warmington House, SITE NAME: 744 High Road, Tottenham N17

Listed Building Grade II, CA DESIGNATION:

Fair CONDITION: Vacant C(C)PRIORITY: Company OWNER TYPE:

Early C19 house last used as offices. Partly in use for storage. Tottenham Hotspur FC are exploring options for the building within the proposed stadium redevelopment proposal.

Contact: Mortimer MacSweeney (LPA) 020 8489 2841



Percy House, SITE NAME: 796 High Road,

Tottenham N17

DESIGNATION: Listed Building Grade II*, CA

CONDITION: Vacant OCCUPANCY: C(D)PRIORITY-OWNER TYPE: Company Mid C18 house with late C17 forecourt walls and railings. The council have been liaising with Tottenham Hotspur FC to secure the repair and reuse of Percy House as part of the stadium redevelopment proposals.

Contact: Richard Parish 020 7973 3717



SITE NAME: 810 High Road, Tottenham N17

DESIGNATION: Listed Building Grade II*, CA

Fair CONDITION: Vacant PRIORITY: C(C)OWNER TYPE: Company

Fine house built circa 1715 as part of a symmetrical pair. Externally restored by a building preservation trust. The Council and Trust have been seeking to secure the internal refurbishment and the reuse of the building.

Contact: Richard Parish 020 7973 3717

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



South boundary wall SITE NAME: to Bruce Castle Park, Lordship Lane, Tottenham N17

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION: N/A OCCUPANCY: A(A)PRIORITY:

OWNER TYPE: Local authority

Probably early C17 tall red brick wall in Flemish bond. Tall sloped coping and plinth. Wall ramped gently up at intervals towards the west. Now seriously deteriorating with open decayed pointing, loose and unstable brickwork, previous re-pointing damage also extensive ivy/creeper and frost damage. Programme of urgent repairs proposed for summer 2011.

Contact: Mortimer MacSweeney (LPA) 020 8489 2841



SITE NAME: Drinking fountain and cattle trough, High Road.

Wood Green N22 DESIGNATION: Listed Building Grade II

Poor CONDITION: N/A OCCUPANCY: C(C)PRIORITY:

OWNERTYPE: Local authority

Cattle trough and drinking fountain, 1901. Elaborate Roman baroque style stone fountain head. Grey granite trough. Neglected but some repair works carried out last year, but further works are still required.



Retaining wall along Highgate Hill SITE NAME: (The Bank), Highgate Hill, Highgate N19

Listed Building Grade II, CA DESIGNATION:

Poor CONDITION: N/A OCCUPANCY: C(C)PRIORITY:

OWNERTYPE: Local authority

Retaining wall along Highgate Hill between the street pavement and higher paved walk. Early C19 wall in need of repair. Some repairs carried out in 2010/11 but further repairs are required.

Contact: Mortimer MacSweeney (LPA) 020 8489 2841



SITE NAME: 62 Monument Way, Tottenham N17

DESIGNATION: Listed Building Grade II

CONDITION: Poor Vacant B (New entry) PRIORITY:

Private OWNER TYPE:

Late C18 three storey detached house, also known as 62 High Cross Road. Seriously affected by water penetration into the structure and interior. The Council is seeking repair and refurbishment proposals.

Contact: Mortimer MacSweeney (LPA) 020 8489 2841

Contact: Mortimer MacSweeney (LPA) 020 8489 2841



Porters and Walters Almshouses, SITE NAME: St Leonard's Almshouses, Nightingale Road, Wood Green N22

DESIGNATION: Listed Building Grade II, CA

CONDITION: Occupied OCCUPANCY: C (C) PRIORITY

OWNERTYPE: Charity

Circa 1904. Four two-storey almshouses which form a group with a commemorative stone and front railings. The buildings have suffered from lack of proper maintenance over a number of years and are in a slow state of decay.

Contact: Mortimer MacSweeney (LPA) 020 8489 2841



The Bull Inn. SITE NAME:

> 13 North Hill, Highgate N6

DESIGNATION: Listed Building Grade II, CA

Fair CONDITION: Vacant PRIORITY: E (New entry)

OWNERTYPE: Private

This two storey C18 public house was refurbished in 2005, however the enterprise has not been successful and the building now stands vacant and the site is boarded up.

Contact: Mortimer MacSweeney (LPA) 020 8489 2841

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category given in brackets

ABBREVIATIONS

Conservation Area CA LB/LBs LPA NP RPG SM/SMs UA WHS



St George's House, SITE NAME: 6 North Hill,

Highgate N6

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION: Vacant OCCUPANCY:

PRIORITY: A (New entry)

OWNER TYPE: Company

Early C19, three storeys and basement, stucco fronted, with side extensions. Used as a nursing home in the 1930s and afterwards as a hostel. Subsequently squatted and vandalised. Now vacant and in a state of dilapidation, with water penetration damage. Proposals for listed building consent and planning permission under discussion.

Contact: Mortimer MacSweeney (LPA) 020 8489 2841



The Palace Cathedral SITE NAME:

> (former Tottenham Palace Theatre), High Road, Tottenham N17

DESIGNATION: Listed Place of Worship Grade II, CA

C (C) PRIORITY:

Religious organisation OWNER TYPE:

The former Tottenham Palace was built in 1908 by Wylson Long as a variety theatre. The building is currently occupied by a church group but is suffering from water ingress which is causing significant damage to both the structure and interior plasterwork.

Contact: Bob Brabner 020 7973 3727

SITE NAME:	Clyde Circus		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Improving
CONTACT:	Mortimer MacSweeney (LPA) 020 8489 2841	NEW ENTRY?:	No
SITE NAME:	Noel Park		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Mortimer MacSweeney (LPA) 020 8489 2841	NEW ENTRY?:	No
SITE NAME:	Scotland Green		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Improving
CONTACT:	Mortimer MacSweeney (LPA) 020 8489 2841	NEW ENTRY?:	No

HARROW



SITE NAME:

Brick Kiln to south-east of The Kiln, Common Road, Stanmore

DESIGNATION: Listed Building Grade II

Very bad CONDITION: OCCUPANCY: N/A

C (D) Private OWNER TYPE:

Lower part of a C18 brick kiln conical chimney of which the upper part no longer exists. In urgent need of structural stabilisation and repair.

Contact: Lucy Haile (LPA) 020 8736 6101



SITE NAME:

Cannons Farm Barn, Hereford Gardens,

DESIGNATION: Listed Building Grade II

CONDITION: Fair **Vacant** OCCUPANCY: PRIORITY: C (C)

OWNERTYPE: Private

C17 barn with three bays and narrow central bay. An Urgent Works Notice was served on the owners in 2008. Some repair works are required. The Council is considering proposals for the future use of this building.

Contact: Lucy Haile (LPA) 020 8736 6101

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



SITE NAME:	The Hermita	ge,
	776 Kenton	lane

Private

OWNER TYPE:

DESIGNATION: Listed Building Grade II Poor CONDITION: Vacant OCCUPANCY: D(C)

The building is a partially timber-framed, rendered, two-storey cottage of two bays that probably dates to the late C16 or early C17. The building is in a state of disrepair with cracks in walls, holes in ceilings and broken roof tiles and damp problems. A proposal for enabling development to secure the repair and future upkeep of the building approved with conditions, awaiting implementation.

Contact: Lucy Haile (LPA) 020 8736 6101



Boundary wall fronting road SITE NAME: from Nos 118-128. Stanmore Hill (East Side), Stanmore

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION: N/A C(C)PRIORITY: OWNERTYPE: Private

C18 brick wall with buttresses with chamfered bases. Many bricks at base have weathered away and parts require re-pointing. Harrow Council are discussing repairs with the owners (April 2011).

Contact: Lucy Haile (LPA) 020 8736 6101



Boundary wall fronting road (Hill House), SITE NAME: 173 Stanmore Hill (East Side), Stanmore

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION: N/A OCCUPANCY: PRIORITY: C(C)OWNERTYPE: Private This brick wall originates from the C18 or early C19. It is 10 foot high red brick with chamfered pilaster buttresses. Many sections of the wall have weathered away and parts require re-pointing.

Contact: Lucy Haile (LPA) 020 8736 6101



Bentley Priory -SITE NAME: central entrance block, The Common, Stanmore

DESIGNATION: Listed Building Grade II*, RPG II

Fair CONDITION:

Part occupied

C(C)PRIORITY: Company OWNER TYPE:

Built in C18 the property has a rich history ranging from its association with the architect Sir John Soane, the role it played in hosting political figures in the 1800s through to its use as the home of fighter command in WWII. Part of the building is currently occupied and there are plans to turn it into a museum, but this is dependent on enabling development which is now starting (April 2011).

Contact: Samantha Johnson 020 7973 3749



Bentley Priory SITE NAME:

DESIGNATION: Registered Park and Garden Grade II,

also 2 LBs

Generally unsatisfactory

with major localised problems

VULNERABILITY: High

Declining

OWNER TYPE: Mixed, multiple owners A C16 estate enlarged and improved in the late C18. Sir Uvedale Price and William Gilpin influenced the design in the early C19. Royal Air Force Fighter Command occupied the mansion from 1936 and it played a central role during WWII. They withdrew from the site in 2008. Plans for a museum and housing in the house and grounds plus landscape conservation are on hold.

Contact: Zosia Mellor 020 7973 3473



The Rayners Public House, SITE NAME: 23 Village Way East

DESIGNATION: Listed Building Grade II Fair CONDITION: OCCUPANCY: Vacant

E (E) PRIORITY: OWNERTYPE: Private

A virtually unaltered 1930s public house retaining its internal plan form and original fittings. The building has been empty since 2006. The council is currently in discussions with the owner about a possible future scheme to secure the future of this building.

Contact: Lucy Haile (LPA) 020 8736 6101

SITE NAME

Grim's Ditch: four linear sections between Uxbridge Road and Oxhey Lane, Harrow

DESIGNATION:	Scheduled Monument (No. 1003530)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Jane Sidell 020 7973 3738

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category given in brackets

ABBREVIATIONS

Conservation Area CA LB/LBs LPA NP RPG SM/SMs UA WHS

	Grim's Ditch: section extending I 500yds (1370m) north east from Oxhey Lane, Harrow			
DESIGNATION:	Scheduled	Monument (No. 1002044)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tre	ee growth	TREND:	Declining
OWNER TYPE:	Local Auth	<u> </u>	CONTACT:	Jane Sidell 020 7973 3738
SITE NAME:	Grim's Di	tch: section north of Blythwood House	e, Harrow	
DESIGNATION:	Scheduled	Monument (No. 1002007)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tre	ee growth	TREND:	Declining
OWNER TYPE:	Local Auth	_	CONTACT:	Jane Sidell 020 7973 3738
SITE NAME:	Linear ear	thworks in Pear Wood, west of Watlir	g Street, Har	row
DESIGNATION:	Scheduled	Monument (No. 1001996)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tre	ee growth	TREND:	Stable
OWNER TYPE:	Local Auth	nority	CONTACT:	Jane Sidell 020 7973 3738
SITE NAME:	Pinner de	er park, Pinner Park Farm, Harrow		
DESIGNATION:	Scheduled	Monument (No. 1019135)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tre	ee growth	TREND:	Declining
OWNER TYPE:	Local Auth	nority	CONTACT:	Jane Sidell 020 7973 3738
HAVERING				
-	SITE NAME:	Garden walls to former North Ockendon Hall, Church Lane, North Ockendon RM14		ter garden walls to Ockendon Hall olished). Slowly deteriorating.
A STATE OF THE PARTY OF THE PAR	DESIGNATION:	Listed Building Grade II, CA		
2 12 1	CONDITION:	_		
	OCCUPANCY:	N/A		
	PRIORITY:	C (C)		
	PRIORITY:	C (C)		



SITE NAME: Bridge in Parklands Park, Corbets Tey Road, Upminster RM14

DESIGNATION: Listed Building Grade II, CA

condition: Fair
occupancy: N/A
priority: D (F)

OWNER TYPE: Local authority

C18 bridge, attributed to James Paine; in the former landscaped park to Gaynes House (demolished), and now a public park. Listed building consent has been granted for repairs; funding is now being sought.





SITE NAME: 96-102 North Street, Romford RM1

DESIGNATION: Listed Building Grade II

CONDITION: Poor

OCCUPANCY: Occupied

PRIORITY: C (C)

OWNER TYPE: Company

Late C17 timber-framed building consisting of two parallel ranges. The building is occupied, but in need of extensive repairs. Listed building consent has been granted for the rebuilding of the chimney stack.

Contact: Katie Dickson (LPA) 01708 432606

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Claracteristics

 C Claracteristics

 C Claracteristics

 C Claracteristics

 C Claracteristics

 C Claracteristics
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

010 egory

ABBREVIATIONS
CA Conservation Area
LB/LBs LPA Listed Building/s
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM/SMS Scheduled Monument/S
UA Unitary Authority
WHS World Heritage Site



High House Farmhouse, SITE NAME: Ockendon Road

DESIGNATION: Listed Building Grade II*, CA

Very bad CONDITION: Part occupied OCCUPANCY:

A(A)Trust OWNER TYPE:

Three storey house of brick and timber frame c1700 with older timber frame wing. Timber frame to three storey section under stress, porch propped by scaffold, significant water damage from roof. Many rooms uninhabitable. Vegetation growth.

Contact: Nick Collins 020 7973 3739



Garden walls to south SITE NAME: of Brettons House. Rainham Road, Hornchurch

DESIGNATION: Listed Building Grade II

Very bad CONDITION: N/A A(A)PRIORITY:

OWNERTYPE: Local authority

C16 garden walls to Brettons House. In need of extensive repairs.



Upminster Old Chapel, SITE NAME: St Mary's Lane,

Upminster RM14 Listed Building Grade II DESIGNATION:

Poor CONDITION:

Vacant OCCUPANCY: C (C) PRIORITY:

OWNER TYPE: Educational Body

Chapel built in 1800, and no longer used as a place of worship. Listed building consent has been secured to convert the building into a performance space and meeting hall. A stage II Heritage Lottery Fund grant has just been offered for repairing and refurbishing the building.

Contact: Katie Dickson (LPA) 01708 432606

Contact: Katie Dickson (LPA) 01708 432606



Upminster Windmill, SITE NAME: St Mary's Lane,

DESIGNATION: Listed Building Grade II*

Upminster RM14

CONDITION: Fair Occupied

PRIORITY-

D (C) Local authority OWNER TYPE:

Smock mill 1803, retaining original machinery. The building preservation trust (Friends of Úpminster Windmill) are recording the mill machinery, and are gradually and sympathetically repairing the windmill. Regular public opening.

Contact: Simon Hickman 020 7973 3762



Stable block, Rainham Hall, SITE NAME: The Broadway, Rainham RMÍ3

DESIGNATION: Listed Building Grade II*, CA

CONDITION: Poor Vacant OCCUPANCY: C (C) PRIORITY-

Trust OWNER TYPE:

Stables and coach house dating to C18. Used for some storage but in need of repair. A feasibility study for the entire Rainham Hall site has been prepared and proposals for the future use of the building are being prepared. Work is underway to restore the accompanying gardens as a visitor attraction to open in 2012.

Contact: Simon Hickman 020 7973 3762



SITE NAME: Garden walls at Cranham Hall, The Chase,

Cranham RM14 DESIGNATION: Listed Building Grade II, CA

Poor CONDITION: N/A PRIORITY: C (C) OWNERTYPE: Private

C16 walls to earlier house on site of Cranham Hall. In need of extensive repairs.

Contact: Katie Dickson (LPA) 01708 432606

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS



Mill Cottage, SITE NAME: The Dell, High Street, Hornchurch RMI2

DESIGNATION: Listed Building Grade II

Poor CONDITION: Occupied OCCUPANCY: C (C) OWNERTYPE: Private

Single storey timber-framed range, C17. Now one dwelling. In poor condition and continuing to deteriorate.

Contact: Katie Dickson (LPA) 01708 432606



Footbridge to rear of Nos. 52 and 54, SITE NAME: The Grove.

Upminster

DESIGNATION: Listed Building Grade II

Fair CONDITION: N/A F (F) PRIORITY:

OWNERTYPE: Local authority

Footbridge and eye-catcher, circa 1765, probably by James Paine who laid out the estate of Gaynes Park in the 1760s for Sir James Esdaile, Lord Mayor of London 1777-78. First stage of repairs to ensure structural stability complete; final phase of repairs underway.

Contact: Katie Dickson (LPA) 01708 432606



Barn to south west of Great Tomkyns, SITE NAME: Tomkyns Lane,

Upminster RM14 Listed Building Grade II* DESIGNATION:

Poor CONDITION: Vacant OCCUPANCY: C (C) PRIORITY-OWNERTYPE: Private Late C13 or C14 timber-framed barn. Previous owner carried out basic holding repairs, but further comprehensive scheme of repair needed. A scheme is currently being prepared for repairing and refurbishing the barn.

Contact: Nick Collins 020 7973 3739

Dagnam Park	Farm moated six	te. Noak Hill. Ror	nford. Havering

DESIGNATION:	Scheduled Monument (No. 1001988)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Stable
OWNER TYPE:	Local Authority	CONTACT:	Jane Sidell 020 7973 3738

SITE NAME:	Romford		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Improving
CONTACT:	Katie Dickson (LPA) 01708 432606	NEW ENTRY?:	No

HILLINGDON



Barn to the west of Weekly House, SITE NAME: Bath Road.

Harmondswoth

DESIGNATION: Listed Building Grade II, CA CONDITION:

Very bad Vacant OCCUPANCY: A (B) PRIORITY OWNERTYPE: Private

Late C17 or early C18 weatherboarded barn with tiled roof. Queen post truss at west end. Weekly House, the boundary wall and the barn form a group. Dilapidated state. Listed building and planning consent granted for conversion to use as a children's nursery.

Contact: Sarah Harper (LPA) 01895 556000



Former King Henry Public House SITE NAME: and stables, 456 Bath Road,

Longford

DESIGNATION: Listed Building Grade II CONDITION: Poor

Unknown OCCUPANCY: C (New entry) PRIORITY:

OWNERTYPE: Private

Converted to a house, the rear of the building is the former "King Henry" public house. Front part of property has been rebuilt, using old material, after a fire. All walls of exposed timber framing with brick filling; tiled roofs. The adjacent stables are also of interest with an early diamond mullioned window. The buildings are in poor condition and have recently been included in large development proposals.

Contact: Sarah Harper (LPA) 01895 556000

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

CA LB/LBs LPA NP RPG SM/SMs UA WHS



SITE NAME:	Breakspear House,
	Breakspear Road North,
	Harefield

DESIGNATION: Listed Building Grade I, CA

Fair CONDITION: Vacant OCCUPANCY:

F (D) PRIORITY: OWNER TYPE: Company Early to mid C17 manor house in extensive grounds. Inspected on a regular basis and being maintained in a secure and relatively weathertight state, but long-term use is required. Listed building consent granted and planning permission agreed for conversion to residential use, building re-roofed and other repairs underway.

Contact: Samantha Johnson 020 7973 3749



Dovecote to north west SITE NAME: of Breakspear House. Breakspear Road North, Harefield

DESIGNATION: Listed Building Grade II*, CA

Poor CONDITION: N/A D (C) PRIORITY: OWNER TYPE: Company

C17 dovecote to the north west of Breakspear House. The building has structural problems, but its condition appears stable. Repair agreed as part of the approval for the residential conversion of main house and enabling development.

Contact: Samantha Johnson 020 7973 3749



Langley Farm Barn, SITE NAME: Breakspear Road North, Harefield, Northwood

Listed Building Grade II, CA DESIGNATION:

Very bad CONDITION: N/A OCCUPANCY: PRIORITY: A(C)OWNERTYPE: Private

C16 barn in private ownership at Langley Farm. The barn is three bay timber-framed and weatherboarded with a tiled roof. It has lost parts of the brick plinth to the north-east elevation. The front area adjacent to the barn appears to have been subject to fly tipping. Applications for redevelopment of adjacent farm buildings refused.

Contact: Sarah Harper (LPA) 01895 556000

Contact: Sarah Harper (LPA) 01895 556000



Garden walls SITE NAME:

> to Church Gardens Nursery, Church Hill, Harefield

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION: N/A A(A)PRIORITY-Private OWNER TYPE:

C17 red brick garden walls in need of extensive repairs.



Cinema, RAF Uxbridge, SITE NAME: Grays Road,

Uxbridge DESIGNATION: Listed Building Grade II

Very bad CONDITION: Vacant OCCUPANCY:

A(A)PRIORITY-

OWNER TYPE: Company

Designed in 1918, it has a large auditorium used historically as lecture hall/cinema or concert hall and was converted to a gymnasium in the 1960s. The building is vacant and in very poor condition. RAF Uxbridge has been sold by the MoD to a private-sector consortium on a long lease. Developers and local authority are working together to find a suitable new use. Minor repairs carried out in February 2010.

Contact: Sarah Harper (LPA) 01895 556000



Former Stables to Eastcote House, SITE NAME: High Road, Eastcote,

Pinner

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION: Occupied PRIORITY: C (C)

OWNER TYPE: Local authority

Early C17 timber-framed building with alterations. Two storeys, three windows blocked. High pitched roof renewed in machine tiles. A Conservation Management Plan jointly funded by Hillingdon and English Heritage has been produced and a bid for funding from the Heritage Lottery Fund for the repair and reuse of the buildings is anticipated in August 2011.

Contact: Sarah Harper (LPA) 01895 556000

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



SITE NAME:	Dovecote and garden walls		
	to Eastcote House, High Road		
	Eastcote, Pinner		

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION: N/A OCCUPANCY: C(C)PRIORITY:

OWNER TYPE: Local authority

Square red brick building of C18 appearance with pyramidal tiled roof and central louvred turret. Inside, the roof structure is visible and part of the wooden potence remains. Wall is to west of dovecote.

Contact: Sarah Harper (LPA) 01895 556000



Garden walls to former stables SITE NAME: to Eastcote House, High Road, Eastcote, Pinner

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION: N/A C(C)PRIORITY:

OWNERTYPE: Local authority

CI7 red brick walls surrounding an inner and an outer garden. North west wall has large square brick piers at intervals and a flat stone coping. The north east wall has been much lowered and repaired. Elsewhere wall has been breached and made good in two places.

C18 red brick wall with sloped coping. Later screened

opening. Wall is to the north of The Beeches which is

Contact: Sarah Harper (LPA) 01895 556000



Front garden wall, SITE NAME: The Beeches, High Street, Cowley

Listed Building Grade II DESIGNATION:

Poor CONDITION: N/A OCCUPANCY: PRIORITY: A(A)

OWNERTYPE: Private

Contact: Sarah Harper (LPA) 01895 556000

also on the Register.



The Beeches, High Street, Cowley

DESIGNATION: Listed Building Grade II

Poor CONDITION: Vacant F (A) PRIORITY-Private OWNER TYPE:

The Beeches is a two storey house with attic and basement, probably dating from the C17, although refronted in the C18. Also Victorian additions to the side and rear. Good interior, however there has been damage to the attic floor. Last used as a hostel, the building and associated Coach House were recently sold by the Council to a private owner. Approval for conversion to flats agreed and repairs underway.

Contact: Sarah Harper (LPA) 01895 556000



The Dower House, SITE NAME: 393 High Street, Harlington

DESIGNATION: Listed Building Grade II

CONDITION: Very bad OCCUPANCY: Vacant

A (New entry) PRIORITY-

OWNER TYPE: Private Two storey house with C18 brick front to older timber framed structure. Four windows wide, brown brick with red brick quoins and window dressings. High pitched roof hipped at right and renewed in machine tile. Rebuilt large C16 chimney. The building suffered severe fire damage in May 2011.

Contact: Sarah Harper (LPA) 01895 556000



SITE NAME: Manor Farm barn, High Street, Harmondsworth

DESIGNATION: Listed Building Grade I, CA

Poor CONDITION: Vacant PRIORITY: A (C) OWNER TYPE: Company Medieval timber framed, aisled barn of 12 bays, one of the finest buildings of its type. Vacant and no future plans for use agreed. Ürgent works undertaken by English Heritage in January 2010 to repair slipped/missing tiles and areas of weatherboarding. Securing a long-term future is a priority for English Heritage.

Contact: Samantha Johnson 020 7973 3749

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



The Cedars, SITE NAME: 66 High Street, Uxbridge

DESIGNATION: Listed Building Grade II, CA

Fair CONDITION: Vacant OCCUPANCY: C (C) PRIORITY

C18 town house with later additions. Three storeys, central doorway with Doric pilasters, entablature and open pediment. Red brick facade, with bands at first and second floors, dentil and cyma recta cornice with plain tiled roof. Distinctive Dutch gables to side elevation. Development proposals including the site to the rear have been discussed with the local authority.

Contact: Sarah Harper (LPA) 01895 556000



Harefield Park SITE NAME:

Trust

(Annexe to Harefield Hospital). Hill End Road, Harefield

DESIGNATION: Listed Building Grade II*, CA

Very bad CONDITION: Vacant A(C)PRIORITY:

Health Authority OWNER TYPE:

Site comprises main building and two flanking stable buildings of early C18 date. Hospital may close. House vacant, no use identified, south facade propped and roof in poor condition.

Contact: Samantha Johnson 020 7973 3749



The Stable Block, north east of SITE NAME: Harefield Park, (Annexe to Harefield Hospital), Hill End Road, Harefield

Listed Building Grade II, CA DESIGNATION:

CONDITION:

Part occupied OCCUPANCY:

PRIORITY: C(C)

OWNERTYPE: Health Authority

Site comprises one of two stable buildings of early C18 date. Hospital may close. In the interim, the stable building will continue to be used for clinical storage. A long-term use needs to be identified.



SITE NAME: The Stable Block, south east of Harefield Park, (Annexe to Harefield Hospital), Hill End Road, Harefield

Listed Building Grade II, CA DESIGNATION:

CONDITION: Poor

Part occupied OCCUPANCY:

C(C)PRIORITY:

Health Authority OWNER TYPE:

Site comprises one of two stable buildings of early C18 date. Hospital may close. In the interim the stable building will continue to be used for clinical storage. A long-term use needs to be identified.

Contact: Sarah Harper (LPA) 01895 556000

Contact: Sarah Harper (LPA) 01895 556000



Harefield Grove, SITE NAME: Rickmansworth Road, Harefield

DESIGNATION: Listed Building Grade II

CONDITION: Good Vacant OCCUPANCY:

E (New entry) PRIORITY-

Private OWNER TYPE:

Probably early C19 country house of 3 storeys, 5 windows. Stucco with stone cornice and parapet concealing fairly low pitched hipped slate roof. Extension 2 storey modern courtyard wing for office use with atrium link. The building has been vacant for a number of years and is deteriorating.

Contact: Sarah Harper (LPA) 01895 556000



SITE NAME: Cellars of former Cranford House, Roseville Road,

Cranford

DESIGNATION: Listed Building Grade II, CA

Fair CONDITION: Vacant PRIORITY: C (C)

OWNERTYPE: Local authority

Brick vaulted cellars to Cranford House circa 1722 (demolished). Of archaeological interest, but potential for use limited due to likely very high costs involved. Suffering from structural weakening and condition deteriorating.

Contact: Sarah Harper (LPA) 01895 556000

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable)
 end use or user identified;
 functionally redundant buildings
 with new use agreed but not yet implemented

NOTE:

If the priority category has changed since the 2010 register, the previous category given in brackets

ABBREVIATIONS



Cranford House Stables, SITE NAME:

Roseville Road. Cranford

DESIGNATION: Listed Building Grade II, CA

Fair CONDITION: Vacant OCCUPANCY: C (E)

OWNERTYPE: Local authority

Stables to Cranford House circa 1720 (demolished). Jointly managed by the London Boroughs of Hillingdon and Hounslow. In reasonable condition following repairs, but in need of a long-term, possibly residential, use.

Contact: Sarah Harper (LPA) 01895 556000



Benlow Works, SITE NAME: Silverdale Road. **HaWHS**

DESIGNATION: Listed Building Grade II

Very bad CONDITION: Part occupied

A (C) PRIORITY: Unknown OWNER TYPE:

Orchestrelle Factory of 1909-11. Reinforced concrete frame; brick exterior, four storeys with 19 bay elevation. Entrance bay has semi-circular stepped brick architrave to doorway and segimental-arched metal casements flanked by rusticated pilasters slightly set forward and breaking

parapet. No current proposals.



Chapel SITE NAME:

in Hillingdon-Uxbridge Cemetery, Uxbridge Road

DESIGNATION: Listed Building Grade II

Very bad CONDITION: Part occupied OCCUPANCY: PRIORITY:

F (A) OWNER TYPE: Local authority One of two listed mid C19 chapels, coursed rubble with stone dressings. West Chapel has been subject to extensive fire damage with only the shell of the building remaining. Repairs have started on site.

Contact: Sarah Harper (LPA) 01895 556000

Contact: Sarah Harper (LPA) 01895 556000



SITE NAME: Gatehouse

at Hillingdon-Uxbridge Cemetery, Uxbridge Road

DESIGNATION: Listed Building Grade II

CONDITION: Poor Vacant C(C)PRIORITY-

Local authority OWNER TYPE:

Mid C19 gatehouse by Benjamin Ferrey. Constructed of rubble with stone dressings, tiled roof, five bays with wide central entrance under arch. In deteriorating condition and vacant.

Contact: Sarah Harper (LPA) 01895 556000

Walls at rear of Hillingdon House, SITE NAME: RAF Uxbridge, Vine Lane, Uxbridge DESIGNATION: Listed Building Grade II

CONDITION: OCCUPANCY: N/A D (C) PRIORITY: OWNERTYPE: Company

The walls form part of the curtilage of grade II listed Hillingdon House. They are in poor repair and show evidence of some structural problems; approval has recently been agreed for repairs to the walls. RAF Uxbridge has been sold by the MoD to a private sector consortium on a long lease. Hillingdon Borough Council has adopted a Supplementary Planning Document for the whole site.

Contact: Sarah Harper (LPA) 01895 556000



Hubbard's Farm Barn SITE NAME:

and outbuildings, West Drayton Road, Colham Green, Uxbridge

DESIGNATION: Listed Building Grade II

Very bad CONDITION: Vacant PRIORITY: A (B) OWNERTYPE: Private

Large, probably late C16, five bay barn with original east aisle. Queen strut roof trusses, lower timbers original except for some added arch braces to the tie beams. Extremely bad condition. Planning and listed building consent granted in 2008 for conversion to four flats and rebuilding of extension and granary following unauthorised demolition. New scheme in discussion, but future uncertain.

Contact: Sarah Harper (LPA) 01895 556000

Jane Sidell 020 7973 3738

SITE NAME:

OWNER TYPE:

Manor Farm moat, Ickenham, Hillingdon

Scheduled Monument (No. 1002006) Generally unsatisfactory DESIGNATION: CONDITION: with major localised problems Scrub / tree growth Declining PRINCIPAL VULNERABILITY: TREND:

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.

Local Authority

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented

NOTE:

CONTACT:

If the priority category has changed since the 2010 register, the previous category given in brackets

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Moated site, west bank of River Pinn, near I	ckenham (1/2 mile	e (800m) north west of church), Hillingdo
DESIGNATION:	Scheduled Monument (No. 1002001)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Stable
OWNER TYPE:	Local Authority	CONTACT:	Jane Sidell 020 7973 3738
SITE NAME:	Black Jacks Lock and Copper Mill Lock, Har	refield	
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Sarah Harper (LPA) 01895 556000	NEW ENTRY?:	No
SITE NAME:	Botwell (Thorn/EMI), Hayes		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Sarah Harper (LPA) 01895 556000	NEW ENTRY?:	No
SITE NAME:	Harlington Village, Heathrow Villages		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Sarah Harper (LPA) 01895 556000	NEW ENTRY?:	No
SITE NAME:	Harmondsworth Village, Heathrow Villages		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating significantly
CONTACT:	Sarah Harper (LPA) 01895 556000	NEW ENTRY?:	No ,
SITE NAME:	Hayes Village		
DESIGNATION:	Conservation Area	CONDITION:	Fair
VULNERABILITY:	Low	TREND:	Deteriorating significantly
CONTACT:	Sarah Harper (LPA) 01895 556000	NEW ENTRY?:	Yes
SITE NAME:	Longford Village, Heathrow Villages		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Sarah Harper (LPA) 01895 556000	NEW ENTRY?:	No
SITE NAME:	Morford Way, Eastcote, Ruislip		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Sarah Harper (LPA) 01895 556000	NEW ENTRY?:	No
SITE NAME:	Ruislip Manor Way, Ruislip		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Sarah Harper (LPA) 01895 556000	NEW ENTRY?:	No
SITE NAME:	The Greenway, Uxbridge		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.


NOTE:

NOTE:
If the priority category
has changed since the 2010
register, the previous category
is given in brackets.

ABBREVIATIONS

CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

HOUNSLOW



Hardinge Block, SITE NAME: Hounslow Barracks, Beavers Lane TW4

DESIGNATION: Listed Building Grade II

Fair CONDITION: Vacant D(C)PRIORITY-

Government OWNER TYPE:

Standard-pattern barrack block of the 1870s Cardwell Forces Localisation Programme, unoccupied since c1997. There is evidence of rainwater penetration through the roof. Repair/conversion proposals have been agreed in principle but discussions ongoing in particular for the re-use as barracks accommodation.

Contact: Maggie Urquhart (LPA) 020 8583 4941



Boston Manor House, SITE NAME: Boston Manor Road, Boston Manor Park TW8

Listed Building Grade I, CA DESIGNATION:

CONDITION: Vacant OCCUPANCY: E (B) PRIORITY:

OWNERTYPE: Local authority

Built 1623 for Lady Mary Reade. Stabilising action to south and west elevations undertaken. English Heritage grant awarded towards options appraisal for future uses. Repairs to south west corner substantially completed. Reinstatement of finishes awaited. Options appraisal almost ready for public consultation.

Contact: Stephen Senior 020 7973 3783



SITE NAME: Boundary wall to Tudor House and Parr Court, Castle Way, Hanworth Park TW13

Listed Building Grade II, SM, CA DESIGNATION:

Poor CONDITION: N/A OCCUPANCY: D(D)PRIORITY: Private OWNER TYPE:

Red brick boundary wall of considerable height, C17 and later. Partly shored and in need of repair. A scheme has been agreed to reduce the amount of loss of material to the head of the wall. English Heritage has awarded a grant towards the repairs and works are set to commence in the summer of 2011.

Public baths and swimming pool 1895-96. Closed 1990. Sold by London Borough of Hounslow in November 1998.

Interiors in reasonable condition. Application for reuse as

offices and residential approved on appeal in 2002 and an

outline planning application and listed building consent for

change of use to live-work units has been approved.

Contact: Timothy Jones 020 7973 3780



Brentford Baths, SITE NAME: Clifden Road, **Brentford TW8**

DESIGNATION: Listed Building Grade II, CA

CONDITION: OCCUPANCY: Vacant D (C) PRIORITY

SITE NAME:

Contact: Maggie Urquhart (LPA) 020 8583 4941 OWNER TYPE: Company

> Archway near east entrance lodge, Gunnersbury Avenue, Gunnersbury Park W3

DESIGNATION: Listed Building Grade II, CA, RPG II*

Very bad CONDITION: OCCUPANCY: N/A

A(A)OWNER TYPE: Local authority

Stucco pedimented archway, circa 1837, situated near to the East Lodge, on the eastern edge of Gunnersbury Park, a public park since 1925. Discussions are continuing with the LPAs and Heritage Lottery Fund to secure funding for repair and restoration of the estate and a major bid is due to be submitted to the Heritage Lottery Fund in November 2011.

Contact: Maggie Urquhart (LPA) 020 8583 4941



Boundary wall at Gunnersbury Park, SITE NAME Gunnersbury Avenue, Gunnersbury Park W3

DESIGNATION: Listed Building Grade II, CA, RPG II*

CONDITION: Fair N/A OCCUPANCY: PRIORITY: C (A)

OWNER TYPE: Local authority

Part of boundary wall of the garden of the original Gunnersbury House, built I 658-63 by John Webb for Sir John Maynard. Wall runs N-S from arch to S-E of Princess Amelia's Bath House. Discussions are continuing with LPAs and Heritage Lottery Fund to secure funding for repair and restoration of the estate and a major bid is due to be submitted to the Heritage Lottery Fund in November 2011.

Contact: Maggie Urquhart (LPA) 020 8583 4941

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable)
 end use or user identified;
 functionally redundant buildings
 with new use agreed but not yet implemented

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



East lodge to Gunnersbury Park, SITE NAME: Gunnersbury Avenue, Gunnersbury Park W3

DESIGNATION: Listed Building Grade II, CA, RPG II*

Very bad CONDITION: N/A OCCUPANCY:

C(A)PRIORITY OWNER TYPE: Local authority Entrance lodge circa 1837, situated on the eastern edge of the C18 and C19 Gunnersbury Park which became a public park in 1925. All that remains are small sections of the south and west elevations. Discussions are continuing with LPAs and Heritage Lottery Fund to secure funding for repair and restoration of the estate and a major bid is due to be submitted to the Heritage Lottery Fund in November 2011.

Contact: Maggie Urquhart (LPA) 020 8583 4941



East stables in Gunnersbury Park, SITE NAME: Gunnersbury Avenue, Gunnersbury Park W3


DESIGNATION: Listed Building Grade II*, CA, RPG II*

Very bad CONDITION: Vacant OCCUPANCY: A(A)PRIORITY:

Local authority OWNER TYPE:

Stable block 1835, on the eastern edge of Park, to the south of the Small Mansion. Emergency works have been undertaken, partly funded by English Heritage. Discussions are continuing with LPAs and Heritage Lottery Fund to secure funding for repair and restoration of the estate. and a major bid is due to be submitted to the Heritage Lottery Fund in November 2011.

Contact: Timothy Jones 020 7973 3780



Gothic Boathouse, SITE NAME: Gunnersbury Avenue, Gunnersbury Park W3

Listed Building Grade II, CA, RPG II* DESIGNATION:

Very bad CONDITION: N/A OCCUPANCY:

PRIORITY:

A(A)OWNERTYPE: Local authority Mid C19 Gothic folly tower, converted from a tile kiln and situated on the southern shore of Potomac Lake. Emergency works have been undertaken, partly funded by English Heritage. Discussions are continuing with LPAs and Heritage Lottery Fund to secure funding for repair and restoration of the estate and a major bid is to be submitted to the Heritage Lottery Fund in November 2011.

Contact: Maggie Urquhart (LPA) 020 8583 4941



SITE NAME: Gothic ruins in Gunnersbury Park, Gunnersbury Avenue, Gunnersbury Park W3

DESIGNATION: Listed Building Grade II, CA, RPG II*

Poor CONDITION: N/A A(A)PRIORITY:

Local authority OWNER TYPE:

Sham Gothic ruins, on the east side of Gunnersbury Park. Discussions are continuing with LPAs and Heritage Lottery Fund to secure funding for repair and restoration of the estate and a major bid is due to be submitted to the Heritage Lottery Fund in November 2011.

Contact: Maggie Urquhart (LPA) 020 8583 4941



The Large Mansion, Gunnersbury SITE NAME: Park House, Gunnersbury Avenue, Gunnersbury Park W3

DESIGNATION: Listed Building Grade II*, CA, RPG II*

CONDITION: Occupied OCCUPANCY:

C (C) PRIORITY

OWNERTYPE: Local authority

Country house 1801-28 by and for Alexander Copland; remodelled 1836 by Sydney Smirke for Nathan Rothschild. Good interiors, houses local history museum and education centre for the Boroughs of Hounslow and Ealing. Discussions are continuing with LPAs and Heritage Lottery Fund to secure funding for repair and restoration of the estate and a major bid is due to be submitted to the HLF in November 2011.

Contact: Timothy Jones 020 7973 3780



The Small Mansion. SITE NAME:

> Gunnersbury House, Gunnersbury Avenue, Gunnersbury Park W3

DESIGNATION: Listed Building Grade II, CA, RPG II*

Poor CONDITION: Vacant PRIORITY: C (C)

OWNERTYPE: Local authority

Built circa 1810, the smaller of the two houses on the site of Gunnersbury House demolished circa 1801. Discussions are continuing with LPAs and Heritage Lottery Fund to secure funding for repair and restoration of the estate and a major bid is due to be submitted in November 2011.

Contact: Maggie Urquhart (LPA) 020 8583 4941

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented

NOTE:

If the priority category has changed since the 2010 register, the previous category given in brackets

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



West stable block in Gunnersbury SITE NAME: Park, Gunnersbury Avenue, Gunnersbury Park W3

DESIGNATION: Listed Building Grade II, CA, RPG II*

Very bad CONDITION: Vacant OCCUPANCY:

PRIORITY

A(A)OWNER TYPE: Local authority Early C19 stables situated within the Gunnersbury Park, now a public park. Emergency works have been undertaken, partly funded by English Heritage. Discussions are continuing with LPAs and Heritage Lottery Fund to secure funding for repair and restoration of the estate and a major bid is due to be submitted to the Heritage Lottery Fund in November 2011.

Contact: Maggie Urquhart (LPA) 020 8583 4941



Gunnersbury Park SITE NAME: DESIGNATION: Registered Park and Garden Grade II*, also part in CA, 22 LBs Extensive significant problems CONDITION: VULNERABILITY: High TREND: Declining

Local Authority, multiple owners OWNER TYPE:

A landscape park developed in the C18 by Princess Amelia and in C19 by Baron Lionel de Rothschild. Became a public park in 1925 jointly owned by Hounslow and Ealing. Landscape in variable condition with nine buildings at risk. Gunnersbury remains one of the most sensitive and complex cases in the Region. London Borough of Ealing has secured £5m for repair to the mansion. Consultants appointed in March 2011 to prepare a landscape Development Plan by July 2011.

Contact: Zosia Mellor 020 7973 3473



St Lawrence's Church (former), SITE NAME: High Street. **Brentford TW8**

DESIGNATION: Listed Building Grade II*, CA

Vacant OCCUPANCY: PRIORITY: C(C)OWNER TYPE: Company

Redundant C15 church tower, nave 1764 by Thomas Hardwick. Victorian additions. Empty since 1960s and stripped of fittings. Urgent repairs to the medieval tower were carried out; building since neglected but weathertight. Proposals for waterside development, including the church, have stalled. Condition of the building is deteriorating.

Contact: Timothy Jones 020 7973 3780



"Roman Bridge", SITE NAME: lersey Road, Osterley Park TW7

DESIGNATION: Listed Building Grade II*

Very bad CONDITION: OCCUPANCY: N/A PRIORITY A(A)OWNERTYPE: Private

Bridge, 1780, by Robert Adam. Rusticated stone-faced with one segmental arch. Flanking pairs of rusticated Doric half columns. Severed from the historic park by the M4. Straddles the borough boundary between Ealing and Hounslow. In need of repair and consolidation; suffers from sporadic vandalism.

Contact: Timothy Jones 020 7973 3780



Kew Bridge Railway Station, SITE NAME Kew Bridge Road, **Brentford TW8**

DESIGNATION: Listed Building Grade II, CA

Part occupied OCCUPANCY:

C (C) PRIORITY

OWNER TYPE: Company

Railway station built 1850 by Sir William Tite for the London and South Western Railway. Largely unoccupied, boarded up and deterioration increasing. Externally weathertight. No longer required for railway use and is likely to be sold. Nearby development site now under construction may help as a catalyst for combined action by English Heritage, the Local Authority and others.

Contact: Maggie Urquhart (LPA) 020 8583 4941



Rose and Crown Inn. SITE NAME: 333 London Road

DESIGNATION: Listed Building Grade II

CONDITION: Vacant OCCUPANCY:

B (New entry) PRIORITY

OWNERTYPE: Private

C18 Coaching Inn with watching bay at first floor. Characterful and deliberatively attractive elevations. Public House on ground floor. Following a long period of lack of maintenance and water ingress, listed building consent has been granted for conversion to small hotel.

Contact: Maggie Urquhart (LPA) 020 8583 4941

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



Ornamental bridge in Syon Park, SITE NAME:

Park Road, Isleworth TW7

DESIGNATION: Listed Building Grade II, CA, RPG II

Poor CONDITION: N/A OCCUPANCY: D(D)PRIORITY:

Wrought iron bridge, 1827-30 over west lake on the north west boundary of Park. The owners have carried out a structural survey and works of repair are due to commence in September 2011.

Contact: Maggie Urquhart (LPA) 020 8583 4941



Fortescue House (Former Rectory), SITE NAME: Park Road, Hanworth Park, Hanworth TWI3

DESIGNATION: Listed Building Grade II, CA

Fair CONDITION: Vacant C(C)PRIORITY: Private OWNER TYPE:

Early C19 classical villa style house, symmetrical front. Has been extended and used as a school. Discrete areas have suffered former dry rot following water ingress. Repairs to halt deterioration have been carried out. The building is currently the subject of a planning appeal for change of use.

Contact: Maggie Urquhart (LPA) 020 8583 4941



The Hermitage, SITE NAME: 17 Upper Sutton Lane, Heston TW5

DESIGNATION: Listed Building Grade II

CONDITION: Very bad Vacant OCCUPANCY: PRIORITY-A (B) Private OWNER TYPE:

Late C15 timber-framed house with later additions. Badly damaged by fire in 2003. The building has suffered further deterioration following theft of the temporary protective roof. Owner seeking enabling development but proposals are considered excessive. Discussions ongoing.

Contact: Maggie Urquhart (LPA) 020 8583 4941



SITE NAME: Hanworth Park House, Uxbridge Road, Hanworth TW13

DESIGNATION: Listed Building Grade II

CONDITION: Poor Vacant A(A)PRIORITY: OWNERTYPE: Company

Country house built after 1828 with extension c1860. Urgent works carried out 2002 but building has suffered vandalism and further deterioration. Further works undertaken to stem dry rot outbreaks and secure the building but will need renewal. Lack of agreements on land swap for enabling development have stalled progress.

Contact: Maggie Urquhart (LPA) 020 8583 4941

SITE NAME:

18th century garden feature at Hanworth Park, Hounslow

Scheduled Monument (No. 1002008) DESIGNATION: CONDITION: Generally satisfactory but with significant localised problems Declining PRINCIPAL VULNERABILITY: Deterioration – in need of management TREND: Private Jane Sidell 020 7973 3738 OWNER TYPE: CONTACT:

Double ditched enclosure beside A30 road 500yds (460m) west of East Bedfont parish church, Hounslow SITE NAME:

DESIGNATION:	Scheduled Monument (No. 1002043)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Jane Sidell 020 7973 3738

Romano-British site 1000yds (910m) west of East Bedfont parish church, Hounslow

DESIGNATION:	Scheduled Monument (No. 1002042)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Jane Sidell 020 7973 3738

Gunnersbury Park SITE NAME:

DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Unknown
CONTACT:	Maggie Urquhart (LPA) 020 8583 4941	NEW ENTRY?:	No

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	St Pauls Church, Heston East		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Maggie Urquhart (LPA) 020 8583 4941	NEW ENTRY?:	No

ISLINGTON
一位
THE PERSON NAMED IN
101

Stables to rear of No. 55, SITE NAME: Balfe Street NI

DESIGNATION: Listed Building Grade II, CA Fair CONDITION: Vacant OCCUPANCY:

Company. Forms part of the P&O development site. Scheme approved for repair and regeneration of this whole block, including the stables. Permission has been granted for conversion into office use, and likely to be implemented in 2012.

1900-01. Ground floor in use as a public house, upper

floors are vacant and in poor condition (roof leaking).

Stables built circa 1895 for the London General Omnibus

Contact: Luciana Grave (LPA) 020 7527 2389



Flying Scotsman Public House, SITE NAME: 2-4 Caledonian Road, King's Cross NI

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION:

PRIORITY:

Part occupied OCCUPANCY:

D (D) OWNER TYPE: Company

C(C)PRIORITY: OWNER TYPE: Company

Contact: Luciana Grave (LPA) 020 7527 2389



Former Board School. SITE NAME: Eagle Court ECI

DESIGNATION: Listed Building Grade II, CA

Fair CONDITION: Vacant OCCUPANCY: F(D) PRIORITY: OWNER TYPE: Company Built 1872-74, extended 1894 in a simple Queen Anne style. A scheme has been approved for redevelopment of the site, and works are now well advanced and scheduled for completion October 2011. The building will be occupied for academic use.

Contact: Andy Rayner (LPA) 020 7527 4087



Mecca Bingo Hall, SITE NAME: 161-169 Essex Road NI

DESIGNATION: Listed Building Grade II*, CA Poor CONDITION: Vacant C(C)PRIORITY: Company OWNER TYPE:

Built as the Carlton Cinema in 1930 by George Coles, now a bingo hall. Black, white and coloured faience to the Essex Road front, the rest of yellow brick; roof slate. The facade to Essex Road is in Egyptian style. Currently vacant but scheme for repair being progressed. A planning appeal for roof and basement extension to the hall was dismissed by the Planning Inspectorate. Future unknown.

Contact: Dorian Crone 020 7973 3763



Rear of (remains of wall), SITE NAME: 23 Goswell Road ECI

DESIGNATION: Listed Building Grade II, CA CONDITION: OCCUPANCY: N/A

C (F) PRIORITY: OWNERTYPE: Unknown Remains of wall, ten metres long and three metres high, west of 23 Goswell Road, on former tennis courts site. Uncertain date although possible boundary wall to mansion built by Sir Edward North from 1545 on the Charterhouse site. Repairs only partially completed. Condition of the wall has deteriorated and now is propped up. Further consolidation and repairs required.

Contact: Luciana Grave (LPA) 020 7527 2389



SITE NAME: Hornsey Road Baths, Hornsey Road N7

DESIGNATION: Listed Building Grade II CONDITION: Fair Vacant OCCUPANCY: C (C) PRIORITY: OWNERTYPE: Local authority

Public baths and wash house with rear laundry, built 1892 to design of A Hessell Tiltman in Queen Anne style. Distinctive 1930s Art Deco 'diving lady' neon sign on south east elevation. Much of the complex is converted to residential use. The proposed theatre group users are no longer intending to occupy the former laundry building. Future use unknown.

Contact: Luciana Grave (LPA) 020 7527 2389

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented

NOTE:

If the priority category has changed since the 2010 register, the previous category given in brackets

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



SITE NAME: Studio (former Chapel), Lloyd Baker Street, Thornhill WC I

DESIGNATION: Listed Building Grade II, CA

CONDITION: Fair
OCCUPANCY: Vacant
PRIORITY: D (C)
OWNER TYPE: Private

Former Chapel of the House of Retreat (Lloyd Baker Street and Lloyd Square), 1891-2 by Ernest Newton. Stock brick with tracery windows in stone, slate roof, late decorated gothic. Permission granted to convert building to residential use, but works not started (May 2011).

Contact: Andy Rayner (LPA) 020 7527 4087



SITE NAME: Islington War Memorial Arch,
Manor Gardens N7

DESIGNATION: Listed Building Grade II CONDITION: Fair

occupancy: N/A
priority: C (C)
owner type: Company

Listed war memorial designed by Percy Adams, formerly part of the Royal Northern Hospital. The memorial is the archway around which the new building has been constructed. Repairs carried out including works to the lettering and stonework and the arch remains in a fair condition. Further investigative work is required to establish the cause of water ingress into stonework.

Contact: Kate Graham (LPA) 020 7527 2380



SITE NAME: Railings, walls, gate piers and gates to Caledonian Park, Market Road N7

DESIGNATION: Listed Building Grade II

condition: Poor occupancy: N/A priority: C (C)

OWNERTYPE: Local authority

Railings, walls and gates to Caledonian Market built 1854 (market demolished). Some repairs carried out with help of English Heritage grant, but extensive further works required. Redevelopment of housing on adjacent site underway. Section of railings to be repaired as part of this but no scheme for complete repair as yet.

Contact: Luciana Grave (LPA) 020 7527 2389



SITE NAME: Finsbury Health Centre,
Pine Street ECI

DESIGNATION: Listed Building Grade I

CONDITION: Poor
OCCUPANCY: Occupied
PRIORITY: C (C)

OWNER TYPE: Health Authority

Seminal Modern Movement health centre built 1935-8 to the design of Berthold Lubetkin. Conservation plan and management guidelines grant-aided by English Heritage. The Health Authority are considering vacating the building. Future of the building remains in doubt.

Contact: Dorian Crone 020 7973 3763



SITE NAME: Finsbury Town Hall,
Rosebery Avenue ECI

DESIGNATION: Listed Building Grade II*, CA

CONDITION: Fair
OCCUPANCY: Occupied
PRIORITY: F (F)

OWNERTYPE: Local authority

Town hall, built 1895 to the design of C Evans Vaughan in an eclectic 'Free Renaissance' style. Magnificent public hall on first floor with elaborate plasterwork in Belle Epoque manner. Now in use as dance studios with main halls available for public use. External fabric of building still not repaired.

Contact: Dorian Crone 020 7973 3763



SITE NAME: House of Detention (part of former), Sans Walk ECI

DESIGNATION: Listed Building Grade II, CA CONDITION: Fair

OCCUPANCY: Vacant PRIORITY: D (D)
OWNERTYPE: Private

Part of Middlesex House of Detention built 1845-47, occupied until recently as a museum. In stable condition and works for conversion to office space for a part of the structure approved. No proposals for the remaining elements.

Contact: Luciana Grave (LPA) 020 7527 2389

PRIORITY (FOR BUILDINGS)


- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



St Paul's Church, SITE NAME: St Paul's Road NI

DESIGNATION: Listed Building Grade II*, CA

Poor CONDITION:

Part occupied OCCUPANCY:

F (F) Charity OWNER TYPE:

Redundant church, built 1826-28 to design of Sir Charles Barry in early Gothic Revival style. Occupied by the Steiner Foundation and in use as school. Application under consideration for partnership funding from English Heritage for repairs to former vestry roof and associated works.

Contact: Dorian Crone 020 7973 3763



49 Thornhill Road NI SITE NAME:

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION:

Part occupied

D (C) PRIORITY: Private OWNER TYPE:

House, 1868/9 of stock brick with hipped slate roof and end stock. Two storeys, three window range of two light casements and central 6 over 6 sash. Moulded shouldered architraves. Central porch with ionic columns and entablature. The single storey side extension is derelict. Permission granted in 2011 for residential use, but not yet commenced (May 2011).

Contact: Kate Graham (LPA) 020 7527 2380



Railings. SITE NAME:

Thornhill Square NI

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION: N/A OCCUPANCY: PRIORITY: D (D)

OWNERTYPE: Local authority

English Heritage grant-aided work for repairs to railings has been completed. Islington are proposing to apply to the Heritage Lottery Fund for further repairs and landscaping funding.

Contact: Andy Rayner (LPA) 020 7527 4087

Contact: Andy Rayner (LPA) 020 7527 4087



SITE NAME: Railings,

Wilmington Square WCI

DESIGNATION: Listed Building Grade II, CA

CONDITION: Poor N/A C(C)PRIORITY:

Local authority OWNER TYPE:

Cast iron railings of 1819-1841. Urgent works carried out, but currently no funding for full repair programme.



SITE NAME:

Celestial Church of Christ, Cloudesley Square N1

DESIGNATION: Listed Place of Worship Grade II*, CA


Very bad CONDITION:

C (C) PRIORITY:

Religious organisation OWNER TYPE:

Built 1826-9 to the design of Sir Charles Barry. Although urgent repairs to the roof and high level stonework have been carried out with English Heritage / Lottery Fund funding, the west turrets are in a very poor condition and the finials remain clad in netting, also the ceiling has been badly affected by decayed roof trusses. The church remains in use.

Contact: Don Bianco 020 7973 3745



SITE NAME:

Union Chapel, Compton Terrace N1

DESIGNATION: Listed Place of Worship Grade II*, CA

Very bad PRIORITY: F(D)

OWNER TYPE: Religious organisation

Congregational chapel and related buildings of 1876-7, the upper part of the tower completed in 1889, by James Cubbit, on the site of the chapel of 1806 built for a joint Anglican / non conformist congregation. The Union Chapel have major tower / roof renewal / high level work to carry out. Joint English Heritage / Heritage Lottery Fund grant awarded in December 2008 and 2009, also major funding from Islington Council in 2010.

Contact: Don Bianco 020 7973 3745

SITE NAME:

Bunhill Fields, Finsbury Square

DESIGNATION:	Conservation Area	CONDITION:	Fair
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Luciana Grave (LPA) 020 7527 3000	NEW ENTRY?:	No

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable)
 end use or user identified;
 functionally redundant buildings
 with new use agreed but not yet implemented

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Chapel Market		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Improving significantly
CONTACT:	Luciana Grave (LPA) 020 7527 3000	NEW ENTRY?:	No
SITE NAME:	Mercers Road / Tavistock Terrace		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Luciana Grave (LPA) 020 7527 3000	NEW ENTRY?:	No
SITE NAME:	St John's Grove		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	No significant change
CONTACT:	Luciana Grave (LPA) 020 7527 3000	NEW ENTRY?:	No
SITE NAME:	St Mary Magdalene		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Deteriorating
	ricalarri		
CONTACT:	Luciana Grave (LPA) 020 7527 3000	NEW ENTRY?:	No
CONTACT: SITE NAME:		NEW ENTRY?:	No
	Luciana Grave (LPA) 020 7527 3000	NEW ENTRY?: CONDITION:	
SITE NAME:	Luciana Grave (LPA) 020 7527 3000 Stroud Green		Very bad No significant change
SITE NAME: DESIGNATION:	Luciana Grave (LPA) 020 7527 3000 Stroud Green Conservation Area	CONDITION:	Very bad
SITE NAME: DESIGNATION: VULNERABILITY:	Luciana Grave (LPA) 020 7527 3000 Stroud Green Conservation Area Low	CONDITION: TREND:	Very bad No significant change
SITE NAME: DESIGNATION: VULNERABILITY: CONTACT:	Luciana Grave (LPA) 020 7527 3000 Stroud Green Conservation Area Low Luciana Grave (LPA) 020 7527 3000	CONDITION: TREND:	Very bad No significant change
SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME:	Luciana Grave (LPA) 020 7527 3000 Stroud Green Conservation Area Low Luciana Grave (LPA) 020 7527 3000 Tollington Park	CONDITION: TREND: NEW ENTRY?:	Very bad No significant change No

KENSINGTON AND CHELSEA



SITE NAME: 31, Brompton Square, South Kensington SW3

DESIGNATION: Listed Building Grade II, CA

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNERTYPE: Unknown

House I 824-39, part of Brompton Square layout. A series of planning and listed building consents have been granted for internal alterations and rear extensions. Works to implement the consents came to a halt in December 2008. An urgent works notice to make the building weathertight was served and complied with in December 2009.

Contact: Mark Butler (LPA) 020 7361 2465



SITE NAME: Campden Hill,
I Campden Hill W8

DESIGNATION: Listed Building Grade II, CA
CONDITION: Fair
OCCUPANCY: Vacant
PRIORITY: D (D)
OWNERTYPE: Private

Private house built 1914-15. It represents an Edwardian Arts and Crafts led interpretation of a large C17 country house in an urban setting. Permission was granted for internal alterations and extensions in July 2008. Works have not yet commenced on site and the building is now showing the initial signs of neglect with lack of general maintenance.

Contact: Mark Butler (LPA) 020 7361 2465

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS CA Conserv

CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS



Boundary wall SITE NAME: to Kensal Green Cemetery, Harrow Road W10

DESIGNATION: Listed Building Grade II, CA, RPG I

Very bad CONDITION: N/A OCCUPANCY:

E (A) PRIORITY: OWNER TYPE: Company

High brick boundary wall to Harrow Road, a 100m section (approx.) of which collapsed in 2006. Proposals have been formulated for the rebuilding and strengthening works. English Heritage have awarded a grant towards the first phase of rebuilding the collapsed section. Further movement has occurred resulting in a Dangerous Structure Notice being served. Unsound sections have been carefully removed.

Contact: Mark Butler (LPA) 020 7361 2465



Monuments SITE NAME: at Kensal Green Cemetery. Harrow Road

DESIGNATION: Listed Building Grade II*, CA, RPG I

Poor CONDITION: N/A C(C)PRIORITY: OWNER TYPE: Company London's first metropolitan cemetery begun 1833, designed by John William Griffith. Contains numbers of listed monuments and structures in a poor state of repair A Conservation Management Plan is guiding future work to the cemetery.

Contact: Sheila Stones 020 7973 3785



The Anglican Chapel, SITE NAME: Harrow Road, Kensal Green Cemetery W10

Listed Building Grade I, CA, RPG I DESIGNATION: CONDITION:

N/A OCCUPANCY: PRIORITY: C(C)OWNER TYPE: Company 1835-36 by John Griffith for the General Cemetery Company. Portland stone and stucco. Central chapel of a Greek Doric tetrastyle, flanked by three-bay colonades, with nine-bay returns to north and south, terminating in (now roofless) pavilions containing marble memorial sculpture. No longer in use, it is suffering from water ingress. A detailed condition survey is now underway with English Heritage grant.

Contact: Timothy Jones 020 7973 3780



SITE NAME: The North Colonnade, Harrow Road, Kensal Green Cemetery W10

DESIGNATION: Listed Building Grade II, CA, RPG I

Poor CONDITION: N/A C(C)PRIORITY-OWNER TYPE: Company Built by John Griffith in 1833 to display tablets and monuments, with a brick vaulted catacomb underneath. In poor condition. English Heritage grant awarded in 2010 towards a condition survey of the Western bay of the Colonnade.

Contact: Mark Butler (LPA) 020 7361 2465



Kensal Green (All Souls) Cemetery SITE NAME: DESIGNATION: Registered Park and Garden Grade I,

also CA, 139 LBs

Generally unsatisfactory

with major localised problems

VULNERABILITY: High Declining

OWNER TYPE: Corporate, single owner London's first metropolitan cemetery begun 1833, designed by John William Griffith. Contains a number of listed monuments and structures at risk. The Anglican Chapel and the North Colonnade are buildings at risk and the boundary wall has partially collapsed. A Conservation Management Plan is in place to guide future work to the cemetery.

Contact: Zosia Mellor 020 7973 3473



Commonwealth Institute, SITE NAME: Kensington High Street W6

DESIGNATION: Listed Building Grade II*, CA, RPG II

Fair CONDITION: OCCUPANCY: Vacant D (D) PRIORITY:

OWNERTYPE: Company

The Commonwealth Institute designed by Robert Matthew, Johnson-Marshall and Partners is one of the most important public buildings in Britain of the late 1950s. Vacant since 1995. Scheme agreed subject to Section 106.

Contact: Timothy Jones 020 7973 3780

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented

NOTE:

If the priority category has changed since the 2010 register, the previous category given in brackets

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



SITE NAME:	Commonwealth	Institute

DESIGNATION: Registered Park and Garden Grade II,

also CA, I LB

Extensive significant problems CONDITION:

VULNERABILITY: High

Unknown

OWNER TYPE: Corporate, single owner

Garden for the Commonwealth Institute (1960-2). Outline design by architects Robert Matthew and Johnson Marshall refined and detailed by Dame Sylvia Crowe, showing a strong unity between architecture and a designed landscape. The Institute has been vacant since 1995. Future use as the Design Museum has been granted planning consent.

Arcade, 1839-40, situated in centre of southern half of 1830s cemetery designed by Benjamin Baud. A magnificent

united composition comprising the four quadrants which

form the circle and the avenue. The structure is suffering

flat roof necessitating (temporary) propping in parts. Some stone and brick cleaning was carried out in 2008.

gradual decay owing to the later addition of a cast concrete

Contact: Zosia Mellor 020 7973 3473



SITE NAME: Arcade forming circle and avenue, Brompton Cemetery, Old Brompton Road SW10

DESIGNATION: Listed Building Grade II*, RPG II*

CONDITION: Poor

OCCUPANCY: N/A C (C) PRIORITY:

OWNERTYPE: Crown

Contact: Sheila Stones 020 7973 3785



25-26 Pembridge Square W2 SITE NAME

DESIGNATION: Listed Building Grade II, CA

CONDITION:

Part occupied OCCUPANCY:

B (New entry) PRIORITY: Private OWNER TYPE:

June 2009 for change of use back to residential with rear extension and basement. Works have not yet commenced on site and the buildings are now showing signs of neglect.

Two mid C19 stucco houses in florid classical style now

joined together to form an hotel. Permission granted in



18, Queen's Gate Place SW7 SITE NAME:

DESIGNATION: Listed Building Grade II, CA CONDITION: Poor Vacant OCCUPANCY:

PRIORITY: C(C)Private OWNER TYPE:

Mid C19 terrace house with attached mews arch. Planning and listed building consent were granted in June 2008 for internal alterations and rear extensions. The works were part implemented and then came to a halt and the property sold. After pre-application discussions with new owner, an application was submitted in March 2010. The building is in a poor state of repair with water ingress and dry rot.

Contact: Mark Butler (LPA) 020 7361 2465

Contact: Mark Butler (LPA) 020 7361 2465



Church of St Augustine, SITE NAME Queen's Gate, Kensington SW7

DESIGNATION: Listed Place of Worship Grade II*, CA

Poor CONDITION:

PRIORITY: F (New entry)

OWNER TYPE: Religious organisation

Large church designed by W Butterfield in the Gothic style. Constructed from yellow brick with black and red and stone bands. Rich polychrome brick decoration throughout. In active use for worship and offices. General wear and tear beyond facade with partly boarded east window. Large derelict site adjacent to north. Ongoing grant aid towards high level works.

Contact: Tracey Craig 020 7973 3756

SITE	NIAME:

Kensal Green Cemetery

DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Improving
CONTACT:	David McDonald (LPA) 020 7361 3352	NEW ENTRY?:	No

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS

KINGSTON UPON THAMES



Kingston Telephone Exchange, Ashdown Road, Kingston upon Thames

DESIGNATION: Listed Building Grade II

Fair CONDITION: Vacant C(C)PRIORITY-

Company OWNER TYPE:

Purpose built telephone exchange. Built in 1907 and opened in 1908. Arts and Crafts style in asymmetrical plan. Works to make the building secure and weathertight completed in 2008/2009. Building located within an area identified for comprehensive redevelopment as set out in the K+20 Area Action Plan.

Contact: Andrew Lynch (LPA) 020 8547 5376



Former Head Post Office, SITE NAME: 42 Eden Street, Kingston upon Thames

Listed Building Grade II DESIGNATION: CONDITION: Fair Vacant OCCUPANCY: E (E) PRIORITY: OWNERTYPE: Company

Post office built in 1875. Three storeys in red brick with stone dressings. Works for internal improvements and weather proofing were carried out in 2008/2009 in preparation for leasing out. However, the reuse of the building has been delayed due to wider considerations relating to the Council's aspirations for town centre renewal as set out in the K+20 Area Action Plan.

Contact: Andrew Lynch (LPA) 020 8547 5376



Lambeth uncovered coal store SITE NAME: including tower and attached tunnels, Portsmouth Road, Surbiton

Listed Building Grade II, CA DESIGNATION: CONDITION: Poor

Vacant OCCUPANCY: A(A)PRIORITY: Private OWNER TYPE:

Uncovered coal store with tower and attached underground tunnels. Built 1851-1852 to the design of James Simpson in a Romanesque style for the Lambeth Waterworks. Vacant for many years. No works have been carried out recently. Local authority to instigate negotiations with owner.

Contact: Andrew Lynch (LPA) 020 8547 5376

SITE NAME:

Castle Hill earthwork, Chessington, Kingston upon Thames

DESIGNATION:	Scheduled Monument (No. 1002018)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Digging	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Jane Sidell 020 7973 3738

LAMBETH



Beaufoy Institute, 39 Black Prince Road. Vauxhall SEI

DESIGNATION: Listed Building Grade II, CA

Fair CONDITION: Vacant OCCUPANCY: C(C)

OWNERTYPE: Local authority

Educational building of 1907 (architect FA Powell). Brick and terracotta facade with free Baroque motifs. 1930 laboratory wing to the side and assembly hall at the rear. Vacated by Lilian Baylis Secondary School in 1999. Options for reuse being discussed.

Contact: Elizabeth Martin (LPA) 020 7926 1213



118 Camberwell New Road SE5 SITE NAME:

Small, two storey early-mid C19 house. Vacant and boarded up. Sold by the local planning authority to a private buyer at auction in March 2011.

DESIGNATION: Listed Building Grade II, CA

Vacant OCCUPANCY: PRIORITY:

E (New entry) OWNERTYPE: Private

Contact: Elizabeth Martin (LPA) 020 7926 1213

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable)
 end use or user identified;
 functionally redundant buildings
 with new use agreed but not yet implemented

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

Conservation Area CA LB/LBs LPA NP RPG SM/SMs UA WHS



SITE NAME: 124 and 134

Camberwell New Road SE5

DESIGNATION: Listed Building Grade II, CA

CONDITION: Fair

PRIORITY: E (New entry)

OWNERTYPE: Local authority

Contact: Elizabeth Martin (LPA) 020 7926 1213

Two terrace houses part of an early-mid C19 terace.

authority to a private buyer at auction in March 2011.

Vacant and boarded up. Sold by the local planning



SITE NAME: 135 Clapham Road SW9

House begun in 1821 by builder John Lett. Stock brick with stone dressing. Later C19 extension. Permission granted for conversion to flats in March 2007. Repairs in progress.

DESIGNATION: Listed Building Grade II, CA

condition: Poor
occupancy: Vacant
priority: E (E)
ownertype: Company

Contact: Douglas Black (LPA) 020 7926 4065



SITE NAME: Shelter,


Denmark Hill, Ruskin Park SE5

DESIGNATION: Listed Building Grade II, RPG II

condition: Poor occupancy: N/A priority: B (B)

OWNER TYPE: Local authority

Late C18 screen and flanking walls of house that stood on the site. Funding is being sought by the Local Authority for future refurbishment and through access.





SITE NAME: Raleigh Hall,

I and 3 Effra Road SW2

DESIGNATION: Listed Building Grade II, CA

CONDITION: Very bad
OCCUPANCY: Vacant
PRIORITY: A (A)

OWNERTYPE: Local authority

Substantial pair of villas built 1824. There is a current approval for an extension and conversion to house the black cultural archive. Conditions are being submitted for discharge and building works due to start with a planned opening date of July 2012.

Contact: Elizabeth Martin (LPA) 020 7926 1213



SITE NAME: Gentlemen's Public Convenience, Kennington Cross SEI I

DESIGNATION: Listed Building Grade II, CA

condition: Fair occupancy: N/A PRIORITY: C (C)

OWNERTYPE: Local authority

Underground gentlemen's public lavatory with ornate railings enclosing stairway. Listing includes elegant flue ventilator pipe and adjacent C19 bollards and horse trough. Lavatories unused since the 1980s. Some repairs have been completed but no use has yet been secured. A local group is considering use options.

Contact: Elizabeth Martin (LPA) 020 7926 1213



SITE NAME: Off licence attached to the Old Red Lion PH, 44 Kennington Park Road SEI I

DESIGNATION: Listed Building Grade II

condition: Poor occupancy: Vacant PRIORITY: C (New

PRIORITY: C (New entry)

OWNERTYPE: Private

Tudorbethan style off-licence, built circa 1929. Vacant. Damage including broken window pane. Planning permission for redevelopment with facade retention granted in 2004 but has expired. The building is for sale.

Contact: Elizabeth Martin (LPA) 020 7926 1213

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA Conse LB/LBs Listed LPA Local NP Natior RPG Regist: SM/SMs Sched UA Unitar WHS World



Walls of former graveyard SITE NAME: on perimeter of recreation ground, Lambeth High Street SEII

DESIGNATION: Listed Building Grade II

Very bad CONDITION: N/A OCCUPANCY:

D (New entry) PRIORITY: OWNER TYPE: Local authority

C18 walls of reddish brick, C19 piers and railings added at eastern part of southern range. Brickwork and coping in poor condition; cracked and bowed in places. Listed building consent has been granted to carry out repair works 2011.

Contact: Elizabeth Martin (LPA) 020 7926 1213



Walls, railings and gates SITE NAME: to Church of St Mary. Lambeth Road SEI

DESIGNATION: Listed Building Grade II, CA

Very bad CONDITION: N/A A(A)PRIORITY: Trust OWNER TYPE:

Mid C19 ragstone walls and ironwork. In a partial state of collapse. Urgent action needed to secure repair and restoration. English Heritage are in discussions with the owner.

Contact: Elizabeth Martin (LPA) 020 7926 1213



Lilian Baylis School, SITE NAME: Lollard Street SEII

DESIGNATION: Listed Building Grade II

CONDITION:

Part occupied OCCUPANCY: C (E) PRIORITY:

OWNERTYPE: Local authority

County Council. Future uses for the site are being considered. Planning application for part of the site is being considered.

Contact: Elizabeth Martin (LPA) 020 7926 1213

Comprehensive school. Designed 1960 and built

by the Architects' Co-Partnership for the London



SITE NAME: Old Fire Station (South London Theatre), 2A Norwood High Street SE27

DESIGNATION: Listed Building Grade II, CA

CONDITION: Poor

Part occupied

A(A)PRIORITY-

Local authority OWNER TYPE:

Former fire station in use as South London Theatre for many years, leased from London Borough of Lambeth by South London Theatre. There has been internal water damage and significant roof repairs are required.

Contact: Elizabeth Martin (LPA) 020 7926 1213



Catacombs beneath the Remembrance SITE NAME: Garden, Norwood High Street, West Norwood Memorial Park SE27

DESIGNATION: Listed Building Grade II, CA, RPG II*

CONDITION: Very bad N/A OCCUPANCY:

B (C) PRIORITY

OWNER TYPE: Local authority

Catacombs circa 1837; cemetery laid out circa 1837 by Sir William Tite. A temporary roof has been erected over the entrance to allow the structure to dry out before agreeing repairs and funding options are being explored. Application to retain temporary roof expected 2011.

Contact: Elizabeth Martin (LPA) 020 7926 1213



SITE NAME: Monuments.

> Norwood High Street, West Norwood Memorial Park SE27

DESIGNATION: Listed Building Grade II, CA, RPG II*

Fair CONDITION: N/A PRIORITY: F (F)

OWNERTYPE: Local authority

Originally the South Metropolitan Cemetery laid out in circa 1837 to the design of Sir William Tite. A management plan is being drafted which will include a conservation strategy.

Contact: Elizabeth Martin (LPA) 020 7926 1213

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable)
 end use or user identified;
 functionally redundant buildings
 with new use agreed but not yet implemented

NOTE:

If the priority category has changed since the 2010 register, the previous category given in brackets

ABBREVIATIONS CA LB/LBs LPA NP RPG SM/SMs

UA WHS



SITE NAME: Israel Thomas tomb,

Norwood Road,

West Norwood Memorial Park SE27

DESIGNATION: Listed Building Grade II, CA, RPG II*

CONDITION: Poor

PRIORITY: A (New entry)

OWNER TYPE: Unknown

Pedestal monument above a vault in the Egyptian revival style, circa I 842. Overgrown with vegetation, plinth broken and open to the elements.

Contact: Elizabeth Martin (LPA) 020 7926 1213



SITE NAME: Thomas De La Garde Grissell Tomb, Norwood Road.

West Norwood Memorial Park SE27

DESIGNATION: Listed Building Grade II, CA, RPG II*

CONDITION: Poor OCCUPANCY: N/A

PRIORITY: A (New entry)
OWNERTYPE: Unknown

Chest tomb, circa 1847. Cast iron, stucco and pink granite. Plinth broken, and parts exposed.

Contact: Elizabeth Martin (LPA) 020 7926 1213

Contact: Simon Hickman 020 7973 3762



SITE NAME: Tomb of Alexander Berens,

Norwood Road,

West Norwood Memorial Park SE27

DESIGNATION: Listed Building Grade II*, CA, RPG II*

condition: Very bad

occupancy: N/A

PRIORITY: A (New entry)

OWNERTYPE: Unknown

1858 chest tomb designed by E M Barry. Pink granite plinth, with marble superstructure and Portland stone sculpture. The roof is broken, door missing, slabs of granite broken and water ingress has occurred.

An arcaded chest tomb, circa 1847. The columns and top slab have been lost, leaving the structural rods exposed.



SITE NAME: Tomb of Mrs Alice Moffatt,

Norwood Road,

West Norwood Memorial Park SE27

DESIGNATION: Listed Building Grade II, CA, RPG II*

condition: Very bad

OCCUPANCY: N/A

PRIORITY: A (New entry)
OWNER TYPE: Unknown

Contact: Elizabeth Martin (LPA) 020 7926 1213



SITE NAME: West Norwood Memorial Park

DESIGNATION: Registered Park and Garden Grade II*,

also CA, 66 LBs

CONDITION: Generally unsatisfactory

with major localised problems

VULNERABILITY: High

TREND: Declining

owner type: Local Authority, single owner

Originally the South Metropolitan Cemetery founded in 1837 and designed by William Tite. A number of tombs and monuments are in poor condition. Background studies and a draft landscape Conservation Management Plan have been prepared but have yet to be adopted.

Contact: Zosia Mellor 020 7973 3473



SITE NAME: Water tower to former

Lambeth Workhouse, Renfrew Road SEII

DESIGNATION: Listed Building Grade II, CA

condition: Poor occupancy: Vacant

priority: C (C)

OWNERTYPE: Unknown

1877 water tower built in Venetian Gothic style. Vacant. Proposal for conversion and extension are being considered.

Contact: Elizabeth Martin (LPA) 020 7926 1213

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA Conservation Area
LB/LBs Listed Building/S
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM/SMs Scheduled Monument/S
UA Unitary Authority
WHS WOrld Heritage Site

.OND	on / Lambe	тн	
	SITE NAME:	St Michael's Convent (Formerly Park Hill)	A rare example of a C19 villa garden in south London. Designed by JB Papworth for William Leaf in the mid C19 and improved by Robert Marnock for Sir Henry
	DESIGNATION:	Registered Park and Garden Grade II, also CA, I0 LBs	Tate in the late C19. The garden is deteriorating in parts. Clearance work was undertaken to the lake and
	CONDITION:	Extensive significant problems	surrounding trees in the winter 2010-2011 and restoration of the terrace wall is planned. The Pulhamite grotto (grade
	VULNERABILITY:	Low	Il listed building) has been repaired and removed from the
	TREND:	Improving	Heritage at Risk Register.
	OWNER TYPE:	Private, multiple owners	Contact: Zosia Mellor 020 7973 3473
	SITE NAME:	ABC Cinema, Streatham High Road, Streatham SW16	Art Deco style cinema built in 1938 to the design of WR Glen. Facade and double height foyer are of notable quality. Repair work completed, awaiting new use.
	DESIGNATION:	Listed Building Grade II, CA	
	CONDITION:	Good	
	OCCUPANCY:	Vacant	
	PRIORITY:	E (E)	
	OWNER TYPE:	Company	Contact: Douglas Black (LPA) 020 7926 4065
	SITE NAME:	Monument to George Abell, St Leonard's churchyard, Streatham High Road, Streatham SW16	Chest tomb of circa 1826 commemorating George and Elizabeth Abell. Slab of Portland limestone – curved-edged top – has broken and the plinth is in a bad condition.
12	DESIGNATION:	Listed Building Grade II	
	CONDITION:	-	
400	OCCUPANCY:	N/A	
	PRIORITY:	A (New entry)	
	OWNER TYPE:	Unknown	Contact: Elizabeth Martin (LPA) 020 7926 1213
	SITE NAME:	Monument to Joseph Hay, St Leonards churchyard, Streatham High Road, Streatham SW16	Chest tomb in railed enclosure, dated I 808 in coadestone by Coade and Sealy. Railings are broken and in poor state of repair.
	DESIGNATION:	Listed Building Grade II, CA	
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
The second	PRIORITY:	A (New entry)	
	OWNER TYPE:	Unknown	Contact: Elizabeth Martin (LPA) 020 7926 1213
	SITE NAME:	Monument to Lt. Col. William Boyce, St Leonards churchyard, Streatham High Road, Streatham SW16	Chest tomb in railed enclosure, circa I 808 by Coade and Sealy. The coadestone is in an advanced state of decay.
	DESIGNATION:	Listed Building Grade II	
	CONDITION:	Poor	
-	OCCUPANCY:	N/A	
The same of		A (NI)	



A (New entry) PRIORITY: OWNER TYPE: Unknown

Contact: Elizabeth Martin (LPA) 020 7926 1213



335-337 Wandsworth Road SW8 SITE NAME:

DESIGNATION: Listed Building Grade II, CA Fair CONDITION: Vacant OCCUPANCY: C (C) PRIORITY: OWNERTYPE: Private

Pair of Regency houses, formerly undertaker's premises. Boarded up at ground floor. Building vulnerable and at risk. Approval for conversion granted but poorly implemented, enforcement case by the Local Authority is pending.

Contact: Elizabeth Martin (LPA) 020 7926 1213

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS



Wall on the southside SITE NAME:

of St John with All Saints' churchyard,

Waterloo Road SEI

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION: N/A OCCUPANCY:

A (New entry) PRIORITY: OWNER TYPE: Religious organisation

Early C19 stock brick walls, spalled and cracked brickwork, finials broken and missing.

Contact: Elizabeth Martin (LPA) 020 7926 1213



SITE NAME: The Clapham Orangery, Worsopp Drive SW4

DESIGNATION: Listed Building Grade II

Fair CONDITION: N/A C(C)PRIORITY:

OWNERTYPE: Local authority

Orangery built in 1793 to the design of William Burgh, in a Palladian style. It stood in the grounds of Thornton House, demolished in the 1940s. Now standing in the middle of a housing estate.

Contact: Elizabeth Martin (LPA) 020 7926 1213

Designed in the Byzantine style by Beresford Pite.

First phase of roof repairs to nave, transepts and dome completed. A second phase of repairs to



SITE NAME:

Christ Church, Christ Church Road, Brixton SW2

chancel and tower roofs will start 2011. DESIGNATION: Listed Place of Worship Grade I, CA

Poor CONDITION:

F (New entry) PRIORITY:

Religious organisation OWNER TYPE:

Contact: Tracey Craig 020 7973 3756



SITE NAME:

Trinity Congregational Church, St Matthews Road, Brixton SW2

Classical Chapel built 1828 of stock brick with stucco entablature with original pews. There are structural problems with the front elevation.

DESIGNATION: Listed Place of Worship Grade II

CONDITION: Poor C(C)PRIORITY:

OWNER TYPE: Religious organisation

Contact: Simon Hickman 020 7973 3762

LEWISHAM



SITE NAME:

Stable block and garden walls to Beckenham Place, Beckenham Hill Road SE26

Late C18 stable block. Part-used and in need of repair. Currently being tendered as golfing/educational facility in association with the use of the park.

DESIGNATION: Listed Building Grade II

Very bad CONDITION: OCCUPANCY: Part occupied PRIORITY: C (C)

OWNER TYPE: Local authority

Contact: Regina Jaszinski (LPA) 020 8314 9112



SITE NAME:

Louise House, Dartmouth Road, Lewisham SE23

DESIGNATION: Listed Building Grade II

CONDITION: Fair Occupied OCCUPANCY: PRIORITY: E (E)

OWNER TYPE: Local authority

Former Girls Industrial Home, built in 1891, and surviving former laundry block to rear. Some essential repairs have been carried out and the building is currently in use as offices.

Contact: Regina Jaszinski (LPA) 020 8314 9112

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



SITE NAME:	Ramp at Deptford Railway Station,
	Deptford High Street SE8

DESIGNATION: Listed Building Grade II, CA CONDITION: Poor

N/A OCCUPANCY: D(D)PRIORITY: OWNER TYPE: Company Built 1856 to the design of engineer Colonel Lordmann. A dog-leg ramp formed by a series of brick arches rising up from Deptford High Street to the level of the tracks. Listed building consent and planning permission granted for redevelopment of enclosed square, repair of ramp and occupation of arches. Anticipated start of work on site is autumn 2011.

Contact: Regina Jaszinski (LPA) 020 8314 9112

House, shop and bakehouse built 1791-2 for Thomas

Palmer, baker. Further modifications made 1801-2 and

wind and weather tight, and internally it has remained

1822-3. C19 shop front in disrepair. Bake house demolished. Some repairs have been carried out to make the building



227 Deptford High Street, SITE NAME: Deptford SE8

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION: Vacant A(A)PRIORITY: Private OWNER TYPE:

Contact: Regina Jaszinski (LPA) 020 8314 9112

gutted and unoccupied.



Beckenham Place, SITE NAME: Foxgrove Road, Beckenham Place Park BR3

Listed Building Grade II*, CA DESIGNATION:

CONDITION:

Part occupied OCCUPANCY: PRIORITY-C(C)

OWNER TYPE: Local authority

Mansion built circa 1773, situated within former park land, now golf course. Some use made by golfers and the local authority, but otherwise limited occupancy. Cracks evident near entrance portico. The Local Authority is actively seeking new owners and uses that could secure the long-term future of the building.

Contact: Malcolm Woods 020 7973 3769



Old Swimming Baths, SITE NAME: Ladywell Road SE13

DESIGNATION: Listed Building Grade II, CA

CONDITION: Poor Vacant D (D) PRIORITY-

Local authority OWNER TYPE:

Public baths, consisting of first and second class swimming pools constructed in 1884. Designed in the Gothic style by Wilson and Son and Thomas Aldwinkle. Unused and deteriorating condition. The Local Authority has commissioned a Conservation Management Plan for the building.

Contact: Regina Jaszinski (LPA) 020 8314 9112



Monuments at St Margaret's SITE NAME: Old Churchyard, Lee Terrace SE3

DESIGNATION: Listed Building Grade II, CA

CONDITION: Very bad N/A OCCUPANCY:

PRIORITY-

C (C) OWNER TYPE: Religious organisation Burial ground surrounding the remains of the old church of St Margaret. With 21 listed C18 and C19 tombs some in need of repair. Halley the astronomer is buried here. Restoration plans currently being prepared to priority listed tombs. Some landscape improvement works carried out in 2010 to the churchyard.

Contact: Regina Jaszinski (LPA) 020 8314 9112



SITE NAME: 25 Tanners Hill, Deptford SE8

DESIGNATION: Listed Building Grade II, CA Poor CONDITION:

Vacant PRIORITY: C(C)OWNERTYPE: Private Late C17 house, until recently used as a cycle shop and workshop. The business closed in 2009 and the building currently stands empty. The building has suffered from long-term lack of maintenance, under-use and water ingress. Planning and listed building consent applications have been submitted for the conversion into part residential and part gallery use.

Contact: Regina Jaszinski (LPA) 020 8314 9112

SITE NAME:

Deptford High Street

DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Improving
CONTACT:	Philip Ashford (LPA) 020 8314 8533	NEW ENTRY?:	No

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.


NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS

MERTON



SITE NAME: Garden wall enclosing four sides of playing field, Church Lane, Merton Park

DESIGNATION: Listed Building Grade II, CA

Fair CONDITION: N/A C(C)PRIORITY-

OWNERTYPE: Local authority

Garden wall C16 to C17 and later. The wall has suffered from ad hoc repairs carried out over time but some sections are still eroded, mainly in areas subjected to inappropriate past repairs. Repairs were carried out in 2002 and 2005 with listed building consent.

Contact: Caroline Kearey (LPA) 020 8545 3055



St Peter and St Paul's Churchyard, SITE NAME: Church Road,

Mitcham

Listed Building Grade II, CA DESIGNATION:

Poor CONDITION: N/A OCCUPANCY: E (D) PRIORITY:

OWNER TYPE: Religious organisation

Repairs to listed memorials have been carried out, funded by the Mitcham Conservation Area Partnership Scheme. Management plan was prepared in 1997 and is currently being implemented by the church. This includes work on the damaged graves and tombs.

Contact: Caroline Kearey (LPA) 020 8545 3055



Motor House, SITE NAME: 2 Highbury Road, Wimbledon

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION: Occupied OCCUPANCY: PRIORITY C (C) Private OWNER TYPE:

Built in 1907, RJ Thomas and AG Pomeroy. Unique purpose-built motor house listed in its own right adjacent to grade II listed dwelling, Good Hope. The glazed washing porch has been partly dismantled and the glass has been removed. Application has been received to alter and convert to an alternative use.

Contact: Caroline Kearey (LPA) 020 8545 3055



Ravensbury Mill (North Wing), SITE NAME: 245 Morden Road,

Morden

DESIGNATION: Listed Building Grade II, CA

CONDITION:

OCCUPANCY: Part occupied

C(C)PRIORITY Charity OWNER TYPE:

C18 and C19 snuff mill powered by water. The North Wing is subject to a Section 106 agreement. Slow progress towards resolving outstanding planning obligations, enabling a lease for the occupation of the North Wing by Wandle Industrial Museum. Discussions ongoing to resolve outstanding issues.

Contact: Caroline Kearey (LPA) 020 8545 3055



Tombs at St Mary's Churchyard, SITE NAME: St Mary's Road,

Wimbledon DESIGNATION: Listed Building Grade II, CA

Poor CONDITION: N/A OCCUPANCY: PRIORITY: C (D)

OWNER TYPE: Religious organisation

The churchyard of St Mary's Church, SW19, has 31 listed tombs. Many are in disrepair and in need of restoration. A condition survey has been carried out identifying priority for repairs. No work has yet been undertaken.



Rutlish School footpath wall SITE NAME:

(part of the curtilage of Manor House), Watery Lane, Merton Park

DESIGNATION: Listed Building Grade II, CA CONDITION: Very bad

N/A PRIORITY: D (New entry) OWNER TYPE: Local authority

OCCUPANCY:

Freestanding brick boundary wall. The wall is part of the curtilage of The Manor House and is considered to be unstable and in danger of collapse. English Heritage has offered a grant towards a Stage I Development grant to ascertain the exact nature of the repairs and the methods to be used in the rebuilding.

Contact: Caroline Kearey (LPA) 020 8545 3055

Contact: Caroline Kearey (LPA) 020 8545 3055

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



SITE NAME:	Base of windmill at Mill House,
	Windmill Road

DESIGNATION: Listed Building Grade II Fair CONDITION:

N/A OCCUPANCY: E (F) Company OWNER TYPE:

Brick with timber framing comprising base of hollow-post windmill. Located within the car park of Windmill Public House with its timber superstructure exposed to the elements. The new owners have undertaken preservation work on the timbers which have now been reinstated. The structure remains at risk without a protective cover.

Contact: Caroline Kearey (LPA) 020 8545 3055



SITE NAME: Wall to rear of flats,

27-33 (consec) Windsor Avenue,

Colliers Wood

DESIGNATION: Listed Building Grade II, CA

Very bad CONDITION: N/A OCCUPANCY: A(A)PRIORITY: OWNERTYPE: Private

Fragment of medieval and probably later precinct wall of former Merton Priory. Constructed from flint and rubble stone, it is being damaged by vegetation growing out of the wall structure.

Contact: Caroline Kearey (LPA) 020 8545 3055

学文是
一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个
经验
一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个

SITE NAME

OWNER TYPE:

Merton Priory (site of), Merton

Scheduled Monument (No. 1001976) Generally unsatisfactory DESIGNATION: CONDITION:

with major localised problems

PRINCIPAL VULNERABILITY: Development requiring planning permission TREND:

Private

Declining Jane Sidell 020 7973 3738 CONTACT

SITE NAME:	Morden Park Mound, Merton

Scheduled Monument (No. 1002011) DESIGNATION:

Generally unsatisfactory CONDITION: with major localised problems

CONTACT

Extensive vehicle damage/erosion Declining PRINCIPAL VULNERABILITY: TREND:

Local Authority OWNER TYPE:

Jane Sidell 020 7973 3738

SITE NAME:	Bathgate Road
------------	---------------

Conservation Area Very bad DESIGNATION: CONDITION: Medium VULNERABILITY: TREND Deteriorating

Caroline Kearey (LPA) 020 8545 3055 CONTACT: NEW ENTRY?:

NEWHAM



SITE NAME: Abbey Mills Pumping Station (Station A),

Abbey Lane E15

DESIGNATION: Listed Building Grade II*

CONDITION:

Part occupied OCCUPANCY:

E (C) PRIORITY:

OWNERTYPE: Former utility

Pumping Station built 1865-8 by Sir Joseph Bazalgette. South east wing and cupola restored 1999. Still operational, but long-term future uncertain. An options appraisal has been completed along with a Conservation Plan (part funded by English Heritage). Subsequent Heritage Lottery Fund Townscape Heritage Initiative bid failed. Listed building consent granted for external repair and restoration. Work underway.

Contact: Andrew Hargreaves 020 7973 3718



SITE NAME: Abbey Mills Pumping Station (Station C) with Associated

Valve House, Abbey Lane E15 DESIGNATION: Listed Building Grade II

Poor CONDITION: OCCUPANCY: Vacant

PRIORITY

C(C)OWNER TYPE: Former utility Pumping station 1910-14, white stock brick with terracotta and moulded stone dressings. Internal pumping floor sunk deep below ground level. Heritage Lottery Fund Townscape Heritage Initiative bid, involving conversion to Building Craft Centre failed. No current long-term proposals for reuse of the building at this stage.

Contact: Ben Hull (LPA) 020 3373 9574

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



SITE NAME: Bases of pair of chimneystacks at Abbey Mills Pumping Station, Abbey Lane E15

DESIGNATION: Listed Building Grade II

condition: Poor occupancy: N/A priority: C (C)

OWNER TYPE: Former utility

Two chimney bases built 1865 by Bazalgette. Elaborate pedimented porches to battered brick plinths crowned by stone bases of octagonal stacks (demolished). Options appraisal completed along with a Conservation Plan (part funded by EH). Townscape Heritage Initiative bid failed. Thames Water considering options with regard to works to structure.

Contact: Ben Hull (LPA) 020 3373 9574



SITE NAME: Gate lodge at Abbey Mills
Pumping Station,
Abbey Lane E15

DESIGNATION: Listed Building Grade II

CONDITION: Fair
OCCUPANCY: Vacant
PRIORITY: C (C)
OWNER TYPE: Former utility

Lodge to pumping station, built circa 1865. No long-term proposals. Options appraisal completed along with a Conservation Plan (part funded by EH). Townscape Heritage Initiative bid failed. No long-term proposals for reuse at this stage.

Contact: Ben Hull (LPA) 020 3373 9574



Offices (former Superintendent's House) at Abbey Mills Pumping Station, Abbey Lane E15

DESIGNATION: Listed Building Grade II

condition: Fair

OCCUPANCY: Part occupied PRIORITY: E (C)

OWNERTYPE: Former utility

Former Superintendent's House to pumping station, built 1865 by Bazalgette. Two storeys in yellow brick with stone dressings. Part used as offices. An options appraisal has been completed along with a Conservation Plan (part funded by EH). Subsequent HLF Townscape Heritage Initiative bid failed. Listed building consent granted for external repair and restoration. Work underway. No long-term proposals for reuse.

Contact: Ben Hull (LPA) 020 3373 9574



Stores Building
at Abbey Mills Pumping Station,
Abbey Lane E15

DESIGNATION: Listed Building Grade II

CONDITION: Very bad

OCCUPANCY: Vacant

PRIORITY: A (A)

OWNER TYPE: Former utility

Storage building circa 1865 by Sir Joseph Bazalgette. Vacant. Significant structural movement. Damage due to water ingress. Options appraisal completed with Conservation Plan (part funded by English Heritage) Heritage Lottery Fund Townscape Heritage Initiative bid failed. Thames Water considering options for repair.

Contact: Ben Hull (LPA) 020 3373 9574



SITE NAME: Ancillary Pump House at Abbey Mills Pumping Station, Abbey Road E15

DESIGNATION: Listed Building Grade II

condition: Fair occupancy: Vacant Priority: C (C)

OWNER TYPE: Former utility

Pump house circa I 868, probably by Bazalgette and Cooper, built in similar style to main pumping station. Options appraisal completed along with a Conservation Plan (part funded by EH). Townscape Heritage Initiative bid failed. No long-term proposals for reuse at this stage.

Contact: Ben Hull (LPA) 020 3373 9574



SITE NAME: West Ham Pumping Station Engine House,

Engine House, Abbey Road E15

DESIGNATION: Listed Building Grade II

condition: Fair

occupancy: Part occupied

PRIORITY: E (E)

OWNERTYPE: Former utility

Engine house, 1897. Contains original Lilleshall Company beam engines. In use as training facility. Unauthorised works to interior.

Contact: Ben Hull (LPA) 020 3373 9574

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA Cons LB/LBs Liste LPA Loca NP Natic RPG Regis SM/SMs Sche UA Units WHS Wor



Dukes Head Public House, SITE NAME: 593 Barking Road,

East Ham E6

DESIGNATION: Listed Building Grade II

Poor CONDITION: Vacant OCCUPANCY: B (A) PRIORITY: Private OWNER TYPE:

Public house, 1900. A recent fire to the first floor has meant that a large proportion of the internal structure has been damaged. Some damage to the roof has temporary repairs. Some restoration work underway.

Contact: Ben Hull (LPA) 020 3373 9574



Gallions Hotel. SITE NAME: Gallions Road. Royal Albert Dock E16

DESIGNATION: Listed Building Grade II*

Good CONDITION: Vacant E (F) PRIORITY: OWNER TYPE: Company

Hotel built 1881-3 to the design of Vigers and Wagstaffe. Conversion and restoration works appear to be complete, but building still vacant.

Contact: Andrew Hargreaves 020 7973 3718

Three storey C18 public house, yellow brick with

Application expected for reuse and restoration.

red brick arches and reveals. Extensive damage to 1930s interior. Urgent repairs have been carried out following

threat of S54 notice. Recent pre-application discussions.



Coach and Horses Public House, SITE NAME: 100 High Street,

Plaistow E13

Listed Building Grade II DESIGNATION:

Poor CONDITION: Vacant OCCUPANCY: PRIORITY: A(A)OWNER TYPE: Company

Contact: Ben Hull (LPA) 020 3373 9574



The Log Cabin SITE NAME:

(formerly known as The Yorkshire Grey), 335-337 High Street, Stratford E15

DESIGNATION: Listed Building Grade II

Very bad CONDITION: Vacant F (B) PRIORITY-Private

OWNER TYPE:

Three storey, C18 coaching inn. Permission granted for conversion to hotel. Damaged by fire in March 2009. Listed building consent subsequently granted for restoration works. Details pursuant to listed building consent conditions submitted. Works have commenced and are progressing well.

Contact: Ben Hull (LPA) 020 3373 9574



Chimney to Beckton Sewage Works, SITE NAME: Jenkins Lane,

Beckton IGII

DESIGNATION: Listed Building Grade II

CONDITION: Poor N/A OCCUPANCY: D (D) PRIORITY-

OWNER TYPE: Company

Chimney 1887/89, designed by Joseph Bazalgette, as part of the improvements to the northern outfall of the London drainage network. Listed building consent granted for works to facilitate Lee Tunnel and Beckton extension works. Chimney dismantled and in storage, pending re-erection following completion of tunnelling works.

Contact: Ben Hull (LPA) 020 3373 9574



SITE NAME: Earl of Derby, London Road, West Ham E13

DESIGNATION: Listed Building Grade II

Poor CONDITION: Vacant PRIORITY: C (New entry)

OWNERTYPE: Private

Public House, circa 1880, two storey with stucco dressings and slate roof. The building is currently unoccupied. Damage to ground floor windows and doors. Pre-application discussions held and application expected for residential use and repair.

Contact: Ben Hull (LPA) 020 3373 9574

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



SITE NAME:	Silo D, North Woolwich Road,
	Comming Tourn Eld

Canning Town E16

DESIGNATION: Listed Building Grade II

Fair CONDITION: N/A OCCUPANCY: C (C) PRIORITY: OWNER TYPE: Unknown

Grain silo, 1920. Reinforced concrete. Building appears neglected. Vegetation growing from various areas of the structure. Broken windows in many places.

Contact: Ben Hull (LPA) 020 3373 9574



SITE NAME: North Woolwich Station including turntable and platform lamp standards, Pier Road, North Woolwich E16

DESIGNATION: Listed Building Grade II

Poor CONDITION: Vacant OCCUPANCY: C (C) PRIORITY: Company OWNER TYPE:

Former railway station, 1847. Broken windows on first floor front elevation. Vegetation growing from the stonework and brickwork. Platform overgrown. Site unsecured.

Contact: Ben Hull (LPA) 020 3373 9574



Central buffet at Custom House, SITE NAME: Royal Albert Dock E16

DESIGNATION: Listed Building Grade II CONDITION: Good Vacant OCCUPANCY: E (E) PRIORITY: OWNERTYPE: Quango

Restaurant, built 1883 to the design of Vigers and Wagstaff in a free classical style. Repaired and 'mothballed' by the London Docklands Development Corporation. Ownership now with London Development Agency and part of the Royals Business Park. Security has been improved. Some emergency repairs have been undertaken. No current plans for the building.

Contact: Ben Hull (LPA) 020 3373 9574



SITE NAME: Central offices at Custom House, Royal Albert Dock E16

DESIGNATION: Listed Building Grade II CONDITION: Good Vacant E (E) PRIORITY-Quango OWNER TYPE:

Offices, built 1883 to the design of Vigers and Wagstaffe in the manner of Norman Shaw. Repaired and 'mothballed' by the London Docklands Development Corporation. Now owned by London Development Agency and part of Royals Business Park. Security has been improved. Some emergency repairs have been undertaken. No current plans for the building.

Contact: Ben Hull (LPA) 020 3373 9574



Tide Mill (known as the House Mill), SITE NAME: Three Mill Lane E3

DESIGNATION: Listed Building Grade I, CA CONDITION: Part occupied OCCUPANCY: E (E) PRIORITY-Trust OWNER TYPE:

Tide Mill 1776, last used in 1941. Four undershot water wheels in very poor condition. Much machinery remains, though dismantled. The owners, the Waterways Trust, and other partners including British Waterways, English Heritage and London Thames Gateway Development Corporation commissioned an options appraisal. An HLF development grant has been secured and fully developed proposals to be submitted.

Contact: Andrew Hargreaves 020 7973 3718



SITE NAME: Spotted Dog Public House, 212 Upton Lane E7

DESIGNATION: Listed Building Grade II Very bad CONDITION: Vacant OCCUPANCY: PRIORITY: A (A) OWNERTYPE: Private

Weatherboarded C16 timber-framed public house with pantiled roof, and currently boarded up. Local authority have carried out works to secure the property and make it watertight following non compliance with Urgent Works Notice part funded by English Heritage. Repairs Notice served and urgent repairs carried out. Asbestos has been removed from the interior. Pre application scheme expected.

Contact: Ben Hull (LPA) 020 3373 9574

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented

NOTE:

If the priority category has changed since the 2010 register, the previous category given in brackets

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



West Ham Court House, SITE NAME: West Ham Lane E15

DESIGNATION: Listed Building Grade II, CA

CONDITION: Poor Vacant OCCUPANCY: PRIORITY: C (C)

OWNERTYPE: Local authority

Court house built 1884 to the design of Lewis Angell. Urgent works carried out to prevent water ingress. Newham Council have prepared a conservation plan

and are considering options.

Contact: Ben Hull (LPA) 020 3373 9574

DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	High	TREND:	Improving significantly
CONTACT:	Ben Hull (LPA) 020 3373 9574	NEW ENTRY?:	No

Three Mills SITE NAME:

DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Improving significantly
CONTACT:	Ben Hull (LPA) 020 3373 9574	NEW ENTRY?:	No

REDBRIDGE



SITE NAME: Dr Johnson Public House,

Longwood Gardens, llford

DESIGNATION: Listed Building Grade II

Poor CONDITION: Vacant OCCUPANCY:

C (New entry)

OWNERTYPE: Unknown

Moderne-style public house constructed 1937-8 by H Reginald Ross with linked shop for off-sales. Built to serve the large new estates in Barkingside. The building has been vacant and boarded up since 2010, and is on the market. The roof is damaged allowing possible water ingress.

Contact: Simon Algar (LPA) 020 8708 2747



Barn at Aldborough House Farm,

Oaks Lane, llford

DESIGNATION: Listed Building Grade II

CONDITION: Fair Vacant OCCUPANCY: F (F) PRIORITY: OWNERTYPE: Private Barn circa 1730. Formerly the chapel attached to Aldborough Hall. Consent granted for residential conversion and extension. Scheme not fully implemented.

Contact: Simon Algar (LPA) 020 8708 2747



Garden Temple in garden SITE NAME:

of Temple House, 14 The Avenue, Wanstead

DESIGNATION: Listed Building Grade II*, CA

Poor CONDITION: N/A OCCUPANCY: D (D)

OWNERTYPE: Private

Garden temple, 1730-40, with Ionic pedimented portico. Roof repairs completed with English Heritage grant aid. English Heritage funded development grant for repairs to the portico.

Contact: Simon Wartnaby 020 7973 3715

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS CA LB/LBs LPA NP

UA WHS



III- NAME:	ITE NAME:	Wanstead	Park
------------	-----------	----------	------

DESIGNATION: Registered Park and Garden Grade II*,

also part in CA, 6 LBS

Generally satisfactory but with CONDITION:

significant localised problems

VULNERABILITY: High

Declining


OWNERTYPE: Mixed, multiple owners

Remains of an important landscape dating from the late C17 to early C19, developed late C19 by the City of London as a public park. Central area converted to a private golf course in the early C20. Some historic features are undergoing restoration but others are in poor condition. The City of London commissioned a Statement of Significance towards which English Heritage gave grant aid. In May 2011, the City of London deferred making a decision ón submission óf a Heritage Lottery Fund bid.

Contact: Zosia Mellor 020 7973 3473

SITE NAME:	Wanstead Park, Wanstead		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Simon Algar (LPA) 020 8708 2747	NEW ENTRY?:	No
SITE NAME:	Woodford Bridge		
SITE NAME: DESIGNATION:	Woodford Bridge Conservation Area	CONDITION:	Poor
	•	CONDITION: TREND:	Poor Deteriorating

RICHMOND UPON THAMES



SITE NAME: Summer House, Radnor Gardens, Cross Deep

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION:

N/A OCCUPANCY: D (New entry) PRIORITY:

OWNER TYPE: Local authority

Mid C18 summer house, built in Gothick style and situated in Radnor Gardens, a public park owned and operated by the Local Authority. The timber structure is located not far from the river and is vulnerable to the elements. Its decorative elements are in poor condition. English Heritage has provided a grant in conjunction with the Local Authority to ascertain the exact nature of repairs required.

Contact: Nicolette Duckham (LPA) 020 8891 7335



Loggia and grotto in grounds SITE NAME: of Thames Eyot, Cross Deep, Twickenham

DESIGNATION: Listed Building Grade II, CA

Very bad N/A OCCUPANCY: PRIORITY: A(A)

OWNER TYPE: Company

Probably C18. Stone loggia of nine Doric columns and shellwork grotto. Situated in grounds of 1930s flats on the bank of the Thames. Roof has suffered partial collapse and structural movement causing distortion to colonnade. An options appraisal to find a solution to saving the Loggia is due for completion in early 2011. Ongoing monitoring.

Contact: Nicolette Duckham (LPA) 020 8891 7335

Grotto with rusticated arched entrance facing the river. Long passage with two 'chapels', one on either side of

garden history. Basic structural condition appears sound,

A new project coordinator has been appointed to take repair works forward and a charitable trust is in the

entrance. Seen as the 'locus classicus' of English C18

but much of the decorative lining is loose or missing.



SITE NAME: Pope's Grotto in grounds of St James Independent School for Boys, Cross Deep (east side), Twickenham

Listed Building Grade II*, CA, RPG II DESIGNATION: Fair CONDITION:

OCCUPANCY: N/A C(C)Private OWNER TYPE:

process of being formed. Contact: Stephen Senior 020 7973 3783



SITE NAME: Stanford Grotto in grounds of St James' Independent School for Boys, Cross Deep (east side), Twickenham TWI

Listed Building Grade II*, CA, RPG II DESIGNATION:

CONDITION: N/A OCCUPANCY: D (D) PRIORITY

OWNERTYPE: Private

Grotto built by Sir William Stanhope circa 1761, to connect to what had been Pope's Gardens to another property he owned. The end leading from Pope's Gardens was known as "Stanhope Caves" Grotto entrance now overgrown and partially obscured by other decaying vegetation. Project to clear vegetation and expose structure due to commence summer 2011.

Contact: Stephen Senior 020 7973 3783

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable)
 end use or user identified;
 functionally redundant buildings
 with new use agreed but not yet implemented

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



SITE NAME: Garrick's Villa,

Hampton Court Road, Hampton

DESIGNATION: Listed Building Grade I, CA

condition: Very bad occupancy: Vacant

PRIORITY: B (B)

OWNER TYPE: Private

Villa by Robert Adam built in 1756 and remodelled in 1773. Three storeys, seven window-wide frontage in yellow brick with fluted stucco frieze, cornice and low parapet. Converted into nine apartments in the 1960s and severely damaged by fire in 2008. Listed building consent approved for reinstatement and works to commence in January 2011.

Contact: Sheila Stones 020 7973 3785



SITE NAME: Normansfield Hospital, Kingston Road, Teddington

DESIGNATION: Listed Building Grade II*

CONDITION: Very bad OCCUPANCY: Vacant PRIORITY: B (A)
OWNER TYPE: Company

Former private sanatorium established by Dr Langdon-Down. Central portion 1866 incorporating original house. Original fine interiors vandalised or removed and theft of roof tiles and lead have led to serious water penetration and severe deterioration. Listed building consent has been granted to refurbish and convert the main building into flats. Urgent works of repair are taking place.

Contact: Sheila Stones 020 7973 3785



SITE NAME: Boat house No. 5 (easternmost I 3 bays), Platts Eyot, Hampton

DESIGNATION: Listed Building Grade II, CA

CONDITION: Very bad
OCCUPANCY: Part occupied
PRIORITY: A (A)

OWNER TYPE: Company

Timber-framed boathouse built 1917 by Augustine Alban Hamilton Scott for the Thorneycroft firm to build torpedo boats for the Admiralty. A full measured survey of the remaining structure has been completed. Ongoing monitoring.

Contact: Nicolette Duckham (LPA) 020 889 I 7335



SITE NAME: The Gallery at Doughty House, 142 Richmond Hill, Richmond upon Thames

DESIGNATION: Listed Building Grade II, CA

condition: Poor

occupancy: Part occupied

PRIORITY: D (D)

OWNER TYPE: Private

Gallery built in 1880 for Sir Francis Cook, extended in 1915 by Brewer Smith. Eleven bays. Giant lonic order with balustrade, the lower order containing door and window openings between Doric pilasters. Works required to roof, balustrade and especially rainwater goods. Application for renewal of consent for conversion of gallery to offices approved. A feasibility study to consider other uses has been completed.

Contact: Nicolette Duckham (LPA) 020 8891 7335

OCCUPAN
PRIORITY:
OWNERT

Platt's Eyot


DESIGNATION: Conservation Area condition: Poor

VULNERABILITY: Medium TREND: Deteriorating significantly

CONTACT: Nicolette Duckham (LPA) 020 8891 7335 NEW ENTRY: No

SOUTHWARK

SITE NAME:



SITE NAME: Licensed Victuallers Almshouses: Chapel,

Asylum Road SEI5

DESIGNATION: Listed Building Grade II, CA

CONDITION: Poor OCCUPANCY: Vacant PRIORITY: C (C)

OWNERTYPE: Local authority

Former almshouse chapel, I 827-31. In stable condition, but in need of extensive repairs. Marketed by London Borough of Southwark and discussions and consultation on its use as an artist's studio currently being undertaken with residents.

Contact: David Lane (LPA) 0207 525 5449



SITE NAME: Monuments at St Mary Magdalene Churchyard, Bermondsey Street,

Bermondsey SEI

DESIGNATION: Listed Building Grade II, CA

condition: Poor occupancy: N/A priority: D (D)

OWNERTYPE: Local authority

Churchyard at the junction of Abbey Street and Bermondsey Street containing a number of listed tombs, a stele and drinking fountain dating from C18 and C19. The condition of these structures varies considerably. A master plan has been prepared for the churchyard which includes the repairs to the listed tombs (scheduled to be carried out 2011).

Contact: David Lane (LPA) 0207 525 5449

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



SITE NAME: Presbyterian Chapel, 109 Borough Road SEI

DESIGNATION: Listed Building Grade II

condition: Poor occupancy: Vacant Priority: B (B)

OWNER TYPE: Educational Body

Redundant Presbyterian chapel, 1846. Consent approved for facade retention (2006) and conditions discharged but work has stopped on site. South Bank University is reviewing options since the Primary Care Trust withdrew.

Contact: David Lane (LPA) 0207 525 5449



SITE NAME: 113-119 Borough Road SEI

DESIGNATION: Listed Building Grade II, CA

CONDITION: Poor
OCCUPANCY: Vacant
PRIORITY: C (C)

OWNERTYPE: Educational Body

Terrace of three storey late Georgian brick houses with shops on the ground floor. Formed part of a larger site assembled by South Bank University. Stabilisation programme completed. Buildings weathertight and drying. South Bank University reviewing options.

Contact: David Lane (LPA) 0207 525 5449




SITE NAME: Lodge, Camberwell New Cemetery, Brenchley Gardens, Honor Oak SE23

DESIGNATION: Listed Building Grade II

CONDITION: Fair

PRIORITY: C (New entry)
OWNER TYPE: Local authority

Former cemetery lodge (1928-29) designed by Sir Aston Webb. Building is vacant and condition is deteriorating.





SITE NAME: Gate piers and railings to the churchyard

of the former Church of St John, Fair Street, London SEI

DESIGNATION: Listed Building Grade II, CA

CONDITION: Poor
OCCUPANCY: N/A
PRIORITY: C (C)

OWNERTYPE: Local authority

Early to mid C19 railings, gates and gate piers. Wrought iron railings and Portland stone piers and plinth. They are a good example of late Georgian ironwork but have started to corrode.

Contact: David Lane (LPA) 0207 525 5449



SITE NAME: 38 Glengall Road, Peckham SE17

DESIGNATION: Listed Building Grade II, CA

condition: Poor

occupancy: Part occupied

PRIORITY: C (C)

OWNERTYPE: Private

Semi-detached house dating from 1843-1845 by the Brighton architect Amon Henry Wilds. Ionic entrance porch is in poor condition. Discussions have been held on the repair of the building.

Contact: David Lane (LPA) 0207 525 5449



SITE NAME: 133 Kennington Park Road, Walworth SEII

A late C18 terrace house. Conditional planning and listed building consents for conversion to four flats granted May 2008, but not implemented.

DESIGNATION: Listed Building Grade II, CA

CONDITION: Fair
OCCUPANCY: Vacant
PRIORITY: D (C)
OWNER TYPE: Private

Contact: David Lane (LPA) 0207 525 5449

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified, or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA Conservation Area
LB/LBs Listed Building/s
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM/SMs Scheduled Monument/s
UA Unitary Authority
WHS World Heritage Site



SITE NAME: 139 Kennington Park Road

Part of late C18 terrace. The building has been vacant for sometime and unauthorised works undertaken. Condition of building is deteriorating.

DESIGNATION: Listed Building Grade II, CA

CONDITION: Poor

PRIORITY: C (New entry)

OWNERTYPE: Company

Contact: David Lane (LPA) 0207 525 5449



SITE NAME: 143 Kennington Park Road, Kennington SE17

DESIGNATION: Listed Building Grade II, CA

condition: Poor occupancy: Vacant

PRIORITY: C (New entry)
OWNER TYPE: Company

sometime and was sold to a new owner in February 2011. Condition of building is deteriorating.

Part of late C18 terrace. The building has been vacant for

Contact: David Lane (LPA) 0207 525 5449



SITE NAME: East Lodge to Nunhead Cemetery, Linden Grove SE15

DESIGNATION: Listed Building Grade II, CA, RPG II

condition: Very bad

OCCUPANCY: Vacant
PRIORITY: A (A)

OWNERTYPE: Local authority

One of a pair of gate lodges, I 840, by James Bunstone Bunning, adjacent to the main entrance gates. In ruinous condition, but stabilised. English Heritage has awarded a development grant. Friends of Nunhead Cemetery exploring matched funding and Building Preservation Trusts to repair building.

Contact: David Lane (LPA) 0207 525 5449



SITE NAME: Nunhead Cemetery (All Saints)

DESIGNATION: Registered Park and Garden Grade II*,

also CA, I3 LBs

condition: Generally unsatisfactory

with major localised problems

VULNERABILITY: High
TREND: Declining

OWNER TYPE: Local Authority, single owner

An important public cemetery designed by J Bunstone Bunning and consecrated in 1840. The layout of the cemetery skilfully exploits the undulating topography to create picturesque effects and vistas. Despite Heritage Lottery Fund funded repair of some elements in 1998, many tombs remain in poor condition and East Lodge is a building at risk.

Contact: Zosia Mellor 020 7973 3473



SITE NAME: 123-131 London Road SEI

DESIGNATION: Listed Building Grade II, CA

CONDITION: Poor

occupancy: Part occupied

priority: C(E)

OWNER TYPE: Educational Body

Terrace of three and four storey late Georgian houses with shops on the ground floors. Formed part of a larger site assembled by South Bank University. Stabilisation programme completed. Buildings weathertight and drying. South Bank University reviewing options.

Contact: David Lane (LPA) 0207 525 5449



SITE NAME: The Duke of Clarence Public House, 132 London Road SEI

DESIGNATION: Listed Building Grade II, CA

condition: Poor

occupancy: Vacant

PRIORITY: C (E)

OWNERTYPE: Educational Body

Part of the formal composition of St George's Circus on the approach to Blackfriars Bridge. Four storey late Georgian brick and stucco composition with later C19 pub front. Formed part of a larger site assembled by South Bank University. Stabilisation programme completed. Buildings weathertight and drying. South Bank University reviewing options.

Contact: David Lane (LPA) 0207 525 5449

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA C LB/LBs Li LPA Lc NP N RPG R SM/SMs So UA U WHS W



SITE NAME: 549 Lordship Lane SE22

DESIGNATION: Listed Building Grade II CONDITION: Very bad

Vacant

PRIORITY: D (A)
OWNER TYPE: Trust

OCCUPANCY:

House built in 1873 by Charles Drake of the Patent Concrete Building Company. Serious structural problems. Compulsory Purchase Order confirmed. Building preservation trust has consent for conversion to five flats and work to start 2011.

Contact: David Lane (LPA) 0207 525 5449



St Peter's Church Hall, 522 Lordship Lane,

East Dulwich SE22

DESIGNATION: Listed Building Grade II, CA

condition: Poor occupancy: Vacant priority: A (A)

OWNER TYPE: Religious organisation

Situated adjacent to St Peter's Church, the hall was constructed in 1899. Both buildings are believed to be by Charles Barry Junior. The building is currently vacant and is suffering from structural movement and lack of maintenance. The Dulwich Society are planning a proposal for repair of the hall.

Contact: David Lane (LPA) 0207 525 5449



SITE NAME: Driscoll House, 172 New Kent Road, Walworth SEI

DESIGNATION: Listed Building Grade II

condition: Poor occupancy: Vacant

PRIORITY: C (New entry)
OWNER TYPE: Company

Former Ada Lewis women's hostel, built in 1913 as first women's hostel, and renamed Driscoll House when the hostel was run by Terrance Driscoll from late 1960s. The building is currently vacant and the condition is deteriorating.

Contact: David Lane (LPA) 0207 525 5449



Fire station (former), 306-312 (even) Old Kent Road SEI

DESIGNATION: Listed Building Grade II

condition: Poor

occupancy: Part occupied

priority: C (C)
owner type: Company

Fire station built between 1903-4 by the London County Council Architects Department. Red brick with Portland stone dressings. Roof has recently been repaired. No suitable scheme has been submitted. Unauthorised removal of original fire station doors and installation of shop fronts.

Contact: David Lane (LPA) 0207 525 5449



The Kentish Drovers Public House, 720 Old Kent Road, Peckham SEI5

DESIGNATION: Listed Building Grade II

CONDITION: Poor
OCCUPANCY: Occupied
PRIORITY: C (C)
OWNER TYPE: Company

Mid C19 public house. The mural over painting has been removed. Enforcement pending on unauthorised alterations to fabric and UPVC windows and investigation of further breaches.

Contact: David Lane (LPA) 0207 525 5449



SITE NAME: 38 Peckham Hill Street SE15

One of a terrace of four houses. Built circa 1840. Building damaged by fire in 2009. Sold to new owner in February 2011. Currently vacant.

DESIGNATION: Listed Building Grade II

CONDITION: Poor
OCCUPANCY: Vacant
PRIORITY: C (New entry)

OWNERTYPE: Private

Contact: David Lane (LPA) 0207 525 5449

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA Co LB/LBs List LPA Loo NP Na RPG Reg SM/SMs Sch UA Un WHS Wo



SITE NAME: 112 Peckham Park Road,
Peckham SEL5

DESIGNATION: Listed Building Grade II

CONDITION: Poor
OCCUPANCY: Occupied
PRIORITY: C (C)

OWNER TYPE:

One of a group of four pairs of early C19 houses. No proposals for reuse. Repairs have been carried out using unsuitable materials. Grant application made under the East Peckham Renewal Scheme and currently investigating adaptations to make the building disability accessible with London Borough of Southwark housing.

Contact: David Lane (LPA) 0207 525 5449



SITE NAME: 40 Queens Road, Peckham SE15

Private

s Road, Early C19 terraced building. Extensive unauthorised works. In a poor condition.

DESIGNATION: Listed Building Grade II

CONDITION: Poor
OCCUPANCY: Vacant

PRIORITY: C (New entry)

OWNERTYPE: Private

Contact: David Lane (LPA) 0207 525 5449



SITE NAME: Former Clare College Mission Church, Southwark Park SE16

DESIGNATION: Listed Building Grade II

CONDITION: Poor
OCCUPANCY: Occupied
PRIORITY: D (F)

OWNERTYPE: Local authority

Redundant church. The Bermondsey Artists Group were awarded a Big Lottery grant under the Community Assets Programme (2008) to refurbish the building as an art gallery space. English Heritage and Southwark Council have funded roof repairs completed in 2010. Further repairs are required to the walls.

Contact: David Lane (LPA) 0207 525 5449



SITE NAME: Southwark Park School, Southwark Park Road,

DESIGNATION: Listed Building Grade II

Southwark SE16

condition: Poor occupancy: Vacant

PRIORITY: C (New entry)
OWNER TYPE: Local authority

London Board School, by ER Robson, of 1873 with extensions of 1899. Major redevelopment scheme began 2010 but abandoned. Retained fabric is protected from the weather:

Contact: David Lane (LPA) 0207 525 5449



St Giles Hospital, St Giles Road, London SE5

DESIGNATION: Listed Building Grade II


CONDITION: Fair
OCCUPANCY: Vacant

priority: D (D)

OWNER TYPE: Health Authority

Hospital administration block with attached ward block, 1904 by ET Hall. Brick in Flemish bond with stone dressings. Hipped roofs of slate. Building vacant since the Trust moved in 2008. Windows currently blocked up. Proposals to convert the building to 12 flats have been agreed subject to a legal agreement (March 2010).

Contact: David Lane (LPA) 0207 525 5449



Beltwood House, 41 Sydenham Hill, Camberwell SE26

DESIGNATION: Listed Building Grade II, CA

CONDITION: Fair

OCCUPANCY: Vacant

PRIORITY: C (New entry)

OWNERTYPE: Private

Large mid-Victorian villa, possibly by Banks and Barry, Dulwich College architects. House remodelled in the neo-classical style in circa 1895. Building contains fine interiors, but currently vacant and suffering effects of water ingress. The curtilage buildings (stables, lodge, two cottages and animal store) are in a poor state of repair.

Contact: David Lane (LPA) 0207 525 5449

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA CC LB/LBs Lis LPA Lc NP Ni RPG Re SM/SMs Sc UA Ur WHS W



Drinking Fountain, SITE NAME: Tanner Street Park, Bermondsey SEI

DESIGNATION: Listed Building Grade II, CA

CONDITION: Poor N/A OCCUPANCY: C(C)PRIORITY:

OWNER TYPE: Local authority

Originally a turret and the capping to the tower of the former Church of St Olave, Tooley Street. 1738-9, re-sited 1929. Now a drinking fountain. In poor condition. Consultant commissioned for schedule of repairs.

Funding has been identified.

Contact: David Lane (LPA) 0207 525 5449



Henry Wood Hall, SITE NAME: Trinity Church Square SEI

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION: Occupied C (C) PRIORITY: Trust OWNER TYPE:

Former Church of the Holy Trinity built 1823-4 to the design of Francis Bedford. Gutted by fire and rebuilt inside as orchestral hall 1973-5 by Arup Associates. The Hall is in regular use but the clock tower requires extensive repair.

Contact: David Lane (LPA) 0207 525 5449



62 and 64 Union Street SEI SITE NAME:

DESIGNATION: Listed Building Grade II, CA CONDITION: Fair Vacant OCCUPANCY:

E (A) PRIORITY: OWNERTYPE: Company Pair of terraced houses built circa 1835. Network Rail has carried out works to make the property weatherproof and structurally secure. Phase II to start autumn 2011 and bring houses into beneficial use.

Contact: David Lane (LPA) 0207 525 5449



SITE NAME: Kennedys Sausages shop, 305 Walworth Road,


Walworth SE17

DESIGNATION: Listed Building Grade II

CONDITION: Poor occupancy: Vacant C (New entry) PRIORITY-

Company OWNER TYPE:

Former Kennedy sausages shop, circa 1923. A well-preserved example of a 1920s shop. Vacant and in a deteriorating condition.





Church of St Augustine, SITE NAME: Honor Oak Park, Camberwell SE23

DESIGNATION: Listed Place of Worship Grade II

CONDITION:

D (New entry) PRIORITY:

OWNER TYPE: Religious organisation

Constructed between 1872-73 by William Oakley in Kentish ragstone with ashlar détails and slate roof. Rainwater goods have experienced extensive rusting, numerous stone dressings have weathered and structural cracks are visible above the northern transept. In use for Sunday worship with regular church meetings. English Heritage grant offer for programme of high level repairs has been made.

Contact: Donald Wahlberg 020 7973 3786

		Qu n			1
*	#	*		1	100
				Vin	
	65-18		4	100	3

SITE NAME:

Roman boat at New Guy's House, Bermondsey

Scheduled Monument (No. 1001979) Generally satisfactory DESIGNATION: CONDITION: but with significant localised problems PRINCIPAL VULNERABILITY: Drainage/dewatering Declining TREND:

Other Jane Sidell 020 7973 3738 OWNER TYPE: CONTACT

SITE NAME: The Rose Theatre, Rose Court

DESIGNATION:	Scheduled Monument (No. 1012707)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Unknown
OWNER TYPE:	Other	CONTACT:	Jane Sidell 020 7973 3738

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	St George's Circus		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Improving
CONTACT:	Michael Tsoukaris (LPA) 020 8299 6078	NEW ENTRY?:	No

SUTTON



Orangery wall to Beddington Place, SITE NAME: Church Road,

Beddington

Orangery wall of circa 1720. Subject to severe vandalism. The Local Authority have completed a restoration strategy document.

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION: N/A OCCUPANCY: PRIORITY: A(A)

OWNER TYPE: Local authority

Contact: Sally Blomfield (LPA) 020 8770 6253



The Hermitage, SITE NAME: Pound. Carshalton

DESIGNATION: Listed Building Grade II*, CA, RPG II Poor CONDITION:

N/A C(C)PRIORITY:

Trust OWNER TYPE:

Early C18 single storey garden building in the grounds of St Philomena's School, formerly Carshalton House. Interior vaulted in stone and latterly used as a chapel. Subject to water ingress. Grant offered by English Heritage in 2011 towards the repair of the building. Works are to commence shortly.

Contact: Stephen Senior 020 7973 3783



Grotto in Carshalton Park. SITE NAME Ruskin Road,

Carshalton

Listed Building Grade II, CA DESIGNATION:

Poor CONDITION: N/A OCCUPANCY: PRIORITY: A(A)

OWNERTYPE: Local authority

Early C18 grotto in Carshalton Park. The exterior of the grotto has symmetrical curved walls of brick, ramped up gradually to a central peak. The grotto is extremely vulnerable to vandalism and graffiti. The Local Authority have completed a restoration strategy document and English Heritage has recently offered a grant towards investigative works to the structure.

Commenced 1880s designed by Newman and Jacques. Large and imposing red brick with stone dressings.

Notable chancel screen and Arts and Crafts treatment

of the Baptistery. Grant offered towards high level works.

Contact: Sally Blomfield (LPA) 020 8770 6253



Christ Church, King Charles Road,

Surbiton

DESIGNATION: Listed Place of Worship Grade II, CA

Poor CONDITION:

D (New entry) PRIORITY:

OWNER TYPE: Religious organisation

Contact: Tracey Craig 020 7973 3756



Church of St Barnabas, SITE NAME: St Barnabas Road, Sutton New Town

DESIGNATION: Listed Place of Worship Grade II

CONDITION:

PRIORITY: D (New entry)

OWNER TYPE: Religious organisation

Built 1880s designed by Carpenter and Ingelow. North aisle added 1920s. Slate roofs, brick with stone dressings. Corner bell tower with timber shingle spire. Internally fairfaced brickwork now plastered over. Grant offered towards high level works due to commence May 2011.

Contact: Tracey Craig 020 7973 3756

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS

TOWER HAMLETS



Well and Bucket Public House, SITE NAME:

143 Bethnal Green Road E2

DESIGNATION: Listed Building Grade II

Fair CONDITION:

Part occupied OCCUPANCY:

D (D) PRIORITY-Private OWNER TYPE:

Part of mid to late C19 terrace of shops which is subject to current Tower Hamlets / English Heritage partnership scheme. Ongoing discussions between owners / occupiers and the London Borough of Tower Hamlets.

Contact: Mark Hutton (LPA) 020 7364 5372



Front wall, gate piers and gates SITE NAME: at St Clements Hospital, Bow Road, Bow E3

Listed Building Grade II, CA DESIGNATION:

CONDITION: N/A OCCUPANCY: C(C)PRIORITY:

OWNER TYPE: Health Authority

Decorative gates and railings forming front boundary to redundant St Clements Hospital. Homes and Community Agency (HCA) are engaged with active discussions with the Local Planning Authority concerning future development.

Contact: Mark Hutton (LPA) 020 7364 5372



SITE NAME: St Clements Hospital,

Bow Road, Bow E3

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION: Vacant OCCUPANCY: PRIORITY: C (C)

OWNERTYPE: Health Authority

Redundant hospital, formerly City of London infirmary. Impressive Italianate main block fronting Bow Road. Vacant. Homes and Community Agency (HCA) are engaged with active discussions with the Local Planning Authority concerning future development.

Two C19 bollards which formed a group along with

St Mary's Church, its gates and railings and the statue of

W E Gladstone. One of the bollards has been removed.

Contact: Mark Hutton (LPA) 020 7364 5372



2 Bollards (Between statue of Gladstone SITE NAME: and St Mary's churchyard entrance),

Bow Road, Bromley-By-Bow E3

DESIGNATION: Listed Building Grade II, CA

CONDITION: Poor OCCUPANCY: N/A C (C) PRIORITY-

SITE NAME:

OWNERTYPE: Company Contact: Mark Hutton (LPA) 020 7364 5372

> Gentlemen's public convenience, Bow Road, Bromley-By-Bow E3

DESIGNATION: Listed Building Grade II, CA

Very bad CONDITION: OCCUPANCY: N/A

A(A)OWNERTYPE: Unknown Underground Gentlemen's Public Convenience, constructed by the Board of Works and opened in 1899. Curved entrance steps designed to fit around statue of W E Gladstone. Decorative iron gates recently damaged. Decorative interior finishes including russet marble urinals. Disused for many years. Interior subject to vandalism. LB Tower Hamlets is aiming to work with strategic partners to find a way forward.

Contact: Mark Hutton (LPA) 020 7364 5372



163 Bow Road, SITE NAME: Bromley-By-Bow E3

DESIGNATION: Listed Building Grade II, CA

CONDITION: Poor Occupied OCCUPANCY:

PRIORITY: D (D)

OWNERTYPE: Private

Early C18 property. Stock brick with red brick dressings. Modern shop on forecourt. Interior includes panelled rooms and good staircase. Inappropriate window frames added to facade. Paint applied to brick facade. External repairs, part of High Street 2012 English Heritage part-funded partnership scheme, have started.

Contact: Mark Hutton (LPA) 020 7364 5372

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable)
 end use or user identified;
 functionally redundant buildings
 with new use agreed but not yet implemented

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS



SITE NAME: 199 Bow Road, Bromley-By-Bow E3

DESIGNATION: Listed Building Grade II, CA CONDITION: Very bad

OCCUPANCY: Vacant
PRIORITY: B (B)
OWNER TYPE: Private

Late C17 stock brick with red brick dressings. Neo-Georgian shop front. Unauthorised works to shop front and alterations including changes to dormer windows. Some roof repairs have been undertaken. External repairs, part of High Street 2012 English Heritage part funded-partnership scheme, have started on site.

Contact: Mark Hutton (LPA) 020 7364 5372



SITE NAME: How Memorial Gateway, Bromley High Street E3

DESIGNATION: Listed Building Grade II

CONDITION: POOR
OCCUPANCY: N/A
PRIORITY: C (C)
OWNER TYPE: Unknown

Circa 1893. Gabled stone gothic arch with double buttresses at each side. Formerly an entrance to St Mary's Churchyard. Suffering from stonework decay.

Contact: Mark Hutton (LPA) 020 7364 5372



SITE NAME: The British Prince Public House, 49 Bromley Street EI

DESIGNATION: Listed Building Grade II, CA
CONDITION: Poor

OCCUPANCY: Part occupied
PRIORITY: A (A)
OWNER TYPE: Private

Early C19, but facade partly rebuilt, probably as a result of war damage. Recent unauthorised works have removed much of the ground floor interior. A planning application has been submitted and negotiations are proceeding.

Contact: Mark Hutton (LPA) 020 7364 5372



SITE NAME: Mortuary Chapel,

churchyard of St George in the East, Cannon Street Road El

DESIGNATION: Scheduled Monument, CA

CONDITION: Very bad OCCUPANCY: N/A
PRIORITY: A (A)

OWNERTYPE: Religious organisation

Circa 1870 brick and tile mortuary chapel. In curtilage of grade I listed church. Adapted in 1930s as a nature study centre but abandoned during World War II. Now derelict. Two previous restoration projects foundered. New scheme for drop-in centre under consideration, subject to funding being found.

Contact: Mark Hutton (LPA) 020 7364 5372



SITE NAME: Limehouse Town Hall, Commercial Road E14

DESIGNATION: Listed Building Grade II, CA

CONDITION: Poor
OCCUPANCY: Occupied
PRIORITY: D (D)

OWNER TYPE: Local authority

Built 1879-81 as Limehouse Vestry Hall, designed by A & C Harston. Leased to the Limehouse Town Hall Consortium for arts, educational and community projects. Roof repairs partly grant-aided by English Heritage are expected to commence in 2011.

Contact: Mark Hutton (LPA) 020 7364 5372



SITE NAME: George Tavern Public House, 373 Commercial Road EI

DESIGNATION: Listed Building Grade II, CA

CONDITION: Poor
OCCUPANCY: Occupied
PRIORITY: C (C)
OWNER TYPE: Private

Prominent public house c1820-25. Remodelled 1862. Interior remodelled 1891. Water ingress from roof; slow deterioration of building fabric. Some grant assistance secured; further sources of funding being investigated.

Contact: Mark Hutton (LPA) 020 7364 5372

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA Conservation Area
LB/LBs Listed Building/s
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM/SMs Scheduled Monument/s
UA Unitary Authority
WHS World Heritage Site



Former Caird & Rayner SITE NAME:

Ltd Warehouse,

777-783 Commercial Road E14

DESIGNATION: Listed Building Grade II, CA Very bad CONDITION: Vacant

A(A)Company OWNER TYPE:

OCCUPANCY:

OWNER TYPE:

Former sail-makers and ship-chandler's warehouse, 1869. A rare survival consisting of a brick skin enclosing a timber structure. Fire damaged with loss of roof covering. Urgent works completed April 2010.

Contact: Mark Hutton (LPA) 020 7364 5372



SITE NAME: 795 Commercial Road E14

DESIGNATION: Listed Building Grade II

Poor CONDITION: Occupied OCCUPANCY: C (C) PRIORITY:

Private

Late C18 / early C19 terraced house, with late C19 / early C20 shop to ground floor. Unauthorised works have recently been carried out. Enforcement action currently underway.

Contact: Mark Hutton (LPA) 020 7364 5372

Former public baths, slipper baths and vapour



Poplar Baths, SITE NAME: East India Dock Road E14

DESIGNATION: Listed Building Grade II Poor CONDITION: Vacant OCCUPANCY: C(C)PRIORITY:

Local authority are considering re-opening as a swimming pool and sports centre.

baths. Built 1932-4 for Poplar Borough Council to the

designs of Harley Heckford, Borough Engineer and R W Stanton, Chief Assistant. Vacant and in poor condition.



Dowgate Wharf warehouses, SITE NAME: 22-23 Gillender Street E14

Mid C19 brick warehouses. Future under discussion with local authority.

Contact: Mark Hutton (LPA) 020 7364 5372

DESIGNATION: Listed Building Grade II Poor CONDITION: Vacant A(A)PRIORITY:

Contact: Mark Hutton (LPA) 020 7364 5372



Wiltons Music Hall, SITE NAME: Graces Alley EI

Company

DESIGNATION: Listed Building Grade II* CONDITION:

Occupied OCCUPANCY: C (C) PRIORITY OWNER TYPE: Trust

OWNER TYPE:

Former music hall with fine ornamental interior built 1858. Leased to opera company and now in regular use. Some repair and restoration required. English Heritage and London Borough of Tower Hamlets discussing way forward with Trust and assisting search for funding. English Heritage grant-aided condition survey completed.

Contact: Andrew Hargreaves 020 7973 3718



SITE NAME: Tablet in the North Wall of the Portuguese Jewish Burial Ground, Mile End Road E1

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION: N/A OCCUPANCY: PRIORITY: A (B)

OWNERTYPE: Religious organisation

An inscribed stone tablet, formerly in a glazed case with side scrolls, moulded cornice and pediment recording laying of first stone in the burial ground in 1684. The top of the wall including moulded cornice and pediment has collapsed, leaving the stone open to the elements.

Contact: Mark Hutton (LPA) 020 7364 5372

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category given in brackets

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



Drinking fountain (on pavement SITE NAME: outside 31-74 Mile End Road), Mile End Road, Stepney EI

DESIGNATION: Listed Building Grade II

Very bad CONDITION: N/A OCCUPANCY:

PRIORITY:

D(D)OWNER TYPE: Local authority Late C19 polished granite drinking fountain, short column on plinth with inscription commemorating erection by Metropolitan Cattle Trough and Drinking Fountain Association. Bowl removed. Restoration proposed as part of the High Street 2012 initiative, subject to available funding.

Contact: Mark Hutton (LPA) 020 7364 5372



SITE NAME: Drinking fountain (on pavement outside 99 Mile End Road). Mile End Road, Stepney E1

DESIGNATION: Listed Building Grade II, CA

Very bad CONDITION: N/A D (D) PRIORITY: Company OWNER TYPE:

C19 small granite polished drinking fountain with dog trough. Upper part of structure removed. Restoration proposed as part of the High Street 2012 initiative, subject to available funding.

Contact: Mark Hutton (LPA) 020 7364 5372



St Saviours Church, SITE NAME: Northumbria Street,

Poplar E14 Listed Building Grade II DESIGNATION:

Very bad CONDITION: Vacant OCCUPANCY:

PRIORITY-

OWNER TYPE: Religious organisation

A(A)

Redundant church dating from 1873-4 to design by Frederick J and Horace Francis. Declared redundant in 1984. The church was severely damaged by fire in May 2007 and is currently propped by scaffolding. The Local Authority has been approached by developers but no application has been submitted.

Contact: Mark Hutton (LPA) 020 7364 5372



Tobacco Dock, SITE NAME: Pennington Street EI

DESIGNATION: Listed Building Grade I

Fair CONDITION: Vacant E (E) PRIORITY: Company Warehouse building of 1811-13, converted to form a shopping complex in the early 1990s. This was not successful and the building has been vacant for some time, although occasionally used as an events venue. Pre application discussions between owners and local authority have taken place.

Contact: Andrew Hargreaves 020 7973 3718



19 Princelet Street, SITE NAME: Spitalfields E1

DESIGNATION: Listed Building Grade II*, CA

CONDITION:

Part occupied OCCUPANCY:

C (C) PRIORITY

OWNER TYPE: Trust Terraced house of 1719 by Samuel Warrall, builder, with added synagogue of 1869 by a Mr Hudson. Combines a well preserved Spitalfields Huguenot merchant's house with weaving garrets, and rare surviving small synagogue. Discussions underway regarding condition of the building.

Contact: Andrew Hargreaves 020 7973 3718



SITE NAME: 113 Redchurch Street, Tower Hamlets E2

DESIGNATION: Listed Building Grade II, CA

Very bad CONDITION: Part occupied

PRIORITY: A (A) OWNERTYPE: Private Weavers' tenement house. Built c1735 by William Farmer, a local builder. Of interest as a rare and early survival of a building type that once dominated Spitalfields. The building is derelict and has structural problems. The facade is braced to prevent further movement.

Contact: Mark Hutton (LPA) 020 7364 5372

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



SITE NAME:	10-12 Stroudley Walk,
	Bromley-by-Bow F3

DESIGNATION: Listed Building Grade II

Poor CONDITION: Vacant OCCUPANCY: C(C)

OWNERTYPE: Private

Late C18, early C19, three storeys, stock brick with shop on ground floor Attached to the Rose and Crown Public House. Application for conversion to residential use refused. Negotiations with local authority continuing.

Contact: Mark Hutton (LPA) 020 7364 5372



SITE NAME: Rose and Crown Public House, 8 Stroudley Walk, Bromley-by-Bow E3

DESIGNATION: Listed Building Grade II

Poor CONDITION: Vacant E (A) PRIORITY: OWNERTYPE: Private Late C18, early C19 inn, of three storeys with parapet and stucco band. Forms an important local focal point. Building currently empty but repairs underway and work to convert upper floors into flats.

Contact: Mark Hutton (LPA) 020 7364 5372



Braithwaite Viaduct, SITE NAME: Bishopsgate Goods Yard, Wheler Street / Brick Lane EI

DESIGNATION: Listed Building Grade II

Poor CONDITION: N/A OCCUPANCY: PRIORITY: C(C)OWNERTYPE: Company Early railway viaduct built 1840 by John Braithwaite for the Eastern Counties Railway, formerly set within extensive brick vaulted goods yard circa 1880, demolished 2003. Master plan completed. Condition survey and other works to vaults required.

Contact: Mark Hutton (LPA) 020 7364 5372



Drinking fountain set in wall SITE NAME: of former St Mary's Churchyard, Whitechapel Road EI

DESIGNATION: Listed Building Grade II

CONDITION: Poor N/A OCCUPANCY: D (D) PRIORITY:

SITE NAME:

OWNER TYPE: Local authority


Drinking fountain with pink marble basin and plaque set in Norman style arch. Erected 1860 but moved to present position 1879. The Local Authority has carried out cleaning, but repairs outstanding. Further restoration proposed as part of the High Street 2012 initiative, subject to available funding.

Contact: Mark Hutton (LPA) 020 7364 5372



2 Wilkes Street EI

Early C18 terraced house. Three storeys with basement and attic in painted brick. Some repair works commenced.



Contact: Mark Hutton (LPA) 020 7364 5372



Church of St John on Bethnal Green, SITE NAME: Cambridge Heath Road, Bethnal Green E2

DESIGNATION: Listed Place of Worship Grade I, CA CONDITION:

PRIORITY: F (F) OWNER TYPE: Religious organisation Parish church of 1824 by Sir John Soane. Heavily restored and extended in C19 by William Munday and G F Bodley. Stock brick with artificial stone dressings and western portico. Phased programme of English Heritage / Heritage Lottery Fund grant-aided repairs underway to high level

stonework and render.

Contact: Donald Wahlberg 020 7973 3786

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



New Testament Church of God SITE NAME:

(former Holy Trinity),

Morgan Street, Bethnal Green E3

DESIGNATION: Listed Place of Worship Grade II, CA

CONDITION: PRIORITY:

Religious organisation OWNER TYPE:

London stock brick with stone dressings designed by G Austin and built 1836-9. Repairs to roofs and stonework have been undertaken. The church is being used with a marquee in the nave.

Former Huguenot chapel which was altered in mid C19 as

a synagogue. The roof was found to be at serious structural

risk. The urgent repairs are underway with English Heritage

/ Heritage Lottery Fund grant aid and completion is

Contact: Andrew Hargreaves 020 7973 3718



Sandy's Row Synagogue, SITE NAME:

Sandy's Row, Bethnal Green EI

DESIGNATION: Listed Place of Worship Grade II, CA

F (New entry) PRIORITY:

Religious organisation OWNER TYPE:

Contact: Tracey Craig 020 7973 3756

expected in 2011.



Gurdwara Sikh Sanghat, SITE NAME:

Harley Grove,

Bow E3

DESIGNATION: Listed Place of Worship Grade II, CA

Very bad CONDITION:

C (C) PRIORITY:

OWNER TYPE: Religious organisation

Stuccoed mid C19 classical building. Built as a chapel, converted to a synagogue in 1927 and re-opened as a Sikh Temple in 1979. Part of the rear is in use as the former Sunday School. The entire building was severely damaged by fire in 2009 and is currently propped by scaffolding.

Contact: Donald Wahlberg 020 7973 3786



SITE NAME: Former Trinity Methodist Church

> (including attached hall and Church rooms), East India Dock Road, Poplar E14

DESIGNATION: Listed Place of Worship Grade II, CA

Poor CONDITION: C (C) PRIORITY:

OWNER TYPE: Religious organisation

Church built in 1950s part of the live architectural exhibition of the 1951 Festival of Britain by Cecil Handisyde and D Rogers Stark. Spalling of aggregate faced concrete is exposing reinforcement which requires repair. A new congregation has acquired the building.

Contact: Donald Wahlberg 020 7973 3786

ITE NAME:	Priory and Hospital of St Mary Spital, Tower Hamlets			
DESIGNATION:	Scheduled Monument (No. 1001982)	CONDITION:	Generally unsatisfactory	
	,		with major localised problems	
PRINCIPAL VULNERABILITY:	Public utilities	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Jane Sidell 020 7973 3738	
SITE NAME:	Balfron Tower			
DESIGNATION:	Conservation Area	CONDITION:	Very bad	
VULNERABILITY:	Medium	TREND:	Deteriorating	
CONTACT:	Mark Hutton (LPA) 020 7364 5372	NEW ENTRY?:	No	
SITE NAME:	London Hospital, Stepney			
DESIGNATION:	Conservation Area	CONDITION:	Very bad	
VULNERABILITY:	Low	TREND:	Improving significantly	
CONTACT:	Mark Hutton (LPA) 020 7364 5372	NEW ENTRY?:	No	

PRIORITY (FOR BUILDINGS)

SITE NAME DESIGNATION:

VULNERABILITY:

CONTACT:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

Conservation Area

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Redchurch Street, Bethnal Green

Mark Hutton (LPA) 020 7364 5372

Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

No

CONDITION:

NEW ENTRY?:

TREND:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

Very bad

Improving

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	St Anne's Church		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Improving
CONTACT:	Mark Hutton (LPA) 020 7364 5372	NEW ENTRY?:	No
SITE NAME:	Stepney Green		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Mark Hutton (LPA) 020 7364 5372	NEW ENTRY?:	No
SITE NAME:	Tower Hamlets Cemetery, Bow		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Deteriorating significantly
CONTACT:	Mark Hutton (LPA) 020 7364 5372	NEW ENTRY?:	No
SITE NAME:	Wentworth Street, Bethnal Green		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	No significant change
CONTACT:	Mark Hutton (LPA) 020 7364 5372	NEW ENTRY?:	No
SITE NAME:	Whitechapel High Street, Bethnal Green		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Improving significantly
CONTACT:	Mark Hutton (LPA) 020 7364 5372	NEW ENTRY?:	No
SITE NAME:	Wilton's Music Hall		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Mark Hutton (LPA) 020 7364 5372	NEW ENTRY?:	No

WALTHAM FOREST



Wall to south east SITE NAME: of St Mary's Churchyard, Church End E17

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION: N/A OCCUPANCY: PRIORITY: A(A)OWNERTYPE: Private C18 walls, formerly belonging to a house, now demolished, on the adjacent site.

Contact: Guy Osborne (LPA) 020 8496 6737



698a High Road Leytonstone, SITE NAME: Leytonstone EII

DESIGNATION: Listed Building Grade II Poor CONDITION: occupancy: Part occupied

PRIORITY: C (C) OWNERTYPE: Charity Probably late C18. One of a surviving terrace of three Georgian houses, for many years the home of the local British Legion branch. Largely vacant and up for sale, pre-application discussions held for conversion into flats.

Contact: Guy Osborne (LPA) 020 8496 6737

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



Granada Cinema, SITE NAME: 186 Hoe Street, Walthamstow E17

DESIGNATION: Listed Building Grade II*

Poor CONDITION:

Part occupied OCCUPANCY:

A(A)

OWNER TYPE: Religious organisation

Built 1929-30 as the Granada Cinema to the design of Cecil Masey with fine Art Deco and Moorish style interiors by Theodore Komisarjevsky. Planning and listed building applications for a place of worship, and community uses refused by the Local Planning Authority May 2011.

Contact: Rachel Godden 020 7973 3716



Pimp Hall dovecote, SITE NAME: King's Road.

Chingford E4 DESIGNATION: Listed Building Grade II

Poor CONDITION: N/A C (C) PRIORITY:

Local authority OWNER TYPE:

C16 / C17 timber framed dovecote, the last surviving structure from the historic Chingford Manor of Gowers and Buckerells. Currently in a poor condition as a result of deterioration of the timber frame and repeated vandalism.



Chapel to south of main hospital block, SITE NAME: Langthorne Road EII

Redundant chapel to hospital (formerly a workhouse), 1840. Being maintained. Long-term use to be determined as part of hospital site.

DESIGNATION: Listed Building Grade II CONDITION: Fair Vacant OCCUPANCY: E (E) PRIORITY:

Contact: Guy Osborne (LPA) 020 8496 6737

Contact: Guy Osborne (LPA) 020 8496 6737



Lodge south of main hospital block, SITE NAME: Langthorne Road EII

1840 lodge to hospital (formerly a workhouse). Being maintained; long-term usé to be determined as part of hospital site.

DESIGNATION: Listed Building Grade II CONDITION: Poor Vacant C(C)PRIORITY-Health Authority OWNER TYPE:

Contact: Guy Osborne (LPA) 020 8496 6737



Chingford Mill Pumping Station, SITE NAME: Lower Hall Lane E4

DESIGNATION: Listed Building Grade II CONDITION: Vacant OCCUPANCY: D (D) PRIORITY-

Pumping station built 1895 for East London Water Works, in a variant of the style popularised by Norman Shaw. Planning permission and listed building consent for residential use granted in 2007 subject to a Section 106 agreement. Currently the subject of enforcement action for unauthorised works.

Contact: Guy Osborne (LPA) 020 8496 6737



SITE NAME: Water Turbine House, Chingford Mill Pumping Station, Lower Hall Lane E4

DESIGNATION: Listed Building Grade II

Very bad CONDITION: Vacant PRIORITY: D (D) OWNERTYPE: Private

OWNERTYPE: Private

Water turbine house to pumping station built 1895 for East London Water Works. Planning permission and listed building consent for residential use granted in 2007 subject to a Section 106 agreement. Currently the subject of enforcement action for unauthorised works.

Contact: Guy Osborne (LPA) 020 8496 6737

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category given in brackets

ABBREVIATIONS



133 Whipps Cross Road, SITE NAME: Leytonstone EII

DESIGNATION: Listed Building Grade II, CA Poor CONDITION:

Occupied OCCUPANCY: C (C)

OWNER TYPE:

Private

One of six survivors from an original terrace of I2 'middle-class' three storey houses called Assembly Row built in 1767 on the high ground at the edge of the forest land. Within Leytonstone Conservation Area. Planning consent and listed building consent for conversion into flats refused in 2005 and upheld on appeal. Occupied but in deteriorating condition.

Italianate style railway station built circa I 865 for the London, Brighton and South Coast Railway. Application for

alterations, repairs and refurbishment to station building approved September 2010. Application received February 2011 to discharge conditions regarding redecoration.

Contact: Guy Osborne (LPA) 020 8496 6737

WANDSWORTH



Battersea Park Station, SITE NAME: Battersea Park Road SW8

DESIGNATION: Listed Building Grade II, CA

CONDITION:

Part occupied OCCUPANCY:

D (C) PRIORITY: OWNERTYPE: Company

Contact: Barry Sellers (LPA) 020 8871 6631

Works expected to commence 2011.



SITE NAME: Former St Mark's Infant School, Battersea Rise SWII

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION: Vacant OCCUPANCY: A(A)PRIORITY

Religious organisation OWNER TYPE:

Church School of 1866-67 designed by Benjamin Ferrey. The building is now vacant and in poor condition with structural problems to the rear wall. Owners have commissioned a report on structural condition.

Contact: Barry Sellers (LPA) 020 8871 6631



Battersea Power Station, SITE NAME: Cringle Street SW8

DESIGNATION: Listed Building Grade II* Very bad CONDITION: OCCUPANCY: Vacant D (D) PRIORITY OWNER TYPE: Company

Power station built 1932 onwards. Closed and vacated in 1983. Building upgraded to II* in October 2007. Revised master plan launched June 2008 with public consultation. Fresh planning and listed building applications approved 2010 subject to legal agreement for restoration, extension and conversion of Power Station to provide retail, residential flats, business, cultural, hotel and conference facilities.

Contact: Nick Collins 020 7973 3739



Battersea Pumping Station, SITE NAME: Cringle Street SW8

DESIGNATION: Listed Building Grade II Very bad CONDITION:

OCCUPANCY: Vacant D (A)

OWNER TYPE: Company

Water pumping station, circa 1846. Linked to development of Battersea Power Station. Separate demolition of boiler house agreed in 2002 in advance of works to engine house. Archaeological report and building recording completed. Application to demolish approved November 2010 subject to determination by Secretary of State and completion of \$106 of planning agreement.

Contact: John Webb (LPA) 020 8871 6645



Springfield Hospital (main building), SITE NAME: Glenburnie Road SW17

DESIGNATION: Listed Building Grade II, RPG II

CONDITION: Poor Part occupied OCCUPANCY:

PRIORITY: C (D)

OWNERTYPE: Health Authority

Former Psychiatric hospital built 1840 in Tudor Gothic style as the Surrey County Asylum. A master plan for the site and Phase I of reprovision of mental health facilities complete. Revised planning application for the redevelopment of site and demolition of curtilage listed buildings refused in December 2010.

Contact: Barry Sellers (LPA) 020 8871 6631

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



Monuments at Huguenot SITE NAME: Burial Ground,

Huguenot Place SW18

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION: N/A OCCUPANCY: D(C)PRIORITY:

OWNER TYPE: Religious organisation

Five tombs circa 1720-1843. Substantial funding towards the repairs to the tombs to be provided as part of \$106 Agreement on adjoining property 39-41 East Hill.

Contact: Barry Sellers (LPA) 020 8871 6631



SITE NAME: The Montague Arms, 3 Medfield Street. Roehampton Village SW15

DESIGNATION: Listed Building Grade II, CA

CONDITION: Vacant F (C) PRIORITY: OWNER TYPE: Company

C17 house converted into a public house in the 1860s. Vacant. Applications for change of use from public house to retail or office uses on ground floor with residential above approved in June 2010. Works currently being implemented.

Contact: Barry Sellers (LPA) 020 8871 6631



Temple in the grounds SITE NAME: of Mount Clare. Minstead Gardens SW15

DESIGNATION: Listed Building Grade II*, CA

CONDITION: Poor N/A OCCUPANCY:

PRIORITY:

C(C)OWNER TYPE: Educational Body Temple 1762-69. Some damage caused by vandalism following unauthorised access. Site has been re-secured. Long-term strategy for temple still being discussed with owners.

Contact: Simon Hickman 020 7973 3762



St Peter's Church Hall, SITE NAME: Plough Road SWII

DESIGNATION: Listed Building Grade II

CONDITION: Poor

Part occupied

D (C) PRIORITY-

Religious organisation OWNER TYPE:

Late C19 church hall used as hall and drop-in centre. Repairs to roof, windows and brickwork required. Application for listed building consent to demolish and planning permission for new church facility and flats approved subject to Secretary of State decision.

Contact: John Webb (LPA) 020 8871 6645



Ice house at the Priory Hospital, SITE NAME: Priory Lane SW15

DESIGNATION: Listed Building Grade II

CONDITION: Poor N/A OCCUPANCY: C (C) PRIORITY-OWNERTYPE: Private Early C19 ice house in grounds of the Priory Hospital. In poor but stable condition. Listed building consent application expected in conjunction with proposed works to playground and day school.

Contact: Barry Sellers (LPA) 020 8871 6631



SITE NAME: Queenstown Road Station, Queenstown Road SW8

DESIGNATION: Listed Building Grade II, CA Poor CONDITION: Part occupied

PRIORITY: D (D) OWNERTYPE: Company

Station built in 1877. Repairs needed to doors, windows and floors of disused areas of this unattended station. Former station ticket office re-used for cafe and redecoration to lobby area completed 2010. Minor works to Platform I, which is scheduled for major overhaul as part of a re-commission for public use. Proposals to be prepared 2011.

Contact: Barry Sellers (LPA) 020 8871 6631

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



King's Head Public House, SITE NAME: I Roehampton High Street SW15

DESIGNATION: Listed Building Grade II, CA

Fair CONDITION: Vacant OCCUPANCY: D(C)PRIORITY: OWNERTYPE: Company

C17 public house. Vacant but in fair condition. Planning and listed building consent applications approved October 2010 for alterations and creation of 2 flats in stable block in conjunction with re-use as a public house.

Contact: John Webb (LPA) 020 8871 6645



The Watchers, behind Downshire SITE NAME: House, Roehampton Lane, Roehampton SW15

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION: N/A

C (New entry) PRIORITY: OWNERTYPE: Educational Body

Sculpture of 1960 by Lynn Chadwick and installed in 1963 by the London County Council. The sculpture has been temporarily removed following vandalism. The owners are preparing a scheme to reinstate.

Contact: Barry Sellers (LPA) 020 8871 6631



Former Gala Bingo Hall (Granada), SITE NAME: 58 St John's Hill SWII

DESIGNATION: Listed Building Grade II*

CONDITION: Poor Vacant OCCUPANCY: F (F) PRIORITY: OWNER TYPE: Company

Cinema built 1937. Last used as a bingo club, now vacant. Scheme for residential development being implemented. Auditorium recently sold to church group. Applications to fit out church interior approved, subject to conditions, in 2008. Completion expected 2011.

Contact: Simon Hickman 020 7973 3762



SITE NAME: 100 Tooting Bec Road SW17

DESIGNATION: Listed Building Grade II Poor CONDITION: Vacant A (New entry) PRIORITY-Private

Early C19 stucco lodge. Vacant and in need of repair. Planning and listed building consent applications submitted for extension and refurbishment and two additional dwellings in rear garden.

Contact: Barry Sellers (LPA) 020 8871 6631



Former Bolingbroke Hospital, SITE NAME: Wakehurst Road SWII

DESIGNATION: Listed Building Grade II, CA CONDITION:

OCCUPANCY: Vacant PRIORITY-

OWNER TYPE:

D (New entry) OWNER TYPE: Local authority

Hospital built in 1901-1936 by Young and Hall. Vacant following redundancy. Planning and listed building consent applications submitted. Planning permission for use as health care facility and residential use approved in February 2011.

Contact: Barry Sellers (LPA) 020 8871 6631

WESTMINSTER, CITY OF



SITE NAME: Crockers Public House, 23-24 Aberdeen Place NW8

DESIGNATION: Listed Building Grade II*, CA CONDITION: Part occupied OCCUPANCY: PRIORITY: C(C)

Public house circa 1900. Formerly known as "The Crown". Has been closed since autumn 2004. Temporary works have been undertaken to secure the building and to make weathertight. Upper floors currently occupied and discussions are taking place between the owners and the planning authority regarding the future use of the building including re-opening the pub with a restaurant including restoration.

Contact: Sheila Stones 020 7973 3785

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

OWNERTYPE: Company

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: If the priority category has changed since the 2010 register, the previous category given in brackets

ABBREVIATIONS CA LB/LBs LPA NP RPG SM/SMs UA WHS



SITE NAME: Bow Street Magistrates' Court and Police Station,
Bow Street WC2

DESIGNATION: Listed Building Grade II, CA

condition: Fair

OCCUPANCY: Vacant
PRIORITY: D (New entry)

OWNERTYPE: Company

Court and Police Station. I 879-80. Portland stone. Dignified eclectic Greco-Roman with some slightly Vanbrughian details. Building is vacant. Planning permission and listed building consent granted in 2008 for various extensions and alterations in connection with use as an hotel. No work has yet commenced. Application to renew the 2008 permission expected.

Contact: Tom Burke (LPA) 020 7641 3488



SITE NAME: 21 Charles Street WI

DESIGNATION: Listed Building Grade II, CA

condition: Poor occupancy: Vacant priority: D (D)

OWNER TYPE: Unknown

Terraced town house circa 1750-53. Vacant and deteriorating. Some unauthorised works have taken place. Planning permission and listed building consent granted in July 2008 for various works including demolition and rebuilding of the mews building to the rear. A site inspection has taken place but no works have commenced.

Contact: Robert Ayton (LPA) 020 7641 2978



SITE NAME: 39 Charles Street, Mayfair W I

DESIGNATION: Listed Building Grade II*, CA

CONDITION: Poor
OCCUPANCY: Vacant
PRIORITY: D (D)
OWNER TYPE: Company

Contact: Timothy Jones 020 7973 3780



SITE NAME: 76 Dean Street, Soho WI

DESIGNATION: Listed Building Grade II*, CA

CONDITION: Very bad

OCCUPANCY: Vacant

PRIORITY: A (A)

OWNER TYPE: Company

Terraced town house dating from 1730s. The property was seriously damaged by fire in 2009. Discussions ongoing to ensure necessary repair and restoration.

Main house dates from 1750s. There are two mews houses

attached to the site by a link building. Planning permission

granted in May 2006 and January 2009, but to date no works have commenced on site. Building currently vacant.

English Heritage and the local authority are monitoring

Contact: Timothy Jones 020 7973 3780



SITE NAME: Span Four,

Paddington Station, Eastbourne Terrace W2

DESIGNATION: Listed Building Grade I

CONDITION: Fair
OCCUPANCY: Occupied
PRIORITY: F (F)
OWNER TYPE: Company

Train shed completed in 1916 as an extension to Brunel's station. Lacking in routine maintenance. Repair and refurbishment underway and close to completion.





SITE NAME: 112 Eaton Square SWI

DESIGNATION: Listed Building Grade II*, CA CONDITION: Poor

OCCUPANCY: Vacant PRIORITY: B (D)
OWNER TYPE: Private

Grand terrace house. Building is suffering from neglect, water ingress and a serious outbreak of dry rot. Works to improve the building have been undertaken and a photographic survey completed.

Contact: Timothy Jones 020 7973 3780

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS CA Conser LB/LBs Listed E LPA Local P NP Nationa RPG Registe SM/SMs Schedu

UA WHS



SITE NAME:	12-22 ((even)	Gloucester	Place	W	I
------------	---------	--------	------------	-------	---	---

Terraced houses circa 1800-20. Planning permission and listed building consent for alterations and refurbishment implemented and works almost completed.

DESIGNATION: Listed Building Grade II, CA CONDITION: Fair

Vacant OCCUPANCY: F (F) OWNER TYPE: Company

Contact: Robert Ayton (LPA) 020 7641 2978



SITE NAME: 46 and 52 Gloucester Place WI

DESIGNATION: Listed Building Grade II, CA Poor CONDITION: Vacant F (F) PRIORITY: OWNER TYPE: Company

Terraced houses built 1790-1800 for the Portman Estate. Mainly vacant, but planning permission and listed building consent agreed for alterations and change of use back to residential. Some works are taking place with refurbishment works being carried out at No. 52. Minor repairs are being carried out at No. 46.

Contact: Lucy Metcalfe (LPA) 020 7641 2169



65 Gloucester Place WI SITE NAME:

DESIGNATION: Listed Building Grade II, CA CONDITION: Poor Vacant OCCUPANCY: F (E) PRIORITY: OWNERTYPE: Company


Part of long terrace of town houses built circa 1790-1800 by the Portman Estate. Planning permission and listed building consent granted and works are underway; due for completion in 2011.



SITE NAME: 73 Gloucester Place WI

Part of a long terrace of houses built circa 1790-1800 by the Portman Estate.

Contact: Robert Ayton (LPA) 020 7641 2978



Contact: David English (LPA) 020 7641 2510



94,100,102 and 104 SITE NAME: Gloucester Place WI

DESIGNATION: Listed Building Grade II, CA CONDITION: Part occupied OCCUPANCY: D (D) PRIORITY-OWNERTYPE: Private

Terraced houses built circa I 800 for the Portman Estate. Mainly vacant. No.s 96 and 98 are now occupied. Listed building consent was granted in July 2009 for the internal refurbishment and alterations to No. 100. Works have yet to be implemented.

Contact: Robert Ayton (LPA) 020 7641 2978



SITE NAME: 2-5 (consec) Hertford Street WI

DESIGNATION: Listed Building Grade II, CA Fair CONDITION: Vacant PRIORITY: F (F) OWNER TYPE: Company

Part of a block of terraced houses, some with shops. Mid to late C18. Linked to scheme for 35 Shepherd Market, 20 Shepherd Street, and No.s 2, 2A, 4-8 (even) Trebeck Street. Largely repaired but still unoccupied. Consent granted in 2010 for further alterations and use of the building for a private members' restaurant, retail and residential units.

Contact: Matthew Pendleton (LPA) 020 7641 5971

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

LPA NP



SITE NAME:	10 Hertfor	rd Street W
------------	------------	-------------

DESIGNATION: Listed Building Grade I, CA

Poor CONDITION: Vacant OCCUPANCY:

F (F) Company

Terraced town house, 1768-69. Interior by Robert Adam for General Burgoyne 1769-71. Planning permission and listed building consent granted in November 2008 for extensions and alterations. Works are currently taking place on site to implement this scheme.

Contact: Timothy Jones 020 7973 3780



41 Lancaster Gate W2 SITE NAME:

DESIGNATION: Listed Building Grade II, CA

Poor CONDITION: Vacant D (New entry) PRIORITY:

Company OWNER TYPE:

Part of a grand terrace of houses, 1865. Stucco with Doric porches. Building is vacant and in poor condition, particularly the internal plasterwork. Listed building consent granted in March 2011 and application for use as four flats is currently being considered.

Contact: Alistair Taylor (LPA) 020 7641 2979

Contact: Timothy Jones 020 7973 3780



Middlesex Hospital Chapel, SITE NAME: Mortimer street, East Marylebone WI

Listed Building Grade II*, CA DESIGNATION:

Fair CONDITION: Vacant OCCUPANCY: D (C) PRIORITY: OWNERTYPE: Private Permission has been granted for redevelopment of the site and repair of the chapel but has not been implemented.



Railings around Crescent Gardens, SITE NAME: Regents Park, Park Crescent WI

DESIGNATION: Listed Building Grade II, CA

Fair CONDITION: N/A F (F) PRIORITY: Crown

OWNER TYPE:

OCCUPANCY:

Railings of circa 1812. Part of wider scheme for repair of paving, railings, gates and lodges in the park. Railings in places cracked and fractured. English Heritage grant made in 2009 and 2010 towards the repairs. Works currently underway with Phase I completed and Phase II set to commence in June 2011. English Heritage has offered a further grant towards Phase III.

Contact: Matthew Pendleton (LPA) 020 7641 5971

Large 1832 house, split into flats in the 1920s, ground

floor retail units. Has been empty and boarded for a number of years; squatters have caused serious damage. Condition deteriorating. Pre-application underway.



138 Park Lane WI SITE NAME:

DESIGNATION: Listed Building Grade II, CA CONDITION:

Vacant C (New entry) PRIORITY-

OWNER TYPE: Company

Contact: Matthew Pendleton (LPA) 020 7641 5971



SITE NAME: 94 Piccadilly W I

DESIGNATION: Listed Building Grade I, CA Fair CONDITION:

PRIORITY: C(C)OWNER TYPE: Company

Town Mansion of 1756-1760 by Matthew Brettingham for Lord Egremont, with 1822 and later alterations. Naval and Military Club from 1866 until 1999. Building for sale. Suffering from water ingress. English Heritage and the Local Authority are monitoring the site.

Contact: Timothy Jones 020 7973 3780

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



95 Piccadilly, Mayfair WI SITE NAME:

A grade II town house dating from I 886. Now forms part of a larger site with Former Naval and Military Club.

DESIGNATION: Listed Building Grade II, CA

CONDITION: Fair Vacant OCCUPANCY: C(C)

Contact: Matthew Pendleton (LPA) 020 7641 5971



SITE NAME: 26 Portland Place, Harley Street WI

DESIGNATION: Listed Building Grade II*, CA

Fair CONDITION: Vacant E (E) PRIORITY: OWNER TYPE: Company

Main house circa 1770s, with some C18 interiors. Planning permission and listed building consent granted in October 2005. Works have commenced on site albeit slowly. The building is currently vacant.

Contact: Timothy Jones 020 7973 3780



33 Portland Place WI SITE NAME:

DESIGNATION: Listed Building Grade II*, CA CONDITION:

Occupied C (C) PRIORITY: OWNERTYPE: Company

OCCUPANCY:

Town house built circa 1780 to design of James Adam. Retains fine Adam interiors. Now occupied and in residential use; largely refurbished internally but works to the roof are still outstanding. Enforcement action is currently taking place relating to the use of the building.

Contact: Timothy Jones 020 7973 3780



Wharf side shelter and store SITE NAME: to rear of builders' merchants, 22 Praed Street W2

DESIGNATION: Listed Building Grade II

CONDITION: Fair Vacant D (D) PRIORITY-Company OWNER TYPE:

Wharf side shelter and store circa 1840. Brick ground floor with timber first floor with large slated hipped roof. Part of redevelopment scheme for Paddington Basin. The shelter will be re-erected as part of the final landscaping proposals.

Contact: David Clegg (LPA) 020 7641 3014



20 Shepherd Street WI SITE NAME:

DESIGNATION: Listed Building Grade II, CA CONDITION: Vacant OCCUPANCY: F (F) PRIORITY-OWNERTYPE: Company

Terraced house, probably late C18 with mid C20 shop front across ground floor. Part of a group with 2-5 Hertford Street, 35 Shepherd Market, 2, 2a and 4-8 Trebeck Street. Planning permission and listed building consent granted for further alterations and use of building for a private members' restaurant, retail and seven residential units.

Contact: Matthew Pendleton (LPA) 020 7641 5971



SITE NAME: 35 Shepherd Market WI

Part of a block of terraced houses, some with shops. Mid to late C18. Scheme for alterations, refurbishment and change of use is being implemented.

DESIGNATION: Listed Building Grade II, CA Fair CONDITION: Vacant PRIORITY: F (F) OWNERTYPE: Company

Contact: Alistair Taylor (LPA) 020 7641 2979

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



SITE NAME:	2, 2A and 4-8 (even	ı)
	Trebeck Street WI	

DESIGNATION: Listed Building Grade II, CA

CONDITION: Fair Vacant OCCUPANCY: F (F)

OWNER TYPE: Company

Part of a block of terraced houses, some with shops. Mid to late C18. Largely repaired but still unoccupied. Planning permission and listed building consent granted in February 2010 for further alterations and use of the building for a private members' restaurant, retail and seven residential units.

Contact: Matthew Pendleton (LPA) 020 7641 5971



SITE NAME: 55 Upper Berkeley Street WI

Terraced house circa 1800-20. Part of Portman Estate development. Run down and mainly vacant.

DESIGNATION: Listed Building Grade II, CA

Fair CONDITION:

Part occupied OCCUPANCY:

C (C) PRIORITY: OWNER TYPE: Company

Contact: Susanna Millar (LPA) 020 764 12459



21 Upper Grosvenor Street WI SITE NAME:

DESIGNATION: Listed Building Grade II, CA CONDITION: Poor

Vacant OCCUPANCY: A(A)PRIORITY: OWNERTYPE: Company Terraced town house circa 1732. Building suffering from general lack of maintenance and repair with water ingress. Planning permission and listed building consent granted in November 2005 for alterations and refurbishment. No works have taken place.

Contact: Robert Ayton (LPA) 020 7641 2978



SITE NAME: 140 Westbourne Terrace W2

DESIGNATION: Listed Building Grade II, CA CONDITION: Good Occupied F (F) PRIORITY-Company OWNER TYPE:

Detached villa dated to 1843-8 in Italianate style. Occupied as a number of bedsits. Recent inspection has taken place. An application for listed building consent has been received to remove the covered link from footpath to house and carry out internal refurbishment and reinstate damaged fabric of the building and handrails. Some repairs undertaken. Applications submitted to retain unauthorised works.

Contact: John Wilman (LPA) 020 7641 2561



Church of St Mary Magdalene, SITE NAME: Rowington Close, Paddington W2

DESIGNATION: Listed Place of Worship Grade I, CA

Poor CONDITION: B (B) PRIORITY:

OWNER TYPE: Religious organisation

1867-78 by GE Street, with crypt chapel of St Sepulchre of 1895 by Sir Ninian Comper An exceptional High Victorian Gothic Church with complete internal decorative scheme. Roof repairs completed with English Heritage grant in 2008 but further work required for which English Heritage has offered grant aid.

Contact: Tracey Craig 020 7973 3756

PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

CA LB/LBs LPA NP RPG SM/SMs

UA WHS



This document is one in a series of publications produced as part of English Heritage's national Heritage at Risk programme. More information about Heritage at Risk and other titles in the series can be found at www.english-heritage.org.uk/risk

HERITAGE AT RISK

Published October 2011 by English Heritage I Waterhouse Square, 138-142 Holborn, London ECIN 2ST